

# 141 - Work In Progress Work Orders (Fiscal Year)

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
118	Work In Progress B-Wing - Need to replace contactor for ERV.	3/7/2005 Medium	Jaime Gomez Jaime Gomez		
547	Work In Progress MARCIA BENTO - FILE CABINET KEY WILL NOT OPEN.	3/18/2005 Medium	Luz Griego Hector Lozoya		Alma Del Valle Daycare
489	Work In Progress replace long gate with half swing and half slide. gate 3 and 1. Had a injury with a custodial	3/17/2005 Medium	Hector Villalobos Michael Munoz		Anthony ES
655	Work In Progress Anthony Elem. 2-3 campus Door stop to kitchen door cracked in half. Could it be replace.  Becky S. - SNP Manager 882-5607	3/29/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Anthony ES
623	Work In Progress 3/18/05 1. check boilers 1.5 go to shop put gas pick up supplies 5.5 pruning trees by football field	3/24/2005 Medium	Hector Villalobos Hector Villalobos		Anthony ES
462	Work In Progress DISPOSAL DOWN  REBECCA SAENZ - K-1 882-5607	3/16/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Anthony ES
102	Work In Progress need to remove dirt with tractor by dumpster	3/7/2005 Medium	Hector Villalobos Lorenzo Hernandez	Cafeteria	Anthony ES
104	Work In Progress annex blg office door handle came off	3/7/2005 Medium	Hector Villalobos Hector Lozoya	Classroom	Anthony ES
103	Work In Progress boiler room we have a leak in pipe line	3/7/2005 Medium	Hector Villalobos Jaime Gomez	Mechanical Room	Anthony ES
331	Work In Progress need 8 sheet metal plates 20x20	3/11/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
228	Work In Progress pt 217 replace heating and cooling	3/10/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
226	Work In Progress need to fill in sidewalk with crusher fine	3/10/2005 Medium	Hector Villalobos Lorenzo Hernandez	Athletic Field	Anthony ES
227	Work In Progress need tractor to scrape off weeds	3/10/2005 Medium	Hector Villalobos Lorenzo Hernandez	Athletic Field	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
205	Work In Progress Annex Bldg Girls rr - Broken window 45 1/2 x 14 3/4.	3/9/2005 Medium	Hector Villalobos Ruben Ronquillo	Restroom (Girls)	Anthony ES Annex Bldg
236	Work In Progress PORTABLE 137 A/C UNIT WILL NOT TURN ON PUSH BOTTOMS ARE NOT WORKING	3/10/2005 Medium	Ramiro Holguin Jaime Gomez		Berino ES
203	Work In Progress NEED PLAYGROUND FERTELIZES	3/9/2005 Medium	Ramiro Holguin Lorenzo Hernandez		Berino ES
441	Work In Progress CHARGER NEEDS TO BE FIXED AGAIN	3/16/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES
601	Work In Progress remove commodes and re-install when new floor covering is installed. portables 143-144	3/24/2005 Medium	Fred Appelzoller		Berino ES
576	Work In Progress vaccum need to be work on need cap for tire ....the red cap where belt gos.	3/23/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES
543	Work In Progress Need to emergency lighting fixtures as per pm 125544.	3/18/2005 Medium	Michael Mc Dermott Enrique Sotelo		Chaparral MS
551	Work In Progress 100, 200 & CAFETERIA - WIRING FOR REPLACEMENT MASTER COOLS.	3/18/2005 Medium	Jaime Gomez Enrique Sotelo		Chaparral MS
456	Work In Progress NEED FLUSH VALVE FOR COMMODE. ASAP.	3/16/2005 Medium	Vickie Reed Fred Appelzoller	Restroom (Boys)	Chaparral MS 100 wing (faculty)
415	Work In Progress URINAL NEED TO BE REPAIRED.	3/15/2005 Medium	Vickie Reed Fred Appelzoller	Restroom (Boys)	Chaparral MS MAIN HALLWAY
248	Work In Progress Need to replace gate valve that supplies pond.	3/10/2005 Medium	Vickie Reed Fred Appelzoller		Chaparral MS Pond area
210	Work In Progress need golfer traps	3/9/2005 Medium	David Acosta Ruben Ronquillo		Desert Pride
361	Work In Progress 2nd building. Please see Mr.Y and install a gutter where needed.	3/14/2005 Medium	Michael Munoz Danny Miranda		Desert Pride
360	Work In Progress PLEASE REPAIR PARKING LOT SECURITY LIGHT FIXTURE LOCATED IN THE PARKING LOT ENTRANCE/EXIT GATE.	3/14/2005 Medium	Johnny Acuna Enrique Sotelo		Desert Trail Intermediate
545	Work In Progress I HAVE A BROKEN VACCUM CLEANER	3/18/2005 Medium	Salvador Gonzalez Jimmy Carbajal		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
668	Work In Progress BROKEN: MAIN ELECTRICAL PVC LINE UNDERNEATH PORTABLE #408.	3/29/2005 Medium	Johnny Acuna Enrique Sotelo		Desert Trail Intermediate
231	Work In Progress need a couple of (chicago faucets) gaskets for custodial closet sink faucets. Thank You.....	3/10/2005 Medium	Johnny Acuna Fred Appelzoller		Desert Trail Intermediate
192	Work In Progress Garbage Disposal - Shakes alot and water is coming out from the bottom.	3/8/2005 Medium	Jacqueline Aguilar Danny Orozco		Desert Trail Intermediate Cafeteria
212	Work In Progress As per Manny Prospero & Danny Miranda- The new bathrooms - partions in both women & men's need to be replaced. (A-Wing)	3/9/2005 3/18/2005 Medium	Mary Garcia Danny Miranda	Restroom (Boys)	GAC
144	Work In Progress IN A-WING SPECIAL ED, ACROSS COMPUTER LAB; ROOMS HAVE NO COOLING AND HEATING. NEED TO TALK W/SYLIVIA MORENO.	3/8/2005 Medium	Mary Garcia Jose Ambriz	Office	GAC
408	Work In Progress Please have Manny Lozoya make the following name plates. See if we can have them for March 24th, if not then no later than April 14th.  Gregg Martinez  Dino Anastasia	3/15/2005 Medium	Hector Lozoya		GAC Cruz Drake
446	Work In Progress Rm 112-Have a HJ5 key made for key box.	3/16/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
451	Work In Progress Requested by Ms. Vermillion Rm 754 Barracks- Have file and storage cabinets re-keyed.	3/16/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
447	Work In Progress Requested by Mr. D. Martinez Rm 227C North Building-Replace windows in the Assistant Principal's Office. The windows that are there currently are painted shut.	3/16/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
450	Work In Progress Requested by Mr. D. Martinez main hallway in North Building-Move the snack machines from the main hallway to the shaded area outside, once the electrical outlets have been placed.	3/16/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
445	Work In Progress Rm 158 Concession Stand-need to connect power to new exhaust fan.	3/16/2005 Medium	Velia Alarcon Carlos Castillo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
448	Work In Progress Requested by Mr. D. Martinez Outside of North Building-Have electrical outlets placed outside the North Building in the shaded area for the candy/snack machines.	3/16/2005 Medium	Velia Alarcon Carlos Castillo		Gadsden HS
314	Work In Progress 3rd Request for Welder power cord and power end connections.	3/11/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
315	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop-Install exhaust system (hook up pipe, tubes, etc.) for Jointer/Planer	3/11/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
316	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop-1. Install heavier electric circuit for operation of drum sander. 2. Re-route machine wiring (belt/disc., sander, etc.) through safety kill switch.	3/11/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
321	Work In Progress Requested by Mr. J. Gonzales Rm 300 Academic Building-No power on south wall of classroom.	3/11/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
337	Work In Progress Coke machines by Academic Building, Cafeteria, and Auto Shop no power to Coke machines. Mario checked out the problem, they seem to be working correctly now.	3/11/2005 Medium	Velia Alarcon Carlos Castillo		Gadsden HS
653	Work In Progress NEED TO REMOVE AND REINSTALL SAFETY SWITCH BOXES FOR E/COOLER AT WEIGHT ROOM AND ACADEMIC BLDG SO WE CAN PUT NEW WET SIDE	3/29/2005 Medium	Mario Apodaca Carlos Castillo		Gadsden HS
654	Work In Progress NEED A NEW SWITCH W/PILOT LIGHT FOR WALK IN COOLER ASAP	3/29/2005 Medium	Mario Apodaca Carlos Castillo		Gadsden HS
689	Work In Progress Classrooms above Varsity Gym-Due to the power outage a few weeks ago, several outlet have no electricity.	3/30/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
652	Work In Progress NEED TO ORDER THE WET SIED FOR E/COOLER AT ACADEMIC BLDG W/NEW COOLING MEDIA	3/29/2005 Medium	Mario Apodaca Jose Ambriz		Gadsden HS
615	Work In Progress I have an Advance burnisher #1178815 that has a broken handle.	3/24/2005 Medium	Jesus Estrada Jimmy Carbajal		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
190	Work In Progress Main Bldg Room 109 - Dead air not working.	3/8/2005 Medium	Jose Ambriz	Classroom	Gadsden HS 109
178	Work In Progress Requested by Ms. M. Gonzalez, Rm 140 Old English Building-The window on the far left side will not stay open. We have to hold it up with a book. Mario looked at it and he states that the Window Company needs to come in and fix all windows in building	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
179	Work In Progress Requested by Ms. M. Gonzalez, Rm 140 Old English Building-Third Request-The blinds in my room are broken and do not work properly. This will help keep the sun out in the afternoon when the roon gets "very hot". Mario took a look at them, class will need 4 set of blinds measurements 44 X 90	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
185	Work In Progress Requested by Mr. Martin, Rm 551 Wood Shop-Broken Window	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
174	Work In Progress check electrical systems after poweroutage	3/8/2005 3/16/2005 Emergency	Carlos Castillo		Gadsden HS
182	Work In Progress North Bldg Room 328 Pam Holguin - need to check outlet that comes from west wall where there is no electricity.	3/8/2005 Medium	Carlos Castillo	Classroom	Gadsden HS 328
181	Work In Progress Requested by Ms. Lam, Rm 104 Main Building-A heavy duty doorstop for the south door to help the air flow. Classroom does not have windows that can be opened.	3/8/2005 Medium	Velia Alarcon Danny Miranda	Classroom	Gadsden HS
147	Work In Progress Rm 112-varnish new door  waiting on materials	3/8/2005 Medium	Fernando Moncayo Fernando Moncayo		Gadsden HS
186	Work In Progress Requested by Mr. Whitener Rm Ag. Shop- 3 sets of keys made of HK4 (Store Room)	3/8/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
134	Work In Progress NEED TO REWELD TRAY RAILING AT LINE #2	3/7/2005 Medium	Mario Apodaca Danny Orozco	Cafeteria	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
107	Work In Progress need to varnish 4 new doors in rooms #109,134,147,1542	3/7/2005 Medium	Danny Miranda Fernando Moncayo		Gadsden HS
133	Work In Progress NEED NEW STAIR VINYL STRIP FOR MAIN GOING UP TO OLD/ENG	3/7/2005 Medium	Mario Apodaca Michael Munoz	Stairway	Gadsden HS
317	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop- Install mirror on office wall, next to bathroom door and wash/clean-up station (between 554e and 554d)	3/11/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
261	Work In Progress NEED NEW WOOD DOOR AT OLD ENG BLDG ROOM #140,141,135,134,132,128,129,153,150,148.	3/10/2005 Medium	Mario Apodaca Danny Miranda	Classroom	Gadsden HS
263	Work In Progress NEED NEW WOOD DOOR AT N-BLDG AT ROOM # 224,230,211,232,233	3/10/2005 Medium	Mario Apodaca Danny Miranda		Gadsden HS
264	Work In Progress NEED A METAL DOOR FOR BOY RESTROOM AT N-BLDG - ONE DOOR	3/10/2005 Medium	Mario Apodaca Danny Miranda	Restroom (Boys)	Gadsden HS
345	Work In Progress The gate on the south side of the school was hit over the weekend. We're unable to close gate, we need this repaired as soon as possible.	3/14/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
332	Work In Progress DOOR AT ACADEMIC BLDG NEED TO BE FIX HINGES ARE LOSS FRAM BY ROOM 344	3/11/2005 Medium	Mario Apodaca Danny Miranda	Office	Gadsden HS
333	Work In Progress NEED NEW DOOR AT MAIN BLDG GOING OUT TO COMPUTER LAB WEST WING	3/11/2005 Medium	Mario Apodaca Danny Miranda	Hallway/Corridor	Gadsden HS
318	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop- Repair/replace toilet flush mechanism in 554 bathroom.	3/11/2005 Medium	Velia Alarcon David Villalobos	Classroom	Gadsden HS
322	Work In Progress Requested by Luis Saucedo-Weight Room, room # 502 One of the sink faucets is broken.	3/11/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS

3/30/2005 9:50:46 AM

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
354	Work In Progress Need to installing emerg. lights in hallways and restrooms girls and boys as per pm 125602.	3/14/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
312	Work In Progress Need to have a metal frame to cover for new window just installed.	3/11/2005 Medium	Rudy Arreola Danny Miranda	Office	Gadsden MS
266	Work In Progress washing machine out of order  Teresa Portillo - SNP Manager (505) 882-2824	3/10/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Gadsden MS
326	Work In Progress We are having a problem with students in the cafeteria after hours we need to have dead bolts installed so we can secure cafeteria.	3/11/2005 Medium	Rudy Arreola Margret Villalobos	Cafeteria	Gadsden MS
207	Work In Progress need both doors on portable #500 repaired	3/9/2005 Medium	Dana Hamel Danny Miranda	Classroom	Gadsden MS
269	Work In Progress Broken window need to be replaced this window was replaced about 1 week ago and its broken again. 31 x 76 As per Mike Munoz cove it with a board, this window was replace on 2/28/05.	3/10/2005 Medium	Rudy Arreola Ruben Ronquillo	Hallway/Corridor	Gadsden MS
240	Work In Progress SMALL GATE BY THE CANAL NEEDS TO BE PAD LOCKED.	3/10/2005 Medium	Juliet Parra Hector Lozoya	Athletic Field	Gadsden MS
159	Work In Progress Main Bldg Boys RR - Lock is not opening (Boys stuck in restroom).	3/8/2005 Medium	Hector Lozoya	Restroom (Boys)	Gadsden MS
117	Work In Progress Softball Field Concession Stand need to run power to it.	3/7/2005 Medium	Mario Apodaca Carlos Castillo	Athletic Field	Gadsden MS
600	Work In Progress need new breakers to be installed on wwp.	3/24/2005 Medium	Michael Munoz Ricardo Jacquez		Gadsden MS
686	Work In Progress Some of the sprinklers in the front of campus are watering on to the street need to them adjusted or replaced.	3/30/2005 Medium	Rudy Arreola Lorenzo Hernandez		Gadsden MS
657	Work In Progress the door is cracked/broken. The teacher must lift the door to close it properly. Room 112 B Wing	3/29/2005 Medium	Dana Hamel Danny Miranda	Classroom	Gadsden MS
407	Work In Progress Complete the molding/trim around the new window in the rear office A wing	3/15/2005 Medium	Dana Hamel Rudy Arreola	Office	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
688	Work In Progress need one new vacuum cleaner	3/30/2005 Medium	Armando Diaz Jimmy Carbajal		La Mesa ES
644	Work In Progress REQUESTING 1 NEW VACUUM CLEANER	3/29/2005 Medium	Armando Diaz Jimmy Carbajal		La Mesa ES
525	Work In Progress 600 Pounds of fertilizer is requested for the playground area.	3/18/2005 Medium	Eddie Baeza Lorenzo Hernandez		La Union ES
413	Work In Progress Lithonia emergency lights at main bldg. need batteries or replacement,(2).	3/15/2005 Medium	Eddie Baeza Carlos Castillo		La Union ES
166	Work In Progress A motor starter coil is requested for the boiler pump at new addition	3/8/2005 Medium	Eddie Baeza Jose Ambriz		La Union ES
164	Work In Progress need tractor&scraper to clean west pine tree-line/also rock wall sand	3/8/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
163	Work In Progress side walk by front entrance has buckled and lifted/safety hazard/redo portion of sidewalk. 1395 wo	3/8/2005 Medium	Danny Vega Michael Munoz		Loma Linda ES
180	Work In Progress need all classrooms sprayed // kitchen/restrooms/nurses office/library/front offices Waiting on Purchase Order.	3/8/2005 Medium	Danny Vega Margret Villalobos		Loma Linda ES
290	Work In Progress Vandalism report/truck window case#2005-02110	3/11/2005 Medium	Danny Vega Pete Flores		Loma Linda ES
311	Work In Progress locks in Mr. Ramos windows are broben and need to be replaced. also the window on south end of room could use new blinds	3/11/2005 Medium	Grace Alvarado Ruben Ronquillo		Loma Linda ES
352	Work In Progress UNABLE TO LOCK ROOM	3/14/2005 Medium	Grace Alvarado Hector Lozoya	Classroom	Loma Linda ES 114
452	Work In Progress DISTRICT ART SHOW SETUP AT GADSDEN MIDDLE SCHOOL, PUT UP IS APRIL 14, 2005 AT 8:30 AM TAKE DOWN IS APRIL 18, 2005 AT 10:00 AM	3/16/2005 Medium	Grace Alvarado Danny Vega		Loma Linda ES
490	Work In Progress need tractor to clean-up walk-in paths by north fence line/also east fence line	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
491	Work In Progress need fill-dirt on baseball diamonds/puddling water	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
492	Work In Progress need to re-do borders around playground equipment/plus remove sand from rockwall	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
493	Work In Progress need tractor to level off dirt in library courtyard	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
494	Work In Progress need tractor to level off rain erosion in bus parking run-off circle/eastside	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
617	Work In Progress broken 1/2 in. insulated window 28 1/4 x 29 1/2 also sw exit door 47 3/4 x 29 3/4 clear safety glass case#05-02473	3/24/2005 Medium	Danny Vega Ruben Ronquillo	Classroom	Loma Linda ES east wing/rm202
685	Work In Progress need to fix two vacuum cleaners	3/30/2005 Medium	Ruben Solis Jimmy Carbajal		Mesquite ES
506	Work In Progress rick , need grease traps secured w/ locks safety issue.	3/17/2005 Medium	Romauldo Apodaca Ricardo Jacquez		Mesquite ES
275	Work In Progress hot water return leaking in solis rm. 2nd grade wing.	3/10/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES
237	Work In Progress need 25 bags fertilizer.	3/10/2005 Medium	Romauldo Apodaca Lorenzo Hernandez		Mesquite ES
238	Work In Progress need to replace broken glass size is 23 1/2 x 23 3/4 clear safety. thanx.	3/10/2005 Medium	Romauldo Apodaca Ruben Ronquillo		Mesquite ES
274	Work In Progress need 5 4x6 peg boards,20 2x4x8 studs.to make stands for art show. the old ones are to damaged .attn. ruben ronquillo.	3/10/2005 Medium	Romauldo Apodaca Ruben Ronquillo		Mesquite ES
152	Work In Progress Food Service Warehouse - Loading Dock Area dirt needs to be removed.	3/8/2005 Medium	Lorenzo Hernandez		Physical Plant Complex
578	Work In Progress need to repair restroom in maint. office	3/23/2005 Medium	Danny Miranda Danny Miranda		Physical Plant Complex
364	Work In Progress Please paint new dry wall that was installed.	3/14/2005 Medium	Michael Munoz Joe Ramirez		Physical Plant Complex
353	Work In Progress Need to installing emerg. lights as per pm 125559.	3/14/2005 Medium	Rudy Arreola Enrique Sotelo		Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
338	Work In Progress MR CARLOS CASTILLO WILL NEED TO REPLACE LIGHT COVERS IN PORTABLE BROKEN AND SOME IN NEW WING NEED TO COME OVER SO THAT YOU WILL KNOW WHAT KIND TO GET THANK YOU SIR	3/11/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
418	Work In Progress JOSE AMBRIZ WILL NEED COVERS FOR AC UNITS 42X18 WILL NEED 6 OLD ONES RUSTED OUT THANK YOU SIR	3/15/2005 Medium	Adan Duran Jose Ambriz		Riverside ES
123	Work In Progress Mr. Valtierra, Principal RS, is requesting new carpet/flooring in Rm#36.	3/7/2005 3/2/2005 Medium	Miguel Aguilar Michael Munoz	Classroom	Riverside ES
124	Work In Progress As per School Pricipal, Need a truck load of 3/4 inch rock for spreading in front of portable. Need it ASAP. Thank You!	3/7/2005 3/2/2005 Medium	Lorenzo Solis Lorenzo Hernandez		San Miguel ES
146	Work In Progress "Please sent one of you employees to assist me with fixing 9 broken sprinklers, ASAP need to start watering grass. Please bring the following. Tees 1 1/2 inch to 1inch screw in. niples 1 inch 12 and 8 inch long. easy fix 1 1/2 inch. "	3/8/2005 Medium	Lorenzo Solis Lorenzo Hernandez		San Miguel ES
214	Work In Progress Please replace nonlocking door knob with locking one. Mrs. Avalos portable#45.	3/9/2005 Medium	Lorenzo Solis Hector Lozoya		San Miguel ES
216	Work In Progress Replaced falling apart door knob with new one on entrance door in cafeteria.	3/9/2005 Medium	Lorenzo Solis Hector Lozoya		San Miguel ES
454	Work In Progress ATT. CALI CASTILLO. CALI, NEED FOR YOU TO FOLLOW UP ON WK. OR. 124323. THANKS. NEED FOR YOU TO COME CHECK A COUPLE OF LIGHT FIXTURES THAT I AM HAVING TROUBLE WITH.	3/16/2005 Medium	Gerardo Marquez Carlos Castillo		Santa Teresa ES
651	Work In Progress LOCKSET IN NURSES RR. SEEMS TO BE INSTALLED BACKWARDS. LATCH LOCKS ON THE INSIDE , BUT DOES NOT LOCK ON THE OUTSIDE. NEED FOR APCO TO CORRECT THE PROBLEM.	3/29/2005 Medium	Gerardo Marquez Hector Lozoya		Santa Teresa ES nurses restroom

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
453	Work In Progress ATT. ANGEL GONZALEZ. ANGEL I NEED FOR YOU TO SERVICE TRUCK 107.WOULD YOU LET ME KNOW WHEN YOU CAN FIT IT IN TO YOUR SCHEDULE. THANKS.	3/16/2005 Medium	Gerardo Marquez Angel Gonzales		Santa Teresa ES
455	Work In Progress ANGEL. GONZALEZ. ANGEL COULD YOU BRING ME THE BOB CAT WITH THE BUCKET AND ALSO THE SWEEPER . IF YOU COULD BRING IT TO ME ON FRIDAY THAT WOULD BE GREAT.	3/16/2005 Medium	Gerardo Marquez Angel Gonzales		Santa Teresa ES
656	Work In Progress NEED SIX PAIRS OF LEATHER MEDIUM GLOVES	3/29/2005 Medium	Luis Murillo Ruben Ronquillo		Santa Teresa HS
449	Work In Progress MS. HILL SHE HAS A PROBLEM WITH CUCARACHAS AND GRILLOS ON CLASS ROOM 312 AT ENGLISH WING AREA	3/16/2005 Medium	Joel Herrera Margret Villalobos		Santa Teresa HS
444	Work In Progress RUBEN RONQUILLO I NNED REPLACE WINDOW'S SCREENS ON CLASS ROOM 308 AT ENGLISH WING SIZE 30 3/4 X 36 1/2 INCHES. THANK YOU RUBEN...	3/16/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
403	Work In Progress NEED DAY CARE FUMIGATED FOR BUGS.	3/15/2005 Medium	Arturo Nunez Margret Villalobos	Classroom	Santa Teresa HS Daycare
404	Work In Progress NEED FOODS LAB. SPRAYED FOR BUGS, COAROCHEs.	3/15/2005 Medium	Arturo Nunez Margret Villalobos		Santa Teresa HS
405	Work In Progress NEED T-8 LIGHT BULBS 3 CASES EA.	3/15/2005 Medium	Arturo Nunez Carlos Castillo		Santa Teresa HS
295	Work In Progress MIKE MUNOZ WE NEED REPAIR OVERHEAD DOORS AT VOCATIONAL BUILDING CLASS ROOMS THANK YOU... MIKE	3/11/2005 Medium	Joel Herrera Danny Miranda		Santa Teresa HS
406	Work In Progress NEED TO HAVE MOP SINK FAUCETS AT KITCHEN REPLACED, WE HAVE A WATER LEAK.	3/15/2005 Medium	Arturo Nunez David Villalobos		Santa Teresa HS
151	Work In Progress English Wing Hallway & Office - Need to replace damaged wire from panel box to swt box. To wire circuit properly and safely a/s/a/p	3/8/2005 Emergency	Carlos Castillo	Hallway/Corridor	Santa Teresa HS
341	Work In Progress BROKEN DOOR GLASS AT V.O.C BUILDING SIZE 23 3/4 X 23 1/4 WIRE GLASS	3/14/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To</b>	<b>Area Type</b>	<b>Location Area Number</b>
348	Work In Progress BOTH MIRROR FROM BOYS BATH ROOM ARE FADED THEY NEED TO BE REPLACE IN THE ENGLISH WING THANK YOU.	3/14/2005 Medium	Luis Murillo Ruben Ronquillo		Santa Teresa HS
173	Work In Progress Rm 8 N.bldg- Nurses office is going to be remodeled and is going to need new electrical outlets for counter areas and office area.	3/8/2005 Medium	Jaime Mijarez Carlos Castillo		Santa Teresa MS
298	Work In Progress Gym - Replace westside doors.	3/11/2005 Medium	Jaime Mijarez Danny Miranda		Santa Teresa MS
542	Work In Progress Choir Rm . Outside metal door is damaged and old used to belong to the demolished mechanical rm. Door is to big and heavy for students to be opening every day. Would like to have it replaced to a new and smaller door. Approved by principal.	3/18/2005 Medium	Jaime Mijarez Danny Miranda		Santa Teresa MS
497	Work In Progress S.Bldg parking light post glass cover opened and is just hanging. I need bucket truck and operater to get up there.	3/17/2005 Medium	Jaime Mijarez Carlos Castillo		Santa Teresa MS
488	Work In Progress NEED TO REPAIR WINDOWS @ OPERATORS	3/17/2005 Medium	Danny Miranda Danny Miranda		Sunland Park ES
546	Work In Progress Room 28 - Need to replace door glass on outside door.	3/18/2005 Medium	Sebastian Diaz Ruben Ronquillo	Classroom	Sunland Park ES
138	Work In Progress NEED A SNAKE TO UNCLOG A TOILET THANK YOU 1-I USED THE FLANCH TO UNCLOG. BUT I NEED THE SNAKE TO UNCLOG IT.	3/7/2005 Medium	Sebastian Diaz David Villalobos	Restroom (Boys)	Sunland Park ES RESTROOM BOYS