

287- Work In Progress Work Orders (Fiscal Year)

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
805	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Ruben Solis		Alma Del Valle Daycare
882	Work In Progress freezer at 20 degrees Rebecca Saenz - SNP Manager (505) 882-3507	4/6/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Anthony ES
766	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Carlos Lujan		Anthony ES
1320	Work In Progress pick up medicine cadinet at sths over to anthony elementary nurse	4/21/2005 Medium	Hector Villalobos Hector Villalobos		Anthony ES
1321	Work In Progress hook up electrical power to storage outside	4/21/2005 Medium	Hector Villalobos Enrique Sotelo	Athletic Field	Anthony ES
1324	Work In Progress need two 4l 580 belts and one 4l570	4/21/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
1038	Work In Progress replace a/c unit in cafeteria 63 a/c unit	4/11/2005 Medium	Hector Villalobos Jaime Gomez	Cafeteria	Anthony ES
1039	Work In Progress primary office to replace 45 sidedraft master cool	4/11/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
764	Work In Progress rooms 3 4 5 6 7 8 emergency windows do not open	4/1/2005 Medium	Hector Villalobos Ruben Ronquillo	Classroom	Anthony ES
823	Work In Progress ALL windows in old primary blg do not open	4/4/2005 Medium	Hector Villalobos Ruben Ronquillo	Classroom	Anthony ES
489	Work In Progress replace long gate with half swing and half slide. gate 3 and 1. Had a injury with a custodial	3/17/2005 Medium	Hector Villalobos Michael Munoz		Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
623	Work In Progress 3/18/05 1. check boilers 1.5 go to shop put gas pick up supplies 5.5 pruning trees by football field	3/24/2005 Medium	Hector Villalobos Hector Villalobos		Anthony ES
820	Work In Progress Pump house tank has a big leak upper primary	4/4/2005 Medium	Hector Villalobos Ricardo Jacquez	Athletic Field	Anthony ES
331	Work In Progress need 8 sheet metal plates 20x20	3/11/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
228	Work In Progress pt 217 replace heating and cooling	3/10/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
226	Work In Progress need to fill in sidewalk with crusher fine	3/10/2005 Medium	Hector Villalobos Lorenzo Hernandez	Athletic Field	Anthony ES
227	Work In Progress need tractor to scrape off weeds	3/10/2005 Medium	Hector Villalobos Lorenzo Hernandez	Athletic Field	Anthony ES
205	Work In Progress Annex Bldg Girls rr - Broken window 45 1/2 x 14 3/4.	3/9/2005 Medium	Hector Villalobos Ruben Ronquillo	Restroom (Girls)	Anthony ES Annex Bldg
103	Work In Progress boiler room we have a leak in pipe line	3/7/2005 Medium	Hector Villalobos Jaime Gomez	Mechanical Room	Anthony ES
102	Work In Progress need to remove dirt with tractor by dumpster	3/7/2005 Medium	Hector Villalobos Lorenzo Hernandez	Cafeteria	Anthony ES
911	Work In Progress Lucky,Joe WE need to find out which lockers are to be moved and re-locate to GMS. Rudy will assist.	4/6/2005 4/12/2005 Medium	Michael Munoz Hector Villalobos		Anthony ES
1500	Work In Progress Irrigation Wells - Need Grounds to pick up old well column piping and dispose of it properly.	4/28/2005 Medium	Raul Sanchez Lorenzo Hernandez		Anthony ES
1239	Work In Progress 4/19/05 NEED TO REPLACE A/C IN KITCHEN AREA AND LIBRARY	4/19/2005 Medium	Ramiro Holguin Jaime Gomez		Berino ES
203	Work In Progress NEED PLAYGROUND FERTELIZES	3/9/2005 Medium	Ramiro Holguin Lorenzo Hernandez		Berino ES
846	Work In Progress JAIME GOMEZ NEED TO REPLACE FOUR A/C UNITS WESTWING 131,128 ON EASTWING 103,107 ALL 6500	4/5/2005 Medium	Ramiro Holguin Jaime Gomez		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
720	Work In Progress PLAYGROUND NEEDS TO BE AERATED	3/31/2005 Medium	Ramiro Holguin Lorenzo Hernandez		Berino ES
576	Work In Progress vaccum need to be work on need cap for tirethe red cap where belt gos.	3/23/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES
441	Work In Progress CHARGER NEEDS TO BE FIXED AGAIN	3/16/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES
1523	Work In Progress vaccum tire fell off again	4/29/2005 Medium	Jimmy Cortez Jimmy Carbajal		Berino ES
769	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Jimmy Cortez		Berino ES
771	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Daniel Ramirez		Chaparral ES
1369	Work In Progress Automobile ran thru about 70ft of fence and 1 gate. Fence is located between DT and CHE Northend of Mc Combs. Case # 2005-03486 Deputy Williams	4/22/2005 Medium	Juan Vargas Michael Munoz		Chaparral ES
1422	Work In Progress 04/26/05/jaime gomes library need 3 new master cools	4/26/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
1075	Work In Progress 04/12/05 enrique sotelo main bldg. need new timer for the outside lites	4/12/2005 Medium	Juan Vargas Enrique Sotelo		Chaparral ES
1080	Work In Progress START ON WOOD FLOORS E-WING	4/12/2005 Medium	Danny Miranda Danny Miranda		Chaparral ES
1407	Work In Progress SMALL LEAK UNDER DISHWASHER. ALICE ESCALANTE SNP MGR 824-0048	4/25/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1129	Work In Progress Keys - Need to issue keys to Joe Ramirez transferring from PPD to CHMID. Mike Mc Dermott will be turning in his keys. (April 29, 2005 - Payday)	4/14/2005 Medium	Michael Munoz Hector Lozoya		Chaparral MS
551	Work In Progress 100, 200 & CAFETERIA - WIRING FOR REPLACEMENT MASTER COOLS.	3/18/2005 Medium	Jaime Gomez Enrique Sotelo		Chaparral MS
1314	Work In Progress ONE OF OUR BURNISHER IS NOT WORKING RIGHT.IT PULLS TO ONE SIDE.	4/21/2005 Medium	Robert Gonzalez Jimmy Carbajal		Chaparral MS
1316	Work In Progress ONE OF OUR SHOWER SCRUBBERS HAD A HARD TIME WORKING LAST SUMMER WHEN WE WERE USING A GRIT SCREENS IN THE GYM. MAY BE THE BRUSHES	4/21/2005 Medium	Robert Gonzalez Jimmy Carbajal		Chaparral MS
1020	Work In Progress WEST DOOR TO FOOTBALL LOCKER ROOM NEED TO BE REPAIRED.	4/11/2005 Medium	Vickie Reed Danny Miranda		Chaparral MS FOOTBALL LOCKER ROOM
724	Work In Progress REPAIR BROKEN 3" WATER LINE ON WEST SIDE OF SCHOOL.	3/31/2005 Medium	Vickie Reed Lorenzo Hernandez		Chaparral MS west side of school
456	Work In Progress NEED FLUSH VALVE FOR COMMODE. ASAP.	3/16/2005 Medium	Vickie Reed Fred Appenzoller	Restroom (Boys)	Chaparral MS 100 wing (faculty)
772	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Robert Gonzalez		Chaparral MS
1454	Work In Progress please cut weed in and around pressure tanks.	4/27/2005 Medium	Ricardo Jacquez		Chaparral MS
773	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo David Acosta		Desert Pride

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1108	Work In Progress need to replace the pump for a toilet (front office)	4/13/2005 Medium	David Acosta David Villalobos	Office	Desert Pride
1388	Work In Progress new door that was installed is lock on the inside. need to have door open. (asap)	4/25/2005 Medium	David Acosta Hector Lozoya	Office	Desert Pride
1410	Work In Progress need seven locks for doors to front offices. (in counslor, social workers area.)	4/25/2005 Medium	David Acosta Hector Lozoya	Office	Desert Pride
1391	Work In Progress molding on the new door frame is coming unglued	4/25/2005 Medium	David Acosta Danny Miranda	Office	Desert Pride
210	Work In Progress need golfer traps	3/9/2005 Medium	David Acosta Ruben Ronquillo		Desert Pride
1380	Work In Progress need to paint new frame @ varnish door to lounge	4/25/2005 Medium	Danny Miranda David Acosta		Desert Pride
1068	Work In Progress NEED TO PUT IN GUTTER SECOND BUILDING TWO DOORS TOTAL	4/12/2005 Medium	Danny Miranda Danny Miranda		Desert Pride
361	Work In Progress 2nd building. Please see Mr.Y and install a gutter where needed.	3/14/2005 Medium	Michael Munoz Danny Miranda		Desert Pride
1279	Work In Progress BURNISHING MACHINE IS BROKEN	4/20/2005 Medium	Salvador Gonzalez Jimmy Carbajal		Desert Trail Intermediate
1280	Work In Progress BACK PACK IS NOT WORKING WELL	4/20/2005 Medium	Salvador Gonzalez Jimmy Carbajal		Desert Trail Intermediate
1282	Work In Progress WETBACK IS NOT WORKIN WELL	4/20/2005 Medium	Salvador Gonzalez Jimmy Carbajal		Desert Trail Intermediate
545	Work In Progress I HAVE A BROKEN VACCUM CLEANER	3/18/2005 Medium	Salvador Gonzalez Jimmy Carbajal		Desert Trail Intermediate
1298	Work In Progress TEACHER IN ROOM #205. MR. HOLMES IS REQUESTING TO REPLACE COMODE TO A FLUSHMATE COMODE.	4/21/2005 Medium	Johnny Acuna Fred Appelzoller		Desert Trail Intermediate
1476	Work In Progress PORTABLE #403: EVAP. A/C, NEED (2) 3/4" HIGH RISE BEARINGS. THANK YOU !!!!	4/27/2005 Medium	Johnny Acuna Jaime Gomez		Desert Trail Intermediate
1211	Work In Progress need irrigation backflow preventer to be installed for irrigation to front trees. (irrigation line has been installed).	4/18/2005 Medium	Johnny Acuna Lorenzo Hernandez		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1192	Work In Progress RM. #112 GUTIERREZ . NEED TO FIX AND MAKE A KEY FOR FILING CABINET INSIDE CLASSROOM..THANK YOU.....	4/15/2005 Medium	Johnny Acuna Hector Lozoya		Desert Trail Intermediate
1041	Work In Progress NEED A HALL AND CLOSET NON-LOCKING DOOR SET FOR PORTABLE #412 INSIDE DOOR.	4/11/2005 Medium	Johnny Acuna Hector Lozoya		Desert Trail Intermediate
360	Work In Progress PLEASE REPAIR PARKING LOT SECURITY LIGHT FIXTURE LOCATED IN THE PARKING LOT ENTRANCE/EXIT GATE.	3/14/2005 Medium	Johnny Acuna Enrique Sotelo		Desert Trail Intermediate
192	Work In Progress Garbage Disposal - Shakes alot and water is coming out from the bottom.	3/8/2005 Medium	Jacqueline Aguilar Danny Orozco	Desert Trail Intermediate Cafeteria	
704	Work In Progress GLASS TO SERVING LINE IS CRACKED. PATRICIA CISNEROS 824-3822	3/30/2005 Medium	Jacqueline Aguilar Danny Orozco		Desert Trail Intermediate
774	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Salvador Gonzalez		Desert Trail Intermediate
888	Work In Progress DP 1020 monitoring data is due in this office before April 28,2005	4/6/2005 Scheduled	Ricardo Jacquez		Desert Trail Intermediate
1275	Work In Progress Please fabricate iron stand for new marquee.	4/20/2005 Medium	Angel Gonzales		Desert View ES
1276	Work In Progress please install fabricated iron supports for new marquee. Please see mike before installation.	4/20/2005 Medium	Lorenzo Hernandez		Desert View ES
1533	Work In Progress Please use auger and assist with installation of marquee.	4/29/2005 Medium	Lorenzo Hernandez		Desert View ES
1183	Work In Progress NEED TO REPLACE HOSE SPIGOTS IN PATIOS. LOOSING WATER PRESSURE AND HANDLES ARE BROKEN. NO HEAD CUSTODIAN AT SCHOOL SITE. IF YOU NEED ANY INFORMATION, CONTACT JIMMY CARBAJAL @ THE CUSTODIAL WAREHOUSE	4/15/2005 Medium	Aida Salcedo David Villalobos		Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
804	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Oscar Estrada		Desert View ES
1474	Work In Progress pat aguilar locksmith need anther lock for file cabinet #32	4/27/2005 Medium	Patricio Aguilar Hector Lozoya		Desert View ES
716	Work In Progress N. Roof - need to replace temp gauges. As per Boiler Inspector.	3/30/2005 Medium	Michael Munoz Jose Ambriz		Desert View ES
1212	Work In Progress NEED TO REPAIR A VACUUM	4/18/2005 Medium	Jimmy Carbajal Jimmy Carbajal		Desert View ES
740	Work In Progress MIKE, THE SCHOOL SIGN THAT MRS. YTURRALDE REQUESTED IT'S ALREADY AT THE WAREHOUSE. LARRY TOLD ME TO LET YOU KNOW SO YOU CAN PICK IT UP AND INSTALL IT. THANK YOU VERY MUCH FOR YOUR HELP! THANK YOU, MARGARET :)	3/31/2005 Medium	Margarita Terrazas Michael Munoz		Desert View ES
850	Work In Progress As per Manny Prospero: Needs weeds to be cut if can have ground come out to help.	4/5/2005 Medium	Mary Garcia Lorenzo Hernandez		GAC
144	Work In Progress IN A-WING SPECIAL ED, ACROSS COMPUTER LAB; ROOMS HAVE NO COOLING AND HEATING. NEED TO TALK W/SYLVIA MORENO.	3/8/2005 Medium	Mary Garcia Jose Ambriz	Office	GAC
1059	Work In Progress As per Manny Prospero, the Main Office Portable needs the old instalation replaced. (due to the dust and wind)	4/12/2005 Medium	Mary Garcia Manuel Prospero	Office	GAC Point-across the street
1021	Work In Progress As per Jose Ambriz, needs Cali to come in and check power in the A-Wing Offices and Conference Room #1, across from Computer Lab in order for him to install cooling & heating unit. Please refer back to work order # 1368.	4/11/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC
929	Work In Progress As per Rafa-mop holder needs to be replaced with a new mop holder. Old one does not hold items in place.	4/7/2005 Medium	Mary Garcia Jimmy Carbajal	Custodial	GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1457	Work In Progress As per Mr. Giovas - Need to replace locks and rekey to off-master. (Only 2 Keys)	4/27/2005 Medium	Mary Garcia Hector Lozoya	Cafeteria	GAC
1366	Work In Progress MS. BROWDER'S OFFICE-B WING, NEEDS FOR THERMASTATE TO BE WIRED. AS PER MANNY PROSPERO, CALI WAS ALREADY AWARE TO CONNECT WIRES, BUT HAS NOT BEEN DONE FOR OVER 1 YEAR.	4/22/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC
790	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Ralph Lara		GAC
791	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Jesus Estrada		Gadsden HS
1307	Work In Progress Replace damaged steamer contactor	4/21/2005 Medium	Carlos Castillo Carlos Castillo	Electrical Room	Gadsden HS
1067	Work In Progress G.H.S. NEED TO REMOVE SINK @ COUNTER TOP	4/12/2005 Medium	Danny Miranda Danny Miranda		Gadsden HS
1544	Work In Progress Please remove old sink an ice machine by 5-05-05 for new install	4/29/2005 Medium	David Villalobos		Gadsden HS
1548	Work In Progress please reomove sink, dishwasher and ice machine for new install.panther hut	4/29/2005 Medium	David Villalobos		Gadsden HS
182	Work In Progress North Bldg Room 328 Pam Holguin - need to check outlet that comes from west wall where there is no electricity.	3/8/2005 Medium	Carlos Castillo	Classroom	Gadsden HS 328
1232	Work In Progress PLease demo and cancell all plumbing as per Mr.Foster.	4/19/2005 Medium	David Villalobos		Gadsden HS
190	Work In Progress Main Bldg Room 109 - Dead air not working.	3/8/2005 Medium	Jose Ambriz	Classroom	Gadsden HS 109

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1329	Work In Progress Need assistance with electrical problems;There is no power on a/cs.After ckd them out I think the 3ph conntactor is bad thank you	4/21/2005 Medium	Fernando Moncayo Carlos Castillo	Custodial	Gadsden HS
1342	Work In Progress Refrig. air unit in room 611 at BUSINESS BLDG is not working	4/22/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
1094	Work In Progress Need an exhaust fan motor, for DAY CARE restroom no info in old motor, will match it with BROAN motor	4/13/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
1153	Work In Progress All restrooms and plumbing chases need to be sprayed to control roaches, thankyou!	4/14/2005 Medium	Fernando Moncayo Margret Villalobos	Restroom (Boys)	Gadsden HS
1097	Work In Progress Need to connect electrical power to new exhaust fan in COUNCELING CTR	4/13/2005 Medium	Fernando Moncayo Carlos Castillo		Gadsden HS
147	Work In Progress Rm 112-varnish new door waiting on materials	3/8/2005 Medium	Fernando Moncayo Fernando Moncayo		Gadsden HS
895	Work In Progress Need to order new fire extinguishers;10;10lb-5;5lb also need fire extinguisher locator stiker to identify extinguisher location asap please 100 stikers	4/6/2005 Medium	Fernando Moncayo Ruben Ronquillo		Gadsden HS
107	Work In Progress need to varnish 4 new doors in rooms #109,134,147,1542	3/7/2005 Medium	Danny Miranda Fernando Moncayo		Gadsden HS
816	Work In Progress REACH-IN REFRIGERATOR NOT WORKING.	4/4/2005 Medium	Danny Orozco Danny Orozco	Cafeteria	Gadsden HS
1354	Work In Progress need casters on tables fixed. I counted 14 that need replacement.	4/22/2005 Medium	Jesus Estrada Guillermo Hernandez	Cafeteria	Gadsden HS
615	Work In Progress I have an Advance burnisher #1178815 that has a broken handle.	3/24/2005 Medium	Jesus Estrada Jimmy Carbajal		Gadsden HS
1522	Work In Progress Need Grand Masters 6 & 7 for Bobby Aldaz.	4/29/2005 Medium	Lorenzo Hernandez Hector Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1393	Work In Progress BASEBALL & SOFTBALL DUGOUT AREA - NEED (3) HOLLOW METAL DOORS WITH HOLLOW METAL FRAMES (3'0" X 6'8") FOR STORAGE ROOMS.	4/25/2005 Medium	Lorenzo Hernandez Danny Miranda	Athletic Field	Gadsden HS
1394	Work In Progress GROUNDS SHOP - NEED TO RESTOCK FIRST AID KIT.	4/25/2005 Medium	Lorenzo Hernandez Ruben Ronquillo		Gadsden HS
134	Work In Progress NEED TO REWELD TRAY RAILING AT LINE #2	3/7/2005 Medium	Mario Apodaca Danny Orozco	Cafeteria	Gadsden HS
133	Work In Progress NEED NEW STAIR VINYL STRIP FOR MAIN GOING UP TO OLD/ENG	3/7/2005 Medium	Mario Apodaca Michael Munoz	Stairway	Gadsden HS
261	Work In Progress NEED NEW WOOD DOOR AT OLD ENG BLDG ROOM #140,141,135,134,132,128,129,153,150,148.	3/10/2005 Medium	Mario Apodaca Danny Miranda	Classroom	Gadsden HS
263	Work In Progress NEED NEW WOOD DOOR AT N-BLDG AT ROOM # 224,230,211,232,233	3/10/2005 Medium	Mario Apodaca Danny Miranda		Gadsden HS
264	Work In Progress NEED A METAL DOOR FOR BOY RESTROOM AT N-BLDG - ONE DOOR	3/10/2005 Medium	Mario Apodaca Danny Miranda	Restroom (Boys)	Gadsden HS
332	Work In Progress DOOR AT ACADEMIC BLDG NEED TO BE FIX HINGES ARE LOSS FRAM BY ROOM 344	3/11/2005 Medium	Mario Apodaca Danny Miranda	Office	Gadsden HS
333	Work In Progress NEED NEW DOOR AT MAIN BLDG GOING OUT TO COMPUTER LAB WEST WING	3/11/2005 Medium	Mario Apodaca Danny Miranda	Hallway/Corridor	Gadsden HS
652	Work In Progress NEED TO ORDER THE WET SIED FOR E/COOLER AT ACADEMIC BLDG W/NEW COOLING MEDIA	3/29/2005 Medium	Mario Apodaca Jose Ambriz		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
653	Work In Progress NEED TO REMOVE AND REINSTALL SAFETY SWITCH BOXES FOR E/COOLER AT WEIGHT ROOM AND ACADEMIC BLDG SO WE CAN PUT NEW WET SIDE	3/29/2005 Medium	Mario Apodaca Carlos Castillo		Gadsden HS
654	Work In Progress NEED A NEW SWITCH W/PILOT LIGHT FOR WALK IN COOLER ASAP	3/29/2005 Medium	Mario Apodaca Carlos Castillo		Gadsden HS
1483	Work In Progress NEED TO PUT NEW GLASS AT WOOD SHOP 69"X 49" AT TOOL ROOM	4/28/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
1501	Work In Progress NEED 2 # NEW SINKS AND FAUCETS FOR THE CONCESSION STAND	4/28/2005 Medium	Mario Apodaca David Villalobos		Gadsden HS
1204	Work In Progress NEED A OIL PRESSUREFOR AIR COMPRESSOR AT AG SHOP	4/15/2005 Medium	Mario Apodaca Jose Ambriz		Gadsden HS
898	Work In Progress BUS BLDG 611- REMOVE AND INSTALL COVEBASE. (Please call Mike before you start on this work order) - Thanks mkv	4/6/2005 Medium	Michael Munoz Mario Apodaca	Classroom	Gadsden HS
1498	Work In Progress Swimming Pool - Need an electrician (Mike Mc Dermott as per Mike) to install/connect new circulating pump and run conduit for new booster pump.	4/28/2005 Medium	Raul Sanchez Margret Villalobos		Gadsden HS
445	Work In Progress Rm 158 Concession Stand-need to connect power to new exhaust fan.	3/16/2005 Medium	Velia Alarcon Carlos Castillo		Gadsden HS
448	Work In Progress Requested by Mr. D. Martinez Outside of North Building-Have electrical outlets placed outside the North Building in the shaded area for the candy/snack machines.	3/16/2005 Medium	Velia Alarcon Carlos Castillo		Gadsden HS
450	Work In Progress Requested by Mr. D. Martinez main hallway in North Building-Move the snack machines from the main hallway to the shaded area outside, once the electrical outlets have been placed.	3/16/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
726	Work In Progress Requested by Mr. S. Alvarado, Rm 141 Old English Building-Room needs to be painted.	3/31/2005 Medium	Velia Alarcon Joe Ontiveros	Classroom	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
727	Work In Progress Requested by Mr. Haack, Rm 127 Main Building- Window was broken on 3/30/05.	3/31/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
689	Work In Progress Classrooms above Varsity Gym-Due to the power outage a few weeks ago, several outlet have no electricity.	3/30/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
893	Work In Progress Requested by Mr. Contaldo Rm 103-Paint outside of observatory using white oil-based paint.	4/6/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS
725	Work In Progress Requested by Mr. S. Alvarado, Rm 141 Old English building-Door is about ready to fall off it's hinges.	3/31/2005 Medium	Velia Alarcon Danny Miranda	Classroom	Gadsden HS
317	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop- Install mirror on office wall, next to bathroom door and wash/clean-up station (between 554e and 554d)	3/11/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
314	Work In Progress 3rd Request for Welder power cord and power end connections.	3/11/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
315	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop- Install exhaust system (hook up pipe, tubes, etc.) for Jointer/Planer	3/11/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
316	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop- 1. Install heavier electric circuit for operation of drum sander. 2. Re-route machine wiring (belt/disc., sander, etc.) through safety kill switch.	3/11/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
321	Work In Progress Requested by Mr. J. Gonzales Rm 300 Academic Building-No power on south wall of classroom.	3/11/2005 Medium	Velia Alarcon Carlos Castillo	Classroom	Gadsden HS
337	Work In Progress Coke machines by Academic Building, Cafeteria, and Auto Shop no power to Coke machines. Mario checked out the problem, they seem to be working correctly now.	3/11/2005 Medium	Velia Alarcon Carlos Castillo		Gadsden HS
447	Work In Progress Requested by Mr. D. Martinez Rm 227C North Building-Replace windows in the Assistant Principal's Office. The windows that are there currently are painted shut.	3/16/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
345	Work In Progress The gate on the south side of the school was hit over the weekend. We're unable to close gate, we need this repaired as soon as possible.	3/14/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS
178	Work In Progress Requested by Ms. M. Gonzalez, Rm 140 Old English Building-The window on the far left side will not stay open. We have to hold it up with a book. Mario looked at it and he states that the Window Company needs to come in and fix all windows in building	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
179	Work In Progress Requested by Ms. M. Gonzalez, Rm 140 Old English Building-Third Request-The blinds in my room are broken and do not work properly. This will help keep the sun out in the afternoon when the roon gets "very hot". Mario took a look at them, class will need 4 set of blinds measurements 44 X 90	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
185	Work In Progress Requested by Mr. Martin, Rm 551 Wood Shop-Broken Window	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
1490	Work In Progress Requested by Mr. Villa Rm. 510 Annex Building (Band Room)-Need replacement bulbs in main band room and office.	4/28/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
1486	Work In Progress Requested by Velia Alarcon Rm. 112 Main Building-We need 3 sets of the following keys made: D master, H master, M master, and N master.	4/28/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
1487	Work In Progress Requested by Mr. Fensch Rm. 334 Academic Building-Storage cabinet to the left inside the door, needs to be re-keyed.	4/28/2005 Medium	Velia Alarcon Hector Lozoya	Classroom	Gadsden HS
1489	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace broken ceiling tile and install plank roof over office and storeroom.	4/28/2005 Medium	Velia Alarcon Joe Ontiveros	Classroom	Gadsden HS
1524	Work In Progress Requested by Mr. Rios Varsity Gym-Key is stuck in cylinder. Cylinder is in Velia's office. (Outside door to Girls Locker Room)	4/29/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
1525	Work In Progress Requested by Maricruz Carrasco Rm. 343 Academic Building-Faculty restroom on south hallway cylinder came out, needs to be replaced.	4/29/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1526	Work In Progress Requested by Mrs. Pena Rm. 208 North Building- Clogged kitchen sink, 1st sink to the left as you enter from classroom.	4/29/2005 Medium	Velia Alarcon David Villalobos	Classroom	Gadsden HS
1527	Work In Progress Requested by Mr. A. Perez Rm. 550 Wood Shop Building-Paint entry door; in order to avoid tagging. Adjust gap between door.	4/29/2005 Medium	Velia Alarcon Joe Ontiveros		Gadsden HS
1488	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace broken glass, large broken glass panel separating tool room from shop area.	4/28/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
1425	Work In Progress Requested by Mr. Chambers Rm. 100 Mailroom- Change combination as soon as possible.	4/26/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
1426	Work In Progress Requested by Mr. Chambers Rm. 275d Library- Make 5 additional HG7 keys for Administrators. (Library Storage Room)	4/26/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
1159	Work In Progress Requested by Ms. M. Garcia Rm 752 Barracks- Blinds needed on one window (45 x 60). Fire hazard, covered with paper. Special Ed. classroom	4/14/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
1179	Work In Progress Requested by Velia Rm 113 & 114 Main Building (Front Office)-We need the windows replaced in the men and women bathrooms, we're unable to open or close windows properly.	4/15/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS PATIO
1019	Work In Progress Requested by Ms. Moreno Rm. 126 Main Building- Put blinds on the windows.	4/11/2005 Medium	Velia Alarcon Ruben Ronquillo	Classroom	Gadsden HS
963	Work In Progress Requested by Jesus Estrada Varsity Gym-Girls locker room, sink has been pulled off the wall.	4/8/2005 Medium	Velia Alarcon David Villalobos	Restroom (Girls)	Gadsden HS
1499	Work In Progress Irrigation Wells - Need Grounds to pick up old well column piping and dispose of it properly.	4/28/2005 Medium	Raul Sanchez Lorenzo Hernandez		Gadsden HS
1521	Work In Progress Water Tank - Replace switch for compressor.	4/29/2005 Medium	Ricardo Jacquez Enrique Sotelo		Gadsden MS
1101	Work In Progress We are going have a new student in a wheelchair the only concern is we need a walkway where the new fence was put up to connect to the side of the bandroom.	4/13/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1102	Work In Progress Some of the doors to the main entrance have a little step the wheelchair may not be able to go up (Concerned the student may flip forward).	4/13/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
1105	Work In Progress Sidewalk on eastside of annex bldg is to steep for wheelchair need sidewalk raised.	4/13/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
1465	Work In Progress We need metal frames around windows we several threw out the campus in main bldg. The moulding is missing.	4/27/2005 Medium	Rudy Arreola Ruben Ronquillo		Gadsden MS
1535	Work In Progress We have 5 broken windows on the west side of the MAIN GYM that need to be replaced.	4/29/2005 Medium	Rudy Arreola Ruben Ronquillo		Gadsden MS
354	Work In Progress Need to installing emerg. lights in hallways and restrooms girls and boys as per pm 125602.	3/14/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
686	Work In Progress Some of the sprinklers in the front of campus are watering on to the street need to them adjusted or replaced.	3/30/2005 Medium	Rudy Arreola Lorenzo Hernandez		Gadsden MS
851	Work In Progress Fence by the football feild is getting knocked down by students when they are running.	4/5/2005 Medium	Rudy Arreola Michael Munoz		Gadsden MS
852	Work In Progress We are having problems with mice in the gym area. Boys and girls lockerrooms and coaches offices. Faxed PO on 4/14/05 - mkv	4/5/2005 Medium	Rudy Arreola Margret Villalobos		Gadsden MS
326	Work In Progress We are having a problem with students in the cafeteria after hours we need to have dead bolts installed so we can secure cafeteria.	3/11/2005 Medium	Rudy Arreola Margret Villalobos	Cafeteria	Gadsden MS
269	Work In Progress Broken window need to be replaced this window was replaced about 1 week ago and its broken again. 31 x 76 As per Mike Munoz cove it with a board, this window was replace on 2/28/05.	3/10/2005 Medium	Rudy Arreola Ruben Ronquillo	Hallway/Corridor	Gadsden MS
117	Work In Progress Softball Field Concession Stand need to run power to it.	3/7/2005 Medium	Mario Apodaca Carlos Castillo	Athletic Field	Gadsden MS
600	Work In Progress need new breakers to be installed on wwp. pulled old breakers and install new breakers	3/24/2005 4/7/2005 Medium	Michael Munoz Ricardo Jacquez		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1429	Work In Progress B-Wing - Please paint new doors that were installed.	4/26/2005 Medium	Michael Munoz Rudy Arreola	Classroom	Gadsden MS
1520	Work In Progress please pick-up and secure fence that is on the south side of the footballfield behind mobile home.	4/29/2005 Medium	Michael Munoz Rudy Arreola	Athletic Field	Gadsden MS
1537	Work In Progress please cut weeds and in and around bus turn around.	4/29/2005 Medium	Rudy Arreola		Gadsden MS
266	Work In Progress washing machine out of order Teresa Portillo - SNP Manager (505) 882-2824	3/10/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Gadsden MS
207	Work In Progress need both doors on portable #500 repaired	3/9/2005 Medium	Dana Hamel Danny Miranda	Classroom	Gadsden MS
407	Work In Progress Complete the molding/trim around the new window in the rear office A wing	3/15/2005 Medium	Dana Hamel Rudy Arreola	Office	Gadsden MS
657	Work In Progress the door is cracked/broken. The teacher must lift the door to close it properly. Room 112 B Wing	3/29/2005 Medium	Dana Hamel Danny Miranda	Classroom	Gadsden MS
1463	Work In Progress heater keeps going out in office	4/27/2005 Medium	Dana Hamel Jaime Gomez	Cafeteria	Gadsden MS
1064	Work In Progress Would like to take out an office wall and turn the old tech offices into one classroom.	4/12/2005 Medium	Dana Hamel Michael Munoz	Office	Gadsden MS
792	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Juan Acosta		Gadsden MS
793	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Armando Diaz		La Mesa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1310	Work In Progress need to repair vacumm cleaner asap	4/21/2005 Medium	Armando Diaz Jimmy Carbajal		La Mesa ES
1136	Work In Progress need x tractor fix leaking water asap WAS ORIGINALLY SUBMITTED TO VECHILE REPAIR/A. GONZALEZ. CHANGED TO CUSTODIAL EQUIPMENT REPAIR/J. CARBAJAL. 4-25-05. MS	4/14/2005 Medium	Armando Diaz Jimmy Carbajal		La Mesa ES
688	Work In Progress need one new vacuum cleaner	3/30/2005 Medium	Armando Diaz Jimmy Carbajal		La Mesa ES
644	Work In Progress REQUESTING 1 NEW VACUUM CLEANER	3/29/2005 Medium	Armando Diaz Jimmy Carbajal		La Mesa ES
1453	Work In Progress need to plow playground and seed	4/27/2005 Medium	Frank Lara Lorenzo Hernandez		La Mesa ES
817	Work In Progress Hookup of washer & dryer at La Union JTP (Alvarez) building.	4/4/2005 Medium	David Villalobos David Villalobos		La Union ES JTP - Alvarez
739	Work In Progress Exterior light at the front parking lot near storm drain is out.	3/31/2005 Medium	Eddie Baeza Carlos Castillo		La Union ES
525	Work In Progress 600 Pounds of fertilizer is requested for the playground area.	3/18/2005 Medium	Eddie Baeza Lorenzo Hernandez		La Union ES
166	Work In Progress A motor starter coil is requested for the boiler pump at new addition	3/8/2005 Medium	Eddie Baeza Jose Ambriz		La Union ES
1138	Work In Progress (3) Keys are requested to secure file cabinet in rm. 210. There is no key for this cabinet at this time.	4/14/2005 Medium	Eddie Baeza Hector Lozoya		La Union ES
1331	Work In Progress (2) 4L260 V-belts are requested for the exhaust fans at the kitchen.	4/21/2005 Medium	Eddie Baeza Danny Orozco		La Union ES
886	Work In Progress Alvarez farms. washer and drier can be installed after May 17th. When David has completed the install please provide power. Might want to get with David.	4/6/2005 Medium	Carlos Castillo		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
794	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Santos Galindo		La Union ES
795	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Luis Solis		Loma Linda ES
699	Work In Progress need window latches for rms 103-106-105-204 asap- need to secure windows at end of day- sent sample to ppd	3/30/2005 Medium	Danny Vega Danny Miranda	Classroom	Loma Linda ES
490	Work In Progress need tractor to clean-up walk-in paths by north fence line/also east fence line	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
491	Work In Progress need fill-dirt on baseball diamonds/puddling water	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
492	Work In Progress need to re-do borders around playground equipment/plus remove sand from rockwall	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
493	Work In Progress need tractor to level off dirt in library courtyard	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
494	Work In Progress need tractor to level off rain erosion in bus parking run-off circle/eastside	3/17/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
164	Work In Progress need tractor&scraper to clean west pine tree-line/also rock wall sand	3/8/2005 Medium	Danny Vega Lorenzo Hernandez		Loma Linda ES
163	Work In Progress side walk by front entrance has buckled and lifted/safety hazard/redo portion of sidewalk. 1395 wo	3/8/2005 Medium	Danny Vega Michael Munoz		Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
452	Work In Progress DISTRICT ART SHOW SETUP AT GADSDEN MIDDLE SCHOOL, PUT UP IS APRIL 14, 2005 AT 8:30 AM TAKE DOWN IS APRIL 18, 2005 AT 10:00 AM	3/16/2005 Medium	Grace Alvarado Danny Vega		Loma Linda ES
311	Work In Progress locks in Mr. Ramos windonws are broken and need to be replaced. also the window on south end of room could use new blinds	3/11/2005 Medium	Grace Alvarado Danny Vega		Loma Linda ES
352	Work In Progress UNABLE TO LOCK ROOM	3/14/2005 Medium	Grace Alvarado Hector Lozoya	Classroom	Loma Linda ES 114
1126	Work In Progress Keys - Need to issue keys to Mike Mc Dermott transferring from CHMID to LL. Danny Vega will be turning in his keys. (April 29, 2005 Payday)	4/14/2005 Medium	Michael Munoz Hector Lozoya		Loma Linda ES
993	Work In Progress Need concrete poured around grease trap lids.	4/8/2005 Medium	Ricardo Jacquez Michael Munoz		Mesquite ES
971	Work In Progress NEED FILING CABINETS CYLINDERS REPLACED.THANX.	4/8/2005 Medium	Romauldo Apodaca Hector Lozoya		Mesquite ES
1117	Work In Progress NEED TO MAKE 6 FT. OPENING IN BOOK RM. TO ENTER NEXT RM. PER PHILLIPS.	4/13/2005 Medium	Romauldo Apodaca Michael Munoz		Mesquite ES
1506	Work In Progress need electrical outlet installed in kitchen for milk cabinet .	4/28/2005 Medium	Romauldo Apodaca Enrique Sotelo	Cafeteria	Mesquite ES
237	Work In Progress need 25 bags fertilizer.	3/10/2005 Medium	Romauldo Apodaca Lorenzo Hernandez		Mesquite ES
811	Work In Progress broken window (VANDALISM)	4/4/2005 Medium	Ruben Solis Ruben Ronquillo	Hallway/Corridor	Mesquite ES
685	Work In Progress need to fix two vaccum cleaners	3/30/2005 Medium	Ruben Solis Jimmy Carbajal		Mesquite ES
796	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Ruben Solis		Mesquite ES
887	Work In Progress need to pour concrete and asphalt where gas line was repaired.	4/6/2005 Medium	Michael Munoz		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1248	Work In Progress Transportation Office - Needs to be painted before June (before furniture comes in). Thanks	4/19/2005 Medium	Guillermo Hernandez		Physical Plant Complex Walter Sitters
152	Work In Progress Food Service Warehouse - Loading Dock Area dirt needs to be removed.	3/8/2005 Medium	Lorenzo Hernandez		Physical Plant Complex
1309	Work In Progress Need to make material list and request for general maintenance duties	4/21/2005 Medium	Carlos Castillo Carlos Castillo	Electrical Room	Physical Plant Complex
1434	Work In Progress BARRACKS - NEED A PRICE QUOTE FOR BATS.	4/26/2005 Medium	Ruben Ronquillo Margret Villalobos		Physical Plant Complex
353	Work In Progress Need to installing emerg. lights as per pm 125559.	3/14/2005 Medium	Rudy Arreola Enrique Sotelo		Physical Plant Complex
744	Work In Progress NEED TO REPLACE BOTH BATTERIES ON THE AUTOMATIC SCRUBBER AT DESERT TRAIL	3/31/2005 Medium	Jimmy Carbajal Jimmy Carbajal	Custodial	Physical Plant Complex
711	Work In Progress N. Roof - replace temp/pressure gage. As per Boiler Inspector.	3/30/2005 Medium	Michael Munoz Jose Ambriz		Riverside ES
123	Work In Progress Mr. Valtierra, Principal RS, is requesting new carpet/flooring in Rm#36.	3/7/2005 3/2/2005 Medium	Miguel Aguilar Michael Munoz	Classroom	Riverside ES
797	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Miguel Aguilar		Riverside ES
338	Work In Progress MR CARLOS CASTILLO WILL NEED TO REPLACE LIGHT COVERS IN PORTABLE BROKEN AND SOME IN NEW WING NEED TO COME OVER SO THAT YOU WILL KNOW WHAT KIND TO GET THANK YOU SIR	3/11/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
1257	Work In Progress 4/19/05 1 SIGN IN CLOSE NORTH AND WEST GATES AND REOPEN 6 CLEAN AND SERVICE AC UNITS 1/2 CLOSE WEST AND DROP OFF GATES 1/2 FILE WORK REPORT AND SIGN OUTE 4/19 - 8	4/19/2005 Medium	Adan Duran Adan Duran		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1368	Work In Progress MR MANNY LOZOYA THE BATHROOM DOOR HANDLE IS COMING APART NEED TO REPAIR OR REPLACE ASAP THANK YOU SIR	4/22/2005 Medium	Adan Duran Hector Lozoya		Riverside ES
1471	Work In Progress 4/27/05 MR DAVID VILLALOBOS WATER FOUNTAIN WILL NEED REPLACEING WILL NOT TURN OFF THE NEW ONES ON THE WEST SIDE THE INSIDE NO GOOD THE OLD ONES ON THE EAST SIDE NEED PARTS THANK YOU SIR	4/27/2005 Medium	Adan Duran David Villalobos		Riverside ES
1430	Work In Progress OVEN NOT WORKING AT ALL. NANCY ROLLIN SNP MGR 589-2550	4/26/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Riverside ES
798	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Cervando Padilla		San Miguel ES
1528	Work In Progress PLEASE CHECK A VACUMM CLEANER, MAKE TO MUCH NOISE AND IT DOESN'T HAVE POWER TO PICK UP. THANK YOU	4/29/2005 Medium	Cervando Padilla Jimmy Carbajal		San Miguel ES
1214	Work In Progress WALK IN REFRIGERATOR - VERY WARM, NOT COOLING AT ALL EVA MIRANDA - SNP MANAGER 505-233-2860	4/18/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	San Miguel ES
1127	Work In Progress Keys - Need to issue keys to Danny Vega transferring from LL to SM. Lorenzo Solis will be turning in his keys. (April 29, 2005 - Payday)	4/14/2005 Medium	Michael Munoz Hector Lozoya		San Miguel ES
214	Work In Progress Please replace nonlocking door knob with locking one. Mrs. Avalos portable#45.	3/9/2005 Medium	Lorenzo Solis Hector Lozoya		San Miguel ES
216	Work In Progress Replaced falling apart door knob with new one on entrance door in cafeteria.	3/9/2005 Medium	Lorenzo Solis Hector Lozoya		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
124	Work In Progress As per School Pricipal, Need a truck load of 3/4 inch rock for spreading in front of portable. Need it ASAP. Thank You!	3/7/2005 3/2/2005 Medium	Lorenzo Solis Lorenzo Hernandez		San Miguel ES
146	Work In Progress "Please sent one of you employees to assist me with fixing 9 broken sprinklers, ASAP need to start watering grass. Please bring the following. Tees 1 1/2 inch to 1inch screw in. niples 1 inch 12 and 8 inch long. easy fix 1 1/2 inch. "	3/8/2005 Medium	Lorenzo Solis Lorenzo Hernandez		San Miguel ES
717	Work In Progress Boiler Room - relief valve drain is not properly supported. As per Boiler Inspector.	3/30/2005 Medium	Michael Munoz Jaime Gomez		San Miguel ES
799	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Pablo Diaz		Santa Teresa ES
454	Work In Progress ATT. CALI CASTILLO. CALI, NEED FOR YOU TO FOLLOW UP ON WK. OR. 124323. THANKS. NEED FOR YOU TO COME CHECK A COUPLE OF LIGHT FIXTURES THAT I AM HAVING TROUBLE WITH.	3/16/2005 Medium	Gerardo Marquez Carlos Castillo		Santa Teresa ES
453	Work In Progress ATT. ANGEL GONZALEZ. ANGEL I NEED FOR YOU TO SERVICE TRUCK 107.WOULD YOU LET ME KNOW WHEN YOU CAN FIT IT IN TO YOUR SCHEDULE. THANKS.	3/16/2005 Medium	Gerardo Marquez Angel Gonzales		Santa Teresa ES
1305	Work In Progress ATTN. MANNY. NEED FOR YOU TO INSTALL LOCKS ON CABINETS IN THE RESOURCE RM.	4/21/2005 Medium	Gerardo Marquez Hector Lozoya		Santa Teresa ES
955	Work In Progress PIN KNOB ON MIXER BROKE	4/8/2005 Medium	Danny Orozco Danny Orozco	Cafeteria	Santa Teresa ES
295	Work In Progress MIKE MUNOZ WE NEED REPAIR OVERHEAD DOORS AT VOCATIONAL BUILDING CLASS ROOMS THANK YOU... MIKE	3/11/2005 Medium	Joel Herrera Danny Miranda		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
341	Work In Progress BROKEN DOOR GLASS AT V.O.C BUILDING SIZE 23 3/4 X 23 1/4 WIRE GLASS	3/14/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
449	Work In Progress MS. HILL SHE HAS A PROBLEM WITH CUCARACHAS AND GRILLOS ON CLASS ROOM 312 AT ENGLISH WING AREA	3/16/2005 Medium	Joel Herrera Margret Villalobos		Santa Teresa HS
444	Work In Progress RUBEN RONQUILLO I NNED REPLACE WINDOW'S SCREENS ON CLASS ROOM 308 AT ENGLISH WING SIZE 30 3/4 X 36 1/2 INCHES. THANK YOU RUBEN...	3/16/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
1450	Work In Progress BRONKEN WINDOW AT ROOM 37 SIZE 42 1/2 X 32 INCHES SINGLE GLASS	4/27/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
923	Work In Progress WE NEED CHECK AND REPAIR DOOR LOCK NO WELDING CLASS ROOM AT V.O.C BUILDING	4/7/2005 Medium	Joel Herrera Hector Lozoya		Santa Teresa HS
1387	Work In Progress need to repair sheetrock in gym locker room	4/25/2005 Medium	Danny Miranda Danny Miranda	Auditorium	Santa Teresa HS
800	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Luis Murillo		Santa Teresa HS
695	Work In Progress NEED TILE INSTALLED AT TRAINERS WRAPPING AREA, REQUESTED BY MR. MUNOZ,FRANK.	3/30/2005 Medium	Arturo Nunez Michael Munoz		Santa Teresa HS
406	Work In Progress NEED TO HAVE MOP SINK FAUCETS AT KITCHEN REPLACED, WE HAVE A WATER LEAK.	3/15/2005 Medium	Arturo Nunez David Villalobos		Santa Teresa HS
693	Work In Progress NEED SIX (6) 240V OUTLET INSTALLED IN WELDING SHOP FOR WELDERS	3/30/2005 Medium	Arturo Nunez Carlos Castillo		Santa Teresa HS
1011	Work In Progress NEED CYLINDER AT DRESSING ROOM HALLWAY CHECKED SOME ONE STUCK SOMETHING IN IT, CAN" T OPEN IT ,AFRAID SOMEONE WILL BREAK KEY.	4/11/2005 Medium	Arturo Nunez Hector Lozoya		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
925	Work In Progress NEED TO HAVE OUTSIDE LIGHTING ON FRONT PARKING LOT CHECKED, MIGHT HAVE TO REPLACE LIGHT FIXTURES, TO DARK BY FENCE AREA,	4/7/2005 Medium	Arturo Nunez Carlos Castillo		Santa Teresa HS
151	Work In Progress English Wing Hallway & Office - Need to replace damaged wire from panel box to swt box. To wire circuit properly and safely a/s/a/p	3/8/2005 Emergency	Carlos Castillo	Hallway/Corridor	Santa Teresa HS
714	Work In Progress Dress Room - replace electrical covers. As per Boiler Inspector.	3/30/2005 Medium	Michael Munoz Carlos Castillo		Santa Teresa HS
1130	Work In Progress Bus driveway - Need to fill pot holes located where Airport Road meets with the turn	4/14/2005 Medium	Michael Munoz Lorenzo Hernandez		Santa Teresa HS
1395	Work In Progress GROUNDS SHOP - NEED TO RESTOCK FIRST AID KIT.	4/25/2005 Medium	Lorenzo Hernandez Ruben Ronquillo		Santa Teresa HS
1428	Work In Progress NEED SIX PAIRS OF MEDIAUM LEATHER GLOVES THANK YOU.	4/26/2005 Medium	Luis Murillo Ruben Ronquillo		Santa Teresa HS
1559	Work In Progress Annex Bldg Room 37 - 2 broken window.	4/28/2005 Medium	Luis Murillo Ruben Ronquillo	Classroom	Santa Teresa HS
656	Work In Progress NEED SIX PAIRS OF LEATHER MEDIUM GLOVES	3/29/2005 Medium	Luis Murillo Ruben Ronquillo		Santa Teresa HS
348	Work In Progress BOTH MIORRORS FROM BOYS BATH ROOM ARE FADED THEY NEED TO BE REPLACE IN THE ENGLISH WING THANK YOU.	3/14/2005 Medium	Luis Murillo Ruben Ronquillo		Santa Teresa HS
1277	Work In Progress please support with setting in of new portable and install ramps.	4/20/2005 Medium	Lorenzo Hernandez		Santa Teresa MS
801	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Ismael Rodriguez		Santa Teresa MS
1100	Work In Progress Receptacle shocking staff.	4/13/2005 Emergency	Carlos Castillo Carlos Castillo		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
1103	Work In Progress ATTN;RUBEN RONQILLO. I NEED A TRAILER TOO TRANSPORT ART WORK FOR MR. SANCHEZ TO THE G.M.S 4/14/05. THANK YOU.	4/13/2005 Medium	Ismael Rodriguez Ruben Ronquillo		Santa Teresa MS
1055	Work In Progress SPEEDY HERNANDEZ NEED BACKHOE TO REMOVE SAND FROM NORTH AND SOUTHBUILDING.THANK YOU SIR.	4/12/2005 Medium	Ismael Rodriguez Lorenzo Hernandez		Santa Teresa MS
1098	Work In Progress Need a electrician to run some electrical wiring through some particians in the new nurses office. as per MS.WILLIAMS. THANK YOU.	4/13/2005 Medium	Ismael Rodriguez Carlos Castillo	Classroom	Santa Teresa MS
1301	Work In Progress ATTN;AIDA SAUCEDO I WILL NEED 2 CAFETERIA DOLLEYS AND A REGULER WHEEL DOLLEY FOR THIS SUMMER CONTACT MR.RODRIGUEZ.THANK YOU.	4/21/2005 Medium	Ismael Rodriguez Jimmy Carbajal		Santa Teresa MS
1431	Work In Progress NORTH BUILDING NURSES OFFICE ROOM 8 NEED ELECTRICIAN TO SET UP ELECTRICAL ACCESS DUE TO REMODLING	4/26/2005 Medium	Jose Hinojosa Carlos Castillo	Office	Santa Teresa MS
542	Work In Progress Choir Rm . Outside metal door is damaged and old used to belong to the demolished mechanical rm. Door is to big and heavy for students to be opening every day. Would like to have it replaced to a new and smaller door. Approved by principal.	3/18/2005 Medium	Jaime Mijarez Danny Miranda		Santa Teresa MS
173	Work In Progress Rm 8 N.bldg- Nurses office is going to be remodeled and is going to need new electrical outlets for counter areas and office area.	3/8/2005 Medium	Jaime Mijarez Carlos Castillo		Santa Teresa MS
298	Work In Progress Gym - Replace westside doors.	3/11/2005 Medium	Jaime Mijarez Danny Miranda		Santa Teresa MS
488	Work In Progress NEED TO REPAIR WINDOWS @ OPERATORS	3/17/2005 Medium	Danny Miranda Danny Miranda		Sunland Park ES
1435	Work In Progress INSERTED KEY TO LOCK WALK-IN REFRIGERTOR -- WHEN KEY WAS REMOVED THE WHOLE CYLINDER CAME OUT WITH THE KEY VIRGINIA PRUIT - TEMP MANAGER (505) 589- 2545	4/26/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
802	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Larry Flores		Sunland Park ES
1427	Work In Progress Carlos Vigil - Needs a Master Key for Sound & Signal, Contractor.	4/26/2005 Medium	Margret Villalobos Hector Lozoya		Sunland Park ES
546	Work In Progress Room 28 - Need to replace door glass on outside door.	3/18/2005 Medium	Sebastian Diaz Ruben Ronquillo	Classroom	Sunland Park ES
1083	Work In Progress 4/12/05 need 4 metal cover for A/C THANK YOU	4/12/2005 Medium	Sebastian Diaz Jose Ambriz		Sunland Park ES
1318	Work In Progress EXHAUST FAN IN KITCHEN THAT INTERLOCKS WITH STERLING UNIT SHUTS DOWN ON HIGH AMPS I NEED A HIGHER RATING HEATING ELEMENT.THANKS	4/21/2005 Medium	Paul Quinones Enrique Sotelo		Sunrise ES
946	Work In Progress I NEED SAND FOR BOTH PLAY GROUNDS	4/7/2005 Medium	Paul Quinones Lorenzo Hernandez		Sunrise ES
992	Work In Progress Need North and South leachfields cleaned out.	4/8/2005 Medium	Ricardo Jacquez Lorenzo Hernandez		Sunrise ES
803	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 29, 2005.	4/1/2005 Medium	Aida Salcedo Ramon Dominguez		Sunrise ES