

419 - Work Orders In Progress

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3234	Work In Progress Monthly - Alma Del Valle Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3235	Work In Progress Monthly - Alma Del Valle Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3211	Work In Progress Monthly - Alma Del Valle Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Alma Del Valle Daycare
3184	Work In Progress Monthly - Alma Del Valle Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3144	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3982	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3981	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3960	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3312	Work In Progress Yearly - Alma Del Valle Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3308	Work In Progress Yearly - Alma Del Valle Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3310	Work In Progress Yearly - Anthony ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
3333	Work In Progress Yearly - Anthony ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
3961	Work In Progress Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3983	Work In Progress Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
3985	Work In Progress Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
3145	Work In Progress Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
3162	Work In Progress Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
3212	Work In Progress Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Anthony ES
3238	Work In Progress Monthly - Anthony ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
3236	Work In Progress Monthly - Anthony ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
3661	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Carlos Lujan		Anthony ES
3745	Work In Progress paint room 210	7/21/2005 Medium	Hector Villalobos Hector Villalobos	Classroom	Anthony ES
3899	Work In Progress room 201 bad capert half is bad replace with tile	7/28/2005 Medium	Hector Villalobos Michael Munoz	Classroom	Anthony ES
3898	Work In Progress remove all thing from wall in old book room and install chalk board bullentin boards new book room 8	7/28/2005 Medium	Hector Villalobos Hector Villalobos	Classroom	Anthony ES
3900	Work In Progress PT 220 needs toilet seats need two	7/28/2005 Medium	Hector Villalobos Joe Ontiveros	Classroom	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3434	Work In Progress WASHING MACHINE DOES NOT WORK ANY MORE. (IT GAVE UP) ELSA CHAIRZ - SNP MGR 882-2417	7/11/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Berino ES
3518	Work In Progress need keys made for kitchen manager for office and double doors to shut off alarm and change keys in kitchen so master keys wount open doors	7/14/2005 Medium	Jimmy Cortez Hector Lozoya		Berino ES
3504	Work In Progress One of my Custodians lost or misplaced his keys what is the cost and how quickly ca we have the school rekeyed? (Need Custodian's Name)	7/13/2005 Medium	Jimmy Cortez Hector Lozoya		Berino ES
3734	Work In Progress 7/21/50 MANNY LOZOYA NEED TO INSTALL FILE CABINTE LOCK ROOM 109	7/21/2005 Medium	Ramiro Holguin Hector Lozoya		Berino ES
3240	Work In Progress Monthly - Berino ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
3237	Work In Progress Monthly - Berino ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
3213	Work In Progress Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Berino ES
3189	Work In Progress Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Berino ES
3163	Work In Progress Monthly - Berino ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
3146	Work In Progress Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
3984	Work In Progress Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
3987	Work In Progress Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3962	Work In Progress Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
3334	Work In Progress Yearly - Berino ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
3311	Work In Progress Yearly - Berino ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
3309	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
3313	Work In Progress Yearly - Chaparral ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
3335	Work In Progress Yearly - Chaparral ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
3963	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
3986	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
3164	Work In Progress Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
3147	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
3214	Work In Progress Monthly - Chapparral ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Chaparral ES
3239	Work In Progress Monthly - Chaparral ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
3628	Work In Progress need to cut weeds and weedeat inside and around treatment station. lots of weeds growing and is getting out of hand.	7/18/2005 Medium	Juan Vargas		Chaparral ES
3868	Work In Progress ROOMS 83-82-81-80-72-96-70 NEED WINDOWS REPAIRED OR REPLACE 2-REPORT	7/27/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3800	Work In Progress 07/25/05 jaime gomes main office need new A/C two 4500 and one 6500	7/25/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
3817	Work In Progress 07/25/05 D. MIRANDA 2 request main bldg. need new doors on northside westside and frontdoors	7/25/2005 Medium	Juan Vargas Danny Miranda		Chaparral ES
3801	Work In Progress 5/25/05/ mike neseito que pongan sistema de riego para los arboles	7/25/2005 Medium	Juan Vargas Guadalupe Ontiveros		Chaparral ES
3846	Work In Progress 07/26/05 j. gomes rooms 2 -20-21- 51-47-107- 44- 55-46- need replace A/C 6500	7/26/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
3837	Work In Progress 07/26/05 freed el bano de los homres del main office nesecita cambiar esta quebrado	7/26/2005 Medium	Juan Vargas Margret Villalobos		Chaparral ES
3293	Work In Progress WWTP - The fence around plant needs wind screen replaced.	7/5/2005 Medium	Juan Vargas Ricardo Jacquez		Chaparral ES
3284	Work In Progress 07/05/05 mike munoz Mr. cardona quiere bertical blind en su oficina size 82 width and 80 length	7/5/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
3299	Work In Progress I need some keys for two of the new administrators who will be coming to this school. They have requested main keys to the gate that opens up the fence outside the school and also a set of main keys for the building. If you can please do as soon as possible. Keys for Chaparral Elementary.	7/5/2005 Medium	Jennifer Corral Hector Lozoya	Office	Chaparral ES
3836	Work In Progress for Juan to please replace light bulb and assemble computer desk-table. thank you. rm- 114 Ledesma	7/26/2005 Medium	Jennifer Corral Juan Vargas	Classroom	Chaparral ES
3785	Work In Progress NEED A KEY FOR ROOM 114,LEDESMA REPRINT FOR MANNY - REGARDING E-MAIL 7/27/05 - MKV	7/22/2005 Medium	Jennifer Corral Hector Lozoya	Classroom	Chaparral ES
3871	Work In Progress need an extra key for Even start classroom, Jeannette rm-118	7/27/2005 Medium	Jennifer Corral Hector Lozoya	Classroom	Chaparral ES
3945	Work In Progress Air Conditioner smells like burn and is not cold in rm-128 for Ms. Word	7/29/2005 Medium	Jennifer Corral Jaime Gomez	Classroom	Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3946	Work In Progress Air Conditioner not working in rm-20 for Ms. Gary	7/29/2005 Medium	Jennifer Corral Jaime Gomez	Classroom	Chaparral ES
3548	Work In Progress Need electrical outlet to be installed nurse's office for computer. Thank you	7/14/2005 Medium	Jennifer Corral Enrique Sotelo	Office	Chaparral ES
3821	Work In Progress two/sprite/water/vaccums/not/picking/up/water/p olisher/buffer/wheel/broken/one/vaccum/cleaner/ roller/brush/bearing/broen	7/26/2005 Medium	Daniel Ramirez Jimmy Carbajal		Chaparral ES
3861	Work In Progress Pipes under dishwasher are leaking Alice Escalante - SNP MGR 824-0048	7/27/2005 Medium	Jacqueline Aguilar Danny Orozco	Computer Lab	Chaparral ES
3727	Work In Progress HOOKUP SEWER&WATER TO PORTABLE	7/21/2005 Medium	David Villalobos David Villalobos	Portables	Chaparral MS
3607	Work In Progress need to paint new door @ football storage rm.	7/18/2005 Medium	Danny Miranda Joe Ramirez		Chaparral MS
3608	Work In Progress need to paint new door @ rm. 86	7/18/2005 Medium	Danny Miranda Joe Ramirez		Chaparral MS
3720	Work In Progress 7/12/05. need a/c replaced on portable 1 rm. 2 please.	7/20/2005 Medium	Joe Ramirez Jaime Gomez		Chaparral MS
3793	Work In Progress ROOM 355 HAS A STORAGE ROOM THAT DOESN'T OPEN WITH THE SAME KEY THAT OPENS THE CLASS ROOM. NEED TO BE REKEYED. THANK YOU ROBERT	7/25/2005 Medium	Robert Gonzalez Hector Lozoya		Chaparral MS
3499	Work In Progress We need locks to be installed on the center pole to the double doors in the front entrance,north east doors and south east doors. This is the oldest part of the school. the newer part of the school already have locks on the center poles. This old doors are the once that we use more often. This locks will make it so much faster and easier. THANK YOU ROBERT	7/13/2005 Medium	Robert Gonzalez Hector Lozoya		Chaparral MS
3682	Work In Progress WE HAVE AN OLDER MODEL SHOWER SCRUBBER THAT DOESN'T WORK THAT GOOD ONCE WE USE IT FOR A WHILE. THANK YOU ROBERT	7/19/2005 Medium	Robert Gonzalez Jimmy Carbajal		Chaparral MS
3717	Work In Progress NEED BACKHOE TO CLEAN OUT POND AREA.	7/20/2005 Medium	Vickie Reed Lorenzo Hernandez		Chaparral MS POND

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3481	Work In Progress need to rekey locks on cabinets in rm. 405a.	7/12/2005 Medium	Vickie Reed Hector Lozoya		Chaparral MS
3439	Work In Progress NEED KEYS FOR TWO NEW PORTABLES.	7/11/2005 Medium	Vickie Reed Hector Lozoya	Portables	Chaparral MS
3855	Work In Progress NEED TO REKEY CABINET.	7/26/2005 Medium	Vickie Reed Hector Lozoya	Classroom	Chaparral MS 204
3648	Work In Progress please get with speedy and have him train you on the sprikler system on football field and thru out campus. Identify all valves and repair what is needed. also ask him for a key for sprinkler box and have him teach you the programs.	7/19/2005 Medium	Joe Ramirez	Football Field	Chaparral MS
3649	Work In Progress need to cut weeds and grass behind library and courtyard and surrounding areas tru -out campus including pond. Also need to irrigate these areas also.	7/19/2005 High	Joe Ramirez		Chaparral MS
3650	Work In Progress please paint railing on new portables that where installed and modified and all railings that are in need.	7/19/2005 Medium	Joe Ramirez		Chaparral MS
3656	Work In Progress please put up fence where portables where installed even if its on a temp bases.	7/19/2005 Medium	Joe Ramirez	Football Field	Chaparral MS
3241	Work In Progress Monthly - Chaparral MS Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3243	Work In Progress Monthly - Chaparral MS Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3215	Work In Progress Monthly - Chapparal MS Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Chaparral MS
3191	Work In Progress Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Chaparral MS
3148	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3990	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3988	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3964	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3977	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3336	Work In Progress Yearly - Chaparral MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3314	Work In Progress Yearly - Chaparral MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3307	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3942	Work In Progress need emergency light and exit signs check out.	7/29/2005 Medium	David Acosta Carlos Castillo	Office	Desert Pride
3943	Work In Progress need to check out two light fixture in room #7, two in room# 8, and room#5	7/29/2005 Medium	David Acosta Carlos Castillo	Classroom	Desert Pride 5,7,8.
3791	Work In Progress need plastic name plates(12)MS. S. VERLANDER, MS. I. RAMIREZ, MS. BACH-HAGUE, MS. B. COSTULIS, MS. C. MCDONALD, MR. C. VELA, MR. P. WYMAN, MS. G. PARKER, MS. S. GARCIA, MR. D. NEAL , MS. J. ZAPATA, MS. D. DEAN	7/25/2005 Medium	David Acosta Hector Lozoya	Classroom	Desert Pride
3315	Work In Progress Yearly - Desert Pride Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3337	Work In Progress Yearly - Desert Pride Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3979	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3995	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin David Acosta		Desert Pride

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3991	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3165	Work In Progress Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3185	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3216	Work In Progress Monthly - Desert Pride Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Desert Pride
3248	Work In Progress Monthly - Desert Pride Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3244	Work In Progress Monthly - Desert Pride Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3665	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo David Acosta		Desert Pride
3120	Work In Progress ROOM 110 - NEED ELECTRICAL POLES FOR THE LAB AT DT (PLEASE CALL JAVIER GUTIERREZ WILL ASSIST IN QUESTIONS 882-6277	7/1/2005 Medium	Cora Ramirez Enrique Sotelo		Desert Trail Intermediate
3121	Work In Progress ROOM 207 - NEED ELECTRICAL POLES FOR THE LAB AT DT (PLEASE CALL JAVIER GUTIERREZ WILL ASSIST IN QUESTIONS 882-6277	7/1/2005 Medium	Cora Ramirez Enrique Sotelo		Desert Trail Intermediate
3739	Work In Progress DIAG/PSYCH ROOM NEED (2) CLASSROOM KEYS MADE. CORE IS: J-53	7/21/2005 Medium	Johnny Acuna Hector Lozoya		Desert Trail Intermediate
3619	Work In Progress MENS RESTROOM (NW HALL) : PLEASE CHANGE DOOR CYLINDER WHERE KEY ENTERS TO OPEN UP DOOR. STUDENTS STUFFED IN CYLINDER WITH CLAY AND HARDENED. THANK YOU !!!!!	7/18/2005 Medium	Johnny Acuna Hector Lozoya		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3620	Work In Progress NEED NAME PLATES TO BE MADE: (1) PRINCIPAL, (1) ASSISTANT PRINCIPAL, (1) COMPUTER LAB	7/18/2005 Medium	Johnny Acuna Hector Lozoya		Desert Trail Intermediate
3375	Work In Progress (CHAPARRAL SUNRISE ELEMENTARY) CUSTODIAL REQUESTING FOR FLAG POLE ROPE TO BE RE-INSTALLED ON OUTDOOR FLAG POLE BEFORE SCHOOL STARTS. (VANDALS CUT OFF ROPE) THANK YOU...	7/7/2005 Medium	Johnny Acuna Ruben Ronquillo		Desert Trail Intermediate
3936	Work In Progress I HAVE A BROKEN VACCUM	7/29/2005 Medium	Salvador Gonzalez Jimmy Carbajal		Desert Trail Intermediate
3937	Work In Progress THE EXTRACTOR MACHINE IS BROKEN	7/29/2005 Medium	Salvador Gonzalez Jimmy Carbajal		Desert Trail Intermediate
3766	Work In Progress I NEED THREE VACCUM MACHINE BELTS	7/22/2005 Medium	Salvador Gonzalez Jimmy Carbajal		Desert Trail Intermediate
3767	Work In Progress TWO VACCUM MACHINE BRUSHES NEEDSTO BE FIXED	7/22/2005 Medium	Salvador Gonzalez Jimmy Carbajal		Desert Trail Intermediate
3938	Work In Progress AIDA CAN WE HAVE SAFETY BELTS?	7/29/2005 Medium	Salvador Gonzalez Aida Salcedo		Desert Trail Intermediate
3247	Work In Progress Monthly - Desert Trail Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
3242	Work In Progress Monthly - Desert Trail Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
3217	Work In Progress Monthly - Desert Trail Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Desert Trail Intermediate
3193	Work In Progress Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Desert Trail Intermediate
3166	Work In Progress Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
3149	Work In Progress Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
3994	Work In Progress Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3989	Work In Progress Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
3965	Work In Progress Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
3338	Work In Progress Yearly - Desert Trail Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
3316	Work In Progress Yearly - Desert Trail Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
3666	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Salvador Gonzalez		Desert Trail Intermediate
3667	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Miguel Aguilar		Desert View ES
3317	Work In Progress Yearly - Desert View ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
3339	Work In Progress Yearly - Desert View ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
3966	Work In Progress Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
3992	Work In Progress Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
3996	Work In Progress Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3150	Work In Progress Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
3167	Work In Progress Monthly - Desert View ES Roof Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
3218	Work In Progress Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Desert View ES
3245	Work In Progress Monthly - Desert View ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
3249	Work In Progress Monthly - Desert View ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
3827	Work In Progress Requesting electrical setup for installation of garbage disposal inside teachers lounge.	7/26/2005 Medium	Miguel Aguilar Carlos Castillo		Desert View ES
3828	Work In Progress Requesting necessary setup of sink plumbing for installation of garbage disposal inside teachers lounge.	7/26/2005 Medium	Miguel Aguilar David Villalobos		Desert View ES
3826	Work In Progress Need sand blaster to remove graffitti on exterior school rock wall near lower grade playground. Note:Graffitti extends approximately 30ft and is very visible.	7/26/2005 Medium	Miguel Aguilar Ruben Ronquillo		Desert View ES
3567	Work In Progress Server Room - Breaker is tripping.	7/14/2005 Medium	Norma Alvarado Carlos Castillo		GAC
3580	Work In Progress SWIMMING POOL AREA ELECTRICAL ROOM - NEED A KEY FOR THIS AREA.	7/15/2005 Medium	Lorenzo Hernandez Hector Lozoya		GAC
3799	Work In Progress AS PER SALLY SEPULVEDA-CLOSET/STORAGE IS VERY HOT AND THEY HAVE 2 PRINTERS THERE. (NOTE: THERE IS A PORTABLE AIR CONDITIONER THERE, BUT DOES NOT HELP THE PROBLEM.)	7/25/2005 Medium	Mary Garcia Jose Ambriz	Office	GAC B WING
3797	Work In Progress ELISA SAENZ-NEEDS TO HAVE SOME PICTURES/PAINTING HUNG ON THE HALL WAY NEXT TO ROSIE'S & HER OFFICE. (PICTURES ARE IN SUPT'S FILE ROOM)	7/25/2005 Medium	Mary Garcia Manuel Prospero	Hallway/Corridor	GAC A WING

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3798	Work In Progress AS PER ELOIDA SALINAS-AIR CONDITIONING UNIT NEEDS TO BE CHECKED, DOES NOT COOL AND MAKING FUNNY NOISES.	7/25/2005 Medium	Mary Garcia Manuel Prospero	Office	GAC C WING
3773	Work In Progress NEED AN AB-20 KEY FOR FELIPE GUZMAN	7/22/2005 Medium	Mary Garcia Hector Lozoya	Office	GAC A WING
3932	Work In Progress NEED TABLES TO BE ASSEMBLED FOR PRE-K CAFETERIA. (ASAP-SO STUDENTS DO NOT HAVE TO SIT ON THE FLOOR TO EAT.)	7/29/2005 Medium	Mary Garcia Manuel Prospero	Cafeteria	GAC PRE-K
3933	Work In Progress AS PER CAROLYN GRESSITT-NEED SOME FILING CABINETS & OTHER ITEMS TO BE MOVED.	7/29/2005 Medium	Mary Garcia Manuel Prospero	Office	GAC C-WING
3944	Work In Progress AS PER MR. BOYD-PLEASE CHANGE OUT CORE FOR ALL PRE-K BATHROOMS TO BE ABLE TO OPEN WITH CLASSROOM KEY AND GRAND MASTER KEY. (DOORS LOCK FROM INSIDE ONLY AND CAN NOT BE OPENED.)	7/29/2005 Medium	Mary Garcia Hector Lozoya	Restroom (Girls)	GAC PRE-K
3547	Work In Progress AS PER DAVID BOYD & SHORTY- NEED A PAD LOCK TO LOCK THE PRE-K NORTHSIDE GATE. (BEFORE STUDENTS COME IN.)	7/14/2005 Medium	Mary Garcia Hector Lozoya		GAC PRE-K GATE
3545	Work In Progress AS PER ANN STEINHOFF-CHECK ELECTRICITY IN LAST OFFICE ON WEST SIDE OF C -WING MAYBE TRIPPED BREAKER.	7/14/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC C WING
3579	Work In Progress AS PER JOSE HINOJOSA-NEEDS AN OUTLET TO BE REPLACED NEXT TO HIS COMPUTER DESK.	7/15/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC C WING
3618	Work In Progress LAURA GARCIA NEEDS FURNITURE TO BE REARRANGED IN HER OFFICE. WILL WAIT FOR TECHNOLOGY TO CALL US ON A DAY TO SCHEDULE CUSTODIAL TO MOVE FURNITURE.	7/18/2005 Medium	Mary Garcia Manuel Prospero	Office	GAC B WING
3408	Work In Progress AS PER CARLOS VIGIL-NEEDS A GRAND MASTER 7, ASAP. (HIS BROKE IN HALF) ALREADY TALKED WITH MANNY LOZOYA	7/8/2005 Medium	Mary Garcia Hector Lozoya	Office	GAC ALL SCHOOLS
3432	Work In Progress AS PER LINDA REYES-NEED FURNITURE FROM 3 OFFICES & BOXES ALONG WITH THIS TO BE MOVED A.S.A.P. TO NEW AREA IN C-WING. STAFF WILL START WORKING IN THESE NEW OFFICES BY TOMORROW.	7/11/2005 Medium	Mary Garcia Manuel Prospero	Office	GAC C WING

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3460	Work In Progress AS PER JULIE HERNANDEZ, NEED ELECTRICIAN TO CONNECT WIRES WITH AN END CONNECTION TO BE ABLE TO PLUG CONNECTION TO THE WALL. (CALL JULIE @ 6417 BEFORE COMING)	7/12/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC A WING
3470	Work In Progress AS PER CARMEN MORRISSETTE, NEEDS A DC490 ELECTRICAL OUTLET FOR COPIER AND AN EXTRA OUTLET FOR LAMINATING MACHINE ASAP. (HAS A NEW OFFICE SHE MOVED INTO, THIS IS NEEDED IN ORDER FOR HER TO COME IN AND DO HER DAILY WORK)	7/12/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC
3431	Work In Progress AS PER MS. CANTRELL, NEED A KEY MADE FOR MARIYLN WATSON, WHICH WILL BE HOUSED AT GAC. (KEY # A3)	7/11/2005 Medium	Mary Garcia Hector Lozoya	Office	GAC C WING
3295	Work In Progress AS PER MS. CANTRELL, NEEDS FURNITURE TO BE MOVED FROM HER OFFICE INTO MS. LOZANO'S OFFICE AND ALSO MOVE LOZANO'S OFFICE FURNITURE INTO MS. CANTRELL'S OLD OFFICE.	7/5/2005 Medium	Mary Garcia Manuel Prospero	Office	GAC C WING
3246	Work In Progress Monthly - GAC Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3250	Work In Progress Monthly - GAC Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3233	Work In Progress Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		GAC
3913	Work In Progress AS PER NORMA ALVARADO, HANDICAP RESTROOM IN ENTRANCE HALLWAY IS CLOGGED UP AGAIN. MANUEL PROSPERO HAS LEFT FOR THE DAY, GUSTAVO HAS TRIED TO UNCLOG BUT UNSUCCESSFUL. NEED A PLUMBER.	7/28/2005 Medium	Danny Orozco		GAC
3546	Work In Progress Technology Server Room-Install Battery powered Emergency lighting in this room	7/14/2005 Medium	Carlos Castillo		GAC
3282	Work In Progress C-WING - TAKE OFF TILE AND INSTALL NEW TILE (TILE HAS BEEN DELIVERED), ALSO FINISH PAINTING. WILL SEND GERRY MARQUEZ TO ASSIST.	7/5/2005 Medium	Alfredo Holguin Manuel Prospero		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3195	Work In Progress Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		GAC
3180	Work In Progress Monthly - GAC Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3140	Work In Progress Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3993	Work In Progress Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3997	Work In Progress Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3956	Work In Progress Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3376	Work In Progress Need a key to get into Manuel Prospero's storage building (Morgan building).	7/7/2005 Medium	Alfredo Holguin Hector Lozoya		GAC
3340	Work In Progress Yearly - GAC Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3318	Work In Progress Yearly - GAC Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
3668	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Ralph Lara		GAC
3669	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Jesus Estrada		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3319	Work In Progress Yearly - Gadsden HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
3341	Work In Progress Yearly - Gadsden HS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Fernando Moncayo		Gadsden HS
3377	Work In Progress I need to do to get the bucket truck and an operator, to remove speakers at GHS football field. Thanks Carlos Vigil	7/7/2005 Medium	Alfredo Holguin Carlos Castillo	Football Field	Gadsden HS
3957	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
3998	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Fernando Moncayo		Gadsden HS
4001	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS
3141	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
3168	Work In Progress Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS
3219	Work In Progress Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Gadsden HS
3809	Work In Progress REQUESTING TO BORROW THE POWER WASHER BY THURSDAY MORNING TO COMPLETE A W.O. REQUEST BY AIDA.	7/25/2005 Medium	Jimmy Carbajal		Gadsden HS
3659	Work In Progress Please install stair treads when they come in. Old english stair ways. I will order. See Mike Install from main to old english stairs.	7/19/2005 Medium	Mario Apodaca	Stairway	Gadsden HS
3660	Work In Progress Please install new tile in main concession stand.	7/19/2005 Medium	Michael Munoz		Gadsden HS
3254	Work In Progress Monthly - Gadsden HS Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3251	Work In Progress Monthly - Gadsden HS Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Fernando Moncayo		Gadsden HS
3645	Work In Progress BOTH OVENS ARE DOWN. LYDIA M. SNP MGR 882-5522	7/19/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Gadsden HS
3479	Work In Progress All Campus - Need to replace old door knobs w/new levers.	7/12/2005 Medium	Hector Lozoya Hector Lozoya		Gadsden HS
3524	Work In Progress NEED TO FIX FOOTBALL FIELD SCOREBOARD BREAKER BOX	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
3525	Work In Progress NEED TO CK ALL FOOTBALL FIELD LAMPS	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
3917	Work In Progress 7-27-05 1-IN PUT TO SCHOOL DUDE 4-HELP CARLOS PUT NEW BOX FOR SCOREBOARD 3-ASSEMBLE DESK AT N-BLDG OFFICE 7/27 - 8	7/28/2005 Medium	Mario Apodaca Mario Apodaca		Gadsden HS
3736	Work In Progress NEED TO PUT A NEW KEY SWITCH ON VEHICLE #95	7/21/2005 Medium	Mario Apodaca Angel Gonzales		Gadsden HS
3802	Work In Progress NEED TO REPLACE GATE VALVE AT OLD COUNING CENTER BLDG TO GET WATER-UP TO E/COOLER	7/25/2005 Medium	Mario Apodaca David Villalobos		Gadsden HS
3883	Work In Progress check football field lights	7/27/2005 Medium	Carlos Castillo Carlos Castillo	Football Field	Gadsden HS
3726	Work In Progress Attn electrician need a better security ligths by CONCESSION STAND to control vandalism	7/20/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
3593	Work In Progress Need to repair or replace electrical conduit outside of CONCESSION STAND by GIRL'S GYM	7/15/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
3742	Work In Progress ***URGENT***Requested by Ms. Lopez Rm. 610 & 611-They have changed the door knobs and the cylinders need to be installed. Ms. Lopez has many supplies and equipment that need to me locked and secured!	7/21/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3743	Work In Progress ***URGENT***Requested by Ms. Lopez Xerox Paper Storage Room-They have changed the door knobs and the cylinders need to be installed. All of our paper order has arrived today and storage needs to be locked and secured as soon as possible!	7/21/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
3754	Work In Progress Requested by Velia Rm. 800 Old Counseling Center Portable-Doors need to be re-keyed as soon as possible. This portable will be used as the ISS classroom, 4 keys are needed.	7/21/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
3755	Work In Progress Requested by Velia Rm. 112 Front Office-Key # HJ2 is needed for the key box.	7/21/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
3774	Work In Progress Requested by Velia Rm. 112 Front Office- Key # HH7 is needed for the key box.	7/22/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
3897	Work In Progress Requested by Mr. Mendoza Rm. 214 North Building-Paint chalk boards.	7/28/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
3910	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Bracket needed for N.M. Flag.	7/28/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
3902	Work In Progress Requested by Ms. Marquez New Counseling Portable-Two filing cabinets need to be keyed.	7/28/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
3911	Work In Progress Requested by Mr. G. Holguin Rm. 342 Academic Building-Need door re-keyed, will need 3 keys.	7/28/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
3920	Work In Progress Requested by Velia Front Office-The cylinder for room #107 will not open with a D Master or key assigned to door. This classroom is the Day Care on our campus and the building custodian can not open the classroom to clean. Please fix as soon as possible.	7/28/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
3908	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Dr. Pockets to be placed in Marie's copy to be placed on wall.	7/28/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
3909	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Install clock on wall.	7/28/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3901	Work In Progress Requested by Mr. Chambers Rm. 110 Front Offices-Remove ice machine from concession stand, take and install in Football Field concession stand.	7/28/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS
3903	Work In Progress Requested by Isela Martinez New Counseling Center Portable-The water keeps running in the bathroom.	7/28/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
3495	Work In Progress Requested by Marie New Counseling Center-The portable needs stairs and a wheelchair accessible ramps to be doors.	7/12/2005 Medium	Velia Alarcon Michael Munoz	Portables	Gadsden HS
3493	Work In Progress Requested by Pamela Holguin Rm. 228 North Building-A door frame is needed. Will have an old door installed, left over from doors that are being replaced in North Building. Also, a door knob that will not lock is needed.	7/12/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS
3494	Work In Progress Requested by Marie New Counseling Center Portable-New portable needs to be keyed HE134. Change old cylinder to doors of new portable doors.	7/12/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
3435	Work In Progress Requested by Marie New Counseling Center Portable-Have 3 additional electrical outlets installed on each side of the portable. One will need to be dropped down from the ceiling in the middle of the room, on each side of the portable. Speak to Marie Acosta, Registrar for additional instructions. REVISED: AS PER ISELA MARTINEZ, DO NOT NEED DROP DOWN FORM THE CENTER OF ROOM, ONLY ON THE SIDES. 7/25/05 MS.	7/11/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
3744	Work In Progress Requested by Mr. Lawrence Rm. 402 Boys Gym-Please fumigate, there's a roach infestation in the office.	7/21/2005 Medium	Velia Alarcon Michael Munoz	Office	Gadsden HS
3715	Work In Progress Requested by Mr. Pawloski Rm. 109A Main Building (Sp.Ed. Office)-Please remove the lock in my file cabinet, replace, and re-key it with a new one.	7/20/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS
3716	Work In Progress ***URGENT***Requested by Velia Library-All the doors in the library need to be secured. They have changed all the door knobs and the cylinders need to be installed. URGENT library has alot of equipment that needs to me locked and secured!	7/20/2005 Medium	Velia Alarcon Hector Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3589	Work In Progress Requested by Isela Martinez New Counseling Center-Paint both doors going into Counseling Center.	7/15/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
3587	Work In Progress Requested by Isela Martinez New Counseling Center-Remove chalkboards.	7/15/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
3842	Work In Progress Main Office - A/C Unit is not working (Informed Jaime)	7/26/2005 Medium	Rosa Apodaca Jaime Gomez	Office	Gadsden MS
3404	Work In Progress 7*07*05 .50 Picking up paint and tarps. 5.5 Replacing lamps that were burned out and starting doing cut in RM399 1.0 Moved new furniture to hallway. 1.0 Mr Q showing me the desks that needed to be repalced. 7/7 - 8	7/8/2005 Medium	Rudy Arreola Rudy Arreola		Gadsden MS
3410	Work In Progress Need an additonal register and supply duct. for RM#399	7/8/2005 Medium	Rudy Arreola Jaime Gomez	Classroom	Gadsden MS
3289	Work In Progress Broken window needs to be replaced in RM#501.	7/5/2005 Medium	Rudy Arreola Ruben Ronquillo	Portables	Gadsden MS
3290	Work In Progress Broken window in RM#150 needs to be replaced.	7/5/2005 Medium	Rudy Arreola Ruben Ronquillo	Classroom	Gadsden MS
3292	Work In Progress Broken window in Libray needs to be replaced.	7/5/2005 Medium	Rudy Arreola Ruben Ronquillo		Gadsden MS
3616	Work In Progress replace door at pump room	7/18/2005 Medium	Ricardo Jacquez Danny Miranda		Gadsden MS
3582	Work In Progress IRRIGATION CTRL PANEL - IRRIGATION BOOSTER PUMP IS NOT WORKING. PLEASE TROUBLESHOOT BUS TURNAROUND AREA. ROUTED TO ENRIQUE AS PER RICK 8/2/05	7/15/2005 8/2/2005 Medium	Lorenzo Hernandez Enrique Sotelo		Gadsden MS
3626	Work In Progress please cut and weed eat around bldgs and campus before you leave on vacation.	7/18/2005 Medium	Rudy Arreola		Gadsden MS
3220	Work In Progress Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Gadsden MS
3999	Work In Progress Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Rudy Arreola		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4004	Work In Progress Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Rudy Arreola		Gadsden MS
3967	Work In Progress Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Rudy Arreola		Gadsden MS
3670	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Juan Acosta		Gadsden MS
3653	Work In Progress paint the columns on outside of gym	7/19/2005 Medium	Dana Hamel Rudy Arreola	Gym	Gadsden MS
3654	Work In Progress paint over the scratchouts in boys black restrooms	7/19/2005 Medium	Dana Hamel Rudy Arreola	Restroom (Boys)	Gadsden MS
3655	Work In Progress paint the front columns of the school to remove tagging	7/19/2005 Medium	Dana Hamel Rudy Arreola		Gadsden MS
3651	Work In Progress Mice in Gloria Hernandez office in C Wing. Need control as soon as possible 1) HAD JUAN CHECK FOR ANY FOOD AROUND, 2) REQUESTED THAT THEY ASK R. RONQUILLO FOR MICE TRAPS (W/GLUE) 3) FAXED FOR PRICE QUOTE AS PER M. MUNOZ FOR THE WHOLE C-WING.	7/19/2005 Medium	Dana Hamel Margret Villalobos	Office	Gadsden MS
3652	Work In Progress Cockroach issues for the total school, need a monthly spraying	7/19/2005 Medium	Dana Hamel Margret Villalobos	Hallway/Corridor	Gadsden MS
3671	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Armando Diaz		La Mesa ES
3968	Work In Progress Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Frank Lara		La Mesa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4006	Work In Progress Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Frank Lara		La Mesa ES
4000	Work In Progress Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Frank Lara		La Mesa ES
3221	Work In Progress Monthly - La Mesa ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		La Mesa ES
3222	Work In Progress Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		La Union ES
4002	Work In Progress Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES
4010	Work In Progress Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES
3969	Work In Progress Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES
3672	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Santos Galindo		La Union ES
3572	Work In Progress NEED LIGHT BULBS FOR RECESSED LIGHTS AT LA UNION ELEM. THE MAJORITY ARE BURNED OUT. THANK YOU.	7/15/2005 Medium	Arturo Nunez Carlos Castillo		La Union ES
3707	Work In Progress NEED TO HAVE WATER LINE CHECKED AT L.U.E ON DRIVEWAY TO BACK PARKING LOT, POSSIBLE WATER LINE BREAK, AREA HAS BEEN WET FOR A COUPLE OF DAYS. THANK YOU... ASSIGNED TO D. VILLALOBOS AS PER M. MUNOZ	7/20/2005 Medium	Arturo Nunez David Villalobos		La Union ES
3344	Work In Progress Yearly - La Union ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3322	Work In Progress Yearly - La Union ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES
3934	Work In Progress rotor needs repair; probably needs motor	7/29/2005 Medium	Santos Galindo Jimmy Carbajal		La Union ES
3935	Work In Progress key of room #302 opens custodial storage room in the cafeteria; principal request this be change.	7/29/2005 Medium	Santos Galindo Hector Lozoya		La Union ES
3281	Work In Progress ice machine needs to be repired.	7/5/2005 Medium	Santos Galindo Danny Orozco		La Union ES
3829	Work In Progress MR. TRUJILLO IS WANTING NEW KEYS MADE FOR DESKS, CABINETTS AND FILE CABINETS. ALSO NEEDING NAME PLATE FOR NEW TEACHERS. MS. BERARD, CHAVEZ-FISHER, GRIEGO, DESANTIAGO, HUGHES, MARKHAM, MEDINA, MERRICK, MONTES, PINA, PRICE, RIOS- ALVILLAR,	7/26/2005 Medium	Grace Alvarado Hector Lozoya		Loma Linda ES
3323	Work In Progress Yearly - Loma Linda ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
3345	Work In Progress Yearly - Loma Linda ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
3673	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Luis Solis		Loma Linda ES
3970	Work In Progress Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
4012	Work In Progress Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
4003	Work In Progress Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
3223	Work In Progress Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3200	Work In Progress Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Loma Linda ES
3173	Work In Progress Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3224	Work In Progress Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Mesquite ES
3155	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3269	Work In Progress Monthly - Mesquite ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3258	Work In Progress Monthly - Mesquite ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
4005	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
4015	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3971	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3674	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Ruben Solis		Mesquite ES
3346	Work In Progress Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3324	Work In Progress Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3122	Work In Progress wet and dry machine's motor (BURNED)	7/1/2005 Medium	Ruben Solis Jimmy Carbajal	Hallway/Corridor	Mesquite ES

8/2/2005 3:31:38 PM

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3558	Work In Progress need compresor changed out on armstrong unit in rm. 608.thanx.	7/14/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES
3507	Work In Progress 7/13/05 1hr. reported checked b. rm.1hr. marqui..5 picked up trailer at s.m..5 p.o..4hr. moving furniture and boxes from a.d.v. to mq..1hr. assembling 2 bikes. 7/13 - 8	7/13/2005 Medium	Romauldo Apodaca Margret Villalobos		Mesquite ES
3955	Work In Progress DINING AREA - NEED TO WELD HINGES ON DOOR FALLING DOWN.	7/29/2005 Medium	Romauldo Apodaca Hector Lozoya		Mesquite ES
3844	Work In Progress Purchasing Warehouse - The sign that reads STUDENT RECORDS needs to be re-located and placed on the north side of bldg over the buzzer button for the warehouse a/s/a/p.	7/26/2005 Medium	Marta Jacquez Rudy Arreola		Physical Plant Complex
3940	Work In Progress MARTA JACQUEZ - A/C UNIT IS NOT WORKING AT ALL.	7/29/2005 Medium	Marta Jacquez Jaime Gomez		Physical Plant Complex
3769	Work In Progress need door in auto shop office	7/22/2005 Medium	Danny Miranda Danny Miranda		Physical Plant Complex
3770	Work In Progress need window locks at s.t. elem.	7/22/2005 Medium	Danny Miranda Danny Miranda		Physical Plant Complex
3347	Work In Progress Yearly - Physical Plant Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
3980	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
3461	Work In Progress Need a copy of control key (core) to keep here at the Maintenance Dept - as per A. Holguin.	7/12/2005 Medium	Alfredo Holguin Hector Lozoya		Physical Plant Complex
3271	Work In Progress Monthly - Physical Plant Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
3915	Work In Progress PPD OFFICE (JULIET) & CUSTODIAL OFFICE (MARY) HAVING PROBLEMS WITH MICE. THERE ARE GLUE BOARDS SET-UP BUT NOT CATCHING ANYTHING. IS THERE SOMETHING ELSE THAT CAN BE USED?	7/28/2005 Medium	Margret Villalobos		Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3379	Work In Progress Mens Restroom in Custodial Warehouse -Install new privacy lockset	7/7/2005 Low		Restroom (Boys)	Physical Plant Complex
3380	Work In Progress Mens Restroom in Custodial Warehouse- Replace toilet tank cover with appropriate size for unit.	7/7/2005 Medium	Fred Appelzoller	Restroom (Boys)	Physical Plant Complex
4017	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
3186	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
3174	Work In Progress Monthly - Riverside ES Roof Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3225	Work In Progress Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Riverside ES
4019	Work In Progress Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3156	Work In Progress Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3414	Work In Progress MR LOZOYA MRS ARIAS IS HAVING TROUBLE WITH THE STORAGE ROOM LOCK WOULD LIKE FOR YOU TO LOOK AT IT THANK YOU SIR	7/8/2005 Medium	Adan Duran Hector Lozoya		Riverside ES
3415	Work In Progress MR JOSE AMBRIZ THE LITTLE ROOM WHERE WATER HEATER IS IN THE NEW WING IS GETTING HOT SETTING OFF ALARM NEED EXHUST FAN TO DRAW HEAT OUT THANK YOU SIR	7/8/2005 Medium	Adan Duran Jose Ambriz		Riverside ES
3467	Work In Progress MR MIKE MUNOZ SIR MRS ARIAS WOULD LIKE THE WALL IN WAITING AREA REMOVE TO MAKE A BIGGER OFFICE Olga called wanting status on wo 7/13/05 - mkv emailed Mike Munoz No, this is not a priority, Portables movement and renovation of portables has put us back. Will get to project when we get a little bit of time. As per Mike Munoz - xc: Olga 7/15/05	7/12/2005 Medium	Adan Duran Michael Munoz		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3486	Work In Progress MR MIKE MUNOZ SIR WOULD LIKE TO USE BOBCAT LOADER HAVE 70 TONS OF SAND TO SPREAD THANK YOU SIR	7/12/2005 Medium	Adan Duran Angel Gonzales		Riverside ES
3690	Work In Progress MR MANNY LOZOYA FILE CABINET NEW PORTABLE RM B NEEDS REPAIR WILL NOT LOCK PARTS MISSING THANK YOU SIR	7/19/2005 Medium	Adan Duran Hector Lozoya		Riverside ES
3778	Work In Progress MR DAVID VILLALOBOS WE HAVE SOME LEAKING FUACTS NEW WING NEED REPAIR KIT OR REPLACEMENT THANK YOU SIR	7/22/2005 Medium	Adan Duran David Villalobos		Riverside ES
3362	Work In Progress 7/6/05 MR RUBEN RONQILLO NEED TO REPLACE BROKEN WINDOW NORTH WING WEST SIDE 15 1/4 X 13 1/4 THANK YOU SIR	7/6/2005 Medium	Adan Duran Danny Miranda		Riverside ES
3273	Work In Progress Monthly - Riverside ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3261	Work In Progress Monthly - Riverside ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3972	Work In Progress Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
4007	Work In Progress Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3348	Work In Progress Yearly - Riverside ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3326	Work In Progress Yearly - Riverside ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
3675	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Raul Romero		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3480	Work In Progress REPARAR LA MAQUINA DE SACAR BRILLO LA MAQUINA SE PRENDE SOLA.	7/12/2005 Medium	Raul Romero Jimmy Carbajal	Classroom	Riverside ES
3768	Work In Progress NEED APPLIANCE TRUCK TO MOVE SOME FIREPROOF CABINETS.	7/22/2005 Medium	Raul Romero Jimmy Carbajal	Classroom	Riverside ES
3834	Work In Progress A/C UNIT NOT WORKING IN HIGH SPEED PORTABLE#58	7/26/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
3794	Work In Progress PORTABLES #29 & 44 REF. UNITS NOT WORKING/STOP BY ASAP	7/25/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
3924	Work In Progress ELECTICAL SHORT RM 58 PORTABLE A/C UNIT.STOP BY ASAP	7/28/2005 Medium	Danny Vega Enrique Sotelo		San Miguel ES
3914	Work In Progress PORTABLE#37 UNEVEN RAMPS- DOOR HITS ON STAIRS/RAMP NOT EVEN WITH STAIRS/WELDS BROKEN /SAFETY HAZARD.PLEASE STOP BY ASAP Route to B. Aldaz as per Mike 8/1/05 -mkv	7/28/2005 Medium	Danny Vega Bobby Aldaz		San Miguel ES
3604	Work In Progress need ramps leveled by portables/need to weld stairs to ramps/asap	7/18/2005 Medium	Danny Vega Lorenzo Hernandez		San Miguel ES
3676	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Cervando Padilla		San Miguel ES
3327	Work In Progress Yearly - San Miguel ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
3349	Work In Progress Yearly - San Miguel ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
4008	Work In Progress Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
3973	Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3262	Work In Progress Monthly - San Miguel ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
3274	Work In Progress Monthly - San Miguel ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
3157	Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
4020	Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
3226	Work In Progress Monthly - San Miguel ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		San Miguel ES
3175	Work In Progress Monthly - San Miguel ES Roof Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
3178	Work In Progress Monthly - Santa Teresa ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
4021	Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
3142	Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
3275	Work In Progress Monthly - Santa Teresa ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
3263	Work In Progress Monthly - Santa Teresa ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
3227	Work In Progress Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Santa Teresa ES
3958	Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
4009	Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3350	Work In Progress Yearly - Santa Teresa ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
3328	Work In Progress Yearly - Santa Teresa ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
3677	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Pablo Diaz		Santa Teresa ES
3657	Work In Progress ATTN. Manny . NEED FOR YOU TO DUPLICATE A KEY TO THE MAIL BOX . THANKS .	7/19/2005 Medium	Gerardo Marquez Hector Lozoya		Santa Teresa ES
3884	Work In Progress check football field lights	7/27/2005 Medium	Carlos Castillo Carlos Castillo	Elevator	Santa Teresa HS
3885	Work In Progress welding shop needs 8 more welders	7/27/2005 Medium	Carlos Castillo Carlos Castillo	Classroom	Santa Teresa HS
3452	Work In Progress 7-06-05 8.0 PAINTING CLASS ROOMS 7/6 - 8	7/11/2005 Medium	Joel Herrera Joel Herrera		Santa Teresa HS
3678	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Luis Murillo		Santa Teresa HS
3930	Work In Progress NEED WEST DOOR HANDLE IN WOODSHOP REPLACED IT IS BROKEN, HANDLE JUST TURNS, AND DOOR WILL NOT OPEN.	7/29/2005 Medium	Arturo Nunez Hector Lozoya		Santa Teresa HS
3658	Work In Progress NEED TEN (10) MD63 KEYS MADE FOR STAFF. THANK YOU..	7/19/2005 Medium	Arturo Nunez Hector Lozoya		Santa Teresa HS
3630	Work In Progress NEED A MD 10 AND A #478 FOR GROUNDS AND FOOTBALL STORAGE	7/18/2005 Medium	Arturo Nunez Hector Lozoya		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3571	Work In Progress NEED CONDENSER MTR. FOR SNACK ROOM A.C. UNIT, MTR. IS FROZEN UNIT IS DOWN.	7/15/2005 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS
3329	Work In Progress Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3351	Work In Progress Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
4011	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
3378	Work In Progress I need to do to get the bucket truck and an operator, to remove speakers at STHS football field. Thanks Carlos Vigil	7/7/2005 Medium	Alfredo Holguin Carlos Castillo	Football Field	Santa Teresa HS
3974	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3228	Work In Progress Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Santa Teresa HS
3265	Work In Progress Monthly - Santa Teresa HS Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
3276	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
4022	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
3158	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3176	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3206	Work In Progress Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Santa Teresa HS
3177	Work In Progress Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3159	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
4023	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3476	Work In Progress The Old marquee that is next to the building has not been removed. There should be an old WO for this. Ms. Williams wants to know why this was not removed when they removed the one by the road.	7/12/2005 Medium	Lorenzo Hernandez		Santa Teresa MS
3277	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3267	Work In Progress Monthly - Santa Teresa MS Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3229	Work In Progress Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Santa Teresa MS
3975	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
4013	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3353	Work In Progress Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3330	Work In Progress Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3679	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Ismael Rodriguez		Santa Teresa MS
3118	Work In Progress I NEED FOR GYM KEY CYLINDERS TOO TO BE CHANGE BEFORE 7/13/05.CONT.MR.RODRIGUEZ.	7/1/2005 Medium	Ismael Rodriguez Hector Lozoya		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3465	Work In Progress N.bldg home ec rm 10. Ruben Ronquillo I am going to need a Miter saw to cut legs on ten of the tables. please make sure it has a good blade. I am planning this project for next week (7/18/05.) The wood is oak.	7/12/2005 Medium	Jaime Mijarez Ruben Ronquillo		Santa Teresa MS
3387	Work In Progress Rm 1. N. bldg lower level Removal of carpet is going to require tile installation. Alfredo H. requested a work order for contractor.	7/7/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
3412	Work In Progress S.bldg upper level. Because of the shortage of classrooms Mrs. williams has to move the teachers lounge to a storage rm. The floor has no tile, can you include this room with the area's that the contractor will be installing floor tile. Attn: Alfredo holguin.	7/8/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
3891	Work In Progress S.bldg counselors office. Heatpump needs to be replaced. The compressor gave out and is still under warranty.	7/28/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
3364	Work In Progress S.bldg custodial storage. please make 2ea. A-7 keys for principal and building mechanic.	7/6/2005 Medium	Jaime Mijarez Hector Lozoya		Santa Teresa MS
3872	Work In Progress NEED REPLACEMENT KEYS FOR ROOM 40	7/27/2005 Medium	Irene Trujillo Hector Lozoya	Classroom	Sunland Park ES
3875	Work In Progress NEED REPLACEMENT KEYS FOR NURSE'S OFFICE DORR AND FILE CABINET	7/27/2005 Medium	Irene Trujillo Hector Lozoya		Sunland Park ES
3447	Work In Progress 7/5/05 4-FINISH ROOM 41- 4-START TO PAINT ROOM 25 7/5 - 8	7/11/2005 Medium	Sebastian Diaz Margret Villalobos		Sunland Park ES
3436	Work In Progress 7/11/05 need to replace door knob in main entrance northwest and check some doors need parts thank you	7/11/2005 Medium	Sebastian Diaz Hector Lozoya		Sunland Park ES
3680	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Larry Flores		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4014	Work In Progress Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3976	Work In Progress Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3423	Work In Progress Yearly - Sunland Park ES Emer. Light Test: Annual - Refer to PM schedule details.	7/10/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3355	Work In Progress Yearly - Sunland Park ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3230	Work In Progress Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Sunland Park ES
3278	Work In Progress Monthly - Sunland Park ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3268	Work In Progress Monthly - Sunland Park ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
4024	Work In Progress Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3160	Work In Progress Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3179	Work In Progress Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3181	Work In Progress Monthly - Sunrise ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
4016	Work In Progress Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
4025	Work In Progress Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
3143	Work In Progress Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3270	Work In Progress Monthly - Sunrise ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
3279	Work In Progress Monthly - Sunrise ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
3629	Work In Progress please cut and weedeat in and around lift station. weeds are growing rapid and are going to end up on the playing fields.	7/18/2005 Medium	Paul Quinones		Sunrise ES
3231	Work In Progress Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Sunrise ES
3354	Work In Progress Yearly - Sunrise ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
3959	Work In Progress Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
3681	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Ramon Dominguez		Sunrise ES
3331	Work In Progress Yearly - Sunrise ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Paul Quinones		Sunrise ES
3469	Work In Progress FENCING AREA IN BACK OF SCHOOL NEAR LIFT STATION NEEDS TO BE REPAIRED,AND ROLL GATE.PROBABLE HIGH WINDS ON 7-11-05 CAUSED THE DAMAGE.NO SIGNS OF VANDILISM ON SCHOOL PROPERTY	7/12/2005 Medium	Paul Quinones Michael Munoz		Sunrise ES
3477	Work In Progress I NEED SAND FOR THE PLAY GROUNDS, THANKS.	7/12/2005 Medium	Paul Quinones Lorenzo Hernandez		Sunrise ES
3876	Work In Progress RM.307,BAD CIRCULATING PUMP NEED TO REPLACE	7/27/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3533	Work In Progress Could you turn the air conditioning on we have teachers coming in to get a head start on their rooms. It is very hot and we would greatly appreciate it. Since we are a year round school the teachers need to report on Monday. Thank-you	7/14/2005 Medium	Joanne Munoz Jaime Gomez	Classroom	Sunrise ES
3232	Work In Progress Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Vado ES