

663 - Work Orders In Progress (7/1/05 - 10/31/05)

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3982	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3981	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3960	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3312	Work In Progress Yearly - Alma Del Valle Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3308	Work In Progress Yearly - Alma Del Valle Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Alma Del Valle Daycare
3661	Work In Progress NEED TO COMPLETE PERFORMANCE INSPECTION ON ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN AUGUST 5, 2005.	7/19/2005 4/26/2005 Medium	Aida Salcedo Carlos Lujan		Anthony ES
6221	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Jimmy Carbajal		Anthony ES
6148	Work In Progress vaccum need to be fix the screws came losse and they got lost the screws	10/4/2005 Medium	Carlos Lujan Jimmy Carbajal		Anthony ES
6005	Work In Progress Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Hector Villalobos		Anthony ES
4487	Work In Progress plese grade and add crusher fine for neww parking for parents and add parking curbs.	8/11/2005 Medium	Guadalupe Ontiveros		Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4097	Work In Progress please scrape and add crusher fine along with parking curbs.see mike	8/2/2005 Medium	Guadalupe Ontiveros		Anthony ES
5285	Work In Progress KNIFE BROKE ON MIXERS BLADE ASSEMBLY	9/6/2005 Medium	Danny Orozco Danny Orozco	Cafeteria	Anthony ES
3899	Work In Progress room 201 bad capert half is bad replace with tile	7/28/2005 Medium	Hector Villalobos Michael Munoz	Classroom	Anthony ES
4255	Work In Progress room 109 needs carpet repair	8/8/2005 Medium	Hector Villalobos Michael Munoz	Classroom	Anthony ES
4581	Work In Progress old main blg a/c motor burn out a 3 hp volts 230	8/15/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
4742	Work In Progress need a 3/4 hp motor cafeteira motor burn out old cafeteria	8/22/2005 Medium	Hector Villalobos Jaime Gomez	Cafeteria	Anthony ES
4743	Work In Progress mild cafeteria burn motor 3/4 hp with a belt 4-L 660 or 670	8/22/2005 Medium	Hector Villalobos Jaime Gomez	Cafeteria	Anthony ES
4478	Work In Progress Chapter bg p.e room replace 3/4 motor with a 1hp motor	8/11/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
4861	Work In Progress Nurse office refrigerator is not working water is leaking from seal	8/24/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
5944	Work In Progress Old main blg boiler room needs a thermocuple size 56 inch	9/29/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
5992	Work In Progress upper primary boiler is leaking replace	9/30/2005 Medium	Hector Villalobos Jaime Gomez		Anthony ES
6586	Work In Progress heater is not working need to replace parts	10/20/2005 Medium	Hector Villalobos Jose Ambriz	Cafeteria	Anthony ES
6587	Work In Progress Boiler needs parts valve is leaking	10/20/2005 Medium	Hector Villalobos Jaime Gomez	Mechanical Room	Anthony ES
6588	Work In Progress Chapter blg p.e room heater needs parts	10/20/2005 Medium	Hector Villalobos Jaime Gomez	Classroom	Anthony ES
6797	Work In Progress In all 4 praking lot put up sings	10/27/2005 Medium	Hector Villalobos Hector Villalobos	Parking Lot	Anthony ES
6794	Work In Progress Portables replace broken boards on ramps and deck 218 219 220 221	10/26/2005 Medium	Hector Villalobos Danny Miranda	Portables	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5090	Work In Progress new oven is completely down. Becky S. SNP Mgr 882-3507	8/30/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Anthony ES
6556	Work In Progress 2 - Freezers at AE4-6 Campus/Freezer #1 temp is at 18 / Freezer #2 food is 1/2 frozen 1/2 thaw Becky S. SNP Mgr 882-3507	10/19/2005 Medium	Jacqueline Aguilar Danny Orozco	Custodial	Anthony ES
4059	Work In Progress DAYCARE - NEED TO ISSUE KEYS TO CORINA VALDESPINO for (Krishna's Office). WILL BE HERE AT 8:00 AM TOMORROW.	8/1/2005 Medium	Margret Villalobos Manny Lozoya		Anthony ES
5338	Work In Progress WALK - IN FREEZER IS LEAKING ALOT OF WATER BETWEEN THE FREEZER AND REFRIG. ELSA - 882-2417	9/8/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Berino ES
3434	Work In Progress WASHING MACHINE DOES NOT WORK ANY MORE. (IT GAVE UP) ELSA CHAIRZ - SNP MGR 882-2417	7/11/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Berino ES
5898	Work In Progress Need 2 new keys for office gate and recut master key for Mr Silva THANKS OFFICE KEY IS ON YOUR KEY CHAIN ALREADY	9/28/2005 Medium	Jimmy Cortez Manny Lozoya		Berino ES
5585	Work In Progress need nemaster b key and 55key for new custodian thanks a.s. p	9/19/2005 Medium	Jimmy Cortez Manny Lozoya		Berino ES
4055	Work In Progress please cut weeds and pick-up debris on east side of rockwall. (i.e weeds bottles cinder blocks.)	8/1/2005 Medium	Ramiro Holguin		Berino ES
4208	Work In Progress MOBILE HOME OCCUPANT WILL BE RECEIVING NEW MOBILE HOME ON APPROXIMATELY 8-29-05. PLEASE CONNECT ELECTRICAL. 28X54	8/4/2005 Medium	Enrique Sotelo		Berino ES
6023	Work In Progress Monthly - Berino ES Roof Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Ramiro Holguin		Berino ES
4082	Work In Progress Monitoring Wells - I need a set of keys to the monitoring well caps	8/2/2005 Medium	Alfredo Holguin Manny Lozoya		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6222	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Jimmy Cortez		Berino ES
6447	Work In Progress DISHWASHER CHEMICAL DESPENSERS NOT WORKING RIGHT HAS TO BE CHECK OUT	10/17/2005 Medium	Ramiro Holguin Danny Orozco		Berino ES
6863	Work In Progress Monthly - DP-91 CES - Refer to PM schedule details.	10/31/2005 Medium	Alfredo Holguin Ricardo Jacquez		Chaparral ES
4518	Work In Progress please replace urinal and commode in mens restrrom.	8/12/2005 Medium	Joe Ontiveros	Mechanical Room	Chaparral ES
6123	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Juan Vargas		Chaparral ES
5951	Work In Progress room 31 need change 8 fluorescent lighting troffer	9/29/2005 Medium	Juan Vargas Enrique Sotelo		Chaparral ES
6502	Work In Progress room 72 heating not work need help to fix	10/18/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
6395	Work In Progress north side nesesito que enparejar	10/13/2005 Medium	Juan Vargas Guadalupe Ontiveros		Chaparral ES
6415	Work In Progress cafeteria exit sign need change	10/14/2005 Medium	Juan Vargas Enrique Sotelo		Chaparral ES
6343	Work In Progress las vanquetas need grabo a round	10/12/2005 Medium	Juan Vargas Guadalupe Ontiveros		Chaparral ES
6885	Work In Progress ruben nesesito 5-galones pintura amarillan 2-azul 1-blanca de para pintar el main parking	10/31/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
6728	Work In Progress ruben nesesito 4 metal signs 1-principal 1-secretary 2-assistant principal y tambien los tubos	10/25/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
3846	Work In Progress 07/26/05 j. gomes rooms 2 -20-21- 51-47-107-44- 55-46- need replace A/C 6500	7/26/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3801	Work In Progress 5/25/05/ mike neseito que pongan sistema de riego para los arboles	7/25/2005 Medium	Juan Vargas Guadalupe Ontiveros		Chaparral ES
3800	Work In Progress 07/25/05 jaime gomes main office need new A/C two 4500 and one 6500	7/25/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
3868	Work In Progress ROOMS 83-82-81-80-72-96-70 NEED WINDOWS REPAIRED OR REPLACE 2-REPORT	7/27/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
4030	Work In Progress Room 47 need to instaled a/c ventilation	8/1/2005 Medium	Juan Vargas Jaime Gomez		Chaparral ES
4213	Work In Progress Rooms 101-102-60-62-61-54-70-96-72-73-97 80-82-83 need carpet repace	8/4/2005 Medium	Juan Vargas Michael Munoz		Chaparral ES
5053	Work In Progress need to be replaced front area gate doors and chain link fence as mr. cardona	8/30/2005 Medium	Juan Vargas Michael Munoz		Chaparral ES
4602	Work In Progress ruben ronquillo need 10 pvc 45 elbows 6 inches 10 square grate basin 6 inches and 200 ft. 6 inches pvc pipe	8/16/2005 Medium	Juan Vargas Joe Ontiveros		Chaparral ES
3284	Work In Progress 07/05/05 mike munoz Mr. cardona quiere bertical blind en su oficina size 82 width and 80 length	7/5/2005 Medium	Juan Vargas Ruben Ronquillo		Chaparral ES
4797	Work In Progress repair storage, boy,s , girl,s r.r. @ chaparral elem	8/22/2005 Medium	Danny Miranda Danny Miranda		Chaparral ES
5498	Work In Progress sweeper/blower/not/working/choke/broken	9/14/2005 Medium	Daniel Ramirez Jimmy Carbajal		Chaparral ES
6714	Work In Progress vaccum/cleaner/motor/not/working	10/25/2005 Medium	Daniel Ramirez Jimmy Carbajal		Chaparral ES
6555	Work In Progress wheels/on/vaccum/cleaner/broken	10/19/2005 Medium	Daniel Ramirez Jimmy Carbajal		Chaparral ES
6529	Work In Progress Had done a work order before for Ms. Barrett about fixing her windows needs a screen.She says they still haven't done the work order. Thanks	10/18/2005 Medium	Jennifer Corral Ruben Ronquillo	Classroom	Chaparral ES
4110	Work In Progress Rm-72 Ms. Barret needs screens on her windows. Says they were suppose to be put in last year.	8/3/2005 Medium	Jennifer Corral Ruben Ronquillo	Classroom	Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3945	Work In Progress Air Conditioner smells like burn and is not cold in rm-128 for Ms. Word	7/29/2005 Medium	Jennifer Corral Jaime Gomez	Classroom	Chaparral ES
3946	Work In Progress Air Conditioner not working in rm-20 for Ms. Gary	7/29/2005 Medium	Jennifer Corral Jaime Gomez	Classroom	Chaparral ES
3871	Work In Progress need an extra key for Even start classroom, Jeannette rm-118	7/27/2005 Medium	Jennifer Corral Manny Lozoya	Classroom	Chaparral ES
3785	Work In Progress NEED A KEY FOR ROOM 114,LEDESMA REPRINT FOR MANNY - REGARDING E-MAIL 7/27/05 - MKV	7/22/2005 Medium	Jennifer Corral Manny Lozoya	Classroom	Chaparral ES
3299	Work In Progress I need some keys for two of the new administators who will be coming to this school. They have requested main keys to the gate that opens up the fence outside the school and also a set of main keys for the building. If you can please do as soon as possible. Keys for Chaparral Elementary.	7/5/2005 Medium	Jennifer Corral Manny Lozoya	Office	Chaparral ES
4042	Work In Progress Need sensor replaced in girls locker room lavatory.	8/1/2005 Medium	Joe Ramirez Joe Ontiveros		Chaparral MS
3720	Work In Progress 7/12/05. need a/c replaced on portable 1 rm. 2 please.	7/20/2005 Medium	Joe Ramirez Jaime Gomez		Chaparral MS
6558	Work In Progress 10/19/05. we need propane tank filled for portable housing rms. 1&2. ATTEN. RUBEN.	10/19/2005 10/21/2005 Medium	Joe Ramirez Ruben Ronquillo		Chaparral MS
6245	Work In Progress Need lightbulb replaced parking lot area, will probably need Boom truck. ASSINGED TO E.SOTELO	10/10/2005 10/26/2005 Medium	Joe Ramirez Enrique Sotelo		Chaparral MS
6246	Work In Progress Need about 2 yards base coarse for use around pond area.	10/10/2005 Medium	Joe Ramirez Guadalupe Ontiveros		Chaparral MS
3607	Work In Progress need to paint new door @ football storage rm.	7/18/2005 Medium	Danny Miranda Joe Ramirez		Chaparral MS
3608	Work In Progress need to paint new door @ rm. 86	7/18/2005 Medium	Danny Miranda Joe Ramirez		Chaparral MS
6369	Work In Progress (CHAPARRAL MIDDLE SCHOOL) need snake to unclogg drain to classroom sinks in the main building. (science room #103)	10/13/2005 Medium	Johnny Acuna Joe Ontiveros		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4072	Work In Progress Room 208 - Mold on ceiling tiles. (Nancy, Nurse @ site called in) - mkv Margaret, Joe replied and said there where a couple of ceiling tiles with small mold droppings on them. He replaced them. However still go ahead and generate a w.o. for our records and have him fill it out. Mike	8/2/2005 Medium	Mary Garcia Joe Ramirez	Classroom	Chaparral MS
6086	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
6084	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
4485	Work In Progress please take a load of crusher fine so sewer line. Ak David (plumbing) for the specifics.	8/11/2005 Medium	Guadalupe Ontiveros	Portables	Chaparral MS
4031	Work In Progress Please level around ponding and surrounding areas. Check with Mr.Diggs	8/1/2005 Medium	Guadalupe Ontiveros		Chaparral MS
3648	Work In Progress please get with speedy and have him train you on the sprikler system on football field and thru out campus. Identify all valves and repair what is needed. also ask him for a key for sprinkler box and have him teach you the programs.	7/19/2005 Medium	Joe Ramirez	Football Field	Chaparral MS
3649	Work In Progress need to cut weeds and grass behind library and courtyard and surrounding areas tru -out campus including pond. Also need to irrigate these areas also.	7/19/2005 High	Joe Ramirez		Chaparral MS
3650	Work In Progress please paint railing on new portables that where installed and modified and all railings that are in need.	7/19/2005 Medium	Joe Ramirez		Chaparral MS
3656	Work In Progress please put up fence where portables where installed even if its on a temp bases.	7/19/2005 Medium	Joe Ramirez	Football Field	Chaparral MS
5463	Work In Progress need to pour landing and sidewalks to portables by football feild.	9/13/2005 Medium	Michael Munoz	Portables	Chaparral MS
5204	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3990	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3988	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3977	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3964	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
6008	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
5229	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
5227	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
6048	Work In Progress Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		Chaparral MS
6057	Work In Progress Monthly - Chaparral MS Fire Suppression Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		Chaparral MS
4586	Work In Progress garbage disposal is clogged up	8/16/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Chaparral MS
4772	Work In Progress walk-in refrigerator/fan is making alot of noise Sandra Diaz - SNP Manager 824-4376	8/22/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Chaparral MS
3307	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3336	Work In Progress Yearly - Chaparral MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3243	Work In Progress Monthly - Chaparral MS Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3241	Work In Progress Monthly - Chaparral MS Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3191	Work In Progress Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Orozco		Chaparral MS
3314	Work In Progress Yearly - Chaparral MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
3148	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez		Chaparral MS
5062	Work In Progress I NEED 1 MALE WATER HOSE CONNECTOR, 1 HX-1 VINYL ANCHOR KIT AND 1 WEJIT DRY WALL AUGER ANCHOR KIT SIZE 8. THANK YOU	8/30/2005 Medium	Robert Gonzalez Jimmy Carbajal		Chaparral MS
3499	Work In Progress We need locks to be installed on the center pole to the double doors in the front entrance,north east doors and south east doors. This is the oldest part of the school. the newer part of the school already have locks on the center poles. This old doors are the once that we use more often. This locks will make it so much faster and easier. THANK YOU ROBERT	7/13/2005 Medium	Robert Gonzalez Manny Lozoya		Chaparral MS
5563	Work In Progress STILL HAVING PROBLEMS WITH THE BURNISHER THAT JOSE USES. VERY HARD TO PUSH. THANK YOU	9/16/2005 Medium	Robert Gonzalez Jimmy Carbajal		Chaparral MS
3439	Work In Progress NEED KEYS FOR TWO NEW PORTABLES.	7/11/2005 Medium	Vickie Reed Manny Lozoya	Portables	Chaparral MS
3717	Work In Progress NEED BACKHOE TO CLEAN OUT POND AREA.	7/20/2005 Medium	Vickie Reed Lorenzo Hernandez		Chaparral MS POND
3855	Work In Progress NEED TO REKEY CABINET.	7/26/2005 Medium	Vickie Reed Manny Lozoya	Classroom	Chaparral MS 204
4639	Work In Progress NEED 3 REPLACEMENT KEYS FOR 3 A-34'S THAT DO NOT WORK.	8/17/2005 Medium	Vickie Reed Manny Lozoya	Office	Chaparral MS VICKIE-KEY
4509	Work In Progress need to rekey file cabinets. 2	8/12/2005 Medium	Vickie Reed Manny Lozoya	Classroom	Chaparral MS 104
3185	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin David Acosta		Desert Pride

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3337	Work In Progress Yearly - Desert Pride Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3315	Work In Progress Yearly - Desert Pride Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3248	Work In Progress Monthly - Desert Pride Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3244	Work In Progress Monthly - Desert Pride Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
6223	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo David Acosta		Desert Pride
3165	Work In Progress Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
6368	Work In Progress principal requests - to add crush fine to parking lot and bus turn around to help keep the dust down	10/13/2005 Medium	David Acosta Guadalupe Ontiveros	Parking Lot	Desert Pride
5959	Work In Progress need to ckeck a/c blower . It stops blowing	9/29/2005 Medium	David Acosta Jose Ambriz	Classroom	Desert Pride #1
5294	Work In Progress NEED OUTSIDE NIGHT LIGHT BETEEW LAST PORTABLE AND END OF CAMPUS. ALSO NEED LIGHT BULK FOR NIGHT LIGHT BETEEW 2ND BUILDING AND PUMP HOUSE	9/6/2005 Medium	David Acosta Carlos Castillo	Classroom	Desert Pride
5336	Work In Progress Principals requests: for dead bolt locks for last portable (where break-in occur)	9/8/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride #6,7.
4642	Work In Progress need one key for storage closet for teacher in room #3	8/17/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride 3
3942	Work In Progress need emergency light and exit signs check out.	7/29/2005 Medium	David Acosta Carlos Castillo	Office	Desert Pride

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4304	Work In Progress need locks for two doors to the hall way, that needs to be use as storage for science rooms.	8/8/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride #3,4
3791	Work In Progress need plastic name plates(12)MS. S. VERLANDER, MS. I. RAMIREZ, MS. BACH-HAGUE, MS. B. COSTULIS, MS. C. MCDONALD, MR. C. VELA, MR. P. WYMAN, MS. G. PARKER, MS. S. GARCIA, MR. D. NEAL , MS. J. ZAPATA, MS. D. DEAN	7/25/2005 Medium	David Acosta Manny Lozoya	Classroom	Desert Pride
6025	Work In Progress Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
6045	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
5218	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
5230	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
5234	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3979	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3995	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
3991	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
4992	Work In Progress please remove marquee sign from desertveiw and install at desert pride. please be careful when removing.see mike	8/29/2005 Medium	Guadalupe Ontiveros		Desert Pride
6091	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin David Acosta		Desert Pride
6087	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin David Acosta		Desert Pride

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4460	Work In Progress I need an office key for Ms. Maes, Clerk at Desert Pride Academy	8/10/2005 Medium	Mary Telles Manny Lozoya	Office	Desert Pride
6884	Work In Progress Marquee Light not working properly. (vice-principal)	10/31/2005 Medium	Johnny Acuna Enrique Sotelo		Desert Trail Intermediate
6886	Work In Progress need (2) security lights fixed: One in the parking lot and the other in the playground area closest to mobile home.	10/31/2005 Medium	Johnny Acuna Enrique Sotelo		Desert Trail Intermediate
6883	Work In Progress need a lock (J-11) for new gate that was installed located in the fence between CH. ELEM and CH. DESERT TRAIL closest to Lisa ST. (To be locked during LOCK DOWN events). Thank You !!!!!!!	10/31/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
6841	Work In Progress need a heating and cooling t-stat for portable #408 unit.	10/28/2005 Medium	Johnny Acuna Lorenzo Solis		Desert Trail Intermediate
6846	Work In Progress fire-proof filing cabinet inside vault: please fix or replace lock.	10/28/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
5426	Work In Progress need a replacement heating coil (Boiler System) in the Cafeteria/Gym. (Old one Leaks)	9/12/2005 Medium	Johnny Acuna Jaime Gomez		Desert Trail Intermediate
6170	Work In Progress please repair or replace door knob in the kitchen going outdoors in the back:(door jams and is hard to open) Thank You !!!!!!!!!!!!!!!!!!!!!	10/4/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
3739	Work In Progress DIAG/PSYCH ROOM NEED (2) CLASSROOM KEYS MADE. CORE IS: J-53	7/21/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
3619	Work In Progress MENS RESTROOM (NW HALL) : PLEASE CHANGE DOOR CYLINDER WHERE KEY ENTERS TO OPEN UP DOOR. STUDENTS STUFFED IN CYLINDER WITH CLAY AND HARDENED. THANK YOU !!!!!!!	7/18/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
3620	Work In Progress NEED NAME PLATES TO BE MADE: (1) PRINCIPAL, (1) ASSISTANT PRINCIPAL, (1) COMPUTER LAB	7/18/2005 Medium	Johnny Acuna Manny Lozoya		Desert Trail Intermediate
4116	Work In Progress need a replacement single knob water faucet for room #112.	8/3/2005 Medium	Johnny Acuna Joe Ontiveros		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4558	Work In Progress Mrs. Bonham (Asst. Principal) requesting concrete slab to be installed between portable #412 and #413 art studio.	8/15/2005 Medium	Johnny Acuna Michael Munoz		Desert Trail Intermediate
6266	Work In Progress RUSH ! or as soon as possible or Monday even. Could I get a line locate for Desert Trails Portables?	10/11/2005 Medium	Carlos Vigil Enrique Sotelo		Desert Trail Intermediate
6294	Work In Progress need help with scraping in back, front, and fencelines of desert trail school grounds. Thank You !!!!!!!	10/11/2005 Medium	Johnny Acuna Guadalupe Ontiveros		Desert Trail Intermediate
5462	Work In Progress need to demo and repour concrete to sectioned area by cafeteria.	9/13/2005 Medium	Michael Munoz	Desert Trail Intermediate Cafeteria	
5233	Work In Progress Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
5228	Work In Progress Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
5205	Work In Progress Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
6026	Work In Progress Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
3166	Work In Progress Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Johnny Acuna		Desert Trail Intermediate
6224	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Guillermo Hernandez		Desert Trail Intermediate
4149	Work In Progress key cylinder to walk-in refrigerator doesn't lock, key continously goes round and round, please repair as soon as possible, groceries and commodities are stored in there.	8/3/2005 Medium	Alma Terrell Manny Lozoya	Cafeteria	Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6225	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Miguel Aguilar		Desert View ES
3317	Work In Progress Yearly - Desert View ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
3339	Work In Progress Yearly - Desert View ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Patricio Aguilar		Desert View ES
5616	Work In Progress REQUESTING (2) "R" KEYS, ONE FOR NEW COUNSELOR, Mr. David Gonzalez and the other one to replace Ms. Esther Maldonado's "R" key. (Bended Key) Please pick up bended key with Margarita Terrazas at the front office	9/19/2005 Medium	Margarita Terrazas Manny Lozoya		Desert View ES 5055891180
4083	Work In Progress TEACHER DESK WITH LOCKING DRAWER, DOES NOT LOCK. ROOM#19, LOWER GRADE SIDE. MRS. GRISWOLD	8/2/2005 Medium	Margarita Terrazas Manny Lozoya		Desert View ES
5340	Work In Progress MOUSE PROBLEM. MOUSE GOT ON THE TABLE WHILE EATING MARTHA FLORES - 589-2425 HELP PLEASE	9/8/2005 Medium	Jacqueline Aguilar Margret Villalobos	Cafeteria	Desert View ES
6477	Work In Progress second requist on wo 123783 12/15/04 wo 115914 7/22/04 play grounds need 10 truck louds of play ground sand need 4 trucks of pressure crush need rain drains cleaned out need sand moved from rock wall need sand moved off drive way and back up hill	10/17/2005 Medium	Patricio Aguilar Guadalupe Ontiveros		Desert View ES
6788	Work In Progress electrician frount school grounds need the elect line repaired to maeqee	10/26/2005 Medium	Patricio Aguilar Carlos Castillo		Desert View ES
6697	Work In Progress electrician frount school grounds need the elect line repaired to marqee	10/24/2005 Medium	Patricio Aguilar Carlos Castillo		Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4781	Work In Progress pat aguilar rock wall (safety concern) 6 rock wall metal gates need to be replaced rusted throw	8/22/2005 Medium	Patricio Aguilar Michael Munoz		Desert View ES
6455	Work In Progress Need heavy amounts of sand/dirt removed from road leading to backside of school parking lot, mud and debri causing a hazard. Hard rains exposed many water pipes and created many deep crevices, also a hazard for students.	10/17/2005 Medium	Miguel Aguilar Guadalupe Ontiveros		Desert View ES
5145	Work In Progress Urgent: Need center pole repaired in exterior double door on east side of school repaired, pole fell and struck teacher. Door cannot be fully secured and will compromise security after school hours.	9/1/2005 Medium	Miguel Aguilar Manny Lozoya		Desert View ES
5146	Work In Progress Need copies (3) made of padlocks on hall doors, need for sub keys and replacement.	9/1/2005 Medium	Miguel Aguilar Manny Lozoya		Desert View ES
4182	Work In Progress B-Wing - Human Resources Dept Please spray Lucy Garcia's & Ms. Browder's office for bugs (crickets, centerpedes, etc.)	8/4/2005 Medium	Mary Garcia Margret Villalobos		GAC
3460	Work In Progress AS PER JULIE HERNANDEZ, NEED ELECTRICIAN TO CONNECT WIRES WITH AN END CONNECTION TO BE ABLE TO PLUG CONNECTION TO THE WALL. (CALL JULIE @ 6417 BEFORE COMING)	7/12/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC A WING
4925	Work In Progress C Wing- Having problems with mice.	8/25/2005 Medium	Mary Garcia Margret Villalobos		GAC
4655	Work In Progress AS PER ANN STEINHOFF-NEEDS 1 MORE GRAND MASTER KEY FOR HER SECRETARY AT PRE-K	8/17/2005 Medium	Mary Garcia Manny Lozoya	Office	GAC WHOLE BUILDING
5796	Work In Progress AS PER CORA-NEEDS THE DOOR LOCK TO THE DATA CENTER SWITCHED OUT FROM SWIPE CARD TO A COMBINATION LOCK. (MANNY, PLEASE SEE CORA BEFORE CHANGING OUT)	9/23/2005 Medium	Mary Garcia Manny Lozoya	Computer Lab	GAC DATA CENTER- TECHNOLOGY
6743	Work In Progress AS PER MS. BERRY-NEEDS 3 SIGNS THAT SAY SLOW CHILDREN TO PUT IN THE ENTRANCE AND PARKING AREA. TALKED WITH RUBEN RONQUILLO AND KNOW WHICH SIGNS TO ORDER	10/25/2005 Medium	Mary Garcia Ruben Ronquillo		GAC PARKING AREA

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6811	Work In Progress AS PER GLORIA SAENZ- LIGHTS ARE NOT TURNING ON MANNY PROSPERO IS ALREADY AWARE OF WHICH LIGHTS	10/27/2005 Medium	Mary Garcia Carlos Castillo	Office	GAC
3408	Work In Progress AS PER CARLOS VIGIL-NEEDS A GRAND MASTER 7, ASAP. (HIS BROKE IN HALF) ALREADY TALKED WITH MANNY LOZOYA	7/8/2005 Medium	Mary Garcia Manny Lozoya	Office	GAC ALL SCHOOLS
3432	Work In Progress AS PER LINDA REYES-NEED FURNITURE FROM 3 OFFICES & BOXES ALONG WITH THIS TO BE MOVED A.S.A.P. TO NEW AREA IN C-WING. STAFF WILL START WORKING IN THESE NEW OFFICES BY TOMORROW.	7/11/2005 Medium	Mary Garcia Manuel Prospero	Office	GAC C WING
5557	Work In Progress THE A/C IN THE CAFETERIA IN PRE-K IN NOT WORKING AND IN ON WARANTY. AS PER MR. DAVID BOYD.	9/15/2005 Medium	Manuel Prospero David Boyd		GAC
6525	Work In Progress I NEED 3 EXOST MOTOR FOR C WING V 115 HZ 60 PH 1 HP 1/20 AO AMPS 1.7 NO.7108-5136 RPM 1500. AND AIR FILTERS 20X20XX2. 16X20X2. 16X20X1. 20X25X2. 16X25X2. AS PER JOSE AMBRIZ.	10/18/2005 Medium	Manuel Prospero Jose Ambriz		GAC
4377	Work In Progress NEED NEW R. R. PARTITIONS IN "A" WING AS PER MENNY PROSPERO	8/9/2005 Medium	Manuel Prospero Danny Miranda		GAC
5824	Work In Progress NEED A WATERHOSE AND ALSO A HOSE ROLL A WAY.2 WATERHOSE ONE FOR THE PATIO AND ONE FOR THE PRE KINDER AREA I ONLY HAVE ONE AND I USE IT FOR THE FRONT AREA,THE HOSE ROLL A WAYS I NEED ONE FOR EACH HOSE THANK YOU FOR YOUR CONTINUED SUPPORT YOU ARE THE BEST!!!!	9/26/2005 Medium	Jimmy Carbajal Sal Acuna	Custodial	GAC
3282	Work In Progress C-WING - TAKE OFF TILE AND INSTALL NEW TILE (TILE HAS BEEN DELIVERED), ALSO FINISH PAINTING. WILL SEND GERRY MARQUEZ TO ASSIST.	7/5/2005 Medium	Alfredo Holguin Manuel Prospero		GAC
6050	Work In Progress Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		GAC
6061	Work In Progress Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6802	Work In Progress AS PER GINGER BERRY, REQUESTED TO BORROW MINI STAGE FROM GH -CHIRSTINA MUNOZ. NEED TO PICK UP, DEL & SET UP IN CAFETERIA. ALSO NEED TO HELP SET UP CAFETERIA TABLES INTO BENCHES. NEED TO PICK UP STAGE ON 10/28/05 A.M.	10/27/2005 Medium			GAC
3546	Work In Progress Technology Server Room-Install Battery powered Emergency lighting in this room	7/14/2005 Medium	Carlos Castillo		GAC
6226	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Ralph Lara		GAC
6270	Work In Progress I would like to request a 120v outlet to be installed above kitchen (dock entrance side) door for door horn.	10/11/2005 Medium	Carlos Vigil Danny Orozco		GAC
4612	Work In Progress Need a bucket operator and a bucket truck at GHS football field some time this week.	8/16/2005 Medium	Carlos Vigil Danny Orozco	Football Field	Gadsden HS
4626	Work In Progress Attn. JOSE AMBRIZ; This w/o is for the pilow block bearings that I, called for.Need two more 1 3/16 THANK YOU!!!	8/17/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
5101	Work In Progress ATTN. JOSE AMBRIZ need about ten three pole contactors for the a/c's nighth set back system in the ACADEMIC BLDG. Some burned out by the power outage.Thank you!!	8/30/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
4902	Work In Progress AG BLDG entry door,won't open or lock key just turns;Also WOOD SHOP entry door new lock doesn't work	8/25/2005 Medium	Fernando Moncayo Manny Lozoya		Gadsden HS
4305	Work In Progress NORTH bus entrance gate keep falling, bottom rail all bend;Also needs new roller bearings for both gates thank you !!! [safety hazard]	8/8/2005 Medium	Fernando Moncayo Michael Munoz		Gadsden HS
4240	Work In Progress Need six wheels for large gates in NORTH parking lot THANK YOU!!! 8/11 - Route to Ruben as per Mike	8/5/2005 Medium	Fernando Moncayo Ruben Ronquillo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4307	Work In Progress Room 244-245 HVAC unit not working properly too many problems. m#d136090g20025b- s#nls361523	8/8/2005 Medium	Fernando Moncayo Jose Ambriz		Gadsden HS
4311	Work In Progress PANTHER HUT porch entrance too dark security ligh dosen't work	8/8/2005 Medium	Fernando Moncayo Fernando Moncayo		Gadsden HS
3726	Work In Progress Attn electrician need a better security ligths by CONCESSION STAND to control vandalism	7/20/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
3593	Work In Progress Need to repair or replace electrical conduit outside of CONCESSION STAND by GIRL'S GYM	7/15/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
6607	Work In Progress LIBRARY EAST wall;There is a, wall keyed hose bib that is leaking	10/20/2005 Medium	Fernando Moncayo David Villalobos		Gadsden HS
6609	Work In Progress Need to install flouresent ligh lamps in ANNEX CORRIDOR, is too dark	10/20/2005 Medium	Fernando Moncayo Michael Mc Dermott		Gadsden HS
6489	Work In Progress VARSITY GYM; girl's BASKETBALL locker room,water heater is leaking from bottom of tank	10/17/2005 Medium	Fernando Moncayo David Villalobos		Gadsden HS
6756	Work In Progress ATTN.RUBEN RONQUILLO;Please order four signs with 8in letters.for outside restrooms. 2-women 2-men THANK YOU!!	10/26/2005 Medium	Fernando Moncayo Ruben Ronquillo		Gadsden HS
5622	Work In Progress Attn. MANNY LO TOYA , need four pad locks for new electrical panels at SWIMMING POOL and storages under bleachers ASAP please!! THANK YOU!!	9/19/2005 Medium	Fernando Moncayo Manny Lozoya		Gadsden HS
5943	Work In Progress Attn. MIKE MUNOZ need about ten parking stops[parking curb]on refrence from w/o# 5464 thank you!!	9/28/2005 Medium	Fernando Moncayo Michael Munoz		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6227	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Jesus Estrada		Gadsden HS
3168	Work In Progress Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS
3319	Work In Progress Yearly - Gadsden HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
3141	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
5962	Work In Progress please install a couple of l-brackets to desk where new electrical was installed. see mr.carrasco in auto shop	9/29/2005 Medium	Fernando Moncayo		Gadsden HS
4916	Work In Progress please check and repair leak & secure drop ceiling in rm 142. possible safety hazard.	8/25/2005 Medium	Danny Miranda		Gadsden HS
5464	Work In Progress Need to paint stripings for student parking lot and east of Auto Shop.	9/13/2005 Medium	Michael Munoz	Parking Lot	Gadsden HS
5458	Work In Progress need to restripe all parking lines ,handi-cap-arrowa etc.	9/13/2005 Medium	Michael Munoz	Parking Lot	Gadsden HS
4448	Work In Progress Telescope observatory locate on the west side of the baseball field - Installl fencing around it to prevent vandalism	8/10/2005 Medium	Michael Munoz		Gadsden HS
3659	Work In Progress PLease install stair treads when they come in. Old english stair ways. I will order. See Mike INstall from main to old english stairs. FAXED PO 8/4/05 - MKV	7/19/2005 Medium	Mario Apodaca	Stairway	Gadsden HS
6097	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS
6028	Work In Progress Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Mario Apodaca		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6001	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ontiveros		Gadsden HS
5768	Work In Progress NEED A NEW FAUCET AT ROOM 229 FOR MR PALMER LAB SINK	9/22/2005 Medium	Mario Apodaca David Villalobos		Gadsden HS
5842	Work In Progress NEED A NEW GLASS PUT ON CONCESSION STAND WINDOW AT FOOTBALL FIELD (VANDALISM) 23X23 ASAP	9/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
5708	Work In Progress THE OUTSIDE OUTLET NEED TO BE FIX AT WEIGHT ROOM	9/21/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
6308	Work In Progress NEED SCISSOR LIFT TO FIX SCOREBOARD AT V- GYM FOR CARLOS V ON 10-13-05	10/11/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
6526	Work In Progress NEED TOO RUN SEWER SNAKE AT WOOD SHOP BLDG unclog main sewer line to woodshop	10/18/2005 10/19/2005 Medium	Mario Apodaca David Villalobos		Gadsden HS
6595	Work In Progress OUTSIDE CONDUIT AT ROOM 233 NEED TO BEREPAIR SO IT CAN'T BE PULL OFF THE WALL ON MORE AND THE KID CAN'T USE THE CONDUIT AS A LADDER TO GATING UP TO THE ROOF TOP	10/20/2005 Medium	Mario Apodaca Michael Mc Dermott	Restroom (Boys)	Gadsden HS
6425	Work In Progress NEED TO REMOVE ALL OUTLET AT ROOM 126 AT ARE ON BOOK SHEVING FLOOR AND RELOCA OUTLETS	10/14/2005 Medium	Mario Apodaca Michael Mc Dermott	Custodial	Gadsden HS
6777	Work In Progress GLASS AT CAFETERIA 24X60 TINT NEED TOBE REPLACES VANDALISM	10/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
4502	Work In Progress NEED TO LAMPES AT WOOD SHOP SAME ARE BURNED OUT	8/11/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
5108	Work In Progress NEED TO PUT NEW BALLAST AT WOOD SHOP LAMPES	8/31/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
4849	Work In Progress NEED A NEW THERMOSTAT FOR BIG PAN	8/23/2005 Medium	Mario Apodaca Danny Orozco		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4970	Work In Progress GLASS AT MAIN BLDG HALLWAY 40X18 NEED TOBE REPLACES VANDALISM	8/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
4976	Work In Progress NEED ALL WINDOW BLINDSON OLD ENGLISH BLDG 40 EA 40WX90L	8/26/2005 Medium	Mario Apodaca Ruben Ronquillo		Gadsden HS
3524	Work In Progress NEED TO FIX FOOTBALL FIELD SCOREBOARD BREAKER BOX	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
3525	Work In Progress NEED TO CK ALL FOOTBALL FIELD LAMPS	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott		Gadsden HS
3645	Work In Progress BOTH OVENS ARE DOWN. LYDIA M. SNP MGR 882-5522	7/19/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Gadsden HS
3479	Work In Progress All Campus - Need to replace old door knobs w/new levers.	7/12/2005 Medium	Hector Lozoya Manny Lozoya		Gadsden HS
4212	Work In Progress need metal door @ frame for dugout storage	8/4/2005 Medium	Danny Miranda Danny Miranda		Gadsden HS
4726	Work In Progress Royal vacuum is missing bag and brush, belt serial No.H93266101B GISD tag 014131	8/19/2005 Medium	Jesus Estrada Jimmy Carbajal		Gadsden HS
5915	Work In Progress Pressbox - There is a Bee Hive in pressbox. Having a game tomorrow. Please send someone out today. (Open PO) as per A. Holguin.	9/28/2005 Medium	Jesus Estrada Margret Villalobos	Football Field	Gadsden HS
4814	Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Air conditioner still does not work. No air is coming out of vents, very hot. Wires hanging into light fixture and a piece of ceiling tile (broken) is in one of the air conditioning vents. (room was damaged over summer)	8/23/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4811	Work In Progress Requested by Mr. Cordova Storage Room in Varsity Gym Stage-The door needs to be re- keyed to an off master key, light board room. 4 keys are needed.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4812	Work In Progress Requested by Lt. Dickerson Rm. 202 North Building-His HEM key has broken, 3 HEM keys are needed. One for him and two for the key box.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4815	Work In Progress Requested by Priscilla Martinez Rm. 605 Business Building-Two HJ masters are needed, one for Priscilla and one for key box.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4816	Work In Progress Requested by Ms. L. Melendrez Rm. 331 Academic Building-I have been having trouble opening my front door for over a year, and now I am having trouble opening the back door. It's not my key it's the door handle and deadbolts. Both back doors are very difficult to open.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4817	Work In Progress Requested by Mr. S. Perez Weight Room-Boys locker room door handle needs repair does not open. West side Weight Room door needs repairs does not lock.	8/23/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4819	Work In Progress Requested by Mr. S. Perez Weight Room-Water fountain does not give cold water.	8/23/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS
4810	Work In Progress Requested by Ms. L. Chavez Rm. 245 Classroom Over Varsity Gym-Re-place several burned out light bulbs. RE-ROUTE TO BUILDING MECHANIC as per Mike Mc Dermott 9/19/05	8/23/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4820	Work In Progress Requested by Luis Saucedo Rm. 507 & 509 Annex Building-Install door stops on each of these doors.	8/23/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4821	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- The boys bathroom door handle is very loose, needs to be tightened.	8/23/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4822	Work In Progress Requested by Ms. Zapien Rm. 154 Old English Building-The blinds are completely broken, the curtain is hanging.	8/23/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4905	Work In Progress Requested by Mr. Milligan Rm. 143 Old English Building-Four keys are needed of HX2. Three for the assistant coaches and one for key box.	8/25/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4908	Work In Progress Requested by Mr. Myers Rm. 506 Annex Building- Front door needs adjustment, it will not lock unless it is slammed.	8/25/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4915	Work In Progress Requested by Mr. Myers Rm. 506 Annex Building- The room needs more electrical outlets on the east and north walls. For computer setup-plugs on floor are a safety issue.	8/25/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4914	Work In Progress Requested by Mr. Myers Rm. 506 Annex Building- There is no air coming out of the vents of the A.C.	8/25/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4904	Work In Progress Requested by Mr. D. Gallegos Rm. 403-Please install water fountains with hose bibs, between soccer canopies for Athletic events and Gadsden High School P.E. classes.	8/25/2005 Medium	Velia Alarcon Guadalupe Ontiveros		Gadsden HS
4897	Work In Progress Requested by Velia Rm. 112 Front Office-Two HE27 are needed for key box.	8/25/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5066	Work In Progress Requested by Ms. Anderson Rm. 233 North Building(Panther Hut)-Clothes Dryer takes several hours to dry clothes. Order new heating element or check and see if vent is clogged. 9/23 - Route to Mario as per Mike.	8/30/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
5068	Work In Progress Requested by Ms. Anderson Rm. 233 North Building (Panther Hut)-Replace circuit breakers with ones that can handle the load of appliances in the kitchen so we don't constantly trip them. Note from Mr. Chambers: Question? Check and see if appliances can be re-routed to another outlet? Too many appliances on one outlet will cause fire.	8/30/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
5083	Work In Progress Requested by Mr. Martin Rm. 551 Wood Shop- Hall lock will no unlock, 2nd Notice.	8/30/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5076	Work In Progress Requested by Ms. Anderson Rm. 233 North Building (Panther Hut)-Pastry refrigerator has severe condensation dripping.	8/30/2005 Medium	Velia Alarcon Danny Orozco		Gadsden HS
5084	Work In Progress Requested by Velia Press Box-Safety Hazard; need to re-duct and install new air conditioner were it can be serviced. FERNANDO, JOSE WILL LOOK INTO ORDERING UPDRAFT UNIT AND SHEETMETAL. AS PER OUR CONVERSATION YOU AND MARIO WILL FORM AND POUR CONCRETE FOR SMALL PAD FOR A/C STAND. IN THE MEAN TIME SERVICE WHAT IS THERE. - M. MUNOZ 9/1/05-MKV XC: WO TO FERNANDO	8/30/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4947	Work In Progress Old English Bldg - Heating is turning on and on the computer it states that it is off. Teachers have been complaining on a daily basis that it is too hot. Need your help!	8/26/2005 Medium	Velia Alarcon Margret Villalobos		Gadsden HS
4516	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-New water heater for kitchen area of Panther Hut. Route to Bldg Mechanic as per Mike 8/15/05 Check to see whats wrong with the H2o heater they have new one in small mech. room.	8/12/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4521	Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Need a lock and spare keys on the new filing cabinet.	8/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4519	Work In Progress Requested by Mr. Grace Rm. 603 Business Building-Electrical outlets by teacher's desk and west wall do not work. Also, need electrical outlets by television disconnected from light switch.	8/12/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4380	Work In Progress Requested by Velia Rm. 112 Front Office-Five D49 are needed, key to men's restroom in the Main Building.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4381	Work In Progress Requested by Velia Rm. 112 Front Office-Five DX are needed, key to women's restroom in the Main Building.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4385	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-Two large shop lights are burned out.	8/9/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4386	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-220 Volt Electric extension cord needed with a new female end, current ones puts people at risk of electrocution.	8/9/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4387	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-Need a new oil pressure gauge for air compressor. (0-30 PSI) Current gauge leaks compressor oil out of crankcase and on to the floor. Need a new air pressure gauge for air compressor, current gauge is to small. Need a 0-150PSI gauge.	8/9/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4359	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional key are needed of HJ13, one for the floating teacher and one for the Key Box. For room number 609.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4360	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HJ7, one for the floating teacher and one for the Key Box. For room number 753.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4361	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK1, one for the floating teacher and one for the Key Box. For the Auto Shop.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4362	Work In Progress Requested by Velia Rm. 112 Front Office-We need 5 additional keys of HE1. For the Gyms.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4363	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK5, one for the I.A. in the classroom and one for the key box. For room number 569.	8/9/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4429	Work In Progress Requested by Velia Rm. 112 Front Office-Three HE keys are needed for Key Box.	8/10/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4633	Work In Progress Requested by ISS Rm. 800 Old Counseling Center-Door frame falling off portable door leading to the old counseling center.	8/17/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS
4629	Work In Progress Requested by Mr. Dixon Rm. 600 Business Building-Two keys of M114 for the Varsity Gym bathrooms. One for Mr. Dixon and one for key box.	8/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4630	Work In Progress Requested by Mr. Dixon Rm. 600 Business Building-Needs an F3 gate key.	8/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4563	Work In Progress Requested by Ms. Moreno Rm. 126 Main Building-Install white board.	8/15/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4562	Work In Progress Requested by Ms. Klein Rm. 504 Annex Building-Air conditioner not working and appears to be leaking.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4564	Work In Progress Requested by Ms. Nanez Library-Install plywood baks to magazine shelves.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4627	Work In Progress Requested by Velia Rm. 112 Front Office-Work order #3911 was not asked to me made off master, also three keys were asked for not two. An additional 4 keys are needed as soon as possible.	8/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4631	Work In Progress Requested by Ms. M. Gonzalez Rm. 140 Old English Building-I would like to request a door stop for the new door and blinds fo one of my windows. The room gets "very" warm espcially 4th period. Receive measurements from Bldg Mechanic and re-route to Ruben for ordering. 4 ea - 43" W x 90' L	8/17/2005 9/16/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
4288	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-Lights are burned out in the shop.	8/8/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
4272	Work In Progress Requested by Ms. Klein Rm. 504 Annex Building-Having a hard time locking and opening door, appears to be locked but stays unlocked.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4279	Work In Progress Requested by Ms. Littlefield Rm. 226 North Building-The lock on my podium and one storage cabinet is brocken and lost.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4283	Work In Progress Requested by Mr. Myers Rm. 509 Annex Building-Key will not open storage door. HJ10 is the key that should open door.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4286	Work In Progress Requested by Mr. Villa Rm. 510 Band Room-Need two HK13 keys made.	8/8/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4268	Work In Progress Requested by Ms. Hunt Rm. 105 Main Building-Roof leaks. 8/11 - Route to Fernie as per Mike	8/8/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4271	Work In Progress Requested by Ms. Kalkwarf Rm. 750 Barracks-Floor tiles are broken and coming off the floor.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4285	Work In Progress Requested by Mr. Villa Rm. 510 Band Room-Security light in the center of the room does not work.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4248	Work In Progress Requested by Ms. Gutierrez Rm. 823 Barracks- New cylinder is needed for new filing cabinet, 3 keys are needed.	8/5/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4243	Work In Progress Requested by Ms. Bradley Rm. 602 Business Building-Handle on window has broken off, needs to be replaced.	8/5/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
4282	Work In Progress Requested by Mr. Martinez Rm. 227 North Building-Replace carpet in Attendance Office area. One edge of the carpet is lifting, our concern is that a person may trip and fall.	8/8/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
4269	Work In Progress Requested by Ms. Jacquez Rm. 752 Barracks- Window is unhinged and needs to be repaired.	8/8/2005 Medium	Velia Alarcon Ruben Ronquillo		Gadsden HS
4199	Work In Progress Requested by Mr. Chambers Rm. 110 Front Office-Re-key doors, make cylinders off D Master, 4 keys will be needed. Have had several items stolen from office, please re-key as soon as possible.	8/4/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
4222	Work In Progress Requested by Mr. Grubaugh Rm. 275C Library- The door to the video room has swollen and will not shut properly unless its slammed.	8/4/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS
4204	Work In Progress Requested by Cathy Cano Parking Lot-Over Fall Break, have the lines in the North Parking Lot painted.	8/4/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
4166	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace ceiling tile in storeroom and office.	8/3/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
4153	Work In Progress Requested by Mary Barreras Rm. 130 Old English Building-Need the new key to new lock to Sp. Ed. storage room for files and equipment. Key # M260	8/3/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3754	Work In Progress Requested by Velia Rm. 800 Old Counseling Center Portable-Doors need to be re-keyed as soon as possible. This portable will be used as the ISS classroom, 4 keys are needed.	7/21/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3715	Work In Progress Requested by Mr. Pawloski Rm. 109A Main Building (Sp.Ed. Office)-Please remove the lock in my file cabinet, replace, and re-key it with a new one.	7/20/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3716	Work In Progress ***URGENT***Requested by Velia Library-All the doors in the library need to be secured. They have changed all the door knobs and the cylinders need to be installed. URGENT library has alot of equipment that needs to me locked and secured!	7/20/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3910	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Bracket needed for N.M. Flag.	7/28/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
3902	Work In Progress Requested by Ms. Marquez New Counseling Portable-Two filing cabinets need to be keyed.	7/28/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3920	Work In Progress Requested by Velia Front Office-The cylinder for room #107 will not open with a D Master or key assigned to door. This classroom is the Day Care on our campus and the building custodian can not open the classroom to clean. Please fix as soon as possible.	7/28/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
3908	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Dr. Pockets to be placed in Marie's copy to be placed on wall.	7/28/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
3909	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Install clock on wall.	7/28/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
3493	Work In Progress Requested by Pamela Holguin Rm. 228 North Building-A door frame is needed. Will have an old door installed, left over from doors that are being replaced in North Building. Also, a door knob that will not lock is needed.	7/12/2005 Medium	Velia Alarcon Danny Miranda		Gadsden HS
3494	Work In Progress Requested by Marie New Counseling Center Portable-New portable needs to be keyed HE134. Change old cylinder to doors of new portable doors.	7/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5601	Work In Progress Requested by Ms. Thornley Rm. 660 Business Building-No heat/A.C. in lounge. Please attempt to tie into the ducting in my classroom (it has it's own system and is immediately adjacent) so that our lounge can be more comfortable.	9/19/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS
5798	Work In Progress Requested by Mr. D. Gallegos Rm. 406 Boys Gyn-Roof leaks, air conditioner condensation.	9/23/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5412	Work In Progress Requested by D. Gallegos Rm. 403 Boys Gym- Install threaded end on faucet or shower in volleyball and boys basketball lockers to allow for a water hose connection.	9/12/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
5414	Work In Progress Requested by Mr. G. Holguin Rm. 342 Academic Building-Cabinets in room need to be stabilized.	9/12/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
5416	Work In Progress Requested by Mrs. Klein Rm. 504 Annex Building- Roof is leaking, one spot has mold, and one panel is buldging down.	9/12/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
5405	Work In Progress Requested by Velia Rm. 112 Front Office-HG3 is needed for key box.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5406	Work In Progress Requested by Velia Rm. 112 Front Office-Two SA16 are needed, one for Ms. Dominguez and one for key box.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5407	Work In Progress Requested by Marie School Registrar Storage Room East Wing of the Cafeteria-The new vault needs to be re-keyed. The cylinder from the old vault can be placed on the door of the East Wing of the Cafeteria were her new vault is located now.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
5409	Work In Progress Requested by Marie Storage Room in the East Wing of the Cafeteria-In the move from the old vault to the storage room one of the fire prove filing cabinet's locks broke. The filing cabinet remained locked, needs to be fixed as soon as possible as the Registrar needs access to these files on a daily basis.	9/12/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
6833	Work In Progress Requesed by Luis Saucedo Main Building-East and west hallways the light switches are broken. Having a problem turning on the lights every morning. Light switches on each corner.	10/28/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
6843	Work In Progress Requested by Velia Rm. 112 Front Office-On 8/23/05 Work Order # 4812 was entered, Lt. Dickerson's HEM key had broken and an additional two keys were needed for key box. Lt. Dickerson did recieve his new key from Manny the locksmith, but the two additional keys were not cut or issued to me. Luis Saucedo's (Custodian) HEM key has worn out and needs replacing. Pleace have Manny complete Work Order # 4812.	10/28/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6832	Work In Progress Requested by Ms. Pena Rm. 128 North Building- Plugged kitchen sink.	10/28/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
6834	Work In Progress Requested by Luis Saucedo Rm. 502 Weight Room-2ND REQUEST Both sinks are loose from the base and the water drains to slow and the urinal has a leak in the base.	10/28/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
6830	Work In Progress Requested by Velia Rm. 127 Main Building-When the sound system contractors installed the wiring in Ms. Garcia's classroom. They placed it on a wall Ms. Garcia used for her projector. Once they removed the wiring and placed it on another wall, they left the wall scrated and paint peeled. Wall needs to be repaired and painted.	10/28/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6831	Work In Progress Requested by Ms. L. Chavez Rm. 402 B.Gym Girls Basketball Office-A SA16 key is need for Coach S. Alvarado. A work order has been placed for this key already (Work Order # 5406), but only two keys were asked for. A total of three keys are needed now.	10/28/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
6835	Work In Progress Requested by Luis Saucedo Rm. 507 Annex Building-The door knob turns around and around with the key inside.	10/28/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS
6713	Work In Progress Requested by Ms. Trich Library-Please replace blown light bulbs, especially in Librarian's office, room 275b.	10/25/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6710	Work In Progress Requested Ms. Nanez Library-Backs to shelves need to be installed. Backs are in library, however, they need to be cut down to fit.	10/25/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
6704	Work In Progress Requested by Mr. Lawrence Rm. 402 Boys Gym (Offices)-Please fumigate, roach infestation.	10/25/2005 Medium	Velia Alarcon Margret Villalobos		Gadsden HS
6711	Work In Progress Requested by Ms. A. Torres Rm. 200 North Building-Do not turn off A.C. Teacher has student with special needs, if temparture is not low student becomes ill and A.C. unit is currently not cooling.	10/25/2005 Medium	Velia Alarcon Jose Ambriz		Gadsden HS
6289	Work In Progress Requested by Ms. Trich Rm. 275a Library-Please flush trap or pump sewage to eliminate the odor of raw sewage in the girl's bathroom.	10/11/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6280	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Replace or repair ceiling tile in office. Second Request	10/11/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
6282	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Paint (or provide paint)for repainting the tool room and paint room. Second Request	10/11/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
6286	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Install circuit with sufficient amperage to run Drum Sander. Second Request	10/11/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
6287	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Route stationery power tools through central emergency shut off. Second Request	10/11/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
6288	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Replace burned out transformer for overhead lights. Second Request	10/11/2005 Medium	Velia Alarcon Michael Mc Dermott		Gadsden HS
6274	Work In Progress Requested by Mr. Chambers Varsity Gym- Varsity Gym floor is showing large space and boards are coming loose, needs repair a.s.a.p. SAFETY ISSUE	10/11/2005 Medium	Velia Alarcon Michael Munoz		Gadsden HS
6272	Work In Progress Requested by Velia Rm. 112 Main Building-Sink is leaking, the base is warped and growing mold.	10/11/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
6273	Work In Progress Requested by Velia Rm. 100 Main Building-All of the doors and drawers need to be tightened, they're all off their tracks or broken.	10/11/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6285	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Replace burned out lights in paint room.	10/11/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6454	Work In Progress Requested by Mr. Chambers Football Restrooms- Paint large letters on restroom indicating men's and women's sides, or hang large signs indicating directions.	10/17/2005 Medium	Velia Alarcon Fernando Moncayo		Gadsden HS
6460	Work In Progress Requested by Mr. Whitener Rm. 563 Ag. Shop- Install a hydraulic door closer on the new front door to the building.	10/17/2005 Medium	Velia Alarcon Manny Lozoya		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6459	Work In Progress Requested by Ms. A. Torres Rm. 200 North Building-A new device was placed in my room and needs help putting it together.	10/17/2005 Medium	Velia Alarcon Mario Apodaca		Gadsden HS
6457	Work In Progress Requested by Ms. Littlefield Rm. 226 North Building-Sink faucet needs to be fixed. Faucet is leaking and she will be having labs soon.	10/17/2005 Medium	Velia Alarcon David Villalobos		Gadsden HS
5119	Work In Progress Power Outage - El Paso Electric	8/29/2005 Medium	Margret Villalobos Enrique Sotelo		Gadsden MS
6384	Work In Progress Light by main entrance is not working.	10/13/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
6386	Work In Progress Light on the westside of the bandroom doesnt turn on.	10/13/2005 Medium	Rudy Arreola Enrique Sotelo		Gadsden MS
5569	Work In Progress VOC BLDG RM#306 - Need some assistance changing out ballast already replaced lamps high ceiling.	9/16/2005 Medium	Rudy Arreola Enrique Sotelo	Classroom	Gadsden MS
5793	Work In Progress {{{GYM LOBBY}}} Wall needs to be secured.	9/23/2005 Medium	Rudy Arreola Danny Miranda	Restroom (Boys)	Gadsden MS
5918	Work In Progress Door handle is broken off boys lockerroom	9/28/2005 Medium	Rudy Arreola Manny Lozoya		Gadsden MS
5317	Work In Progress Need to cap of water lines and drain removed already removed sink and counters. RM#188.	9/7/2005 Medium	Rudy Arreola Joe Ontiveros	Classroom	Gadsden MS
5985	Work In Progress We can borrow the 935 to cut around bus turn around and behind annex and football field.	9/30/2005 Medium	Rudy Arreola Guadalupe Ontiveros		Gadsden MS
4218	Work In Progress Coil in not cooling cleaned out strainer and checked valve. RM 156	8/4/2005 Medium	Rudy Arreola Jaime Gomez	Classroom	Gadsden MS
4220	Work In Progress Rm 157/158 Unit is not cooling at all cleaned out strainer and checked valves.	8/4/2005 Medium	Rudy Arreola Jaime Gomez	Classroom	Gadsden MS
4725	Work In Progress Portable 500/501 really leak bad right in the center of the room.	8/19/2005 Medium	Rudy Arreola Rudy Arreola	Portables	Gadsden MS
4528	Work In Progress We need 2 water fountains replaced in cafeteria.	8/12/2005 Medium	Rudy Arreola Jaime Gomez		Gadsden MS
3616	Work In Progress replace door at pump room	7/18/2005 Medium	Ricardo Jacquez Danny Miranda		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4867	Work In Progress THE PAD HOLDER IS WORN OUT AND WONT HOLD THE PAD AT ALL.	8/24/2005 Medium	Jimmy Carbajal Jimmy Carbajal	Hallway/Corridor	Gadsden MS
3582	Work In Progress IRRIGATION CTRL PANEL - IRRIGATION BOOSTER PUMP IS NOT WORKING. PLEASE TROUBLESHOOT BUS TURNAROUND AREA. ROUTED TO ENRIQUE AS PER RICK 8/2/05	7/15/2005 8/2/2005 Medium	Lorenzo Hernandez Enrique Sotelo		Gadsden MS
4095	Work In Progress please fiill hole that is in front of entrance to band room. Will need a backking before gravel is applied. see mike	8/2/2005 High	Rudy Arreola		Gadsden MS
5961	Work In Progress please reomve and replaced stained ceiling tiles in Mr.Lowenburgs office.	9/29/2005 Medium	Rudy Arreola		Gadsden MS
6424	Work In Progress WE NEED LIGHTS IN THE BOYS & GIRLS RR IN MAIN BLDG, ALSO WE NEED THE LIGHTS IN HALLWAYS AS PER PM 6095.	10/14/2005 Medium	Enrique Sotelo		Gadsden MS
6500	Work In Progress please cut weeds around and inside tennis courts	10/18/2005 Medium	Guadalupe Ontiveros	Football Field	Gadsden MS
6499	Work In Progress please order and install gutters, on east portable mold is growing please remove as per trainging.	10/18/2005 Medium	Rudy Arreola	Portables	Gadsden MS
6228	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Juan Acosta		Gadsden MS
4778	Work In Progress 2nd request for an "A" master for GMS Campus	8/22/2005 Medium	Dana Hamel Manny Lozoya	Office	Gadsden MS
4777	Work In Progress The three locks on the office front window are broken, mostly poor design. The front office is wide open until these are repaired or replaced	8/22/2005 Medium	Dana Hamel Rudy Arreola	Office	Gadsden MS
4643	Work In Progress Need a copy of fire alarm key (See Mr. Hamel for his key).	8/17/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
4522	Work In Progress Door broken in room 500, and window shattered	8/12/2005 Medium	Dana Hamel Danny Miranda	Portables	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4982	Work In Progress Whole south side of annex does not have any air, class temperatures are above 95 degrees. The classes opposite hallway have conditioning, Please fix ASAP	8/26/2005 Medium	Dana Hamel Jaime Gomez	Classroom	Gadsden MS
4863	Work In Progress Need extra keys to Key storage cabinet	8/24/2005 Medium	Dana Hamel Manny Lozoya	Office	Gadsden MS
3651	Work In Progress Mice in Gloria Hernandez office in C Wing. Need control as soon as possible 1) HAD JUAN CHECK FOR ANY FOOD AROUND, 2) REQUESTED THAT THEY ASK R. RONQUILLO FOR MICE TRAPS (W/GLUE) 3) FAXED FOR PRICE QUOTE AS PER M. MUNOZ FOR THE WHOLE C-WING.	7/19/2005 Medium	Dana Hamel Margret Villalobos	Office	Gadsden MS
3652	Work In Progress Cockroach issues for the total school, need a monthly spraying Faxed PO - 8/4/05 -mkv	7/19/2005 Medium	Dana Hamel Margret Villalobos	Hallway/Corridor	Gadsden MS
3653	Work In Progress paint the columns on outside of gym	7/19/2005 Medium	Dana Hamel Rudy Arreola	Gym	Gadsden MS
3654	Work In Progress paint over the scratchouts in boys black restrooms	7/19/2005 Medium	Dana Hamel Rudy Arreola	Restroom (Boys)	Gadsden MS
3655	Work In Progress paint the front columns of the school to remove tagging	7/19/2005 Medium	Dana Hamel Rudy Arreola		Gadsden MS
5347	Work In Progress Mr. Hamel needs an "A" master for GMS campus 3rd request	9/8/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
5499	Work In Progress Change M4 key to a G key in all electrical room on campus, we have no "m" master	9/14/2005 Medium	Dana Hamel Manny Lozoya	Electrical Room	Gadsden MS
5500	Work In Progress change A3 key to a "g" key in storage room in annex	9/14/2005 Medium	Dana Hamel Manny Lozoya	Mechanical Room	Gadsden MS
5501	Work In Progress Repair the outside doors locks "w" master will not open doors to lobby	9/14/2005 Medium	Dana Hamel Manny Lozoya	Hallway/Corridor	Gadsden MS
5502	Work In Progress request 3 new "G" keys for principal and custodians	9/14/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
5834	Work In Progress replace the stalls in restroom by nurses office (urinals)	9/26/2005 Medium	Dana Hamel Danny Miranda	Restroom (Boys)	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5832	Work In Progress Key both locks in registrar area (Gloria Hernandez) to the A 53 key	9/26/2005 Medium	Dana Hamel Manny Lozoya	Office	Gadsden MS
5975	Work In Progress Need 1 each of the following keys for box, A88,A86,WA83, WA88,WA148, WA25, WA8 and three O2 keys (Mr. Hamel also)	9/29/2005 Medium	Dana Hamel Manny Lozoya		Gadsden MS
6241	Work In Progress The new roof on the vocational building leaked badly over vacation and the insulation in the old woodshop is falling. Serious problem with students returning tomorrow could fall at any time.	10/10/2005 Medium	Dana Hamel David Boyd	Classroom	Gadsden MS
4195	Work In Progress Gate by canal road still needs to be replaced. Gate not secure and needs to be replaced. (chain is not strong enough).	8/4/2005 Medium	Yolie Jacquez Michael Munoz		Gadsden MS
6229	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Armando Diaz		La Mesa ES
5116	Work In Progress cockroach problem Laura Benavidez - SNP Manager 233-2646	8/31/2005 Medium	Alma Terrell Margret Villalobos	Cafeteria	La Mesa ES
5309	Work In Progress Milk Cooler was at 60 degrees this morning 9/7/05	9/7/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	La Mesa ES
4229	Work In Progress lupe antiv. need helped to cut large branch by picnic table safety issue	8/5/2005 Medium	Frank Lara Guadalupe Ontiveros		La Mesa ES
4446	Work In Progress DANNY NEED BUCKET TO BRING ROPE DOWN TO TIE OTHER END, CAME OF	8/10/2005 Medium	Frank Lara Danny Orozco		La Mesa ES
4378	Work In Progress locksmith need three keys for supply rm. key no F 49 8/23- Debra needs status on this work order submitted on 8/9/05 - mkv	8/9/2005 Medium	Frank Lara Manny Lozoya		La Mesa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5117	Work In Progress Lights in computer room keeps going out; breaker needs to be checked.	8/31/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4853	Work In Progress SINK AT CUSTODIAL CLOSET AT OLD BLDG. IS CLOGGED UP.	8/24/2005 Medium	Santos Galindo David Villalobos		La Union ES
5425	Work In Progress We need Vector Control to come in and spray.	9/12/2005 Medium	Santos Galindo Margret Villalobos		La Union ES
4825	Work In Progress Need keys for room #100, #106, and room #108; plus keys for a file cabinet in the nurse's office.	8/23/2005 Medium	Santos Galindo Manny Lozoya		La Union ES
4775	Work In Progress Parking lanes need to be repaint in yellow and bus lane also needs to be repaint but in red. Route to Sal Gonzalez as per Mike 9/13/05 -mkv	8/22/2005 Medium	Santos Galindo Salvador Gonzalez		La Union ES
4695	Work In Progress AUGUST 31 IS OPEN HOUSE WOULD LIKE ALL LIGHTS OUT SIDE TO BE CHECKED BEFORE THEN.	8/19/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4356	Work In Progress in room 202 there is no outlet for refrigeration unit a.s.p.	8/9/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4408	Work In Progress a light next to my office need to be looked at cause it buzzes all day long.	8/10/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4410	Work In Progress They need to check lighting from building cause several lights are off. And some stay on 24 hrs out side.	8/10/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4223	Work In Progress need an electrical outlet by computer hookups room 203.	8/5/2005 Medium	Santos Galindo Carlos Castillo		La Union ES
4372	Work In Progress need a fan motor in electrical storage room.	8/9/2005 Medium	Santos Galindo Jose Ambriz		La Union ES
5312	Work In Progress After last nights rainfall, leaks were discovered in rooms #208, #209, and the library.	9/7/2005 Medium	Santos Galindo Lorenzo Solis		La Union ES
5371	Work In Progress In the women's restroom, in the southwing, the toilet is constantly flushy.	9/9/2005 Medium	Santos Galindo Salvador Gonzalez		La Union ES
6719	Work In Progress need floor tile in lounge	10/25/2005 Medium	Santos Galindo Michael Munoz	Office	La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6718	Work In Progress need electrical outlet on north wall	10/25/2005 10/26/2005 Medium	Santos Galindo Carlos Castillo	Office	La Union ES
6403	Work In Progress NEED CORK STRIP INFRONT OF THE OFFICE IN HALLAWAY.	10/14/2005 Medium	Santos Galindo Ruben Ronquillo		La Union ES
6418	Work In Progress Work Truck - need to repair broken tial-light.	10/14/2005 Medium	Salvador Gonzalez Angel Gonzales		La Union ES
6840	Work In Progress OFFICE - NEED GLUE BOARD OR MICE TRAPS.	10/28/2005 Medium	Salvador Gonzalez Ruben Ronquillo	Office	La Union ES
5786	Work In Progress Upper hinge on door at JTP needs to be repair. Might need to be weld	9/23/2005 Medium	Salvador Gonzalez Manny Lozoya		La Union ES
5503	Work In Progress Old emergency light fixtures (the complete system) are not working can you check them please. thank you	9/14/2005 Medium	Salvador Gonzalez Carlos Castillo		La Union ES
5949	Work In Progress Music Room needs a new circuit installation.	9/29/2005 Medium	Salvador Gonzalez Carlos Castillo		La Union ES
4864	Work In Progress JTP- Rosaro Ruedas needs a L201 key.	8/24/2005 Medium	Selma Nevarez Manny Lozoya		La Union ES JTP
5447	Work In Progress Student Cross Walk - Path on the west side there is a tree that is in the way. Students have to scoot over onto the street.	9/12/2005 Medium	Margret Villalobos Alfredo Holguin		La Union ES
3572	Work In Progress NEED LIGHT BULBS FOR RECESSED LIGHTS AT LA UNION ELEM. THE MAJORITY ARE BURNED OUT. THANK YOU.	7/15/2005 Medium	Arturo Nunez Carlos Castillo		La Union ES
3322	Work In Progress Yearly - La Union ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES
6230	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Santos Galindo		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6476	Work In Progress LUJTP - INSTALL DRYER (NEED VENT DIRECTED OUT OF BLDG - OKAYED BY MR. ALVAREZ). PLEASE CALL MR. CASVANTES @ 589-3009 IF YOU NEED ANY INFORMATION.	10/17/2005 Medium	David Villalobos		La Union ES
4917	Work In Progress please repair asphalt where other water line was repaired.	8/25/2005 Medium	Michael Munoz		La Union ES
3344	Work In Progress Yearly - La Union ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza		La Union ES
3345	Work In Progress Yearly - Loma Linda ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
6051	Work In Progress Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		Loma Linda ES
6066	Work In Progress Monthly - Loma Linda ES Fire Suppression Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		Loma Linda ES
5568	Work In Progress As per Mike Munoz issue a 6 & 7 Grand Master keys to Mike Mc Dermott.	9/16/2005 Medium	Manny Lozoya		Loma Linda ES
6686	Work In Progress INSTALL ELECTRICAL CIRCUIT IN ROOM 208 FOR MICROWAVE AND FRIDGE.	10/24/2005 Medium	Grace Alvarado Enrique Sotelo		Loma Linda ES
6665	Work In Progress NEEDS TO REPAIR DUMPSTER PAD THAT WAS BUILT. REPLACE TWO BENCHES ON PLAYGROUND. AND LEVEL PLAYGROUND AREA WITH SCRAPER	10/24/2005 Medium	Grace Alvarado Guadalupe Ontiveros		Loma Linda ES
6829	Work In Progress ATTN: MIKE LIGHTS IN ROOM 208, SPLITTING???????	10/28/2005 Medium	Grace Alvarado Michael Mc Dermott		Loma Linda ES
6888	Work In Progress NEEDING STORAGE CABINETT REPAIRED. PREFERRABLY A LATCH AND LOCK. SOMETHING TO KEEP CABINETT CLOSED	10/31/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
6342	Work In Progress NEEDING COAT RACK MOVED IN ROOM 202	10/12/2005 Medium	Grace Alvarado Michael Mc Dermott		Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3829	Work In Progress MR. TRUJILLO IS WANTING NEW KEYS MADE FOR DESKS, CABINETTS AND FILE CABINETS. ALSO NEEDING NAME PLATE FOR NEW TEACHERS. MS. BERARD, CHAVEZ-FISHER, GRIEGO, DESANTIAGO, HUGHES, MARKHAM, MEDINA, MERRICK, MONTES, PINA, PRICE, RIOS-ALVILLAR,	7/26/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
4315	Work In Progress MANNY LOZOYA, FIX LOCK IN 212	8/8/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
4316	Work In Progress MANNY LOZOYA: KEY MADE FOR PORTABLES WILL NOT OPEN STORAGE ROOM. MASTER WILL NOT OPEN STORAGE ROOM. NEEDING STORAGE ROOM OPENED AS SOON AS POSSIBLE.	8/8/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
4317	Work In Progress MANNY LOZOYA: NEEDING KEYS FOR BOOK ROOM, ROOM #208, AND KEY #44	8/8/2005 Medium	Grace Alvarado Manny Lozoya		Loma Linda ES
4330	Work In Progress NEEDING COAT RACK HOOKS IN ROOM #203 & 207& 201	8/8/2005 Medium	Grace Alvarado Ruben Ronquillo		Loma Linda ES
4593	Work In Progress MIKE MUNOZ, REPLACE EAST FENCE	8/16/2005 Medium	Grace Alvarado Michael Munoz		Loma Linda ES
3323	Work In Progress Yearly - Loma Linda ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott		Loma Linda ES
6684	Work In Progress NEED BROKEN DOLLY WHEEL TO BE REPLACED A.S.A.P.	10/24/2005 Medium	Armando Diaz Aida Salcedo		Loma Linda ES
6231	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Luis Solis		Loma Linda ES
5466	Work In Progress attn; mike munoz- we need to have kitchen store room tiled with non slip tile like rest of kitchen. francis would really enjoy it. thank you.	9/13/2005 Medium	Michael Mc Dermott Michael Munoz	Cafeteria	Loma Linda ES store room

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5284	Work In Progress 9-6-5 TO MIKE MUNOZ. MR. T. NEEDS TO TALK WITH YOU ABOUT PUTTING A FENCE ALONG NORTH SIDE OF SCHOOL. K-3 KIDS ARE A CONCERN ABOUT GOING INTO VACANT AREA. THANK YOU.	9/6/2005 Medium	Michael Mc Dermott Michael Munoz	Athletic Field	Loma Linda ES
5283	Work In Progress 9-6-5 attn; lupe b. mr. truillo at loma linda would like to meet with you about moving play ground equpt. to grass area. thank you.	9/6/2005 Medium	Michael Mc Dermott Guadalupe Ontiveros	Athletic Field	Loma Linda ES
6217	Work In Progress NEED TO (PER ATTACHED DRAWING): 1. CUT CURB 2. DIG DIRT 4" 3. ADD CRUSH FINE / CEMENT 4. MOVE DUMPSTER INSIDE THE CURB	10/10/2005 Medium	Michael Munoz Guadalupe Ontiveros		Loma Linda ES
6538	Work In Progress Need Ditch Witch delivered to Loma Linda tomorrow.	10/18/2005 Medium	David Villalobos Angel Gonzales		Loma Linda ES
5311	Work In Progress A.S.A.P PLEASE NEED A CORD LESS DRILL , IF POSIBLE A TWO PACK BATTERIAS. (THANK YOU)	9/7/2005 Medium	Luis Solis Aida Salcedo		Loma Linda ES
6778	Work In Progress WE NEED TWO ADJUST O RIGHTCAP AND FOUR WHEEL RETAINERS	10/26/2005 Medium	Ruben Solis Jimmy Carbajal	Custodial	Mesquite ES
6356	Work In Progress wire new pump on lift station #2	10/13/2005 Medium	Ricardo Jacquez Enrique Sotelo		Mesquite ES
6506	Work In Progress david boyd.need 2 sets of plans for the 1995 addition,per ms. phillips and all hazard team.thank you.	10/18/2005 Medium	Romauldo Apodaca David Boyd		Mesquite ES
6509	Work In Progress lupe ontiveros.need play sand for play structures and alma del valle.thanx.	10/18/2005 Medium	Romauldo Apodaca Guadalupe Ontiveros		Mesquite ES
6508	Work In Progress jaime need to assist w/ boilers to change over to heating,also need gas valve for heater in old office.thanx.	10/18/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES
6507	Work In Progress kiki, 5 rms w/ out lights need assistance.thanks. ARREGLAR PROBLEMA EN ALAMBRADO DE LUCES EN SALONES DE OLD WING.	10/18/2005 10/18/2005 Medium	Romauldo Apodaca Romauldo Apodaca		Mesquite ES
6779	Work In Progress NO LIGHTS IN B. WING,WORK RM.,RM. 110 AND 112.THANX.	10/26/2005 Medium	Romauldo Apodaca Enrique Sotelo		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6780	Work In Progress NEED 3 LOADS OF PLAY SAND FOR PLAY STRUCTURES IN MESQUITE.THANX. PLUS 5 BUBBLERS FOR TREES. THANX.	10/26/2005 Medium	Romauldo Apodaca Guadalupe Ontiveros		Mesquite ES
6783	Work In Progress NEED TO ORDER CLAMP FOR FILTERS TANK IN BOILER RM.BOLT IS STIPPED. THANX.	10/26/2005 Medium	Romauldo Apodaca Ricardo Jacquez		Mesquite ES
6700	Work In Progress james need to assist on checking for carbon monoxide on c and b wings and in barracks.thanx.	10/25/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES
5952	Work In Progress attention ruben ronquillo,need 6 tires for gates.thanx.	9/29/2005 Medium	Romauldo Apodaca Ruben Ronquillo		Mesquite ES
3558	Work In Progress need compresor changed out on armstrong unit in rm. 608.thanx.	7/14/2005 Medium	Romauldo Apodaca Jaime Gomez		Mesquite ES
3955	Work In Progress DINING AREA - NEED TO WELD HINGES ON DOOR FALLING DOWN.	7/29/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
4340	Work In Progress manny need to assist w/ 2 doors in porables having hard time tpo close safety issue. also need lever handle.	8/9/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
4699	Work In Progress manny need your assistance w/ doors that are hard to open and close. thanx.	8/19/2005 Medium	Romauldo Apodaca Manny Lozoya		Mesquite ES
6232	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Ruben Solis		Mesquite ES
3324	Work In Progress Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
6067	Work In Progress Monthly - Mesquite ES Fire Suppression Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		Mesquite ES
3346	Work In Progress Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4005	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3971	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
4015	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca		Mesquite ES
3461	Work In Progress Need a copy of control key (core) to keep here at the Maintenance Dept - as per A. Holguin.	7/12/2005 Medium	Alfredo Holguin Manny Lozoya		Physical Plant Complex
4017	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
6046	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
5526	Work In Progress NEED A "CB4" KEY FOR GUILLERMO - TO HAVE ACCESS TO ENERGY OFFICE TO CLEAN.	9/15/2005 Medium	Manny Lozoya		Physical Plant Complex
3379	Work In Progress Mens Restroom in Custodial Warehouse -Install new privacy lockset	7/7/2005 Low			Physical Plant Complex Restroom (Boys)
3380	Work In Progress Mens Restroom in Custodial Warehouse- Replace toilet tank cover with appropriate size for unit.	7/7/2005 Medium	Fred Appelzoller		Physical Plant Complex Restroom (Boys)
6113	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
3186	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Rudy Arreola		Physical Plant Complex
6824	Work In Progress Urinal has slow drain and water lever gets stuck creating water overrun	10/28/2005 Medium	Carlos Castillo Joe Ontiveros		Physical Plant Complex Electrical Room
4585	Work In Progress Need to replace water heater,its giving out an extremeley bad odor.Health issue.	8/16/2005 Medium	Carlos Castillo Joe Ontiveros		Physical Plant Complex Electrical Room
5432	Work In Progress Auto Shop - need to install new door knob to new door at Angel's Office.	9/12/2005 Medium	Danny Miranda Manny Lozoya		Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6716	Work In Progress need to check water leak @ warehouse mail room	10/25/2005 Medium	Danny Miranda Danny Miranda		Physical Plant Complex
3940	Work In Progress MARTA JACQUEZ - A/C UNIT IS NOT WORKING AT ALL.	7/29/2005 Medium	Marta Jacquez Jaime Gomez		Physical Plant Complex
5121	Work In Progress Power Outage - El Paso Electric	8/29/2005 Medium	Margret Villalobos Enrique Sotelo		Physical Plant Complex
5735	Work In Progress AS PER ALFREDO I NEED A COPY OF KEY TO CUSTODIAL OFFICE. THANK YOU.	9/22/2005 Medium	Maritza Gonzalez Manny Lozoya		Physical Plant Complex
4998	Work In Progress NEED TO ORDER 2 R.R. PARTITIONS FOR RIVERSIDE ELEM.	8/29/2005 Medium	Danny Miranda Danny Miranda		Riverside ES
5058	Work In Progress Carpet (Doorway) to Data clerk office is coming loose. Plastic edge is picking-up.. Thanks	8/30/2005 Medium	Olga Arias Michael Munoz		Riverside ES
5057	Work In Progress We need a new Door Knob placed in the Data Clerk office. (office area) At this time the door doesn't lock.	8/30/2005 Medium	Olga Arias Manny Lozoya		Riverside ES
5614	Work In Progress Carpet and plastic cover (edge) into Room 17 is picking-up and is coming loose and you please check it and repair it.	9/19/2005 Medium	Olga Arias Michael Munoz		Riverside ES
5609	Work In Progress Having prolems with Roaches and Black insect (Ticks) in rooms and Hallways, Storage area etc.. could we have the Whole building extremited during intersession. We have no students at this time. 10/11 - WAITING ON PURCHASE ORDER - MKV	9/19/2005 Medium	Olga Arias Margret Villalobos		Riverside ES
3326	Work In Progress Yearly - Riverside ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
6233	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Jimmy Carbajal		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3414	Work In Progress MR LOZOYA MRS ARIAS IS HAVING TROUBLE WITH THE STORAGE ROOM LOCK WOULD LIKE FOR YOU TO LOOK AT IT THANK YOU SIR	7/8/2005 Medium	Adan Duran Manny Lozoya		Riverside ES
3415	Work In Progress MR JOSE AMBRIZ THE LITTLE ROOM WHERE WATER HEATER IS IN THE NEW WING IS GETTING HOT SETTING OFF ALARM NEED EXHUST FAN TO DRAW HEAT OUT THANK YOU SIR	7/8/2005 Medium	Adan Duran Jose Ambriz		Riverside ES
3690	Work In Progress MR MANNY LOZOYA FILE CABINET NEW PORTABLE RM B NEEDS REPAIR WILL NOT LOCK PARTS MISSING THANK YOU SIR	7/19/2005 Medium	Adan Duran Manny Lozoya		Riverside ES
3778	Work In Progress MR DAVID VILLALOBOS WE HAVE SOME LEAKING FUACTS NEW WING NEED REPAIR KIT OR REPLACEMENT THANK YOU SIR	7/22/2005 Medium	Adan Duran David Villalobos		Riverside ES
4388	Work In Progress MR JOSE AMBRIZ SIR WE NEED TO HOOK BACK UP THE AIR IN WHAT USE TO BE MRS FLORES OFFICE IT WAS REMOVE AT HER REQUEST AND ITS KIND OF WARM IN THERE THANK YOU SIR	8/9/2005 Medium	Adan Duran Jose Ambriz		Riverside ES
4473	Work In Progress MR MANNY LOZOYA SIR THE DOOR ON NEW PORTABLE IS STUCK IN LOCK CAN NOT GET IT TO UNLOCK PORTABLE B IN BACK THANK YOU SIR	8/11/2005 Medium	Adan Duran Manny Lozoya	Portables	Riverside ES
4596	Work In Progress MR MANNY LOYZOA SIR NEED TO CHANGE OUT DOOR HANDLE BY MRS ARIAS OFFICE THE ONE THERE DO NOT LOCK NEED ONE THAT CAN BE LOCKED THANK YOU SIR	8/16/2005 Medium	Adan Duran Manny Lozoya		Riverside ES
5115	Work In Progress MR LUPE ONTIVEROS SIR WILL NEED THE USE OF THE BACKHOE TO MOVE SOCCOR GOAL POST AWAY FROM PARKING AREA UNSAFE FOR KIDS THANK YOU SIR	8/31/2005 Medium	Adan Duran Guadalupe Ontiveros		Riverside ES
6456	Work In Progress FRONT OF SCHOOL - SOME SPRINKLER HEADS WERE REMOVED BY VANDALS (ONE WAS BROKEN).	10/17/2005 Medium	Adan Duran Guadalupe Ontiveros		Riverside ES
6559	Work In Progress MR CARLOS CASTILLO MR CASTILLO THE LIGHTS ON THE OUT SIDE NORTH EAST SIDE ARE OUT NEED TO REPLACE VERY DARK ON THAT SIDE THANK YOU SIR	10/19/2005 Medium	Adan Duran Carlos Castillo		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6854	Work In Progress MR DAVID VILLALOBOS SIR RELIEF VALUE BIG WATER HEATER IN NEW WING IS LEAK NEED TO REPLACE THANK YOU SIR	10/28/2005 Medium	Adan Duran David Villalobos		Riverside ES
6786	Work In Progress MR JOSE AMBRIZ SIR ONE OF THE BOILER PUMPS IS STUCK NEED TO BREAK IT LOSE WILL NOT TURN NEED YOUR HELP!!!!!! THANK YOU SIR	10/26/2005 Medium	Adan Duran Jose Ambriz		Riverside ES
6689	Work In Progress MR CARLOS CASTILLO CALLI MR LORENZO SPEEDY REPORTED SOME OF THE LIGHTS ON BACK POLE AND ONE ON NORTH SIDE PARKING POLE ARE NOT COMING ON WILL NEED THE HIGH LIFT TO CHANGE THANK YOU SIR	10/24/2005 Medium	Adan Duran Carlos Castillo		Riverside ES
5592	Work In Progress please see what can be done to repair or remove electrical outlet on floor on serving line. Outlet has a can over it and could be a trip hazard.	9/19/2005 Medium	Danny Orozco	Cafeteria	Riverside ES
3348	Work In Progress Yearly - Riverside ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran		Riverside ES
6362	Work In Progress I NEED VACUUM BELTS PLEASE.	10/13/2005 Medium	Raul Romero Jimmy Carbajal	Classroom	Riverside ES
3768	Work In Progress NEED APPLIANCE TRUCK TO MOVE SOME FIREPROOF CABINETS.	7/22/2005 Medium	Raul Romero Jimmy Carbajal	Classroom	Riverside ES
6035	Work In Progress Monthly - San Miguel ES Roof Inpsection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
6017	Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
6116	Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
6104	Work In Progress Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
6879	Work In Progress DP 1088 Monitoring Data Due In This Office Before Nov. 30,2005	10/31/2005 Scheduled	Alfredo Holguin Ricardo Jacquez		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6234	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Cervando Padilla		San Miguel ES
3175	Work In Progress Monthly - San Miguel ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Vega		San Miguel ES
4489	Work In Progress Need an extra key for these rooms.	8/11/2005 Medium	Barbara Cardenas Manny Lozoya	Classroom	San Miguel ES 25, 49,50
6621	Work In Progress 3 vacuum cleaner broken/do not have spare need loaner today before 2:00 pm 10-21-05 asap thank you	10/21/2005 Medium	Cervando Padilla Jimmy Carbajal		San Miguel ES
6584	Work In Progress NEED LOCK-OUT DEVICE FOR DISCONNECT BOX/PORTABLE 28-29/POWER SHUT-OFF DAILY-ASAP	10/20/2005 Medium	Danny Vega Enrique Sotelo		San Miguel ES
6367	Work In Progress rm#32 day&night type furnace/pilot wont stay on-needs thermo-couple	10/13/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
6301	Work In Progress need additional ventilation in cafeteria/exhaust	10/11/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
6785	Work In Progress boiler is not heating/please ck it out/class rooms are cold in the morning	10/26/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
6617	Work In Progress j.gomez/need to start and go thru check list on boiler unit/before 10-28-05 (.you can do it)	10/21/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
6618	Work In Progress need two loads playground sand asap	10/21/2005 Medium	Danny Vega Guadalupe Ontiveros		San Miguel ES
5270	Work In Progress NEED LDO 2QT/FLUSH VALVE KIT/DIAPRAHMS/TUB&SINK SEALER/ELONGATED TIOLET SEAT	9/6/2005 Medium	Danny Vega Joe Ontiveros		San Miguel ES
5315	Work In Progress need replacement faucets for double sinks /kitchen .please stop by asap/	9/7/2005 Medium	Danny Vega Danny Orozco	Cafeteria	San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5307	Work In Progress portable #28 refrig unit not cooling/please check it out asap	9/7/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
5750	Work In Progress need tractor&scraper to remove goat-head stickers by play ground area.weeds also by fence line	9/22/2005 Medium	Danny Vega Guadalupe Ontiveros		San Miguel ES
4445	Work In Progress Portable 29 - Needs to be secured by the end of the day.	8/10/2005 Medium	Danny Vega Manny Lozoya	Portables	San Miguel ES
4447	Work In Progress principals office door hard to open/door needs to be shaved.stop by asap	8/10/2005 Medium	Danny Vega Manny Lozoya		San Miguel ES
5177	Work In Progress NEED FILTERS 12X24X1	9/2/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
5176	Work In Progress CAFETERIA GIRLS RR/SINK FAUCET BROKEN - OFF /PLEASE REPLACE/HOT-COLD TYPE	9/2/2005 Medium	Danny Vega Joe Ontiveros		San Miguel ES
3834	Work In Progress A/C UNIT NOT WORKING IN HIGH SPEED PORTABLE#58	7/26/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
4051	Work In Progress portable #30/rheem a/c unit not woking.stop by asap	8/1/2005 Medium	Danny Vega Jaime Gomez		San Miguel ES
5337	Work In Progress DISHWASHER LEAKING WATER. EVA MIRANDA - 233-2860	9/8/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	San Miguel ES
4152	Work In Progress ATTN MANNY. MANNY, WE STILL NEED FOR YOU TO MAKE US ANOTHER KEY TO THE MAIL BOX. THANKS.	8/3/2005 Medium	Gerardo Marquez Manny Lozoya		Santa Teresa ES
4154	Work In Progress ATTN LUPE, LUPE, WE STILL NEED THE COBBLESTONE TO KEEP CHECK THE RAIN ERROSION. ALSO NEED FOR BETO AND MANNY TO REDIG TRENCH AT BACK FENCE TO KEEP RAIN FROM FLOODING GROUNDS AND CLASS RMS.	8/3/2005 Medium	Gerardo Marquez Guadalupe Ontiveros		Santa Teresa ES
3657	Work In Progress ATTN. Manny . NEED FOR YOU TO DUPLICATE A KEY TO THE MAIL BOX . THANKS .	7/19/2005 Medium	Gerardo Marquez Manny Lozoya		Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6450	Work In Progress 10/3/05 1-insp. bldg.and grnds. picked up trash. 1-tried to fix broken stop sign at bus pick up exit. 1-fixed bus exit gate. (was knocked down over the wk. end) 4-mowed grass. 10/3 - 7	10/17/2005 Medium	Gerardo Marquez Gerardo Marquez		Santa Teresa ES
5872	Work In Progress ATTN. DAVID VILLALOBOS; DAVE , NEED FOR YOU TO CHECK OUT TOILETS IN RM. 107, AND ALSO THE ONE IN THE MENS FACULTY RR. FLOATS ARE STICKING.	9/27/2005 Medium	Gerardo Marquez David Villalobos		Santa Teresa ES
5725	Work In Progress ATTN; CALICASTILLO CALI COULD YOU PLEASE ORDER ME FOUR BOXES OF 4 FOOT FLOURECENT LAMPS. THANKS. supplied J.MARQUEZ WIHT LAMPS.	9/22/2005 10/26/2005 Medium	Gerardo Marquez Carlos Castillo		Santa Teresa ES
6491	Work In Progress walk - in freezer is at -32 degrees Pat Sanchez - SNP Manager	10/17/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Santa Teresa ES
6235	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Pablo Diaz		Santa Teresa ES
6105	Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
6117	Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
6002	Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
6038	Work In Progress Monthly - Santa Teresa ES Roof Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Lorenzo Solis		Santa Teresa ES
6071	Work In Progress Monthly - Santa Teresa ES Fire Suppression Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3958	Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
4009	Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
4021	Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Gerardo Marquez		Santa Teresa ES
3351	Work In Progress Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
6052	Work In Progress Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		Santa Teresa HS
6036	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
6018	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
5214	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
6118	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
6107	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joel Herrera		Santa Teresa HS
6072	Work In Progress Monthly - Santa Teresa HS Fire Suppression Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		Santa Teresa HS
4484	Work In Progress please install venting system and exhaust hood in the metal shop. See Joe Angelo.	8/11/2005 Medium	Jose Ambriz		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6236	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Luis Murillo		Santa Teresa HS
6724	Work In Progress AS PER MR. GIOVAS - CONSTRUCTION WILL BE COMPLETED WITHIN 2 WEEKS. NEED TO INSTALL PAPER TOWEL DISPENSORS IN CAFETERIA. PLEASE LET MARY KNOW WHEN COMPLETED SO THAT WE CAN CALL ALMA AND LET HER KNOW.	10/25/2005 Medium	Alma Terrell Guillermo Hernandez	Cafeteria	Santa Teresa HS
5903	Work In Progress Due to gas lines being broken yesterday-when Manager turned on Ovens this morning she is having problems (one oven is not heating up enough and the other one-- the blower is not working). Olga Bustamante - SNP Manager 589-5332	9/28/2005 Medium	Alma Terrell Danny Orozco	Cafeteria	Santa Teresa HS
3158	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3329	Work In Progress Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
3176	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez		Santa Teresa HS
6759	Work In Progress NEED THE FOLLOWING SUPPLIES: 18 INCH THERMOCOULS (3 EA.) 24V. HEATING T'STATS (3 EA.) BELT DRESSING (2 CANS) THANK YOU.	10/26/2005 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS
6517	Work In Progress AS PER MR. GALLEGOS HE IS REQUESTING THE USE OF THE DISTRICT SCAFFLING, FOR A PLAY THAT MRS. BRENDA SMITH IS DOING . SHE WOULD LIKE TO USE IT FROM OCTOBER 24-DECEMBER 16, 2005. SHE NEEDS ONE SECTION WITH 4 OR 5 PLANKS. REFER TO E-MAIL DATED OCTOBER 18 THANK YOU.....	10/18/2005 Medium	Arturo Nunez Ruben Ronquillo		Santa Teresa HS
4346	Work In Progress NEED TO FUMIGATE VOC. SHOPS TO MANNY CRICKETS, ANTS, ETC,ETC.	8/9/2005 Medium	Arturo Nunez Margret Villalobos		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
4465	Work In Progress NEED 1/4 INCH GAS VALVE TO PILOT , ON BOILER #1 ON NEW SYSTEM REPLACED, LEAKING REAL BAD,	8/11/2005 Medium	Arturo Nunez David Villalobos		Santa Teresa HS
3571	Work In Progress NEED CONDENSER MTR. FOR SNACK ROOM A.C. UNIT, MTR. IS FROZEN UNIT IS DOWN.	7/15/2005 Medium	Arturo Nunez Jose Ambriz		Santa Teresa HS
4613	Work In Progress Need a bucket operator and a bucket truck at STHS football field some time this week.	8/16/2005 Medium	Carlos Vigil Danny Orozco	Football Field	Santa Teresa HS
4186	Work In Progress Milk Cooler not cooling at all. Olga B. Snp Manager 589-5332	8/4/2005 Medium	Jacqueline Aguilar Danny Orozco	Cafeteria	Santa Teresa HS
5923	Work In Progress MIKE MUNOZ WE NEED BARRIER FENCE ON WEST SIDE AT SOCCER FIELD TO RETAIN BALLS OUT IT PLAY . ALSO NEED FENCE FROM 20 YARD LINE TO 20 YARD LINE IN FRONT OF FOOTBALL VISITORS SEATING AREA. SEE R GALLEGOS THANK YOU MIKE...	9/28/2005 Medium	Joel Herrera Michael Munoz		Santa Teresa HS
6567	Work In Progress BROKEN TOILER SET AT ISS CLASS ROOM AND WE NEED REPLACE IT	10/19/2005 Medium	Joel Herrera David Villalobos		Santa Teresa HS
4807	Work In Progress MANNY MY MASTER KEY IS BROKEN IT DOESN'T WORK NO MORE.	8/23/2005 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS
5102	Work In Progress WE NEED REPLACE MA 51 AND TREE LOCKS AT R.O.T.C CLASS ROOMS.	8/30/2005 Medium	Joel Herrera Manny Lozoya		Santa Teresa HS
4966	Work In Progress RUBEN WE NEED REPAIR THE WINDOWS AT DAYCAREBUILDING IT DOESN'T OPEN THANK YOU Route to Joel as per Mike 9/12/05 - mkv	8/26/2005 Medium	Joel Herrera Joel Herrera		Santa Teresa HS
4463	Work In Progress SENER ON SINCK AT GIRLS REST ROOM IT DOESN'T WORK WE REPLACE IT .	8/11/2005 Medium	Joel Herrera David Villalobos		Santa Teresa HS
4454	Work In Progress SMASHED WINDOW ON DOOR - STOLEN LARGE SCREEN TV. DISCOVERED BY MR. BUCKLEY	8/1/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS
4306	Work In Progress 8-08-05 RUBEN RONQUILLO I NEED TWO BATTERY FOR MY CORDLESS SIZE 14.4 V MY BATTERY NOT GOOD NO MORE THANK YOU RUBEN	8/8/2005 Medium	Joel Herrera Ruben Ronquillo		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6624	Work In Progress WHEEL FROM BURNISHER MACHAINE KEEPS FAILING OFF NEEDS TO BE REPAIR . THANK YOU JIMMY	10/21/2005 Medium	Luis Murillo Jimmy Carbajal		Santa Teresa HS
6717	Work In Progress JIMMY NEED A BRUSH FOR ROYAL VACUUM CLEANER BEARING FROM SIDE NEEDS TO BE REPLACE THANK YOUUUUUUU.	10/25/2005 Medium	Luis Murillo Jimmy Carbajal		Santa Teresa HS
6519	Work In Progress NEED 4-PR*S OF BLACK RUBBER BOOTS FOR SCRUBBING FLOORS SIZES 11, 7, 7, N 9 THANK YOU GUILLERMO.	10/18/2005 Medium	Luis Murillo Guillermo Hernandez		Santa Teresa HS
4720	Work In Progress POWER STRIP ON WEST SIDE OF ROOM IS NOT WORKING IN ROOM 52	8/19/2005 Medium	Laura Parra Jaime Mijarez	Classroom	Santa Teresa MS ROOM # 52
5113	Work In Progress AIR CONDITIONER DOES NOT TURN ON THE LEFT SIDE OF THE ROOM FACING CHALK BOARD ROOM 3 MR. DORANTES	8/31/2005 Medium	Laura Parra Jose Ambriz	Classroom	Santa Teresa MS
4506	Work In Progress Need to replace all condensate pumps for all geothermo units, trough all school.	8/12/2005 Medium	Lorenzo Solis Jose Ambriz		Santa Teresa MS
3387	Work In Progress Rm 1. N. bldg lower level Removal of carpet is going to require tile installation. Alfredo H. requested a work order for contractor.	7/7/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
3412	Work In Progress S.bldg upper level. Because of the shortage of classrooms Mrs. williams has to move the teachers lounge to a storage rm. The floor has no tile, can you include this room with the area's that the contractor will be installing floor tile. Attn: Alfredo holguin.	7/8/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
3364	Work In Progress S.bldg custodial storage. please make 2ea. A-7 keys for principal and building mechanic.	7/6/2005 Medium	Jaime Mijarez Manny Lozoya		Santa Teresa MS
3465	Work In Progress N.bldg home ec rm 10. Ruben Ronquillo I am going to need a Miter saw to cut legs on ten of the tables. please make sure it has a good blade. I am planning this project for next week (7/18/05.) The wood is oak.	7/12/2005 Medium	Jaime Mijarez Ruben Ronquillo		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
5149	Work In Progress N.bldg Rm 3. Mrs. williams would like to have a sidewalk that goes from Rm 3 exit door out to the fence. This way when there is a fire drill the special ed students on wheel chairs can be moved away from the building in case of an actual emergency.	9/1/2005 Medium	Jaime Mijarez Michael Munoz		Santa Teresa MS
4806	Work In Progress North and South bldgs. Condensation pumps are starting to give out. I am going to need help to start replacing them. I have been getting call after call of water spilling into classroom which requires changing damaged ceiling tiles. Attn: Joe A.	8/23/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
6314	Work In Progress Rms 43 and 38. Please order 2 ea. Bell & Gosset circulating pumps.	10/12/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
6317	Work In Progress Geothermal condensate pumps. Please order parts and 2x2 metal grills for condensate replacement pumps. See me on this.	10/12/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
6333	Work In Progress S.bldg administration area. I have been having problems with mice eating on communication wire and now on one of the condensate pumps in the lobby. They are completely eating the plastic condensate water tubing and electrical wiring to pumps. I don't know how many are up on the ceiling but they are causing alot of damage. They have already damage 2 pumps and ceiling tiles on this heat pump so far. I know that the pest control company has little bags that they throw on the on ceilings to kill the mice. Do think that we can get the pest control to take care of this problem before it gets worse.	10/12/2005 Medium	Jaime Mijarez Margret Villalobos		Santa Teresa MS
6321	Work In Progress Second Request. Mrs. williams wants to know status on broken urinal at S.bldg lower level boys restroom by ramp.	10/12/2005 Medium	Jaime Mijarez David Villalobos		Santa Teresa MS
6417	Work In Progress Metal portable Castanedas rm. Carrier cooling and electric heating unit. Fan did not start for heating and caused some wiring and other parts to melt. Attn: Joe Ambriz	10/14/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
6800	Work In Progress Fence materials. As per Alfredo H. He wants all fencing removed from grounds storage including goal post. Please take to physical plant or grounds dept.	10/27/2005 Medium	Jaime Mijarez Guadalupe Ontiveros		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6798	Work In Progress School grounds. Can we have Manny blade the grounds. There is some erosion caused by rain, and students walk through. Requested by Mrs. williams. Can he also blade the weeds.	10/27/2005 Medium	Jaime Mijarez Manuel Barrientos		Santa Teresa MS
5363	Work In Progress N.bldg maintenance and custodial. Would like a duct and register installed on heat pump.	9/9/2005 Medium	Jaime Mijarez Jose Ambriz		Santa Teresa MS
5329	Work In Progress North & South - I lost communication to both buildings and i am getting constant calls of hot areas. I am getting a message of an error on the IP address.	9/8/2005 Medium	Jaime Mijarez Margret Villalobos		Santa Teresa MS
5308	Work In Progress I NEED A KEY A7 FOR THE PRINCIPAL TO HAVE ACCESS TO MY STORAGE ROOM. THANK YOU.SEE MR. RODRIGUEZ.	9/7/2005 Medium	Ismael Rodriguez Manny Lozoya	Custodial	Santa Teresa MS
4641	Work In Progress THERE A BOYS URINAL THAT IS CRACK FROM THE BOTTOM AND EVERY TIME THEY FLUSH IT WATER COMES OUT.SEE MR. RODRIGUEZ.	8/17/2005 Medium	Ismael Rodriguez David Villalobos	Restroom (Boys)	Santa Teresa MS
3118	Work In Progress I NEED FOR GYM KEY CYLINDERS TOO TO BE CHANGE BEFORE 7/13/05.CONT.MR.RODRIGUEZ.	7/1/2005 Medium	Ismael Rodriguez Manny Lozoya		Santa Teresa MS
3330	Work In Progress Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
6237	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Ismael Rodriguez		Santa Teresa MS
6218	Work In Progress DUE TO WATER OVER FLOW, GYM FLOOR HAS BUBBLED BY FLOODING. NEED VENDOR TO DO A RECOMMENDATION AND QUOTE US.	10/10/2005 Medium	Aida Salcedo Michael Munoz		Santa Teresa MS
6073	Work In Progress Monthly - Santa Teresa MS Fire Suppression Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco		Santa Teresa MS
6109	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6119	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
6437	Work In Progress please replace h20 fountain and unclog drain.	10/14/2005 Medium	David Villalobos	Office	Santa Teresa MS
6503	Work In Progress please remove all the debre (i.e trash, tree limbs, fence etc) from where fill dirt if being applied on the arroyo.Also please bring back to the plant fencing and poles behind bldg mech shop.	10/18/2005 Medium	Guadalupe Ontiveros		Santa Teresa MS
6019	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
6037	Work In Progress Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3353	Work In Progress Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3975	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
4013	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
4023	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez		Santa Teresa MS
3423	Work In Progress Yearly - Sunland Park ES Emer. Light Test: Annual - Refer to PM schedule details.	7/10/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3355	Work In Progress Yearly - Sunland Park ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
6238	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Larry Flores		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3160	Work In Progress Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3278	Work In Progress Monthly - Sunland Park ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3268	Work In Progress Monthly - Sunland Park ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
3179	Work In Progress Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz		Sunland Park ES
4868	Work In Progress BLACK WIDOW SPIDERS, SCORPIONS, ETC. HAVE BEEN FOUND IN THE CLASSROOMS, PLAYGROUND, AND HALLS OF THIS SCHOOL. PLEASE SEND SOMEONE TO SPRAY. FAXED PO 9/1/05	8/24/2005 Medium	Irene Trujillo Margret Villalobos		Sunland Park ES
4171	Work In Progress ROOM #25 LIGHTS IN THE CLASSROOM DO NOT TURN OFF.	8/3/2005 Medium	Irene Trujillo Carlos Castillo		Sunland Park ES
3875	Work In Progress NEED REPLACEMENT KEYS FOR NURSE'S OFFICE DORR AND FILE CABINET	7/27/2005 Medium	Irene Trujillo Manny Lozoya		Sunland Park ES
5422	Work In Progress NEED TO REMOVED DEAD TREES.	9/12/2005 Medium	Irene Trujillo Guadalupe Ontiveros		Sunland Park ES
5687	Work In Progress We have a mice problem throughout the school. Please help!	9/21/2005 Medium	Irene Trujillo Margret Villalobos		Sunland Park ES
6836	Work In Progress Need two additional keys for TA32	10/28/2005 Medium	Irene Trujillo Manny Lozoya		Sunland Park ES
6882	Work In Progress Need 2 additional keys for TA64	10/31/2005 Medium	Irene Trujillo Manny Lozoya		Sunland Park ES
6878	Work In Progress ADD NEW ELECTRICAL OUTLET TO TEACHER'S LOUNGE.	10/31/2005 Medium	Irene Trujillo Carlos Castillo		Sunland Park ES
6727	Work In Progress Roaches in classroom #25.	10/25/2005 Medium	Irene Trujillo Margret Villalobos		Sunland Park ES
6465	Work In Progress THE GROUNDS NEED TO BE SMOOTHED OUT AFTER THE RAIN. THE SAND WAS WASHED AWAY IN SOME AREAS.	10/17/2005 Medium	Irene Trujillo Guadalupe Ontiveros		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6279	Work In Progress I need to replace camode in room #25. It is broken.	10/11/2005 Medium	Irene Trujillo David Villalobos		Sunland Park ES
6805	Work In Progress Vacuums need to be repaired.	10/27/2005 Medium	Larry Flores Jimmy Carbajal		Sunland Park ES
6625	Work In Progress Need Heavy Duty Dolly for fire proof file cabinet on Monday October 24, 2005	10/21/2005 Medium	Larry Flores Margret Villalobos		Sunland Park ES
6692	Work In Progress Need 4 metal blinds for portable F 46"X 52" thank you.	10/24/2005 Medium	Sebastian Diaz Ruben Ronquillo		Sunland Park ES
5888	Work In Progress 9/27/05 Need to fix water line sprinkler under the sidewalk in the new playground thank you	9/27/2005 9/28/2005 Medium	Sebastian Diaz Guadalupe Ontiveros		Sunland Park ES
5195	Work In Progress 9/2/05 Lupe Ontiveros Need the heavy tractor to remove the weeds around the school thank you	9/2/2005 Medium	Sebastian Diaz Guadalupe Ontiveros		Sunland Park ES
3533	Work In Progress Could you turn the air conditioning on we have teachers coming in to get a head start on their rooms. It is very hot and we would greatly appreciate it. Since we are a year round school the teachers need to report on Monday. Thank-you	7/14/2005 Medium	Joanne Munoz Jaime Gomez	Classroom	Sunrise ES
3876	Work In Progress RM.307,BAD CIRCULATING PUMP NEED TO REPLACE	7/27/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
3477	Work In Progress I NEED SAND FOR THE PLAY GROUNDS, THANKS.	7/12/2005 Medium	Paul Quinones Lorenzo Hernandez		Sunrise ES
3469	Work In Progress FENCING AREA IN BACK OF SCHOOL NEAR LIFT STATION NEEDS TO BE REPAIRED, AND ROLL GATE. PROBABLE HIGH WINDS ON 7-11-05 CAUSED THE DAMAGE. NO SIGNS OF VANDILISM ON SCHOOL PROPERTY	7/12/2005 Medium	Paul Quinones Michael Munoz		Sunrise ES
6781	Work In Progress REQUESTING SEAL KITS ,AND GASKETS.FOR CIRCULATING PUMPS GEO THERMAL UNITS. UNIT LEAKING FROM SEAL RM.210	10/26/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
6782	Work In Progress STERLING HEATING UNIT IN KITCHEN AREA.WILL NOT TURN ON ,MIXED AIR CONTROL NOT WORKING PROPERLY	10/26/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
6803	Work In Progress G.F.CI OUTLET TRIPPING BOILER IN WING A.MORE THAN USUAL.RESET AT LEAST TWICE A WEEK	10/27/2005 Medium	Paul Quinones Enrique Sotelo		Sunrise ES
6570	Work In Progress WATER LEAKING FROM PUMP SEAL,NEED TO REPLACE IN RM. 210. THANKS	10/19/2005 Medium	Paul Quinones Jaime Gomez		Sunrise ES
6449	Work In Progress 10-14-05 2.0,REMOVE SAND GRAVEL FROM BACK SIDEWALK ENTRANCE 4.5,ASSIST ENRIQUE W/ELECTRICAL PROBLEM RM.201 1.5,VISUAL INSPECT PLAYGROUNDS 10/14 - 8	10/17/2005 Medium	Paul Quinones Paul Quinones		Sunrise ES
5190	Work In Progress As per Nurse Creegan & Mr. Chavez request would like the 2 rooms fumigated where they had the infestation. (Spoke to Daniel he said they could send someone out on Tuesday.	9/2/2005 Medium	Richard Chavez Margret Villalobos		Sunrise ES
6239	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Ramon Dominguez		Sunrise ES
4920	Work In Progress Infestation of bug at school site office. (Health Issue)	8/25/2005 Medium	Alfredo Holguin Margret Villalobos		Sunrise ES
6887	Work In Progress The Wastwater Flow Meter needs to be checked for proper calibration ASAP	10/31/2005 High	Ricardo Jacquez		Sunrise ES
5331	Work In Progress Treat inside and outside of perimeter for insects. Note: Service setup w/principal on 9/9/05 at 3:00pm) - B. Watson Open Purchase Order!	9/8/2005 Medium	Alfredo Holguin Margret Villalobos		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To	Area Type	Location Area Number
3629	Work In Progress please cut and weedeat in and around lift station. weeds are growing rapid and are going to end up on the playing fields.	7/18/2005 Medium	Paul Quinones		Sunrise ES
4722	Work In Progress Needs 2 master keys for Vado Elementary.	8/19/2005 Medium	David Boyd Manny Lozoya		Vado ES
4628	Work In Progress Need to meet contractor on Monday - to rekey school site.	8/17/2005 Medium	David Boyd Manny Lozoya		Vado ES