

951 - Work Orders In Progress - (7/1/05 - 3/31/06 Fiscal Year)

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3308	Work In Progress Yearly - Alma Del Valle Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Alma Del Valle Daycare
3312	Work In Progress Yearly - Alma Del Valle Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Alma Del Valle Daycare
3960	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Alma Del Valle Daycare
3981	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
3982	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
10197	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Alma Del Valle Daycare
10218	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
10219	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
6005	Work In Progress Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Hector Villalobos Fire Extinguishers		Anthony ES
8636	Work In Progress NEED TO COMPLETE BUILDING INSPECTION FOR ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOU OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED & SIGNED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JANUARY 27, 2006	1/11/2006 Medium	Aida Salcedo Carlos Lujan Custodial		Anthony ES
10183	Work In Progress Walk-in Freezer at 60 degrees Becky Saenz - SNP Manager 882-5607	3/3/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10792	Work In Progress need to fix two vaccum one of them needs too scerw and the other needs to fix it 00001721 theother one is a94296936b	3/29/2006 Medium	Carlos Lujan Jimmy Carbajal Custodial Equipment Repair		Anthony ES
9303	Work In Progress I request a tool set for us we need some tools fore exsample a drill that has 18v we have a 9.6v and the batter is slow.and tools sets	2/3/2006 Medium	Carlos Lujan Sal Acuna Custodial		Anthony ES
9185	Work In Progress need metal frame for new opening @ music rm. anthony elem.	1/31/2006 Medium	Danny Miranda Danny Miranda Doors and Hardware		Anthony ES
4097	Work In Progress please scrape and add crusher fine along with parking curbs.see mike	8/2/2005 Medium	Guadalupe Ontiveros Grounds		Anthony ES
4487	Work In Progress plese grade and add crusher fine for neww parking for parents and add parking curbs.	8/11/2005 Medium	Guadalupe Ontiveros Grounds		Anthony ES
8736	Work In Progress please add additional sprinklers to existing sprinkler system in the corredore and between the primary and drug free. Also if h2o can be tied in to pine trees. Thanks	1/13/2006 Medium	Guadalupe Ontiveros Grounds		Anthony ES
9133	Work In Progress main bldg behind annex. Please use backhoe for repair of sewer line.	1/30/2006 High	Guadalupe Ontiveros Grounds		Anthony ES
9925	Work In Progress please provide carpet in music classrooms. (chapter bldg)	2/22/2006 Medium	Michael Munoz Carpet Repair		Anthony ES
4255	Work In Progress room 109 needs carpet repair	8/8/2005 Medium	Hector Villalobos Michael Munoz Carpet Repair	Classroom	Anthony ES
3899	Work In Progress Room 201 - Half of the carpet is bad replace with tile. 11/29/05 - Teacher requesting status on this work order on 11/10/05 a student fell and hurt her leg. -mkv	7/28/2005 Medium	Hector Villalobos Michael Munoz Carpet Repair	Classroom	Anthony ES
4478	Work In Progress Chapter bg p.e room replace 3/4 motor with a 1hp motor	8/11/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
4581	Work In Progress old main blg a/c motor burn out a 3 hp volts 230	8/15/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
4742	Work In Progress need a 3/4 hp motor cafeteira motor burn out old cafeteria	8/22/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Cafeteria	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4743	Work In Progress mild cafeteria burn motor 3/4 hp with a belt 4-L 660 or 670	8/22/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Cafeteria	Anthony ES
4861	Work In Progress Nurse office refrigerator is not working water is leaking from seal	8/24/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning		Anthony ES
8966	Work In Progress upper primary office needs two filing cabinet locks and two desk locks two cabinet locks	1/24/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Office	Anthony ES
8967	Work In Progress Headstrat pt1 h 2 keys can not open lock on door	1/24/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Portables	Anthony ES
9065	Work In Progress Replace a/c 45 to a 65 master cool room 306	1/26/2006 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
7339	Work In Progress Custodial storage faucet is leaking need to replace faucet	11/14/2005 Medium	Hector Villalobos Joe Ontiveros Plumbing	Custodial	Anthony ES
5992	Work In Progress upper primary boiler is leaking replace	9/30/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning		Anthony ES
5944	Work In Progress Old main blg boiler room needs a thermocuple size 56 inch	9/29/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning		Anthony ES
10790	Work In Progress broken window size 19 1/4 x15 1/2 old cafeteria	3/29/2006 Medium	Hector Villalobos Ruben Ronquillo Glass\Window Repairs	Cafeteria	Anthony ES
10754	Work In Progress Room 301 broken windows 3 size 18 1/2 x14 3/4 two 18 1/2 x14 1/4	3/28/2006 Medium	Hector Villalobos Ruben Ronquillo Glass\Window Repairs	Classroom	Anthony ES
10755	Work In Progress PT 1 broken window 33 1/2 x22 double insulate	3/28/2006 Medium	Hector Villalobos Ruben Ronquillo Glass\Window Repairs	Classroom	Anthony ES
10600	Work In Progress Need to replace air compressor at pump house	3/17/2006 Medium	Hector Villalobos Ricardo Jacquez Sewage/Water Treatment Plant	Mechanical Room	Anthony ES
10601	Work In Progress We need to replace all 11 high presure toilet valve	3/17/2006 Medium	Hector Villalobos Joe Ontiveros Plumbing	Classroom	Anthony ES
10602	Work In Progress Replace master cool 65 old cafeteria	3/17/2006 Medium	Hector Villalobos Lorenzo Solis Heating/Ventilation /Air Conditioning	Cafeteria	Anthony ES
10603	Work In Progress Need a 3/4 hp motor for a/c	3/17/2006 Medium	Hector Villalobos Lorenzo Solis Heating/Ventilation /Air Conditioning	Cafeteria	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10346	Work In Progress need a truck of sand for playground upper primary	3/8/2006 Medium	Hector Villalobos Guadalupe Ontiveros Grounds		Anthony ES
10347	Work In Progress need some crusher fine for parking lot entrance	3/8/2006 Medium	Hector Villalobos Guadalupe Ontiveros Grounds	Parking Lot	Anthony ES
10349	Work In Progress We need to replace a/c unit in pt 217	3/8/2006 Medium	Hector Villalobos Lorenzo Solis Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
9853	Work In Progress MISSING 1 FIRE EXTINGUISHER AT OLD MAIN HALLWAY AS PER PM 9335	2/17/2006 Medium	Hector Villalobos Ruben Ronquillo Fire Extinguishers		Anthony ES
10013	Work In Progress Replace all 4 bathroom lighting	2/27/2006 Medium	Hector Villalobos Enrique Sotelo Electrical	Restroom (Boys)	Anthony ES
10015	Work In Progress Need to replace pump seal	2/27/2006 Medium	Hector Villalobos Lorenzo Solis Heating/Ventilation /Air Conditioning	Mechanical Room	Anthony ES
9250	Work In Progress Chapter blg p. e bathroom replace lock and straighten out door	2/2/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Office	Anthony ES
9251	Work In Progress Social worker office needs to rekey cabinets	2/2/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Office	Anthony ES
9595	Work In Progress replace water heater in leaning center 2. 5 gal.	2/10/2006 Medium	Hector Villalobos Joe Ontiveros Plumbing		Anthony ES
9440	Work In Progress Need a/c vents for two class rooms 201 202	2/7/2006 Medium	Hector Villalobos Lorenzo Solis Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
10875	Work In Progress There are 3 rooms that the toilets water is running and the valve will not close	3/31/2006 Medium	Hector Villalobos Joe Ontiveros Plumbing	Classroom	Anthony ES
10839	Work In Progress Pts 1 and 3 needs two locks for disconnect electrical box	3/30/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Portables	Anthony ES
9088	Work In Progress AE 4-6 CAMPUS. DISHWASHER HAS ALOT OF LIME BUILD-UP , MAY NEED NEW TIPS ON THE RINSE . BECKY S. SNP MGR 882-3507	1/27/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES
10279	Work In Progress FAN TO OVEN NOT WORKING AND ITS SEEMS THAT THERE IS AN ELECTRIC SHORT SOMEWHERE. BECKY S. SNP MGR 882-3507	3/6/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4059	Work In Progress DAYCARE - NEED TO ISSUE KEYS TO CORINA VALDESPINO for (Krishna's Office). WILL BE HERE AT 8:00 AM TOMORROW.	8/1/2005 Medium	Margret Villalobos Manny Lozoya Key and Lock		Anthony ES
10606	Work In Progress PORTALBE 141 NEEDS SWAMP COOLER REPLACE WITH A MASTERCOOL 4500 SIDE DRAFT ALSO NEEDS STAND	3/17/2006 Medium	Ramiro Holguin Lorenzo Solis Heating/Ventilation /Air Conditioning		Berino ES
10787	Work In Progress NEED TO REPLACE BROKEN SECURITY LIGHT COVER ABOVE ELECTRICAL DOOR ROOM ALSO NEED ELECTRICAL COVERS TO REPLACE SOME BROKEN ONES.	3/29/2006 Medium	Ramiro Holguin Enrique Sotelo Electrical		Berino ES
10490	Work In Progress SECOND NOTICE FRIST ONE WAS LAST YEAR WHEN SPEEDY WAS STILL HERE. PLAYGROUND AREA NEEDS TO BE AERATED AND FERTILIZED	3/14/2006 Medium	Ramiro Holguin Guadalupe Ontiveros Grounds		Berino ES
9765	Work In Progress ROOMS 119,120 NEED A/C REPLACE TWO 6500 MIDDLE WESTWING NEEDS TWO WET SECTIONS 6500 NORTH WESTWING NEEDS ONE WET SECTION 4500 NORTH EASTWING NEEDS FOUR WET SECTIONS REPLACED 6500 AND ONE 4500 GYM NEEDS TWO 8500 A/C REPLACE	2/16/2006 Medium	Ramiro Holguin Lorenzo Solis Heating/Ventilation /Air Conditioning		Berino ES
9404	Work In Progress 2/03/06 SECURITY LIGHT COVER ON CAFETERIA OUTSIDE WALL NEEDS TO BE REPLACE	2/6/2006 Medium	Ramiro Holguin Enrique Sotelo Electrical		Berino ES
9557	Work In Progress TOILET IN ROOM 100 IS LEAKING WATER FROM BOTTOM OF TANK NEEDS TO BE REPLACE	2/10/2006 Medium	Ramiro Holguin Joe Ontiveros Plumbing		Berino ES
9644	Work In Progress 2/13/06 NEED FIVE 2X12X12	2/13/2006 Medium	Ramiro Holguin Ruben Ronquillo General Maintenance		Berino ES
7907	Work In Progress 12/06/05 TO MIKE PORTABLE 154 FLOOR TITLES ARE COMING OFF IF POSSIBLE THIS CHRISTMAS BREAK YOU CAN SOME CARPET INSTALL ED	12/7/2005 Medium	Ramiro Holguin Michael Munoz Carpet Repair		Berino ES
8684	Work In Progress NEED TO REPLACE BROKEN BLINDS ROOM 108 NEEDS ONE 54" P.145 NEEDS 3 35" P. 147 3 45" P 156 2 47"	1/12/2006 Medium	Ramiro Holguin Ruben Ronquillo Glass\Window Repairs		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8630	Work In Progress PORTABLE 154, NEEDS CARPET INSTALL FLOOR TILES ARE COMING OFF	1/11/2006 Medium	Ramiro Holguin Michael Munoz Carpet Repair		Berino ES
8560	Work In Progress NEED TO RELACE SKY LIGHT WINDOW 6X6 FEET HAS A HOLE IN TOP CLASS	1/9/2006 Medium	Ramiro Holguin Ruben Ronquillo Glass\Window Repairs		Berino ES
8526	Work In Progress NEED TO REPLACE TWO SINGLE SINK FAUCETS IN CLASS ROOMS	1/9/2006 Medium	Ramiro Holguin Joe Ontiveros Plumbing		Berino ES
8945	Work In Progress NEED TO REPLACE KEY FOR TV BROKEN ASAP	1/23/2006 Medium	Ramiro Holguin Manny Lozoya Key and Lock		Berino ES
8947	Work In Progress NEED TWO LOADS OF TOP RED SOIL FOR PLAYGROUND ON EASTSIDE	1/23/2006 Medium	Ramiro Holguin Guadalupe Ontiveros Grounds		Berino ES
9006	Work In Progress Need a gate key for El Paso Disposal.	1/24/2006 Medium	Juliet Parra Manny Lozoya Key and Lock		Berino ES
5585	Work In Progress need nemaster b key and 55key for new custodian thanks a.s. p	9/19/2005 Medium	Jimmy Cortez Manny Lozoya Key and Lock		Berino ES
5898	Work In Progress Need 2 new keys for office gate and recut master key for Mr Silva THANKS OFFICE KEY IS ON YOUR KEY CHAIN ALREADY	9/28/2005 Medium	Jimmy Cortez Manny Lozoya Key and Lock		Berino ES
10513	Work In Progress vaccum cleaner need new handle thanks	3/15/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial Equipment Repair		Berino ES
10856	Work In Progress need 4 new belts for vaccum	3/31/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial Equipment Repair		Berino ES
10857	Work In Progress need new brushes for royal	3/31/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial Equipment Repair		Berino ES
9455	Work In Progress Need another gate key for El Paso Disposal.	2/7/2006 Medium	Juliet Parra Manny Lozoya Key and Lock		Berino ES
5338	Work In Progress WALK - IN FREEZER IS LEAKING ALOT OF WATER BETWEEN THE FREEZER AND REFRIG. ELSA - 882-2417	9/8/2005 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3434	Work In Progress WASHING MACHINE DOES NOT WORK ANY MORE. (IT GAVE UP) ELSA CHAIRZ - SNP MGR 882-2417	7/11/2005 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Berino ES
4208	Work In Progress MOBILE HOME OCCUPANT WILL BE RECEIVING NEW MOBILE HOME ON APPROXIMATELY 8-29-05. PLEASE CONNECT ELECTRICAL. 28X54	8/4/2005 Medium	Enrique Sotelo Electrical		Berino ES
4055	Work In Progress please cut weeds and pick-up debris on east side of rockwall. (i.e weeds bottles cinder blocks.)	8/1/2005 Medium	Ramiro Holguin General Maintenance		Berino ES
4082	Work In Progress Monitoring Wells - I need a set of keys to the monitoring well caps	8/2/2005 Medium	Alfredo Holguin Manny Lozoya Key and Lock		Berino ES
10221	Work In Progress Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Ramiro Holguin General Maintenance		Berino ES
10199	Work In Progress Monthly - Berino ES Monthly FE Inspection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Ramiro Holguin Fire Extinguishers		Berino ES
10224	Work In Progress Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Ramiro Holguin General Maintenance		Berino ES
10200	Work In Progress Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral ES
10223	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral ES
9401	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Juan Vargas Fire Protection		Chaparral ES
6123	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Juan Vargas Fire Protection		Chaparral ES
9337	Work In Progress Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Juan Vargas Fire Extinguishers		Chaparral ES
9360	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9742	Work In Progress Could I get a key for Chap E for sound signal? Thanks, carlos	2/15/2006 Medium	Carlos Vigil Manny Lozoya Key and Lock		Chaparral ES
9630	Work In Progress 2/13/06 need to replace r.r. partitions in boys @ girls r.r. E-eing	2/13/2006 Medium	Danny Miranda Danny Miranda Doors and Hardware		Chaparral ES
10264	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral ES
4518	Work In Progress please replace urinal and commode in mens restrrom.	8/12/2005 Medium	Joe Ontiveros Plumbing	Mechanical Room	Chaparral ES
8428	Work In Progress please remove and remodel restrooms and custodial closet.	1/5/2006 Medium	Danny Miranda General Maintenance		Chaparral ES
8429	Work In Progress please remove all old fixtures and order new material for rough and top out. also order new fixures.	1/5/2006 Medium	Joe Ontiveros Ramps/Platforms		Chaparral ES
8430	Work In Progress please remove and provide new electrical to e- wing restrooms as needed. i.e exhaust fan, electric heat. please discuss with hvac techs.	1/5/2006 Medium	Enrique Sotelo Electrical		Chaparral ES
10767	Work In Progress E-WING GIRLS RR - CYLINDER KEEPS TURNING AND CAN NOT BE LOCKED.	3/28/2006 Medium	Manny Lozoya Key and Lock	Restroom (Girls)	Chaparral ES
8408	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas Fire Protection		Chaparral ES
7756	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas Fire Extinguishers		Chaparral ES
7779	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral ES
7820	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas Fire Protection		Chaparral ES
8295	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas Fire Extinguishers		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8312	Work In Progress Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas Roof		Chaparral ES
8367	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral ES
8834	Work In Progress THE TWO OVENS THAT WERE MOVED DO NOT WORK. ALICE E. SNP MGR 824-0048	1/18/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Chaparral ES
4797	Work In Progress repair storage, boy,s , girl,s r.r. @ chaparral elem	8/22/2005 Medium	Danny Miranda Danny Miranda General Maintenance		Chaparral ES
5498	Work In Progress sweeper/blower/not/working/choke/broken	9/14/2005 Medium	Daniel Ramirez Jimmy Carbajal Custodial Equipment Repair		Chaparral ES
10830	Work In Progress vaccum/cleaner/motor/not/working	3/30/2006 Medium	Daniel Ramirez Jimmy Carbajal Custodial Equipment Repair		Chaparral ES
10831	Work In Progress need/four/vaccum/belts	3/30/2006 Medium	Daniel Ramirez Jimmy Carbajal Custodial Equipment Repair		Chaparral ES
10836	Work In Progress E-Wing Girls & Boys RR - Need to core 4 new doors.	3/30/2006 Medium	Danny Miranda Manny Lozoya Key and Lock		Chaparral ES
10303	Work In Progress 3/6/06. as per Mr. Cardona he wants the locks in the maint. cust office and maint shed. to be keyed with a master key.	3/6/2006 Medium	Joe Ramirez Manny Lozoya Key and Lock		Chaparral ES
9980	Work In Progress Mr. Cardona is requesting verticle blinds for the front office. measurements are 48"x 84".	2/24/2006 Medium	Joe Ramirez Ruben Ronquillo Glass\Window Repairs		Chaparral ES
9199	Work In Progress need replce a/c rooms 20 -2-46-21-51- 47 and 3 more in library	1/31/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning		Chaparral ES
9201	Work In Progress portables 63 -62 -and 54 need replace a/c master cool 3800	1/31/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning		Chaparral ES
4602	Work In Progress ruben ronquillo need 10 pvc 45 elbows 6 inches 10 square grate basin 6 inches and 200 ft. 6 inches pvc pipe	8/16/2005 Medium	Juan Vargas Joe Ontiveros Plumbing		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3284	Work In Progress 07/05/05 mike munoz Mr. cardona quiere bertical blind en su oficina size 82 width and 80 length	7/5/2005 Medium	Juan Vargas Ruben Ronquillo General Maintenance		Chaparral ES
4213	Work In Progress Rooms 101-102-60-62-61-54-70-96-72-73-97 80-82-83 need carpet repace	8/4/2005 Medium	Juan Vargas Michael Munoz Carpet Repair		Chaparral ES
3800	Work In Progress 07/25/05 jaime gomes main office need new A/C two 4500 and one 6500	7/25/2005 Medium	Juan Vargas Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral ES
3801	Work In Progress 5/25/05/ mike neseito que pongan sistema de riego para los arboles	7/25/2005 Medium	Juan Vargas Guadalupe Ontiveros Grounds		Chaparral ES
3846	Work In Progress 07/26/05 j. gomes rooms 2 -20-21- 51-47-107-44- 55-46- need replace A/C 6500	7/26/2005 Medium	Juan Vargas Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral ES
3868	Work In Progress ROOMS 83-82-81-80-72-96-70 NEED WINDOWS REPAIRED OR REPLACE 2-REPORT	7/27/2005 Medium	Juan Vargas Ruben Ronquillo Glass\Window Repairs		Chaparral ES
4030	Work In Progress Room 47 need to instaled a/c ventilation	8/1/2005 Medium	Juan Vargas Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral ES
9107	Work In Progress need 200ft. swing chain and 10 swing hanger	1/27/2006 Medium	Juan Vargas Guadalupe Ontiveros Grounds		Chaparral ES
8842	Work In Progress portables 414/416/and 418 need ventilation duct	1/18/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning		Chaparral ES
8718	Work In Progress NEED NEW NUMBERS FOR THE CLASSROOMS 0-1/0-2/0-3/0-4/0-5/0-7/ 101/102/103/104/105/106/107/108/109/ 201/202/203/204/205/206/207/208/209/210/211/212/213/214/215/216/217/218/219/220 401/402/403/404/405/406/408/409/410/412/414/416/418 301/302/303/304/305/306/307/308/309/310/311/312 501/502/503/504/505/506/507/508/510/509/511/512 4-B.RESTROOMS 4-G.RESTROOMS 3-MANS 3-WOMANS 1-T.L.ROOMS	1/12/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral ES
8523	Work In Progress room 20 need fix cabinets lock	1/9/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral ES
6502	Work In Progress room 72 heating not work need help to fix	10/18/2005 Medium	Juan Vargas Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral ES
6415	Work In Progress cafeteria exit sign need change	10/14/2005 Medium	Juan Vargas Enrique Sotelo Electrical		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6343	Work In Progress las vanquetas need grabo a round	10/12/2005 Medium	Juan Vargas Guadalupe Ontiveros Grounds		Chaparral ES
7376	Work In Progress portables and e. wing need doors replace	11/15/2005 Medium	Juan Vargas Danny Miranda Doors and Hardware		Chaparral ES
7378	Work In Progress muisic room and gym. need doors replace	11/15/2005 Medium	Juan Vargas Danny Miranda Doors and Hardware		Chaparral ES
7359	Work In Progress 2 request e. wing rooms need to repair windows	11/15/2005 Medium	Juan Vargas Ruben Ronquillo Glass\Window Repairs		Chaparral ES
7360	Work In Progress rooms 79 71 70 83 need 12 blinds size 33 width 58 length	11/15/2005 Medium	Juan Vargas Ruben Ronquillo General Maintenance		Chaparral ES
7946	Work In Progress cafeteria need replace two entry doors	12/8/2005 Medium	Juan Vargas Danny Miranda Doors and Hardware	Cafeteria	Chaparral ES
7947	Work In Progress kitchen need replace entry door	12/8/2005 Medium	Juan Vargas Danny Miranda Doors and Hardware	Cafeteria	Chaparral ES
7949	Work In Progress room 120 need fix bathroom door frame	12/8/2005 Medium	Juan Vargas Danny Miranda Doors and Hardware		Chaparral ES
7953	Work In Progress nesesito 6 donpes de arena para los colunpios y acuitment playground	12/8/2005 Medium	Juan Vargas Guadalupe Ontiveros Grounds		Chaparral ES
7646	Work In Progress evenstar playgroun need water fouting fix	11/30/2005 Medium	Juan Vargas Joe Ontiveros Plumbing		Chaparral ES
7863	Work In Progress cafeteria need replace floor tile	12/6/2005 Medium	Juan Vargas Michael Munoz Carpet Repair		Chaparral ES
10306	Work In Progress computer lab has only one master key to open the door and that key was given to computer Teacher, per Mr. Cardona request he would like extra keys for the computer lab. To be distributed with the administrators.	3/6/2006 Medium	Jennifer Corral Manny Lozoya Key and Lock	Computer Lab	Chaparral ES
10469	Work In Progress Need work order done for screens in Ms. Barrett's classroom. Window in her classroom is falling apart. Fourth work order that has not been done. Rm-72	3/13/2006 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs	Classroom	Chaparral ES
10470	Work In Progress Need work order done for screen to be put in windows for Ms. Herrera's Classroom. Rm-54	3/13/2006 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs	Classroom	Chaparral ES
4110	Work In Progress Rm-72 Ms. Barret needs screens on her windows. Says they were suppose to be put in last year.	8/3/2005 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs	Classroom	Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3871	Work In Progress need an extra key for Even start classroom, Jeannette rm-118	7/27/2005 Medium	Jennifer Corral Manny Lozoya Key and Lock	Classroom	Chaparral ES
3945	Work In Progress Air Conditioner smells like burn and is not cold in rm-128 for Ms. Word	7/29/2005 Medium	Jennifer Corral Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Chaparral ES
3946	Work In Progress Air Conditioner not working in rm-20 for Ms. Gary	7/29/2005 Medium	Jennifer Corral Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Chaparral ES
3299	Work In Progress I need some keys for two of the new administrators who will be coming to this school. They have requested main keys to the gate that opens up the fence outside the school and also a set of main keys for the building. If you can please do as soon as possible. Keys for Chaparral Elementary.	7/5/2005 Medium	Jennifer Corral Manny Lozoya Key and Lock	Office	Chaparral ES
3785	Work In Progress NEED A KEY FOR ROOM 114,LEDESMA REPRINT FOR MANNY - REGARDING E-MAIL 7/27/05 - MKV	7/22/2005 Medium	Jennifer Corral Manny Lozoya Key and Lock	Classroom	Chaparral ES
7710	Work In Progress Window in rm-72 is falling out. When opened it falls out. Doesn't stay up alone needs a stick to hold it up. See Ms. Barrett.	12/1/2005 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs		Chaparral ES
6529	Work In Progress Had done a work order before for Ms. Barrett about fixing her windows needs a screen.She says they still haven't done the work order. Thanks	10/18/2005 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs	Classroom	Chaparral ES
10768	Work In Progress Need to cut weeds all around campus (front, bb courts, etc.)	3/28/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
9053	Work In Progress E-Wing Barracks - Repair hole on eastside.	1/26/2006 Medium	Michael Munoz Juan Vargas General Maintenance		Chaparral ES
9054	Work In Progress E-Wing Barracks -Paint door on E-Wing Patio area and repair door (hole on wall E-Wing by Patio).	1/26/2006 Medium	Michael Munoz Juan Vargas Painting		Chaparral ES
8069	Work In Progress Need to cleanout Mech, Bolier and Electrical Rooms as per Mike Munoz.	12/13/2005 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral MS
8070	Work In Progress Need to cut, pickup weeds and cleanup debris around WWTP as per Mike Munoz.	12/13/2005 1/24/2006 Medium	Michael Munoz Ricardo Jacquez Sewage/Water Treatment Plant		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9052	Work In Progress Patio (Behind Library) Cut grass, weeds and trim edges of grass on sidewalk.	1/26/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral MS
9486	Work In Progress need to replace cloged lines on top of rsf unit	2/8/2006 Medium	Ricardo Jacquez Ricardo Jacquez Sewage/Water Treatment Plant		Chaparral MS
5062	Work In Progress I NEED 1 MALE WATER HOSE CONNECTOR, 1 HX-1 VINYL ANCHOR KIT AND 1 WEJIT DRY WALL AUGER ANCHOR KIT SIZE 8. THANK YOU	8/30/2005 Medium	Robert Gonzalez Jimmy Carbajal Custodial		Chaparral MS
3499	Work In Progress We need locks to be installed on the center pole to the double doors in the front entrance,north east doors and south east doors. This is the oldest part of the school. the newer part of the school already have locks on the center poles. This old doors are the once that we use more often. This locks will make it so much faster and easier. THANK YOU ROBERT	7/13/2005 Medium	Robert Gonzalez Manny Lozoya Key and Lock		Chaparral MS
7525	Work In Progress MRS. ADAMS ROOM 203 HAS CABINETS AND DRAWERS THAT ARE LOCKED AND SHE DOESN'T HAVE A KEY TO UNLOCK THEM. SHE WOULD LIKE TO HAVE THEM UNLOCKED AS SOON AS POSSIBLE. THANK YOU	11/22/2005 Medium	Robert Gonzalez Manny Lozoya Key and Lock		Chaparral MS
10715	Work In Progress WE NEED AN APPLIANCE DOLLY TO MOVE THREE HEAVY FIRE PROOF FILING CABINETS. THANK YOU	3/27/2006 Medium	Robert Gonzalez Jimmy Carbajal Custodial		Chaparral MS
3439	Work In Progress NEED KEYS FOR TWO NEW PORTABLES.	7/11/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Portables	Chaparral MS
3855	Work In Progress NEED TO REKEY CABINET.	7/26/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Classroom	Chaparral MS 204
4639	Work In Progress NEED 3 REPLACEMENT KEYS FOR 3 A-34'S THAT DO NOT WORK.	8/17/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Office	Chaparral MS VICKIE-KEY
4509	Work In Progress need to rekey file cabinets. 2	8/12/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Classroom	Chaparral MS 104
9827	Work In Progress Coach Y. would like to have a plumber check out the shower system it is not functioning at full capacity.	2/17/2006 Medium	Joe Ramirez Joe Ontiveros Plumbing		Chaparral MS
8490	Work In Progress 1/6/06. need a new lock for bus turnaround south gate, lock has been cut off.	1/6/2006 Medium	Joe Ramirez Manny Lozoya Key and Lock		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6246	Work In Progress Need about 2 yards base coarse for use around pond area.	10/10/2005 Medium	Joe Ramirez Guadalupe Ontiveros Grounds		Chaparral MS
6558	Work In Progress 10/19/05. we need propane tank filled for portable housing rms. 1&2. ATTEN. RUBEN.	10/19/2005 10/21/2005 Medium	Joe Ramirez Ruben Ronquillo General Maintenance		Chaparral MS
7324	Work In Progress 11/14/05. door closer on walk in freezer door needs to be replaced. thanks.	11/14/2005 Medium	Joe Ramirez Danny Orozco Food Services		Chaparral MS
3720	Work In Progress 7/12/05. need a/c replaced on portable 1 rm. 2 please.	7/20/2005 Medium	Joe Ramirez Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral MS
9808	Work In Progress STOVE NOT HEATING VERY WELL/NOT ENOUGH JUANA MONTELONGO ASSIST. MGR 824-4376	2/17/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Chaparral MS
10843	Work In Progress gym southside door not open need fix	3/30/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral MS
10514	Work In Progress need master cool wide sections 10- 6500 and 6 - 4500	3/15/2006 Medium	Juan Vargas Lorenzo Solis General Maintenance		Chaparral MS
10650	Work In Progress GYM need replace two a/c 8500	3/20/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning	Gym	Chaparral MS
10660	Work In Progress boys and grls. r. rooms exaus not work	3/21/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning		Chaparral MS
10399	Work In Progress LIBRARY NEED REPLACE TWO 6500 MASTER COOL AND ROOMS 107 108 105 109 106 104	3/9/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning		Chaparral MS
10401	Work In Progress MIKE. NEED TOOLBOX FOR THE WORK TRUCK	3/9/2006 Medium	Juan Vargas Michael Munoz Vehicle Maintenance		Chaparral MS
4072	Work In Progress Room 208 - Mold on ceiling tiles. (Nancy, Nurse @ site called in) - mkv Margaret, Joe replied and said there where a couple of ceiling tiles with small mold droppings on them. He replaced them. However still go ahead and generate a w.o. for our records and have him fill it out. Mike	8/2/2005 Medium	Mary Garcia Joe Ramirez General Maintenance	Classroom	Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3607	Work In Progress need to paint new door @ football storage rm.	7/18/2005 Medium	Danny Miranda Joe Ramirez General Maintenance		Chaparral MS
3608	Work In Progress need to paint new door @ rm. 86	7/18/2005 Medium	Danny Miranda Joe Ramirez General Maintenance		Chaparral MS
9778	Work In Progress c.m.s. need to paint new doors around gym	2/16/2006 Medium	Danny Miranda Juan Vargas Painting		Chaparral MS
9825	Work In Progress SHOWERS IN BOYS GYM NEED SERVICING ONLY SEVEN OUT OF TEN ARE WORKING. POSSIBLY INSTALL NEW SHOWER HEADS.	2/17/2006 Medium	Elena Palacios Joe Ontiveros Plumbing	Gym	Chaparral MS BOYS GYM
9629	Work In Progress sink in womens bathroom in front office is leaking and splashes water everywhere from the sides when it is opened.	2/13/2006 Medium	Elena Palacios Joe Ontiveros Plumbing		Chaparral MS
8702	Work In Progress needs copy of key A-24, needs to put new locks on two files cabinets in front office	1/12/2006 Medium	Elena Palacios Manny Lozoya Key and Lock		Chaparral MS Room 201
8488	Work In Progress Need keys to be made/duplicated for various rooms.	1/6/2006 1/9/2006 Medium	Elena Palacios Manny Lozoya Key and Lock	Classroom	Chaparral MS
8369	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
8371	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
8296	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
7061	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
7074	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral MS
7085	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
7087	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
7781	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
7783	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
7757	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
3148	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
3241	Work In Progress Monthly - Chaparral MS Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
3243	Work In Progress Monthly - Chaparral MS Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
3314	Work In Progress Yearly - Chaparral MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral MS
3336	Work In Progress Yearly - Chaparral MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral MS
3648	Work In Progress please get with speedy and have him train you on the sprikler system on football field and thru out campus. Identify all valves and repair what is needed. also ask him for a key for sprinkler box and have him teach you the programs.	7/19/2005 Medium	Joe Ramirez General Maintenance	Football Field	Chaparral MS
3649	Work In Progress need to cut weeds and grass behind library and courtyard and surrounding areas tru -out campus including pond. Also need to irrigate these areas also.	7/19/2005 High	Joe Ramirez Grounds		Chaparral MS
3650	Work In Progress please paint railing on new portables that where installed and modified and all railings that are in need.	7/19/2005 Medium	Joe Ramirez General Maintenance		Chaparral MS
3656	Work In Progress please put up fence where portables where installed even if its on a temp bases.	7/19/2005 Medium	Joe Ramirez General Maintenance	Football Field	Chaparral MS
4485	Work In Progress please take a load of crusher fine so sewer line. Ak David (plumbing) for the specifics.	8/11/2005 Medium	Guadalupe Ontiveros Grounds	Portables	Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
5463	Work In Progress need to pour landing and sidewalks to portables by football feild.	9/13/2005 Medium	Michael Munoz Concrete	Portables	Chaparral MS
9362	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
5227	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
5229	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
9338	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
9351	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral MS
6008	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
6048	Work In Progress Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Chaparral MS
6084	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
6086	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
3977	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral MS
3307	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral MS
3964	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
3988	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3990	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
5204	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
10201	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Juan Vargas Fire Extinguishers		Chaparral MS
9364	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
10225	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral MS
10227	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral MS
10228	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
10232	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
10215	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin David Acosta Fire Extinguishers		Desert Pride
9877	Work In Progress front office building - roof missing tile Route to Gerry Marquez as per Mike 3/10/06	2/21/2006 Medium	David Acosta Michael Munoz Roof	Office	Desert Pride
7731	Work In Progress need gate repairs-vehicles hit and run on gate (front entrance)	12/2/2005 Medium	David Acosta Ruben Ronquillo Fence Repair	Parking Lot	Desert Pride front entrance
7955	Work In Progress Vandalism - Damage to front entrance roll gate hit by vehicle. (Case# 2005-1037) Julio Ledesma #831	12/2/2005 Medium	David Acosta Michael Munoz Fence Repair		Desert Pride
7666	Work In Progress having trouble unlocking the westside door (cylinder).	11/30/2005 Medium	David Acosta Manny Lozoya Key and Lock	Classroom	Desert Pride #8
5959	Work In Progress need to ckeck a/c blower . It stops blowing	9/29/2005 Medium	David Acosta Jose Ambriz Heating/Ventilation /Air Conditioning	Classroom	Desert Pride #1

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6368	Work In Progress principal requests - to add crush fine to parking lot and bus turn around to help keep the dust down	10/13/2005 Medium	David Acosta Guadalupe Ontiveros Grounds	Parking Lot	Desert Pride
8848	Work In Progress need help with tree pruning for bigger trees	1/18/2006 Medium	David Acosta Guadalupe Ontiveros Grounds		Desert Pride
8880	Work In Progress need to replace broken toilet seat	1/19/2006 Medium	David Acosta David Villalobos Plumbing	Computer Lab	Desert Pride
4642	Work In Progress need one key for storage closet for teacher in room #3	8/17/2005 Medium	David Acosta Manny Lozoya Key and Lock	Classroom	Desert Pride 3
5336	Work In Progress Principals requests: for dead bolt locks for last portable (where break-in occur)	9/8/2005 Medium	David Acosta Manny Lozoya Key and Lock	Classroom	Desert Pride #6,7.
4304	Work In Progress need locks for two doors to the hall way, that needs to be use as storage for science rooms.	8/8/2005 Medium	David Acosta Manny Lozoya Key and Lock	Classroom	Desert Pride #3,4
3791	Work In Progress need plastic name plates(12)MS. S. VERLANDER, MS. I. RAMIREZ, MS. BACH-HAGUE, MS. B. COSTULIS, MS. C. MCDONALD, MR. C. VELA, MR. P. WYMAN, MS. G. PARKER, MS. S. GARCIA, MR. D. NEAL , MS. J. ZAPATA, MS. D. DEAN	7/25/2005 Medium	David Acosta Manny Lozoya Key and Lock	Classroom	Desert Pride
4992	Work In Progress please remove marquee sign from desertveiw and install at desert pride. please be careful when removing.see mike	8/29/2005 Medium	Guadalupe Ontiveros Grounds		Desert Pride
4460	Work In Progress I need an office key for Ms. Maes, Clerk at Desert Pride Academy	8/10/2005 Medium	Mary Telles Manny Lozoya Key and Lock	Office	Desert Pride
9144	Work In Progress NEED A KEY (CD-32) FOR KITCHEN DOORS. REQUESTED BY MRS. MARTINEZ: PRINCIPAL	1/30/2006 Medium	Marisela Torres Manny Lozoya Key and Lock		Desert Trail Intermediate
10511	Work In Progress NEED TO REPLACE COMERCIAL FLOOR TILE TO BUS LOBBY	3/15/2006 Medium	Marisela Torres Michael Munoz General Maintenance		Desert Trail Intermediate
9944	Work In Progress BUFFER SP20H00051912 CADA VEZ QUE LA CONECTO HACE CORTO (NO TRABAJA) ME PODRIAN PRESTAR UNA POR MIENTRAS? GRACIAS.	2/23/2006 Medium	Marisela Torres Jimmy Carbajal Custodial Equipment Repair		Desert Trail Intermediate
5462	Work In Progress need to demo and repour concrete to sectioned area by cafeteria.	9/13/2005 Medium	Michael Munoz Concrete	Desert Trail Intermediate Cafeteria	

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8314	Work In Progress Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Johnny Acuna Roof		Desert Trail Intermediate
8596	Work In Progress Dryer is out of order - Not working at all Patricia Cisneros - SNP Manager - 824-3822	1/10/2006 Medium	Alma Terrell Danny Orozco Food Services		Desert Trail Intermediate Cafeteria
6266	Work In Progress RUSH ! or as soon as possible or Monday even. Could I get a line locate for Desert Trails Portables?	10/11/2005 Medium	Carlos Vigil Enrique Sotelo Electrical		Desert Trail Intermediate
9368	Work In Progress Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Johnny Acuna General Maintenance		Desert Trail Intermediate
10202	Work In Progress Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Johnny Acuna Fire Extinguishers		Desert Trail Intermediate
10231	Work In Progress Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Johnny Acuna General Maintenance		Desert Trail Intermediate
10226	Work In Progress Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Johnny Acuna General Maintenance		Desert Trail Intermediate
9363	Work In Progress Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Johnny Acuna General Maintenance		Desert Trail Intermediate
10568	Work In Progress FREEZER WAS TURNED OFF ON MONDAY PAT C. SNP MGR 824-3822	3/16/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services		Desert Trail Intermediate Cafeteria
9830	Work In Progress Portable #412, need to replace cracked window glass.	2/17/2006 Medium	Johnny Acuna Ruben Ronquillo Glass\Window Repairs		Desert Trail Intermediate
9779	Work In Progress Need keys made for Portable #400 furniture: Teacher's desk (3) different locks, need to install a lock to filing cabinet (cabinet still has the knockout), and a key for storage cabinet.	2/16/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
9430	Work In Progress (Danny Miranda) Portable #411, #412: Need to replace hallway and restroom doors. Thank You !!!!!	2/6/2006 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9614	Work In Progress Need a new key for room #212. Teacher lost key. (J-50) Sylvia Lorenzo.	2/13/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
10697	Work In Progress re-key cylinders to new portables at chaparral desert trail.	3/22/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
7573	Work In Progress need a gas valve for reznor roof top heater. (valve doesn't close and leaks a little). HONEYWELL : VR8304M 2880 supplied Johnny w/gas valve and he will install.	11/28/2005 12/1/2005 Medium	Johnny Acuna Lorenzo Solis Heating/Ventilation /Air Conditioning		Desert Trail Intermediate
8064	Work In Progress Please fill in holes in playground area with top soil located in the side of the swings area. Thank You !!!!!!!	12/13/2005 Medium	Johnny Acuna Guadalupe Ontiveros Grounds		Desert Trail Intermediate
7920	Work In Progress need a new classroom water faucet for room #111. The old one is bent up, classroom cabinets fell on top of it. (single handle faucet)	12/7/2005 Medium	Johnny Acuna Joe Ontiveros Plumbing		Desert Trail Intermediate
7366	Work In Progress need to replace door frame and door to portable #404.	11/15/2005 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
7520	Work In Progress (Ruben Ronquillo) Need cement mixer for next week to do cement project in parking lot area. (ramp)	11/22/2005 Medium	Johnny Acuna Ruben Ronquillo General Maintenance		Desert Trail Intermediate
7408	Work In Progress NEED TO INSTALL FENCE AROUND FIRE HYDRANT. (SEE ATTACHED)	11/16/2005 Medium	Johnny Acuna Michael Munoz Fence Repair		Desert Trail Intermediate
6846	Work In Progress fire-proof filing cabinet inside vault: please fix or replace lock.	10/28/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
7184	Work In Progress Please replace metal door (Back Door) from the kitchen. Door is corroded and getting worse. Thank You !!!	11/8/2005 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
7205	Work In Progress need to replace hydraulic door closure in the back kitchen door. (old door closure leaked oil out and doesn't work)	11/8/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
6883	Work In Progress need a lock (J-11) for new gate that was installed located in the fence between CH. ELEM and CH. DESERT TRAIL closest to Lisa ST. (To be locked during LOCK DOWN events). Thank You !!!!!!!	10/31/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6910	Work In Progress need a replacement heating coil (boiler heating system) for cafeteria heater. Old heater leaks: Model # LHD103CH Serial #35C01059-06	11/1/2005 Medium	Johnny Acuna Jose Ambriz Heating/Ventilation /Air Conditioning		Desert Trail Intermediate
9062	Work In Progress need (2) flush valve kits for restroom comodotes. One for boy's RR in the NW hall (handicap), and the other for the girl's RR in front of the teacher's lounge (handicap).	1/26/2006 Medium	Johnny Acuna Joe Ontiveros Plumbing		Desert Trail Intermediate
9048	Work In Progress need a J-11 lock for outdoor cage gate between the lift station and the baseball backstop in the playground area. Thank You !!!	1/25/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
9001	Work In Progress need a restroom partition installed in room #107. (handicapp room)	1/24/2006 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
8625	Work In Progress portable #407: need a lock with key installed to filing cabinet. cabinet has no lock installed. It still has an oval knockout hole to it. Also need a key made to teacher's desk. I have tried out all extra keys from the office.	1/11/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
8166	Work In Progress need to replace cracked window to portable #412. Have already placed glass patch on the window (both sides)	12/16/2005 Medium	Johnny Acuna Ruben Ronquillo Glass\Window Repairs		Desert Trail Intermediate
5426	Work In Progress need a replacement heating coil (Boiler System) in the Cafeteria/Gym. (Old one Leaks)	9/12/2005 Medium	Johnny Acuna Jaime Gomez Heating/Ventilation /Air Conditioning		Desert Trail Intermediate
6170	Work In Progress please repair or replace door knob in the kitchen going outdoors in the back:(door jams and is hard to open) Thank You !!!!!!!!!!!!!!!!!!!!!	10/4/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
4558	Work In Progress Mrs. Bonham (Asst. Principal) requesting concrete slab to be installed between portable #412 and #413 art studio.	8/15/2005 Medium	Johnny Acuna Michael Munoz Concrete		Desert Trail Intermediate
3739	Work In Progress DIAG/PSYCH ROOM NEED (2) CLASSROOM KEYS MADE. CORE IS: J-53	7/21/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
4116	Work In Progress need a replacement single knob water faucet for room #112.	8/3/2005 Medium	Johnny Acuna Joe Ontiveros Plumbing		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3619	Work In Progress MENS RESTROOM (NW HALL) : PLEASE CHANGE DOOR CYLINDER WHERE KEY ENTERS TO OPEN UP DOOR. STUDENTS STUFFED IN CYLINDER WITH CLAY AND HARDENED. THANK YOU !!!!!	7/18/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
3620	Work In Progress NEED NAME PLATES TO BE MADE: (1) PRINCIPAL, (1) ASSISTANT PRINCIPAL, (1) COMPUTER LAB	7/18/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
9872	Work In Progress Electrical cord wiring on roto machine exposed, tank also may need to be fixed.	2/21/2006 Medium	Miguel Aguilar Jimmy Carbajal Custodial Equipment Repair		Desert View ES
5145	Work In Progress Urgent: Need center pole repaired in exterior double door on east side of school repaired, pole fell and struck teacher. Door cannot be fully secured and will compromise security after school hours.	9/1/2005 Medium	Miguel Aguilar Manny Lozoya Key and Lock		Desert View ES
5146	Work In Progress Need copies (3) made of padlocks on hall doors, need for sub keys and replacement.	9/1/2005 Medium	Miguel Aguilar Manny Lozoya Key and Lock		Desert View ES
7232	Work In Progress Trees in front courtyard unhealthy/dying, signs of infestation, requesting solution/insecticide to remedy problem.	11/9/2005 Medium	Miguel Aguilar Guadalupe Ontiveros Grounds		Desert View ES
7613	Work In Progress Have a nonfunctioning electrical outlet in gymnasium.	11/29/2005 Medium	Miguel Aguilar Carlos Castillo Electrical		Desert View ES
7614	Work In Progress Have a nonfunctional electrical outlet in cafeteria.	11/29/2005 Medium	Miguel Aguilar Carlos Castillo Electrical		Desert View ES
4083	Work In Progress TEACHER DESK WITH LOCKING DRAWER, DOES NOT LOCK. ROOM#19, LOWER GRADE SIDE. MRS. GRISWOLD	8/2/2005 Medium	Margarita Terrazas Manny Lozoya Key and Lock		Desert View ES
8110	Work In Progress MANNY, PLEASE MAKE TWO NAME PLAQUES FOR MINERVA SINGH, RN AND YOLANDA F. GOMEZ, CNA. THANK YOU, THANK YOU!! margarita :)	12/14/2005 Medium	Margarita Terrazas Manny Lozoya Key and Lock		Desert View ES
10483	Work In Progress Please replace tracer summit board. Thank You!!	3/14/2006 Medium	Lorenzo Solis Lorenzo Solis Heating/Ventilation /Air Conditioning		Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10723	Work In Progress EXHAUST HOOD OVER STOVE/OVENS IS NOT WORKING AT ALL. MARTHA F. SNP MGR 589-2425	3/27/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Desert View ES
4149	Work In Progress key cylinder to walk-in refrigerator doesn't lock, key continuously goes round and round, please repair as soon as possible, groceries and commodities are stored in there.	8/3/2005 Medium	Alma Terrell Manny Lozoya Key and Lock	Cafeteria	Desert View ES
6225	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Miguel Aguilar Custodial		Desert View ES
10125	Work In Progress There is an electrical short near light bulb in Walk-In Refrigerator. Martha Flores - SNP Manager 589-2425	3/2/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Desert View ES
10491	Work In Progress #1. Fan above cooking stopped working, #2. On and Off button to mixer is broken and #3. Light Bulb area is still not fixed Martha Flores - DV Manager - 589-2425	3/14/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Desert View ES
3339	Work In Progress Yearly - Desert View ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Patricio Aguilar Fire Protection		Desert View ES
3317	Work In Progress Yearly - Desert View ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Patricio Aguilar Fire Protection		Desert View ES
4781	Work In Progress pat aguilar rock wall (safety concern) 6 rock wall metal gates need to be replaced rusted throw	8/22/2005 Medium	Patricio Aguilar Michael Munoz Fence Repair		Desert View ES
10899	Work In Progress pat aguilar need to install 2 new outlet elect poles in comp room	3/31/2006 Medium	Patricio Aguilar Carlos Castillo Electrical		Desert View ES
4377	Work In Progress NEED NEW R. R. PARTITIONS IN "A" WING AS PER MENNY PROSPERO	8/9/2005 Medium	Manuel Prospero Danny Miranda General Maintenance		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
7950	Work In Progress 12/8/05.EXHAUST POWER IN RESTROOM AT C WING DOESN'T WORK. THIS WORK ORDER IN FOR CARLOS CASTILLO. 2ND REQUEST. FIRST WORK ORER #6990. 11/3/05.	12/8/2005 Medium	Manuel Prospero Carlos Castillo Electrical		GAC
9066	Work In Progress I AM REQUESTING A CHAIN AND LOCK TO TIE UP TWO PIC-NIC TABLES. THI W O AS PER MANNY LOZOYA.	1/26/2006 Medium	Manuel Prospero Manny Lozoya General Maintenance		GAC
10560	Work In Progress 3/16/06. WE NEED TO REPLACE THE SHORT LIGHT POSTS.THEY ARE BROKEN AND NEED TO CHECK IF THERE IS POWER. THIS NEEDS TO BE DONE AS SOON AS POSSIBLE. MR. HAUGEN IS REQUESTING THIS WORK ORDER. AS PER MR. CARLOS CASTILLO.	3/16/2006 Medium	Manuel Prospero Carlos Castillo Electrical		GAC
10652	Work In Progress I NEED 10 LIGHTS SENSOR (FOTO SELDA) FOR OUT SIDE LIGHTS. THIS WORK ORDER IS FOR CARLOS CASTILLO.	3/20/2006 Medium	Manuel Prospero Carlos Castillo Electrical		GAC
9067	Work In Progress Swimming Pool Area - Remove dangling wooden boards.	1/26/2006 Medium	Michael Munoz Gerardo Marquez General Maintenance		GAC
9320	Work In Progress THE BURNISHER HAS NO POWER TO SWITCH,1681715 THANK YOU	2/3/2006 Medium	Ralph Lara Jimmy Carbajal Custodial Equipment Repair	Cafeteria	GAC
9981	Work In Progress RTC Office - Transfer furniture to Portable 3 take computer from Margaret's Office to RTC Office.	2/24/2006 Medium	Selma Nevarez Ralph Lara Custodial		GAC
3282	Work In Progress C-WING - TAKE OFF TILE AND INSTALL NEW TILE (TILE HAS BEEN DELIVERED), ALSO FINISH PAINTING. WILL SEND GERRY MARQUEZ TO ASSIST.	7/5/2005 Medium	Alfredo Holguin Manuel Prospero General Maintenance		GAC
3546	Work In Progress Technology Server Room-Install Battery powered Emergency lighting in this room	7/14/2005 Medium	Carlos Castillo Electrical		GAC
9297	Work In Progress please cut weeds and rake in the entrance to the GAC and also do the same where new landscaping was done by the students. Please apply chemical if need be but be careful not to hurt the other plants.	2/3/2006 Medium	Manuel Prospero General Maintenance		GAC
9141	Work In Progress please do a line locate on the east side of the pre-k. Plans are in yor mail box	1/30/2006 Medium	David Villalobos Plumbing		GAC
9145	Work In Progress please install water line for misters on the east side of the pre-k. Plans are in your mail box.	1/30/2006 Medium	Guadalupe Ontiveros Grounds		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9281	Work In Progress NEED TO RE-KEY CUSTODIAL CLOSET IN "ON-TRACK" PRE-K BUILDING TO GAC BLDG MASTER.	2/2/2006 Medium	Aida Salcedo Manny Lozoya Key and Lock		GAC
10729	Work In Progress GUILLERMO & JIMMY - FLOOR MAINTENANCE TRAINING ON 1) STRIPPING 2) SEALING 3) WAXING 4) BURNNISHING ON MARCH 20 & 21.	3/27/2006 Medium	Aida Salcedo Jimmy Carbajal Custodial		GAC
5824	Work In Progress NEED A WATERHOSE AND ALSO A HOSE ROLL A WAY.2 WATERHOSE ONE FOR THE PATIO AND ONE FOR THE PRE KINDER AREA I ONLY HAVE ONE AND I USE IT FOR THE FRONT AREA,THE HOSE ROLL A WAYS I NEED ONE FOR EACH HOSE THANK YOU FOR YOUR CONTINUED SUPPORT YOU ARE THE BEST!!!!	9/26/2005 Medium	Jimmy Carbajal Sal Acuna Custodial Equipment Repair	Custodial	GAC
8924	Work In Progress AS PER ELISA SAENZ-NEEDS NAME PLATES DONE FOR OUR NEW BOARD MEMBERS, BEFORE NEXT WEDNESDAY. 1.) ANDREW MORALES 2.) MANUELA HUERTA	1/20/2006 Medium	Mary Garcia Manny Lozoya Key and Lock		GAC BOARD ROOM
8925	Work In Progress AS PER ELISA SAENZ-NEEDS NAME PLATES DONE FOR OUR STUDENT REPRESENTATIVES. FOR NAME PLATES TO ALSO SAY STUDENT REPRESENTATIVE BELOW THEIR NAME IF POSSIBLE. 1.) DELILAH APPELZOLLER 2.) JOSUE CASTREJON	1/20/2006 Medium	Mary Garcia Manny Lozoya Key and Lock		GAC STUDENT REPRESENTATIV E @ GAC
9106	Work In Progress AS PER MIKE MUNOZ-PATIO AREA, TO REMOVE DEAD WEEDS, TRIM TREES AND CLEAN THE AREA. 2/2 - THIS WO WAS GIVEN TO MANNY P PERSONALLY FROM MIKE MUNOZ - M. GARCIA 2/3 - ROUTED TO M. PROSPERO	1/27/2006 Medium	Mary Garcia Manuel Prospero General Maintenance		GAC PATIO AREA
9073	Work In Progress AS PER MANNY-NEEDS TO RE-KEY ELODIA'S OFFICE, KEY DID NOT WORK.	1/26/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC C-WING
6743	Work In Progress AS PER MS. BERRY-NEEDS 3 SIGNS THAT SAY SLOW CHILDREN TO PUT IN THE ENTRANCE AND PARKING AREA. TALKED WITH RUBEN RONQUILLO AND KNOW WHICH SIGNS TO ORDER	10/25/2005 Medium	Mary Garcia Ruben Ronquillo General Maintenance		GAC PARKING AREA
7235	Work In Progress SPED Portable - need ramp for portable located at GAC. (see Margaret Villalobos-SPED_ Route to Manuel Prospero as per Mike 11/9/05 - mkv	11/9/2005 12/1/2005 Medium	Margret Villalobos Manuel Prospero Ramps/Platforms		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8635	Work In Progress SPED Office - Need to plaster holes in wall and replace ceiling tile.	1/11/2006 Medium	Margret Villalobos Manuel Prospero General Maintenance	Office	GAC
3408	Work In Progress AS PER CARLOS VIGIL-NEEDS A GRAND MASTER 7, ASAP. (HIS BROKE IN HALF) ALREADY TALKED WITH MANNY LOZOYA	7/8/2005 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC ALL SCHOOLS
3432	Work In Progress AS PER LINDA REYES-NEED FURNITURE FROM 3 OFFICES & BOXES ALONG WITH THIS TO BE MOVED A.S.A.P. TO NEW AREA IN C-WING. STAFF WILL START WORKING IN THESE NEW OFFICES BY TOMORROW.	7/11/2005 Medium	Mary Garcia Manuel Prospero General Maintenance	Office	GAC C WING
4655	Work In Progress AS PER ANN STEINHOFF-NEEDS 1 MORE GRAND MASTER KEY FOR HER SECRETARY AT PRE-K	8/17/2005 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC WHOLE BUILDING
5796	Work In Progress AS PER CORA-NEEDS THE DOOR LOCK TO THE DATA CENTER SWITCHED OUT FROM SWIPE CARD TO A COMBINATION LOCK. (MANNY, PLEASE SEE CORA BEFORE CHANGING OUT)	9/23/2005 Medium	Mary Garcia Manny Lozoya Key and Lock	Computer Lab	GAC DATA CENTER-TECHNOLOGY
9880	Work In Progress AS PER JOSE AMBRIZ-NEEDS TO REPLACE THE WHOLE AIR CONDITING UNIT FOR A-WING. (WILL BE ORDERING PARTS TO HAVE READY)	2/21/2006 Medium	Mary Garcia Jose Ambriz Heating/Ventilation /Air Conditioning		GAC A WING
9275	Work In Progress AS PER MARY GARCIA-NEED SUPPLY CABINET LOCK TO BE REPLACED OR FIXED. DOES NOT LOCK. (MANNY P. HAS ALREADY TRIED TWICE AND LOCKS ONLY FOR 1 DAY AND BACK TO THE SAME THING.)	2/2/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC FILE ROOM
9215	Work In Progress AS PER MIKE SORIA NEEDS A KEY TO THE PATIO LOCK. (WAS CHANGED BY MANNY L. TO OPEN W/GRAND MASTER) MIKE HAS AN OLD KEY.	2/1/2006 Medium	Mary Garcia Manny Lozoya Key and Lock		GAC PATIO AREA
9166	Work In Progress AS PER MS. BERRY-ROOM 101 IN THE PRE-K FRONT DOOR NEEDS TO BE TINTED. IT FACES THE WEST SIDE OF THE BUILDING AND IS VERY HOT IN THE AFTERNOON.	1/30/2006 Medium	Mary Garcia Ruben Ronquillo Glass\Window Repairs	Classroom	GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9318	Work In Progress AS PER MS. CUBILETTE-NEED CEMENT SCREWS FOR PINIC TABLES. (IF POSSIBLE TO BE SENT TODAY, CAUSE MANNY P. ALREADY ASSEMBLED TABLES & ARE SET OUTSIDE WITHOUT BEING SECURED. TABLES ARE WORTH \$600.000 EACH & IS VERY CONCERNED THEY MIGHT WALK OFF OVER THE WEEKEND.) AS PER MANNY P. STATED HE WAS NOT GOING TO PUT TABLES OUTSIDE UNTIL CEMENT SCREWS WERE SENT (BY YET HE DID). MANNY P. STATED THEY WERE ALREADY ORDER BY WORK ORDER AND ALSO PLACE A PHONE CALL TO RUBEN R. SINCE A WEEK AGO. AS PER RUBEN NO WORK ORDER HAS BEEN DONE BY MANNY P. RUBEN R. WILL TRY TO SENT CEMENT SCREWS TODAY W/JIMMY.	2/3/2006 Medium	Mary Garcia Manuel Prospero General Maintenance		GAC PATIO
9496	Work In Progress AS PER MARGARET V W/SPED-NEED AN ELECTRICAL OUTLET UNDER A DESK TO BE REMOVED. (SAM GALLEGOS OFFICE) IF POSSIBLE ASAP.	2/8/2006 Medium	Mary Garcia Carlos Castillo Electrical	Mechanical Room	GAC A WINT
9529	Work In Progress AS PER MS. BERRY-NEEDS FOR RUGS TO BE SET UP IN EACH CLASSROOM. (SEE ATTACHED SHEET GIVEN TO MANNY P.)	2/9/2006 Medium	Mary Garcia Manuel Prospero General Maintenance	Classroom	GAC
10732	Work In Progress AS PER MARGARET VILLALOBOS W/SPECIAL ED-NEEDS WINDOW BLINDS AND SILKS TO BE CLEANED IN HER AND SELMA'S OFFICE.	3/27/2006 Medium	Mary Garcia Ralph Lara Custodial	Office	GAC
10565	Work In Progress AS PER MR. GALLEGOS-NEEDS HIS CONFERENCE & OFFICE ROOM WAXED.	3/16/2006 Medium	Mary Garcia Ralph Lara Custodial	Office	GAC CONFERENCE ROOM
8844	Work In Progress AS PER MR. CHAVEZ OVER AT THE GHS ACADEMIC BUILDING BOYS RESTROOM ON THE WEST SIDE NEEDS A PARTION BETWEEN HANDICAP & REGULAR TOILET.	1/18/2006 Medium	Mary Garcia Danny Miranda Doors and Hardware	Restroom (Boys)	Gadsden HS GHS ACADEMIC BLDG
10580	Work In Progress BROKEN WINDOW GLASS AT ANNEX BLDG DOOR 30X30 VANDALISM	3/16/2006 Medium	Mario Apodaca Ruben Ronquillo Glass\Window Repairs		Gadsden HS
10765	Work In Progress NEED SEWER SNAKE AT KITCHEN FOR FLOOR SINK CALL DANNY O	3/28/2006 Medium	Mario Apodaca Danny Orozco Food Services		Gadsden HS
10766	Work In Progress NEED TO PUT NEW FLOOR TILE AT V-GYM GIRLS LOCK ROOM	3/28/2006 Medium	Mario Apodaca Michael Munoz Carpet Repair	Restroom (Girls)	Gadsden HS
10837	Work In Progress Sewer lines are backing up.	3/30/2006 Medium	Mario Apodaca Danny Orozco Food Services	Cafeteria	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10816	Work In Progress NEED TO PUT A NEW WAX RING KITCHEN WOMEM RESTROOM TOILET . ASAP	3/29/2006 Medium	Mario Apodaca David Villalobos Plumbing		Gadsden HS
9622	Work In Progress NEED LOCK BACK TOO A F3 KEY ON GUARD HOUSE ON NORTH SIED	2/13/2006 Medium	Mario Apodaca Manny Lozoya Key and Lock		Gadsden HS
9696	Work In Progress NEED #5 FIRE EXTINGUISHER CABINETS FOR THE N/BLDG 10 LB DRY CHEMICAL SURFACEMOUNT	2/14/2006 Medium	Mario Apodaca Danny Orozco Fire Extinguishers		Gadsden HS
9697	Work In Progress THE WATER BOILER AT CAFETERIA ARE RUSTING	2/14/2006 Medium	Mario Apodaca David Villalobos Plumbing		Gadsden HS
9266	Work In Progress NEED TOW LACK FOR CONCESSION STAND AT FOOTBALL FIELD	2/2/2006 Medium	Mario Apodaca Manny Lozoya Key and Lock		Gadsden HS
10036	Work In Progress NEED A NEW DOOR AT OLD ENG BOY RESTROOM DO TOO VANDALISM	2/27/2006 Medium	Mario Apodaca Danny Miranda Doors and Hardware		Gadsden HS
10007	Work In Progress ROOF LEAK AT NEW RESTROOM BOY SIDE AT FOOTBALL FIELD	2/24/2006 Medium	Mario Apodaca David Boyd Construction	Football Field	Gadsden HS Roof
10138	Work In Progress NEED TO PUT A NEW TOILE FLANGE AT N-BLDG GIRLS RESTROOM	3/2/2006 Medium	Mario Apodaca David Villalobos Plumbing		Gadsden HS
8582	Work In Progress NEED NEW E/COOLER AND DUCTING FOR BOY GYM	1/9/2006 Medium	Mario Apodaca Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
8584	Work In Progress NEED NEW E/COOLER AT ROOM 506 ANNEX BLDG	1/9/2006 Medium	Mario Apodaca Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
8585	Work In Progress NEED NEW E/COOLER AT GIRLS LOCKROOM ROOM 237 V-GYM	1/9/2006 Medium	Mario Apodaca Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
8714	Work In Progress NEED A NEW E/COOLER AT FOOTBALL FIELD PRESS BOX REPLACE UNIT FOR A M/C 6500 UPFLOW WITH DUCTWORK, SIZE WAS INSTALLED BECAUSE INSTALLED A DUCT WORK 20X20X90. 1HP MOTOR INSTEAD OF 1/3 HP MOTOR.	1/12/2006 Medium	Mario Apodaca Jose Ambriz Heating/Ventilation /Air Conditioning	Football Field	Gadsden HS New Equip. Installation
8095	Work In Progress NEED A NEW FLOODLIGHT FIXER FOR THE SCHOOL SIGN AT FRONT OF CAMPUS.	12/13/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8901	Work In Progress CAFETERIA KITCHEN - TOW FLOOR MOP SINK IS LEAKING NEEDS TO BE RESET TO P-TRAP.	1/20/2006 Medium	Mario Apodaca Danny Orozco Food Services	Cafeteria	Gadsden HS
6526	Work In Progress NEED TOO RUN SEWER SNAKE AT WOOD SHOP BLDG unclog main sewer line to woodshop	10/18/2005 10/19/2005 Medium	Mario Apodaca David Villalobos Plumbing		Gadsden HS
6425	Work In Progress NEED TO REMOVE ALL OUTLET AT ROOM 126 AT ARE ON BOOK SHEVING FLOOR AND RELOCA OUTLETS	10/14/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical	Custodial	Gadsden HS
7239	Work In Progress NEED KEY FOR TOW FILE CABINETS AT ROOM 223	11/9/2005 Medium	Mario Apodaca Manny Lozoya Key and Lock		Gadsden HS
7277	Work In Progress NEED TO PUT CRUSH ROCK ON ROAD BY THE WOOD SHOP , ANNEX BLDG AND POOL SO DUST WOOD NOT P-PU ASAP	11/10/2005 Medium	Mario Apodaca Guadalupe Ontiveros Grounds		Gadsden HS
7886	Work In Progress NEED TO REPAIR ALL DOOR FRAMS AT THE WEIGHT ROOM THE KID WILL PULL THE DOOR OPEN W/THE DOOR ARE LOCK	12/6/2005 Medium	Mario Apodaca Danny Miranda Doors and Hardware		Gadsden HS
7956	Work In Progress Vandalism - Damage to south front entrance roll gate hit by vehicle. (Case# 2005-10383) Deputy Isidro Gonzalez #935	12/2/2005 Medium	Mario Apodaca Michael Munoz Fence Repair		Gadsden HS
5108	Work In Progress NEED TO PUT NEW BALLAST AT WOOD SHOP LAMPES	8/31/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
5842	Work In Progress NEED A NEW GLASS PUT ON CONCESSION STAND WINDOW AT FOOTBALL FIELD (VANDALISM) 23X23 ASAP	9/26/2005 Medium	Mario Apodaca Ruben Ronquillo Glass\Window Repairs		Gadsden HS
4502	Work In Progress NEED TO LAMPES AT WOOD SHOP SAME ARE BURNED OUT	8/11/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
4970	Work In Progress GLASS AT MAIN BLDG HALLWAY 40X18 NEED TOBE REPLACES VANDALISM	8/26/2005 Medium	Mario Apodaca Ruben Ronquillo Glass\Window Repairs		Gadsden HS
4976	Work In Progress NEED ALL WINDOW BLINDSON OLD ENGLISH BLDG 40 EA 40WX90L	8/26/2005 Medium	Mario Apodaca Ruben Ronquillo Glass\Window Repairs		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3524	Work In Progress NEED TO FIX FOOTBALL FIELD SCOREBOARD BREAKER BOX	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
3525	Work In Progress NEED TO CK ALL FOOTBALL FIELD LAMPS	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
4726	Work In Progress Royal vacuum is missing bag and brush, belt serial No.H93266101B GISD tag 014131	8/19/2005 Medium	Jesus Estrada Jimmy Carbajal Custodial Equipment Repair		Gadsden HS
3479	Work In Progress All Campus - Need to replace old door knobs w/new levers.	7/12/2005 Medium	Hector Lozoya Manny Lozoya Key and Lock		Gadsden HS
10789	Work In Progress Grounds Shop - Need an electrical outlet installed outside of shop.	3/29/2006 Medium	Guadalupe Ontiveros Michael Mc Dermott Electrical		Gadsden HS
7638	Work In Progress Girls BB Lockerroom - Connect Electric Water Heater.	11/29/2005 Medium	David Villalobos Michael Mc Dermott Electrical		Gadsden HS
10428	Work In Progress AG Shop - Walk In Cooler needs refrigerant (freeon) as per Fernando needs it by next week.	3/10/2006 Medium	Fernando Moncayo Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
10647	Work In Progress Broken window in hall on top of VARSITY GYM 14.5x37.5+- single pane glass	3/17/2006 Medium	Fernando Moncayo Ruben Ronquillo Glass\Window Repairs	Hallway/Corridor	Gadsden HS
10081	Work In Progress PRESCHOOL sink is clogged up, run small cable through,but no luck.please assist THANK YOU!!	2/28/2006 Medium	Fernando Moncayo David Villalobos Plumbing		Gadsden HS
10114	Work In Progress ATTN. DAVID VILLALOBOS;Need to replace two toilets and flanges in LIBRARY GIRL'S R. R.Also one toilet in MAIN GIRL'S R.R THANK YOU!!	3/1/2006 Medium	Fernando Moncayo David Villalobos Plumbing		Gadsden HS
9959	Work In Progress ATTN.MR.LAZOYA;Key stuck and almost broken in NORTH side door at WEIGHTROOM.Need you a.s.a.p THANK YOU!!!	2/23/2006 Medium	Fernando Moncayo Manny Lozoya Key and Lock		Gadsden HS
4902	Work In Progress AG BLDG entry door,won't open or lock key just turns;Also WOOD SHOP entry door new lock dosn't work	8/25/2005 Medium	Fernando Moncayo Manny Lozoya Key and Lock		Gadsden HS
4305	Work In Progress NORTH bus entrance gate keep falling, bottom rail all bend;Also needs new roller bearings for both gates thank you !!! [safety hazard]	8/8/2005 Medium	Fernando Moncayo Michael Munoz Fence Repair		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4311	Work In Progress PANTHER HUT porch entrance too dark security ligh dosen't work	8/8/2005 Medium	Fernando Moncayo Fernando Moncayo Electrical		Gadsden HS
4240	Work In Progress Need six wheels for large gates in NORTH parking lot THANK YOU!! 8/11 - Route to Ruben as per Mike	8/5/2005 Medium	Fernando Moncayo Ruben Ronquillo General Maintenance		Gadsden HS
3593	Work In Progress Need to repair or replace electrical conduit outside of CONCESSION STAND by GIRL'S GYM Parent called regarding the outlets to the concession stand need status. Work Order has been placed along time ago needs to be repaired before next Saturday.	7/15/2005 Medium	Fernando Moncayo Michael Mc Dermott Electrical		Gadsden HS
7301	Work In Progress BOY'S GYM SOUTH EAST exterior door need to be replace	11/11/2005 Medium	Fernando Moncayo Danny Miranda Doors and Hardware	Gym	Gadsden HS
6607	Work In Progress LIBRARY EAST wall;There is a, wall keyed hose bib that is leaking	10/20/2005 Medium	Fernando Moncayo David Villalobos Plumbing		Gadsden HS
6609	Work In Progress Need to install flouresent ligh lamps in ANNEX CORRIDOR, is too dark	10/20/2005 Medium	Fernando Moncayo Michael Mc Dermott Electrical		Gadsden HS
9147	Work In Progress Need a new metal door for BOY'S restroom in OLD ENGLISH 1st. floor. ASAP please,can't lock restroom to control vandalism THANK YOU!!	1/30/2006 Medium	Fernando Moncayo Danny Miranda Doors and Hardware	Restroom (Boys)	Gadsden HS
8932	Work In Progress MR.CASTILLO;When you have a chance please drop by ghs with two plug-in photocell 120v THANK YOU!!	1/20/2006 Medium	Fernando Moncayo Carlos Castillo Electrical		Gadsden HS
8896	Work In Progress Attn. MR. JOJO AMBRIZ;Will need to replace a/c's in rooms 750,752and 753 MC-6500 side draft	1/19/2006 Medium	Fernando Moncayo Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
8254	Work In Progress Need to replace return unit's disconnect	12/22/2005 Medium	Carlos Castillo Carlos Castillo Electrical	Cafeteria	Gadsden HS
8145	Work In Progress Several light pole around cafeteria area are out.Already change lamps but still not working,need to change ballasts. As per Mike Munoz route to Mike Mc Dermott. 12/18/05-Cali ordered material (10) 100w MH Ballast and (10) 100 WMH Lamps.	12/15/2005 Medium	Carlos Castillo Michael Mc Dermott Electrical		Gadsden HS
9596	Work In Progress PORTABLE NEXT TO NURSES OFFICE - NEED EMT PIPE AT CORNER OF BUILDING FOR COMPUTER DROPS. PLEASE CALL SILVER IN TECH FOR INFORMATION	2/10/2006 Medium	Cora Ramirez Michael Mc Dermott General Maintenance	Portables	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9432	Work In Progress need to replace key switches with regular two pole switches.	2/6/2006 Medium	Carlos Castillo Carlos Castillo Electrical	Classroom	Gadsden HS
10372	Work In Progress On March 20, 21, and 22, the State Fire Marshal will be conducting a complete and thorough inspection of the new system; this entails checking every device in the system in all rooms and storage spaces. If you could please either have a complete set of keys for all rooms, storage and padlocks, or give me your permission to open any locks necessary to conduct this test it would be very much appreciated. I could pick them up this Friday. We will of course secure all sites as they are checked. 1. North Building: Office of vice prin., panther hut. 2. Academic Bldg: Office of vice prin, his storage. Choir storage. Dark room in yearbook class. Custodial closets. 3. Main bldg: Office area, Vault will need to be open! Can we have a person with combination in the area that day? Custodial closet, Old nurses office, Lab storage areas. 4. Old English: basement and other storage rooms were off master, 5. Nurses offices 6. Cafeteria: all storage areas in kitchen 7. Gyms: All coaches offices and storage areas 8. NROTC armory area.	3/8/2006 Medium	Carlos Vigil Manny Lozoya Key and Lock		Gadsden HS
6001	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ontiveros Fire Extinguishers		Gadsden HS
10235	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
10238	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Mario Apodaca General Maintenance		Gadsden HS
9372	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
9375	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Mario Apodaca General Maintenance		Gadsden HS
10194	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Joe Ontiveros Fire Extinguishers		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9546	Work In Progress please repair clean out that east of concession stand.	2/10/2006 Medium	David Villalobos Plumbing	Football Field	Gadsden HS
4916	Work In Progress please check and repair leak & secure drop ceiling in rm 142. possible safety hazard.	8/25/2005 Medium	Danny Miranda General Maintenance		Gadsden HS
4448	Work In Progress Telescope observatory locate on the west side of the baseball field - Install fencing around it to prevent vandalism	8/10/2005 Medium	Michael Munoz Fence Repair		Gadsden HS
5464	Work In Progress Need to paint stripings for student parking lot and east of Auto Shop.	9/13/2005 Medium	Michael Munoz General Maintenance	Parking Lot	Gadsden HS
5458	Work In Progress need to restripe all parking lines ,handi-cap-arrowa etc.	9/13/2005 Medium	Michael Munoz Painting	Parking Lot	Gadsden HS
7499	Work In Progress please re-route conduit and repair where kids get on roof by panther hut. north bldg.	11/21/2005 Medium	Enrique Sotelo Electrical	Classroom	Gadsden HS
7500	Work In Progress please replace disconnect to heating unit on the S- wing north bldg. blades do not work properly.	11/21/2005 Medium	Jose Ambriz Heating/Ventilation /Air Conditioning	Classroom	Gadsden HS
3141	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ontiveros Fire Extinguishers		Gadsden HS
3319	Work In Progress Yearly - Gadsden HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ontiveros Fire Protection		Gadsden HS
8316	Work In Progress Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Mario Apodaca Roof		Gadsden HS
8379	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
8382	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Mario Apodaca General Maintenance		Gadsden HS
7095	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
7791	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9172	Work In Progress GHS pool needs an emergency cut-off switch for circulating pump installed outside of pump room as per pool inspection 2005 report	1/30/2006 Medium	Raul Sanchez Michael Mc Dermott Electrical	Parking Lot	Gadsden HS
10291	Work In Progress please repair the concession stand and order material for windows and door.(girls softball feild) Thanks	3/6/2006 Medium	Michael Munoz Gerardo Marquez General Maintenance	Athletic Field	Gadsden HS
8193	Work In Progress please repair the goal on the northeast side.	12/19/2005 Medium	Michael Munoz Michael Munoz Athletic Fields	Gym	Gadsden HS
8946	Work In Progress Requested by Ms. Lopez Rm. 605 Business Building-Replacement of school lock on the second floor of the Business Building elevator, due to it not being able to find an original key to open the Master Pad. Lock currently on the door. Please contact Ms. Lopez for information regarding the type of lock to be placed on the door.	1/23/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
9093	Work In Progress Requested by Velia Rm. 112 Front Office-Two keys of HE203 are needed for Key Box; for Concession Stand at Football Field.	1/27/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
9094	Work In Progress Requested by Velia Rm. 112 Front Office-Key broke inside cylinder, we need lock fixed and also, please complete Work Order # 4362. Five keys are needed of HE1 (Gym Key), three keys are now broken and need replacing.	1/27/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
9098	Work In Progress Requested by Mr. Contaldo Observatory-Close and lubricate observatory dome as soon as possible.	1/27/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
9099	Work In Progress Requested by Mr. Contaldo Observatory-Replace power cord going to white light bulbs on top, inside of dome.	1/27/2006 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
9100	Work In Progress Requested by Mr. Contaldo Observatory-Replace acciator switches.	1/27/2006 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
9101	Work In Progress Requested by Ms. Jacquez Rm. 752 Barracks-Mount flags on wall.	1/27/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9111	Work In Progress Requested by Ms. Lam Women's Restroom Main Building-The door can not be locked, with the key given to us. Students are using the restroom.	1/27/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
8687	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-Ovens not working at all. First and third ovens on the right side of kitchen, possibly a problem with the outlets.	1/12/2006 Medium	Velia Alarcon Danny Orozco Food Services		Gadsden HS
8688	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-Dishwasher not pulling cleaner or rinse products, only pulls sanitizer.	1/12/2006 Medium	Velia Alarcon Danny Orozco Food Services		Gadsden HS
8689	Work In Progress Requested by Ms. Anderson Rm. 233 Panter Hut-Mice in Panther Hut.	1/12/2006 Medium	Velia Alarcon Margret Villalobos Pest Control		Gadsden HS
8691	Work In Progress Requested by Chief Arms Rifle Range/Adjacent to Boys Gym-Rifle Range is coming loose in numerous panels and range is no longer secure. Recommend a permanent wall or welded metal plating. Kids are using basketballs to break the screens; also maintenance caught three kids in the rifle range before break. Note from Mr. Foster: THIS IS IMPORTANT! Route to Bldg Mechanic as per Mike - 2/8/06 -mkv	1/12/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
8696	Work In Progress Requested by Mrs. Quinones Rm. 653 Busines Building-Replace florescent light bulbs.	1/12/2006 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
8534	Work In Progress Requested by Velia Rm. 112 Front Office-One key of D47 is needed for key box, for room 125. Ms. Holguin's classroom.	1/9/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
8178	Work In Progress Requested by Mr. Contaldo Campus Observatory-Fix or replace limiting switches on Observatory hatch. Existing switches may (?) be fixed by bending metal contact plates to correct position. Key problem: need to be able to open and close hatch. Replace or fix white light bulbs inside Observatory.	12/16/2005 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
8179	Work In Progress Requested by Mr. Contaldo Campus Observatory-Install 6' chain link fence around Observatory Deck with locking gate. Key problem: prevent future vandalism. 1/11 - Route to Lupe as per Mike.	12/16/2005 Medium	Velia Alarcon Guadalupe Ontiveros Grounds		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8182	Work In Progress Requested by L. Melendrez Rm. 333 Academic Building-Classroom walls need to be repaired. There are holes in the walls and it needs to be repainted.	12/16/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
8185	Work In Progress Requested by Ms. Trich Library-The drawer slides for the cashbox are loose. They may be missing screws to attach them to the base. Might someone please assess the situation to determine if the present one can be repaired or if they need replacement? Please check with Leslie, this is a safety issue; the drawer may fall out of the base.	12/16/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
6274	Work In Progress Requested by Mr. Chambers Varsity Gym- Varsity Gym floor is showing large space and boards are coming loose, needs repair a.s.a.p. SAFETY ISSUE	10/11/2005 Medium	Velia Alarcon Michael Munoz Carpet Repair		Gadsden HS
6282	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Paint (or provide paint)for repainting the tool room and paint room. Second Request	10/11/2005 Medium	Velia Alarcon Mario Apodaca Painting		Gadsden HS
6454	Work In Progress Requested by Mr. Chambers Football Restrooms- Paint large letters on restroom indicating men's and women's sides, or hang large signs indicating directions.	10/17/2005 Medium	Velia Alarcon Fernando Moncayo Painting		Gadsden HS
6460	Work In Progress Requested by Mr. Whitener Rm. 563 Ag. Shop- Install a hydraulic door closer on the new front door to the building.	10/17/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
6710	Work In Progress Requested Ms. Nanez Library-Backs to shelves need to be installed. Backs are in library, however, they need to be cut down to fit.	10/25/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
6713	Work In Progress Requested by Ms. Trich Library-Please replace blown light bulbs, especially in Librarian's office, room 275b.	10/25/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
6830	Work In Progress Requested by Velia Rm. 127 Main Building-When the sound system contractors installed the wiring in Ms. Garcia's classroom. They placed it on a wall Ms. Garcia used for her projector. Once they removed the wiring and placed it on another wall, they left the wall scrated and paint peeled. Wall needs to be repaired and painted.	10/28/2005 Medium	Velia Alarcon Fernando Moncayo Painting		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
7145	Work In Progress Requested by Ms. V. Lopez Old Counseling Center-Repair hole in ceiling near new ventilation work.	11/7/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
7370	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop- 2ND REQUEST Replace ceiling tile in office storeroom. Consider placing a plywood floor over unprotected tile.	11/15/2005 Medium	Velia Alarcon Michael Munoz General Maintenance		Gadsden HS
8081	Work In Progress Requested by Ms. Trich Rm. 275 Library-Tops of the short book shelves are losing the laminate, which is peeling off. Please re-attach the laminate tops. Please check with either Bonnie or me.	12/13/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
8068	Work In Progress Requested by Mr. Chambers North Building Project-Temporarily remove cable from North Building Lockers by Saturday, Dec. 17. (For Columbia University Film Documentary)	12/13/2005 Medium	Velia Alarcon Michael Munoz General Maintenance		Gadsden HS
7913	Work In Progress Requested by Cathy Cano Concession Stand-Windows to concession stand need to be put back on. Reasons: cold, and too many flies and/or bees. Route to Bldg Mechanic as per Mike Munoz 12/16/05 - mkv	12/7/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
7914	Work In Progress Requested by Ms. Hunt Rm. 105 Main Building-Cupboard door broke off, screws on my desk.	12/7/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
7915	Work In Progress Requested by Mr. Contaldo Campus Observatory-Close hatch door on observatory, check out electrical connection for motor drive and white overhead lights. route to Mike Mc Dermott - As per Mike Munoz 12/12/05 - mkv	12/7/2005 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
7626	Work In Progress Requested by Mr. Foster and Mr. Chambers Varsity Gym-ATTN: Mike Munoz Replace heating units and duct work. *Girls team practiced in 23 degrees this morning in the gym. *Parents calling and complaining about conditions. *Parents calling Central Office.	11/29/2005 Medium	Velia Alarcon Jose Ambriz Heating/Ventilation /Air Conditioning	Gym	Gadsden HS
4897	Work In Progress Requested by Velia Rm. 112 Front Office-Two HE27 are needed for key box.	8/25/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
5083	Work In Progress Requested by Mr. Martin Rm. 551 Wood Shop-Hall lock will no unlock, 2nd Notice.	8/30/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
5084	Work In Progress Requested by Velia Press Box-Safety Hazard; need to re-duct and install new air conditioner were it can be serviced. FERNANDO, JOSE WILL LOOK INTO ORDERING UPDRAFT UNIT AND SHEETMETAL. AS PER OUR CONVERSATION YOU AND MARIO WILL FORM AND POUR CONCRETE FOR SMALL PAD FOR A/C STAND. IN THE MEAN TIME SERVICE WHAT IS THERE. - M. MUNOZ 9/1/05-MKV XC: WO TO FERNANDO	8/30/2005 Medium	Velia Alarcon Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
4810	Work In Progress Requested by Ms. L. Chavez Rm. 245 Classroom Over Varsity Gym-Re-place several burned out light bulbs. RE-ROUTE TO BUILDING MECHANIC as per Mike Mc Dermott 9/19/05	8/23/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
4811	Work In Progress Requested by Mr. Cordova Storage Room in Varsity Gym Stage-The door needs to be re- keyed to an off master key, light board room. 4 keys are needed.	8/23/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4812	Work In Progress Requested by Lt. Dickerson Rm. 202 North Building-His HEM key has broken, 3 HEM keys are needed. One for him and two for the key box.	8/23/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4814	Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Air conditioner still does not work. No air is coming out of vents, very hot. Wires hanging into light fixture and a piece of ceiling tile (broken) is in one of the air conditioning vents. (room was damaged over summer)	8/23/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4816	Work In Progress Requested by Ms. L. Melendrez Rm. 331 Academic Building-I have been having trouble opening my front door for over a year, and now I am having trouble opening the back door. It's not my key it's the door handle and deadbolts. Both back doors are very difficult to open.	8/23/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4817	Work In Progress Requested by Mr. S. Perez Weight Room-Boys locker room door handle needs repair does not open. West side Weight Room door needs repairs does not lock.	8/23/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4820	Work In Progress Requested by Luis Saucedo Rm. 507 & 509 Annex Building-Install door stops on each of these doors.	8/23/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
4822	Work In Progress Requested by Ms. Zapien Rm. 154 Old English Building-The blinds are completely broken, the curtain is hanging.	8/23/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4429	Work In Progress Requested by Velia Rm. 112 Front Office-Three HE keys are needed for Key Box.	8/10/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4386	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop- 220 Volt Electric extension cord needed with a new female end, current ones puts people at risk of electrocution.	8/9/2005 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
4562	Work In Progress Requested by Ms. Klein Rm. 504 Annex Building- Air conditioner not working and appears to be leaking.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4564	Work In Progress Requested by Ms. Nanez Library-Install plywood baks to magazine shelves.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4516	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-New water heater for kitchen area of Panther Hut. Route to Bldg Mechanic as per Mike 8/15/05 Check to see whats wrong with the H2o heater they have new one in small mech. room.	8/12/2005 Medium	Velia Alarcon Fernando Moncayo Plumbing		Gadsden HS
4521	Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Need a lock and spare keys on the new filing cabinet.	8/12/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4627	Work In Progress Requested by Velia Rm. 112 Front Office-Work order #3911 was not asked to me made off master, also three keys were asked for not two. An additional 4 keys are needed as soon as possible.	8/17/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4630	Work In Progress Requested by Mr. Dixon Rm. 600 Business Building-Needs an F3 gate key.	8/17/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4631	Work In Progress Requested by Ms. M. Gonzalez Rm. 140 Old English Building-I would like to request a door stop for the new door and blinds fo one of my windows. The room gets "very" warm especialy 4th period. Receive measurements from Bldg Mechanic and re-route to Ruben for ordering. 4 ea - 43" W x 90' L	8/17/2005 9/16/2005 Medium	Velia Alarcon Ruben Ronquillo General Maintenance		Gadsden HS
4633	Work In Progress Requested by ISS Rm. 800 Old Counseling Center-Door frame falling off portable door leading to the old counseling center.	8/17/2005 Medium	Velia Alarcon Danny Miranda Doors and Hardware		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4904	Work In Progress Requested by Mr. D. Gallegos Rm. 403-Please install water fountains with hose bibs, between soccer canopies for Athletic events and Gadsden High School P.E. classes.	8/25/2005 Medium	Velia Alarcon Guadalupe Ontiveros Grounds		Gadsden HS
4905	Work In Progress Requested by Mr. Milligan Rm. 143 Old English Building-Four keys are needed of HX2. Three for the assistant coaches and one for key box.	8/25/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
5405	Work In Progress Requested by Velia Rm. 112 Front Office-HG3 is needed for key box.	9/12/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
5406	Work In Progress Requested by Velia Rm. 112 Front Office-Two SA16 are needed, one for Ms. Dominguez and one for key box.	9/12/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
5407	Work In Progress Requested by Marie School Registrar Storage Room East Wing of the Cafeteria-The new vault needs to be re-keyed. The cylinder from the old vault can be placed on the door of the East Wing of the Cafeteria were her new vault is located now.	9/12/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
5409	Work In Progress Requested by Marie Storage Room in the East Wing of the Cafeteria-In the move from the old vault to the storage room one of the fire prove filing cabinet's locks broke. The filing cabinet remained locked, needs to be fixed as soon as possible as the Registrar needs access to these files on a daily basis.	9/12/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
5412	Work In Progress Requested by D. Gallegos Rm. 403 Boys Gym-Install threaded end on faucet or shower in volleyball and boys basketball lockers to allow for a water hose connection.	9/12/2005 Medium	Velia Alarcon David Villalobos Plumbing		Gadsden HS
4243	Work In Progress Requested by Ms. Bradley Rm. 602 Business Building-Handle on window has broken off, needs to be replaced.	8/5/2005 Medium	Velia Alarcon Mario Apodaca Glass\Window Repairs		Gadsden HS
4248	Work In Progress Requested by Ms. Gutierrez Rm. 823 Barracks-New cylinder is needed for new filing cabinet, 3 keys are needed.	8/5/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4360	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HJ7, one for the floating teacher and one for the Key Box. For room number 753.	8/9/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4361	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK1, one for the floating teacher and one for the Key Box. For the Auto Shop.	8/9/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4362	Work In Progress Requested by Velia Rm. 112 Front Office-We need 5 additional keys of HE1. For the Gyms.	8/9/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4363	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK5, one for the I.A. in the classroom and one for the key box. For room number 569.	8/9/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4153	Work In Progress Requested by Mary Barreras Rm. 130 Old English Building-Need the new key to new lock to Sp. Ed. storage room for files and equipment. Key # M260	8/3/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4166	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace ceiling tile in storeroom and office.	8/3/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4199	Work In Progress Requested by Mr. Chambers Rm. 110 Front Office-Re-key doors, make cylinders off D Master, 4 keys will be needed. Have had several items stolen from office, please re-key as soon as possible.	8/4/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4204	Work In Progress Requested by Cathy Cano Parking Lot-Over Fall Break, have the lines in the North Parking Lot painted.	8/4/2005 Medium	Velia Alarcon Michael Munoz Painting		Gadsden HS
4269	Work In Progress Requested by Ms. Jacquez Rm. 752 Barracks-Window is unhinged and needs to be repaired.	8/8/2005 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
4271	Work In Progress Requested by Ms. Kalkwarf Rm. 750 Barracks-Floor tiles are broken and coming off the floor.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4272	Work In Progress Requested by Ms. Klein Rm. 504 Annex Building-Having a hard time locking and opening door, appears to be locked but stays unlocked.	8/8/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4279	Work In Progress Requested by Ms. Littlefield Rm. 226 North Building-The lock on my podium and one storage cabinet is brocken and lost.	8/8/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4282	Work In Progress Requested by Mr. Martinez Rm. 227 North Building-Replace carpet in Attendance Office area. One edge of the carpet is lifting, our concern is that a person may trip and fall.	8/8/2005 Medium	Velia Alarcon Michael Munoz Carpet Repair		Gadsden HS
4283	Work In Progress Requested by Mr. Myers Rm. 509 Annex Building-Key will not open storage door. HJ10 is the key that should open door.	8/8/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4285	Work In Progress Requested by Mr. Villa Rm. 510 Band Room-Security light in the center of the room does not work.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4286	Work In Progress Requested by Mr. Villa Rm. 510 Band Room-Need two HK13 keys made.	8/8/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
3902	Work In Progress Requested by Ms. Marquez New Counseling Portable-Two filing cabinets need to be keyed.	7/28/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
3910	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Bracket needed for N.M. Flag.	7/28/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
3920	Work In Progress Requested by Velia Front Office-The cylinder for room #107 will not open with a D Master or key assigned to door. This classroom is the Day Care on our campus and the building custodian can not open the classroom to clean. Please fix as soon as possible.	7/28/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
3494	Work In Progress Requested by Marie New Counseling Center Portable-New portable needs to be keyed HE134. Change old cylinder to doors of new portable doors.	7/12/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
3715	Work In Progress Requested by Mr. Pawloski Rm. 109A Main Building (Sp.Ed. Office)-Please remove the lock in my file cabinet, replace, and re-key it with a new one.	7/20/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
3716	Work In Progress ***URGENT***Requested by Velia Library-All the doors in the library need to be secured. They have changed all the door knobs and the cylinders need to be installed. URGENT library has alot of equipment that needs to me locked and secured!	7/20/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9972	Work In Progress Requested by Mr. D. Martinez North Building Main Hallway-Some tiles in the main hallway are damaged and are a hazard for parents, students, and teachers.	2/24/2006 Medium	Velia Alarcon Michael Munoz Carpet Repair		Gadsden HS
10031	Work In Progress Requested by Velia North Building-Door connecting Main North Building hallway and Varsity Gym does not want to open with the HE1 key, needs repair.	2/27/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
10034	Work In Progress Requested by Mr. Grubaugh Rm. 275C Library-Toilet in the boy's restroom won't quit flushing.	2/27/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
10035	Work In Progress Requested by Mr. Palmer Rm. 229 North Building-1.) Remove permanent desks that stick out into room. (There's 7 of them.) 2.) Relocate the gas and electrical outlets to the side counters. *Call me before work begins so I can clean out stored items.	2/27/2006 Medium	Velia Alarcon Michael Munoz General Maintenance		Gadsden HS
9823	Work In Progress Requested by Mr. Chambers All G.H.S. Buildings-Paint all G.H.S. Buildings with maroon trim (outside)-doors, windows, and flashing etc.	2/17/2006 Medium	Velia Alarcon Mario Apodaca Painting		Gadsden HS
9824	Work In Progress Requested by Mr. Chambers Weightroom-Need double doors at the Weightroom repaired to protect new equipment. Need dead bolts with keys installed on side doors (two way).	2/17/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
9905	Work In Progress Requested by Josie Enriquez Day Care Playgroun-Debris on playground needs to be removed, as per licensing. Playground needs to be maintained.	2/22/2006 Medium	Velia Alarcon Guadalupe Ontiveros Grounds		Gadsden HS
9909	Work In Progress Requested by Dolores Nanez Library-Anchor wall (partition) has glass window and shelves, made of wood.	2/22/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
9230	Work In Progress Requested by Velia Rm. 112 Front Office-Ms. Hamilton's classroom door does not want to lock, she's in room # 562.	2/1/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
9232	Work In Progress Requested by Jenny Gonzalez Rm. 250 Computer Lab-Light bulb needs to be replaced in the Boys Restroom.	2/1/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9276	Work In Progress Requested by Velia Rm. 112 Front Office-Pad lock are needed to be placed on roll down metal shades in the Concession Stand at the Football Field and three sets of keys will be needed. Students have been raising the metal shades climbing into the Concession Stand and ditching for the day. The doors are also very easily kicked and forced open, please repair as soon as possible.	2/2/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
9685	Work In Progress Requested by Ms. Foote Rm. 332 Academic Building-Replace ceiling light bulbs. ROUTE TO BM - AS PER MIKE 2/17/06	2/14/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
9686	Work In Progress Requested by David Vega Business Building-Light switch on north wall, bottom floor needs to be replace.	2/14/2006 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
9688	Work In Progress Requested by David Vega Rm. 243 Classroom Over Varsity Gym-Needs a few light bulbs replaced, on one of the lights. ROUTE TO BM - AS PER MIKE 2/17/06	2/14/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
9451	Work In Progress Requested by Velia Rm. 112 Front Office-Two keys of HE25 are needed for Key Box; room 200, Ms. A. Torres' classroom.	2/7/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
10521	Work In Progress Requested by Coach A. Lopez Softball Field-Replace light bulbs on score board. *AS PER MR. FOSTER, PLEASE RUSH THIS.	3/15/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
10522	Work In Progress Requested by Coach A. Lopez Softball Field-Paint dug outs maroon and trim gold.	3/15/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10524	Work In Progress Requested by Ms. L. Melendrez Rm. 333 Academic Building-This room needs to be painted this summer.	3/15/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
10525	Work In Progress Requested by Ms. L. Melendrez Rm. 333 Academic Building-Replace the chalkboard (back of room), 1/3 of the board can't be used because their is glue all over it.	3/15/2006 3/15/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10526	Work In Progress Requested by Ms. Runyan Rm. 900 Nurse's Office-Requesting refridgerated air conditioner or cieling fans. 3/27 - As per Mike Munoz please route this work order thru Mr. Chambers. e-mailed Velia and Mr. Chambers on 3/27 - mkv	3/15/2006 Medium	Velia Alarcon Michael Munoz Heating/Ventilation /Air Conditioning		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10573	Work In Progress Requested by Ms. Jordan Rm. 320 Academic Building-Has a light fixture with broken bulbs. It's been that way since October.	3/16/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10574	Work In Progress Requested by Velia Rm. 109C Main Building-Replace light bulb in Women's Faculty Restroom. *SECOND REQUEST	3/16/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10796	Work In Progress Requested by Velia Old English Building-Fix hole on the wall of the 1st floor of the Old English Building, close to room # 128. As Per Mr. Foster this needs to be fixed as soon as possible.	3/29/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10797	Work In Progress Requested by Velia Concession Stand by Girl's Gym-Change cylinder and four keys are needed for the door.	3/29/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
10800	Work In Progress Requested by Ms. Moreno Rm. 126 Main Building-There is a water leak above my channel one monitor. The monitor was replaced, but the technician said that this one would be damaged as well if the leak was not fixed.	3/29/2006 Medium	Velia Alarcon Fernando Moncayo Roof		Gadsden HS
10801	Work In Progress Requested by Mrs. Munoz Rm. 610 Business Building-Nine light bulbs need to be replaced.	3/29/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10287	Work In Progress Requested by Ms. L. Melendrez Rm. 333 Academic Building-I need a screen for a window in my room, so we can open it. Unfortunately we opened it last week and a bee came in and stung a student.	3/6/2006 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
10288	Work In Progress Requested by Ms. Trevizo Rm. 314 Academic Building-A window screen is missing, bees and flies enter classroom.	3/6/2006 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
10877	Work In Progress Requested by Mr. Wall Rm. 346 Academic Building-Two window blinds are need for the windows. They're required for Lock Down Fire Drills.	3/31/2006 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
10872	Work In Progress Requested by Mr. Grubaugh Rm. 275c Library-He believes a water pipe is leaking in the library storage room. It looks like the wall has taken some water damage.	3/31/2006 Medium	Velia Alarcon David Villalobos Plumbing		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10891	Work In Progress Requested by Ms. Papitto Rm. 216 North Building- Both door handles are broken, outside and inside on second door.	3/31/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
10879	Work In Progress Requested by Velia for Rm. 140 Old English Building-FOURTH REQUEST-The blinds in the room are broken and do not work properly. This will help keep the sun out in the afternoon when the room gets "very hot". Blind measurements 44 x 90.	3/31/2006 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
10881	Work In Progress Requested by Mr. Gamboa Rm. 128 Old Enlish Building-Blinds are needed for the windows, blind measurements 44 x 90, four sets are needed.	3/31/2006 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
10885	Work In Progress Requested by Velia for the hallways in the Old English Building-Halls need to be painted.	3/31/2006 Medium	Velia Alarcon Mario Apodaca Painting		Gadsden HS
5119	Work In Progress Power Outage - El Paso Electric	8/29/2005 Medium	Margret Villalobos Enrique Sotelo Electrical		Gadsden MS
8845	Work In Progress DOUBLE DOORS INSIDE BAND ROOM WHERE INSTRUMENTS ARE STORED DO NOT LOCK AND SECURE PROPERLY. EQUIPMENT SAFETY ISSUE.	1/18/2006 Medium	Maria Sitters Danny Miranda Doors and Hardware		Gadsden MS
9002	Work In Progress Sink is clogged we need the snake. to run it threw the wall drain.	1/24/2006 Medium	Rudy Arreola Joe Ontiveros Plumbing		Gadsden MS
9003	Work In Progress We need a new handle behind gym annex handle was pulled and broken off.	1/24/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock		Gadsden MS
9004	Work In Progress Rm #114 cylinder is stuck and wont turn and door needs to be secured for the end of the day.	1/24/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock		Gadsden MS
9038	Work In Progress Main Gym - pulled handle and broken, tagging on door, mirror and baseball dugouts.	1/23/2006 Medium	Rudy Arreola Rudy Arreola General Maintenance		Gadsden MS
9150	Work In Progress We need 2 cylinders changed so they can match the WA-94 key to the classroom and storage RMS	1/30/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock	Classroom	Gadsden MS
8468	Work In Progress We need to have front office fumigated big and small roaches when you turn on the lights.	1/6/2006 Medium	Rudy Arreola Margret Villalobos Pest Control		Gadsden MS
8472	Work In Progress We have broken water line front of the school.	1/6/2006 Medium	Rudy Arreola Guadalupe Ontiveros Grounds		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8602	Work In Progress Back flow in A-WING is leaking water. Route to Lupe as per Mike Munoz 3/10/06 - mkv	1/10/2006 Medium	Rudy Arreola Guadalupe Ontiveros Grounds		Gadsden MS
8603	Work In Progress Backflow in B-WING is leaking water.	1/10/2006 Medium	Rudy Arreola Guadalupe Ontiveros Grounds		Gadsden MS
6386	Work In Progress Light on the westside of the bandroom doesnt turn on.	10/13/2005 Medium	Rudy Arreola Enrique Sotelo Electrical		Gadsden MS
4218	Work In Progress Coil in not cooling cleaned out strainer and checked valve. RM 156	8/4/2005 Medium	Rudy Arreola Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Gadsden MS
4220	Work In Progress Rm 157/158 Unit is not cooling at all cleaned out strainer and checked valves.	8/4/2005 Medium	Rudy Arreola Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Gadsden MS
4528	Work In Progress We need 2 water fountains replaced in cafeteria.	8/12/2005 Medium	Rudy Arreola Jaime Gomez Heating/Ventilation /Air Conditioning		Gadsden MS
5918	Work In Progress Door handle is broken off boys lockerroom	9/28/2005 Medium	Rudy Arreola Manny Lozoya Key and Lock		Gadsden MS
5793	Work In Progress {{{GYM LOBBY}}} Wall needs to be secured.	9/23/2005 Medium	Rudy Arreola Danny Miranda General Maintenance	Restroom (Boys)	Gadsden MS
5569	Work In Progress VOC BLDG RM#306 - Need some assistance changing out ballast already replaced lamps high ceiling.	9/16/2005 Medium	Rudy Arreola Enrique Sotelo Electrical	Classroom	Gadsden MS
5317	Work In Progress Need to cap of water lines and drain removed already removed sink and counters. RM#188.	9/7/2005 Medium	Rudy Arreola Joe Ontiveros Plumbing	Classroom	Gadsden MS
10653	Work In Progress Need a new housing for riding burnisher.	3/20/2006 Medium	Rudy Arreola Jimmy Carbajal Custodial		Gadsden MS
9590	Work In Progress Boiler RM in B-WING not heating B-WING area. Called Control and Equipment	2/10/2006 Medium	Rudy Arreola Margret Villalobos Energy Management System		Gadsden MS
9591	Work In Progress Three way valve in unit is getting stuck needs to be replaced in RM 116	2/10/2006 Medium	Rudy Arreola Lorenzo Solis Heating/Ventilation /Air Conditioning	Classroom	Gadsden MS
9494	Work In Progress MAIN BLDG - NEED EMERGENCY LIGHTS IN HALLWAYS AND RESTROOMS AS PER PM 9373.	2/8/2006 Medium	Rudy Arreola Enrique Sotelo Electrical		Gadsden MS
9495	Work In Progress ANNEX GYM - ONE EXIT SIGN NOT WORKING DOOR LEADING TO BUS TURNAROUND. AS PER PM 9378.	2/8/2006 Medium	Rudy Arreola Enrique Sotelo Electrical		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9285	Work In Progress Small gate by the old Library Services Portable, needs to be fixed. It cannot be closed or locked.	2/2/2006 Medium	Yolie Jacquez Michael Munoz Fence Repair		Gadsden MS
3616	Work In Progress replace door at pump room	7/18/2005 Medium	Ricardo Jacquez Danny Miranda General Maintenance		Gadsden MS
7760	Work In Progress Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola Fire Extinguishers		Gadsden MS
10710	Work In Progress please install lights on the north side off the gym annex so the light will shine on the bus turnaround.	3/27/2006 Medium	Enrique Sotelo Electrical		Gadsden MS
5961	Work In Progress please reomve and replaced stained ceiling tiles in Mr.Lowenburgs office.	9/29/2005 Medium	Rudy Arreola General Maintenance		Gadsden MS
6424	Work In Progress WE NEED LIGHTS IN THE BOYS & GIRLS RR IN MAIN BLDG, ALSO WE NEED THE LIGHTS IN HALLWAYS AS PER PM 6095.	10/14/2005 Medium	Enrique Sotelo Electrical		Gadsden MS
4095	Work In Progress please fiil hole that is in front of entrance to band room. Will need a backing before gravel is applied. see mike	8/2/2005 High	Rudy Arreola General Maintenance		Gadsden MS
9295	Work In Progress please replaced stained ceiling tiles in Mr.Lowenburgs office and thru-out c-wing area thats needed. Thanks	2/3/2006 Medium	Rudy Arreola General Maintenance		Gadsden MS
8735	Work In Progress please install new sprinklers by picnic tables & where needed and level grounds around area. Thanks	1/13/2006 Medium	Guadalupe Ontiveros Grounds	Cafeteria	Gadsden MS
10204	Work In Progress Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Rudy Arreola Fire Extinguishers		Gadsden MS
4522	Work In Progress Door broken in room 500, and window shattered	8/12/2005 Medium	Dana Hamel Danny Miranda Doors and Hardware	Portables	Gadsden MS
4643	Work In Progress Need a copy of fire alarm key (See Mr. Hamel for his key).	8/17/2005 Medium	Dana Hamel Manny Lozoya Key and Lock		Gadsden MS
4777	Work In Progress The three locks on the office front window are broken, mostly poor design. The front office is wide open until these are repaired or replaced	8/22/2005 Medium	Dana Hamel Rudy Arreola General Maintenance	Office	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4778	Work In Progress 2nd request for an "A" master for GMS Campus	8/22/2005 Medium	Dana Hamel Manny Lozoya Key and Lock	Office	Gadsden MS
4982	Work In Progress Whole south side of annex does not have any air, class temperatures are above 95 degrees. The classes opposite hallway have conditioning, Please fix ASAP	8/26/2005 Medium	Dana Hamel Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Gadsden MS
5499	Work In Progress Change M4 key to a G key in all electrical room on campus, we have no "m" master	9/14/2005 Medium	Dana Hamel Manny Lozoya Key and Lock	Electrical Room	Gadsden MS
5500	Work In Progress change A3 key to a "g" key in storage room in annex	9/14/2005 Medium	Dana Hamel Manny Lozoya Key and Lock	Mechanical Room	Gadsden MS
5501	Work In Progress Repair the outside doors locks "w" master will not open doors to lobby	9/14/2005 Medium	Dana Hamel Manny Lozoya Key and Lock	Hallway/Corridor	Gadsden MS
5502	Work In Progress request 3 new "G" keys for principal and custodians	9/14/2005 Medium	Dana Hamel Manny Lozoya Key and Lock		Gadsden MS
3653	Work In Progress paint the columns on outside of gym	7/19/2005 Medium	Dana Hamel Rudy Arreola General Maintenance	Gym	Gadsden MS
3654	Work In Progress paint over the scratchouts in boys black restrooms	7/19/2005 Medium	Dana Hamel Rudy Arreola General Maintenance	Restroom (Boys)	Gadsden MS
3655	Work In Progress paint the front columns of the school to remove tagging	7/19/2005 Medium	Dana Hamel Rudy Arreola General Maintenance		Gadsden MS
9148	Work In Progress Please repair the bleachers, the rollers are out of sync, and we have a tournament coming up	1/30/2006 Medium	Dana Hamel Michael Munoz Equipment	Gym	Gadsden MS
9149	Work In Progress Extend concrete eastward from doorway towards the gym, not enough room for a motorized wheelchair	1/30/2006 Medium	Dana Hamel Michael Munoz Concrete	Hallway/Corridor	Gadsden MS
6241	Work In Progress The new roof on the vocational building leaked badly over vacation and the insulation in the old woodshop is falling. Serious problem with students returning tomorrow could fall at any time.	10/10/2005 Medium	Dana Hamel David Boyd Construction	Classroom	Gadsden MS
9518	Work In Progress check out the recepticle on front wall room 121, teacher currently using a side outlet for 5 computers	2/9/2006 Medium	Dana Hamel Enrique Sotelo Electrical		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10319	Work In Progress NEED TO PICK UP AN OVERHEAD PROJECTOR FROM G.M (MS. SWANSON) ON 3/15/06 MID MORNING FOR USE IN THE FORK LIFT CERTIFICATION CLASS @ 2:00 P.M. NEED TO RETURN IT ON 3/16/06 MORNING.	3/7/2006 Medium	Aida Salcedo Jimmy Carbajal Custodial		Gadsden MS
7479	Work In Progress Also at GMS Gym Bleachers They have a cheap extension for the score board, could we get a permanent 120v outlet fastened to front of bleachers? thanks , Carlos	11/18/2005 Medium	Carlos Vigil Enrique Sotelo Electrical		Gadsden MS
9876	Work In Progress Dugouts - Need to be painted there is graffitti all over them.	2/21/2006 Medium	Guadalupe Ontiveros Rudy Arreola Painting	Athletic Field	Gadsden MS
4867	Work In Progress THE PAD HOLDER IS WORN OUT AND WONT HOLD THE PAD AT ALL.	8/24/2005 Medium	Jimmy Carbajal Jimmy Carbajal Custodial Equipment Repair	Hallway/Corridor	Gadsden MS
3582	Work In Progress IRRIGATION CTRL PANEL - IRRIGATION BOOSTER PUMP IS NOT WORKING. PLEASE TROUBLESHOOT BUS TURNAROUND AREA. ROUTED TO ENRIQUE AS PER RICK 8/2/05	7/15/2005 8/2/2005 Medium	Lorenzo Hernandez Enrique Sotelo Electrical		Gadsden MS
9613	Work In Progress Need to remove A/C's on barracks that will be demolished as per Mike. A/C's will be reinstall at CHE for W/O #9201.	2/13/2006 Medium	Lorenzo Solis Lorenzo Solis Heating/Ventilation /Air Conditioning	Portables	La Mesa ES
4378	Work In Progress locksmith need three keys for supply rm. key no F 49 8/23- Debra needs status on this work order submitted on 8/9/05 - mkv	8/9/2005 Medium	Frank Lara Manny Lozoya Key and Lock		La Mesa ES
9899	Work In Progress MAIN BLDG - NEED TO REPLACE 2 BROKEN WINDOWS 26 1/2 W X 54 3/4 L	2/21/2006 Medium	Frank Lara Ruben Ronquillo Glass\Window Repairs		La Mesa ES
9715	Work In Progress MAIN BLDG - NEED TO REPLACE BROKEN WINDOWS 26 1/2 W X 54 5/8 L (WIRE GLASS)	2/15/2006 Medium	Frank Lara Ruben Ronquillo Glass\Window Repairs		La Mesa ES
7716	Work In Progress Kitchen - Need to shutdown gas and water service on Friday, 12/16/05 @ 1:00 pm. Route to Pancho, Spoke to him today 12/15/05 and he can do this. - M. Munoz	12/1/2005 12/2/2005 Medium	Alfredo Holguin Frank Lara Plumbing	Cafeteria	La Mesa ES
3322	Work In Progress Yearly - La Union ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza Fire Protection		La Union ES
3344	Work In Progress Yearly - La Union ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza Fire Protection		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4917	Work In Progress please repair asphalt where other water line was repired.	8/25/2005 Medium	Michael Munoz Concrete		La Union ES
8256	Work In Progress Alvarez Farms ,panel needs main lug kit replaced	12/22/2005 Medium	Carlos Castillo Carlos Castillo Electrical	Classroom	La Union ES
3572	Work In Progress NEED LIGHT BULBS FOR RECESSED LIGHTS AT LA UNION ELEM. THE MAJORITY ARE BURNED OUT. THANK YOU.	7/15/2005 Medium	Arturo Nunez Carlos Castillo Electrical		La Union ES
10888	Work In Progress Outside - 12 walls graffiti w/spray paint. Case# 200602694	3/27/2006 Medium	Eddie Mendez Salvador Gonzalez General Maintenance		La Union ES
10878	Work In Progress Need to set old fashion mouse traps.	3/31/2006 Medium	Mary Garcia Salvador Gonzalez Pest Control		La Union ES Irma Lazarin
10120	Work In Progress Please send exterminator have found mouse dropping in bldg.	3/2/2006 Medium	Margret Villalobos Margret Villalobos Pest Control		La Union ES
10121	Work In Progress Please shampoo upstairs carpet during Spring Break.	3/2/2006 Medium	Margret Villalobos Santos Galindo Custodial		La Union ES
10119	Work In Progress JTP - Mr. Casavantes needs you to replace lock from the stroage computer cabinet.	3/2/2006 Medium	Julie Hernandez Manny Lozoya Key and Lock		La Union ES
10085	Work In Progress need to replace starter and heater thanks	3/1/2006 Medium	Ricardo Jacquez Carlos Castillo Electrical		La Union ES
4864	Work In Progress JTP- Rosaro Ruedas needs a L201 key.	8/24/2005 Medium	Selma Nevarez Manny Lozoya Key and Lock		La Union ES JTP
5371	Work In Progress In the women's restroom, in the southwing, the toilet is constantly flushy.	9/9/2005 Medium	Santos Galindo Salvador Gonzalez General Maintenance		La Union ES
5117	Work In Progress Lights in computer room keeps going out; breaker needs to be checked.	8/31/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES
5312	Work In Progress After last nights rainfall, leaks were discovered in rooms #208, #209, and the library.	9/7/2005 Medium	Santos Galindo Lorenzo Solis Roof		La Union ES
4825	Work In Progress Need keys for room #100, #106, and room #108; plus keys for a file cabinet in the nurse's office.	8/23/2005 Medium	Santos Galindo Manny Lozoya Key and Lock		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4853	Work In Progress SINK AT CUSTODIAL CLOSET AT OLD BLDG. IS CLOGGED UP.	8/24/2005 Medium	Santos Galindo David Villalobos Plumbing		La Union ES
4775	Work In Progress Parking lanes need to be repaint in yellow and bus lane also needs to be repaint but in red. Route to Sal Gonzalez as per Mike 9/13/05 -mkv	8/22/2005 Medium	Santos Galindo Salvador Gonzalez General Maintenance		La Union ES
4408	Work In Progress a light next to my office need to be looked at cause it buzzes all day long.	8/10/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES
4410	Work In Progress They need to check lighting from building cause several lights are off. And some stay on 24 hrs out side.	8/10/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES
4356	Work In Progress in room 202 there is no outlet for refrigeration unit a.s.p.	8/9/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES
4223	Work In Progress need an electrical outlet by computer hookups room 203.	8/5/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES
4372	Work In Progress need a fan motor in electrical storage room.	8/9/2005 Medium	Santos Galindo Jose Ambriz Heating/Ventilation /Air Conditioning		La Union ES
6718	Work In Progress need electrical outlet on north wall	10/25/2005 10/26/2005 Medium	Santos Galindo Carlos Castillo Electrical	Office	La Union ES
6403	Work In Progress NEED CORK STRIP INFRONT OF THE OFFICE IN HALLAWAY.	10/14/2005 Medium	Santos Galindo Ruben Ronquillo General Maintenance		La Union ES
7446	Work In Progress would like hallway in old wing painted and frames. and new base trimming.	11/18/2005 Medium	Santos Galindo Salvador Gonzalez Painting		La Union ES
7391	Work In Progress 11/15/05 To Caly. Relocate electrical outlet.	11/15/2005 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
6418	Work In Progress Work Truck - need to repair broken tial-light.	10/14/2005 Medium	Salvador Gonzalez Angel Gonzales Vehicle Maintenance		La Union ES
5949	Work In Progress Music Room needs a new circuit installation.	9/29/2005 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
8547	Work In Progress Take out grass at swings area with the back hoe and fill with sand (has half of needed sand)	1/9/2006 Medium	Salvador Gonzalez Guadalupe Ontiveros Grounds		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9087	Work In Progress 1/27/06 To David Villalobos. There is a boiler back flow water valve leaking , on my opinion has to replaced.	1/27/2006 Medium	Salvador Gonzalez David Villalobos Plumbing		La Union ES
8982	Work In Progress David I need some PVC to make a drain fanel for boiler room please. Thank you.	1/24/2006 Medium	Salvador Gonzalez David Villalobos Plumbing		La Union ES
5786	Work In Progress Upper hinge on door at JTP needs to be repair. Might need to be weld	9/23/2005 Medium	Salvador Gonzalez Manny Lozoya Key and Lock		La Union ES
5503	Work In Progress Old emergency light fixtures (the complete system) are not working can you check them please. thank you	9/14/2005 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
10313	Work In Progress Room 206 needs to be fumigated for spiders.	3/7/2006 Medium	Salvador Gonzalez Margret Villalobos Pest Control		La Union ES
10409	Work In Progress Manny, the lock door knob at classroom 100 is mising. Can you come and fix it please.	3/10/2006 Medium	Salvador Gonzalez Manny Lozoya Key and Lock		La Union ES
10569	Work In Progress 1/16/06 Manny We need to secure door for the end of the day, lock problem.	3/16/2006 Medium	Salvador Gonzalez Manny Lozoya Key and Lock		La Union ES
9768	Work In Progress To Mike Munoz Subject: I would like to install PVC watering system on side of the school and between buildings.	2/16/2006 Medium	Salvador Gonzalez Guadalupe Ontiveros Grounds		La Union ES
9769	Work In Progress Teacher in classroom 110 requires more power outlets because his room only has two.	2/16/2006 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
10076	Work In Progress 2/28/06 To Jose Ambriz: I would like to replace some (4) old water cooler for master cool system.	2/28/2006 Medium	Salvador Gonzalez Jose Ambriz Heating/Ventilation /Air Conditioning		La Union ES
10849	Work In Progress 3/30/06 To David Villalobos. Subject: Porcelain sink in restroom at JTP was broken. Needs an other one to be installed.	3/30/2006 Medium	Salvador Gonzalez David Villalobos Plumbing		La Union ES
5447	Work In Progress Student Cross Walk - Path on the west side there is a tree that is in the way. Students have to scoot over onto the street.	9/12/2005 Medium	Margret Villalobos Alfredo Holguin General Maintenance		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6217	Work In Progress NEED TO (PER ATTACHED DRAWING): 1. CUT CURB 2. DIG DIRT 4" 3. ADD CRUSH FINE / CEMENT 4. MOVE DUMPSTER INSIDE THE CURB	10/10/2005 Medium	Michael Munoz Guadalupe Ontiveros Grounds		Loma Linda ES
9454	Work In Progress Need a gate key for El Paso Disposal.	2/7/2006 Medium	Juliet Parra Manny Lozoya Key and Lock		Loma Linda ES
10567	Work In Progress CLOGGED DRAIN. FRANCES BLACK LLI SNP MGR 882-4707	3/16/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Loma Linda ES
6538	Work In Progress Need Ditch Witch delivered to Loma Linda tomorrow.	10/18/2005 Medium	David Villalobos Angel Gonzales Equipment		Loma Linda ES
8607	Work In Progress NEEDING KEY FOR ROOM 119,	1/10/2006 Medium	Grace Alvarado Manny Lozoya Key and Lock		Loma Linda ES
8143	Work In Progress MIKE INSTALL OUTLET IN BOOKROOM	12/15/2005 Medium	Grace Alvarado Michael Mc Dermott General Maintenance		Loma Linda ES
6686	Work In Progress INSTALL ELECTRICAL CIRCUIT IN ROOM 208 FOR MICROWAVE AND FRIDGE.	10/24/2005 Medium	Grace Alvarado Enrique Sotelo Electrical		Loma Linda ES
7361	Work In Progress REPLACE TIMER FOR BOILER	11/15/2005 Medium	Grace Alvarado Jose Ambriz Heating/Ventilation /Air Conditioning		Loma Linda ES
3829	Work In Progress MR. TRUJILLO IS WANTING NEW KEYS MADE FOR DESKS, CABINETTS AND FILE CABINETS. ALSO NEEDING NAME PLATE FOR NEW TEACHERS. MS. BERARD, CHAVEZ-FISHER, GRIEGO, DESANTIAGO, HUGHES, MARKHAM, MEDINA, MERRICK, MONTES, PINA, PRICE, RIOS-ALVILLAR,	7/26/2005 Medium	Grace Alvarado Manny Lozoya Key and Lock		Loma Linda ES
4593	Work In Progress MIKE MUNOZ, REPLACE EAST FENCE	8/16/2005 Medium	Grace Alvarado Michael Munoz Fence Repair		Loma Linda ES
9897	Work In Progress MIKE MCDERMOTT: REQUEST REPAIR OR REPLACEMENT OF VENETIAN BLINDS, PARTICULARLY WINDOW ON NORTH ISE OF EAST WALL ROOM 103 LET ME KNOW. AS PER MR. T.	2/21/2006 Medium	Grace Alvarado Ruben Ronquillo Glass\Window Repairs		Loma Linda ES
10129	Work In Progress MIKE, PLEASE REPLACE BALLASTE IN NURSES BATHROOM	3/2/2006 Medium	Grace Alvarado Michael Mc Dermott General Maintenance		Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10133	Work In Progress MANNY LOZOYA, MEN BATHROOM IN SECOND GRADE LOST TUMBLER. TUMBLER CAN BE FOUND IN THE OFFICE	3/2/2006 Medium	Grace Alvarado Manny Lozoya Key and Lock		Loma Linda ES
9831	Work In Progress ATTN: PLUMBERS NEED KIT INSTALLED TO BOLT TOILET TO FLOOR & NEW BOWLI WAY. BOYS R.R. NORTHWEST WING. NEED SENSOR SINKS REPAIRED. 2ND REQUEST LEAKING VERY BADLY. BOYS RR SOUTH WEST WING. NEED NEW HOSE BIB INSTALLED IN COURTYARD BEHIND LIBRARY. OLD ONE WILL NOT CLOSE.	2/17/2006 Medium	Grace Alvarado Joe Ontiveros Plumbing		Loma Linda ES
9219	Work In Progress MANNY. REPAIR NE GATE. LOCK IS BROKEN	2/1/2006 Medium	Grace Alvarado Manny Lozoya Key and Lock		Loma Linda ES
10538	Work In Progress ATTN: GROUNDS NEED PATHS CLEARED AND GROUNDS LEVELED. ALSO WOULD LIKE TO HAVE BORDERS BUILT AROUND WEST PINETREES	3/15/2006 Medium	Grace Alvarado Guadalupe Ontiveros Grounds		Loma Linda ES
10173	Work In Progress MIKE, NEED YOU TO TRANSPORT ARTBOARDS TO SANTA TERESA MIDDLE SCHOOL. MUST BE THERE BY APRIL 20TH BY 8:00 AM. TAKE DOWN IS APRIL 24TH, FROM 8:00 AM TO 3:30	3/3/2006 Medium	Grace Alvarado Michael Mc Dermott General Maintenance		Loma Linda ES
10892	Work In Progress FAUCET LEAKS IN ROOM 209	3/31/2006 Medium	Grace Alvarado Joe Ontiveros Plumbing		Loma Linda ES
8647	Work In Progress NEED TO COMPLETE BUILDING INSPECTION FOR ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOU OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED & SIGNED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JANUARY 27, 2006	1/11/2006 Medium	Aida Salcedo Luis Solis Custodial		Loma Linda ES
9386	Work In Progress Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Michael Mc Dermott General Maintenance		Loma Linda ES
5568	Work In Progress As per Mike Munoz issue a 6 & 7 Grand Master keys to Mike Mc Dermott.	9/16/2005 Medium	Manny Lozoya Key and Lock		Loma Linda ES
3345	Work In Progress Yearly - Loma Linda ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott Fire Protection		Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3323	Work In Progress Yearly - Loma Linda ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott Fire Protection		Loma Linda ES
3324	Work In Progress Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Mesquite ES
3346	Work In Progress Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Mesquite ES
9132	Work In Progress please remove grass and tiller ,then level on the enviromental park as per our discussion and reweiv of the plans.	1/30/2006 Medium	Guadalupe Ontiveros Grounds	Athletic Field	Mesquite ES
10208	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Mesquite ES
10242	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
10252	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
4015	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
4005	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
3971	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Mesquite ES
9135	Work In Progress Barracks - Remove rocks from roof and repair and secure water lines (safety issue).	1/30/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
9137	Work In Progress East of Library - Lots of weeds growing apply chemical, treat weeds ask for imput from Lupe so you wont kill trees.	1/30/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
9138	Work In Progress Pecan Trees in back parking lot - Trim branches, cut weeds around and make new wells and water.	1/30/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9139	Work In Progress North Fence Line by Pine Trees - Cut weeds and pickup trash and treat fence line.	1/30/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
9176	Work In Progress NEED TO ASSIT W/ BROKEN 1-1/4 INCH FEMALE ADDAPTER AS DISCUSSED.THANX.ALSO NEED 4 MORE 3500 HUNTER SPRINKLERS.	1/31/2006 Medium	Romauldo Apodaca Guadalupe Ontiveros Grounds		Mesquite ES
10061	Work In Progress broken master key need one right away,thanx.	2/28/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
10130	Work In Progress need to replace lever handle in sanchez portable,security issue. thanx.	3/2/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
9935	Work In Progress MANNY, NEED TO HELP W/ OPENING STORAGE RM. TRIED TO OPEN BUT CAN,T. THANX.	2/23/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
9937	Work In Progress DANNY MIRANDA, NEED DOOR HARDEWARE FOR CAFETERIA DOORS, AND MAIN DOORS. THANX.	2/23/2006 Medium	Romauldo Apodaca Danny Miranda Doors and Hardware		Mesquite ES
10714	Work In Progress need to open dry storage in kitchen for sound and signal. thanx	3/27/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
10835	Work In Progress rick,please assist w/disposal of cancelled leach lines.thanx.	3/30/2006 Medium	Romauldo Apodaca Ricardo Jacquez Sewage/Water Treatment Plant		Mesquite ES
8677	Work In Progress Portable 602 - Need vinyl flooring replaced w/ carpet, floor in bad shape,safety issue, someone may trip.	1/12/2006 Medium	Romauldo Apodaca Michael Munoz Carpet Repair	Portables	Mesquite ES
6507	Work In Progress kiki, 5 rms w/ out lights need assistance.thanks. ARREGLAR PROBLEMA EN ALAMBRADO DE LUCES EN SALONES DE OLD WING.	10/18/2005 10/18/2005 Medium	Romauldo Apodaca Romauldo Apodaca Electrical		Mesquite ES
6508	Work In Progress jaime need to assist w/ boilers to change over to heating,also need gas valve for heater in old office.thanx.	10/18/2005 Medium	Romauldo Apodaca Jaime Gomez Heating/Ventilation /Air Conditioning		Mesquite ES
6509	Work In Progress lupe ontiveros.need play sand for play structures and alma del valle.thanx.	10/18/2005 Medium	Romauldo Apodaca Guadalupe Ontiveros Grounds		Mesquite ES
7825	Work In Progress NEED TO RUN ELECTRICAL LINES TO MAIN FIELD FOR RED RIBBON CUTTING CEROMONY ON 12/8/05 AT 6:AM FOR HEATERS AND LIGHTING,PER MS. PHILLIPS.	12/5/2005 Medium	Romauldo Apodaca Enrique Sotelo Electrical		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3558	Work In Progress need compresor changed out on armstrong unit in rm. 608.thanx.	7/14/2005 Medium	Romauldo Apodaca Jaime Gomez Heating/Ventilation /Air Conditioning		Mesquite ES
4340	Work In Progress manny need to assist w/ 2 doors in porables having hard time tpo close safety issue. also need lever handle.	8/9/2005 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
3955	Work In Progress DINING AREA - NEED TO WELD HINGES ON DOOR FALLING DOWN.	7/29/2005 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
4699	Work In Progress manny need your assistance w/ doors that are hard to open and close. thanx.	8/19/2005 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
10758	Work In Progress Need a gate key for Gloria Martinez w/PSFA.	3/28/2006 Medium	Peggy Jo Hernandez Manny Lozoya Key and Lock		Mesquite ES
8822	Work In Progress Front Entrance Blue Double Doors - Cylinders need to be cleaned.	1/18/2006 Medium	Peggy Jo Hernandez Manny Lozoya Key and Lock		Physical Plant Complex
8774	Work In Progress I would like to request the "Student Records Office" sign be moved from the north outside wall of the loading bay to the wall beside the Records Room door and also the door leading into the warehouse by the rec. room re-painted with "Student Records Office" Inside.	1/17/2006 Medium	Tracey Swinford Rudy Arreola General Maintenance		Physical Plant Complex
7834	Work In Progress Need to make a key for D. Miranda's Office for Ruben.	12/5/2005 Medium	Ruben Ronquillo Manny Lozoya Key and Lock		Physical Plant Complex
9057	Work In Progress PPD Barracks - Need to run power to existing panel box. (Coordinate w/eachother Cali, Enrique and Mike Mc Dermott).	1/26/2006 Medium	Michael Munoz Enrique Sotelo Electrical		Physical Plant Complex
5121	Work In Progress Power Outage - El Paso Electric	8/29/2005 Medium	Margret Villalobos Enrique Sotelo Electrical		Physical Plant Complex
3461	Work In Progress Need a copy of control key (core) to keep here at the Maintenance Dept - as per A. Holguin.	7/12/2005 Medium	Alfredo Holguin Manny Lozoya Key and Lock		Physical Plant Complex
4017	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Rudy Arreola General Maintenance		Physical Plant Complex
10254	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Rudy Arreola General Maintenance		Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10216	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Rudy Arreola Fire Extinguishers		Physical Plant Complex
9749	Work In Progress WILL NEED ELECTRICAL WORK DONE IN CUSTODIAL WAREHOUSE TO BE ABLE TO INSTALL NEW WASHER & DRYER - MUST BE DONE BY FEBUARY 24, 2005.	2/16/2006 Medium	Aida Salcedo Enrique Sotelo Electrical		Physical Plant Complex
9750	Work In Progress WILL NEED PLUMBING WORK DONE IN CUSTODIAL WAREHOUSE TO BE ABLE TO INSTALL NEW WASHER & DRYER - MUST BE DONE BY FEBUARY 24, 2005.	2/16/2006 Medium	Aida Salcedo Joe Ontiveros Plumbing		Physical Plant Complex
8737	Work In Progress NEED SPARE KEY FOR AIDA (TRUCK) - P1106 BB6	1/13/2006 Medium	Aida Salcedo Manny Lozoya Key and Lock		Physical Plant Complex
4585	Work In Progress Need to replace water heater,its giving out an extremeley bad odor.Health issue.	8/16/2005 Medium	Carlos Castillo Joe Ontiveros Plumbing	Electrical Room	Physical Plant Complex
7711	Work In Progress please order all material needed to paint barracks in the back and let me know what staff will be need to accomplish the project.	12/1/2005 Medium	Danny Miranda Painting		Physical Plant Complex Portables
5526	Work In Progress NEED A "CB4" KEY FOR GUILLERMO - TO HAVE ACCESS TO ENERGY OFFICE TO CLEAN.	9/15/2005 Medium	Manny Lozoya Key and Lock		Physical Plant Complex
3379	Work In Progress Mens Restroom in Custodial Warehouse -Install new privacy lockset	7/7/2005 Low		Restroom (Boys)	Physical Plant Complex
3380	Work In Progress Mens Restroom in Custodial Warehouse- Replace toilet tank cover with appropriate size for unit.	7/7/2005 Medium	Fred Appelzoller Plumbing	Restroom (Boys)	Physical Plant Complex
3186	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Rudy Arreola Fire Extinguishers		Physical Plant Complex
10419	Work In Progress Need to open Barrack for Melissa w/Finance on Monday, March 13th. She will be here at 10:00 am. -Thanks mkv	3/10/2006 3/7/2006 Medium	Manny Lozoya Key and Lock		Physical Plant Complex
7642	Work In Progress Auto Shop - Need to install 4 cylinders all the same but different from main entrance. Need 4 keys issued (see Angel).	11/30/2005 Medium	Angel Gonzales Manny Lozoya Key and Lock		Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
7772	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola Fire Extinguishers		Physical Plant Complex
7810	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola General Maintenance		Physical Plant Complex
9950	Work In Progress 2/21/06 (2)7910 (4)unload materials for chaparral elen. @ san miguel elem. (1.5)exchange corner bead @ foxworth (.5)back to vado elem. 2/21-6	2/23/2006 Medium	Danny Miranda Danny Miranda Doors and Hardware		Physical Plant Complex
5432	Work In Progress Auto Shop - need to install new door knob to new door at Angel's Office.	9/12/2005 Medium	Danny Miranda Manny Lozoya Key and Lock		Physical Plant Complex
8634	Work In Progress As per Mike Vehicle # 23 (Manny Lozoya Van) needs new tires.	1/11/2006 Medium	Manny Lozoya Angel Gonzales Vehicle Maintenance		Physical Plant Complex
3940	Work In Progress MARTA JACQUEZ - A/C UNIT IS NOT WORKING AT ALL.	7/29/2005 Medium	Marta Jacquez Jaime Gomez Heating/Ventilation /Air Conditioning		Physical Plant Complex
10175	Work In Progress DISHWASHER - WHERE THE SOAP GOES THRU IS CLOGGED UP. NANCY ROLLIN SNP MGR 589-2550	3/3/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Riverside ES
3348	Work In Progress Yearly - Riverside ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran Fire Protection		Riverside ES
3326	Work In Progress Yearly - Riverside ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran Fire Protection		Riverside ES
5592	Work In Progress please see what can be done to repair or remove electrical outlet on floor on serving line. Outlet has a can over it and could be a trip hazard.	9/19/2005 Medium	Danny Orozco Food Services	Cafeteria	Riverside ES
10803	Work In Progress MR MANNY LOZOYA SIR NEED TO HAVE KEYS MADE FOR HALL LIGHT AND GYM OLD KEYS VERY HARD TO TURN ON AND OFF THANK YOU SIR AND GOD BLESS	3/29/2006 Medium	Adan Duran Manny Lozoya Key and Lock		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10773	Work In Progress MR JOSE AMBRIZ SIR WILL NEED SOME 520 FEN BELTS ALSO FOR 4500 AC UNITS ABOUT 3 WILL DO ME FOR NOW I THANK YOU SIR AND GOD BLESS	3/28/2006 Medium	Adan Duran Jose Ambriz Heating/Ventilation /Air Conditioning		Riverside ES
10717	Work In Progress MR MIKE MUNOZ AND RUBEN RONQILLO SIR I WOULK LIKE TO EXCHANGE COMODE OGER HAS A KINK IN THE CABLE ALSO WOULD LIKE TO EXCHANGE BLOWER LEAKS ALOT AND KEEPS GETTING CHOKE THANK YOU SIR AND GOD BLESS	3/27/2006 Medium	Adan Duran Ruben Ronquillo Equipment		Riverside ES
10642	Work In Progress 3/17/06 SIGN IN CHECK SCHOOL GROUNDS BUILDING FENCE 2 DIG OUT AND REPAIR BROKEN WATER LINE 11/2 REPAIR 5 BROKEN BUBBLERS VANDELS 21/2 WO 10582 CHANGE OUT BURN OUT SWITCH AC COMPUTER LAB CHANGE OUT BURN OUT SWITCHS REZNOR HEATERS RM 101 AND 145 1/2 CLOSE WEST AND DROP OFF GATES 1 FILE PAPER WORK REPORT AND SIGN OUT 3/17-5.5	3/17/2006 3/27/2006 Medium	Adan Duran Adan Duran General Maintenance		Riverside ES
9714	Work In Progress NORTH ENTRANCE DOUBLE DOORS - AUTOMATIC DOOR CLOSER IS LEAKING ALOT OF OIL AND DOOR IS CLOSING FAST.	2/15/2006 Medium	Adan Duran Manny Lozoya Key and Lock		Riverside ES
9734	Work In Progress MR CARLOS CASTILLO SIR WE HAVE SEVERAL EMERGENCY LIGHT THAT NEED BATTRIES WILL NEED 6 AT THIS TIME THANK YOU SIR	2/15/2006 Medium	Adan Duran Carlos Castillo Electrical		Riverside ES
9856	Work In Progress NEED TAGS TO TAG FIRE EXTINGUISHERS AS PER PM 9346.	2/17/2006 Medium	Adan Duran Ruben Ronquillo Fire Extinguishers		Riverside ES
8225	Work In Progress 12/20/05 1/2 SIGN IN CHECK SCHOOL GROUND 6 PAINT BATHROOMS 1/2 WASH ROLLERS AND PAINT BRUSH AND PAN 1 FILE PAPER WORK AND SIGN OUT 12/20 - 8	12/20/2005 Medium	Adan Duran Adan Duran General Maintenance		Riverside ES
8661	Work In Progress MR CARLOS CASTILLO SIR WILL NEED SOME LAMPS SOME U LAMPS HALL WAY LAMPS SOME PL 13 SOME METAL HALIDE THANK YOU VERY MUCH SIR	1/11/2006 Medium	Adan Duran Carlos Castillo Electrical		Riverside ES
7156	Work In Progress 11/7/05 1/2 SIGN IN CHECK SCHOOL GROUNDS 2 1/2 MOWED GRASS 1 1/2 EDGE WITH TRIMER 1 CLEAN SIDEWALKS WITH BLOWER 1 REPAIR ENTRANCE DOOR WILL NOT CLOSE 1/2 CLOSE WEST AND DROP OFF GATES 1 FILE PAPER WORK AND SIGN OUT 11/7 - 8	11/7/2005 Medium	Adan Duran Adan Duran General Maintenance		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
5115	Work In Progress MR LUPE ONTIVEROS SIR WILL NEED THE USE OF THE BACKHOE TO MOVE SOCCOR GOAL POST AWAY FROM PARKING AREA UNSAFE FOR KIDS THANK YOU SIR	8/31/2005 Medium	Adan Duran Guadalupe Ontiveros Grounds		Riverside ES
4596	Work In Progress MR MANNY LOZOA SIR NEED TO CHANGE OUT DOOR HANDLE BY MRS ARIAS OFFICE THE ONE THERE DO NOT LOCK NEED ONE THAT CAN BE LOCKED THANK YOU SIR	8/16/2005 Medium	Adan Duran Manny Lozoya Doors and Hardware		Riverside ES
4473	Work In Progress MR MANNY LOZOYA SIR THE DOOR ON NEW PORTABLE IS STUCK IN LOCK CAN NOT GET IT TO UNLOCK PORTABLE B IN BACK THANK YOU SIR	8/11/2005 Medium	Adan Duran Manny Lozoya Key and Lock	Portables	Riverside ES
4388	Work In Progress MR JOSE AMBRIZ SIR WE NEED TO HOOK BACK UP THE AIR IN WHAT USE TO BE MRS FLORES OFFICE IT WAS REMOVE AT HER REQUEST AND ITS KIND OF WARM IN THERE THANK YOU SIR	8/9/2005 Medium	Adan Duran Jose Ambriz Heating/Ventilation /Air Conditioning		Riverside ES
3690	Work In Progress MR MANNY LOZOYA FILE CABINET NEW PORTABLE RM B NEEDS REPAIR WILL NOT LOCK PARTS MISSING THANK YOU SIR	7/19/2005 Medium	Adan Duran Manny Lozoya Key and Lock		Riverside ES
3778	Work In Progress MR DAVID VILLALOBOS WE HAVE SOME LEAKING FUACTS NEW WING NEED REPAIR KIT OR REPLACEMENT THANK YOU SIR	7/22/2005 Medium	Adan Duran David Villalobos Plumbing		Riverside ES
3414	Work In Progress MR LOZOYA MRS ARIAS IS HAVING TROUBLE WITH THE STORAGE ROOM LOCK WOULD LIKE FOR YOU TO LOOK AT IT THANK YOU SIR	7/8/2005 Medium	Adan Duran Manny Lozoya Key and Lock		Riverside ES
10827	Work In Progress Milk Cooler is out of order Nancy Rollin - SNP Manager 589-2550	3/30/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Riverside ES
5057	Work In Progress We need a new Door Knob placed in the Data Clerk office. (office area) At this time the door doesn't lock.	8/30/2005 Medium	Olga Arias Manny Lozoya Key and Lock		Riverside ES
5058	Work In Progress Carpet (Doorway) to Data clerk office is coming loose. Plastic edge is picking-up.. Thanks	8/30/2005 Medium	Olga Arias Michael Munoz Carpet Repair		Riverside ES
10290	Work In Progress please paint the interior of the cafeteria. Thanks	3/6/2006 Medium	Michael Munoz Danny Vega Painting	Cafeteria	San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
7015	Work In Progress Need backflow tested on irrigation system thanks	11/4/2005 Medium	Ricardo Jacquez Ricardo Jacquez Sewage/Water Treatment Plant		San Miguel ES
8801	Work In Progress Lock is hard to open and lock on pump house. Please repara thank you.	1/17/2006 Medium	Ricardo Jacquez Manny Lozoya Key and Lock		San Miguel ES
4489	Work In Progress Need an extra key for these rooms.	8/11/2005 Medium	Barbara Cardenas Manny Lozoya Key and Lock	Classroom	San Miguel ES 25, 49,50
7632	Work In Progress The backflow prevention device on the irrigation distribution system needs to have the annual inspection performed.	11/29/2005 Medium	Guadalupe Ontiveros Grounds		San Miguel ES
3175	Work In Progress Monthly - San Miguel ES Roof Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Vega Roof		San Miguel ES
8401	Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Danny Vega General Maintenance		San Miguel ES
9670	Work In Progress main building, please apply 10% bleach and scrub pillars on the north side of building as per work shop. Use your PPEs.	2/13/2006 High	Michael Munoz Danny Vega General Maintenance		San Miguel ES
5337	Work In Progress DISHWASHER LEAKING WATER. EVA MIRANDA - 233-2860	9/8/2005 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	San Miguel ES
10794	Work In Progress DISHWASHER: THERE IS NOT SOAP COMING OUT. EVA M. SNP MGR 233-2860	3/29/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	San Miguel ES
10733	Work In Progress need 10gal Q6-57P MARBLETIQUE PAINT TO PAINT CAFETERIA ASAP (2nd request)	3/27/2006 Medium	Danny Vega Ruben Ronquillo Painting		San Miguel ES
10721	Work In Progress water leak in kitchen/dish washer drain/need gasket	3/27/2006 Medium	Danny Vega Danny Orozco Food Services		San Miguel ES
10432	Work In Progress need a 220v outlet in boiler rm/as per MR.MARRUFO/MR.CHAVEZ	3/10/2006 Medium	Danny Vega Enrique Sotelo Electrical		San Miguel ES
10433	Work In Progress NEED REPAIRS ON MARQUEE /PLEXY GLASS & FRAME DAMAGE BY WINDS/6FT X 6FT	3/10/2006 Medium	Danny Vega Ruben Ronquillo Glass/Window Repairs		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10434	Work In Progress NEED A FLUSH HANDLE/CHAIN TYPE FOR TANK/FILL VALVE ALSO RM40	3/10/2006 Medium	Danny Vega Joe Ontiveros Plumbing		San Miguel ES
10435	Work In Progress REQUESTING A SMALL 3GAL WATER HEATER INSTALLED IN ART&MUSIC RM44-45	3/10/2006 Medium	Danny Vega Joe Ontiveros Plumbing		San Miguel ES
10465	Work In Progress need some boards 12x12x2 to replace/ repair ramps/asap safety hazard portable46	3/13/2006 Medium	Danny Vega Ruben Ronquillo Ramps/Platforms		San Miguel ES
10861	Work In Progress library door/key jamms in cylinder/very hard to secure	3/31/2006 Medium	Danny Vega Manny Lozoya Key and Lock		San Miguel ES
5270	Work In Progress NEED LDO 2QT/FLUSH VALVE KIT/DIAPRAHMS/TUB&SINK SEALER/ELONGATED TIOLET SEAT	9/6/2005 Medium	Danny Vega Joe Ontiveros Plumbing		San Miguel ES
5307	Work In Progress portable #28 refig unit not cooling/please check it out asap	9/7/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
5176	Work In Progress CAFETERIA GIRLS RR/SINK FAUCET BROKEN - OFF /PLEASE REPLACE/HOT-COLD TYPE	9/2/2005 Medium	Danny Vega Joe Ontiveros Plumbing		San Miguel ES
5177	Work In Progress NEED FILTERS 12X24X1	9/2/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
4445	Work In Progress Portable 29 - Needs to be secured by the end of the day.	8/10/2005 Medium	Danny Vega Manny Lozoya Key and Lock	Portables	San Miguel ES
4447	Work In Progress principals office door hard to open/door needs to be shaved.stop by asap	8/10/2005 Medium	Danny Vega Manny Lozoya Key and Lock		San Miguel ES
3834	Work In Progress A/C UNIT NOT WORKING IN HIGH SPEED PORTABLE#58	7/26/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
4051	Work In Progress portable #30/rheem a/c unit not woking.stop by asap	8/1/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
6367	Work In Progress rm#32 day&night type furnance/pilot wont stay on-needs thermo-couple	10/13/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
6584	Work In Progress NEED LOCK-OUT DEVICE FOR DISCONNECT BOX/PORTABLE 28-29/POWER SHUT-OFF DAILY-ASAP	10/20/2005 Medium	Danny Vega Enrique Sotelo Electrical		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6617	Work In Progress j.gomez/need to start and go thru check list on boiler unit/before 10-28-05 (.you can do it)	10/21/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
6618	Work In Progress need two loads playground sand asap	10/21/2005 Medium	Danny Vega Guadalupe Ontiveros Grounds		San Miguel ES
6785	Work In Progress boiler is not heating/please ck it out/class rooms are cold in the morning	10/26/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
7563	Work In Progress boys restroom heater coil leaks water/need replaced asap found leak and repaired it	11/28/2005 12/1/2005 Medium	Danny Vega Lorenzo Solis Heating/Ventilation /Air Conditioning		San Miguel ES
8007	Work In Progress need one set gates wheels /west gate wheels damaged /asap(ruben ronquillo)	12/12/2005 Medium	Danny Vega Ruben Ronquillo Fence Repair		San Miguel ES
8847	Work In Progress need fertilizer spread on campus fields/front lawn 16-8-8	1/18/2006 Medium	Danny Vega Guadalupe Ontiveros Grounds	Athletic Field	San Miguel ES
8082	Work In Progress library toilet will not flush/we need to replace it	12/13/2005 Medium	Danny Vega Joe Ontiveros Plumbing		San Miguel ES
8676	Work In Progress east exit door/main bldg/having trouble securing /panic bar stuck	1/12/2006 Medium	Danny Vega Manny Lozoya Key and Lock		San Miguel ES
10327	Work In Progress NEED PARTS FOR WALL HYDRANT, AND A 1/2" SHUT OFF VALVE TO ISOLATE IT.	3/7/2006 Medium	Gerardo Marquez David Villalobos Plumbing		Santa Teresa ES
10329	Work In Progress LUPE, NEED FOR YOU TO GET WITH ME ABOUT SCHEDULEING FOR THE AERRATOR AND ALSO TO FIGURE HOW MUCH FERTILIZER TO ORDER FOR PLAY AREA. (WE TALKED ABOUT THIS WITH M.MUNOZ ON 3,6,06 IF YOU RECALL.)	3/7/2006 Medium	Gerardo Marquez Guadalupe Ontiveros Grounds		Santa Teresa ES
10330	Work In Progress LUPE STILL NEED FOR YOU TO SEND SOMEONE TO REDIG TRENCH TO DIVERT RAIN WATER AT BACK FENCE AREA. ALSO TO CLEAR SAND DRIFTS FROM FENCE.	3/7/2006 Medium	Gerardo Marquez Guadalupe Ontiveros Grounds		Santa Teresa ES
10485	Work In Progress need electrician to check out emergency lights that failed to come on during my last m. emerg. lighting insp..	3/14/2006 Medium	Gerardo Marquez Carlos Castillo Electrical		Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10527	Work In Progress MANNY; COULD YOU CHECK OUT THE LOCK TO THE WK RM. IN C-WING. A KID STUCK SOMETHING IN THE KEYHOLE, AND I AM UNABLE TO SECURE THE RM. THIS RM. HAS A COMPUTER, PRINTER, AND OTHER EQUIP. THAT I MUST SECURE.	3/15/2006 Medium	Gerardo Marquez Manny Lozoya Key and Lock		Santa Teresa ES
10736	Work In Progress RUBEN, NEED 60-50 POUND BAGS OF 16-8-8 FERTILIZER.FOR PLAY AREA.	3/27/2006 Medium	Gerardo Marquez Ruben Ronquillo General Maintenance		Santa Teresa ES
9995	Work In Progress DAVE, NEED FOR YOU TO GET ME A 1/2 INCH SHUT OFF VALVE FOR WALL HYDRANT THATS LEAKING.	2/24/2006 Medium	Gerardo Marquez David Villalobos Plumbing		Santa Teresa ES
4152	Work In Progress ATTN MANNY. MANNY, WE STILL NEED FOR YOU TO MAKE US ANOTHER KEY TO THE MAIL BOX. THANKS.	8/3/2005 Medium	Gerardo Marquez Manny Lozoya Key and Lock		Santa Teresa ES
4154	Work In Progress ATTN LUPE, LUPE, WE STILL NEED THE COBBLESTONE TO KEEP CHECK THE RAIN ERROSION. ALSO NEED FOR BETO AND MANNY TO REDIG TRENCH AT BACK FENCE TO KEEP RAIN FROM FLOODING GROUNDS AND CLASS RMS.	8/3/2005 Medium	Gerardo Marquez Guadalupe Ontiveros Grounds		Santa Teresa ES
3657	Work In Progress ATTN. Manny . NEED FOR YOU TO DUPLICATE A KEY TO THE MAIL BOX . THANKS .	7/19/2005 Medium	Gerardo Marquez Manny Lozoya Key and Lock		Santa Teresa ES
8731	Work In Progress DAVE; NEED FOR YOU TO COME AND CHECK OUT HOSE BIB AT S.END OF A-WING. I CAN'T GET IT TO STOP LEAKING. I TOOK APART THE FRONT COVER AND CLEANED OFF THE DIAPHRAM , BUT IT STILL LEAKS. THEHOSE BIBS HAVE NO SHUT OFF VALVES UNLESS WE SHUT OFF THE WATER TO THE RR. WATER.	1/13/2006 Medium	Gerardo Marquez David Villalobos Plumbing		Santa Teresa ES
9005	Work In Progress Need a gate key for El Paso Disposal.	1/24/2006 Medium	Juliet Parra Manny Lozoya Key and Lock		Santa Teresa ES
10488	Work In Progress VACUUM CLEANER NEEDS SERVICE	3/14/2006 Medium	Pablo Diaz Jimmy Carbajal Custodial Equipment Repair		Santa Teresa ES
10489	Work In Progress BURNISHER IS NOT WORKING, WHEN YOU PLUG IT IN THERE IS NOT POWER.	3/14/2006 Medium	Pablo Diaz Jimmy Carbajal Custodial Equipment Repair		Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9213	Work In Progress ADVANCE BA/6124 NEW SCRUBBER NEEDS TO BE CHECKED OUT WATER NOT COMEING OUT THANK YOU .	2/1/2006 Medium	Luis Murillo Jimmy Carbajal Custodial		Santa Teresa HS
10100	Work In Progress BROKEN SYLINDER SOMETHING INSIDE WE TO REPLACED AT CLASS ROOM 15	3/1/2006 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
9210	Work In Progress BROKENT COMMED FROM BOYS REST ROOMS AT THE NEW AREA WE NEED REPLACE	2/1/2006 Medium	Joel Herrera David Villalobos Plumbing		Santa Teresa HS
9411	Work In Progress DOOR FROM MAINT ENTRANCE IT DOESN'T LOCKE MANNY WE NEED FIX IT.	2/6/2006 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
9679	Work In Progress NEW CAFETERIA BOTH DRESSING ROOMS. 1.KEY FOR MAIN DOOR TO DRESSING ROOM BOTH BOYS AND GIRLS. 2 KEY FOR CLOSET DOOR BOTH BOYS AND GIRLS. 3 ADULT BATHROOMS NEED TO BE RE-CORE THE LOCKS 4.KEY FOR BATHROOMS IN BOTH DRESSING ROOMS 5.MD-12 AND MD-2 KEYS NEED FOR MR. ANGELO AND MR. JEWETT. 6. LOCK FOR MS. FRANCIS SOCCER CABINET BY G.Y.M AREA.	2/14/2006 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
10537	Work In Progress NEED EIGHT (8) FLO. LIGHT BULBS FOR MARQUEE, IT IS NOT LIGHTING, WOULD LIKE TO HAVE IT LIT.	3/15/2006 Medium	Joel Herrera Carlos Castillo Electrical		Santa Teresa HS
10860	Work In Progress WE HAVE ELECTRICAL PROBLEM ON A/C AT CLASS ROOM 312 AT ENGLISH WING AREA.	3/31/2006 Medium	Joel Herrera Carlos Castillo Electrical		Santa Teresa HS
5102	Work In Progress WE NEED REPLACE MA 51 AND TREE LOCKS AT R.O.T.C CLASS ROOMS.	8/30/2005 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
5923	Work In Progress MIKE MUNOZ WE NEED BARRIER FENCE ON WEST SIDE AT SOCCER FIELD TO RETAIN BALLS OUT IT PLAY . ALSO NEED FENCE FROM 20 YARD LINE TO 20 YARD LINE IN FRONT OF FOOTBALL VISITORS SEATING AREA. SEE R GALLEGOS THANK YOU MIKE...	9/28/2005 Medium	Joel Herrera Michael Munoz Fence Repair		Santa Teresa HS
4807	Work In Progress MANNY MY MASTER KEY IS BROKEN IT DOESN'T WORK NO MORE.	8/23/2005 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
4966	Work In Progress RUBEN WE NEED REPAIR THE WINDOWS AT DAYCAREBUILDING IT DOESN'T OPEN THANK YOU Route to Joel as per Mike 9/12/05 - mkv	8/26/2005 Medium	Joel Herrera Joel Herrera General Maintenance		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4463	Work In Progress SENSER ON SINCK AT GIRLS REST ROOM IT DOESN'T WORK WE REPLACE IT .	8/11/2005 Medium	Joel Herrera David Villalobos Plumbing		Santa Teresa HS
4454	Work In Progress SMASHED WINDOW ON DOOR - STOLEN LARGE SCREEN TV. DISCOVERED BY MR. BUCKLEY	8/1/2005 Medium	Joel Herrera Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS
8157	Work In Progress MR. GALLEGOS WANTS DEADBOLT ON BOYS AND GIRLS DRESSING ROOMS 2- NEED TO CHANGE DOOR KNOBS TO BE ABLE TO LOCK THE WORK ROOM BETWEEN THE BAND AND CHORUS ROOM 3- AND NEED TO CHANGE ONE ENTRY KEY TO THE RESTROOMS FROM THE MEETINS ROOM. 12/15 - 5	12/15/2005 12/15/2005 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
9143	Work In Progress 1-27-06 2.0 RE-MOVE FLAIRS AT G.Y.M AREA. 1.0 CHECK HEATINGS UNITS 1.0 REPLACE ELECTRICAL SWITCH AT G.Y.M AREA 2.0 CHECK ELECTRICAL PROBLEM AT KITCHEN 2.0 CHECK AND REPAIR DOOR LOCK AT COACHES ROOM AT SOFBALL FIELD AREA. 1/27 - 8	1/30/2006 Medium	Joel Herrera Joel Herrera General Maintenance		Santa Teresa HS
8403	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
3158	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
3176	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez Roof		Santa Teresa HS
3329	Work In Progress Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez Fire Protection		Santa Teresa HS
3351	Work In Progress Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez Fire Protection		Santa Teresa HS
7815	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
7773	Work In Progress Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Santa Teresa HS
7804	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10716	Work In Progress Soccer Field & Football Field - Need to install sprigs on fields.	3/27/2006 Medium	Guadalupe Ontiveros Grounds	Athletic Field	Santa Teresa HS
7767	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
7108	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
7119	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
7071	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
8306	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
8392	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
8324	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Arturo Nunez Roof		Santa Teresa HS
4484	Work In Progress please install venting system and exhaust hood in the metal shop. See Joe Angelo.	8/11/2005 Medium	Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa HS
9990	Work In Progress bleachers do not go in or out. please repair.	2/24/2006 Medium	Michael Munoz Equipment	Gym	Santa Teresa HS ATHLETIC
9999	Work In Progress please repair the wood that is breaking off the dugouts. Thanks	2/24/2006 Medium	Guadalupe Ontiveros Grounds	Athletic Field	Santa Teresa HS
8410	Work In Progress NEED DOOR WINDOW REPLACED ON ROOM #304 6 3/4X24 1/2 1/4" WIRE SAFETY GLASS. WILL NEED PRICE TO PUT ON VANDALISM REPORT. THANK YOU.....	1/4/2006 Medium	Arturo Nunez Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS
8571	Work In Progress NEED TO BORROW SCISSOR LIFT TO PUT UP BANNERS ON GYM RAFTERS. AND PUT UP SOME ACUSTIC PANELS THAT FELL . AND CHECK THEM ALL, FOR SAFETY PURPOSES.	1/9/2006 Medium	Arturo Nunez Ruben Ronquillo Equipment		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8757	Work In Progress NEED TO HAVE OLD BAND ROOM FUMIGATED, AND MOUSE TRAP INSTALLED, MICE HAVE BEEN SIGHTED, DUE TO FOOD NOT PROPERLY STORED. A.S.AP. THANK YOU....	1/13/2006 Medium	Arturo Nunez Margret Villalobos Pest Control		Santa Teresa HS
7840	Work In Progress NEED FIVE (5) LOCKS 6" SLIDE LOCKING HASP	12/5/2005 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
7194	Work In Progress ADULT RESTROOM IN OFFICE AREA NEEDS TO BE PAINTED.	11/8/2005 Medium	Aida Salcedo Arturo Nunez General Maintenance		Santa Teresa HS
10724	Work In Progress NEED TO DO TRAINING ON CLEANING RESTROOMS, USING CHEMICALS & EQUIPMENT AND TIME MANAGEMENT FOR: JAVIER PARRA, RAFAEL MERA, MARIA DE SANTIAGO & OSCAR ESPARZA	3/27/2006 Medium	Aida Salcedo Guillermo Hernandez Custodial		Santa Teresa HS
10730	Work In Progress NEED TO TRAIN: JAVIER PARRA, RAFAEL MERAZ, MARIA DE SANTIAGO & OSCAR ESPARZA ON USING ROTO & BURNISHER MACHINES	3/27/2006 Medium	Aida Salcedo Sal Acuna Custodial		Santa Teresa HS
10318	Work In Progress NEED TO POWER WASH WALL BY LOCKER ROOM	3/7/2006 Medium	Aida Salcedo Guillermo Hernandez Custodial		Santa Teresa HS
10217	Work In Progress Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Santa Teresa HS
10132	Work In Progress NEED EMERGENCY PUSH BUTTONS FOR SHOP AREAS, THE ONE ON THERE, ARE BROKEN, OTHERS DON'T WORK. SAFETY ISSUE. SIX (6) EA.	3/2/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
9869	Work In Progress NEED ASSISTANT ON C.W. LINE AT A.H.U. AT LIBRARY, A SMALL SMALL LEAK HAS SPRUNG, NEED TO SEE IF WE CAN REPAIR.	2/21/2006 Medium	Arturo Nunez Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa HS
9737	Work In Progress NEED FIRE EXT. THAT WERE TOOK IN TO BE REFILLED , SERVICED, AND TESTED. BACK TO SCHOOL SITE. GOOD MORNING MARGRET, AS PER MIKE, WORK ORDER 9737 NEEDS TO GO TO RUBEN. THANKS, DANNY	2/15/2006 Medium	Arturo Nunez Ruben Ronquillo Fire Extinguishers		Santa Teresa HS
9785	Work In Progress NEED 12 EA. 2X4 277V. LAY IN LIGHTS WITH EMERGENCY BALAST. FOR 300 WING ROOMS, AND HALLWAYS.	2/16/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9787	Work In Progress NEED 14 EA. OUSIDE SECURITY LIGHT FIXTURES TO REPLACE EXISTING ORIGINAL FIXTURES ON MAIN BUILDING, AND ANNEX. WILL ASISSIT ELECTRICAN ON REPLACING FIXTURES.	2/16/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
9623	Work In Progress DOOR KNOB IN COUSELORS OFFICE, SOUTH SIDE DOOR,CLINDER IS BROKEN THEY CAN'T OPEN DOOR WITH THEIR KEY. WOULD LIKE TO HAVE LOCKSMITH HELP US WITH THIS SITUATION. REPAIR CYLINDER AT COUNSELORS OFFICE	2/13/2006 1/16/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
10414	Work In Progress NEED 227V PRIMARY TO 120V SECONDARY FOR A.H.U. AT LIBRARY, NED AS SOON AS POSSIBLE,	3/10/2006 Medium	Arturo Nunez Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa HS
10415	Work In Progress NEED TO REPLACE FOUR (4) FLO. LIGHT BULB FIXTURES ON CAGE STORAGE HALLWAY.	3/10/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
10371	Work In Progress NEED THE CYLINDERS AT REMOLED SECTION OF SCHOOL, EXTERIOR DOORS INSTALLED AS SOON AS POSSIBLE. FOR SECURITY PURPOSE.	3/8/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
10646	Work In Progress NEED THE LOCK AT CAGE STORAGE , CHANGED TO DIFFRENT KEY, SO ONLY TRACK COACH, CAN HAVE ACESS TO EQUIPMENT, HE IS MISSING SOME STUFF.	3/17/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
10635	Work In Progress NEED 70 WATTS METAL HALIDE BULBS # M143/E TWELVE (12) EA. FOR NEW ADDITION, OUTSIDE LIGHTS.	3/17/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
10780	Work In Progress NEED CALI TO COME AND SEE WHAT NEEDS TO BE DONE FOR WASHER AND DRIER HOOK UP AT TRAINERS OFFICE. APPLIANCES ARE ON ORDER AS PER TRAINER.	3/28/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
10781	Work In Progress NEED SIX (6) EA. 50A 125/250 PLUGS FOR WELDING SHOP, WOULD LIKE TO USE ONE TYPE OF PLUG FOR OUTLETS SO THAT WELDING MACHINES CAN BE USED ANY WHERE IN THE ROOM.	3/28/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
3571	Work In Progress NEED CONDENSER MTR. FOR SNACK ROOM A.C. UNIT, MTR. IS FROZEN UNIT IS DOWN.	7/15/2005 Medium	Arturo Nunez Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa HS
5214	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6107	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
6118	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
6018	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
6036	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Arturo Nunez Roof		Santa Teresa HS
4023	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez General Maintenance		Santa Teresa MS
4013	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez General Maintenance		Santa Teresa MS
3975	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez Fire Extinguishers		Santa Teresa MS
6218	Work In Progress DUE TO WATER OVER FLOW, GYM FLOOR HAS BUBBLED BY FLOODING. NEED VENDOR TO DO A RECOMMENDATION AND QUOTE US.	10/10/2005 Medium	Aida Salcedo Michael Munoz Carpet Repair		Santa Teresa MS
10177	Work In Progress Need line locates at STMS, to portables and to gym from north building and any major water electrical gas between north and south building. Thanks , Carlos	3/3/2006 Medium	Carlos Vigil David Villalobos Plumbing		Santa Teresa MS
10178	Work In Progress Need line locates at STMS, to portables and to gym from north building and any major water electrical gas between north and south building. Thanks , Carlos	3/3/2006 Medium	Carlos Vigil Carlos Castillo Electrical		Santa Teresa MS
9776	Work In Progress s.t.m.s. need to paint new doors in front of gym	2/16/2006 Medium	Danny Miranda Jaime Mijarez Painting		Santa Teresa MS
9777	Work In Progress s.t.m.s. need to paint new door at music room	2/16/2006 Medium	Danny Miranda Jaime Mijarez Painting		Santa Teresa MS
6437	Work In Progress please replace h20 fountain and unclog drain.	10/14/2005 Medium	David Villalobos Plumbing	Office	Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3353	Work In Progress Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez Fire Protection		Santa Teresa MS
3330	Work In Progress Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez Fire Protection		Santa Teresa MS
8159	Work In Progress Markee Sign. As per Mrs. Williams she would like to have the sign installed during winter break.	12/15/2005 Medium	Jaime Mijarez Carlos Castillo Electrical		Santa Teresa MS
8160	Work In Progress Markee Sign. As per Mrs. Williams she would like to have the sign installed during the winter break.	12/15/2005 Medium	Jaime Mijarez Guadalupe Ontiveros Grounds		Santa Teresa MS
8161	Work In Progress Principals office. Need a window installed on interior door.	12/15/2005 Medium	Jaime Mijarez Danny Miranda Doors and Hardware		Santa Teresa MS
3465	Work In Progress N.bldg home ec rm 10. Ruben Ronquillo I am going to need a Miter saw to cut legs on ten of the tables. please make sure it has a good blade. I am planning this project for next week (7/18/05.) The wood is oak.	7/12/2005 Medium	Jaime Mijarez Ruben Ronquillo General Maintenance		Santa Teresa MS
3412	Work In Progress S.bldg upper level. Because of the shortage of classrooms Mrs. williams has to move the teachers lounge to a storage rm. The floor has no tile, can you include this room with the area's that the contractor will be installing floor tile. Attn: Alfredo holguin.	7/8/2005 Medium	Jaime Mijarez Michael Munoz Carpet Repair		Santa Teresa MS
3387	Work In Progress Rm 1. N. bldg lower level Removal of carpet is going to require tile installation. Alfredo H. requested a work order for contractor.	7/7/2005 Medium	Jaime Mijarez Michael Munoz Carpet Repair		Santa Teresa MS
3364	Work In Progress S.bldg custodial storage. please make 2ea. A-7 keys for principal and building mechanic.	7/6/2005 Medium	Jaime Mijarez Manny Lozoya Key and Lock		Santa Teresa MS
5363	Work In Progress N.bldg maintenance and custodial. Would like a duct and register installed on heat pump.	9/9/2005 Medium	Jaime Mijarez Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa MS
5149	Work In Progress N.bldg Rm 3. Mrs. williams would like to have a sidewalk that goes from Rm 3 exit door out to the fence. This way when there is a fire drill the special ed students on wheel chairs can be moved away from the building in case of an actual emergency.	9/1/2005 Medium	Jaime Mijarez Michael Munoz Concrete		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10458	Work In Progress S.bldg Rm 3037(Guerrero). 1- Need keys for filing cabinet. 2- Need classroom door key, the key that I have only opens one door and not the other. 3- Need key for teachers desk or replacement.	3/13/2006 Medium	Jaime Mijarez Manny Lozoya Key and Lock		Santa Teresa MS
10425	Work In Progress N.bldg lower level HP 32 is on hi/lo pressure failure. I found leak and sealed it. I need Joe A. to charge the the unit with R22 refrigerant.	3/10/2006 Medium	Jaime Mijarez Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa MS
10028	Work In Progress Locker key. PLease make a duplicate key for the locks. This key is the only master Margie or Mr. kamenski have.	2/27/2006 Medium	Jaime Mijarez Manny Lozoya Key and Lock		Santa Teresa MS
9828	Work In Progress Gym ceiling heaters not working.Need scissor lift to light up pilots.ASAP!!!!	2/17/2006 Medium	Jaime Mijarez Ruben Ronquillo Equipment		Santa Teresa MS
9910	Work In Progress Campus. Can you help us with a tracter to move all the sand that has accumulated by the walk ways and stairways to the gym. Requested by Mr. Mora.	2/22/2006 Medium	Jaime Mijarez Guadalupe Ontiveros Grounds		Santa Teresa MS
5113	Work In Progress AIR CONDITIONER DOES NOT TURN ON THE LEFT SIDE OF THE ROOM FACING CHALK BOARD ROOM 3 MR. DORANTES	8/31/2005 Medium	Laura Parra Jose Ambriz Heating/Ventilation /Air Conditioning	Classroom	Santa Teresa MS
8556	Work In Progress Kitchen #1- Sink is clogged unable to use Kitchen #4- Pipes under sink leak	1/9/2006 Medium	Laura Parra David Villalobos Plumbing	Classroom	Santa Teresa MS room 10
9575	Work In Progress MR. SORIA PRUNE OUR CAMPUS TREES .THANK YOU.	2/10/2006 Medium	Ismael Rodriguez Mike Soria Grounds	Parking Lot	Santa Teresa MS
10363	Work In Progress I NEED SOME SERVICE ON ADVANCE AQUA CLEAN SERIAL NUM.00-02264.NOT WORKING PROPERLY.THANK YOU.	3/8/2006 Medium	Ismael Rodriguez Jimmy Carbajal Custodial Equipment Repair	Custodial	Santa Teresa MS
10365	Work In Progress ALSO, I NEED SOME SERVICE ON ANOTHER EXTRACTER SERIAL NUM.97-00353.BRAND AQUA CLASSIC.NEED THEM FOR SUMMER READY.THANK YOU.	3/8/2006 Medium	Ismael Rodriguez Jimmy Carbajal Custodial Equipment Repair	Office	Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10325	Work In Progress JIMMY I NEED FOR YOU TO DO SOME SERVICE ON ONE WET N DRY IT IS NOT LIFTING THE WATER PROPERLY I WANTED TO HAVE IT READY FOR SUMMER.THANK YOU.SERIAL NUM.013674 BRAND.NOBLER.	3/7/2006 Medium	Ismael Rodriguez Jimmy Carbajal Custodial Equipment Repair	Custodial	Santa Teresa MS
10791	Work In Progress MR.LOZOYA YOU CAN ALREADY CHANGE THE CYLINDERS FROM NORTH AND SOUTH BUILDINGS.CHECK WITH MR. RODRIGUEZ.THANK YOU.	3/29/2006 Medium	Ismael Rodriguez Manny Lozoya Key and Lock	Office	Santa Teresa MS
5308	Work In Progress I NEED A KEY A7 FOR THE PRINCIPAL TO HAVE ACCESS TO MY STORAGE ROOM. THANK YOU.SEE MR. RODRIGUEZ.	9/7/2005 Medium	Ismael Rodriguez Manny Lozoya Key and Lock	Custodial	Santa Teresa MS
3118	Work In Progress I NEED FOR GYM KEY CYLINDERS TOO TO BE CHANGE BEFORE 7/13/05.CONT.MR.RODRIGUEZ.	7/1/2005 Medium	Ismael Rodriguez Manny Lozoya Key and Lock		Santa Teresa MS
3875	Work In Progress NEED REPLACEMENT KEYS FOR NURSE'S OFFICE DORR AND FILE CABINET	7/27/2005 Medium	Irene Trujillo Manny Lozoya Key and Lock		Sunland Park ES
5422	Work In Progress NEED TO REMOVED DEAD TREES.	9/12/2005 Medium	Irene Trujillo Guadalupe Ontiveros Grounds		Sunland Park ES
6465	Work In Progress THE GROUNDS NEED TO BE SMOOTHED OUT AFTER THE RAIN. THE SAND WAS WASHED AWAY IN SOME AREAS.	10/17/2005 Medium	Irene Trujillo Guadalupe Ontiveros Grounds		Sunland Park ES
6878	Work In Progress ADD NEW ELECTRICAL OUTLET TO TEACHER'S LOUNGE.	10/31/2005 Medium	Irene Trujillo Carlos Castillo Electrical		Sunland Park ES
7041	Work In Progress A door opening is needed from lounge to existing bathroom in nurse's office. Please send someone to check wiring. 1/25 - Faxed to Mr. Chavez for approval - mkv	11/4/2005 Medium	Irene Trujillo Carlos Castillo Electrical		Sunland Park ES
7522	Work In Progress A kitchen sink is needed in room 52. The new teacher's lounge.	11/22/2005 Medium	Irene Trujillo David Villalobos Plumbing		Sunland Park ES
7523	Work In Progress Please remove carpet in room #52 and install floor tile.	11/22/2005 Medium	Irene Trujillo Michael Munoz Carpet Repair		Sunland Park ES
10373	Work In Progress 2 classroom keys need to be re-keyed so these can open the hall doors from the outside. TA25 AND TA63	3/8/2006 Medium	Irene Trujillo Manny Lozoya Key and Lock		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10102	Work In Progress PLEASE SPRAY CLASSROOM #21 AND OFFICE AREA FOR LICE.	3/1/2006 Medium	Irene Trujillo Margret Villalobos Pest Control		Sunland Park ES
9270	Work In Progress TA17 AND TA31 - PLEASE ADJUST SO THAT THE KEYS OPEN SIDE DOORS.	2/2/2006 Medium	Irene Trujillo Manny Lozoya Key and Lock		Sunland Park ES
9985	Work In Progress PORTABLE A & B NEED THE FLOOR TILE TO BE REPLACED.	2/24/2006 Medium	Irene Trujillo Michael Munoz Carpet Repair		Sunland Park ES
10890	Work In Progress need a key - TA24 - to open classroom and outside doors. also need 2 keys to be keyed to open outside doors.	3/31/2006 Medium	Irene Trujillo Manny Lozoya Key and Lock		Sunland Park ES
6625	Work In Progress Need Heavy Duty Dolly for fire proof file cabinet on Monday October 24, 2005	10/21/2005 Medium	Larry Flores Maria Sitters Custodial		Sunland Park ES
9317	Work In Progress vac-needs repairer none	2/3/2006 Medium	Larry Flores Jimmy Carbajal Custodial Equipment Repair	Elevator	Sunland Park ES
10317	Work In Progress Vacuum needs repair	3/7/2006 Medium	Larry Flores Jimmy Carbajal Custodial Equipment Repair		Sunland Park ES
10623	Work In Progress Vacuum needs repair	3/17/2006 Medium	Larry Flores Jimmy Carbajal Custodial Equipment Repair		Sunland Park ES
3355	Work In Progress Yearly - Sunland Park ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Sebastian Diaz Fire Protection		Sunland Park ES
3179	Work In Progress Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz Roof		Sunland Park ES
3268	Work In Progress Monthly - Sunland Park ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz General Maintenance		Sunland Park ES
3278	Work In Progress Monthly - Sunland Park ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz General Maintenance		Sunland Park ES
3160	Work In Progress Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz Fire Extinguishers		Sunland Park ES
3423	Work In Progress Yearly - Sunland Park ES Emer. Light Test: Annual - Refer to PM schedule details.	7/10/2005 Medium	Alfredo Holguin Sebastian Diaz Fire Protection		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9214	Work In Progress need borders for playground S.P.E.	2/1/2006 Medium	Danny Miranda Sebastian Diaz General Maintenance		Sunland Park ES
9120	Work In Progress 1.3 compartment sink is leaking 2. right side of serving line (cold unit) is not working. and 3. Blodgett Oven is still not heating properly Marina Ramirez - SNP Manager 589-2545	1/27/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Sunland Park ES
8041	Work In Progress Portable A - Broken window 30 x 28 Double Glass. Est. Damage 125.00	12/1/2005 Medium	Sebastian Diaz Ruben Ronquillo Glass\Window Repairs	Portables	Sunland Park ES
7029	Work In Progress The sink in the room 41 is clog need to bring the snake also need to replace the fauset thank you	11/4/2005 Medium	Sebastian Diaz David Villalobos Plumbing		Sunland Park ES
6692	Work In Progress Need 4 metal blinds for portable F 46"X 52" thank you.	10/24/2005 Medium	Sebastian Diaz Ruben Ronquillo General Maintenance		Sunland Park ES
8879	Work In Progress Need to repair lock at cafeteria double doors. thank you.	1/19/2006 Medium	Sebastian Diaz Manny Lozoya Key and Lock		Sunland Park ES
9082	Work In Progress Need to replace door knob portable E .Is broken is difficult to open from inside.thank you.	1/27/2006 Medium	Sebastian Diaz Manny Lozoya Key and Lock		Sunland Park ES
8710	Work In Progress In the cafeteria the water heater need to replace the ingicion pilot. thank you	1/12/2006 Medium	Sebastian Diaz Jose Ambriz Heating/Ventilation /Air Conditioning		Sunland Park ES
5195	Work In Progress 9/2/05 Lupe Ontiveros Need the heavy tractor to remove the weeds around the school thank you	9/2/2005 Medium	Sebastian Diaz Guadalupe Ontiveros Grounds		Sunland Park ES
9221	Work In Progress Need to replace door closer in front library. thank you	2/1/2006 Medium	Sebastian Diaz Manny Lozoya Key and Lock		Sunland Park ES
9834	Work In Progress Need to remove sand by the south area with the heavy tractor. thank you.	2/17/2006 Medium	Sebastian Diaz Guadalupe Ontiveros Grounds		Sunland Park ES
10499	Work In Progress 3/14/06 need to replace filter grill on the southeast roof thank you	3/14/2006 Medium	Sebastian Diaz Jose Ambriz Heating/Ventilation /Air Conditioning		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9916	Work In Progress REQUESTING WIND SCREENING FOR BACK FENCING AREA LOCATED NEAR LIFT STATION AREA IS WHERE WIND SCREENING NEEDS TO BE REPLACED	2/22/2006 Medium	Paul Quinones Ruben Ronquillo General Maintenance		Sunrise ES
10829	Work In Progress REQUESTING AIR FILTERS FOR THE UNITS IN CLASSROOMS FOR PM SCHEDULING.	3/30/2006 Medium	Paul Quinones Lorenzo Solis Heating/Ventilation /Air Conditioning		Sunrise ES
10452	Work In Progress BACK FENCING AREA,HIGH WINDS BROKE PAD LOCK TO ROLL GATE NEED TO REPLACE. THANK YOU VERY MUCH!	3/13/2006 Medium	Paul Quinones Manny Lozoya Key and Lock		Sunrise ES
3876	Work In Progress RM.307,BAD CIRCULATING PUMP NEED TO REPLACE	7/27/2005 Medium	Paul Quinones Jaime Gomez Heating/Ventilation /Air Conditioning		Sunrise ES
3469	Work In Progress FENCING AREA IN BACK OF SCHOOL NEAR LIFT STATION NEEDS TO BE REPAIRED,AND ROLL GATE.PROBABLE HIGH WINDS ON 7-11-05 CAUSED THE DAMAGE.NO SIGNS OF VANDILISM ON SCHOOL PROPERTY	7/12/2005 Medium	Paul Quinones Michael Munoz Fence Repair		Sunrise ES
3477	Work In Progress I NEED SAND FOR THE PLAY GROUNDS, THANKS.	7/12/2005 Medium	Paul Quinones Lorenzo Hernandez Grounds		Sunrise ES
8984	Work In Progress REQUESTING KEY CYLINDERS FOR ROOMS,205,AND 210 DOORS LOCATED IN BETWEEN CLASSROOMS REQUESTING ALSO A LOCK FOR THE FENCING AREA PROTECTING THE GAS METER ON SCHOOL GROUNDS	1/24/2006 Medium	Paul Quinones Manny Lozoya Key and Lock		Sunrise ES
6782	Work In Progress STERLING HEATING UNIT IN KITCHEN AREA.WILL NOT TURN ON ,MIXED AIR CONTROL NOT WORKING PROPERLY	10/26/2005 Medium	Paul Quinones Jaime Gomez Heating/Ventilation /Air Conditioning		Sunrise ES
6887	Work In Progress The Wastwater Flow Meter needs to be checked for proper calibration ASAP	10/31/2005 High	Ricardo Jacquez Sewage/Water Treatment Plant		Sunrise ES
7495	Work In Progress please order fill dirt for new arrivals of new portables. sunrise, che, desert-trail	11/21/2005 Medium	Guadalupe Ontiveros Grounds	Portables	Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3629	Work In Progress please cut and weedeat in and around lift station. weeds are growing rapid and are going to end up on the playing fields.	7/18/2005 Medium	Paul Quinones Grounds		Sunrise ES
3533	Work In Progress Could you turn the air conditioning on we have teachers coming in to get a head start on their rooms. It is very hot and we would greatly appreciate it. Since we are a year round school the teachers need to report on Monday. Thank-you	7/14/2005 Medium	Joanne Munoz Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Sunrise ES
9456	Work In Progress Need a gate key for El Paso Disposal.	2/7/2006 Medium	Juliet Parra Manny Lozoya Key and Lock		Sunrise ES
9294	Work In Progress both of my buffing machines are down need to be fixed	2/3/2006 Medium	Ramon Dominguez Jimmy Carbajal Custodial Equipment Repair		Sunrise ES
10457	Work In Progress vaccume smells like smoke co2a 00003436	3/13/2006 Medium	Jesus Urquidi Jimmy Carbajal Custodial	Custodial	Sunrise ES
10718	Work In Progress NEW DESKS FOR SNP MANAGER AND CLERK NEED TO BE ASSEMBLE TOGETHER. LAURA B. SNP MGR 233-2945	3/27/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Vado ES
10622	Work In Progress WOULD LIKE A DOOR BELL INSTALL TO THE BACK DOOR FOR DELIVERIES. UNABLE TO HEAR ANYONE AT THE BACK DOOR. LAURA B. SNP MGR 233-2945	3/17/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Vado ES
9641	Work In Progress Manny, having trouble with door on rm 310	2/13/2006 Medium	Frank Lara Frank Lara Key and Lock		Vado ES
10427	Work In Progress 100 Wing - Room 106 Need new exit sign for back door the one there does not work.	3/10/2006 Medium	Danny Miranda David Boyd Construction		Vado ES
10051	Work In Progress 2/28/06 lupe need tiller to work dirt in playground	2/28/2006 Medium	Frank Lara Guadalupe Ontiveros Grounds		Vado ES
10422	Work In Progress Need RFP panels for walls by classrooms	3/10/2006 Medium	Frank Lara David Boyd Construction		Vado ES
8739	Work In Progress manny need to change lock p.e. office also re-key rm207 also dupicent keys for testing, counslor rm	1/13/2006 Medium	Frank Lara Frank Lara Key and Lock		Vado ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9113	Work In Progress Lupe Need to take out two tether balls poles out of la mesa and re-locate at vado	1/27/2006 Medium	Frank Lara Guadalupe Ontiveros Grounds		Vado ES
8045	Work In Progress LUPE ONTIV. need backhoe at vado to spread sand for play ground equitement	12/12/2005 Medium	Frank Lara Guadalupe Ontiveros Grounds		Vado ES
9028	Work In Progress please remove salt cedar trees that are at Valley Grove Baptist church. They are in the the way for the bus drivers. W.O as per R.Chavez.	1/25/2006 High	Guadalupe Ontiveros Grounds	Parking Lot	Vado ES
10571	Work In Progress Left Side of Serving Line - Cold Unit not working Laura Benavidez - SNP Manager 233-2945	3/16/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Vado ES
9982	Work In Progress Outside electrical covers are being kicked off.	2/24/2006 Medium	Armando Diaz Danny Miranda General Maintenance		Vado ES
9983	Work In Progress Stove knobs were removed from stove.	2/24/2006 Medium	Armando Diaz Danny Orozco Food Services	Cafeteria	Vado ES
4628	Work In Progress Need to meet contractor on Monday - to rekey school site.	8/17/2005 Medium	David Boyd Manny Lozoya Key and Lock		Vado ES