

# 1288 - Work Orders In Progress - (Fiscal Year 7/1/05 - 4/30/06)

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                           | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 10197 | Work In Progress<br>Monthly - Alma Del Valle Monthly FE Inspection -<br>Refer to PM schedule details.     | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Romauldo Apodaca<br>Fire Extinguishers   |           | Alma Del Valle Daycare  |
| 10218 | Work In Progress<br>Monthly - Alma Del Valle Emer. Light Test:<br>Monthly - Refer to PM schedule details. | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Romauldo Apodaca<br>General Maintenance  |           | Alma Del Valle Daycare  |
| 10219 | Work In Progress<br>Monthly - Alma Del Valle Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Romauldo Apodaca<br>General Maintenance  |           | Alma Del Valle Daycare  |
| 10910 | Work In Progress<br>Monthly - Alma Del Valle Monthly FE Inspection -<br>Refer to PM schedule details.     | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Romauldo Apodaca<br>Fire Extinguishers   |           | Alma Del Valle Daycare  |
| 10950 | Work In Progress<br>Monthly - Alma Del Valle Roof Inspection - Refer<br>to PM schedule details.           | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Romauldo Apodaca<br>Roof                 |           | Alma Del Valle Daycare  |
| 10980 | Work In Progress<br>Monthly - Alma Del Valle Emer. Light Test:<br>Monthly - Refer to PM schedule details. | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Romauldo Apodaca<br>General Maintenance  |           | Alma Del Valle Daycare  |
| 10981 | Work In Progress<br>Monthly - Alma Del Valle Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Romauldo Apodaca<br>General Maintenance  |           | Alma Del Valle Daycare  |
| 3308  | Work In Progress<br>Yearly - Alma Del Valle Emer. Light Test: Annual -<br>Refer to PM schedule details.   | 7/6/2005<br>Medium                          | Alfredo Holguin<br>Romauldo Apodaca<br>Fire Protection      |           | Alma Del Valle Daycare  |
| 3312  | Work In Progress<br>Yearly - Alma Del Valle Exit Sign Test: Annual -<br>Refer to PM schedule details.     | 7/6/2005<br>Medium                          | Alfredo Holguin<br>Romauldo Apodaca<br>Fire Protection      |           | Alma Del Valle Daycare  |
| 3960  | Work In Progress<br>Monthly - Alma Del Valle Monthly FE Inspection -<br>Refer to PM schedule details.     | 7/31/2005<br>Medium                         | Alfredo Holguin<br>Romauldo Apodaca<br>Fire Extinguishers   |           | Alma Del Valle Daycare  |
| 3981  | Work In Progress<br>Monthly - Alma Del Valle Emer. Light Test:<br>Monthly - Refer to PM schedule details. | 7/31/2005<br>Medium                         | Alfredo Holguin<br>Romauldo Apodaca<br>General Maintenance  |           | Alma Del Valle Daycare  |
| 3982  | Work In Progress<br>Monthly - Alma Del Valle Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 7/31/2005<br>Medium                         | Alfredo Holguin<br>Romauldo Apodaca<br>General Maintenance  |           | Alma Del Valle Daycare  |
| 6005  | Work In Progress<br>Monthly - Anthony ES Monthly FE Inspection -<br>Refer to PM schedule details.         | 10/2/2005<br>Medium                         | Alfredo Holguin<br>Hector Villalobos<br>Fire Extinguishers  |           | Anthony ES              |
| 10982 | Work In Progress<br>Monthly - Anthony ES Exit Sign Insp: Monthly -<br>Refer to PM schedule details.       | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Hector Villalobos<br>General Maintenance |           | Anthony ES              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                               | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 10984 | Work In Progress<br>Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Hector Villalobos<br>General Maintenance     |           | Anthony ES              |
| 10928 | Work In Progress<br>Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Hector Villalobos<br>Roof                    |           | Anthony ES              |
| 10958 | Work In Progress<br>Monthly - Anthony ES Fire Suppression Insp. - Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System        |           | Anthony ES              |
| 10911 | Work In Progress<br>Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Hector Villalobos<br>Fire Extinguishers      |           | Anthony ES              |
| 1862  | Work In Progress<br>New unit that was installed in Nurces area is not sufficient. Need to provide more cooling. Please see Mike   | 5/11/2005<br>Medium                         | Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning         |           | Anthony ES              |
| 8736  | Work In Progress<br>please add additional sprinklers to existing sprinkler system in the corredore and between the primary and drug free. Also if h2o can be tied in to pine trees.<br>Thanks   | 1/13/2006<br>Medium                         | Guadalupe Ontiveros<br>Grounds                                  |           | Anthony ES              |
| 9133  | Work In Progress<br>main bldg behind annex. Please use backhoe for repair of sewer line.  | 1/30/2006<br>High                           | Guadalupe Ontiveros<br>Grounds                                  |           | Anthony ES              |
| 9925  | Work In Progress<br>please provide carpet in music classrooms. (chapter bldg)   | 2/22/2006<br>Medium                         | Michael Munoz<br>Carpet Repair                                  |           | Anthony ES              |
| 11173 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Carlos Lujan<br>Custodial                       |           | Anthony ES              |
| 10183 | Work In Progress<br>Walk-in Freezer at 60 degrees<br><br>Becky Saenz - SNP Manager 882-5607   | 3/3/2006<br>Medium                          | Alma Terrell<br>Danny Orozco<br>Food Services                   | Cafeteria | Anthony ES              |
| 11691 | Work In Progress<br>the vaccum of Mr. calderon need to be fix from the swich or the cord it dosen work on and off   | 4/27/2006<br>Medium                         | Carlos Lujan<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair |           | Anthony ES              |
| 11145 | Work In Progress<br>need to paint new metal frame in music rm.  | 4/6/2006<br>Medium                          | Danny Miranda<br>Hector Villalobos<br>Painting                  |           | Anthony ES              |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft   | Area Type       | Location<br>Area Number |
|-------|--|---|---|-----------------|-------------------------|
| 2867  | Work In Progress<br>need four sinks Anthony elem girls r.r.'s  | 6/20/2005<br>Medium                         | Danny Miranda<br>Fred Appenzoller<br>Plumbing                               |                 | Anthony ES              |
| 8966  | Work In Progress<br>upper primary office needs two filing cabinet locks and two desk locks two cabinet locks   | 1/24/2006<br>Medium                         | Hector Villalobos<br>Manny Lozoya<br>Key and Lock                           | Office          | Anthony ES              |
| 8967  | Work In Progress<br>Headstrat pt1 h 2 keys can not open lock on door   | 1/24/2006<br>Medium                         | Hector Villalobos<br>Manny Lozoya<br>Key and Lock                           | Portables       | Anthony ES              |
| 9065  | Work In Progress<br>Replace a/c 45 to a 65 master cool room 306  | 1/26/2006<br>Medium                         | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air Conditioning   | Classroom       | Anthony ES              |
| 10015 | Work In Progress<br>Need to replace pump seal  | 2/27/2006<br>Medium                         | Hector Villalobos<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning | Mechanical Room | Anthony ES              |
| 9250  | Work In Progress<br>Chapter blg p. e bathroom replace lock and straighten out door   | 2/2/2006<br>Medium                          | Hector Villalobos<br>Manny Lozoya<br>Key and Lock                           | Office          | Anthony ES              |
| 9251  | Work In Progress<br>Social worker office needs to rekey cabinets   | 2/2/2006<br>Medium                          | Hector Villalobos<br>Manny Lozoya<br>Key and Lock                           | Office          | Anthony ES              |
| 9440  | Work In Progress<br>Need a/c vents for two class rooms 201 202   | 2/7/2006<br>Medium                          | Hector Villalobos<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning | Classroom       | Anthony ES              |
| 10600 | Work In Progress<br>Need to replace air compressor at pump house<br>As per Rick route to Raul Sanchez 4/7/06 - mkv   | 3/17/2006<br>Medium                         | Hector Villalobos<br>Raul Sanchez<br>Sewage/Water Treatment Plant           | Mechanical Room | Anthony ES              |
| 10601 | Work In Progress<br>We need to replace all 11 high presure toilet valve  | 3/17/2006<br>Medium                         | Hector Villalobos<br>Joe Ontiveros<br>Plumbing                              | Classroom       | Anthony ES              |
| 10349 | Work In Progress<br>We need to replace a/c unit in pt 217  | 3/8/2006<br>Medium                          | Hector Villalobos<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning | Classroom       | Anthony ES              |
| 10839 | Work In Progress<br>Pts 1 and 3 needs two locks for disconnect electrical box  | 3/30/2006<br>Medium                         | Hector Villalobos<br>Manny Lozoya<br>Key and Lock                           | Portables       | Anthony ES              |
| 11247 | Work In Progress<br>old cafeteria clog drain kitchen<br>UNCLOG DRAIN   | 4/10/2006<br>4/14/2006<br>Medium            | Hector Villalobos<br>Danny Orozco<br>Food Services                          | Cafeteria       | Anthony ES              |
| 11350 | Work In Progress<br>Chapter blg music room broken lock need to secuve door for today.<br>Stolen Equipment - 2 Guitars, CD/Radio recorder<br>CD's (4)<br>Damage to Door<br>Case# 2006-63333<br>Est. Loss 730.00 | 4/13/2006<br>Medium                         | Hector Villalobos<br>Manny Lozoya<br>Key and Lock                           | Classroom       | Anthony ES              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft  | Area Type        | Location<br>Area Number  |
|-------|---|---|--|------------------|--------------------------|
| 11127 | Work In Progress<br>Broken window replace with plexglal two   | 4/6/2006<br>Medium                          | Hector Villalobos<br>Ruben Ronquillo<br>Glass\Window Repairs                 | Cafeteria        | Anthony ES               |
| 11241 | Work In Progress<br>Pump house irrigation pump is not working   | 4/10/2006<br>Medium                         | Hector Villalobos<br>Raul Sanchez<br>Sewage/Water<br>Treatment Plant         | Athletic Field   | Anthony ES               |
| 11479 | Work In Progress<br>pt 218 need to replace kitchen faucet   | 4/21/2006<br>Medium                         | Hector Villalobos<br>Joe Ontiveros<br>Plumbing                               | Portables        | Anthony ES               |
| 2390  | Work In Progress<br>room 207 door will not lock need to fix a.s. a. p.<br>for today   | 5/31/2005<br>Medium                         | Hector Villalobos<br>Manny Lozoya<br>Key and Lock                            | Classroom        | Anthony ES               |
| 623   | Work In Progress<br>3/18/05<br>1. check boilers<br>1.5 go to shop put gas pick up supplies<br>5.5 pruning trees by football field | 3/24/2005<br>Medium                         | Hector Villalobos<br>Hector Villalobos<br>General Maintenance                |                  | Anthony ES               |
| 764   | Work In Progress<br>rooms 3 4 5 6 7 8 emergency windows do not<br>open<br>Route to Danny Miranda as per Mike. 9/12/05 -<br>mkv    | 4/1/2005<br>Medium                          | Hector Villalobos<br>Danny Miranda<br>Glass\Window Repairs                   | Classroom        | Anthony ES               |
| 823   | Work In Progress<br>ALL windows in old primary blg do not open<br>Route to Danny Miranda as per Mike 9/12/05 - mkv                | 4/4/2005<br>Medium                          | Hector Villalobos<br>Danny Miranda<br>Glass\Window Repairs                   | Classroom        | Anthony ES               |
| 205   | Work In Progress<br>Annex Bldg Girls rr - Broken window 45 1/2 x 14<br>3/4.   | 3/9/2005<br>Medium                          | Hector Villalobos<br>Ruben Ronquillo<br>Glass\Window Repairs                 | Restroom (Girls) | Anthony ES<br>Annex Bldg |
| 102   | Work In Progress<br>need to remove dirt with tractor by dumpster  | 3/7/2005<br>Medium                          | Hector Villalobos<br>Lorenzo Hernandez<br>Grounds                            | Cafeteria        | Anthony ES               |
| 103   | Work In Progress<br>boiler room we have a leak in pipe line   | 3/7/2005<br>Medium                          | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Mechanical Room  | Anthony ES               |
| 228   | Work In Progress<br>pt 217 replace heating and cooling  | 3/10/2005<br>Medium                         | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Classroom        | Anthony ES               |
| 331   | Work In Progress<br>need 8 sheet metal plates 20x20   | 3/11/2005<br>Medium                         | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Classroom        | Anthony ES               |
| 1321  | Work In Progress<br>hook up electrial power to storage outside  | 4/21/2005<br>Medium                         | Hector Villalobos<br>Enrique Sotelo<br>Electrical                            | Athletic Field   | Anthony ES               |
| 1038  | Work In Progress<br>replace a/c unit in cafeteria 63 a/c unit   | 4/11/2005<br>Medium                         | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Cafeteria        | Anthony ES               |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft  | Area Type       | Location<br>Area Number |
|-------|---|---|--|-----------------|-------------------------|
| 1039  | Work In Progress<br>primary office to replace 45 sidedraft master cool  | 4/11/2005<br>Medium                         | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |                 | Anthony ES              |
| 2812  | Work In Progress<br>Mrs marquez is requesting that the old cabinets<br>in the old main blg and mild blg lounge be replace   | 6/16/2005<br>Medium                         | Hector Villalobos<br>Danny Miranda<br>General Maintenance                    |                 | Anthony ES              |
| 4255  | Work In Progress<br>room 109 needs carpet repair  | 8/8/2005<br>Medium                          | Hector Villalobos<br>Michael Munoz<br>Carpet Repair                          | Classroom       | Anthony ES              |
| 3899  | Work In Progress<br>Room 201 - Half of the carpet is bad replace<br>with tile.<br>11/29/05 - Teacher requesting status on this<br>work order on 11/10/05 a student fell and hurt<br>her leg. -mkv | 7/28/2005<br>Medium                         | Hector Villalobos<br>Michael Munoz<br>Carpet Repair                          | Classroom       | Anthony ES              |
| 4581  | Work In Progress<br>old main blg a/c motor burn out a 3 hp volts 230  | 8/15/2005<br>Medium                         | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Classroom       | Anthony ES              |
| 4478  | Work In Progress<br>Chapter bg p.e room replace 3/4 motor with a<br>1hp motor   | 8/11/2005<br>Medium                         | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Classroom       | Anthony ES              |
| 4861  | Work In Progress<br>Nurse office refrigerator is not working water is<br>leaking from seal  | 8/24/2005<br>Medium                         | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |                 | Anthony ES              |
| 4742  | Work In Progress<br>need a 3/4 hp motor cafeteira motor burn out<br>old cafeteria   | 8/22/2005<br>Medium                         | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Cafeteria       | Anthony ES              |
| 4743  | Work In Progress<br>mild cafeteria burn motor 3/4 hp with a belt 4-L<br>660 or 670  | 8/22/2005<br>Medium                         | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Cafeteria       | Anthony ES              |
| 7339  | Work In Progress<br>Custodial storage faucet is leaking need to<br>replace faucet   | 11/14/2005<br>Medium                        | Hector Villalobos<br>Joe Ontiveros<br>Plumbing                               | Custodial       | Anthony ES              |
| 5992  | Work In Progress<br>upper primary boiler is leaking replace   | 9/30/2005<br>Medium                         | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |                 | Anthony ES              |
| 5944  | Work In Progress<br>Old main blg boiler room needs a thermocuple<br>size 56 inch  | 9/29/2005<br>Medium                         | Hector Villalobos<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |                 | Anthony ES              |
| 11845 | Work In Progress<br>Need to order flush valves for toilets in old main<br>mild blg annex blg need 20  | 5/2/2006<br>Medium                          | Hector Villalobos<br>Joe Ontiveros<br>Plumbing                               | Restroom (Boys) | Anthony ES              |
| 11847 | Work In Progress<br>We need to install water filters in old main mild blg<br>uuper primary  | 5/2/2006<br>Medium                          | Hector Villalobos<br>Joe Ontiveros<br>Plumbing                               | Mechanical Room | Anthony ES              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type      | Location<br>Area Number |
|-------|---|---|--|----------------|-------------------------|
| 11676 | Work In Progress<br>Mild blg front office replace rollup door secure opening a.s.a.p  | 4/27/2006<br>Medium                         | Hector Villalobos<br>Danny Miranda<br>Doors and Hardware |                | Anthony ES              |
| 9088  | Work In Progress<br>AE 4-6 CAMPUS. DISHWASHER HAS ALOT OF LIME BUILD-UP , MAY NEED NEW TIPS ON THE RINSE .<br><br>BECKY S. SNP MGR 882-3507   | 1/27/2006<br>Medium                         | Jacqueline Aguilar<br>Danny Orozco<br>Food Services      | Cafeteria      | Anthony ES              |
| 10279 | Work In Progress<br>FAN TO OVEN NOT WORKING AND ITS SEEMS THAT THERE IS AN ELECTRIC SHORT SOMEWHERE.<br><br>BECKY S. SNP MGR 882-3507   | 3/6/2006<br>Medium                          | Jacqueline Aguilar<br>Danny Orozco<br>Food Services      | Cafeteria      | Anthony ES              |
| 4059  | Work In Progress<br>DAYCARE - NEED TO ISSUE KEYS TO CORINA VALDESPINO for (Krishna's Office). WILL BE HERE AT 8:00 AM TOMORROW.   | 8/1/2005<br>Medium                          | Margret Villalobos<br>Manny Lozoya<br>Key and Lock       |                | Anthony ES              |
| 11610 | Work In Progress<br>please remove manhole lids/rings and concrete rings as per E.I.D.<br>remove septic tank lids and rings. cover septic tanks w/sand.  | 4/25/2006<br>4/25/2006<br>High              | Michael Munoz<br>Ramiro Holguin<br>General Maintenance   | Athletic Field | Berino ES               |
| 11394 | Work In Progress<br>please deliver 1 load of sand to site Monday 4-24-06  | 4/18/2006<br>Medium                         | Michael Munoz<br>Guadalupe Ontiveros<br>Grounds          | Athletic Field | Berino ES               |
| 2817  | Work In Progress<br>1-6 TO 8FT DOOM SKYLIGHT BROKEN AND A/C UNIT CAVED IN.<br>MIKE WILLIAMS-DEPUTY<br>(Pending Skylight)<br>WITNESSED 3 TEENAGERS WALKING INTO BLDG 2 JUMP ON TO WALK-IN FREEZER AND TO BLDG (CALLED SHERIFF) - JIMMY CORTEZ<br><br>SKYLIGHT WORK ORDER IS PENDING - A/C UNIT WAS PUSH UP (COVER) - 7/13 R. HOLGUIN | 6/16/2005<br>Medium                         | Jimmy Cortez<br>Ramiro Holguin<br>General Maintenance    |                | Berino ES               |
| 441   | Work In Progress<br>CHARGER NEEDS TO BE FIXED AGAIN   | 3/16/2005<br>Medium                         | Jimmy Cortez<br>Jimmy Carbajal<br>Custodial              |                | Berino ES               |
| 5585  | Work In Progress<br>need nemaster b key and 55key for new custodian thanks a.s. p   | 9/19/2005<br>Medium                         | Jimmy Cortez<br>Manny Lozoya<br>Key and Lock             |                | Berino ES               |
| 5898  | Work In Progress<br>Need 2 new keys for office gate and recut master key for Mr Silva THANKS OFFICE KEY IS ON YOUR KEY CHAIN ALREADY  | 9/28/2005<br>Medium                         | Jimmy Cortez<br>Manny Lozoya<br>Key and Lock             |                | Berino ES               |
| 9006  | Work In Progress<br>Need a gate key for El Paso Disposal.   | 1/24/2006<br>Medium                         | Juliet Parra<br>Manny Lozoya<br>Key and Lock             |                | Berino ES               |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft   | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 9455  | Work In Progress<br>Need another gate key for El Paso Disposal.   | 2/7/2006<br>Medium                          | Juliet Parra<br>Manny Lozoya<br>Key and Lock                                |           | Berino ES               |
| 10606 | Work In Progress<br>PORTALBE 141 NEEDS SWAMP COOLER<br>REPLACE WITH A MASTERCOOL 4500 SIDE<br>DRAFT ALSO NEEDS STAND  | 3/17/2006<br>Medium                         | Ramiro Holguin<br>Lorenzo Solis<br>Heating/Ventilation /Air<br>Conditioning |           | Berino ES               |
| 7907  | Work In Progress<br>12/06/05 TO MIKE<br>PORTABLE 154 FLOOR TITLES ARE COMING<br>OFF IF POSSIBLE THIS CHRISTMAS BREAK YOU<br>CAN SOME CARPET INSTALL ED  | 12/7/2005<br>Medium                         | Ramiro Holguin<br>Michael Munoz<br>Carpet Repair                            |           | Berino ES               |
| 8684  | Work In Progress<br>NEED TO REPLACE BROKEN BLINDS ROOM 108<br>NEEDS ONE 54" P.145 NEEDS 3 35" P. 147 3 45"<br>P 156 2 47"   | 1/12/2006<br>Medium                         | Ramiro Holguin<br>Ruben Ronquillo<br>Glass\Window Repairs                   |           | Berino ES               |
| 8560  | Work In Progress<br>NEED TO RELACE SKY LIGHT WINDOW 6X6<br>FEET HAS A HOLE IN TOP CLASS   | 1/9/2006<br>Medium                          | Ramiro Holguin<br>Ruben Ronquillo<br>Glass\Window Repairs                   |           | Berino ES               |
| 8630  | Work In Progress<br>PORTABLE 154, NEEDS CARPET INSTALL<br>FLOOR TILES ARE COMING OFF  | 1/11/2006<br>Medium                         | Ramiro Holguin<br>Michael Munoz<br>Carpet Repair                            |           | Berino ES               |
| 8945  | Work In Progress<br>NEED TO REPLACE KEY FOR TV BROKEN ASAP  | 1/23/2006<br>Medium                         | Ramiro Holguin<br>Manny Lozoya<br>Key and Lock                              |           | Berino ES               |
| 9765  | Work In Progress<br>ROOMS 119,120 NEED A/C REPLACE TWO 6500<br>MIDDLE WESTWING NEEDS TWO WET SECTIONS<br>6500<br>NORTH WESTWING NEEDS ONE WET SECTION<br>4500<br>NORTH EASTWING NEEDS FOUR WET SECTIONS<br>REPLACED 6500 AND ONE 4500<br>GYM NEEDS TWO 8500 A/C REPLACE | 2/16/2006<br>Medium                         | Ramiro Holguin<br>Lorenzo Solis<br>Heating/Ventilation /Air<br>Conditioning |           | Berino ES               |
| 9644  | Work In Progress<br>2/13/06 NEED FIVE 2X12X12   | 2/13/2006<br>Medium                         | Ramiro Holguin<br>Ruben Ronquillo<br>General Maintenance                    |           | Berino ES               |
| 9404  | Work In Progress<br>2/03/06<br>SECURITY LIGHT COVER ON CAFETERIA<br>OUTSIDE WALL NEEDS TO BE REPLACE  | 2/6/2006<br>Medium                          | Ramiro Holguin<br>Enrique Sotelo<br>Electrical                              |           | Berino ES               |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                      | Area Type   | Location<br>Area Number |
|-------|--|---|--|-------------|-------------------------|
| 2551  | Work In Progress<br>5/26/05<br>0.5 CHECK WITH JIMMY CLOSE GATES<br>1.0 CHECHING WITH TEACHERS ON ROOMS TO BE PAINTED<br>0.5 UNCLOG TIOLET ROOM 100<br>2.0 HELP RAUL CHECK WELLS<br>1.0 CHANGE OUT ELECTRICAL BALLAST TEACHERS LOUNGE<br>0.5 REPAIR BROKEN ELECTRICAL OUTLET IN GYM<br>1.5 CHECK ALL SPRINKLERS IN PLAYGROUND CHANGE OUT THE ONES NOT WORKING FILL OUT DAILY WORK LOG<br><br>5/26 - 7 | 6/6/2005<br><br>Medium                      | Ramiro Holguin<br>Ramiro Holguin<br>General Maintenance                |             | Berino ES               |
| 2247  | Work In Progress<br>MANNY LOZOYA<br>PORTABLE 140 DOOR NEEDS CLOSURE AND PORTABLE 151 CORE IN HANDLE NEEDS TO BE CHECK OUT KEYS DO NOT WORK   | 5/24/2005<br><br>Medium                     | Ramiro Holguin<br>Manny Lozoya<br>Key and Lock                         |             | Berino ES               |
| 203   | Work In Progress<br>NEED PLAYGROUND FERTELIZES   | 3/9/2005<br><br>Medium                      | Ramiro Holguin<br>Lorenzo Hernandez<br>Grounds                         |             | Berino ES               |
| 846   | Work In Progress<br>JAIME GOMEZ<br>NEED TO REPLACE FOUR A/C UNITS WESTWING 131,128 ON EASTWING 103,107 ALL 6500  | 4/5/2005<br><br>Medium                      | Ramiro Holguin<br>Jaime Gomez<br>Heating/Ventilation /Air Conditioning |             | Berino ES               |
| 2222  | Work In Progress<br>Room 140 - Need to replace door closer.  | 5/23/2005<br><br>Medium                     | Hector Lozoya<br>Danny Miranda<br>Key and Lock                         |             | Berino ES               |
| 5338  | Work In Progress<br>WALK - IN FREEZER IS LEAKING ALOT OF WATER BETWEEN THE FREEZER AND REFRIG.<br><br>ELSA - 882-2417  | 9/8/2005<br><br>Medium                      | Jacqueline Aguilar<br>Danny Orozco<br>Food Services                    | Cafeteria   | Berino ES               |
| 2480  | Work In Progress<br>CONNECT UTILITIES TO PORTABLES (4).  | 6/3/2005<br><br>Medium                      | Fred Appelzoller<br>Fred Appelzoller<br>Plumbing                       |             | Berino ES<br>PORTABLES  |
| 11174 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006.  | 4/7/2006<br><br>Medium                      | Aida Salcedo<br>Jimmy Cortez<br>Custodial                              |             | Berino ES               |
| 2956  | Work In Progress<br>please check all portables and see if all blocking cinder blocks are placed properly and repair if neede.  | 6/23/2005<br><br>High                       | Ramiro Holguin<br>General Maintenance                                  | Parking Lot | Berino ES               |



| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|-------|---|---|--|-----------|-------------------------|
| 4055  | Work In Progress<br>please cut weeds and pick-up debris on east side of rockwall. (i.e weeds bottles cinder blocks.)                  | 8/1/2005<br>Medium                          | Ramiro Holguin<br>General Maintenance                    |           | Berino ES               |
| 4208  | Work In Progress<br>MOBILE HOME OCCUPANT WILL BE RECEIVING NEW MOBILE HOME ON APPROXIMATELY 8-29-05. PLEASE CONNECT ELECTRICAL. 28X54 | 8/4/2005<br>Medium                          | Enrique Sotelo<br>Electrical                             |           | Berino ES               |
| 10221 | Work In Progress<br>Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.                                       | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Ramiro Holguin<br>General Maintenance |           | Berino ES               |
| 10224 | Work In Progress<br>Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.                                     | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Ramiro Holguin<br>General Maintenance |           | Berino ES               |
| 10199 | Work In Progress<br>Monthly - Berino ES Monthly FE Inspection - Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Ramiro Holguin<br>Fire Extinguishers  |           | Berino ES               |
| 10959 | Work In Progress<br>Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System |           | Berino ES               |
| 10953 | Work In Progress<br>Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System |           | Berino ES               |
| 4082  | Work In Progress<br>Monitoring Wells - I need a set of keys to the monitoring well caps   | 8/2/2005<br>Medium                          | Alfredo Holguin<br>Manny Lozoya<br>Key and Lock          |           | Berino ES               |
| 6123  | Work In Progress<br>Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.                                  | 10/2/2005<br>Medium                         | Alfredo Holguin<br>Juan Vargas<br>Fire Protection        |           | Chaparral ES            |
| 10985 | Work In Progress<br>Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.                                    | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance    |           | Chaparral ES            |
| 10930 | Work In Progress<br>Monthly - Chaparral ES Roof Inspection - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Joe Ramirez<br>Roof                   |           | Chaparral ES            |
| 10960 | Work In Progress<br>Monthly - Chaparral ES Fire Suppression Insp. - Refer to PM schedule details.                                     | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System |           | Chaparral ES            |
| 11026 | Work In Progress<br>Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.                                  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Joe Ramirez<br>Fire Protection        |           | Chaparral ES            |
| 10200 | Work In Progress<br>Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.                                      | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Joe Ramirez<br>Fire Extinguishers     |           | Chaparral ES            |

| <b>WOID</b> | <b>Status<br/>Description<br/>Action Taken</b>  | <b>Request Date<br/>Completion Date<br/>Priority</b> | <b>Requester<br/>Assigned To<br/>Craft</b>            | <b>Area Type</b> | <b>Location<br/>Area Number</b> |
|-------------|---|--|---|------------------|---------------------------------|
| 8295        | Work In Progress<br>Monthly - Chaparral ES Monthly FE Inpsection -<br>Refer to PM schedule details.     | 1/1/2006<br>Medium                                   | Alfredo Holguin<br>Juan Vargas<br>Fire Extinguishers  |                  | Chaparral ES                    |
| 8312        | Work In Progress<br>Monthly - Chapparral ES Roof Inspection - Refer<br>to PM schedule details.          | 1/1/2006<br>Medium                                   | Alfredo Holguin<br>Juan Vargas<br>Roof                |                  | Chaparral ES                    |
| 8367        | Work In Progress<br>Monthly - Chaparral ES Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 1/1/2006<br>Medium                                   | Alfredo Holguin<br>Juan Vargas<br>General Maintenance |                  | Chaparral ES                    |
| 7756        | Work In Progress<br>Monthly - Chaparral ES Monthly FE Inpsection -<br>Refer to PM schedule details.     | 12/4/2005<br>Medium                                  | Alfredo Holguin<br>Juan Vargas<br>Fire Extinguishers  |                  | Chaparral ES                    |
| 7779        | Work In Progress<br>Monthly - Chaparral ES Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 12/4/2005<br>Medium                                  | Alfredo Holguin<br>Juan Vargas<br>General Maintenance |                  | Chaparral ES                    |
| 7820        | Work In Progress<br>Monthly - Chaparral ES Emer. Light Test: Monthly -<br>Refer to PM schedule details. | 12/4/2005<br>Medium                                  | Alfredo Holguin<br>Juan Vargas<br>Fire Protection     |                  | Chaparral ES                    |
| 10223       | Work In Progress<br>Monthly - Chaparral ES Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 3/5/2006<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance |                  | Chaparral ES                    |
| 8408        | Work In Progress<br>Monthly - Chaparral ES Emer. Light Test: Monthly -<br>Refer to PM schedule details. | 1/1/2006<br>Medium                                   | Alfredo Holguin<br>Juan Vargas<br>Fire Protection     |                  | Chaparral ES                    |
| 10913       | Work In Progress<br>Monthly - Chaparral ES Monthly FE Inpsection -<br>Refer to PM schedule details.     | 4/2/2006<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>Fire Extinguishers  |                  | Chaparral ES                    |
| 9360        | Work In Progress<br>Monthly - Chaparral ES Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 2/5/2006<br>Medium                                   | Alfredo Holguin<br>Juan Vargas<br>General Maintenance |                  | Chaparral ES                    |
| 9401        | Work In Progress<br>Monthly - Chaparral ES Emer. Light Test: Monthly -<br>Refer to PM schedule details. | 2/5/2006<br>Medium                                   | Alfredo Holguin<br>Juan Vargas<br>Fire Protection     |                  | Chaparral ES                    |
| 10264       | Work In Progress<br>Monthly - Chaparral ES Emer. Light Test: Monthly -<br>Refer to PM schedule details. | 3/5/2006<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>Fire Protection     |                  | Chaparral ES                    |
| 9337        | Work In Progress<br>Monthly - Chaparral ES Monthly FE Inpsection -<br>Refer to PM schedule details.     | 2/5/2006<br>Medium                                   | Alfredo Holguin<br>Juan Vargas<br>Fire Extinguishers  |                  | Chaparral ES                    |
| 4518        | Work In Progress<br>please replace urinal and commode in mens<br>restrom.                               | 8/12/2005<br>Medium                                  | Joe Ontiveros<br>Plumbing                             | Mechanical Room  | Chaparral ES                    |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                 | Area Type        | Location<br>Area Number |
|-------|---|---|---|------------------|-------------------------|
| 10767 | Work In Progress<br>E-WING GIRLS RR - CYLINDER KEEPS TURNING<br>AND CAN NOT BE LOCKED.  | 3/28/2006<br>Medium                         | Manny Lozoya<br>Key and Lock                                      | Restroom (Girls) | Chaparral ES            |
| 8429  | Work In Progress<br>please remove all old fixtures and order new<br>material for rough and top out. also order new<br>fixures.  | 1/5/2006<br>Medium                          | Joe Ontiveros<br>Ramps/Platforms                                  |                  | Chaparral ES            |
| 8430  | Work In Progress<br>please remove and provide new electrical to e-<br>wing restrooms as needed. i.e exhaust fan,<br>electric heat. please discuss with hvac techs.  | 1/5/2006<br>Medium                          | Enrique Sotelo<br>Electrical                                      |                  | Chaparral ES            |
| 11175 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE<br>INSPECTIONS ON ALL CUSTODIANS TO INCLUDED<br>CLOSET, MSDS, LABELED SPRAY BOTTLES &<br>SAFETY EQUIPMENT. HEAD CUSTODIANS NEED<br>TO INCLUDE INSPECTION OF YOUR OWN AREA.<br>INSPECTION REPORTS ALONG WITH<br>COMPLETED WORK ORDER MUST BE RETURNED<br>AND RECEIVED BY US NO LATER THAN APRIL<br>21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Daniel Ramirez<br>Custodial                       |                  | Chaparral ES            |
| 11144 | Work In Progress<br>need to paint all new doors in e-wing   | 4/6/2006<br>Medium                          | Danny Miranda<br>Joe Ramirez<br>Painting                          |                  | Chaparral ES            |
| 5498  | Work In Progress<br>sweeper/blower/not/working/choke/broken   | 9/14/2005<br>Medium                         | Daniel Ramirez<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair |                  | Chaparral ES            |
| 9630  | Work In Progress<br>2/13/06<br>need to replace r.r. partitions in boys @ girls r.r.<br>E-eing   | 2/13/2006<br>Medium                         | Danny Miranda<br>Danny Miranda<br>Doors and Hardware              |                  | Chaparral ES            |
| 9742  | Work In Progress<br>Could I get a key for Chap E for sound signal?<br>Thanks, carlos  | 2/15/2006<br>Medium                         | Carlos Vigil<br>Manny Lozoya<br>Key and Lock                      |                  | Chaparral ES            |
| 11480 | Work In Progress<br>4/21/06.<br>need to replace the full lenth urinal with a wall<br>mount urinal as per MR CARDONA.  | 4/21/2006<br>Medium                         | Joe Ramirez<br>Joe Ontiveros<br>Plumbing                          |                  | Chaparral ES            |
| 10303 | Work In Progress<br>3/6/06.<br>as per Mr. Cardona he wants the locks in the<br>maint. cust office and maint shed. to be keyed<br>with a master key.   | 3/6/2006<br>Medium                          | Joe Ramirez<br>Manny Lozoya<br>Key and Lock                       |                  | Chaparral ES            |
| 9980  | Work In Progress<br>Mr. Cardona is requesting verticle blinds for the<br>front office.<br>measurements are 48"x 84".  | 2/24/2006<br>Medium                         | Joe Ramirez<br>Ruben Ronquillo<br>Glass\Window Repairs            |                  | Chaparral ES            |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                      | Area Type | Location<br>Area Number |
|-------|--|---|--|-----------|-------------------------|
| 11669 | Work In Progress<br>As per mr. cardona need to replace floor type<br>urinal with wall mount urinal, also sensor<br>activated lavatory in girls bathroom is not<br>working. | 4/27/2006<br>Medium                         | Joe Ramirez<br>Joe Ontiveros<br>Plumbing                               |           | Chaparral ES            |
| 7359  | Work In Progress<br>2 request e. wing rooms need to repair<br>windows  | 11/15/2005<br>Medium                        | Juan Vargas<br>Ruben Ronquillo<br>Glass\Window Repairs                 |           | Chaparral ES            |
| 7360  | Work In Progress<br>rooms 79 71 70 83 need 12 blinds size 33<br>width 58 length  | 11/15/2005<br>Medium                        | Juan Vargas<br>Ruben Ronquillo<br>General Maintenance                  |           | Chaparral ES            |
| 7378  | Work In Progress<br>music room and gym. need doors replace   | 11/15/2005<br>Medium                        | Juan Vargas<br>Danny Miranda<br>Doors and Hardware                     |           | Chaparral ES            |
| 6415  | Work In Progress<br>cafeteria exit sign need change  | 10/14/2005<br>Medium                        | Juan Vargas<br>Enrique Sotelo<br>Electrical                            |           | Chaparral ES            |
| 6502  | Work In Progress<br>room 72 heating not work need help to fix  | 10/18/2005<br>Medium                        | Juan Vargas<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Chaparral ES            |
| 6343  | Work In Progress<br>las vanquetas need grabo a round   | 10/12/2005<br>Medium                        | Juan Vargas<br>Guadalupe Ontiveros<br>Grounds                          |           | Chaparral ES            |
| 4602  | Work In Progress<br>ruben ronquillo need 10 pvc 45 elbows 6 inches<br>10 square grate basin 6 inches and 200 ft. 6<br>inches pvc pipe                                      | 8/16/2005<br>Medium                         | Juan Vargas<br>Joe Ontiveros<br>Plumbing                               |           | Chaparral ES            |
| 3800  | Work In Progress<br>07/25/05 jaime gomes main office need new<br>A/C two 4500 and one 6500   | 7/25/2005<br>Medium                         | Juan Vargas<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Chaparral ES            |
| 3801  | Work In Progress<br>5/25/05/ mike neseito que pongan sistema de<br>riego para los arboles  | 7/25/2005<br>Medium                         | Juan Vargas<br>Guadalupe Ontiveros<br>Grounds                          |           | Chaparral ES            |
| 3846  | Work In Progress<br>07/26/05 j. gomes rooms 2 -20-21- 51-47-107-<br>44- 55-46- need replace A/C 6500   | 7/26/2005<br>Medium                         | Juan Vargas<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Chaparral ES            |
| 3868  | Work In Progress<br>ROOMS 83-82-81-80-72-96-70 NEED WINDOWS<br>REPAIRED OR REPLACE 2-REPORT  | 7/27/2005<br>Medium                         | Juan Vargas<br>Ruben Ronquillo<br>Glass\Window Repairs                 |           | Chaparral ES            |
| 4030  | Work In Progress<br>Room 47 need to instaled a/c ventilation   | 8/1/2005<br>Medium                          | Juan Vargas<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Chaparral ES            |
| 4213  | Work In Progress<br>Rooms 101-102-60-62-61-54-70-96-72-73-97 80-<br>82-83 need carpet repace   | 8/4/2005<br>Medium                          | Juan Vargas<br>Michael Munoz<br>Carpet Repair                          |           | Chaparral ES            |

| WOID | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                     | Area Type | Location<br>Area Number |
|------|---|---|---|-----------|-------------------------|
| 1422 | Work In Progress<br>04/26/05/jaime gomes library need 3 new master cools  | 4/26/2005<br>Medium                         | Juan Vargas<br>Jaime Gomez<br>Heating/Ventilation /Air Conditioning   |           | Chaparral ES            |
| 1871 | Work In Progress<br>05/11/05/ jaime gomes cafeteria need new air conditioning   | 5/12/2005<br>Medium                         | Juan Vargas<br>Jaime Gomez<br>Heating/Ventilation /Air Conditioning   | Cafeteria | Chaparral ES            |
| 2121 | Work In Progress<br>Air condition on cosesion stand need new motor 2 peed   | 5/19/2005<br>Medium                         | Juan Vargas<br>Jaime Gomez<br>Heating/Ventilation /Air Conditioning   |           | Chaparral ES            |
| 2314 | Work In Progress<br>05/26/05 lorenzo nesesito ayada para ubicar los sprinklers  | 5/26/2005<br>Medium                         | Juan Vargas<br>Lorenzo Hernandez<br>Grounds                           |           | Chaparral ES            |
| 2829 | Work In Progress<br>06/16/05 rooms 81 82 and 72 need window repair  | 6/16/2005<br>Medium                         | Juan Vargas<br>Ruben Ronquillo<br>Glass\Window Repairs                |           | Chaparral ES            |
| 2760 | Work In Progress<br>SECURE STORAGE  | 6/14/2005<br>Medium                         | Juan Vargas<br>Manny Lozoya<br>Key and Lock                           |           | Chaparral ES            |
| 2738 | Work In Progress<br>06/13/05 mike munos need to clean the parking   | 6/13/2005<br>Medium                         | Juan Vargas<br>General Maintenance                                    |           | Chaparral ES            |
| 3284 | Work In Progress<br>07/05/05 mike munoz Mr. cardona quiere bertical blind en su oficina size 82 width and 80 length   | 7/5/2005<br>Medium                          | Juan Vargas<br>Ruben Ronquillo<br>General Maintenance                 |           | Chaparral ES            |
| 9201 | Work In Progress<br>portables 63 -62 -and 54 need replace a/c master cool 3800  | 1/31/2006<br>Medium                         | Juan Vargas<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning |           | Chaparral ES            |
| 9107 | Work In Progress<br>need 200ft. swing chain and 10 swing hanger   | 1/27/2006<br>Medium                         | Juan Vargas<br>Guadalupe Ontiveros<br>Grounds                         |           | Chaparral ES            |
| 8523 | Work In Progress<br>room 20 need fix cabinets lock  | 1/9/2006<br>Medium                          | Juan Vargas<br>Manny Lozoya<br>Key and Lock                           |           | Chaparral ES            |
| 8718 | Work In Progress<br>NEED NEW NUMBERS FOR THE CLASSROOMS 0-1/0-2/0-3/0-4/0-5/0-7/101/102/103/104/105/106/107/108/109/201/202/203/204/205/206/207/208/209/210/211/212/213/214/215/216/217/218/219/220401/402/403/404/405/406/408/409/410/412/414/416/418301/302/303/304/305/306/307/308/309/310/311/312501/502/503/504/505506/507/508/510/509/511/5124-B.RESTROOMS 4-G.RESTROOMS 3-MANS3-WOMANS 1-T.L.ROOMS | 1/12/2006<br>Medium                         | Juan Vargas<br>Manny Lozoya<br>Key and Lock                           |           | Chaparral ES            |
| 7646 | Work In Progress<br>evenstar playgroun need water fouting fix   | 11/30/2005<br>Medium                        | Juan Vargas<br>Joe Ontiveros<br>Plumbing                              |           | Chaparral ES            |

| WOID | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft  | Area Type | Location<br>Area Number |
|------|--|---|--|-----------|-------------------------|
| 7946 | Work In Progress<br>cafeteria need replace two entry doors   | 12/8/2005<br>Medium                         | Juan Vargas<br>Danny Miranda<br>Doors and Hardware                         | Cafeteria | Chaparral ES            |
| 7947 | Work In Progress<br>kitchen need replace entry door  | 12/8/2005<br>Medium                         | Juan Vargas<br>Danny Miranda<br>Doors and Hardware                         | Cafeteria | Chaparral ES            |
| 7949 | Work In Progress<br>room 120 need fix bathroom door frame  | 12/8/2005<br>Medium                         | Juan Vargas<br>Danny Miranda<br>Doors and Hardware                         |           | Chaparral ES            |
| 7863 | Work In Progress<br>cafeteria need replace floor tile  | 12/6/2005<br>Medium                         | Juan Vargas<br>Michael Munoz<br>Carpet Repair                              |           | Chaparral ES            |
| 3299 | Work In Progress<br>I need some keys for two of the new<br>administrators who will be coming to this school.<br>They have requested main keys to the gate that<br>opens up the fence outside the school and also a<br>set of main keys for the building. If you can<br>please do as soon as possible. Keys for<br>Chaparral Elementary.  | 7/5/2005<br>Medium                          | Jennifer Corral<br>Manny Lozoya<br>Key and Lock                            | Office    | Chaparral ES            |
| 3785 | Work In Progress<br>NEED A KEY FOR ROOM 114,LEDESMA<br>REPRINT FOR MANNY - REGARDING E-MAIL<br>7/27/05 - MKV   | 7/22/2005<br>Medium                         | Jennifer Corral<br>Manny Lozoya<br>Key and Lock                            | Classroom | Chaparral ES            |
| 2536 | Work In Progress<br>Meza lost keys:He did pay to replace the ones he<br>lost.<br>Meza is room # 130.<br>Rosalinda Mendez would like keys to her filing<br>cabinet. She never got any keys, she has been<br>having to borrow the keys in the office. Mendez is<br>in room #122.<br>Manuela Ledesma needs keys for her room. She<br>never received any. She is room # 114.<br>9/7 - Manny, Mr. Meza is requesting on status of<br>key.- mkv<br>ref wo 4337 | 6/6/2005<br>Medium                          | Jennifer Corral<br>Manny Lozoya<br>Key and Lock                            | Classroom | Chaparral ES            |
| 4110 | Work In Progress<br>Rm-72 Ms. Barret needs screens on her<br>windows. Says they were suppose to be put in<br>last year.  | 8/3/2005<br>Medium                          | Jennifer Corral<br>Ruben Ronquillo<br>Glass\Window Repairs                 | Classroom | Chaparral ES            |
| 3871 | Work In Progress<br>need an extra key for Even start classroom,<br>Jeannette rm-118  | 7/27/2005<br>Medium                         | Jennifer Corral<br>Manny Lozoya<br>Key and Lock                            | Classroom | Chaparral ES            |
| 3945 | Work In Progress<br>Air Conditioner smells like burn and is not cold in<br>rm-128 for Ms. Word   | 7/29/2005<br>Medium                         | Jennifer Corral<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Classroom | Chaparral ES            |
| 3946 | Work In Progress<br>Air Conditioner not working in rm-20 for Ms. Gary  | 7/29/2005<br>Medium                         | Jennifer Corral<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Classroom | Chaparral ES            |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                          | Area Type        | Location<br>Area Number |
|-------|---|---|--|------------------|-------------------------|
| 6529  | Work In Progress<br>Had done a work order before for Ms. Barrett about fixing her windows needs a screen. She says they still haven't done the work order. Thanks   | 10/18/2005<br>Medium                        | Jennifer Corral<br>Ruben Ronquillo<br>Glass\Window Repairs | Classroom        | Chaparral ES            |
| 10306 | Work In Progress<br>computer lab has only one master key to open the door and that key was given to computer Teacher, per Mr. Cardona request he would like extra keys for the computer lab. To be distributed with the administrators. | 3/6/2006<br>Medium                          | Jennifer Corral<br>Manny Lozoya<br>Key and Lock            | Computer Lab     | Chaparral ES            |
| 10469 | Work In Progress<br>Need work order done for screens in Ms. Barrett's classroom.<br>Window in her classroom is falling apart. Fourth work order that has not been done. Rm-72   | 3/13/2006<br>Medium                         | Jennifer Corral<br>Ruben Ronquillo<br>Glass\Window Repairs | Classroom        | Chaparral ES            |
| 10470 | Work In Progress<br>Need work order done for screen to be put in windows for Ms. Herrera's Classroom. Rm-54   | 3/13/2006<br>Medium                         | Jennifer Corral<br>Ruben Ronquillo<br>Glass\Window Repairs | Classroom        | Chaparral ES            |
| 11335 | Work In Progress<br>need a key for another show case we have so we can remove from wall.  | 4/12/2006<br>Medium                         | Jennifer Corral<br>Manny Lozoya<br>Key and Lock            | Hallway/Corridor | Chaparral ES            |
| 11336 | Work In Progress<br>need safe in Mr. Cardona's room to be changed again Please as soon as possible very important Please!!!!!!<br>Thank you   | 4/12/2006<br>Medium                         | Jennifer Corral<br>Manny Lozoya<br>Key and Lock            | Office           | Chaparral ES            |
| 7710  | Work In Progress<br>Window in rm-72 is falling out. When opened it falls out. Doesn't stay up alone needs a stick to hold it up. See Ms. Barrett.   | 12/1/2005<br>Medium                         | Jennifer Corral<br>Ruben Ronquillo<br>Glass\Window Repairs |                  | Chaparral ES            |
| 11648 | Work In Progress<br>Danny needed a new master key, his was getting ready to break. I went ahead and got him another master key from the office. Not sure if this is procedure but I gave him one. He gave me his key                    | 4/26/2006<br>Medium                         | Jennifer Corral<br>Manny Lozoya<br>Key and Lock            | Custodial        | Chaparral ES            |
| 11052 | Work In Progress<br>area on the east side of campus and in and around water tank. Need to cut weeds and pick-up debris.   | 4/3/2006<br>Medium                          | Michael Munoz<br>Joe Ramirez<br>General Maintenance        |                  | Chaparral ES            |
| 10768 | Work In Progress<br>Need to cut weeds all around campus (front, bb courts, etc.)  | 3/28/2006<br>Medium                         | Michael Munoz<br>Joe Ramirez<br>General Maintenance        |                  | Chaparral ES            |
| 9053  | Work In Progress<br>E-Wing Barracks - Repair hole on eastside.  | 1/26/2006<br>Medium                         | Michael Munoz<br>Juan Vargas<br>General Maintenance        |                  | Chaparral ES            |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                     | Area Type | Location<br>Area Number |
|-------|--|---|---|-----------|-------------------------|
| 9054  | Work In Progress<br>E-Wing Barracks -Paint door on E-Wing Patio area and repair door (hole on wall E-Wing by Patio).   | 1/26/2006<br>Medium                         | Michael Munoz<br>Juan Vargas<br>Painting                              |           | Chaparral ES            |
| 8069  | Work In Progress<br>Need to cleanout Mech, Bolier and Electrical Rooms as per Mike Munoz.  | 12/13/2005<br>Medium                        | Michael Munoz<br>Joe Ramirez<br>General Maintenance                   |           | Chaparral MS            |
| 8070  | Work In Progress<br>Need to cut, pickup weeds and cleanup debris around WWTP as per Mike Munoz.  | 12/13/2005<br>1/24/2006<br>Medium           | Michael Munoz<br>Ricardo Jacquez<br>Sewage/Water Treatment Plant      |           | Chaparral MS            |
| 11100 | Work In Progress<br>Last portable on the north end of campus. The northeast corner needs more fill dirt. please jack building up and install more bricks in the center and add dirt to the corner and finish the earth work behind portable.   | 4/5/2006<br>Medium                          | Michael Munoz<br>Guadalupe Ontiveros<br>Grounds                       | Portables | Chaparral MS            |
| 9052  | Work In Progress<br>Patio (Behind Library) Cut grass, weeds and trim edges of grass on sidewalk.   | 1/26/2006<br>Medium                         | Michael Munoz<br>Joe Ramirez<br>General Maintenance                   |           | Chaparral MS            |
| 4072  | Work In Progress<br>Room 208 - Mold on ceiling tiles. (Nancy, Nurse @ site called in) - mkv Margaret, Joe replied and said there where a couple of ceiling tiles with small mold droppings on them. He replaced them. However still go ahead and generate a w.o. for our records and have him fill it out.<br><br>Mike | 8/2/2005<br>Medium                          | Mary Garcia<br>Joe Ramirez<br>General Maintenance                     | Classroom | Chaparral MS            |
| 11695 | Work In Progress<br>cotrto circuito en la linea que va pal exaut de g. locker room   | 4/27/2006<br>Medium                         | Juan Vargas<br>Enrique Sotelo<br>Electrical                           |           | Chaparral MS            |
| 11696 | Work In Progress<br>water founting in main lobby not working   | 4/27/2006<br>Medium                         | Juan Vargas<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning |           | Chaparral MS            |
| 10843 | Work In Progress<br>gym southside door not open need fix   | 3/30/2006<br>Medium                         | Juan Vargas<br>Manny Lozoya<br>Key and Lock                           |           | Chaparral MS            |
| 10401 | Work In Progress<br>MIKE. NEED TOOLBOX FOR THE WORK TRUCK  | 3/9/2006<br>Medium                          | Juan Vargas<br>Michael Munoz<br>Vehicle Maintenance                   |           | Chaparral MS            |
| 10514 | Work In Progress<br>need master cool wide sections 10- 6500 and 6 - 4500   | 3/15/2006<br>Medium                         | Juan Vargas<br>Lorenzo Solis<br>General Maintenance                   |           | Chaparral MS            |
| 10650 | Work In Progress<br>GYM need replace two a/c 8500  | 3/20/2006<br>Medium                         | Juan Vargas<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning | Gym       | Chaparral MS            |



| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft  | Area Type      | Location<br>Area Number |
|-------|---|---|--|----------------|-------------------------|
| 11565 | Work In Progress<br>boys locker room need secure door by the end<br>of the day panicbar is broken                                   | 4/24/2006<br>Medium                         | Juan Vargas<br>Manny Lozoya<br>Key and Lock                              |                | Chaparral MS            |
| 11447 | Work In Progress<br>lobby need fix front entry door   | 4/20/2006<br>Medium                         | Juan Vargas<br>Manny Lozoya<br>Key and Lock                              |                | Chaparral MS            |
| 11448 | Work In Progress<br>coudtian door closed lobby area not lock  | 4/20/2006<br>Medium                         | Juan Vargas<br>Manny Lozoya<br>Key and Lock                              |                | Chaparral MS            |
| 11397 | Work In Progress<br>hollway 200 and 400 need repace exit sing   | 4/18/2006<br>Medium                         | Juan Vargas<br>Enrique Sotelo<br>Electrical                              |                | Chaparral MS            |
| 11486 | Work In Progress<br>mike . need instaled new football score bord in<br>football field<br>4/15 - Route to Lupe as per Mike           | 4/21/2006<br>Medium                         | Juan Vargas<br>Guadalupe Ontiveros<br>Grounds                            | Football Field | Chaparral MS            |
| 11545 | Work In Progress<br>nurse portable need the fix window  | 4/24/2006<br>Medium                         | Juan Vargas<br>Ruben Ronquillo<br>Glass\Window Repairs                   |                | Chaparral MS            |
| 11546 | Work In Progress<br>room 312 a/c need fix or replace electric<br>disconet   | 4/24/2006<br>Medium                         | Juan Vargas<br>Enrique Sotelo<br>Electrical                              |                | Chaparral MS            |
| 11326 | Work In Progress<br>mike. need instaled new football score bord in<br>southside football field                                      | 4/12/2006<br>Medium                         | Juan Vargas<br>Guadalupe Ontiveros<br>Grounds                            | Football Field | Chaparral MS            |
| 11329 | Work In Progress<br>400 hollway entry door wireglass is broken<br>need replace  | 4/12/2006<br>Medium                         | Juan Vargas<br>Ruben Ronquillo<br>Glass\Window Repairs                   |                | Chaparral MS            |
| 11274 | Work In Progress<br>restrooms 200 hollway and main office man r.<br>room need fix   | 4/11/2006<br>Medium                         | Juan Vargas<br>Joe Ontiveros<br>Plumbing                                 |                | Chaparral MS            |
| 11275 | Work In Progress<br>woman locker room need fix and cover exaus<br>fan   | 4/11/2006<br>Medium                         | Juan Vargas<br>Lorenzo Solis<br>Heating/Ventilation /Air<br>Conditioning |                | Chaparral MS            |
| 9827  | Work In Progress<br>Coach Y. would like to have a plumber check out<br>the shower system it is not functioning at full<br>capacity. | 2/17/2006<br>Medium                         | Joe Ramirez<br>Joe Ontiveros<br>Plumbing                                 |                | Chaparral MS            |
| 8490  | Work In Progress<br>1/6/06.<br>need a new lock for bus turnaround south gate,<br>lock has been cut off.                             | 1/6/2006<br>Medium                          | Joe Ramirez<br>Manny Lozoya<br>Key and Lock                              |                | Chaparral MS            |
| 6558  | Work In Progress<br>10/19/05.<br>we need propane tank filled for portable housing<br>rms. 1&2.<br>ATTEN. RUBEN.                     | 10/19/2005<br>10/21/2005<br>Medium          | Joe Ramirez<br>Ruben Ronquillo<br>General Maintenance                    |                | Chaparral MS            |

| WOID | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                      | Area Type | Location<br>Area Number |
|------|--|---|--|-----------|-------------------------|
| 7324 | Work In Progress<br>11/14/05.<br>door closer on walk in freezer door needs to be replaced.<br>thanks.  | 11/14/2005<br>Medium                        | Joe Ramirez<br>Danny Orozco<br>Food Services                           |           | Chaparral MS            |
| 3720 | Work In Progress<br>7/12/05.<br>need a/c replaced on portable 1 rm. 2 please.  | 7/20/2005<br>Medium                         | Joe Ramirez<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Chaparral MS            |
| 2919 | Work In Progress<br>6/21/05.<br>need to replace s.e. corner a/c gym area.  | 6/21/2005<br>Medium                         | Joe Ramirez<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Chaparral MS            |
| 9486 | Work In Progress<br>need to replace cloged lines on top of rsf unit  | 2/8/2006<br>Medium                          | Ricardo Jacquez<br>Ricardo Jacquez<br>Sewage/Water<br>Treatment Plant  |           | Chaparral MS            |
| 7525 | Work In Progress<br>MRS. ADAMS ROOM 203 HAS CABINETS AND DRAWERS THAT ARE LOCKED AND SHE DOESN'T HAVE A KEY TO UNLOCK THEM. SHE WOULD LIKE TO HAVE THEM UNLOCKED AS SOON AS POSSIBLE. THANK YOU  | 11/22/2005<br>Medium                        | Robert Gonzalez<br>Manny Lozoya<br>Key and Lock                        |           | Chaparral MS            |
| 5062 | Work In Progress<br>I NEED 1 MALE WATER HOSE CONNECTOR, 1 HX-1 VINYL ANCHOR KIT AND 1 WEJIT DRY WALL AUGER ANCHOR KIT SIZE 8. THANK YOU  | 8/30/2005<br>Medium                         | Robert Gonzalez<br>Jimmy Carbajal<br>Custodial                         |           | Chaparral MS            |
| 2818 | Work In Progress<br>WE NEED 3 CHAIR DOLLIES. WE HAVE ALOT OF SPECIAL EVENTS IN WHICH WE HAVE TO TAKE ANY WHERE FROM 200 TO 400 CHAIRS TO THE GYM FROM THE CAFETERIA AND CLASSROOMS. THIS YEAR WITH THE 9TH GRADERS WE"LL HAVE EVEN MORE SET UPS TO DO . WE NEED THE DOLLIES TO BE LIKE THE TWO THAT WE HAVE NOW, TALL WE CAN CARRY TEN CHAIRS AT A TIME. THANK YOU<br>ROBERT | 6/16/2005<br>Medium                         | Robert Gonzalez<br>Aida Salcedo<br>Custodial                           |           | Chaparral MS            |
| 2799 | Work In Progress<br>I NEED IF POSSIBLE 2 MORE 2 WHEEL DOLLIES. EVERY BREAK WE HAVE ESPECIALLY THE SUMMER BREAK. WE HAVE TEACHERS MOVING FROM ONE ROOM TO ANOTHER AND SOME OF THEM BORROW THE DOLLIES. IT MAKES HARD FOR US BECAUSE WE"RE MOVING FURNITURE OR BOOKS AND OTHER THINGS. THANK YOU<br>ROBERT   | 6/15/2005<br>Medium                         | Robert Gonzalez<br>Aida Salcedo<br>Custodial                           |           | Chaparral MS            |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                  | Area Type        | Location<br>Area Number     |
|-------|---|---|--|------------------|-----------------------------|
| 3499  | Work In Progress<br>We need locks to be installed on the center pole to the double doors in the front entrance,north east doors and south east doors. This is the oldest part of the school. the newer part of the school already have locks on the center poles. This old doors are the once that we use more often. This locks will make it so much faster and easier. THANK YOU ROBERT | 7/13/2005<br>Medium                         | Robert Gonzalez<br>Manny Lozoya<br>Key and Lock                    |                  | Chaparral MS                |
| 11104 | Work In Progress<br>NEED A SMALL FENCE BETWEEN PROTABLE # 1 AND THE SIDE FENCE TO STOP STAFF AND STUDENTS FROM TAKING A SHORTCUT THROUGH THERE. ALOT OF DIRT IS TRACKED IN BECAUSE OF THIS . THE FENCE WE NEED ONLY HAS TO BE ABOUT 4 FT BY 6 FT. THANK YOU<br>As per Mike route to Juan Carlos - mkv 5/2/06  | 4/5/2006<br>Medium                          | Robert Gonzalez<br>Juan Vargas<br>General Maintenance              |                  | Chaparral MS                |
| 11231 | Work In Progress<br>OUR CARPET EXTRACTOR IS NOT WORKING RIGHT. IT'S NOT SPRAYING THE SOAP OUT. THANK YOU  | 4/10/2006<br>Medium                         | Robert Gonzalez<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair |                  | Chaparral MS                |
| 1708  | Work In Progress<br>NEED TO CHANGE STORAGE ROOM LOCK TO OPEN WITH KEY A-82 ONLY. ALSO DOOR MUST REMAIN LOCKED AT ALL TIMES.   | 5/6/2005<br>Medium                          | Vickie Reed<br>Manny Lozoya<br>Key and Lock                        | Hallway/Corridor | Chaparral MS<br>100 STORAGE |
| 3439  | Work In Progress<br>NEED KEYS FOR TWO NEW PORTABLES.  | 7/11/2005<br>Medium                         | Vickie Reed<br>Manny Lozoya<br>Key and Lock                        | Portables        | Chaparral MS                |
| 2487  | Work In Progress<br>need extra key for rm 405a  | 6/3/2005<br>Medium                          | Vickie Reed<br>Manny Lozoya<br>Key and Lock                        | Classroom        | Chaparral MS<br>405a        |
| 2488  | Work In Progress<br>need extra key for rm 405b  | 6/3/2005<br>Medium                          | Vickie Reed<br>Manny Lozoya<br>Key and Lock                        | Classroom        | Chaparral MS<br>405b        |
| 2489  | Work In Progress<br>need to rekey storage rm in 100 hall to open only w/ A82  | 6/3/2005<br>6/3/2005<br>Medium              | Vickie Reed<br>Manny Lozoya<br>Key and Lock                        | Office           | Chaparral MS<br>storage rm  |
| 2822  | Work In Progress<br>rekey file cabinets--about 8 or 9   | 6/16/2005<br>Medium                         | Vickie Reed<br>Manny Lozoya<br>Key and Lock                        | Custodial        | Chaparral MS                |
| 2823  | Work In Progress<br>need to key stage cabinets to open w/ only one key.   | 6/16/2005<br>Medium                         | Vickie Reed<br>Manny Lozoya<br>Key and Lock                        |                  | Chaparral MS                |
| 3855  | Work In Progress<br>NEED TO REKEY CABINET.  | 7/26/2005<br>Medium                         | Vickie Reed<br>Manny Lozoya<br>Key and Lock                        | Classroom        | Chaparral MS<br>204         |
| 4639  | Work In Progress<br>NEED 3 REPLACEMENT KEYS FOR 3 A-34'S THAT DO NOT WORK.  | 8/17/2005<br>Medium                         | Vickie Reed<br>Manny Lozoya<br>Key and Lock                        | Office           | Chaparral MS<br>VICKIE-KEY  |
| 4509  | Work In Progress<br>need to rekey file cabinets. 2  | 8/12/2005<br>Medium                         | Vickie Reed<br>Manny Lozoya<br>Key and Lock                        | Classroom        | Chaparral MS<br>104         |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                   | Area Type | Location<br>Area Number        |
|-------|---|---|---|-----------|--------------------------------|
| 9778  | Work In Progress<br>c.m.s. need to paint new doors around gym   | 2/16/2006<br>Medium                         | Danny Miranda<br>Juan Vargas<br>Painting            |           | Chaparral MS                   |
| 3607  | Work In Progress<br>need to paint new door @ football storage rm.   | 7/18/2005<br>Medium                         | Danny Miranda<br>Joe Ramirez<br>General Maintenance |           | Chaparral MS                   |
| 3608  | Work In Progress<br>need to paint new door @ rm. 86   | 7/18/2005<br>Medium                         | Danny Miranda<br>Joe Ramirez<br>General Maintenance |           | Chaparral MS                   |
| 11176 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Robert Gonzalez<br>Custodial        |           | Chaparral MS                   |
| 11323 | Work In Progress<br>NEED TO POWER WASH ALL CAFETERIA CHAIRS.  | 4/12/2006<br>Medium                         | Aida Salcedo<br>Guillermo Hernandez                 |           | Chaparral MS                   |
| 8702  | Work In Progress<br>needs copy of key A-24, needs to put new locks on two files cabinets in front office  | 1/12/2006<br>Medium                         | Elena Palacios<br>Manny Lozoya<br>Key and Lock      |           | Chaparral MS<br>Room 201       |
| 8488  | Work In Progress<br>Need keys to be made/duplicated for various rooms.  | 1/6/2006<br>1/9/2006<br>Medium              | Elena Palacios<br>Manny Lozoya<br>Key and Lock      | Classroom | Chaparral MS                   |
| 9825  | Work In Progress<br>SHOWERS IN BOYS GYM NEED SERVICING ONLY SEVEN OUT OF TEN ARE WORKING. POSSIBLY INSTALL NEW SHOWER HEADS.  | 2/17/2006<br>Medium                         | Elena Palacios<br>Joe Ontiveros<br>Plumbing         | Gym       | Chaparral MS<br>BOYS GYM       |
| 9629  | Work In Progress<br>sink in womens bathroom in front office is leaking and splashes water everywhere from the sides when it is opened.  | 2/13/2006<br>Medium                         | Elena Palacios<br>Joe Ontiveros<br>Plumbing         |           | Chaparral MS                   |
| 11036 | Work In Progress<br>NEED A KEY FOR NEW FILE CABINET THAT DOESN'T HAVE ONE.  | 4/3/2006<br>Medium                          | Elena Palacios<br>Manny Lozoya<br>Key and Lock      | Office    | Chaparral MS<br>Shirley's Desk |
| 11555 | Work In Progress<br>REACH - IN REFRIG. TEMP. AT 63.<br><br>SANDRA DIAZ - 824-4376   | 4/24/2006<br>Medium                         | Jacqueline Aguilar<br>Danny Orozco<br>Food Services | Cafeteria | Chaparral MS                   |
| 5463  | Work In Progress<br>need to pour landing and sidewalks to portables by football feild.  | 9/13/2005<br>Medium                         | Michael Munoz<br>Concrete                           | Portables | Chaparral MS                   |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                     | Area Type      | Location<br>Area Number |
|-------|--|---|---|----------------|-------------------------|
| 1854  | Work In Progress<br>Joe please order paint from Ruben so when portables arrive you can start painting them. Please call Mike   | 5/11/2005<br>Medium                         | Joe Ramirez<br>Painting                               | Portables      | Chaparral MS            |
| 3648  | Work In Progress<br>please get with speedy and have him train you on the sprikler system on football field and thru out campus. Identify all valves and repair what is needed. also ask him for a key for sprinkler box and have him teach you the programs. | 7/19/2005<br>Medium                         | Joe Ramirez<br>General Maintenance                    | Football Field | Chaparral MS            |
| 3649  | Work In Progress<br>need to cut weeds and grass behind library and courtyard and surrounding areas tru -out campus including pond. Also need to irrigate these areas also.   | 7/19/2005<br>High                           | Joe Ramirez<br>Grounds                                |                | Chaparral MS            |
| 3650  | Work In Progress<br>please paint railing on new portables that where installed and modified and all railings that are in need.   | 7/19/2005<br>Medium                         | Joe Ramirez<br>General Maintenance                    |                | Chaparral MS            |
| 3656  | Work In Progress<br>please put up fence where portables where installed even if its on a temp bases.   | 7/19/2005<br>Medium                         | Joe Ramirez<br>General Maintenance                    | Football Field | Chaparral MS            |
| 9338  | Work In Progress<br>Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.   | 2/5/2006<br>Medium                          | Alfredo Holguin<br>Joe Ramirez<br>Fire Extinguishers  |                | Chaparral MS            |
| 9351  | Work In Progress<br>Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.  | 2/5/2006<br>Medium                          | Alfredo Holguin<br>Joe Ramirez<br>Roof                |                | Chaparral MS            |
| 9364  | Work In Progress<br>Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.   | 2/5/2006<br>Medium                          | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance |                | Chaparral MS            |
| 9362  | Work In Progress<br>Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.   | 2/5/2006<br>Medium                          | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance |                | Chaparral MS            |
| 10225 | Work In Progress<br>Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Juan Vargas<br>General Maintenance |                | Chaparral MS            |
| 10227 | Work In Progress<br>Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Juan Vargas<br>General Maintenance |                | Chaparral MS            |
| 7781  | Work In Progress<br>Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.   | 12/4/2005<br>Medium                         | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance |                | Chaparral MS            |
| 7783  | Work In Progress<br>Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.   | 12/4/2005<br>Medium                         | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance |                | Chaparral MS            |

| <b>WOID</b> | <b>Status<br/>Description<br/>Action Taken</b>  | <b>Request Date<br/>Completion Date<br/>Priority</b> | <b>Requester<br/>Assigned To<br/>Craft</b>               | <b>Area Type</b> | <b>Location<br/>Area Number</b> |
|-------------|---|--|--|------------------|---------------------------------|
| 7757        | Work In Progress<br>Monthly - Chaparral MS Monthly FE Inpsection -<br>Refer to PM schedule details.     | 12/4/2005<br>Medium                                  | Alfredo Holguin<br>Joe Ramirez<br>Fire Extinguishers     |                  | Chaparral MS                    |
| 11139       | Work In Progress<br>Portable - Include exterior siding and skirting<br>repairs and painting.            | 4/6/2006<br>Medium                                   | Danny Miranda<br>General Maintenance                     | Portables        | Chaparral MS                    |
| 8369        | Work In Progress<br>Monthly - Chaparral MS Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 1/1/2006<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance    |                  | Chaparral MS                    |
| 8371        | Work In Progress<br>Monthly - Chaparral MS Emer. Light Test: Monthly<br>- Refer to PM schedule details. | 1/1/2006<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance    |                  | Chaparral MS                    |
| 8296        | Work In Progress<br>Monthly - Chaparral MS Monthly FE Inpsection -<br>Refer to PM schedule details.     | 1/1/2006<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>Fire Extinguishers     |                  | Chaparral MS                    |
| 10201       | Work In Progress<br>Monthly - Chaparral MS Monthly FE Inpsection -<br>Refer to PM schedule details.     | 3/5/2006<br>Medium                                   | Alfredo Holguin<br>Juan Vargas<br>Fire Extinguishers     |                  | Chaparral MS                    |
| 3148        | Work In Progress<br>Monthly - Chaparral MS Monthly FE Inpsection -<br>Refer to PM schedule details.     | 7/3/2005<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>Fire Extinguishers     |                  | Chaparral MS                    |
| 3314        | Work In Progress<br>Yearly - Chaparral MS Emer. Light Test: Annual -<br>Refer to PM schedule details.   | 7/6/2005<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>Fire Protection        |                  | Chaparral MS                    |
| 3241        | Work In Progress<br>Monthly - Chaparral MS Exit Sign Insp. - Refer to<br>PM schedule details.           | 7/3/2005<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance    |                  | Chaparral MS                    |
| 3243        | Work In Progress<br>Monthly - Chaparral MS Emergency Lighting Insp.<br>- Refer to PM schedule details.  | 7/3/2005<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance    |                  | Chaparral MS                    |
| 10961       | Work In Progress<br>Monthly - Chaparral MS Fire Suppression Insp. -<br>Refer to PM schedule details.    | 4/2/2006<br>Medium                                   | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System |                  | Chaparral MS                    |
| 7061        | Work In Progress<br>Monthly - Chaparral MS Monthly FE Inpsection -<br>Refer to PM schedule details.     | 11/6/2005<br>Medium                                  | Alfredo Holguin<br>Joe Ramirez<br>Fire Extinguishers     |                  | Chaparral MS                    |
| 5227        | Work In Progress<br>Monthly - Chaparral MS Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 9/4/2005<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance    |                  | Chaparral MS                    |
| 5229        | Work In Progress<br>Monthly - Chaparral MS Emer. Light Test: Monthly<br>- Refer to PM schedule details. | 9/4/2005<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance    |                  | Chaparral MS                    |

| <b>WOID</b> | <b>Status<br/>Description<br/>Action Taken</b>  | <b>Request Date<br/>Completion Date<br/>Priority</b> | <b>Requester<br/>Assigned To<br/>Craft</b>            | <b>Area Type</b> | <b>Location<br/>Area Number</b> |
|-------------|---|--|---|------------------|---------------------------------|
| 6084        | Work In Progress<br>Monthly - Chaparral MS Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 10/2/2005<br>Medium                                  | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance |                  | Chaparral MS                    |
| 6086        | Work In Progress<br>Monthly - Chaparral MS Emer. Light Test: Monthly<br>- Refer to PM schedule details. | 10/2/2005<br>Medium                                  | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance |                  | Chaparral MS                    |
| 7074        | Work In Progress<br>Monthly - Chapparral MS Roof Inspection - Refer<br>to PM schedule details.          | 11/6/2005<br>Medium                                  | Alfredo Holguin<br>Joe Ramirez<br>Roof                |                  | Chaparral MS                    |
| 7085        | Work In Progress<br>Monthly - Chaparral MS Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 11/6/2005<br>Medium                                  | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance |                  | Chaparral MS                    |
| 7087        | Work In Progress<br>Monthly - Chaparral MS Emer. Light Test: Monthly<br>- Refer to PM schedule details. | 11/6/2005<br>Medium                                  | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance |                  | Chaparral MS                    |
| 3977        | Work In Progress<br>Monthly - Chapparral MS Roof Inspection - Refer<br>to PM schedule details.          | 7/31/2005<br>Medium                                  | Alfredo Holguin<br>Joe Ramirez<br>Roof                |                  | Chaparral MS                    |
| 3988        | Work In Progress<br>Monthly - Chaparral MS Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 7/31/2005<br>Medium                                  | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance |                  | Chaparral MS                    |
| 3990        | Work In Progress<br>Monthly - Chaparral MS Emer. Light Test: Monthly<br>- Refer to PM schedule details. | 7/31/2005<br>Medium                                  | Alfredo Holguin<br>Joe Ramirez<br>General Maintenance |                  | Chaparral MS                    |
| 6008        | Work In Progress<br>Monthly - Chaparral MS Monthly FE Inpsection -<br>Refer to PM schedule details.     | 10/2/2005<br>Medium                                  | Alfredo Holguin<br>Joe Ramirez<br>Fire Extinguishers  |                  | Chaparral MS                    |
| 5204        | Work In Progress<br>Monthly - Chaparral MS Monthly FE Inpsection -<br>Refer to PM schedule details.     | 9/4/2005<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>Fire Extinguishers  |                  | Chaparral MS                    |
| 3964        | Work In Progress<br>Monthly - Chaparral MS Monthly FE Inpsection -<br>Refer to PM schedule details.     | 7/31/2005<br>Medium                                  | Alfredo Holguin<br>Joe Ramirez<br>Fire Extinguishers  |                  | Chaparral MS                    |
| 3307        | Work In Progress<br>Monthly - Chapparral MS Roof Inspection - Refer<br>to PM schedule details.          | 7/6/2005<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>Roof                |                  | Chaparral MS                    |
| 3336        | Work In Progress<br>Yearly - Chaparral MS Exit Sign Test: Annual -<br>Refer to PM schedule details.     | 7/6/2005<br>Medium                                   | Alfredo Holguin<br>Joe Ramirez<br>Fire Protection     |                  | Chaparral MS                    |
| 10931       | Work In Progress<br>Monthly - Desert Pride Roof Inspection - Refer to<br>PM schedule details.           | 4/2/2006<br>Medium                                   | Alfredo Holguin<br>David Acosta<br>Roof               |                  | Desert Pride                    |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                      | Area Type   | Location<br>Area Number |
|-------|---|---|--|-------------|-------------------------|
| 10951 | Work In Progress<br>Monthly - Desert Pride Monthly FE Inspection -<br>Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>David Acosta<br>Fire Extinguishers  |             | Desert Pride            |
| 10990 | Work In Progress<br>Monthly - Desert Pride Emer. Light Test: Monthly -<br>Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>David Acosta<br>General Maintenance |             | Desert Pride            |
| 10994 | Work In Progress<br>Monthly - Desert Pride Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>David Acosta<br>General Maintenance |             | Desert Pride            |
| 10228 | Work In Progress<br>Monthly - Desert Pride Emer. Light Test: Monthly -<br>Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>David Acosta<br>General Maintenance |             | Desert Pride            |
| 10232 | Work In Progress<br>Monthly - Desert Pride Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>David Acosta<br>General Maintenance |             | Desert Pride            |
| 10215 | Work In Progress<br>Monthly - Desert Pride Monthly FE Inspection -<br>Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>David Acosta<br>Fire Extinguishers  |             | Desert Pride            |
| 4992  | Work In Progress<br>please remove marquee sign from desertveiw<br>and install at desert pride. please be careful<br>when removing.see mike  | 8/29/2005<br>Medium                         | Guadalupe Ontiveros<br>Grounds                         |             | Desert Pride            |
| 11178 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE<br>INSPECTIONS ON ALL CUSTODIANS TO INCLUDED<br>CLOSET, MSDS, LABELED SPRAY BOTTLES &<br>SAFETY EQUIPMENT. HEAD CUSTODIANS NEED<br>TO INCLUDE INSPECTION OF YOUR OWN AREA.<br>INSPECTION REPORTS ALONG WITH<br>COMPLETED WORK ORDER MUST BE RETURNED<br>AND RECEIVED BY US NO LATER THAN APRIL<br>21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>David Acosta<br>Custodial              |             | Desert Pride            |
| 11597 | Work In Progress<br>In classroom students restroom toilet needs a<br>chain to flapper (chain was remove).   | 4/25/2006<br>Medium                         | David Acosta<br>David Villalobos<br>Plumbing           | Classroom   | Desert Pride<br>1 & 2   |
| 11598 | Work In Progress<br>Sinks in restrooms- one missing pop-up drain<br>and the other is broken. need to replace.   | 4/25/2006<br>Medium                         | David Acosta<br>David Villalobos<br>Plumbing           | Classroom   | Desert Pride<br>1 & 2   |
| 11599 | Work In Progress<br>Staff members complaining about front entrance<br>gate to parking lot a little hard to push open & pull<br>gate.  | 4/25/2006<br>Medium                         | David Acosta<br>Michael Munoz<br>Fence Repair          | Parking Lot | Desert Pride            |
| 9877  | Work In Progress<br>front office building - roof missing tile<br>Route to Gerry Marquez as per Mike 3/10/06   | 2/21/2006<br>Medium                         | David Acosta<br>Michael Munoz<br>Roof                  | Office      | Desert Pride            |



| <b>WOID</b> | <b>Status<br/>Description<br/>Action Taken</b>   | <b>Request Date<br/>Completion Date<br/>Priority</b> | <b>Requester<br/>Assigned To<br/>Craft</b>                              | <b>Area Type</b> | <b>Location<br/>Area Number</b> |
|-------------|--|--|---|------------------|---------------------------------|
| 7731        | Work In Progress<br>need gate repairs-vehicles hit and run on gate<br>(front entrance)   | 12/2/2005<br>Medium                                  | David Acosta<br>Ruben Ronquillo<br>Fence Repair                         | Parking Lot      | Desert Pride<br>front entrance  |
| 7666        | Work In Progress<br>having trouble unlocking the westside door<br>(cylinder).  | 11/30/2005<br>Medium                                 | David Acosta<br>Manny Lozoya<br>Key and Lock                            | Classroom        | Desert Pride<br>#8              |
| 7955        | Work In Progress<br>Vandalism - Damage to front entrance roll gate hit<br>by vehicle.<br>(Case# 2005-1037) Julio Ledesma #831  | 12/2/2005<br>Medium                                  | David Acosta<br>Michael Munoz<br>Fence Repair                           |                  | Desert Pride                    |
| 8880        | Work In Progress<br>need to replace broken toilet seat   | 1/19/2006<br>Medium                                  | David Acosta<br>David Villalobos<br>Plumbing                            | Computer Lab     | Desert Pride                    |
| 5959        | Work In Progress<br>need to ckeck a/c blower . It stops blowing  | 9/29/2005<br>Medium                                  | David Acosta<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning | Classroom        | Desert Pride<br>#1              |
| 5336        | Work In Progress<br>Principals requests: for dead bolt locks for last<br>portable (where break-in occur )  | 9/8/2005<br>Medium                                   | David Acosta<br>Manny Lozoya<br>Key and Lock                            | Classroom        | Desert Pride<br>#6,7.           |
| 4642        | Work In Progress<br>need one key for storage closet for teacher in<br>room #3  | 8/17/2005<br>Medium                                  | David Acosta<br>Manny Lozoya<br>Key and Lock                            | Classroom        | Desert Pride<br>3               |
| 4304        | Work In Progress<br>need locks for two doors to the hall way, that<br>needs to be use as storage for science rooms.  | 8/8/2005<br>Medium                                   | David Acosta<br>Manny Lozoya<br>Key and Lock                            | Classroom        | Desert Pride<br>#3,4            |
| 3791        | Work In Progress<br>need plastic name plates(12)MS. S. VERLANDER,<br>MS. I. RAMIREZ, MS. BACH-HAGUE, MS. B.<br>COSTULIS, MS. C. MCDONALD, MR. C. VELA,<br>MR. P. WYMAN, MS. G. PARKER, MS. S.<br>GARCIA, MR. D. NEAL , MS. J. ZAPATA, MS. D.<br>DEAN | 7/25/2005<br>Medium                                  | David Acosta<br>Manny Lozoya<br>Key and Lock                            | Classroom        | Desert Pride                    |
| 1410        | Work In Progress<br>need seven locks for doors to front offices. (in<br>counslor, social workers area.)  | 4/25/2005<br>Medium                                  | David Acosta<br>Manny Lozoya<br>Key and Lock                            | Office           | Desert Pride                    |
| 1834        | Work In Progress<br>need two plactic name plates for front office<br>doors-( ALL VISITORS MUST SIGN IN AT FRONT<br>OFFICE )  | 5/11/2005<br>Medium                                  | David Acosta<br>Manny Lozoya<br>Key and Lock                            | Office           | Desert Pride                    |
| 3064        | Work In Progress<br>Att: Sal Acuna-requesting for a desk mover and<br>red flat truck.  | 6/29/2005<br>Medium                                  | David Acosta<br>Sal Acuna<br>Custodial                                  | Football Field   | Desert Pride                    |
| 2910        | Work In Progress<br>need two light switches installed for iep room<br>and custodian office (no light switches in rooms.)   | 6/21/2005<br>Medium                                  | David Acosta<br>Carlos Castillo<br>Electrical                           | Office           | Desert Pride                    |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                  | Area Type | Location<br>Area Number   |
|-------|---|---|--|-----------|---------------------------|
| 2606  | Work In Progress<br>need one key for classroom for new teacher  | 6/7/2005<br>Medium                          | David Acosta<br>Manny Lozoya<br>Key and Lock                       | Classroom | Desert Pride<br>5         |
| 4460  | Work In Progress<br>I need an office key for Ms. Maes, Clerk at Desert<br>Pride Academy   | 8/10/2005<br>Medium                         | Mary Telles<br>Manny Lozoya<br>Key and Lock                        | Office    | Desert Pride              |
| 9144  | Work In Progress<br>NEED A KEY (CD-32) FOR KITCHEN DOORS.<br>REQUESTED BY MRS. MARTINEZ: PRINCIPAL  | 1/30/2006<br>Medium                         | Marisela Torres<br>Manny Lozoya<br>Key and Lock                    |           | Desert Trail Intermediate |
| 11318 | Work In Progress<br>1522 ASPIRADORA RUEDAS . MANGO.   | 4/12/2006<br>Medium                         | Marisela Torres<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair |           | Desert Trail Intermediate |
| 11319 | Work In Progress<br>3383 ASPIRADORA. ELECTRCO   | 4/12/2006<br>Medium                         | Marisela Torres<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair |           | Desert Trail Intermediate |
| 11321 | Work In Progress<br>NEED SOLUTION TANK  | 4/12/2006<br>Medium                         | Marisela Torres<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair |           | Desert Trail Intermediate |
| 10511 | Work In Progress<br>NEED TO REPLACE COMERCIAL FLOOR TILE TO<br>BUS LOBBY  | 3/15/2006<br>Medium                         | Marisela Torres<br>Michael Munoz<br>General Maintenance            |           | Desert Trail Intermediate |
| 11641 | Work In Progress<br>ASPIRADORA E98C-00002771. NO TRABAJA .<br>POR FAVOR REVISAR EL MANGO. GRACIAS.  | 4/26/2006<br>Medium                         | Marisela Torres<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair |           | Desert Trail Intermediate |
| 11179 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE<br>INSPECTIONS ON ALL CUSTODIANS TO INCLUDED<br>CLOSET, MSDS, LABELED SPRAY BOTTLES &<br>SAFETY EQUIPMENT. HEAD CUSTODIANS NEED<br>TO INCLUDE INSPECTION OF YOUR OWN AREA.<br>INSPECTION REPORTS ALONG WITH<br>COMPLETED WORK ORDER MUST BE RETURNED<br>AND RECEIVED BY US NO LATER THAN APRIL<br>21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Marisela Torres<br>Custodial                       |           | Desert Trail Intermediate |
| 6266  | Work In Progress<br>RUSH ! or as soon as possible or Monday even.<br>Could I get a line locate for Desert Trails<br>Portables?  | 10/11/2005<br>Medium                        | Carlos Vigil<br>Enrique Sotelo<br>Electrical                       |           | Desert Trail Intermediate |
| 3739  | Work In Progress<br>DIAG/PSYCH ROOM NEED (2) CLASSROOM<br>KEYS MADE. CORE IS: J-53  | 7/21/2005<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                       |           | Desert Trail Intermediate |
| 4558  | Work In Progress<br>Mrs. Bonham (Asst. Principal) requesting<br>concrete slab to be installed between portable<br>#412 and #413 art studio.   | 8/15/2005<br>Medium                         | Johnny Acuna<br>Michael Munoz<br>Concrete                          |           | Desert Trail Intermediate |

| WOID | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                    | Area Type | Location<br>Area Number   |
|------|---|---|--|-----------|---------------------------|
| 6883 | Work In Progress<br>need a lock (J-11) for new gate that was installed located in the fence between CH. ELEM and CH. DESERT TRAIL closest to Lisa ST. (To be locked during LOCK DOWN events). Thank You !!!!!!! | 10/31/2005<br>Medium                        | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                         |           | Desert Trail Intermediate |
| 6910 | Work In Progress<br>need a replacement heating coil (boiler heating system) for cafeteria heater. Old heater leaks: Model # LHD103CH<br>Serial #35C01059-06   | 11/1/2005<br>Medium                         | Johnny Acuna<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |           | Desert Trail Intermediate |
| 6846 | Work In Progress<br>fire-proof filing cabinet inside vault: please fix or replace lock.   | 10/28/2005<br>Medium                        | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                         |           | Desert Trail Intermediate |
| 7184 | Work In Progress<br>Please replace metal door (Back Door) from the kitchen. Door is corroded and getting worse. Thank You !!!   | 11/8/2005<br>Medium                         | Johnny Acuna<br>Danny Miranda<br>Doors and Hardware                  |           | Desert Trail Intermediate |
| 7520 | Work In Progress<br>(Ruben Ronquillo)<br>Need cement mixer for next week to do cement project in parking lot area. (ramp)   | 11/22/2005<br>Medium                        | Johnny Acuna<br>Ruben Ronquillo<br>General Maintenance               |           | Desert Trail Intermediate |
| 7408 | Work In Progress<br>NEED TO INSTALL FENCE AROUND FIRE HYDRANT.<br>(SEE ATTACHED)  | 11/16/2005<br>Medium                        | Johnny Acuna<br>Michael Munoz<br>Fence Repair                        |           | Desert Trail Intermediate |
| 7366 | Work In Progress<br>need to replace door frame and door to portable #404.   | 11/15/2005<br>Medium                        | Johnny Acuna<br>Danny Miranda<br>Doors and Hardware                  |           | Desert Trail Intermediate |
| 6170 | Work In Progress<br>please repair or replace door knob in the kitchen going outdoors in the back:(door jams and is hard to open) Thank You !!!!!!!!!!!!!!!!!!!!!  | 10/4/2005<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                         |           | Desert Trail Intermediate |
| 5426 | Work In Progress<br>need a replacement heating coil (Boiler System) in the Cafeteria/Gym. (Old one Leaks)   | 9/12/2005<br>Medium                         | Johnny Acuna<br>Jaime Gomez<br>Heating/Ventilation /Air Conditioning |           | Desert Trail Intermediate |
| 2322 | Work In Progress<br>PLEASE SEND EXTERMINATOR OR MOUSE TRAPS TO RM.#116(MRS. DOMINGUEZ) MOUSE INSIDE CLASSROOM.  | 5/26/2005<br>Medium                         | Johnny Acuna<br>Johnny Acuna<br>Pest Control                         |           | Desert Trail Intermediate |
| 2376 | Work In Progress<br>NEED TO REPLACE DOOR FRAME TO PORTABLE #411. (MAIN DOOR).   | 5/31/2005<br>Medium                         | Johnny Acuna<br>Danny Miranda<br>Doors and Hardware                  |           | Desert Trail Intermediate |
| 2289 | Work In Progress<br>NEED A SCREW EXTRACTOR FOR CLASSROOM #112 SINK HANDLE. (VALVE)  | 5/25/2005<br>Medium                         | Johnny Acuna<br>Fred Appelzoller<br>Plumbing                         |           | Desert Trail Intermediate |

| WOID | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                       | Area Type | Location<br>Area Number   |
|------|--|---|---|-----------|---------------------------|
| 2290 | Work In Progress<br>NEED NEW LOCKS AND KEYS FOR<br>CABINET/CLOSET AND THE TEACHER'S DESK.<br>MAIN BLDG. RM. #115.  | 5/25/2005<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                            |           | Desert Trail Intermediate |
| 2298 | Work In Progress<br>5/25/05<br>.5-CHECK LIFT STATION<br>.5-REPLACE MISSING INTERCOM BUTTONS TO<br>CLASSROOMS.<br>2.0-FIX LIGHT FIXTURES TO CLASSROOM<br>RESTROOMS.<br>.5-REPLACE PENCIL SHARPENERS TO ROOMS.<br>#102 AND 406.<br>1.5-TROUBLESHOOT AND FIX A/C TO ROOM<br>#209.<br>3.0-CUT WEEDS.<br>5/25 - 8 | 5/25/2005<br>Medium                         | Johnny Acuna<br>Johnny Acuna<br>General Maintenance                     |           | Desert Trail Intermediate |
| 2403 | Work In Progress<br>NEED A LOCK FOR SOUTHWEST GATE NEXT TO<br>LISA ST.   | 6/1/2005<br>Medium                          | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                            |           | Desert Trail Intermediate |
| 2425 | Work In Progress<br>NEED TO REPLACE A LOST KEY FOR ROOM<br>#201: MARIA RONGEL  | 6/1/2005<br>Medium                          | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                            |           | Desert Trail Intermediate |
| 2211 | Work In Progress<br>NEED A NEW REPLACEMENT HOLLOW DOOR<br>FOR CLASSROOM # 411 GIRL'S RESTROOM.<br>DOOR SIZE: 32 1/2" WIDE X 80" LONG. ALSO<br>NEED (2) DOOR KNOBS. ONE (ROUND) FOR<br>HALLWAY DOOR, AND ONE (LEVER) FOR<br>BOY'S RESTROOM DOOR. THANK YOU !!!!!  | 5/23/2005<br>Medium                         | Johnny Acuna<br>Danny Miranda<br>Doors and Hardware                     |           | Desert Trail Intermediate |
| 2212 | Work In Progress<br>(STUDENT RECORDS) NEED TO REPAIR<br>BROKEN FILE CABINET LOCK, ALSO NEED A<br>KEY TO BE ABLE TO LOCK CABINETS. BOTH<br>STUDENT RECORD CABINETS ARE THE SAME<br>KEY. (LOCATED INSIDE THE VAULT IN THE MAIN<br>OFFICE)  | 5/23/2005<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                            |           | Desert Trail Intermediate |
| 1556 | Work In Progress<br>PORTABLE #411: NEED A NEW DOORKNOB<br>(LEVER TYPE) FOR BOYS RR, AND ALSO NEED<br>TO RE-WELD DOOR HINGE TO MAIN<br>CLASSROOM DOOR. FALLEN DOOR HARD TO<br>CLOSE.  | 5/2/2005<br>Medium                          | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                            |           | Desert Trail Intermediate |
| 2061 | Work In Progress<br>NEED TO REPLACE CONDENSATION PUMP TO<br>THE REFRIGERATION UNIT LOCATED INSIDE THE<br>SERVER ROOM.  | 5/18/2005<br>Medium                         | Johnny Acuna<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Desert Trail Intermediate |
| 1192 | Work In Progress<br>RM. #112 GUTIERREZ . NEED TO FIX AND MAKE<br>A KEY FOR FILING CABINET INSIDE<br>CLASSROOM..THANK YOU.....  | 4/15/2005<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                            |           | Desert Trail Intermediate |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                       | Area Type | Location<br>Area Number   |
|-------|--|---|---|-----------|---------------------------|
| 1211  | Work In Progress<br>need irrigation backflow preventer to be installed for irrigation to front trees. (irrigation line has been installed).  | 4/18/2005<br>Medium                         | Johnny Acuna<br>Lorenzo Hernandez<br>Grounds            |           | Desert Trail Intermediate |
| 2585  | Work In Progress<br>(DANNY MIRANDA) NEED TO SEE IF FRAME AND DOOR COULD BE MOVED TO THE OTHER SIDE OF THE WALL TOWARDS HALLWAY AND CLOSE OFF WALL WHERE DOOR AND FRAME USED TO BE. *LOCATION: SPEECH ROOM* | 6/7/2005<br>Medium                          | Johnny Acuna<br>Danny Miranda<br>Doors and Hardware     |           | Desert Trail Intermediate |
| 3619  | Work In Progress<br>MENS RESTROOM (NW HALL) : PLEASE CHANGE DOOR CYLINDER WHERE KEY ENTERS TO OPEN UP DOOR. STUDENTS STUFFED IN CYLINDER WITH CLAY AND HARDENED. THANK YOU !!!!!                           | 7/18/2005<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock            |           | Desert Trail Intermediate |
| 3620  | Work In Progress<br>NEED NAME PLATES TO BE MADE: (1) PRINCIPAL, (1) ASSISTANT PRINCIPAL, (1) COMPUTER LAB  | 7/18/2005<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock            |           | Desert Trail Intermediate |
| 10697 | Work In Progress<br>re-key cylinders to new portables at chaparral desert trail.   | 3/22/2006<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock            |           | Desert Trail Intermediate |
| 11601 | Work In Progress<br>(BROKEN FIRE ESCAPE WINDOW HARDWARE AND BUTTONS TO PORTABLES)<br>NEED TO REPLACE BROKEN FIRE ESCAPE WINDOW HARDWARE AND BUTTONS TO PORTABLES: #403, #409, AND #410. THANK YOU.....     | 4/25/2006<br>Medium                         | Johnny Acuna<br>Ruben Ronquillo<br>Glass\Window Repairs |           | Desert Trail Intermediate |
| 11559 | Work In Progress<br>(David Boyd) Outdoor expansion joint located in the bus area turnaround has a 1" separation and has cracked the upper part of the wall. Please come and check. Thank You....           | 4/24/2006<br>Medium                         | Johnny Acuna<br>David Boyd<br>Construction              |           | Desert Trail Intermediate |
| 11560 | Work In Progress<br>NEED A GATE INSTALLED WHERE TWO SIDEWALKS MEET BETWEEN CHAPARRAL ELEM. AND DESERT TRAIL. (MIDDLE FENCE LINE). (SIDEWALKS ARE FOR HANDICAPP FIRE EXIT ESCAPE ROUTE.)                    | 4/24/2006<br>Medium                         | Johnny Acuna<br>Michael Munoz<br>Fence Repair           |           | Desert Trail Intermediate |
| 11561 | Work In Progress<br>need 277v ballasts, and 120v ballasts. Also need wire nuts. Thank You....  | 4/24/2006<br>Medium                         | Johnny Acuna<br>Enrique Sotelo<br>Electrical            |           | Desert Trail Intermediate |
| 9830  | Work In Progress<br>Portable #412, need to replace cracked window glass.   | 2/17/2006<br>Medium                         | Johnny Acuna<br>Ruben Ronquillo<br>Glass\Window Repairs |           | Desert Trail Intermediate |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft   | Area Type | Location<br>Area Number   |
|-------|--|---|---|-----------|---------------------------|
| 9779  | Work In Progress<br>Need keys made for Portable #400 furniture:<br>Teacher's desk (3) different locks, need to install<br>a lock to filing cabinet (cabinet still has the<br>knockout), and a key for storage cabinet.   | 2/16/2006<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                              |           | Desert Trail Intermediate |
| 9430  | Work In Progress<br>(Danny Miranda) Portable #411, #412: Need<br>to replace hallway and restroom doors. Thank<br>You !!!!!   | 2/6/2006<br>Medium                          | Johnny Acuna<br>Danny Miranda<br>Doors and Hardware                       |           | Desert Trail Intermediate |
| 9614  | Work In Progress<br>Need a new key for room #212. Teacher lost<br>key. (J-50) Sylvia Lorenzo.  | 2/13/2006<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                              |           | Desert Trail Intermediate |
| 9062  | Work In Progress<br>need (2) flush valve kits for restroom comodes.<br>One for boy's RR in the NW hall (handicap), and<br>the other for the girl's RR in front of the teacher's<br>lounge (handicap).  | 1/26/2006<br>Medium                         | Johnny Acuna<br>Joe Ontiveros<br>Plumbing                                 |           | Desert Trail Intermediate |
| 9048  | Work In Progress<br>need a J-11 lock for outdoor cage gate between<br>the lift station and the baseball backstop in the<br>playground area. Thank You !!!  | 1/25/2006<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                              |           | Desert Trail Intermediate |
| 9001  | Work In Progress<br>need a restroom partition installed in room #107.<br>(handicapp room)  | 1/24/2006<br>Medium                         | Johnny Acuna<br>Danny Miranda<br>Doors and Hardware                       |           | Desert Trail Intermediate |
| 8625  | Work In Progress<br>portable #407: need a lock with key installed to<br>filing cabinet. cabinet has no lock installed. It still<br>has an oval knockout hole to it.<br>Also need a key made to teacher's desk. I have<br>tried out all extra keys from the office. | 1/11/2006<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock                              |           | Desert Trail Intermediate |
| 8166  | Work In Progress<br>need to replace cracked window to portable<br>#412. Have already placed glass patch on the<br>window (both sides)  | 12/16/2005<br>Medium                        | Johnny Acuna<br>Ruben Ronquillo<br>Glass\Window Repairs                   |           | Desert Trail Intermediate |
| 7573  | Work In Progress<br>need a gas valve for reznor roof top heater.<br>(valve doesn't close and leaks a little).<br>HONEYWELL : VR8304M 2880<br>supplied Johnny w/gas valve and he will install.  | 11/28/2005<br>12/1/2005<br>Medium           | Johnny Acuna<br>Lorenzo Solis<br>Heating/Ventilation /Air<br>Conditioning |           | Desert Trail Intermediate |
| 11675 | Work In Progress<br>NEED (4) FIRE EXTINGUISHERS FOR NEW<br>PORTABLES AT CHAPARRAL DESERT TRAIL.  | 4/27/2006<br>Medium                         | Johnny Acuna<br>Ruben Ronquillo<br>Fire Extinguishers                     |           | Desert Trail Intermediate |
| 11693 | Work In Progress<br>need the whole flush valve kit to replace in the<br>nurse's office restroom. Have changed the<br>diaphragm and vaccum breaker, but still gets<br>stuck. Water keeps running.   | 4/27/2006<br>Medium                         | Johnny Acuna<br>Joe Ontiveros<br>Plumbing                                 |           | Desert Trail Intermediate |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                      | Area Type                              | Location<br>Area Number   |
|-------|--|---|--|--|---------------------------|
| 11707 | Work In Progress<br>NEED PLAYGROUND SAND FOR SWINGS.   | 4/27/2006<br>Medium                         | Johnny Acuna<br>Guadalupe Ontiveros<br>Grounds         |  | Desert Trail Intermediate |
| 11849 | Work In Progress<br>need (2) square keys for outdoor water valves on the main building walls. (where the water hoses connect)  | 5/2/2006<br>Medium                          | Johnny Acuna<br>Joe Ontiveros<br>Plumbing              |  | Desert Trail Intermediate |
| 11728 | Work In Progress<br>need to replace door knob to audio/visual room to one that can stay open unlocked. (Librarian's Request)   | 4/28/2006<br>Medium                         | Johnny Acuna<br>Manny Lozoya<br>Key and Lock           |  | Desert Trail Intermediate |
| 11831 | Work In Progress<br>(TRUCK #94)<br>PLEASE FIX DRIVER'S SIDE DOOR WINDOW TO WORK TRUCK. WINDOW DOES NOT ROLL DOWN. THANK YOU.....   | 5/1/2006<br>Medium                          | Johnny Acuna<br>Angel Gonzales<br>Vehicle Maintenance  |  | Desert Trail Intermediate |
| 11836 | Work In Progress<br>DAVID BOYD<br>ROOF LEAK IN THE GIRL'S RESTROOM IN FRONT OF THE TEACHER'S LOUNGE. LEAK GOES THROUGH ALL THE WAY DOWN INTO THE CEILING OF THE RESTROOM AND BUBBLES UP THE PAINT. HAVE TRIED TO PATCH IT UP BUT CANNOT FIND THE LEAK. PLEASE STOP BY WHEN YOU GET A CHANCE OR SEND ME SOME CONTRACTORS TO HELP ME FIND THE LEAK. THANK YOU..... | 5/1/2006<br>Medium                          | Johnny Acuna<br>David Boyd<br>Construction             |  | Desert Trail Intermediate |
| 5462  | Work In Progress<br>need to demo and repour concrete to sectioned area by cafeteria.   | 9/13/2005<br>Medium                         | Michael Munoz<br>Concrete                              | Desert Trail Intermediate<br>Cafeteria |                           |
| 10231 | Work In Progress<br>Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Johnny Acuna<br>General Maintenance |  | Desert Trail Intermediate |
| 10226 | Work In Progress<br>Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Johnny Acuna<br>General Maintenance |  | Desert Trail Intermediate |
| 9363  | Work In Progress<br>Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.   | 2/5/2006<br>Medium                          | Alfredo Holguin<br>Johnny Acuna<br>General Maintenance |  | Desert Trail Intermediate |
| 10915 | Work In Progress<br>Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Johnny Acuna<br>Fire Extinguishers  |  | Desert Trail Intermediate |
| 9368  | Work In Progress<br>Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.   | 2/5/2006<br>Medium                          | Alfredo Holguin<br>Johnny Acuna<br>General Maintenance |  | Desert Trail Intermediate |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number   |
|-------|---|---|--|-----------|---------------------------|
| 10202 | Work In Progress<br>Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.  | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Johnny Acuna<br>Fire Extinguishers    |           | Desert Trail Intermediate |
| 8314  | Work In Progress<br>Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.  | 1/1/2006<br>Medium                          | Alfredo Holguin<br>Johnny Acuna<br>Roof                  |           | Desert Trail Intermediate |
| 10993 | Work In Progress<br>Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Johnny Acuna<br>General Maintenance   |           | Desert Trail Intermediate |
| 10988 | Work In Progress<br>Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Johnny Acuna<br>General Maintenance   |           | Desert Trail Intermediate |
| 10932 | Work In Progress<br>Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Johnny Acuna<br>Roof                  |           | Desert Trail Intermediate |
| 10963 | Work In Progress<br>Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System |           | Desert View ES            |
| 6225  | Work In Progress<br>NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005. | 10/10/2005<br>Medium                        | Aida Salcedo<br>Miguel Aguilar<br>Custodial              |           | Desert View ES            |
| 11180 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006.       | 4/7/2006<br>Medium                          | Aida Salcedo<br>Miguel Aguilar<br>Custodial              |           | Desert View ES            |
| 1183  | Work In Progress<br>NEED TO REPLACE HOSE SPIGOTS IN PATIOS. LOOSING WATER PRESSURE AND HANDLES ARE BROKEN. NO HEAD CUSTODIAN AT SCHOOL SITE. IF YOU NEED ANY INFORMATION, CONTACT JIMMY CARBAJAL @ THE CUSTODIAL WAREHOUSE  | 4/15/2005<br>Medium                         | Aida Salcedo<br>David Villalobos<br>Plumbing             |           | Desert View ES            |
| 10125 | Work In Progress<br>There is an electrical short near light bulb in Walk-In Refrigerator.<br><br>Martha Flores - SNP Manager 589-2425   | 3/2/2006<br>Medium                          | Alma Terrell<br>Danny Orozco<br>Food Services            | Cafeteria | Desert View ES            |



| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft   | Area Type | Location<br>Area Number |
|-------|--|---|---|-----------|-------------------------|
| 10491 | Work In Progress<br>#1. Fan above cooking stopped working,<br>#2. On and Off button to mixer is broken and<br>#3. Light Bulb area is still not fixed<br><br>Martha Flores - DV Manager - 589-2425        | 3/14/2006<br>Medium                         | Alma Terrell<br>Danny Orozco<br>Food Services                               | Cafeteria | Desert View ES          |
| 4149  | Work In Progress<br>key cylinder to walk-in refrigerator doesn't lock,<br>key continuously goes round and round, please<br>repair as soon as possible, groceries and<br>commodities are stored in there. | 8/3/2005<br>Medium                          | Alma Terrell<br>Manny Lozoya<br>Key and Lock                                | Cafeteria | Desert View ES          |
| 4781  | Work In Progress<br>pat aguilar<br>rock wall<br>(safety concern) 6 rock wall metal gates need to<br>be replaced<br>rusted throw  | 8/22/2005<br>Medium                         | Patricio Aguilar<br>Michael Munoz<br>Fence Repair                           |           | Desert View ES          |
| 1968  | Work In Progress<br>pat aguilar - asper principal<br>to replace ac in port #2 room 3&4 with refrigrated<br>air conditioning  | 5/16/2005<br>Medium                         | Patricio Aguilar<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning |           | Desert View ES          |
| 1969  | Work In Progress<br>pat aguilar<br>move sand away from rock wall<br>move sand back up hill   | 5/16/2005<br>Medium                         | Patricio Aguilar<br>Lorenzo Hernandez<br>Grounds                            |           | Desert View ES          |
| 2448  | Work In Progress<br>pat aguilar<br>locksmith<br>frount door to building need repair<br>door closures need replacement<br>door handdels need replacement  | 6/2/2005<br>Medium                          | Patricio Aguilar<br>Manny Lozoya<br>Key and Lock                            |           | Desert View ES          |
| 11245 | Work In Progress<br>W.O. : PRINCIPAL<br>CARPET TO BE REPLACED IN CLASS ROOMS -<br>16 ROOMS<br>R-21=25=18-14-23-27-29-31-34-36-39-30-41-32-<br>24-5<br>TO BE TILED<br>PAT AGUILAR                         | 4/10/2006<br>Medium                         | Patricio Aguilar<br>Michael Munoz<br>Carpet Repair                          |           | Desert View ES          |
| 11706 | Work In Progress<br>pat aguilar<br>need light bulbs<br>class rooms - fluorescent lamps order #26668<br>hall ways - light fixtures<br>class rooms - ballasts light icn-4p32-sc                            | 4/27/2006<br>Medium                         | Patricio Aguilar<br>Carlos Castillo<br>Electrical                           |           | Desert View ES          |
| 11832 | Work In Progress<br>please repair the 1/2" copper water line on the<br>east roof top. (where boilers are at)   | 5/1/2006<br>Medium                          | Michael Munoz<br>Patricio Aguilar<br>General Maintenance                    |           | Desert View ES          |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                       | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 11833 | Work In Progress<br>please remove all debris and dead pigeons from roof tops .  | 5/1/2006<br>Medium                          | Michael Munoz<br>Patricio Aguilar<br>General Maintenance                |           | Desert View ES          |
| 7613  | Work In Progress<br>Have a nonfunctioning electrical outlet in gymnasium.   | 11/29/2005<br>Medium                        | Miguel Aguilar<br>Carlos Castillo<br>Electrical                         |           | Desert View ES          |
| 7614  | Work In Progress<br>Have a nonfunctional electrical outlet in cafeteria.  | 11/29/2005<br>Medium                        | Miguel Aguilar<br>Carlos Castillo<br>Electrical                         |           | Desert View ES          |
| 2546  | Work In Progress<br>Faucets in both patio areas need repair. Note: Work order is for Desert View Elementary, not RS.  | 6/6/2005<br>Medium                          | Miguel Aguilar<br>David Villalobos<br>Plumbing                          |           | Desert View ES          |
| 5145  | Work In Progress<br>Urgent: Need center pole repaired in exterior double door on east side of school repaired, pole fell and struck teacher. Door cannot be fully secured and will compromise security after school hours.  | 9/1/2005<br>Medium                          | Miguel Aguilar<br>Manny Lozoya<br>Key and Lock                          |           | Desert View ES          |
| 5146  | Work In Progress<br>Need copies (3) made of padlocks on hall doors, need for sub keys and replacement.  | 9/1/2005<br>Medium                          | Miguel Aguilar<br>Manny Lozoya<br>Key and Lock                          |           | Desert View ES          |
| 7232  | Work In Progress<br>Trees in front courtyard unhealthy/dying, signs of infestation, requesting solution/insecticide to remedy problem.  | 11/9/2005<br>Medium                         | Miguel Aguilar<br>Guadalupe Ontiveros<br>Grounds                        |           | Desert View ES          |
| 10483 | Work In Progress<br>Please replace tracer summit board. Thank You!!   | 3/14/2006<br>Medium                         | Lorenzo Solis<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning |           | Desert View ES          |
| 11246 | Work In Progress<br>As per Alfredo Holguin he would like for you to mark portables at your site with the following numbers:<br><br>(59DM,<br>16DM,<br>85 DM1R,<br>12 SM)<br><br>Mark them inside electrical box and top corner of portable. If you have any question please contact Alfredo. Thank you. | 4/10/2006<br>Medium                         | Maritza Gonzalez<br>Patricio Aguilar<br>General Maintenance             | Portables | Desert View ES          |
| 8110  | Work In Progress<br>MANNY,<br>PLEASE MAKE TWO NAME PLAQUES FOR MINERVA SINGH, RN<br>AND YOLANDA F. GOMEZ, CNA. THANK YOU,<br>THANK YOU!!<br><br>margarita :)  | 12/14/2005<br>Medium                        | Margarita Terrazas<br>Manny Lozoya<br>Key and Lock                      |           | Desert View ES          |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                            | Area Type    | Location<br>Area Number           |
|-------|---|---|--|--------------|-----------------------------------|
| 4083  | Work In Progress<br>TEACHER DESK WITH LOCKING DRAWER, DOES NOT LOCK. ROOM#19, LOWER GRADE SIDE. MRS. GRISWOLD   | 8/2/2005<br>Medium                          | Margarita Terrazas<br>Manny Lozoya<br>Key and Lock           |              | Desert View ES                    |
| 11556 | Work In Progress<br>Need to have electrical power strips installed in 3 classrooms in order to plug several computers.  | 4/24/2006<br>Medium                         | Julie Hinojosa<br>Carlos Castillo<br>Electrical              | Portables    | GAC                               |
| 8635  | Work In Progress<br>SPED Office - Need to plaster holes in wall and replace ceiling tile.   | 1/11/2006<br>Medium                         | Margret Villalobos<br>Manuel Prospero<br>General Maintenance | Office       | GAC                               |
| 11557 | Work In Progress<br>RTC - Please exterminate for ants all portables asap a big issue.   | 4/24/2006<br>Medium                         | Margret Villalobos<br>Margret Villalobos<br>Pest Control     | Portables    | GAC                               |
| 7235  | Work In Progress<br>SPED Portable - need ramp for portable located at GAC. (see Margaret Villalobos-SPED_Route to Manuel Prospero as per Mike 11/9/05 - mkv   | 11/9/2005<br>12/1/2005<br>Medium            | Margret Villalobos<br>Manuel Prospero<br>Ramps/Platforms     |              | GAC                               |
| 11595 | Work In Progress<br>Repair restroom by swimming pool.   | 4/25/2006<br>Medium                         | Michael Munoz<br>David Villalobos<br>Plumbing                |              | GAC                               |
| 11596 | Work In Progress<br>Need to install dispenser in restroom by swimming pool.   | 4/25/2006<br>Medium                         | Michael Munoz<br>Ralph Lara<br>Custodial                     |              | GAC                               |
| 4655  | Work In Progress<br>AS PER ANN STEINHOFF-NEEDS 1 MORE GRAND MASTER KEY FOR HER SECRETARY AT PRE-K   | 8/17/2005<br>Medium                         | Mary Garcia<br>Manny Lozoya<br>Key and Lock                  | Office       | GAC<br>WHOLE<br>BUILDING          |
| 6743  | Work In Progress<br>AS PER MS. BERRY-NEEDS 3 SIGNS THAT SAY SLOW CHILDREN TO PUT IN THE ENTRANCE AND PARKING AREA.<br>TALKED WITH RUBEN RONQUILLO AND KNOW WHICH SIGNS TO ORDER                     | 10/25/2005<br>Medium                        | Mary Garcia<br>Ruben Ronquillo<br>General Maintenance        |              | GAC<br>PARKING AREA               |
| 5796  | Work In Progress<br>AS PER CORA-NEEDS THE DOOR LOCK TO THE DATA CENTER SWITCHED OUT FROM SWIPE CARD TO A COMBINATION LOCK. (MANNY, PLEASE SEE CORA BEFORE CHANGING OUT)                             | 9/23/2005<br>Medium                         | Mary Garcia<br>Manny Lozoya<br>Key and Lock                  | Computer Lab | GAC<br>DATA CENTER-<br>TECHNOLOGY |
| 3408  | Work In Progress<br>AS PER CARLOS VIGIL-NEEDS A GRAND MASTER 7, ASAP. (HIS BROKE IN HALF) ALREADY TALKED WITH MANNY LOZOYA  | 7/8/2005<br>Medium                          | Mary Garcia<br>Manny Lozoya<br>Key and Lock                  | Office       | GAC<br>ALL SCHOOLS                |
| 3432  | Work In Progress<br>AS PER LINDA REYES-NEED FURNITURE FROM 3 OFFICES & BOXES ALONG WITH THIS TO BE MOVED A.S.A.P. TO NEW AREA IN C-WING. STAFF WILL START WORKING IN THESE NEW OFFICES BY TOMORROW. | 7/11/2005<br>Medium                         | Mary Garcia<br>Manuel Prospero<br>General Maintenance        | Office       | GAC<br>C WING                     |

| WOID | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                   | Area Type | Location<br>Area Number                 |
|------|---|---|---|-----------|---|
| 2909 | Work In Progress<br>AS PER TINA B-WING, OUTLET IN THE FILE ROOM DOES NOT WORK. (NEED TO PLUG A FAN IN ORDER TO WORK IN THAT ROOM TO HOT.)<br>Need Electrician's assistance, checked for power, breaker and no power.<br>routed to Cali 6/27/05. | 6/21/2005<br>10/26/2005<br>Medium           | Mary Garcia<br>Carlos Castillo<br>Electrical                        | Office    | GAC<br>FILE ROOM                        |
| 2755 | Work In Progress<br>AS PER LAURA GARCIA-WOULD LIKE TO CLOSE OFF OFFICE DOOR TOTALLY & HAVE A DOOR MADE THROUGH ANNIE'S OFFICE, GOING INTO HER OFFICE. (PLEASE CHECK W/LAURA BEFORE DOING ANYTING.)  | 6/13/2005<br>Medium                         | Mary Garcia<br>Danny Miranda<br>Doors and Hardware                  | Office    | GAC                                     |
| 2548 | Work In Progress<br>AS PER CORA W/TECHNOLOGY, SHE NEEDS A KEYS TO BE ISSUE TO LYNCO ELECTRIC AND SOUND & SINGNAL FOR GHS AND LU (FOR THE WHOLE SCHOOL)  | 6/6/2005<br>Medium                          | Mary Garcia<br>Manny Lozoya<br>Key and Lock                         | Classroom | GAC                                     |
| 2658 | Work In Progress<br>RAY LARA-C WING; NEEDS FURNITURE TO BE MOVED FROM CORINA & DEBBIE'S OFFICE INTO THE CONFERENCE ROOM. (WIRE SHELVE WILL BE PLACED IN MR. LARA'S OFFICE). NOTE: THIS MUST BE DONE BY 6/15/05 AS PER MS. STEINHOFF.            | 6/9/2005<br>Medium                          | Mary Garcia<br>Manuel Prospero<br>General Maintenance               | Office    | GAC                                     |
| 2660 | Work In Progress<br>AS PER CARLOS VIGIL-NEEDS 6 PAD LOCKS FOR GHS MASTER. (FOR THIS TO OPEN WITH BEST LOCK MASTER KEY)<br>APPROVED BY MR. CHAVEZ  | 6/9/2005<br>Medium                          | Mary Garcia<br>Manny Lozoya<br>Key and Lock                         | Classroom | GAC                                     |
| 144  | Work In Progress<br>IN A-WING SPECIAL ED, ACROSS COMPUTER LAB; ROOMS HAVE NO COOLING AND HEATING. NEED TO TALK W/SYLVIA MORENO.   | 3/8/2005<br>Medium                          | Mary Garcia<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning | Office    | GAC                                     |
| 850  | Work In Progress<br>As per Manny Prospero: Needs weeds to be cut if can have ground come out to help.   | 4/5/2005<br>Medium                          | Mary Garcia<br>Lorenzo Hernandez<br>Grounds                         |           | GAC                                     |
| 8924 | Work In Progress<br>AS PER ELISA SAENZ-NEEDS NAME PLATES DONE FOR OUR NEW BOARD MEMBERS, BEFORE NEXT WEDNESDAY.<br>1.) ANDREW MORALES 2.) MANUELA HUERTA  | 1/20/2006<br>Medium                         | Mary Garcia<br>Manny Lozoya<br>Key and Lock                         |           | GAC<br>BOARD ROOM                       |
| 8925 | Work In Progress<br>AS PER ELISA SAENZ-NEEDS NAME PLATES DONE FOR OUR STUDENT REPRESENTATIVES. FOR NAME PLATES TO ALSO SAY STUDENT REPRESENTATIVE BELOW THEIR NAME IF POSSIBLE. 1.) DELILAH APPELZOLLER 2.) JOSUE CASTREJON                     | 1/20/2006<br>Medium                         | Mary Garcia<br>Manny Lozoya<br>Key and Lock                         |           | GAC<br>STUDENT REPRESENTATIV<br>E @ GAC |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                   | Area Type       | Location<br>Area Number |
|-------|---|---|---|-----------------|-------------------------|
| 9215  | Work In Progress<br>AS PER MIKE SORIA NEEDS A KEY TO THE PATIO LOCK. (WAS CHANGED BY MANNY L. TO OPEN W/GRAND MASTER) MIKE HAS AN OLD KEY.  | 2/1/2006<br>Medium                          | Mary Garcia<br>Manny Lozoya<br>Key and Lock                         |                 | GAC<br>PATIO AREA       |
| 9166  | Work In Progress<br>AS PER MS. BERRY-ROOM 101 IN THE PRE-K FRONT DOOR NEEDS TO BE TINTED. IT FACES THE WEST SIDE OF THE BUILDING AND IS VERY HOT IN THE AFTERNOON.  | 1/30/2006<br>Medium                         | Mary Garcia<br>Ruben Ronquillo<br>Glass/Window Repairs              | Classroom       | GAC                     |
| 9073  | Work In Progress<br>AS PER MANNY-NEEDS TO RE-KEY ELODIA'S OFFICE, KEY DID NOT WORK.   | 1/26/2006<br>Medium                         | Mary Garcia<br>Manny Lozoya<br>Key and Lock                         | Office          | GAC<br>C-WING           |
| 9496  | Work In Progress<br>AS PER MARGARET V W/SPED-NEED AN ELECTRICAL OUTLET UNDER A DESK TO BE REMOVED. (SAM GALLEGOS OFFICE) IF POSSIBLE ASAP.  | 2/8/2006<br>Medium                          | Mary Garcia<br>Carlos Castillo<br>Electrical                        | Mechanical Room | GAC<br>A WINT           |
| 9318  | Work In Progress<br>AS PER MS. CUBILETTE-NEED CEMENT SCREWS FOR PINIC TABLES. (IF POSSIBLE TO BE SENT TODAY, CAUSE MANNY P. ALREADY ASSEMBLED TABLES & ARE SET OUTSIDE WITHOUT BEING SECURED. TABLES ARE WORTH \$600.000 EACH & IS VERY CONCERNED THEY MIGHT WALK OFF OVER THE WEEKEND.) AS PER MANNY P. STATED HE WAS NOT GOING TO PUT TABLES OUTSIDE UNTIL CEMENT SCREWS WERE SENT (BY YET HE DID). MANNY P. STATED THEY WERE ALREADY ORDER BY WORK ORDER AND ALSO PLACE A PHONE CALL TO RUBEN R. SINCE A WEEK AGO. AS PER RUBEN NO WORK ORDER HAS BEEN DONE BY MANNY P. RUBEN R. WILL TRY TO SENT CEMENT SCREWS TODAY W/JIMMY. | 2/3/2006<br>Medium                          | Mary Garcia<br>Manuel Prospero<br>General Maintenance               |                 | GAC<br>PATIO            |
| 9275  | Work In Progress<br>AS PER MARY GARCIA-NEED SUPPLY CABINET LOCK TO BE REPLACED OR FIXED. DOES NOT LOCK. (MANNY P. HAS ALREADY TRIED TWICE AND LOCKS ONLY FOR 1 DAY AND BACK TO THE SAME THING.)   | 2/2/2006<br>Medium                          | Mary Garcia<br>Manny Lozoya<br>Key and Lock                         | Office          | GAC<br>FILE ROOM        |
| 9529  | Work In Progress<br>AS PER MS. BERRY-NEEDS FOR RUGS TO BE SET UP IN EACH CLASSROOM. (SEE ATTACHED SHEET GIVEN TO MANNY P.)  | 2/9/2006<br>Medium                          | Mary Garcia<br>Manuel Prospero<br>General Maintenance               | Classroom       | GAC                     |
| 9880  | Work In Progress<br>AS PER JOSE AMBRIZ-NEEDS TO REPLACE THE WHOLE AIR CONDITING UNIT FOR A-WING. (WILL BE ORDERING PARTS TO HAVE READY)   | 2/21/2006<br>Medium                         | Mary Garcia<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |                 | GAC<br>A WING           |
| 11266 | Work In Progress<br>AS PER SELMA-NEED TO EXTERMINATE FOR ANTS AND SWSEEP DIRT FROM WALKWAYS.  | 4/11/2006<br>Medium                         | Mary Garcia<br>Margret Villalobos<br>Pest Control                   | Office          | GAC                     |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                   | Area Type        | Location<br>Area Number |
|-------|---|---|---|------------------|-------------------------|
| 11267 | Work In Progress<br>AS PER MARGARET V- WINDOW SEALS NEED TO BE CLEANED, DUE TO DIRT AND CAN NOT OPEN WINDOWS.   | 4/11/2006<br>Medium                         | Mary Garcia<br>Ralph Lara<br>Custodial                              | Office           | GAC<br>A WING-SPEED     |
| 11382 | Work In Progress<br>AS PER GUSTAVO-BATHROOM IN ROOM #103 MAKES ALOT OF NOISE WHEN FLUSHING. (LIKE IF IT IS GOING TO BRAKE DOWN.)  | 4/18/2006<br>Medium                         | Mary Garcia<br>David Villalobos<br>Plumbing                         | Restroom (Girls) | GAC<br>ROOM 103         |
| 11272 | Work In Progress<br>AS PER LUCY GARCIA-NEEDS HELP MOVING FIRE PROOF CABINETS.   | 4/11/2006<br>Medium                         | Mary Garcia<br>Manuel Prospero<br>General Maintenance               | Office           | GAC<br>B WING           |
| 11443 | Work In Progress<br>AS PER MIKE MUNOZ-MANNY P. TO PAINT THE BATHROOMS IN C-WING   | 4/20/2006<br>Medium                         | Mary Garcia<br>Manuel Prospero<br>Painting                          | Restroom (Girls) | GAC<br>C WING           |
| 11041 | Work In Progress<br>AS PER MS. BERRY-IF IT WOULD BE POSSIBLE TO HAVE SOME KIND OF MESH OR FENCE PUT UP ALL AROUND THE PLAYGROUND AREA DUE TO SNAKES. THE PRE-K STUDENTS ARE ALWAYS AROUND THAT AREA PLAYING. (A SNAKES WAS FOUND NEAR THE FINANCE BACK DOOR.) | 4/3/2006<br>Medium                          | Mary Garcia<br>Michael Munoz<br>General Maintenance                 |                  | GAC<br>PLAY GROUND      |
| 11716 | Work In Progress<br>AS PER MS. RAIHL-AIR CONDITIONING UNIT IS RATTING & MAKING NOISE OFF & ON   | 4/28/2006<br>Medium                         | Mary Garcia<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning | Office           | GAC<br>C-WING           |
| 11839 | Work In Progress<br>AS PER MS. CANTRELL-ASSEMBLE AND ARRANGE FURNITURE THAT IS ARRIVING ON MAY 2ND. (GOING INTO DAVID QUINTANA'S OFFICE)  | 5/1/2006<br>Medium                          | Mary Garcia<br>Manuel Prospero<br>General Maintenance               | Office           | GAC<br>C WING           |
| 2163  | Work In Progress<br>5/20/05 WE NEED TO CHANGED LOCKS AT NEW HANDICAP RESTROOMS. TO PRIMUS LOCKS. THIS IN FOR MANNY LOZOYA   | 5/20/2005<br>Medium                         | Manuel Prospero<br>Manny Lozoya<br>Key and Lock                     |                  | GAC                     |
| 1980  | Work In Progress<br>AS PER MANY LOZOYA WE NEED 4 KEY FOR RESETE FIRE ALARM.   | 5/17/2005<br>Medium                         | Manuel Prospero<br>Manny Lozoya<br>Key and Lock                     |                  | GAC                     |
| 4377  | Work In Progress<br>NEED NEW R. R. PARTITIONS IN "A" WING AS PER MENNY PROSPERO   | 8/9/2005<br>Medium                          | Manuel Prospero<br>Danny Miranda<br>General Maintenance             |                  | GAC                     |
| 7950  | Work In Progress<br>12/8/05.EXAUST POWER IN RESTROOM AT C WING DOESN'T WORK. THIS WORK ORDER IN FOR CARLOS CASTILLO. 2ND REQUEST. FIRST WORK ORER #6990. 11/3/05.   | 12/8/2005<br>Medium                         | Manuel Prospero<br>Carlos Castillo<br>Electrical                    |                  | GAC                     |
| 9066  | Work In Progress<br>I AM REQUESTING A CHAIN AND LOCK TO TIE UP TWO PIC-NIC TABLES. THI W O AS PER MANNY LOZOYA.   | 1/26/2006<br>Medium                         | Manuel Prospero<br>Manny Lozoya<br>General Maintenance              |                  | GAC                     |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                       | Area Type | Location<br>Area Number |
|-------|--|---|---|-----------|-------------------------|
| 10560 | Work In Progress<br>3/16/06. WE NEED TO REPLACE THE SHORT LIGHT POSTS.THEY ARE BROKEN AND NEED TO CHECK IF THERE IS POWER. THIS NEEDS TO BE DONE AS SOON AS POSSIBLE. MR. HAUGEN IS REQUESTING THIS WORK ORDER.<br>AS PER MR. CARLOS CASTILLO. | 3/16/2006<br>Medium                         | Manuel Prospero<br>Carlos Castillo<br>Electrical                        |           | GAC                     |
| 11502 | Work In Progress<br>4/21/06.WE NEED ELECTRIC CONNECTION IN ROOF FOR 25 TON UNID.   | 4/21/2006<br>Medium                         | Manuel Prospero<br>Carlos Castillo<br>Electrical                        |           | GAC                     |
| 11277 | Work In Progress<br>FOR LUPE ONTIVEROS. REPLACE THE SPRINKLERS THAT ARE IN THE MAIN ENTRANCE WHERE THE PINE TREES ARE, REASON IS THE WATER SPREADS ON THE ROAD. THE REPLACEMENTS ARE THE BUBBLES SPRINKLES THEY ARE WATER SAVERS.              | 4/11/2006<br>Medium                         | Manuel Prospero<br>Guadalupe Ontiveros<br>Grounds                       |           | GAC                     |
| 11214 | Work In Progress<br>4/7/06. NEED TO REPLACE DOOR C-WING  | 4/7/2006<br>Medium                          | Manuel Prospero<br>Manuel Prospero<br>General Maintenance               |           | GAC                     |
| 11835 | Work In Progress<br>WE NEED TO INSTALL NEW EXOST TO BETROOM IN C WING..  | 5/1/2006<br>Medium                          | Manuel Prospero<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |           | GAC                     |
| 9067  | Work In Progress<br>Swimming Pool Area - Remove dangling wooden boards.  | 1/26/2006<br>Medium                         | Michael Munoz<br>Gerardo Marquez<br>General Maintenance                 |           | GAC                     |
| 9981  | Work In Progress<br>RTC Office - Transfer furniture to Portable 3 take computer from Margaret's Office to RTC Office.  | 2/24/2006<br>Medium                         | Selma Nevarez<br>Ralph Lara<br>Custodial                                |           | GAC                     |
| 9320  | Work In Progress<br>THE BURNISHER HAS NO POWER TO SWITCH,1681715 THANK YOU   | 2/3/2006<br>Medium                          | Ralph Lara<br>Jimmy Carbajal<br>Custodial Equipment Repair              | Cafeteria | GAC                     |
| 11643 | Work In Progress<br>PLEASE PUT TOGETHER SHELVES FOR SHED   | 4/26/2006<br>Medium                         | Cora Ramirez<br>Manuel Prospero<br>General Maintenance                  |           | GAC                     |
| 9281  | Work In Progress<br>NEED TO RE-KEY CUSTODIAL CLOSET IN "ON-TRACK" PRE-K BUILDING TO GAC BLDG MASTER.   | 2/2/2006<br>Medium                          | Aida Salcedo<br>Manny Lozoya<br>Key and Lock                            |           | GAC                     |
| 11444 | Work In Progress<br>Trim trees next to Pine Trees at entrance to the GAC.  | 4/20/2006<br>Medium                         | Aida Salcedo<br>Guadalupe Ontiveros<br>Grounds                          |           | GAC                     |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                            | Area Type | Location<br>Area Number |
|-------|---|---|--|-----------|-------------------------|
| 11182 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Ralph Lara<br>Custodial                      |           | GAC                     |
| 1674  | Work In Progress<br>NEED 2FT.BY2FT. CONCRETE BASE TO INTALL LIGHT FIXTURES ON BOTH SIDES OF ENTRANCE SIGN TO THE GAC.   | 5/5/2005<br>Medium                          | Carlos Castillo<br>Michael Munoz<br>Concrete                 |           | GAC                     |
| 5824  | Work In Progress<br>NEED A WATERHOSE AND ALSO A HOSE ROLL A WAY.2 WATERHOSE ONE FOR THE PATIO AND ONE FOR THE PRE KINDER AREA I ONLY HAVE ONE AND I USE IT FOR THE FRONT AREA,THE HOSE ROLL A WAYS I NEED ONE FOR EACH HOSE THANK YOU FOR YOUR CONTINUED SUPPORT YOU ARE THE BEST!!!!   | 9/26/2005<br>Medium                         | Jimmy Carbajal<br>Sal Acuna<br>Custodial Equipment<br>Repair | Custodial | GAC                     |
| 3094  | Work In Progress<br>Install fencing on north property line for site security.   | 6/30/2005<br>6/30/2005<br>Medium            | Alfredo Holguin<br>Michael Munoz<br>Fence Repair             |           | GAC                     |
| 10964 | Work In Progress<br>Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System     |           | GAC                     |
| 10956 | Work In Progress<br>Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System     |           | GAC                     |
| 3282  | Work In Progress<br>C-WING - TAKE OFF TILE AND INSTALL NEW TILE (TILE HAS BEEN DELIVERED), ALSO FINISH PAINTING. WILL SEND GERRY MARQUEZ TO ASSIST.   | 7/5/2005<br>Medium                          | Alfredo Holguin<br>Manuel Prospero<br>General Maintenance    |           | GAC                     |
| 9145  | Work In Progress<br>please install water line for misters on the east side of the pre-k. Plans are in your mail box.  | 1/30/2006<br>Medium                         | Guadalupe Ontiveros<br>Grounds                               |           | GAC                     |
| 11038 | Work In Progress<br>please provide sand to daycare area where new playground equipment was installed .Might need the bobcat to lay sand.  | 4/3/2006<br>Medium                          | Guadalupe Ontiveros<br>Grounds                               |           | GAC                     |
| 3546  | Work In Progress<br>Technology Server Room-Install Battery powered Emergency lighting in this room  | 7/14/2005<br>Medium                         | Carlos Castillo<br>Electrical                                |           | GAC                     |



| WOID | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                          | Area Type      | Location<br>Area Number |
|------|--|---|--|----------------|-------------------------|
| 2315 | Work In Progress<br>Please paint inside and out of both guard shacks and repair what is damaged before school starts this year.          | 5/26/2005<br>Medium                         | Mario Apodaca<br>Painting                                  |                | Gadsden HS              |
| 5458 | Work In Progress<br>need to restripe all parking lines ,handi-cap-arrowa etc.  | 9/13/2005<br>Medium                         | Michael Munoz<br>Painting                                  | Parking Lot    | Gadsden HS              |
| 4916 | Work In Progress<br>please check and repair leak & secure drop ceiling in rm 142. possible safety hazard.                                | 8/25/2005<br>Medium                         | Danny Miranda<br>General Maintenance                       |                | Gadsden HS              |
| 4448 | Work In Progress<br>Telescope observatory locate on the west side of the baseball field - Install fencing around it to prevent vandalism | 8/10/2005<br>Medium                         | Michael Munoz<br>Fence Repair                              |                | Gadsden HS              |
| 5464 | Work In Progress<br>Need to paint stripings for student parking lot and east of Auto Shop.   | 9/13/2005<br>Medium                         | Michael Munoz<br>General Maintenance                       | Parking Lot    | Gadsden HS              |
| 7499 | Work In Progress<br>please re-route conduit and repair where kids get on roof by panther hut. north bldg.                                | 11/21/2005<br>Medium                        | Enrique Sotelo<br>Electrical                               | Classroom      | Gadsden HS              |
| 7500 | Work In Progress<br>please replace disconnect to heating unit on the - S- wing north bldg. blades do not work properly.                  | 11/21/2005<br>Medium                        | Jose Ambriz<br>Heating/Ventilation /Air Conditioning       | Classroom      | Gadsden HS              |
| 9546 | Work In Progress<br>please repair clean out that east of concession stand.   | 2/10/2006<br>Medium                         | David Villalobos<br>Plumbing                               | Football Field | Gadsden HS              |
| 8316 | Work In Progress<br>Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.   | 1/1/2006<br>Medium                          | Alfredo Holguin<br>Mario Apodaca<br>Roof                   |                | Gadsden HS              |
| 8379 | Work In Progress<br>Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.                                       | 1/1/2006<br>Medium                          | Alfredo Holguin<br>Fernando Moncayo<br>General Maintenance |                | Gadsden HS              |
| 8382 | Work In Progress<br>Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.   | 1/1/2006<br>Medium                          | Alfredo Holguin<br>Mario Apodaca<br>General Maintenance    |                | Gadsden HS              |
| 7791 | Work In Progress<br>Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.                                       | 12/4/2005<br>Medium                         | Alfredo Holguin<br>Fernando Moncayo<br>General Maintenance |                | Gadsden HS              |
| 9372 | Work In Progress<br>Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.                                       | 2/5/2006<br>Medium                          | Alfredo Holguin<br>Fernando Moncayo<br>General Maintenance |                | Gadsden HS              |
| 9375 | Work In Progress<br>Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.   | 2/5/2006<br>Medium                          | Alfredo Holguin<br>Mario Apodaca<br>General Maintenance    |                | Gadsden HS              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                          | Area Type | Location<br>Area Number |
|-------|---|---|--|-----------|-------------------------|
| 10907 | Work In Progress<br>Monthly - Gadsden HS Monthly FE Inspection -<br>Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Joe Ontiveros<br>Fire Extinguishers     |           | Gadsden HS              |
| 10235 | Work In Progress<br>Monthly - Gadsden HS Emer. Light Test: Monthly -<br>Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 10238 | Work In Progress<br>Monthly - Gadsden HS Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 10194 | Work In Progress<br>Monthly - Gadsden HS Monthly FE Inspection -<br>Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Joe Ontiveros<br>Fire Extinguishers     |           | Gadsden HS              |
| 3319  | Work In Progress<br>Yearly - Gadsden HS Emer. Light Test: Annual -<br>Refer to PM schedule details.   | 7/6/2005<br>Medium                          | Alfredo Holguin<br>Joe Ontiveros<br>Fire Protection        |           | Gadsden HS              |
| 3141  | Work In Progress<br>Monthly - Gadsden HS Monthly FE Inspection -<br>Refer to PM schedule details.   | 7/3/2005<br>Medium                          | Alfredo Holguin<br>Joe Ontiveros<br>Fire Extinguishers     |           | Gadsden HS              |
| 10997 | Work In Progress<br>Monthly - Gadsden HS Emer. Light Test: Monthly -<br>Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 11000 | Work In Progress<br>Monthly - Gadsden HS Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 10934 | Work In Progress<br>Monthly - Gadsden HS Roof Inspection - Refer to<br>PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Mario Apodaca<br>Roof                   |           | Gadsden HS              |
| 10965 | Work In Progress<br>Monthly - Gadsden HS Fire Suppression Insp. -<br>Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System   |           | Gadsden HS              |
| 11186 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE<br>INSPECTIONS ON ALL CUSTODIANS TO INCLUDED<br>CLOSET, MSDS, LABELED SPRAY BOTTLES &<br>SAFETY EQUIPMENT. HEAD CUSTODIANS NEED<br>TO INCLUDE INSPECTION OF YOUR OWN AREA.<br>INSPECTION REPORTS ALONG WITH<br>COMPLETED WORK ORDER MUST BE RETURNED<br>AND RECEIVED BY US NO LATER THAN APRIL<br>21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Jesus Estrada<br>Custodial                 |           | Gadsden HS              |
| 7095  | Work In Progress<br>Monthly - Gadsden HS Emer. Light Test: Monthly -<br>Refer to PM schedule details.   | 11/6/2005<br>Medium                         | Alfredo Holguin<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 6001  | Work In Progress<br>Monthly - Gadsden HS Monthly FE Inspection -<br>Refer to PM schedule details.   | 10/2/2005<br>Medium                         | Alfredo Holguin<br>Joe Ontiveros<br>Fire Extinguishers     |           | Gadsden HS              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft  | Area Type       | Location<br>Area Number |
|-------|---|---|--|-----------------|-------------------------|
| 11248 | Work In Progress<br>please sweep the basketball courts by the weight room on 4-21-06 for special olympics   | 4/10/2006<br>Medium                         | Guadalupe Ontiveros<br>Guadalupe Ontiveros<br>Grounds                    |                 | Gadsden HS              |
| 10789 | Work In Progress<br>Grounds Shop - Need an electrical outlet installed outside of shop.   | 3/29/2006<br>Medium                         | Guadalupe Ontiveros<br>Michael Mc Dermott<br>Electrical                  |                 | Gadsden HS              |
| 3479  | Work In Progress<br>All Campus - Need to replace old door knobs w/new levers.   | 7/12/2005<br>Medium                         | Hector Lozoya<br>Manny Lozoya<br>Key and Lock                            |                 | Gadsden HS              |
| 7638  | Work In Progress<br>Girls BB Lockerroom - Connect Electric Water Heater.  | 11/29/2005<br>Medium                        | David Villalobos<br>Michael Mc Dermott<br>Electrical                     |                 | Gadsden HS              |
| 8932  | Work In Progress<br>MR.CASTILLO;When you have a chance please drop by ghs with two plug-in photocell 120v THANK YOU!!   | 1/20/2006<br>Medium                         | Fernando Moncayo<br>Carlos Castillo<br>Electrical                        |                 | Gadsden HS              |
| 10081 | Work In Progress<br>PRESCHOOL sink is clogged up, run small cable through,but no luck.please assist THANK YOU!!   | 2/28/2006<br>Medium                         | Fernando Moncayo<br>David Villalobos<br>Plumbing                         |                 | Gadsden HS              |
| 9959  | Work In Progress<br>ATTN.MR.LAZOYA;Key stuck and almost broken in NORTH side door at WEIGHTROOM.Need you a.s.a.p THANK YOU!!!                                   | 2/23/2006<br>Medium                         | Fernando Moncayo<br>Manny Lozoya<br>Key and Lock                         |                 | Gadsden HS              |
| 9147  | Work In Progress<br>Need a new metal door for BOY'S restroom in OLD ENGLISH 1st. floor. ASAP please,can't lock restroom to control vandalism THANK YOU!!        | 1/30/2006<br>Medium                         | Fernando Moncayo<br>Danny Miranda<br>Doors and Hardware                  | Restroom (Boys) | Gadsden HS              |
| 10428 | Work In Progress<br>AG Shop - Walk In Cooler needs refrigerant (freeon) as per Fernando needs it by next week.  | 3/10/2006<br>Medium                         | Fernando Moncayo<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |                 | Gadsden HS              |
| 10114 | Work In Progress<br>ATTN. DAVID VILLALOBOS;Need to replace two toilets and flanges in LIBRARY GIRL'S R. R.Also one toilet in MAIN GIRL'S R.R THANK YOU!!        | 3/1/2006<br>Medium                          | Fernando Moncayo<br>David Villalobos<br>Plumbing                         |                 | Gadsden HS              |
| 11523 | Work In Progress<br>Please check and replace all a/c contactors in ACADEMIC bldg;Some are burn and not making good contact                                      | 4/21/2006<br>Medium                         | Fernando Moncayo<br>Michael Mc Dermott<br>Electrical                     |                 | Gadsden HS              |
| 11439 | Work In Progress<br>Attn.MR.MIRA&ANDA,sliding door in room 106 storage won't open,please help THANK YOU!!!<br><br>Route to D. Miranda as per Mike 4/26/06 - mkv | 4/20/2006<br>Medium                         | Fernando Moncayo<br>Danny Miranda<br>Doors and Hardware                  |                 | Gadsden HS              |
| 4240  | Work In Progress<br>Need six wheels for large gates in NORTH parking lot THANK YOU!!<br>8/11 - Route to Ruben as per Mike                                       | 8/5/2005<br>Medium                          | Fernando Moncayo<br>Ruben Ronquillo<br>General Maintenance               |                 | Gadsden HS              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                       | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 4305  | Work In Progress<br>NORTH bus entrance gate keep falling, bottom rail all bend;Also needs new roller bearings for both gates thank you !!! [safety hazard]  | 8/8/2005<br>Medium                          | Fernando Moncayo<br>Michael Munoz<br>Fence Repair       |           | Gadsden HS              |
| 4311  | Work In Progress<br>PANTHER HUT porch entrance too dark security lighth doesn't work  | 8/8/2005<br>Medium                          | Fernando Moncayo<br>Fernando Moncayo<br>Electrical      |           | Gadsden HS              |
| 4902  | Work In Progress<br>AG BLDG entry door,won't open or lock key just turns;Also WOOD SHOP entry door new lock doesn't work  | 8/25/2005<br>Medium                         | Fernando Moncayo<br>Manny Lozoya<br>Key and Lock        |           | Gadsden HS              |
| 6607  | Work In Progress<br>LIBRARY EAST wall;There is a wall keyed hose bib that is leaking  | 10/20/2005<br>Medium                        | Fernando Moncayo<br>David Villalobos<br>Plumbing        |           | Gadsden HS              |
| 6609  | Work In Progress<br>Need to install flouresent lighth lamps in ANNEX CORRIDOR, is too dark  | 10/20/2005<br>Medium                        | Fernando Moncayo<br>Michael Mc Dermott<br>Electrical    |           | Gadsden HS              |
| 7301  | Work In Progress<br>BOY'S GYM SOUTH EAST exterior door need to be replace   | 11/11/2005<br>Medium                        | Fernando Moncayo<br>Danny Miranda<br>Doors and Hardware | Gym       | Gadsden HS              |
| 2630  | Work In Progress<br>06/08/05<br>Attn;MANNY LATOYA , need to change the lock cilinders to restrict the access to the VARSITY GYM due to been paint thank you!  | 6/8/2005<br>Medium                          | Fernando Moncayo<br>Manny Lozoya<br>Key and Lock        |           | Gadsden HS              |
| 3593  | Work In Progress<br>Need to repair or replace electrical conduit outside of CONCESSION STAND by GIRL'S GYM<br><br>Parent called regarding the outlets to the concession stand need status. Work Order has been placed along time ago needs to be repaired before next Saturday. | 7/15/2005<br>Medium                         | Fernando Moncayo<br>Michael Mc Dermott<br>Electrical    |           | Gadsden HS              |
| 2459  | Work In Progress<br>Attn. MANNY LOCKSMITH; Need to ck. storage cabinet in room 226 not locking  | 6/2/2005<br>Medium                          | Fernando Moncayo<br>Manny Lozoya<br>Key and Lock        |           | Gadsden HS              |
| 1973  | Work In Progress<br>Need to rerun conduit and wires to kitchen exhaust in PANTHER HUT HOMEC ROOM  | 5/16/2005<br>Medium                         | Fernando Moncayo<br>Michael Mc Dermott<br>Electrical    |           | Gadsden HS              |
| 11694 | Work In Progress<br>Need to connect [ electrical ] on new a/c at PRESS BOX THANKS!!!  | 4/27/2006<br>Medium                         | Fernando Moncayo<br>Michael Mc Dermott<br>Electrical    |           | Gadsden HS              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                         | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 8145  | Work In Progress<br>Several light pole around cafeteria area are out. Already change lamps but still not working, need to change ballasts.<br>As per Mike Munoz route to Mike Mc Dermott. 12/18/05-Cali ordered material (10) 100w MH Ballast and (10) 100 WMH Lamps.   | 12/15/2005<br>Medium                        | Carlos Castillo<br>Michael Mc Dermott<br>Electrical       |           | Gadsden HS              |
| 10372 | Work In Progress<br>On March 20, 21, and 22, the State Fire Marshal will be conducting a complete and thorough inspection of the new system; this entails checking every device in the system in all rooms and storage spaces. If you could please either have a complete set of keys for all rooms, storage and padlocks, or give me your permission to open any locks necessary to conduct this test it would be very much appreciated. I could pick them up this Friday. We will of course secure all sites as they are checked.<br><br>1. North Building: Office of vice prin., panther hut.<br>2. Academic Bldg: Office of vice prin, his storage. Choir storage. Dark room in yearbook class.<br>Custodial closets.<br>3. Main bldg: Office area, Vault will need to be open! Can we have a person with combination in the area that day?<br>Custodial closet, Old nurses office, Lab storage areas.<br>4. Old English: basement and other storage rooms were off master,<br>5. Nurses offices<br>6. Cafeteria: all storage areas in kitchen<br>7. Gyms: All coaches offices and storage areas<br>8. NROTC armory area. | 3/8/2006<br>Medium                          | Carlos Vigil<br>Manny Lozoya<br>Key and Lock              |           | Gadsden HS              |
| 11142 | Work In Progress<br>need to paint new double doors main building  | 4/6/2006<br>Medium                          | Danny Miranda<br>Fernando Moncayo<br>Painting             |           | Gadsden HS              |
| 11143 | Work In Progress<br>need to paint new door at old english boys r.r.   | 4/6/2006<br>Medium                          | Danny Miranda<br>Mario Apodaca<br>Painting                |           | Gadsden HS              |
| 2762  | Work In Progress<br>need to varnish 15 new doors  | 6/14/2005<br>Medium                         | Danny Miranda<br>Joe Ontiveros<br>Painting                |           | Gadsden HS              |
| 9596  | Work In Progress<br>PORTABLE NEXT TO NURSES OFFICE - NEED EMT PIPE AT CORNER OF BUILDING FOR COMPUTER DROPS. PLEASE CALL SILVER IN TECH FOR INFORMATION   | 2/10/2006<br>Medium                         | Cora Ramirez<br>Michael Mc Dermott<br>General Maintenance | Portables | Gadsden HS              |
| 9432  | Work In Progress<br>need to replace key switches with regular two pole switches.  | 2/6/2006<br>Medium                          | Carlos Castillo<br>Carlos Castillo<br>Electrical          | Classroom | Gadsden HS              |

| WOID | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type   | Location<br>Area Number |
|------|--|---|--|-------------|-------------------------|
| 8254 | Work In Progress<br>Need to replace return unit's disconnect   | 12/22/2005<br>Medium                        | Carlos Castillo<br>Carlos Castillo<br>Electrical         | Cafeteria   | Gadsden HS              |
| 2385 | Work In Progress<br>SWIMMING POOL (PUMP ROOM) - AS PER NM ENVIRONMENT DEPT. POOL REGULATIONS, PUBLIC POOLS AND GENERAL USE POOLS WILL HAVE AN EMERGENCY SHUT OFF SWITCH INSTALLED TO TURN OFF RECIRCULATING PUMP IN CASE OF AN EMERGENCY.  | 5/31/2005<br>Medium                         | Raul Sanchez<br>Michael Mc Dermott<br>Electrical         |             | Gadsden HS              |
| 1499 | Work In Progress<br>Irrigation Wells - Need Grounds to pick up old well column piping and dispose of it properly.  | 4/28/2005<br>Medium                         | Raul Sanchez<br>Lorenzo Hernandez<br>Grounds             |             | Gadsden HS              |
| 9172 | Work In Progress<br>GHS pool needs an emergency cut-off switch for circulating pump installed outside of pump room as per pool inspection 2005 report  | 1/30/2006<br>Medium                         | Raul Sanchez<br>Michael Mc Dermott<br>Electrical         | Parking Lot | Gadsden HS              |
| 8946 | Work In Progress<br>Requested by Ms. Lopez Rm. 605 Business Building-Replacement of school lock on the second floor of the Business Building elevator, due to it not being able to find an original key to open the Master Pad. Lock currently on the door.<br><br>Please contact Ms. Lopez for information regarding the type of lock to be placed on the door. | 1/23/2006<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |             | Gadsden HS              |
| 9093 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Two keys of HE203 are needed for Key Box; for Concession Stand at Football Field.  | 1/27/2006<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |             | Gadsden HS              |
| 9094 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Key broke inside cylinder, we need lock fixed and also, please complete Work Order # 4362. Five keys are needed of HE1 (Gym Key), three keys are now broken and need replacing.  | 1/27/2006<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |             | Gadsden HS              |
| 9098 | Work In Progress<br>Requested by Mr. Contaldo Observatory-Close and lubricate observatory dome as soon as possible.  | 1/27/2006<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |             | Gadsden HS              |
| 9099 | Work In Progress<br>Requested by Mr. Contaldo Observatory-Replace power cord going to white light bulbs on top, inside of dome.  | 1/27/2006<br>Medium                         | Velia Alarcon<br>Michael Mc Dermott<br>Electrical        |             | Gadsden HS              |
| 9100 | Work In Progress<br>Requested by Mr. Contaldo Observatory-Replace acciator switches.   | 1/27/2006<br>Medium                         | Velia Alarcon<br>Michael Mc Dermott<br>Electrical        |             | Gadsden HS              |

| WOID | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|------|---|---|--|-----------|-------------------------|
| 9101 | Work In Progress<br>Requested by Ms. Jacquez Rm. 752 Barracks-<br>Mount flags on wall.  | 1/27/2006<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 8687 | Work In Progress<br>Requested by Ms. Anderson Rm. 233 Panther<br>Hut-Ovens not working at all. First and third<br>ovens on the right side of kitchen, possibly a<br>problem with the outlets.   | 1/12/2006<br>Medium                         | Velia Alarcon<br>Danny Orozco<br>Food Services           |           | Gadsden HS              |
| 8688 | Work In Progress<br>Requested by Ms. Anderson Rm. 233 Panther<br>Hut-Dishwasher not pulling cleaner or rinse<br>products, only pulls sanitizer.   | 1/12/2006<br>Medium                         | Velia Alarcon<br>Danny Orozco<br>Food Services           |           | Gadsden HS              |
| 8689 | Work In Progress<br>Requested by Ms. Anderson Rm. 233 Panter Hut-<br>Mice in Panther Hut.   | 1/12/2006<br>Medium                         | Velia Alarcon<br>Margret Villalobos<br>Pest Control      |           | Gadsden HS              |
| 8691 | Work In Progress<br>Requested by Chief Arms Rifle Range/Adjacent<br>to Boys Gym-Rifle Range is coming loose in<br>numerous panels and range is no longer secure.<br>Recommend a permanent wall or welded metal<br>plating. Kids are using basketballs to break the<br>screens; also maintenance caught three kids in<br>the rifle range before break.<br><br>Note from Mr. Foster: THIS IS IMPORTANT!<br>Route to Bldg Mechanic as per Mike - 2/8/06 -mkv | 1/12/2006<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 8696 | Work In Progress<br>Requested by Mrs. Quinones Rm. 653 Busines<br>Building-Replace florescent light bulbs.<br>ROUTE TO BM AS PER M. MC DERMOTT  | 1/12/2006<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 8068 | Work In Progress<br>Requested by Mr. Chambers North Building<br>Project-Temporarily remove cable from North<br>Building Lockers by Saturday, Dec. 17. (For<br>Columbia University Film Documentary)   | 12/13/2005<br>Medium                        | Velia Alarcon<br>Michael Munoz<br>General Maintenance    |           | Gadsden HS              |
| 7913 | Work In Progress<br>Requested by Cathy Cano Concession Stand-<br>Windows to concession stand need to be put<br>back on. Reasons: cold, and too many flies<br>and/or bees.<br>Route to Bldg Mechanic as per Mike Munoz<br>12/16/05 - mkv   | 12/7/2005<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 7914 | Work In Progress<br>Requested by Ms. Hunt Rm. 105 Main Building-<br>Cupboard door broke off, screws on my desk.   | 12/7/2005<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 7915 | Work In Progress<br>Requested by Mr. Contaldo Campus Observatory-<br>Close hatch door on observatory, check out<br>electrical connection for motor drive and white<br>overhead lights.<br>route to Mike Mc Dermott - As per Mike Munoz<br>12/12/05 - mkv  | 12/7/2005<br>Medium                         | Velia Alarcon<br>Michael Mc Dermott<br>Electrical        |           | Gadsden HS              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft  | Area Type | Location<br>Area Number |
|-------|---|---|--|-----------|-------------------------|
| 7626  | Work In Progress<br>Requested by Mr. Foster and Mr. Chambers<br>Varsity Gym-ATTN: Mike Munoz Replace<br>heating units and duct work.<br>*Girls team practiced in 23 degrees this morning<br>in the gym.<br>*Parents calling and complaining about conditions.<br>*Parents calling Central Office.   | 11/29/2005<br>Medium                        | Velia Alarcon<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning | Gym       | Gadsden HS              |
| 8081  | Work In Progress<br>Requested by Ms. Trich Rm. 275 Library-Tops of<br>the short book shelves are losing the laminate,<br>which is peeling off. Please re-attach the<br>laminate tops. Please check with either Bonnie or<br>me.   | 12/13/2005<br>Medium                        | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance                 |           | Gadsden HS              |
| 8178  | Work In Progress<br>Requested by Mr. Contaldo Campus Observatory-<br>Fix or replace limiting switches on Observatory<br>hatch. Existing switches may (?) be fixed by<br>bending metal contact plates to correct position.<br>Key problem: need to be able to open and close<br>hatch. Replace or fix white light bulbs inside<br>Observatory.   | 12/16/2005<br>Medium                        | Velia Alarcon<br>Michael Mc Dermott<br>Electrical                        |           | Gadsden HS              |
| 8179  | Work In Progress<br>Requested by Mr. Contaldo Campus Observatory-<br>Install 6' chain link fence around Observatory<br>Deck with locking gate. Key problem: prevent<br>future vandalism.<br>1/11 - Route to Lupe as per Mike.   | 12/16/2005<br>Medium                        | Velia Alarcon<br>Guadalupe Ontiveros<br>Grounds                          |           | Gadsden HS              |
| 8182  | Work In Progress<br>Requested by L. Melendrez Rm. 333 Academic<br>Building-Classroom walls need to be repaired.<br>There are holes in the walls and it needs to be<br>repainted.  | 12/16/2005<br>Medium                        | Velia Alarcon<br>Mario Apodaca<br>General Maintenance                    |           | Gadsden HS              |
| 8185  | Work In Progress<br>Requested by Ms. Trich Library-The drawer<br>slides for the cashbox are loose. They may be<br>missing screws to attach them to the base. Might<br>someone please assess the situation to<br>determine if the present one can be repaired or if<br>they need replacement? Please check with<br>Leslie, this is a safety issue; the drawer may fall<br>out of the base. | 12/16/2005<br>Medium                        | Velia Alarcon<br>Mario Apodaca<br>General Maintenance                    |           | Gadsden HS              |
| 9972  | Work In Progress<br>Requested by Mr. D. Martinez North Building Main<br>Hallway-Some tiles in the main hallway are<br>damaged and are a hazard for parents, students,<br>and teachers.  | 2/24/2006<br>Medium                         | Velia Alarcon<br>Michael Munoz<br>Carpet Repair                          |           | Gadsden HS              |
| 10034 | Work In Progress<br>Requested by Mr. Grubaugh Rm. 275C Library-<br>Toilet in the boy's restroom won't quit flushing.  | 2/27/2006<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance                 |           | Gadsden HS              |



| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|-------|---|---|--|-----------|-------------------------|
| 10035 | Work In Progress<br>Requested by Mr. Palmer Rm. 229 North Building-<br>1.) Remove permanent desks that stick out into<br>room. (There's 7 of them.) 2.) Relocate the gas<br>and electrical outlets to the side counters. *Call<br>me before work begins so I can clean out stored<br>items. | 2/27/2006<br>Medium                         | Velia Alarcon<br>Michael Munoz<br>General Maintenance    |           | Gadsden HS              |
| 9823  | Work In Progress<br>Requested by Mr. Chambers All G.H.S. Buildings-<br>Paint all G.H.S. Buildings with maroon trim<br>(outside)-doors, windows, and flashing etc.   | 2/17/2006<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>Painting               |           | Gadsden HS              |
| 9824  | Work In Progress<br>Requested by Mr. Chambers Weightroom-Need<br>double doors at the Weightroom repaired to<br>protect new equipment. Need dead bolts with<br>keys installed on side doors (two way).   | 2/17/2006<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 9909  | Work In Progress<br>Requested by Dolores Nanez Library-Anchor<br>wall (partition) has glass window and shelves,<br>made of wood.  | 2/22/2006<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 9230  | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Ms.<br>Hamilton's classroom door does not want to lock,<br>she's in room # 562.   | 2/1/2006<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 9232  | Work In Progress<br>Requested by Jenny Gonzalez Rm. 250<br>Computer Lab-Light bulb needs to be replaced in<br>the Boys Restroom.  | 2/1/2006<br>Medium                          | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 9685  | Work In Progress<br>Requested by Ms. Foote Rm. 332 Academic<br>Building-Replace ceiling light bulbs.<br>ROUTE TO BM - AS PER MIKE 2/17/06   | 2/14/2006<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 9686  | Work In Progress<br>Requested by David Vega Business Building-<br>Light switch on north wall, bottom floor needs to<br>be replace.  | 2/14/2006<br>Medium                         | Velia Alarcon<br>Michael Mc Dermott<br>Electrical        |           | Gadsden HS              |
| 9688  | Work In Progress<br>Requested by David Vega Rm. 243 Classroom<br>Over Varsity Gym-Needs a few light bulbs<br>replaced, on one of the lights.<br>ROUTE TO BM - AS PER MIKE 2/17/06   | 2/14/2006<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 9451  | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Two<br>keys of HE25 are needed for Key Box; room 200,<br>Ms. A. Torres' classroom.  | 2/7/2006<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 11422 | Work In Progress<br>Requested by Ms. Leahy Rm. 215 North Building-<br>Windows need mini-blinds, windows need to be<br>measured to order the blinds.   | 4/19/2006<br>Medium                         | Velia Alarcon<br>Ruben Ronquillo<br>Glass\Window Repairs |           | Gadsden HS              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                       | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 11270 | Work In Progress<br>Requested Ms. Aragon Rm. 146 Old English Building-Air Ducts are blowing out dust and bugs since last spring, they might need to be cleaned.   | 4/11/2006<br>Medium                         | Velia Alarcon<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning   |           | Gadsden HS              |
| 11271 | Work In Progress<br>Requested by Dolores Nanez Library-Double doors at the Library entrance need oiling or greasing.  | 4/11/2006<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock                           |           | Gadsden HS              |
| 10521 | Work In Progress<br>Requested by Coach A. Lopez Softball Field- Replace light bulbs on score board.<br><br>*AS PER MR. FOSTER, PLEASE RUSH THIS.  | 3/15/2006<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance                |           | Gadsden HS              |
| 10522 | Work In Progress<br>Requested by Coach A. Lopez Softball Field- Paint dug outs maroon and trim gold.  | 3/15/2006<br>Medium                         | Velia Alarcon<br>Guadalupe Ontiveros<br>Painting                        |           | Gadsden HS              |
| 10524 | Work In Progress<br>Requested by Ms. L. Melendrez Rm. 333 Academic Building-This room needs to be painted this summer.  | 3/15/2006<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance                |           | Gadsden HS              |
| 10525 | Work In Progress<br>Requested by Ms. L. Melendrez Rm. 333 Academic Building-Replace the chalkboard (back of room), 1/3 of the board can't be used because their is glue all over it.  | 3/15/2006<br>3/15/2006<br>Medium            | Velia Alarcon<br>Mario Apodaca<br>General Maintenance                   |           | Gadsden HS              |
| 10526 | Work In Progress<br>Requested by Ms. Runyan Rm. 900 Nurse's Office-Requesting refridgerated air conditioner or cieling fans.<br>3/27 - As per Mike Munoz please route this work order thru Mr. Chambers. e-mailed Velia and Mr. Chambers on 3/27 - mkv<br>4/10 - As per Mike Faxed to Mr. Chavez for approval - mkv | 3/15/2006<br>Medium                         | Velia Alarcon<br>Michael Munoz<br>Heating/Ventilation /Air Conditioning |           | Gadsden HS              |
| 10573 | Work In Progress<br>Requested by Ms. Jordan Rm. 320 Academic Building-Has a light fixture with broken bulbs. It's been that way since October.  | 3/16/2006<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance                   |           | Gadsden HS              |
| 10574 | Work In Progress<br>Requested by Velia Rm. 109C Main Building- Replace light bulb in Women's Faculty Restroom.<br><br>*SECOND REQUEST   | 3/16/2006<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance                   |           | Gadsden HS              |
| 10796 | Work In Progress<br>Requested by Velia Old English Building-Fix hole on the wall of the 1st floor of the Old English Building, close to room # 128.<br><br>As Per Mr. Foster this needs to be fixed as soon as possible.  | 3/29/2006<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance                   |           | Gadsden HS              |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|-------|--|---|--|-----------|-------------------------|
| 10797 | Work In Progress<br>Requested by Velia Concession Stand by Girl's Gym-Change cylinder and four keys are needed for the door.   | 3/29/2006<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 10800 | Work In Progress<br>Requested by Ms. Moreno Rm. 126 Main Building- There is a water leak above my channel one monitor. The monitor was replaced, but the technician said that this one would be damaged as well if the leak was not fixed.                     | 3/29/2006<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>Roof                |           | Gadsden HS              |
| 10801 | Work In Progress<br>Requested by Mrs. Munoz Rm. 610 Business Building-Nine light bulbs need to be replaced.  | 3/29/2006<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 11162 | Work In Progress<br>Requested by Ms. V. Lopez Business Building- The assembly of 6 steel shelving units. These units are located in the "old Counseling Center."   | 4/6/2006<br>Medium                          | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 11163 | Work In Progress<br>Requested by Ms. D. Nanez Library-Change the time on the clock. Clock is about 13 feet high on the wall, a latter is needed.   | 4/6/2006<br>Medium                          | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 11165 | Work In Progress<br>Requested by Ms. Ulibarri-Klein Rm. 504 Annex Building-Remove switch on bottom of 3rd pole to back, but leave outlet active that is on top of pole. For questions call Sylvester the District Telecommunication Tech.                      | 4/6/2006<br>Medium                          | Velia Alarcon<br>Michael Mc Dermott<br>Electrical        |           | Gadsden HS              |
| 10877 | Work In Progress<br>Requested by Mr. Wall Rm. 346 Academic Building-Two window blinds are need for the windows. They're required for Lock Down Fire Drills.  | 3/31/2006<br>Medium                         | Velia Alarcon<br>Ruben Ronquillo<br>Glass\Window Repairs |           | Gadsden HS              |
| 10879 | Work In Progress<br>Requested by Velia for Rm. 140 Old English Building-FOURTH REQUEST-The blinds in the room are broken and do not work properly. This will help keep the sun out in the afternoon when the room gets "very hot". Blind measurements 44 x 90. | 3/31/2006<br>Medium                         | Velia Alarcon<br>Ruben Ronquillo<br>Glass\Window Repairs |           | Gadsden HS              |
| 10881 | Work In Progress<br>Requested by Mr. Gamboa Rm. 128 Old English Building-Blinds are needed for the windows, blind measurements 44 x 90, four sets are needed.  | 3/31/2006<br>Medium                         | Velia Alarcon<br>Ruben Ronquillo<br>Glass\Window Repairs |           | Gadsden HS              |
| 10885 | Work In Progress<br>Requested by Velia for the hallways in the Old English Building-Halls need to be painted.  | 3/31/2006<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>Painting               |           | Gadsden HS              |

| WOID | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|------|---|---|--|-----------|-------------------------|
| 4897 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Two HE27 are needed for key box.  | 8/25/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 5083 | Work In Progress<br>Requested by Mr. Martin Rm. 551 Wood Shop-Hall lock will no unlock, 2nd Notice.   | 8/30/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4905 | Work In Progress<br>Requested by Mr. Milligan Rm. 143 Old English Building-Four keys are needed of HX2. Three for the assistant coaches and one for key box.  | 8/25/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4627 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Work order #3911 was not asked to me made off master, also three keys were asked for not two. An additional 4 keys are needed as soon as possible.  | 8/17/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4810 | Work In Progress<br>Requested by Ms. L. Chavez Rm. 245 Classroom Over Varsity Gym-Re-place several burned out light bulbs.<br>RE-ROUTE TO BUILDING MECHANIC as per Mike Mc Dermott 9/19/05  | 8/23/2005<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 4811 | Work In Progress<br>Requested by Mr. Cordova Storage Room in Varsity Gym Stage-The door needs to be re-keyed to an off master key, light board room. 4 keys are needed.   | 8/23/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4812 | Work In Progress<br>Requested by Lt. Dickerson Rm. 202 North Building-His HEM key has broken, 3 HEM keys are needed. One for him and two for the key box.   | 8/23/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4814 | Work In Progress<br>Requested by Ms. Greene-Wall Rm. 505 Annex Building-Air conditioner still does not work. No air is coming out of vents, very hot. Wires hanging into light fixture and a piece of ceiling tile (broken) is in one of the air conditioning vents. (room was damaged over summer) | 8/23/2005<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 4816 | Work In Progress<br>Requested by Ms. L. Melendrez Rm. 331 Academic Building-I have been having trouble opening my front door for over a year, and now I am having trouble opening the back door. It's not my key it's the door handle and deadbolts. Both back doors are very difficult to open.    | 8/23/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4817 | Work In Progress<br>Requested by Mr. S. Perez Weight Room-Boys locker room door handle needs repair does not open. West side Weight Room door needs repairs does not lock.  | 8/23/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |

| WOID | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|------|---|---|--|-----------|-------------------------|
| 4820 | Work In Progress<br>Requested by Luis Saucedo Rm. 507 & 509 Annex Building-Install door stops on each of these doors.   | 8/23/2005<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 4822 | Work In Progress<br>Requested by Ms. Zapien Rm. 154 Old English Building-The blinds are completely broken, the curtain is hanging.  | 8/23/2005<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 4429 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Three HE keys are needed for Key Box.   | 8/10/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4521 | Work In Progress<br>Requested by Ms. Greene-Wall Rm. 505 Annex Building-Need a lock and spare keys on the new filing cabinet.   | 8/12/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4630 | Work In Progress<br>Requested by Mr. Dixon Rm. 600 Business Building-Needs an F3 gate key.  | 8/17/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4631 | Work In Progress<br>Requested by Ms. M. Gonzalez Rm. 140 Old English Building-I would like to request a door stop for the new door and blinds fo one of my windows. The room gets "very" warm especially 4th period.<br>Receive measurements from Bldg Mechanic and re-route to Ruben for ordering.<br>4 ea - 43" W x 90' L | 8/17/2005<br>9/16/2005<br>Medium            | Velia Alarcon<br>Ruben Ronquillo<br>General Maintenance  |           | Gadsden HS              |
| 4633 | Work In Progress<br>Requested by ISS Rm. 800 Old Counseling Center-Door frame falling off portable door leading to the old counseling center.   | 8/17/2005<br>Medium                         | Velia Alarcon<br>Danny Miranda<br>Doors and Hardware     |           | Gadsden HS              |
| 4562 | Work In Progress<br>Requested by Ms. Klein Rm. 504 Annex Building-Air conditioner not working and appears to be leaking.  | 8/15/2005<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 4564 | Work In Progress<br>Requested by Ms. Nanez Library-Install plywood baks to magazine shelves.  | 8/15/2005<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 4516 | Work In Progress<br>Requested by Ms. Anderson Rm. 233 Panther Hut-New water heater for kitchen area of Panther Hut.<br>Route to Bldg Mechanic as per Mike 8/15/05<br>Check to see whats wrong with the H2o heater they have new one in small mech. room.  | 8/12/2005<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>Plumbing            |           | Gadsden HS              |
| 4166 | Work In Progress<br>Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace ceiling tile in storeroom and office.  | 8/3/2005<br>Medium                          | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |

| WOID | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|------|--|---|--|-----------|-------------------------|
| 4199 | Work In Progress<br>Requested by Mr. Chambers Rm. 110 Front Office-Re-key doors, make cylinders off D Master, 4 keys will be needed. Have had several items stolen from office, please re-key as soon as possible. | 8/4/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4204 | Work In Progress<br>Requested by Cathy Cano Parking Lot-Over Fall Break, have the lines in the North Parking Lot painted.  | 8/4/2005<br>Medium                          | Velia Alarcon<br>Michael Munoz<br>Painting               |           | Gadsden HS              |
| 4269 | Work In Progress<br>Requested by Ms. Jacquez Rm. 752 Barracks-Window is unhinged and needs to be repaired.   | 8/8/2005<br>Medium                          | Velia Alarcon<br>Ruben Ronquillo<br>Glass\Window Repairs |           | Gadsden HS              |
| 4271 | Work In Progress<br>Requested by Ms. Kalkwarf Rm. 750 Barracks-Floor tiles are broken and coming off the floor.  | 8/8/2005<br>Medium                          | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 4272 | Work In Progress<br>Requested by Ms. Klein Rm. 504 Annex Building-Having a hard time locking and opening door, appears to be locked but stays unlocked.  | 8/8/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4279 | Work In Progress<br>Requested by Ms. Littlefield Rm. 226 North Building-The lock on my podium and one storage cabinet is brocken and lost.   | 8/8/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4282 | Work In Progress<br>Requested by Mr. Martinez Rm. 227 North Building-Replace carpet in Attendance Office area. One edge of the carpet is lifting, our concern is that a person may trip and fall.                  | 8/8/2005<br>Medium                          | Velia Alarcon<br>Michael Munoz<br>Carpet Repair          |           | Gadsden HS              |
| 4283 | Work In Progress<br>Requested by Mr. Myers Rm. 509 Annex Building-Key will not open storage door. HJ10 is the key that should open door.   | 8/8/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4285 | Work In Progress<br>Requested by Mr. Villa Rm. 510 Band Room-Security light in the center of the room does not work.   | 8/8/2005<br>Medium                          | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 4286 | Work In Progress<br>Requested by Mr. Villa Rm. 510 Band Room-Need two HK13 keys made.  | 8/8/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4386 | Work In Progress<br>Requested by Mr. Whitener Rm. 566 Ag. Shop-220 Volt Electric extension cord needed with a new female end, current ones puts people at risk of electrocution.                                   | 8/9/2005<br>Medium                          | Velia Alarcon<br>Michael Mc Dermott<br>Electrical        |           | Gadsden HS              |

| WOID | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|------|--|---|--|-----------|-------------------------|
| 4153 | Work In Progress<br>Requested by Mary Barreras Rm. 130 Old English Building-Need the new key to new lock to Sp. Ed. storage room for files and equipment. Key # M260   | 8/3/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4243 | Work In Progress<br>Requested by Ms. Bradley Rm. 602 Business Building-Handle on window has broken off, needs to be replaced.  | 8/5/2005<br>Medium                          | Velia Alarcon<br>Mario Apodaca<br>Glass\Window Repairs   |           | Gadsden HS              |
| 4248 | Work In Progress<br>Requested by Ms. Gutierrez Rm. 823 Barracks-New cylinder is needed for new filing cabinet, 3 keys are needed.  | 8/5/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4360 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HJ7, one for the floating teacher and one for the Key Box. For room number 753.  | 8/9/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4361 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK1, one for the floating teacher and one for the Key Box. For the Auto Shop.  | 8/9/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4362 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-We need 5 additional keys of HE1. For the Gyms.  | 8/9/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 4363 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK5, one for the I.A. in the classroom and one for the key box. For room number 569.   | 8/9/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 3902 | Work In Progress<br>Requested by Ms. Marquez New Counseling Portable-Two filing cabinets need to be keyed.   | 7/28/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 3910 | Work In Progress<br>Requested by Isela Martinez New Counseling Center Portable-Bracket needed for N.M. Flag.   | 7/28/2005<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 3920 | Work In Progress<br>Requested by Velia Front Office-The cylinder for room #107 will not open with a D Master or key assigned to door. This classroom is the Day Care on our campus and the building custodian can not open the classroom to clean. Please fix as soon as possible. | 7/28/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 6282 | Work In Progress<br>Requested by Mr. Donaldson Rm. 554 Woodshop-Paint (or provide paint)for repainting the tool room and paint room. Second Request  | 10/11/2005<br>Medium                        | Velia Alarcon<br>Mario Apodaca<br>Painting               |           | Gadsden HS              |

| WOID | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|------|--|---|--|-----------|-------------------------|
| 6454 | Work In Progress<br>Requested by Mr. Chambers Football Restrooms-<br>Paint large letters on restroom indicating men's<br>and women's sides, or hang large signs<br>indicating directions.  | 10/17/2005<br>Medium                        | Velia Alarcon<br>Fernando Moncayo<br>Painting            |           | Gadsden HS              |
| 6460 | Work In Progress<br>Requested by Mr. Whitener Rm. 563 Ag. Shop-<br>Install a hydraulic door closer on the new front<br>door to the building.   | 10/17/2005<br>Medium                        | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 6830 | Work In Progress<br>Requested by Velia Rm. 127 Main Building-When<br>the sound system contractors installed the wiring<br>in Ms. Garcia's classroom. They placed it on a<br>wall Ms. Garcia used for her projector. Once<br>they removed the wiring and placed it on another<br>wall, they left the wall scrated and paint peeled.<br>Wall needs to be repaired and painted. | 10/28/2005<br>Medium                        | Velia Alarcon<br>Fernando Moncayo<br>Painting            |           | Gadsden HS              |
| 6710 | Work In Progress<br>Requested Ms. Nanez Library-Backs to shelves<br>need to be installed. Backs are in library,<br>however, they need to be cut down to fit.   | 10/25/2005<br>Medium                        | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 6713 | Work In Progress<br>Requested by Ms. Trich Library-Please replace<br>blown light bulbs, especially in Librarian's office,<br>room 275b.  | 10/25/2005<br>Medium                        | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 7370 | Work In Progress<br>Requested by Mr. Donaldson Rm. 554 Wood<br>Shop- 2ND REQUEST Replace ceiling tile in office<br>storeroom. Consider placing a plywood floor<br>over unprotected tile.   | 11/15/2005<br>Medium                        | Velia Alarcon<br>Michael Munoz<br>General Maintenance    |           | Gadsden HS              |
| 7145 | Work In Progress<br>Requested by Ms. V. Lopez Old Counseling<br>Center-Repair hole in ceiling near new ventilation<br>work.  | 11/7/2005<br>Medium                         | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |           | Gadsden HS              |
| 5405 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-HG3 is<br>needed for key box.  | 9/12/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 5406 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Two<br>SA16 are needed, one for Ms. Dominguez and<br>one for key box.  | 9/12/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 5407 | Work In Progress<br>Requested by Marie School Registrar Storage<br>Room East Wing of the Cafeteria-The new vault<br>needs to be re-keyed. The cylinder from the old<br>vault can be placed on the door of the East Wing<br>of the Cafeteria were her new vault is located<br>now.  | 9/12/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |



| WOID | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                 | Area Type | Location<br>Area Number |
|------|---|---|---|-----------|-------------------------|
| 5409 | Work In Progress<br>Requested by Marie Storage Room in the East Wing of the Cafeteria-In the move from the old vault to the storage room one of the fire prove filing cabinet's locks broke. The filing cabinet remained locked, needs to be fixed as soon as possible as the Registrar needs access to these files on a daily basis. | 9/12/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock     |           | Gadsden HS              |
| 2530 | Work In Progress<br>Requested by Mr. Chambers Rm. 110 Front Office-Need a 6 and 7 point keys to open classrooms, storerooms, etc. for construction people at G.H.S., one key of each.   | 6/6/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock     |           | Gadsden HS              |
| 2745 | Work In Progress<br>Requested by Velia-In room 505 of the Annex Building there's a storage room that the contractors of Lynco Electric need access to. We do not have a key for the deadbolt on that door, needs to be opened as soon as possible for them.   | 6/13/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock     |           | Gadsden HS              |
| 2698 | Work In Progress<br>Requested by Marie Acosta Rm. 803 Old Counseling Center-Re-key vault in Old Counseling Center. Needs to be off master, 5 keys are needed.   | 6/10/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock     |           | Gadsden HS              |
| 2699 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Fix or re-place light bulbs on posts where Juan Diaz' mobile home is located. Where D.P.A. was located on our campus before, extremely dark at night.   | 6/10/2005<br>Medium                         | Velia Alarcon<br>Michael Mc Dermott<br>Electrical |           | Gadsden HS              |
| 2700 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Have one HE200 re-cut, key does not open room. (Weight Room)  | 6/10/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock     |           | Gadsden HS              |
| 2701 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-Have three HE87 re-cut, keys do not open room. (Training Room)  | 6/10/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock     |           | Gadsden HS              |
| 2471 | Work In Progress<br>Requested by Ms. Lopez Rm. 805 Counseling Center-Re-Key room 805 (both doors) to a D106, two keys are needed.   | 6/2/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock     |           | Gadsden HS              |
| 2578 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-We need two additional keys of HH6, downstairs Social Workers Office in Old English Building.   | 6/7/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock     |           | Gadsden HS              |

| WOID | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|------|--|---|--|-----------|-------------------------|
| 2579 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-We need three additional keys of HE200 (Weight Room).  | 6/7/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 2580 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-We need three additional keys of HE131 (my office).  | 6/7/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 2581 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-We need five additional keys of DC17 (Swimming Pool).  | 6/7/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 2582 | Work In Progress<br>Requested by Velia Rm. 112 Front Office- We need two additional keys of HH9, upstairs Social Workers Office in Old English Building.   | 6/7/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 2583 | Work In Progress<br>Requested by Velia Rm. 112 Front Office-We need one additional key of HH7, for I.A. in Ms. Axtell's classroom.   | 6/7/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 2584 | Work In Progress<br>Requested by Isela Rm. 800 Counseling Center- Paint office and doors.  | 6/7/2005<br>Medium                          | Velia Alarcon<br>Joe Ontiveros<br>Painting               |           | Gadsden HS              |
| 3494 | Work In Progress<br>Requested by Marie New Counseling Center Portable-New portable needs to be keyed HE134. Change old cylinder to doors of new portable doors.  | 7/12/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 3715 | Work In Progress<br>Requested by Mr. Pawloski Rm. 109A Main Building (Sp.Ed. Office)-Please remove the lock in my file cabinet, replace, and re-key it with a new one.   | 7/20/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 3716 | Work In Progress<br>***URGENT***Requested by Velia Library-All the doors in the library need to be secured. They have changed all the door knobs and the cylinders need to be installed. URGENT library has alot of equipment that needs to me locked and secured! | 7/20/2005<br>Medium                         | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 893  | Work In Progress<br>Requested by Mr. Contaldo Rm 103-Paint outside of observatory using white oil-based paint.   | 4/6/2005<br>Medium                          | Velia Alarcon<br>Joe Ontiveros<br>Painting               |           | Gadsden HS              |
| 727  | Work In Progress<br>Requested by Mr. Haack, Rm 127 Main Building- Window was broken on 3/30/05.  | 3/31/2005<br>Medium                         | Velia Alarcon<br>Ruben Ronquillo<br>Glass\Window Repairs | Classroom | Gadsden HS              |

| WOID | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|------|--|---|--|-----------|-------------------------|
| 447  | Work In Progress<br>Requested by Mr. D. Martinez Rm 227C North Building-Replace windows in the Assistant Principal's Office. The windows that are there currently are painted shut.  | 3/16/2005<br>Medium                         | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |           | Gadsden HS              |
| 448  | Work In Progress<br>Requested by Mr. D. Martinez Outside of North Building-Have electrical outlets placed outside the North Building in the shaded area for the candy/snack machines.<br>THIS WO WAS REROUTED TO MIKE MC DERMOTT AS PER MIKE MUNOZ - CC 9/21/05  | 3/16/2005<br>Medium                         | Velia Alarcon<br>Michael Mc Dermott<br>Electrical        |           | Gadsden HS              |
| 450  | Work In Progress<br>Requested by Mr. D. Martinez main hallway in North Building-Move the snack machines from the main hallway to the shaded area outside, once the electrical outlets have been placed.<br>Need to run new outlets for snack machines - reassign to Dist. Electrician - as per Mario Apodaca 8/23/05 - mkv | 3/16/2005<br>Medium                         | Velia Alarcon<br>Michael Mc Dermott<br>Electrical        |           | Gadsden HS              |
| 345  | Work In Progress<br>The gate on the south side of the school was hit over the weekend. We're unable to close gate, we need this repaired as soon as possible.  | 3/14/2005<br>Medium                         | Velia Alarcon<br>Joe Ontiveros<br>General Maintenance    |           | Gadsden HS              |
| 316  | Work In Progress<br>Requested by Mr. Donaldson Rm 554 Wood Shop-1. Install heavier electric circuit for operation of drum sander. 2. Re-route machine wiring (belt/disc., sander, etc.) through safety kill switch.  | 3/11/2005<br>Medium                         | Velia Alarcon<br>Carlos Castillo<br>Electrical           | Classroom | Gadsden HS              |
| 321  | Work In Progress<br>Requested by Mr. J. Gonzales Rm 300 Academic Building-No power on south wall of classroom. as per BM reset breaker after power outage.   | 3/11/2005<br>5/18/2005<br>Medium            | Velia Alarcon<br>Fernando Moncayo<br>Electrical          | Classroom | Gadsden HS              |
| 179  | Work In Progress<br>Requested by Ms. M. Gonzalez, Rm 140 Old English Building-Third Request-The blinds in my room are broken and do not work properly. This will help keep the sun out in the afternoon when the roon gets "very hot".<br>Mario took a look at them, class will need 4 set of blinds measurements 44 X 90  | 3/8/2005<br>Medium                          | Velia Alarcon<br>Ruben Ronquillo<br>Glass\Window Repairs | Classroom | Gadsden HS              |
| 185  | Work In Progress<br>Requested by Mr. Martin, Rm 551 Wood Shop-Broken Window  | 3/8/2005<br>Medium                          | Velia Alarcon<br>Ruben Ronquillo<br>Glass\Window Repairs |           | Gadsden HS              |
| 1019 | Work In Progress<br>Requested by Ms. Moreno Rm. 126 Main Building-Put blinds on the windows.   | 4/11/2005<br>Medium                         | Velia Alarcon<br>Ruben Ronquillo<br>General Maintenance  | Classroom | Gadsden HS              |
| 1159 | Work In Progress<br>Requested by Ms. M. Garcia Rm 752 Barracks-Blinds needed on one window (45 x 60). Fire hazard, covered with paper. Special Ed. classroom   | 4/14/2005<br>Medium                         | Velia Alarcon<br>Ruben Ronquillo<br>General Maintenance  | Classroom | Gadsden HS              |

| WOID | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|------|---|---|--|-----------|-------------------------|
| 1179 | Work In Progress<br>Requested by Velia Rm 113 & 114 Main Building (Front Office)-We need the windows replaced in the men and women bathrooms, we're unable to open or close windows properly.   | 4/15/2005<br>Medium                         | Velia Alarcon<br>Ruben Ronquillo<br>Glass\Window Repairs |           | Gadsden HS<br>PATIO     |
| 1638 | Work In Progress<br>Requested by Ms. Jordan Rm. 320 Academic Building-Lights blown out.   | 5/4/2005<br>Medium                          | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance | Classroom | Gadsden HS              |
| 1640 | Work In Progress<br>Requested by Mr. Whitener Rm. 563 Ag. Shop-Needed: one 25 foot extension cord made for the arc welding machines.<br><br>Also, repair the female ends on 3 existing extension cords.   | 5/4/2005<br>Medium                          | Velia Alarcon<br>Michael Mc Dermott<br>Electrical        |           | Gadsden HS              |
| 1641 | Work In Progress<br>Requested by Mr. Whitener Rm. 566 Ag. Shop-The oil pressure gauge on the air compressor is broken and drips crankcase oil onto the floor. It also has an air leak on the small copper tubing on the compressor which causes it to turn on frequently. | 5/4/2005<br>Medium                          | Velia Alarcon<br>Joe Ontiveros<br>General Maintenance    |           | Gadsden HS              |
| 1642 | Work In Progress<br>Requested by Mr. Whitener Rm. 566 Ag. Shop-The door lock on the south shop door (emergency exit) is very difficult to lock and unlock.  | 5/4/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 1527 | Work In Progress<br>Requested by Mr. A. Perez Rm. 550 Wood Shop Building-Paint entry door; in order to avoid tagging. Adjust gap between door.  | 4/29/2005<br>Medium                         | Velia Alarcon<br>Joe Ontiveros<br>Painting               |           | Gadsden HS              |
| 1489 | Work In Progress<br>Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace broken ceiling tile and install plank roof over office and storeroom.  | 4/28/2005<br>Medium                         | Velia Alarcon<br>Joe Ontiveros<br>General Maintenance    | Classroom | Gadsden HS              |
| 2467 | Work In Progress<br>Requested by Velia Front Office-Five additional keys needed of the M master key.  | 6/2/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 2469 | Work In Progress<br>Requested by Ms. Lopez Counseling Center-1. Re-key rooms 804, 806, 808, 809 (room 809 has two doors, both doors need to be re-keyed) to an off master key. Needed to store testing materials and is a security issue. Four keys are needed.           | 6/2/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |           | Gadsden HS              |
| 2436 | Work In Progress<br>Requested by Maria Perez Rm. 228 North Building-Have the small brown filing cabinet re-keyed. 3 keys are needed.  | 6/2/2005<br>Medium                          | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            | Office    | Gadsden HS              |

| <b>WOID</b> | <b>Status<br/>Description<br/>Action Taken</b>   | <b>Request Date<br/>Completion Date<br/>Priority</b> | <b>Requester<br/>Assigned To<br/>Craft</b>               | <b>Area Type</b> | <b>Location<br/>Area Number</b>    |
|-------------|--|--|--|------------------|------------------------------------|
| 2437        | Work In Progress<br>Requested by Cathy Rm. 115 Front Office-Need<br>3 name plates with Cathryn Cano  | 6/2/2005<br>Medium                                   | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            | Office           | Gadsden HS                         |
| 2441        | Work In Progress<br>Requested by Ms. Lopez Rooms 802-809<br>Counseling Center-Remove carpet from all rooms.<br>As per Mike route to Bldg Mechanic 6/10/05 - mkv  | 6/2/2005<br>Medium                                   | Velia Alarcon<br>Joe Ontiveros<br>General Maintenance    |                  | Gadsden HS                         |
| 1569        | Work In Progress<br>Requested by Fernando Moncayo Varsity Gym-<br>Broken glass in basketball locker room.  | 5/2/2005<br>Medium                                   | Velia Alarcon<br>Ruben Ronquillo<br>Glass\Window Repairs |                  | Gadsden HS                         |
| 1680        | Work In Progress<br>Requested by Mr. Chambers Rm. 317 Academic<br>Building-Install a combination lock in the mail room<br>in the Academic Building.  | 5/5/2005<br>Medium                                   | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |                  | Gadsden HS                         |
| 11644       | Work In Progress<br>Requested by Velia-Mr. S. Alvarado's HX2 key<br>does not open his basketball office. Key needs to<br>be corrected before summer time when he has<br>summer basketball practice begins. | 4/26/2006<br>Medium                                  | Velia Alarcon<br>Manny Lozoya<br>Key and Lock            |                  | Gadsden HS                         |
| 11645       | Work In Progress<br>Requested by Velia for Upstairs hallway of<br>Business Building-Several light bulbs are burned<br>out and need replacing.  | 4/26/2006<br>Medium                                  | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |                  | Gadsden HS                         |
| 11646       | Work In Progress<br>Requested by Velia for New Counseling Center<br>Portable-On Marie's and Isela's side of the<br>portable, several light bulbs are out and need<br>replacing.                            | 4/26/2006<br>Medium                                  | Velia Alarcon<br>Fernando Moncayo<br>General Maintenance |                  | Gadsden HS                         |
| 11654       | Work In Progress<br>Requested by Mr. Whitener Rm. 563 Ag. Shop-<br>Two hallway lights are not working.   | 4/26/2006<br>Medium                                  | Velia Alarcon<br>Mario Apodaca<br>General Maintenance    |                  | Gadsden HS                         |
| 11655       | Work In Progress<br>Requested by Mrs. Ulibarri-klein Rm. 504 Annex<br>Building-Need to repair electrical outlets on NE<br>wall.  | 4/26/2006<br>Medium                                  | Velia Alarcon<br>Michael Mc Dermott<br>Electrical        |                  | Gadsden HS                         |
| 10291       | Work In Progress<br>please repair the concession stand and order<br>material for windows and door.(girls softball feild)<br>Thanks   | 3/6/2006<br>Medium                                   | Michael Munoz<br>Gerardo Marquez<br>General Maintenance  | Athletic Field   | Gadsden HS                         |
| 8844        | Work In Progress<br>AS PER MR. CHAVEZ OVER AT THE GHS<br>ACADEMIC BUILDING BOYS RESTROOM ON THE<br>WEST SIDE NEEDS A PARTION BETWEEN<br>HANDICAP & REGULAR TOILET.   | 1/18/2006<br>Medium                                  | Mary Garcia<br>Danny Miranda<br>Doors and Hardware       | Restroom (Boys)  | Gadsden HS<br>GHS ACADEMIC<br>BLDG |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft  | Area Type        | Location<br>Area Number                  |
|-------|--|---|--|------------------|--|
| 1393  | Work In Progress<br>BASEBALL & SOFTBALL DUGOUT AREA - NEED<br>(3) HOLLOW METAL DOORS WITH HOLLOW<br>METAL FRAMES (3'0" X 6'8") FOR STORAGE<br>ROOMS.   | 4/25/2005<br>Medium                         | Lorenzo Hernandez<br>Danny Miranda<br>Doors and Hardware                 | Athletic Field   | Gadsden HS                               |
| 1394  | Work In Progress<br>GROUNDS SHOP - NEED TO RESTOCK FIRST AID<br>KIT.   | 4/25/2005<br>Medium                         | Lorenzo Hernandez<br>Ruben Ronquillo<br>General Maintenance              |                  | Gadsden HS                               |
| 11551 | Work In Progress<br>BROKEN GLASS WINDOW AT V-GYM BOY<br>LOCKEROOM 239 20X40 VANDALISM  | 4/24/2006<br>Medium                         | Mario Apodaca<br>Ruben Ronquillo<br>Glass\Window Repairs                 |                  | Gadsden HS                               |
| 11484 | Work In Progress<br>NEED A 12 INCH MASTE COOL MEDIA FOR 6500<br>COOLER AT KITCHEN  | 4/21/2006<br>Medium                         | Mario Apodaca<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning |                  | Gadsden HS                               |
| 11257 | Work In Progress<br>NEED NEW LAMPS COVER FOR NORTH BLDG  | 4/10/2006<br>Medium                         | Mario Apodaca<br>Michael Mc Dermott<br>Electrical                        |                  | Gadsden HS                               |
| 10138 | Work In Progress<br>NEED TO PUT A NEW TOILE FLANGE AT N-BLDG<br>GIRLS RESTROOM   | 3/2/2006<br>Medium                          | Mario Apodaca<br>David Villalobos<br>Plumbing                            |                  | Gadsden HS                               |
| 10580 | Work In Progress<br>BROKEN WINDOW GLASS AT ANNEX BLDG<br>DOOR 30X30 VANDALISM  | 3/16/2006<br>Medium                         | Mario Apodaca<br>Ruben Ronquillo<br>Glass\Window Repairs                 |                  | Gadsden HS                               |
| 10816 | Work In Progress<br>NEED TO PUT A NEW WAX RING KITCHEN<br>WOMEM RESTROOM TOILET . ASAP   | 3/29/2006<br>Medium                         | Mario Apodaca<br>David Villalobos<br>Plumbing                            |                  | Gadsden HS                               |
| 10766 | Work In Progress<br>NEED TO PUT NEW FLOOR TILE AT V-GYM<br>GIRLS LOCK ROOM   | 3/28/2006<br>Medium                         | Mario Apodaca<br>Michael Munoz<br>Carpet Repair                          | Restroom (Girls) | Gadsden HS                               |
| 8582  | Work In Progress<br>NEED NEW E/COOLER AND DUCTING FOR BOY<br>GYM   | 1/9/2006<br>Medium                          | Mario Apodaca<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning |                  | Gadsden HS                               |
| 8714  | Work In Progress<br>NEED A NEW E/COOLER AT FOOTBALL FIELD<br>PRESS BOX<br><br>REPLACE UNIT FOR A M/C 6500 UPFLOW WITH<br>DUCTWORK, SIZE WAS INSTALLED BECAUSE<br>INSTALLED A DUCT WORK 20X20X90. 1HP<br>MOTOR INSTEAD OF 1/3 HP MOTOR. | 1/12/2006<br>Medium                         | Mario Apodaca<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning | Football Field   | Gadsden HS<br>New Equip.<br>Installation |
| 7886  | Work In Progress<br>NEED TO REPAIR ALL DOOR FRAMS AT THE<br>WEIGHT ROOM THE KID WILL PULL THE DOOR<br>OPEN W/THE DOOR ARE LOCK   | 12/6/2005<br>Medium                         | Mario Apodaca<br>Danny Miranda<br>Doors and Hardware                     |                  | Gadsden HS                               |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type       | Location<br>Area Number |
|-------|--|---|--|-----------------|-------------------------|
| 7956  | Work In Progress<br>Vandalism - Damage to south front entrance roll gate hit by vehicle.<br>(Case# 2005-10383) Deputy Isidro Gonzalez #935 | 12/2/2005<br>Medium                         | Mario Apodaca<br>Michael Munoz<br>Fence Repair           |                 | Gadsden HS              |
| 9696  | Work In Progress<br>NEED #5 FIRE EXTINGUISHER CABINETS FOR THE N/BLDG 10 LB DRY CHEMICAL SURFACEMOUNT                                      | 2/14/2006<br>Medium                         | Mario Apodaca<br>Danny Orozco<br>Fire Extinguishers      |                 | Gadsden HS              |
| 10007 | Work In Progress<br>ROOF LEAK AT NEW RESTROOM BOY SIDE AT FOOTBALL FIELD   | 2/24/2006<br>Medium                         | Mario Apodaca<br>David Boyd<br>Construction              | Football Field  | Gadsden HS<br>Roof      |
| 9266  | Work In Progress<br>NEED TOW LACK FOR CONCESSION STAND AT FOOTBALL FIELD   | 2/2/2006<br>Medium                          | Mario Apodaca<br>Manny Lozoya<br>Key and Lock            |                 | Gadsden HS              |
| 133   | Work In Progress<br>NEED NEW STAIR VINYL STRIP FOR MAIN GOING UP TO OLD/ENG  | 3/7/2005<br>Medium                          | Mario Apodaca<br>Michael Munoz<br>General Maintenance    | Stairway        | Gadsden HS              |
| 264   | Work In Progress<br>NEED A METAL DOOR FOR BOY RESTROOM AT N-BLDG - ONE DOOR  | 3/10/2005<br>Medium                         | Mario Apodaca<br>Danny Miranda<br>Doors and Hardware     | Restroom (Boys) | Gadsden HS              |
| 3524  | Work In Progress<br>NEED TO FIX FOOTBALL FIELD SCOREBOARD BREAKER BOX  | 7/14/2005<br>Medium                         | Mario Apodaca<br>Michael Mc Dermott<br>Electrical        |                 | Gadsden HS              |
| 3525  | Work In Progress<br>NEED TO CK ALL FOOTBALL FIELD LAMPS  | 7/14/2005<br>Medium                         | Mario Apodaca<br>Michael Mc Dermott<br>Electrical        |                 | Gadsden HS              |
| 5108  | Work In Progress<br>NEED TO PUT NEW BALLAST AT WOOD SHOP LAMPES  | 8/31/2005<br>Medium                         | Mario Apodaca<br>Michael Mc Dermott<br>Electrical        |                 | Gadsden HS              |
| 5842  | Work In Progress<br>NEED A NEW GLASS PUT ON CONCESSION STAND WINDOW AT FOOTBALL FIELD (VANDALISM) 23X23 ASAP                               | 9/26/2005<br>Medium                         | Mario Apodaca<br>Ruben Ronquillo<br>Glass\Window Repairs |                 | Gadsden HS              |
| 6526  | Work In Progress<br>NEED TOO RUN SEWER SNAKE AT WOOD SHOP BLDG<br>unclog main sewer line to woodshop                                       | 10/18/2005<br>10/19/2005<br>Medium          | Mario Apodaca<br>David Villalobos<br>Plumbing            |                 | Gadsden HS              |
| 6425  | Work In Progress<br>NEED TO REMOVE ALL OUTLET AT ROOM 126 AT ARE ON BOOK SHEVING FLOOR AND RELOCA OUTLETS                                  | 10/14/2005<br>Medium                        | Mario Apodaca<br>Michael Mc Dermott<br>Electrical        | Custodial       | Gadsden HS              |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft  | Area Type   | Location<br>Area Number |
|-------|--|---|--|-------------|-------------------------|
| 4502  | Work In Progress<br>NEED TO LAMPES AT WOOD SHOP SAME ARE<br>BURNED OUT   | 8/11/2005<br>Medium                         | Mario Apodaca<br>Michael Mc Dermott<br>Electrical                        |             | Gadsden HS              |
| 4970  | Work In Progress<br>GLASS AT MAIN BLDG HALLWAY 40X18 NEED<br>TOBE REPLACES VANDALISM   | 8/26/2005<br>Medium                         | Mario Apodaca<br>Ruben Ronquillo<br>Glass\Window Repairs                 |             | Gadsden HS              |
| 4976  | Work In Progress<br>NEED ALL WINDOW BLINDSON OLD ENGLISH<br>BLDG 40 EA 40WX90L   | 8/26/2005<br>Medium                         | Mario Apodaca<br>Ruben Ronquillo<br>Glass\Window Repairs                 |             | Gadsden HS              |
| 11664 | Work In Progress<br>NEED A NEW MOTER STARTER CONTROL FOR A<br>E/COOER  | 4/26/2006<br>Medium                         | Mario Apodaca<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning | Gym         | Gadsden HS              |
| 11729 | Work In Progress<br>NEED A NEW FAN MOTOR FOR A/C UNIT AT<br>ROOM 504   | 4/28/2006<br>Medium                         | Mario Apodaca<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning |             | Gadsden HS              |
| 11730 | Work In Progress<br>WINDOWS AT ROOM 147 NEED TOBE REPAIRS<br>IT IS A DOUBLE PANE GLASS UNIT ARE 3# UNIT<br>NEED FIX AT OLD ENG BLDG VANDALISM                              | 4/28/2006<br>Medium                         | Mario Apodaca<br>Ruben Ronquillo<br>Glass\Window Repairs                 | Classroom   | Gadsden HS              |
| 4726  | Work In Progress<br>Royal vacuum is missing bag and brush, belt<br>serial No.H93266101B GISD tag 014131  | 8/19/2005<br>Medium                         | Jesus Estrada<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair         |             | Gadsden HS              |
| 11674 | Work In Progress<br>GHS Old English – Change program back to how<br>it was w/Outside Temp  | 4/27/2006<br>Medium                         | Jose Ambriz<br>Margret Villalobos<br>Energy Management<br>System         |             | Gadsden HS              |
| 3582  | Work In Progress<br>IRRIGATION CTRL PANEL - IRRIGATION<br>BOOSTER PUMP IS NOT WORKING. PLEASE<br>TROUBLESHOOT BUS TURNAROUND AREA.<br>ROUTED TO ENRIQUE AS PER RICK 8/2/05 | 7/15/2005<br>8/2/2005<br>Medium             | Lorenzo Hernandez<br>Enrique Sotelo<br>Electrical                        |             | Gadsden MS              |
| 11690 | Work In Progress<br>Broken shower head and broken door handle to<br>coaches office.<br>Broken door handle 130.00 parts/labor<br>Broken shower head 300parts/200labor       | 4/24/2006<br>Medium                         | Jose Pinon<br>Rudy Arreola<br>General Maintenance                        |             | Gadsden MS              |
| 11049 | Work In Progress<br>3-compartment sink - two of the facuets are<br>leaking really bad.<br><br>Terry P. SNP Mgr 882-2824  | 4/3/2006<br>Medium                          | Jacqueline Aguilar<br>Danny Orozco<br>Food Services                      | Cafeteria   | Gadsden MS              |
| 11630 | Work In Progress<br>please remove dead trees and cut weeds,also<br>weed eat the wells.   | 4/25/2006<br>Medium                         | Michael Munoz<br>Rudy Arreola<br>General Maintenance                     | Parking Lot | Gadsden MS              |
| 11631 | Work In Progress<br>please cut weeds in and around bus turn<br>around, also on the corner by the trash dumpster.   | 4/25/2006<br>Medium                         | Michael Munoz<br>Rudy Arreola<br>General Maintenance                     |             | Gadsden MS              |



| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                    | Area Type      | Location<br>Area Number |
|-------|--|---|--|----------------|-------------------------|
| 5119  | Work In Progress<br>Power Outage - El Paso Electric  | 8/29/2005<br>Medium                         | Margret Villalobos<br>Enrique Sotelo<br>Electrical                   |                | Gadsden MS              |
| 2221  | Work In Progress<br>Weeds are growing out on the new tennis courts. Please cut and apply a none coloring chemical to prevent weeds from coming out thru concrete and damaging the courts. Also please cut the weeds around tennis court. THanks                    | 5/23/2005<br>Medium                         | Michael Munoz<br>Lorenzo Hernandez<br>Grounds                        | Athletic Field | Gadsden MS              |
| 2470  | Work In Progress<br>GATE BY DITCH NEEDS TO BE REPLACED. IT'S ONLY LOCKED BY A SMALL CHAIN THAT CAN EASILY BE BROKEN (PER YOLIE JACQUEZ). ROUTE TO MANNY LOZOYA AS PER MIKE MUNOZ.  | 6/2/2005<br>Medium                          | Michael Munoz<br>Manny Lozoya<br>Key and Lock                        |                | Gadsden MS              |
| 2954  | Work In Progress<br>Please install new sprinkler by picnic area where sprinkler was broken and run a new line for additional sprinkler by the south east door by cafeteria for proper coverage of irrigation. As per Rudy need to route to Fred Appelzoller. - mkv | 6/23/2005<br>Medium                         | Michael Munoz<br>Fred Appelzoller<br>Plumbing                        |                | Gadsden MS<br>GROUNDS   |
| 354   | Work In Progress<br>Need to installing emerg. lights in hallways and restrooms girls and boys as per pm 125602.  | 3/14/2005<br>Medium                         | Rudy Arreola<br>Enrique Sotelo<br>Electrical                         |                | Gadsden MS              |
| 326   | Work In Progress<br>We are having a problem with students in the cafeteria after hours we need to have dead bolts installed so we can secure cafeteria.  | 3/11/2005<br>Medium                         | Rudy Arreola<br>Manny Lozoya<br>Key and Lock                         | Cafeteria      | Gadsden MS              |
| 2031  | Work In Progress<br>2 A/C in main gym need to be replaced.   | 5/17/2005<br>Medium                         | Rudy Arreola<br>Jaime Gomez<br>Heating/Ventilation /Air Conditioning |                | Gadsden MS              |
| 2242  | Work In Progress<br>MAIN BANDROOM.<br>We need to remove 2 steps in bandroom to make more room.   | 5/24/2005<br>Medium                         | Rudy Arreola<br>Michael Munoz<br>General Maintenance                 |                | Gadsden MS              |
| 2244  | Work In Progress<br>Room 140 handle was broken need to have it replaced.   | 5/24/2005<br>Medium                         | Rudy Arreola<br>Manny Lozoya<br>Key and Lock                         |                | Gadsden MS              |
| 2194  | Work In Progress<br>Need some help for knocking down some walls to make an extra classroom in C-WING old Calixto's office.   | 5/23/2005<br>Medium                         | Rudy Arreola<br>Danny Miranda<br>General Maintenance                 |                | Gadsden MS              |
| 11732 | Work In Progress<br>RM#404 We are having problems with the door handle unlocking or locking room. Possible we have to replace the key also.  | 4/28/2006<br>Medium                         | Rudy Arreola<br>Manny Lozoya<br>Key and Lock                         |                | Gadsden MS              |
| 11147 | Work In Progress<br>We are having problems with mice and roaches in homec RM.  | 4/6/2006<br>Medium                          | Rudy Arreola<br>Margret Villalobos<br>Pest Control                   | Classroom      | Gadsden MS              |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                      | Area Type        | Location<br>Area Number |
|-------|--|---|--|------------------|-------------------------|
| 11148 | Work In Progress<br>We need the light fixture replaced cover is missing replaced ballast but light fixture is not secure.                                | 4/6/2006<br>Medium                          | Rudy Arreola<br>Enrique Sotelo<br>Electrical                           | Restroom (Boys)  | Gadsden MS              |
| 11330 | Work In Progress<br>We need to have the 6x6 glass cubes removed and install wall with plaster glass keeps broken. 4/19/06 - Routed to Gerry as per Mike. | 4/12/2006<br>Medium                         | Rudy Arreola<br>Michael Munoz<br>General Maintenance                   | Hallway/Corridor | Gadsden MS              |
| 11608 | Work In Progress<br>BOY'S LOCKER ROOM WAS BROKEN IN DOOR HANDLE BROKEN OFF - NEED TO SECURE BY THE END OF THE DAY  | 4/25/2006<br>Medium                         | Rudy Arreola<br>Manny Lozoya<br>Key and Lock                           | Restroom (Boys)  | Gadsden MS              |
| 11609 | Work In Progress<br>WATER SPICETT WAS DAMAGED AND LEAKING WATER<br>NEED TO REPLACE ASAP  | 4/25/2006<br>Medium                         | Rudy Arreola<br>Joe Ontiveros<br>Plumbing                              | Restroom (Boys)  | Gadsden MS              |
| 9002  | Work In Progress<br>Sink is clogged we need the snake. to run it threw the wall drain.   | 1/24/2006<br>Medium                         | Rudy Arreola<br>Joe Ontiveros<br>Plumbing                              |                  | Gadsden MS              |
| 9003  | Work In Progress<br>We need a new handle behind gym annex handle was pulled and broken off.  | 1/24/2006<br>Medium                         | Rudy Arreola<br>Manny Lozoya<br>Key and Lock                           |                  | Gadsden MS              |
| 9004  | Work In Progress<br>Rm #114 cylinder is stuck and wont turn and door needs to be secured for the end of the day.   | 1/24/2006<br>Medium                         | Rudy Arreola<br>Manny Lozoya<br>Key and Lock                           |                  | Gadsden MS              |
| 9038  | Work In Progress<br>Main Gym - pulled handle and broken, tagging on door, mirror and baseball dugouts.   | 1/23/2006<br>Medium                         | Rudy Arreola<br>Rudy Arreola<br>General Maintenance                    |                  | Gadsden MS              |
| 8602  | Work In Progress<br>Back flow in A-WING is leaking water.<br>Route to Lupe as per Mike Munoz 3/10/06 - mkv   | 1/10/2006<br>Medium                         | Rudy Arreola<br>Guadalupe Ontiveros<br>Grounds                         |                  | Gadsden MS              |
| 8603  | Work In Progress<br>Backflow in B-WING is leaking water.   | 1/10/2006<br>Medium                         | Rudy Arreola<br>Guadalupe Ontiveros<br>Grounds                         |                  | Gadsden MS              |
| 8468  | Work In Progress<br>We need to have front office fumigated big and small roaches when you turn on the lights.  | 1/6/2006<br>Medium                          | Rudy Arreola<br>Margret Villalobos<br>Pest Control                     |                  | Gadsden MS              |
| 9150  | Work In Progress<br>We need 2 cylinders changed so they can match the WA-94 key to the classroom and storage RMS   | 1/30/2006<br>Medium                         | Rudy Arreola<br>Manny Lozoya<br>Key and Lock                           | Classroom        | Gadsden MS              |
| 9590  | Work In Progress<br>Boiler RM in B-WING not heating B-WING area.<br>Called Control and Equipment   | 2/10/2006<br>Medium                         | Rudy Arreola<br>Margret Villalobos<br>Energy Management System         |                  | Gadsden MS              |
| 9591  | Work In Progress<br>Three way valve in unit is getting stuck needs to be replaced in RM 116  | 2/10/2006<br>Medium                         | Rudy Arreola<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning | Classroom        | Gadsden MS              |

| WOID | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                       | Area Type       | Location<br>Area Number |
|------|---|---|---|-----------------|-------------------------|
| 9494 | Work In Progress<br>MAIN BLDG - NEED EMERGENCY LIGHTS IN<br>HALLWAYS AND RESTROOMS AS PER PM 9373.  | 2/8/2006<br>Medium                          | Rudy Arreola<br>Enrique Sotelo<br>Electrical                            |                 | Gadsden MS              |
| 6386 | Work In Progress<br>Light on the westside of the bandroom doesnt<br>turn on.  | 10/13/2005<br>Medium                        | Rudy Arreola<br>Enrique Sotelo<br>Electrical                            |                 | Gadsden MS              |
| 5793 | Work In Progress<br>{{{GYM LOBBY}}} Wall needs to be secured.   | 9/23/2005<br>Medium                         | Rudy Arreola<br>Danny Miranda<br>General Maintenance                    | Restroom (Boys) | Gadsden MS              |
| 5317 | Work In Progress<br>Need to cap of water lines and drain removed<br>already removed sink and counters. RM#188.  | 9/7/2005<br>Medium                          | Rudy Arreola<br>Joe Ontiveros<br>Plumbing                               | Classroom       | Gadsden MS              |
| 5569 | Work In Progress<br>VOC BLDG RM#306 - Need some assistance<br>changing out ballast already replaced lamps high<br>ceiling.  | 9/16/2005<br>Medium                         | Rudy Arreola<br>Enrique Sotelo<br>Electrical                            | Classroom       | Gadsden MS              |
| 5918 | Work In Progress<br>Door handle is broken off boys lockerroom   | 9/28/2005<br>Medium                         | Rudy Arreola<br>Manny Lozoya<br>Key and Lock                            |                 | Gadsden MS              |
| 4218 | Work In Progress<br>Coil in not cooling cleaned out strainer and<br>checked valve. RM 156   | 8/4/2005<br>Medium                          | Rudy Arreola<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Classroom       | Gadsden MS              |
| 4220 | Work In Progress<br>Rm 157/158 Unit is not cooling at all cleaned out<br>strainer and checked valves.   | 8/4/2005<br>Medium                          | Rudy Arreola<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Classroom       | Gadsden MS              |
| 4528 | Work In Progress<br>We need 2 water fountains replaced in cafeteria.  | 8/12/2005<br>Medium                         | Rudy Arreola<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |                 | Gadsden MS              |
| 3000 | Work In Progress<br>We need change locks due to the floor getting a<br>new coat of varnish and so one can go in.  | 6/27/2005<br>Medium                         | Rudy Arreola<br>Manny Lozoya<br>Key and Lock                            | Gym             | Gadsden MS              |
| 2784 | Work In Progress<br>We need to have the sprinklers in front of school<br>adjusted especially in the B-WING.   | 6/15/2005<br>Medium                         | Rudy Arreola<br>Lorenzo Hernandez<br>Grounds                            | Parking Lot     | Gadsden MS              |
| 1101 | Work In Progress<br>We are going have a new student in a<br>wheelchair the only concern is we need a<br>walkway where the new fence was put up to<br>connect to the side of the bandroom. | 4/13/2005<br>Medium                         | Rudy Arreola<br>Michael Munoz<br>Concrete                               |                 | Gadsden MS              |
| 1102 | Work In Progress<br>Some of the doors to the main entance have a<br>little step the wheelchair may not be able to go up<br>(Concerned the student may flip forward).                      | 4/13/2005<br>Medium                         | Rudy Arreola<br>Michael Munoz<br>Concrete                               |                 | Gadsden MS              |
| 1105 | Work In Progress<br>Sidewalk on eastside of annex bldg is to steep<br>for wheelchair need sidewalk raised.  | 4/13/2005<br>Medium                         | Rudy Arreola<br>Michael Munoz<br>Concrete                               |                 | Gadsden MS              |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                     | Area Type        | Location<br>Area Number |
|-------|--|---|---|------------------|-------------------------|
| 1465  | Work In Progress<br>We need metal frames around windows we<br>several threw out the campus in main bldg. The<br>moulding is missing.   | 4/27/2005<br>Medium                         | Rudy Arreola<br>Ruben Ronquillo<br>Glass\Window Repairs               |                  | Gadsden MS              |
| 8845  | Work In Progress<br>DOUBLE DOORS INSIDE BAND ROOM WHERE<br>INSTRUMENTS ARE STORED DO NOT LOCK AND<br>SECURE PROPERLY. EQUIPMENT SAFETY ISSUE.  | 1/18/2006<br>Medium                         | Maria Sitters<br>Danny Miranda<br>Doors and Hardware                  |                  | Gadsden MS              |
| 3616  | Work In Progress<br>replace door at pump room  | 7/18/2005<br>Medium                         | Ricardo Jacquez<br>Danny Miranda<br>General Maintenance               |                  | Gadsden MS              |
| 11544 | Work In Progress<br>Athletic Office - Having trouble opening door -<br>key is sticking.  | 4/24/2006<br>Medium                         | Terry Alvarado<br>Manny Lozoya<br>Key and Lock                        |                  | Gadsden MS              |
| 7479  | Work In Progress<br>Also at GMS Gym Bleachers They have a<br>cheap extension for the score board, could we<br>get a permanent 120v outlet fastened to front of<br>bleachers? thanks , Carlos | 11/18/2005<br>Medium                        | Carlos Vigil<br>Enrique Sotelo<br>Electrical                          |                  | Gadsden MS              |
| 4643  | Work In Progress<br>Need a copy of fire alarm key (See Mr. Hamel for<br>his key).  | 8/17/2005<br>Medium                         | Dana Hamel<br>Manny Lozoya<br>Key and Lock                            |                  | Gadsden MS              |
| 4522  | Work In Progress<br>Door broken in room 500, and window shattered  | 8/12/2005<br>Medium                         | Dana Hamel<br>Danny Miranda<br>Doors and Hardware                     | Portables        | Gadsden MS              |
| 4777  | Work In Progress<br>The three locks on the office front window are<br>broken, mostly poor design. The front office is<br>wide open until these are repaired or replaced                      | 8/22/2005<br>Medium                         | Dana Hamel<br>Rudy Arreola<br>General Maintenance                     | Office           | Gadsden MS              |
| 4778  | Work In Progress<br>2nd request for an "A" master for GMS Campus   | 8/22/2005<br>Medium                         | Dana Hamel<br>Manny Lozoya<br>Key and Lock                            | Office           | Gadsden MS              |
| 4982  | Work In Progress<br>Whole south side of annex does not have any<br>air, class temperatures are above 95 degrees.<br>The classes opposite hallway have conditioning,<br>Please fix ASAP       | 8/26/2005<br>Medium                         | Dana Hamel<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning | Classroom        | Gadsden MS              |
| 5499  | Work In Progress<br>Change M4 key to a G key in all electrical room on<br>campus, we have no "m" master  | 9/14/2005<br>Medium                         | Dana Hamel<br>Manny Lozoya<br>Key and Lock                            | Electrical Room  | Gadsden MS              |
| 5500  | Work In Progress<br>change A3 key to a "g" key in storage room in<br>annex   | 9/14/2005<br>Medium                         | Dana Hamel<br>Manny Lozoya<br>Key and Lock                            | Mechanical Room  | Gadsden MS              |
| 5501  | Work In Progress<br>Repair the outside doors locks "w" master will<br>not open doors to lobby  | 9/14/2005<br>Medium                         | Dana Hamel<br>Manny Lozoya<br>Key and Lock                            | Hallway/Corridor | Gadsden MS              |

| WOID | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                 | Area Type       | Location<br>Area Number |
|------|--|---|---|-----------------|-------------------------|
| 5502 | Work In Progress<br>request 3 new "G" keys for principal and custodians  | 9/14/2005<br>Medium                         | Dana Hamel<br>Manny Lozoya<br>Key and Lock        |                 | Gadsden MS              |
| 6241 | Work In Progress<br>The new roof on the vocational building leaked badly over vacation and the insulation in the old woodshop is falling. Serious problem with students returning tomorrow could fall at any time.   | 10/10/2005<br>Medium                        | Dana Hamel<br>David Boyd<br>Construction          | Classroom       | Gadsden MS              |
| 2572 | Work In Progress<br>need locks on desk draws and other security measures to ensure that data is not compromised. Gloria Hernandez office and Terry Villalobos data entry clerks in C wing. ASAP  | 6/7/2005<br>Medium                          | Dana Hamel<br>Manny Lozoya<br>Key and Lock        | Office          | Gadsden MS              |
| 2929 | Work In Progress<br>Replace door into storage area and repair the frame to keep students from upstairs area  | 6/21/2005<br>Medium                         | Dana Hamel<br>Danny Miranda<br>Doors and Hardware | Stairway        | Gadsden MS              |
| 2789 | Work In Progress<br>check to ensure that the flushes are working in lobby bathroom. If they are, then request that custodial clean, clean, and clean again this area (stinks)  | 6/15/2005<br>Medium                         | Dana Hamel<br>Fred Appelzoller<br>Plumbing        | Restroom (Boys) | Gadsden MS              |
| 2881 | Work In Progress<br>fix exhaust fan in science room 150  | 6/20/2005<br>Medium                         | Dana Hamel<br>Rudy Arreola<br>General Maintenance | Classroom       | Gadsden MS              |
| 2888 | Work In Progress<br>repair holes in ceiling by air conditioner, needs 4 new window blinds, secure fuse box, secure air conditioner switch, repair entry door to class and last can not use the high switch on air conditioner because it makes too much noise. | 6/20/2005<br>Medium                         | Dana Hamel<br>Rudy Arreola<br>General Maintenance | Portables       | Gadsden MS              |
| 2889 | Work In Progress<br>repair all the interior doors, jams and latches. Outside doors are not closing unless lifted by handles  | 6/20/2005<br>Medium                         | Dana Hamel<br>Danny Miranda<br>Doors and Hardware | Gym             | Gadsden MS              |
| 3653 | Work In Progress<br>paint the columns on outside of gym  | 7/19/2005<br>Medium                         | Dana Hamel<br>Rudy Arreola<br>General Maintenance | Gym             | Gadsden MS              |
| 3654 | Work In Progress<br>paint over the scratchouts in boys black restrooms   | 7/19/2005<br>Medium                         | Dana Hamel<br>Rudy Arreola<br>General Maintenance | Restroom (Boys) | Gadsden MS              |
| 3655 | Work In Progress<br>paint the front columns of the school to remove tagging  | 7/19/2005<br>Medium                         | Dana Hamel<br>Rudy Arreola<br>General Maintenance |                 | Gadsden MS              |
| 9518 | Work In Progress<br>check out the recepticle on front wall room 121, teacher currently using a side outlet for 5 computers   | 2/9/2006<br>Medium                          | Dana Hamel<br>Enrique Sotelo<br>Electrical        |                 | Gadsden MS              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                              | Area Type        | Location<br>Area Number |
|-------|---|---|--|------------------|-------------------------|
| 9148  | Work In Progress<br>Please repair the bleachers, the rollers are out of sync, and we have a tournament coming up  | 1/30/2006<br>Medium                         | Dana Hamel<br>Michael Munoz<br>Equipment                       | Gym              | Gadsden MS              |
| 9149  | Work In Progress<br>Extend concrete eastward from doorway towards the gym, not enough room for a motorized wheelchair   | 1/30/2006<br>Medium                         | Dana Hamel<br>Michael Munoz<br>Concrete                        | Hallway/Corridor | Gadsden MS              |
| 11553 | Work In Progress<br>Again the basketball goals will not go up or down without sticking  | 4/24/2006<br>Medium                         | Dana Hamel<br>Michael Munoz<br>Equipment                       | Gym              | Gadsden MS              |
| 11550 | Work In Progress<br>The bleachers are off track and will not retrack. We have events planned this whole week and need them, plus this weekend "Literacy Festival." I have requested this repair before but now it is really bad   | 4/24/2006<br>Medium                         | Dana Hamel<br>Michael Munoz<br>Equipment                       | Gym              | Gadsden MS              |
| 11684 | Work In Progress<br>Need new power strips in classroom for additional computers. See Mrs. Osborn room 121. Also repair wall outlets in room, possible shock hazzard   | 4/27/2006<br>Medium                         | Dana Hamel<br>Enrique Sotelo<br>Electrical                     | Classroom        | Gadsden MS              |
| 11685 | Work In Progress<br>repair a sewing machine leg room 301  | 4/27/2006<br>Medium                         | Dana Hamel<br>Rudy Arreola<br>General Maintenance              |                  | Gadsden MS              |
| 4867  | Work In Progress<br>THE PAD HOLDER IS WORN OUT AND WONT HOLD THE PAD AT ALL.  | 8/24/2005<br>Medium                         | Jimmy Carbajal<br>Jimmy Carbajal<br>Custodial Equipment Repair | Hallway/Corridor | Gadsden MS              |
| 11187 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Juan Acosta<br>Custodial                       |                  | Gadsden MS              |
| 10966 | Work In Progress<br>Monthly - Gadsden MS Fire Suppression Insp. - Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System       |                  | Gadsden MS              |
| 7760  | Work In Progress<br>Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.  | 12/4/2005<br>Medium                         | Alfredo Holguin<br>Rudy Arreola<br>Fire Extinguishers          |                  | Gadsden MS              |
| 10710 | Work In Progress<br>please install lights on the north side off the gym annex so the light will shine on the bus turnaround.  | 3/27/2006<br>Medium                         | Enrique Sotelo<br>Electrical                                   |                  | Gadsden MS              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                     | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 9295  | Work In Progress<br>please replaced stained ceiling tiles in Mr.Lowenburgs office and thru-out c-wing area thats needed. Thanks   | 2/3/2006<br>Medium                          | Rudy Arreola<br>General Maintenance                   |           | Gadsden MS              |
| 8735  | Work In Progress<br>please install new sprinklers by picnic tables & where needed and level grounds around area. Thanks   | 1/13/2006<br>Medium                         | Guadalupe Ontiveros<br>Grounds                        | Cafeteria | Gadsden MS              |
| 5961  | Work In Progress<br>please reomve and replaced stained ceiling tiles in Mr.Lowenburgs office.   | 9/29/2005<br>Medium                         | Rudy Arreola<br>General Maintenance                   |           | Gadsden MS              |
| 6424  | Work In Progress<br>WE NEED LIGHTS IN THE BOYS & GIRLS RR IN MAIN BLDG, ALSO WE NEED THE LIGHTS IN HALLWAYS AS PER PM 6095.   | 10/14/2005<br>Medium                        | Enrique Sotelo<br>Electrical                          |           | Gadsden MS              |
| 4095  | Work In Progress<br>please fiill hole that is in front of entrance to band room. Will need a backking before gravel is applied. see mike  | 8/2/2005<br>High                            | Rudy Arreola<br>General Maintenance                   |           | Gadsden MS              |
| 7716  | Work In Progress<br>Kitchen - Need to shutdown gas and water service on Friday, 12/16/05 @ 1:00 pm. Route to Pancho, Spoke to him today 12/15/05 and he can do this. - M. Munoz | 12/1/2005<br>12/2/2005<br>Medium            | Alfredo Holguin<br>Frank Lara<br>Plumbing             | Cafeteria | La Mesa ES              |
| 4378  | Work In Progress<br>locksmith<br>need three keys for supply rm.<br>key no F 49<br>8/23- Debra needs status on this work order submitted on 8/9/05 - mkv                         | 8/9/2005<br>Medium                          | Frank Lara<br>Manny Lozoya<br>Key and Lock            |           | La Mesa ES              |
| 9899  | Work In Progress<br>MAIN BLDG - NEED TO REPLACE 2 BROKEN WINDOWS 26 1/2 W X 54 3/4 L  | 2/21/2006<br>Medium                         | Frank Lara<br>Ruben Ronquillo<br>Glass\Window Repairs |           | La Mesa ES              |
| 9715  | Work In Progress<br>MAIN BLDG - NEED TO REPLACE BROKEN WINDOWS<br>26 1/2 W X 54 5/8 L (WIRE GLASS)  | 2/15/2006<br>Medium                         | Frank Lara<br>Ruben Ronquillo<br>Glass\Window Repairs |           | La Mesa ES              |
| 11316 | Work In Progress<br>NEED A KEY TO OPEN GATE AND FRONT OFFICE - WORK BEING DONE FOR FIRE DAMAGE ON FRIDAY AND MONDAY 4/14/06 & 4/17/06 (PLAN B)                                  | 4/12/2006<br>Medium                         | Cora Ramirez<br>Manny Lozoya<br>Key and Lock          |           | La Mesa ES              |
| 8256  | Work In Progress<br>Alvarez Farms ,panel needs main lug kit replaced  | 12/22/2005<br>Medium                        | Carlos Castillo<br>Carlos Castillo<br>Electrical      | Classroom | La Union ES             |
| 3572  | Work In Progress<br>NEED LIGHT BULBS FOR RECESSED LIGHTS AT LA UNION ELEM. THE MAJORITY ARE BURNED OUT. THANK YOU.  | 7/15/2005<br>Medium                         | Arturo Nunez<br>Carlos Castillo<br>Electrical         |           | La Union ES             |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                   | Area Type       | Location<br>Area Number |
|-------|---|---|---|-----------------|-------------------------|
| 11138 | Work In Progress<br>need to run water line to front of old main building for irrigation   | 4/6/2006<br>Medium                          | David Villalobos<br>David Villalobos<br>Plumbing                    | Mechanical Room | La Union ES             |
| 166   | Work In Progress<br>A motor starter coil is requested for the boiler pump at new addition   | 3/8/2005<br>Medium                          | Eddie Baeza<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |                 | La Union ES             |
| 1613  | Work In Progress<br>Transformer for the high temp. alarm in the server rm. does not have 120v circuit only the 24v side was hooked up.  | 5/3/2005<br>Medium                          | Eddie Baeza<br>Carlos Castillo<br>Electrical                        |                 | La Union ES             |
| 4917  | Work In Progress<br>please repair asphalt where other water line was repired.   | 8/25/2005<br>Medium                         | Michael Munoz<br>Concrete   |                 | La Union ES             |
| 10968 | Work In Progress<br>Monthly - La Union ES Fire Suppression Insp. - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System            |                 | La Union ES             |
| 3322  | Work In Progress<br>Yearly - La Union ES Emer. Light Test: Annual - Refer to PM schedule details.   | 7/6/2005<br>Medium                          | Alfredo Holguin<br>Eddie Baeza<br>Fire Protection                   |                 | La Union ES             |
| 11188 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Santos Galindo<br>Custodial                         |                 | La Union ES             |
| 3344  | Work In Progress<br>Yearly - La Union ES Exit Sign Test: Annual - Refer to PM schedule details.   | 7/6/2005<br>Medium                          | Alfredo Holguin<br>Eddie Baeza<br>Fire Protection                   |                 | La Union ES             |
| 4864  | Work In Progress<br>JTP- Rosaro Ruedas needs a L201 key.  | 8/24/2005<br>Medium                         | Selma Nevarez<br>Manny Lozoya<br>Key and Lock                       |                 | La Union ES<br>JTP      |
| 10085 | Work In Progress<br>need to replace starter and heater thanks   | 3/1/2006<br>Medium                          | Ricardo Jacquez<br>Carlos Castillo<br>Electrical                    |                 | La Union ES             |
| 6718  | Work In Progress<br>need electrical outlet on north wall  | 10/25/2005<br>10/26/2005<br>Medium          | Santos Galindo<br>Carlos Castillo<br>Electrical                     | Office          | La Union ES             |
| 6403  | Work In Progress<br>NEED CORK STRIP INFRONT OF THE OFFICE IN HALLAWAY.  | 10/14/2005<br>Medium                        | Santos Galindo<br>Ruben Ronquillo<br>General Maintenance            |                 | La Union ES             |



| WOID | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                      | Area Type | Location<br>Area Number |
|------|---|---|--|-----------|-------------------------|
| 7446 | Work In Progress<br>would like hallway in old wing painted and frames. and new base trimming.   | 11/18/2005<br>Medium                        | Santos Galindo<br>Salvador Gonzalez<br>Painting                        |           | La Union ES             |
| 5117 | Work In Progress<br>Lights in computer room keeps going out; breaker needs to be checked.   | 8/31/2005<br>Medium                         | Santos Galindo<br>Carlos Castillo<br>Electrical                        |           | La Union ES             |
| 5312 | Work In Progress<br>After last nights rainfall, leaks were discovered in rooms #208, #209, and the library.   | 9/7/2005<br>Medium                          | Santos Galindo<br>Lorenzo Solis<br>Roof                                |           | La Union ES             |
| 5371 | Work In Progress<br>In the women's restroom, in the southwing, the toilet is constantly flushy.   | 9/9/2005<br>Medium                          | Santos Galindo<br>Salvador Gonzalez<br>General Maintenance             |           | La Union ES             |
| 4825 | Work In Progress<br>Need keys for room #100, #106, and room #108; plus keys for a file cabinet in the nurse's office.   | 8/23/2005<br>Medium                         | Santos Galindo<br>Manny Lozoya<br>Key and Lock                         |           | La Union ES             |
| 4853 | Work In Progress<br>SINK AT CUSTODIAL CLOSET AT OLD BLDG. IS CLOGGED UP.  | 8/24/2005<br>Medium                         | Santos Galindo<br>David Villalobos<br>Plumbing                         |           | La Union ES             |
| 4775 | Work In Progress<br>Parking lanes need to be repaint in yellow and bus lane also needs to be repaint but in red. Route to Sal Gonzalez as per Mike 9/13/05 -mkv | 8/22/2005<br>Medium                         | Santos Galindo<br>Salvador Gonzalez<br>General Maintenance             |           | La Union ES             |
| 4408 | Work In Progress<br>a light next to my office need to be looked at cause it buzzes all day long.  | 8/10/2005<br>Medium                         | Santos Galindo<br>Carlos Castillo<br>Electrical                        |           | La Union ES             |
| 4356 | Work In Progress<br>in room 202 there is no outlet for refrigeration unit a.s.p.  | 8/9/2005<br>Medium                          | Santos Galindo<br>Carlos Castillo<br>Electrical                        |           | La Union ES             |
| 4372 | Work In Progress<br>need a fan motor in electrical storage room.  | 8/9/2005<br>Medium                          | Santos Galindo<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |           | La Union ES             |
| 4223 | Work In Progress<br>need an electrical outlet by computer hookups room 203.   | 8/5/2005<br>Medium                          | Santos Galindo<br>Carlos Castillo<br>Electrical                        |           | La Union ES             |
| 5949 | Work In Progress<br>Music Room needs a new circuit installation.  | 9/29/2005<br>Medium                         | Salvador Gonzalez<br>Carlos Castillo<br>Electrical                     |           | La Union ES             |
| 5503 | Work In Progress<br>Old emergency light fixtures (the complete system) are not working can you check them please. thank you                                     | 9/14/2005<br>Medium                         | Salvador Gonzalez<br>Carlos Castillo<br>Electrical                     |           | La Union ES             |
| 5786 | Work In Progress<br>Upper hinge on door at JTP needs to be repair. Might need to be weld  | 9/23/2005<br>Medium                         | Salvador Gonzalez<br>Manny Lozoya<br>Key and Lock                      |           | La Union ES             |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft   | Area Type | Location<br>Area Number |
|-------|--|---|---|-----------|-------------------------|
| 7391  | Work In Progress<br>11/15/05<br>To Caly. Relocate electrical outlet.   | 11/15/2005<br>Medium                        | Salvador Gonzalez<br>Carlos Castillo<br>Electrical                        |           | La Union ES             |
| 6418  | Work In Progress<br>Work Truck - need to repair broken tial-light.   | 10/14/2005<br>Medium                        | Salvador Gonzalez<br>Angel Gonzales<br>Vehicle Maintenance                |           | La Union ES             |
| 11629 | Work In Progress<br>Replace old lighth bulbs and ballasts.   | 4/25/2006<br>Medium                         | Salvador Gonzalez<br>Carlos Castillo<br>Electrical                        |           | La Union ES             |
| 10569 | Work In Progress<br>1/16/06<br>Manny We need to secure door for the end of the day, lock problem.                                      | 3/16/2006<br>Medium                         | Salvador Gonzalez<br>Manny Lozoya<br>Key and Lock                         |           | La Union ES             |
| 10313 | Work In Progress<br>Room 206 needs to be fumigated for spiders.  | 3/7/2006<br>Medium                          | Salvador Gonzalez<br>Margret Villalobos<br>Pest Control                   |           | La Union ES             |
| 10409 | Work In Progress<br>Manny, the lock door knob at classroom 100 is mising. Can you come and fix it please.                              | 3/10/2006<br>Medium                         | Salvador Gonzalez<br>Manny Lozoya<br>Key and Lock                         |           | La Union ES             |
| 9768  | Work In Progress<br>To Mike Munoz<br>Subject: I would like to install PVC watering system on side of the school and between buildings. | 2/16/2006<br>Medium                         | Salvador Gonzalez<br>Guadalupe Ontiveros<br>Grounds                       |           | La Union ES             |
| 9769  | Work In Progress<br>Teacher in classroom 110 requires more power outlets because his room only has two.                                | 2/16/2006<br>Medium                         | Salvador Gonzalez<br>Carlos Castillo<br>Electrical                        |           | La Union ES             |
| 10076 | Work In Progress<br>2/28/06<br>To Jose Ambriz:<br>I would like to replace some (4) old water cooler for master cool system.            | 2/28/2006<br>Medium                         | Salvador Gonzalez<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |           | La Union ES             |
| 9087  | Work In Progress<br>1/27/06<br>To David Villalobos. There is a boiler back flow water valve leaking , on my opinion has to replaced.   | 1/27/2006<br>Medium                         | Salvador Gonzalez<br>David Villalobos<br>Plumbing                         |           | La Union ES             |
| 8982  | Work In Progress<br>David I need some PVC to make a drain fanel for boiler room please. Thank you.                                     | 1/24/2006<br>Medium                         | Salvador Gonzalez<br>David Villalobos<br>Plumbing                         |           | La Union ES             |
| 8547  | Work In Progress<br>Take out grass at swings area with the back hoe and fill with sand ( has half of needed sand)                      | 1/9/2006<br>Medium                          | Salvador Gonzalez<br>Guadalupe Ontiveros<br>Grounds                       |           | La Union ES             |
| 10119 | Work In Progress<br>JTP - Mr. Casavantes needs you to replace lock from the stroage computer cabinet.                                  | 3/2/2006<br>Medium                          | Julie Hernandez<br>Manny Lozoya<br>Key and Lock                           |           | La Union ES             |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                 | Area Type | Location<br>Area Number    |
|-------|---|---|---|-----------|----------------------------|
| 9454  | Work In Progress<br>Need a gate key for El Paso Disposal.   | 2/7/2006<br>Medium                          | Juliet Parra<br>Manny Lozoya<br>Key and Lock                      |           | Loma Linda ES              |
| 11724 | Work In Progress<br>WE NEED AT LEAST (5) 55 GALS METAL TRASH<br>CANS LIDS (BEE PROBLEMS). THANK YOU.  | 4/28/2006<br>Medium                         | Luis Solis<br>Jimmy Carbajal<br>Custodial                         |           | Loma Linda ES              |
| 1676  | Work In Progress<br>NEED ANOTHER ROYAL BAG FOR THE VACUUM<br>CLEANER. TO REPLACE TWO WITH SOME<br>HOLES (DAMAGED). THANK YOU.   | 5/5/2005<br>Medium                          | Luis Solis<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair     |           | Loma Linda ES              |
| 11542 | Work In Progress<br>NEED SERVICE FOR MR. CHACON VACUUM<br>CLEANER, IT NOT WORKING.( ALSO NEED A<br>NEW BAG ) THANK YOU.   | 4/24/2006<br>Medium                         | Luis Solis<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair     |           | Loma Linda ES              |
| 11830 | Work In Progress<br>3-1-6 ATTN RUBEN RONQUILLO I NEED A 3/4<br>HP 2 SPEED A/C MOTOR.  | 5/1/2006<br>Medium                          | Michael Mc Dermott<br>Ruben Ronquillo<br>General Maintenance      | Classroom | Loma Linda ES<br>RM 202    |
| 3345  | Work In Progress<br>Yearly - Loma Linda ES Exit Sign Test: Annual -<br>Refer to PM schedule details.  | 7/6/2005<br>Medium                          | Alfredo Holguin<br>Michael Mc Dermott<br>Fire Protection          |           | Loma Linda ES              |
| 11189 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE<br>INSPECTIONS ON ALL CUSTODIANS TO INCLUDED<br>CLOSET, MSDS, LABELED SPRAY BOTTLES &<br>SAFETY EQUIPMENT. HEAD CUSTODIANS NEED<br>TO INCLUDE INSPECTION OF YOUR OWN AREA.<br>INSPECTION REPORTS ALONG WITH<br>COMPLETED WORK ORDER MUST BE RETURNED<br>AND RECEIVED BY US NO LATER THAN APRIL<br>21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Luis Solis<br>Custodial                           |           | Loma Linda ES              |
| 3323  | Work In Progress<br>Yearly - Loma Linda ES Emer. Light Test: Annual -<br>Refer to PM schedule details.  | 7/6/2005<br>Medium                          | Alfredo Holguin<br>Michael Mc Dermott<br>Fire Protection          |           | Loma Linda ES              |
| 5568  | Work In Progress<br>As per Mike Munoz issue a 6 & 7 Grand Master<br>keys to Mike Mc Dermott.  | 9/16/2005<br>Medium                         | Manny Lozoya<br>Key and Lock                                      |           | Loma Linda ES              |
| 9386  | Work In Progress<br>Monthly - Loma Linda ES Exit Sign Insp: Monthly -<br>Refer to PM schedule details.  | 2/5/2006<br>Medium                          | Alfredo Holguin<br>Michael Mc Dermott<br>General Maintenance      |           | Loma Linda ES              |
| 6538  | Work In Progress<br>Need Ditch Witch delivered to Loma Linda<br>tomorrow.   | 10/18/2005<br>Medium                        | David Villalobos<br>Angel Gonzales<br>Equipment                   |           | Loma Linda ES              |
| 2481  | Work In Progress<br>CONNECT UTILITIES TO PORTABLE.  | 6/3/2005<br>Medium                          | Fred Appelzoller<br>Fred Appelzoller<br>Plumbing                  |           | Loma Linda ES<br>PORTABLES |
| 11692 | Work In Progress<br>RAUL SANCHEZ: REPAIR BOOSTER PUMP FOR<br>SPRINKLER SYSTEM   | 4/27/2006<br>Medium                         | Grace Alvarado<br>Raul Sanchez<br>Sewage/Water<br>Treatment Plant |           | Loma Linda ES              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft   | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 11723 | Work In Progress<br>JIMMY CARBAJAL: NEED 3 ROYAL BELTS.   | 4/28/2006<br>Medium                         | Grace Alvarado<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair         |           | Loma Linda ES           |
| 1761  | Work In Progress<br>Needing Speedy to fertilize within next 2 weeks,<br>also needing dirt to build borders for trees  | 5/9/2005<br>Medium                          | Grace Alvarado<br>Lorenzo Hernandez<br>Grounds                            |           | Loma Linda ES           |
| 352   | Work In Progress<br>UNABLE TO LOCK ROOM   | 3/14/2005<br>Medium                         | Grace Alvarado<br>Manny Lozoya<br>Key and Lock                            | Classroom | Loma Linda ES<br>114    |
| 452   | Work In Progress<br>DISTRICT ART SHOW SETUP AT GADSDEN<br>MIDDLE SCHOOL, PUT UP IS APRIL 14, 2005 AT<br>8:30 AM<br>TAKE DOWN IS APRIL 18, 2005 AT 10:00 AM  | 3/16/2005<br>Medium                         | Grace Alvarado<br>Danny Vega<br>General Maintenance                       |           | Loma Linda ES           |
| 7361  | Work In Progress<br>REPLACE TIMER FOR BOILER  | 11/15/2005<br>Medium                        | Grace Alvarado<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning |           | Loma Linda ES           |
| 6686  | Work In Progress<br>INSTALL ELECTRICAL CIRCUIT IN ROOM 208 FOR<br>MICROWAVE AND FRIDGE.   | 10/24/2005<br>Medium                        | Grace Alvarado<br>Enrique Sotelo<br>Electrical                            |           | Loma Linda ES           |
| 4593  | Work In Progress<br>MIKE MUNOZ, REPLACE EAST FENCE  | 8/16/2005<br>Medium                         | Grace Alvarado<br>Michael Munoz<br>Fence Repair                           |           | Loma Linda ES           |
| 3829  | Work In Progress<br>MR. TRUJILLO IS WANTING NEW KEYS MADE<br>FOR DESKS, CABINETTS AND FILE CABINETS.<br>ALSO NEEDING NAME PLATE FOR NEW<br>TEACHERS. MS. BERARD, CHAVEZ-FISHER,<br>GRIEGO, DESANTIAGO, HUGHES, MARKHAM,<br>MEDINA, MERRICK, MONTES, PINA, PRICE, RIOS-<br>ALVILLAR, | 7/26/2005<br>Medium                         | Grace Alvarado<br>Manny Lozoya<br>Key and Lock                            |           | Loma Linda ES           |
| 11396 | Work In Progress<br>MANNY LOZOYA: INSTALL LOCK FOR FILE<br>CABINETT. MIKE AMAYA ROOM 107 ASAP<br>(SECURITY REASON)  | 4/18/2006<br>Medium                         | Grace Alvarado<br>Manny Lozoya<br>Key and Lock                            |           | Loma Linda ES           |
| 11425 | Work In Progress<br>MANNY LOZOYA; INSTALL NEW LOCK ON<br>EAST WING GATE.  | 4/19/2006<br>Medium                         | Grace Alvarado<br>Manny Lozoya<br>Key and Lock                            |           | Loma Linda ES           |
| 10133 | Work In Progress<br>MANNY LOZOYA, MEN BATHROOM IN SECOND<br>GRADE LOST TUMBLER. TUMBLER CAN BE<br>FOUND IN THE OFFICE   | 3/2/2006<br>Medium                          | Grace Alvarado<br>Manny Lozoya<br>Key and Lock                            |           | Loma Linda ES           |
| 9219  | Work In Progress<br>MANNY. REPAIR NE GATE. LOCK IS BROKEN   | 2/1/2006<br>Medium                          | Grace Alvarado<br>Manny Lozoya<br>Key and Lock                            |           | Loma Linda ES           |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                           | Area Type | Location<br>Area Number |
|-------|--|---|---|-----------|-------------------------|
| 9897  | Work In Progress<br>MIKE MCDERMOTT: REQUEST REPAIR OR REPLACEMENT OF VENETIAN BLINDS, PARTICULARLY WINDOW ON NORTH ISE OF EAST WALL ROOM 103 LET ME KNOW. AS PER MR. T.  | 2/21/2006<br>Medium                         | Grace Alvarado<br>Ruben Ronquillo<br>Glass\Window Repairs   |           | Loma Linda ES           |
| 9831  | Work In Progress<br>ATTN: PLUMBERS<br>NEED KIT INSTALLED TO BOLT TOILET TO FLOOR & NEW BOWLI WAY. BOYS R.R. NORTHWEST WING. NEED SENSOR SINKS REPAIRED. 2ND REQUEST LEAKING VERY BADLY. BOYS RR SOUTH WEST WING. NEED NEW HOSE BIB INSTALLED IN COURTYARD BEHIND LIBRARY. OLD ONE WILL NOT CLOSE.  | 2/17/2006<br>Medium                         | Grace Alvarado<br>Joe Ontiveros<br>Plumbing                 |           | Loma Linda ES           |
| 8143  | Work In Progress<br>MIKE INSTALL OUTLET IN BOOKROOM  | 12/15/2005<br>Medium                        | Grace Alvarado<br>Michael Mc Dermott<br>General Maintenance |           | Loma Linda ES           |
| 699   | Work In Progress<br>need window latches for rms 103-106-105-204 asap- need to secure windows at end of day- sent sample to ppd   | 3/30/2005<br>Medium                         | Danny Vega<br>Danny Miranda<br>Doors and Hardware           | Classroom | Loma Linda ES           |
| 11463 | Work In Progress<br>NEED TO COMPLETE FLOOR PLAN ON YOUR WORK SCHEDULE.   | 4/20/2006<br>Medium                         | Aida Salcedo<br>Custodial                                   |           | Loma Linda ES           |
| 8647  | Work In Progress<br>NEED TO COMPLETE BUILDING INSPECTION FOR ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOU OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED & SIGNED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JANUARY 27, 2006 | 1/11/2006<br>Medium                         | Aida Salcedo<br>Luis Solis<br>Custodial                     |           | Loma Linda ES           |
| 11462 | Work In Progress<br>NEED TO COMPLETE FLOOR PLAN ON YOUR WORK SCHEDULE.   | 4/20/2006<br>Medium                         | Aida Salcedo<br>Custodial                                   |           | Mesquite ES             |
| 10921 | Work In Progress<br>Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Romauldo Apodaca<br>Fire Extinguishers   |           | Mesquite ES             |
| 10242 | Work In Progress<br>Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.  | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Romauldo Apodaca<br>General Maintenance  |           | Mesquite ES             |
| 10252 | Work In Progress<br>Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.  | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Romauldo Apodaca<br>General Maintenance  |           | Mesquite ES             |

| <b>WOID</b> | <b>Status<br/>Description<br/>Action Taken</b>  | <b>Request Date<br/>Completion Date<br/>Priority</b> | <b>Requester<br/>Assigned To<br/>Craft</b>                 | <b>Area Type</b> | <b>Location<br/>Area Number</b> |
|-------------|---|--|--|------------------|---------------------------------|
| 10208       | Work In Progress<br>Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.   | 3/5/2006<br>Medium                                   | Alfredo Holguin<br>Romauldo Apodaca<br>Fire Extinguishers  |                  | Mesquite ES                     |
| 9132        | Work In Progress<br>please remove grass and tiller ,then level on the enviromental park as per our discussion and reiev of the plans.   | 1/30/2006<br>Medium                                  | Guadalupe Ontiveros<br>Grounds                             | Athletic Field   | Mesquite ES                     |
| 3324        | Work In Progress<br>Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.   | 7/6/2005<br>Medium                                   | Alfredo Holguin<br>Romauldo Apodaca<br>Fire Protection     |                  | Mesquite ES                     |
| 11004       | Work In Progress<br>Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.   | 4/2/2006<br>Medium                                   | Alfredo Holguin<br>Romauldo Apodaca<br>General Maintenance |                  | Mesquite ES                     |
| 11014       | Work In Progress<br>Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.   | 4/2/2006<br>Medium                                   | Alfredo Holguin<br>Romauldo Apodaca<br>General Maintenance |                  | Mesquite ES                     |
| 10939       | Work In Progress<br>Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.   | 4/2/2006<br>Medium                                   | Alfredo Holguin<br>Romauldo Apodaca<br>Roof                |                  | Mesquite ES                     |
| 11190       | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006. | 4/7/2006<br>Medium                                   | Aida Salcedo<br>Ruben Solis<br>Custodial                   |                  | Mesquite ES                     |
| 3346        | Work In Progress<br>Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.   | 7/6/2005<br>Medium                                   | Alfredo Holguin<br>Romauldo Apodaca<br>Fire Protection     |                  | Mesquite ES                     |
| 3971        | Work In Progress<br>Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.   | 7/31/2005<br>Medium                                  | Alfredo Holguin<br>Romauldo Apodaca<br>Fire Extinguishers  |                  | Mesquite ES                     |
| 4005        | Work In Progress<br>Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.   | 7/31/2005<br>Medium                                  | Alfredo Holguin<br>Romauldo Apodaca<br>General Maintenance |                  | Mesquite ES                     |
| 4015        | Work In Progress<br>Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.   | 7/31/2005<br>Medium                                  | Alfredo Holguin<br>Romauldo Apodaca<br>General Maintenance |                  | Mesquite ES                     |
| 9135        | Work In Progress<br>Barracks - Remove rocks from roof and repair and secure water lines (safety issue).   | 1/30/2006<br>Medium                                  | Michael Munoz<br>Romauldo Apodaca<br>General Maintenance   |                  | Mesquite ES                     |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft  | Area Type | Location<br>Area Number |
|-------|--|---|--|-----------|-------------------------|
| 9137  | Work In Progress<br>East of Library - Lots of weeds growing apply chemical, treat weeds ask for input from Lupe so you wont kill trees.                      | 1/30/2006<br>Medium                         | Michael Munoz<br>Romauldo Apodaca<br>General Maintenance                   |           | Mesquite ES             |
| 9138  | Work In Progress<br>Pecan Trees in back parking lot - Trim branches, cut weeds around and make new wells and water.  | 1/30/2006<br>Medium                         | Michael Munoz<br>Romauldo Apodaca<br>General Maintenance                   |           | Mesquite ES             |
| 9139  | Work In Progress<br>North Fence Line by Pine Trees - Cut weeds and pickup trash and treat fence line.  | 1/30/2006<br>Medium                         | Michael Munoz<br>Romauldo Apodaca<br>General Maintenance                   |           | Mesquite ES             |
| 2116  | Work In Progress<br>BERNICE SAPIEN - ROOM 304<br>NEED A NEW LOCK FOR FILING CABINET - KEY BROKE INSIDE LOCK.   | 5/19/2005<br>Medium                         | Luz Griego<br>Manny Lozoya<br>Key and Lock                                 | Classroom | Mesquite ES             |
| 10758 | Work In Progress<br>Need a gate key for Gloria Martinez w/PSFA.  | 3/28/2006<br>Medium                         | Peggy Jo Hernandez<br>Manny Lozoya<br>Key and Lock                         |           | Mesquite ES             |
| 11725 | Work In Progress<br>armstrong unit in portable 611 not working. need to assit w/ unit.   | 4/28/2006<br>Medium                         | Romauldo Apodaca<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning |           | Mesquite ES             |
| 10061 | Work In Progress<br>broken master key need one right away,thanx.   | 2/28/2006<br>Medium                         | Romauldo Apodaca<br>Manny Lozoya<br>Key and Lock                           |           | Mesquite ES             |
| 9935  | Work In Progress<br>MANNY, NEED TO HELP W/ OPENING STORAGE RM. TRIED TO OPEN BUT CAN,T. THANX.   | 2/23/2006<br>Medium                         | Romauldo Apodaca<br>Manny Lozoya<br>Key and Lock                           |           | Mesquite ES             |
| 9937  | Work In Progress<br>DANNY MIRANDA, NEED DOOR HARDEWARE FOR CAFETERIA DOORS, AND MAIN DOORS. THANX.   | 2/23/2006<br>Medium                         | Romauldo Apodaca<br>Danny Miranda<br>Doors and Hardware                    |           | Mesquite ES             |
| 8677  | Work In Progress<br>Portable 602 - Need vinyl flooring replaced w/ carpet, floor in bad shape,safety issue, someone may trip.                                | 1/12/2006<br>Medium                         | Romauldo Apodaca<br>Michael Munoz<br>Carpet Repair                         | Portables | Mesquite ES             |
| 7825  | Work In Progress<br>NEED TO RUN ELECTRICAL LINES TO MAIN FIELD FOR RED RIBBON CUTTING CEROMONY ON 12/8/05 AT 6:AM FOR HEATERS AND LIGHTING,PER MS. PHILLIPS. | 12/5/2005<br>Medium                         | Romauldo Apodaca<br>Enrique Sotelo<br>Electrical                           |           | Mesquite ES             |
| 11634 | Work In Progress<br>lorenzo,broken water fountain in cafeteria.need to replace.thanx.  | 4/26/2006<br>Medium                         | Romauldo Apodaca<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning |           | Mesquite ES             |
| 11635 | Work In Progress<br>need motor for exsaust fan electrical rm.thanx.  | 4/26/2006<br>Medium                         | Romauldo Apodaca<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning |           | Mesquite ES             |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft   | Area Type | Location<br>Area Number         |
|-------|---|---|---|-----------|---------------------------------|
| 11570 | Work In Progress<br>kiki need to assit w/ emergency light, ballast.   | 4/25/2006<br>Medium                         | Romauldo Apodaca<br>Enrique Sotelo<br>Electrical                              |           | Mesquite ES                     |
| 11572 | Work In Progress<br>lorenzo, split system in electrical rm main hallway not working.  | 4/25/2006<br>Medium                         | Romauldo Apodaca<br>Lorenzo Solis<br>Heating/Ventilation /Air<br>Conditioning |           | Mesquite ES                     |
| 11284 | Work In Progress<br>portable 602 lever handle does not work. rm. 101 door knob does not open.rm. 112. door knob hard to open. | 4/11/2006<br>Medium                         | Romauldo Apodaca<br>Manny Lozoya<br>Key and Lock                              |           | Mesquite ES                     |
| 11103 | Work In Progress<br>need door frame and door for rm. 612,door in very bad conditon.thanx.                                     | 4/5/2006<br>Medium                          | Romauldo Apodaca<br>Danny Miranda<br>Doors and Hardware                       |           | Mesquite ES                     |
| 10714 | Work In Progress<br>need to open dry storage in kitchen for sound and signal. thanx   | 3/27/2006<br>Medium                         | Romauldo Apodaca<br>Manny Lozoya<br>Key and Lock                              |           | Mesquite ES                     |
| 10130 | Work In Progress<br>need to replace lever handle in sanchez portable,security issue. thanx.                                   | 3/2/2006<br>Medium                          | Romauldo Apodaca<br>Manny Lozoya<br>Key and Lock                              |           | Mesquite ES                     |
| 3558  | Work In Progress<br>need compresor changed out on armstrong unit in rm. 608.thanx.  | 7/14/2005<br>Medium                         | Romauldo Apodaca<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning   |           | Mesquite ES                     |
| 2664  | Work In Progress<br>need tile replaced rm. 113,111,110. 602 carpet instead of tile.   | 6/9/2005<br>Medium                          | Romauldo Apodaca<br>Michael Munoz<br>Carpet Repair                            | Classroom | Mesquite ES<br>602,113,111,110. |
| 1619  | Work In Progress<br>have leak between wall in rm. 401 rest rm.thanx.  | 5/3/2005<br>Medium                          | Romauldo Apodaca<br>Fred Appelzoller<br>Plumbing                              |           | Mesquite ES                     |
| 1621  | Work In Progress<br>need replacement of a/c side draft in portable 610.   | 5/3/2005<br>Medium                          | Romauldo Apodaca<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning   |           | Mesquite ES                     |
| 1622  | Work In Progress<br>need replacement of indusrial unit on barracks,per phillips and leyva.                                    | 5/3/2005<br>Medium                          | Romauldo Apodaca<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning   |           | Mesquite ES                     |
| 971   | Work In Progress<br>NEED FILING CABINETS CYLINDERS REPLACED.THANX.  | 4/8/2005<br>Medium                          | Romauldo Apodaca<br>Manny Lozoya<br>Key and Lock                              |           | Mesquite ES                     |
| 2152  | Work In Progress<br>PORTABLE 612 - DOOR HANDLE BROKEN.  | 5/20/2005<br>Medium                         | Romauldo Apodaca<br>Manny Lozoya<br>Key and Lock                              | Portables | Mesquite ES                     |
| 4699  | Work In Progress<br>manny need your assistance w/ doors that are hard to open and close. thanx.                               | 8/19/2005<br>Medium                         | Romauldo Apodaca<br>Manny Lozoya<br>Key and Lock                              |           | Mesquite ES                     |



| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft   | Area Type | Location<br>Area Number |
|-------|--|---|---|-----------|-------------------------|
| 4340  | Work In Progress<br>manny need to assist w/ 2 doors in porables<br>having hard time tpo close safety issue. also<br>need lever handle.   | 8/9/2005<br>Medium                          | Romauldo Apodaca<br>Manny Lozoya<br>Key and Lock                            |           | Mesquite ES             |
| 3955  | Work In Progress<br>DINING AREA - NEED TO WELD HINGES ON<br>DOOR FALLING DOWN.   | 7/29/2005<br>Medium                         | Romauldo Apodaca<br>Manny Lozoya<br>Key and Lock                            |           | Mesquite ES             |
| 6507  | Work In Progress<br>kiki, 5 rms w/ out lights need assistance.thanks.<br>ARREGLAR PROBLEMA EN ALAMBRADO DE<br>LUCES EN SALONES DE OLD WING.  | 10/18/2005<br>10/18/2005<br>Medium          | Romauldo Apodaca<br>Romauldo Apodaca<br>Electrical                          |           | Mesquite ES             |
| 6508  | Work In Progress<br>jaime need to assist w/ boilers to change over to<br>heating,also need gas valve for heater in old<br>office.thanx.  | 10/18/2005<br>Medium                        | Romauldo Apodaca<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Mesquite ES             |
| 8822  | Work In Progress<br>Front Entrance Blue Double Doors - Cylinders<br>need to be cleaned.  | 1/18/2006<br>Medium                         | Peggy Jo Hernandez<br>Manny Lozoya<br>Key and Lock                          |           | Physical Plant Complex  |
| 7834  | Work In Progress<br>Need to make a key for D. Miranda's Office for<br>Ruben.   | 12/5/2005<br>Medium                         | Ruben Ronquillo<br>Manny Lozoya<br>Key and Lock                             |           | Physical Plant Complex  |
| 2997  | Work In Progress<br>TRANSP. OFFICE - NEED TO RELOCATE ELEC.<br>OUTLETS A/S/A/P.  | 6/27/2005<br>Medium                         | Sitters Walter<br>Enrique Sotelo<br>Electrical                              |           | Physical Plant Complex  |
| 8774  | Work In Progress<br>I would like to request the "Student Records<br>Office" sign be moved from the north outside<br>wall of the loading bay to the wall beside the<br>Records Room door and also the door leading<br>into the warehouse by the rec. room re-painted<br>with "Student Records Office" Inside. | 1/17/2006<br>Medium                         | Tracey Swinford<br>Rudy Arreola<br>General Maintenance                      |           | Physical Plant Complex  |
| 9057  | Work In Progress<br>PPD Barracks - Need to run power to existing<br>panel box. (Coordinate w/eachother Cali, Enrique<br>and Mike Mc Dermott).  | 1/26/2006<br>Medium                         | Michael Munoz<br>Enrique Sotelo<br>Electrical                               |           | Physical Plant Complex  |
| 353   | Work In Progress<br>Need to installing emerg. lights as per pm 125559.   | 3/14/2005<br>Medium                         | Rudy Arreola<br>Enrique Sotelo<br>Electrical                                |           | Physical Plant Complex  |
| 11268 | Work In Progress<br>NEED "CB-4" KEY TO HAVE AS AN EXTRA<br>WHEN NEEDED FOR CUSTODIAL TRAINING<br>VIDEOS.   | 4/11/2006<br>Medium                         | Maria Sitters<br>Manny Lozoya<br>Key and Lock                               |           | Physical Plant Complex  |
| 5121  | Work In Progress<br>Power Outage - El Paso Electric  | 8/29/2005<br>Medium                         | Margret Villalobos<br>Enrique Sotelo<br>Electrical                          |           | Physical Plant Complex  |
| 3940  | Work In Progress<br>MARTA JACQUEZ - A/C UNIT IS NOT WORKING<br>AT ALL.   | 7/29/2005<br>Medium                         | Marta Jacquez<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning    |           | Physical Plant Complex  |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                       | Area Type        | Location<br>Area Number |
|-------|---|---|---|------------------|-------------------------|
| 2657  | Work In Progress<br>LADIES RR - THE FAUCET SHOOTS THE WATER OUT IN UNEVEN SPURTS AND ON THE TOILET THE LINE CONNECTING TO THE WALL, MAKES A LOUD SOUND AND RATTLES AND THE WATER FILLING IN COMES IN DIRTY. | 6/9/2005<br>Medium                          | Marta Jacquez<br>Fred Appelzoller<br>Plumbing                           | Restroom (Girls) | Physical Plant Complex  |
| 1673  | Work In Progress<br>Transporation Office - Need to install door w/window.   | 5/5/2005<br>Medium                          | Margret Villalobos<br>Danny Miranda<br>Doors and Hardware               |                  | Physical Plant Complex  |
| 2263  | Work In Progress<br>Maint. Office - Need to fix door closer to main door.   | 5/24/2005<br>Medium                         | Margret Villalobos<br>Manny Lozoya<br>Key and Lock                      |                  | Physical Plant Complex  |
| 11710 | Work In Progress<br>Need to get a/c's going.  | 4/27/2006<br>Medium                         | Michael Munoz<br>Danny Orozco<br>Food Services                          |                  | Physical Plant Complex  |
| 11711 | Work In Progress<br>Need to get a/c's going.  | 4/27/2006<br>Medium                         | Michael Munoz<br>Rudy Arreola<br>General Maintenance                    |                  | Physical Plant Complex  |
| 11712 | Work In Progress<br>Maint. Shops - Need to get a/c's going.   | 4/27/2006<br>Medium                         | Michael Munoz<br>Rudy Arreola<br>General Maintenance                    |                  | Physical Plant Complex  |
| 11574 | Work In Progress<br>please primer and paint barracks.   | 4/25/2006<br>Medium                         | Michael Munoz<br>Danny Miranda<br>Painting                              |                  | Physical Plant Complex  |
| 4017  | Work In Progress<br>Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.  | 7/31/2005<br>Medium                         | Alfredo Holguin<br>Rudy Arreola<br>General Maintenance                  |                  | Physical Plant Complex  |
| 2357  | Work In Progress<br>Custodial Office - Need to correct cooling in Mary and Aida's Office.   | 5/27/2005<br>Medium                         | Alfredo Holguin<br>Jaime Gomez<br>Heating/Ventilation /Air Conditioning | Custodial        | Physical Plant Complex  |
| 3092  | Work In Progress<br>Install Speed limit signs and speed bumps on access road. See me on specifics<br>Faxed PO on 8/4/05 - mkv   | 6/30/2005<br>8/8/2005<br>Safety             | Alfredo Holguin<br>Michael Munoz<br>General Maintenance                 |                  | Physical Plant Complex  |
| 3461  | Work In Progress<br>Need a copy of control key (core) to keep here at the Maintenance Dept - as per A. Holguin.   | 7/12/2005<br>Medium                         | Alfredo Holguin<br>Manny Lozoya<br>Key and Lock                         |                  | Physical Plant Complex  |
| 3186  | Work In Progress<br>Monthly - Physical Plant FE Inspection - Refer to PM schedule details.  | 7/3/2005<br>Medium                          | Alfredo Holguin<br>Rudy Arreola<br>Fire Extinguishers                   |                  | Physical Plant Complex  |
| 7711  | Work In Progress<br>please order all material needed to paint barracks in the back and let me know what staff will be need to accomplish the project.   | 12/1/2005<br>Medium                         | Danny Miranda<br>Painting   | Portables        | Physical Plant Complex  |
| 10419 | Work In Progress<br>Need to open Barrack for Melissa w/Finance on Monday, March 13th. She will be here at 10:00 am. -Thanks mkv   | 3/10/2006<br>3/7/2006<br>Medium             | Manny Lozoya<br>Key and Lock  |                  | Physical Plant Complex  |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft   | Area Type       | Location<br>Area Number |
|-------|--|---|---|-----------------|-------------------------|
| 5526  | Work In Progress<br>NEED A "CB4" KEY FOR GUILLERMO - TO HAVE ACCESS TO ENERGY OFFICE TO CLEAN.   | 9/15/2005<br>Medium                         | Manny Lozoya<br>Key and Lock  |                 | Physical Plant Complex  |
| 2235  | Work In Progress<br>please order material for fill for district portable re-location. please include site and material that will be delivered on w.o . (per site)                                      | 5/24/2005<br>Medium                         | Lorenzo Hernandez<br>Grounds  |                 | Physical Plant Complex  |
| 3379  | Work In Progress<br>Mens Restroom in Custodial Warehouse -Install new privacy lockset  | 7/7/2005<br>Low                             |   | Restroom (Boys) | Physical Plant Complex  |
| 3380  | Work In Progress<br>Mens Restroom in Custodial Warehouse- Replace toilet tank cover with appropriate size for unit.  | 7/7/2005<br>Medium                          | Fred Appelzoller<br>Plumbing  | Restroom (Boys) | Physical Plant Complex  |
| 7810  | Work In Progress<br>Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.   | 12/4/2005<br>Medium                         | Alfredo Holguin<br>Rudy Arreola<br>General Maintenance                    |                 | Physical Plant Complex  |
| 7642  | Work In Progress<br>Auto Shop - Need to install 4 cylinders all the same but different from main entrance. Need 4 keys issued (see Angel).   | 11/30/2005<br>Medium                        | Angel Gonzales<br>Manny Lozoya<br>Key and Lock                            |                 | Physical Plant Complex  |
| 7772  | Work In Progress<br>Monthly - Physical Plant FE Inspection - Refer to PM schedule details.   | 12/4/2005<br>Medium                         | Alfredo Holguin<br>Rudy Arreola<br>Fire Extinguishers                     |                 | Physical Plant Complex  |
| 8737  | Work In Progress<br>NEED SPARE KEY FOR AIDA (TRUCK) - P1106 BB6  | 1/13/2006<br>Medium                         | Aida Salcedo<br>Manny Lozoya<br>Key and Lock                              |                 | Physical Plant Complex  |
| 9749  | Work In Progress<br>WILL NEED ELECTRICAL WORK DONE IN CUSTODIAL WAREHOUSE TO BE ABLE TO INSTALL NEW WASHER & DRYER - MUST BE DONE BY FEBUARY 24, 2005.   | 2/16/2006<br>Medium                         | Aida Salcedo<br>Enrique Sotelo<br>Electrical                              |                 | Physical Plant Complex  |
| 9750  | Work In Progress<br>WILL NEED PLUMBING WORK DONE IN CUSTODIAL WAREHOUSE TO BE ABLE TO INSTALL NEW WASHER & DRYER - MUST BE DONE BY FEBUARY 24, 2005.<br>4/24/06 - Please assist Joe w/this work order. | 2/16/2006<br>Medium                         | Aida Salcedo<br>Joe Ontiveros<br>Plumbing                                 | Custodial       | Physical Plant Complex  |
| 11566 | Work In Progress<br>Need to replace exhuaast fan motor   | 4/24/2006<br>Medium                         | Carlos Castillo<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning | Restroom (Boys) | Physical Plant Complex  |
| 5432  | Work In Progress<br>Auto Shop - need to install new door knob to new door at Angel's Office.   | 9/12/2005<br>Medium                         | Danny Miranda<br>Manny Lozoya<br>Key and Lock                             |                 | Physical Plant Complex  |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                     | Area Type       | Location<br>Area Number |
|-------|--|---|---|-----------------|-------------------------|
| 1309  | Work In Progress<br>Need to make material list and request for general maintenance duties  | 4/21/2005<br>Medium                         | Carlos Castillo<br>Carlos Castillo<br>Electrical      | Electrical Room | Physical Plant Complex  |
| 4585  | Work In Progress<br>Need to replace water heater,its giving out an extremeley bad odor.Health issue.   | 8/16/2005<br>Medium                         | Carlos Castillo<br>Joe Ontiveros<br>Plumbing          | Electrical Room | Physical Plant Complex  |
| 9950  | Work In Progress<br>2/21/06<br>(2)7910<br>(4)unload materials for chaparral elen. @ san miguel elem.<br>(1.5)exchange corner bead @ foxworth<br>(.5)back to vado elem.<br><br>2/21-6   | 2/23/2006<br>Medium                         | Danny Miranda<br>Danny Miranda<br>Doors and Hardware  |                 | Physical Plant Complex  |
| 8634  | Work In Progress<br>As per Mike Vehicle # 23 (Manny Lozoya Van) needs new tires.   | 1/11/2006<br>Medium                         | Manny Lozoya<br>Angel Gonzales<br>Vehicle Maintenance |                 | Physical Plant Complex  |
| 11459 | Work In Progress<br>ENRIQUE SOTELO<br>WOULD YOU PLEASE INSTAL THE ELECTREICAL HOOK UP TO INSTALL THE DRYER.<br>THANK YOU   | 4/20/2006<br>Medium                         | Guillermo Hernandez<br>Enrique Sotelo<br>Electrical   | Custodial       | Physical Plant Complex  |
| 2631  | Work In Progress<br>Need to replace door knob to outside Double Doors.   | 6/8/2005<br>Medium                          | HECTOR LOZOYA<br>Manny Lozoya<br>Key and Lock         |                 | Physical Plant Complex  |
| 10175 | Work In Progress<br>DISHWASHER - WHERE THE SOAP GOES THRU IS CLOGGED UP.<br><br>NANCY ROLLIN SNP MGR 589-2550  | 3/3/2006<br>Medium                          | Jacqueline Aguilar<br>Danny Orozco<br>Food Services   | Cafeteria       | Riverside ES            |
| 11591 | Work In Progress<br>drain clogged up to vegetable sink<br><br>Virginia Pruitt - Substitute Manager 589-2550  | 4/25/2006<br>Medium                         | Alma Terrell<br>Danny Orozco<br>Food Services         | Cafeteria       | Riverside ES            |
| 2088  | Work In Progress<br>PLEASE REMOVE OLD SEAL, INSTALL NEW ONE WITH NEW CAULKING AND 45 CONCRETE AGAINST WALL AND FLOOR. OUTSIDE PATIO WHERE MAIN HALL WAY ENTERS TOWARDS CAFETERIA. THIS WILL PREVENT WATER FROM ENTERING TO BUILDING. | 5/18/2005<br>Medium                         | Adan Duran<br>General Maintenance                     | Cafeteria       | Riverside ES            |
| 5592  | Work In Progress<br>please see what can be done to repair or remove electrical outlet on floor on serving line. Outlet has a can over it and could be a trip hazard.   | 9/19/2005<br>Medium                         | Danny Orozco<br>Food Services                         | Cafeteria       | Riverside ES            |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                     | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 11681 | Work In Progress<br>Break-In on 4/24/06<br>Windows Broken -   | 4/27/2006<br>Medium                         | Ruben Ronquillo<br>Glass\Window Repairs                               |           | Riverside ES            |
| 11306 | Work In Progress<br>MR MANNY LOZOYA SIR HAVE A DOOR THAT<br>IS JAMED NEED YOUR HELP MAY NEED TO<br>REPLACE I THANK YOU SIR AND GOD BLESS  | 4/12/2006<br>Medium                         | Adan Duran<br>Manny Lozoya<br>Key and Lock                            |           | Riverside ES            |
| 11420 | Work In Progress<br>MR JOSE AMBRIZ SIR WILL NEED TO REPLACE<br>AC UNIT ROOM 31 ITS RUSTED REAL BAD 6500<br>PADS ARE 12" WATER STARTING GO GET IN TO<br>ROOM THROUGH DUCT THANK YOU SIR AND<br>GOD BLESS   | 4/19/2006<br>Medium                         | Adan Duran<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning |           | Riverside ES            |
| 11611 | Work In Progress<br>MR CARLOS CASTILLO SIR WILL NEED<br>SEVERAL BOXS OF FLORCENT LAMPS WILL<br>NEED BELEAST HALL WAY LIGHTS AND BULBS<br>I THANK YOU SIR AND GOD BLESS  | 4/25/2006<br>Medium                         | Adan Duran<br>Carlos Castillo<br>Electrical                           |           | Riverside ES            |
| 10717 | Work In Progress<br>MR MIKE MUNOZ AND RUBEN RONQILLO SIR I<br>WOULK LIKE TO EXCHANGE COMODE OGER<br>HAS A KINK IN THE CABLE ALSO WOULD LIKE<br>TO EXCHANGE BLOWER LEAKS ALOT AND<br>KEEPS GETTING CHOKE THANK YOU SIR AND<br>GOD BLESS  | 3/27/2006<br>Medium                         | Adan Duran<br>Ruben Ronquillo<br>Equipment                            |           | Riverside ES            |
| 10642 | Work In Progress<br>3/17/06 SIGN IN CHECK SCHOOL GROUNDS<br>BUILDING FENCE 2 DIG OUT AND REPAIR<br>BROKEN WATER LINE 11/2 REPAIR 5 BROKEN<br>BUBBLERS VANDELS 21/2 WO 10582<br>CHANGE OUT BURN OUT SWITCH AC<br>COMPUTER LAB CHANGE OUT BURN OUT<br>SWITCHS REZNOR HEATERS RM 101 AND 145<br>1/2 CLOSE WEST AND DROP OFF GATES 1<br>FILE PAPER WORK REPORT AND SIGN OUT<br>3/17-5.5 | 3/17/2006<br>3/27/2006<br>Medium            | Adan Duran<br>Adan Duran<br>General Maintenance                       |           | Riverside ES            |
| 9856  | Work In Progress<br>NEED TAGS TO TAG FIRE EXTINGUISHERS AS<br>PER PM 9346.  | 2/17/2006<br>Medium                         | Adan Duran<br>Ruben Ronquillo<br>Fire Extinguishers                   |           | Riverside ES            |
| 9714  | Work In Progress<br>NORTH ENTRANCE DOUBLE DOORS -<br>AUTOMATIC DOOR CLOSER IS LEAKING ALOT<br>OF OIL AND DOOR IS CLOSING FAST.  | 2/15/2006<br>Medium                         | Adan Duran<br>Manny Lozoya<br>Key and Lock                            |           | Riverside ES            |
| 9734  | Work In Progress<br>MR CARLOS CASTILLO SIR WE HAVE SEVERAL<br>EMERGENCY LIGHT THAT NEED BATTRIES WILL<br>NEED 6 AT THIS TIME THANK YOU SIR  | 2/15/2006<br>Medium                         | Adan Duran<br>Carlos Castillo<br>Electrical                           |           | Riverside ES            |

| WOID | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                     | Area Type | Location<br>Area Number |
|------|---|---|---|-----------|-------------------------|
| 8661 | Work In Progress<br>MR CARLOS CASTILLO SIR WILL NEED SOME<br>LAMPS SOME U LAMPS HALL WAY LAMPS<br>SOME PL 13 SOME METAL HALIDE THANK YOU<br>VERY MUCH SIR   | 1/11/2006<br>Medium                         | Adan Duran<br>Carlos Castillo<br>Electrical                           |           | Riverside ES            |
| 8225 | Work In Progress<br>12/20/05 1/2 SIGN IN CHECK SCHOOL<br>GROUNDS 6 PAINT BATHROOMS 1/2 WASH<br>ROLLERS AND PAINT BRUSH AND PAN 1 FILE<br>PAPER WORK AND SIGN OUT<br>12/20 - 8   | 12/20/2005<br>Medium                        | Adan Duran<br>Adan Duran<br>General Maintenance                       |           | Riverside ES            |
| 7156 | Work In Progress<br>11/7/05 1/2 SIGN IN CHECK SCHOOL GROUNDS<br>2 1/2 MOWED GRASS 1 1/2 EDGE WITH<br>TRIMER 1 CLEAN SIDEWALKS WITH BLOWER 1<br>REPAIR ENTRANCE DOOR WILL NOT CLOSE 1/2<br>CLOSE WEST AND DROP OFF GATES 1 FILE<br>PAPER WORK AND SIGN OUT<br>11/7 - 8 | 11/7/2005<br>Medium                         | Adan Duran<br>Adan Duran<br>General Maintenance                       |           | Riverside ES            |
| 5115 | Work In Progress<br>MR LUPE ONTIVEROS SIR WILL NEED THE USE<br>OF THE BACKHOE TO MOVE SOCCOR GOAL<br>POST AWAY FROM PARKING AREA UNSAFE<br>FOR KIDS THANK YOU SIR   | 8/31/2005<br>Medium                         | Adan Duran<br>Guadalupe Ontiveros<br>Grounds                          |           | Riverside ES            |
| 4596 | Work In Progress<br>MR MANNY LOYZOA SIR NEED TO CHANGE<br>OUT DOOR HANDLE BY MRS ARIAS OFFICE<br>THE ONE THERE DO NOT LOCK NEED ONE THAT<br>CAN BE LOCKED THANK YOU SIR   | 8/16/2005<br>Medium                         | Adan Duran<br>Manny Lozoya<br>Doors and Hardware                      |           | Riverside ES            |
| 4473 | Work In Progress<br>MR MANNY LOZOYA SIR THE DOOR ON NEW<br>PORTABLE IS STUCK IN LOCK CAN NOT GET IT<br>TO UNLOCK PORTABLE B IN BACK THANK<br>YOU SIR  | 8/11/2005<br>Medium                         | Adan Duran<br>Manny Lozoya<br>Key and Lock                            | Portables | Riverside ES            |
| 4388 | Work In Progress<br>MR JOSE AMBRIZ SIR WE NEED TO HOOK BACK<br>UP THE AIR IN WHAT USE TO BE MRS FLORES<br>OFFICE IT WAS REMOVE AT HER REQUEST AND<br>ITS KIND OF WARM IN THERE THANK YOU SIR  | 8/9/2005<br>Medium                          | Adan Duran<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning |           | Riverside ES            |
| 3690 | Work In Progress<br>MR MANNY LOZOYA FILE CABINET NEW<br>PORTABLE RM B NEEDS REPAIR WILL NOT<br>LOCK PARTS MISSING THANK YOU SIR   | 7/19/2005<br>Medium                         | Adan Duran<br>Manny Lozoya<br>Key and Lock                            |           | Riverside ES            |
| 3778 | Work In Progress<br>MR DAVID VILLALOBOS WE HAVE SOME<br>LEAKING FUACTS NEW WING NEED REPAIR KIT<br>OR REPLACEMENT THANK YOU SIR   | 7/22/2005<br>Medium                         | Adan Duran<br>David Villalobos<br>Plumbing                            |           | Riverside ES            |
| 3414 | Work In Progress<br>MR LOZOYA MRS ARIAS IS HAVING TROUBLE<br>WITH THE STORAGE ROOM LOCK WOULD LIKE<br>FOR YOU TO LOOK AT IT THANK YOU SIR   | 7/8/2005<br>Medium                          | Adan Duran<br>Manny Lozoya<br>Key and Lock                            |           | Riverside ES            |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft  | Area Type | Location<br>Area Number |
|-------|---|---|--|-----------|-------------------------|
| 3326  | Work In Progress<br>Yearly - Riverside ES Emer. Light Test: Annual -<br>Refer to PM schedule details.   | 7/6/2005<br>Medium                          | Alfredo Holguin<br>Adan Duran<br>Fire Protection                         |           | Riverside ES            |
| 10972 | Work In Progress<br>Monthly - Riverside ES Fire Suppression Insp. -<br>Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System                 |           | Riverside ES            |
| 3348  | Work In Progress<br>Yearly - Riverside ES Exit Sign Test: Annual -<br>Refer to PM schedule details.   | 7/6/2005<br>Medium                          | Alfredo Holguin<br>Adan Duran<br>Fire Protection                         |           | Riverside ES            |
| 11191 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE<br>INSPECTIONS ON ALL CUSTODIANS TO INCLUDED<br>CLOSET, MSDS, LABELED SPRAY BOTTLES &<br>SAFETY EQUIPMENT. HEAD CUSTODIANS NEED<br>TO INCLUDE INSPECTION OF YOUR OWN AREA.<br>INSPECTION REPORTS ALONG WITH<br>COMPLETED WORK ORDER MUST BE RETURNED<br>AND RECEIVED BY US NO LATER THAN APRIL<br>21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Raul Romero<br>Custodial                                 |           | Riverside ES            |
| 2540  | Work In Progress<br>Need copies (3) made of regular master padlocks<br>located in halls used to secure exits with chain.  | 6/6/2005<br>Medium                          | Miguel Aguilar<br>Manny Lozoya<br>Key and Lock                           |           | Riverside ES            |
| 5057  | Work In Progress<br>We need a new Door Knob placed in the Data<br>Clerk office. (office area) At this time the door<br>doesn't lock.  | 8/30/2005<br>Medium                         | Olga Arias<br>Manny Lozoya<br>Key and Lock                               |           | Riverside ES            |
| 5058  | Work In Progress<br>Carpet (Doorway) to Data clerk office is coming<br>loose. Plastic edge is picking-up.. Thanks   | 8/30/2005<br>Medium                         | Olga Arias<br>Michael Munoz<br>Carpet Repair                             |           | Riverside ES            |
| 717   | Work In Progress<br>Boiler Room - relief valve drain is not properly<br>supported. As per Boiler Inspector.   | 3/30/2005<br>Medium                         | Michael Munoz<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | San Miguel ES           |
| 214   | Work In Progress<br>Please replace nonlocking door knob with locking<br>one.<br>Mrs. Avalos portable#45.  | 3/9/2005<br>Medium                          | Lorenzo Solis<br>Manny Lozoya<br>Key and Lock                            |           | San Miguel ES           |
| 216   | Work In Progress<br>Replaced falling apart door knob with new one<br>on entrance door<br>in cafeteria.  | 3/9/2005<br>Medium                          | Lorenzo Solis<br>Manny Lozoya<br>Key and Lock                            |           | San Miguel ES           |
| 5337  | Work In Progress<br>DISHWASHER LEAKING WATER.<br><br>EVA MIRANDA - 233-2860   | 9/8/2005<br>Medium                          | Jacqueline Aguilar<br>Danny Orozco<br>Food Services                      | Cafeteria | San Miguel ES           |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number    |
|-------|--|---|--|-----------|----------------------------|
| 8801  | Work In Progress<br>Lock is hard to open and lock on pump house.<br>Please repare thank you.   | 1/17/2006<br>Medium                         | Ricardo Jacquez<br>Manny Lozoya<br>Key and Lock          |           | San Miguel ES              |
| 3087  | Work In Progress<br>Double portable relocated to site was labeled as<br>SM17DM1R there is no portable with that ID. Re-<br>label this and all portables correctly.             | 6/29/2005<br>Low                            | Alfredo Holguin<br>Michael Munoz<br>General Maintenance  | Portables | San Miguel ES              |
| 10973 | Work In Progress<br>Monthly - San Miguel ES Fire Suppression Insp. -<br>Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System |           | San Miguel ES              |
| 10941 | Work In Progress<br>Monthly - San Miguel ES Roof Inpsection - Refer<br>to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Vega<br>Roof                    |           | San Miguel ES              |
| 3175  | Work In Progress<br>Monthly - San Miguel ES Roof Inpsection - Refer<br>to PM schedule details.   | 7/3/2005<br>Medium                          | Alfredo Holguin<br>Danny Vega<br>Roof                    |           | San Miguel ES              |
| 11019 | Work In Progress<br>Monthly - San Miguel ES Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Vega<br>General Maintenance     |           | San Miguel ES              |
| 11007 | Work In Progress<br>Monthly - San Miguel ES Emer. Light Test: Monthly<br>- Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Vega<br>General Maintenance     |           | San Miguel ES              |
| 7632  | Work In Progress<br>The backflow prevention device on the irrigation<br>distribution system needs to have the annual<br>inspection performed.                                  | 11/29/2005<br>Medium                        | Guadalupe Ontiveros<br>Grounds                           |           | San Miguel ES              |
| 1852  | Work In Progress<br>Please order paint so when portables arrive you<br>can go ahead and paint. You site will be<br>receiving one PLease see mike or call him for<br>more info. | 5/11/2005<br>Medium                         | Danny Vega<br>Painting                                   | Portables | San Miguel ES              |
| 8401  | Work In Progress<br>Monthly - San Miguel ES Exit Sign Insp: Monthly -<br>Refer to PM schedule details.   | 1/1/2006<br>Medium                          | Alfredo Holguin<br>Danny Vega<br>General Maintenance     |           | San Miguel ES              |
| 10923 | Work In Progress<br>Monthly - San Miguel ES Monthly FE Inpsection -<br>Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Vega<br>Fire Extinguishers      |           | San Miguel ES              |
| 4489  | Work In Progress<br>Need an extra key for these rooms.   | 8/11/2005<br>Medium                         | Barbara Cardenas<br>Manny Lozoya<br>Key and Lock         | Classroom | San Miguel ES<br>25, 49,50 |
| 1777  | Work In Progress<br>Need a lock installed in a filing cabinet in the<br>Library.   | 5/10/2005<br>Medium                         | Barbara Cardenas<br>Manny Lozoya<br>Key and Lock         |           | San Miguel ES              |



| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                   | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 11075 | Work In Progress<br>Need nameplates for the following:<br>Mr. Padilla<br>Mr. Gonzales<br>Mrs. Gonzales<br>Mrs. Boucher<br>Ms. Barraza<br>Mrs. Tovar<br>Ms. Porter<br>PE Coach<br>Ms. Sanchez<br>Mrs. Nuñez<br>Mrs. Henderson<br>Ms Avalos<br>Ms. O'Neill<br>Mrs. Jackson<br>Mrs. Jaramillo-Granados<br>Ms. Brand<br>Ms. Mendoza<br>Mrs. Rhodes<br>Ms. Reyes<br>Mr. Villalobos<br>Mrs. Gurrola<br>Mrs. Ruiz<br>Ms. Rodriguez<br>Mr. Vega | 4/4/2006<br>Medium                          | Barbara Cardenas<br>Manny Lozoya<br>Key and Lock                    |           | San Miguel ES           |
| 11076 | Work In Progress<br>Need the following room numbers.<br>#1, #2, #4, #5, #10, #12, #17, #19, #25, #26, #28,<br>#34, #37, #42, #47, #49, #50, #51   | 4/4/2006<br>Medium                          | Barbara Cardenas<br>Manny Lozoya<br>Key and Lock                    |           | San Miguel ES           |
| 11829 | Work In Progress<br>vacuum machine has no power thank you   | 5/1/2006<br>Medium                          | Cervando Padilla<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair |           | San Miguel ES           |
| 11376 | Work In Progress<br>vacuum has no power /please check asap.thank<br>you.  | 4/18/2006<br>Medium                         | Cervando Padilla<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair |           | San Miguel ES           |
| 11387 | Work In Progress<br>vacuum. no power  | 4/18/2006<br>Medium                         | Cervando Padilla<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair |           | San Miguel ES           |
| 11594 | Work In Progress<br>broken handle on shower scrubbing machine<br>thank you.   | 4/25/2006<br>Medium                         | Cervando Padilla<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair |           | San Miguel ES           |
| 11193 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE<br>INSPECTIONS ON ALL CUSTODIANS TO INCLUDED<br>CLOSET, MSDS, LABELED SPRAY BOTTLES &<br>SAFETY EQUIPMENT. HEAD CUSTODIANS NEED<br>TO INCLUDE INSPECTION OF YOUR OWN AREA.<br>INSPECTION REPORTS ALONG WITH<br>COMPLETED WORK ORDER MUST BE RETURNED<br>AND RECEIVED BY US NO LATER THAN APRIL<br>21, 2006.   | 4/7/2006<br>Medium                          | Aida Salcedo<br>Cervando Padilla<br>Custodial                       |           | San Miguel ES           |

| WOID | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                     | Area Type | Location<br>Area Number      |
|------|---|---|---|-----------|------------------------------|
| 5176 | Work In Progress<br>CAFETERIA GIRLS RR/SINK FAUCET BROKEN -<br>OFF /PLEASE REPLACE/HOT-COLD TYPE                    | 9/2/2005<br>Medium                          | Danny Vega<br>Joe Ontiveros<br>Plumbing                               |           | San Miguel ES                |
| 5177 | Work In Progress<br>NEED FILTERS 12X24X1  | 9/2/2005<br>Medium                          | Danny Vega<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | San Miguel ES                |
| 5270 | Work In Progress<br>NEED LDO 2QT/FLUSH VALVE<br>KIT/DIAPRAHMS/TUB&SINK<br>SEALER/ELONGATED TIOLET SEAT              | 9/6/2005<br>Medium                          | Danny Vega<br>Joe Ontiveros<br>Plumbing                               |           | San Miguel ES                |
| 5307 | Work In Progress<br>portable #28 refrig unit not cooling/please check<br>it out asap                                | 9/7/2005<br>Medium                          | Danny Vega<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | San Miguel ES                |
| 6367 | Work In Progress<br>rm#32 day&night type furnance/pilot wont stay<br>on-needs thermo-couple                         | 10/13/2005<br>Medium                        | Danny Vega<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | San Miguel ES                |
| 6584 | Work In Progress<br>NEED LOCK-OUT DEVICE FOR DISCONNECT<br>BOX/PORTABLE 28-29/POWER SHUT-OFF<br>DAILY-ASAP          | 10/20/2005<br>Medium                        | Danny Vega<br>Enrique Sotelo<br>Electrical                            |           | San Miguel ES                |
| 6617 | Work In Progress<br>j.gomez/need to start and go thru check list on<br>boiler unit/before 10-28-05 (.you can do it) | 10/21/2005<br>Medium                        | Danny Vega<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | San Miguel ES                |
| 6618 | Work In Progress<br>need two loads playground sand asap   | 10/21/2005<br>Medium                        | Danny Vega<br>Guadalupe Ontiveros<br>Grounds                          |           | San Miguel ES                |
| 6785 | Work In Progress<br>boiler is not heating/please ck it out/class rooms<br>are cold in the morning                   | 10/26/2005<br>Medium                        | Danny Vega<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | San Miguel ES                |
| 4445 | Work In Progress<br>Portable 29 - Needs to be secured by the end of<br>the day.                                     | 8/10/2005<br>Medium                         | Danny Vega<br>Manny Lozoya<br>Key and Lock                            | Portables | San Miguel ES                |
| 4447 | Work In Progress<br>principals office door hard to open/door needs to<br>be shaved.stop by asap                     | 8/10/2005<br>Medium                         | Danny Vega<br>Manny Lozoya<br>Key and Lock                            |           | San Miguel ES                |
| 3834 | Work In Progress<br>A/C UNIT NOT WORKING IN HIGH SPEED<br>PORTABLE#58   | 7/26/2005<br>Medium                         | Danny Vega<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | San Miguel ES                |
| 4051 | Work In Progress<br>portable #30/rheem a/c unit not woking.stop by<br>asap  | 8/1/2005<br>Medium                          | Danny Vega<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | San Miguel ES                |
| 1766 | Work In Progress<br>KEY JAMMED IN CORE/CORE WILL NOT TURN -<br>OVER   | 5/10/2005<br>Medium                         | Danny Vega<br>Manny Lozoya<br>Key and Lock                            | Classroom | San Miguel ES<br>PORTABLE#37 |

| WOID | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                       | Area Type      | Location<br>Area Number  |
|------|--|---|---|----------------|--------------------------|
| 1749 | Work In Progress<br>NEED TO REPLACE GUTTERS IN KITCHEN<br>ROOF/NEED SCAFFOLDS/ D.MIRANDA NEED TO<br>ORDERS GUTTERS.        | 5/9/2005<br>5/9/2005<br>Medium              | Danny Vega<br>Danny Miranda<br>General Maintenance                      | Cafeteria      | San Miguel ES            |
| 1820 | Work In Progress<br>need filetrs for units<br>12ea) 20x20x1 pleated<br>12ea )12x25x1 pleated<br>12ea)12x25x1 pleated -asap | 5/11/2005<br><br>Medium                     | Danny Vega<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning   |                | San Miguel ES            |
| 1821 | Work In Progress<br>ramp not level- door hits bottom platform -need to<br>lift with chains asap                            | 5/11/2005<br>5/12/2005<br>Medium            | Danny Vega<br>Danny Vega<br>Ramps/Platforms                             | Classroom      | San Miguel ES<br>#37     |
| 1826 | Work In Progress<br>NEED 14X30X1 PLEATED FILERS 8EA  | 5/11/2005<br><br>Medium                     | Danny Vega<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning   |                | San Miguel ES            |
| 2103 | Work In Progress<br>need number (stick-on )plates for all class rm<br>doors as per MRS DUNCAN (PRINCIPAL) 1 THRU<br>60     | 5/19/2005<br><br>Medium                     | Danny Vega<br>Manny Lozoya<br>Key and Lock                              |                | San Miguel ES            |
| 1881 | Work In Progress<br>NEED TOP PIVOT LACTH HINGE/RIGHT SIDE FOR<br>METAL DOOR IN LIBRARY ASAP                                | 5/12/2005<br><br>Medium                     | Danny Vega<br>Manny Lozoya<br>Key and Lock                              | Classroom      | San Miguel ES<br>LIBRARY |
| 2118 | Work In Progress<br>REFG. AIR UNIT PORTABLE#33/IS NOT<br>WORKING/USED FOR SUMMER SCHOOL /NEED<br>HVAC -TECH                | 5/19/2005<br><br>Medium                     | Danny Vega<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning   |                | San Miguel ES            |
| 2686 | Work In Progress<br>need bob-cat sweeper to clean staff parking &<br>re-stripe   | 6/10/2005<br><br>Medium                     | Danny Vega<br>Lorenzo Hernandez<br>Grounds                              |                | San Miguel ES            |
| 8847 | Work In Progress<br>need fertilizer spread on campus fields/front<br>lawn 16-8-8   | 1/18/2006<br><br>Medium                     | Danny Vega<br>Guadalupe Ontiveros<br>Grounds                            | Athletic Field | San Miguel ES            |
| 8676 | Work In Progress<br>east exit door/main bldg/having trouble securing<br>/panic bar stuck                                   | 1/12/2006<br><br>Medium                     | Danny Vega<br>Manny Lozoya<br>Key and Lock                              |                | San Miguel ES            |
| 8007 | Work In Progress<br>need one set gates wheels /west gate wheels<br>damaged /asap(ruben ronquillo)                          | 12/12/2005<br><br>Medium                    | Danny Vega<br>Ruben Ronquillo<br>Fence Repair                           |                | San Miguel ES            |
| 7563 | Work In Progress<br>boys restroom heater coil leaks water/need<br>replaced asap<br>found leak and repaired it              | 11/28/2005<br>12/1/2005<br>Medium           | Danny Vega<br>Lorenzo Solis<br>Heating/Ventilation /Air<br>Conditioning |                | San Miguel ES            |
| 8082 | Work In Progress<br>library toilet will not flush/we need to replace it  | 12/13/2005<br><br>Medium                    | Danny Vega<br>Joe Ontiveros<br>Plumbing                                 |                | San Miguel ES            |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                       | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 10432 | Work In Progress<br>need a 220v outlet in boiler rm/as per<br>MR.MARRUFO/MR.CHAVEZ  | 3/10/2006<br>Medium                         | Danny Vega<br>Enrique Sotelo<br>Electrical                              |           | San Miguel ES           |
| 10433 | Work In Progress<br>NEED REPAIRS ON MARQUEE /PLEXY GLASS &<br>FRAME DAMAGE BY WINDS/6FT X 6FT   | 3/10/2006<br>Medium                         | Danny Vega<br>Ruben Ronquillo<br>Glass\Window Repairs                   |           | San Miguel ES           |
| 10721 | Work In Progress<br>water leak in kitchen/dish washer drain/need<br>gasket  | 3/27/2006<br>Medium                         | Danny Vega<br>Danny Orozco<br>Food Services                             |           | San Miguel ES           |
| 11600 | Work In Progress<br>custodians are unable to secure east cafeteria<br>exit door/core will not turn-over/master key jams<br>in core.please repair asap   | 4/25/2006<br>Medium                         | Danny Vega<br>Manny Lozoya<br>Key and Lock                              |           | San Miguel ES           |
| 11320 | Work In Progress<br>rm #32 need additional unit on window as per<br>MR.Marrufo<br>-/6500master-cool is to small   | 4/12/2006<br>Medium                         | Danny Vega<br>Lorenzo Solis<br>Heating/Ventilation /Air<br>Conditioning |           | San Miguel ES           |
| 11686 | Work In Progress<br>need to replace basket strainer in copy rm<br>sink/leaking all over/double sink type  | 4/27/2006<br>Medium                         | Danny Vega<br>Joe Ontiveros<br>Plumbing                                 |           | San Miguel ES           |
| 10794 | Work In Progress<br>DISHWASHER: THERE IS NOT SOAP COMING<br>OUT.<br><br>EVA M. SNP MGR 233-2860   | 3/29/2006<br>Medium                         | Jacqueline Aguilar<br>Danny Orozco<br>Food Services                     | Cafeteria | San Miguel ES           |
| 10485 | Work In Progress<br>need electrician to check out emergency lights<br>that failed to come on during my last m. emerg.<br>lighting insp..  | 3/14/2006<br>Medium                         | Gerardo Marquez<br>Carlos Castillo<br>Electrical                        |           | Santa Teresa ES         |
| 10736 | Work In Progress<br>RUBEN, NEED 60-50 POUND BAGS OF 16-8-8<br>FERTILIZER.FOR PLAY AREA.   | 3/27/2006<br>Medium                         | Gerardo Marquez<br>Ruben Ronquillo<br>General Maintenance               |           | Santa Teresa ES         |
| 10527 | Work In Progress<br>MANNY;<br>COULD YOU CHECK OUT THE LOCK TO THE WK<br>RM. IN C-WING. A KID STUCK SOMETHING IN<br>THE KEYHOLE, AND I AM UNABLE TO SECURE<br>THE RM. THIS RM. HAS A COMPUTER, PRINTER,<br>AND OTHER EQUIP. THAT I MUST SECURE.                      | 3/15/2006<br>Medium                         | Gerardo Marquez<br>Manny Lozoya<br>Key and Lock                         |           | Santa Teresa ES         |
| 11111 | Work In Progress<br>DAVID, NEED FOR YOU TO RECONNECT WALL<br>HYDRANT THAT WAS LEAKING AT END OF A-<br>WING. DOUG DEVORE WITH MASEY JOHNSON<br>CAME AND REVERSED O RING THAT HE<br>THOUGHT MAY HAVE CAUSED IT TO LEAK.<br>WANTS US TO LET HIM KNOW IF THIS FIXED IT. | 4/5/2006<br>Medium                          | Gerardo Marquez<br>David Villalobos<br>Plumbing                         |           | Santa Teresa ES         |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                       | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 11050 | Work In Progress<br>AUTOMATIC OPENER AT WEST ENTRANCE IS NOT WORKING. NEED FOR CONTRACTOR TO CHECK THIS OUT ASAP. HANDICAP STUDENTS ARE UNABLE TO GAIN ENTRY TO BUILDING THROUGH THIS ENTRANCE.   | 4/3/2006<br>Medium                          | Gerardo Marquez<br>Danny Miranda<br>Doors and Hardware  |           | Santa Teresa ES         |
| 11131 | Work In Progress<br>MANNY, NEED FOR YOU TO COME AND CHECK OUT THE RR. DR. BETWEEN RMS. 102 AND 104,. DOOR LOCKED AND I DONT HAVE ACCESS TO UNLOCK IT. DOOR IS KEYED DIFFERENT THAN ALL THE REST.  | 4/6/2006<br>Medium                          | Gerardo Marquez<br>Manny Lozoya<br>Key and Lock         |           | Santa Teresa ES         |
| 4152  | Work In Progress<br>ATTN MANNY.<br>MANNY, WE STILL NEED FOR YOU TO MAKE US ANOTHER KEY TO THE MAIL BOX. THANKS.   | 8/3/2005<br>Medium                          | Gerardo Marquez<br>Manny Lozoya<br>Key and Lock         |           | Santa Teresa ES         |
| 4154  | Work In Progress<br>ATTN LUPE,<br>LUPE, WE STILL NEED THE COBBLESTONE TO KEEP CHECK THE RAIN ERROSION. ALSO NEED FOR BETO AND MANNY TO REDIG TRENCH AT BACK FENCE TO KEEP RAIN FROM FLOODING GROUNDS AND CLASS RMS.<br>Remvoe sand along fence line and make trench deeper on westside of fence, cover pond with piles of sand tso people will not enter as per Gerry. Trench was redug, but need cobble stone for ponds. | 8/3/2005<br>3/28/2006<br>Medium             | Gerardo Marquez<br>Robert Sanchez<br>Grounds            |           | Santa Teresa ES         |
| 454   | Work In Progress<br>ATT. CALI CASTILLO.<br>CALI, NEED FOR YOU TO FOLLOW UP ON WK. OR. 124323. THANKS.<br>NEED FOR YOU TO COME CHECK A COUPLE OF LIGHT FIXTURES THAT I AM HAVING TROUBLE WITH.   | 3/16/2005<br>Medium                         | Gerardo Marquez<br>Carlos Castillo<br>Electrical        |           | Santa Teresa ES         |
| 2323  | Work In Progress<br>MIKE; I NEED FOR YOU TO GET ME A COPY OF THE PAINT SCHEDULE. THANKS.  | 5/26/2005<br>Medium                         | Gerardo Marquez<br>Michael Munoz<br>General Maintenance |           | Santa Teresa ES         |
| 3657  | Work In Progress<br>ATTN. Manny .<br>NEED FOR YOU TO DUPLICATE A KEY TO THE MAIL BOX .<br>THANKS .  | 7/19/2005<br>Medium                         | Gerardo Marquez<br>Manny Lozoya<br>Key and Lock         |           | Santa Teresa ES         |
| 11827 | Work In Progress<br>CALI, NEED FOR YOU TO ORDER ME BALLASTS AND BULBS BOR STE. ALSO NEED FOR YOU TO CHECK OUT EMERG. LIGHTS THAT FAILED ON LAST TEST.   | 5/1/2006<br>Medium                          | Gerardo Marquez<br>Carlos Castillo<br>Electrical        |           | Santa Teresa ES         |
| 11828 | Work In Progress<br>NEED 3-COMPARTMENT SINK AT CAFET. PREP AREA CHECKED OUT. (STOPPER WILL NOT HOLD WATER)  | 5/1/2006<br>Medium                          | Gerardo Marquez<br>Danny Orozco<br>Food Services        |           | Santa Teresa ES         |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                         | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 11194 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Pablo Diaz<br>Custodial                   |           | Santa Teresa ES         |
| 11593 | Work In Progress<br>Tilt Skillet is still out of order<br><br>Patricia Sanchez - SNP Manager 589-3439   | 4/25/2006<br>Medium                         | Alma Terrell<br>Danny Orozco<br>Food Services             | Cafeteria | Santa Teresa ES         |
| 10908 | Work In Progress<br>Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Gerardo Marquez<br>Fire Extinguishers  |           | Santa Teresa ES         |
| 11008 | Work In Progress<br>Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Gerardo Marquez<br>General Maintenance |           | Santa Teresa ES         |
| 11020 | Work In Progress<br>Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Gerardo Marquez<br>General Maintenance |           | Santa Teresa ES         |
| 10944 | Work In Progress<br>Monthly - Santa Teresa ES Roof Inspection - Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Gerardo Marquez<br>Roof                |           | Santa Teresa ES         |
| 10974 | Work In Progress<br>Monthly - Santa Teresa ES Fire Suppression Insp. - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System  |           | Santa Teresa ES         |
| 11726 | Work In Progress<br>We need 3 additional keys made for our security box in the office. Key #CH751. Please ask for Gerry Marquez as he has the only key in the office. Thanks.   | 4/28/2006<br>Medium                         | Rita Mendez<br>Manny Lozoya<br>Key and Lock               | Office    | Santa Teresa ES         |
| 9005  | Work In Progress<br>Need a gate key for El Paso Disposal.   | 1/24/2006<br>Medium                         | Juliet Parra<br>Manny Lozoya<br>Key and Lock              |           | Santa Teresa ES         |
| 923   | Work In Progress<br>WE NEED CHECK AND REPAIR DOOR LOCK NO WELDING CLASS ROOM AT V.O.C BUILDING  | 4/7/2005<br>Medium                          | Joel Herrera<br>Manny Lozoya<br>Key and Lock              |           | Santa Teresa HS         |
| 5102  | Work In Progress<br>WE NEED REPLACE MA 51 AND TREE LOCKS AT R.O.T.C CLASS ROOMS.  | 8/30/2005<br>Medium                         | Joel Herrera<br>Manny Lozoya<br>Key and Lock              |           | Santa Teresa HS         |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                    | Area Type | Location<br>Area Number |
|-------|--|---|--|-----------|-------------------------|
| 5923  | Work In Progress<br>MIKE MUNOZ WE NEED BARRIER FENCE ON WEST SIDE AT SOCCER FIELD TO RETAIN BALLS OUT IT PLAY . ALSO NEED FENCE FROM 20 YARD LINE TO 20 YARD LINE IN FRONT OF FOOTBALL VISITORS SEATING AREA. SEE R GALLEGOS THANK YOU MIKE... | 9/28/2005<br>Medium                         | Joel Herrera<br>Michael Munoz<br>Fence Repair                        |           | Santa Teresa HS         |
| 4966  | Work In Progress<br>RUBEN WE NEED REPAIR THE WINDOWS AT DAYCAREBUILDING IT DOESN'T OPEN THANK YOU<br>Route to Joel as per Mike 9/12/05 - mkv   | 8/26/2005<br>Medium                         | Joel Herrera<br>Joel Herrera<br>General Maintenance                  |           | Santa Teresa HS         |
| 4807  | Work In Progress<br>MANNY MY MASTER KEY IS BROKEN IT DOESN'T WORK NO MORE.   | 8/23/2005<br>Medium                         | Joel Herrera<br>Manny Lozoya<br>Key and Lock                         |           | Santa Teresa HS         |
| 4454  | Work In Progress<br>SMASHED WINDOW ON DOOR - STOLEN LARGE SCREEN TV.<br>DISCOVERED BY MR. BUCKLEY  | 8/1/2005<br>Medium                          | Joel Herrera<br>Ruben Ronquillo<br>Glass\Window Repairs              |           | Santa Teresa HS         |
| 4463  | Work In Progress<br>SENER ON SINCK AT GIRLS REST ROOM IT DOESN'T WORK WE REPLACE IT .  | 8/11/2005<br>Medium                         | Joel Herrera<br>David Villalobos<br>Plumbing                         |           | Santa Teresa HS         |
| 10537 | Work In Progress<br>NEED EIGHT (8) FLO. LIGHT BULBS FOR MARQUEE, IT IS NOT LIGHTING, WOULD LIKE TO HAVE IT LIT.  | 3/15/2006<br>Medium                         | Joel Herrera<br>Carlos Castillo<br>Electrical                        |           | Santa Teresa HS         |
| 11264 | Work In Progress<br>NEED MR. CASTILLO TO ASSIST ME ON ELEC. PROBLEM ON GYM. A.C. NOT GETTING POWER TO MOTOR, ALREADY TROUBLE SHOOT, CAN'T SEEM TO FIND THE PROBLEM.  | 4/11/2006<br>Medium                         | Joel Herrera<br>Carlos Castillo<br>Electrical                        |           | Santa Teresa HS         |
| 11558 | Work In Progress<br>BROKEN DOOR'S GLASS SIZE 25 1/4 X 36 1/4 WIRE GLASS ON DRESSING ROOM HALL'S FRONT DOORS AT G.Y.M AREA  | 4/24/2006<br>Medium                         | Joel Herrera<br>Ruben Ronquillo<br>Glass\Window Repairs              |           | Santa Teresa HS         |
| 11588 | Work In Progress<br>NEED SIX (6) EA. TOGGLE THREE WAY SWITHES TO REPLACED DAMAGED ONES ON GYM.   | 4/25/2006<br>Medium                         | Joel Herrera<br>Carlos Castillo<br>Electrical                        |           | Santa Teresa HS         |
| 11590 | Work In Progress<br>NEED SHEETMETAL COVER FOR A.C. AT GYM. AREA MADE, THE EXISTING ONE IS DAMAGED, NEED AS SOON AS POSSIBLE TO PROTECT SWITCHES.   | 4/25/2006<br>Medium                         | Joel Herrera<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |           | Santa Teresa HS         |
| 10100 | Work In Progress<br>BROKEN SYLINEDER SOMETHING INSIDE WE TO REPLACED AT CLASS ROOM 15  | 3/1/2006<br>Medium                          | Joel Herrera<br>Manny Lozoya<br>Key and Lock                         |           | Santa Teresa HS         |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|-------|--|---|--|-----------|-------------------------|
| 9143  | Work In Progress<br>1-27-06 2.0 RE-MOVE FLAIRS AT G.Y.M AREA.<br>1.0 CHECK HEATINGS UNITS 1.0 REPLACE<br>ELECTRICAL SWITCH AT G.Y.M AREA 2.0<br>CHECK ELECTRICAL PROBLEM AT KITCHEN 2.0<br>CHECK AND REPAIR DOOR LOCK AT COACHES<br>ROOM AT SOFBALL FIELD AREA.<br>1/27 - 8  | 1/30/2006<br>Medium                         | Joel Herrera<br>Joel Herrera<br>General Maintenance      |           | Santa Teresa HS         |
| 9411  | Work In Progress<br>DOOR FROM MAINT ENTRANCE IT DOESN'T<br>LOCKE MANNY WE NEED FIX IT.   | 2/6/2006<br>Medium                          | Joel Herrera<br>Manny Lozoya<br>Key and Lock             |           | Santa Teresa HS         |
| 9679  | Work In Progress<br>NEW CAFETERIA BOTH DRESSING ROOMS.<br>1.KEY FOR MAIN DOOR TO DRESSING ROOM<br>BOTH BOYS AND GIRLS. 2 KEY FOR CLOSET<br>DOOR BOTH BOYS AND GIRLS. 3 ADULT<br>BATHROOMS NEED TO BE RE-CORE THE LOCKS<br>4.KEY FOR BATHROOMS IN BOTH DRESSING<br>ROOMS 5.MD-12 AND MD-2 KEYS NEED FOR<br>MR. ANGELO AND MR. JEWETT. 6. LOCK FOR<br>MS. FRANCIS SOCCER CABINET BY G.Y.M<br>AREA. | 2/14/2006<br>Medium                         | Joel Herrera<br>Manny Lozoya<br>Key and Lock             |           | Santa Teresa HS         |
| 8157  | Work In Progress<br>MR. GALLEGOS WANTS DEADBOLT ON BOYS<br>AND GIRLS DRESSING ROOMS 2- NEED TO<br>CHANGE DOOR KNOBS TO BE ABLE TO LOCK<br>THE WORK ROOM BETWEEN THE BAND AND<br>CHORUS ROOM 3- AND NEED TO CHANGE ONE<br>ENTRY KEY TO THE RESTROOMS FROM THE<br>MEETINS ROOM.<br>12/15 - 5   | 12/15/2005<br>12/15/2005<br>Medium          | Joel Herrera<br>Manny Lozoya<br>Key and Lock             |           | Santa Teresa HS         |
| 11639 | Work In Progress<br>WE NEED REPLACE STOP VALBULAS AT BOYS<br>REST ROOM AT MATH WING AREA.  | 4/26/2006<br>Medium                         | Joel Herrera<br>David Villalobos<br>Plumbing             |           | Santa Teresa HS         |
| 348   | Work In Progress<br>BOTH MIORRORS FROM BOYS BATH ROOM<br>ARE FADED THEY NEED TO BE REPLACE IN THE<br>ENGLISH WING THANK YOU.   | 3/14/2005<br>Medium                         | Luis Murillo<br>Ruben Ronquillo<br>General Maintenance   |           | Santa Teresa HS         |
| 11834 | Work In Progress<br>GRAFFITI ON CAFETERIA DOORS. WINDOWS,<br>MAIN LIB ENTRANCE, APROX 5 CLASSROOMS, 3<br>ENTRANCE DOORS AND WALL.  | 4/27/2006<br>Medium                         | Luis Murillo<br>Arturo Nunez<br>Painting                 |           | Santa Teresa HS         |
| 10975 | Work In Progress<br>Monthly - Santa Teresa HS Fire Suppression<br>Insp. - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System |           | Santa Teresa HS         |
| 10942 | Work In Progress<br>Monthly - Santa Teresa HS Roof Inspection -<br>Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Arturo Nunez<br>Roof                  |           | Santa Teresa HS         |
| 3158  | Work In Progress<br>Monthly - Santa Teresa HS Monthly FE Inspection<br>- Refer to PM schedule details.   | 7/3/2005<br>Medium                          | Alfredo Holguin<br>Arturo Nunez<br>Fire Extinguishers    |           | Santa Teresa HS         |



| <b>WOID</b> | <b>Status<br/>Description<br/>Action Taken</b>   | <b>Request Date<br/>Completion Date<br/>Priority</b> | <b>Requester<br/>Assigned To<br/>Craft</b>             | <b>Area Type</b> | <b>Location<br/>Area Number</b> |
|-------------|--|--|--|------------------|---------------------------------|
| 11021       | Work In Progress<br>Monthly - Santa Teresa HS Exit Sign Insp:<br>Monthly - Refer to PM schedule details.               | 4/2/2006<br>Medium                                   | Alfredo Holguin<br>Joel Herrera<br>General Maintenance |                  | Santa Teresa HS                 |
| 11010       | Work In Progress<br>Monthly - Santa Teresa HS Emer Light Test:<br>Monthly - Refer to PM schedule details.              | 4/2/2006<br>Medium                                   | Alfredo Holguin<br>Joel Herrera<br>General Maintenance |                  | Santa Teresa HS                 |
| 3176        | Work In Progress<br>Monthly - Santa Teresa HS Roof Inspection -<br>Refer to PM schedule details.                       | 7/3/2005<br>Medium                                   | Alfredo Holguin<br>Arturo Nunez<br>Roof                |                  | Santa Teresa HS                 |
| 3329        | Work In Progress<br>Yearly - Santa Teresa HS Emer. Light Test:<br>Annual - Refer to PM schedule details.               | 7/6/2005<br>Medium                                   | Alfredo Holguin<br>Arturo Nunez<br>Fire Protection     |                  | Santa Teresa HS                 |
| 3351        | Work In Progress<br>Yearly - Santa Teresa HS Exit Sign Test: Annual -<br>Refer to PM schedule details.                 | 7/6/2005<br>Medium                                   | Alfredo Holguin<br>Arturo Nunez<br>Fire Protection     |                  | Santa Teresa HS                 |
| 5214        | Work In Progress<br>Monthly - Santa Teresa HS Monthly FE Inspection<br>- Refer to PM schedule details.                 | 9/4/2005<br>Medium                                   | Alfredo Holguin<br>Arturo Nunez<br>Fire Extinguishers  |                  | Santa Teresa HS                 |
| 6018        | Work In Progress<br>Monthly - Santa Teresa HS Monthly FE Inspection<br>- Refer to PM schedule details.                 | 10/2/2005<br>Medium                                  | Alfredo Holguin<br>Arturo Nunez<br>Fire Extinguishers  |                  | Santa Teresa HS                 |
| 6036        | Work In Progress<br>Monthly - Santa Teresa HS Roof Inspection -<br>Refer to PM schedule details.                       | 10/2/2005<br>Medium                                  | Alfredo Holguin<br>Arturo Nunez<br>Roof                |                  | Santa Teresa HS                 |
| 7108        | Work In Progress<br>Monthly - Santa Teresa HS Emer Light Test:<br>Monthly - Refer to PM schedule details.              | 11/6/2005<br>Medium                                  | Alfredo Holguin<br>Joel Herrera<br>General Maintenance |                  | Santa Teresa HS                 |
| 7119        | Work In Progress<br>Monthly - Santa Teresa HS Exit Sign Insp:<br>Monthly - Refer to PM schedule details.               | 11/6/2005<br>Medium                                  | Alfredo Holguin<br>Joel Herrera<br>General Maintenance |                  | Santa Teresa HS                 |
| 7071        | Work In Progress<br>Monthly - Santa Teresa HS Monthly FE Inspection<br>- Refer to PM schedule details.                 | 11/6/2005<br>Medium                                  | Alfredo Holguin<br>Arturo Nunez<br>Fire Extinguishers  |                  | Santa Teresa HS                 |
| 6107        | Work In Progress<br>Monthly - Santa Teresa HS Emer Light Test:<br>Monthly - Refer to PM schedule details.              | 10/2/2005<br>Medium                                  | Alfredo Holguin<br>Joel Herrera<br>General Maintenance |                  | Santa Teresa HS                 |
| 6118        | Work In Progress<br>Monthly - Santa Teresa HS Exit Sign Insp:<br>Monthly - Refer to PM schedule details.               | 10/2/2005<br>Medium                                  | Alfredo Holguin<br>Joel Herrera<br>General Maintenance |                  | Santa Teresa HS                 |
| 9785        | Work In Progress<br>NEED 12 EA. 2X4 277V. LAY IN LIGHTS WITH<br>EMERGENCY BALAST. FOR 300 WING ROOMS,<br>AND HALLWAYS. | 2/16/2006<br>Medium                                  | Arturo Nunez<br>Carlos Castillo<br>Electrical          |                  | Santa Teresa HS                 |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                    | Area Type | Location<br>Area Number |
|-------|---|---|--|-----------|-------------------------|
| 9787  | Work In Progress<br>NEED 14 EA. OUSIDE SECURITY LIGHT FIXTURES TO REPLACE EXISTING ORIGINAL FIXTURES ON MAIN BUILDING, AND ANNEX. WILL ASISSIT ELECTRICAN ON REPLACING FIXTURES.  | 2/16/2006<br>Medium                         | Arturo Nunez<br>Carlos Castillo<br>Electrical                        |           | Santa Teresa HS         |
| 9869  | Work In Progress<br>NEED ASSISTANT ON C.W. LINE AT A.H.U. AT LIBRARY, A SMALL SMALL LEAK HAS SPRUNG, NEED TO SEE IF WE CAN REPAIR.  | 2/21/2006<br>Medium                         | Arturo Nunez<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |           | Santa Teresa HS         |
| 9623  | Work In Progress<br>DOOR KNOB IN COUSELORS OFFICE, SOUTH SIDE DOOR,CLINDER IS BROKEN THEY CAN'T OPEN DOOR WITH THEIR KEY. WOULD LIKE TO HAVE LOCKSMITH HELP US WITH THIS SITUATION.<br>REPAIR CYLINDER AT COUNSELORS OFFICE | 2/13/2006<br>1/16/2006<br>Medium            | Arturo Nunez<br>Manny Lozoya<br>Key and Lock                         |           | Santa Teresa HS         |
| 8410  | Work In Progress<br>NEED DOOR WINDOW REPLACED ON ROOM #304 6 3/4X24 1/2 1/4" WIRE SAFETY GLASS. WILL NEED PRICE TO PUT ON VANDALISM REPORT. THANK YOU.....  | 1/4/2006<br>Medium                          | Arturo Nunez<br>Ruben Ronquillo<br>Glass\Window Repairs              |           | Santa Teresa HS         |
| 7840  | Work In Progress<br>NEED FIVE (5) LOCKS 6" SLIDE LOCKING HASP   | 12/5/2005<br>Medium                         | Arturo Nunez<br>Manny Lozoya<br>Key and Lock                         |           | Santa Teresa HS         |
| 8571  | Work In Progress<br>NEED TO BORROW SCISSOR LIFT TO PUT UP BANNERS ON GYM RAFTERS. AND PUT UP SOME ACUSTIC PANELS THAT FELL . AND CHECK THEM ALL, FOR SAFETY PURPOSES.   | 1/9/2006<br>Medium                          | Arturo Nunez<br>Ruben Ronquillo<br>Equipment                         |           | Santa Teresa HS         |
| 8757  | Work In Progress<br>NEED TO HAVE OLD BAND ROOM FUMIGATED, AND MOUSE TRAP INSTALLED, MICE HAVE BEEN SIGHTED, DUE TO FOOD NOT PROPERLY STORED. A.S.AP. THANK YOU....  | 1/13/2006<br>Medium                         | Arturo Nunez<br>Margret Villalobos<br>Pest Control                   |           | Santa Teresa HS         |
| 11091 | Work In Progress<br>NEED SOME LIGHTS INSTALLED ON EXHAUST FAN HOOD THAT WAS INSTALLED ON WELDING SHOP. TO DARK UNDER HOOD.  | 4/4/2006<br>Medium                          | Arturo Nunez<br>Carlos Castillo<br>Electrical                        |           | Santa Teresa HS         |
| 11105 | Work In Progress<br>URGENTE; A/C IS LEACKING WATER PAN IS VERY RUSTING WE CAN'T USED NO MORE WE NEED REPLACE IT AT MS.CHAVES' OFFICE  | 4/5/2006<br>Medium                          | Arturo Nunez<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |           | Santa Teresa HS         |
| 10646 | Work In Progress<br>NEED THE LOCK AT CAGE STORAGE , CHANGED TO DIFFRENT KEY, SO ONLY TRACK COACH, CAN HAVE ACESS TO EQUIPMENT, HE IS MISSING SOME STUFF.  | 3/17/2006<br>Medium                         | Arturo Nunez<br>Manny Lozoya<br>Key and Lock                         |           | Santa Teresa HS         |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft             | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 10635 | Work In Progress<br>NEED 70 WATTS METAL HALIDE BULBS #<br>M143/E TWELVE (12) EA. FOR NEW ADDITION,<br>OUTSIDE LIGHTS.   | 3/17/2006<br>Medium                         | Arturo Nunez<br>Carlos Castillo<br>Electrical |           | Santa Teresa HS         |
| 10780 | Work In Progress<br>NEED CALI TO COME AND SEE WHAT NEEDS TO<br>BE DONE FOR WASHER AND DRIER HOOK UP<br>AT TRAINERS OFFICE. APPLIANCES ARE ON<br>ORDER AS PER TRAINER.                           | 3/28/2006<br>Medium                         | Arturo Nunez<br>Carlos Castillo<br>Electrical |           | Santa Teresa HS         |
| 10781 | Work In Progress<br>NEED SIX (6) EA. 50A 125/250 PLUGS FOR<br>WELDING SHOP, WOULD LIKE TO USE ONE TYPE<br>OF PLUG FOR OUTLETS SO THAT WELDING<br>MACHINES CAN BE USED ANY WHERE IN THE<br>ROOM. | 3/28/2006<br>Medium                         | Arturo Nunez<br>Carlos Castillo<br>Electrical |           | Santa Teresa HS         |
| 10415 | Work In Progress<br>NEED TO REPLACE FOUR (4) FLO. LIGHT BULB<br>FIXTURES ON CAGE STORAGE HALLWAY.   | 3/10/2006<br>Medium                         | Arturo Nunez<br>Carlos Castillo<br>Electrical |           | Santa Teresa HS         |
| 10132 | Work In Progress<br>NEED EMERGENCY PUSH BUTTONS FOR SHOP<br>AREAS, THE ONE ON THERE, ARE BROKEN,<br>OTHERS DON'T WORK. SAFETY ISSUE. SIX (6)<br>EA.   | 3/2/2006<br>Medium                          | Arturo Nunez<br>Carlos Castillo<br>Electrical |           | Santa Teresa HS         |
| 10371 | Work In Progress<br>NEED THE CYLINDERS AT REMOED SECTION<br>OF SCHOOL, EXTERIOR DOORS INSTALLED AS<br>SOON AS POSSIBLE. FOR SECURITY PURPOSE.   | 3/8/2006<br>Medium                          | Arturo Nunez<br>Manny Lozoya<br>Key and Lock  |           | Santa Teresa HS         |
| 11239 | Work In Progress<br>NEED TWO (2) EA. 115V. TO 24V.<br>TRANSFORMERS TO SUPPLY POWER TO<br>SENSOR AT GIRLS LABATORIES, THE EXISTING<br>ONE IS SHOT, NO WATER.                                     | 4/10/2006<br>Medium                         | Arturo Nunez<br>Carlos Castillo<br>Electrical |           | Santa Teresa HS         |
| 11201 | Work In Progress<br>NEED SIX (6) EA. SENSORS FOR LABATORIES<br>AT DRESSING ROOMS.   | 4/7/2006<br>Medium                          | Arturo Nunez<br>David Villalobos<br>Plumbing  |           | Santa Teresa HS         |
| 11192 | Work In Progress<br>LOCK ON OLD CONSESSION ON MAIN BUILDING<br>NEEDS TO BE CHECKED, CUSTODIANS HAVING<br>TROUBLE WITH LOCK.   | 4/7/2006<br>Medium                          | Arturo Nunez<br>Manny Lozoya<br>Key and Lock  |           | Santa Teresa HS         |
| 11184 | Work In Progress<br>NEED A 115V. HAND DRIER FOR VOCATIONAL<br>BOYS RESTROOM.  | 4/7/2006<br>Medium                          | Arturo Nunez<br>Carlos Castillo<br>Electrical |           | Santa Teresa HS         |
| 11185 | Work In Progress<br>DOOR KNOB HANDLE ON CUSTODIAL CLOSET<br>AT VOC. BLDG. NEEDS TO BE REPLACED. (<br>BROKEN)  | 4/7/2006<br>Medium                          | Arturo Nunez<br>Manny Lozoya<br>Key and Lock  |           | Santa Teresa HS         |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                       | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 1998  | Work In Progress<br>03/23/05<br>3/23 8.0 - CONT. PAINTING DRESSING ROOM   | 5/17/2005<br>Medium                         | Arturo Nunez<br>Arturo Nunez<br>General Maintenance                     |           | Santa Teresa HS         |
| 695   | Work In Progress<br>NEED TILE INSTALLED AT TRAINERS WRAPPING<br>AREA, REQUESTED BY MR. MUNOZ,FRANK.   | 3/30/2005<br>Medium                         | Arturo Nunez<br>Michael Munoz<br>Carpet Repair                          |           | Santa Teresa HS         |
| 1011  | Work In Progress<br>NEED CYLINDER AT DRESSING ROOM<br>HALLWAY CHECKED SOME ONE STUCK<br>SOMETHING IN IT, CAN'T OPEN IT ,AFRAID<br>SOMEONE WILL BREAK KEY. | 4/11/2005<br>Medium                         | Arturo Nunez<br>Manny Lozoya<br>Key and Lock                            |           | Santa Teresa HS         |
| 3571  | Work In Progress<br>NEED CONDENSER MTR. FOR SNACK ROOM<br>A.C. UNIT, MTR. IS FROZEN UNIT IS DOWN.   | 7/15/2005<br>Medium                         | Arturo Nunez<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning |           | Santa Teresa HS         |
| 10924 | Work In Progress<br>Monthly - Santa Teresa HS Monthly FE Inspection<br>- Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Arturo Nunez<br>Fire Extinguishers                   |           | Santa Teresa HS         |
| 10217 | Work In Progress<br>Monthly - Santa Teresa HS Fire Sprinkler Insp. -<br>Refer to PM schedule details.   | 3/5/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System                |           | Santa Teresa HS         |
| 8403  | Work In Progress<br>Monthly - Santa Teresa HS Exit Sign Insp:<br>Monthly - Refer to PM schedule details.  | 1/1/2006<br>Medium                          | Alfredo Holguin<br>Joel Herrera<br>General Maintenance                  |           | Santa Teresa HS         |
| 8306  | Work In Progress<br>Monthly - Santa Teresa HS Monthly FE Inspection<br>- Refer to PM schedule details.  | 1/1/2006<br>Medium                          | Alfredo Holguin<br>Arturo Nunez<br>Fire Extinguishers                   |           | Santa Teresa HS         |
| 8392  | Work In Progress<br>Monthly - Santa Teresa HS Emer Light Test:<br>Monthly - Refer to PM schedule details.   | 1/1/2006<br>Medium                          | Alfredo Holguin<br>Joel Herrera<br>General Maintenance                  |           | Santa Teresa HS         |
| 8324  | Work In Progress<br>Monthly - Santa Teresa HS Roof Inspection -<br>Refer to PM schedule details.  | 1/1/2006<br>Medium                          | Alfredo Holguin<br>Arturo Nunez<br>Roof                                 |           | Santa Teresa HS         |
| 11213 | Work In Progress<br>NEED TO DO A CHEMICAL TRAINING FOR<br>OSCAR ESPARZA @ STH   | 4/7/2006<br>Medium                          | Aida Salcedo<br>Custodial   |           | Santa Teresa HS         |
| 7767  | Work In Progress<br>Monthly - Santa Teresa HS Monthly FE Inspection<br>- Refer to PM schedule details.  | 12/4/2005<br>Medium                         | Alfredo Holguin<br>Arturo Nunez<br>Fire Extinguishers                   |           | Santa Teresa HS         |
| 7815  | Work In Progress<br>Monthly - Santa Teresa HS Exit Sign Insp:<br>Monthly - Refer to PM schedule details.  | 12/4/2005<br>Medium                         | Alfredo Holguin<br>Joel Herrera<br>General Maintenance                  |           | Santa Teresa HS         |
| 7804  | Work In Progress<br>Monthly - Santa Teresa HS Emer Light Test:<br>Monthly - Refer to PM schedule details.   | 12/4/2005<br>Medium                         | Alfredo Holguin<br>Joel Herrera<br>General Maintenance                  |           | Santa Teresa HS         |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                       | Area Type      | Location<br>Area Number |
|-------|---|---|---|----------------|-------------------------|
| 4484  | Work In Progress<br>please install venting system and exhaust hood<br>in the metal shop. See Joe Angelo.  | 8/11/2005<br>Medium                         | Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning |                | Santa Teresa HS         |
| 9999  | Work In Progress<br>please repair the wood that is breaking off the<br>dugouts. Thanks  | 2/24/2006<br>Medium                         | Guadalupe Ontiveros<br>Grounds                          | Athletic Field | Santa Teresa HS         |
| 10716 | Work In Progress<br>Soccer Field & Football Field - Need to install<br>sprigs on fields.  | 3/27/2006<br>Medium                         | Guadalupe Ontiveros<br>Grounds                          | Athletic Field | Santa Teresa HS         |
| 10724 | Work In Progress<br>NEED TO DO TRAINING ON CLEANING<br>RESTROOMS, USING CHEMICALS & EQUIPMENT<br>AND TIME MANAGEMENT FOR: JAVIER PARRA,<br>RAFAEL MERA, MARIA DE SANTIAGO &<br>OSCAR ESPARZA  | 3/27/2006<br>Medium                         | Aida Salcedo<br>Guillermo Hernandez<br>Custodial        |                | Santa Teresa HS         |
| 10730 | Work In Progress<br>NEED TO TRAIN: JAVIER PARRA, RAFAEL<br>MERA, MARIA DE SANTIAGO & OSCAR<br>ESPARZA ON USING ROTO & BURNISHER<br>MACHINES   | 3/27/2006<br>Medium                         | Aida Salcedo<br>Sal Acuna<br>Custodial                  |                | Santa Teresa HS         |
| 11099 | Work In Progress<br>NEED TO ISSUE A 4 WET FLOOR SIGNS, 1 CHAIR<br>DOLLY, 1 FLAT BED, EXTENSION CORD AND A<br>LADDER.  | 4/5/2006<br>Medium                          | Aida Salcedo<br>Sal Acuna                               |                | Santa Teresa HS         |
| 11195 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE<br>INSPECTIONS ON ALL CUSTODIANS TO INCLUDED<br>CLOSET, MSDS, LABELED SPRAY BOTTLES &<br>SAFETY EQUIPMENT. HEAD CUSTODIANS NEED<br>TO INCLUDE INSPECTION OF YOUR OWN AREA.<br>INSPECTION REPORTS ALONG WITH<br>COMPLETED WORK ORDER MUST BE RETURNED<br>AND RECEIVED BY US NO LATER THAN APRIL<br>21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Luis Murillo<br>Custodial               |                | Santa Teresa HS         |
| 7194  | Work In Progress<br>ADULT RESTROOM IN OFFICE AREA NEEDS TO<br>BE PAINTED.   | 11/8/2005<br>Medium                         | Aida Salcedo<br>Arturo Nunez<br>General Maintenance     |                | Santa Teresa HS         |
| 11445 | Work In Progress<br>JIMMY & GUILLERMO - ON 4/18/06 WILL NEED<br>TO PICK UP FROM GAC 350 CHIARS ON AND<br>DELIVER & HELP WILTH SET UP. RETURN ON<br>5/22/06.   | 4/20/2006<br>Medium                         | Aida Salcedo<br>Jimmy Carbajal<br>Custodial             |                | Santa Teresa HS         |
| 11460 | Work In Progress<br>NEED TO SHOWER SCRUB FLOORS AND 1<br>COAT OF WAX (1 QUARDANT PER DAY) ON<br>MON, TUE, WED & THUR. (MAY 15-18, 2006)<br><br>MAY 15 - TO TRAIN<br>MAY 16 - TO OSSERVE<br>MAY 17 - SET UP THE STAGE.   | 4/20/2006<br>Medium                         | Aida Salcedo<br>Guillermo Hernandez                     |                | Santa Teresa HS         |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                       | Area Type  | Location<br>Area Number |
|-------|---|---|---|------------|-------------------------|
| 11461 | Work In Progress<br>LUIS- NEED TO ISSUE AND SPREAD OUT ALL EQUIPMENT THAT HAD BEEN ISSUED TO YOU ( EX. LADDERS, EXTENSION CORDS, DOLLIES, ECT). SEPARATE THRU OUT ALL AREAS OF CUSTODIAL CLOSETS FOR EASY ACCESS TO THEM.   | 4/20/2006<br>Medium                         | Aida Salcedo<br>Luis Murillo                            |            | Santa Teresa HS         |
| 1387  | Work In Progress<br>need to repair sheetrock in gym locker room   | 4/25/2005<br>Medium                         | Danny Miranda<br>Danny Miranda<br>General Maintenance   | Auditorium | Santa Teresa HS         |
| 11493 | Work In Progress<br>Need a set of Keys for STHS for Lynco, thanks, Carlos   | 4/21/2006<br>Medium                         | Carlos Vigil<br>Manny Lozoya<br>Key and Lock            |            | Santa Teresa HS         |
| 9776  | Work In Progress<br>s.t.m.s. need to paint new doors in front of gym  | 2/16/2006<br>Medium                         | Danny Miranda<br>Jaime Mijarez<br>Painting              |            | Santa Teresa MS         |
| 9777  | Work In Progress<br>s.t.m.s. need to paint new door at music room   | 2/16/2006<br>Medium                         | Danny Miranda<br>Jaime Mijarez<br>Painting              |            | Santa Teresa MS         |
| 2728  | Work In Progress<br>need to replace doors @ 10x56 window kit  | 6/13/2005<br>Medium                         | Danny Miranda<br>Danny Miranda<br>Doors and Hardware    |            | Santa Teresa MS         |
| 6218  | Work In Progress<br>DUE TO WATER OVER FLOW, GYM FLOOR HAS BUBBLED BY FLOODING. NEED VENDOR TO DO A RECOMMENDATION AND QUOTE US.   | 10/10/2005<br>Medium                        | Aida Salcedo<br>Michael Munoz<br>Carpet Repair          |            | Santa Teresa MS         |
| 11197 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Ismael Rodriguez<br>Custodial           |            | Santa Teresa MS         |
| 11286 | Work In Progress<br>NEW reach in at 32 - 37 degrees<br><br>Paula Sanchez - SNP Manager 589-9836   | 4/11/2006<br>Medium                         | Alma Terrell<br>Danny Orozco<br>Food Services           | Cafeteria  | Santa Teresa MS         |
| 11035 | Work In Progress<br>Pipe fell off to dishwasher<br><br>Paula Sanchez - 589-9836   | 4/3/2006<br>Medium                          | Alma Terrell<br>Danny Orozco<br>Food Services           | Cafeteria  | Santa Teresa MS         |
| 11386 | Work In Progress<br>Broken window on gym lobby entrance door.<br>Offenders: Viridian Barrajas, Guadalupe Lopez<br>Est. Damage 54.00   | 11/29/2005<br>Medium                        | Coach Martinez<br>Jaime Mijarez<br>Glass\Window Repairs |            | Santa Teresa MS         |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                   | Area Type   | Location<br>Area Number |
|-------|--|---|---|-------------|-------------------------|
| 11642 | Work In Progress<br>MR.ONTEVERO WE NEED TO FILL OUT WITH SOME CRUSHER FINE ALONG THE SIDEWALK GOING TO THE PORTABLES THE SIDEWALK IS HIGH FROM THE GROUND.SEE MR. RODRIGUEZ.AS PER MS. WILLIAMS.THANK YOU. | 4/26/2006<br>Medium                         | Ismael Rodriguez<br>Guadalupe Ontiveros<br>Grounds                  | Library     | Santa Teresa MS         |
| 5308  | Work In Progress<br>I NEED A KEY A7 FOR THE PRINCIPAL TO HAVE ACCESS TO MY STORAGE ROOM. THANK YOU.SEE MR. RODRIGUEZ.  | 9/7/2005<br>Medium                          | Ismael Rodriguez<br>Manny Lozoya<br>Key and Lock                    | Custodial   | Santa Teresa MS         |
| 2828  | Work In Progress<br>NEED TO REMOVE WEEDS ON OUR CAMPUS AREA AS PER. MISS WILLIAMS . NORTH AND SOUTH BUILDING AND GYM AREA.THANK YOU.   | 6/16/2005<br>Medium                         | Ismael Rodriguez<br>Mike Soria<br>Grounds                           |             | Santa Teresa MS         |
| 3118  | Work In Progress<br>I NEED FOR GYM KEY CYLINDERS TOO TO BE CHANGE BEFORE 7/13/05.CONT.MR.RODRIGUEZ.  | 7/1/2005<br>Medium                          | Ismael Rodriguez<br>Manny Lozoya<br>Key and Lock                    |             | Santa Teresa MS         |
| 1103  | Work In Progress<br>ATTN;RUBEN RONQUILLO. I NEED A TRAILER TOO TRANSPORT ART WORK FOR MR. SANCHEZ TO THE G.M.S 4/14/05. THANK YOU.   | 4/13/2005<br>Medium                         | Ismael Rodriguez<br>Ruben Ronquillo<br>General Maintenance          |             | Santa Teresa MS         |
| 10325 | Work In Progress<br>JIMMY I NEED FOR YOU TO DO SOME SERVICE ON ONE WET N DRY IT IS NOT LIFTING THE WATER PROPERLY I WANTED TO HAVE IT READY FOR SUMMER.THANK YOU.SERIAL NUM.013674 BRAND.NOBLLES.          | 3/7/2006<br>Medium                          | Ismael Rodriguez<br>Jimmy Carbajal<br>Custodial Equipment<br>Repair | Custodial   | Santa Teresa MS         |
| 10791 | Work In Progress<br>MR.LOZOYA YOU CAN ALREADY CHANGE THE CYLINDERS FROM NORTH AND SOUTH BUILDINGS.CHECK WITH MR. RODRIGUEZ.THANK YOU.  | 3/29/2006<br>Medium                         | Ismael Rodriguez<br>Manny Lozoya<br>Key and Lock                    | Office      | Santa Teresa MS         |
| 9575  | Work In Progress<br>MR. SORIA PRUNE OUR CAMPUS TREES .THANK YOU.   | 2/10/2006<br>Medium                         | Ismael Rodriguez<br>Mike Soria<br>Grounds                           | Parking Lot | Santa Teresa MS         |
| 6437  | Work In Progress<br>please replace h20 fountain and unclog drain.  | 10/14/2005<br>Medium                        | David Villalobos<br>Plumbing  | Office      | Santa Teresa MS         |
| 11668 | Work In Progress<br>NEED TO HAVE RED BAG (CONTAMINATED WASTE) PICKED UP.   | 4/26/2006<br>Medium                         | Sal Acuna<br>Custodial  |             | Santa Teresa MS         |
| 4023  | Work In Progress<br>Monthly - Santa Teresa MS Exit Sign Insp:<br>Monthly - Refer to PM schedule details.   | 7/31/2005<br>Medium                         | Alfredo Holguin<br>Jaime Mijarez<br>General Maintenance             |             | Santa Teresa MS         |
| 4013  | Work In Progress<br>Monthly - Santa Teresa MS Emer Light Test:<br>Monthly - Refer to PM schedule details.  | 7/31/2005<br>Medium                         | Alfredo Holguin<br>Jaime Mijarez<br>General Maintenance             |             | Santa Teresa MS         |

| <b>WOID</b> | <b>Status<br/>Description<br/>Action Taken</b>   | <b>Request Date<br/>Completion Date<br/>Priority</b> | <b>Requester<br/>Assigned To<br/>Craft</b>                          | <b>Area Type</b> | <b>Location<br/>Area Number</b> |
|-------------|--|--|---|------------------|---------------------------------|
| 3353        | Work In Progress<br>Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details.  | 7/6/2005<br>Medium                                   | Alfredo Holguin<br>Jaime Mijarez<br>Fire Protection                 |                  | Santa Teresa MS                 |
| 3975        | Work In Progress<br>Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.  | 7/31/2005<br>Medium                                  | Alfredo Holguin<br>Jaime Mijarez<br>Fire Extinguishers              |                  | Santa Teresa MS                 |
| 3330        | Work In Progress<br>Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details.  | 7/6/2005<br>Medium                                   | Alfredo Holguin<br>Jaime Mijarez<br>Fire Protection                 |                  | Santa Teresa MS                 |
| 10943       | Work In Progress<br>Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.  | 4/2/2006<br>Medium                                   | Alfredo Holguin<br>Jaime Mijarez<br>Roof                            |                  | Santa Teresa MS                 |
| 10976       | Work In Progress<br>Monthly - Santa Teresa MS Fire Suppression Insp. - Refer to PM schedule details.   | 4/2/2006<br>Medium                                   | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System            |                  | Santa Teresa MS                 |
| 5113        | Work In Progress<br>AIR CONDITIONER DOES NOT TURN ON THE LEFT SIDE OF THE ROOM FACING CHALK BOARD<br>ROOM 3 MR. DORANTES   | 8/31/2005<br>Medium                                  | Laura Parra<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning | Classroom        | Santa Teresa MS                 |
| 8556        | Work In Progress<br>Kitchen #1- Sink is clogged unable to use<br>Kitchen #4- Pipes under sink leak   | 1/9/2006<br>Medium                                   | Laura Parra<br>David Villalobos<br>Plumbing                         | Classroom        | Santa Teresa MS<br>room 10      |
| 2161        | Work In Progress<br>duplicate keys for new portables   | 5/20/2005<br>Medium                                  | Jose Hinojosa<br>Manny Lozoya<br>Key and Lock                       | Portables        | Santa Teresa MS                 |
| 2204        | Work In Progress<br>5 copies of cabinet key for North building kitchen cabinets  | 5/23/2005<br>Medium                                  | Jose Hinojosa<br>Manny Lozoya<br>Key and Lock                       | Restroom (Boys)  | Santa Teresa MS                 |
| 2059        | Work In Progress<br>HINGES NEED TO BE REPLACED...DOOR NOT CLOSING IN UPPER LEVEL GIRLS BATHROOM  | 5/18/2005<br>Medium                                  | Jose Hinojosa<br>Danny Miranda<br>Doors and Hardware                | Restroom (Girls) | Santa Teresa MS                 |
| 8159        | Work In Progress<br>Markee Sign. As per Mrs. Williams she would like to have the sign installed during winter break.   | 12/15/2005<br>Medium                                 | Jaime Mijarez<br>Carlos Castillo<br>Electrical                      |                  | Santa Teresa MS                 |
| 8161        | Work In Progress<br>Principals office. Need a window installed on interior door.   | 12/15/2005<br>Medium                                 | Jaime Mijarez<br>Danny Miranda<br>Doors and Hardware                |                  | Santa Teresa MS                 |
| 9910        | Work In Progress<br>Campus. Can you help us with a tractor to move all the sand that has accumulated by the walk ways and stairways to the gym. Requested by Mr. Mora. | 2/22/2006<br>Medium                                  | Jaime Mijarez<br>Guadalupe Ontiveros<br>Grounds                     |                  | Santa Teresa MS                 |



| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                     | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 11380 | Work In Progress<br>S.bldg. There is a broken glass on the second level door that exits from the ramp. Ruben please send the glass company,I already patched it up.   | 4/18/2006<br>Medium                         | Jaime Mijarez<br>Ruben Ronquillo<br>Glass\Window Repairs              |           | Santa Teresa MS         |
| 10425 | Work In Progress<br>N.bldg lower level HP 32 is on hi/lo pressure failure. I found leak and sealed it. I need Joe A. to charge the the unit with R22 refrigerant.   | 3/10/2006<br>Medium                         | Jaime Mijarez<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |           | Santa Teresa MS         |
| 11113 | Work In Progress<br>Cafeteria water fountain has a broken drain line. David V. can you help me run a new drain line that goes out through the cynder block wall and into a small gravel pit.  | 4/5/2006<br>Medium                          | Jaime Mijarez<br>David Villalobos<br>Plumbing                         |           | Santa Teresa MS         |
| 11107 | Work In Progress<br>S.bldg office. Joe I need your help on the heat pump. The heat pump leaked out the refrigerant.   | 4/5/2006<br>Medium                          | Jaime Mijarez<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |           | Santa Teresa MS         |
| 5363  | Work In Progress<br>N.bldg maintenance and custodial. Would like a duct and register installed on heat pump.  | 9/9/2005<br>Medium                          | Jaime Mijarez<br>Jose Ambriz<br>Heating/Ventilation /Air Conditioning |           | Santa Teresa MS         |
| 5149  | Work In Progress<br>N.bldg Rm 3. Mrs. williams would like to have a sidewalk that goes from Rm 3 exit door out to the fence. This way when there is a fire drill the special ed students on wheel chairs can be moved away from the building in case of an actual emergency.  | 9/1/2005<br>Medium                          | Jaime Mijarez<br>Michael Munoz<br>Concrete                            |           | Santa Teresa MS         |
| 2597  | Work In Progress<br>N.bldg. Handicap ramp side walk was repaired without expansion joint. Concrete slab cracked and needs to be repaired again. Heavy traffic area.   | 6/7/2005<br>Medium                          | Jaime Mijarez<br>Michael Munoz<br>Concrete                            |           | Santa Teresa MS         |
| 2957  | Work In Progress<br>N. Bldg upper level. Need Price Quote to correct communication problem on hps 17 thru 22, and 25. They go on failure and restore every few minutes.<br><br>Waiting on Vendor (ok) by Purchasing Agent. Will route to Alpine Electric. 10/05<br>3/31 -Pending Price Quote from Joe Valenzuela - mkv<br>4/7 - Job will be completed during the Summer Break | 6/23/2005<br>Medium                         | Jaime Mijarez<br>Margret Villalobos<br>Energy Management System       |           | Santa Teresa MS         |
| 3412  | Work In Progress<br>S.bldg upper level. Because of the shortage of classrooms Mrs. williams has to move the teachers lounge to a storage rm. The floor has no tile, can you include this room with the area's that the contractor will be installing floor tile. Attn: Alfredo holguin.   | 7/8/2005<br>Medium                          | Jaime Mijarez<br>Michael Munoz<br>Carpet Repair                       |           | Santa Teresa MS         |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                            | Area Type | Location<br>Area Number |
|-------|--|---|--|-----------|-------------------------|
| 3465  | Work In Progress<br>N.bldg home ec rm 10. Ruben Ronquillo I am going to need a Miter saw to cut legs on ten of the tables. please make sure it has a good blade. I am planning this project for next week ( 7/18/05.) The wood is oak. | 7/12/2005<br>Medium                         | Jaime Mijarez<br>Ruben Ronquillo<br>General Maintenance      |           | Santa Teresa MS         |
| 3387  | Work In Progress<br>Rm 1. N. bldg lower level Removal of carpet is going to require tile installation. Alfredo H. requested a work order for contractor.   | 7/7/2005<br>Medium                          | Jaime Mijarez<br>Michael Munoz<br>Carpet Repair              |           | Santa Teresa MS         |
| 3364  | Work In Progress<br>S.bldg custodial storage. please make 2ea. A-7 keys for principal and building mechanic.   | 7/6/2005<br>Medium                          | Jaime Mijarez<br>Manny Lozoya<br>Key and Lock                |           | Santa Teresa MS         |
| 1884  | Work In Progress<br>S.bldg rm36. Need to have a safety window with safety glass installed. Rm will be used for a special ed student. Requested by Ms Williams.   | 5/12/2005<br>Medium                         | Jaime Mijarez<br>Danny Miranda<br>Doors and Hardware         | Classroom | Santa Teresa MS         |
| 11383 | Work In Progress<br>Graffiti on Volleyball by Joshua Sifentes 8th grade.<br>Est. Damage 15.00  | 2/14/2006<br>Medium                         | Mr. Mora<br>Jaime Mijarez<br>General Maintenance             |           | Santa Teresa MS         |
| 11384 | Work In Progress<br>Graffiti on Volleyball by Desiree Diaz 8th grade.<br>Est. Damage 15.00   | 2/14/2006<br>Medium                         | Mr. Mora<br>Jaime Mijarez<br>General Maintenance             |           | Santa Teresa MS         |
| 11418 | Work In Progress<br>North office area need to replace carpet.  | 4/19/2006<br>Medium                         | Michael Munoz<br>Michael Munoz<br>Carpet Repair              | Office    | Santa Teresa MS         |
| 11592 | Work In Progress<br>Please get a quote fror acucore for penetration of wall in electrical room.Thanks contact person J.Mijarez   | 4/25/2006<br>Medium                         | Michael Munoz<br>Danny Miranda<br>General Maintenance        | Classroom | Santa Teresa MS         |
| 6625  | Work In Progress<br>Need Heavy Duty Dolly for fire proof file cabinet on Monday October 24, 2005   | 10/21/2005<br>Medium                        | Larry Flores<br>Maria Sitters<br>Custodial                   |           | Sunland Park ES         |
| 10623 | Work In Progress<br>Vacuum needs repair  | 3/17/2006<br>Medium                         | Larry Flores<br>Jimmy Carbajal<br>Custodial Equipment Repair |           | Sunland Park ES         |
| 7029  | Work In Progress<br>The sink in the room 41 is clog need to bring the snake also need to replace the fauset thank you  | 11/4/2005<br>Medium                         | Sebastian Diaz<br>David Villalobos<br>Plumbing               |           | Sunland Park ES         |
| 6692  | Work In Progress<br>Need 4 metal blinds for portable F 46"X 52" thank you.   | 10/24/2005<br>Medium                        | Sebastian Diaz<br>Ruben Ronquillo<br>General Maintenance     |           | Sunland Park ES         |
| 8041  | Work In Progress<br>Portable A - Broken window 30 x 28 Double Glass.<br>Est. Damage 125.00   | 12/1/2005<br>Medium                         | Sebastian Diaz<br>Ruben Ronquillo<br>Glass\Window Repairs    | Portables | Sunland Park ES         |

| <b>WOID</b> | <b>Status<br/>Description<br/>Action Taken</b>   | <b>Request Date<br/>Completion Date<br/>Priority</b> | <b>Requester<br/>Assigned To<br/>Craft</b>                                | <b>Area Type</b> | <b>Location<br/>Area Number</b> |
|-------------|--|--|---|------------------|---------------------------------|
| 8879        | Work In Progress<br>Need to repair lock at cafeteria double doors.<br>thank you.                                   | 1/19/2006<br>Medium                                  | Sebastian Diaz<br>Manny Lozoya<br>Key and Lock                            |                  | Sunland Park ES                 |
| 9221        | Work In Progress<br>Need to replace door closer in front library. thank<br>you                                     | 2/1/2006<br>Medium                                   | Sebastian Diaz<br>Manny Lozoya<br>Key and Lock                            |                  | Sunland Park ES                 |
| 9082        | Work In Progress<br>Need to replace door knob portable E .Is broken<br>is difficult to open from inside.thank you. | 1/27/2006<br>Medium                                  | Sebastian Diaz<br>Manny Lozoya<br>Key and Lock                            |                  | Sunland Park ES                 |
| 9834        | Work In Progress<br>Need to remove sand by the south area with the<br>heavy tractor. thank you.                    | 2/17/2006<br>Medium                                  | Sebastian Diaz<br>Guadalupe Ontiveros<br>Grounds                          |                  | Sunland Park ES                 |
| 10499       | Work In Progress<br>3/14/06<br>need to replace filter grill on the southeast roof<br>thank you                     | 3/14/2006<br>Medium                                  | Sebastian Diaz<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning |                  | Sunland Park ES                 |
| 11617       | Work In Progress<br>Need to replace overload in the water fountain<br>southside inthe hall thank you               | 4/25/2006<br>Medium                                  | Sebastian Diaz<br>Jose Ambriz<br>Heating/Ventilation /Air<br>Conditioning |                  | Sunland Park ES                 |
| 11619       | Work In Progress<br>Need three loads of sand in the kinder<br>playground thank you                                 | 4/25/2006<br>Medium                                  | Sebastian Diaz<br>Guadalupe Ontiveros<br>Grounds                          |                  | Sunland Park ES                 |
| 10977       | Work In Progress<br>Monthly - Sunland Park ES Fire Suppression Insp.<br>- Refer to PM schedule details.            | 4/2/2006<br>Medium                                   | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System                  |                  | Sunland Park ES                 |
| 3179        | Work In Progress<br>Monthly - Sunland Park ES Roof Inspection -<br>Refer to PM schedule details.                   | 7/3/2005<br>Medium                                   | Alfredo Holguin<br>Sebastian Diaz<br>Roof                                 |                  | Sunland Park ES                 |
| 3268        | Work In Progress<br>Monthly - Sunland Park ES Emergency Lighting<br>Insp. - Refer to PM schedule details.          | 7/3/2005<br>Medium                                   | Alfredo Holguin<br>Sebastian Diaz<br>General Maintenance                  |                  | Sunland Park ES                 |
| 3278        | Work In Progress<br>Monthly - Sunland Park ES Exit Sign Insp. - Refer<br>to PM schedule details.                   | 7/3/2005<br>Medium                                   | Alfredo Holguin<br>Sebastian Diaz<br>General Maintenance                  |                  | Sunland Park ES                 |
| 3160        | Work In Progress<br>Monthly - Sunland Park ES Monthly FE Inspection -<br>Refer to PM schedule details.             | 7/3/2005<br>Medium                                   | Alfredo Holguin<br>Sebastian Diaz<br>Fire Extinguishers                   |                  | Sunland Park ES                 |
| 3423        | Work In Progress<br>Yearly - Sunland Park ES Emer. Light Test:<br>Annual - Refer to PM schedule details.           | 7/10/2005<br>Medium                                  | Alfredo Holguin<br>Sebastian Diaz<br>Fire Protection                      |                  | Sunland Park ES                 |
| 3355        | Work In Progress<br>Yearly - Sunland Park ES Exit Sign Test: Annual -<br>Refer to PM schedule details.             | 7/6/2005<br>Medium                                   | Alfredo Holguin<br>Sebastian Diaz<br>Fire Protection                      |                  | Sunland Park ES                 |

| WOID  | Status<br>Description<br>Action Taken  | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                    | Area Type | Location<br>Area Number    |
|-------|--|---|--|-----------|----------------------------|
| 2953  | Work In Progress<br>Please remove sand along fence line by houses.<br>Also scrape playing area.  | 6/23/2005<br>Medium                         | Robert Sanchez<br>Grounds                            |           | Sunland Park ES            |
| 9270  | Work In Progress<br>TA17 AND TA31 - PLEASE ADJUST SO THAT<br>THE KEYS OPEN SIDE DOORS.   | 2/2/2006<br>Medium                          | Irene Trujillo<br>Manny Lozoya<br>Key and Lock       |           | Sunland Park ES            |
| 9985  | Work In Progress<br>PORTABLE A & B NEED THE FLOOR TILE TO BE<br>REPLACED.  | 2/24/2006<br>Medium                         | Irene Trujillo<br>Michael Munoz<br>Carpet Repair     |           | Sunland Park ES            |
| 10102 | Work In Progress<br>PLEASE SPRAY CLASSROOM #21 AND OFFICE<br>AREA FOR LICE.  | 3/1/2006<br>Medium                          | Irene Trujillo<br>Margret Villalobos<br>Pest Control |           | Sunland Park ES            |
| 10373 | Work In Progress<br>2 classroom keys need to be re-keyed so these<br>can open the hall doors from the outside. TA25<br>AND TA63  | 3/8/2006<br>Medium                          | Irene Trujillo<br>Manny Lozoya<br>Key and Lock       |           | Sunland Park ES            |
| 2321  | Work In Progress<br>THE GRASS SHOULD BE REPLACED ON THE<br>CIRCLE ENTERING THE SCHOOL GROUNDS. WE<br>NEED THE AREA SMOOTHED AND SOD PLACED.<br>REQUESTED AS PER MS. LINDA PEREZ, ASST.<br>PRINCIPAL. | 5/26/2005<br>Medium                         | Irene Trujillo<br>Lorenzo Hernandez<br>Grounds       |           | Sunland Park ES<br>GROUNDS |
| 7522  | Work In Progress<br>A kitchen sink is needed in room 52. The new<br>teacher's lounge.  | 11/22/2005<br>Medium                        | Irene Trujillo<br>David Villalobos<br>Plumbing       |           | Sunland Park ES            |
| 7523  | Work In Progress<br>Please remove carpet in room #52 and install<br>floor tile.  | 11/22/2005<br>Medium                        | Irene Trujillo<br>Michael Munoz<br>Carpet Repair     |           | Sunland Park ES            |
| 7041  | Work In Progress<br>A door opening is needed from lounge to existing<br>bathroom in nurse's office. Please send someone<br>to check wiring.<br>1/25 - Faxed to Mr. Chavez for approval - mkv         | 11/4/2005<br>Medium                         | Irene Trujillo<br>Carlos Castillo<br>Electrical      |           | Sunland Park ES            |
| 6878  | Work In Progress<br>ADD NEW ELECTRICAL OUTLET TO TEACHER'S<br>LOUNGE.  | 10/31/2005<br>Medium                        | Irene Trujillo<br>Carlos Castillo<br>Electrical      |           | Sunland Park ES            |
| 3875  | Work In Progress<br>NEED REPLACEMENT KEYS FOR NURSE'S<br>OFFICE DORR AND FILE CABINET  | 7/27/2005<br>Medium                         | Irene Trujillo<br>Manny Lozoya<br>Key and Lock       |           | Sunland Park ES            |
| 11428 | Work In Progress<br>fan is out of order<br><br>Marina Ramirez - SNP Manager 589-2545   | 4/19/2006<br>Medium                         | Alma Terrell<br>Danny Orozco<br>Food Services        | Choral    | Sunland Park ES            |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                    | Area Type | Location<br>Area Number |
|-------|---|---|--|-----------|-------------------------|
| 11495 | Work In Progress<br>ON MAY 3, NEED TO DEL APPROXIMATELY 20 - 30 CHIARS AND 25 TABLES FROM PPD FOR HONORS BANQUET ON 5/4/06. NEED TO PICK UP CHAIRS ON 5/5/06.   | 4/21/2006<br>Medium                         | Aida Salcedo<br>Guillermo Hernandez<br>Custodial                     |           | Sunland Park ES         |
| 9120  | Work In Progress<br>1.3 compartment sink is leaking 2. right side of serving line (cold unit) is not working. and 3. Blodgett Oven is still not heating properly<br><br>Marina Ramirez - SNP Manager 589-2545   | 1/27/2006<br>Medium                         | Alma Terrell<br>Danny Orozco<br>Food Services                        | Cafeteria | Sunland Park ES         |
| 11198 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Larry Flores<br>Custodial                            |           | Sunland Park ES         |
| 9214  | Work In Progress<br>need borders for playground S.P.E.  | 2/1/2006<br>Medium                          | Danny Miranda<br>Sebastian Diaz<br>General Maintenance               |           | Sunland Park ES         |
| 11199 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Jesus Urquidi<br>Custodial                           |           | Sunrise ES              |
| 3533  | Work In Progress<br>Could you turn the air conditioning on we have teachers coming in to get a head start on their rooms. It is very hot and we would greatly appreciate it. Since we are a year round school the teachers need to report on Monday. Thank-you  | 7/14/2005<br>Medium                         | Joanne Munoz<br>Jaime Gomez<br>Heating/Ventilation /Air Conditioning | Classroom | Sunrise ES              |
| 3629  | Work In Progress<br>please cut and weedeat in and aroud lift station. weeds are growing rapid and are going to end up on the playing fields.  | 7/18/2005<br>Medium                         | Paul Quinones<br>Grounds   |           | Sunrise ES              |
| 10978 | Work In Progress<br>Monthly - Sunrise ES Fire Suppression Insp. - Refer to PM schedule details.   | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System             |           | Sunrise ES              |
| 11535 | Work In Progress<br>please check lift station pump is triping thanks  | 4/24/2006<br>Medium                         | Ricardo Jacquez<br>Enrique Sotelo<br>Electrical                      |           | Sunrise ES              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                                       | Area Type | Location<br>Area Number |
|-------|---|---|---|-----------|-------------------------|
| 9456  | Work In Progress<br>Need a gate key for El Paso Disposal.   | 2/7/2006<br>Medium                          | Juliet Parra<br>Manny Lozoya<br>Key and Lock                            |           | Sunrise ES              |
| 11494 | Work In Progress<br>need to cut fence and install 2 new swing gates on south end of campus by lift station  | 4/21/2006<br>Medium                         | Michael Munoz<br>Michael Munoz<br>Fence Repair                          |           | Sunrise ES              |
| 11204 | Work In Progress<br>REQUESTING FERTILIZER TO AEREATE PLAY GROUND THANKS.  | 4/7/2006<br>Medium                          | Paul Quinones<br>Guadalupe Ontiveros<br>Grounds                         |           | Sunrise ES              |
| 11356 | Work In Progress<br>I HAVE A PIGEON CONTROL PROBLEM ON THE ROOFING AREA AGIAN,AROUND THE ROOFING OVER HANG,AND THE MECHANICAL EQUIPMENT.  | 4/13/2006<br>Medium                         | Paul Quinones<br>Margret Villalobos<br>Pest Control                     |           | Sunrise ES              |
| 10452 | Work In Progress<br>BACK FENCING AREA,HIGH WINDS BROKE PAD LOCK TO ROLL GATE NEED TO REPLACE. THANK YOU VERY MUCH!  | 3/13/2006<br>Medium                         | Paul Quinones<br>Manny Lozoya<br>Key and Lock                           |           | Sunrise ES              |
| 10829 | Work In Progress<br>REQUESTING AIR FILTERS FOR THE UNITS IN CLASSROOMS FOR PM SCHEDULING.   | 3/30/2006<br>Medium                         | Paul Quinones<br>Lorenzo Solis<br>Heating/Ventilation /Air Conditioning |           | Sunrise ES              |
| 11074 | Work In Progress<br>Room 203 - Need to change out ballast lamp at entrance to room.   | 4/4/2006<br>Medium                          | Paul Quinones<br>Enrique Sotelo<br>Electrical                           |           | Sunrise ES              |
| 11083 | Work In Progress<br>TROUBLE SHOOT PROBLEM WITH WATER PRESSURE SPRIKLER SYSTEM,I HAVE A BAD BOOSTER PUMP MOTOR TO CURCULATING PUMP I NEED IT REPLACED TO WATER THE GRASS FIELD THANKS. | 4/4/2006<br>Medium                          | Paul Quinones<br>Guadalupe Ontiveros<br>Grounds                         |           | Sunrise ES              |
| 9916  | Work In Progress<br>REQUESTING WIND SCREENING FOR BACK FENCING AREA LOCATED NEAR LIFT STATION AREA IS WHERE WIND SREENING NEEDS TO BE REPLACED  | 2/22/2006<br>Medium                         | Paul Quinones<br>Ruben Ronquillo<br>General Maintenance                 |           | Sunrise ES              |
| 2208  | Work In Progress<br>MASTER COOL UNIT WILL NOT TURN ON AND THE EXHAUST FAN AS WELL,  | 5/23/2005<br>Medium                         | Paul Quinones<br>Jaime Gomez<br>Heating/Ventilation /Air Conditioning   |           | Sunrise ES              |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft  | Area Type | Location<br>Area Number |
|-------|---|---|--|-----------|-------------------------|
| 2209  | Work In Progress<br>STERLING UNIT WET SECTION MIXED AIR<br>CONTROL NOT WORKING PROPERLY DAMPER<br>STAYS SHUT AT TIMES,AND<br>HAS TO BE MOVED MANUALLY FOR<br>COOLING,AND HEATING<br>AS WELL.                        | 5/23/2005<br>Medium                         | Paul Quinones<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Sunrise ES              |
| 2278  | Work In Progress<br>UNIT IN RM.308 NO CIRCULATING WATER.A<br>SLEEVE IS<br>NEEDED TRIPPING ON HIGH HEAD PRESSURE AS<br>WELL  | 5/25/2005<br>Medium                         | Paul Quinones<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Sunrise ES              |
| 2113  | Work In Progress<br>I NEED A COUPLING THAT TURNS THE<br>CIRCULATING PUMP<br>WITH MOTOR SHAFT,TO CIRCULATE WATER TO<br>UNIT IN OUT<br>DOOR MECH. RM.   | 5/19/2005<br>Medium                         | Paul Quinones<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Sunrise ES              |
| 946   | Work In Progress<br>I NEED SAND FOR BOTH PLAY GROUNDS   | 4/7/2005<br>Medium                          | Paul Quinones<br>Lorenzo Hernandez<br>Grounds                            |           | Sunrise ES              |
| 2987  | Work In Progress<br>I NEED SLEEVES,AND ALSO GASKETS THAT<br>CONNECT TO THE MOTOR,AND PUMP HOUSING.<br>THANKS  | 6/24/2005<br>Medium                         | Paul Quinones<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Sunrise ES              |
| 3469  | Work In Progress<br>FENCING AREA IN BACK OF SCHOOL NEAR LIFT<br>STATION<br>NEEDS TO BE REPAIRED,AND ROLL<br>GATE.PROBABLE HIGH<br>WINDS ON 7-11-05 CAUSED THE DAMAGE.NO<br>SIGNS OF<br>VANDILISM ON SCHOOL PROPERTY | 7/12/2005<br>Medium                         | Paul Quinones<br>Michael Munoz<br>Fence Repair                           |           | Sunrise ES              |
| 3477  | Work In Progress<br>I NEED SAND FOR THE PLAY<br>GROUNDS,THANKS.   | 7/12/2005<br>Medium                         | Paul Quinones<br>Lorenzo Hernandez<br>Grounds                            |           | Sunrise ES              |
| 3876  | Work In Progress<br>RM.307,BAD CIRCULATING PUMP NEED TO<br>REPLACE  | 7/27/2005<br>Medium                         | Paul Quinones<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Sunrise ES              |
| 6782  | Work In Progress<br>STERLING HEATING UNIT IN KITCHEN AREA.WILL<br>NOT TURN ON ,MIXED AIR CONTROL NOT<br>WORKING PROPERLY  | 10/26/2005<br>Medium                        | Paul Quinones<br>Jaime Gomez<br>Heating/Ventilation /Air<br>Conditioning |           | Sunrise ES              |
| 11670 | Work In Progress<br>Rooms 108 A-Wing & 209 B-Wing - Units are not<br>working properly in these two rooms.   | 4/27/2006<br>Medium                         | Lorenzo Solis<br>David Boyd<br>Construction                              |           | Vado ES                 |

| WOID  | Status<br>Description<br>Action Taken   | Request Date<br>Completion Date<br>Priority | Requester<br>Assigned To<br>Craft                        | Area Type | Location<br>Area Number |
|-------|---|---|--|-----------|-------------------------|
| 10979 | Work In Progress<br>Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.  | 4/2/2006<br>Medium                          | Alfredo Holguin<br>Danny Orozco<br>Fire Sprinkler System |           | Vado ES                 |
| 9982  | Work In Progress<br>Outside electrical covers are being kicked off.   | 2/24/2006<br>Medium                         | Armando Diaz<br>Enrique Sotelo<br>Electrical             |           | Vado ES                 |
| 10622 | Work In Progress<br>WOULD LIKE A DOOR BELL INSTALL TO THE BACK DOOR FOR DELIVERIES. UNABLE TO HEAR ANYONE AT THE BACK DOOR. LAURA B. SNP MGR 233-2945   | 3/17/2006<br>Medium                         | Jacqueline Aguilar<br>Danny Orozco<br>Food Services      | Cafeteria | Vado ES                 |
| 10422 | Work In Progress<br>Need RFP panels for walls by classrooms   | 3/10/2006<br>Medium                         | Frank Lara<br>David Boyd<br>Construction                 |           | Vado ES                 |
| 9641  | Work In Progress<br>Manny, having trouble with door on rm 310   | 2/13/2006<br>Medium                         | Frank Lara<br>Frank Lara<br>Key and Lock                 |           | Vado ES                 |
| 10051 | Work In Progress<br>2/28/06<br>lupe<br>need tiller to work dirt in playground   | 2/28/2006<br>Medium                         | Frank Lara<br>Guadalupe Ontiveros<br>Grounds             |           | Vado ES                 |
| 8739  | Work In Progress<br>manny need to change lock p.e. office also re-key rm207 also duplicit keys for testing, counslor rm   | 1/13/2006<br>Medium                         | Frank Lara<br>Frank Lara<br>Key and Lock                 |           | Vado ES                 |
| 11200 | Work In Progress<br>NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006. | 4/7/2006<br>Medium                          | Aida Salcedo<br>Armando Diaz<br>Custodial                |           | Vado ES                 |
| 4628  | Work In Progress<br>Need to meet contractor on Monday - to rekey school site.   | 8/17/2005<br>Medium                         | David Boyd<br>Manny Lozoya<br>Key and Lock               |           | Vado ES                 |
| 11541 | Work In Progress<br>WARRANTY WORK NEED TO REPAIR AUTO DOOR OPENER SOUTH EXIE  | 4/24/2006<br>Medium                         | Danny Miranda<br>David Boyd<br>Construction              |           | Vado ES                 |
| 10427 | Work In Progress<br>100 Wing - Room 106<br>Need new exit sign for back door the one there does not work.  | 3/10/2006<br>Medium                         | Danny Miranda<br>David Boyd<br>Construction              |           | Vado ES                 |