

1428 - Work Orders In Progress (Fiscal Year 7/1/05 - 5/31/06)

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10197	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Alma Del Valle Daycare
10218	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
10219	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
11743	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Alma Del Valle Daycare
11764	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
11765	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
3308	Work In Progress Yearly - Alma Del Valle Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Alma Del Valle Daycare
3312	Work In Progress Yearly - Alma Del Valle Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Alma Del Valle Daycare
3960	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Alma Del Valle Daycare
3981	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
3982	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
6005	Work In Progress Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Hector Villalobos Fire Extinguishers		Anthony ES
12467	Work In Progress We need underground utility locates where the new portable will be placed by Tuesday May 30. (Portable Pier Locations)	5/24/2006 Medium	Alfredo Holguin Enrique Sotelo Electrical	Portables	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12471	Work In Progress We need underground utility locates where the new portable will be placed by Tuesday May 30. (Portable Pier Locations)	5/24/2006 Medium	Alfredo Holguin Fred Appelzoller Plumbing	Portables	Anthony ES
10958	Work In Progress Monthly - Anthony ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Anthony ES
11766	Work In Progress Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Hector Villalobos General Maintenance		Anthony ES
11768	Work In Progress Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Hector Villalobos General Maintenance		Anthony ES
11744	Work In Progress Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Hector Villalobos Fire Extinguishers		Anthony ES
1862	Work In Progress New unit that was installed in Nurces area is not sufficient. Need to provide more cooling. Please see Mike	5/11/2005 Medium	Jaime Gomez Heating/Ventilation /Air Conditioning		Anthony ES
8736	Work In Progress please add additional sprinklers to existing sprinkler system in the corridore and between the primary and drug free. Also if h2o can be tied in to pine trees. Thanks	1/13/2006 Medium	Guadalupe Ontiveros Grounds		Anthony ES
9133	Work In Progress main bldg behind annex. Please use backhoe for repair of sewer line.	1/30/2006 High	Guadalupe Ontiveros Grounds		Anthony ES
10183	Work In Progress Walk-in Freezer at 60 degrees Becky Saenz - SNP Manager 882-5607	3/3/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Anthony ES
12234	Work In Progress door of the boiler room is brocken it will not lock with key it needs to be checked out asap to day.	5/16/2006 Medium	Carlos Lujan Manny Lozoya Key and Lock		Anthony ES
12236	Work In Progress the bus exit gate need to fix a wheel is missing it is hard to close	5/16/2006 Medium	Carlos Lujan Hector Villalobos General Maintenance		Anthony ES
12450	Work In Progress I need a part for the x-tractorit is brocken.it is the part the water comes out	5/24/2006 Medium	Carlos Lujan Jimmy Carbajal Custodial Equipment Repair		Anthony ES
12233	Work In Progress REMOVE LIGHTS AND RUN NEW WIRE FOR ALARM	5/16/2006 Medium	Cora Ramirez Carlos Castillo Electrical	Hallway/Corridor	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
2867	Work In Progress need four sinks Anthony elem girls r.r.'s	6/20/2005 Medium	Danny Miranda Fred Appelzoller Plumbing		Anthony ES
2390	Work In Progress room 207 door will not lock need to fix a.s. a. p. for today	5/31/2005 Medium	Hector Villalobos Manny Lozoya Key and Lock	Classroom	Anthony ES
623	Work In Progress 3/18/05 1. check boilers 1.5 go to shop put gas pick up supplies 5.5 pruning trees by football field	3/24/2005 Medium	Hector Villalobos Hector Villalobos General Maintenance		Anthony ES
764	Work In Progress rooms 3 4 5 6 7 8 emergency windows do not open Route to Danny Miranda as per Mike. 9/12/05 - mkv Route to Ruben as per Danny - 5/25/06 - mkv	4/1/2005 Medium	Hector Villalobos Ruben Ronquillo Glass\Window Repairs	Classroom	Anthony ES
823	Work In Progress ALL windows in old primary blg do not open Route to Danny Miranda as per Mike 9/12/05 - mkv Route to Ruben as per Danny - 5/25/06 - mkv	4/4/2005 Medium	Hector Villalobos Ruben Ronquillo Glass\Window Repairs	Classroom	Anthony ES
205	Work In Progress Annex Bldg Girls rr - Broken window 45 1/2 x 14 3/4.	3/9/2005 Medium	Hector Villalobos Ruben Ronquillo Glass\Window Repairs	Restroom (Girls)	Anthony ES Annex Bldg
102	Work In Progress need to remove dirt with tractor by dumpster	3/7/2005 Medium	Hector Villalobos Lorenzo Hernandez Grounds	Cafeteria	Anthony ES
103	Work In Progress boiler room we have a leak in pipe line	3/7/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Mechanical Room	Anthony ES
228	Work In Progress pt 217 replace heating and cooling	3/10/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
331	Work In Progress need 8 sheet metal plates 20x20	3/11/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
1038	Work In Progress replace a/c unit in cafeteria 63 a/c unit	4/11/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Cafeteria	Anthony ES
1039	Work In Progress primary office to replace 45 sidedraft master cool	4/11/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning		Anthony ES
3899	Work In Progress Room 201 - Half of the carpet is bad replace with tile. 11/29/05 - Teacher requesting status on this work order on 11/10/05 a student fell and hurt her leg. -mkv	7/28/2005 Medium	Hector Villalobos Michael Munoz Carpet Repair	Classroom	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
2812	Work In Progress Mrs marquez is requesting that the old cabinets in the old main blg and mild blg lounge be replace	6/16/2005 Medium	Hector Villalobos Danny Miranda General Maintenance		Anthony ES
4255	Work In Progress room 109 needs carpet repair	8/8/2005 Medium	Hector Villalobos Michael Munoz Carpet Repair	Classroom	Anthony ES
4581	Work In Progress old main blg a/c motor burn out a 3 hp volts 230	8/15/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
4478	Work In Progress Chapter bg p.e room replace 3/4 motor with a 1hp motor	8/11/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
4742	Work In Progress need a 3/4 hp motor cafeteira motor burn out old cafeteria	8/22/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Cafeteria	Anthony ES
4743	Work In Progress mild cafeteria burn motor 3/4 hp with a belt 4-L 660 or 670	8/22/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Cafeteria	Anthony ES
4861	Work In Progress Nurse office refrigerator is not working water is leaking from seal	8/24/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning		Anthony ES
7339	Work In Progress Custodial storage faucet is leaking need to replace faucet	11/14/2005 Medium	Hector Villalobos Joe Ontiveros Plumbing	Custodial	Anthony ES
5992	Work In Progress upper primary boiler is leaking replace	9/30/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning		Anthony ES
5944	Work In Progress Old main blg boiler room needs a thermocuple size 56 inch	9/29/2005 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning		Anthony ES
11479	Work In Progress pt 218 need to replace kitchen faucet	4/21/2006 Medium	Hector Villalobos Joe Ontiveros Plumbing	Portables	Anthony ES
11241	Work In Progress Pump house irrigation pump is not working	4/10/2006 Medium	Hector Villalobos Raul Sanchez Sewage/Water Treatment Plant	Athletic Field	Anthony ES
10839	Work In Progress Pts 1 and 3 needs two locks for disconnect electrical box	3/30/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Portables	Anthony ES
11910	Work In Progress Riding mowing machine will not start	5/3/2006 Medium	Hector Villalobos Angel Gonzales Equipment		Anthony ES
11988	Work In Progress I need a key made the old master key for class rooms	5/8/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Classroom	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11989	Work In Progress i need 10 pumps for toilet water tanks	5/8/2006 Medium	Hector Villalobos Joe Ontiveros Plumbing	Restroom (Boys)	Anthony ES
11845	Work In Progress Need to order flush valves for toilets in old main mild blg annex blg need 20	5/2/2006 Medium	Hector Villalobos Joe Ontiveros Plumbing	Restroom (Boys)	Anthony ES
11847	Work In Progress We need to install water filters in old main mild blg uuper primary	5/2/2006 Medium	Hector Villalobos Joe Ontiveros Plumbing	Mechanical Room	Anthony ES
11676	Work In Progress Mild blg front office replace rollup door secure opening a.s.a.p	4/27/2006 Medium	Hector Villalobos Danny Miranda Doors and Hardware		Anthony ES
10600	Work In Progress Need to replace air compressor at pump house As per Rick route to Raul Sanchez 4/7/06 - mkv	3/17/2006 Medium	Hector Villalobos Raul Sanchez Sewage/Water Treatment Plant	Mechanical Room	Anthony ES
10601	Work In Progress We need to replace all 11 high presure toilet valve	3/17/2006 Medium	Hector Villalobos Joe Ontiveros Plumbing	Classroom	Anthony ES
10349	Work In Progress We need to replace a/c unit in pt 217	3/8/2006 Medium	Hector Villalobos Lorenzo Solis Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
10015	Work In Progress Need to replace pump seal	2/27/2006 Medium	Hector Villalobos Lorenzo Solis Heating/Ventilation /Air Conditioning	Mechanical Room	Anthony ES
9440	Work In Progress Need a/c vents for two class rooms 201 202	2/7/2006 Medium	Hector Villalobos Lorenzo Solis Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
9250	Work In Progress Chapter blg p. e bathroom replace lock and straighten out door	2/2/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Office	Anthony ES
9251	Work In Progress Social worker office needs to rekey cabinets	2/2/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Office	Anthony ES
8966	Work In Progress upper primary office needs two filing cabinet locks and two desk locks two cabinet locks	1/24/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Office	Anthony ES
8967	Work In Progress Headstrat pt1 h 2 keys can not open lock on door	1/24/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Portables	Anthony ES
9065	Work In Progress Replace a/c 45 to a 65 master cool room 306	1/26/2006 Medium	Hector Villalobos Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
12286	Work In Progress Adm Intern Mrs menchaca office replace carpet old and to many spots	5/18/2006 Medium	Hector Villalobos Michael Munoz Carpet Repair	Office	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12081	Work In Progress old main blg front office needs to change locks and replace haif door	5/10/2006 Medium	Hector Villalobos Manny Lozoya Key and Lock	Office	Anthony ES
12562	Work In Progress Girls bathroom replace partitions for RC . Wheelchair and one person to fit inside . Handicapped	5/30/2006 Medium	Hector Villalobos Danny Miranda General Maintenance	Restroom (Girls)	Anthony ES
11145	Work In Progress need to paint new metal frame in music rm.	4/6/2006 Medium	Danny Miranda Hector Villalobos Painting		Anthony ES
12297	Work In Progress WATER COMING OUT OF FLOOR DRAIN. AGAIN. BECKY S. SNP MGR 882-3507	5/18/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES
12119	Work In Progress MILK COOLER ON THE AE 4-6 CAMPUS. IS FORMING ALOT OF ICE. IT'S ICE OVER. BECKY S. SNP MGR 882-3507	5/11/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES
9088	Work In Progress AE 4-6 CAMPUS. DISHWASHER HAS ALOT OF LIME BUILD-UP , MAY NEED NEW TIPS ON THE RINSE . BECKY S. SNP MGR 882-3507	1/27/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES
10279	Work In Progress FAN TO OVEN NOT WORKING AND ITS SEEMS THAT THERE IS AN ELECTRIC SHORT SOMEWHERE. BECKY S. SNP MGR 882-3507	3/6/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES
12192	Work In Progress AS PER ANN STEINHOFF- IF CAN REMOVE CARPET FROM CLASSROOM AND APPLY TILE TO THE FLOOR FOR EASIER CLEAN UP.(THERE MIGHT ALREADY BE TILE UNDER CARPET). PROGRAM ENDS MAY 31ST, 2006.	5/15/2006 Medium	Mary Garcia Michael Munoz Carpet Repair	Classroom	Anthony ES
4059	Work In Progress DAYCARE - NEED TO ISSUE KEYS TO CORINA VALDESPINO for (Krishna's Office). WILL BE HERE AT 8:00 AM TOMORROW.	8/1/2005 Medium	Margret Villalobos Manny Lozoya Key and Lock		Anthony ES
12353	Work In Progress Need to line locate behind Mid Bldg on Tuesday, May 23, 2006.	5/19/2006 Medium	Michael Munoz Enrique Sotelo Electrical		Anthony ES
12354	Work In Progress Need to line locate behind Mid Bldg on Tuesday, May 23, 2006.	5/19/2006 Medium	Michael Munoz David Villalobos Plumbing		Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12584	Work In Progress Purchase a 20 x 20 Steel Carport Kit and Trim Kit.	5/30/2006 Medium	Michael Munoz Ruben Ronquillo General Maintenance		Anthony ES
11915	Work In Progress plesae provide a 20x20 slab of concrete for picnic tables and shade.	5/3/2006 Medium	Michael Munoz Michael Munoz Concrete		Anthony ES
11610	Work In Progress please remove manhole lids/rings and concrete rings as per E.I.D. remove septic tank lids and rings. cover septic tanks w/sand.	4/25/2006 4/25/2006 High	Michael Munoz Ramiro Holguin General Maintenance	Athletic Field	Berino ES
11394	Work In Progress please deliver 1 load of sand to site Monday 4-24- 06	4/18/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds	Athletic Field	Berino ES
11993	Work In Progress SPRINKLER HEAD IN ROOM 124 WAS LEAKING WATER NEEDS TO BE CHECK OUT ASAP	5/8/2006 Medium	Ramiro Holguin Joe Ontiveros Fire Sprinkler System		Berino ES
9644	Work In Progress 2/13/06 NEED FIVE 2X12X12	2/13/2006 Medium	Ramiro Holguin Ruben Ronquillo General Maintenance		Berino ES
10606	Work In Progress PORTALBE 141 NEEDS SWAMP COOLER REPLACE WITH A MASTERCOOL 4500 SIDE DRAFT ALSO NEEDS STAND	3/17/2006 Medium	Ramiro Holguin Lorenzo Solis Heating/Ventilation /Air Conditioning		Berino ES
8684	Work In Progress NEED TO REPLACE BROKEN BLINDS ROOM 108 NEEDS ONE 54" P.145 NEEDS 3 35" P. 147 3 45" P 156 2 47"	1/12/2006 Medium	Ramiro Holguin Ruben Ronquillo Glass\Window Repairs		Berino ES
8630	Work In Progress PORTABLE 154, NEEDS CARPET INSTALL FLOOR TILES ARE COMING OFF	1/11/2006 Medium	Ramiro Holguin Michael Munoz Carpet Repair		Berino ES
8560	Work In Progress NEED TO RELACE SKY LIGHT WINDOW 6X6 FEET HAS A HOLE IN TOP CLASS	1/9/2006 Medium	Ramiro Holguin Ruben Ronquillo Glass\Window Repairs		Berino ES
7907	Work In Progress 12/06/05 TO MIKE PORTABLE 154 FLOOR TITLES ARE COMING OFF IF POSSIBLE THIS CHRISTMAS BREAK YOU CAN SOME CARPET INSTALL ED	12/7/2005 Medium	Ramiro Holguin Michael Munoz Carpet Repair		Berino ES
8945	Work In Progress NEED TO REPLACE KEY FOR TV BROKEN ASAP	1/23/2006 Medium	Ramiro Holguin Manny Lozoya Key and Lock		Berino ES
9404	Work In Progress 2/03/06 SECURITY LIGHT COVER ON CAFETERIA OUTSIDE WALL NEEDS TO BE REPLACE	2/6/2006 Medium	Ramiro Holguin Enrique Sotelo Electrical		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
2247	Work In Progress MANNY LOZOYA PORTABLE 140 DOOR NEEDS CLOSURE AND PORTABLE 151 CORE IN HANDLE NEEDS TO BE CHECK OUT KEYS DO NOT WORK	5/24/2005 Medium	Ramiro Holguin Manny Lozoya Key and Lock		Berino ES
2551	Work In Progress 5/26/05 0.5 CHECK WITH JIMMY CLOSE GATES 1.0 CHECHING WITH TEACHERS ON ROOMS TO BE PAINTED 0.5 UNCLOG TIOLET ROOM 100 2.0 HELP RAUL CHECK WELLS 1.0 CHANGE OUT ELECTRICAL BALLAST TEACHERS LOUNGE 0.5 REPAIR BROKEN ELECTRICAL OUTLET IN GYM 1.5 CHECK ALL SPRINKLERS IN PLAYGROUND CHANGE OUT THE ONES NOT WORKING FILL OUT DAILY WORK LOG 5/26 - 7	6/6/2005 Medium	Ramiro Holguin Ramiro Holguin General Maintenance		Berino ES
846	Work In Progress JAIME GOMEZ NEED TO REPLACE FOUR A/C UNITS WESTWING 131,128 ON EASTWING 103,107 ALL 6500	4/5/2005 Medium	Ramiro Holguin Jaime Gomez Heating/Ventilation /Air Conditioning		Berino ES
203	Work In Progress NEED PLAYGROUND FERTELIZES	3/9/2005 Medium	Ramiro Holguin Lorenzo Hernandez Grounds		Berino ES
5338	Work In Progress WALK - IN FREEZER IS LEAKING ALOT OF WATER BETWEEN THE FREEZER AND REFRIG. ELSA - 882-2417	9/8/2005 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Berino ES
2222	Work In Progress Room 140 - Need to replace door closer.	5/23/2005 Medium	Manny Lozoya Manny Lozoya Key and Lock		Berino ES
2817	Work In Progress 1-6 TO 8FT DOOM SKYLIGHT BROKEN AND A/C UNIT CAVED IN. MIKE WILLIAMS-DEPUTY (Pending Skylight) WITNESSED 3 TEENAGERS WALKING INTO BLDG 2 JUMP ON TO WALK-IN FREEZER AND TO BLDG (CALLED SHERIFF) - JIMMY CORTEZ SKYLIGHT WORK ORDER IS PENDING - A/C UNIT WAS PUSH UP (COVER) - 7/13 R. HOLGUIN	6/16/2005 Medium	Jimmy Cortez Ramiro Holguin General Maintenance		Berino ES
5898	Work In Progress Need 2 new keys for office gate and recut master key for Mr Silva THANKS OFFICE KEY IS ON YOUR KEY CHAIN ALREADY	9/28/2005 Medium	Jimmy Cortez Manny Lozoya Key and Lock		Berino ES
5585	Work In Progress need nemaster b key and 55key for new custodian thanks a.s. p	9/19/2005 Medium	Jimmy Cortez Manny Lozoya Key and Lock		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12184	Work In Progress need more belts for royal vaccum	5/15/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial		Berino ES
12185	Work In Progress need 4 new belts for royals vaccum	5/15/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial		Berino ES
12186	Work In Progress need3 new brushs for royal vaccum	5/15/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial		Berino ES
12443	Work In Progress need new vaccum bag for royal	5/24/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial Equipment Repair		Berino ES
9006	Work In Progress Need a gate key for El Paso Disposal.	1/24/2006 Medium	Juliet Parra Manny Lozoya Key and Lock		Berino ES
9455	Work In Progress Need another gate key for El Paso Disposal.	2/7/2006 Medium	Juliet Parra Manny Lozoya Key and Lock		Berino ES
2956	Work In Progress please check all portables and see if all blocking cinder blocks are placed properly and repair if neede.	6/23/2005 High	Ramiro Holguin General Maintenance	Parking Lot	Berino ES
4055	Work In Progress please cut weeds and pick-up debre on east side of rockwall. (i.e weeds bottles cinder blocks.)	8/1/2005 Medium	Ramiro Holguin General Maintenance		Berino ES
4208	Work In Progress MOBILE HOME OCCUPANT WILL BE RECEIVING NEW MOBILE HOME ON APPROXIMATELY 8-29- 05. PLEASE CONNECT ELECTRICAL. 28X54	8/4/2005 Medium	Enrique Sotelo Electrical		Berino ES
10221	Work In Progress Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Ramiro Holguin General Maintenance		Berino ES
10199	Work In Progress Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Ramiro Holguin Fire Extinguishers		Berino ES
10224	Work In Progress Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Ramiro Holguin General Maintenance		Berino ES
10959	Work In Progress Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Berino ES
10953	Work In Progress Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Berino ES
4082	Work In Progress Monitoring Wells - I need a set of keys to the monitoring well caps	8/2/2005 Medium	Alfredo Holguin Manny Lozoya Key and Lock		Berino ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
7756	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas Fire Extinguishers		Chaparral ES
7779	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral ES
7820	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas Fire Protection		Chaparral ES
6123	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Juan Vargas Fire Protection		Chaparral ES
11026	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral ES
10985	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral ES
10930	Work In Progress Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral ES
10913	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral ES
10960	Work In Progress Monthly - Chaparral ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Chaparral ES
10264	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral ES
11984	Work In Progress Need to line locate by blue meter box that belongs to Cloquitt Water Company. DABCC wants to place a sign next to it.	5/5/2006 Medium	Alfredo Holguin Joe Ontiveros Plumbing		Chaparral ES
10200	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral ES
10223	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral ES
8367	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8312	Work In Progress Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas Roof		Chaparral ES
8408	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas Fire Protection		Chaparral ES
9337	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Juan Vargas Fire Extinguishers		Chaparral ES
9360	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral ES
11746	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral ES
11769	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral ES
9401	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Juan Vargas Fire Protection		Chaparral ES
11810	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral ES
11811	Work In Progress Monthly - DP-91 CES - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Ricardo Jacquez Sewage/Water Treatment Plant		Chaparral ES
4518	Work In Progress please replace urinal and commode in mens restroom.	8/12/2005 Medium	Joe Ontiveros Plumbing	Mechanical Room	Chaparral ES
8429	Work In Progress please remove all old fixtures and order new material for rough and top out. also order new fixtures.	1/5/2006 Medium	Joe Ontiveros Ramps/Platforms		Chaparral ES
8430	Work In Progress please remove and provide new electrical to e-wing restrooms as needed. i.e exhaust fan, electric heat. please discuss with hvac techs.	1/5/2006 Medium	Enrique Sotelo Electrical		Chaparral ES
8295	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas Fire Extinguishers		Chaparral ES
10767	Work In Progress E-WING GIRLS RR - CYLINDER KEEPS TURNING AND CAN NOT BE LOCKED.	3/28/2006 Medium	Manny Lozoya Key and Lock	Restroom (Girls)	Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12320	Work In Progress need to cut and remove dead tree by pine trees by new wing.	5/19/2006 Medium	Joe Ramirez General Maintenance		Chaparral ES
5498	Work In Progress sweeper/blower/not/working/choke/broken	9/14/2005 Medium	Daniel Ramirez Jimmy Carbajal Custodial Equipment Repair		Chaparral ES
12561	Work In Progress Broken main water line to irrigation water tank at chaparral elementary.	5/30/2006 Medium	Johnny Acuna Margret Villalobos General Maintenance		Chaparral ES
11144	Work In Progress need to paint all new doors in e-wing	4/6/2006 Medium	Danny Miranda Joe Ramirez Painting		Chaparral ES
9742	Work In Progress Could I get a key for Chap E for sound signal? Thanks, carlos	2/15/2006 Medium	Carlos Vigil Manny Lozoya Key and Lock		Chaparral ES
12326	Work In Progress 5/19/06. need to replace two swamp units in kitchen area with two master cools that are in my storage shed A.S.A.P. the swamp units are very corroded as is the duct work, that pushing thru the ceiling.	5/19/2006 Medium	Joe Ramirez Lorenzo Solis Heating/Ventilation /Air Conditioning		Chaparral ES
12316	Work In Progress 5/19/06. requesting fertilizer be applied to areas where there is grass.	5/19/2006 Medium	Joe Ramirez Guadalupe Ontiveros Grounds		Chaparral ES
12106	Work In Progress 5/11/06. need new portable to be rekeyed thank you.	5/11/2006 Medium	Joe Ramirez Manny Lozoya Key and Lock		Chaparral ES
12163	Work In Progress lupe the valve that controls the water to the pine trees is not working the trees need water badly.	5/12/2006 Medium	Joe Ramirez Guadalupe Ontiveros Grounds		Chaparral ES
11669	Work In Progress As per mr. cardona need to replace floor type urinal with wall mount urinal, also sensor activated lavatory in girls bathroom is not working.	4/27/2006 Medium	Joe Ramirez Joe Ontiveros Plumbing		Chaparral ES
11480	Work In Progress 4/21/06. need to replace the full lenth urinal with a wall mount urinal as per MR CARDONA.	4/21/2006 Medium	Joe Ramirez Joe Ontiveros Plumbing		Chaparral ES
9980	Work In Progress Mr. Cardona is requesting verticle blinds for the front office. measurements are 48"x 84".	2/24/2006 Medium	Joe Ramirez Ruben Ronquillo Glass\Window Repairs		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10303	Work In Progress 3/6/06. as per Mr. Cardona he wants the locks in the maint. cust office and maint shed. to be keyed with a master key.	3/6/2006 Medium	Joe Ramirez Manny Lozoya Key and Lock		Chaparral ES
9201	Work In Progress portables 63 -62 -and 54 need replace a/c master cool 3800	1/31/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning		Chaparral ES
9107	Work In Progress need 200ft. swing chain and 10 swing hanger	1/27/2006 Medium	Juan Vargas Guadalupe Ontiveros Grounds		Chaparral ES
8718	Work In Progress NEED NEW NUMBERS FOR THE CLASSROOMS 0- 1/0-2/0-3/0-4/0-5/0-7/ 101/102/103/104/105/106/107/108/109/ 201/202/203/204/205/206/207/208/209/210/211/2 12/213/214/215/216/217/218/219/220 401/402/403/404/405/406/408/409/410/412/414/4 16/418 301/302/303/304/305/306/307/308/309/310/311/3 12 501/502/503/504/505/506/507/508/510/509/511/51 2 4-B.RESTROOMS 4-G.RESTROOMS 3-MANS 3-WOMANS 1-T.L.ROOMS	1/12/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral ES
8523	Work In Progress room 20 need fix cabinets lock	1/9/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral ES
7946	Work In Progress cafeteria need replace two entry doors	12/8/2005 Medium	Juan Vargas Danny Miranda Doors and Hardware	Cafeteria	Chaparral ES
7947	Work In Progress kitchen need replace entry door	12/8/2005 Medium	Juan Vargas Danny Miranda Doors and Hardware	Cafeteria	Chaparral ES
7949	Work In Progress room 120 need fix bathroom door frame	12/8/2005 Medium	Juan Vargas Danny Miranda Doors and Hardware		Chaparral ES
7646	Work In Progress evenstar playgroun need water fouting fix	11/30/2005 Medium	Juan Vargas Joe Ontiveros Plumbing		Chaparral ES
7863	Work In Progress cafeteria need replace floor tile	12/6/2005 Medium	Juan Vargas Michael Munoz Carpet Repair		Chaparral ES
6343	Work In Progress las vanquetas need grabo a round	10/12/2005 Medium	Juan Vargas Guadalupe Ontiveros Grounds		Chaparral ES
6415	Work In Progress cafeteria exit sign need change	10/14/2005 Medium	Juan Vargas Enrique Sotelo Electrical		Chaparral ES
7378	Work In Progress miusic room and gym. need doors replace	11/15/2005 Medium	Juan Vargas Danny Miranda Doors and Hardware		Chaparral ES
7359	Work In Progress 2 request e. wing rooms need to repair windows	11/15/2005 Medium	Juan Vargas Ruben Ronquillo Glass/Window Repairs		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
7360	Work In Progress rooms 79 71 70 83 need 12 blinds size 33 width 58 length	11/15/2005 Medium	Juan Vargas Ruben Ronquillo General Maintenance		Chaparral ES
6502	Work In Progress room 72 heating not work need help to fix	10/18/2005 Medium	Juan Vargas Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral ES
4602	Work In Progress ruben ronquillo need 10 pvc 45 elbows 6 inches 10 square grate basin 6 inches and 200 ft. 6 inches pvc pipe	8/16/2005 Medium	Juan Vargas Joe Ontiveros Plumbing		Chaparral ES
4030	Work In Progress Room 47 need to instaled a/c ventilation	8/1/2005 Medium	Juan Vargas Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral ES
4213	Work In Progress Rooms 101-102-60-62-61-54-70-96-72-73-97 80- 82-83 need carpet repace	8/4/2005 Medium	Juan Vargas Michael Munoz Carpet Repair		Chaparral ES
2738	Work In Progress 06/13/05 mike munos need to clean the parking	6/13/2005 Medium	Juan Vargas General Maintenance		Chaparral ES
2829	Work In Progress 06/16/05 rooms 81 82 and 72 need window repair	6/16/2005 Medium	Juan Vargas Ruben Ronquillo Glass\Window Repairs		Chaparral ES
2760	Work In Progress SECURE STORAGE	6/14/2005 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral ES
3284	Work In Progress 07/05/05 mike munoz Mr. cardona quiere bertical blind en su oficina size 82 width and 80 length	7/5/2005 Medium	Juan Vargas Ruben Ronquillo General Maintenance		Chaparral ES
3800	Work In Progress 07/25/05 jaime gomes main office need new A/C two 4500 and one 6500	7/25/2005 Medium	Juan Vargas Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral ES
3801	Work In Progress 5/25/05/ mike neseito que pongan sistema de riego para los arboles	7/25/2005 Medium	Juan Vargas Guadalupe Ontiveros Grounds		Chaparral ES
3846	Work In Progress 07/26/05 j. gomes rooms 2 -20-21- 51-47-107- 44- 55-46- need replace A/C 6500	7/26/2005 Medium	Juan Vargas Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral ES
3868	Work In Progress ROOMS 83-82-81-80-72-96-70 NEED WINDOWS REPAIRED OR REPLACE 2-REPORT	7/27/2005 Medium	Juan Vargas Ruben Ronquillo Glass\Window Repairs		Chaparral ES
1422	Work In Progress 04/26/05/jaime gomes library need 3 new master cools	4/26/2005 Medium	Juan Vargas Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
2121	Work In Progress Air condition on cosesion stand need new motor 2 peed	5/19/2005 Medium	Juan Vargas Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral ES
1871	Work In Progress 05/11/05/ jaime gomes cafeteria need new air conditioning	5/12/2005 Medium	Juan Vargas Jaime Gomez Heating/Ventilation /Air Conditioning	Cafeteria	Chaparral ES
2314	Work In Progress 05/26/05 lorenzo nesesito ayada para ubicar los sprinklers	5/26/2005 Medium	Juan Vargas Lorenzo Hernandez Grounds		Chaparral ES
2536	Work In Progress Meza lost keys:He did pay to replace the ones he lost. Meza is room # 130. Rosalinda Mendez would like keys to her filing cabinet. She never got any keys, she has been having to borrow the keys in the ofice. Mendez is in room #122. Manuela Ledesma needs keys for her room. She never received any. She is room # 114. 9/7 - Manny, Mr. Meza is requesting on status of key.- mkv ref wo 4337	6/6/2005 Medium	Jennifer Corral Manny Lozoya Key and Lock	Classroom	Chaparral ES
3871	Work In Progress need an extra key for Even start classroom, Jeannette rm-118	7/27/2005 Medium	Jennifer Corral Manny Lozoya Key and Lock	Classroom	Chaparral ES
3785	Work In Progress NEED A KEY FOR ROOM 114,LEDESMA REPRINT FOR MANNY - REGARDING E-MAIL 7/27/05 - MKV	7/22/2005 Medium	Jennifer Corral Manny Lozoya Key and Lock	Classroom	Chaparral ES
3299	Work In Progress I need some keys for two of the new administrators who will be coming to this school. They have requested main keys to the gate that opens up the fence outside the school and also a set of main keys for the building. If you can please do as soon as possible. Keys for Chaparral Elementary.	7/5/2005 Medium	Jennifer Corral Manny Lozoya Key and Lock	Office	Chaparral ES
4110	Work In Progress Rm-72 Ms. Barret needs screens on her windows. Says they were suppose to be put in last year.	8/3/2005 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs	Classroom	Chaparral ES
3945	Work In Progress Air Conditioner smells like burn and is not cold in rm-128 for Ms. Word	7/29/2005 Medium	Jennifer Corral Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Chaparral ES
3946	Work In Progress Air Conditioner not working in rm-20 for Ms. Gary	7/29/2005 Medium	Jennifer Corral Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6529	Work In Progress Had done a work order before for Ms. Barrett about fixing her windows needs a screen. She says they still haven't done the work order. Thanks	10/18/2005 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs	Classroom	Chaparral ES
10306	Work In Progress computer lab has only one master key to open the door and that key was given to computer Teacher, per Mr. Cardona request he would like extra keys for the computer lab. To be distributed with the administrators.	3/6/2006 Medium	Jennifer Corral Manny Lozoya Key and Lock	Computer Lab	Chaparral ES
10469	Work In Progress Need work order done for screens in Ms. Barrett's classroom. Window in her classroom is falling apart. Fourth work order that has not been done. Rm-72	3/13/2006 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs	Classroom	Chaparral ES
10470	Work In Progress Need work order done for screen to be put in windows for Ms. Herrera's Classroom. Rm-54	3/13/2006 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs	Classroom	Chaparral ES
7710	Work In Progress Window in rm-72 is falling out. When opened it falls out. Doesn't stay up alone needs a stick to hold it up. See Ms. Barrett.	12/1/2005 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs		Chaparral ES
11648	Work In Progress Danny needed a new master key, his was getting ready to break. I went ahead and got him another master key from the office. Not sure if this is procedure but I gave him one. He gave me his key	4/26/2006 Medium	Jennifer Corral Manny Lozoya Key and Lock	Custodial	Chaparral ES
11335	Work In Progress need a key for another show case we have so we can remove from wall.	4/12/2006 Medium	Jennifer Corral Manny Lozoya Key and Lock	Hallway/Corridor	Chaparral ES
11336	Work In Progress need safe in Mr. Cardona's room to be changed again Please as soon as possible very important Please!!!!!! Thank you	4/12/2006 Medium	Jennifer Corral Manny Lozoya Key and Lock	Office	Chaparral ES
12130	Work In Progress need electrical hook up in the evenstart room, where the office is. There is a social worker in that room and needs things to be set up. Rm-R1 See Veronica Rangel	5/11/2006 Medium	Jennifer Corral Enrique Sotelo Electrical	Portables	Chaparral ES
12205	Work In Progress needed a repair lock. Door was stuck in Mens restroom.	5/15/2006 Medium	Jennifer Corral Manny Lozoya Key and Lock	Restroom (Boys)	Chaparral ES
12206	Work In Progress need a change lock to n-master, computer lab.	5/15/2006 Medium	Jennifer Corral Manny Lozoya Key and Lock	Computer Lab	Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12207	Work In Progress need key to concession stand in the office.	5/15/2006 Medium	Jennifer Corral Manny Lozoya Key and Lock	Office	Chaparral ES
12319	Work In Progress need to cover hole on northeast side of barrack .Safety issue.	5/19/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
12105	Work In Progress need to fur out and paint ducting where it was installed for proper air circulation	5/10/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
12195	Work In Progress New Portables - A/S/A/P Start dirt patches for platform not for stairs (pads if needed) and leave a 2 feet surrounding area around platform and installation of ramps and platforms. (If you have any questions call Mike Munoz)	5/15/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds	Portables	Chaparral ES
12321	Work In Progress please trim pine trees that run behind of main bldg and in front of e-wing 1 foot from bottom so you can make wells around tree for watering.	5/19/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
12322	Work In Progress please cut weeds and clean up area in coves of main bldg in the back	5/19/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
12323	Work In Progress please cut weeds and apply round up to weeds on east side of new wing.	5/19/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
12324	Work In Progress please remove all material that is in front of concession stand, delete from inventory and bring to ppd.	5/19/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
10768	Work In Progress Need to cut weeds all around campus (front, bb courts, etc.)	3/28/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
11052	Work In Progress area on the east side of campus and in and around water tank. Need to cut weeds and pick- up debris.	4/3/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
9053	Work In Progress E-Wing Barracks - Repair hole on eastside.	1/26/2006 Medium	Michael Munoz Juan Vargas General Maintenance		Chaparral ES
9054	Work In Progress E-Wing Barracks -Paint door on E-Wing Patio area and repair door (hole on wall E-Wing by Patio).	1/26/2006 Medium	Michael Munoz Juan Vargas Painting		Chaparral ES
9052	Work In Progress Patio (Behind Library) Cut grass, weeds and trim edges of grass on sidewalk.	1/26/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8069	Work In Progress Need to cleanout Mech, Bolier and Electrical Rooms as per Mike Munoz.	12/13/2005 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral MS
11139	Work In Progress Portable - Include exterior siding and skirting repairs and painting.	4/6/2006 Medium	Michael Munoz Danny Miranda General Maintenance	Portables	Chaparral MS
11100	Work In Progress Last portable on the north end of campus. The northeast corner needs more fill dirt. please jack building up and install more bricks in the center and add dirt to the corner and finish the earth work behind portable.	4/5/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds	Portables	Chaparral MS
12444	Work In Progress Need to remove outlets (West Wall) coming down from ceiling, also remove elec. outlet on South Wall by Tuesday, May 30, 2006. Any Questions please call Phillip @ 915-637-0141	5/24/2006 Medium	Phillip Medina Enrique Sotelo Electrical	Library	Chaparral MS
12445	Work In Progress New shelving installed. Carpet pulled away from wall to accommodate new shelving. Carpet needs to be trimmed and fitted around new shelving. For questions please call me (Phillip Medina) at 915-637-0141.	5/24/2006 Medium	Phillip Medina Michael Munoz Carpet Repair	Library	Chaparral MS
9486	Work In Progress need to replace cloged lines on top of rsf unit	2/8/2006 Medium	Ricardo Jacquez Ricardo Jacquez Sewage/Water Treatment Plant		Chaparral MS
12349	Work In Progress Nurse's Portable - Need to run a power pole.	5/19/2006 Medium	Michael Munoz Enrique Sotelo Electrical		Chaparral MS
12350	Work In Progress Nurse's Portable -Install sink and run water thru inside.	5/19/2006 Medium	Michael Munoz Joe Ontiveros Plumbing		Chaparral MS
4072	Work In Progress Room 208 - Mold on ceiling tiles. (Nancy, Nurse @ site called in) - mkv Margaret, Joe replied and said there where a couple of ceiling tiles with small mold droppings on them. He replaced them. However still go ahead and generate a w.o. for our records and have him fill it out. Mike	8/2/2005 Medium	Mary Garcia Joe Ramirez General Maintenance	Classroom	Chaparral MS
10401	Work In Progress MIKE. NEED TOOLBOX FOR THE WORK TRUCK	3/9/2006 Medium	Juan Vargas Michael Munoz Vehicle Maintenance		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10514	Work In Progress need master cool wide sections 10- 6500 and 6 - 4500	3/15/2006 Medium	Juan Vargas Lorenzo Solis General Maintenance		Chaparral MS
11555	Work In Progress REACH - IN REFRIG. TEMP. AT 63. SANDRA DIAZ - 824-4376	4/24/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Chaparral MS
12263	Work In Progress WHERE THE FAN IS INSIDE THE WALK-IN IS LEAKING ALOT OF WATER. HAD TO PUT A PAN TO COLLECT ALL THE WATER LEAKING. JUANA MONTELONGO ASSIST. MGR 824-4376	5/17/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Chaparral MS
11486	Work In Progress mike . need instaled new football score bord in football field 4/15 - Route to Lupe as per Mike	4/21/2006 Medium	Juan Vargas Guadalupe Ontiveros Grounds	Football Field	Chaparral MS
11447	Work In Progress lobby need fix front entry door	4/20/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral MS
11448	Work In Progress coudtian door closed lobby area not lock	4/20/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral MS
11274	Work In Progress restrooms 200 hollway and main office man r. room need fix	4/11/2006 Medium	Juan Vargas Joe Ontiveros Plumbing		Chaparral MS
11326	Work In Progress mike. need instaled new football score bord in southside football field	4/12/2006 Medium	Juan Vargas Guadalupe Ontiveros Grounds	Football Field	Chaparral MS
11329	Work In Progress 400 hollway entry door wireglass is broken need replace	4/12/2006 Medium	Juan Vargas Ruben Ronquillo Glass\Window Repairs		Chaparral MS
10843	Work In Progress gym southside door not open need fix	3/30/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral MS
10650	Work In Progress GYM need replace two a/c 8500	3/20/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning	Gym	Chaparral MS
11565	Work In Progress boys locker room need secure door by the end of the day panicbar is broken	4/24/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral MS
11545	Work In Progress nurse portable need the fix window	4/24/2006 Medium	Juan Vargas Ruben Ronquillo Glass\Window Repairs		Chaparral MS
11696	Work In Progress water founting in main lobby not working	4/27/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11976	Work In Progress urinal clogge in boys r. room hallway 100	5/5/2006 Medium	Juan Vargas Joe Ontiveros Plumbing		Chaparral MS
11936	Work In Progress need replace kitchen grasee tramp	5/4/2006 Medium	Juan Vargas Danny Orozco Food Services		Chaparral MS
8490	Work In Progress 1/6/06. need a new lock for bus turnaround south gate, lock has been cut off.	1/6/2006 Medium	Joe Ramirez Manny Lozoya Key and Lock		Chaparral MS
6558	Work In Progress 10/19/05. we need propane tank filled for portable housing rms. 1&2. ATTEN. RUBEN.	10/19/2005 10/21/2005 Medium	Joe Ramirez Ruben Ronquillo General Maintenance		Chaparral MS
7324	Work In Progress 11/14/05. door closer on walk in freezer door needs to be replaced. thanks.	11/14/2005 Medium	Joe Ramirez Danny Orozco Food Services		Chaparral MS
2919	Work In Progress 6/21/05. need to replace s.e. corner a/c gym area.	6/21/2005 Medium	Joe Ramirez Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral MS
3720	Work In Progress 7/12/05. need a/c replaced on portable 1 rm. 2 please.	7/20/2005 Medium	Joe Ramirez Jaime Gomez Heating/Ventilation /Air Conditioning		Chaparral MS
9827	Work In Progress Coach Y. would like to have a plumber check out the shower system it is not functioning at full capacity.	2/17/2006 Medium	Joe Ramirez Joe Ontiveros Plumbing		Chaparral MS
12439	Work In Progress new portable need change door locks	5/24/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral MS
12511	Work In Progress a/c on weight need fix	5/25/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning		Chaparral MS
12492	Work In Progress front and fotboll fields side entry doors need replace middle post	5/25/2006 Medium	Juan Vargas Danny Miranda Doors and Hardware		Chaparral MS
12156	Work In Progress coach y need 6 storage keys	5/12/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral MS
12168	Work In Progress please check vent duck on serves room on 400 hallway	5/12/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning		Chaparral MS
12255	Work In Progress com lab. a/c need check electrical wire	5/16/2006 Medium	Juan Vargas Enrique Sotelo Electrical	Computer Lab	Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12232	Work In Progress entry door next to boys locker room. 3 glass is broken need replace 2- wire glass 73.5 19.5 in. and 30- 19.5 in. and 1-35.5in, 23.5in	5/16/2006 Medium	Juan Vargas Ruben Ronquillo Glass\Window Repairs		Chaparral MS
12118	Work In Progress BLEACHERS NEED TO BE CLEANED. PLEASE NOTIFY AIDA WHEN PROCEDURE IS COMPLETED SO AN INSPECTION CAN BE DONE.	5/11/2006 Medium	Aida Salcedo Robert Gonzalez Custodial		Chaparral MS
11176	Work In Progress NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006.	4/7/2006 Medium	Aida Salcedo Robert Gonzalez Custodial		Chaparral MS
11323	Work In Progress NEED TO POWER WASH ALL CAFETERIA CHAIRS.	4/12/2006 Medium	Aida Salcedo Guillermo Hernandez Custodial		Chaparral MS
9778	Work In Progress c.m.s. need to paint new doors around gym	2/16/2006 Medium	Danny Miranda Juan Vargas Painting		Chaparral MS
12460	Work In Progress need to repair outside wall on portables chap. mid	5/24/2006 Medium	Danny Miranda Danny Miranda General Maintenance		Chaparral MS
3607	Work In Progress need to paint new door @ football storage rm.	7/18/2005 Medium	Danny Miranda Joe Ramirez General Maintenance		Chaparral MS
3608	Work In Progress need to paint new door @ rm. 86	7/18/2005 Medium	Danny Miranda Joe Ramirez General Maintenance		Chaparral MS
12242	Work In Progress REPLACE SPRINKLERS I-20 AT PLAYING FIELDS.	5/16/2006 Medium	Guadalupe Ontiveros Bobby Aldaz Grounds		Chaparral MS
11036	Work In Progress NEED A KEY FOR NEW FILE CABINET THAT DOESN'T HAVE ONE.	4/3/2006 Medium	Elena Palacios Manny Lozoya Key and Lock	Office	Chaparral MS Shirley's Desk
9825	Work In Progress SHOWERS IN BOYS GYM NEED SERVICING ONLY SEVEN OUT OF TEN ARE WORKING. POSSIBLY INSTALL NEW SHOWER HEADS.	2/17/2006 Medium	Elena Palacios Joe Ontiveros Plumbing	Gym	Chaparral MS BOYS GYM
9629	Work In Progress sink in womens bathroom in front office is leaking and splashes water everywhere from the sides when it is opened.	2/13/2006 Medium	Elena Palacios Joe Ontiveros Plumbing		Chaparral MS
8488	Work In Progress Need keys to be made/duplicated for various rooms.	1/6/2006 1/9/2006 Medium	Elena Palacios Manny Lozoya Key and Lock	Classroom	Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8702	Work In Progress needs copy of key A-24, needs to put new locks on two files cabinets in front office	1/12/2006 Medium	Elena Palacios Manny Lozoya Key and Lock		Chaparral MS Room 201
12304	Work In Progress Need an upgrade on sprinklers , the ones we have are old and do not reach the entire area that needs to be watered.	5/18/2006 Medium	Elena Palacios Guadalupe Ontiveros Grounds		Chaparral MS Around Building
8296	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
5463	Work In Progress need to pour landing and sidewalks to portables by football feild.	9/13/2005 Medium	Michael Munoz Concrete	Portables	Chaparral MS
3648	Work In Progress please get with speedy and have him train you on the sprikler system on football field and thru out campus. Identify all valves and repair what is needed. also ask him for a key for sprinkler box and have him teach you the programs.	7/19/2005 Medium	Joe Ramirez General Maintenance	Football Field	Chaparral MS
3649	Work In Progress need to cut weeds and grass behind library and courtyard and surrounding areas tru -out campus including pond. Also need to irrigate these areas also.	7/19/2005 High	Joe Ramirez Grounds		Chaparral MS
3650	Work In Progress please paint railing on new portables that where installed and modified and all railings that are in need.	7/19/2005 Medium	Joe Ramirez General Maintenance		Chaparral MS
3656	Work In Progress please put up fence where portables where installed even if its on a temp bases.	7/19/2005 Medium	Joe Ramirez General Maintenance	Football Field	Chaparral MS
1854	Work In Progress Joe please order paint from Ruben so when portables arrive you can start painting them. Please call Mike	5/11/2005 Medium	Joe Ramirez Painting	Portables	Chaparral MS
9362	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
9364	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
9338	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9351	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral MS
8369	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
8371	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
10201	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Juan Vargas Fire Extinguishers		Chaparral MS
10225	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral MS
10227	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral MS
10961	Work In Progress Monthly - Chaparral MS Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Chaparral MS
3314	Work In Progress Yearly - Chaparral MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral MS
3336	Work In Progress Yearly - Chaparral MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral MS
3148	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
3241	Work In Progress Monthly - Chaparral MS Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
3243	Work In Progress Monthly - Chaparral MS Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
3307	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral MS
7061	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6008	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
6084	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
6086	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
7781	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
7783	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
7757	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
3977	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral MS
7074	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral MS
7085	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
7087	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
5204	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
5227	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
5229	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
3988	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3990	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
3964	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
12384	Work In Progress we have a biohazard infectious waste sharps container to be picked up.	5/22/2006 Medium	Robert Gonzalez Sal Acuna Custodial		Chaparral MS
12161	Work In Progress I NEED A SQUEEGY FOR THE OLD BLACK WET & DRY. I WILL INSTALL THEM MYSELF. THANK YOU	5/12/2006 Medium	Robert Gonzalez Jimmy Carbajal Custodial Equipment Repair		Chaparral MS
7525	Work In Progress MRS. ADAMS ROOM 203 HAS CABINETS AND DRAWERS THAT ARE LOCKED AND SHE DOESN'T HAVE A KEY TO UNLOCK THEM. SHE WOULD LIKE TO HAVE THEM UNLOCKED AS SOON AS POSSIBLE. THANK YOU	11/22/2005 Medium	Robert Gonzalez Manny Lozoya Key and Lock		Chaparral MS
2799	Work In Progress I NEED IF POSSIBLE 2 MORE 2 WHEEL DOLLIES. EVERY BREAK WE HAVE ESPECIALY THE SUMMER BREAK. WE HAVE TEACHERS MOVING FROM ONE ROOM TO ANOTHER AND SOME OF THEM BORROW THE DOLLIES. IT MAKES HARD FOR US BECAUSE WE'RE MOVING FURNITURE OR BOOKS AND OTHER THINGS. THANK YOU ROBERT	6/15/2005 Medium	Robert Gonzalez Aida Salcedo Custodial		Chaparral MS
2818	Work In Progress WE NEED 3 CHAIR DOLLIES. WE HAVE ALOT OF SPECIAL EVENTS IN WHICH WE HAVE TO TAKE ANY WHERE FROM 200 TO 400 CHAIRS TO THE GYM FROM THE CAFETERIA AND CLASSROOMS. THIS YEAR WITH THE 9TH GRADERS WE'LL HAVE EVEN MORE SET UPS TO DO . WE NEED THE DOLLIES TO BE LIKE THE TWO THAT WE HAVE NOW, TALL WE CAN CARRY TEN CHAIRS AT A TIME. THANK YOU ROBERT	6/16/2005 Medium	Robert Gonzalez Aida Salcedo Custodial		Chaparral MS
3499	Work In Progress We need locks to be installed on the center pole to the double doors in the front entrance,north east doors and south east doors. This is the oldest part of the school. the newer part of the school already have locks on the center poles. This old doors are the once that we use more often. This locks will make it so much faster and easier. THANK YOU ROBERT	7/13/2005 Medium	Robert Gonzalez Manny Lozoya Key and Lock		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11104	Work In Progress NEED A SMALL FENCE BETWEEN PROTABLE # 1 AND THE SIDE FENCE TO STOP STAFF AND STUDENTS FROM TAKING A SHORTCUT THROUGH THERE. ALOT OF DIRT IS TRACKED IN BECAUSE OF THIS . THE FENCE WE NEED ONLY HAS TO BE ABOUT 4 FT BY 6 FT. THANK YOU As per Mike route to Juan Carlos - mkv 5/2/06	4/5/2006 Medium	Robert Gonzalez Juan Vargas General Maintenance		Chaparral MS
2487	Work In Progress need extra key for rm 405a	6/3/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Classroom	Chaparral MS 405a
2488	Work In Progress need extra key for rm 405b	6/3/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Classroom	Chaparral MS 405b
2489	Work In Progress need to rekey storage rm in 100 hall to open only w/ A82	6/3/2005 6/3/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Office	Chaparral MS storage rm
1708	Work In Progress NEED TO CHANGE STORAGE ROOM LOCK TO OPEN WITH KEY A-82 ONLY. ALSO DOOR MUST REMAIN LOCKED AT ALL TIMES.	5/6/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Hallway/Corridor	Chaparral MS 100 STORAGE
3855	Work In Progress NEED TO REKEY CABINET.	7/26/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Classroom	Chaparral MS 204
3439	Work In Progress NEED KEYS FOR TWO NEW PORTABLES.	7/11/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Portables	Chaparral MS
2822	Work In Progress rekey file cabinets--about 8 or 9	6/16/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Custodial	Chaparral MS
2823	Work In Progress need to key stage cabinets to open w/ only one key.	6/16/2005 Medium	Vickie Reed Manny Lozoya Key and Lock		Chaparral MS
4509	Work In Progress need to rekey file cabinets. 2	8/12/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Classroom	Chaparral MS 104
4639	Work In Progress NEED 3 REPLACEMENT KEYS FOR 3 A-34'S THAT DO NOT WORK.	8/17/2005 Medium	Vickie Reed Manny Lozoya Key and Lock	Office	Chaparral MS VICKIE-KEY
10951	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin David Acosta Fire Extinguishers		Desert Pride
11762	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin David Acosta Fire Extinguishers		Desert Pride
10931	Work In Progress Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin David Acosta Roof		Desert Pride

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10990	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
10994	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
11774	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
11778	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
4992	Work In Progress please remove marquee sign from desertveiw and install at desert pride. please be careful when removing.see mike	8/29/2005 Medium	Guadalupe Ontiveros Grounds		Desert Pride
11598	Work In Progress Sinks in restrooms- one missing pop-up drain and the other is broken. need to replace.	4/25/2006 Medium	David Acosta David Villalobos Plumbing	Classroom	Desert Pride 1 & 2
11599	Work In Progress Staff members complaining about front entrance gate to parking lot a little hard to push open & pull gate.	4/25/2006 Medium	David Acosta Michael Munoz Fence Repair	Parking Lot	Desert Pride
9877	Work In Progress front office building - roof missing tile Route to Gerry Marquez as per Mike 3/10/06	2/21/2006 Medium	David Acosta Michael Munoz Roof	Office	Desert Pride
7666	Work In Progress having trouble unlocking the westside door (cylinder).	11/30/2005 Medium	David Acosta Manny Lozoya Key and Lock	Classroom	Desert Pride #8
7731	Work In Progress need gate repairs-vehicles hit and run on gate .(front entrance)	12/2/2005 Medium	David Acosta Ruben Ronquillo Fence Repair	Parking Lot	Desert Pride front entrance
7955	Work In Progress Vandalism - Damage to front entrance roll gate hit by vehicle. (Case# 2005-1037) Julio Ledesma #831	12/2/2005 Medium	David Acosta Michael Munoz Fence Repair		Desert Pride
8880	Work In Progress need to replace broken toilet seat	1/19/2006 Medium	David Acosta David Villalobos Plumbing	Computer Lab	Desert Pride
5959	Work In Progress need to ccheck a/c blower . It stops blowing When completing a work order you need to enter labor hours. - Thanks Margret	9/29/2005 5/17/2006 Medium	David Acosta Jose Ambriz Heating/Ventilation /Air Conditioning	Classroom	Desert Pride #1
5336	Work In Progress Principals requests: for dead bolt locks for last portable (where break-in occur)	9/8/2005 Medium	David Acosta Manny Lozoya Key and Lock	Classroom	Desert Pride #6,7.

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4642	Work In Progress need one key for storage closet for teacher in room #3	8/17/2005 Medium	David Acosta Manny Lozoya Key and Lock	Classroom	Desert Pride 3
4304	Work In Progress need locks for two doors to the hall way, that needs to be use as storage for science rooms.	8/8/2005 Medium	David Acosta Manny Lozoya Key and Lock	Classroom	Desert Pride #3,4
1410	Work In Progress need seven locks for doors to front offices. (in counslor, social workers area.)	4/25/2005 Medium	David Acosta Manny Lozoya Key and Lock	Office	Desert Pride
1834	Work In Progress need two plactic name plates for front office doors-(ALL VISITORS MUST SIGN IN AT FRONT OFFICE)	5/11/2005 Medium	David Acosta Manny Lozoya Key and Lock	Office	Desert Pride
3791	Work In Progress need plastic name plates(12)MS. S. VERLANDER, MS. I. RAMIREZ, MS. BACH-HAGUE, MS. B. COSTULIS, MS. C. MCDONALD, MR. C. VELA, MR. P. WYMAN, MS. G. PARKER, MS. S. GARCIA, MR. D. NEAL , MS. J. ZAPATA, MS. D. DEAN	7/25/2005 Medium	David Acosta Manny Lozoya Key and Lock	Classroom	Desert Pride
3064	Work In Progress Att: Sal Acuna-requesting for a desk mover and red flat truck.	6/29/2005 Medium	David Acosta Sal Acuna Custodial	Football Field	Desert Pride
2910	Work In Progress need two light switches installed for iep room and custodian office (no light switches in rooms.)	6/21/2005 Medium	David Acosta Carlos Castillo Electrical	Office	Desert Pride
2606	Work In Progress need one key for classroom for new teacher	6/7/2005 Medium	David Acosta Manny Lozoya Key and Lock	Classroom	Desert Pride 5
12090	Work In Progress Restroom is out of order- One tie down bolt to toilet base rusted away and broke off.. toilet is very loose and not useable	5/10/2006 Medium	David Acosta David Villalobos Plumbing	Restroom (Boys)	Desert Pride 2nd building
12091	Work In Progress toilet flushing very slow- try hand snake to remove object from trap. still water won't flush enough to use.	5/10/2006 Medium	David Acosta David Villalobos Plumbing	Classroom	Desert Pride 6 & 7
12446	Work In Progress DAVID ACOSTA WILL BE OUT ON: MAY 26 JUNE 5 JUNE 30 - JULY 5 YOU WILL NEED TO DO THE FOLLOWING: -WATER (HOSES BY PORTABLES NEW ONE IN STORAGE. -TAKE OUT TRASH AND RESTROOMS/OFFICE AREA	5/24/2006 Medium	Aida Salcedo Sal Acuna Custodial		Desert Pride

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4460	Work In Progress I need an office key for Ms. Maes, Clerk at Desert Pride Academy	8/10/2005 Medium	Mary Telles Manny Lozoya Key and Lock	Office	Desert Pride
9144	Work In Progress NEED A KEY (CD-32) FOR KITCHEN DOORS. REQUESTED BY MRS. MARTINEZ: PRINCIPAL	1/30/2006 Medium	Marisela Torres Manny Lozoya Key and Lock		Desert Trail Intermediate
10511	Work In Progress NEED TO REPLACE COMERCIAL FLOOR TILE TO BUS LOBBY	3/15/2006 Medium	Marisela Torres Michael Munoz General Maintenance		Desert Trail Intermediate
11318	Work In Progress 1522 ASPIRADORA RUEDAS . MANGO.	4/12/2006 Medium	Marisela Torres Jimmy Carbajal Custodial Equipment Repair		Desert Trail Intermediate
12298	Work In Progress PO R FAVOR, RECOJER ASPIRADORA SERIAL# K96A00001575 PRENDE UN RATO Y SE APAGA. GRACIAS.	5/18/2006 Medium	Marisela Torres Jimmy Carbajal Custodial Equipment Repair		Desert Trail Intermediate
12300	Work In Progress NECESITO BANDAS PARA LAS ASPIRADORAS.ME PODRIA MANDAR 4? GRACIAS	5/18/2006 Medium	Marisela Torres Jimmy Carbajal Custodial Equipment Repair		Desert Trail Intermediate
12301	Work In Progress NECESITO 2 CEPILLOS PARA ASPIRADORA. GRACIAS.	5/18/2006 Medium	Marisela Torres Jimmy Carbajal Custodial Equipment Repair		Desert Trail Intermediate
12559	Work In Progress WALK-IN REFRIG. DOWN. NO POWER TO TOP. WHERE FAN IS AT. PAT C. SNP MGR 824-3822	5/30/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Desert Trail Intermediate Cafeteria	
12194	Work In Progress New Portables - A/S/A/P Start dirt patches for platform not for stairs (pads if needed) and leave a 2 feet surrounding area around platform and installation of ramps and platforms. (If you have any questions call Mike Munoz)	5/15/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		Desert Trail Intermediate Portables
6266	Work In Progress RUSH ! or as soon as possible or Monday even. Could I get a line locate for Desert Trails Portables?	10/11/2005 Medium	Carlos Vigil Enrique Sotelo Electrical		Desert Trail Intermediate
12441	Work In Progress Need a 12' Ft. Extension Cord.	5/24/2006 Medium	Johnny Acuna Enrique Sotelo Electrical		Desert Trail Intermediate
12501	Work In Progress need to replace hand dryer to boys restroom in the NW hall. WORLD DRYER: MODEL #WA126 SERIAL #90332	5/25/2006 Medium	Johnny Acuna Enrique Sotelo Electrical		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9779	Work In Progress Need keys made for Portable #400 furniture: Teacher's desk (3) different locks, need to install a lock to filing cabinet (cabinet still has the knockout), and a key for storage cabinet.	2/16/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
9430	Work In Progress (Danny Miranda) Portable #411, #412: Need to replace hallway and restroom doors. Thank You !!!!!	2/6/2006 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
9614	Work In Progress Need a new key for room #212. Teacher lost key. (J-50) Sylvia Lorenzo.	2/13/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
9062	Work In Progress need (2) flush valve kits for restroom comodes. One for boy's RR in the NW hall (handicap), and the other for the girl's RR in front of the teacher's lounge (handicap).	1/26/2006 Medium	Johnny Acuna Joe Ontiveros Plumbing		Desert Trail Intermediate
9001	Work In Progress need a restroom partition installed in room #107. (handicapp room)	1/24/2006 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
9048	Work In Progress need a J-11 lock for outdoor cage gate between the lift station and the baseball backstop in the playground area. Thank You !!!	1/25/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
8625	Work In Progress portable #407: need a lock with key installed to filing cabinet. cabinet has no lock installed. It still has an oval knockout hole to it. Also need a key made to teacher's desk. I have tried out all extra keys from the office.	1/11/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
8166	Work In Progress need to replace cracked window to portable #412. Have already placed glass patch on the window (both sides)	12/16/2005 Medium	Johnny Acuna Ruben Ronquillo Glass\Window Repairs		Desert Trail Intermediate
11601	Work In Progress (BROKEN FIRE ESCAPE WINDOW HARDWARE AND BUTTONS TO PORTABLES) NEED TO REPLACE BROKEN FIRE ESCAPE WINDOW HARDWARE AND BUTTONS TO PORTABLES: #403, #409, AND #410. THANK YOU.....	4/25/2006 Medium	Johnny Acuna Ruben Ronquillo Glass\Window Repairs		Desert Trail Intermediate
11559	Work In Progress (David Boyd) Outdoor expansion joint located in the bus area turnaround has a 1" separation and has cracked the upper part of the wall. Please come and check. Thank You....	4/24/2006 Medium	Johnny Acuna David Boyd Construction		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11560	Work In Progress NEED A GATE INSTALLED WHERE TWO SIDEWALKS MEET BETWEEN CHAPARRAL ELEM. AND DESERT TRAIL. (MIDDLE FENCE LINE). (SIDEWALKS ARE FOR HANDICAPP FIRE EXIT ESCAPE ROUTE.)	4/24/2006 Medium	Johnny Acuna Michael Munoz Fence Repair		Desert Trail Intermediate
11561	Work In Progress need 277v ballasts, and 120v ballasts. Also need wire nuts. Thank You....	4/24/2006 Medium	Johnny Acuna Enrique Sotelo Electrical		Desert Trail Intermediate
11831	Work In Progress (TRUCK #94) PLEASE FIX DRIVER'S SIDE DOOR WINDOW TO WORK TRUCK. WINDOW DOES NOT ROLL DOWN. THANK YOU.....	5/1/2006 Medium	Johnny Acuna Angel Gonzales Vehicle Maintenance		Desert Trail Intermediate
11849	Work In Progress need (2) square keys for outdoor water valves on the main building walls. (where the water hoses connect)	5/2/2006 Medium	Johnny Acuna Joe Ontiveros Plumbing		Desert Trail Intermediate
11836	Work In Progress DAVID BOYD ROOF LEAK IN THE GIRL'S RESTROOM IN FRONT OF THE TEACHER'S LOUNGE. LEAK GOES THROUGH ALL THE WAY DOWN INTO THE CEILING OF THE RESTROOM AND BUBBLES UP THE PAINT. HAVE TRIED TO PATCH IT UP BUT CANNOT FIND THE LEAK. PLEASE STOP BY WHEN YOU GET A CHANCE OR SEND ME SOME CONTRACTORS TO HELP ME FIND THE LEAK. THANK YOU.....	5/1/2006 Medium	Johnny Acuna David Boyd Construction		Desert Trail Intermediate
11707	Work In Progress NEED PLAYGROUND SAND FOR SWINGS.	4/27/2006 Medium	Johnny Acuna Guadalupe Ontiveros Grounds		Desert Trail Intermediate
6883	Work In Progress need a lock (J-11) for new gate that was installed located in the fence between CH. ELEM and CH. DESERT TRAIL closest to Lisa ST. (To be locked during LOCK DOWN events). Thank You !!!!!!!	10/31/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
6910	Work In Progress need a replacement heating coil (boiler heating system) for cafeteria heater. Old heater leaks: Model # LHD103CH Serial #35C01059-06	11/1/2005 Medium	Johnny Acuna Jose Ambriz Heating/Ventilation /Air Conditioning		Desert Trail Intermediate
6846	Work In Progress fire-proof filing cabinet inside vault: please fix or replace lock.	10/28/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
7573	Work In Progress need a gas valve for reznor roof top heater. (valve doesn't close and leaks a little). HONEYWELL : VR8304M 2880 supplied Johnny w/gas valve and he will install.	11/28/2005 12/1/2005 Medium	Johnny Acuna Lorenzo Solis Heating/Ventilation /Air Conditioning		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
7366	Work In Progress need to replace door frame and door to portable #404.	11/15/2005 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
7184	Work In Progress Please replace metal door (Back Door) from the kitchen. Door is corroded and getting worse. Thank You !!!	11/8/2005 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
7520	Work In Progress (Ruben Ronquillo) Need cement mixer for next week to do cement project in parking lot area. (ramp)	11/22/2005 Medium	Johnny Acuna Ruben Ronquillo General Maintenance		Desert Trail Intermediate
7408	Work In Progress NEED TO INSTALL FENCE AROUND FIRE HYDRANT. (SEE ATTACHED)	11/16/2005 Medium	Johnny Acuna Michael Munoz Fence Repair		Desert Trail Intermediate
6170	Work In Progress please repair or replace door knob in the kitchen going outdoors in the back:(door jams and is hard to open) Thank You !!!!!!!!!!!!!!!!!!!!!	10/4/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
5426	Work In Progress need a replacement heating coil (Boiler System) in the Cafeteria/Gym. (Old one Leaks)	9/12/2005 Medium	Johnny Acuna Jaime Gomez Heating/Ventilation /Air Conditioning		Desert Trail Intermediate
4558	Work In Progress Mrs. Bonham (Asst. Principal) requesting concrete slab to be installed between portable #412 and #413 art studio.	8/15/2005 Medium	Johnny Acuna Michael Munoz Concrete		Desert Trail Intermediate
2322	Work In Progress PLEASE SEND EXTERMINATOR OR MOUSE TRAPS TO RM.#116(MRS. DOMINGUEZ) MOUSE INSIDE CLASSROOM.	5/26/2005 Medium	Johnny Acuna Johnny Acuna Pest Control		Desert Trail Intermediate
2376	Work In Progress NEED TO REPLACE DOOR FRAME TO PORTABLE #411. (MAIN DOOR).	5/31/2005 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
2290	Work In Progress NEED NEW LOCKS AND KEYS FOR CABINET/CLOSET AND THE TEACHER'S DESK. MAIN BLDG. RM. #115.	5/25/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
2298	Work In Progress 5/25/05 .5-CHECK LIFT STATION .5-REPLACE MISSING INTERCOM BUTTONS TO CLASSROOMS. 2.0-FIX LIGHT FIXTURES TO CLASSROOM RESTROOMS. .5-REPLACE PENCIL SHARPENERS TO ROOMS. #102 AND 406. 1.5-TROUBLESHOOT AND FIX A/C TO ROOM #209. 3.0-CUT WEEDS. 5/25 - 8	5/25/2005 Medium	Johnny Acuna Johnny Acuna General Maintenance		Desert Trail Intermediate
2211	Work In Progress NEED A NEW REPLACEMENT HOLLOW DOOR FOR CLASSROOM # 411 GIRL'S RESTROOM. DOOR SIZE: 32 1/2" WIDE X 80" LONG. ALSO NEED (2) DOOR KNOBS. ONE (ROUND) FOR HALLWAY DOOR, AND ONE (LEVER) FOR BOY'S RESTROOM DOOR. THANK YOU !!!!!	5/23/2005 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
2212	Work In Progress (STUDENT RECORDS) NEED TO REPAIR BROKEN FILE CABINET LOCK, ALSO NEED A KEY TO BE ABLE TO LOCK CABINETS. BOTH STUDENT RECORD CABINETS ARE THE SAME KEY. (LOCATED INSIDE THE VAULT IN THE MAIN OFFICE)	5/23/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
2403	Work In Progress NEED A LOCK FOR SOUTHWEST GATE NEXT TO LISA ST.	6/1/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
2425	Work In Progress NEED TO REPLACE A LOST KEY FOR ROOM #201: MARIA RONGEL	6/1/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
2061	Work In Progress NEED TO REPLACE CONDENSATION PUMP TO THE REFRIGERATION UNIT LOCATED INSIDE THE SERVER ROOM.	5/18/2005 Medium	Johnny Acuna Jaime Gomez Heating/Ventilation /Air Conditioning		Desert Trail Intermediate
1192	Work In Progress RM. #112 GUTIERREZ . NEED TO FIX AND MAKE A KEY FOR FILING CABINET INSIDE CLASSROOM..THANK YOU.....	4/15/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
1211	Work In Progress need irrigation backflow preventer to be installed for irrigation to front trees. (irrigation line has been installed).	4/18/2005 Medium	Johnny Acuna Lorenzo Hernandez Grounds		Desert Trail Intermediate
1556	Work In Progress PORTABLE #411: NEED A NEW DOORKNOB (LEVER TYPE) FOR BOYS RR, AND ALSO NEED TO RE-WELD DOOR HINGE TO MAIN CLASSROOM DOOR. FALLEN DOOR HARD TO CLOSE.	5/2/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3739	Work In Progress DIAG/PSYCH ROOM NEED (2) CLASSROOM KEYS MADE. CORE IS: J-53	7/21/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
3619	Work In Progress MENS RESTROOM (NW HALL) : PLEASE CHANGE DOOR CYLINDER WHERE KEY ENTERS TO OPEN UP DOOR. STUDENTS STUFFED IN CYLINDER WITH CLAY AND HARDENED. THANK YOU !!!!!	7/18/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
3620	Work In Progress NEED NAME PLATES TO BE MADE: (1) PRINCIPAL, (1) ASSISTANT PRINCIPAL, (1) COMPUTER LAB	7/18/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
2585	Work In Progress (DANNY MIRANDA) NEED TO SEE IF FRAME AND DOOR COULD BE MOVED TO THE OTHER SIDE OF THE WALL TOWARDS HALLWAY AND CLOSE OFF WALL WHERE DOOR AND FRAME USED TO BE. *LOCATION: SPEECH ROOM*	6/7/2005 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
12070	Work In Progress please remove dirt pile (hill) next to the swing area. (playground).	5/10/2006 Medium	Johnny Acuna Guadalupe Ontiveros Grounds		Desert Trail Intermediate
12083	Work In Progress please relocate a/c selective switch in the teacher's lounge to be able to install a box around it to lock it. the reason is because teachers turn off air-conditioner in the lounge and shuts down a/c to a classroom, and the custodial / maintenance office. (The air- conditioner is used for all 3 rooms.)	5/10/2006 Medium	Johnny Acuna Enrique Sotelo Electrical		Desert Trail Intermediate
12017	Work In Progress need a 1" water backflow preventer for irrigation of trees for the front of the main bldg.	5/8/2006 Medium	Johnny Acuna Joe Ontiveros Plumbing		Desert Trail Intermediate
12208	Work In Progress need a lock with core #A-32. (Off Master)	5/15/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
12209	Work In Progress (Emergency) Need to remove a broken key inside doorhandle to room #412.	5/15/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
12418	Work In Progress need to replace mastercool 6500 to room #211. (Rusted out)	5/23/2006 Medium	Johnny Acuna Lorenzo Solis Heating/Ventilation /Air Conditioning		Desert Trail Intermediate
5462	Work In Progress need to demo and repour concrete to sectioned area by cafeteria.	9/13/2005 Medium	Michael Munoz Concrete		Desert Trail Intermediate Cafeteria

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11812	Work In Progress Monthly - PM Schedule created on 12/5/2005 - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Ricardo Jacquez Sewage/Water Treatment Plant	Desert Trail Intermediate	
10963	Work In Progress Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Desert View ES
1183	Work In Progress NEED TO REPLACE HOSE SPIGOTS IN PATIOS. LOOSING WATER PRESSURE AND HANDLES ARE BROKEN. NO HEAD CUSTODIAN AT SCHOOL SITE. IF YOU NEED ANY INFORMATION, CONTACT JIMMY CARBAJAL @ THE CUSTODIAL WAREHOUSE	4/15/2005 Medium	Aida Salcedo David Villalobos Plumbing		Desert View ES
6225	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005 Medium	Aida Salcedo Miguel Aguilar Custodial		Desert View ES
10491	Work In Progress #1. Fan above cooking stopped working, #2. On and Off button to mixer is broken and #3. Light Bulb area is still not fixed Martha Flores - DV Manager - 589-2425	3/14/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Desert View ES
10125	Work In Progress There is an electrical short near light bulb in Walk- In Refrigerator. Martha Flores - SNP Manager 589-2425	3/2/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Desert View ES
4149	Work In Progress key cylinder to walk-in refrigerator doesn't lock, key continuously goes round and round, please repair as soon as possible, groceries and commodities are stored in there.	8/3/2005 Medium	Alma Terrell Manny Lozoya Key and Lock	Cafeteria	Desert View ES
2546	Work In Progress Faucets in both patio areas need repair. Note: Work order is for Desert View Elementary, not RS.	6/6/2005 Medium	Miguel Aguilar David Villalobos Plumbing		Desert View ES
5145	Work In Progress Urgent: Need center pole repaired in exterior double door on east side of school repaired, pole fell and struck teacher. Door cannot be fully secured and will compromise security after school hours.	9/1/2005 Medium	Miguel Aguilar Manny Lozoya Key and Lock		Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
5146	Work In Progress Need copies (3) made of padlocks on hall doors, need for sub keys and replacement.	9/1/2005 Medium	Miguel Aguilar Manny Lozoya Key and Lock		Desert View ES
7232	Work In Progress Trees in front courtyard unhealthy/dying, signs of infestation, requesting solution/insecticide to remedy problem.	11/9/2005 Medium	Miguel Aguilar Guadalupe Ontiveros Grounds		Desert View ES
7613	Work In Progress Have a nonfunctioning electrical outlet in gymnasium.	11/29/2005 Medium	Miguel Aguilar Carlos Castillo Electrical		Desert View ES
7614	Work In Progress Have a nonfunctional electrical outlet in cafeteria.	11/29/2005 Medium	Miguel Aguilar Carlos Castillo Electrical		Desert View ES
4083	Work In Progress TEACHER DESK WITH LOCKING DRAWER, DOES NOT LOCK. ROOM#19, LOWER GRADE SIDE. MRS. GRISWOLD	8/2/2005 Medium	Margarita Terrazas Manny Lozoya Key and Lock		Desert View ES
8110	Work In Progress MANNY, PLEASE MAKE TWO NAME PLAQUES FOR MINERVA SINGH, RN AND YOLANDA F. GOMEZ, CNA. THANK YOU, THANK YOU!! margarita :)	12/14/2005 Medium	Margarita Terrazas Manny Lozoya Key and Lock		Desert View ES
12487	Work In Progress Vacuum not working properly, serial#F96A0001397.	5/25/2006 Medium	Miguel Aguilar Jimmy Carbajal Custodial Equipment Repair		Desert View ES
12488	Work In Progress Requesting 5 vacuum bands to replace on all machines.	5/25/2006 Medium	Miguel Aguilar Jimmy Carbajal Custodial Equipment Repair		Desert View ES
12490	Work In Progress pat aguilar lift front hall way 6 - 13"x15" glass window 1 - 5 1/2"x13 1/4" safty glass 1 - 13 1/2"x 64" glas door saft glass	5/25/2006 Medium	Miguel Aguilar Ruben Ronquillo Glass\Window Repairs		Desert View ES
10483	Work In Progress Please replace tracer summit board. Thank You!!	3/14/2006 Medium	Lorenzo Solis Lorenzo Solis Heating/Ventilation /Air Conditioning		Desert View ES
4781	Work In Progress pat aguilar rock wall (safety concern) 6 rock wall metal gates need to be replaced rusted throw	8/22/2005 Medium	Patricio Aguilar Michael Munoz Fence Repair		Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
1968	Work In Progress pat aguilar - asper principal to replace ac in port #2 room 3&4 with refrigerated air conditioning	5/16/2005 Medium	Patricio Aguilar Jose Ambriz Heating/Ventilation /Air Conditioning		Desert View ES
1969	Work In Progress pat aguilar move sand away from rock wall move sand back up hill	5/16/2005 Medium	Patricio Aguilar Lorenzo Hernandez Grounds		Desert View ES
2448	Work In Progress pat aguilar locksmith frount door to building need repair door closures need replacement door handdels need replacement	6/2/2005 Medium	Patricio Aguilar Manny Lozoya Key and Lock		Desert View ES
11245	Work In Progress W.O. : PRINCIPAL CARPET TO BE REPLACED IN CLASS ROOMS - 16 ROOMS R-21=25=18-14-23-27-29-31-34-36-39-30-41-32- 24-5 TO BE TILED PAT AGUILAR	4/10/2006 Medium	Patricio Aguilar Michael Munoz Carpet Repair		Desert View ES
11706	Work In Progress pat aguilar need light bulbs class rooms - fluorescent lamps order #26668 hall ways - light fixtures class rooms - ballasts light icn-4p32-sc	4/27/2006 Medium	Patricio Aguilar Carlos Castillo Electrical		Desert View ES
11038	Work In Progress please provide sand to daycare area where new playground equipment was installed .Might need the bobcat to lay sand.	4/3/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		GAC
9067	Work In Progress Swimming Pool Area - Remove dangling wooden boards.	1/26/2006 Medium	Michael Munoz Gerardo Marquez General Maintenance		GAC
1980	Work In Progress AS PER MANY LOZOYA WE NEED 4 KEY FOR RESETE FIRE ALARM.	5/17/2005 Medium	Manuel Prospero Manny Lozoya Key and Lock		GAC
2163	Work In Progress 5/20/05 WE NEED TO CHANGED LOCKS AT NEW HANDICAP RESTROOMS. TO PRIMUS LOCKS. THIS IN FOR MANNY LOZOYA	5/20/2005 Medium	Manuel Prospero Manny Lozoya Key and Lock		GAC
4377	Work In Progress NEED NEW R. R. PARTITIONS IN "A" WING AS PER MENNY PROSPERO	8/9/2005 Medium	Manuel Prospero Danny Miranda General Maintenance		GAC
9066	Work In Progress I AM REQUESTING A CHAIN AND LOCK TO TIE UP TWO PIC-NIC TABLES. THI W O AS PER MANNY LOZOYA.	1/26/2006 Medium	Manuel Prospero Manny Lozoya General Maintenance		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10560	Work In Progress 3/16/06. WE NEED TO REPLACE THE SHORT LIGHT POSTS.THEY ARE BROKEN AND NEED TO CHECK IF THERE IS POWER. THIS NEEDS TO BE DONE AS SOON AS POSSIBLE. MR. HAUGEN IS REQUESTING THIS WORK ORDER. AS PER MR. CARLOS CASTILLO.	3/16/2006 Medium	Manuel Prospero Carlos Castillo Electrical		GAC
11277	Work In Progress FOR LUPE ONTIVEROS. REPLACE THE SPRINKLERS THAT ARE IN THE MAIN ENTRANCE WHERE THE PINE TREES ARE, REASON IS THE WATER SPREADS ON THE ROAD. THE REPLACEMENTS ARE THE BUBBLES SPRINKLES THEY ARE WATER SAVERS.	4/11/2006 Medium	Manuel Prospero Guadalupe Ontiveros Grounds		GAC
11835	Work In Progress WE NEED TO INSTALL NEW EXOST TO BETROOM IN C WING..	5/1/2006 Medium	Manuel Prospero Jose Ambriz Heating/Ventilation /Air Conditioning		GAC
4655	Work In Progress AS PER ANN STEINHOFF-NEEDS 1 MORE GRAND MASTER KEY FOR HER SECRETARY AT PRE-K	8/17/2005 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC WHOLE BUILDING
5796	Work In Progress AS PER CORA-NEEDS THE DOOR LOCK TO THE DATA CENTER SWITCHED OUT FROM SWIPE CARD TO A COMBINATION LOCK. (MANNY, PLEASE SEE CORA BEFORE CHANGING OUT)	9/23/2005 Medium	Mary Garcia Manny Lozoya Key and Lock	Computer Lab	GAC DATA CENTER- TECHNOLOGY
3408	Work In Progress AS PER CARLOS VIGIL-NEEDS A GRAND MASTER 7, ASAP. (HIS BROKE IN HALF) ALREADY TALKED WITH MANNY LOZOYA	7/8/2005 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC ALL SCHOOLS
2909	Work In Progress AS PER TINA B-WING, OUTLET IN THE FILE ROOM DOES NOT WORK. (NEED TO PLUG A FAN IN ORDER TO WORK IN THAT ROOM TO HOT.) Need Electrician's assistance, checked for power, breaker and no power. routed to Cali 6/27/05.	6/21/2005 10/26/2005 Medium	Mary Garcia Carlos Castillo Electrical	Office	GAC FILE ROOM
2660	Work In Progress AS PER CARLOS VIGIL-NEEDS 6 PAD LOCKS FOR GHS MASTER. (FOR THIS TO OPEN WITH BEST LOCK MASTER KEY) APPROVED BY MR. CHAVEZ	6/9/2005 Medium	Mary Garcia Manny Lozoya Key and Lock	Classroom	GAC
2755	Work In Progress AS PER LAURA GARCIA-WOULD LIKE TO CLOSE OFF OFFICE DOOR TOTALLY & HAVE A DOOR MADE THROUTH ANNIE'S OFFICE, GOING INTO HER OFFICE. (PLEASE CHECK W/LAURA BEFORE DOING ANYTING.)	6/13/2005 Medium	Mary Garcia Danny Miranda Doors and Hardware	Office	GAC
144	Work In Progress IN A-WING SPECIAL ED, ACROSS COMPUTER LAB; ROOMS HAVE NO COOLING AND HEATING. NEED TO TALK W/SYLIVIA MORENO.	3/8/2005 Medium	Mary Garcia Jose Ambriz Heating/Ventilation /Air Conditioning	Office	GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
850	Work In Progress As per Manny Prospero: Needs weeds to be cut if can have ground come out to help.	4/5/2005 Medium	Mary Garcia Lorenzo Hernandez Grounds		GAC
2548	Work In Progress AS PER CORA W/TECHNOLOGY, SHE NEEDS A KEYS TO BE ISSUE TO LYNCO ELECTRIC AND SOUND & SINGNAL FOR GHS AND LU (FOR THE WHOLE SCHOOL)	6/6/2005 Medium	Mary Garcia Manny Lozoya Key and Lock	Classroom	GAC
12421	Work In Progress ASPER MS. CANTRELL-WINDOW AIR UNIT NEEDS TO BE CLEANED OUT & FILTER NEEDS TO BE CHANGED OUT. (CONSTANT COUGH WHEN AIR UNIT GOES ON)	5/23/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Office	GAC C-WING
12491	Work In Progress AS PER LUCY MESA-SINK FAUCET WON'T SHUT OFF. (RUNNING WATER) MANNY ALREADY AWARE OF THIS	5/25/2006 Medium	Mary Garcia Manuel Prospero General Maintenance	Restroom (Girls)	GAC C-WING
12521	Work In Progress AS PER ELISA SAENZ-AIR CONDITIONER IS NOT WORKING THROWING OUT HOT AIR.	5/25/2006 Medium	Mary Garcia Jose Ambriz Heating/Ventilation /Air Conditioning	Office	GAC A WING
12541	Work In Progress AS PER ALICE-NEEDS OUTSIDE PATIO SWEPT. THEY WILL BE DOING SOME PAINTING IN THE PATIO & HAS TO MUCH DIRT. ROBERTO IS ALREADY AWARE OF THIS	5/26/2006 Medium	Mary Garcia Ralph Lara Custodial	Cafeteria	GAC OUTSIDE PATIO
12542	Work In Progress AS PER IRMA GOMEZ-WOULD LIKE TO MOVE HER MODULAR DESK ABOUT 2.5 FEET BACK.(DIFFICULT FOR PEOPLE TO SIT W/O BANGING INTO WALL & KNEES) THIS WOULD ENTAIL REMOVAL OF THE CORNER SQUARE LAMINATE TOP. IF YOU COULD PLEASE NOTIFY HER WHEN SCHEDULED DATE TO PERFORM THE JOB, SO SHE CAN CLEAR THE SURFACE. (IF POSSIBLE IF IT COULD BE DONE AROUND JULY 5, 6 OR 7TH) PLEASE LET US KNOW AHEAD.	5/26/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Office	GAC B-WING
12543	Work In Progress AS PER JULIE HERNANDEZ-NEEDS 3 FILING CABINETS TO BE MOVED FROM HER OFFICE TO GHS MR. MARTINEZ OFFICE. (IF THEY CAN CALL HER BEFORE COMING TO MAKE ARRANGEMENT W/MR. MARTINEZ AS WELL)	5/26/2006 Medium	Mary Garcia Ralph Lara Custodial	Office	GAC A WING
12381	Work In Progress AS PER GINGER BERRY-NEEDS US & STATE FLAGS PUT UP IN CLASSROOMS.	5/22/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Classroom	GAC 101, 102, 103, 201, 202 & 203
12382	Work In Progress AS PER GINGER BERRY-NEEDS FOR 3 SMALL TALBLES AND CHAIR SET TO BE ASSEMBLED IN THESE CLASSROOMS.	5/22/2006 Medium	Mary Garcia Manuel Prospero General Maintenance	Classroom	GAC 102, 201 & 202

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12336	Work In Progress AS PER MARIBEL-NEEDS A TOTAL OF 3 OFFICES TO BE MOVED WITHIN. 1.) MARIBEL'S FURNITURE INTO GLORIA'S OFFICE. 2.) GLORIA'S FURNITURE INTO LAURA'S OFFICE. 3.) LAURA'S OFFICE INTO MARIBEL. (FURNITURE WILL BE LABELED AS TO WHERE IT WILL BE GOING INTO). IF CAN BE DONE NEXT WEEK DUE TO MARIBEL BEING OUT	5/19/2006 Medium	Mary Garcia Manuel Prospero General Maintenance	Office	GAC B WING
12337	Work In Progress AS PER MARIBEL-NEEDS OFFICES WAX AND DUSTED OFF BEFORE MOVING IN FURNITURE. IF CAN BE DONE NEXT WEEK-MONDAY DUE TO MARIBEL BEING OUT	5/19/2006 Medium	Mary Garcia Ralph Lara Custodial	Office	GAC B WING
12338	Work In Progress AS PER MARIBEL- IF CAN HAVE AIR UNITS CLEANED OUT BEFORE CUSTODIAL DOES THEIR WAXING, SO DUST WON'T STICK ON FLOORS. OFFICES FOR LAURA, MARIBEL & GLORIA'S OLD OFFICE.	5/19/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Office	GAC B WING
12087	Work In Progress AS PER MIKE SORIA NEEDS A LOCK DM7 FOR A STORAGE ROOM AT STM	5/10/2006 Medium	Mary Garcia Manny Lozoya Key and Lock		GAC STORAGE @STM
12088	Work In Progress AS PER MR. CHAVEZ-NEED TO HAVE KEYS FOR AUTO SHOP AND THE GATE GOING INTO PPD FOR NORMA ALVARADO. (PLEASE DELIVER TO MARY G @ GAC)	5/10/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC AUTO SHOP & PPD GATE
8924	Work In Progress AS PER ELISA SAENZ-NEEDS NAME PLATES DONE FOR OUR NEW BOARD MEMBERS, BEFORE NEXT WEDNESDAY. 1.) ANDREW MORALES 2.) MANUELA HUERTA	1/20/2006 Medium	Mary Garcia Manny Lozoya Key and Lock		GAC BOARD ROOM
8925	Work In Progress AS PER ELISA SAENZ-NEEDS NAME PLATES DONE FOR OUR STUDENT REPRESENTATIVES. FOR NAME PLATES TO ALSO SAY STUDENT REPRESENTATIVE BELOW THEIR NAME IF POSSIBLE. 1.) DELILAH APPELZOLLER 2.) JOSUE CASTREJON	1/20/2006 Medium	Mary Garcia Manny Lozoya Key and Lock		GAC STUDENT REPRESENTATIV E @ GAC
9073	Work In Progress AS PER MANNY-NEEDS TO RE-KEY ELODIA'S OFFICE, KEY DID NOT WORK.	1/26/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC C-WING
9215	Work In Progress AS PER MIKE SORIA NEEDS A KEY TO THE PATIO LOCK. (WAS CHANGED BY MANNY L. TO OPEN W/GRAND MASTER) MIKE HAS AN OLD KEY.	2/1/2006 Medium	Mary Garcia Manny Lozoya Key and Lock		GAC PATIO AREA

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9166	Work In Progress AS PER MS. BERRY-ROOM 101 IN THE PRE-K FRONT DOOR NEEDS TO BE TINTED. IT FACES THE WEST SIDE OF THE BUILDING AND IS VERY HOT IN THE AFTERNOON.	1/30/2006 Medium	Mary Garcia Ruben Ronquillo Glass\Window Repairs	Classroom	GAC
9275	Work In Progress AS PER MARY GARCIA-NEED SUPPLY CABINET LOCK TO BE REPLACED OR FIXED. DOES NOT LOCK. (MANNY P. HAS ALREADY TRIED TWICE AND LOCKS ONLY FOR 1 DAY AND BACK TO THE SAME THING.)	2/2/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC FILE ROOM
9496	Work In Progress AS PER MARGARET V W/SPED-NEED AN ELECTRICAL OUTLET UNDER A DESK TO BE REMOVED. (SAM GALLEGOS OFFICE) IF POSSIBLE ASAP.	2/8/2006 Medium	Mary Garcia Carlos Castillo Electrical	Mechanical Room	GAC A WINT
9880	Work In Progress AS PER JOSE AMBRIZ-NEEDS TO REPLACE THE WHOLE AIR CONDITING UNIT FOR A-WING. (WILL BE ORDERING PARTS TO HAVE READY)	2/21/2006 Medium	Mary Garcia Jose Ambriz Heating/Ventilation /Air Conditioning		GAC A WING
11041	Work In Progress AS PER MS. BERRY-IF IT WOULD BE POSSIBLE TO HAVE SOME KIND OF MESH OR FENCE PUT UP ALL AROUND THE PLAYGROUND AREA DUE TO SNAKES. THE PRE-K STUDENTS ARE ALWAYS AROUND THAT AREA PLAYING. (A SNAKES WAS FOUND NEAR THE FINANCE BACK DOOR.)	4/3/2006 Medium	Mary Garcia Michael Munoz General Maintenance		GAC PLAY GROUND
11382	Work In Progress AS PER GUSTAVO-BATHROOM IN ROOM #103 MAKES ALOT OF NOISE WHEN FLUSHING. (LIKE IF IT IS GOING TO BRAKE DOWN.)	4/18/2006 Medium	Mary Garcia David Villalobos Plumbing	Restroom (Girls)	GAC ROOM 103
11266	Work In Progress AS PER SELMA-NEED TO EXTERMINATE FOR ANTS AND SWSEEP DIRT FROM WALKWAYS.	4/11/2006 Medium	Mary Garcia Margret Villalobos Pest Control	Office	GAC
12193	Work In Progress AS PER MS. WATSON-NEEDS A KEY TO DAVID QUINTANA'S OFFICE. SHE WILL ALSO BE SHARING THIS OFFICE. KEY #A23	5/15/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC C-WING
11557	Work In Progress RTC - Please exterminate for ants all portables asap a big issue.	4/24/2006 Medium	Margret Villalobos Margret Villalobos Pest Control	Portables	GAC
12030	Work In Progress please cut and redo gates at the daycare.	5/9/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		GAC
12031	Work In Progress please install misters for the students in play area.	5/9/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11595	Work In Progress Repair restroom by swimming pool.	4/25/2006 Medium	Michael Munoz David Villalobos Plumbing		GAC
11596	Work In Progress Need to install dispenser in restroom by swimming pool.	4/25/2006 Medium	Michael Munoz Ralph Lara Custodial		GAC
5824	Work In Progress NEED A WATERHOSE AND ALSO A HOSE ROLL A WAY.2 WATERHOSE ONE FOR THE PATIO AND ONE FOR THE PRE KINDER AREA I ONLY HAVE ONE AND I USE IT FOR THE FRONT AREA,THE HOSE ROLL A WAYS I NEED ONE FOR EACH HOSE THANK YOU FOR YOUR CONTINUED SUPPORT YOU ARE THE BEST!!!!	9/26/2005 Medium	Jimmy Carbajal Sal Acuna Custodial Equipment Repair	Custodial	GAC
11556	Work In Progress Need to have electrical power strips installed in 3 classrooms in order to plug several computers.	4/24/2006 Medium	Julie Hinojosa Carlos Castillo Electrical	Portables	GAC
1674	Work In Progress NEED 2FT.BY2FT. CONCRETE BASE TO INTALL LIGHT FIXTURES ON BOTH SIDES OF ENTRANCE SIGN TO THE GAC.	5/5/2005 Medium	Carlos Castillo Michael Munoz Concrete		GAC
9281	Work In Progress NEED TO RE-KEY CUSTODIAL CLOSET IN "ON- TRACK" PRE-K BUILDING TO GAC BLDG MASTER.	2/2/2006 Medium	Aida Salcedo Manny Lozoya Key and Lock		GAC
11444	Work In Progress Trim trees next to Pine Trees at entrance to the GAC.	4/20/2006 Medium	Aida Salcedo Guadalupe Ontiveros Grounds		GAC
12328	Work In Progress DELIVER 180 CHAIRS AND 30 TABLES TO GAC ON 6/6/06. PICK UP ON 6/8/06.	5/19/2006 Medium	Aida Salcedo Jimmy Carbajal Custodial		GAC
12243	Work In Progress REPLACE BROKEN RPA 2" SPRINKLERS NEED TO BE PLACED 4" POP-UPS.	5/16/2006 Medium	Guadalupe Ontiveros Bobby Aldaz Grounds		GAC
10964	Work In Progress Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		GAC
10956	Work In Progress Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		GAC
3094	Work In Progress Install fencing on north property line for site security.	6/30/2005 6/30/2005 Medium	Alfredo Holguin Michael Munoz Fence Repair		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3546	Work In Progress Technology Server Room-Install Battery powered Emergency lighting in this room	7/14/2005 Medium	Carlos Castillo Electrical		GAC
9145	Work In Progress please install water line for misters on the east side of the pre-k. Plans are in your mail box.	1/30/2006 Medium	Guadalupe Ontiveros Grounds		GAC
9981	Work In Progress RTC Office - Transfer furniture to Portable 3 take computer from Margaret's Office to RTC Office.	2/24/2006 Medium	Selma Nevarez Ralph Lara Custodial		GAC
9546	Work In Progress please repair clean out that east of concession stand.	2/10/2006 Medium	David Villalobos Plumbing	Football Field	Gadsden HS
2315	Work In Progress Please paint inside and out of both guard shacks and repair what is damaged before school starts this year.	5/26/2005 Medium	Mario Apodaca Painting		Gadsden HS
5458	Work In Progress need to restripe all parking lines ,handi-cap- arrowa etc.	9/13/2005 Medium	Michael Munoz Painting	Parking Lot	Gadsden HS
4916	Work In Progress please check and repair leak & secure drop ceiling in rm 142. possible safety hazard.	8/25/2005 Medium	Danny Miranda General Maintenance		Gadsden HS
4448	Work In Progress Telescope observatory locate on the west side of the baseball field - Installl fencing around it to prevent vandalism	8/10/2005 Medium	Michael Munoz Fence Repair		Gadsden HS
5464	Work In Progress Need to paint stripings for student parking lot and east of Auto Shop.	9/13/2005 Medium	Michael Munoz General Maintenance	Parking Lot	Gadsden HS
7499	Work In Progress please re-route conduit and repair where kids get on roof by panther hut. north bldg.	11/21/2005 Medium	Enrique Sotelo Electrical	Classroom	Gadsden HS
7500	Work In Progress please replace disconnect to heating unit on the - S- wing north bldg. blades do not work properly.	11/21/2005 Medium	Jose Ambriz Heating/Ventilation /Air Conditioning	Classroom	Gadsden HS
10194	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Joe Ontiveros Fire Extinguishers		Gadsden HS
11784	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Mario Apodaca General Maintenance		Gadsden HS
11781	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10235	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
10238	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Mario Apodaca General Maintenance		Gadsden HS
8379	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
8382	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Mario Apodaca General Maintenance		Gadsden HS
9372	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
9375	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Mario Apodaca General Maintenance		Gadsden HS
3141	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ontiveros Fire Extinguishers		Gadsden HS
3319	Work In Progress Yearly - Gadsden HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ontiveros Fire Protection		Gadsden HS
10997	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
11000	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Mario Apodaca General Maintenance		Gadsden HS
10965	Work In Progress Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Gadsden HS
7095	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
7791	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
12269	Work In Progress Swimming Pool - Carlos Lowenberg needs three sets of keys for the lifeguards by May 24, 2006	5/17/2006 Medium	Alfredo Holguin Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
7638	Work In Progress Girls BB Lockerroom - Connect Electric Water Heater.	11/29/2005 Medium	David Villalobos Michael Mc Dermott Electrical		Gadsden HS
10789	Work In Progress Grounds Shop - Need an electrical outlet installed outside of shop.	3/29/2006 Medium	Guadalupe Ontiveros Michael Mc Dermott Electrical		Gadsden HS
11248	Work In Progress please sweep the basketball courts by the weight room on 4-21-06 for special olympics	4/10/2006 Medium	Guadalupe Ontiveros Guadalupe Ontiveros Grounds		Gadsden HS
3479	Work In Progress All Campus - Need to replace old door knobs w/new levers.	7/12/2005 Medium	Hector Lozoya Manny Lozoya Key and Lock		Gadsden HS
4305	Work In Progress NORTH bus entrance gate keep falling, bottom rail all bend;Also needs new roller bearings for both gates thank you !!! [safety hazard]	8/8/2005 Medium	Fernando Moncayo Michael Munoz Fence Repair		Gadsden HS
4311	Work In Progress PANTHER HUT porch entrance too dark security lighth dosen't work	8/8/2005 Medium	Fernando Moncayo Fernando Moncayo Electrical		Gadsden HS
4240	Work In Progress Need six wheels for large gates in NORTH parking lot THANK YOU!! 8/11 - Route to Ruben as per Mike	8/5/2005 Medium	Fernando Moncayo Ruben Ronquillo General Maintenance		Gadsden HS
4902	Work In Progress AG BLDG entry door,won't open or lock key just turns;Also WOOD SHOP entry door new lock doesn't work	8/25/2005 Medium	Fernando Moncayo Manny Lozoya Key and Lock		Gadsden HS
7301	Work In Progress BOY'S GYM SOUTH EAST exterior door need to be replace	11/11/2005 Medium	Fernando Moncayo Danny Miranda Doors and Hardware	Gym	Gadsden HS
6607	Work In Progress LIBRARY EAST wall;There is a wall keyed hose bib that is leaking	10/20/2005 Medium	Fernando Moncayo David Villalobos Plumbing		Gadsden HS
6609	Work In Progress Need to install flouresent lighth lamps in ANNEX CORRIDOR, is too dark	10/20/2005 Medium	Fernando Moncayo Michael Mc Dermott Electrical		Gadsden HS
1973	Work In Progress Need to rerun conduit and wires to kitchen exhaust in PANTHER HUT HOMEC ROOM	5/16/2005 Medium	Fernando Moncayo Michael Mc Dermott Electrical		Gadsden HS
2459	Work In Progress Attn. MANNY LOCKSMITH; Need to ck. storage cabinet in room 226 not locking	6/2/2005 Medium	Fernando Moncayo Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3593	Work In Progress Need to repair or replace electrical conduit outside of CONCESSION STAND by GIRL'S GYM Parent called regarding the outlets to the concession stand need status. Work Order has been placed along time ago needs to be repaired before next Saturday.	7/15/2005 Medium	Fernando Moncayo Michael Mc Dermott Electrical		Gadsden HS
2630	Work In Progress 06/08/05 Atrn;MANNY LATOYA , need to change the lock cilinders to restrict the access to the VARSITY GYM due to been paint thank you!	6/8/2005 Medium	Fernando Moncayo Manny Lozoya Key and Lock		Gadsden HS
10081	Work In Progress PRESCHOOL sink is clogged up, run small cable through,but no luck.please assist THANK YOU!!	2/28/2006 Medium	Fernando Moncayo David Villalobos Plumbing		Gadsden HS
10114	Work In Progress ATTN. DAVID VILLALOBOS;Need to replace two toilets and flanges in LIBRARY GIRL'S R. R.Also one toilet in MAIN GIRL'S R.R THANK YOU!!	3/1/2006 Medium	Fernando Moncayo David Villalobos Plumbing		Gadsden HS
10428	Work In Progress AG Shop - Walk In Cooler needs refrigerant (freeon) as per Fernando needs it by next week.	3/10/2006 Medium	Fernando Moncayo Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
9959	Work In Progress ATTN.MR.LAZOYA;Key stuck and almost broken in NORTH side door at WEIGHTROOM.Need you a.s.a.p THANK YOU!!!	2/23/2006 Medium	Fernando Moncayo Manny Lozoya Key and Lock		Gadsden HS
8932	Work In Progress MR.CASTILLO;When you have a chance please drop by ghs with two plug-in photocell 120v THANK YOU!!	1/20/2006 Medium	Fernando Moncayo Carlos Castillo Electrical		Gadsden HS
9147	Work In Progress Need a new metal door for BOY'S restroom in OLD ENGLISH 1st. floor. ASAP please,can't lock restroom to control vandalism THANK YOU!!	1/30/2006 Medium	Fernando Moncayo Danny Miranda Doors and Hardware	Restroom (Boys)	Gadsden HS
11439	Work In Progress Attn.MR.MIRA&ANDA,sliding door in room 106 storage won't open,please help THANK YOU!!! Route to D. Miranda as per Mike 4/26/06 - mkv	4/20/2006 Medium	Fernando Moncayo Danny Miranda Doors and Hardware		Gadsden HS
11523	Work In Progress Please check and replace all a/c contactors in ACADEMIC bldg;Some are burn and not making good contact	4/21/2006 Medium	Fernando Moncayo Michael Mc Dermott Electrical		Gadsden HS
11694	Work In Progress Need to connect [electrical] on new a/c at PRESS BOX THANKS!!!	4/27/2006 Medium	Fernando Moncayo Michael Mc Dermott Electrical		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11975	Work In Progress Need to fumigate all WOODSHOP bldg,classrooms and storages,it's infested with roaches.THANK YOU!!	5/5/2006 Medium	Fernando Moncayo Margret Villalobos Pest Control		Gadsden HS
11942	Work In Progress Please fumigate and set up mice traps in NORTH BLDG rooms 224,226 and 238 THANK YOU!!	5/4/2006 Medium	Fernando Moncayo Margret Villalobos Pest Control		Gadsden HS
11943	Work In Progress Attn. HVAC TECH. On SUMMER break the large a/c on VARSITY GYM WEST wall, need to be removed; Don't need it,is falling apart ,danger THANK YOU!!	5/4/2006 Medium	Fernando Moncayo Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
11901	Work In Progress Room 132 in OLD ENGLISH is falling hinges won't hold ,need to be repaired asap THANK YOU!!	5/3/2006 Medium	Fernando Moncayo Manny Lozoya Key and Lock		Gadsden HS
11902	Work In Progress GIRL'S GYM ,inside doors panic bar vandalized pulled from door need to be repaired asap THANK YOU!!	5/3/2006 Medium	Fernando Moncayo Manny Lozoya Key and Lock		Gadsden HS
12392	Work In Progress AUTOSHOP, rollup door ,need a pad lock to secure it over SUMMER break. THANK YOU!!	5/22/2006 Medium	Fernando Moncayo Manny Lozoya Key and Lock		Gadsden HS
6001	Work In Progress Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ontiveros Fire Extinguishers		Gadsden HS
12075	Work In Progress BLEACHERS NEED TO BE CLEANED DURING GYM FINISHING. PLEASE NOTIFY AIDA KNOW WHEN THIS TASK IS COMPLETED SO INSPECTION CAN BE DONE.	5/10/2006 Medium	Aida Salcedo Jesus Estrada Custodial		Gadsden HS
12475	Work In Progress We need underground utility locates where the new portable will be placed by Tuesday May 30. (Portable Pier Locations)	5/24/2006 Medium	Alfredo Holguin Carlos Castillo Electrical	Portables	Gadsden HS
12478	Work In Progress We need underground utility locates where the new portable will be placed by Tuesday May 30. (Portable Pier Locations)	5/24/2006 Medium	Alfredo Holguin David Villalobos Plumbing	Portables	Gadsden HS
12229	Work In Progress need to replace covers on fixtuers	5/16/2006 Medium	Carlos Castillo Carlos Castillo Electrical	Athletic Field	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10372	Work In Progress On March 20, 21, and 22, the State Fire Marshal will be conducting a complete and thorough inspection of the new system; this entails checking every device in the system in all rooms and storage spaces. If you could please either have a complete set of keys for all rooms, storage and padlocks, or give me your permission to open any locks necessary to conduct this test it would be very much appreciated. I could pick them up this Friday. We will of course secure all sites as they are checked. 1. North Building: Office of vice prin., panther hut. 2. Academic Bldg: Office of vice prin, his storage. Choir storage. Dark room in yearbook class. Custodial closets. 3. Main bldg: Office area, Vault will need to be open! Can we have a person with combination in the area that day? Custodial closet, Old nurses office, Lab storage areas. 4. Old English: basement and other storage rooms were off master, 5. Nurses offices 6. Cafeteria: all storage areas in kitchen 7. Gyms: All coaches offices and storage areas 8. NROTC armory area.	3/8/2006 Medium	Carlos Vigil Manny Lozoya Key and Lock		Gadsden HS
8254	Work In Progress Need to replace return unit's disconnect	12/22/2005 Medium	Carlos Castillo Carlos Castillo Electrical	Cafeteria	Gadsden HS
8145	Work In Progress Several light pole around cafeteria area are out. Already change lamps but still not working, need to change ballasts. As per Mike Munoz route to Mike Mc Dermott. 12/18/05-Cali ordered material (10) 100w MH Ballast and (10) 100 WMH Lamps.	12/15/2005 Medium	Carlos Castillo Michael Mc Dermott Electrical		Gadsden HS
9432	Work In Progress need to replace key switches with regular two pole switches.	2/6/2006 Medium	Carlos Castillo Carlos Castillo Electrical	Classroom	Gadsden HS
2762	Work In Progress need to varnish 15 new doors	6/14/2005 Medium	Danny Miranda Joe Ontiveros Painting		Gadsden HS
11142	Work In Progress need to paint new double doors main building	4/6/2006 Medium	Danny Miranda Fernando Moncayo Painting		Gadsden HS
11143	Work In Progress need to paint new door at old english boys r.r.	4/6/2006 Medium	Danny Miranda Mario Apodaca Painting		Gadsden HS
4726	Work In Progress Royal vacuum is missing bag and brush, belt serial No.H93266101B GISD tag 014131	8/19/2005 Medium	Jesus Estrada Jimmy Carbajal Custodial Equipment Repair		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12463	Work In Progress We need the varsity gym entrances re-keyed ASAP. We will start to clean the floor by 5/26/06	5/24/2006 Medium	Jesus Estrada Manny Lozoya Key and Lock		Gadsden HS
11674	Work In Progress GHS Old English – Change program back to how it was w/Outside Temp. Also need training on assigning Nueron Id's. Open Purchase Order 56001131 Refaxed on 5/11/06 - mkv	4/27/2006 Medium	Jose Ambriz Margret Villalobos Energy Management System		Gadsden HS
12240	Work In Progress PANTHER HUT - REMODEL OVER THE SUMMER BREAK.	5/16/2006 Medium	Michael Munoz Danny Miranda General Maintenance		Gadsden HS
12026	Work In Progress install fur ducting to electrical behind panther hut.	5/9/2006 Medium	Michael Munoz Jose Ambriz Heating/Ventilation /Air Conditioning	Classroom	Gadsden HS
12177	Work In Progress Business Bldg - Need to repair hose bib.	5/12/2006 Medium	Michael Munoz Mario Apodaca General Maintenance		Gadsden HS
12104	Work In Progress electrical plug to water fountain in the wood shop is in the wall. Need to put flush to wall.	5/10/2006 Medium	Michael Munoz Michael Mc Dermott Electrical		Gadsden HS
12089	Work In Progress Install picnic tables South of Nursing Area by pine trees.	5/10/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		Gadsden HS
12423	Work In Progress 5-23-6 ELECTRICAL REMODEL OF KITCHEN AREA OF PANTHER HUT.	5/23/2006 Medium	Michael Mc Dermott Michael Mc Dermott Electrical	Classroom	Gadsden HS PANTHER HUT
8844	Work In Progress AS PER MR. CHAVEZ OVER AT THE GHS ACADEMIC BUILDING BOYS RESTROOM ON THE WEST SIDE NEEDS A PARTION BETWEEN HANDICAP & REGULAR TOILET.	1/18/2006 Medium	Mary Garcia Danny Miranda Doors and Hardware	Restroom (Boys)	Gadsden HS GHS ACADEMIC BLDG
1393	Work In Progress BASEBALL & SOFTBALL DUGOUT AREA - NEED (3) HOLLOW METAL DOORS WITH HOLLOW METAL FRAMES (3'0" X 6'8") FOR STORAGE ROOMS.	4/25/2005 Medium	Lorenzo Hernandez Danny Miranda Doors and Hardware	Athletic Field	Gadsden HS
1394	Work In Progress GROUNDS SHOP - NEED TO RESTOCK FIRST AID KIT.	4/25/2005 Medium	Lorenzo Hernandez Ruben Ronquillo General Maintenance		Gadsden HS
11730	Work In Progress WINDOWS AT ROOM 147 NEED TOBE REPAIRS IT IS A DOUBLE PANE GLASS UNIT ARE 3# UNIT NEED FIX AT OLD ENG BLDG VANDALISM	4/28/2006 Medium	Mario Apodaca Ruben Ronquillo Glass/Window Repairs	Classroom	Gadsden HS
11664	Work In Progress NEED A NEW MOTER STARTER CONTROL FOR A E/COOER	4/26/2006 Medium	Mario Apodaca Jose Ambriz Heating/Ventilation /Air Conditioning	Gym	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11551	Work In Progress BROKEN GLASS WINDOW AT V-GYM BOY LOCKEROOM 239 20X40 VANDALISM	4/24/2006 Medium	Mario Apodaca Ruben Ronquillo Glass\Window Repairs		Gadsden HS
11484	Work In Progress NEED A 12 INCH MASTE COOL MEDIA FOR 6500 COOLER AT KITCHEN	4/21/2006 Medium	Mario Apodaca Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
11257	Work In Progress NEED NEW LAMPS COVER FOR NORTH BLDG	4/10/2006 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
10766	Work In Progress NEED TO PUT NEW FLOOR TILE AT V-GYM GIRLS LOCK ROOM	3/28/2006 Medium	Mario Apodaca Michael Munoz Carpet Repair	Restroom (Girls)	Gadsden HS
10580	Work In Progress BROKEN WINDOW GLASS AT ANNEX BLDG DOOR 30X30 VANDALISM	3/16/2006 Medium	Mario Apodaca Ruben Ronquillo Glass\Window Repairs		Gadsden HS
10138	Work In Progress NEED TO PUT A NEW TOILE FLANGE AT N-BLDG GIRLS RESTROOM	3/2/2006 Medium	Mario Apodaca David Villalobos Plumbing		Gadsden HS
10007	Work In Progress ROOF LEAK AT NEW RESTROOM BOY SIDE AT FOOTBALL FIELD	2/24/2006 Medium	Mario Apodaca David Boyd Construction	Football Field	Gadsden HS Roof
9696	Work In Progress NEED #5 FIRE EXTINGUISHER CABINETS FOR THE N/BLDG 10 LB DRY CHEMICAL SURFACEMOUNT	2/14/2006 Medium	Mario Apodaca Danny Orozco Fire Extinguishers		Gadsden HS
9266	Work In Progress NEED TOW LACK FOR CONCESSION STAND AT FOOTBALL FIELD	2/2/2006 Medium	Mario Apodaca Manny Lozoya Key and Lock		Gadsden HS
7886	Work In Progress NEED TO REPAIR ALL DOOR FRAMS AT THE WEIGHT ROOM THE KID WILL PULL THE DOOR OPEN W/THE DOOR ARE LOCK	12/6/2005 Medium	Mario Apodaca Danny Miranda Doors and Hardware		Gadsden HS
7956	Work In Progress Vandalism - Damage to south front entrance roll gate hit by vehicle. (Case# 2005-10383) Deputy Isidro Gonzalez #935	12/2/2005 Medium	Mario Apodaca Michael Munoz Fence Repair		Gadsden HS
8714	Work In Progress NEED A NEW E/COOLER AT FOOTBALL FIELD PRESS BOX REPLACE UNIT FOR A M/C 6500 UPFLOW WITH DUCTWORK, SIZE WAS INSTALLED BECAUSE INSTALLED A DUCT WORK 20X20X90. 1HP MOTOR INSTEAD OF 1/3 HP MOTOR.	1/12/2006 Medium	Mario Apodaca Jose Ambriz Heating/Ventilation /Air Conditioning	Football Field	Gadsden HS New Equip. Installation

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
133	Work In Progress NEED NEW STAIR VINYL STRIP FOR MAIN GOING UP TO OLD/ENG	3/7/2005 Medium	Mario Apodaca Michael Munoz General Maintenance	Stairway	Gadsden HS
264	Work In Progress NEED A METAL DOOR FOR BOY RESTROOM AT N-BLDG - ONE DOOR	3/10/2005 Medium	Mario Apodaca Danny Miranda Doors and Hardware	Restroom (Boys)	Gadsden HS
3524	Work In Progress NEED TO FIX FOOTBALL FIELD SCOREBOARD BREAKER BOX	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
3525	Work In Progress NEED TO CK ALL FOOTBALL FIELD LAMPS	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
5842	Work In Progress NEED A NEW GLASS PUT ON CONCESSION STAND WINDOW AT FOOTBALL FIELD (VANDALISM) 23X23 ASAP	9/26/2005 Medium	Mario Apodaca Ruben Ronquillo Glass\Window Repairs		Gadsden HS
6425	Work In Progress NEED TO REMOVE ALL OUTLET AT ROOM 126 AT ARE ON BOOK SHEVING FLOOR AND RELOCA OUTLETS	10/14/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical	Custodial	Gadsden HS
6526	Work In Progress NEED TOO RUN SEWER SNAKE AT WOOD SHOP BLDG unclog main sewer line to woodshop	10/18/2005 10/19/2005 Medium	Mario Apodaca David Villalobos Plumbing		Gadsden HS
5108	Work In Progress NEED TO PUT NEW BALLAST AT WOOD SHOP LAMPES	8/31/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
4970	Work In Progress GLASS AT MAIN BLDG HALLWAY 40X18 NEED TOBE REPLACES VANDALISM	8/26/2005 Medium	Mario Apodaca Ruben Ronquillo Glass\Window Repairs		Gadsden HS
4976	Work In Progress NEED ALL WINDOW BLINDSON OLD ENGLISH BLDG 40 EA 40WX90L	8/26/2005 Medium	Mario Apodaca Ruben Ronquillo Glass\Window Repairs		Gadsden HS
4502	Work In Progress NEED TO LAMPES AT WOOD SHOP SAME ARE BURNED OUT	8/11/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
12048	Work In Progress BOY RESTROOM FLUSH VAIVES NEED TOBE REPAIR IN MAIN AND ACADEMIC BLDG	5/9/2006 Medium	Mario Apodaca David Villalobos Plumbing		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12051	Work In Progress BOY RESTROOM WINDOW GLASS BROKEN AT BMAIN BLDG 19X36 VANDALISM	5/9/2006 Medium	Mario Apodaca Ruben Ronquillo Glass\Window Repairs	Restroom (Boys)	Gadsden HS
12052	Work In Progress WATER COOLER AT WOOD SHOP BLDE NOT WORKING SAMCON PUT IN	5/9/2006 Medium	Mario Apodaca Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
12218	Work In Progress NEED NEW LAMP COVER FOR CONCESSION STAND AT FOOTBALL FIELD	5/15/2006 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
12277	Work In Progress NEED TO CK ALL LOCK ON BLDG ALL DOORS LOCK ARE GLUE NEED TO WASH OUT OR PUT NEW LOCK DO TO VANDALISM	5/17/2006 Medium	Mario Apodaca Manny Lozoya Key and Lock		Gadsden HS
12389	Work In Progress FOOTBALL FIELD MENS RESTROOM A SINK FAUCET IS LEAKING NEED A NEW ONE	5/22/2006 Medium	Mario Apodaca David Villalobos Plumbing		Gadsden HS
12431	Work In Progress FLUORESCENT SIGN IS OUT AT CATE	5/23/2006 Medium	Mario Apodaca Danny Orozco Food Services	Cafeteria	Gadsden HS
10291	Work In Progress please repair the concession stand and order material for windows and door.(girls softball feild) Thanks	3/6/2006 Medium	Michael Munoz Gerardo Marquez General Maintenance	Athletic Field	Gadsden HS
11879	Work In Progress North Bldg - Cover pond at G-Wing remove concrete and fill (with mesquite dirt will work).	5/2/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		Gadsden HS
12410	Work In Progress Need to have chain-link fence posts re-welded at pool eastside perimeter fence. I had talked to Ruben Ronquillo about this job.	5/22/2006 Medium	Raul Sanchez Ruben Ronquillo General Maintenance		Gadsden HS
2385	Work In Progress SWIMMING POOL (PUMP ROOM) - AS PER NM ENVIRONMENT DEPT. POOL REGULATIONS, PUBLIC POOLS AND GENERAL USE POOLS WILL HAVE AN EMERGENCY SHUT OF SWITCH INSTALLED TO TURN OFF RECIRCULATING PUMP IN CASE OF AN EMERGENCY.	5/31/2005 Medium	Raul Sanchez Michael Mc Dermott Electrical		Gadsden HS
1499	Work In Progress Irrigation Wells - Need Grounds to pick up old well column piping and dispose of it properly.	4/28/2005 Medium	Raul Sanchez Lorenzo Hernandez Grounds		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8946	Work In Progress Requested by Ms. Lopez Rm. 605 Business Building-Replacement of school lock on the second floor of the Business Building elevator, due to it not being able to find an original key to open the Master Pad. Lock currently on the door. Please contact Ms. Lopez for information regarding the type of lock to be placed on the door.	1/23/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
9230	Work In Progress Requested by Velia Rm. 112 Front Office-Ms. Hamilton's classroom door does not want to lock, she's in room # 562.	2/1/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
9232	Work In Progress Requested by Jenny Gonzalez Rm. 250 Computer Lab-Light bulb needs to be replaced in the Boys Restroom.	2/1/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
9093	Work In Progress Requested by Velia Rm. 112 Front Office-Two keys of HE203 are needed for Key Box; for Concession Stand at Football Field.	1/27/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
9094	Work In Progress Requested by Velia Rm. 112 Front Office-Key broke inside cylinder, we need lock fixed and also, please complete Work Order # 4362. Five keys are needed of HE1 (Gym Key), three keys are now broken and need replacing.	1/27/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
9098	Work In Progress Requested by Mr. Contaldo Observatory-Close and lubricate observatory dome as soon as possible.	1/27/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
9099	Work In Progress Requested by Mr. Contaldo Observatory-Replace power cord going to white light bulbs on top, inside of dome.	1/27/2006 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
9100	Work In Progress Requested by Mr. Contaldo Observatory-Replace acciator switches.	1/27/2006 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
9101	Work In Progress Requested by Ms. Jacquez Rm. 752 Barracks-Mount flags on wall.	1/27/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
8178	Work In Progress Requested by Mr. Contaldo Campus Observatory-Fix or replace limiting switches on Observatory hatch. Existing switches may (?) be fixed by bending metal contact plates to correct position. Key problem: need to be able to open and close hatch. Replace or fix white light bulbs inside Observatory.	12/16/2005 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8179	Work In Progress Requested by Mr. Contaldo Campus Observatory- Install 6' chain link fence around Observatory Deck with locking gate. Key problem: prevent future vandalism. 1/11 - Route to Lupe as per Mike.	12/16/2005 Medium	Velia Alarcon Guadalupe Ontiveros Grounds		Gadsden HS
8182	Work In Progress Requested by L. Melendrez Rm. 333 Academic Building-Classroom walls need to be repaired. There are holes in the walls and it needs to be repainted.	12/16/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
8185	Work In Progress Requested by Ms. Trich Library-The drawer slides for the cashbox are loose. They may be missing screws to attach them to the base. Might someone please assess the situation to determine if the present one can be repaired or if they need replacement? Please check with Leslie, this is a safety issue; the drawer may fall out of the base.	12/16/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
8687	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-Ovens not working at all. First and third ovens on the right side of kitchen, possibly a problem with the outlets.	1/12/2006 Medium	Velia Alarcon Danny Orozco Food Services		Gadsden HS
8688	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-Dishwasher not pulling cleaner or rinse products, only pulls sanitizer.	1/12/2006 Medium	Velia Alarcon Danny Orozco Food Services		Gadsden HS
8689	Work In Progress Requested by Ms. Anderson Rm. 233 Panter Hut- Mice in Panther Hut.	1/12/2006 Medium	Velia Alarcon Margret Villalobos Pest Control		Gadsden HS
8691	Work In Progress Requested by Chief Arms Rifle Range/Adjacent to Boys Gym-Rifle Range is coming loose in numerous panels and range is no longer secure. Recommend a permanent wall or welded metal plating. Kids are using basketballs to break the screens; also maintenance caught three kids in the rifle range before break. Note from Mr. Foster: THIS IS IMPORTANT! Route to Bldg Mechanic as per Mike - 2/8/06 -mkv	1/12/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
8696	Work In Progress Requested by Mrs. Quinones Rm. 653 Busines Building-Replace florescent light bulbs. ROUTE TO BM AS PER M. MC DERMOTT	1/12/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
8068	Work In Progress Requested by Mr. Chambers North Building Project-Temporarily remove cable from North Building Lockers by Saturday, Dec. 17. (For Columbia University Film Documentary)	12/13/2005 Medium	Velia Alarcon Michael Munoz General Maintenance		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
7913	Work In Progress Requested by Cathy Cano Concession Stand- Windows to concession stand need to be put back on. Reasons: cold, and too many flies and/or bees. Route to Bldg Mechanic as per Mike Munoz 12/16/05 - mkv	12/7/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
7914	Work In Progress Requested by Ms. Hunt Rm. 105 Main Building- Cupboard door broke off, screws on my desk.	12/7/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
7915	Work In Progress Requested by Mr. Contaldo Campus Observatory- Close hatch door on observatory, check out electrical connection for motor drive and white overhead lights. route to Mike Mc Dermott - As per Mike Munoz 12/12/05 - mkv	12/7/2005 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
8081	Work In Progress Requested by Ms. Trich Rm. 275 Library-Tops of the short book shelves are losing the laminate, which is peeling off. Please re-attach the laminate tops. Please check with either Bonnie or me.	12/13/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
9972	Work In Progress Requested by Mr. D. Martinez North Building Main Hallway-Some tiles in the main hallway are damaged and are a hazard for parents, students, and teachers.	2/24/2006 Medium	Velia Alarcon Michael Munoz Carpet Repair		Gadsden HS
9909	Work In Progress Requested by Dolores Nanez Library-Anchor wall (partition) has glass window and shelves, made of wood.	2/22/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
9823	Work In Progress Requested by Mr. Chambers All G.H.S. Buildings- Paint all G.H.S. Buildings with maroon trim (outside)-doors, windows, and flashing etc.	2/17/2006 Medium	Velia Alarcon Mario Apodaca Painting		Gadsden HS
9824	Work In Progress Requested by Mr. Chambers Weightroom-Need double doors at the Weightroom repaired to protect new equipment. Need dead bolts with keys installed on side doors (two way).	2/17/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
9685	Work In Progress Requested by Ms. Foote Rm. 332 Academic Building-Replace ceiling light bulbs. ROUTE TO BM - AS PER MIKE 2/17/06	2/14/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
9686	Work In Progress Requested by David Vega Business Building- Light switch on north wall, bottom floor needs to be replace.	2/14/2006 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9688	Work In Progress Requested by David Vega Rm. 243 Classroom Over Varsity Gym-Needs a few light bulbs replaced, on one of the lights. ROUTE TO BM - AS PER MIKE 2/17/06	2/14/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
9451	Work In Progress Requested by Velia Rm. 112 Front Office-Two keys of HE25 are needed for Key Box; room 200, Ms. A. Torres' classroom.	2/7/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
10573	Work In Progress Requested by Ms. Jordan Rm. 320 Academic Building-Has a light fixture with broken bulbs. It's been that way since October.	3/16/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10574	Work In Progress Requested by Velia Rm. 109C Main Building- Replace light bulb in Women's Faculty Restroom. *SECOND REQUEST	3/16/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10521	Work In Progress Requested by Coach A. Lopez Softball Field- Replace light bulbs on score board. *AS PER MR. FOSTER, PLEASE RUSH THIS.	3/15/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
10522	Work In Progress Requested by Coach A. Lopez Softball Field- Paint dug outs maroon and trim gold.	3/15/2006 Medium	Velia Alarcon Guadalupe Ontiveros Painting		Gadsden HS
10524	Work In Progress Requested by Ms. L. Melendrez Rm. 333 Academic Building-This room needs to be painted this summer.	3/15/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
10525	Work In Progress Requested by Ms. L. Melendrez Rm. 333 Academic Building-Replace the chalkboard (back of room), 1/3 of the board can't be used because their is glue all over it.	3/15/2006 3/15/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10526	Work In Progress Requested by Ms. Runyan Rm. 900 Nurse's Office-Requesting refridgerated air conditioner or cieling fans. 3/27 - As per Mike Munoz please route this work order thru Mr. Chambers. e-mailed Velia and Mr. Chambers on 3/27 - mkv 4/10 - As per Mike Faxed to Mr. Chavez for approval - mkv	3/15/2006 Medium	Velia Alarcon Michael Munoz Heating/Ventilation /Air Conditioning		Gadsden HS
10034	Work In Progress Requested by Mr. Grubaugh Rm. 275C Library- Toilet in the boy's restroom won't quit flushing.	2/27/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10035	Work In Progress Requested by Mr. Palmer Rm. 229 North Building-1.) Remove permanent desks that stick out into room. (There's 7 of them.) 2.) Relocate the gas and electrical outlets to the side counters. *Call me before work begins so I can clean out stored items.	2/27/2006 Medium	Velia Alarcon Michael Munoz General Maintenance		Gadsden HS
11422	Work In Progress Requested by Ms. Leahy Rm. 215 North Building-Windows need mini-blinds, windows need to be measured to order the blinds.	4/19/2006 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
11162	Work In Progress Requested by Ms. V. Lopez Business Building-The assembly of 6 steel shelving units. These units are located in the "old Counseling Center."	4/6/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
11163	Work In Progress Requested by Ms. D. Nanez Library-Change the time on the clock. Clock is about 13 feet high on the wall, a latter is needed.	4/6/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
11165	Work In Progress Requested by Ms. Ulibarri-Klein Rm. 504 Annex Building-Remove switch on bottom of 3rd pole to back, but leave outlet active that is on top of pole. For questions call Sylvester the District Telecommunication Tech.	4/6/2006 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
11270	Work In Progress Requested Ms. Aragon Rm. 146 Old English Building-Air Ducts are blowing out dust and bugs since last spring, they might need to be cleaned.	4/11/2006 Medium	Velia Alarcon Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
11271	Work In Progress Requested by Dolores Nanez Library-Double doors at the Library entrance need oiling or greasing.	4/11/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
10796	Work In Progress Requested by Velia Old English Building-Fix hole on the wall of the 1st floor of the Old English Building, close to room # 128. As Per Mr. Foster this needs to be fixed as soon as possible.	3/29/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10797	Work In Progress Requested by Velia Concession Stand by Girl's Gym-Change cylinder and four keys are needed for the door.	3/29/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
10800	Work In Progress Requested by Ms. Moreno Rm. 126 Main Building-There is a water leak above my channel one monitor. The monitor was replaced, but the technician said that this one would be damaged as well if the leak was not fixed.	3/29/2006 Medium	Velia Alarcon Fernando Moncayo Roof		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10801	Work In Progress Requested by Mrs. Munoz Rm. 610 Business Building-Nine light bulbs need to be replaced.	3/29/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10877	Work In Progress Requested by Mr. Wall Rm. 346 Academic Building-Two window blinds are need for the windows. They're required for Lock Down Fire Drills.	3/31/2006 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
10879	Work In Progress Requested by Velia for Rm. 140 Old English Building-FOURTH REQUEST-The blinds in the room are broken and do not work properly. This will help keep the sun out in the afternoon when the room gets "very hot". Blind measurements 44 x 90.	3/31/2006 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
10881	Work In Progress Requested by Mr. Gamboa Rm. 128 Old English Building-Blinds are needed for the windows, blind measurements 44 x 90, four sets are needed.	3/31/2006 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
10885	Work In Progress Requested by Velia for the hallways in the Old English Building-Halls need to be painted.	3/31/2006 Medium	Velia Alarcon Mario Apodaca Painting		Gadsden HS
11644	Work In Progress Requested by Velia-Mr. S. Alvarado's HX2 key does not open his basketball office. Key needs to be corrected before summer time when he has summer basketball practice begins.	4/26/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
11645	Work In Progress Requested by Velia for Upstairs hallway of Business Building-Several light bulbs are burned out and need replacing.	4/26/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
11646	Work In Progress Requested by Velia for New Counseling Center Portable-On Marie's and Isela's side of the portable, several light bulbs are out and need replacing.	4/26/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
11876	Work In Progress Requested by Dolores Nanez Library-Requesting a copy made of a key that opens the cash deposit to Xerox machine before summer break.	5/2/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
11903	Work In Progress Requested by Velia for east side entry door to Girl's Gym-Panic bar needs to be repaired or replaced.	5/3/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11925	Work In Progress Requested by Velia for outside the North Building on the "H" hallway-The intercom speaker needs to be re-secured to the wall. The speaker is dangling off the wall.	5/3/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
11926	Work In Progress Requested by Jenny Gonzalez Computer Lab-The Vandal Alert needs to have the battery replaced.	5/3/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
11927	Work In Progress Requested by Mr. Whitener Ag. Shop-The front door to the building can be unlocked using any key by inserting it only 1/4 inch and turning it, please repair as soon as possible.	5/3/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
11654	Work In Progress Requested by Mr. Whitener Rm. 563 Ag. Shop-Two hallway lights are not working.	4/26/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
11655	Work In Progress Requested by Mrs. Ulibarri-klein Rm. 504 Annex Building-Need to repair electrical outlets on NE wall.	4/26/2006 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
4897	Work In Progress Requested by Velia Rm. 112 Front Office-Two HE27 are needed for key box.	8/25/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4905	Work In Progress Requested by Mr. Milligan Rm. 143 Old English Building-Four keys are needed of HX2. Three for the assistant coaches and one for key box.	8/25/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
5083	Work In Progress Requested by Mr. Martin Rm. 551 Wood Shop-Hall lock will no unlock, 2nd Notice.	8/30/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4627	Work In Progress Requested by Velia Rm. 112 Front Office-Work order #3911 was not asked to me made off master, also three keys were asked for not two. An additional 4 keys are needed as soon as possible.	8/17/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4810	Work In Progress Requested by Ms. L. Chavez Rm. 245 Classroom Over Varsity Gym-Re-place several burned out light bulbs. RE-ROUTE TO BUILDING MECHANIC as per Mike Mc Dermott 9/19/05	8/23/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
4811	Work In Progress Requested by Mr. Cordova Storage Room in Varsity Gym Stage-The door needs to be re-keyed to an off master key, light board room. 4 keys are needed.	8/23/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4812	Work In Progress Requested by Lt. Dickerson Rm. 202 North Building-His HEM key has broken, 3 HEM keys are needed. One for him and two for the key box.	8/23/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4814	Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Air conditioner still does not work. No air is coming out of vents, very hot. Wires hanging into light fixture and a piece of ceiling tile (broken) is in one of the air conditioning vents. (room was damaged over summer)	8/23/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4816	Work In Progress Requested by Ms. L. Melendrez Rm. 331 Academic Building-I have been having trouble opening my front door for over a year, and now I am having trouble opening the back door. It's not my key it's the door handle and deadbolts. Both back doors are very difficult to open.	8/23/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4817	Work In Progress Requested by Mr. S. Perez Weight Room-Boys locker room door handle needs repair does not open. West side Weight Room door needs repairs does not lock.	8/23/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4820	Work In Progress Requested by Luis Saucedo Rm. 507 & 509 Annex Building-Install door stops on each of these doors.	8/23/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
4822	Work In Progress Requested by Ms. Zapien Rm. 154 Old English Building-The blinds are completely broken, the curtain is hanging.	8/23/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
4562	Work In Progress Requested by Ms. Klein Rm. 504 Annex Building-Air conditioner not working and appears to be leaking.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4564	Work In Progress Requested by Ms. Nanez Library-Install plywood baks to magazine shelves.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4521	Work In Progress Requested by Ms. Greene-Wall Rm. 505 Annex Building-Need a lock and spare keys on the new filing cabinet.	8/12/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4516	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-New water heater for kitchen area of Panther Hut. Route to Bldg Mechanic as per Mike 8/15/05 Check to see whats wrong with the H2o heater they have new one in small mech. room.	8/12/2005 Medium	Velia Alarcon Fernando Moncayo Plumbing		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4630	Work In Progress Requested by Mr. Dixon Rm. 600 Business Building-Needs an F3 gate key.	8/17/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4631	Work In Progress Requested by Ms. M. Gonzalez Rm. 140 Old English Building-I would like to request a door stop for the new door and blinds fo one of my windows. The room gets "very" warm especially 4th period. Receive measurements from Bldg Mechanic and re-route to Ruben for ordering. 4 ea - 43" W x 90' L	8/17/2005 9/16/2005 Medium	Velia Alarcon Ruben Ronquillo General Maintenance		Gadsden HS
4633	Work In Progress Requested by ISS Rm. 800 Old Counseling Center-Door frame falling off portable door leading to the old counseling center.	8/17/2005 Medium	Velia Alarcon Danny Miranda Doors and Hardware		Gadsden HS
4153	Work In Progress Requested by Mary Barreras Rm. 130 Old English Building-Need the new key to new lock to Sp. Ed. storage room for files and equipment. Key # M260	8/3/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4243	Work In Progress Requested by Ms. Bradley Rm. 602 Business Building-Handle on window has broken off, needs to be replaced.	8/5/2005 Medium	Velia Alarcon Mario Apodaca Glass\Window Repairs		Gadsden HS
4248	Work In Progress Requested by Ms. Gutierrez Rm. 823 Barracks-New cylinder is needed for new filing cabinet, 3 keys are needed.	8/5/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4166	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace ceiling tile in storeroom and office.	8/3/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4199	Work In Progress Requested by Mr. Chambers Rm. 110 Front Office-Re-key doors, make cylinders off D Master, 4 keys will be needed. Have had several items stolen from office, please re-key as soon as possible.	8/4/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4204	Work In Progress Requested by Cathy Cano Parking Lot-Over Fall Break, have the lines in the North Parking Lot painted.	8/4/2005 Medium	Velia Alarcon Michael Munoz Painting		Gadsden HS
4429	Work In Progress Requested by Velia Rm. 112 Front Office-Three HE keys are needed for Key Box.	8/10/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4386	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-220 Volt Electric extension cord needed with a new female end, current ones puts people at risk of electrocution.	8/9/2005 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4360	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HJ7, one for the floating teacher and one for the Key Box. For room number 753.	8/9/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4361	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK1, one for the floating teacher and one for the Key Box. For the Auto Shop.	8/9/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4362	Work In Progress Requested by Velia Rm. 112 Front Office-We need 5 additional keys of HE1. For the Gyms.	8/9/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4363	Work In Progress Requested by Velia Rm. 112 Front Office-Two additional keys are needed of HK5, one for the I.A. in the classroom and one for the key box. For room number 569.	8/9/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4269	Work In Progress Requested by Ms. Jacquez Rm. 752 Barracks-Window is unhinged and needs to be repaired.	8/8/2005 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
4271	Work In Progress Requested by Ms. Kalkwarf Rm. 750 Barracks-Floor tiles are broken and coming off the floor.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4272	Work In Progress Requested by Ms. Klein Rm. 504 Annex Building-Having a hard time locking and opening door, appears to be locked but stays unlocked.	8/8/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4279	Work In Progress Requested by Ms. Littlefield Rm. 226 North Building-The lock on my podium and one storage cabinet is brocken and lost.	8/8/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4282	Work In Progress Requested by Mr. Martinez Rm. 227 North Building-Replace carpet in Attendance Office area. One edge of the carpet is lifting, our concern is that a person may trip and fall.	8/8/2005 Medium	Velia Alarcon Michael Munoz Carpet Repair		Gadsden HS
4283	Work In Progress Requested by Mr. Myers Rm. 509 Annex Building-Key will not open storage door. HJ10 is the key that should open door.	8/8/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4285	Work In Progress Requested by Mr. Villa Rm. 510 Band Room-Security light in the center of the room does not work.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4286	Work In Progress Requested by Mr. Villa Rm. 510 Band Room-Need two HK13 keys made.	8/8/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
7370	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop- 2ND REQUEST Replace ceiling tile in office storeroom. Consider placing a plywood floor over unprotected tile.	11/15/2005 Medium	Velia Alarcon Michael Munoz General Maintenance		Gadsden HS
7626	Work In Progress Requested by Mr. Foster and Mr. Chambers Varsity Gym-ATTN: Mike Munoz Replace heating units and duct work. *Girls team practiced in 23 degrees this morning in the gym. *Parents calling and complaining about conditions. *Parents calling Central Office.	11/29/2005 Medium	Velia Alarcon Jose Ambriz Heating/Ventilation /Air Conditioning	Gym	Gadsden HS
6710	Work In Progress Requested Ms. Nanez Library-Backs to shelves need to be installed. Backs are in library, however, they need to be cut down to fit.	10/25/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
6713	Work In Progress Requested by Ms. Trich Library-Please replace blown light bulbs, especially in Librarian's office, room 275b.	10/25/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
6830	Work In Progress Requested by Velia Rm. 127 Main Building-When the sound system contractors installed the wiring in Ms. Garcia's classroom. They placed it on a wall Ms. Garcia used for her projector. Once they removed the wiring and placed it on another wall, they left the wall scrated and paint peeled. Wall needs to be repaired and painted.	10/28/2005 Medium	Velia Alarcon Fernando Moncayo Painting		Gadsden HS
7145	Work In Progress Requested by Ms. V. Lopez Old Counseling Center-Repair hole in ceiling near new ventilation work.	11/7/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
5405	Work In Progress Requested by Velia Rm. 112 Front Office-HG3 is needed for key box.	9/12/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
5406	Work In Progress Requested by Velia Rm. 112 Front Office-Two SA16 are needed, one for Ms. Dominguez and one for key box.	9/12/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
5407	Work In Progress Requested by Marie School Registrar Storage Room East Wing of the Cafeteria-The new vault needs to be re-keyed. The cylinder from the old vault can be placed on the door of the East Wing of the Cafeteria were her new vault is located now.	9/12/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
5409	Work In Progress Requested by Marie Storage Room in the East Wing of the Cafeteria-In the move from the old vault to the storage room one of the fire prove filing cabinet's locks broke. The filing cabinet remained locked, needs to be fixed as soon as possible as the Registrar needs access to these files on a daily basis.	9/12/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
6454	Work In Progress Requested by Mr. Chambers Football Restrooms- Paint large letters on restroom indicating men's and women's sides, or hang large signs indicating directions.	10/17/2005 Medium	Velia Alarcon Fernando Moncayo Painting		Gadsden HS
6460	Work In Progress Requested by Mr. Whitener Rm. 563 Ag. Shop- Install a hydraulic door closer on the new front door to the building.	10/17/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
6282	Work In Progress Requested by Mr. Donaldson Rm. 554 Woodshop- Paint (or provide paint)for repainting the tool room and paint room. Second Request	10/11/2005 Medium	Velia Alarcon Mario Apodaca Painting		Gadsden HS
2530	Work In Progress Requested by Mr. Chambers Rm. 110 Front Office-Need a 6 and 7 point keys to open classrooms, storerooms, etc. for construction people at G.H.S., one key of each.	6/6/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2745	Work In Progress Requested by Velia-In room 505 of the Annex Building there's a storage room that the contractors of Lynco Electric need access to. We do not have a key for the deadbolt on that door, needs to be opened as soon as possible for them.	6/13/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2698	Work In Progress Requested by Marie Acosta Rm. 803 Old Counseling Center-Re-key vault in Old Counseling Center. Needs to be off master, 5 keys are needed.	6/10/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2699	Work In Progress Requested by Velia Rm. 112 Front Office-Fix or re-place light bulbs on posts where Juan Diaz' mobile home is located. Where D.P.A. was located on our campus before, extremely dark at night.	6/10/2005 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
2700	Work In Progress Requested by Velia Rm. 112 Front Office-Have one HE200 re-cut, key does not open room. (Weight Room)	6/10/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
2701	Work In Progress Requested by Velia Rm. 112 Front Office-Have three HE87 re-cut, keys do not open room. (Training Room)	6/10/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2578	Work In Progress Requested by Velia Rm. 112 Front Office-We need two additional keys of HH6, downstairs Social Workers Office in Old English Building.	6/7/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2579	Work In Progress Requested by Velia Rm. 112 Front Office-We need three additional keys of HE200 (Weight Room).	6/7/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2580	Work In Progress Requested by Velia Rm. 112 Front Office-We need three additional keys of HE131 (my office).	6/7/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2581	Work In Progress Requested by Velia Rm. 112 Front Office-We need five additional keys of DC17 (Swimming Pool).	6/7/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2582	Work In Progress Requested by Velia Rm. 112 Front Office- We need two additional keys of HH9, upstairs Social Workers Office in Old English Building.	6/7/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2583	Work In Progress Requested by Velia Rm. 112 Front Office-We need one additional key of HH7, for I.A. in Ms. Axtell's classroom.	6/7/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2584	Work In Progress Requested by Isela Rm. 800 Counseling Center- Paint office and doors.	6/7/2005 Medium	Velia Alarcon Joe Ontiveros Painting		Gadsden HS
3494	Work In Progress Requested by Marie New Counseling Center Portable-New portable needs to be keyed HE134. Change old cylinder to doors of new portable doors.	7/12/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
3715	Work In Progress Requested by Mr. Pawloski Rm. 109A Main Building (Sp.Ed. Office)-Please remove the lock in my file cabinet, replace, and re-key it with a new one.	7/20/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
3716	Work In Progress ***URGENT***Requested by Velia Library-All the doors in the library need to be secured. They have changed all the door knobs and the cylinders need to be installed. URGENT library has alot of equipment that needs to me locked and secured!	7/20/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3902	Work In Progress Requested by Ms. Marquez New Counseling Portable-Two filing cabinets need to be keyed.	7/28/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
3910	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Bracket needed for N.M. Flag.	7/28/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
3920	Work In Progress Requested by Velia Front Office-The cylinder for room #107 will not open with a D Master or key assigned to door. This classroom is the Day Care on our campus and the building custodian can not open the classroom to clean. Please fix as soon as possible.	7/28/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
345	Work In Progress The gate on the south side of the school was hit over the weekend. We're unable to close gate, we need this repaired as soon as possible.	3/14/2005 Medium	Velia Alarcon Joe Ontiveros General Maintenance		Gadsden HS
316	Work In Progress Requested by Mr. Donaldson Rm 554 Wood Shop-1. Install heavier electric circuit for operation of drum sander. 2. Re-route machine wiring (belt/disc., sander, etc.) through safety kill switch.	3/11/2005 Medium	Velia Alarcon Carlos Castillo Electrical	Classroom	Gadsden HS
321	Work In Progress Requested by Mr. J. Gonzales Rm 300 Academic Building-No power on south wall of classroom. as per BM reset breaker after power outage.	3/11/2005 5/18/2005 Medium	Velia Alarcon Fernando Moncayo Electrical	Classroom	Gadsden HS
179	Work In Progress Requested by Ms. M. Gonzalez, Rm 140 Old English Building-Third Request-The blinds in my room are broken and do not work properly. This will help keep the sun out in the afternoon when the roon gets "very hot". Mario took a look at them, class will need 4 set of blinds measurements 44 X 90	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs	Classroom	Gadsden HS
185	Work In Progress Requested by Mr. Martin, Rm 551 Wood Shop-Broken Window	3/8/2005 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
893	Work In Progress Requested by Mr. Contaldo Rm 103-Paint outside of observatory using white oil-based paint.	4/6/2005 Medium	Velia Alarcon Joe Ontiveros Painting		Gadsden HS
447	Work In Progress Requested by Mr. D. Martinez Rm 227C North Building-Replace windows in the Assistant Principal's Office. The windows that are there currently are painted shut.	3/16/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
448	Work In Progress Requested by Mr. D. Martinez Outside of North Building-Have electrical outlets placed outside the North Building in the shaded area for the candy/snack machines. THIS WO WAS REROUTED TO MIKE MC DERMOTT AS PER MIKE MUNOZ - CC 9/21/05	3/16/2005 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
450	Work In Progress Requested by Mr. D. Martinez main hallway in North Building-Move the snack machines from the main hallway to the shaded area outside, once the electrical outlets have been placed. Need to run new outlets for snack machines - reassign to Dist. Electrician - as per Mario Apodaca 8/23/05 - mkv	3/16/2005 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
727	Work In Progress Requested by Mr. Haack, Rm 127 Main Building-Window was broken on 3/30/05.	3/31/2005 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs	Classroom	Gadsden HS
1638	Work In Progress Requested by Ms. Jordan Rm. 320 Academic Building-Lights blown out.	5/4/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance	Classroom	Gadsden HS
1640	Work In Progress Requested by Mr. Whitener Rm. 563 Ag. Shop-Needed: one 25 foot extension cord made for the arc welding machines. Also, repair the female ends on 3 existing extension cords.	5/4/2005 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
1641	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-The oil pressure gauge on the air compressor is broken and drips crankcase oil onto the floor. It also has an air leak on the small copper tubing on the compressor which causes it to turn on frequently.	5/4/2005 Medium	Velia Alarcon Joe Ontiveros General Maintenance		Gadsden HS
1642	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-The door lock on the south shop door (emergency exit) is very difficult to lock and unlock.	5/4/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
1680	Work In Progress Requested by Mr. Chambers Rm. 317 Academic Building-Install a combination lock in the mail room in the Academic Building.	5/5/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
1527	Work In Progress Requested by Mr. A. Perez Rm. 550 Wood Shop Building-Paint entry door; in order to avoid tagging. Adjust gap between door.	4/29/2005 Medium	Velia Alarcon Joe Ontiveros Painting		Gadsden HS
1569	Work In Progress Requested by Fernando Moncayo Varsity Gym-Broken glass in basketball locker room.	5/2/2005 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
1489	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace broken ceiling tile and install plank roof over office and storeroom.	4/28/2005 Medium	Velia Alarcon Joe Ontiveros General Maintenance	Classroom	Gadsden HS
1159	Work In Progress Requested by Ms. M. Garcia Rm 752 Barracks-Blinds needed on one window (45 x 60). Fire hazard, covered with paper. Special Ed. classroom	4/14/2005 Medium	Velia Alarcon Ruben Ronquillo General Maintenance	Classroom	Gadsden HS
1179	Work In Progress Requested by Velia Rm 113 & 114 Main Building (Front Office)-We need the windows replaced in the men and women bathrooms, we're unable to open or close windows properly.	4/15/2005 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS PATIO
1019	Work In Progress Requested by Ms. Moreno Rm. 126 Main Building-Put blinds on the windows.	4/11/2005 Medium	Velia Alarcon Ruben Ronquillo General Maintenance	Classroom	Gadsden HS
2471	Work In Progress Requested by Ms. Lopez Rm. 805 Counseling Center-Re-Key room 805 (both doors) to a D106, two keys are needed.	6/2/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2467	Work In Progress Requested by Velia Front Office-Five additional keys needed of the M master key.	6/2/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2469	Work In Progress Requested by Ms. Lopez Counseling Center-1. Re-key rooms 804, 806, 808, 809 (room 809 has two doors, both doors need to be re-keyed) to an off master key. Needed to store testing materials and is a security issue. Four keys are needed.	6/2/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
2436	Work In Progress Requested by Maria Perez Rm. 228 North Building-Have the small brown filing cabinet re-keyed. 3 keys are needed.	6/2/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock	Office	Gadsden HS
2437	Work In Progress Requested by Cathy Rm. 115 Front Office-Need 3 name plates with Cathryn Cano	6/2/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock	Office	Gadsden HS
2441	Work In Progress Requested by Ms. Lopez Rooms 802-809 Counseling Center-Remove carpet from all rooms. As per Mike route to Bldg Mechanic 6/10/05 - mkv	6/2/2005 Medium	Velia Alarcon Joe Ontiveros General Maintenance		Gadsden HS
12196	Work In Progress Requested by Ms. Arredondo for Restrooms in Ag. Shop and Wood Shop-Install a locking latch inside the restroom, no way to prevent any one from unlocking the door and find someone using the restroom.	5/15/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12197	Work In Progress I know this is not a General Maintenance Work Order, but I wasn't sure what type it would be (V.A.) Requested by Ms. Arredondo Rm. 568 Vocational Building-THIRD REQUEST to install floor tile in classroom, very important for classroom instruction.	5/15/2006 Medium	Velia Alarcon Michael Munoz Carpet Repair		Gadsden HS
12203	Work In Progress Requested by Ms. Arredondo Rm. 568 Vocational Building-Paint classroom (white or beige) important light source for classroom as it is an Art classroom.	5/15/2006 Medium	Velia Alarcon Mario Apodaca Painting		Gadsden HS
12211	Work In Progress Requested by Ms. Arredondo Rm. 568 Vocational Building-Replace burned out light bulbs (4), important light source for the Art classroom.	5/15/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
12212	Work In Progress Requested by Ms. Melendrez Rm. 333 Academic Building-The lock on the file cabinet next to the door needs to be replaced before school is out on the 23rd of May, having trouble opening it.	5/15/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
3616	Work In Progress replace door at pump room	7/18/2005 Medium	Ricardo Jacquez Danny Miranda General Maintenance		Gadsden MS
11330	Work In Progress We need to have the 6x6 glass cubes removed and install wall with plaster glass keeps broken. 4/19/06 - Routed to Gerry as per Mike.	4/12/2006 Medium	Rudy Arreola Michael Munoz General Maintenance	Hallway/Corridor	Gadsden MS
11147	Work In Progress We are having problems with mice and roaches in homec RM.	4/6/2006 Medium	Rudy Arreola Margret Villalobos Pest Control	Classroom	Gadsden MS
11148	Work In Progress We need the light fixture replaced cover is missing replaced ballast but light fixture is not secure.	4/6/2006 Medium	Rudy Arreola Enrique Sotelo Electrical	Restroom (Boys)	Gadsden MS
11732	Work In Progress RM#404 We are having problems with the door handle unlocking or locking room. Possible we have to replace the key also.	4/28/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock		Gadsden MS
11872	Work In Progress We have 5 doors that are not closing right and having trouble to lock them at night tried to spray them with instant degreaser but did not work.	5/2/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock	Hallway/Corridor	Gadsden MS
11873	Work In Progress We need to reorder the filter for Marta Jaques ref/unit somebody removed it and no where to be found.	5/2/2006 Medium	Rudy Arreola Lorenzo Solis Heating/Ventilation /Air Conditioning		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11875	Work In Progress We need locks for set of double doors in cafeteria so we can lock them at the end of the day. SECURITY ISSUES	5/2/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock	Cafeteria	Gadsden MS
11608	Work In Progress BOY'S LOCKER ROOM WAS BROKEN IN DOOR HANDLE BROKEN OFF - NEED TO SECURE BY THE END OF THE DAY	4/25/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock	Restroom (Boys)	Gadsden MS
11609	Work In Progress WATER SPICETT WAS DAMAGED AND LEAKING WATER NEED TO REPLACE ASAP	4/25/2006 Medium	Rudy Arreola Joe Ontiveros Plumbing	Restroom (Boys)	Gadsden MS
9038	Work In Progress Main Gym - pulled handle and broken, tagging on door, mirror and baseball dugouts.	1/23/2006 Medium	Rudy Arreola Rudy Arreola General Maintenance		Gadsden MS
9002	Work In Progress Sink is clogged we need the snake. to run it threw the wall drain.	1/24/2006 Medium	Rudy Arreola Joe Ontiveros Plumbing		Gadsden MS
9003	Work In Progress We need a new handle behind gym annex handle was pulled and broken off.	1/24/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock		Gadsden MS
9004	Work In Progress Rm #114 cylinder is stuck and wont turn and door needs to be secured for the end of the day.	1/24/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock		Gadsden MS
9150	Work In Progress We need 2 cylinders changed so they can match the WA-94 key to the classroom and storage RMS	1/30/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock	Classroom	Gadsden MS
8602	Work In Progress Back flow in A-WING is leaking water. Route to Lupe as per Mike Munoz 3/10/06 - mkv	1/10/2006 Medium	Rudy Arreola Guadalupe Ontiveros Grounds		Gadsden MS
8603	Work In Progress Backflow in B-WING is leaking water.	1/10/2006 Medium	Rudy Arreola Guadalupe Ontiveros Grounds		Gadsden MS
8468	Work In Progress We need to have front office fumigated big and small roaches when you turn on the lights.	1/6/2006 Medium	Rudy Arreola Margret Villalobos Pest Control		Gadsden MS
9494	Work In Progress MAIN BLDG - NEED EMERGENCY LIGHTS IN HALLWAYS AND RESTROOMS AS PER PM 9373.	2/8/2006 Medium	Rudy Arreola Enrique Sotelo Electrical		Gadsden MS
9590	Work In Progress Boiler RM in B-WING not heating B-WING area. Called Control and Equipment	2/10/2006 Medium	Rudy Arreola Margret Villalobos Energy Management System		Gadsden MS
9591	Work In Progress Three way valve in unit is getting stuck needs to be replaced in RM 116	2/10/2006 Medium	Rudy Arreola Lorenzo Solis Heating/Ventilation /Air Conditioning	Classroom	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
5317	Work In Progress Need to cap of water lines and drain removed already removed sink and counters. RM#188.	9/7/2005 Medium	Rudy Arreola Joe Ontiveros Plumbing	Classroom	Gadsden MS
5793	Work In Progress {{{GYM LOBBY}}} Wall needs to be secured.	9/23/2005 Medium	Rudy Arreola Danny Miranda General Maintenance	Restroom (Boys)	Gadsden MS
5569	Work In Progress VOC BLDG RM#306 - Need some assistance changing out ballast already replaced lamps high ceiling.	9/16/2005 Medium	Rudy Arreola Enrique Sotelo Electrical	Classroom	Gadsden MS
5918	Work In Progress Door handle is broken off boys lockerroom	9/28/2005 Medium	Rudy Arreola Manny Lozoya Key and Lock		Gadsden MS
6386	Work In Progress Light on the westside of the bandroom doesnt turn on.	10/13/2005 Medium	Rudy Arreola Enrique Sotelo Electrical		Gadsden MS
4218	Work In Progress Coil in not cooling cleaned out strainer and checked valve. RM 156	8/4/2005 Medium	Rudy Arreola Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Gadsden MS
4220	Work In Progress Rm 157/158 Unit is not cooling at all cleaned out strainer and checked valves.	8/4/2005 Medium	Rudy Arreola Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Gadsden MS
4528	Work In Progress We need 2 water fountains replaced in cafeteria.	8/12/2005 Medium	Rudy Arreola Jaime Gomez Heating/Ventilation /Air Conditioning		Gadsden MS
3000	Work In Progress We need change locks due to the floor getting a new coat of varnish and so one can go in.	6/27/2005 Medium	Rudy Arreola Manny Lozoya Key and Lock	Gym	Gadsden MS
2784	Work In Progress We need to have the sprinklers in front of school adjusted especially in the B-WING.	6/15/2005 Medium	Rudy Arreola Lorenzo Hernandez Grounds	Parking Lot	Gadsden MS
354	Work In Progress Need to installing emerg. lights in hallways and restrooms girls and boys as per pm 125602.	3/14/2005 Medium	Rudy Arreola Enrique Sotelo Electrical		Gadsden MS
326	Work In Progress We are having a problem with students in the cafeteria after hours we need to have dead bolts installed so we can secure cafeteria.	3/11/2005 Medium	Rudy Arreola Manny Lozoya Key and Lock	Cafeteria	Gadsden MS
1465	Work In Progress We need metal frames around windows we several threw out the campus in main bldg. The moulding is missing.	4/27/2005 Medium	Rudy Arreola Ruben Ronquillo Glass\Window Repairs		Gadsden MS
1105	Work In Progress Sidewalk on eastside of annex bldg is to steep for wheelchair need sidewalk raised.	4/13/2005 Medium	Rudy Arreola Michael Munoz Concrete		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
1101	Work In Progress We are going have a new student in a wheelchair the only concern is we need a walkway where the new fence was put up to connect to the side of the bandroom.	4/13/2005 Medium	Rudy Arreola Michael Munoz Concrete		Gadsden MS
1102	Work In Progress Some of the doors to the main entance have a little step the wheelchair may not be able to go up (Concerned the student may flip forward).	4/13/2005 Medium	Rudy Arreola Michael Munoz Concrete		Gadsden MS
2194	Work In Progress Need some help for knocking down some walls to make an extra classroom in C-WING old Calixto's office.	5/23/2005 Medium	Rudy Arreola Danny Miranda General Maintenance		Gadsden MS
2031	Work In Progress 2 A/C in main gym need to be replaced.	5/17/2005 Medium	Rudy Arreola Jaime Gomez Heating/Ventilation /Air Conditioning		Gadsden MS
2242	Work In Progress MAIN BANDROOM. We need to remove 2 steps in bandroom to make more room.	5/24/2005 Medium	Rudy Arreola Michael Munoz General Maintenance		Gadsden MS
2244	Work In Progress Room 140 handle was broken need to have it replaced.	5/24/2005 Medium	Rudy Arreola Manny Lozoya Key and Lock		Gadsden MS
12276	Work In Progress Unit in RM 209 C-WING not working compressor burned out need to have it replaced.	5/17/2006 Medium	Rudy Arreola Lorenzo Solis Heating/Ventilation /Air Conditioning		Gadsden MS
12166	Work In Progress Door not closing right need to be secured end of the day.	5/12/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock	Restroom (Boys)	Gadsden MS
12158	Work In Progress Medicine cabinet was having trouble to open with all the medications for the students. ASAP.	5/12/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock		Gadsden MS
12006	Work In Progress We need the tractor to mow the bus turnaround if you can drop it off in the MORNING and it will be ready to be picked up by the end of the day.	5/8/2006 Medium	Rudy Arreola Guadalupe Ontiveros Grounds		Gadsden MS
12078	Work In Progress Floor drain collasped need to have it repaired. 5/16 - Route to Rudy as per Mike 5/22 - Route to Plumbers as per Mike.	5/10/2006 Medium	Rudy Arreola Fred Appelzoller Plumbing	Mechanical Room	Gadsden MS
12079	Work In Progress Doors in the B-WING boiler RM are rusted out on the bottom of the door. Need to have them replaced kids started to kick them.	5/10/2006 Medium	Rudy Arreola Danny Miranda Doors and Hardware	Mechanical Room	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11890	Work In Progress please install sprinklers that will cover all grass area and install 2 stations instead of 1 Thanks	5/2/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		Gadsden MS
2221	Work In Progress Weeds are growing out on the new tennis courts. Please cut and apply a none coloring chemical to prevent weeds from coming out thru concrete and damaging the courts. Also please cut the weeds around tennis court. THanks	5/23/2005 Medium	Michael Munoz Lorenzo Hernandez Grounds	Athletic Field	Gadsden MS
2470	Work In Progress GATE BY DITCH NEEDS TO BE REPLACED. IT'S ONLY LOCKED BY A SMALL CHAIN THAT CAN EASILY BE BROKEN (PER YOLIE JACQUEZ). ROUTE TO MANNY LOZOYA AS PER MIKE MUNOZ.	6/2/2005 Medium	Michael Munoz Manny Lozoya Key and Lock		Gadsden MS
2954	Work In Progress Please install new sprinkler by picnic area where sprinkler was broken and run a new line for additional sprinkler by the south east door by cafeteria for proper coverage of irrigation. As per Rudy need to route to Fred Appelzoller. - mkv	6/23/2005 Medium	Michael Munoz Fred Appelzoller Plumbing		Gadsden MS GROUNDS
8845	Work In Progress DOUBLE DOORS INSIDE BAND ROOM WHERE INSTRUMENTS ARE STORED DO NOT LOCK AND SECURE PROPERLY. EQUIPMENT SAFETY ISSUE.	1/18/2006 Medium	Maria Sitters Danny Miranda Doors and Hardware		Gadsden MS
3582	Work In Progress IRRIGATION CTRL PANEL - IRRIGATION BOOSTER PUMP IS NOT WORKING. PLEASE TROUBLESHOOT BUS TURNAROUND AREA. ROUTED TO ENRIQUE AS PER RICK 8/2/05	7/15/2005 8/2/2005 Medium	Lorenzo Hernandez Enrique Sotelo Electrical		Gadsden MS
5119	Work In Progress Power Outage - El Paso Electric	8/29/2005 Medium	Margret Villalobos Enrique Sotelo Electrical		Gadsden MS
11690	Work In Progress Broken shower head and broken door handle to coaches office. Broken door handle 130.00 parts/labor Broken shower head 300parts/200labor	4/24/2006 Medium	Jose Pinon Rudy Arreola General Maintenance		Gadsden MS
4867	Work In Progress THE PAD HOLDER IS WORN OUT AND WONT HOLD THE PAD AT ALL.	8/24/2005 Medium	Jimmy Carbajal Jimmy Carbajal Custodial Equipment Repair	Hallway/Corridor	Gadsden MS
11049	Work In Progress 3-compartment sink - two of the facuets are leaking really bad. Terry P. SNP Mgr 882-2824	4/3/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Gadsden MS
11684	Work In Progress Need new power strips in classroom for additional computers. See Mrs. Osborn room 121. Also repair wall outlets in room, possible shock hazzard	4/27/2006 Medium	Dana Hamel Enrique Sotelo Electrical	Classroom	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11553	Work In Progress Again the basketball goals will not go up or down without sticking	4/24/2006 Medium	Dana Hamel Michael Munoz Equipment	Gym	Gadsden MS
9148	Work In Progress Please repair the bleachers, the rollers are out of sync, and we have a tournament coming up	1/30/2006 Medium	Dana Hamel Michael Munoz Equipment	Gym	Gadsden MS
9149	Work In Progress Extend concrete eastward from doorway towards the gym, not enough room for a motorized wheelchair	1/30/2006 Medium	Dana Hamel Michael Munoz Concrete	Hallway/Corridor	Gadsden MS
9518	Work In Progress check out the recepticle on front wall room 121, teacher currently using a side outlet for 5 computers	2/9/2006 Medium	Dana Hamel Enrique Sotelo Electrical		Gadsden MS
4522	Work In Progress Door broken in room 500, and window shattered	8/12/2005 Medium	Dana Hamel Danny Miranda Doors and Hardware	Portables	Gadsden MS
4643	Work In Progress Need a copy of fire alarm key (See Mr. Hamel for his key).	8/17/2005 Medium	Dana Hamel Manny Lozoya Key and Lock		Gadsden MS
4982	Work In Progress Whole south side of annex does not have any air, class temperatures are above 95 degrees. The classes opposite hallway have conditioning, Please fix ASAP	8/26/2005 Medium	Dana Hamel Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Gadsden MS
4777	Work In Progress The three locks on the office front window are broken, mostly poor design. The front office is wide open until these are repaired or replaced	8/22/2005 Medium	Dana Hamel Rudy Arreola General Maintenance	Office	Gadsden MS
4778	Work In Progress 2nd request for an "A" master for GMS Campus	8/22/2005 Medium	Dana Hamel Manny Lozoya Key and Lock	Office	Gadsden MS
5499	Work In Progress Change M4 key to a G key in all electrical room on campus, we have no "m" master	9/14/2005 Medium	Dana Hamel Manny Lozoya Key and Lock	Electrical Room	Gadsden MS
5500	Work In Progress change A3 key to a "g" key in storage room in annex	9/14/2005 Medium	Dana Hamel Manny Lozoya Key and Lock	Mechanical Room	Gadsden MS
5501	Work In Progress Repair the outside doors locks "w" master will not open doors to lobby	9/14/2005 Medium	Dana Hamel Manny Lozoya Key and Lock	Hallway/Corridor	Gadsden MS
5502	Work In Progress request 3 new "G" keys for principal and custodians	9/14/2005 Medium	Dana Hamel Manny Lozoya Key and Lock		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6241	Work In Progress The new roof on the vocational building leaked badly over vacation and the insulation in the old woodshop is falling. Serious problem with students returning tomorrow could fall at any time.	10/10/2005 Medium	Dana Hamel David Boyd Construction	Classroom	Gadsden MS
2572	Work In Progress need locks on desk draws and other security measures to ensure that data is not compromised. Gloria Hernandez office and Terry Villalobos data entry clerks in C wing. ASAP	6/7/2005 Medium	Dana Hamel Manny Lozoya Key and Lock	Office	Gadsden MS
2789	Work In Progress check to ensure that the flushes are working in lobby bathroom. If they are, then request that custodial clean, clean, and clean again this area (stinks)	6/15/2005 Medium	Dana Hamel Fred Appenzoller Plumbing	Restroom (Boys)	Gadsden MS
2881	Work In Progress fix exhaust fan in science room 150	6/20/2005 Medium	Dana Hamel Rudy Arreola General Maintenance	Classroom	Gadsden MS
2888	Work In Progress repair holes in ceiling by air conditioner, needs 4 new window blinds, secure fuse box, secure air conditioner switch, repair entry door to class and last can not use the high switch on air conditioner because it makes too much noise.	6/20/2005 Medium	Dana Hamel Rudy Arreola General Maintenance	Portables	Gadsden MS
2889	Work In Progress repair all the interior doors, jams and latches. Outside doors are not closing unless lifted by handles	6/20/2005 Medium	Dana Hamel Danny Miranda Doors and Hardware	Gym	Gadsden MS
2929	Work In Progress Replace door into storage area and repair the frame to keep students from upstairs area	6/21/2005 Medium	Dana Hamel Danny Miranda Doors and Hardware	Stairway	Gadsden MS
3653	Work In Progress paint the columns on outside of gym	7/19/2005 Medium	Dana Hamel Rudy Arreola General Maintenance	Gym	Gadsden MS
3654	Work In Progress paint over the scratchouts in boys black restrooms	7/19/2005 Medium	Dana Hamel Rudy Arreola General Maintenance	Restroom (Boys)	Gadsden MS
3655	Work In Progress paint the front columns of the school to remove tagging	7/19/2005 Medium	Dana Hamel Rudy Arreola General Maintenance		Gadsden MS
12094	Work In Progress Room 163 loses power at least 3 times per day. All outlets go down. This causes a problem with computers, instruction and attendance. HELP	5/10/2006 Medium	Dana Hamel Enrique Sotelo Electrical	Classroom	Gadsden MS
12383	Work In Progress Replace light bulbs (3) in class room 107 Route to Rudy as per Mike 5/23/06 - mkv	5/22/2006 Medium	Dana Hamel Rudy Arreola General Maintenance		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12385	Work In Progress repair electrical plug west wall Route to Rudy as per Mike 5/23/06 - mkv	5/22/2006 Medium	Dana Hamel Rudy Arreola General Maintenance	Classroom	Gadsden MS
12351	Work In Progress Could we get GMS utilities marked Wed? Thanks, Carlos	5/19/2006 Medium	Carlos Vigil Fred Appelzoller Plumbing		Gadsden MS
12333	Work In Progress I will be needing a set of Master Keys made for Lynco, for GMS for this coming Monday if possible. Thanks Carlos Vigil	5/19/2006 Medium	Carlos Vigil Manny Lozoya Key and Lock		Gadsden MS
7479	Work In Progress Also at GMS Gym Bleachers They have a cheap extension for the score board, could we get a permanent 120v outlet fastened to front of bleachers? thanks , Carlos	11/18/2005 Medium	Carlos Vigil Enrique Sotelo Electrical		Gadsden MS
11187	Work In Progress NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006.	4/7/2006 Medium	Aida Salcedo Juan Acosta Custodial		Gadsden MS
12074	Work In Progress BLEACHERS NEED TO BE CLEANED DURING GYM FINISHING. PLEASE NOTIFY AIDA KNOW WHEN THIS TASK IS COMPLETED SO INSPECTION CAN BE DONE.	5/10/2006 Medium	Aida Salcedo Juan Acosta Custodial		Gadsden MS
7760	Work In Progress Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola Fire Extinguishers		Gadsden MS
10966	Work In Progress Monthly - Gadsden MS Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Gadsden MS
5961	Work In Progress please reomve and replaced stained ceiling tiles in Mr.Lowenburgs office.	9/29/2005 Medium	Rudy Arreola General Maintenance		Gadsden MS
6424	Work In Progress WE NEED LIGHTS IN THE BOYS & GIRLS RR IN MAIN BLDG, ALSO WE NEED THE LIGHTS IN HALLWAYS AS PER PM 6095.	10/14/2005 Medium	Enrique Sotelo Electrical		Gadsden MS
4095	Work In Progress please fiill hole that is in front of entrance to band room. Will need a backking before gravel is applied. see mike	8/2/2005 High	Rudy Arreola General Maintenance		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9295	Work In Progress please replaced stained ceiling tiles in Mr.Lowenburgs office and thru-out c-wing area thats needed. Thanks	2/3/2006 Medium	Rudy Arreola General Maintenance		Gadsden MS
8735	Work In Progress please install new sprinklers by picnic tables & where needed and level grounds around area. Thanks	1/13/2006 Medium	Guadalupe Ontiveros Grounds	Cafeteria	Gadsden MS
10710	Work In Progress please install lights on the north side off the gym annex so the light will shine on the bus turnaround.	3/27/2006 Medium	Enrique Sotelo Electrical		Gadsden MS
11544	Work In Progress Athletic Office - Having trouble opening door - key is sticking.	4/24/2006 Medium	Terry Alvarado Manny Lozoya Key and Lock		Gadsden MS
12245	Work In Progress I LOCKED CABINET AND WE DO NOT HAVE KEYS TO IT. CALLED GHS SHE DOES NOT HAVE KEYS. DESC. OF CABINET - SMALL BLACK FILING CABINET HON 4191	5/16/2006 Medium	Terry Alvarado Manny Lozoya Key and Lock		Gadsden MS
7716	Work In Progress Kitchen - Need to shutdown gas and water service on Friday, 12/16/05 @ 1:00 pm. Route to Pancho, Spoke to him today 12/15/05 and he can do this. - M. Munoz	12/1/2005 12/2/2005 Medium	Alfredo Holguin Frank Lara Plumbing	Cafeteria	La Mesa ES
11783	Work In Progress Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Frank Lara General Maintenance		La Mesa ES
11751	Work In Progress Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Frank Lara Fire Extinguishers		La Mesa ES
11789	Work In Progress Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Frank Lara General Maintenance		La Mesa ES
11316	Work In Progress NEED A KEY TO OPEN GATE AND FRONT OFFICE - WORK BEING DONE FOR FIRE DAMAGE ON FRIDAY AND MONDAY 4/14/06 & 4/17/06 (PLAN B)	4/12/2006 Medium	Cora Ramirez Manny Lozoya Key and Lock		La Mesa ES
4378	Work In Progress locksmith need three keys for supply rm. key no F 49 8/23- Debra needs status on this work order submitted on 8/9/05 - mkv	8/9/2005 Medium	Frank Lara Manny Lozoya Key and Lock		La Mesa ES
9899	Work In Progress MAIN BLDG - NEED TO REPLACE 2 BROKEN WINDOWS 26 1/2 W X 54 3/4 L	2/21/2006 Medium	Frank Lara Ruben Ronquillo Glass\Window Repairs		La Mesa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12580	Work In Progress please deliver and set up 200 chairs and desk as per our discussion to sunrise elementary. thanks	5/30/2006 Medium	Michael Munoz Jimmy Carbajal Custodial	Classroom	La Mesa ES
12066	Work In Progress Need to replace old pilots on boiler for La Mesa.	5/10/2006 Medium	Lorenzo Solis Lorenzo Solis Heating/Ventilation /Air Conditioning		La Mesa ES
12505	Work In Progress A/C Units are not working (very hot in bldg)	5/25/2006 Medium	Margret Villalobos Jose Ambriz Heating/Ventilation /Air Conditioning		La Union ES
10119	Work In Progress JTP - Mr. Casavantes needs you to replace lock from the stroage computer cabinet.	3/2/2006 Medium	Julie Hernandez Manny Lozoya Key and Lock		La Union ES
10085	Work In Progress need to replace starter and heater thanks	3/1/2006 Medium	Ricardo Jacquez Carlos Castillo Electrical		La Union ES
166	Work In Progress A motor starter coil is requested for the boiler pump at new addition	3/8/2005 Medium	Eddie Baeza Jose Ambriz Heating/Ventilation /Air Conditioning		La Union ES
1613	Work In Progress Transformer for the high temp. alarm in the server rm. does not have 120v circuit only the 24v side was hooked up.	5/3/2005 Medium	Eddie Baeza Carlos Castillo Electrical		La Union ES
12401	Work In Progress Old Mechanical Room - Need to get pump started up.	5/22/2006 Medium	David Villalobos Carlos Castillo Electrical		La Union ES
11138	Work In Progress need to run water line to front of old main building for irrigation	4/6/2006 Medium	David Villalobos David Villalobos Plumbing	Mechanical Room	La Union ES
8256	Work In Progress Alvarez Farms ,panel needs main lug kit replaced	12/22/2005 Medium	Carlos Castillo Carlos Castillo Electrical	Classroom	La Union ES
11188	Work In Progress NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006.	4/7/2006 Medium	Aida Salcedo Santos Galindo Custodial		La Union ES
3572	Work In Progress NEED LIGHT BULBS FOR RECESSED LIGHTS AT LA UNION ELEM. THE MAJORITY ARE BURNED OUT. THANK YOU.	7/15/2005 Medium	Arturo Nunez Carlos Castillo Electrical		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4917	Work In Progress please repair asphalt where other water line was repired.	8/25/2005 Medium	Michael Munoz Concrete		La Union ES
10968	Work In Progress Monthly - La Union ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		La Union ES
3322	Work In Progress Yearly - La Union ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza Fire Protection		La Union ES
3344	Work In Progress Yearly - La Union ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Eddie Baeza Fire Protection		La Union ES
4864	Work In Progress JTP- Rosaro Ruedas needs a L201 key.	8/24/2005 Medium	Selma Nevarez Manny Lozoya Key and Lock		La Union ES JTP
6718	Work In Progress need electrical outlet on north wall	10/25/2005 10/26/2005 Medium	Santos Galindo Carlos Castillo Electrical	Office	La Union ES
7446	Work In Progress would like hallway in old wing painted and frames. and new base trimming.	11/18/2005 Medium	Santos Galindo Salvador Gonzalez Painting		La Union ES
6403	Work In Progress NEED CORK STRIP INFRONT OF THE OFFICE IN HALLAWAY.	10/14/2005 Medium	Santos Galindo Ruben Ronquillo General Maintenance		La Union ES
4356	Work In Progress in room 202 there is no outlet for refrigeration unit a.s.p.	8/9/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES
4372	Work In Progress need a fan motor in electrical storage room.	8/9/2005 Medium	Santos Galindo Jose Ambriz Heating/Ventilation /Air Conditioning		La Union ES
4408	Work In Progress a light next to my office need to be looked at cause it buzzes all day long.	8/10/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES
4223	Work In Progress need an electrical outlet by computer hookups room 203.	8/5/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES
4775	Work In Progress Parking lanes need to be repaint in yellow and bus lane also needs to be repaint but in red. Route to Sal Gonzalez as per Mike 9/13/05 -mkv	8/22/2005 Medium	Santos Galindo Salvador Gonzalez General Maintenance		La Union ES
4825	Work In Progress Need keys for room #100, #106, and room #108; plus keys for a file cabinet in the nurse's office.	8/23/2005 Medium	Santos Galindo Manny Lozoya Key and Lock		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4853	Work In Progress SINK AT CUSTODIAL CLOSET AT OLD BLDG. IS CLOGGED UP.	8/24/2005 Medium	Santos Galindo David Villalobos Plumbing		La Union ES
5117	Work In Progress Lights in computer room keeps going out; breaker needs to be checked.	8/31/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES
5312	Work In Progress After last nights rainfall, leaks were discovered in rooms #208, #209, and the library.	9/7/2005 Medium	Santos Galindo Lorenzo Solis Roof		La Union ES
6418	Work In Progress Work Truck - need to repair broken tial-light.	10/14/2005 Medium	Salvador Gonzalez Angel Gonzales Vehicle Maintenance		La Union ES
5949	Work In Progress Music Room needs a new circuit installation.	9/29/2005 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
5786	Work In Progress Upper hinge on door at JTP needs to be repair. Might need to be weld	9/23/2005 Medium	Salvador Gonzalez Manny Lozoya Key and Lock		La Union ES
5503	Work In Progress Old emergency light fixtures (the complete system) are not working can you check them please. thank you	9/14/2005 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
7391	Work In Progress 11/15/05 To Caly. Relocate electrical outlet.	11/15/2005 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
11629	Work In Progress Replace old lighth bulbs and ballasts.	4/25/2006 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
9768	Work In Progress To Mike Munoz Subject: I would like to install PVC watering system on side of the school and between buildings.	2/16/2006 Medium	Salvador Gonzalez Guadalupe Ontiveros Grounds		La Union ES
9769	Work In Progress Teacher in classroom 110 requires more power outlets because his room only has two.	2/16/2006 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
10569	Work In Progress 1/16/06 Manny We need to secure door for the end of the day, lock problem.	3/16/2006 Medium	Salvador Gonzalez Manny Lozoya Key and Lock		La Union ES
10313	Work In Progress Room 206 needs to be fumigated for spiders.	3/7/2006 Medium	Salvador Gonzalez Margret Villalobos Pest Control		La Union ES
10409	Work In Progress Manny, the lock door knob at classroom 100 is mising. Can you come and fix it please.	3/10/2006 Medium	Salvador Gonzalez Manny Lozoya Key and Lock		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8547	Work In Progress Take out grass at swings area with the back hoe and fill with sand (has half of needed sand)	1/9/2006 Medium	Salvador Gonzalez Guadalupe Ontiveros Grounds		La Union ES
9087	Work In Progress 1/27/06 To David Villalobos. There is a boiler back flow water valve leaking , on my opinion has to be replaced.	1/27/2006 Medium	Salvador Gonzalez David Villalobos Plumbing		La Union ES
8982	Work In Progress David I need some PVC to make a drain panel for boiler room please. Thank you.	1/24/2006 Medium	Salvador Gonzalez David Villalobos Plumbing		La Union ES
3345	Work In Progress Yearly - Loma Linda ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott Fire Protection		Loma Linda ES
3323	Work In Progress Yearly - Loma Linda ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott Fire Protection		Loma Linda ES
5568	Work In Progress As per Mike Munoz issue a 6 & 7 Grand Master keys to Mike Mc Dermott.	9/16/2005 Medium	Manny Lozoya Key and Lock		Loma Linda ES
9386	Work In Progress Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Michael Mc Dermott General Maintenance		Loma Linda ES
11463	Work In Progress NEED TO COMPLETE FLOOR PLAN ON YOUR WORK SCHEDULE.	4/20/2006 Medium	Aida Salcedo Luis Solis Custodial		Loma Linda ES
8647	Work In Progress NEED TO COMPLETE BUILDING INSPECTION FOR ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOU OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED & SIGNED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JANUARY 27, 2006	1/11/2006 Medium	Aida Salcedo Luis Solis Custodial		Loma Linda ES
699	Work In Progress need window latches for rms 103-106-105-204 asap- need to secure windows at end of day- sent sample to ppd Route to Ruben as per Danny - 5/25/06 - mkv	3/30/2005 Medium	Danny Vega Ruben Ronquillo Glass/Window Repairs	Classroom	Loma Linda ES
6538	Work In Progress Need Ditch Witch delivered to Loma Linda tomorrow.	10/18/2005 Medium	David Villalobos Angel Gonzales Equipment		Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12387	Work In Progress MIKE, MR. TRUJILLO IS REQUESTING THAT YOU HAVE DRAPES INSTALLED ON THE CAFETERIA STAGE. THANK YOU	5/22/2006 Medium	Grace Alvarado Michael Munoz General Maintenance		Loma Linda ES
12318	Work In Progress DICE MIKE THAT THE DRINKING FOUNTAIN PART OF THE SINK IN ROOM #119 "NO BUENO"	5/19/2006 Medium	Grace Alvarado Joe Ontiveros Plumbing		Loma Linda ES
12040	Work In Progress ATTN: JOSE THE PLUMBER, REPAIR LEAKS IN GIRL'S RR SENSOR SINKS. MAIN HALL ALSO ROOM 110 SINK IS STOPPED UP.	5/9/2006 Medium	Grace Alvarado Joe Ontiveros Plumbing		Loma Linda ES
11692	Work In Progress RAUL SANCHEZ: REPAIR BOOSTER PUMP FOR SPRINKLER SYSTEM	4/27/2006 Medium	Grace Alvarado Raul Sanchez Sewage/Water Treatment Plant		Loma Linda ES
11396	Work In Progress MANNY LOZOYA: INSTALL LOCK FOR FILE CABINETT. MIKE AMAYA ROOM 107 ASAP (SECURITY REASON)	4/18/2006 Medium	Grace Alvarado Manny Lozoya Key and Lock		Loma Linda ES
11425	Work In Progress MANNY LOZOYA; INSTALL NEW LOCK ON EAST WING GATE.	4/19/2006 Medium	Grace Alvarado Manny Lozoya Key and Lock		Loma Linda ES
9219	Work In Progress MANNY. REPAIR NE GATE. LOCK IS BROKEN	2/1/2006 Medium	Grace Alvarado Manny Lozoya Key and Lock		Loma Linda ES
8143	Work In Progress MIKE INSTALL OUTLET IN BOOKROOM	12/15/2005 Medium	Grace Alvarado Michael Mc Dermott General Maintenance		Loma Linda ES
9897	Work In Progress MIKE MCDERMOTT: REQUEST REPAIR OR REPLACEMENT OF VENETIAN BLINDS, PARTICULARLY WINDOW ON NORTH ISE OF EAST WALL ROOM 103 LET ME KNOW. AS PER MR. T.	2/21/2006 Medium	Grace Alvarado Ruben Ronquillo Glass\Window Repairs		Loma Linda ES
9831	Work In Progress ATTN: PLUMBERS NEED KIT INSTALLED TO BOLT TOILET TO FLOOR & NEW BOWLI WAY. BOYS R.R. NORTHWEST WING. NEED SENSOR SINKS REPAIRED. 2ND REQUEST LEAKING VERY BADLY. BOYS RR SOUTH WEST WING. NEED NEW HOSE BIB INSTALLED IN COURTYARD BEHIND LIBRARY. OLD ONE WILL NOT CLOSE.	2/17/2006 Medium	Grace Alvarado Joe Ontiveros Plumbing		Loma Linda ES
10133	Work In Progress MANNY LOZOYA, MEN BATHROOM IN SECOND GRADE LOST TUMBLER. TUMBLER CAN BE FOUND IN THE OFFICE	3/2/2006 Medium	Grace Alvarado Manny Lozoya Key and Lock		Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3829	Work In Progress MR. TRUJILLO IS WANTING NEW KEYS MADE FOR DESKS, CABINETTS AND FILE CABINETS. ALSO NEEDING NAME PLATE FOR NEW TEACHERS. MS. BERARD, CHAVEZ-FISHER, GRIEGO, DESANTIAGO, HUGHES, MARKHAM, MEDINA, MERRICK, MONTES, PINA, PRICE, RIOS-ALVILLAR,	7/26/2005 Medium	Grace Alvarado Manny Lozoya Key and Lock		Loma Linda ES
1761	Work In Progress Needing Speedy to fertilize within next 2 weeks, also needing dirt to build borders for trees	5/9/2005 Medium	Grace Alvarado Lorenzo Hernandez Grounds		Loma Linda ES
352	Work In Progress UNABLE TO LOCK ROOM	3/14/2005 Medium	Grace Alvarado Manny Lozoya Key and Lock	Classroom	Loma Linda ES 114
452	Work In Progress DISTRICT ART SHOW SETUP AT GADSDEN MIDDLE SCHOOL, PUT UP IS APRIL 14, 2005 AT 8:30 AM TAKE DOWN IS APRIL 18, 2005 AT 10:00 AM	3/16/2005 Medium	Grace Alvarado Danny Vega General Maintenance		Loma Linda ES
6686	Work In Progress INSTALL ELECTRICAL CIRCUIT IN ROOM 208 FOR MICROWAVE AND FRIDGE.	10/24/2005 Medium	Grace Alvarado Enrique Sotelo Electrical		Loma Linda ES
7361	Work In Progress REPLACE TIMER FOR BOILER	11/15/2005 Medium	Grace Alvarado Jose Ambriz Heating/Ventilation /Air Conditioning		Loma Linda ES
4593	Work In Progress MIKE MUNOZ, REPLACE EAST FENCE	8/16/2005 Medium	Grace Alvarado Michael Munoz Fence Repair		Loma Linda ES
9454	Work In Progress Need a gate key for El Paso Disposal.	2/7/2006 Medium	Juliet Parra Manny Lozoya Key and Lock		Loma Linda ES
12204	Work In Progress BACK DOOR TO KITCHEN: NEED TO REPLACE DOOR SWEEP (BOTTOM OF DOOR) FRANCES BLACK SNP MGR 882-4707	5/15/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Loma Linda ES
12422	Work In Progress 5-23-6 ATTN; MIKE MUNOZ AS PER DAVID BOYD ROOM 110 HAS MOLD GROWING ON WEST WALL DUE TO LEAKS IN ROOF DRAINS. ALSO ROOF ABOVE RM 110 NEEDS TO BE REPAIRED.	5/23/2006 Medium	Michael Mc Dermott Michael Munoz General Maintenance	Classroom	Loma Linda ES RM 110
12424	Work In Progress 5-23-6 ATTN; MIKE MUNOZ SMALL PORTABLE NEEDS CARPET REPLACED.	5/23/2006 Medium	Michael Mc Dermott Michael Munoz Carpet Repair	Portables	Loma Linda ES SMALL POT.
12425	Work In Progress 5-23-6 NEED TO REPLACE FLOOR TILES IN WEST ENTRY NEXT TO BOOK ROOM.	5/23/2006 Medium	Michael Mc Dermott Michael Mc Dermott General Maintenance	Hallway/Corridor	Loma Linda ES WEST ENTRY

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12146	Work In Progress 5-4-6 8-hours paint entry way by computer room. 5/4 - 8	5/12/2006 Medium	Michael Mc Dermott Michael Mc Dermott Painting	Classroom	Loma Linda ES
1676	Work In Progress NEED ANOTHER ROYAL BAG FOR THE VACUUM CLEANER. TO REPLACE TWO WITH SOME HOLES (DAMAGED). THANK YOU.	5/5/2005 Medium	Luis Solis Jimmy Carbajal Custodial Equipment Repair		Loma Linda ES
11724	Work In Progress WE NEED AT LEAST (5) 55 GALS METAL TRASH CANS LIDS (BEE PROBLEMS). THANK YOU.	4/28/2006 Medium	Luis Solis Jimmy Carbajal Custodial		Loma Linda ES
11855	Work In Progress THE WATER SCENSOR IN THE GIRLS RESTROOM BY MR. PINA CLASSROOM #112 TURNS ON AND OFF BY IT SELT.	5/2/2006 Medium	Luis Solis Joe Ontiveros Plumbing		Loma Linda ES
11856	Work In Progress THE WATER FAUCET BEHIND THE LIBRARY NEEDS TO BE REPAIRED.	5/2/2006 Medium	Luis Solis Joe Ontiveros Plumbing		Loma Linda ES
11857	Work In Progress ONE OF THE WATERFOUNTAIN NEXT TO MR. GUZMAN CLASSROOM # 113 IS NOT WORKING (NO WATER).	5/2/2006 Medium	Luis Solis Lorenzo Solis Heating/Ventilation /Air Conditioning		Loma Linda ES
11859	Work In Progress THE WATER FOUNTAIN OUT SIDE BEHIND THE LIBRARY NEED TO BE FIX (NO WATER).	5/2/2006 Medium	Luis Solis Joe Ontiveros Plumbing		Loma Linda ES
11860	Work In Progress THE TWO SECURITY LIGHTS LOCATED BEHIND THE CAFETERIA, ONE IS ABOVE BOILER ROOM AND THE OTHER IS ABOVE THE BACK DOOR KITCHEN ENTRANCE, BOTH LIGHTS ARE FLICKING.	5/2/2006 Medium	Luis Solis Enrique Sotelo Electrical		Loma Linda ES
11863	Work In Progress THE TWO SECURITY LIGHTS AS YOU ENTER THE BUILDING, THE TOP RIGHT CORNER AND THE BOTTOM RIGHT HAND CORNER NEED TO BE REPAIR.	5/2/2006 Medium	Luis Solis Enrique Sotelo Electrical		Loma Linda ES
11864	Work In Progress THE SECURITY LIGHT IN SOUTH SIDE ENTRANCE NEED TO BE FIX.	5/2/2006 Medium	Luis Solis Enrique Sotelo Electrical		Loma Linda ES
2116	Work In Progress BERNICE SAPIEN - ROOM 304 NEED A NEW LOCK FOR FILING CABINET - KEY BROKE INSIDE LOCK.	5/19/2005 Medium	Luz Griego Manny Lozoya Key and Lock	Classroom	Mesquite ES
12085	Work In Progress enviromental park please back fill and run a border along side of park. contact Mr.Sedillo for direction.	5/10/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds	Athletic Field	Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12373	Work In Progress please cut grass and pick up debris and also repair where water goes from canal to playground so the water won't go along fence line. fence line by canal.	5/22/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance	Athletic Field	Mesquite ES
12374	Work In Progress please clean around all portables. (cut weeds and rake)	5/22/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance	Portables	Mesquite ES
12375	Work In Progress please pick and dispose charcoal that is by the portable by the playground.	5/22/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance	Portables	Mesquite ES
12376	Work In Progress please irrigate playfield with manual sprinkler and also dry spots where new playground and landscaping was done. grass is in need of water.	5/22/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance	Athletic Field	Mesquite ES
12378	Work In Progress please cut and weed around trees that are east of library, also the front of the campus needs a trim and trees need wells around them.	5/22/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance	Library	Mesquite ES
12379	Work In Progress please trim pinon tree and make new well for watering of tree. also trim and weed at memory garden.	5/22/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
12380	Work In Progress please trim mexican elders that are in front of campus and make wells around trees for watering.	5/22/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
11634	Work In Progress lorenzo, broken water fountain in cafeteria. need to replace. thanx.	4/26/2006 Medium	Romauldo Apodaca Lorenzo Solis Heating/Ventilation /Air Conditioning		Mesquite ES
11635	Work In Progress need motor for exhaust fan electrical rm. thanx.	4/26/2006 Medium	Romauldo Apodaca Lorenzo Solis Heating/Ventilation /Air Conditioning		Mesquite ES
11570	Work In Progress kiki need to assist w/ emergency light, ballast.	4/25/2006 Medium	Romauldo Apodaca Enrique Sotelo Electrical		Mesquite ES
11103	Work In Progress need door frame and door for rm. 612, door in very bad condition. thanx.	4/5/2006 Medium	Romauldo Apodaca Danny Miranda Doors and Hardware		Mesquite ES
11284	Work In Progress portable 602 lever handle does not work. rm. 101 door knob does not open. rm. 112. door knob hard to open.	4/11/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
10714	Work In Progress need to open dry storage in kitchen for sound and signal. thanx	3/27/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8677	Work In Progress Portable 602 - Need vinyl flooring replaced w/ carpet, floor in bad shape,safety issue, someone may trip.	1/12/2006 Medium	Romauldo Apodaca Michael Munoz Carpet Repair	Portables	Mesquite ES
10061	Work In Progress broken master key need one right away,thanx.	2/28/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
10130	Work In Progress need to replace lever handle in sanchez portable,security issue. thanx.	3/2/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
9935	Work In Progress MANNY, NEED TO HELP W/ OPENING STORAGE RM. TRIED TO OPEN BUT CAN,T. THANX.	2/23/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
9937	Work In Progress DANNY MIRANDA, NEED DOOR HARDEWARE FOR CAFETERIA DOORS, AND MAIN DOORS. THANX.	2/23/2006 Medium	Romauldo Apodaca Danny Miranda Doors and Hardware		Mesquite ES
3558	Work In Progress need compresor changed out on armstrong unit in rm. 608.thanx.	7/14/2005 Medium	Romauldo Apodaca Jaime Gomez Heating/Ventilation /Air Conditioning		Mesquite ES
2664	Work In Progress need tile replaced rm. 113,111,110. 602 carpet instead of tile.	6/9/2005 Medium	Romauldo Apodaca Michael Munoz Carpet Repair	Classroom	Mesquite ES 602,113,111,110.
1621	Work In Progress need replacement of a/c side draft in portable 610.	5/3/2005 Medium	Romauldo Apodaca Jaime Gomez Heating/Ventilation /Air Conditioning		Mesquite ES
1622	Work In Progress need replacement of indusrial unit on barracks,per phillips and leyva.	5/3/2005 Medium	Romauldo Apodaca Jaime Gomez Heating/Ventilation /Air Conditioning		Mesquite ES
971	Work In Progress NEED FILING CABINETS CYLINDERS REPLACED.THANX.	4/8/2005 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
2152	Work In Progress PORTABLE 612 - DOOR HANDLE BROKEN.	5/20/2005 Medium	Romauldo Apodaca Manny Lozoya Key and Lock	Portables	Mesquite ES
4699	Work In Progress manny need your assistance w/ doors that are hard to open and close. thanx.	8/19/2005 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
3955	Work In Progress DINING AREA - NEED TO WELD HINGES ON DOOR FALLING DOWN.	7/29/2005 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
4340	Work In Progress manny need to assist w/ 2 doors in porables having hard time tpo close safety issue. also need lever handle.	8/9/2005 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6507	Work In Progress kiki, 5 rms w/ out lights need assistance.thanks. ARREGLAR PROBLEMA EN ALAMBRADO DE LUCES EN SALONES DE OLD WING.	10/18/2005 10/18/2005 Medium	Romauldo Apodaca Romauldo Apodaca Electrical		Mesquite ES
6508	Work In Progress jaime need to assist w/ boilers to change over to heating,also need gas valve for heater in old office.thanx.	10/18/2005 Medium	Romauldo Apodaca Jaime Gomez Heating/Ventilation /Air Conditioning		Mesquite ES
7825	Work In Progress NEED TO RUN ELECTRICAL LINES TO MAIN FIELD FOR RED RIBBON CUTTING CEROMONY ON 12/8/05 AT 6:AM FOR HEATERS AND LIGHTING,PER MS. PHILLIPS.	12/5/2005 Medium	Romauldo Apodaca Enrique Sotelo Electrical		Mesquite ES
12417	Work In Progress NEED TO ASSIST W/ OUTSIDE OUTLET,NO POWER.	5/23/2006 Medium	Romauldo Apodaca Enrique Sotelo Electrical		Mesquite ES
12575	Work In Progress need to change out cylinder in p.e. rm. thanx.	5/30/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
12576	Work In Progress need to replace master key for custodian,worn out.thnx.	5/30/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
12578	Work In Progress need to assist outside outlet no power.	5/30/2006 Medium	Romauldo Apodaca Enrique Sotelo Electrical		Mesquite ES
12525	Work In Progress manny,need new cylinder installed for fire proof cabinet.	5/26/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
12527	Work In Progress need to install cooling ,heating unit in bldg. mech. and head custodial office, no system exsits. thanx.	5/26/2006 Medium	Romauldo Apodaca Lorenzo Solis Heating/Ventilation /Air Conditioning		Mesquite ES
12529	Work In Progress manel,need to replace 3 lever handles on portables,please assist. thanx.	5/26/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
10758	Work In Progress Need a gate key for Gloria Martinez w/PSFA.	3/28/2006 Medium	Peggy Jo Hernandez Manny Lozoya Key and Lock		Mesquite ES
9135	Work In Progress Barracks - Remove rocks from roof and repair and secure water lines (safety issue).	1/30/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
9137	Work In Progress East of Library - Lots of weeds growing apply chemical, treat weeds ask for imput from Lupe so you wont kill trees.	1/30/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9138	Work In Progress Pecan Trees in back parking lot - Trim branches, cut weeds around and make new wells and water.	1/30/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
9139	Work In Progress North Fence Line by Pine Trees - Cut weeds and pickup trash and treat fence line.	1/30/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
12449	Work In Progress DRAIN RUNNING OVER IN THE LAUNDRY ROOM. LOCKER ROOM IS ALSO STARTING ALICE F. SNP MGR 233-2341	5/24/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Mesquite ES
11462	Work In Progress NEED TO COMPLETE FLOOR PLAN ON YOUR WORK SCHEDULE.	4/20/2006 Medium	Aida Salcedo Ruben Solis Custodial		Mesquite ES
10242	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
10252	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
10208	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Mesquite ES
11788	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
11798	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
11754	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Mesquite ES
9132	Work In Progress please remove grass and tiller ,then level on the enviromental park as per our discussion and reveiw of the plans.	1/30/2006 Medium	Guadalupe Ontiveros Grounds	Athletic Field	Mesquite ES
3324	Work In Progress Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Mesquite ES
3346	Work In Progress Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3971	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Mesquite ES
4005	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
4015	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
12416	Work In Progress 1- VACCUM CLEANER NEEDS TO BE REPAIR (ELECTRICAL PLUG) 2- WET AND DRY MACHINE NEEDS TO BE REPAIR	5/23/2006 Medium	Ruben Solis Jimmy Carbajal Custodial Equipment Repair	Custodial	Mesquite ES
2997	Work In Progress TRANSP. OFFICE - NEED TO RELOCATE ELEC. OUTLETS A/S/A/P.	6/27/2005 Medium	Sitters Walter Enrique Sotelo Electrical		Physical Plant Complex
8774	Work In Progress I would like to request the "Student Records Office" sign be moved from the north outside wall of the loading bay to the wall beside the Records Room door and also the door leading into the warehouse by the rec. room re-painted with "Student Records Office" Inside.	1/17/2006 Medium	Tracey Swinford Rudy Arreola General Maintenance		Physical Plant Complex
7834	Work In Progress Need to make a key for D. Miranda's Office for Ruben.	12/5/2005 Medium	Ruben Ronquillo Manny Lozoya Key and Lock		Physical Plant Complex
4017	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Rudy Arreola General Maintenance		Physical Plant Complex
2357	Work In Progress Custodial Office - Need to correct cooling in Mary and Aida's Office.	5/27/2005 Medium	Alfredo Holguin Jaime Gomez Heating/Ventilation /Air Conditioning	Physical Plant Complex Custodial	
7772	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola Fire Extinguishers		Physical Plant Complex
7810	Work In Progress Monthly - Physical Plant Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Rudy Arreola General Maintenance		Physical Plant Complex
12447	Work In Progress Need a key to Jimmy's Storage room. Please issue key to Alfredo Holguin.	5/24/2006 Medium	Alfredo Holguin Manny Lozoya Key and Lock	Physical Plant Complex Custodial	
3092	Work In Progress Install Speed limit signs and speed bumps on access road. See me on specifics Faxed PO on 8/4/05 - mkv	6/30/2005 8/8/2005 Safety	Alfredo Holguin Michael Munoz General Maintenance		Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3461	Work In Progress Need a copy of control key (core) to keep here at the Maintenance Dept - as per A. Holguin.	7/12/2005 Medium	Alfredo Holguin Manny Lozoya Key and Lock		Physical Plant Complex
3186	Work In Progress Monthly - Physical Plant FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Rudy Arreola Fire Extinguishers		Physical Plant Complex
7642	Work In Progress Auto Shop - Need to install 4 cylinders all the same but different from main entrance. Need 4 keys issued (see Angel).	11/30/2005 Medium	Angel Gonzales Manny Lozoya Key and Lock		Physical Plant Complex
7711	Work In Progress please order all material needed to paint barracks in the back and let me know what staff will be need to accomplish the project.	12/1/2005 Medium	Danny Miranda Painting	Portables	Physical Plant Complex
10419	Work In Progress Need to open Barrack for Melissa w/Finance on Monday, March 13th. She will be here at 10:00 am. -Thanks mkv	3/10/2006 3/7/2006 Medium	Manny Lozoya Key and Lock		Physical Plant Complex
12506	Work In Progress Mail Room - A/C Unit is leaking water.	5/25/2006 Medium	Rudy Arreola General Maintenance		Physical Plant Complex
5526	Work In Progress NEED A "CB4" KEY FOR GUILLERMO - TO HAVE ACCESS TO ENERGY OFFICE TO CLEAN.	9/15/2005 Medium	Manny Lozoya Key and Lock		Physical Plant Complex
2235	Work In Progress please order material for fill for disrict portable re-location. please include site and material that will be delivered on w.o . (per site)	5/24/2005 Medium	Lorenzo Hernandez Grounds		Physical Plant Complex
3379	Work In Progress Mens Restroom in Custodial Warehouse -Install new privacy lockset	7/7/2005 Low	Manny Lozoya Key and Lock	Restroom (Boys)	Physical Plant Complex
3380	Work In Progress Mens Restroom in Custodial Warehouse- Replace toilet tank cover with appropriate size for unit.	7/7/2005 Medium	Fred Appenzoller Plumbing	Restroom (Boys)	Physical Plant Complex
9750	Work In Progress WILL NEED PLUMBING WORK DONE IN CUSTODIAL WAREHOUSE TO BE ABLE TO INSTALL NEW WASHER & DRYER - MUST BE DONE BY FEBUARY 24, 2005. 4/24/06 - Please assist Joe w/this work order.	2/16/2006 Medium	Aida Salcedo Joe Ontiveros Plumbing	Custodial	Physical Plant Complex
8737	Work In Progress NEED SPARE KEY FOR AIDA (TRUCK) - P1106 BB6	1/13/2006 Medium	Aida Salcedo Manny Lozoya Key and Lock		Physical Plant Complex
1309	Work In Progress Need to make material list and request for general maintenance duties	4/21/2005 Medium	Carlos Castillo Carlos Castillo Electrical	Electrical Room	Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12231	Work In Progress need to replace light fixture covers at R.Ronquillo's office	5/16/2006 Medium	Carlos Castillo Carlos Castillo Electrical		Physical Plant Complex Office
4585	Work In Progress Need to replace water heater,its giving out an extremeley bad odor.Health issue.	8/16/2005 Medium	Carlos Castillo Joe Ontiveros Plumbing	Electrical Room	Physical Plant Complex
12377	Work In Progress NEED TO CORRECT TRAILER BRAKE WIRING FOR VEHICLE #152	5/22/2006 Medium	Carlos Castillo Angel Gonzales Vehicle Maintenance		Physical Plant Complex
12386	Work In Progress THE DOOR FOR THE TECHNOLOGY WAREHOUSE - PROBLEM WITH LOCKING DOOR. SOMETIMES LOCKS SOMETIMES DOES NOT (IF YOU HAVE QUESTIONS PLEASE CALL CORA EXT. 6275)	5/22/2006 Medium	Cora Ramirez Manny Lozoya Key and Lock		Physical Plant Complex
9950	Work In Progress 2/21/06 (2)7910 (4)unload materials for chaparral elen. @ san miguel elem. (1.5)exchange corner bead @ foxworth (.5)back to vado elem. 2/21-6	2/23/2006 Medium	Danny Miranda Danny Miranda Doors and Hardware		Physical Plant Complex
5432	Work In Progress Auto Shop - need to install new door knob to new door at Angel's Office.	9/12/2005 Medium	Danny Miranda Manny Lozoya Key and Lock		Physical Plant Complex
2631	Work In Progress Need to replace door knob to outside Double Doors.	6/8/2005 Medium	HECTOR LOZOYA Manny Lozoya Key and Lock		Physical Plant Complex
11710	Work In Progress Need to get a/c's going.	4/27/2006 Medium	Michael Munoz Danny Orozco Food Services		Physical Plant Complex
9057	Work In Progress PPD Barracks - Need to run power to existing panel box. (Coordinate w/eachother Cali, Enrique and Mike Mc Dermott).	1/26/2006 Medium	Michael Munoz Enrique Sotelo Electrical		Physical Plant Complex
11268	Work In Progress NEED "CB-4" KEY TO HAVE AS AN EXTRA WHEN NEEDED FOR CUSTODIAL TRAINING VIDEOS.	4/11/2006 Medium	Maria Sitters Manny Lozoya Key and Lock		Physical Plant Complex
8822	Work In Progress Front Entrance Blue Double Doors - Cylinders need to be cleaned.	1/18/2006 Medium	Peggy Jo Hernandez Manny Lozoya Key and Lock		Physical Plant Complex
353	Work In Progress Need to installing emerg. lights as per pm 125559.	3/14/2005 Medium	Rudy Arreola Enrique Sotelo Electrical		Physical Plant Complex
11574	Work In Progress please primer and paint barracks.	4/25/2006 Medium	Michael Munoz Danny Miranda Painting		Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12064	Work In Progress Please replace water filters on HVAC Shop for Ice Machine. As per Rick this wo is for L. Solis 5/17/06-mkv	5/10/2006 Medium	Lorenzo Solis Lorenzo Solis Heating/Ventilation /Air Conditioning		Physical Plant Complex
5121	Work In Progress Power Outage - El Paso Electric	8/29/2005 Medium	Margret Villalobos Enrique Sotelo Electrical		Physical Plant Complex
12448	Work In Progress Need a valve for burnisher.	5/24/2006 Medium	Marco Fattorini Jimmy Carbajal Custodial Equipment Repair	Custodial	Physical Plant Complex
3940	Work In Progress MARTA JACQUEZ - A/C UNIT IS NOT WORKING AT ALL.	7/29/2005 Medium	Marta Jacquez Jaime Gomez Heating/Ventilation /Air Conditioning		Physical Plant Complex
2657	Work In Progress LADIES RR - THE FAUCET SHOOTS THE WATER OUT IN UNEVEN SPURTS AND ON THE TOILET THE LINE CONNECTING TO THE WALL, MAKES A LOUD SOUND AND RATTLES AND THE WATER FILLING IN COMES IN DIRTY.	6/9/2005 Medium	Marta Jacquez Fred Appelzoller Plumbing	Restroom (Girls)	Physical Plant Complex
2263	Work In Progress Maint. Office - Need to fix door closer to main door.	5/24/2005 Medium	Margret Villalobos Manny Lozoya Key and Lock		Physical Plant Complex
1673	Work In Progress Transporation Office - Need to install door w/window.	5/5/2005 Medium	Margret Villalobos Danny Miranda Doors and Hardware		Physical Plant Complex
2540	Work In Progress Need copies (3) made of regular master padlocks located in halls used to secure exits with chain.	6/6/2005 Medium	Miguel Aguilar Manny Lozoya Key and Lock		Riverside ES
10175	Work In Progress DISHWASHER - WHERE THE SOAP GOES THRU IS CLOGGED UP. NANCY ROLLIN SNP MGR 589-2550	3/3/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Riverside ES
12299	Work In Progress se desconpusieron 2 aspiradoras necesito las arreglen por favor, gracias series e99600003712 k96a0001573	5/18/2006 Medium	Raul Romero Jimmy Carbajal Custodial Equipment Repair		Riverside ES
12579	Work In Progress se desconpuso la maquina de pulir los pisos gracias por arreglarla se desconpuso la maquina de pulir el piso necesito que la arreglen por favor	5/30/2006 Medium	Raul Romero Jimmy Carbajal Custodial Equipment Repair		Riverside ES
12293	Work In Progress New shelving installed. Carpet pulled away from wall to accommodate new shelving. Carpet needs to be trimmed and fitted around new shelving. For questions please call me (Phillip Medina) at 915-637-0141.	5/18/2006 Medium	Phillip Medina Michael Munoz Carpet Repair	Library	Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
5057	Work In Progress We need a new Door Knob placed in the Data Clerk office. (office area) At this time the door doesn't lock.	8/30/2005 Medium	Olga Arias Manny Lozoya Key and Lock		Riverside ES
5058	Work In Progress Carpet (Doorway) to Data clerk office is coming loose. Plastic edge is picking-up.. Thanks	8/30/2005 Medium	Olga Arias Michael Munoz Carpet Repair		Riverside ES
11591	Work In Progress drain clogged up to vegetable sink Virginia Pruitt - Substitute Manager 589-2550	4/25/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Riverside ES
2088	Work In Progress PLEASE REMOVE OLD SEAL, INSTALL NEW ONE WITH NEW CAULKING AND 45 CONCRETE AGAINST WALL AND FLOOR. OUTSIDE PATIO WHERE MAIN HALL WAY ENTERS TOWARDS CAFETERIA. THIS WILL PREVENT WATER FROM ENTERING TO BUILDING.	5/18/2005 Medium	Adan Duran General Maintenance	Cafeteria	Riverside ES
5592	Work In Progress please see what can be done to repair or remove electrical outlet on floor on serving line. Outlet has a can over it and could be a trip hazard.	9/19/2005 Medium	Danny Orozco Food Services	Cafeteria	Riverside ES
12433	Work In Progress MR LUPE ONTIVEROS GROUNDS SIR PER REQUEST MR SANCHEZ WOULD LIKE THE RUN OFF DRAIN BEHIND THE SCHOOL TO BE CLEAN OUT FULL OF SAND AND TO HAUL OFF SAND PILE OUTSIDE OF DRAIN THANK YOU AND GOD BLESS	5/23/2006 Medium	Adan Duran Guadalupe Ontiveros Grounds		Riverside ES
12178	Work In Progress MR CARLOS CASTILLO SIR THE NIGHT LIGHT ON THE OUT SIDE OF BUILDING NOT COMING ON TILL MID NIGHT OR LATER ALSO THE LIGHTS ON POST BY PORTABLE NORTH SIDE ARE NOT COMING ON THANK YOU SIR AND GOD BLESS	5/15/2006 Medium	Adan Duran Carlos Castillo Electrical		Riverside ES
12028	Work In Progress MR MANNY LOZOYA SIR WE HAVE A CABLE LOCK STUCK WILL NOT OPEN NORTH EAST ENTRANCE ALL NEED TO RPLACE TWO PAD LOCK MESSED UP THANK YOU SIR AND GOD BLESS	5/9/2006 Medium	Adan Duran Manny Lozoya Key and Lock		Riverside ES
12093	Work In Progress MR LUPE ONTIVEROS GROUNDS SIR WILL NEED FOUR DUMP TRUCKS LOADS OF CRUCHER FINE IN FRONT OF TRAILER WHERE MR HERNANDEZ LIVES WIND HAS BLOWN AWAY TOP SOIL AND PIPES ARE EXPOSE NEED TO COVER THEM UP AGAIN BEFORE THEY GET RUN OVER AND BROKEN I THANK YOU SIR AND GOD BLESS	5/10/2006 Medium	Adan Duran Guadalupe Ontiveros Grounds		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12096	Work In Progress MR DAVID VILLALOBOS SIR HAVE SEVERAL LEAKING FAUCETS THAT NEED REPLACING THREE WASH BASIN'S AND ONE SINK YOU WILL NEED TO LOOK AT THEM TO GET CENTERS THANK YOU SIR AND GOD BLESS	5/10/2006 Medium	Adan Duran David Villalobos Plumbing		Riverside ES
10717	Work In Progress MR MIKE MUNOZ AND RUBEN RONQUILLO SIR I WOULK LIKE TO EXCHANGE COMODE OGER HAS A KINK IN THE CABLE ALSO WOULD LIKE TO EXCHANGE BLOWER LEAKS ALOT AND KEEPS GETTING CHOKE THANK YOU SIR AND GOD BLESS	3/27/2006 Medium	Adan Duran Ruben Ronquillo Equipment		Riverside ES
11306	Work In Progress MR MANNY LOZOYA SIR HAVE A DOOR THAT IS JAMED NEED YOUR HELP MAY NEED TO REPLACE I THANK YOU SIR AND GOD BLESS	4/12/2006 Medium	Adan Duran Manny Lozoya Key and Lock		Riverside ES
11611	Work In Progress MR CARLOS CASTILLO SIR WILL NEED SEVERAL BOXS OF FLORCENT LAMPS WILL NEED BELEAST HALL WAY LIGHTS AND BULBS I THANK YOU SIR AND GOD BLESS	4/25/2006 Medium	Adan Duran Carlos Castillo Electrical		Riverside ES
11681	Work In Progress Break-In on 4/24/06 Windows Broken -	4/27/2006 Medium	Adan Duran Ruben Ronquillo Glass\Window Repairs		Riverside ES
9856	Work In Progress NEED TAGS TO TAG FIRE EXTINGUISHERS AS PER PM 9346.	2/17/2006 Medium	Adan Duran Ruben Ronquillo Fire Extinguishers		Riverside ES
9714	Work In Progress NORTH ENTRANCE DOUBLE DOORS - AUTOMATIC DOOR CLOSER IS LEAKING ALOT OF OIL AND DOOR IS CLOSING FAST.	2/15/2006 Medium	Adan Duran Manny Lozoya Key and Lock		Riverside ES
9734	Work In Progress MR CARLOS CASTILLO SIR WE HAVE SEVERAL EMERGENCY LIGHT THAT NEED BATTRIES WILL NEED 6 AT THIS TIME THANK YOU SIR	2/15/2006 Medium	Adan Duran Carlos Castillo Electrical		Riverside ES
8661	Work In Progress MR CARLOS CASTILLO SIR WILL NEED SOME LAMPS SOME U LAMPS HALL WAY LAMPS SOME PL 13 SOME METAL HALIDE THANK YOU VERY MUCH SIR	1/11/2006 Medium	Adan Duran Carlos Castillo Electrical		Riverside ES
5115	Work In Progress MR LUPE ONTIVEROS SIR WILL NEED THE USE OF THE BACKHOE TO MOVE SOCCOR GOAL POST AWAY FROM PARKING AREA UNSAFE FOR KIDS THANK YOU SIR	8/31/2005 Medium	Adan Duran Guadalupe Ontiveros Grounds		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4473	Work In Progress MR MANNY LOZOYA SIR THE DOOR ON NEW PORTABLE IS STUCK IN LOCK CAN NOT GET IT TO UNLOCK PORTABLE B IN BACK THANK YOU SIR	8/11/2005 Medium	Adan Duran Manny Lozoya Key and Lock	Portables	Riverside ES
4596	Work In Progress MR MANNY LOYZOA SIR NEED TO CHANGE OUT DOOR HANDLE BY MRS ARIAS OFFICE THE ONE THERE DO NOT LOCK NEED ONE THAT CAN BE LOCKED THANK YOU SIR	8/16/2005 Medium	Adan Duran Manny Lozoya Doors and Hardware		Riverside ES
4388	Work In Progress MR JOSE AMBRIZ SIR WE NEED TO HOOK BACK UP THE AIR IN WHAT USE TO BE MRS FLORES OFFICE IT WAS REMOVE AT HER REQUEST AND ITS KIND OF WARM IN THERE THANK YOU SIR	8/9/2005 Medium	Adan Duran Jose Ambriz Heating/Ventilation /Air Conditioning		Riverside ES
3690	Work In Progress MR MANNY LOZOYA FILE CABINET NEW PORTABLE RM B NEEDS REPAIR WILL NOT LOCK PARTS MISSING THANK YOU SIR	7/19/2005 Medium	Adan Duran Manny Lozoya Key and Lock		Riverside ES
3778	Work In Progress MR DAVID VILLALOBOS WE HAVE SOME LEAKING FUACTS NEW WING NEED REPAIR KIT OR REPLACEMENT THANK YOU SIR	7/22/2005 Medium	Adan Duran David Villalobos Plumbing		Riverside ES
3414	Work In Progress MR LOZOYA MRS ARIAS IS HAVING TROUBLE WITH THE STORAGE ROOM LOCK WOULD LIKE FOR YOU TO LOOK AT IT THANK YOU SIR	7/8/2005 Medium	Adan Duran Manny Lozoya Key and Lock		Riverside ES
3348	Work In Progress Yearly - Riverside ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran Fire Protection		Riverside ES
3326	Work In Progress Yearly - Riverside ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Adan Duran Fire Protection		Riverside ES
10972	Work In Progress Monthly - Riverside ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Riverside ES
10973	Work In Progress Monthly - San Miguel ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		San Miguel ES
11007	Work In Progress Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Vega General Maintenance		San Miguel ES
11019	Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Vega General Maintenance		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10941	Work In Progress Monthly - San Miguel ES Roof Inpsection - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Vega Roof		San Miguel ES
10923	Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Vega Fire Extinguishers		San Miguel ES
3175	Work In Progress Monthly - San Miguel ES Roof Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Danny Vega Roof		San Miguel ES
3087	Work In Progress Double portable relocated to site was labeled as SM17DM1R there is no portable with that ID. Re-label this and all portables correctly.	6/29/2005 Low	Alfredo Holguin Michael Munoz General Maintenance	Portables	San Miguel ES
7632	Work In Progress The backflow prevention device on the irrigation distribution system needs to have the annual inspection performed.	11/29/2005 Medium	Guadalupe Ontiveros Grounds		San Miguel ES
1852	Work In Progress Please order paint so when portables arrive you can go ahead and paint. You site will be receiving one PLease see mike or call him for more info.	5/11/2005 Medium	Danny Vega Painting	Portables	San Miguel ES
11756	Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Danny Vega Fire Extinguishers		San Miguel ES
11803	Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Danny Vega General Maintenance		San Miguel ES
11791	Work In Progress Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Danny Vega General Maintenance		San Miguel ES
8401	Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Danny Vega General Maintenance		San Miguel ES
4489	Work In Progress Need an extra key for these rooms.	8/11/2005 Medium	Barbara Cardenas Manny Lozoya Key and Lock	Classroom	San Miguel ES 25, 49,50
1777	Work In Progress Need a lock installed in a filing cabinet in the Library.	5/10/2005 Medium	Barbara Cardenas Manny Lozoya Key and Lock		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11075	Work In Progress Need nameplates for the following: Mr. Padilla Mr. Gonzales Mrs. Gonzales Mrs. Boucher Ms. Barraza Mrs. Tovar Ms. Porter PE Coach Ms. Sanchez Mrs. Nuñez Mrs. Henderson Ms Avalos Ms. O'Neill Mrs. Jackson Mrs. Jaramillo-Granados Ms. Brand Ms. Mendoza Mrs. Rhodes Ms. Reyes Mr. Villalobos Mrs. Gurrola Mrs. Ruiz Ms. Rodriguez Mr. Vega	4/4/2006 Medium	Barbara Cardenas Manny Lozoya Key and Lock		San Miguel ES
11076	Work In Progress Need the following room numbers. #1, #2, #4, #5, #10, #12, #17, #19, #25, #26, #28, #34, #37, #42, #47, #49, #50, #51	4/4/2006 Medium	Barbara Cardenas Manny Lozoya Key and Lock		San Miguel ES
11594	Work In Progress broken handle on shower scrubbing machine thank you.	4/25/2006 Medium	Cervando Padilla Jimmy Carbajal Custodial Equipment Repair		San Miguel ES
1766	Work In Progress KEY JAMMED IN CORE/CORE WILL NOT TURN - OVER	5/10/2005 Medium	Danny Vega Manny Lozoya Key and Lock	Classroom	San Miguel ES PORTABLE#37
2103	Work In Progress need number (stick-on)plates for all class rm doors as per MRS DUNCAN (PRINCIPAL) 1 THRU 60	5/19/2005 Medium	Danny Vega Manny Lozoya Key and Lock		San Miguel ES
2118	Work In Progress REFG. AIR UNIT PORTABLE#33/IS NOT WORKING/USED FOR SUMMER SCHOOL /NEED HVAC -TECH	5/19/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
1820	Work In Progress need filetrs for units 12ea) 20x20x1 pleated 12ea)12x25x1 pleated 12ea)12x25x1 pleated -asap	5/11/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
1821	Work In Progress ramp not level- door hits bottom platform -need to lift with chains asap	5/11/2005 5/12/2005 Medium	Danny Vega Danny Vega Ramps/Platforms	Classroom	San Miguel ES #37
1826	Work In Progress NEED 14X30X1 PLEATED FILERS 8EA	5/11/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
1749	Work In Progress NEED TO REPLACE GUTTERS IN KITCHEN ROOF/NEED SCAFFOLDS/ D.MIRANDA NEED TO ORDERS GUTTERS.	5/9/2005 5/9/2005 Medium	Danny Vega Danny Miranda General Maintenance	Cafeteria	San Miguel ES
1881	Work In Progress NEED TOP PIVOT LACTH HINGE/RIGHT SIDE FOR METAL DOOR IN LIBRARY ASAP	5/12/2005 Medium	Danny Vega Manny Lozoya Key and Lock	Classroom	San Miguel ES LIBRARY
2686	Work In Progress need bob-cat sweeper to clean staff parking & re-stripe	6/10/2005 Medium	Danny Vega Lorenzo Hernandez Grounds		San Miguel ES
3834	Work In Progress A/C UNIT NOT WORKING IN HIGH SPEED PORTABLE#58	7/26/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
11320	Work In Progress rm #32 need additional unit on window as per MR.Marrufo -/6500master-cool is to small	4/12/2006 Medium	Danny Vega Lorenzo Solis Heating/Ventilation /Air Conditioning		San Miguel ES
10721	Work In Progress water leak in kitchen/dish washer drain/need gasket	3/27/2006 Medium	Danny Vega Danny Orozco Food Services		San Miguel ES
11686	Work In Progress need to replace basket strainer in copy rm sink/leaking all over/double sink type	4/27/2006 Medium	Danny Vega Joe Ontiveros Plumbing		San Miguel ES
11600	Work In Progress custodians are unable to secure east cafeteria exit door/core will not turn-over/master key jams in core.please repair asap	4/25/2006 Medium	Danny Vega Manny Lozoya Key and Lock		San Miguel ES
8847	Work In Progress need fertilizer spread on campus fields/front lawn 16-8-8	1/18/2006 Medium	Danny Vega Guadalupe Ontiveros Grounds	Athletic Field	San Miguel ES
8007	Work In Progress need one set gates wheels /west gate wheels damaged /asap(ruben ronquillo)	12/12/2005 Medium	Danny Vega Ruben Ronquillo Fence Repair		San Miguel ES
8082	Work In Progress library toilet will not flush/we need to replace it	12/13/2005 Medium	Danny Vega Joe Ontiveros Plumbing		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8676	Work In Progress east exit door/main bldg/having trouble securing /panic bar stuck	1/12/2006 Medium	Danny Vega Manny Lozoya Key and Lock		San Miguel ES
10432	Work In Progress need a 220v outlet in boiler rm/as per MR.MARRUFO/MR.CHAVEZ	3/10/2006 Medium	Danny Vega Enrique Sotelo Electrical		San Miguel ES
10433	Work In Progress NEED REPAIRS ON MARQUEE /PLEXY GLASS & FRAME DAMAGE BY WINDS/6FT X 6FT	3/10/2006 Medium	Danny Vega Ruben Ronquillo Glass\Window Repairs		San Miguel ES
12025	Work In Progress a/c ducting rotted-out fr previous water leaks/interior-exterior complains fr staff /it smells.rm#32	5/9/2006 Medium	Danny Vega Lorenzo Solis Heating/Ventilation /Air Conditioning		San Miguel ES
12141	Work In Progress rm39-door will not open/teacher&students cant get in.please open asap	5/12/2006 Medium	Danny Vega Manny Lozoya Key and Lock		San Miguel ES
12317	Work In Progress NEED TO BORROW BOX SCRAPER&TRACTOR TO CLEAN FENCE LINES OR SEND GRDS CREW	5/19/2006 Medium	Danny Vega Guadalupe Ontiveros Grounds		San Miguel ES
12225	Work In Progress Need 120v Ballast.	5/16/2006 Medium	Danny Vega Enrique Sotelo Electrical		San Miguel ES
5177	Work In Progress NEED FILTERS 12X24X1	9/2/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
6367	Work In Progress rm#32 day&night type furnance/pilot wont stay on-needs thermo-couple	10/13/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
7563	Work In Progress boys restroom heater coil leaks water/need replaced asap found leak and repaired it	11/28/2005 12/1/2005 Medium	Danny Vega Lorenzo Solis Heating/Ventilation /Air Conditioning		San Miguel ES
6785	Work In Progress boiler is not heating/please ck it out/class rooms are cold in the morning	10/26/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
6584	Work In Progress NEED LOCK-OUT DEVICE FOR DISCONNECT BOX/PORTABLE 28-29/POWER SHUT-OFF DAILY-ASAP	10/20/2005 Medium	Danny Vega Enrique Sotelo Electrical		San Miguel ES
6617	Work In Progress j.gomez/need to start and go thru check list on boiler unit/before 10-28-05 (.you can do it)	10/21/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
6618	Work In Progress need two loads playground sand asap	10/21/2005 Medium	Danny Vega Guadalupe Ontiveros Grounds		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
5270	Work In Progress NEED LDO 2QT/FLUSH VALVE KIT/DIAPRAHMS/TUB&SINK SEALER/ELONGATED TIOLET SEAT	9/6/2005 Medium	Danny Vega Joe Ontiveros Plumbing		San Miguel ES
5307	Work In Progress portable #28 refig unit not cooling/please check it out asap	9/7/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
4445	Work In Progress Portable 29 - Needs to be secured by the end of the day.	8/10/2005 Medium	Danny Vega Manny Lozoya Key and Lock	Portables	San Miguel ES
4447	Work In Progress principals office door hard to open/door needs to be shaved.stop by asap	8/10/2005 Medium	Danny Vega Manny Lozoya Key and Lock		San Miguel ES
4051	Work In Progress portable #30/rheem a/c unit not woking.stop by asap	8/1/2005 Medium	Danny Vega Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
717	Work In Progress Boiler Room - relief valve drain is not properly supported. As per Boiler Inspector.	3/30/2005 Medium	Michael Munoz Jaime Gomez Heating/Ventilation /Air Conditioning		San Miguel ES
8801	Work In Progress Lock is hard to open and lock on pump house. Please repare thank you.	1/17/2006 Medium	Ricardo Jacquez Manny Lozoya Key and Lock		San Miguel ES
5337	Work In Progress DISHWASHER LEAKING WATER. EVA MIRANDA - 233-2860	9/8/2005 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	San Miguel ES
12084	Work In Progress please cover and paint all vents on the north wall.	5/10/2006 Medium	Michael Munoz Danny Vega Painting	Cafeteria	San Miguel ES
214	Work In Progress Please replace nonlocking door knob with locking one. Mrs. Avalos portable#45.	3/9/2005 Medium	Lorenzo Solis Manny Lozoya Key and Lock		San Miguel ES
216	Work In Progress Replaced falling apart door knob with new one on entrace door in cafeteria.	3/9/2005 Medium	Lorenzo Solis Manny Lozoya Key and Lock		San Miguel ES
9005	Work In Progress Need a gate key for El Paso Disposal.	1/24/2006 Medium	Juliet Parra Manny Lozoya Key and Lock		Santa Teresa ES
11726	Work In Progress We need 3 additional keys made for our security box in the office. Key #CH751. Please ask for Gerry Marquez as he has the only key in the office. Thanks.	4/28/2006 Medium	Rita Mendez Manny Lozoya Key and Lock	Office	Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12036	Work In Progress EXTRACTOR DOES NOT WANT TO PICK UP WATER	5/9/2006 Medium	Pablo Diaz Jimmy Carbajal Custodial Equipment Repair		Santa Teresa ES
12188	Work In Progress NEED BACK PACK VAC FILTER BAGS AND ROTO BLOCK LONG BRISTLES	5/15/2006 Medium	Pablo Diaz Jimmy Carbajal Custodial		Santa Teresa ES
4152	Work In Progress ATTN MANNY. MANNY, WE STILL NEED FOR YOU TO MAKE US ANOTHER KEY TO THE MAIL BOX. THANKS.	8/3/2005 Medium	Gerardo Marquez Manny Lozoya Key and Lock		Santa Teresa ES
4154	Work In Progress ATTN LUPE, LUPE, WE STILL NEED THE COBBLESTONE TO KEEP CHECK THE RAIN ERROSION. ALSO NEED FOR BETO AND MANNY TO REDIG TRENCH AT BACK FENCE TO KEEP RAIN FROM FLOODING GROUNDS AND CLASS RMS. Remvoe sand along fence line and make trench deeper on westside of fence, cover pond with piles of sand tso people will not enter as per Gerry. Trench was redug, but need cobble stone for ponds.	8/3/2005 3/28/2006 Medium	Gerardo Marquez Robert Sanchez Grounds		Santa Teresa ES
454	Work In Progress ATT. CALI CASTILLO. CALI, NEED FOR YOU TO FOLLOW UP ON WK. OR. 124323. THANKS. NEED FOR YOU TO COME CHECK A COUPLE OF LIGHT FIXTURES THAT I AM HAVING TROUBLE WITH.	3/16/2005 Medium	Gerardo Marquez Carlos Castillo Electrical		Santa Teresa ES
2323	Work In Progress MIKE; I NEED FOR YOU TO GET ME A COPY OF THE PAINT SCHEDULE. THANKS.	5/26/2005 Medium	Gerardo Marquez Michael Munoz General Maintenance		Santa Teresa ES
3657	Work In Progress ATTN. Manny . NEED FOR YOU TO DUPLICATE A KEY TO THE MAIL BOX . THANKS .	7/19/2005 Medium	Gerardo Marquez Manny Lozoya Key and Lock		Santa Teresa ES
10485	Work In Progress need electrician to check out emergency lights that failed to come on during my last m. emerg. lighting insp..	3/14/2006 Medium	Gerardo Marquez Carlos Castillo Electrical		Santa Teresa ES
10527	Work In Progress MANNY; COULD YOU CHECK OUT THE LOCK TO THE WK RM. IN C-WING. A KID STUCK SOMETHING IN THE KEYHOLE, AND I AM UNABLE TO SECURE THE RM. THIS RM. HAS A COMPUTER, PRINTER, AND OTHER EQUIP. THAT I MUST SECURE.	3/15/2006 Medium	Gerardo Marquez Manny Lozoya Key and Lock		Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11131	Work In Progress MANNY, NEED FOR YOU TO COME AND CHECK OUT THE RR. DR. BETWEEN RMS. 102 AND 104,. DOOR LOCKED AND I DONT HAVE ACCESS TO UNLOCK IT. DOOR IS KEYED DIFFERENT THAN ALL THE REST.	4/6/2006 Medium	Gerardo Marquez Manny Lozoya Key and Lock		Santa Teresa ES
11050	Work In Progress AUTOMATIC OPENER AT WEST ENTRANCE IS NOT WORKING. NEED FOR CONTRACTOR TO CHECK THIS OUT ASAP. HANDICAP STUDENTS ARE UNABLE TO GAIN ENTRY TO BUILDING THROUGH THIS ENTRANCE.	4/3/2006 Medium	Gerardo Marquez Danny Miranda Doors and Hardware		Santa Teresa ES
10736	Work In Progress RUBEN, NEED 60-50 POUND BAGS OF 16-8-8 FERTILIZER.FOR PLAY AREA.	3/27/2006 Medium	Gerardo Marquez Ruben Ronquillo General Maintenance		Santa Teresa ES
11911	Work In Progress DAVID ; NEED THREE REPLACEMENT FAUCETS FOR LAVATORIES IN STUDENT R. ROOMS.	5/3/2006 Medium	Gerardo Marquez David Villalobos Plumbing		Santa Teresa ES
11912	Work In Progress CALI; NEED FOR YOU TO PLEASE ORDER BALSASTS AND BULBS FOR STE. THANKS.	5/3/2006 Medium	Gerardo Marquez Carlos Castillo Electrical		Santa Teresa ES
11913	Work In Progress LUPE; NEED FOR YOU TO SEND ME A COUPLE TRUCKLOADS OF SAND FOR P.G.AREAS. LEVELS ARE LOWER THAN THE 1' REQUIREMENTS. THANKS.	5/3/2006 Medium	Gerardo Marquez Guadalupe Ontiveros Grounds		Santa Teresa ES
11827	Work In Progress CALI, NEED FOR YOU TO ORDER ME BALLASTS AND BULBS BOR STE. ALSO NEED FOR YOU TO CHECK OUT EMERG. LIGHTS THAT FAILED ON LAST TEST.	5/1/2006 Medium	Gerardo Marquez Carlos Castillo Electrical		Santa Teresa ES
11828	Work In Progress NEED 3-COMPARTMENT SINK AT CAFET. PREP AREA CHECKED OUT. (STOPPER WILL NOT HOLD WATER)	5/1/2006 Medium	Gerardo Marquez Danny Orozco Food Services		Santa Teresa ES
12419	Work In Progress RUBEN; WOULD YOU ARRANGE FOR PAINT REP. TO MATCH PAINT IN THE CAFET. NEED 10 GALS. THANKS.	5/23/2006 Medium	Gerardo Marquez Ruben Ronquillo Painting		Santa Teresa ES
11593	Work In Progress Tilt Skillet is still out of order Patricia Sanchez - SNP Manager 589-3439	4/25/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Santa Teresa ES
12479	Work In Progress We need underground utility locates where the new portable will be placed by Tuesday May 30. (Portable Pier Locations)	5/24/2006 Medium	Alfredo Holguin David Villalobos Plumbing	Portables	Santa Teresa ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12480	Work In Progress We need underground utility locates where the new portable will be placed by Tuesday May 30. (Portable Pier Locations)	5/24/2006 Medium	Alfredo Holguin Carlos Castillo Electrical	Portables	Santa Teresa ES
11741	Work In Progress Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Gerardo Marquez Fire Extinguishers		Santa Teresa ES
11792	Work In Progress Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Gerardo Marquez General Maintenance		Santa Teresa ES
11804	Work In Progress Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Gerardo Marquez General Maintenance		Santa Teresa ES
10944	Work In Progress Monthly - Santa Teresa ES Roof Inspection - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Gerardo Marquez Roof		Santa Teresa ES
10974	Work In Progress Monthly - Santa Teresa ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Santa Teresa ES
10975	Work In Progress Monthly - Santa Teresa HS Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Santa Teresa HS
3158	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
3176	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Arturo Nunez Roof		Santa Teresa HS
3329	Work In Progress Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez Fire Protection		Santa Teresa HS
3351	Work In Progress Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Arturo Nunez Fire Protection		Santa Teresa HS
7071	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
6107	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
6118	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6018	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
6036	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Arturo Nunez Roof		Santa Teresa HS
9785	Work In Progress NEED 12 EA. 2X4 277V. LAY IN LIGHTS WITH EMERGENCY BALAST. FOR 300 WING ROOMS, AND HALLWAYS.	2/16/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
9787	Work In Progress NEED 14 EA. OUSIDE SECURITY LIGHT FIXTURES TO REPLACE EXISTING ORIGINAL FIXTURES ON MAIN BUILDING, AND ANNEX. WILL ASISSIT ELECTRICAN ON REPLACING FIXTURES.	2/16/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
9623	Work In Progress DOOR KNOB IN COUSELORS OFFICE, SOUTH SIDE DOOR,CLINDER IS BROKEN THEY CAN'T OPEN DOOR WITH THEIR KEY. WOULD LIKE TO HAVE LOCKSMITH HELP US WITH THIS SITUATION. REPAIR CYLINDER AT COUNSELORS OFFICE	2/13/2006 1/16/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
10132	Work In Progress NEED EMERGENCY PUSH BUTTONS FOR SHOP AREAS, THE ONE ON THERE, ARE BROKEN, OTHERS DON'T WORK. SAFETY ISSUE. SIX (6) EA.	3/2/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
10371	Work In Progress NEED THE CYLINDERS AT REMOLED SECTION OF SCHOOL, EXTERIOR DOORS INSTALLED AS SOON AS POSSIBLE. FOR SECURITY PURPOSE.	3/8/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
10415	Work In Progress NEED TO REPLACE FOUR (4) FLO. LIGHT BULB FIXTURES ON CAGE STORAGE HALLWAY.	3/10/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
8757	Work In Progress NEED TO HAVE OLD BAND ROOM FUMIGATED, AND MOUSE TRAP INSTALLED, MICE HAVE BEEN SIGHTED, DUE TO FOOD NOT PROPERLY STORED. A.S.AP. THANK YOU....	1/13/2006 Medium	Arturo Nunez Margret Villalobos Pest Control		Santa Teresa HS
8410	Work In Progress NEED DOOR WINDOW REPLACED ON ROOM #304 6 3/4X24 1/2 1/4" WIRE SAFETY GLASS. WILL NEED PRICE TO PUT ON VANDALISM REPORT. THANK YOU.....	1/4/2006 Medium	Arturo Nunez Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS
7840	Work In Progress NEED FIVE (5) LOCKS 6" SLIDE LOCKING HASP	12/5/2005 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8571	Work In Progress NEED TO BORROW SCISSOR LIFT TO PUT UP BANNERS ON GYM RAFTERS. AND PUT UP SOME ACUSTIC PANELS THAT FELL . AND CHECK THEM ALL, FOR SAFETY PURPOSES.	1/9/2006 Medium	Arturo Nunez Ruben Ronquillo Equipment		Santa Teresa HS
10635	Work In Progress NEED 70 WATTS METAL HALIDE BULBS # M143/E TWELVE (12) EA. FOR NEW ADDITION, OUTSIDE LIGHTS.	3/17/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
10646	Work In Progress NEED THE LOCK AT CAGE STORAGE , CHANGED TO DIFFRENT KEY, SO ONLY TRACK COACH, CAN HAVE ACESS TO EQUIPMENT, HE IS MISSING SOME STUFF.	3/17/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
10780	Work In Progress NEED CALI TO COME AND SEE WHAT NEEDS TO BE DONE FOR WASHER AND DRIER HOOK UP AT TRAINERS OFFICE. APPLIANCES ARE ON ORDER AS PER TRAINER.	3/28/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
10781	Work In Progress NEED SIX (6) EA. 50A 125/250 PLUGS FOR WELDING SHOP, WOULD LIKE TO USE ONE TYPE OF PLUG FOR OUTLETS SO THAT WELDING MACHINES CAN BE USED ANY WHERE IN THE ROOM.	3/28/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
11091	Work In Progress NEED SOME LIGHTS INSTALLED ON EXHAUST FAN HOOD THAT WAS INSTALLED ON WELDING SHOP. TO DARK UNDER HOOD.	4/4/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
11105	Work In Progress URGENTE; A/C IS LEACKING WATER PAN IS VERY RUSTING WE CAN'T USED NO MORE WE NEED REPLACE IT AT MS.CHAVES' OFFICE	4/5/2006 Medium	Arturo Nunez Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa HS
11184	Work In Progress NEED A 115V. HAND DRIER FOR VOCATIONAL BOYS RESTROOM.	4/7/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
11185	Work In Progress DOOR KNOB HANDLE ON CUSTODIAL CLOSET AT VOC. BLDG. NEEDS TO BE REPLACED. (BROKEN)	4/7/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
11192	Work In Progress LOCK ON OLD CONESSION ON MAIN BUILDING NEEDS TO BE CHECKED, CUSTODIANS HAVING TROUBLE WITH LOCK.	4/7/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
11201	Work In Progress NEED SIX (6) EA. SENSORS FOR LABATORIES AT DRESSING ROOMS.	4/7/2006 Medium	Arturo Nunez David Villalobos Plumbing		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11239	Work In Progress NEED TWO (2) EA. 115V. TO 24V. TRANSFORMERS TO SUPPLY POWER TO SENSOR AT GIRLS LABATORIES, THE EXISTING ONE IS SHOT, NO WATER.	4/10/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
11916	Work In Progress NEED TO CHANGELock TO M115 OFF MASTER SAME KEY AS STORAGE ROOM IN MAIN LOBBY.	5/3/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
1998	Work In Progress 03/23/05 3/23 8.0 - CONT. PAINTING DRESSING ROOM	5/17/2005 Medium	Arturo Nunez Arturo Nunez General Maintenance		Santa Teresa HS
695	Work In Progress NEED TILE INSTALLED AT TRAINERS WRAPPING AREA, REQUESTED BY MR. MUNOZ,FRANK.	3/30/2005 Medium	Arturo Nunez Michael Munoz Carpet Repair		Santa Teresa HS
1011	Work In Progress NEED CYLINDER AT DRESSING ROOM HALLWAY CHECKED SOME ONE STUCK SOMETHING IN IT, CAN"T OPEN IT ,AFRAID SOMEONE WILL BREAK KEY.	4/11/2005 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
3571	Work In Progress NEED CONDENSER MTR. FOR SNACK ROOM A.C. UNIT, MTR. IS FROZEN UNIT IS DOWN.	7/15/2005 Medium	Arturo Nunez Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa HS
7815	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
7108	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
7119	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
7767	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
7804	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
5214	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
11805	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11794	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
11757	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
10217	Work In Progress Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Santa Teresa HS
8403	Work In Progress Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
8324	Work In Progress Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Arturo Nunez Roof		Santa Teresa HS
8392	Work In Progress Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joel Herrera General Maintenance		Santa Teresa HS
4484	Work In Progress please install venting system and exhaust hood in the metal shop. See Joe Angelo.	8/11/2005 Medium	Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa HS
10716	Work In Progress Soccer Field & Football Field - Need to install sprigs on fields.	3/27/2006 Medium	Guadalupe Ontiveros Grounds	Athletic Field	Santa Teresa HS
8306	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
9999	Work In Progress please repair the wood that is breaking off the dugouts. Thanks	2/24/2006 Medium	Guadalupe Ontiveros Grounds	Athletic Field	Santa Teresa HS
12248	Work In Progress NEED ONE CASE OF MULTI VOLTAGE LIGHT BALAST , TWO, THREE, AND FOUR BULBS. TEN (10) T-8 LIGHT BULBS.	5/16/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
12249	Work In Progress NEED TO FUMIGATE DAYCARE, BUGS SEEM TO BE A PROBLEM ON PLAY ROOM, KITCHEN, AND BABY ROOM.	5/16/2006 Medium	Arturo Nunez Margret Villalobos Pest Control		Santa Teresa HS
12250	Work In Progress NEED DEAD BOLT INSTALLED ON DOORS ON D.O.L. PORTABLE , KEYED THE SAME AS THE EXISTING ONE.	5/16/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12011	Work In Progress BLEACHERS NEED TO BE CLEANED. PLEASE NOTIFY AIDA WHEN PROCEDURE IS COMPLETED SO AN INSPECTION CAN BE DONE.	5/8/2006 Medium	Aida Salcedo Luis Murillo Custodial		Santa Teresa HS
10724	Work In Progress NEED TO DO TRAINING ON CLEANING RESTROOMS, USING CHEMICALS & EQUIPMENT AND TIME MANAGEMENT FOR: JAVIER PARRA, RAFAEL MERA, MARIA DE SANTIAGO & OSCAR ESPARZA	3/27/2006 Medium	Aida Salcedo Guillermo Hernandez Custodial		Santa Teresa HS
10730	Work In Progress NEED TO TRAIN: JAVIER PARRA, RAFAEL MERA, MARIA DE SANTIAGO & OSCAR ESPARZA ON USING ROTO & BURNISHER MACHINES	3/27/2006 Medium	Aida Salcedo Sal Acuna Custodial		Santa Teresa HS
11461	Work In Progress LUIS- NEED TO ISSUE AND SPREAD OUT ALL EQUIPMENT THAT HAD BEEN ISSUED TO YOU (EX. LADDERS, EXTENSION CORDS, DOLLIES, ECT). SEPARATE THRU OUT ALL AREAS OF CUSTODIAL CLOSETS FOR EASY ACCESS TO THEM.	4/20/2006 Medium	Aida Salcedo Luis Murillo Custodial		Santa Teresa HS
7194	Work In Progress ADULT RESTROOM IN OFFICE AREA NEEDS TO BE PAINTED.	11/8/2005 Medium	Aida Salcedo Arturo Nunez General Maintenance		Santa Teresa HS
11866	Work In Progress NEED TO SHOWER SCRUB FLOORS AND 2 COAT WAX (1 QUARDANT PER DAY) ON MON,TUE,WED & THUR. (MAY 15-MAY 18,2006)	5/2/2006 Medium	Aida Salcedo Luis Murillo Custodial		Santa Teresa HS
12136	Work In Progress please talk to Calixto about the power in the IDF room	5/11/2006 Medium	Cora Ramirez Carlos Castillo Electrical	Electrical Room	Santa Teresa HS
11493	Work In Progress Need a set of Keys for STHS for Lynco, thanks, Carlos	4/21/2006 Medium	Carlos Vigil Manny Lozoya Key and Lock		Santa Teresa HS
1387	Work In Progress need to repair sheetrock in gym locker room	4/25/2005 Medium	Danny Miranda Danny Miranda General Maintenance	Auditorium	Santa Teresa HS
11961	Work In Progress need to redo floor in rotc restroom boys s. t. h.s.	5/5/2006 Medium	Danny Miranda Danny Miranda General Maintenance		Santa Teresa HS
12241	Work In Progress JD 935 MOWER PTO NOT WORKING.	5/16/2006 Medium	Guadalupe Ontiveros Bobby Aldaz Grounds		Santa Teresa HS
11213	Work In Progress NEED TO DO A CHEMICAL TRAINING FOR OSCAR ESPARZA @ STH	4/7/2006 Medium	Maria Sitters Aida Salcedo Custodial		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
923	Work In Progress WE NEED CHECK AND REPAIR DOOR LOCK NO WELDING CLASS ROOM AT V.O.C BUILDING	4/7/2005 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
5923	Work In Progress MIKE MUNOZ WE NEED BARRIER FENCE ON WEST SIDE AT SOCCER FIELD TO RETAIN BALLS OUT IT PLAY . ALSO NEED FENCE FROM 20 YARD LINE TO 20 YARD LINE IN FRONT OF FOOTBALL VISITORS SEATING AREA. SEE R GALLEGOS THANK YOU MIKE...	9/28/2005 Medium	Joel Herrera Michael Munoz Fence Repair		Santa Teresa HS
4454	Work In Progress SMASHED WINDOW ON DOOR - STOLEN LARGE SCREEN TV. DISCOVERED BY MR. BUCKLEY	8/1/2005 Medium	Joel Herrera Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS
4463	Work In Progress SENER ON SINCK AT GIRLS REST ROOM IT DOESN'T WORK WE REPLACE IT .	8/11/2005 Medium	Joel Herrera David Villalobos Plumbing		Santa Teresa HS
4966	Work In Progress RUBEN WE NEED REPAIR THE WINDOWS AT DAYCAREBUILDING IT DOESN'T OPEN THANK YOU Route to Joel as per Mike 9/12/05 - mkv	8/26/2005 Medium	Joel Herrera Joel Herrera General Maintenance		Santa Teresa HS
5102	Work In Progress WE NEED REPLACE MA 51 AND TREE LOCKS AT R.O.T.C CLASS ROOMS.	8/30/2005 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
4807	Work In Progress MANNY MY MASTER KEY IS BROKEN IT DOESN'T WORK NO MORE.	8/23/2005 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
9411	Work In Progress DOOR FROM MAINT ENTRANCE IT DOESN'T LOCKE MANNY WE NEED FIX IT.	2/6/2006 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
9679	Work In Progress NEW CAFETERIA BOTH DRESSING ROOMS. 1.KEY FOR MAIN DOOR TO DRESSING ROOM BOTH BOYS AND GIRLS. 2 KEY FOR CLOSET DOOR BOTH BOYS AND GIRLS. 3 ADULT BATHROOMS NEED TO BE RE-CORE THE LOCKS 4.KEY FOR BATHROOMS IN BOTH DRESSING ROOMS 5.MD-12 AND MD-2 KEYS NEED FOR MR. ANGELO AND MR. JEWETT. 6. LOCK FOR MS. FRANCIS SOCCER CABINET BY G.Y.M AREA.	2/14/2006 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
10537	Work In Progress NEED EIGHT (8) FLO. LIGHT BULBS FOR MARQUEE, IT IS NOT LIGHTING, WOULD LIKE TO HAVE IT LIT.	3/15/2006 Medium	Joel Herrera Carlos Castillo Electrical		Santa Teresa HS
10100	Work In Progress BROKEN SYLINDER SOMETHING INSIDE WE TO REPLACED AT CLASS ROOM 15	3/1/2006 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8157	Work In Progress MR. GALLEGOS WANTS DEADBOLT ON BOYS AND GIRLS DRESSING ROOMS 2- NEED TO CHANGE DOOR KNOBS TO BE ABLE TO LOCK THE WORK ROOM BETWEEN THE BAND AND CHORUS ROOM 3- AND NEED TO CHANGE ONE ENTRY KEY TO THE RESTROOMS FROM THE MEETINS ROOM. 12/15 - 5	12/15/2005 12/15/2005 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
9143	Work In Progress 1-27-06 2.0 RE-MOVE FLAIRS AT G.Y.M AREA. 1.0 CHECK HEATINGS UNITS 1.0 REPLACE ELECTRICAL SWITCH AT G.Y.M AREA 2.0 CHECK ELECTRICAL PROBLEM AT KITCHEN 2.0 CHECK AND REPAIR DOOR LOCK AT COACHES ROOM AT SOFBALL FIELD AREA. 1/27 - 8	1/30/2006 Medium	Joel Herrera Joel Herrera General Maintenance		Santa Teresa HS
11939	Work In Progress CABINET 'S DOOR IT DOESN'T HAVE LOCK WE NEED PUT LOCK ON CLASS ROOM 203 AT THE NEW WING .	5/4/2006 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
11969	Work In Progress BROKEN DOOR'S GLASS AT PATIO'S DOOR AT ENGLISH WING AREA. SIZE 23 1/4 X 34 3/4 INCHES WIRE GLASS.	5/5/2006 Medium	Joel Herrera Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS
11639	Work In Progress WE NEED REPLACE STOP VALBULAS AT BOYS REST ROOM AT MATH WING AREA.	4/26/2006 Medium	Joel Herrera David Villalobos Plumbing		Santa Teresa HS
11588	Work In Progress NEED SIX (6) EA. TOGGLE THREE WAY SWITHES TO REPLACED DAMAGED ONES ON GYM.	4/25/2006 Medium	Joel Herrera Carlos Castillo Electrical		Santa Teresa HS
11264	Work In Progress NEED MR. CASTILLO TO ASSIST ME ON ELEC. PROBLEM ON GYM. A.C. NOT GETTING POWER TO MOTOR, ALREADY TROUBLE SHOOT, CAN'T SEEM TO FIND THE PROBLEM.	4/11/2006 Medium	Joel Herrera Carlos Castillo Electrical		Santa Teresa HS
12524	Work In Progress BRENDA SMITH SHE NEED TO RE-KEY TO OFF MASTER INSIDE AND OUTSIDE DOOR TO LARGE SCENE ROOM AND ALSO PROTECTINE METAL PLATE FOR INSIDE DOOR TO DOOR	5/26/2006 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
12121	Work In Progress RUBEN WE NEED THE SEASON LIFT FROM THIS DATE 5-30-06 FOR USE INTO THE G.Y.M AND PAINTING.	5/11/2006 Medium	Joel Herrera Ruben Ronquillo Equipment		Santa Teresa HS
348	Work In Progress BOTH MIORRORS FROM BOYS BATH ROOM ARE FADED THEY NEED TO BE REPLACE IN THE ENGLISH WING THANK YOU.	3/14/2005 Medium	Luis Murillo Ruben Ronquillo General Maintenance		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12415	Work In Progress please paint gym as per Mr.Gallegos	5/23/2006 Medium	Michael Munoz Arturo Nunez Painting	Gym	Santa Teresa HS
5113	Work In Progress AIR CONDITIONER DOES NOT TURN ON THE LEFT SIDE OF THE ROOM FACING CHALK BOARD ROOM 3 MR. DORANTES	8/31/2005 Medium	Laura Parra Jose Ambriz Heating/Ventilation /Air Conditioning	Classroom	Santa Teresa MS
8556	Work In Progress Kitchen #1- Sink is clogged unable to use Kitchen #4- Pipes under sink leak	1/9/2006 Medium	Laura Parra David Villalobos Plumbing	Classroom	Santa Teresa MS room 10
2161	Work In Progress duplicate keys for new portables	5/20/2005 Medium	Jose Hinojosa Manny Lozoya Key and Lock	Portables	Santa Teresa MS
2204	Work In Progress 5 copies of cabinet key for North building kitchen cabinets	5/23/2005 Medium	Jose Hinojosa Manny Lozoya Key and Lock	Restroom (Boys)	Santa Teresa MS
2059	Work In Progress HINGES NEED TO BE REPLACED...DOOR NOT CLOSING IN UPPER LEVEL GIRLS BATHROOM	5/18/2005 Medium	Jose Hinojosa Danny Miranda Doors and Hardware	Restroom (Girls)	Santa Teresa MS
12112	Work In Progress N.bldg and S.bldg restrooms. Most of the plumbing is old and leaking. Please order 10 ea. single water regulating sink faucets, 6 ea. 4" in. water regulating sink faucets, 10 ea. 1 1/2" sink traps, 5ea. flush valve repair kits, 5 ea. handle kit, 5 ea. vaccume breaker kits, 2 ea. 1 1/2" or 2" plugs to plug drains where I removed office water fountains.	5/11/2006 Medium	Jaime Mijarez David Villalobos Plumbing		Santa Teresa MS
12514	Work In Progress North and South bldg office copy rooms. Build a wall covered with sheetrock,taped,plastered and painted to seal up sliding door openings. These sliding doors are old and not being used anymore. This will provide more privacy to two of the offices. There is two entrances to the copy rooms and we only need one.	5/25/2006 Medium	Jaime Mijarez Michael Munoz General Maintenance		Santa Teresa MS
12515	Work In Progress South bldg speech office door. Please install lock on door inside of office to lock when session is in progress.	5/25/2006 Medium	Jaime Mijarez Manny Lozoya Key and Lock		Santa Teresa MS
12517	Work In Progress North and South bldg round room benches. Tare down from wall to make more space for chairs and tables.	5/25/2006 Medium	Jaime Mijarez Michael Munoz General Maintenance		Santa Teresa MS
11380	Work In Progress S.bldg. There is a broken glass on the second level door that exits from the ramp. Ruben please send the glass company,I already patched it up.	4/18/2006 Medium	Jaime Mijarez Ruben Ronquillo Glass/Window Repairs		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11107	Work In Progress S.bldg office. Joe I need your help on the heat pump. The heat pump leaked out the refrigerant.	4/5/2006 Medium	Jaime Mijarez Jose Ambriz	Heating/Ventilation /Air Conditioning	Santa Teresa MS
11906	Work In Progress Mr. Hinojos portable rm. Please install a dead bolt lock to secure entrance door.	5/3/2006 Medium	Jaime Mijarez Manny Lozoya	Key and Lock	Santa Teresa MS
11907	Work In Progress N.bldg electrical room need break wall penetrations and install ducts to supply cooling only from home ec. room.	5/3/2006 Medium	Jaime Mijarez Jose Ambriz	Heating/Ventilation /Air Conditioning	Santa Teresa MS
11908	Work In Progress Building lighting. PLease order 20 boxes of flourescent light bulbs, and 10 ea. 277v. ballasts. Attn: Carlos Castillo.	5/3/2006 Medium	Jaime Mijarez Carlos Castillo	Electrical	Santa Teresa MS
8159	Work In Progress Markee Sign. As per Mrs. Williams she would like to have the sign installed during winter break.	12/15/2005 Medium	Jaime Mijarez Carlos Castillo	Electrical	Santa Teresa MS
8161	Work In Progress Principals office. Need a window installed on interior door.	12/15/2005 Medium	Jaime Mijarez Danny Miranda	Doors and Hardware	Santa Teresa MS
10425	Work In Progress N.bldg lower level HP 32 is on hi/lo pressure failure. I found leak and sealed it. I need Joe A. to charge the the unit with R22 refrigerant.	3/10/2006 Medium	Jaime Mijarez Jose Ambriz	Heating/Ventilation /Air Conditioning	Santa Teresa MS
9910	Work In Progress Campus. Can you help us with a tracter to move all the sand that has accumulated by the walk ways and stairways to the gym. Requested by Mr. Mora.	2/22/2006 Medium	Jaime Mijarez Guadalupe Ontiveros	Grounds	Santa Teresa MS
5363	Work In Progress N.bldg maintenance and custodial. Would like a duct and register installed on heat pump.	9/9/2005 Medium	Jaime Mijarez Jose Ambriz	Heating/Ventilation /Air Conditioning	Santa Teresa MS
5149	Work In Progress N.bldg Rm 3. Mrs. williams would like to have a sidewalk that goes from Rm 3 exit door out to the fence. This way when there is a fire drill the special ed students on wheel chairs can be moved away from the building in case of an actual emergency.	9/1/2005 Medium	Jaime Mijarez Michael Munoz	Concrete	Santa Teresa MS
3387	Work In Progress Rm 1. N. bldg lower level Removal of carpet is going to require tile installation. Alfredo H. requested a work order for contractor.	7/7/2005 Medium	Jaime Mijarez Michael Munoz	Carpet Repair	Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3412	Work In Progress S.bldg upper level. Because of the shortage of classrooms Mrs. Williams has to move the teachers lounge to a storage rm. The floor has no tile, can you include this room with the area's that the contractor will be installing floor tile. Attn: Alfredo Holguin.	7/8/2005 Medium	Jaime Mijarez Michael Munoz Carpet Repair		Santa Teresa MS
3465	Work In Progress N.bldg home ec rm 10. Ruben Ronquillo I am going to need a Miter saw to cut legs on ten of the tables. please make sure it has a good blade. I am planning this project for next week (7/18/05.) The wood is oak.	7/12/2005 Medium	Jaime Mijarez Ruben Ronquillo General Maintenance		Santa Teresa MS
2957	Work In Progress N. Bldg upper level. Need Price Quote to correct communication problem on hps 17 thru 22, and 25. They go on failure and restore every few minutes. Waiting on Vendor (ok) by Purchasing Agent. 10/05/05-Will route to Alpine Electric 3/31/06 -Pending Price Quote from Joe Valenzuela - mkv 4/7/06 - Job will be completed during the Summer Break 5/9/06 - Jaime, Jose when do you think we should schedule this?	6/23/2005 Medium	Jaime Mijarez Margret Villalobos Energy Management System		Santa Teresa MS
3364	Work In Progress S.bldg custodial storage. please make 2ea. A-7 keys for principal and building mechanic.	7/6/2005 Medium	Jaime Mijarez Manny Lozoya Key and Lock		Santa Teresa MS
2597	Work In Progress N.bldg. Handicap ramp side walk was repaired without expansion joint. Concrete slab cracked and needs to be repaired again. Heavy traffic area.	6/7/2005 Medium	Jaime Mijarez Michael Munoz Concrete		Santa Teresa MS
1884	Work In Progress S.bldg rm36. Need to have a safety window with safety glass installed. Rm will be used for a special ed student. Requested by Ms Williams.	5/12/2005 Medium	Jaime Mijarez Danny Miranda Doors and Hardware	Classroom	Santa Teresa MS
11592	Work In Progress Please get a quote from acucore for penetration of wall in electrical room. Thanks contact person J.Mijarez	4/25/2006 Medium	Michael Munoz Danny Miranda General Maintenance	Classroom	Santa Teresa MS
11418	Work In Progress North office area need to replace carpet.	4/19/2006 Medium	Michael Munoz Michael Munoz Carpet Repair	Office	Santa Teresa MS
12086	Work In Progress JIMMY I NEED FOR YOU TO FIX A WHEELBARROW AND A DOLLEY LOCATED IN THE SOUTH BUILDING.THANK YOU	5/10/2006 Medium	Ismael Rodriguez Jimmy Carbajal Custodial Equipment Repair	Custodial	Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9575	Work In Progress MR. SORIA PRUNE OUR CAMPUS TREES .THANK YOU.	2/10/2006 Medium	Ismael Rodriguez Mike Soria Grounds	Parking Lot	Santa Teresa MS
11642	Work In Progress MR.ONTEVERO WE NEED TO FILL OUT WITH SOME CRUSHER FINE ALONG THE SIDEWALK GOING TO THE PORTABLES THE SIDEWALK IS HIGH FROM THE GROUND.SEE MR. RODRIGUEZ.AS PER MS. WILLIAMS.THANK YOU.	4/26/2006 Medium	Ismael Rodriguez Guadalupe Ontiveros Grounds	Library	Santa Teresa MS
10791	Work In Progress MR.LOZOYA YOU CAN ALREADY CHANGE THE CYLINDERS FROM NORTH AND SOUTH BUILDINGS.CHECK WITH MR. RODRIGUEZ.THANK YOU.	3/29/2006 Medium	Ismael Rodriguez Manny Lozoya Key and Lock	Office	Santa Teresa MS
5308	Work In Progress I NEED A KEY A7 FOR THE PRINCIPAL TO HAVE ACCESS TO MY STORAGE ROOM. THANK YOU.SEE MR. RODRIGUEZ.	9/7/2005 Medium	Ismael Rodriguez Manny Lozoya Key and Lock	Custodial	Santa Teresa MS
2828	Work In Progress NEED TO REMOVE WEEDS ON OUR CAMPUS AREA AS PER. MISS WILLIAMS . NORTH AND SOUTH BUILDING AND GYM AREA.THANK YOU.	6/16/2005 Medium	Ismael Rodriguez Mike Soria Grounds		Santa Teresa MS
3118	Work In Progress I NEED FOR GYM KEY CYLINDERS TOO TO BE CHANGE BEFORE 7/13/05.CONT.MR.RODRIGUEZ.	7/1/2005 Medium	Ismael Rodriguez Manny Lozoya Key and Lock		Santa Teresa MS
1103	Work In Progress ATTN;RUBEN RONQUILLO. I NEED A TRAILER TOO TRANSPORT ART WORK FOR MR. SANCHEZ TO THE G.M.S 4/14/05. THANK YOU.	4/13/2005 Medium	Ismael Rodriguez Ruben Ronquillo General Maintenance		Santa Teresa MS
12244	Work In Progress NEED TO FIX GEARS ON GATOR NOT WORKING.	5/16/2006 Medium	Guadalupe Ontiveros Bobby Aldaz Grounds		Santa Teresa MS
9776	Work In Progress s.t.m.s. need to paint new doors in front of gym	2/16/2006 Medium	Danny Miranda Jaime Mijarez Painting		Santa Teresa MS
9777	Work In Progress s.t.m.s. need to paint new door at music room	2/16/2006 Medium	Danny Miranda Jaime Mijarez Painting		Santa Teresa MS
2728	Work In Progress need to replace doors @ 10x56 window kit	6/13/2005 Medium	Danny Miranda Danny Miranda Doors and Hardware		Santa Teresa MS
11286	Work In Progress NEW reach in at 32 - 37 degrees Paula Sanchez - SNP Manager 589-9836	4/11/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Santa Teresa MS
11035	Work In Progress Pipe fell off to dishwasher Paula Sanchez - 589-9836	4/3/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12076	Work In Progress BLEACHERS NEED TO BE CLEANED DURING GYM FINISHING. PLEASE NOTIFY AIDA KNOW WHEN THIS TASK IS COMPLETED SO INSPECTION CAN BE DONE.	5/10/2006 Medium	Aida Salcedo Ismael Rodriguez Custodial		Santa Teresa MS
6218	Work In Progress DUE TO WATER OVER FLOW, GYM FLOOR HAS BUBBLED BY FLOODING. NEED VENDOR TO DO A RECOMMENDATION AND QUOTE US.	10/10/2005 Medium	Aida Salcedo Michael Munoz Carpet Repair		Santa Teresa MS
6437	Work In Progress please replace h20 fountain and unclog drain.	10/14/2005 Medium	David Villalobos Plumbing	Office	Santa Teresa MS
11758	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Jaime Mijarez Fire Extinguishers		Santa Teresa MS
11796	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Jaime Mijarez General Maintenance		Santa Teresa MS
11806	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Jaime Mijarez General Maintenance		Santa Teresa MS
4023	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez General Maintenance		Santa Teresa MS
4013	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez General Maintenance		Santa Teresa MS
3975	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Jaime Mijarez Fire Extinguishers		Santa Teresa MS
3353	Work In Progress Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez Fire Protection		Santa Teresa MS
3330	Work In Progress Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez Fire Protection		Santa Teresa MS
10976	Work In Progress Monthly - Santa Teresa MS Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Santa Teresa MS
10943	Work In Progress Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Jaime Mijarez Roof		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3423	Work In Progress Yearly - Sunland Park ES Emer. Light Test: Annual - Refer to PM schedule details.	7/10/2005 Medium	Alfredo Holguin Sebastian Diaz Fire Protection		Sunland Park ES
10977	Work In Progress Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Sunland Park ES
3355	Work In Progress Yearly - Sunland Park ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Sebastian Diaz Fire Protection		Sunland Park ES
3179	Work In Progress Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz Roof		Sunland Park ES
3268	Work In Progress Monthly - Sunland Park ES Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz General Maintenance		Sunland Park ES
3278	Work In Progress Monthly - Sunland Park ES Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz General Maintenance		Sunland Park ES
3160	Work In Progress Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Sebastian Diaz Fire Extinguishers		Sunland Park ES
2953	Work In Progress Please remove sand along fence line by houses. Also scrape playing area.	6/23/2005 Medium	Robert Sanchez Grounds		Sunland Park ES
11428	Work In Progress fan is out of order Marina Ramirez - SNP Manager 589-2545	4/19/2006 Medium	Alma Terrell Danny Orozco Food Services	Choral	Sunland Park ES
9120	Work In Progress 1.3 compartment sink is leaking 2. right side of serving line (cold unit) is not working. and 3. Blodgett Oven is still not heating properly Marina Ramirez - SNP Manager 589-2545	1/27/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Sunland Park ES
11979	Work In Progress 40 quart mixer is rotating too slow, had to go to Desert View Elementary to grate cheese Marina Ramirez - SNP Manager 589-2545	5/5/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Sunland Park ES
11938	Work In Progress Need to rent selfdrive lift to remove netting	5/4/2006 Medium	Carlos Castillo Carlos Castillo Electrical	Parking Lot	Sunland Park ES
9214	Work In Progress need borders for playground S.P.E.	2/1/2006 Medium	Danny Miranda Sebastian Diaz General Maintenance		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
2321	Work In Progress THE GRASS SHOULD BE REPLACED ON THE CIRCLE ENTERING THE SCHOOL GROUNDS. WE NEED THE AREA SMOOTHED AND SOD PLACED. REQUESTED AS PER MS. LINDA PEREZ, ASST. PRINCIPAL.	5/26/2005 Medium	Irene Trujillo Lorenzo Hernandez Grounds		Sunland Park ES GROUNDS
3875	Work In Progress NEED REPLACEMENT KEYS FOR NURSE'S OFFICE DORR AND FILE CABINET	7/27/2005 Medium	Irene Trujillo Manny Lozoya Key and Lock		Sunland Park ES
7522	Work In Progress A kitchen sink is needed in room 52. The new teacher's lounge.	11/22/2005 Medium	Irene Trujillo David Villalobos Plumbing		Sunland Park ES
7523	Work In Progress Please remove carpet in room #52 and install floor tile.	11/22/2005 Medium	Irene Trujillo Michael Munoz Carpet Repair		Sunland Park ES
7041	Work In Progress A door opening is needed from lounge to existing bathroom in nurse's office. Please send someone to check wiring. 1/25 - Faxed to Mr. Chavez for approval - mkv	11/4/2005 Medium	Irene Trujillo Carlos Castillo Electrical		Sunland Park ES
6878	Work In Progress ADD NEW ELECTRICAL OUTLET TO TEACHER'S LOUNGE.	10/31/2005 Medium	Irene Trujillo Carlos Castillo Electrical		Sunland Park ES
9270	Work In Progress TA17 AND TA31 - PLEASE ADJUST SO THAT THE KEYS OPEN SIDE DOORS.	2/2/2006 Medium	Irene Trujillo Manny Lozoya Key and Lock		Sunland Park ES
9985	Work In Progress PORTABLE A & B NEED THE FLOOR TILE TO BE REPLACED.	2/24/2006 Medium	Irene Trujillo Michael Munoz Carpet Repair		Sunland Park ES
10102	Work In Progress PLEASE SPRAY CLASSROOM #21 AND OFFICE AREA FOR LICE.	3/1/2006 Medium	Irene Trujillo Margret Villalobos Pest Control		Sunland Park ES
10373	Work In Progress 2 classroom keys need to be re-keyed so these can open the hall doors from the outside. TA25 AND TA63	3/8/2006 Medium	Irene Trujillo Manny Lozoya Key and Lock		Sunland Park ES
6625	Work In Progress Need Heavy Duty Dolly for fire proof file cabinet on Monday October 24, 2005	10/21/2005 Medium	Larry Flores Maria Sitters Custodial		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12032	Work In Progress Jimmy, I need the following: 1. Cordless Drill 2. 1 set of screwdrivers 3. 1 set of pliers 4. 1 hammer 5. 1 set of wrenches Thank you, Larry Flores	5/9/2006 Medium	Larry Flores Jimmy Carbajal Custodial		Sunland Park ES
6692	Work In Progress Need 4 metal blinds for portable F 46"X 52" thank you.	10/24/2005 Medium	Sebastian Diaz Ruben Ronquillo General Maintenance		Sunland Park ES
7029	Work In Progress The sink in the room 41 is clog need to bring the snake also need to replace the fauset thank you	11/4/2005 Medium	Sebastian Diaz David Villalobos Plumbing		Sunland Park ES
9221	Work In Progress Need to replace door closer in front library. thank you	2/1/2006 Medium	Sebastian Diaz Manny Lozoya Key and Lock		Sunland Park ES
8879	Work In Progress Need to repair lock at cafeteria double doors. thank you.	1/19/2006 Medium	Sebastian Diaz Manny Lozoya Key and Lock		Sunland Park ES
9082	Work In Progress Need to replace door knob portable E .Is broken is difficult to open from inside.thank you.	1/27/2006 Medium	Sebastian Diaz Manny Lozoya Key and Lock		Sunland Park ES
8041	Work In Progress Portable A - Broken window 30 x 28 Double Glass. Est. Damage 125.00	12/1/2005 Medium	Sebastian Diaz Ruben Ronquillo Glass\Window Repairs	Portables	Sunland Park ES
10499	Work In Progress 3/14/06 need to replace filter grill on the southeast roof thank you	3/14/2006 Medium	Sebastian Diaz Jose Ambriz Heating/Ventilation /Air Conditioning		Sunland Park ES
9834	Work In Progress Need to remove sand by the south area with the heavy tractor. thank you.	2/17/2006 Medium	Sebastian Diaz Guadalupe Ontiveros Grounds		Sunland Park ES
11617	Work In Progress Need to replace overload in the water fountain southside inthe hall thank you	4/25/2006 Medium	Sebastian Diaz Jose Ambriz Heating/Ventilation /Air Conditioning		Sunland Park ES
11619	Work In Progress Need three loads of sand in the kinder playground thank you	4/25/2006 Medium	Sebastian Diaz Guadalupe Ontiveros Grounds		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12414	Work In Progress srn co2a 00003436 vacume extention cord and roller do not work thank you	5/23/2006 Medium	Jesus Urquidi Jimmy Carbajal Custodial Equipment Repair		Sunrise ES
9456	Work In Progress Need a gate key for El Paso Disposal.	2/7/2006 Medium	Juliet Parra Manny Lozoya Key and Lock		Sunrise ES
3533	Work In Progress Could you turn the air conditioning on we have teachers coming in to get a head start on their rooms. It is very hot and we would greatly appreciate it. Since we are a year round school the teachers need to report on Monday. Thank-you	7/14/2005 Medium	Joanne Munoz Jaime Gomez Heating/Ventilation /Air Conditioning	Classroom	Sunrise ES
12182	Work In Progress New Portables - A/S/A/P Start dirt patches for platform not for stairs (pads if needed) and leave a 2 feet surrounding area around platform and installation of ramps and platforms. (If you have any questions call Mike Munoz)	5/15/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds	Portables	Sunrise ES
11494	Work In Progress need to cut fence and install 2 new swing gates on south end of campus by lift station	4/21/2006 Medium	Michael Munoz Michael Munoz Fence Repair		Sunrise ES
11204	Work In Progress REQUESTING FERTILIZER TO AEREATE PLAY GROUND THANKS.	4/7/2006 Medium	Paul Quinones Guadalupe Ontiveros Grounds		Sunrise ES
11356	Work In Progress I HAVE A PIGEON CONTROL PROBLEM ON THE ROOFING AREA AGIAN,AROUND THE ROOFING OVER HANG,AND THE MECHANICAL EQUIPMENT.	4/13/2006 Medium	Paul Quinones Margret Villalobos Pest Control		Sunrise ES
11083	Work In Progress TROUBLE SHOOT PROBLEM WITH WATER PRESSURE SPRIKLER SYSTEM,I HAVE A BAD BOOSTER PUMP MOTOR TO CURCULATING PUMP I NEED IT REPLACED TO WATER THE GRASS FIELD THANKS.	4/4/2006 Medium	Paul Quinones Guadalupe Ontiveros Grounds		Sunrise ES
10829	Work In Progress REQUESTING AIR FILTERS FOR THE UNITS IN CLASSROOMS FOR PM SCHEDULING.	3/30/2006 Medium	Paul Quinones Lorenzo Solis Heating/Ventilation /Air Conditioning		Sunrise ES
10452	Work In Progress BACK FENCING AREA,HIGH WINDS BROKE PAD LOCK TO ROLL GATE NEED TO REPLACE. THANK YOU VERY MUCH!	3/13/2006 Medium	Paul Quinones Manny Lozoya Key and Lock		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9916	Work In Progress REQUESTING WIND SCREENING FOR BACK FENCING AREA LOCATED NEAR LIFT STATION AREA IS WHERE WIND SCREENING NEEDS TO BE REPLACED	2/22/2006 Medium	Paul Quinones Ruben Ronquillo General Maintenance		Sunrise ES
2278	Work In Progress UNIT IN RM.308 NO CIRCULATING WATER.A SLEEVE IS NEEDED TRIPPING ON HIGH HEAD PRESSURE AS WELL	5/25/2005 Medium	Paul Quinones Jaime Gomez Heating/Ventilation /Air Conditioning		Sunrise ES
2208	Work In Progress MASTER COOL UNIT WILL NOT TURN ON AND THE EXHAUST FAN AS WELL,	5/23/2005 Medium	Paul Quinones Jaime Gomez Heating/Ventilation /Air Conditioning		Sunrise ES
2209	Work In Progress STERLING UNIT WET SECTION MIXED AIR CONTROL NOT WORKING PROPERLY DAMPER STAYS SHUT AT TIMES,AND HAS TO BE MOVED MANUALLY FOR COOLING,AND HEATING AS WELL.	5/23/2005 Medium	Paul Quinones Jaime Gomez Heating/Ventilation /Air Conditioning		Sunrise ES
2113	Work In Progress I NEED A COUPLING THAT TURNS THE CIRCULATING PUMP WITH MOTOR SHAFT,TO CIRCULATE WATER TO UNIT IN OUT DOOR MECH. RM.	5/19/2005 Medium	Paul Quinones Jaime Gomez Heating/Ventilation /Air Conditioning		Sunrise ES
946	Work In Progress I NEED SAND FOR BOTH PLAY GROUNDS	4/7/2005 Medium	Paul Quinones Lorenzo Hernandez Grounds		Sunrise ES
2987	Work In Progress I NEED SLEEVES,AND ALSO GASKETS THAT CONNECT TO THE MOTOR,AND PUMP HOUSING. THANKS	6/24/2005 Medium	Paul Quinones Jaime Gomez Heating/Ventilation /Air Conditioning		Sunrise ES
3469	Work In Progress FENCING AREA IN BACK OF SCHOOL NEAR LIFT STATION NEEDS TO BE REPAIRED,AND ROLL GATE.PROBABLE HIGH WINDS ON 7-11-05 CAUSED THE DAMAGE.NO SIGNS OF VANDILISM ON SCHOOL PROPERTY	7/12/2005 Medium	Paul Quinones Michael Munoz Fence Repair		Sunrise ES
3477	Work In Progress I NEED SAND FOR THE PLAY GROUNDS,THANKS.	7/12/2005 Medium	Paul Quinones Lorenzo Hernandez Grounds		Sunrise ES
3876	Work In Progress RM.307,BAD CIRCULATING PUMP NEED TO REPLACE	7/27/2005 Medium	Paul Quinones Jaime Gomez Heating/Ventilation /Air Conditioning		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6782	Work In Progress STERLING HEATING UNIT IN KITCHEN AREA.WILL NOT TURN ON ,MIXED AIR CONTROL NOT WORKING PROPERLY	10/26/2005 Medium	Paul Quinones Jaime Gomez Heating/Ventilation /Air Conditioning		Sunrise ES
12252	Work In Progress NEEDED PARTS SEAL KITS 4-J SLEEVES FOR CIRCULATING PUMPS FOR UNITS	5/16/2006 Medium	Paul Quinones Lorenzo Solis Heating/Ventilation /Air Conditioning		Sunrise ES
12073	Work In Progress COMPLAINT TOO WARM A/C NOT WORKING IN KITCHEN AREA STERLING UNIT.BAD MOTOR NEED TO REPLACE	5/10/2006 Medium	Paul Quinones Lorenzo Solis Heating/Ventilation /Air Conditioning		Sunrise ES
12513	Work In Progress REQUESTING DRY CHEMICAL FIRE EXTINGUISHERS A,B,C TYPE.INCLUDING HOSE,AND HORN 16LB.FOR PORTABLES TOTAL OF 10 ARE NEEDED. THANK YOU	5/25/2006 Medium	Paul Quinones Ruben Ronquillo Fire Extinguishers		Sunrise ES
12509	Work In Progress REQUESTING NEW KEYS,AND LOCKS FOR PORTABLES	5/25/2006 Medium	Paul Quinones Manny Lozoya Key and Lock		Sunrise ES
12077	Work In Progress 1. AIR CONDITIONER IS OUT - MOTOR NOT RUNNING 2. SLICER IS OUT OF ORDER MARGIE TORRES - SNP MANAGER 824-3194 Route to Paul as per Mike 5/11 - mkv	5/10/2006 Medium	Alma Terrell Paul Quinones General Maintenance	Cafeteria	Sunrise ES
3629	Work In Progress please cut and weedeat in and around lift station. weeds are growing rapid and are going to end up on the playing fields.	7/18/2005 Medium	Paul Quinones Grounds		Sunrise ES
11808	Work In Progress Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Paul Quinones General Maintenance		Sunrise ES
11799	Work In Progress Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Paul Quinones General Maintenance		Sunrise ES
11742	Work In Progress Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Paul Quinones Fire Extinguishers		Sunrise ES
10978	Work In Progress Monthly - Sunrise ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12472	Work In Progress We need underground utility locates where the new portable will be placed by Tuesday May 30. (Portable Pier Locations)	5/24/2006 Medium	Alfredo Holguin Fred Appelzoller Plumbing	Portables	Sunrise ES
12473	Work In Progress We need underground utility locates where the new portable will be placed by Tuesday May 30. (Portable Pier Locations)	5/24/2006 Medium	Alfredo Holguin Enrique Sotelo Electrical	Portables	Sunrise ES
10979	Work In Progress Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Vado ES
9982	Work In Progress Outside electrical covers are being kicked off.	2/24/2006 Medium	Armando Diaz Enrique Sotelo Electrical		Vado ES
11541	Work In Progress WARRANTY WORK NEED TO REPAIR AUTO DOOR OPENER SOUTH EXIE	4/24/2006 Medium	Danny Miranda David Boyd Construction		Vado ES
10427	Work In Progress 100 Wing - Room 106 Need new exit sign for back door the one there does not work.	3/10/2006 Medium	Danny Miranda David Boyd Construction		Vado ES
12273	Work In Progress need to unclog urnal in 300-wing boy's vado elem.	5/17/2006 Medium	Danny Miranda Danny Miranda General Maintenance		Vado ES
12062	Work In Progress Need to spray all classrooms in building.	5/10/2006 Medium	Danny Miranda Margret Villalobos Pest Control		Vado ES
4628	Work In Progress Need to meet contractor on Monday - to rekey school site.	8/17/2005 Medium	David Boyd Manny Lozoya Key and Lock		Vado ES
11870	Work In Progress Need to have room numbers put above the outside doors 4 inch letters in white.	5/2/2006 Medium	Debra Facio Danny Miranda General Maintenance	Classroom	Vado ES
10422	Work In Progress Need RFP panels for walls by classrooms	3/10/2006 Medium	Frank Lara David Boyd Construction		Vado ES
10051	Work In Progress 2/28/06 lupe need tiller to work dirt in playground	2/28/2006 Medium	Frank Lara Guadalupe Ontiveros Grounds		Vado ES
8739	Work In Progress manny need to change lock p.e. office also re-key rm207 also dupicent keys for testing, counslor rm	1/13/2006 Medium	Frank Lara Frank Lara Key and Lock		Vado ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9641	Work In Progress Manny, having trouble with door on rm 310	2/13/2006 Medium	Frank Lara Frank Lara Key and Lock		Vado ES
11670	Work In Progress Rooms 108 A-Wing & 209 B-Wing - Units are not working properly in these two rooms.	4/27/2006 Medium	Lorenzo Solis David Boyd Construction		Vado ES
10622	Work In Progress WOULD LIKE A DOOR BELL INSTALL TO THE BACK DOOR FOR DELIVERIES. UNABLE TO HEAR ANYONE AT THE BACK DOOR. LAURA B. SNP MGR 233-2945	3/17/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Vado ES