

# 685 - Work Orders In Progress Ending Fiscal Year 05-06

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11765	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
11764	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
11743	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Alma Del Valle Daycare
10219	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
10218	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
10197	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Alma Del Valle Daycare
3982	Work In Progress Monthly - Alma Del Valle Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
3981	Work In Progress Monthly - Alma Del Valle Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Alma Del Valle Daycare
3960	Work In Progress Monthly - Alma Del Valle Monthly FE Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Alma Del Valle Daycare
3312	Work In Progress Yearly - Alma Del Valle Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Alma Del Valle Daycare
3308	Work In Progress Yearly - Alma Del Valle Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Alma Del Valle Daycare
3899	Work In Progress Room 201 - Half of the carpet is bad replace with tile. 11/29/05 - Teacher requesting status on this work order on 11/10/05 a student fell and hurt her leg. -mkv	7/28/2005 Medium	Hector Villalobos Michael Munoz Carpet Repair	Classroom	Anthony ES
4255	Work In Progress room 109 needs carpet repair	8/8/2005 Medium	Hector Villalobos Michael Munoz Carpet Repair	Classroom	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10015	Work In Progress Need to replace pump seal	2/27/2006 Medium	Hector Villalobos Lorenzo Solis Heating/Ventilation /Air Conditioning	Mechanical Room	Anthony ES
10349	Work In Progress We need to replace a/c unit in pt 217	3/8/2006 Medium	Hector Villalobos Lorenzo Solis Heating/Ventilation /Air Conditioning	Classroom	Anthony ES
10600	Work In Progress Need to replace air compressor at pump house As per Rick route to Raul Sanchez 4/7/06 - mkv	3/17/2006 Medium	Hector Villalobos Raul Sanchez Sewage/Water Treatment Plant	Mechanical Room	Anthony ES
11241	Work In Progress Pump house irrigation pump is not working	4/10/2006 Medium	Hector Villalobos Raul Sanchez Sewage/Water Treatment Plant	Athletic Field	Anthony ES
8736	Work In Progress please add additional sprinklers to existing sprinkler system in the corridore and between the primary and drug free. Also if h2o can be tied in to pine trees. Thanks	1/13/2006 Medium	Guadalupe Ontiveros Grounds		Anthony ES
7339	Work In Progress Custodial storage faucet is leaking need to replace faucet	11/14/2005 Medium	Hector Villalobos Joe Ontiveros Plumbing	Custodial	Anthony ES
5992	Work In Progress upper primary boiler is leaking replace	9/30/2005 Medium	Hector Villalobos Lorenzo Solis Heating/Ventilation /Air Conditioning		Anthony ES
11676	Work In Progress Mild blg front office replace rollup door secure opening a.s.a.p	4/27/2006 Medium	Hector Villalobos Danny Miranda Doors and Hardware		Anthony ES
11989	Work In Progress i need 10 pumps for toilet water tanks	5/8/2006 Medium	Hector Villalobos Joe Ontiveros Plumbing	Restroom (Boys)	Anthony ES
11845	Work In Progress Need to order flush valves for toilets in old main mild blg annex blg need 20	5/2/2006 Medium	Hector Villalobos Joe Ontiveros Plumbing	Restroom (Boys)	Anthony ES
11847	Work In Progress We need to install water filters in old main mild blg uuper primary	5/2/2006 Medium	Hector Villalobos Joe Ontiveros Plumbing	Mechanical Room	Anthony ES
12647	Work In Progress Secure quotes for raising of Irrigation well head and schedule work with Maintenance Coordinator	6/2/2006 6/2/2006 Medium	Alfredo Holguin Raul Sanchez Plumbing	Pump House	Anthony ES
12648	Work In Progress Secure quotes and schedule the pump repairs with Maintenance Coordinator. Coordinator will schedule with Electric Co.	6/2/2006 Medium	Alfredo Holguin Raul Sanchez Sewage/Water Treatment Plant	Pump House	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12562	Work In Progress Girls bathroom replace partitions for RC . Wheelchair and one person to fit inside . Handicapped	5/30/2006 Medium	Hector Villalobos Danny Miranda General Maintenance	Restroom (Girls)	Anthony ES
12584	Work In Progress Purchase a 20 x 20 Steel Carport Kit and Trim Kit.	5/30/2006 Medium	Michael Munoz Ruben Ronquillo General Maintenance		Anthony ES
12297	Work In Progress WATER COMING OUT OF FLOOR DRAIN. AGAIN.  BECKY S. SNP MGR 882-3507	5/18/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES
12286	Work In Progress Adm Intern Mrs menchaca office replace carpet old and to many spots	5/18/2006 Medium	Hector Villalobos Michael Munoz Carpet Repair	Office	Anthony ES
12233	Work In Progress REMOVE LIGHTS AND RUN NEW WIRE FOR ALARM Remover luces para instalar nuevo alambre para sistema de alarma en todos los pasillas de la mid.	5/16/2006 6/28/2006 Medium	Cora Ramirez Enrique Sotelo Electrical	Hallway/Corridor	Anthony ES
12234	Work In Progress door of the boiler room is brocken it will not lock with key it needs to be checked out asap to day.	5/16/2006 Medium	Carlos Lujan Manny Lozoya Key and Lock		Anthony ES
12119	Work In Progress MILK COOLER ON THE AE 4-6 CAMPUS. IS FORMING ALOT OF ICE. IT'S ICE OVER.  BECKY S. SNP MGR 882-3507	5/11/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES
13322	Work In Progress restrooms next to mr montanos office need toilet seats replaced	6/29/2006 Medium	David Vega David Villalobos Plumbing		Anthony ES
13344	Work In Progress Run irrigation water lines.	6/29/2006 Medium	Joe Ontiveros Joe Ontiveros Plumbing		Anthony ES
13302	Work In Progress WALK - IN REFRIG. IS DRIPPING WATER  BECKY S. SNP MGR 882-5607	6/28/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES
12901	Work In Progress old main blg . MR montano is requesting that the wood floor be replace and toilets and sinks in teacher bathrooms.	6/9/2006 Medium	Hector Villalobos Michael Munoz Carpet Repair	Restroom (Boys)	Anthony ES
12852	Work In Progress put in new sink on cabinet teachers lounge ANTHONY ELEM.	6/8/2006 Medium	Danny Miranda Joe Ontiveros Plumbing		Anthony ES
12826	Work In Progress REACH IN FREEZER DOWN. AGAIN  BECKY S. SNP MGR 882-3507	6/7/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Anthony ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12861	Work In Progress please provide carpet in room 135 and repair room 136.	6/8/2006 Medium	Michael Munoz Michael Munoz Carpet Repair		Berino ES
12701	Work In Progress Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Ramiro Holguin General Maintenance		Berino ES
12698	Work In Progress Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Ramiro Holguin General Maintenance		Berino ES
12676	Work In Progress Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Ramiro Holguin Fire Extinguishers		Berino ES
13245	Work In Progress need new roto block with one inch brisle used for tile floor in restrooms	6/26/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial Equipment Repair		Berino ES
13205	Work In Progress BUEMISHER YOU JUST FIXED KEEPS STOPPING CAN YOU FIX IT THANKS	6/23/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial Equipment Repair		Berino ES
13042	Work In Progress burnisher need s to be fixed it shut off . if you replace the cord put 10 feet more on it thanks	6/16/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial Equipment Repair		Berino ES
12973	Work In Progress roto need s to be fixed has a short .	6/13/2006 Medium	Jimmy Cortez Jimmy Carbajal Custodial Equipment Repair		Berino ES
12626	Work In Progress FAUCETS IN KITCHEN RESTROOM NEED TO BE REPLACE	6/1/2006 Medium	Ramiro Holguin Fred Appelzoller Plumbing		Berino ES
8684	Work In Progress NEED TO REPLACE BROKEN BLINDS ROOM 108 NEEDS ONE 54" P.145 NEEDS 3 35" P. 147 3 45" P 156 2 47"	1/12/2006 Medium	Ramiro Holguin Ruben Ronquillo Glass\Window Repairs		Berino ES
8560	Work In Progress NEED TO RELACE SKY LIGHT WINDOW 6X6 FEET HAS A HOLE IN TOP CLASS	1/9/2006 Medium	Ramiro Holguin Ruben Ronquillo Glass\Window Repairs		Berino ES
10959	Work In Progress Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Berino ES
10953	Work In Progress Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Berino ES
9455	Work In Progress Need another gate key for El Paso Disposal.	2/7/2006 Medium	Juliet Parra Manny Lozoya Key and Lock		Berino ES

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To Craft</b>	<b>Area Type</b>	<b>Location Area Number</b>
10200	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral ES
9980	Work In Progress Mr. Cardona is requesting verticle blinds for the front office. measurements are 48"x 84".	2/24/2006 Medium	Joe Ramirez Ruben Ronquillo Glass\Window Repairs		Chaparral ES
10768	Work In Progress Need to cut weeds all around campus (front, bb courts, etc.)	3/28/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
10469	Work In Progress Need work order done for screens in Ms. Barrett's classroom. Window in her classroom is falling apart. Fourth work order that has not been done. Rm-72	3/13/2006 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs	Classroom	Chaparral ES
10470	Work In Progress Need work order done for screen to be put in windows for Ms. Herrera's Classroom. Rm-54	3/13/2006 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs	Classroom	Chaparral ES
10264	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral ES
10223	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral ES
10985	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral ES
10930	Work In Progress Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral ES
10913	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral ES
11144	Work In Progress need to paint all new doors in e-wing	4/6/2006 Medium	Danny Miranda Joe Ramirez Painting		Chaparral ES
11052	Work In Progress area on the east side of campus and in and around water tank. Need to cut weeds and pick-up debre.	4/3/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
11026	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11336	Work In Progress need safe in Mr. Cardona's room to be changed again Please as soon as possible very important Please!!!!!! Thank you	4/12/2006 Medium	Jennifer Corral Manny Lozoya Key and Lock	Office	Chaparral ES
8408	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas Fire Protection		Chaparral ES
8367	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral ES
8312	Work In Progress Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas Roof		Chaparral ES
8295	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Juan Vargas Fire Extinguishers		Chaparral ES
8523	Work In Progress room 20 need fix cabinets lock	1/9/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral ES
7946	Work In Progress cafeteria need replace two entry doors	12/8/2005 Medium	Juan Vargas Danny Miranda Doors and Hardware	Cafeteria	Chaparral ES
7947	Work In Progress kitchen need replace entry door	12/8/2005 Medium	Juan Vargas Danny Miranda Doors and Hardware	Cafeteria	Chaparral ES
7820	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas Fire Protection		Chaparral ES
7779	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral ES
7710	Work In Progress Window in rm-72 is falling out. When opened it falls out. Doesn't stay up alone needs a stick to hold it up. See Ms. Barrett.	12/1/2005 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs		Chaparral ES
9053	Work In Progress E-Wing Barracks - Repair hole on eastside.	1/26/2006 Medium	Michael Munoz Juan Vargas General Maintenance		Chaparral ES
9054	Work In Progress E-Wing Barracks -Paint door on E-Wing Patio area and repair door (hole on wall E-Wing by Patio).	1/26/2006 Medium	Michael Munoz Juan Vargas Painting		Chaparral ES
9401	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Juan Vargas Fire Protection		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9360	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral ES
9337	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Juan Vargas Fire Extinguishers		Chaparral ES
9201	Work In Progress portables 63 -62 -and 54 need replace a/c master cool 3800	1/31/2006 Medium	Juan Vargas Lorenzo Solis Heating/Ventilation /Air Conditioning		Chaparral ES
5498	Work In Progress sweeper/blower/not/working/choke/broken	9/14/2005 Medium	Daniel Ramirez Jimmy Carbajal Custodial Equipment Repair		Chaparral ES
7359	Work In Progress 2 request e. wing rooms need to repair windows	11/15/2005 Medium	Juan Vargas Ruben Ronquillo Glass\Window Repairs		Chaparral ES
7360	Work In Progress rooms 79 71 70 83 need 12 blinds size 33 width 58 length	11/15/2005 Medium	Juan Vargas Ruben Ronquillo General Maintenance		Chaparral ES
7756	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Juan Vargas Fire Extinguishers		Chaparral ES
6529	Work In Progress Had done a work order before for Ms. Barrett about fixing her windows needs a screen.She says they still haven't done the work order. Thanks	10/18/2005 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs	Classroom	Chaparral ES
6343	Work In Progress las vanquetas need grabo a round	10/12/2005 Medium	Juan Vargas Guadalupe Ontiveros Grounds		Chaparral ES
12677	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral ES
12561	Work In Progress Broken main water line to irrigation water tank at chaparral elementary.	5/30/2006 Medium	Johnny Acuna Johnny Acuna General Maintenance		Chaparral ES
12130	Work In Progress need electrical hook up in the evenstart room, where the office is. There is a social worker in that room and needs things to be set up. Rm-R1 See Veronica Rangel	5/11/2006 Medium	Jennifer Corral Enrique Sotelo Electrical	Portables	Chaparral ES
12316	Work In Progress 5/19/06. requesting fertilizer be applied to areas where there is grass.	5/19/2006 Medium	Joe Ramirez Guadalupe Ontiveros Grounds		Chaparral ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12319	Work In Progress need to cover hole on northeast side of barrack .Safety issue.	5/19/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
12320	Work In Progress need to cut and remove dead tree by pine trees by new wing.	5/19/2006 Medium	Joe Ramirez General Maintenance		Chaparral ES
12321	Work In Progress please trim pine trees that run behind of main bldg and in front of e-wing 1 foot from bottom so you can make wells around tree for watering.	5/19/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
12322	Work In Progress please cut weeds and clean up area in coves of main bldg in the back	5/19/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
12323	Work In Progress please cut weeds and apply round up to weeds on east side of new wing.	5/19/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
12324	Work In Progress please remove all material that is in front of concession stand, delete from inventory and bring to ppd.	5/19/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
12105	Work In Progress need to fur out and paint ducting where it was installed for proper air circulation	5/10/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral ES
11769	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral ES
11746	Work In Progress Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral ES
11810	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral ES
12700	Work In Progress Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral ES
12905	Work In Progress 6/9/06 CLASSROOM 62 DOOR WILL NOT LOCK, CLASSROOM IS OUTSIDE.	6/9/2006 Medium	Joe Ramirez Manny Lozoya Key and Lock		Chaparral ES
12755	Work In Progress As per Mr. Cardona he is requesting that counter tops, sink and base cabinets and drawers be installed in the new art room .as this is vital for this room to have these cabinets. 6/8/06 - Route to plumbing, please install 2 tub lav. disregard counter tops as per Mr. Cardona. Install in old pe barrack area.	6/5/2006 Medium	Joe Ramirez Joe Ontiveros Plumbing		Chaparral ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12741	Work In Progress Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral ES
4213	Work In Progress Rooms 101-102-60-62-61-54-70-96-72-73-97 80-82-83 need carpet repace	8/4/2005 Medium	Juan Vargas Michael Munoz Carpet Repair		Chaparral ES
4110	Work In Progress Rm-72 Ms. Barret needs screens on her windows. Says they were suppose to be put in last year.	8/3/2005 Medium	Jennifer Corral Ruben Ronquillo Glass\Window Repairs	Classroom	Chaparral ES
3868	Work In Progress ROOMS 83-82-81-80-72-96-70 NEED WINDOWS REPAIRED OR REPLACE 2-REPORT	7/27/2005 Medium	Juan Vargas Ruben Ronquillo Glass\Window Repairs		Chaparral ES
3801	Work In Progress 5/25/05/ mike neseito que pongan sistema de riego para los arboles	7/25/2005 Medium	Juan Vargas Guadalupe Ontiveros Grounds		Chaparral ES
3284	Work In Progress 07/05/05 mike munoz Mr. cardona quiere bertical blind en su oficina size 82 width and 80 length	7/5/2005 Medium	Juan Vargas Ruben Ronquillo General Maintenance		Chaparral ES
3243	Work In Progress Monthly - Chaparral MS Emergency Lighting Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
3241	Work In Progress Monthly - Chaparral MS Exit Sign Insp. - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
3148	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/3/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
3307	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral MS
3648	Work In Progress please get with speedy and have him train you on the sprikler system on football field and thru out campus. Identify all valves and repair what is needed. also ask him for a key for sprinkler box and have him teach you the programs.	7/19/2005 Medium	Joe Ramirez General Maintenance	Football Field	Chaparral MS
3649	Work In Progress need to cut weeds and grass behind library and courtyard and surrounding areas tru -out campus including pond. Also need to irrigate these areas also.	7/19/2005 High	Joe Ramirez Grounds		Chaparral MS
3650	Work In Progress please paint railing on new portables that where installed and modified and all railings that are in need.	7/19/2005 Medium	Joe Ramirez General Maintenance		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3656	Work In Progress please put up fence where portables where installed even if its on a temp bases.	7/19/2005 Medium	Joe Ramirez General Maintenance	Football Field	Chaparral MS
3607	Work In Progress need to paint new door @ football storage rm.	7/18/2005 Medium	Danny Miranda Joe Ramirez General Maintenance		Chaparral MS
3608	Work In Progress need to paint new door @ rm. 86	7/18/2005 Medium	Danny Miranda Joe Ramirez General Maintenance		Chaparral MS
3499	Work In Progress We need locks to be installed on the center pole to the double doors in the front entrance,north east doors and south east doors. This is the oldest part of the school. the newer part of the school already have locks on the center poles. This old doors are the once that we use more often. This locks will make it so much faster and easier. THANK YOU ROBERT	7/13/2005 Medium	Robert Gonzalez Manny Lozoya Key and Lock		Chaparral MS
3336	Work In Progress Yearly - Chaparral MS Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral MS
3314	Work In Progress Yearly - Chaparral MS Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Joe Ramirez Fire Protection		Chaparral MS
4072	Work In Progress Room 208 - Mold on ceiling tiles. (Nancy, Nurse @ site called in) - mkv Margaret, Joe replied and said there where a couple of ceiling tiles with small mold droppings on them. He replaced them. However still go ahead and generate a w.o. for our records and have him fill it out.  Mike	8/2/2005 Medium	Mary Garcia Joe Ramirez General Maintenance	Classroom	Chaparral MS
3977	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral MS
3990	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
3988	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
3964	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
12779	Work In Progress gabinets on room 205 need replace key	6/6/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12877	Work In Progress gate on futbol field need fix lock	6/8/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral MS
12879	Work In Progress hallway 400 dobbel door need fix to security	6/8/2006 Medium	Juan Vargas Manny Lozoya Key and Lock		Chaparral MS
12704	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral MS
12664	Work In Progress need replace silenoid front area sprinklers	6/2/2006 Medium	Juan Vargas Guadalupe Ontiveros Grounds		Chaparral MS
12990	Work In Progress nurse portable need replacwindow glass	6/14/2006 Medium	Juan Vargas Ruben Ronquillo Glass\Window Repairs		Chaparral MS
12349	Work In Progress Nurse's Portable - Need to run a power pole.	5/19/2006 Medium	Michael Munoz Enrique Sotelo Electrical		Chaparral MS
11936	Work In Progress need replace kitchen grasee tramp	5/4/2006 Medium	Juan Vargas Danny Orozco Food Services		Chaparral MS
12304	Work In Progress Need an upgrade on sprinklers , the ones we have are old and do not reach the entire area that needs to be watered.	5/18/2006 Medium	Elena Palacios Guadalupe Ontiveros Grounds		Chaparral MS Around Building
12242	Work In Progress REPLACE SPRINKLERS I-20 AT PLAYING FIELDS.	5/16/2006 Medium	Guadalupe Ontiveros Bobby Aldaz Grounds		Chaparral MS
12118	Work In Progress BLEACHERS NEED TO BE CLEANED.  PLEASE NOTIFY AIDA WHEN PROCEDURE IS COMPLETED SO AN INSPECTION CAN BE DONE.	5/11/2006 Medium	Aida Salcedo Robert Gonzalez Custodial		Chaparral MS
12232	Work In Progress entry door next to boys locker room. 3 glass is broken need replace 2- wire glass 73.5 19.5 in. and 30- 19.5 in. and 1-35.5in, 23.5in	5/16/2006 Medium	Juan Vargas Ruben Ronquillo Glass\Window Repairs		Chaparral MS
12445	Work In Progress New shelving installed. Carpet pulled away from wall to accommodate new shelving. Carpet needs to be trimmed and fitted around new shelving. For questions please call me (Phillip Medina) at 915-637-0141.	5/24/2006 Medium	Phillip Medina Michael Munoz Carpet Repair	Library	Chaparral MS
12629	Work In Progress need the locks to the gym changed. so we can keep the people out when we do the gym floor. need them changed on june friday 30. thank you	6/1/2006 Medium	Robert Gonzalez Manny Lozoya Key and Lock	Gym	Chaparral MS
12492	Work In Progress front and futbol fields side entry doors need replace middle post	5/25/2006 Medium	Juan Vargas Danny Miranda Doors and Hardware		Chaparral MS

<b>WOID</b>	<b>Status Description Action Taken</b>	<b>Request Date Completion Date Priority</b>	<b>Requester Assigned To Craft</b>	<b>Area Type</b>	<b>Location Area Number</b>
8069	Work In Progress Need to cleanout Mech, Bolier and Electrical Rooms as per Mike Munoz.	12/13/2005 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral MS
7087	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
7085	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
7074	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral MS
7061	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
7324	Work In Progress 11/14/05. door closer on walk in freezer door needs to be replaced. thanks.	11/14/2005 Medium	Joe Ramirez Danny Orozco Food Services		Chaparral MS
6086	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
6084	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
6008	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	10/2/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
5229	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
5227	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
5204	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	9/4/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
9351	Work In Progress Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez Roof		Chaparral MS
9338	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9364	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
9362	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
9052	Work In Progress Patio (Behind Library) Cut grass, weeds and trim edges of grass on sidewalk.	1/26/2006 Medium	Michael Munoz Joe Ramirez General Maintenance		Chaparral MS
7757	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
7783	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
7781	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
8296	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joe Ramirez Fire Extinguishers		Chaparral MS
8371	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
8369	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	1/1/2006 Medium	Alfredo Holguin Joe Ramirez General Maintenance		Chaparral MS
11326	Work In Progress mike. need instaled new football score bord in southside football field	4/12/2006 Medium	Juan Vargas Guadalupe Ontiveros Grounds	Football Field	Chaparral MS
11486	Work In Progress mike . need instaled new football score bord in football field 4/15 - Route to Lupe as per Mike	4/21/2006 Medium	Juan Vargas Guadalupe Ontiveros Grounds	Football Field	Chaparral MS
11104	Work In Progress NEED A SMALL FENCE BETWEEN PROTABLE # 1 AND THE SIDE FENCE TO STOP STAFF AND STUDENTS FROM TAKING A SHORTCUT THROUGH THERE. ALOT OF DIRT IS TRACKED IN BECAUSE OF THIS . THE FENCE WE NEED ONLY HAS TO BE ABOUT 4 FT BY 6 FT. THANK YOU As per Mike route to Juan Carlos - mkv 5/2/06	4/5/2006 Medium	Robert Gonzalez Juan Vargas General Maintenance		Chaparral MS
11139	Work In Progress Portable - Include exterior siding and skirting repairs and painting.	4/6/2006 Medium	Michael Munoz Danny Miranda General Maintenance	Portables	Chaparral MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10401	Work In Progress MIKE. NEED TOOLBOX FOR THE WORK TRUCK	3/9/2006 Medium	Juan Vargas Ruben Ronquillo General Maintenance		Chaparral MS
10227	Work In Progress Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral MS
10225	Work In Progress Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Juan Vargas General Maintenance		Chaparral MS
10514	Work In Progress need master cool wide sections 10- 6500 and 6 - 4500 6/8 Routed to Ruben as per Lorenzo	3/15/2006 6/8/2006 Medium	Juan Vargas Ruben Ronquillo General Maintenance		Chaparral MS
10201	Work In Progress Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Juan Vargas Fire Extinguishers		Chaparral MS
9486	Work In Progress need to replace cloged lines on top of rsf unit	2/8/2006 Medium	Ricardo Jacquez Ricardo Jacquez Sewage/Water Treatment Plant		Chaparral MS
9778	Work In Progress c.m.s. need to paint new doors around gym	2/16/2006 Medium	Danny Miranda Juan Vargas Painting		Chaparral MS
9825	Work In Progress SHOWERS IN BOYS GYM NEED SERVICING ONLY SEVEN OUT OF TEN ARE WORKING. POSSIBLY INSTALL NEW SHOWER HEADS.	2/17/2006 Medium	Elena Palacios Joe Ontiveros Plumbing	Gym	Chaparral MS BOYS GYM
9877	Work In Progress front office building - roof missing tile Route to Gerry Marquez as per Mike 3/10/06	2/21/2006 Medium	David Acosta Gerardo Marquez Roof	Office	Desert Pride
10994	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
10990	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
10951	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin David Acosta Fire Extinguishers		Desert Pride
10931	Work In Progress Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin David Acosta Roof		Desert Pride
11598	Work In Progress Sinks in restrooms- one missing pop-up drain and the other is broken. need to replace.	4/25/2006 Medium	David Acosta David Villalobos Plumbing	Classroom	Desert Pride 1 & 2

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11599	Work In Progress Staff members complaining about front entrance gate to parking lot a little hard to push open & pull gate.	4/25/2006 Medium	David Acosta Michael Munoz Fence Repair	Parking Lot	Desert Pride
5959	Work In Progress need to ckeck a/c blower . It stops blowing When completing a work order you need to enter labor hours. - Thanks Margret	9/29/2005 5/17/2006 Medium	David Acosta Jose Ambriz Heating/Ventilation /Air Conditioning	Classroom	Desert Pride #1
12446	Work In Progress DAVID ACOSTA WILL BE OUT ON: MAY 26 JUNE 5 JUNE 30 - JULY 5  YOU WILL NEED TO DO THE FOLLOWING: -WATER (HOSES BY PORTABLES NEW ONE IN STORAGE. -TAKE OUT TRASH AND RESTROOMS/OFFICE AREA	5/24/2006 Medium	Aida Salcedo Sal Acuna Custodial		Desert Pride
11762	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin David Acosta Fire Extinguishers		Desert Pride
11778	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
11774	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
13132	Work In Progress roto- control handle broke at the bottom. need a loaner or a new roto	6/21/2006 Medium	David Acosta Jimmy Carbajal Custodial Equipment Repair	Custodial	Desert Pride
12692	Work In Progress Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin David Acosta Fire Extinguishers		Desert Pride
12709	Work In Progress Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
12705	Work In Progress Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin David Acosta General Maintenance		Desert Pride
4304	Work In Progress need locks for two doors to the hall way, that needs to be use as storage for science rooms.	8/8/2005 Medium	David Acosta Manny Lozoya Key and Lock	Classroom	Desert Pride #3,4
3620	Work In Progress NEED NAME PLATES TO BE MADE: (1) PRINCIPAL, (1) ASSISTANT PRINCIPAL, (1) COMPUTER LAB	7/18/2005 Medium	Johnny Acuna Manny Lozoya Key and Lock	Desert Trail Intermediate	

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12703	Work In Progress Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Johnny Acuna General Maintenance		Desert Trail Intermediate
12708	Work In Progress Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Johnny Acuna General Maintenance		Desert Trail Intermediate
12679	Work In Progress Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Johnny Acuna Fire Extinguishers		Desert Trail Intermediate
12649	Work In Progress 6/2/06 Waren Cloud (IA) in room #118 lost his key to the classroom. J-36	6/2/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
12885	Work In Progress door knob to portable #401 is hard to unlock and lock. key gets stuck.	6/8/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
13263	Work In Progress Portable #411. Need to transfer (core) on old door knob to new door knob.	6/27/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
13264	Work In Progress Portable #411. Inside door needs a door knob that can be able to be locked.	6/27/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
12991	Work In Progress FREEZER NOT WORKING  PAT C. SNP MGR 824-3822	6/14/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Desert Trail Intermediate Cafeteria	
13127	Work In Progress Mice in the library. Please send Exterminator.	6/21/2006 Medium	Johnny Acuna Margret Villalobos Pest Control		Desert Trail Intermediate
13071	Work In Progress need to install a door handle lock to middle door inside portable 411 / 412.	6/19/2006 Medium	Johnny Acuna Manny Lozoya Key and Lock		Desert Trail Intermediate
11836	Work In Progress DAVID BOYD ROOF LEAK IN THE GIRL'S RESTROOM IN FRONT OF THE TEACHER'S LOUNGE. LEAK GOES THROUGH ALL THE WAY DOWN INTO THE CEILING OF THE RESTROOM AND BUBBLES UP THE PAINT. HAVE TRIED TO PATCH IT UP BUT CANNOT FIND THE LEAK. PLEASE STOP BY WHEN YOU GET A CHANCE OR SEND ME SOME CONTRACTORS TO HELP ME FIND THE LEAK. THANK YOU.....	5/1/2006 Medium	Johnny Acuna David Boyd Construction		Desert Trail Intermediate
11707	Work In Progress NEED PLAYGROUND SAND FOR SWINGS.	4/27/2006 Medium	Johnny Acuna Guadalupe Ontiveros Grounds		Desert Trail Intermediate



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11849	Work In Progress need (2) square keys for outdoor water valves on the main building walls. (where the water hoses connect)	5/2/2006 Medium	Johnny Acuna Joe Ontiveros Plumbing		Desert Trail Intermediate
12017	Work In Progress need a 1" water backflow preventer for irrigation of trees for the front of the main bldg.	5/8/2006 Medium	Johnny Acuna Joe Ontiveros Plumbing		Desert Trail Intermediate
12083	Work In Progress please relocate a/c selective switch in the teacher's lounge to be able to install a box around it to lock it. the reason is because teachers turn off air-conditioner in the lounge and shuts down a/c to a classroom, and the custodial / maintenance office. (The air-conditioner is used for all 3 rooms.)	5/10/2006 Medium	Johnny Acuna Enrique Sotelo Electrical		Desert Trail Intermediate
12070	Work In Progress please remove dirt pile (hill) next to the swing area. (playground).	5/10/2006 Medium	Johnny Acuna Guadalupe Ontiveros Grounds		Desert Trail Intermediate
12441	Work In Progress Need a 12' Ft. Extension Cord.	5/24/2006 Medium	Johnny Acuna Enrique Sotelo Electrical		Desert Trail Intermediate
12501	Work In Progress need to replace hand dryer to boys restroom in the NW hall. WORLD DRYER: MODEL #WA126 SERIAL #90332	5/25/2006 Medium	Johnny Acuna Enrique Sotelo Electrical		Desert Trail Intermediate
12559	Work In Progress WALK-IN REFRIG. DOWN. NO POWER TO TOP. WHERE FAN IS AT.  PAT C. SNP MGR 824-3822	5/30/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Desert Trail Intermediate Cafeteria	
5426	Work In Progress need a replacement heating coil (Boiler System) in the Cafeteria/Gym. (Old one Leaks) THIS WO WAS ROUTED TO JOSE AMBRIZ - AS PER L. SOLIS 6/22/06	9/12/2005 Medium	Johnny Acuna Jose Ambriz Heating/Ventilation /Air Conditioning		Desert Trail Intermediate
7184	Work In Progress Please replace metal door (Back Door) from the kitchen. Door is corroded and getting worse. Thank You !!!	11/8/2005 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
7366	Work In Progress need to replace door frame and door to portable #404.	11/15/2005 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
7520	Work In Progress (Ruben Ronquillo) Need cement mixer for next week to do cement project in parking lot area. (ramp)	11/22/2005 Medium	Johnny Acuna Ruben Ronquillo General Maintenance		Desert Trail Intermediate

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6910	Work In Progress need a replacement heating coil (boiler heating system) for cafeteria heater. Old heater leaks: Model # LHD103CH Serial #35C01059-06	11/1/2005 Medium	Johnny Acuna Jose Ambriz Heating/Ventilation /Air Conditioning		Desert Trail Intermediate
9001	Work In Progress need a restroom partition installed in room #107. (handicapp room)	1/24/2006 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
11601	Work In Progress (BROKEN FIRE ESCAPE WINDOW HARDWARE AND BUTTONS TO PORTABLES) NEED TO REPLACE BROKEN FIRE ESCAPE WINDOW HARDWARE AND BUTTONS TO PORTABLES: #403, #409, AND #410. THANK YOU.....	4/25/2006 Medium	Johnny Acuna Ruben Ronquillo Glass\Window Repairs		Desert Trail Intermediate
11559	Work In Progress (David Boyd) Outdoor expansion joint located in the bus area turnaround has a 1" separation and has cracked the upper part of the wall. Please come and check. Thank You....	4/24/2006 Medium	Johnny Acuna David Boyd Construction		Desert Trail Intermediate
11560	Work In Progress NEED A GATE INSTALLED WHERE TWO SIDEWALKS MEET BETWEEN CHAPARRAL ELEM. AND DESERT TRAIL. (MIDDLE FENCE LINE). (SIDEWALKS ARE FOR HANDICAPP FIRE EXIT ESCAPE ROUTE.)	4/24/2006 Medium	Johnny Acuna Michael Munoz Fence Repair		Desert Trail Intermediate
11318	Work In Progress 1522 ASPIRADORA RUEDAS . MANGO.	4/12/2006 Medium	Marisela Torres Jimmy Carbajal Custodial Equipment Repair		Desert Trail Intermediate
9430	Work In Progress (Danny Miranda) Portable #411, #412: Need to replace hallway and restroom doors. Thank You !!!!!	2/6/2006 Medium	Johnny Acuna Danny Miranda Doors and Hardware		Desert Trail Intermediate
10511	Work In Progress NEED TO REPLACE COMERCIAL FLOOR TILE TO BUS LOBBY	3/15/2006 Medium	Marisela Torres Michael Munoz General Maintenance		Desert Trail Intermediate
10483	Work In Progress Please replace tracer summit board. Thank You!!	3/14/2006 Medium	Lorenzo Solis Lorenzo Solis Heating/Ventilation /Air Conditioning		Desert View ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11245	Work In Progress W.O. : PRINCIPAL CARPET TO BE REPLACED IN CLASS ROOMS - 16 ROOMS R-21=25=18-14-23-27-29-31-34-36-39-30-41-32- 24-5 TO BE TILED PAT AGUILAR 6/7/06 Good news, this project will start on June 19th. The contractor says he can finish in 1 week? I say 2.  Have a good day Mike	4/10/2006  Medium	Patricio Aguilar Michael Munoz  Carpet Repair		Desert View ES
6225	Work In Progress NEED TO COMPLETE BUILDING PERFORMANCE INSPECTION REPORTS ON ALL CUSTODIANS, TO INCLUDE CLOSETS, MSDS BOOKS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEEDS TO ALSO INCLUDE INSPECTION ON YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED TO US NO LATER THAN OCTOBER 28, 2005.	10/10/2005  Medium	Aida Salcedo Miguel Aguilar  Custodial		Desert View ES
7232	Work In Progress Trees in front courtyard unhealthy/dying, signs of infestation, requesting solution/insecticide to remedy problem.	11/9/2005  Medium	Miguel Aguilar Guadalupe Ontiveros  Grounds		Desert View ES
4781	Work In Progress pat aguilar rock wall (safety concern) 6 rock wall metal gates need to be replaced rusted throw	8/22/2005  Medium	Patricio Aguilar Michael Munoz  Fence Repair		Desert View ES
12490	Work In Progress pat aguilar lift front hall way 6 - 13"x15" glass window 1 - 5 1/2"x13 1/4" safty glass 1 - 13 1/2"x 64" glas door saft glass	5/25/2006  Medium	Miguel Aguilar Ruben Ronquillo  Glass\Window Repairs		Desert View ES
11706	Work In Progress pat aguilar need light bulbs class rooms - florescent lamps order #26668 hall ways - light fixtures class rooms - ballasts light icn-4p32-sc	4/27/2006  Medium	Patricio Aguilar Carlos Castillo  Electrical		Desert View ES
13199	Work In Progress REPAIR SPRINKLER SYSTEM INSIDE OF ROCKWALL AREA TO WATER GRASS.	6/22/2006  Medium	Margret Villalobos Patricio Aguilar  General Maintenance		Desert View ES OUTSIDE

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13125	Work In Progress C-Wing - Assemble 2 carts.	6/21/2006 Medium	Lucy Meza Juan Ambriz General Maintenance		GAC Federal Programs
13220	Work In Progress AS PER ELISA SAENZ-NEEDS TO HAVE THE SUPT. CONFERENCE ROOM DOOR KNOB CHANGED OUT. THEY NEED ONE WITH A LOCK. (RIGHT NOW IT'S JUST A DOOR KNOB WITH NO KEY HOLE)	6/23/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC A-WING
13265	Work In Progress AS PER YVONNE LOZANO-PLEASE CLEAN THE FLOORS AND REARRANGE THE FURNITURE.	6/27/2006 Medium	Mary Garcia Ralph Lara Custodial	Office	GAC C-WING
13333	Work In Progress AS PER ELVA PEREZ-NEED TO HAVE THE KEY CORE TO HER OFFICE CHANGED. (DUE TO MOVING TO A NEW DEPT. & THERE IS TOO MANY KEYS THAT OPEN THIS OFFICE.) RIGHT NOW SHE HAS KEY A5.	6/29/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC C-WING
13334	Work In Progress AS PER MARY GARCIA-NEED TO HAVE DESK DRAWERS FIXED TO BE ABLE TO LOCK THEM. (THEY USE TO LOCK BEFORE MOVING MODULAR FURNITURE-SO NOW THERE NOT BALANCED TO LOCK)	6/29/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC A-WING
13320	Work In Progress AS PER PHILLIP NEEDS FOR A SIGN TO BE HUNG UP IN HIS OFFICE. NEEDS ANCHERS TO HANG UP. (SEE PHILLIP BEFORE HAND.)	6/29/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Office	GAC C-WING
13330	Work In Progress AS PER YVONNE LOZANO-NEEDS A KEYBOARD HOLDER INSTALLED UNDER IRMA LAZARINS DEKS.	6/29/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Office	GAC C-WING
13331	Work In Progress AS PER YVONNE LOZANO-NEEDS PICTURES TAKEN DOWN FROM IRMA SUAREZ OLD OFFICE AND TO BE PLACED IN HER NEW OFFICE	6/29/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Office	GAC C-WING
13332	Work In Progress AS PER MS. SALINAS-NEED TO HAVE A WALL- MOUNTED FAN TO BE MOVED TO CONCA CHAVEZ'S OFFICE.	6/29/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Office	GAC C-WING
13080	Work In Progress Library Services - Could you place another work order to have our air-unit looked at? It's making awful sounds and it isn't cooling. Thank you.	6/19/2006 Medium	Phillip Medina Jose Ambriz Heating/Ventilation /Air Conditioning	Office	GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13062	Work In Progress AS PER MIKE SORIA-NEED 2 DOOR KNOBS W/KEYS FOR THE 2 BATHROOMS WHERE THE POOL IS AT. (BATHROOMS WORK ON, SO NEED TO KEEP THEM LOCK)	6/16/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Pool	GAC POOL AREA
13064	Work In Progress AS PER LUCY GARCIA-NEEDS FOR HER OFFICE KEY TO OPEN THE COPY ROOM AT HUMAN RESOURCES IF POSSIBLE. IF NOT THEN NEEDS ONE MADE.	6/16/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC COPY ROOM
12987	Work In Progress AS PER JUAN AMBRIZ-NEEDS AN EXTRA PAD LOCK FOR STORAGE AREA	6/14/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC MAINTENANCE
12961	Work In Progress Need to walk-thru building with new building mechanic.	6/13/2006 Medium	Carlos Castillo Carlos Castillo Electrical	Electrical Room	GAC
12934	Work In Progress please rekey on lock on the technology storage building (check with Calixto or Cora) thank you	6/12/2006 Medium	Cora Ramirez Manny Lozoya Key and Lock		GAC
12937	Work In Progress AS PER IRMA GOMEZ- NEEDS REPLACEMENT OF FLORESCENT LAMP (SMALL)	6/12/2006 Medium	Mary Garcia Juan Ambriz General Maintenance	Office	GAC B-WING
12772	Work In Progress TECHNOLOGY DATA CENTER ROOM - NEED TO HAVE DOOR LOCK CHANGED. MANNY LOOKED INTO A NEW SWIPE CARD LOCK. NEED TO ORDER AND INSTALL LOCK (SEE CALIXTO IF MORE INFORMATION NEEDED)	6/5/2006 Medium	Cora Ramirez Manny Lozoya Key and Lock		GAC
12650	Work In Progress AS PER JULIE HERNANDEZ-NEEDS AN OFFICE KEY (AB51)	6/2/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC A WING
12654	Work In Progress Need to issue keys to Juan Ambriz, Bldg Mechanic	6/2/2006 Medium	Michael Munoz Manny Lozoya Key and Lock		GAC
12652	Work In Progress AS PER LUCY MEZA-LIGHT IN WENDY'S CLOSET DOES NOT WORK, NEEDS TO BE REPLACED OR FIXED. 5/29 - Juan Ambriz checked outlet and no power, breaker is ok, but could not find main power. Need assistance from Electrician. - mkv	6/2/2006 Medium	Mary Garcia Carlos Castillo Electrical	Office	GAC C-WING
12653	Work In Progress AS PER LUCY MEZA-THE OULET IN WENDY'S OFFICE WEST WALL HAS NO POWER	6/2/2006 Medium	Mary Garcia Carlos Castillo Electrical	Office	GAC C-WING
11835	Work In Progress WE NEED TO INSTALL NEW EXOST TO BETROOM IN C WING..	5/1/2006 Medium	Manuel Prospero Jose Ambriz Heating/Ventilation /Air Conditioning		GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12030	Work In Progress please cut and redo gates at the daycare.	5/9/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		GAC
12031	Work In Progress please install misters for the students in play area.	5/9/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		GAC
12606	Work In Progress AS PER MANNY LOZOYA-NEED A NAME PLATE FOR YVONNE LOZANO	5/31/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC
12630	Work In Progress AS PER MIKE MUNOZ-NEEDS A GRAND MASTER KEY FOR MANNY PROSPERO ALREADY DONE BY MANNY LOZOYA	6/1/2006 Medium	Mary Garcia Manny Lozoya Key and Lock	Office	GAC MAINTENANCE MAN
12243	Work In Progress REPLACE BROKEN RPA 2" SPRINKLERS NEED TO BE PLACED 4" POP-UPS.	5/16/2006 Medium	Guadalupe Ontiveros Bobby Aldaz Grounds		GAC
5796	Work In Progress AS PER CORA-NEEDS THE DOOR LOCK TO THE DATA CENTER SWITCHED OUT FROM SWIPE CARD TO A COMBINATION LOCK. (MANNY, PLEASE SEE CORA BEFORE CHANGING OUT)	9/23/2005 Medium	Mary Garcia Manny Lozoya Key and Lock	Computer Lab	GAC DATA CENTER- TECHNOLOGY
5824	Work In Progress NEED A WATERHOSE AND ALSO A HOSE ROLL A WAY.2 WATERHOSE ONE FOR THE PATIO AND ONE FOR THE PRE KINDER AREA I ONLY HAVE ONE AND I USE IT FOR THE FRONT AREA,THE HOSE ROLL A WAYS I NEED ONE FOR EACH HOSE THANK YOU FOR YOUR CONTINUED SUPPORT YOU ARE THE BEST!!!!	9/26/2005 Medium	Jimmy Carbajal Sal Acuna Custodial Equipment Repair	Custodial	GAC
9166	Work In Progress AS PER MS. BERRY-ROOM 101 IN THE PRE-K FRONT DOOR NEEDS TO BE TINTED. IT FACES THE WEST SIDE OF THE BUILDING AND IS VERY HOT IN THE AFTERNOON.	1/30/2006 Medium	Mary Garcia Ruben Ronquillo Glass\Window Repairs	Classroom	GAC
9145	Work In Progress please install water line for misters on the east side of the pre-k. Plans are in your mail box.	1/30/2006 Medium	Guadalupe Ontiveros Grounds		GAC
11041	Work In Progress AS PER MS. BERRY-IF IT WOULD BE POSSIBLE TO HAVE SOME KIND OF MESH OR FENCE PUT UP ALL AROUND THE PLAYGROUND AREA DUE TO SNAKES. THE PRE-K STUDENTS ARE ALWAYS AROUND THAT AREA PLAYING. (A SNAKES WAS FOUND NEAR THE FINANCE BACK DOOR.)	4/3/2006 Medium	Mary Garcia Michael Munoz General Maintenance		GAC PLAY GROUND
11266	Work In Progress AS PER SELMA-NEED TO EXTERMINATE FOR ANTS AND SWSEEP DIRT FROM WALKWAYS.	4/11/2006 Medium	Mary Garcia Margret Villalobos Pest Control	Office	GAC

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11556	Work In Progress Need to have electrical power strips installed in 3 classrooms in order to plug several computers.	4/24/2006 Medium	Julie Hinojosa Carlos Castillo Electrical	Portables	GAC
11596	Work In Progress Need to install dispenser in restroom by swimming pool.	4/25/2006 Medium	Michael Munoz Ralph Lara Custodial		GAC
11038	Work In Progress please provide sand to daycare area where new playground equipment was installed .Might need the bobcat to lay sand.	4/3/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		GAC
10560	Work In Progress 3/16/06. WE NEED TO REPLACE THE SHORT LIGHT POSTS.THEY ARE BROKEN AND NEED TO CHECK IF THERE IS POWER. THIS NEEDS TO BE DONE AS SOON AS POSSIBLE. MR. HAUGEN IS REQUESTING THIS WORK ORDER. AS PER MR. CARLOS CASTILLO.	3/16/2006 Medium	Manuel Prospero Carlos Castillo Electrical		GAC
9981	Work In Progress RTC Office - Transfer furniture to Portable 3 take computer from Margaret's Office to RTC Office.	2/24/2006 Medium	Selma Nevarez Ralph Lara Custodial		GAC
4377	Work In Progress NEED NEW R. R. PARTITIONS IN "A" WING AS PER MENNY PROSPERO	8/9/2005 Medium	Manuel Prospero Danny Miranda General Maintenance		GAC
4271	Work In Progress Requested by Ms. Kalkwarf Rm. 750 Barracks- Floor tiles are broken and coming off the floor.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4285	Work In Progress Requested by Mr. Villa Rm. 510 Band Room- Security light in the center of the room does not work.	8/8/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4311	Work In Progress PANTHER HUT porch entrance too dark security lighth dosen't work	8/8/2005 Medium	Fernando Moncayo Fernando Moncayo Electrical		Gadsden HS
4282	Work In Progress Requested by Mr. Martinez Rm. 227 North Building-Replace carpet in Attendance Office area. One edge of the carpet is lifting, our concern is that a person may trip and fall.	8/8/2005 Medium	Velia Alarcon Michael Munoz Carpet Repair		Gadsden HS
4269	Work In Progress Requested by Ms. Jacquez Rm. 752 Barracks- Window is unhinged and needs to be repaired. 5080 - Put bolt on window in place to lock it. (Need to call window co to fix it) - Mario 9/21/05	8/8/2005 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
4502	Work In Progress NEED TO LAMPES AT WOOD SHOP SAME ARE BURNED OUT	8/11/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
4429	Work In Progress Requested by Velia Rm. 112 Front Office-Three HE keys are needed for Key Box.	8/10/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4448	Work In Progress Telescope observatory locate on the west side of the baseball field - Install fencing around it to prevent vandalism	8/10/2005 Medium	Michael Munoz Fence Repair		Gadsden HS
4386	Work In Progress Requested by Mr. Whitener Rm. 566 Ag. Shop-220 Volt Electric extension cord needed with a new female end, current ones puts people at risk of electrocution. 6/9/06 As per Mike Mc Dermott route to C. Castillo - mkv	8/9/2005 Medium	Velia Alarcon Carlos Castillo Electrical		Gadsden HS
4166	Work In Progress Requested by Mr. Donaldson Rm. 554 Wood Shop-Replace ceiling tile in storeroom and office.	8/3/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
4243	Work In Progress Requested by Ms. Bradley Rm. 602 Business Building-Handle on window has broken off, needs to be replaced.	8/5/2005 Medium	Velia Alarcon Mario Apodaca Glass\Window Repairs		Gadsden HS
4199	Work In Progress Requested by Mr. Chambers Rm. 110 Front Office-Re-key doors, make cylinders off D Master, 4 keys will be needed. Have had several items stolen from office, please re-key as soon as possible.	8/4/2005 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
4204	Work In Progress Requested by Cathy Cano Parking Lot-Over Fall Break, have the lines in the North Parking Lot painted.	8/4/2005 Medium	Velia Alarcon Michael Munoz Painting		Gadsden HS
3593	Work In Progress Need to repair or replace electrical conduit outside of CONCESSION STAND by GIRL'S GYM  Parent called regarding the outlets to the concession stand need status. Work Order has been placed along time ago needs to be repaired before next Saturday.	7/15/2005 Medium	Fernando Moncayo Michael Mc Dermott Electrical		Gadsden HS
3524	Work In Progress NEED TO FIX FOOTBALL FIELD SCOREBOARD BREAKER BOX	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
3525	Work In Progress NEED TO CK ALL FOOTBALL FIELD LAMPS	7/14/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
3910	Work In Progress Requested by Isela Martinez New Counseling Center Portable-Bracket needed for N.M. Flag.	7/28/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
9823	Work In Progress Requested by Mr. Chambers All G.H.S. Buildings-Paint all G.H.S. Buildings with maroon trim (outside)-doors, windows, and flashing etc.	2/17/2006 Medium	Velia Alarcon Mario Apodaca Painting		Gadsden HS



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9432	Work In Progress need to replace key switches with regular two pole switches. ROUTED TO MIKE MC DERMOTT AS PER MIKE 6/30/06 - MKV	2/6/2006 Medium	Carlos Castillo Michael Mc Dermott Electrical	Classroom	Gadsden HS
9546	Work In Progress please repair clean out that east of concession stand.	2/10/2006 Medium	David Villalobos Plumbing	Football Field	Gadsden HS
9685	Work In Progress Requested by Ms. Foote Rm. 332 Academic Building-Replace ceiling light bulbs. ROUTE TO BM - AS PER MIKE 2/17/06	2/14/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
9688	Work In Progress Requested by David Vega Rm. 243 Classroom Over Varsity Gym-Needs a few light bulbs replaced, on one of the lights. ROUTE TO BM - AS PER MIKE 2/17/06	2/14/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
9909	Work In Progress Requested by Dolores Nanez Library-Anchor wall (partition) has glass window and shelves, made of wood.	2/22/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10138	Work In Progress NEED TO PUT A NEW TOILE FLANGE AT N-BLDG GIRLS RESTROOM	3/2/2006 Medium	Mario Apodaca David Villalobos Plumbing		Gadsden HS
10114	Work In Progress ATTN. DAVID VILLALOBOS;Need to replace two toilets and flanges in LIBRARY GIRL'S R. R.Also one toilet in MAIN GIRL'S R.R THANK YOU!!	3/1/2006 Medium	Fernando Moncayo David Villalobos Plumbing		Gadsden HS
10035	Work In Progress Requested by Mr. Palmer Rm. 229 North Building-1.) Remove permanent desks that stick out into room. (There's 7 of them.) 2.) Relocate the gas and electrical outlets to the side counters. *Call me before work begins so I can clean out stored items.	2/27/2006 Medium	Velia Alarcon Michael Munoz General Maintenance		Gadsden HS
10007	Work In Progress ROOF LEAK AT NEW RESTROOM BOY SIDE AT FOOTBALL FIELD	2/24/2006 Medium	Mario Apodaca David Boyd Construction	Football Field	Gadsden HS Roof
10573	Work In Progress Requested by Ms. Jordan Rm. 320 Academic Building-Has a light fixture with broken bulbs. It's been that way since October.	3/16/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10766	Work In Progress NEED TO PUT NEW FLOOR TILE AT V-GYM GIRLS LOCK ROOM	3/28/2006 Medium	Mario Apodaca Michael Munoz Carpet Repair	Restroom (Girls)	Gadsden HS
10965	Work In Progress Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10428	Work In Progress AG Shop - Walk In Cooler needs refrigerant (freeon) as per Fernando needs it by next week.	3/10/2006 Medium	Fernando Moncayo Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
11523	Work In Progress Please check and replace all a/c contactors in ACADEMIC bldg;Some are burn and not making good contact	4/21/2006 Medium	Fernando Moncayo Michael Mc Dermott Electrical		Gadsden HS
11439	Work In Progress Attn.MR.MIRA&ANDA,sliding door in room 106 storage won't open,please help THANK YOU!!!  Route to D. Miranda as per Mike 4/26/06 - mkv	4/20/2006 Medium	Fernando Moncayo Danny Miranda Doors and Hardware		Gadsden HS
11257	Work In Progress NEED NEW LAMPS COVER FOR NORTH BLDG 6/9 - Route to Mario as per Mike Mc Dermott. - mkv 6/28 - As per Mario Electrician needs to order covers - mkv	4/10/2006 Medium	Mario Apodaca Carlos Castillo Electrical		Gadsden HS
11422	Work In Progress Requested by Ms. Leahy Rm. 215 North Building-Windows need mini-blinds, windows need to be measured to order the blinds.	4/19/2006 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS
10997	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
11142	Work In Progress need to paint new double doors main building	4/6/2006 Medium	Danny Miranda Fernando Moncayo Painting		Gadsden HS
11162	Work In Progress Requested by Ms. V. Lopez Business Building-The assembly of 6 steel shelving units. These units are located in the "old Counseling Center."	4/6/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
11163	Work In Progress Requested by Ms. D. Nanez Library-Change the time on the clock. Clock is about 13 feet high on the wall, a latter is needed.	4/6/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
11165	Work In Progress Requested by Ms. Ulibarri-Klein Rm. 504 Annex Building-Remove switch on bottom of 3rd pole to back, but leave outlet active that is on top of pole. For questions call Sylvester the District Telecommunication Tech.	4/6/2006 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
10885	Work In Progress Requested by Velia for the hallways in the Old English Building-Halls need to be painted.	3/31/2006 Medium	Velia Alarcon Mario Apodaca Painting		Gadsden HS
10877	Work In Progress Requested by Mr. Wall Rm. 346 Academic Building-Two window blinds are need for the windows. They're required for Lock Down Fire Drills.	3/31/2006 Medium	Velia Alarcon Ruben Ronquillo Glass\Window Repairs		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10800	Work In Progress Requested by Ms. Moreno Rm. 126 Main Building- There is a water leak above my channel one monitor. The monitor was replaced, but the technician said that this one would be damaged as well if the leak was not fixed.	3/29/2006 Medium	Velia Alarcon Fernando Moncayo Roof		Gadsden HS
10796	Work In Progress Requested by Velia Old English Building-Fix hole on the wall of the 1st floor of the Old English Building, close to room # 128.  As Per Mr. Foster this needs to be fixed as soon as possible.	3/29/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10801	Work In Progress Requested by Mrs. Munoz Rm. 610 Business Building-Nine light bulbs need to be replaced.	3/29/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
10789	Work In Progress Grounds Shop - Need an electrical outlet installed outside of shop.	3/29/2006 Medium	Guadalupe Ontiveros Michael Mc Dermott Electrical		Gadsden HS
9147	Work In Progress Need a new metal door for BOY'S restroom in OLD ENGLISH 1st. floor. ASAP please,can't lock restroom to control vandalism THANK YOU!!	1/30/2006 Medium	Fernando Moncayo Danny Miranda Doors and Hardware	Restroom (Boys)	Gadsden HS
9372	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
9232	Work In Progress Requested by Jenny Gonzalez Rm. 250 Computer Lab-Light bulb needs to be replaced in the Boys Restroom.	2/1/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
8844	Work In Progress AS PER MR. CHAVEZ OVER AT THE GHS ACADEMIC BUILDING BOYS RESTROOM ON THE WEST SIDE NEEDS A PARTION BETWEEN HANDICAP & REGULAR TOILET.	1/18/2006 Medium	Mary Garcia Danny Miranda Doors and Hardware	Restroom (Boys)	Gadsden HS GHS ACADEMIC BLDG
8687	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-Ovens not working at all. First and third ovens on the right side of kitchen, possibly a problem with the outlets.	1/12/2006 Medium	Velia Alarcon Danny Orozco Food Services		Gadsden HS
8688	Work In Progress Requested by Ms. Anderson Rm. 233 Panther Hut-Dishwasher not pulling cleaner or rinse products, only pulls sanitizer.	1/12/2006 Medium	Velia Alarcon Danny Orozco Food Services		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
8714	Work In Progress NEED A NEW E/COOLER AT FOOTBALL FIELD PRESS BOX  REPLACE UNIT FOR A M/C 6500 UPFLOW WITH DUCTWORK, SIZE WAS INSTALLED BECAUSE INSTALLED A DUCT WORK 20X20X90. 1HP MOTOR INSTEAD OF 1/3 HP MOTOR.	1/12/2006  Medium	Mario Apodaca Jose Ambriz Heating/Ventilation /Air Conditioning	Football Field	Gadsden HS New Equip. Installation
8691	Work In Progress Requested by Chief Arms Rifle Range/Adjacent to Boys Gym-Rifle Range is coming loose in numerous panels and range is no longer secure. Recommend a permanent wall or welded metal plating. Kids are using basketballs to break the screens; also maintenance caught three kids in the rifle range before break.  Note from Mr. Foster: THIS IS IMPORTANT! Route to Bldg Mechanic as per Mike - 2/8/06 -mkv	1/12/2006  Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
8696	Work In Progress Requested by Mrs. Quinones Rm. 653 Busines Building-Replace florescent light bulbs. ROUTE TO BM AS PER M. MC DERMOTT	1/12/2006  Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
8379	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	1/1/2006  Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
9101	Work In Progress Requested by Ms. Jacquez Rm. 752 Barracks- Mount flags on wall.	1/27/2006  Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
8179	Work In Progress Requested by Mr. Contaldo Campus Observatory- Install 6' chain link fence around Observatory Deck with locking gate. Key problem: prevent future vandalism. 1/11 - Route to Lupe as per Mike.	12/16/2005  Medium	Velia Alarcon Guadalupe Ontiveros Grounds		Gadsden HS
8185	Work In Progress Requested by Ms. Trich Library-The drawer slides for the cashbox are loose. They may be missing screws to attach them to the base. Might someone please assess the situation to determine if the present one can be repaired or if they need replacement? Please check with Leslie, this is a safety issue; the drawer may fall out of the base.	12/16/2005  Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
7638	Work In Progress Girls BB Lockerroom - Connect Electric Water Heater.	11/29/2005  Medium	David Villalobos Michael Mc Dermott Electrical		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
7626	Work In Progress Requested by Mr. Foster and Mr. Chambers Varsity Gym-ATTN: Mike Munoz Replace heating units and duct work. *Girls team practiced in 23 degrees this morning in the gym. *Parents calling and complaining about conditions. *Parents calling Central Office. Mike Munoz has this work order and he will consult w/Mr. Boyd. - Jose Ambriz 7/10/06	11/29/2005 Medium	Velia Alarcon Michael Munoz Heating/Ventilation /Air Conditioning	Gym	Gadsden HS
7791	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	12/4/2005 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
8145	Work In Progress Several light pole around cafeteria area are out.Already change lamps but still not working,need to change ballasts. As per Mike Munoz route to Mike Mc Dermott. 12/18/05-Cali ordered material (10) 100w MH Ballast and (10) 100 WMH Lamps.	12/15/2005 Medium	Carlos Castillo Michael Mc Dermott Electrical		Gadsden HS
8081	Work In Progress Requested by Ms. Trich Rm. 275 Library-Tops of the short book shelves are losing the laminate, which is peeling off. Please re-attach the laminate tops. Please check with either Bonnie or me.	12/13/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
7913	Work In Progress Requested by Cathy Cano Concession Stand- Windows to concession stand need to be put back on. Reasons: cold, and too many flies and/or bees. Route to Bldg Mechanic as per Mike Munoz 12/16/05 - mkv	12/7/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
7914	Work In Progress Requested by Ms. Hunt Rm. 105 Main Building- Cupboard door broke off, screws on my desk.	12/7/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
7886	Work In Progress NEED TO REPAIR ALL DOOR FRAMS AT THE WEIGHT ROOM THE KID WILL PULL THE DOOR OPEN W/THE DOOR ARE LOCK	12/6/2005 Medium	Mario Apodaca Danny Miranda Doors and Hardware		Gadsden HS
5458	Work In Progress need to restripe all parking lines ,handi-cap- arrowa etc.	9/13/2005 Medium	Michael Munoz Painting	Parking Lot	Gadsden HS
5464	Work In Progress Need to paint stripings for student parking lot and east of Auto Shop.	9/13/2005 Medium	Michael Munoz General Maintenance	Parking Lot	Gadsden HS
4810	Work In Progress Requested by Ms. L. Chavez Rm. 245 Classroom Over Varsity Gym-Re-place several burned out light bulbs. RE-ROUTE TO BUILDING MECHANIC as per Mike Mc Dermott 9/19/05	8/23/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4820	Work In Progress Requested by Luis Saucedo Rm. 507 & 509 Annex Building-Install door stops on each of these doors.	8/23/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
4822	Work In Progress Requested by Ms. Zapien Rm. 154 Old English Building-The blinds are completely broken, the curtain is hanging.	8/23/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
4633	Work In Progress Requested by ISS Rm. 800 Old Counseling Center-Door frame falling off portable door leading to the old counseling center.	8/17/2005 Medium	Velia Alarcon Danny Miranda Doors and Hardware		Gadsden HS
4564	Work In Progress Requested by Ms. Nanez Library-Install plywood baks to magazine shelves.	8/15/2005 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
5108	Work In Progress NEED TO PUT NEW BALLAST AT WOOD SHOP LAMPES	8/31/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
4916	Work In Progress please check and repair leak & secure drop ceiling in rm 142. possible safety hazard.	8/25/2005 Medium	Danny Miranda General Maintenance		Gadsden HS
7095	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	11/6/2005 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
7301	Work In Progress BOY'S GYM SOUTH EAST exterior door need to be replace	11/11/2005 Medium	Fernando Moncayo Danny Miranda Doors and Hardware	Gym	Gadsden HS
7500	Work In Progress please replace disconnect to heating unit on the - S- wing north bldg. blades do not work properly.	11/21/2005 Medium	Jose Ambriz Heating/Ventilation /Air Conditioning	Classroom	Gadsden HS
7499	Work In Progress please re-route conduit and repair where kids get on roof by panther hut. north bldg. As per Enrique this wo is for Mike Mc Dermott.	11/21/2005 Medium	Michael Munoz Michael Mc Dermott Electrical	Classroom	Gadsden HS
7956	Work In Progress Vandalism - Damage to south front entrance roll gate hit by vehicle. (Case# 2005-10383) Deputy Isidro Gonzalez #935 6/8 - Route to Ruben as per Mike Munoz - mkv 7/10 - Requesting status from Ruben - mkv	12/2/2005 Medium	Mario Apodaca Ruben Ronquillo General Maintenance		Gadsden HS
6425	Work In Progress NEED TO REMOVE ALL OUTLET AT ROOM 126 AT ARE ON BOOK SHEVING FLOOR AND RELOCA OUTLETS	10/14/2005 Medium	Mario Apodaca Michael Mc Dermott Electrical	Custodial	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
6607	Work In Progress LIBRARY EAST wall;There is a, wall keyed hose bib that is leaking	10/20/2005 Medium	Fernando Moncayo David Villalobos Plumbing		Gadsden HS
6609	Work In Progress Need to install flouresent lighth lamps in ANNEX CORRIDOR, is too dark	10/20/2005 Medium	Fernando Moncayo Michael Mc Dermott Electrical		Gadsden HS
6830	Work In Progress Requested by Velia Rm. 127 Main Building-When the sound system contractors installed the wiring in Ms. Garcia's classroom. They placed it on a wall Ms. Garcia used for her projector. Once they removed the wiring and placed it on another wall, they left the wall scrated and paint peeled. Wall needs to be repaired and painted.	10/28/2005 Medium	Velia Alarcon Fernando Moncayo Painting		Gadsden HS
6710	Work In Progress Requested Ms. Nanez Library-Backs to shelves need to be installed. Backs are in library, however, they need to be cut down to fit.	10/25/2005 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
12269	Work In Progress Swimming Pool - Carlos Lowenberg needs three sets of keys for the lifegaurds by May 24, 2006	5/17/2006 Medium	Alfredo Holguin Manny Lozoya Key and Lock	Pool	Gadsden HS
12277	Work In Progress NEED TO CK ALL LOCK ON BLDG ALL DOORS LOCK ARE GLUE NEED TO WASH OUT OR PUT NEW LOCK DO TO VANDALISM	5/17/2006 Medium	Mario Apodaca Manny Lozoya Key and Lock		Gadsden HS
12392	Work In Progress AUTOSHOP, rollup door ,need a pad lock to secure it over SUMMER break. THANK YOU!!	5/22/2006 Medium	Fernando Moncayo Manny Lozoya Key and Lock		Gadsden HS
12229	Work In Progress need to replace covers on fixtuers	5/16/2006 Medium	Carlos Castillo Carlos Castillo Electrical	Athletic Field	Gadsden HS
12203	Work In Progress Requested by Ms. Arredondo Rm. 568 Vocational Building-Paint classroom (white or beige) important light source for classroom as it is an Art classroom.	5/15/2006 Medium	Velia Alarcon Mario Apodaca Painting		Gadsden HS
12211	Work In Progress Requested by Ms. Arredondo Rm. 568 Vocational Building-Replace burned out light bulbs (4), important light source for the Art classroom.	5/15/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
12218	Work In Progress NEED NEW LAMP COVER FOR CONCESSION STAND AT FOOTBALL FIELD	5/15/2006 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12197	Work In Progress I know this is not a General Maintenance Work Order, but I wasn't sure what type it would be (V.A.) Requested by Ms. Arredondo Rm. 568 Vocational Building-THIRD REQUEST to install floor tile in classroom, very important for classroom instruction.	5/15/2006 Medium	Velia Alarcon Michael Munoz Carpet Repair		Gadsden HS
12633	Work In Progress Exterior chain link mesh needs to be less than 1.25 in. squares and poles need to be 2 in. - Wind screen needs to be on inside or slats need to be installed.	6/1/2006 Medium	Alfredo Holguin Michael Munoz Fence Repair		Gadsden HS
12631	Work In Progress The emergency pump shut-off switch needs to have an audible alarm. ASAP	6/1/2006 Medium	Alfredo Holguin Carlos Castillo Electrical		Gadsden HS
12431	Work In Progress FLUORESCENT SIGN IS OUT AT CATE	5/23/2006 Medium	Mario Apodaca Danny Orozco Food Services	Cafeteria	Gadsden HS
12423	Work In Progress 5-23-6 ELECTRICAL REMODEL OF KITCHEN AREA OF PANTHER HUT.	5/23/2006 Medium	Michael Mc Dermott Michael Mc Dermott Electrical	Classroom	Gadsden HS PANTHER HUT
12389	Work In Progress FOOTBALL FIELD MENS RESTROOM A SINK FAUCET IS LEAKING NEED A NEW ONE	5/22/2006 Medium	Mario Apodaca David Villalobos Plumbing		Gadsden HS
12089	Work In Progress Install picnic tables South of Nursing Area by pine trees.	5/10/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		Gadsden HS
11943	Work In Progress Attn. HVAC TECH. On SUMMER break the large a/c on VARSITY GYM WEST wall, need to be removed; Don't need it, is falling apart ,danger THANK YOU!!	5/4/2006 Medium	Fernando Moncayo Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
12026	Work In Progress install fur ducting to electrical behind panther hut.	5/9/2006 Medium	Michael Munoz Jose Ambriz Heating/Ventilation /Air Conditioning	Classroom	Gadsden HS
12052	Work In Progress WATER COOLER AT WOOD SHOP BLDE NOT WORKING SAMCON PUT IN	5/9/2006 Medium	Mario Apodaca Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
11879	Work In Progress North Bldg - Cover pond at G-Wing remove concrete and fill (with mesquite dirt will work).	5/2/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		Gadsden HS
11975	Work In Progress Need to fumigate all WOODSHOP bldg, classrooms and storages, it's infested with roaches. THANK YOU!!	5/5/2006 Medium	Fernando Moncayo Margret Villalobos Pest Control		Gadsden HS



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11781	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
11694	Work In Progress Need to connect [ electrical ] on new a/c at PRESS BOX THANKS!!!	4/27/2006 Medium	Fernando Moncayo Michael Mc Dermott Electrical		Gadsden HS
11674	Work In Progress GHS Old English – Change program back to how it was w/Outside Temp.  Refaxed on 5/11/06 - mkv	4/27/2006 Medium	Jose Ambriz Margret Villalobos Energy Management System		Gadsden HS
11645	Work In Progress Requested by Velia for Upstairs hallway of Business Building-Several light bulbs are burned out and need replacing.	4/26/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
11654	Work In Progress Requested by Mr. Whitener Rm. 563 Ag. Shop- Two hallway lights are not working.	4/26/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
11655	Work In Progress Requested by Mrs. Ulibarri-klein Rm. 504 Annex Building-Need to repair electrical outlets on NE wall.	4/26/2006 Medium	Velia Alarcon Michael Mc Dermott Electrical		Gadsden HS
12748	Work In Progress Requested by Mr. Dixon Football Field-An HE203 key is needed for the football concession stand before football season begins.	6/5/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
12715	Work In Progress Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Mario Apodaca General Maintenance		Gadsden HS
12712	Work In Progress Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
12750	Work In Progress Requested by Ms. L. Gonzalez Rm. 651 Business Building-Remove green chalkboard on west wall, not needed (already have 2 other chalkboards in the room). Need the space for shelving.	6/5/2006 Medium	Velia Alarcon Fernando Moncayo General Maintenance		Gadsden HS
12749	Work In Progress Requested by Ms. L. Gonzalez Rm. 651 Business Building-Install shelving on west wall for storage purposes.	6/5/2006 Medium	Velia Alarcon Mario Apodaca General Maintenance		Gadsden HS
12751	Work In Progress Requested by Mrs. Munoz Rm. 610 Business Bldg.-Service Sewing machines, sergers, and embroidery machines for next school year. Dean Enterprise-Randy-(505) 522-3216 or (505) 649-2185	6/5/2006 Medium	Velia Alarcon Michael Munoz Equipment		Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12875	Work In Progress REPAIS BROKRN GLASS AT MAIN BLDG ROOM 100 2OX40 DO TO VANDLISM	6/8/2006 Medium	Mario Apodaca Ruben Ronquillo Glass\Window Repairs		Gadsden HS
12880	Work In Progress Requested by Velia Business Building-Four HJ1 keys are needed for the Business Building.	6/8/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
12874	Work In Progress NEED TOO PUT NEW EXIT SIGN AT BOY GYM DO TO VANDALISM	6/8/2006 Medium	Mario Apodaca Michael Mc Dermott Electrical	Gym	Gadsden HS
12878	Work In Progress Requested by Cathy Rm. 562 Ag. Building- Cylinder/Tumbler keeps going round and around, door does not lock.	6/8/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
12944	Work In Progress NEED TO CK ALL FOOTBALL FIELD LIGHTING FOR BURNED OUT BULBS AND ALL LAMPS ON BACK OF BLEACHER NEED TO BE SERVICES TOO	6/12/2006 Medium	Mario Apodaca Michael Mc Dermott Electrical		Gadsden HS
12903	Work In Progress Requested by Velia-Replace two light bulbs that are burned out in the faculty parking lot. Light post may be 20 feet tall, a ladder is needed. Safety issue. 6/28/06 - As per Mario route to Carlos Castillo.	6/9/2006 Medium	Velia Alarcon Carlos Castillo Electrical		Gadsden HS
12960	Work In Progress Need to check welding cords and eliminate any potential hazzard,as requested by Velia Alarcon.	6/13/2006 Medium	Carlos Castillo Carlos Castillo Electrical		Gadsden HS
12993	Work In Progress KITCHEN IS BACKING UP.  LYDIA MONTOYA - SNP MGR 882-5522	6/14/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Gadsden HS
13129	Work In Progress As per Daniel with Lester Humphrey, he says he noticed several areas where the bats are probably getting in. This needs to be sealed to prevent the bats from entering the buildings.	6/21/2006 Medium	Alfredo Holguin Fernando Moncayo General Maintenance		Gadsden HS
13019	Work In Progress ANNEX bldg GIRL'S restrooms door won't open cylinder just turns around	6/15/2006 Medium	Fernando Moncayo Manny Lozoya Key and Lock		Gadsden HS
13046	Work In Progress Please generate a WO for the coping installation along the Pool Dressing rooms and assign to Mike.	6/16/2006 Medium	Alfredo Holguin Michael Munoz General Maintenance	Pool	Gadsden HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13090	Work In Progress Requested by Ms. Hamilton Rm. 562 Ag. Shop-Bearings on A.C. are out, not cooling.	6/19/2006 Medium	Velia Alarcon Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
13092	Work In Progress Requested by Mr. Whitener Rm. 563 Ag. Shop-Need HK3 key replaced, broke in lock due to old age.	6/19/2006 Medium	Velia Alarcon Manny Lozoya Key and Lock		Gadsden HS
13311	Work In Progress please fill area with asphalt where water leak and drain where repaired.	6/29/2006 Medium	Michael Munoz Michael Munoz Concrete		Gadsden HS
13240	Work In Progress As requested by M.Munoz,check football field lights for prper operation.	6/26/2006 Medium	Carlos Castillo Carlos Castillo Electrical	Football Field	Gadsden HS
13247	Work In Progress NEED 2# V-BELT 4L-1000 FOR V -GYM ASAP	6/26/2006 Medium	Mario Apodaca Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden HS
13267	Work In Progress walk-in at 50 degrees  terry portillo - snp manager 882-2824	6/27/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Gadsden MS
13079	Work In Progress We need the 2 emergency lights replaced they were hit by some balls and one is just hanging.	6/19/2006 Medium	Rudy Arreola Enrique Sotelo Electrical	Gym	Gadsden MS
12992	Work In Progress SNP WAREHOUSE FREEZER #2.  GEORGE GOMEZ - SNP WHS 882-6772	6/14/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Gadsden MS
12904	Work In Progress Please paint of ADA the front concrete by both A and B wings. Marking of drop off not clear and will cause an accident of someone stepping off	6/9/2006 Medium	Dana Hamel Rudy Arreola Painting		Gadsden MS
12804	Work In Progress Chiller - Is not working properly. Ask for assistance from Trane. Service Report E028059 6/6/06 - Checked Chiller found locked compressors tried to pull oil sample found no oil on compressors. Need quote to replace compressors. JJ w/Trane	6/6/2006 High	Alfredo Holguin Margret Villalobos Energy Management System		Gadsden MS
12753	Work In Progress Athletics - A/C not cooling properly. I have put in request before and Rudy has checked it, but it still not working. Just making a suggestion: Maybe getting one of the a/c that are in the Teachers Lounge in C-Wing? 6/7/06 - As per Mike Munoz route to Jose Ambriz, HVAC unit has a leak and needs to be recharged.	6/5/2006 Medium	Terry Alvarado Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11890	Work In Progress please install sprinklers that will cover all grass area and install 2 stations instead of 1 Thanks	5/2/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds		Gadsden MS
12094	Work In Progress Room 163 loses power at least 3 times per day. All outlets go down. This causes a problem with computers, instruction and attendance. HELP	5/10/2006 Medium	Dana Hamel Enrique Sotelo Electrical	Classroom	Gadsden MS
12078	Work In Progress Floor drain collapsed need to have it repaired. 5/16 - Route to Rudy as per Mike 5/22 - Route to Plumbers as per Mike.	5/10/2006 Medium	Rudy Arreola Fred Appelzoller Plumbing	Mechanical Room	Gadsden MS
12666	Work In Progress Front office door was not locking and had to lock for the end of the day.	6/2/2006 Medium	Rudy Arreola Manny Lozoya Key and Lock		Gadsden MS
12592	Work In Progress Chiller in A-WING is down no cooling in whole wing.	5/31/2006 Medium	Rudy Arreola Jose Ambriz Heating/Ventilation /Air Conditioning		Gadsden MS
12079	Work In Progress Doors in the B-WING boiler RM are rusted out on the bottom of the door. Need to have them replaced kids started to kick them.	5/10/2006 Medium	Rudy Arreola Danny Miranda Doors and Hardware	Mechanical Room	Gadsden MS
12333	Work In Progress I will be needing a set of Master Keys made for Lynco, for GMS for this coming Monday if possible. Thanks Carlos Vigil	5/19/2006 Medium	Carlos Vigil Manny Lozoya Key and Lock		Gadsden MS
12276	Work In Progress Unit in RM 209 C-WING not working compressor burned out need to have it replaced.	5/17/2006 Medium	Rudy Arreola Lorenzo Solis Heating/Ventilation /Air Conditioning		Gadsden MS
6241	Work In Progress The new roof on the vocational building leaked badly over vacation and the insulation in the old woodshop is falling. Serious problem with students returning tomorrow could fall at any time.	10/10/2005 Medium	Dana Hamel David Boyd Construction	Classroom	Gadsden MS
4522	Work In Progress Door broken in room 500, and window shattered	8/12/2005 Medium	Dana Hamel Danny Miranda Doors and Hardware	Portables	Gadsden MS
4777	Work In Progress The three locks on the office front window are broken, mostly poor design. The front office is wide open until these are repaired or replaced	8/22/2005 Medium	Dana Hamel Rudy Arreola General Maintenance	Office	Gadsden MS
5317	Work In Progress Need to cap of water lines and drain removed already removed sink and counters. RM#188.	9/7/2005 Medium	Rudy Arreola Joe Ontiveros Plumbing	Classroom	Gadsden MS
5793	Work In Progress {{{GYM LOBBY}}} Wall needs to be secured.	9/23/2005 Medium	Rudy Arreola Danny Miranda General Maintenance	Restroom (Boys)	Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
5961	Work In Progress please reomve and replaced stained ceiling tiles in Mr.Lowenburgs office.	9/29/2005 Medium	Rudy Arreola General Maintenance		Gadsden MS
8602	Work In Progress Back flow in A-WING is leaking water. Route to Lupe as per Mike Munoz 3/10/06 - mkv	1/10/2006 Medium	Rudy Arreola Guadalupe Ontiveros Grounds		Gadsden MS
8845	Work In Progress DOUBLE DOORS INSIDE BAND ROOM WHERE INSTRUMENTS ARE STORED DO NOT LOCK AND SECURE PROPERLY. EQUIPMENT SAFETY ISSUE.	1/18/2006 Medium	Maria Sitters Danny Miranda Doors and Hardware		Gadsden MS
8735	Work In Progress please install new sprinklers by picnic tables & where needed and level grounds around area. Thanks	1/13/2006 Medium	Guadalupe Ontiveros Grounds	Cafeteria	Gadsden MS
9002	Work In Progress Sink is clogged we need the snake. to run it threw the wall drain.	1/24/2006 Medium	Rudy Arreola Joe Ontiveros Plumbing		Gadsden MS
9295	Work In Progress please replaced stained ceiling tiles in Mr.Lowenburgs office and thru-out c-wing area thats needed. Thanks	2/3/2006 Medium	Rudy Arreola General Maintenance		Gadsden MS
11147	Work In Progress We are having problems with mice and roaches in homec RM.	4/6/2006 Medium	Rudy Arreola Margret Villalobos Pest Control	Classroom	Gadsden MS
11148	Work In Progress We need the light fixture replaced cover is missing replaced ballast but light fixture is not secure.	4/6/2006 Medium	Rudy Arreola Enrique Sotelo Electrical	Restroom (Boys)	Gadsden MS
11330	Work In Progress We need to have the 6x6 glass cubes removed and install wall with plaster glass keeps broken. 4/19/06 - Routed to Gerry as per Mike.	4/12/2006 Medium	Rudy Arreola Gerardo Marquez General Maintenance	Hallway/Corridor	Gadsden MS
11609	Work In Progress WATER SPICETT WAS DAMAGED AND LEAKING WATER NEED TO REPLACE ASAP	4/25/2006 Medium	Rudy Arreola Joe Ontiveros Plumbing	Restroom (Boys)	Gadsden MS
11187	Work In Progress NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006.	4/7/2006 Medium	Aida Salcedo Juan Acosta Custodial		Gadsden MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11684	Work In Progress Need new power strips in classroom for additional computers. See Mrs. Osborn room 121. Also repair wall outlets in room, possible shock hazzard	4/27/2006 Medium	Dana Hamel Enrique Sotelo Electrical	Classroom	Gadsden MS
10710	Work In Progress please install lights on the north side off the gym annex so the light will shine on the bus turnaround.	3/27/2006 Medium	Enrique Sotelo Electrical		Gadsden MS
3616	Work In Progress replace door at pump room	7/18/2005 Medium	Ricardo Jacquez Danny Miranda General Maintenance		Gadsden MS
4867	Work In Progress THE PAD HOLDER IS WORN OUT AND WONT HOLD THE PAD AT ALL.	8/24/2005 Medium	Jimmy Carbajal Jimmy Carbajal Custodial Equipment Repair	Hallway/Corridor	Gadsden MS
12066	Work In Progress Need to replace old pilots on boiler for La Mesa.	5/10/2006 Medium	Lorenzo Solis Lorenzo Solis Heating/Ventilation /Air Conditioning		La Mesa ES
12657	Work In Progress Trophy Case - Need to install a lock on it.	6/2/2006 Medium	Michael Munoz Manny Lozoya Key and Lock		La Mesa ES
12683	Work In Progress Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Salvador Gonzalez Fire Extinguishers		La Union ES
12724	Work In Progress Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Salvador Gonzalez General Maintenance		La Union ES
12716	Work In Progress Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Salvador Gonzalez General Maintenance		La Union ES
12971	Work In Progress 6/13/06 To Manny Lozoya There is a bend it door that is hard to be closed at JTP. May you come and help me please. Thank you Manny.	6/13/2006 Medium	Salvador Gonzalez Manny Lozoya Key and Lock		La Union ES
12978	Work In Progress 6/13/06 Manny: I need to secure rolling door at main office.	6/13/2006 Medium	Salvador Gonzalez Manny Lozoya Key and Lock		La Union ES
12628	Work In Progress Relace broken cleanout cover in south side of playground.	6/1/2006 Medium	Alfredo Holguin Raul Sanchez Sewage/Water Treatment Plant		La Union ES
10313	Work In Progress Room 206 needs to be fumigated for spiders.	3/7/2006 Medium	Salvador Gonzalez Margret Villalobos Pest Control		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9769	Work In Progress Teacher in classroom 110 requires more power outlets because his room only has two.	2/16/2006 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
9768	Work In Progress To Mike Munoz Subject: I would like to install PVC watering system on side of the school and between buildings.	2/16/2006 Medium	Salvador Gonzalez Guadalupe Ontiveros Grounds		La Union ES
11629	Work In Progress Replace old lighth bulbs and ballasts.	4/25/2006 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
11188	Work In Progress NEED TO COMPLETE BUILDING / PERFORMANCE INSPECTIONS ON ALL CUSTODIANS TO INCLUDED CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIANS NEED TO INCLUDE INSPECTION OF YOUR OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN APRIL 21, 2006.	4/7/2006 Medium	Aida Salcedo Santos Galindo Custodial		La Union ES
8547	Work In Progress Take out grass at swings area with the back hoe and fill with sand ( has half of needed sand)	1/9/2006 Medium	Salvador Gonzalez Guadalupe Ontiveros Grounds		La Union ES
8256	Work In Progress Alvarez Farms ,panel needs main lug kit replaced	12/22/2005 Medium	Carlos Castillo Carlos Castillo Electrical	Classroom	La Union ES
5949	Work In Progress Music Room needs a new circuit installation.	9/29/2005 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
4917	Work In Progress please repair asphalt where other water line was repired.	8/25/2005 Medium	Michael Munoz Concrete		La Union ES
5117	Work In Progress Lights in computer room keeps going out; breaker needs to be checked.	8/31/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES
6718	Work In Progress need electrical outlet on north wall	10/25/2005 10/26/2005 Medium	Santos Galindo Carlos Castillo Electrical	Office	La Union ES
7446	Work In Progress would like hallway in old wing painted and frames. and new base trimming.	11/18/2005 Medium	Santos Galindo Salvador Gonzalez Painting		La Union ES
7391	Work In Progress 11/15/05 To Caly. Relocate electrical outlet.	11/15/2005 Medium	Salvador Gonzalez Carlos Castillo Electrical		La Union ES
4356	Work In Progress in room 202 there is no outlet for refrigeration unit a.s.p.	8/9/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
4408	Work In Progress a light next to my office need to be looked at cause it buzzes all day long.	8/10/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES
4223	Work In Progress need an electrical outlet by computer hookups room 203.	8/5/2005 Medium	Santos Galindo Carlos Castillo Electrical		La Union ES
3322	Work In Progress Yearly - La Union ES Emer. Light Test: Annual - Refer to PM schedule details. Routed to Sal	7/6/2005 Medium	Alfredo Holguin Salvador Gonzalez Fire Protection		La Union ES
3344	Work In Progress Yearly - La Union ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Salvador Gonzalez Fire Protection		La Union ES
3345	Work In Progress Yearly - Loma Linda ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott Fire Protection		Loma Linda ES
3323	Work In Progress Yearly - Loma Linda ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Michael Mc Dermott Fire Protection		Loma Linda ES
7361	Work In Progress REPLACE TIMER FOR BOILER	11/15/2005 Medium	Grace Alvarado Jose Ambriz Heating/Ventilation /Air Conditioning		Loma Linda ES
6686	Work In Progress INSTALL ELECTRICAL CIRCUIT IN ROOM 208 FOR MICROWAVE AND FRIDGE. Completed by Mike Mc Dermott as per Enrique	10/24/2005 Medium	Grace Alvarado Michael Mc Dermott General Maintenance		Loma Linda ES
8143	Work In Progress MIKE INSTALL OUTLET IN BOOKROOM	12/15/2005 Medium	Grace Alvarado Michael Mc Dermott General Maintenance		Loma Linda ES
9386	Work In Progress Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.	2/5/2006 Medium	Alfredo Holguin Michael Mc Dermott General Maintenance		Loma Linda ES
8647	Work In Progress NEED TO COMPLETE BUILDING INSPECTION FOR ALL CUSTODIANS TO INCLUDE CLOSET, MSDS, LABELED SPRAY BOTTLES & SAFETY EQUIPMENT. HEAD CUSTODIAN NEED TO INCLUDE INSPECTION ON YOU OWN AREA. INSPECTION REPORTS ALONG WITH COMPLETED & SIGNED WORK ORDER MUST BE RETURNED AND RECEIVED BY US NO LATER THAN JANUARY 27, 2006	1/11/2006 Medium	Aida Salcedo Luis Solis Custodial		Loma Linda ES
11463	Work In Progress NEED TO COMPLETE FLOOR PLAN ON YOUR WORK SCHEDULE.	4/20/2006 Medium	Aida Salcedo Luis Solis Custodial		Loma Linda ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9831	Work In Progress ATTN: PLUMBERS NEED KIT INSTALLED TO BOLT TOILET TO FLOOR & NEW BOWLI WAY. BOYS R.R. NORTHWEST WING. NEED SENSOR SINKS REPAIRED. 2ND REQUEST LEAKING VERY BADLY. BOYS RR SOUTH WEST WING. NEED NEW HOSE BIB INSTALLED IN COURTYARD BEHIND LIBRARY. OLD ONE WILL NOT CLOSE.	2/17/2006 Medium	Grace Alvarado Joe Ontiveros Plumbing		Loma Linda ES
9897	Work In Progress MIKE MCDERMOTT: REQUEST REPAIR OR REPLACEMENT OF VENETIAN BLINDS, PARTICULARLY WINDOW ON NORTH ISE OF EAST WALL ROOM 103 LET ME KNOW. AS PER MR. T.	2/21/2006 Medium	Grace Alvarado Ruben Ronquillo Glass\Window Repairs		Loma Linda ES
12424	Work In Progress 5-23-6 ATTN; MIKE MUNOZ SMALL PORTABLE NEEDS CARPET REPLACED.	5/23/2006 Medium	Michael Mc Dermott Michael Munoz Carpet Repair	Portables	Loma Linda ES SMALL POT.
12146	Work In Progress 5-4-6 8-hours paint entry way by computer room. 5/4 - 8	5/12/2006 Medium	Michael Mc Dermott Michael Mc Dermott Painting	Classroom	Loma Linda ES
11855	Work In Progress THE WATER SCENSOR IN THE GIRLS RESTROOM BY MR. PINA CLASSROOM #112 TURNS ON AND OFF BY IT SELT.	5/2/2006 Medium	Luis Solis Joe Ontiveros Plumbing		Loma Linda ES
11857	Work In Progress ONE OF THE WATERFOUNTAIN NEXT TO MR. GUZMAN CLASSROOM # 113 IS NOT WORKING ( NO WATER ).	5/2/2006 Medium	Luis Solis Lorenzo Solis Heating/Ventilation /Air Conditioning		Loma Linda ES
11860	Work In Progress THE TWO SECURITY LIGHTS LOCATED BEHIND THE CAFETERIA, ONE IS ABOVE BOILER ROOM AND THE OTHER IS ABOVE THE BACK DOOR KITCHEN ENTRANCE, BOTH LIGHTS ARE FLICKING.	5/2/2006 Medium	Luis Solis Michael Mc Dermott Electrical		Loma Linda ES
11863	Work In Progress THE TWO SECURITY LIGHTS AS YOU ENTER THE BUILDING, THE TOP RIGHT CORNER AND THE BOTTOM RIGHT HAND CORNER NEED TO BE REPAIR.	5/2/2006 Medium	Luis Solis Michael Mc Dermott General Maintenance		Loma Linda ES
11864	Work In Progress THE SECURITY LIGHT IN SOUTH SIDE ENTRANCE NEED TO BE FIX.	5/2/2006 Medium	Luis Solis Michael Mc Dermott General Maintenance		Loma Linda ES
11724	Work In Progress WE NEED AT LEAST (5) 55 GALS METAL TRASH CANS LIDS (BEE PROBLEMS). THANK YOU.	4/28/2006 Medium	Luis Solis Jimmy Carbajal Custodial		Loma Linda ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12819	Work In Progress NEEDING ALL CLASS ROOMS CHECKED FOR FLOURECENT LIGHTS TO BE WORKING. MAJORITY OF CLASSROOMS NEEDING REPLACEMENTS	6/7/2006 Medium	Grace Alvarado Michael Mc Dermott General Maintenance		Loma Linda ES
12909	Work In Progress WET AND DRY MACHINE NEEDS A NEW SQUEGEE.	6/9/2006 Medium	Luis Solis Jimmy Carbajal Custodial Equipment Repair		Loma Linda ES
12719	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
12924	Work In Progress manny,custodin, broken key please assit.	6/12/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
13266	Work In Progress please move furniture from Mesquite to La Mesa. Pancho will assist. Roma will only identify furniure. Please inventory what is moved and submitt with w.o when completer. Thanks	6/27/2006 Medium	Michael Munoz Danny Miranda General Maintenance		Mesquite ES
13347	Work In Progress ice machine not making ice to its capacity. thanx.	6/30/2006 Medium	Romauldo Apodaca Danny Orozco Food Services		Mesquite ES
11798	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
11788	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
11754	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	4/30/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Mesquite ES
12380	Work In Progress please trim mexican elders that are in front of campus and make wells around trees for watering.	5/22/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
12449	Work In Progress DRAIN RUNNING OVER IN THE LAUNDRY ROOM. LOCKER ROOM IS ALSO STARTING  ALICE F. SNP MGR 233-2341	5/24/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Mesquite ES
12529	Work In Progress manel,need to replace 3 lever handles on portables,please assist. thanx.	5/26/2006 Medium	Romauldo Apodaca Manny Lozoya Key and Lock		Mesquite ES
12527	Work In Progress need to install cooling ,heating unit in bldg. mech. and head custodial office, no system exsits. thanx.	5/26/2006 Medium	Romauldo Apodaca Lorenzo Solis Heating/Ventilation /Air Conditioning		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9937	Work In Progress DANNY MIRANDA, NEED DOOR HARDEWARE FOR CAFETERIA DOORS, AND MAIN DOORS. THANK.	2/23/2006 Medium	Romauldo Apodaca Danny Miranda Doors and Hardware		Mesquite ES
10252	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
10242	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
10208	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Mesquite ES
11462	Work In Progress NEED TO COMPLETE FLOOR PLAN ON YOUR WORK SCHEDULE.	4/20/2006 Medium	Aida Salcedo Ruben Solis Custodial		Mesquite ES
11635	Work In Progress need motor for exsaust fan electrical rm.thanx.	4/26/2006 Medium	Romauldo Apodaca Lorenzo Solis Heating/Ventilation /Air Conditioning		Mesquite ES
11103	Work In Progress need door frame and door for rm. 612,door in very bad conditon.thanx.	4/5/2006 Medium	Romauldo Apodaca Danny Miranda Doors and Hardware		Mesquite ES
8677	Work In Progress Portable 602 - Need vinyl flooring replaced w/ carpet, floor in bad shape,safety issue, someone may trip.	1/12/2006 Medium	Romauldo Apodaca Michael Munoz Carpet Repair	Portables	Mesquite ES
9135	Work In Progress Barracks - Remove rocks from roof and repair and secure water lines (safety issue).	1/30/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
9137	Work In Progress East of Library - Lots of weeds growing apply chemical, treat weeds ask for imput from Lupe so you wont kill trees.	1/30/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
9138	Work In Progress Pecan Trees in back parking lot - Trim branches, cut weeds around and make new wells and water.	1/30/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
9139	Work In Progress North Fence Line by Pine Trees - Cut weeds and pickup trash and treat fence line.	1/30/2006 Medium	Michael Munoz Romauldo Apodaca General Maintenance		Mesquite ES
6507	Work In Progress kiki, 5 rms w/ out lights need assistance.thanks. ARREGLAR PROBLEMA EN ALAMBRADO DE LUCES EN SALONES DE OLD WING.	10/18/2005 10/18/2005 Medium	Romauldo Apodaca Romauldo Apodaca Electrical		Mesquite ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3324	Work In Progress Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Mesquite ES
3346	Work In Progress Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.	7/6/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Protection		Mesquite ES
4015	Work In Progress Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
4005	Work In Progress Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca General Maintenance		Mesquite ES
3971	Work In Progress Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.	7/31/2005 Medium	Alfredo Holguin Romauldo Apodaca Fire Extinguishers		Mesquite ES
3461	Work In Progress Need a copy of control key (core) to keep here at the Maintenance Dept - as per A. Holguin.	7/12/2005 Medium	Alfredo Holguin Manny Lozoya Key and Lock		Physical Plant Complex
3380	Work In Progress Mens Restroom in Custodial Warehouse- Replace toilet tank cover with appropriate size for unit.	7/7/2005 Medium	Fred Appelzoller Plumbing	Restroom (Boys)	Physical Plant Complex
3379	Work In Progress Mens Restroom in Custodial Warehouse -Install new privacy lockset	7/7/2005 Low	Manny Lozoya Key and Lock	Restroom (Boys)	Physical Plant Complex
8737	Work In Progress NEED SPARE KEY FOR AIDA (TRUCK) - P1106 BB6	1/13/2006 Medium	Aida Salcedo Manny Lozoya Key and Lock		Physical Plant Complex
11574	Work In Progress please primer and paint barracks.	4/25/2006 Medium	Michael Munoz Danny Miranda Painting		Physical Plant Complex
9750	Work In Progress WILL NEED PLUMBING WORK DONE IN CUSTODIAL WAREHOUSE TO BE ABLE TO INSTALL NEW WASHER & DRYER - MUST BE DONE BY FEBUARY 24, 2005. 4/24/06 - Please assist Joe w/this work order.	2/16/2006 Medium	Aida Salcedo Joe Ontiveros Plumbing		Physical Plant Complex Custodial
12447	Work In Progress Need a key to Jimmy's Storage room. Please issue key to Alfredo Holguin.	5/24/2006 Medium	Alfredo Holguin Manny Lozoya Key and Lock		Physical Plant Complex Custodial
12386	Work In Progress THE DOOR FOR THE TECHNOLOGY WAREHOUSE - PROBLEM WITH LOCKING DOOR. SOMETIMES LOCKS SOMETIMES DOES NOT (IF YOU HAVE QUESTIONS PLEASE CALL CORA EXT. 6275)	5/22/2006 Medium	Cora Ramirez Manny Lozoya Key and Lock		Physical Plant Complex

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12231	Work In Progress need to replace light fixture covers at R.Ronquillo's office	5/16/2006 Medium	Carlos Castillo Carlos Castillo Electrical	Physical Plant Complex Office	Physical Plant Complex
11710	Work In Progress Need to get a/c's going.	4/27/2006 Medium	Michael Munoz Danny Orozco Food Services		Physical Plant Complex
11611	Work In Progress MR CARLOS CASTILLO SIR WILL NEED SEVERAL BOXS OF FLORCENT LAMPS WILL NEED BELEAST HALL WAY LIGHTS AND BULBS I THANK YOU SIR AND GOD BLESS	4/25/2006 Medium	Adan Duran Carlos Castillo Electrical		Riverside ES
12093	Work In Progress MR LUPE ONTIVEROS GROUNDS SIR WILL NEED FOUR DUMP TRUCKS LOADS OF CRUCHER FINE IN FRONT OF TRAILER WHERE MR HERNANDEZ LIVES WIND HAS BLOWN AWAY TOP SOIL AND PIPES ARE EXPOSE NEED TO COVER THEM UP AGAIN BEFORE THEY GET RUN OVER AND BROKEN I THANK YOU SIR AND GOD BLESS	5/10/2006 Medium	Adan Duran Guadalupe Ontiveros Grounds		Riverside ES
12028	Work In Progress MR MANNY LOZOYA SIR WE HAVE A CABLE LOCK STUCK WILL NOT OPEN NORTH EAST ENTRANCE ALL NEED TO RPLACE TWO PAD LOCK MESSED UP THANK YOU SIR AND GOD BLESS 7/7 - As per Mr. Sanchez 2nd Request to get this repaired.	5/9/2006 Medium	Adan Duran Manny Lozoya Key and Lock		Riverside ES
12096	Work In Progress MR DAVID VILLALOBOS SIR HAVE SEVERAL LEAKING FAUCETS THAT NEED REPLACING THREE WASH BAIN'S AND ONE SINK YOU WILL NEED TO LOOK AT THEM TO GET CENTERS THANK YOU SIR AND GOD BLESS	5/10/2006 Medium	Adan Duran David Villalobos Plumbing		Riverside ES
12293	Work In Progress New shelving installed. Carpet pulled away from wall to accommodate new shelving. Carpet needs to be trimmed and fitted around new shelving. For questions please call me (Phillip Medina) at 915-637-0141.	5/18/2006 Medium	Phillip Medina Michael Munoz Carpet Repair	Library	Riverside ES
12433	Work In Progress MR LUPE ONTIVEROS GROUNDS SIR PER REQUEST MR SANCHEZ WOULD LIKE THE RUN OFF DRAIN BEHIND THE SCHOOL TO BE CLEAN OUT FULL OF SAND AND TO HAUL OFF SAND PILE OUTSIDE OF DRAIN THANK YOU AND GOD BLESS	5/23/2006 Medium	Adan Duran Guadalupe Ontiveros Grounds		Riverside ES
12926	Work In Progress Need to assist Adan in removing boards from hallways, for contractor to paint.	6/12/2006 Medium	Alfredo Holguin Adan Duran General Maintenance		Riverside ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12917	Work In Progress MR CASTILLO SIR NEED TO REPLACE EXIT AND EMERG LIGHT IN GYM ONE UNIT ALSO WE HAVE TWO IN THE HALL WAY THAT NEEDS REPLACING THANK YOU SIR AND GOD BLESS	6/9/2006 Medium	Adan Duran Carlos Castillo Electrical		Riverside ES
12911	Work In Progress please cut and repair carpet area where shelves where installed.	6/9/2006 Medium	Michael Munoz Michael Munoz Carpet Repair		Riverside ES
12882	Work In Progress MR LUPE ONTIVEROS SIR PER MR SANCHES AND MR MUNOZ NEED A LEACHE LINE NORTH WEST SIDE OF NORTH WING DRAIN WATER FROM AC UNITS NOT GOING DOWN ITS TO WET AND IT STINKS LODO NEGRO THANK YOU SIR	6/8/2006 Medium	Adan Duran Guadalupe Ontiveros Grounds		Riverside ES
10175	Work In Progress DISHWASHER - WHERE THE SOAP GOES THRU IS CLOGGED UP.  NANCY ROLLIN SNP MGR 589-2550	3/3/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Riverside ES
5115	Work In Progress MR LUPE ONTIVEROS SIR WILL NEED THE USE OF THE BACKHOE TO MOVE SOCCOR GOAL POST AWAY FROM PARKING AREA UNSAFE FOR KIDS THANK YOU SIR	8/31/2005 Medium	Adan Duran Guadalupe Ontiveros Grounds		Riverside ES
5058	Work In Progress Carpet (Doorway) to Data clerk office is coming loose. Plastic edge is picking-up.. Thanks 6/8 - Route to Adan Duran as per Mike Munoz - mkv	8/30/2005 6/8/2006 Medium	Olga Arias Adan Duran General Maintenance		Riverside ES
5592	Work In Progress please see what can be done to repair or remove electrical outlet on floor on serving line. Outlet has a can over it and could be a trip hazard.	9/19/2005 Medium	Danny Orozco Food Services	Cafeteria	Riverside ES
3778	Work In Progress MR DAVID VILLALOBOS WE HAVE SOME LEAKING FUACTS NEW WING NEED REPAIR KIT OR REPLACEMENT THANK YOU SIR	7/22/2005 Medium	Adan Duran David Villalobos Plumbing		Riverside ES
4388	Work In Progress MR JOSE AMBRIZ SIR WE NEED TO HOOK BACK UP THE AIR IN WHAT USE TO BE MRS FLORES OFFICE IT WAS REMOVE AT HER REQUEST AND ITS KIND OF WARM IN THERE THANK YOU SIR	8/9/2005 Medium	Adan Duran Jose Ambriz Heating/Ventilation /Air Conditioning		Riverside ES
4445	Work In Progress Portable 29 - Needs to be secured by the end of the day.	8/10/2005 Medium	Danny Vega Manny Lozoya Key and Lock	Portables	San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
5270	Work In Progress NEED LDO 2QT/FLUSH VALVE KIT/DIAPRAHMS/TUB&SINK SEALER/ELONGATED TIOLET SEAT	9/6/2005 Medium	Danny Vega Joe Ontiveros Plumbing		San Miguel ES
6618	Work In Progress need two loads playground sand asap	10/21/2005 Medium	Danny Vega Guadalupe Ontiveros Grounds		San Miguel ES
8082	Work In Progress library toilet will not flush/we need to replace it	12/13/2005 Medium	Danny Vega Joe Ontiveros Plumbing		San Miguel ES
7632	Work In Progress The backflow prevention device on the irrigation distribution system needs to have the annual inspection performed. As per Lupe Ontiveros route to Lupe.	11/29/2005 Medium	Alfredo Holguin Ricardo Jacquez Sewage/Water Treatment Plant		San Miguel ES
7563	Work In Progress boys restroom heater coil leaks water/need replaced asap found leak and repaired it	11/28/2005 12/1/2005 Medium	Danny Vega Lorenzo Solis Heating/Ventilation /Air Conditioning		San Miguel ES
10433	Work In Progress NEED REPAIRS ON MARQUEE /PLEXY GLASS & FRAME DAMAGE BY WINDS/6FT X 6FT	3/10/2006 Medium	Danny Vega Ruben Ronquillo Glass\Window Repairs		San Miguel ES
11320	Work In Progress rm #32 need additional unit on window as per MR.Marrufo -/6500master-cool is to small	4/12/2006 Medium	Danny Vega Lorenzo Solis Heating/Ventilation /Air Conditioning		San Miguel ES
11075	Work In Progress Need nameplates for the following: Mr. Padilla Mr. Gonzales Mrs. Gonzales Mrs. Boucher Ms. Barraza Mrs. Tovar Ms. Porter PE Coach Ms. Sanchez Mrs. Nuñez Mrs. Henderson Ms Avalos Ms. O'Neill Mrs. Jackson Mrs. Jaramillo-Granados Ms. Brand Ms. Mendoza Mrs. Rhodes Ms. Reyes Mr. Villalobos Mrs. Gurrola Mrs. Ruiz Ms. Rodriguez Mr. Vega	4/4/2006 Medium	Barbara Cardenas Manny Lozoya Key and Lock		San Miguel ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11076	Work In Progress Need the following room numbers. #1, #2, #4, #5, #10, #12, #17, #19, #25, #26, #28, #34, #37, #42, #47, #49, #50, #51	4/4/2006 Medium	Barbara Cardenas Manny Lozoya Key and Lock		San Miguel ES
12886	Work In Progress need to borrow bobcat sweeper/clean-up parking lot to re -stripe	6/8/2006 Medium	Danny Vega Guadalupe Ontiveros Grounds		San Miguel ES
12722	Work In Progress Monthly - San Miguel ES Emer. Light Test: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Danny Vega General Maintenance		San Miguel ES
12734	Work In Progress Monthly - San Miguel ES Exit Sign Insp: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Danny Vega General Maintenance		San Miguel ES
12687	Work In Progress Monthly - San Miguel ES Monthly FE Inpsection - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Danny Vega Fire Extinguishers		San Miguel ES
12925	Work In Progress On/Off Switch broke off to Reach-In Refrigerator	6/12/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	San Miguel ES
13039	Work In Progress need sun city to replace (3) three windows clear safty glass/31 3/4 x14 3/4 rms#1-3-22 asap	6/16/2006 Medium	Danny Vega Ruben Ronquillo Glass\Window Repairs		San Miguel ES
13280	Work In Progress portable#32 a/c unit is not sufficent/need additional unit /2nd request	6/27/2006 Medium	Danny Vega Lorenzo Solis Heating/Ventilation /Air Conditioning		San Miguel ES
13279	Work In Progress portable #37 ramp needs to be level/door will not open properly/safety hazard	6/27/2006 Medium	Danny Vega Michael Munoz Ramps/Platforms		San Miguel ES
13278	Work In Progress need three loads playground sand /one load on leech field rutts/potholes	6/27/2006 Medium	Danny Vega Guadalupe Ontiveros Grounds		San Miguel ES
13282	Work In Progress need to replace west gate wheels/please order	6/27/2006 Medium	Danny Vega Ruben Ronquillo General Maintenance		San Miguel ES
12025	Work In Progress a/c ducting rotted-out fr previous water leaks/interior-exterior complains fr staff /it smells.rm#32	5/9/2006 Medium	Danny Vega Lorenzo Solis Heating/Ventilation /Air Conditioning		San Miguel ES
11686	Work In Progress need to replace basket strainer in copy rm sink/leaking all over/double sink type	4/27/2006 Medium	Danny Vega Joe Ontiveros Plumbing		San Miguel ES
11912	Work In Progress CALI; NEED FOR YOU TO PLEASE ORDER BALSASTS AND BULBS FOR STE. THANKS.	5/3/2006 Medium	Gerardo Marquez Carlos Castillo Electrical		Santa Teresa ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11913	Work In Progress LUPE; NEED FOR YOU TO SEND ME A COUPLE TRUCKLOADS OF SAND FOR P.G.AREAS. LEVELS ARE LOWER THAN THE 1' REQUIREMENTS. THANKS.	5/3/2006 Medium	Gerardo Marquez Guadalupe Ontiveros Grounds		Santa Teresa ES
11827	Work In Progress CALI, NEED FOR YOU TO ORDER ME BALLASTS AND BULBS BOR STE. ALSO NEED FOR YOU TO CHECK OUT EMERG. LIGHTS THAT FAILED ON LAST TEST.	5/1/2006 Medium	Gerardo Marquez Carlos Castillo Electrical		Santa Teresa ES
12824	Work In Progress MANNY, NEED FOR YOU TO MAKE A NEW KEY FOR TEACHER IN RM. 301. REQUESTED BY RITA MENDEZ.	6/7/2006 Medium	Gerardo Marquez Manny Lozoya Key and Lock		Santa Teresa ES
13287	Work In Progress BROKEN WINDOW ON ROOM #4, NEED TO HAVE IT REPLACED BROKEN. WAITING FOR CASE# THE SIZE IS 29 5/8 BY 32 5/8. (VANDALIZM). THANK YOU.	6/8/2006 Medium	Arturo Nunez Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS
12883	Work In Progress side backboards do not go up or down and volley sleeves need covers.(4)	6/8/2006 Medium	Michael Munoz Michael Munoz Equipment	Gym	Santa Teresa HS
12688	Work In Progress Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Arturo Nunez Fire Extinguishers		Santa Teresa HS
12694	Work In Progress Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Santa Teresa HS
13246	Work In Progress NEED LOCKS TO BE CHANGE FROM GYM DOORS FLOORS ARE GOING TO BE DONE ON JULY 15-06 THANK YOU.	6/26/2006 Medium	Luis Murillo Manny Lozoya General Maintenance		Santa Teresa HS
13151	Work In Progress NEED ROPE TO REPLACE EXISTING ROPE ON FLAG POLES. 3/8" THICK BY 70' LONG.	6/22/2006 Medium	Arturo Nunez Ruben Ronquillo Equipment		Santa Teresa HS
13259	Work In Progress As per M.Munoz need to check foot ballfield lighting for proper operation.	6/27/2006 Medium	Carlos Castillo Carlos Castillo Electrical	Football Field	Santa Teresa HS
13351	Work In Progress SPRITE WET -N- DRY S-N- 1372815 SWITCH WILL NOT TURN MACHINE ON THANK YOU.	6/30/2006 Medium	Luis Murillo Jimmy Carbajal Custodial		Santa Teresa HS
13353	Work In Progress WATER NOT COMEING OUT OF ADVANCE EXTRACTOR SEARIAL* 009109 THANK YOU.	6/30/2006 Medium	Luis Murillo Jimmy Carbajal Custodial		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
13041	Work In Progress BROKEN WINDOW ON ROOM #4, NEED TO HAVE IT REPLACED , SAME WINDOW THAT WAS BROKEN A COUPLE OF WEEKS AGO. THE SIZE IS 29 5/8 BY 32 5/8. (VANDALISM). THANK YOU. Art called Suncity Glass	6/16/2006 Medium	Arturo Nunez Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS
13044	Work In Progress BROKEN OUTSIDE DOOR'S GLASS ON ELECTRICAL ROOM AT THE NEW CAFETERIA SINGLE GLASS SIZE 16X72 INCHES	6/16/2006 Medium	Joel Herrera Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS
13048	Work In Progress BROKEN WINDOW AT ROOM #22, NEEDS TO BE REPAIRED.36"BY 22". THANK YOU. (VANDALISM.)	6/16/2006 Medium	Arturo Nunez Ruben Ronquillo Glass\Window Repairs		Santa Teresa HS
13027	Work In Progress need to paint new doors and frame by gym.	6/15/2006 Medium	Danny Miranda Arturo Nunez Painting		Santa Teresa HS
13050	Work In Progress Senior Hallway - Would like it repainted during the summer as per Maria Zamora, Senior Class President.	6/16/2006 Medium	Ralph Gallegos Arturo Nunez Painting	Hallway/Corridor	Santa Teresa HS
13043	Work In Progress NEED TO HAVE CIRCUIT TO A.C. UNIT ON ROOM #12, NO POWER TO UNIT. CONTRACTORS MIGHT HAVE DISCONNECTED POWER TO UNIT, DURING THE CONSTRUCTION PHASE. THANK YOU	6/16/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
12923	Work In Progress NEED TO HAVE ELEC. CIRCUIT ON BAND ROOM, AND CHROUS CHECKED THERE SEEMS TO BE AN ELEC. SHORT ON ONE OF THE LINES. NEED TO HAVE IT CHECKED. WARRANTY MAY STILL COVER IT.	6/12/2006 Medium	Arturo Nunez David Boyd Construction		Santa Teresa HS
12918	Work In Progress NEED TO HAVE CHILLER CHECKED GIVING A LOW REFRIF. PRESSURE DIAGNOSTIC. SUCTION REFRI. TEMPS SEEM TO LOW TO ME. WASHED OUT COILS TO SEE IF IT WAS THAT THE COILS WERE DIRTY, BUT PRESSURES DIDN'T CHANGE MUCH. COULD WE PLEASE HAVE THEM CHECKED. THANK YOU.	6/9/2006 Medium	Arturo Nunez David Boyd Construction		Santa Teresa HS
11961	Work In Progress need to redo floor in rotc restroom boys s. t. h.s. 6/8 Route to Gerry as per Mike.	5/5/2006 Medium	Danny Miranda Gerardo Marquez General Maintenance		Santa Teresa HS
12011	Work In Progress BLEACHERS NEED TO BE CLEANED.  PLEASE NOTIFY AIDA WHEN PROCEDURE IS COMPLETED SO AN INSPECTION CAN BE DONE.	5/8/2006 Medium	Aida Salcedo Luis Murillo Custodial		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11639	Work In Progress WE NEED REPLACE STOP VALBULAS AT BOYS REST ROOM AT MATH WING AREA.	4/26/2006 Medium	Joel Herrera David Villalobos Plumbing		Santa Teresa HS
11916	Work In Progress NEED TO CHANGELOCK TO M115 OFF MASTER SAME KEY AS STORAGE ROOM IN MAIN LOBBY.	5/3/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
12415	Work In Progress please paint gym as per Mr.Gallegos	5/23/2006 Medium	Michael Munoz Arturo Nunez Painting	Gym	Santa Teresa HS
12609	Work In Progress EXTERMINATION OF DAYCARE DUE TO EXCESSURE RED + BLACK ARTS.	5/31/2006 Medium	Joel Herrera Margret Villalobos Pest Control		Santa Teresa HS
12604	Work In Progress MARYLOU WANTS TO CHANGE LOCK TO M115- OFF MASTER SAME KEY TO STORAGE ROOM IN MAIN LOBBY.	5/31/2006 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
12136	Work In Progress please talk to Calixto about the power in the IDF room	5/11/2006 Medium	Cora Ramirez Carlos Castillo Electrical	Electrical Room	Santa Teresa HS
12248	Work In Progress NEED ONE CASE OF MULTI VOLTAGE LIGHT BALAST , TWO, THREE, AND FOUR BULBS. TEN (10) T-8 LIGHT BULBS.	5/16/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
12250	Work In Progress NEED DEAD BOLT INSTALLED ON DOORS ON D.O.L. PORTABLE , KEYED THE SAME AS THE EXISTING ONE.	5/16/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
12249	Work In Progress NEED TO FUMIGATE DAYCARE, BUGS SEEM TO BE A PROBLEM ON PLAY ROOM, KITCHEN, AND BABY ROOM.	5/16/2006 Medium	Arturo Nunez Margret Villalobos Pest Control		Santa Teresa HS
11091	Work In Progress NEED SOME LIGHTS INSTALLED ON EXHAUST FAN HOOD THAT WAS INSTALLED ON WELDING SHOP. TO DARK UNDER HOOD.	4/4/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
11105	Work In Progress URGENTE; A/C IS LEACKING WATER PAN IS VERY RUSTING WE CAN'T USED NO MORE WE NEED REPLACE IT AT MS.CHAVES' OFFICE	4/5/2006 Medium	Arturo Nunez Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa HS
10780	Work In Progress NEED CALI TO COME AND SEE WHAT NEEDS TO BE DONE FOR WASHER AND DRIER HOOK UP AT TRAINERS OFFICE. APPLIANCES ARE ON ORDER AS PER TRAINER.	3/28/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10781	Work In Progress NEED SIX (6) EA. 50A 125/250 PLUGS FOR WELDING SHOP, WOULD LIKE TO USE ONE TYPE OF PLUG FOR OUTLETS SO THAT WELDING MACHINES CAN BE USED ANY WHERE IN THE ROOM.	3/28/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
11264	Work In Progress NEED MR. CASTILLO TO ASSIST ME ON ELEC. PROBLEM ON GYM. A.C. NOT GETTING POWER TO MOTOR, ALREADY TROUBLE SHOOT, CAN'T SEEM TO FIND THE PROBLEM.	4/11/2006 Medium	Joel Herrera Carlos Castillo Electrical		Santa Teresa HS
11201	Work In Progress NEED SIX (6) EA. SENSORS FOR LABATORIES AT DRESSING ROOMS.	4/7/2006 Medium	Arturo Nunez David Villalobos Plumbing		Santa Teresa HS
11461	Work In Progress LUIS- NEED TO ISSUE AND SPREAD OUT ALL EQUIPMENT THAT HAD BEEN ISSUED TO YOU ( EX. LADDERS, EXTENSION CORDS, DOLLIES, ECT). SEPARATE THRU OUT ALL AREAS OF CUSTODIAL CLOSETS FOR EASY ACCESS TO THEM.	4/20/2006 Medium	Aida Salcedo Luis Murillo Custodial		Santa Teresa HS
10217	Work In Progress Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.	3/5/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Santa Teresa HS
10724	Work In Progress NEED TO DO TRAINING ON CLEANING RESTROOMS, USING CHEMICALS & EQUIPMENT AND TIME MANAGEMENT FOR: JAVIER PARRA, RAFAEL MERA, MARIA DE SANTIAGO & OSCAR ESPARZA	3/27/2006 Medium	Aida Salcedo Guillermo Hernandez Custodial		Santa Teresa HS
10730	Work In Progress NEED TO TRAIN: JAVIER PARRA, RAFAEL MERA, MARIA DE SANTIAGO & OSCAR ESPARZA ON USING ROTO & BURNISHER MACHINES	3/27/2006 Medium	Aida Salcedo Sal Acuna Custodial		Santa Teresa HS
10635	Work In Progress NEED 70 WATTS METAL HALIDE BULBS # M143/E TWELVE (12) EA. FOR NEW ADDITION, OUTSIDE LIGHTS.	3/17/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
10537	Work In Progress NEED EIGHT (8) FLO. LIGHT BULBS FOR MARQUEE, IT IS NOT LIGHTING, WOULD LIKE TO HAVE IT LIT.	3/15/2006 Medium	Joel Herrera Carlos Castillo Electrical		Santa Teresa HS
10975	Work In Progress Monthly - Santa Teresa HS Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
10415	Work In Progress NEED TO REPLACE FOUR (4) FLO. LIGHT BULB FIXTURES ON CAGE STORAGE HALLWAY.	3/10/2006 Medium	Arturo Nunez Carlos Castillo Electrical		Santa Teresa HS
9999	Work In Progress please repair the wood that is breaking off the dugouts. Thanks	2/24/2006 Medium	Guadalupe Ontiveros Grounds	Athletic Field	Santa Teresa HS
9623	Work In Progress DOOR KNOB IN COUSELORS OFFICE, SOUTH SIDE DOOR,CLINDER IS BROKEN THEY CAN'T OPEN DOOR WITH THEIR KEY. WOULD LIKE TO HAVE LOCKSMITH HELP US WITH THIS SITUATION. REPAIR CYLINDER AT COUNSELORS OFFICE	2/13/2006 1/16/2006 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
7840	Work In Progress NEED FIVE (5) LOCKS 6" SLIDE LOCKING HASP	12/5/2005 Medium	Arturo Nunez Manny Lozoya Key and Lock		Santa Teresa HS
8157	Work In Progress MR. GALLEGOS WANTS DEADBOLT ON BOYS AND GIRLS DRESSING ROOMS 2- NEED TO CHANGE DOOR KNOBS TO BE ABLE TO LOCK THE WORK ROOM BETWEEN THE BAND AND CHORUS ROOM 3- AND NEED TO CHANGE ONE ENTRY KEY TO THE RESTROOMS FROM THE MEETINS ROOM. 12/15 - 5	12/15/2005 12/15/2005 Medium	Joel Herrera Manny Lozoya Key and Lock		Santa Teresa HS
7194	Work In Progress ADULT RESTROOM IN OFFICE AREA NEEDS TO BE PAINTED.	11/8/2005 Medium	Aida Salcedo Arturo Nunez General Maintenance		Santa Teresa HS
5923	Work In Progress MIKE MUNOZ WE NEED BARRIER FENCE ON WEST SIDE AT SOCCER FIELD TO RETAIN BALLS OUT IT PLAY . ALSO NEED FENCE FROM 20 YARD LINE TO 20 YARD LINE IN FRONT OF FOOTBALL VISITORS SEATING AREA. SEE R GALLEGOS THANK YOU MIKE...	9/28/2005 Medium	Joel Herrera Guadalupe Ontiveros Grounds		Santa Teresa HS
4966	Work In Progress RUBEN WE NEED REPAIR THE WINDOWS AT DAYCAREBUILDING IT DOESN'T OPEN THANK YOU Route to Joel as per Mike 9/12/05 - mkv	8/26/2005 Medium	Joel Herrera Joel Herrera General Maintenance		Santa Teresa HS
4463	Work In Progress SENER ON SINCK AT GIRLS REST ROOM IT DOESN'T WORK WE REPLACE IT .	8/11/2005 Medium	Joel Herrera David Villalobos Plumbing		Santa Teresa HS
4484	Work In Progress please install venting system and exhaust hood in the metal shop. See Joe Angelo.	8/11/2005 Medium	Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa HS
3571	Work In Progress NEED CONDENSER MTR. FOR SNACK ROOM A.C. UNIT, MTR. IS FROZEN UNIT IS DOWN.	7/15/2005 Medium	Arturo Nunez Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa HS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3387	Work In Progress Rm 1. N. bldg lower level Removal of carpet is going to require tile installation. Alfredo H. requested a work order for contractor.	7/7/2005 Medium	Jaime Mijarez Michael Munoz Carpet Repair		Santa Teresa MS
3353	Work In Progress Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details. I was not familiar with this type of testing (pending)	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez Fire Protection		Santa Teresa MS
3412	Work In Progress S.bldg upper level. Because of the shortage of classrooms Mrs. williams has to move the teachers lounge to a storage rm. The floor has no tile, can you include this room with the area's that the contractor will be installing floor tile. Attn: Alfredo holguin.	7/8/2005 Medium	Jaime Mijarez Michael Munoz Carpet Repair		Santa Teresa MS
3330	Work In Progress Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details. I was not familiar with this type of testing (pending)	7/6/2005 Medium	Alfredo Holguin Jaime Mijarez Fire Protection		Santa Teresa MS
3364	Work In Progress S.bldg custodial storage. please make 2ea. A-7 keys for principal and building mechanic.	7/6/2005 Medium	Jaime Mijarez Manny Lozoya Key and Lock		Santa Teresa MS
3118	Work In Progress I NEED FOR GYM KEY CYLINDERS TOO TO BE CHANGE BEFORE 7/13/05.CONT.MR.RODRIGUEZ.	7/1/2005 Medium	Ismael Rodriguez Manny Lozoya Key and Lock		Santa Teresa MS
5113	Work In Progress AIR CONDITIONER DOES NOT TURN ON THE LEFT SIDE OF THE ROOM FACING CHALK BOARD ROOM 3 MR. DORANTES	8/31/2005 Medium	Laura Parra Jose Ambriz Heating/Ventilation /Air Conditioning	Classroom	Santa Teresa MS
5363	Work In Progress N.bldg maintenance and custodial. Would like a duct and register installed on heat pump.	9/9/2005 Medium	Jaime Mijarez Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa MS
5329	Work In Progress North & South - I lost communication to both buildings and i am getting constant calls of hot areas. I am getting a message of an error on the IP address. e-mailed Jaime for status of wo 11/8/05 South Bldg was taken care of by replacing comm wire. Completed by Trane during the Fall Break (10/4 - 10/6). North Bldg is still having comm failures in upper level. Need to replace comm wire also reference wo 2957 (pending)	9/8/2005 10/4/2005 Medium	Jaime Mijarez Margret Villalobos Energy Management System		Santa Teresa MS
8556	Work In Progress Kitchen #1- Sink is clogged unable to use Kitchen #4- Pipes under sink leak	1/9/2006 Medium	Laura Parra David Villalobos Plumbing	Classroom	Santa Teresa MS room 10

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9776	Work In Progress s.t.m.s. need to paint new doors in front of gym	2/16/2006 Medium	Danny Miranda Jaime Mijarez Painting		Santa Teresa MS
9777	Work In Progress s.t.m.s. need to paint new door at music room	2/16/2006 Medium	Danny Miranda Jaime Mijarez Painting		Santa Teresa MS
11592	Work In Progress Please get a quote fror acucore for penetration of wall in electrical room.Thanks contact person J.Mijarez	4/25/2006 Medium	Michael Munoz Danny Miranda General Maintenance	Classroom	Santa Teresa MS
11418	Work In Progress North office area need to replace carpet.	4/19/2006 Medium	Michael Munoz Michael Munoz Carpet Repair	Office	Santa Teresa MS
12112	Work In Progress N.bldg and S.bldg restrooms. Most of the plumbing is old and leaking. Please order 10 ea. single water regulating sink faucets, 6 ea. 4" in. water regulating sink faucets, 10 ea. 1 1/2" sink traps, 5ea. flush valve repair kits, 5 ea. handle kit, 5 ea. vaccume breaker kits, 2 ea. 1 1/2" or 2" plugs to plug drains where I removed office water fountains.	5/11/2006 Medium	Jaime Mijarez David Villalobos Plumbing		Santa Teresa MS
12244	Work In Progress NEED TO FIX GEARS ON GATOR NOT WORKING.	5/16/2006 Medium	Guadalupe Ontiveros Bobby Aldaz Grounds		Santa Teresa MS
12515	Work In Progress South bldg speech office door. Please install lock on door inside of office to lock when session is in progress.	5/25/2006 Medium	Jaime Mijarez Manny Lozoya Key and Lock		Santa Teresa MS
12514	Work In Progress North and South bldg office copy rooms. Build a wall covered with sheetrock,taped,plastered and painted to seal up sliding door openings. These sliding doors are old and not being used anymore. This will provide more privacy to two of the offices. There is two entrances to the copy rooms and we only need one.	5/25/2006 Medium	Jaime Mijarez Michael Munoz General Maintenance		Santa Teresa MS
11907	Work In Progress N.bldg electrical room need break wall penetrations and install ducts to supply cooling only from home ec. room.	5/3/2006 Medium	Jaime Mijarez Jose Ambriz Heating/Ventilation /Air Conditioning		Santa Teresa MS
12076	Work In Progress BLEACHERS NEED TO BE CLEANED DURING GYM FINISHING.  PLEASE NOTIFY AIDA KNOW WHEN THIS TASK IS COMPLETED SO INSPECTION CAN BE DONE.	5/10/2006 Medium	Aida Salcedo Ismael Rodriguez Custodial		Santa Teresa MS
11906	Work In Progress Mr. Hinojos portable rm. Please install a dead bolt lock to secure entrance door.	5/3/2006 Medium	Jaime Mijarez Manny Lozoya Key and Lock		Santa Teresa MS

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
11908	Work In Progress Building lighting. PLease order 20 boxes of flourescent light bulbs, and 10 ea. 277v. ballasts. Attn: Carlos Castillo.	5/3/2006 Medium	Jaime Mijarez Carlos Castillo Electrical		Santa Teresa MS
13325	Work In Progress Manny on this date 6/17/06 i will be doing the gym , so I need for to change the gym cylinders.Thank you.	6/29/2006 Medium	Ismael Rodriguez Manny Lozoya Key and Lock		Santa Teresa MS
12689	Work In Progress Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Jaime Mijarez Fire Extinguishers		Santa Teresa MS
12661	Work In Progress Need door checked as per Paula.	6/2/2006 Medium	Margret Villalobos Manny Lozoya Key and Lock	Cafeteria	Santa Teresa MS
12727	Work In Progress Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Jaime Mijarez General Maintenance		Santa Teresa MS
12745	Work In Progress NEED TO ASSIST TRANE TO RUN NEW CONTROL WIRE FOR AC SYSTEM.	6/5/2006 Medium	Carlos Castillo Carlos Castillo Electrical	Mechanical Room	Santa Teresa MS
12747	Work In Progress Door in counselor's office does not lock.  Filing cabinet needs a key.	6/5/2006 Medium	Laura Parra Manny Lozoya Key and Lock	Office	Santa Teresa MS
12737	Work In Progress Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.	6/4/2006 Medium	Alfredo Holguin Jaime Mijarez General Maintenance		Santa Teresa MS
12787	Work In Progress 2 bottom ovens are NOT holding temperature  Marina Ramirez - SP Manager 589-2545	6/6/2006 Medium	Alma Terrell Danny Orozco Food Services	Cafeteria	Sunland Park ES
12656	Work In Progress Need two keys for padlocks inside.	6/2/2006 Medium	Sebastian Diaz Manny Lozoya Key and Lock		Sunland Park ES
13200	Work In Progress CUT GRASS ALL AROUND CAMPUS	6/22/2006 Medium	Margret Villalobos Manuel Prospero General Maintenance		Sunland Park ES ALL CAMPUS GROUNDS
12910	Work In Progress 6/9/06. SIX BIG BAGS OF FERTILIZING. 10 LBS GRASS SEED. (GROUNDS). AS PER LUPE ONTIBEROS.	6/9/2006 Medium	Manuel Prospero Guadalupe Ontiveros Grounds		Sunland Park ES



WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
12032	Work In Progress Jimmy, I need the following:  1. Cordless Drill 2. 1 set of screwdrivers 3. 1 set of pliers 4. 1 hammer 5. 1 set of wrenches  Thank you, Larry Flores	5/9/2006  Medium	Larry Flores Jimmy Carbajal  Custodial		Sunland Park ES
11979	Work In Progress 40 quart mixer is rotating too slow, had to go to Desert View Elementary to grate cheese  Marina Ramirez - SNP Manager 589-2545	5/5/2006  Medium	Alma Terrell Danny Orozco  Food Services	Cafeteria	Sunland Park ES
11619	Work In Progress Need three loads of sand in the kinder playground thank you	4/25/2006  Medium	Sebastian Diaz Guadalupe Ontiveros  Grounds		Sunland Park ES
11617	Work In Progress Need to replace overload in the water fountain southside in the hall thank you	4/25/2006  Medium	Sebastian Diaz Jose Ambriz  Heating/Ventilation /Air Conditioning		Sunland Park ES
9985	Work In Progress PORTABLE A & B NEED THE FLOOR TILE TO BE REPLACED.	2/24/2006  Medium	Irene Trujillo Michael Munoz  Carpet Repair		Sunland Park ES
9834	Work In Progress Need to remove sand by the south area with the heavy tractor. thank you.	2/17/2006  Medium	Sebastian Diaz Guadalupe Ontiveros  Grounds		Sunland Park ES
9120	Work In Progress 1.3 compartment sink is leaking 2. right side of serving line (cold unit) is not working. and 3. Blodgett Oven is still not heating properly  Marina Ramirez - SNP Manager 589-2545	1/27/2006  Medium	Alma Terrell Danny Orozco  Food Services	Cafeteria	Sunland Park ES
9214	Work In Progress need borders for playground S.P.E.	2/1/2006  Medium	Danny Miranda Guadalupe Ontiveros  Grounds		Sunland Park ES
6625	Work In Progress Need Heavy Duty Dolly for fire proof file cabinet on Monday October 24, 2005	10/21/2005  Medium	Larry Flores Maria Sitters  Custodial		Sunland Park ES
6692	Work In Progress Need 4 metal blinds for portable F 46"X 52" thank you.	10/24/2005  Medium	Sebastian Diaz Ruben Ronquillo  General Maintenance		Sunland Park ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
9916	Work In Progress REQUESTING WIND SCREENING FOR BACK FENCING AREA LOCATED NEAR LIFT STATION AREA IS WHERE WIND SREENING NEEDS TO BE REPLACED	2/22/2006 Medium	Paul Quinones Ruben Ronquillo General Maintenance		Sunrise ES
11494	Work In Progress need to cut fence and install 2 new swing gates on south end of campus by lift station	4/21/2006 Medium	Michael Munoz Michael Munoz Fence Repair		Sunrise ES
10829	Work In Progress REQUESTING AIR FILTERS FOR THE UNITS IN CLASSROOMS FOR PM SCHEDULING. 6/8 Routed to Ruben as per Lorenzo	3/30/2006 Medium	Paul Quinones Ruben Ronquillo General Maintenance		Sunrise ES
12077	Work In Progress 1. AIR CONDITIONER IS OUT - MOTOR NOT RUNNING  2. SLICER IS OUT OF ORDER  MARGIE TORRES - SNP MANAGER 824-3194 Route to Paul as per Mike 5/11 - mkv	5/10/2006 Medium	Alma Terrell Paul Quinones General Maintenance	Cafeteria	Sunrise ES
12513	Work In Progress REQUESTING DRY CHEMICAL FIRE EXTINGUISHERS A,B,C TYPE.INCLUDING HOSE,AND HORN 16LB.FOR PORTABLES TOTAL OF 10 ARE NEEDED. THANK YOU	5/25/2006 Medium	Paul Quinones Ruben Ronquillo Fire Extinguishers		Sunrise ES
12509	Work In Progress REQUESTING NEW KEYS,AND LOCKS FOR PORTABLES	5/25/2006 Medium	Paul Quinones Manny Lozoya Key and Lock		Sunrise ES
12182	Work In Progress New Portables - A/S/A/P Start dirt patches for platform not for stairs (pads if needed) and leave a 2 feet surrounding area around platform and installation of ramps and platforms. (If you have any questions call Mike Munoz)	5/15/2006 Medium	Michael Munoz Guadalupe Ontiveros Grounds	Portables	Sunrise ES
13328	Work In Progress REQUESTING KEYS FOR ROOM 206,AS PER PRINCAPLES REQUEST,AND OFFICE PERSONAL	6/29/2006 Medium	Paul Quinones Manny Lozoya Key and Lock		Sunrise ES
12862	Work In Progress BACK FENCE LINE WIND SCREEN NEEDS TO BE REPLACED 500 FT.	6/8/2006 Medium	Paul Quinones Ricardo Jacquez Sewage/Water Treatment Plant		Sunrise ES
12866	Work In Progress CLASSROOM 307 NOT COOLING	6/8/2006 Medium	Paul Quinones Jose Ambriz Heating/Ventilation /Air Conditioning		Sunrise ES

WOID	Status Description Action Taken	Request Date Completion Date Priority	Requester Assigned To Craft	Area Type	Location Area Number
3469	Work In Progress FENCING AREA IN BACK OF SCHOOL NEAR LIFT STATION NEEDS TO BE REPAIRED,AND ROLL GATE.PROBABLE HIGH WINDS ON 7-11-05 CAUSED THE DAMAGE.NO SIGNS OF VANDILISM ON SCHOOL PROPERTY 6/5/06 - Route to R. Jacquez as per Mike Munoz	7/12/2005 Medium	Paul Quinones Ricardo Jacquez Sewage/Water Treatment Plant		Sunrise ES
3629	Work In Progress please cut and weedeat in and aroud lift station. weeds are growing rapid and are going to end up on the playing fields.	7/18/2005 Medium	Paul Quinones Grounds		Sunrise ES
13047	Work In Progress Install cobblestones at points where water runoff enters the ponding areas. Eroison is starting to cut into pavement. As per Mike route to Lupe. 6/20/06 - mkv	6/16/2006 Medium	Alfredo Holguin Guadalupe Ontiveros Grounds		Vado ES
12062	Work In Progress Need to spray all classrooms in building.	5/10/2006 Medium	Danny Miranda Margret Villalobos Pest Control		Vado ES
11670	Work In Progress Rooms 108 A-Wing & 209 B-Wing - Units are not working properly in these two rooms.	4/27/2006 Medium	Lorenzo Solis David Boyd Construction		Vado ES
10979	Work In Progress Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.	4/2/2006 Medium	Alfredo Holguin Danny Orozco Fire Sprinkler System		Vado ES
11541	Work In Progress WARRANTY WORK NEED TO REPAIR AUTO DOOR OPENER SOUTH EXIE	4/24/2006 Medium	Danny Miranda David Boyd Construction		Vado ES
10422	Work In Progress Need RFP panels for walls by classrooms	3/10/2006 Medium	Frank Lara David Boyd Construction		Vado ES
10427	Work In Progress 100 Wing - Room 106 Need new exit sign for back door the one there does not work.	3/10/2006 Medium	Danny Miranda David Boyd Construction		Vado ES
10622	Work In Progress WOULD LIKE A DOOR BELL INSTALL TO THE BACK DOOR FOR DELIVERIES. UNABLE TO HEAR ANYONE AT THE BACK DOOR. LAURA B. SNP MGR 233-2945	3/17/2006 Medium	Jacqueline Aguilar Danny Orozco Food Services	Cafeteria	Vado ES