

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Alma Del Valle Daycare							
32043					2/29/2008		124		\$0.00
Medium	Work In Progress				2/29/2008 2:31:22 PM				
Ramirez, Joe	joe as per our conversation, please move washer and drier and also stove and store at Lamesa.								
Michael Munoz									
Count: 1 Work Orders		Avg. Age of WO's	124		Total for Alma Del Valle Daycare		0		\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
24366					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:48 AM				
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
<u>Alfredo Holguin</u>									
25385	Main Building	Custodial			8/3/2007		334		\$0.00
Medium	Work In Progress				8/3/2007 11:57:08 AM				
Gonzales, Angel		repair weed eater							
<u>David Vega</u>									
27868	Main Building	Office			10/4/2007		272		\$0.00
Medium	Work In Progress				10/4/2007 11:04:20 AM				
Lozoya, Manny		WE WILL BE NEEDING TO CHANGE THE LOCK FOR THE SUPPLY ROOM IN THE MAIN AND PRIMARY BUILDING. WE WILL BE NEEDING 9 ADDITIONAL KEYS. IF YOU HAVE ANY QUESTIONS PLEASE FREE TO CONTACT ME.							
<u>Loraine Gandara</u>									
28350					10/19/2007		257		\$0.00
Medium	Work In Progress	Anthony On Track			10/19/2007 4:48:27 PM				
Ronquillo, Ruben		Blinds for windows (6) in office portable and in two classrooms. 4- 47 x 37 2- 33 x 62							
<u>Lucy Meza</u>									
28492	Dona Ana	Office			10/24/2007		252		\$0.00
Medium	Work In Progress				10/24/2007 3:14:21 PM				
Lara, Ralph		Need to charge locks for p.e and office							
<u>Hector Villalobos</u>									
28563		Classroom			10/25/2007		251		\$0.00
Medium	Work In Progress	Pre - K			10/25/2007 3:46:59 PM				
Ronquillo, Ruben		P.R.E.K headstart rooms 306 307 blinds 12 63x54							
<u>Hector Villalobos</u>									
29151	Original Main	Classroom			11/13/2007		232		\$0.00
Medium	Work In Progress				11/13/2007 9:07:01 AM				
Lozoya, Manny		WE NEED AN KEYS FOR ROOM 206 SPEECH ROOM...							
<u>Loraine Gandara</u>									
29390	Chapter I	Classroom			11/26/2007		219		\$0.00
Medium	Work In Progress				11/26/2007 8:21:25 AM				
Lozoya, Manny		Chapter blg music room borken lock can not open							
<u>Hector Villalobos</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
29811		Portables			12/4/2007		211		\$0.00
Medium	Work In Progress			12/4/2007 3:02:11 PM					
Lozoya, Manny		PT219 need a key made for filing cabinet							
Hector Villalobos									
29812		Portables			12/4/2007		211		\$0.00
Medium	Work In Progress			12/4/2007 3:04:29 PM					
Lozoya, Manny		Headstrat pt 1 need a key made for filing cabinet							
Hector Villalobos									
29903	Original Main	Office			12/7/2007		208		\$0.00
Medium	Work In Progress			12/7/2007 9:39:26 AM					
Lozoya, Manny		Old main blg new office cabinet and filing cabinet need keys made							
Hector Villalobos									
30908					1/24/2008		160		\$0.00
Medium	Work In Progress			1/24/2008 11:02:52 AM					
Lozoya, Manny		Provide me with a list of individuals who have keys to the gates on this campus							
Alfredo Holguin									
31029	Main Building	Classroom			1/29/2008		155		\$0.00
Medium	Work In Progress			1/29/2008 2:32:28 PM					
Sotelo, Enrique		Replace brun out lamps and ballast in milg blg							
Hector Villalobos									
31463		Athletic Field			2/11/2008		142		\$0.00
High	Work In Progress			2/11/2008 11:27:42 AM					
Villalobos, Hector		Barbwire supports for fencing will be ordered (35). Please install when they are in. Norht fence by apartments. thxs							
Michael Munoz									
31465					2/11/2008		142		\$0.00
High	Work In Progress			2/11/2008 11:35:19 AM					
Villalobos, Hector		warehouse will be purchasing no trespassing signs(15) please install on north of campus by apt. thxs							
Michael Munoz									
31650	Main Building	Hallway/Corridor			2/19/2008		134		\$0.00
Medium	Work In Progress			2/19/2008 7:18:12 AM					
Lozoya, Manny		break in milg blg need to order new panic bars 6							
Hector Villalobos									
32960	Annex Building	Classroom			4/4/2008		89		\$0.00
Medium	Work In Progress			4/4/2008 7:26:24 AM					
Lozoya, Manny		need locks for cabinet and desk a.s.a.p. room 201							
Hector Villalobos									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
32961		Parking Lot			4/4/2008		89		\$0.00
Medium	Work In Progress				4/4/2008 7:33:04 AM				
Lozoya, Manny		parking lot need a new lock mild bld							
Hector Villalobos									
33049					4/6/2008	4/27/2008	87		\$0.00
Medium	Work In Progress				4/6/2008 12:18:18 AM				
Orozco, Danny		Monthly - Anthony ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
33211	Dona Ana	Office			4/9/2008		84		\$0.00
Medium	Work In Progress				4/9/2008 7:26:16 AM				
Lozoya, Manny		need to charge lock on door							
Hector Villalobos									
33334	Annex Building	Classroom			4/11/2008		82		\$0.00
Medium	Work In Progress				4/11/2008 1:43:24 PM				
Ronquillo, Ruben		broken window 37x 14 wire glass room 204							
Hector Villalobos									
33579	Original Main	Classroom			4/21/2008		72		\$0.00
Medium	Work In Progress				4/21/2008 1:18:06 PM				
Lozoya, Manny		POA NEEDS KEYS FOR CABINETS...							
Loraine Gandara									
33659	Original Main	Classroom			4/23/2008		70		\$0.00
Medium	Work In Progress				4/23/2008 8:37:59 AM				
Ronquillo, Ruben		Room 101 borken window 12x18							
Hector Villalobos									
33660	Cafeteria				4/23/2008		70		\$0.00
Medium	Work In Progress				4/23/2008 8:40:37 AM				
Ronquillo, Ruben		Old cafeteria broken window 19 1/2 x15 3/4							
Hector Villalobos									
33939	Cafeteria				5/2/2008		61		\$0.00
Medium	Work In Progress				5/2/2008 7:21:54 AM				
Ronquillo, Ruben		borken widow 19 1/2 x153/4							
Hector Villalobos									
33942	Main Building	Office			5/2/2008		61		\$0.00
Medium	Work In Progress				5/2/2008 8:12:28 AM				
Lozoya, Manny		OFFICE WILL NEED NEW LOCK AND NEW KEYS...							
Loraine Gandara									
34266	Main Building	Classroom			5/13/2008		50		\$0.00
Medium	Work In Progress				5/13/2008 1:34:30 PM				
Ronquillo, Ruben		Mid Bldg - Room 23 broken window size 22x58 1/2 wire glass							
Hector Villalobos									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Anthony ES								
34490		Classroom			5/21/2008		42		\$0.00	
Medium	Work In Progress	ANTHONY		5/21/2008 2:04:40 PM						
Lozoya, Manny		AS PER ANN S. - TO PLEASE PUT A DOOR BETWEEN THE TWO CLASSROOMS. (LIZ RUIZ AND MARCIA BENTO)								
Mary Garcia										
35130					6/12/2008		20		\$0.00	
Medium	Work In Progress			6/12/2008 11:42:25 AM						
Orozco, Danny		WALK - IN REFRIG. TEMP OUTSIDE THE DOOR DOES NOT WORK.								
		BECKY SAENZ SNP MGR 882-5607								
Jacqueline Aguilar										
35240		Classroom			6/18/2008		14		\$0.00	
Medium	Work In Progress	ANTHONY		6/18/2008 8:38:26 AM						
Sotelo, Enrique		Need to disconnect some electrical in order to put the door a/s/a/p. AS PER ANN S. - TO PLEASE PUT A DOOR BETWEEN THE TWO CLASSROOMS. (LIZ RUIZ AND MARCIA BENTO)								
Manny Lozoya										
35241		Classroom			6/18/2008		14		\$0.00	
Medium	Work In Progress	ANTHONY		6/18/2008 8:39:42 AM						
Villalobos, David		Need to disconnect some plumbing in order to put the door a/s/a/p. AS PER ANN S. - TO PLEASE PUT A DOOR BETWEEN THE TWO CLASSROOMS. (LIZ RUIZ AND MARCIA BENTO)								
Manny Lozoya										
35301	Drug Free Bldg.				6/20/2008		12		\$0.00	
High	Work In Progress			6/20/2008 3:01:27 PM						
Villalobos, Hector		there are some openings around the bottom of the bldg. please repair, someone or thing could crawl in.thxs								
Michael Munoz										
Count: 32 Work Orders		Avg. Age of WO's 140		Total for Anthony ES				0	\$0.00	

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Berino ES								
26824	Main Building	Gym			9/10/2007		296		\$0.00	
Medium	Work In Progress	5058822242			9/10/2007 6:54:35 AM					
Lozoya, Manny		LOCK TO HATCH TO ROOF WAS BROKEN OFF DURING THE BREAK IN NEEDS TO BE REPLACED								
Jimmy Cortez										
28572		Cafeteria			10/26/2007		250		\$0.00	
Medium	Work In Progress				10/26/2007 8:57:26 AM					
Orozco, Danny		Having problems with Dishwasher - Tom/Ecolab checked the DW-his recommendation: repair or replace the vacuum breaker and repair or replace the solenoid valve for the final rinse.								
		Aida Salcedo - SNP Coord. 882-6772 and Elsa Chairez - SNP Manager 882-2417								
Alma Terrell										
29029					11/7/2007		238		\$0.00	
Medium	Work In Progress				11/7/2007 9:26:08 AM					
Orozco, Danny		BROKEN FLOOR TILES THROUGHOUT FACILITY - REPEAT VIOLATION FROM ENVIRONMENT INSPECTION DEPARTMENT.								
		AIDA SALCEDO - SNP COMPLIANCE COORDINATOR 882-6772 ELSA CHAIREZ - SNP MANAGER - 882-2417								
Alma Terrell										
30778		Restroom (Boys)			1/18/2008		166		\$0.00	
Medium	Work In Progress				1/18/2008 9:29:45 AM					
Duran, Adan		BASEBOARDS NEEDS TO BE REPLACED IN ALL 8 SMALL RESTROOMS BOYS AND GIRLS IN CLASSROOMS 100 101 105 104				AS PER JESUS ESTRADA - ROUTE TO BLDG MECH.				
Jimmy Cortez										
31053	Main Building	Library			1/30/2008		154		\$0.00	
Medium	Work In Progress				1/30/2008 10:40:38 AM					
Lozoya, Manny		Library - Door knob is coming loose.								
Adan Duran										
31054		Portables			1/30/2008		154		\$0.00	
Medium	Work In Progress				1/30/2008 10:41:13 AM					
Lozoya, Manny		Portable 158- Door knob is coming loose.								
Adan Duran										
31055	Main Building	Restroom (Boys)			1/30/2008		154		\$0.00	
Medium	Work In Progress				1/30/2008 10:42:13 AM					
Ontiveros, Joe		Kinder Classroom (Boys RR) - Need a bowl wax.								
Adan Duran										

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
31633					2/15/2008		138		\$0.00
Medium	Work In Progress				2/15/2008 2:59:37 PM				
Moncayo, Fernando	MR JOSE AMBRIZ SIR EXHUAST FAN ROOM 100 MOTOR IS NOT WORKING NEED TO REPLACE THANK YOU SIR AND GOD BLESS								
Adan Duran									
31706					2/20/2008		133		\$0.00
Medium	Work In Progress				2/20/2008 3:12:15 PM				
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR THE IRRIGATION TIMER IN FRONT IS NOT WORKING ALL IRRIGATION HAS TO BE DONE BY HAND THE IRRIGATION BOX NAME IS IRRI-TROL HAVE BEEN TOLD BY MR HOLGIN THAT IT HAS NOT WORKED OVER A YEAR WOULD YOU HAVE SOME ONE LOOK AT IT PLEASE THANK YOU SIR AND GOD BLESS								
Adan Duran									
32003					2/28/2008		125		\$0.00
Medium	Work In Progress				2/28/2008 3:12:46 PM				
Ambriz, Jose	MR JOSE AMBRIZ SIR THE BOILER ON THE RIGHT SIDE THE ONE MR SOLIS CHANGE THE CONTROL IS MAKING A LOT OF NOISE BAD ITS HAMMERING SOMETHING IS NOT RIGHT WILL NEED TO CHECK OUT THANK YOU SIR AND GOD BLESS								
Adan Duran									
32396					3/7/2008		117		\$0.00
Medium	Work In Progress				3/7/2008 3:32:19 PM				
Sotelo, Enrique	MR ENRIQUE SOTELO LAS EMERGENGE LIGHT EN EL WEST SIDE GIRLS BATHROOM Y LOS MEN NESISITAN BATTERIES Y EL STORAGE EN LA CAFETERIA THANK YOU SIR								
Adan Duran									
32523					3/12/2008		112		\$0.00
Medium	Work In Progress				3/12/2008 3:25:02 PM				
Sotelo, Enrique	MR ENREQUE SOTELO SENOR SOTELO LA LUZ EN EL POSTE ESTA QUEBRIDA EL PLASTIC COVER TAMBIEN POR FAVOR QUENDO PUEDA CHECK IT PLEASE ESTA EN LOS PORTABLES THANK YOU SIR								
Adan Duran									
33004					4/6/2008	4/12/2008	87		\$0.00
Medium	Work In Progress				4/6/2008 12:18:03 AM				
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
33021					4/6/2008	4/14/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:09 AM					
Duran, Adan	Monthly - Berino ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
33044					4/6/2008	4/27/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:16 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
33050					4/6/2008	4/27/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:18 AM					
Orozco, Danny	Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
33071					4/6/2008	4/14/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:25 AM					
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
33074					4/6/2008	4/14/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:26 AM					
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
33189		Cafeteria			4/8/2008		85		\$0.00
Medium	Work In Progress			4/8/2008 1:17:04 PM					
Sanchez, Raul	FILTER NEEDS TO BE CHANGED TO THE WATER. ITS COMING OUT YELLOW.								
ELSA CHAIREZ - 882-2417									
Jacqueline Aguilar									
34059					5/5/2008		58		\$0.00
Medium	Work In Progress			5/5/2008 3:22:48 PM					
Appelzoller, Fred	MR FRED APPELZOLLER SIR THE CIRCULATION PUMP ON WATER HEATER IS NOT WORKING HAS A SHORT KEEPS KICKING THE BREAKER OUT MAY NEED TO REPLACE THANK YOU SIR AND GOD BLESS								
Adan Duran									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
34206					5/9/2008		54		\$0.00
Medium	Work In Progress			5/9/2008 3:08:22 PM					
Lozoya, Manny	MR MANNY LOZOYA SIR PER MR VALTIERRA THERE ARE ABOUT 3 CABINET FILES WITH OUT LOCKS NEED TO REPAIR NEED TO LOCK IMPORTANT PAPERS AND TEST THANK YOU SIR								
Adan Duran									
34343	Main Building	Portables			5/15/2008		48		\$0.00
Medium	Work In Progress			5/15/2008 8:15:12 AM					
Appelzoller, Fred	broken drinking fountain bubblers need to replace								
Fred Appelzoller									
34500					5/21/2008		42		\$0.00
Medium	Work In Progress			5/21/2008 3:20:31 PM					
Sanchez, Raul	MR RAUL SANCHES SIR THE IRRGATION PUMP FOR BERINO IS BURNED OUT WILL NEED TO REPLACE AS SOON AS WE CAN GET A REPLACEMENT THE PLAYGOUNDS ARE VERY DRY THANK YOU SIR AND GOD BLESS								
Adan Duran									
34616					5/27/2008		36		\$0.00
Medium	Work In Progress			5/27/2008 3:10:58 PM					
Appelzoller, Fred	MR FRED APPELZOLLER SIR THE WATER HEATER IN PORTABLE 157 IS LEAKING BAD NEED TO REPLACE ITS THE SMALL ONE THAT GOES ON WALL UNDER SINK 220 V THANK YOU SIR AND GOD BLESS								
Adan Duran									
34663					5/28/2008		35		\$0.00
Medium	Work In Progress			5/28/2008 3:36:47 PM					
Sotelo, Enrique	MR ENRIQUE SOTELO KIKI NEED TO CHANGE EMERGENCY LIGHT EN EL CURATO DE JIMMY CORTEZ NO GOOD BROKEN THANK YOU SIR								
Adan Duran									
35289					6/19/2008		13		\$0.00
Medium	Work In Progress			6/19/2008 4:40:59 PM					
Solis, Lorenzo	MR LORENZO SOLIS SIR THE AC UNIT PORTABLE 153 IS MAKING ALOT OF NOISE AND ITS NOT COOLING AS IT SHOULD MAY NEED TO REPLACE THANK YOU SIR AND GOD BLESS								
Adan Duran									
35309					6/23/2008		9		\$0.00
Medium	Work In Progress			6/23/2008 8:23:38 AM					
Lozoya, Manny	MR MANNY LOZOYA SIR THE FRONT ENTRANCE DOOR TO BUILDING IS JAMMED WILL NOT OPEN WILL YOU TAKE A LOOK AT IT PLEASE THANK YOU AND GOD BLESS								
Adan Duran									

7/2/2008 10:38:00 AM

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Berino ES							
35449					6/30/2008		2		\$0.00
Medium	Work In Progress				6/30/2008 9:06:29 AM				
Carrasco, Danny	MRS MARGRET VILLALOBOS AND TO WHOM IT MAY CONCERN NEED WELDER TO WELD TABLE IN CAFETERIA THE SEAT IS BROKEN OR NEED TO REPLACE ITS THE BIG LONG TABLES FOR THE KIDS THANK YOU								
Adan Duran									
Count: 28 Work Orders		Avg. Age of WO's 105			Total for Berino ES			0	\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral ES								
26649		Portables			9/4/2007		302		\$0.00	
Medium	Work In Progress	p-3		9/4/2007 8:25:13 AM						
Lozoya, Manny		need another key to portable 3 for pre kinder classes for new clerk. See Judy Atkins								
Jennifer Corral										
26931		Classroom			9/12/2007		294		\$0.00	
Medium	Work In Progress	512		9/12/2007 10:40:56 AM						
Lozoya, Manny		teacher is requesting another key for room. There are now two teachers in that room. See Ms. Adina								
Jennifer Corral										
26976					9/13/2007		293		\$0.00	
Medium	Work In Progress			9/13/2007 6:57:38 AM						
Lozoya, Manny		9/13/07 fire proof file cabinet in principals' office needs to be re-keyed.								
Joe Ramirez										
27215					9/20/2007		286		\$0.00	
Medium	Work In Progress			9/20/2007 8:32:42 AM						
Briones, Enrique		9/20/07. we need discarded furn. and equip. to be picked up by the purch. whse. turn in sheets are available.								
Joe Ramirez										
28241					10/17/2007		259		\$0.00	
Medium	Work In Progress			10/17/2007 3:45:12 PM						
Lozoya, Manny		(Chaparral Elementary): (Ms. Vasquez, Room #414) : Door to classroom is fallen. Door is hard to close. Need to re-weld top hinge of frame. Also, need to weld door closure to top of metal frame.								
Johnny Acuna										
28503					10/24/2007		252		\$0.00	
Medium	Work In Progress			10/24/2007 3:51:34 PM						
Munoz, Michael		Mike Muñoz: Need a double gate installed on the east side of fence area (Where the Trees are). Pre-K portable at Chaparral Elementary. (4/29/08 Asp Juan has not been done)								
Johnny Acuna										
29796					12/4/2007		211		\$0.00	
Medium	Work In Progress			12/4/2007 10:54:27 AM						
Ontiveros, Joe		Chaparral Elementary: Portable 2 / Pre-K. Water faucet to sink is leaking. Need a new gasket in the cold water side of the valve.								
Johnny Acuna										

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									
Location: Chaparral ES									
29828					12/4/2007		211		\$0.00
Medium	Work In Progress				12/4/2007 4:00:15 PM				
Lozoya, Manny		Need a pad lock for Blue box inside the irrigation system area. Pad Lock (N-53)							
<u>Johnny Acuna</u>									
29916					12/7/2007		208		\$0.00
Medium	Work In Progress				12/7/2007 2:39:27 PM				
Lozoya, Manny		Need to re-weld rebar back on to the Roof top Ladder and re-enforce all other bars. Main building: Metal Ladder on top of Roof: Cafeteria Section.							
<u>Johnny Acuna</u>									
29917					12/7/2007		208		\$0.00
Medium	Work In Progress				12/7/2007 2:42:29 PM				
Lozoya, Manny		Chaparral Elementary Rooftop: Need to Make and install Metal ladder and frame to main building wall to be able to go up from the kitchen rooftop to cafeteria rooftop.							
<u>Johnny Acuna</u>									
30154					12/17/2007		198		\$0.00
Medium	Work In Progress				12/17/2007 3:36:14 PM				
Lozoya, Manny		Chaparral Elementary School Principal: Mrs. Ballard is requesting a lock for the Fire Proof Filing Cabinet.							
<u>Johnny Acuna</u>									
30577		Classroom			1/14/2008		170		\$0.00
Medium	Work In Progress	101			1/14/2008 7:51:37 AM				
Lozoya, Manny		need key for cabinet, teacher misplaced cabinet key and cannot open it. See Ms. Ledesma							
<u>Jennifer Corral</u>									
30721	2001 Classroom	Classroom			1/17/2008		167		\$0.00
Medium	Work In Progress	220			1/17/2008 9:19:23 AM				
Lozoya, Manny		Chaparral Elementary: (Emergency Health Issue)- Need to replace Restroom Door Knob to Room #220 in the New Wing Area. Students remove loose handle and dump it in the toilet.							
<u>Johnny Acuna</u>									
30897					1/24/2008		160		\$0.00
Medium	Work In Progress				1/24/2008 8:22:20 AM				
Orozco, Danny		Sink to kitchen area is cracked. (Where pots and pans are washed)							
<u>Johnny Acuna</u>									
30977		Custodial			1/28/2008		156		\$0.00
Medium	Work In Progress	office			1/28/2008 1:48:11 PM				
Lozoya, Manny		need extra master keys for head custodian/ please see front office. as soon as possible							
<u>Jennifer Corral</u>									
7/2/2008 10:38:00 AM									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral ES									
31652					2/19/2008		134		\$0.00
Medium	Work In Progress			2/19/2008 8:43:51 AM					
Lozoya, Manny	need replace doors on barracas 416 414-412- 410 408 406 506 501								
<u>Juan Vargas</u>									
33051					4/6/2008	4/27/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:19 AM					
Orozco, Danny	Monthly - Chaparral ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
33505					4/17/2008		76		\$0.00
Medium	Work In Progress			4/17/2008 3:31:43 PM					
Ontiveros, Joe	water founting on main hall next to nurse have leck need replace lines								
<u>Juan Vargas</u>									
33717					4/24/2008		69		\$0.00
Medium	Work In Progress			4/24/2008 2:03:53 PM					
Lozoya, Manny	e wing doors portables need replace closers hiwges water stripers seeps adjment of door and reweld same hingereinfor rcement # 501 502 503 505 506 507 508 509 510 512								
<u>Juan Vargas</u>									
34404					5/19/2008		44		\$0.00
Medium	Work In Progress			5/19/2008 8:03:47 AM					
Lozoya, Manny	room 408 need fix lock not closed								
<u>Juan Vargas</u>									
34405					5/19/2008		44		\$0.00
Medium	Work In Progress			5/19/2008 8:06:16 AM					
Lozoya, Manny	room 408 need fix lock not closed								
<u>Juan Vargas</u>									
34406					5/19/2008		44		\$0.00
Medium	Work In Progress			5/19/2008 8:06:35 AM					
Lozoya, Manny	room 408 need fix lock not closed								
<u>Juan Vargas</u>									
34476					5/21/2008		42		\$0.00
Medium	Work In Progress			5/21/2008 7:54:31 AM					
Ronquillo, Ruben	room 406 need replace window glass zise 16 w.24l. 1/8 regular glass								
<u>Juan Vargas</u>									
34613		Custodial			5/27/2008		36		\$0.00
Medium	Work In Progress			5/27/2008 1:43:55 PM					
Hernandez, Guillermo	need/to/borrow/three/dollies/to/move/furniture/one/big/dollie								
<u>Daniel Ramirez</u>									

7/2/2008 10:38:00 AM

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
34634					5/28/2008		35	\$0.00	
Medium	Work In Progress			5/28/2008 8:33:06 AM					
Solis, Lorenzo	need fix water fonting next to nurse								
Juan Vargas									
34635					5/28/2008		35	\$0.00	
Medium	Work In Progress			5/28/2008 8:40:12 AM					
Ontiveros, Joe	main drain next to portable #1 need 3 in. tapa								
Juan Vargas									
34638					5/28/2008		35	\$0.00	
Medium	Work In Progress			5/28/2008 8:51:04 AM					
Vargas, Juan	05-21-08 8- paint halls on main building		5/21 - 8						
Juan Vargas									
34822					6/1/2008		31	\$0.00	
Medium	Work In Progress			6/1/2008 12:22:08 AM					
Vargas, Juan	Monthly - Chaparral ES C-6 Quarterly HP - Refer to PM schedule details.								
Margret Villalobos									
34823					6/1/2008		31	\$0.00	
Medium	Work In Progress			6/1/2008 12:22:08 AM					
Vargas, Juan	Monthly - Chaparral ES A-8 Quarterly HPW Unit - Refer to PM schedule details.								
Margret Villalobos									
34824					6/1/2008		31	\$0.00	
Medium	Work In Progress			6/1/2008 12:22:08 AM					
Vargas, Juan	Monthly - Chaparral ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
Margret Villalobos									
34825					6/1/2008		31	\$0.00	
Medium	Work In Progress			6/1/2008 12:22:09 AM					
Vargas, Juan	Monthly - Chaparral ES A-5 Quarterly SS - Refer to PM schedule details.								
Margret Villalobos									
34856					6/1/2008		31	\$0.00	
Medium	Work In Progress			6/1/2008 12:22:22 AM					
Jacquez, Ricardo	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									
34910					6/3/2008		29	\$0.00	
Medium	Work In Progress			6/3/2008 2:40:42 PM					
Ontiveros, Joe	replace the drinking facet is broken on portable #1								
Juan Vargas									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
34913					6/3/2008		29		\$0.00
Medium	Work In Progress			6/3/2008 2:49:42 PM					
Sotelo, Enrique		need assit. to replace lights and ballast							
Juan Vargas									
35123					6/12/2008		20		\$0.00
Medium	Work In Progress			6/12/2008 7:12:08 AM					
Ontiveros, Joe		boys and grls. r.rooms front offices and 200 haal need fix water lecks							
Juan Vargas									
35189					6/16/2008		16		\$0.00
Medium	Work In Progress			6/16/2008 4:40:05 PM					
Vargas, Juan		New Metal Canopies - Backfill dirt against concrete slab to create slope that can be mowed							
Alfredo Holguin									
35265					6/19/2008		13		\$0.00
Medium	Work In Progress			6/19/2008 2:25:54 PM					
Estrada, Jesus		barracks 402and 404 need carpet replace							
Juan Vargas									
35266					6/19/2008		13		\$0.00
Medium	Work In Progress			6/19/2008 2:30:34 PM					
Solis, Lorenzo		barracks 406-408-410-412-414 416-418 nesesian cambiar los a/c estan muy chicos no es suficiente para enfriar los cuartos							
Juan Vargas									
35267					6/19/2008		13		\$0.00
Medium	Work In Progress			6/19/2008 2:33:53 PM					
Ontiveros, Guadalupe		new playground need 50 toneladas de arena o mas							
Juan Vargas									
35402					6/26/2008		6		\$0.00
Medium	Work In Progress			6/26/2008 8:57:58 AM					
Vargas, Juan		REMOVE 2X4 FROM SIDEWALKS.							
Michael Munoz									
35407					6/26/2008		6		\$0.00
Medium	Work In Progress			6/26/2008 9:12:51 AM					
Vargas, Juan		COVER UP OLD ELECTRICAL BOX ON CORNER.							
Michael Munoz									
35408					6/26/2008		6		\$0.00
Medium	Work In Progress			6/26/2008 9:14:40 AM					
Vargas, Juan		NEED TO BACKFILL SIDEWALK AREAS WHERE INSTALLED AND CHECK SPRINKLERS.							
Michael Munoz									
Count: 42 Work Orders		Avg. Age of WO's 104		Total for Chaparral ES			0	\$0.00	

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
26036					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:18:09 PM					
Boyd, David	WARRANTY WO. D-WING COMPUTOR RM. CHANGE STORE RM. LOCK TO CLASS RM.LOCK								
Eddie Baeza									
26038					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:24:09 PM					
Boyd, David	WARRANTY WO. (7) MULLENS ON EXTERIOR DOORS MISSING PLATES,ADJUST CYL. SO CORE CAN BE IN LOCKED POSITION.								
Eddie Baeza									
26039					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:26:06 PM					
Boyd, David	WARRANTY WO. NEED CRANK FOR ROLL UP CURTAIN AT THE CONCESSION STAND.								
Eddie Baeza									
26040					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:29:14 PM					
Boyd, David	WARRANTY WO. TRANSITION STRIPS IN KITCHEN FLOORS ARE COMING LOOSE.								
Eddie Baeza									
26041					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:32:07 PM					
Boyd, David	WARRANTY WO. E-WING COMPUTER LAB HOLE IN WALL UNDER BULLETIN BOARD.								
Eddie Baeza									
26043					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:36:10 PM					
Boyd, David	WARRANTY WO. VENT UNCOVERED IN CEILING. UNFINISHED HOLE IN WALL COUNCELORS OFFICE. (BARNETT)								
Eddie Baeza									
26045					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:38:33 PM					
Boyd, David	WARRANTY WO PAPER LEFT IN LIGHT FIXTURE IN COUNCELORS OFFICE.								
Eddie Baeza									
26046					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:45:56 PM					
Boyd, David	WARRANTY WO. F-WING COMPUTER LAB 2 HOLES IN WALL NEXT TO TV STAND, HOLES NEAR OUTLETS, MISSING PAINT BETWEEN GLASS BLOCKS, CEILING TILES MISSING.								
Eddie Baeza									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
26047					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:49:28 PM					
Boyd, David	WARRANTY WO. RM. D-1 WALL OUTLET NOT COMPLETED, STAIN ON CEILING TILE, CEILING TILES MISSING.								
Eddie Baeza									
26048					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:51:57 PM					
Boyd, David	WARRANTY WO. BAND RM. OUTLETS HAVE NOT BEEN COVERED AND WIRES ARE STICKING OUT.								
Eddie Baeza									
26049					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:54:28 PM					
Boyd, David	WARRANTY WO. CEILING TILES MISSING THRU OUT CAMPUS.								
Eddie Baeza									
26050					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:56:27 PM					
Boyd, David	WARRAFNTY WO. RM B-6 CHIPPED PAINT ON A/C VENT.								
Eddie Baeza									
26051					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 1:59:36 PM					
Boyd, David	WARRANTY WO. RM. C-3 DOOR ON STORAGE CABINET CANNOT OPEN ALL THE WAY DUE TO T-STAT COVER.								
Eddie Baeza									
26052					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 2:04:24 PM					
Boyd, David	WARRANTY WO. RM. F-7 WATER STAINS ON CEILING TILES.								
Eddie Baeza									
26053					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 2:07:05 PM					
Boyd, David	WARRANTY WO. LIBRARY CONFERENCE RM. JHOLE IN NORTH WALL. ELECTRICAL OUTLETS DO NOT WORK.								
Eddie Baeza									
26054					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 2:11:34 PM					
Boyd, David	WARRANTY WO. B-SPED NEED HOOK UP FOR WASHER, NEED HOOK UP DRIER.NEED HOOKUP FOR STOVE. HOOK UP FOR DISHWASHER.								
Eddie Baeza									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
26055					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 2:13:14 PM					
Boyd, David	WARRANTY WO. WEST SCORE BOARD IN GYM NOT WORKING.								
Eddie Baeza									
26056					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 2:16:29 PM					
Boyd, David	WARRANTY WO. BLEACHERS IN GYM NEED TO HAVE 120 VOLT, AND PA RECEPTALS AT THE BLEACHERS								
Eddie Baeza									
26057					8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 2:22:33 PM					
Boyd, David	WARRANTY WO FIRE PUMP NEEDS TO BE PROGRAMMED SO THAT IT WILL SHUT OFF AUTOMATICALLY. ALSO EVERY TIME IT STARTS IT CALLS THE FIRE DEPT.								
Eddie Baeza									
26821					9/7/2007		299		\$0.00
Medium	Work In Progress	BAND ROOM		9/7/2007 4:31:33 PM					
Lozoya, Manny	RESTROOMS - LOCKS SHOULD BE CHANGED BECAUSE STUDENTS CAN LOCK THE DOOR FROM THE INSIDE AND IT SHOULDN'T BE THE CASE. GIRLS DOOR WON'T LOCK EITHER. ALSO, THE BATHROOM NEEDS BOYS AND GIRLS SIGNS POSTED ONT THE DOORS								
Rosa Quezada									
26822					9/7/2007		299		\$0.00
Medium	Work In Progress	OUTSIDE HOSE		9/7/2007 4:33:14 PM					
Lozoya, Manny	NEED 8 KEYS FOR OUTSIDE HOSE BIBS, AS PER EDDIE BAEZA								
Rosa Quezada									
26941					9/12/2007		294		\$0.00
Medium	Work In Progress	gym		9/12/2007 2:15:46 PM					
Lozoya, Manny	please rekey the ch1 key to a ch86 to fit the custodial door on the northwest end of the gym.								
Rosa Quezada									
26943	B-Wing				9/12/2007		294		\$0.00
Medium	Work In Progress	B-2		9/12/2007 2:26:44 PM					
Lozoya, Manny	COACH YTURRALDE NEEDS A KEY (CH32) TO ACCESS WASHER AND DRYER FOR FOOTBALL								
Rosa Quezada									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral HS									
26964	C-Wing				9/12/2007		294		\$0.00
Medium	Work In Progress	sped room		9/12/2007 3:55:48 PM					
Lozoya, Manny		need ch32 to open door - need two keys - one for teacher and one for spare							
Rosa Quezada									
26965		Gym			9/12/2007		294		\$0.00
Medium	Work In Progress	gym		9/12/2007 3:57:05 PM					
Lozoya, Manny		need 4 keys off the GM1 master for coaches, Nougues, Yturalde, and Ulibarri and one for spare							
Rosa Quezada									
26967	C-Wing	Classroom			9/12/2007		294		\$0.00
Medium	Work In Progress	sped - c wing		9/12/2007 3:59:24 PM					
Lozoya, Manny		please change order # 26964 previously entered to ch45 (2 keys) instead of ch32 - my mistake							
Rosa Quezada									
28146		Custodial			10/15/2007		261		\$0.00
Medium	Work In Progress			10/15/2007 3:16:11 PM					
		Need a set of tools and drill motor for various jobs that ON HOLD AS PER CHUY pop up							
Arthur Contreras									
28641					10/30/2007		246		\$0.00
Medium	Work In Progress			10/30/2007 7:46:46 AM					
Boyd, David		#1 UNIT IN THE CAFETERIA IS TRIPPING THE CONTROL TRANSFORMER SEEMS LIKE A DIRECT SHORT							
Eddie Baeza									
28837	C-Wing				11/2/2007		243		\$0.00
Medium	Work In Progress	c-4		11/2/2007 2:27:46 PM					
Lozoya, Manny		NEED A SET OF D156AR KEYS (CABINET) FOR HALLEY WOODS AT C-4							
Rosa Quezada									
29213					11/14/2007		231		\$0.00
Medium	Work In Progress			11/14/2007 11:07:12					
Lozoya, Manny		STORAGE RM IN THE CAREER CENTER NEEDS TO BE REKEYED OFF MASTER, AND 4 KEYS ARE NEEDED							
Eddie Baeza									
29748					12/3/2007		212		\$0.00
Medium	Work In Progress			12/3/2007 2:28:29 PM					
Boyd, David		POWER NEEDS TO BE SUPPLIED TO BLEACHERS, AND PA SYSTEM							
Eddie Baeza									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral HS									
29749					12/3/2007		212		\$0.00
Medium	Work In Progress				12/3/2007 2:30:00 PM				
Lozoya, Manny		FIRE BLOCK DOORS IN THE MAIN CORRIDOR NEEDS LOCKSETS INSTALLED							
Eddie Baeza									
29806					12/4/2007		211		\$0.00
Medium	Work In Progress				12/4/2007 2:47:41 PM				
Lozoya, Manny		(1) CH-7 AND (1) CH-3 KEYS ARE REQUESTED FOR NURSE HIGGS IN THE HEALTH CENTER							
Eddie Baeza									
29858					12/6/2007		0		\$0.00
Medium	Work In Progress				12/6/2007 7:52:44 AM	12/6/2007			
Lozoya, Manny		Can we get a key to the gate for the compactor at Chaparral High School. Please let me know when the key is ready and I will go by and pick it up.							
Juliet Parra									
29953		Gym			12/10/2007		205		\$0.00
Medium	Work In Progress	GYM			12/10/2007 3:38:16 PM				
Lozoya, Manny		NEED A KEY TO RETRACT THE SIDE BASKETS IN THE GYM (F.SANCHEZ)							
Rosa Quezada									
29954		Classroom			12/10/2007		205		\$0.00
Medium	Work In Progress	SECRETARY			12/10/2007 3:39:28 PM				
Lozoya, Manny		NEED A WA (LIFT STATION GATE KEY)							
Rosa Quezada									
30137	A-Wing				12/17/2007		198		\$0.00
Medium	Work In Progress	RECEPTIONIST			12/17/2007 10:23:58				
Lozoya, Manny		NEED COPIES OF D-264AR FOR CABINETS BEHIND RECEPTIONIST DESK (M.MEZA)							
Rosa Quezada									
30138		Gym			12/17/2007		198		\$0.00
Medium	Work In Progress	OFFICE			12/17/2007 10:25:42				
Lozoya, Manny		NEED A KEY FOR CABINET IN P.E. OFFICE FOR COACH YTURREALDE A.S.A.P.							
Rosa Quezada									
30485		Office			1/10/2008		174		\$0.00
Medium	Work In Progress	MAINTENANCE			1/10/2008 2:19:49 PM				
Lozoya, Manny		NEED A C-T KEY FOR EDDIE BAEZA (MAINTENANCE) TO ACCESS ROOF HATCH AND A/C UNITS							
Rosa Quezada									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
30728	E-Wing	Classroom			1/17/2008		167		\$0.00
Medium	Work In Progress	E-7		1/17/2008 10:48:11 AM					
Lozoya, Manny		LOCK ON TALL CABINET IN BACK OF CLASSROOM FELL OUT. NEEDS TO BE REPAIRED (SAVOIE)							
Rosa Quezada									
30729	D-Wing	Classroom			1/17/2008		167		\$0.00
Medium	Work In Progress	D-4		1/17/2008 10:50:47 AM					
Lozoya, Manny		CABINET KEYS GET STUCK - UNABLE TO LOCK)							
Rosa Quezada									
30732		Classroom			1/17/2008		167		\$0.00
Medium	Work In Progress	E-7		1/17/2008 10:54:33 AM					
Lozoya, Manny		NEED KEY# RD025 TO OPEN CABINETS (SAVOIE)							
Rosa Quezada									
30805		Gym			1/18/2008		166		\$0.00
High	Work In Progress			1/18/2008 3:26:09 PM					
Baeza, Eddie		6 breakaway goals where purchsaed for courts. 2 have been installed, please install the remaining 4 and return to the physical plant. THXS							
Michael Munoz									
31011	E-Wing	Classroom			1/29/2008		155		\$0.00
Medium	Work In Progress	E-3		1/29/2008 9:17:45 AM					
Lozoya, Manny		NEED A CH-12 TO OPEN THE WEIGHTLIFTING ROOM FOR HIS CLASS (DIOSDADO)							
Rosa Quezada									
31050		Cafeteria			1/30/2008		154		\$0.00
Medium	Work In Progress	Kitchen		1/30/2008 8:50:54 AM					
Baeza, Eddie		As per Pest Control need to redo door kitchen entry from exterior 1/2 - 1in cap under door.							
Margret Villalobos									
31167					2/1/2008		152		\$0.00
Medium	Work In Progress			2/1/2008 10:18:36 AM					
Lozoya, Manny		A CH-1 CORE IS REQUESTED FOR THE ROOF HATCH AAT THE B-WING.							
Eddie Baeza									
31417		Office			2/7/2008		146		\$0.00
Medium	Work In Progress	TROPHY CASES		2/7/2008 6:50:49 PM					
Lozoya, Manny		NEED SIX LOCKS FOR TROPHY CASES AND TWO LOCKS FOR DISPLAY CASES (QUEZADA)							
Rosa Quezada									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
31459					2/11/2008		142		\$0.00
Medium	Work In Progress				2/11/2008 10:52:30 AM				
Lozoya, Manny		42 FLOOR DOOR STOPS ARE REQUESTED FOR CLASS RM. DOORS.(PURCHASE THROUGH RAWSON)							
Eddie Baeza									
31686					2/20/2008		133		\$0.00
Medium	Work In Progress				2/20/2008 9:53:02 AM				
Orozco, Danny		A DOOR BELL IS REQUESTED FOR THE RECEIVING DOOR AT THE KITCHEN.							
Eddie Baeza									
31858					2/26/2008		127		\$0.00
Medium	Work In Progress				2/26/2008 7:50:53 AM				
Lozoya, Manny		STORAGE DOOR AT THE GIRLS LOCKER RM. CANNOT BE OPENED. SEEMS LIKE LATCH IS NOT ENGAGING.							
Eddie Baeza									
31975					2/28/2008		125		\$0.00
Medium	Work In Progress	GIRLS LOCKER			2/28/2008 8:20:15 AM				
Lozoya, Manny		PLEASE RE-KEY DOOR THAT SEPARATES DOORS BETWEEN GIRLS LOCKER ROOM. NEEDS TO BE KEY ENTRY ON BOTH SIDES. (NOUGUES)							
Rosa Quezada									
31984	E-Wing	Classroom			2/28/2008		125		\$0.00
Medium	Work In Progress	E-7			2/28/2008 8:34:23 AM				
Lozoya, Manny		NEED KEYS TO LOCK AND UNLOCK CABINETS IN SOTRE ROOM . THE STAMP CODE IS RD025. (SAVOIE) 2ND REQUEST							
Rosa Quezada									
32384					3/7/2008		117		\$0.00
High	Work In Progress				3/7/2008 1:12:14 PM				
Contreras, Arthur		Pick up trash around fence line and entrance east side is the worst.							
Jesus Estrada									
32440					3/10/2008		114		\$0.00
Medium	Work In Progress				3/10/2008 3:02:25 PM				
Sotelo, Enrique		ELECTRICAL CIRCUITS ARE REQUESTED FOR THE GAURD SHACK AT MAIN ENTRANCE							
Eddie Baeza									
32493	C-Wing				3/11/2008		113		\$0.00
Medium	Work In Progress	C-COMPUTER			3/11/2008 3:47:14 PM				
Lozoya, Manny		NEED SIX COPIES OF PORT A POTTY KEY #3172 (ROSA HAS A KEY)							
Rosa Quezada									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
32537					3/13/2008		111		\$0.00
Medium	Work In Progress			3/13/2008 8:54:26 AM					
Boyd, David	LOCHINVAR BOILERS ARE KICKING OFF ON LOW AIR PRESSURE								
Eddie Baeza									
32538					3/13/2008		111		\$0.00
Medium	Work In Progress			3/13/2008 9:02:26 AM					
Boyd, David	DOMESTIC WATER PUMPS ARE GOING INTO ALARM ON HIGH DISCHARGE PRESSURE								
Eddie Baeza									
32540					3/13/2008		111		\$0.00
Medium	Work In Progress			3/13/2008 9:04:40 AM					
Boyd, David	DOOR CLOSER IN THE CONCESSION STAND HAS FALLEN OFF.								
Eddie Baeza									
32541					3/13/2008		111		\$0.00
Medium	Work In Progress			3/13/2008 9:06:13 AM					
Boyd, David	START UP OF HEATING AND COOLING UNITS AT THE GREENHOUSES, NEEDS TO BE PERFORMED AND CHECKED FOR PROPER PERFORMANCE.								
Eddie Baeza									
32542					3/13/2008		111		\$0.00
Medium	Work In Progress			3/13/2008 9:07:31 AM					
Boyd, David	CIRCULATING PUMP IN THE CUSTODIAL CLOSET IN THE C-WING IS MAKING NOISE.								
Eddie Baeza									
32978					4/4/2008		89		\$0.00
Medium	Work In Progress			4/4/2008 1:22:10 PM					
Lozoya, Manny	N.W. DOOR AT THE GYM WILL NOT UNLOCK								
Eddie Baeza									
33136		Office			4/7/2008		86		\$0.00
Medium	Work In Progress	secretary		4/7/2008 12:09:53 PM					
Lozoya, Manny	I NEED TWO E-158 KEYS FOR THE TRASH COMPACTOR								
Rosa Quezada									
33253					4/9/2008		84		\$0.00
Medium	Work In Progress			4/9/2008 2:52:29 PM					
Boyd, David	DOMESTIC WATER PUMPS ARE GOING INTO ALARM AND SHUTTING DOWN ON HI SYSTEM PRESSURE.								
Eddie Baeza									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
33298					4/10/2008		83		\$0.00
Medium	Work In Progress			4/10/2008 12:10:01 PM					
Lozoya, Manny	(60) DOOR LATCH PROTECTORS AND (60) FLOOR DOOR STOPS ARE REQUESTED FOR CLASSROOM DOORS.								
<u>Eddie Baeza</u>									
33652					4/22/2008		71		\$0.00
Medium	Work In Progress			4/22/2008 3:52:55 PM					
Lozoya, Manny	(2) DISPLAY CASE LOCKS ARE REQUESTED FOR THE LIBRARY. KEYED TO # 998 IF POSSIBLE								
<u>Eddie Baeza</u>									
33772					4/28/2008		65		\$0.00
Medium	Work In Progress	CHAPARRAL		4/28/2008 1:35:12 PM					
Lozoya, Manny	NEED TO CHANGE THE KEYS AT THE IDF ROOMS @ CHAPARRAL HIGH SCHOOL - PLEASE CALL CALIXTO IN THE TECHNOLOGY DEPT. EXT 6274 FOR INSTRUCTIONS. THANK YOU								
<u>Cora Ramirez</u>									
34539		Athletic Field			5/22/2008		41		\$0.00
Medium	Work In Progress			5/22/2008 3:05:46 PM					
Estrada, Jesus	Need pitchfork for tumble weeds that accumulate on the perimeter of the facility. The fence line								
<u>Arthur Contreras</u>									
34682		Classroom			5/29/2008		34		\$0.00
Medium	Work In Progress	F-2		5/29/2008 2:55:59 PM					
Lozoya, Manny	NEED CH86 FOR COACH ROY GERELA (GERELA)								
<u>Rosa Quezada</u>									
34862					6/1/2008	6/22/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:24 AM					
Orozco, Danny	Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35153					6/15/2008		17		\$0.00
Medium	Work In Progress			6/15/2008 12:18:04 AM					
Ontiveros, Guadalupe	Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35171		Office			6/16/2008		16		\$0.00
Medium	Work In Progress	VARIOUS		6/16/2008 10:46:35 AM					
Lozoya, Manny	WE NEED THE FOLLOWING NAME PLATES; REGISTRAR, DATA ENTRY, CLERK, SCHOOL SECRETARY, ATTENDANCE, COMPUTER TECH, PRINCIPAL, ASSISTANT PRINCIPAL (3) COUNSELOR (4) AND RECEPTIONIST								
<u>Rosa Quezada</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
35209		Cafeteria			6/17/2008		15		\$0.00
Medium	Work In Progress			6/17/2008 10:42:38 AM					
Villalobos, Margret		HAS A BUG PROBLEM - PLEASE CALL THE PEST CONTROL, THANK YOU!							
Alma Terrell		GREGORIA BATISTA - ASST. MGR. 824-4461							
35243		Gym			6/18/2008		14		\$0.00
Medium	Work In Progress			6/18/2008 9:40:56 AM					
Carbajal, Jimmy		MACHINE NEEDS REPAIR NEEDS BELT DRIVE ALSO TIRES AND SQUEEGE REPLACED THANK YOU .							
Jimmy Carbajal									
35327					6/24/2008		8		\$0.00
Medium	Work In Progress			6/24/2008 9:14:02 AM					
Villalobos, Margret		(Need a price quote please a/s/a/p) There is a plague of bugs on outside walls throughout bldg.				Faxed to Watson 6/24/08-mkv Price Quote 150.00			
Michael Munoz									
35409					6/26/2008		6		\$0.00
Medium	Work In Progress			6/26/2008 9:23:34 AM					
Lozoya, Manny		NEED 4 CH-86 KEYS FOR COACHES. (QUEZADA)							
Rosa Quezada									
35410					6/26/2008		6		\$0.00
Medium	Work In Progress	CONCESSION		6/26/2008 9:26:15 AM					
Lozoya, Manny		NEED TO REKEY CONCESSION ROOM - AND STORAGE ROOM IN F-WING (QUEZADA)							
Rosa Quezada									
35446					6/30/2008		2		\$0.00
Medium	Work In Progress			6/30/2008 12:19:41 AM					
Baeza, Eddie		Yearly - Chaparral HS Exit Sign Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35447					6/30/2008		2		\$0.00
Medium	Work In Progress			6/30/2008 12:19:42 AM					
Baeza, Eddie		Yearly - Chaparral HS Emer. Light Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35463		Football Field			6/30/2008		2		\$0.00
Medium	Work In Progress	Press Box		6/30/2008 1:37:29 PM					
Munoz, Michael		Need to remodel press box.							
Carlos Lowenberg									
Count: 79 Work Orders		Avg. Age of WO's 180		Total for Chaparral HS				0	\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
24411					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:56 AM				
Villalobos, David	Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24412					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:56 AM				
Villalobos, David	Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24413					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:56 AM				
Villalobos, David	Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
26037					8/20/2007		317		\$0.00
Medium	Work In Progress				8/20/2007 1:20:23 PM				
Boyd, David	WARRANTY WO. DEADBOLTS NEED TO BE REPLACED IN ALL REST RMS.								
Eddie Baeza									
27127					9/18/2007		288		\$0.00
Medium	Work In Progress				9/18/2007 11:19:23 AM				
Lozoya, Manny	we need to change the lock from 405A to 405B and 405B TO 405A. we have computers in room 405A and we do not want people with the A master key to be able to go in there.								
Robert Gonzalez									
27255					9/21/2007		285		\$0.00
Medium	Work In Progress				9/21/2007 7:27:57 AM				
Lozoya, Manny	girls locker room door that leads to the back girls sports locker room is hard to open and lock. choach ramos would like a dead bolt put on there if possible.								
Robert Gonzalez									
31295		Gym			2/5/2008		-60		\$0.00
Medium	Work In Progress				2/5/2008 9:00:35 AM	12/7/2007			
Lozoya, Manny	boys and grls. lockers rooms need replace partitions.								
Juan Vargas									
31598		Portables			2/14/2008		139		\$0.00
Medium	Work In Progress				2/14/2008 1:19:14 PM				
Lozoya, Manny	Portable #14 has two file cabinets that need keys and the building mechanic needs locks and keys for his desk								
Eric Medina									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral MS									
31601					2/14/2008		139		\$0.00
Medium	Work In Progress			2/14/2008 2:26:42 PM					
Ontiveros, Joe	4 custodial closets have leaks at faucet								
Eric Medina									
32025		Portables			2/29/2008		124		\$0.00
Medium	Work In Progress	P-10		2/29/2008 8:35:00 AM					
Lozoya, Manny	Need file cabinet re-keyed for Ms. Smith in portable 10 needs to file important confidential papers.								
Elena Palacios									
32305					3/5/2008		119		\$0.00
Medium	Work In Progress			3/5/2008 3:16:24 PM					
Ontiveros, Joe	3/5	need to replace valve under portable #2							
Eric Medina									
32354					3/6/2008		118		\$0.00
High	Work In Progress			3/6/2008 3:03:01 PM					
Gonzalez, Robert	Shampoo and extract carpet in band room. As per Ms. Muela the carpet is making the band director sick. (assign to R. Gonzalez)								
Jesus Estrada									
32418					3/10/2008		114		\$0.00
High	Work In Progress			3/10/2008 9:39:00 AM					
Lozoya, Manny	We need all the locks that were taken off the file cabinets re-installed. We have been waiting since SEPTEMBER!!!								
Elena Palacios									
32429					3/10/2008		114		\$0.00
Medium	Work In Progress			3/10/2008 11:22:23 AM					
Lozoya, Manny	outside door to boys locker rooms westside is very hard to unlock. then it's very hard to lock again. door handle is loose.								
Robert Gonzalez									
33045					4/6/2008	4/27/2008	-11		\$0.00
Medium	Work In Progress			4/6/2008 12:18:17 AM		3/26/2008			
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
33350					4/11/2008		82		\$0.00
Medium	Work In Progress			4/11/2008 3:50:10 PM					
Lozoya, Manny	Room 206 need lock on file cabinet replaced								
Eric Medina									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

33389					4/14/2008		79		\$0.00
Medium	Work In Progress			4/14/2008 12:33:51 PM					
Lozoya, Manny	THE DOOR HANDLE IN ROOM 450 (BAND ROOM) LOCKS BUT IF YOU JIGGLE IT IT UNLOCKS.								

Robert Gonzalez

33549					4/18/2008		75		\$0.00
Medium	Work In Progress	DP-781		4/18/2008 2:21:11 PM					
Jacquez, Ricardo	As per DP-781 Closure Plan: Needs to be done before July 11, 2008. (Please inform Alfredo when complete). 1. Remove or plug all lines conveying wastewater to the septic tank/leachfield system (s) so that a discharge can no longer occur.								

2. Pump the grease interceptor and septic tanks and dispose of pumpings in accordance with all local, state and federal regulations.

Alfredo Holguin

33552					4/18/2008		75		\$0.00
Medium	Work In Progress	DP-781		4/18/2008 2:24:24 PM					
Ontiveros, Guadalupe	As per DP-781 Closure Plan: Needs to be done before July 11, 2008. (Please inform Alfredo when complete). Backfill the tanks with clean fill or sand or remove from site. (Lupe ck w/Rick Jacquez to see if he is done w/his part first). Thanks								

Alfredo Holguin

34225					5/12/2008		51		\$0.00
Medium	Work In Progress			5/12/2008 9:03:47 AM					
Sotelo, Enrique	Smelling burnt wires in room 304 requesting electrician to come inspect room								

Eric Medina

34678					5/29/2008		34		\$0.00
Medium	Work In Progress			5/29/2008 12:11:59 PM					
Carbajal, Jimmy	WE NEED A WET & DRY WE EXCHANGED AN OLD ROUND BLACK ONE THAT WE HAD BUT THE ONE THAT WAS GIVEN TO US IS AN AWD 315 AND IT'S TO SMALL IT GETS FULL TO FAST. WE WOULD LIKE TO KEEP THE AWD 315 TO PICKUP WATER WHEN IT RAINS. WE HAVE A LOT OF LEAKS AND ITS EASY TO RUN AROUND WITH IN THE MORNINGS WHEN I GET HERE. THANK YOU								

Robert Gonzalez

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
34731					5/30/2008		33		\$0.00
Medium	Work In Progress			5/30/2008 2:50:50 PM					
Lozoya, Manny		5/30	had door replaced in south side cafeteria and need lock to fit our keys						
Eric Medina									
34732					5/30/2008		33		\$0.00
Medium	Work In Progress			5/30/2008 2:53:36 PM					
Ontiveros, Joe		5/30	ball valve to cold water entering 300 hall way is leaking need to replace as soon as possible						
Eric Medina									
35099	Main Building	Parking Lot			6/11/2008		21		\$0.00
Medium	Work In Progress	GATE BETWEEN		6/11/2008 10:15:32 AM					
Lozoya, Manny		NEED EXTRA KEYS MADE FOR THE LOCK BETWEEN THE PORTABLES AND THE BUILDING							
Elena Palacios									
35100	Main Building	Classroom			6/11/2008		21		\$0.00
Medium	Work In Progress	ROOM 107		6/11/2008 10:17:16 AM					
Lozoya, Manny		NEED SPECIAL KEY MADE FOR LAUNDRY ROOM IN ROOM 107 ONE THAT CANNOT BE ACCESSED WITH THE A MASTER KEY							
Elena Palacios									
35102	Main Building	Office			6/11/2008		21		\$0.00
Medium	Work In Progress	ADMINISTRATIO		6/11/2008 10:19:14 AM					
Lozoya, Manny		NEED TO CHECK LOCK ON DOOR LEADING TO ADMINISTRATION OFFICE. KEEPS GETTING JAMMED							
Elena Palacios									
35236		Gym			6/17/2008		15		\$0.00
Medium	Work In Progress			6/17/2008 5:12:22 PM					
Lozoya, Manny		need to change locks in the gym. we'll be doing the gym july 14 to the 18. if the locks can be changed on the july 9th or 10th that would be great. thank you							
Robert Gonzalez									
Count: 27 Work Orders		Avg. Age of WO's 123		Total for Chaparral MS				0	\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
28788		Restroom (Girls)			11/1/2007		244		\$0.00
Medium	Work In Progress	front office			11/1/2007 10:12:05 AM				
Appelzoller, Fred		Need an ADA toilet installed in the restroom in the front office.							
Mary Telles									
32873		Portables			4/1/2008		92		\$0.00
Medium	Work In Progress	6 , 7 & 8			4/1/2008 10:44:19 AM				
Castillo, Carlos		OUTSIDE NIGHTLIGHTS NOT TURNING ON AT NITE							
David Acosta									
32874		Office			4/1/2008		92		\$0.00
Medium	Work In Progress				4/1/2008 10:50:50 AM				
Castillo, Carlos		SECURITY NIGHTLIGHT NEEDED ON NORTH SIDE OF FRONT OFFICE BUILDING. THAT AREA VERY DARK.							
David Acosta									
33605	Storage A	Pump House			4/21/2008		72		\$0.00
Medium	Work In Progress				4/21/2008 3:37:05 PM				
Castillo, Carlos		I need an electrician to check flourescent fixture in pump house.It may need to be replaced or repaired. Thanks,Raul							
Raul Sanchez									
33670		Portables			4/23/2008		70		\$0.00
Medium	Work In Progress	ROOM 7			4/23/2008 1:59:16 PM				
Castillo, Carlos		NEED TO REPLACE BALLAST IN ONE LIGHT FIXTURE							
David Acosta									
33777					4/28/2008		65		\$0.00
Medium	Work In Progress				4/28/2008 2:53:48 PM				
Holguin, Alfredo		Provide Electrical power to new marquee							
Alfredo Holguin									
33893		Portables			5/1/2008		62		\$0.00
Medium	Work In Progress				5/1/2008 9:27:53 AM				
Ontiveros, Guadalupe		Portable 5/9SM - Need to make sure area is ready for portable. (entrance, fencing, blocks, cookies, leveled, etc.)							
Michael Munoz									
33894		Portables			5/1/2008		62		\$0.00
Medium	Work In Progress				5/1/2008 9:29:28 AM				
Castillo, Carlos		Portable 5/9SM - Need to connect utilities.							
Michael Munoz									
33895		Portables			5/1/2008		62		\$0.00
Medium	Work In Progress				5/1/2008 9:30:47 AM				
Appelzoller, Fred		Portable 5/9SM - Need to connect utilities (if any).							
Michael Munoz									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Pride									
33898					5/1/2008		62		\$0.00
Medium	Work In Progress	Barrack			5/1/2008 9:42:20 AM				
Ambriz, Jose		Need to install (2) Bards for Barrack will be divided in the middle, ck amp w/Electrician. (by Julie's Trailer).							
Michael Munoz									
33899					5/1/2008		62		\$0.00
Medium	Work In Progress	Barrack			5/1/2008 10:49:24 AM				
Estrada, Jesus		Need to install VCT in Barrack (by Julie's Mobile Home) partition will be installed 2 classrooms.							
Michael Munoz									
33901					5/1/2008		62		\$0.00
Medium	Work In Progress	Barrack			5/1/2008 10:53:14 AM				
Gonzalez, Salvador		Need to install ramp at barrack (by Julie's Mobile Home). See Mike							
Michael Munoz									
33902					5/1/2008		62		\$0.00
Medium	Work In Progress	Barrack			5/1/2008 10:54:30 AM				
Lara, Ralph		Need to install door and window at barrack (by Julie's Mobile Home). See Mike							
Michael Munoz									
34304					5/14/2008		49		\$0.00
Medium	Work In Progress	Barrack			5/14/2008 8:18:23 AM				
Castillo, Carlos		Need to install lighting and electrical outlets to barrack will be divided into 2 classrooms. (by Julie's Mobile Home). See Mike							
Michael Munoz									
34875		Library			6/2/2008		30		\$0.00
Medium	Work In Progress				6/2/2008 4:24:28 PM				
Gonzalez, Salvador		NEED TO REPAIR A SMALL SECTION OF SIDEWALK AT THE END OF RAMP TO LIBRARY [TRIP HAZARD].				6/9 - Asp Mike route to Sal			
David Acosta									
35167		Pump House			6/16/2008		16		\$0.00
Medium	Work In Progress				6/16/2008 8:06:14 AM				
Sanchez, Raul		VERY LOW WATER PRESSURE HERE AT D.P.							
David Acosta									
35325	Storage B-				6/24/2008		8		\$0.00
High	Work In Progress				6/24/2008 8:43:12 AM				
Munoz, Michael		need to pour a 10 x 40 slab of concrete for new ramp installation							
Michael Munoz									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Desert Pride							
35326					6/24/2008		8		\$0.00
High	Work In Progress				6/24/2008 8:48:13 AM				
Munoz, Michael	need to provide a landing slab and a 7 x 70 side walk to portable 9SM								
Michael Munoz									
Count: 18 Work Orders			Avg. Age of WO's	66			Total for Desert Pride	0	\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
25347		Cafeteria			8/2/2007		335		\$0.00
Medium	Work In Progress			8/2/2007 1:47:59 PM					
Orozco, Danny	Kitchen: Washroom Door Frame needs to be replaced. Door Frame is corroded on the bottom.								
Johnny Acuna									
26689					9/5/2007		301		\$0.00
Medium	Work In Progress			9/5/2007 1:18:39 PM					
Lozoya, Manny	Need to check Custodial J-Master Key. Key does not open doorknob lock to portable #415 for her to clean classroom during her working hours.								
Johnny Acuna									
26782					9/7/2007		299		\$0.00
Medium	Work In Progress			9/7/2007 8:57:11 AM					
Lozoya, Manny	Custodial Dept. requesting a lock for filing cabinet in the custodial / maintenance office.								
Johnny Acuna									
26788					9/7/2007		299		\$0.00
Medium	Work In Progress			9/7/2007 10:28:19 AM					
Sotelo, Enrique	Need to replace (2) Ballasts for Outdoor security light poles. *-light next to storage shed. *-Light in back of portables closest to grass area:Also for this light pole need to replace broken light cover.								
Johnny Acuna									
28406					10/23/2007		253		\$0.00
Medium	Work In Progress			10/23/2007 11:10:46					
Acuna, Johnny	Please connect existing sidewalk to playground ramp approx. 3 x 5 section after grounds does backfill of dirt.				6/26 - Sent picture to Johnny asp Mike				
Michael Munoz									
28408					10/23/2007		253		\$0.00
Medium	Work In Progress			10/23/2007 11:13:37					
Acuna, Johnny	Digout grass around wells in trees.								
Michael Munoz									
28536					10/25/2007		251		\$0.00
Medium	Work In Progress			10/25/2007 1:01:41 PM					
Acuna, Johnny	PLAYGROUND ARE-NEED CONNECTION FROM SIDEWALK TO SURFACING FOR ADA.								
Michael Munoz									
28537					10/25/2007		251		\$0.00
Medium	Work In Progress			10/25/2007 1:05:49 PM					
Acuna, Johnny	NOT GOOD FOR 5 YEAR OLD.- NEED SIGN FOR 6YRS AND OLDER.								
Michael Munoz									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
31197					2/3/2008	2/11/2008	150		\$0.00
Medium	Work In Progress				2/3/2008 12:30:34 AM				
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
31202					2/3/2008	2/11/2008	150		\$0.00
Medium	Work In Progress				2/3/2008 12:30:36 AM				
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
31855					2/25/2008		128		\$0.00
Medium	Work In Progress				2/25/2008 4:03:54 PM				
Lozoya, Manny	Need 3 Muliums installed in our main building main entry door areas. (1)-Front office area, main doors. (1)-Bus area main doors. (1)-Middle main door going to portable area.								
<u>Johnny Acuna</u>									
32095					3/2/2008	3/10/2008	122		\$0.00
Medium	Work In Progress				3/2/2008 12:33:00 AM				
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
32251					3/4/2008		120		\$0.00
Medium	Work In Progress				3/4/2008 11:11:58 AM				
Ontiveros, Joe	Need to unclogg urinal in the 2nd grade boys restroom.								
<u>Johnny Acuna</u>									
32909	Main Building	Library			4/2/2008		91		\$0.00
Medium	Work In Progress				4/2/2008 10:11:14 AM				
Estrada, Jesus	Carpet in Library needs to be replaced.								
<u>Jesus Estrada</u>									
33046					4/6/2008	4/27/2008	-11		\$0.00
Medium	Work In Progress				4/6/2008 12:18:17 AM	3/26/2008			
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
33081					4/6/2008	4/14/2008	87		\$0.00
Medium	Work In Progress				4/6/2008 12:18:28 AM				
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
33662					4/23/2008		70		\$0.00
Medium	Work In Progress			4/23/2008 10:36:24 AM					
Lozoya, Manny		Need to install a lock for new filing cabinet to classroom #398.							
Johnny Acuna									
33710		Cafeteria			4/24/2008		69		\$0.00
Medium	Work In Progress			4/24/2008 9:44:18 AM					
Lozoya, Manny		NAME PLATE FOR CAFETERIA CLERK. (AMANDA MEDRANO)							
Marisela Torres									
33774	Main Building	Library			4/28/2008		65		\$0.00
Medium	Work In Progress			4/28/2008 2:09:50 PM					
Torres, Marisela		The furniture in the library needs to be taken out before May 27th which is when new rug will be installed.							
Jesus Estrada									
34004					5/4/2008	5/12/2008	59		\$0.00
Medium	Work In Progress			5/4/2008 12:19:08 AM					
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
34261		Custodial			5/13/2008		50		\$0.00
Medium	Work In Progress			5/13/2008 10:45:35 AM					
Estrada, Jesus		ME PODRIA FACILITAR LA SIGUIENTE HERRAMIENTA? drill bit extension- #2 phillip drill bits- 1/4 " nut driver drill bit- 5/16"nut driver drill bit- #3 phillip drill bits. GRACIAS.							
Marisela Torres									
34692					5/29/2008		34		\$0.00
Medium	Work In Progress			5/29/2008 3:52:19 PM					
Ontiveros, Joe		need a replacement bubbler for outdoor water fountain in the playground area.							
Johnny Acuna									
34760					6/1/2008	6/7/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:21:47 AM					
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
34782					6/1/2008	6/9/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:21:54 AM					
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
34787					6/1/2008	6/9/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:21:56 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
34888					6/3/2008		29		\$0.00
Medium	Work In Progress			6/3/2008 8:13:29 AM					
Ontiveros, Guadalupe	Need a couple of loads of top soil and a tractor to spread out soil around grass area. On Field day, Firefighter trucks damaged part of playground grass area.								
<u>Johnny Acuna</u>									
34936					6/3/2008		29		\$0.00
Medium	Work In Progress	113		6/3/2008 4:50:44 PM					
Sotelo, Enrique	Ms. Moeller RM#113 needs to have installed a power outlet for that room for her computer.								
<u>Elizabeth Hernandez</u>									
35201					6/17/2008		15		\$0.00
Medium	Work In Progress			6/17/2008 8:32:15 AM					
Orozco, Danny	Need to replace both water valves on the wall for the washing machine in the laundry room to the kitchen. (Leaking valves).								
<u>Johnny Acuna</u>									
35262		Cafeteria			6/19/2008		13		\$0.00
Medium	Work In Progress			6/19/2008 10:55:32 AM					
Orozco, Danny	garbage disposal is still not working.								
Pat Cisneros SNP MGR 824-3822									
<u>Jacqueline Aguilar</u>									
35344					6/24/2008		8		\$0.00
Medium	Work In Progress			6/24/2008 4:57:38 PM					
Lozoya, Manny	Please change core in Maintenance office to (A-32).								
<u>Johnny Acuna</u>									
35375					6/25/2008		7		\$0.00
Medium	Work In Progress			6/25/2008 11:15:02 AM					
Estrada, Jesus	Principal requesting for new vinyl floor tile installed in portable #407.								
<u>Johnny Acuna</u>									
35448					6/30/2008		2		\$0.00
Medium	Work In Progress			6/30/2008 7:38:53 AM					
Estrada, Jesus	Please replace original carpet to Vinyl commercial tile to room #107. Room was used as a SPED room over the years and smells like urine. Also, please replace carpet to VCT in the teacher's lounge.								
<u>Johnny Acuna</u>									
7/2/2008 10:38:01 AM									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
35464					6/30/2008		2		\$0.00
Medium	Work In Progress			6/30/2008 1:37:34 PM					
Miranda, Danny	Principal requesting a full partition from wall to wall with a door in classroom restroom. (Room #107)								
Johnny Acuna									
35465					6/30/2008		2		\$0.00
Medium	Work In Progress			6/30/2008 2:26:05 PM					
Estrada, Jesus	Need to replace VCT in portable #413.								
Johnny Acuna									
Count: 34 Work Orders		Avg. Age of WO's	107	Total for Desert Trail Intermediate			0		\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
24378					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:51 AM					
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24379					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:51 AM					
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24380					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:51 AM					
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
29032		Cafeteria			11/7/2007		238		\$0.00
Medium	Work In Progress			11/7/2007 9:44:32 AM					
Moncayo, Fernando	AS PER HEALTH INSPECTION ON 10/29/07 -- BACK DOOR MISSING A GOOD SEAL TO PREVENT THE ENTRY OF INSECTS AND VERMIN.								
	AIDA SALCEDO - SNP COMPLIANCE COORDINATOR 882-6772 MARTHA FLORES - SNP MANAGER 589-2425								
Alma Terrell									
30613					1/14/2008		170		\$0.00
High	Work In Progress			1/14/2008 4:18:52 PM					
Lara, Ralph	need locks installed on new gates on new buss turn around.THXS								
Michael Munoz									
31725		Cafeteria			2/20/2008		133		\$0.00
Medium	Work In Progress			2/20/2008 4:02:08 PM					
Moncayo, Fernando	DOOR OPENS TO MIXER								
	AIDA SALCEDO - SNP COORD.								
Alma Terrell									
31757					2/21/2008		132		\$0.00
Medium	Work In Progress			2/21/2008 3:12:03 PM					
Gonzales, Angel	pat aguilar lawnmower need service - blades - battey need my weed eater repaired - thank you								
Patricio Aguilar									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Desert View ES									
31806					2/22/2008		131		\$0.00
Medium	Work In Progress			2/22/2008 3:26:23 PM					
Castillo, Carlos	paguilar need lights - philips fc8t 9/cw 22watt - philips fc6t 9/cw 20watt								
Patricio Aguilar									
31868					2/26/2008		0		\$0.00
Medium	Work In Progress			2/26/2008 10:14:40 AM	2/26/2008				
Munoz, Michael	Need to pour new sidewalke to connect existing sidewalk on east side of building to new playground equipment								
Alfredo Holguin									
32397					3/7/2008		117		\$0.00
Medium	Work In Progress			3/7/2008 3:33:31 PM					
Castillo, Carlos	pat aguilar need 4 emer light replaced								
Patricio Aguilar									
32944					4/3/2008		90		\$0.00
Medium	Work In Progress			4/3/2008 3:09:10 PM					
Castillo, Carlos	No power to ac lower grade wing.								
Patricio Aguilar									
33138		Cafeteria			4/7/2008		86		\$0.00
Medium	Work In Progress			4/7/2008 1:09:59 PM					
Moncayo, Fernando	SCREEN DOOR TO KITCHEN NEEDS TO BE REPLACED.								
	DIANA LAZARIN - SNP MGR 589-2425								
Jacqueline Aguilar									
33573	Main Building				4/21/2008		72		\$0.00
Medium	Work In Progress			4/21/2008 8:48:06 AM					
Appelzoller, Fred	This work order is for a broken waterline that is on the front sidewalk and we used to water the grass that is in the main entrance so will you please come and fixed for us. THANK YOU.								
Hector Rivera									
34251					5/12/2008		51		\$0.00
High	Work In Progress			5/12/2008 4:21:27 PM					
Aguilar, Patricio	there are red tiles around the campus on the sidewalks that are missing. this is a trip hazard. either order the material to repair the tile or fill w/ concrete.								
Michael Munoz									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
34523	Main Building	Custodial			5/22/2008		41		\$0.00
Medium	Work In Progress			5/22/2008 8:45:17 AM					
Briones, Enrique		This work order is for warehouse will you please come and pickup the computers that are in the storage they are already checked and ready to go we need to clean the storage so they can moved. THANK YOU IN ADVANCED.							
Hector Rivera									
34583					5/23/2008		40		\$0.00
Medium	Work In Progress			5/23/2008 3:23:15 PM					
Castillo, Carlos		paguilar need 3 emer lights replaced dinning room = gym - left front hall way							
Patricio Aguilar									
34983					6/5/2008		27		\$0.00
Medium	Work In Progress			6/5/2008 3:29:25 PM					
Castillo, Carlos		Need 3 emerg. lights replaced in dining rm, gym, front hallway asp PM 34006.							
Patricio Aguilar									
35261		Restroom (Boys)			6/19/2008		13		\$0.00
Medium	Work In Progress			6/19/2008 9:38:55 AM					
Villalobos, David		This work order is for a clogged urinal on the boys restroom will you please send somebody to fixed for us.ATTENTION MARGRET.THANK YOU IN ADVANCED.							
Hector Rivera									
35270		Custodial			6/19/2008		13		\$0.00
Medium	Work In Progress			6/19/2008 3:36:25 PM					
Carbajal, Jimmy		This work order is for a broken vacum cleaner something is wrong with the motor will you come and picked up.THANK YOU IN ADVANCED.							
Hector Rivera									
35469					6/30/2008		2		\$0.00
Medium	Work In Progress			6/30/2008 3:34:07 PM					
Carrasco, Danny		pat aguilar 15 1/2" x 43 1/2" double pan port 1 13 1/2" x 40" double pan port 2 13 1/2" x 64" safty glass dinning room back door 13 1/2" x 64" safty glass left hall way							
Patricio Aguilar									
Count: 20 Work Orders		Avg. Age of WO's 123		Total for Desert View ES			0	\$0.00	

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
24382					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:51 AM					
Villalobos, David	Yearly - GAC Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24381					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:51 AM					
Villalobos, David	Yearly - GAC Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24383					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:51 AM					
Villalobos, David	Yearly - GAC Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24815	Pre-K	Classroom			7/16/2007		352		\$0.00
Medium	Work In Progress	PRE-K		7/16/2007 4:18:02 PM					
Boyd, David	AS PER JUAN AMBRIZ-ROOF LEAKED IN 2 OF THE PRE-K CLASSROOMS.					ON HOLD UNTIL MR. BOYD LOOKS INTO THIS, TO MAKE SURE IT IS NOT UNDER WARRENTY.			
Mary Garcia									
24918	RTC	Classroom			7/19/2007		349		\$0.00
Medium	Work In Progress	ACROSS THE		7/19/2007 2:34:45 PM					
Ontiveros, Guadalupe	AS PER GLORIA SAENZ-IF A SIDE WALK CAN BE INSTALLED BEHIND THE PORTABLE. THERE IS TO MUCH SAND FOR STUDENT TO WALK IN.					1/14 - Asp Mike route to Lupe			
Mary Garcia									
26441		Cafeteria			8/30/2007		307		\$0.00
Medium	Work In Progress			8/30/2007 9:55:03 AM					
Moncayo, Fernando	Water leaking from garbage disposal water line area.								
	Gessica Blazquez - SNP Manager 882-6784								
Alma Terrell									
26842		Portables			9/10/2007		296		\$0.00
Medium	Work In Progress	STORAGE-MS.		9/10/2007 1:33:27 PM					
Ambriz, Juan	AS PER MS. SALINAS-THE STORAGE UNIT NEEDS ADDITIONAL SHELVING AND WOULD LIKE TO HAVE SOME INSTALLED. BILINGUAL DEPT. HAS NO MATERIALS FOR THIS, AND WOULD LIKE TO KNOW IF MAINTENANCE WOULD BE ABLE TO SUPPLY THEM WITH THE MATERIALS NEEDED.					9/19 - Asp Mike route to Juan Ambriz			
Mary Garcia									
28141		Office			10/15/2007		261		\$0.00
Medium	Work In Progress	C-WING		10/15/2007 3:07:50 PM					
Miranda, Danny	AS PER SHEILA RAIHL-NEED TO REMOVE OBSERVATION WINDOW IN HER OFFICE.					ASP Mike route to Danny 10/25			
Mary Garcia									
7/2/2008 10:38:01 AM									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									
Location: GAC									
28143		Office			10/15/2007		261		\$0.00
Medium	Work In Progress	C-WING		10/15/2007 3:09:23 PM					
Miranda, Danny		AS PER MS. RAIHL-AFTER REMOVING THE WINDOW, THE WALL NEEDS TO BE TAPED/TEXTURED AND PAINTED.				10/25 - ASP Mike route to Danny M.			
Mary Garcia									
29377	RTC	Stairway			11/20/2007		225		\$0.00
Medium	Work In Progress	Portable ramps		11/20/2007 3:23:11 PM					
Ambriz, Juan		As per Ms. Julie Hinojosa Ramp boards are worpped and seperated. Students tripping need to be replaced as sson as possible for Staff and Student safety							
Juan Ambriz									
29783					12/4/2007		211		\$0.00
Medium	Work In Progress			12/4/2007 9:36:05 AM					
Ambriz, Jose		Receptionist Area - Need to check for addtional Heating and Cooling (see Mike)							
Michael Munoz									
30298					1/6/2008	1/27/2008	178		\$0.00
Medium	Work In Progress			1/6/2008 12:28:56 AM					
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
30698		Computer Lab			1/16/2008		168		\$0.00
Medium	Work In Progress			1/16/2008 3:30:49 PM					
Ronquillo, Ruben		As per Ms. Socorro need to tint windows in computer lab							
Juan Ambriz									
30766		Cafeteria			1/17/2008		167		\$0.00
Medium	Work In Progress	Cafeteria Heating		1/17/2008 3:44:54 PM					
Ambriz, Jose		Need to repair heating unit in cafeteria not working properly							
Juan Ambriz									
30848					1/22/2008		162		\$0.00
Medium	Work In Progress			1/22/2008 3:20:21 PM					
Ambriz, Juan		AS PER IRMA TRUJILLO-SOME OF THE LIGHTS IN CONFERENCE ROOM #2 ARE OUT AND NEED TO BE REPLACED.							
Mary Garcia									
31869		Office			2/26/2008		127		\$0.00
Medium	Work In Progress			2/26/2008 10:19:59 AM					
Ambriz, Jose		Gloria Lopez - This office is getting to hot. neet to balance system or provide her with a supply diffuser with a damper so she can limit the supply air if necessary.							
Alfredo Holguin									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									
Location: GAC									
32027					2/29/2008		124		\$0.00
Medium	Work In Progress			2/29/2008 8:43:11 AM					
Castillo, Carlos		As per Mike generate work order for installation of emergency lighting at the Gac.							
Michael Munoz									
32207		Office			3/3/2008		121		\$0.00
Medium	Work In Progress	C-WING		3/3/2008 11:17:12 AM					
Ambriz, Juan		AS PER LINDA REYES-NEED TO HAVE DESK LIGHT BULBS REPLACED.							
Mary Garcia									
32512		Office			3/12/2008		112		\$0.00
Medium	Work In Progress	B-WING		3/12/2008 10:18:58 AM					
Lara, Ralph		AS PER MS. BROWDER-NEED AN OFFICE KEY A24 FOR MR. SUTTMILLER.							
Mary Garcia									
32567		Office			3/13/2008		111		\$0.00
Medium	Work In Progress	A WING		3/13/2008 4:47:47 PM					
Ambriz, Juan		AS PER JULIE-NEED TO HAVE DOOR WINDOW TINTED.							
Mary Garcia									
32919		Mechanical Room			4/2/2008		91		\$0.00
Medium	Work In Progress	A-Wing		4/2/2008 3:22:26 PM					
Villalobos, David		Need the gasket for the circulating pump							
Juan Ambriz									
33047					4/6/2008	4/27/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:17 AM					
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
33055					4/6/2008	4/27/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:20 AM					
Orozco, Danny		Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
33218		Hallway/Corridor			4/9/2008		84		\$0.00
Medium	Work In Progress	A-WING		4/9/2008 8:32:32 AM					
Estrada, Jesus		AS PER JUAN AMBRIZ-NEED TO RETILE THE HALLWAY NEXT TO MAINTENANCE AND CUSTODIAL OFFICES.							
Mary Garcia									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									
Location:		GAC							
33223		Office			4/9/2008		84		\$0.00
Medium	Work In Progress	C-WING		4/9/2008 10:24:19 AM					
Lara, Ralph		AS PER WILMA MARTINEZ-NEED TO HAVE A STORAGE CABINET KEYED. (ITEMS ARE DUE TO COME IN & MUST HAVE THEM LOCKED UP.)							
Mary Garcia									
33241		Hallway/Corridor			4/9/2008		84		\$0.00
Medium	Work In Progress	A-Wing Exit door		4/9/2008 1:15:03 PM					
Ambriz, Juan		Need to replace door closure on door							
Juan Ambriz									
33256		Restroom (Boys)			4/9/2008		84		\$0.00
Medium	Work In Progress	A-Wing		4/9/2008 3:16:16 PM					
Castillo, Carlos		Need to replace the whole light in A-Wing restroom							
Juan Ambriz									
33422					4/15/2008		78		\$0.00
Medium	Work In Progress	PATIO AREA		4/15/2008 9:42:48 AM					
Villalobos, David		AS PER MIKE SORIA-NEED TO REPAIR A BROKEN DRIP LINE TO THE SPRINKLER SYSTEM.							
Mary Garcia									
33437		Office			4/16/2008		77		\$0.00
Medium	Work In Progress	C-WING		4/16/2008 10:53:53 AM					
Lara, Ralph		AS PER OFELIA-NEED TO HAVE ALL HER OFFICE DRAWERS TO BE REKEYED INTO ONE KEY. THIS WAY SHE HAS ONE KEY THAT OPENS AND LOCKS ALL DRAWERS IN THE OFFICE.				RAFA IS AWARE OF THIS			
Mary Garcia									
33438		Office			4/16/2008		77		\$0.00
Medium	Work In Progress	C-WING		4/16/2008 10:57:27 AM					
Lara, Ralph		AS PER SALLY S. - NEED TO HAVE ALL HER OFFICE DRAWERS TO BE REKEYED INTO ONE KEY. THIS WAY SHE HAS ONE KEY THAT OPENS AND LOCKS ALL DRAWERS IN THE OFFICE.				RAFA IS AWARE OF THIS			
Mary Garcia									
33439		Office			4/16/2008		77		\$0.00
Medium	Work In Progress	C-WING		4/16/2008 11:00:33 AM					
Lara, Ralph		AS PER DORA-NEED TO HAVE ALL HER OFFICE DRAWERS REKEYED INOT ONE KEY. THIS WAY SHE HAS ONE KEY THAT OPENS AND LOCKS ALL DRAWERS IN THE OFFICE				RAFA IS AWARE OF THIS			
Mary Garcia									
33656	Pre-K				4/23/2008		70		\$0.00
Medium	Work In Progress	PLAY GROUND		4/23/2008 7:54:46 AM					
Soria, Mike		AS PER MS. BERRY-NEED TO HAVE 2 PLANTERS IN THE BACK OF PRE-K FILLED UP WITH SAND.				OKAY AS PER MR. CHAVEZ			
Mary Garcia									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		GAC								
33672		Office			4/23/2008		70		\$0.00	
Medium	Work In Progress	STM POA			4/23/2008 2:24:21 PM					
Castillo, Carlos		AS PER JUANA ESPINOZA-NEED AN ELECTRICAL OUTLET IN THE POA OFFICE/PARENT CENTER.								
Mary Garcia										
33740		Office			4/24/2008		69		\$0.00	
Medium	Work In Progress	A-WING			4/24/2008 5:04:54 PM					
Castillo, Carlos		AS PER JUAN A. - NEED TO HAVE AN ELECTRICAL OUTLET MOVED OVER SOME WHAT WITH IN THE SAME WALL IN OREDER TO HAVE EXTRA ROOM FOR SOME CABINETS.								
Mary Garcia										
33813		Cafeteria			4/29/2008		64		\$0.00	
Medium	Work In Progress				4/29/2008 12:00:38 PM					
Moncayo, Fernando		WARMER FOR THE PRE-K JUST DIED. (NEEDS IT TO TRANSPORT THE FOOD.)								
		GESSICA B. SNP MGR 882-6784								
Jacqueline Aguilar										
33945					5/2/2008		61		\$0.00	
Medium	Work In Progress	Reception Area			5/2/2008 10:53:10 AM					
Castillo, Carlos		New refreg package unit will be installed @ GAC (Reception Area).								
Michael Munoz										
33946					5/2/2008		61		\$0.00	
Medium	Work In Progress	Reception Area			5/2/2008 10:57:36 AM					
Ambriz, Jose		New refreg package unit will be installed @ GAC (Reception Area).								
Michael Munoz										
33949		Office			5/2/2008		61		\$0.00	
Medium	Work In Progress	A-WING			5/2/2008 1:42:23 PM					
Lara, Ralph		AS PER CORA-NEED TO HAVE AN AB36 KEY MADE FOR MARCO PERALES W/TECHNOLOGY.								
Mary Garcia										
34082		Cafeteria			5/6/2008		57		\$0.00	
Medium	Work In Progress				5/6/2008 9:19:08 AM					
Moncayo, Fernando		BRAKE WHEEL TO STOVE IS BROKEN.								
		GESSICA B. SNP MGR 882-6784								
Jacqueline Aguilar										

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
34205		Office			5/9/2008		54		\$0.00
Medium	Work In Progress	A-WING		5/9/2008 3:04:11 PM					
Ronquillo, Ruben	AS PER ART R.-IF COULD HAVE HIS OFFICE WINDOW REMOVED WHICH HAPPENS TO BE A SLIDE WINDOW AND INSTALL 1 SOLID PIECE WINDOW. (DUE TO TOO MUCH EQUIPMENT IN HIS OFFICE DIRT KEEPS COMING IN)								
Mary Garcia									
34238					5/12/2008		51		\$0.00
Medium	Work In Progress			5/12/2008 3:03:11 PM					
Munoz, Michael	Need to abate tile and have an air clearance,so work order 33218 can be completed.								
Michael Munoz									
34265		Office			5/13/2008		50		\$0.00
Medium	Work In Progress	C-WING		5/13/2008 1:02:38 PM					
Ambriz, Juan	AS PER LEZIE LEYVA-NEED TO HAVE A KEYBOARD INSTALLED.								
Mary Garcia									
34310		Cafeteria			5/14/2008		49		\$0.00
Medium	Work In Progress			5/14/2008 10:54:20 AM					
Lara, Ralph	Fernando needs keys for GAC Kitchen and Electric/Mechanical Room								
	Demetrious P. Giovas - SNP Director								
Alma Terrell									
34318					5/14/2008		49		\$0.00
Medium	Work In Progress	Board Room		5/14/2008 3:05:18 PM					
Castillo, Carlos	Need to replace 4 Emergency Lights in the board room not working								
Juan Ambriz									
34320		Parking Lot			5/14/2008		49		\$0.00
Medium	Work In Progress	Flag pole		5/14/2008 3:23:22 PM					
Orozco, Danny	Need to replace the rope and hooks on the flag pole (need bucket truck)								
Juan Ambriz									
34424					5/19/2008		44		\$0.00
Medium	Work In Progress	Front lobby		5/19/2008 3:27:45 PM					
Ambriz, Juan	As Per Art Rulioba need to Install TV stand and TV in front lobby								
Juan Ambriz									
34547		Hallway/Corridor			5/22/2008		41		\$0.00
Medium	Work In Progress	A-Wing Unit		5/22/2008 3:35:23 PM					
Ambriz, Jose	A-Wing Unit not working properly								
Juan Ambriz									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
34597		Hallway/Corridor			5/27/2008		36		\$0.00
Medium	Work In Progress	A-WING		5/27/2008 9:56:25 AM					
Ambriz, Juan	AS PER ELISA S. -NEED TO HAVE THE BALLAST REPLACED								
Mary Garcia									
34619		Electrical Room			5/27/2008		36		\$0.00
Medium	Work In Progress	A-wing Main		5/27/2008 3:31:31 PM					
Castillo, Carlos	Need to Install conduit in electrical wiring in motor								
Juan Ambriz									
34945		Office			6/4/2008		28		\$0.00
Medium	Work In Progress	SPED Office		6/4/2008 8:34:06 AM					
Villalobos, David	Need to reroute gas line to install new A/C unit								
Juan Ambriz									
34976					6/5/2008		27		\$0.00
Medium	Work In Progress			6/5/2008 8:32:52 AM					
Morales, Ramon	ABATEMENT IN THE CUSTODIAL/MAINTENANCE HALLWAY AREA WILL BE DONE ON JUNE 13. PLEASE HAVE THE AREA EMPTY AND READY.								
Jesus Estrada									
34977		Office			6/5/2008		27		\$0.00
Medium	Work In Progress	A-WING		6/5/2008 10:30:37 AM					
Morales, Ramon	AS PER MS. BROWDER-NEED TO HAVE A XEROX MACHINE MOVED FROM SNP TO HR (MS. PHILLIPS OFFICE)		TALKED W/ PAM AND OKAY TO MOVE IT.						
Mary Garcia									
35005		Hallway/Corridor			6/6/2008		26		\$0.00
Medium	Work In Progress	C-Wing reception		6/6/2008 3:16:31 PM					
Ambriz, Juan	Need to paint door & window frames in C-Wing reception area								
Juan Ambriz									
35068	Pre-K	Classroom			6/10/2008		22		\$0.00
Medium	Work In Progress	ROOM 202		6/10/2008 11:16:10 AM					
Ambriz, Juan	AS PER MS. BERRY-NEED TO HAVE A BULLETIN BOARD MOVED FROM THE HALL/BATHRRROM TO THE NORTH WALL. (SEE ATTACHED DIAGRAM)								
Mary Garcia									
35069	Pre-K	Classroom			6/10/2008		22		\$0.00
Medium	Work In Progress	ROOM 203		6/10/2008 11:18:04 AM					
Ambriz, Juan	AS PER MS. BERRY-NEED TO HAVE A WHITE BOARD AND 2 SMALL BULLETIN BOARDS MOVED. (SEE ATTACHED DIAGRAM)								
Mary Garcia									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		GAC								
35070	Pre-K				6/10/2008		22		\$0.00	
Medium	Work In Progress	OUTSIDE AREA		6/10/2008 11:20:33 AM						
Morales, Ramon	AS PER MS. BERRY-NEED TO HAVE SOMEONE WATER PLANTS OUT FRONT OF PLAYGROUND AND ALSO THE ONES IN THE INSIDE HALLWAY, UNTIL THEY RETURN TO WORK.									
Mary Garcia										
35237		Office			6/17/2008		15		\$0.00	
Medium	Work In Progress	C-WING		6/17/2008 5:36:23 PM						
Ambriz, Juan	AS PER HEIDI -NEED TO HAVE A SHELF AND CART ASSEMBLED.									
Mary Garcia										
35247		Office			6/18/2008		14		\$0.00	
Medium	Work In Progress	Maint. and		6/18/2008 3:18:35 PM						
Ambriz, Juan	Need to paint maint. and custodial offices									
Juan Ambriz										
35268		Office			6/19/2008		13		\$0.00	
Medium	Work In Progress	C-WING		6/19/2008 2:49:04 PM						
Ambriz, Juan	AS PER LINDA R. - NEED TO HAVE SOME BROKEN DRAWERS REMOVED AND REPLACED WITH NEW ONES.									
Mary Garcia										
35380		Restroom (Boys)			6/25/2008		7		\$0.00	
Medium	Work In Progress	B-WING		6/25/2008 2:32:35 PM						
Lara, Ralph	AS PER RAMON-NEED TO HAVE OUR LOCKSMITH FIX THE BATHROOM DOOR IN B-WING. THE KNOB NEEDS TO BE RESCREWED. JUAN ALREADY LOOKED INTO THIS AND IS NOT ABLE TO FIX IT.									
Mary Garcia										
35381	Pre-K	Cafeteria			6/25/2008		7		\$0.00	
Medium	Work In Progress	PRE-K		6/25/2008 2:36:05 PM						
Lara, Ralph	AS PER RAMON-OVER IN THE PRE-K CAFETERIA THE DOOR GOING TO THE OUTSIDE, CUSTODIAL IS HAVING TROUBLE LOCKING THE DOOR, DUE TO DOOR NOT BEING EVEN OR BENT.									
Mary Garcia										
35425		Classroom			6/26/2008		6		\$0.00	
Medium	Work In Progress	Pre-K #203		6/26/2008 3:34:36 PM						
Castillo, Carlos	Need to replace light switches in room 203 not working propely									
Juan Ambriz										
Count: 62 Work Orders			Avg. Age of WO's	109				Total for GAC	0	\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
24386					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:52 AM				
Villalobos, David	Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24823					7/17/2007		351		\$0.00
Medium	Work In Progress				7/17/2007 9:44:36 AM				
Lara, Ralph	Requested by Agustin Garcia Rm. 310A Academic Building-Door handle to Custodian's storage closet is broken and needs to be replaced before school begins.								
Velia Alarcon									
24836					7/17/2007		351		\$0.00
Medium	Work In Progress				7/17/2007 2:30:46 PM				
Lara, Ralph	Requested by Velia-Four HK7 keys are needed for the Intervention Staff that will be in Rm. 554.								
Velia Alarcon									
24912	North Building	Custodial			7/19/2007		349		\$0.00
Medium	Work In Progress				7/19/2007 11:54:19 AM				
Munoz, Joe	The windows in the attendance office need to be washed.								
25204	Boys Gym				7/30/2007		338		\$0.00
Medium	Work In Progress	Football Side			7/30/2007 2:49:17 PM				
Lara, Ralph	NEED A NEW DOOR FOR THE BOYS GYM FOOTBALL SIDE LOCKER ROOM DO TO VANDALISM								
Mario Apodaca									
25208					7/30/2007		338		\$0.00
Medium	Work In Progress				7/30/2007 3:12:59 PM				
Lara, Ralph	Requested by Velia for rm. 245 over Varsity Gym-Mr. Foster has placed the Parent Out-Reach Ambassador's in this classroom has their new office. Four HE38 keys are need to issue to the Ambassador's. They will be re-located once a space is found for them.								
Velia Alarcon									
25212					7/30/2007		338		\$0.00
Medium	Work In Progress				7/30/2007 3:25:27 PM				
Lara, Ralph	Requested by Velia-Four HE1 (Gym Keys) are needed for the Parent Out-Reach Ambassador's to open small hallway over the Varsity Gym to access their new office/classroom.								
Velia Alarcon									
25221					7/30/2007		338		\$0.00
Medium	Work In Progress				7/30/2007 3:44:32 PM				
Lara, Ralph	Requested by Velia for Rm. 126A Main Building-Four HH16 keys are needed to office.								
Velia Alarcon									
7/2/2008 10:38:01 AM									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
25225					7/30/2007		338		\$0.00
Medium	Work In Progress			7/30/2007 4:00:35 PM					
Lara, Ralph	Requested by Velia for Rm. 554 Wood Shop-Four HK7 keys are needed for Intervention Staff.								
Velia Alarcon									
25259					7/31/2007		337		\$0.00
Medium	Work In Progress			7/31/2007 10:22:16 AM					
Lara, Ralph	Requested by Oscar Menchaca Rm. 123 Custodial Storage Room in Main Building-Door lock does not work.								
Velia Alarcon									
25260					7/31/2007		337		\$0.00
Medium	Work In Progress			7/31/2007 10:34:23 AM					
Lara, Ralph	Requested by Debbie Costalez Rm. 118 Bookkeeper's Office in Main Building-The bookkeeping office in the same as the concession stand. The concession stand is going to be used as a Marketing classroom. The bookkeeping office needs to be off master and four keys are needed.								
Velia Alarcon									
25342	Boys Gym	Dressing Room			8/2/2007		335		\$0.00
Medium	Work In Progress			8/2/2007 1:24:08 PM					
Lara, Ralph	NEED A NEW DOOR CYLINDER AT THE GIRLS LOCKERROOM AT BOYS GYM ROOM 404								
Mario Apodaca									
25343	Cafeteria (1998)	Restroom (Boys)			8/2/2007		335		\$0.00
Medium	Work In Progress			8/2/2007 1:26:39 PM					
Lara, Ralph	BOYS RESTROOM NEED A NEW LEVER LOCKSET FOR THE DOOR								
Mario Apodaca									
25344	Academic Bldg				8/2/2007		335		\$0.00
Medium	Work In Progress			8/2/2007 1:30:21 PM					
Lara, Ralph	A KEY IS BROKEN IN A DOOR CYLINDER AT ACADEMIC BLDG ON THE N-SIDE OF TNE BLDG								
Mario Apodaca									
25682	Old English Bldg	Restroom (Boys)			8/9/2007		328		\$0.00
Medium	Work In Progress			8/9/2007 2:51:13 PM					
Lara, Ralph	BOYS RESTROOM AT THE TOP FLOOR NEED A NEW KEY CYLINDER								
Mario Apodaca									
25689					8/9/2007		328		\$0.00
Medium	Work In Progress			8/9/2007 3:38:10 PM					
Lara, Ralph	Attn;MR. LATOYA my key is about to break,need one asap THANK YOU!!								
Fernando Moncayo									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
25690					8/9/2007		328		\$0.00
Medium	Work In Progress			8/9/2007 3:40:46 PM					
Lara, Ralph	CAFETERIA WEST wing door lock has something inside the cylinder								
<u>Fernando Moncayo</u>									
25691	Varsity Gym	Gym			8/9/2007		328		\$0.00
Medium	Work In Progress			8/9/2007 3:43:17 PM					
Lara, Ralph	GIRL'S dressing rooms in VARSITY gym, has a broken lock handle								
<u>Fernando Moncayo</u>									
25726	Concession	Football Field			8/10/2007		327		\$0.00
Medium	Work In Progress			8/10/2007 3:12:22 PM					
Lara, Ralph	CONCESSION STAND AT FOOTBALL NEED A NEW DOOR LEVER FOR BACK ROOM								
<u>Mario Apodaca</u>									
25743					8/10/2007		327		\$0.00
Medium	Work In Progress			8/10/2007 4:11:29 PM					
Lara, Ralph	Requested by Ms. Jaraba Rm. 124 Main Building-Rekey desk and three keys will be needed.								
<u>Velia Alarcon</u>									
25760					8/13/2007		324		\$0.00
Medium	Work In Progress			8/13/2007 9:52:12 AM					
Lara, Ralph	Requested by Ms. Jaraba Rm. 124 Main Building-Replace missing cylinder in closet and three keys will be needed.								
<u>Velia Alarcon</u>									
25763					8/13/2007		324		\$0.00
Medium	Work In Progress			8/13/2007 9:57:56 AM					
Lara, Ralph	Requested by Velia for Cafeteria-A dead bolt lock needs to be installed on both doors that connect the Conference rooms to the kitchen area of the Cafeteria and five keys are needed.								
<u>Velia Alarcon</u>									
25767					8/13/2007		324		\$0.00
Medium	Work In Progress			8/13/2007 11:07:57 AM					
Lara, Ralph	Requested by Velia for Main Building and Academic Building Mail Rooms-Combination locks into mail rooms need to be changed, several students have figured out combination. Also, WO# 17300 has not been completed, please review.								
<u>Velia Alarcon</u>									
25771					8/13/2007		324		\$0.00
Medium	Work In Progress			8/13/2007 11:37:05 AM					
Lara, Ralph	Requested by Ms. Lam Rm. 104 Main Building-Lock of the North door can no be locked.								
<u>Velia Alarcon</u>									

7/2/2008 10:38:01 AM

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

25774					8/13/2007		324		\$0.00
Medium	Work In Progress				8/13/2007 12:04:00 PM				
Lara, Ralph		Requested by Chief Arms Rm. 203 North Building-Key does not want to open classroom.							
Velia Alarcon									
25782					8/13/2007		324		\$0.00
Medium	Work In Progress				8/13/2007 1:01:42 PM				
Lara, Ralph		Requested by Velia-Five HJ2 keys are needed for room 801.							
Velia Alarcon									
25783		Gym			8/13/2007		324		\$0.00
Medium	Work In Progress				8/13/2007 1:08:57 PM				
Lara, Ralph		Requested by Velia-Three HG3 keys are needed (Girl's Gym Office.)							
Velia Alarcon									
25786					8/13/2007		324		\$0.00
Medium	Work In Progress				8/13/2007 1:35:55 PM				
Lara, Ralph		Requested by Velia Rm. 153 Old English Building-Room # 153 needs to have the door knob replaced and re-keyed, four keys will be needed.							
Velia Alarcon									
25788					8/13/2007		324		\$0.00
Medium	Work In Progress				8/13/2007 1:47:30 PM				
Lara, Ralph		Requested by Velia-Four D Master keys are needed.							
Velia Alarcon									
25790					8/13/2007		324		\$0.00
Medium	Work In Progress				8/13/2007 1:55:05 PM				
Lara, Ralph		Requested by Velia-Five HEM1 Master keys are needed.							
Velia Alarcon									
25791					8/13/2007		324		\$0.00
Medium	Work In Progress				8/13/2007 1:59:05 PM				
Lara, Ralph		Requested by Velia-Two M251 keys are needed for the new Cross Country Coach for restrooms at Football Field.							
Velia Alarcon									
25894					8/15/2007		322		\$0.00
Medium	Work In Progress	GATE			8/15/2007 2:32:57 PM				
Lara, Ralph		Mr. Joe S. Mendez, would like to request a key for the gate in the back of Gadsden High School by the alfalfa field in the back of schools ground. That he is requesting is (GM-7) master key to lock. If any questions you may reach me at (505) 882-3364.							
Joe Mendez									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
25933					8/16/2007		321		\$0.00
Medium	Work In Progress			8/16/2007 2:24:53 PM					
Castillo, Carlos	Emerg. Light not working as per PM 24571 Comp. Lab Southside Entrance Comp. Lab. Storage Boys Locker Rm West Wing Panther Hut								
<u>Rudy Arreola</u>									
25977	Cafeteria (1998)	Restroom (Boys)			8/17/2007		320		\$0.00
Medium	Work In Progress			8/17/2007 3:20:32 PM					
Appelzoller, Fred	the water fountain by the boys restroom is leaking								
<u>Joe Munoz</u>									
26031	Counselors				8/20/2007		317		\$0.00
Medium	Work In Progress			8/20/2007 10:30:31 AM					
Lara, Ralph	NEED LOCK FOR COUNSELING CENTER. PLEASE SEE LUPE ONTIVEROS FOR DETAILS. THANKS.								
<u>Guadalupe Ontiveros</u>									
26099					8/21/2007		316		\$0.00
Medium	Work In Progress			8/21/2007 2:10:31 PM					
Lara, Ralph	NEED SIX NEW LOCK FOR THE NEW POWER PLANT								
<u>Mario Apodaca</u>									
26102	Cafeteria (1998)	Restroom (Boys)			8/21/2007		316		\$0.00
Medium	Work In Progress			8/21/2007 2:32:13 PM					
Lara, Ralph	Requested by Velia for Cafeteria-Door knob for the Boy's Restroom does not lock properly, needs to be repaired.								
<u>Velia Alarcon</u>									
26105	Main Building				8/21/2007		316		\$0.00
Medium	Work In Progress			8/21/2007 2:42:35 PM					
Lara, Ralph	Requested by Ms. Moreno Rm. 126 Main Building-Lock for classroom sticks, can't get in or get out.								
<u>Velia Alarcon</u>									
26106	Main Building				8/21/2007		316		\$0.00
Medium	Work In Progress			8/21/2007 2:50:45 PM					
Lara, Ralph	Requested by Ms. Moreno for Women's Faculty Restroom in Main Building-Key does not open restroom.								
<u>Velia Alarcon</u>									
26109	Old English Bldg				8/21/2007		316		\$0.00
Medium	Work In Progress			8/21/2007 3:09:33 PM					
Lara, Ralph	Requested by Ms. Spivey Rm. 134 Old English Building- Tighten door knob on room 134-key sticks in lock.								
<u>Velia Alarcon</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

26110	Old English Bldg				8/21/2007		316		\$0.00
Medium	Work In Progress				8/21/2007 3:12:21 PM				

Lara, Ralph Requested by Ms. Spivey Rm. 134A Old English Building-Fix door frame on bathroom.

Velia Alarcon

26114	Old English Bldg				8/21/2007		316		\$0.00
Medium	Work In Progress				8/21/2007 3:32:49 PM				

Lara, Ralph Requested by Ms. Zapien Rm. 154 Old English Building-Request to have name plate made to be placed over door.

Velia Alarcon

26444					8/30/2007		307		\$0.00
Medium	Work In Progress				8/30/2007 10:45:01 AM				

Lara, Ralph Requested by Linda Solis Rm. 801 Parent Center-The door between room 801 and 800 won't close, latch is stuck.

Velia Alarcon

26656	Concession	Football Field			9/4/2007		302		\$0.00
Medium	Work In Progress				9/4/2007 11:09:22 AM				

Lara, Ralph THE LOCK SET AT CONCESSION STAD NEED WORK

Mario Apodaca

26853	Academic Bldg	Restroom (Boys)			9/10/2007		296		\$0.00
Medium	Work In Progress				9/10/2007 3:44:28 PM				

Munoz, Michael THE PARTITONS AT ACADIMIC BLDG AT THE BOY'S RESTROOM ARE VANDALIS ON THE E/SIDE WING (4/28/08 Asp Mario has not been done)

Mario Apodaca

26892	Counselors	Portables			9/11/2007		295		\$0.00
Medium	Work In Progress				9/11/2007 1:01:38 PM				

Lara, Ralph We need the door that seperates RM 823 and 822 to lock students are trying to open the door from the other side.

Rudy Arreola

27346	Counselors				9/24/2007		282		\$0.00
Medium	Work In Progress				9/24/2007 8:18:44 AM				

Moncayo, Fernando Requested by Marie for Counseling Center-Thermostat does not work and it is very hot in Counseling Center.

Velia Alarcon

27519					9/27/2007		279		\$0.00
Medium	Work In Progress				9/27/2007 3:45:50 PM				

Lara, Ralph Requested by Velia for Rm. 109D Main Building Men's Faculty Restroom-The cylinder lock is missing out of the door knob, please replace.

Velia Alarcon

7/2/2008 10:38:01 AM

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
28064		Electrical Room			10/11/2007		265		\$0.00
Medium	Work In Progress			10/11/2007 1:26:26 PM					
Apodaca, Mario		All numbers in electrical panels need to be updated.							
Jesus Estrada									
28138	Business	Hallway/Corridor			10/15/2007		261		\$0.00
Medium	Work In Progress			10/15/2007 3:00:58 PM					
Lara, Ralph		NEED TO WELD A DOOR HING AT THE BUS BLDG ON THE N-END BOTT FLOOR							
Mario Apodaca									
28235	Agricultural				10/17/2007		259		\$0.00
Medium	Work In Progress			10/17/2007 2:55:30 PM					
Appelzoller, Fred		THE GAS REGULATOR AT THE AG BLDG IS LEAKING NEED FIXING							
Mario Apodaca									
28307	North Building				10/19/2007		257		\$0.00
Medium	Work In Progress			10/19/2007 8:03:48 AM					
Vallejo, Albert		Shingles in North bldg(G wing)are coming off from roof				Pending from Fernando			
Fernando Moncayo									
28317		Electrical Room			10/19/2007		257		\$0.00
Medium	Work In Progress			10/19/2007 8:39:04 AM					
Castillo, Carlos		NEED THE ASSIST OF THE ELECTRICAN TOO HELP OUT ON NUMBERING THE BREAKER W/O 28064							
Mario Apodaca									
28397	Cafeteria (1998)				10/23/2007		253		\$0.00
Medium	Work In Progress			10/23/2007 10:56:32					
Vallejo, Albert		Please paint patio frames around canopy area.				Pending from Fernando			
Michael Munoz									
28398	Varsity Gym				10/23/2007		253		\$0.00
Medium	Work In Progress			10/23/2007 10:59:51					
Ambriz, Jose		Please order parts to repair water fountain in lobby area.				Pending from Fernando			
Michael Munoz									
28401	Academic Bldg				10/23/2007		253		\$0.00
Medium	Work In Progress			10/23/2007 11:02:57					
Ontiveros, Guadalupe		Please install irr. watering system to all trees and shurbs around bldg.							
Michael Munoz									
28437	North Building				10/23/2007		253		\$0.00
Medium	Work In Progress			10/23/2007 3:45:44 PM					
Lara, Ralph		Requested by Mr. Belle Rm 213 North Building-Lock on file cabinet is broken-comes out completely.							
Velia Alarcon									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
28442	Main Building				10/23/2007		253		\$0.00
Medium	Work In Progress				10/23/2007 3:49:53 PM				
Lara, Ralph	Requested by Velia for Rm. 109d Main Building Men's Faculty Restroom-Lock cylinder has being missing for several months. Students are getting in and ditching, needs to be replaced as soon as possible.								
Velia Alarcon									
28480	Agricultural				10/24/2007		252		\$0.00
Medium	Work In Progress				10/24/2007 11:28:25				
Appelzoller, Fred	REPLACE GAS REGULATORS IN AG BLDG.								
Michael Munoz									
28707					10/30/2007		246		\$0.00
Medium	Work In Progress				10/30/2007 4:06:05 PM				
Gonzales, Angel	Truck #166 driver's side door won't close,safety issue								
Fernando Moncayo									
28790	Academic Bldg				11/1/2007		244		\$0.00
Medium	Work In Progress				11/1/2007 11:33:00 AM				
Lara, Ralph	Requested by Ms. Kalkwarf for the Faculty Restrooms (both North and South Restroom) in the Academic Building-Door locks do not open at times, difficult to turn key.								
Velia Alarcon									
28792	North Building				11/1/2007		244		\$0.00
Medium	Work In Progress				11/1/2007 12:56:25 PM				
Lara, Ralph	Requested by Ms. Leahy Rm. 215 North Building- Replace door stopper on the south side door.								
Velia Alarcon									
28794	Concession				11/1/2007		244		\$0.00
Medium	Work In Progress				11/1/2007 1:00:55 PM				
Castillo, Carlos	Requested by Ms. I. Ramos for Panther Paw/Concession Stand-Need to have a power outlet put in the backroom of the Concession Stand.								
Velia Alarcon									
28978	Old English Bldg	Classroom			11/6/2007		239		\$0.00
Medium	Work In Progress				11/6/2007 8:07:59 AM				
Lara, Ralph	OLd English room 148 door is badly broken complete coming apart,need to be replace ASAP.Thanks!!								
Fernando Moncayo									
29036					11/7/2007		238		\$0.00
Medium	Work In Progress				11/7/2007 10:24:39 AM				
Lara, Ralph	Requested by Mr. Contaldo Rm. 103 Main Building- Make key for drawer locks. I already gave our Locksmith one of the locks which are all keyed alike.								
Velia Alarcon									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
29164	North Building	Hallway/Corridor			11/13/2007		232		\$0.00
Medium	Work In Progress				11/13/2007 12:52:11				
Lara, Ralph	A SET OF DOOR HINGES ARE BROKEN AT N-BLDG BY THE OFFICE AT G -WING NEED TOBE REWELD								
Mario Apodaca									
29201					11/14/2007		231		\$0.00
Medium	Work In Progress				11/14/2007 9:26:12 AM				
Lara, Ralph	Requested by Bonnie Sloan for Library-Has a key to a desk that used to work, but they put a new key lock and now it doesn't work, please repair.								
Velia Alarcon									
29202	Library				11/14/2007		231		\$0.00
Medium	Work In Progress				11/14/2007 9:29:18 AM				
Lara, Ralph	Requested by Mr. Grubaugh for Library-The lock is failing on the south emergency exit in the Library. If the lock can not be repaired, the door needs to be chained at night.								
Velia Alarcon									
29336					11/19/2007		226		\$0.00
Medium	Work In Progress				11/19/2007 1:21:16 PM				
Lara, Ralph	Requested by Mr. McNiece Rm. 213 North Building-2nd door does not shut/lock. (North door)								
Velia Alarcon									
29337					11/19/2007		226		\$0.00
Medium	Work In Progress				11/19/2007 1:21:28 PM				
Lara, Ralph	Requested by Mr. McNiece Rm. 213 North Building-2nd door does not shut/lock. (North door)								
Velia Alarcon									
29467					11/27/2007		218		\$0.00
Medium	Work In Progress				11/27/2007 4:02:20 PM				
Lara, Ralph	Requested by Oscar Menchaca for Rm. 109d Men's Faculty Restroom in Main Building-WORK ORDER # 28442 HAS NOT BEEN COMPLETED. Lock cylinder has being missing for several months. Students are getting in and ditching, needs to be replaced as soon as possible.								
Velia Alarcon									
29469	North Building				11/27/2007		218		\$0.00
Medium	Work In Progress				11/27/2007 4:04:53 PM				
Lara, Ralph	Requested by Velia for Rm. 217 Men's Faculty Restroom in North Building-Teacher and custodian keys do not open door, something is wrong with cylinder.								
Velia Alarcon									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
29797					12/4/2007		211		\$0.00
Medium	Work In Progress			12/4/2007 11:06:02 AM					
Lara, Ralph	Requested by Ms. I. Ramos for Panter Paw/Concession Stand-Check or replace locks, door knob not closing properly.								
<u>Velia Alarcon</u>									
29798					12/4/2007		211		\$0.00
Medium	Work In Progress			12/4/2007 11:08:16 AM					
Castillo, Carlos	Requested by Ms. I. Ramos Panther Paw/Concession Stand-Need additional outlets with more power added in Concession Stand.								
<u>Velia Alarcon</u>									
29871		Athletic Field			12/6/2007		209		\$0.00
Medium	Work In Progress			12/6/2007 1:57:16 PM					
Castillo, Carlos	please relocate electrical breaker panel box from back of boys home dug out to the north wall.								
<u>Michael Munoz</u>									
29939					12/10/2007		205		\$0.00
Medium	Work In Progress			12/10/2007 11:29:34					
Lara, Ralph	Requested by Mr. Belle Rm. 315 Academic Building-Lock on file cabinet needs to be replaced.								
<u>Velia Alarcon</u>									
29980					12/11/2007		204		\$0.00
Medium	Work In Progress			12/11/2007 9:26:32 AM					
Ambriz, Jose	Computer Lab - Leaking water.								
<u>Fernando Moncayo</u>									
30141					12/17/2007		198		\$0.00
Medium	Work In Progress			12/17/2007 2:04:04 PM					
Appelzoller, Fred	Requested by Mrs. B-Holzhausen Rm. 226 North Building-Replace sink with deep tub lab sink and drying board.								
<u>Velia Alarcon</u>									
30142					12/17/2007		198		\$0.00
Medium	Work In Progress			12/17/2007 2:05:58 PM					
Moncayo, Fernando	Requested by Mrs. B-Holzhausen Rm. 226 North Building-Repair or replace broken floor tiles.								
<u>Velia Alarcon</u>									
30143					12/17/2007		198		\$0.00
Medium	Work In Progress			12/17/2007 2:09:49 PM					
Ontiveros, Guadalupe	Requested by Mr. A. Lopez for Varsity Softball Field-Sprinkler installed on varsity in-field/wet down dirt.								
<u>Velia Alarcon</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
30145					12/17/2007		198		\$0.00
Medium	Work In Progress				12/17/2007 2:13:33 PM				
Ontiveros, Guadalupe	Requested by Mr. A. Lopez for JV Softball Field-Dug out shade for JV field.		1/8 - Route to Lupe asp Mike						
<u>Velia Alarcon</u>									
30151	North Building	Office			12/17/2007		198		\$0.00
Medium	Work In Progress				12/17/2007 3:16:51 PM				
Lara, Ralph	THE DOOR LOCKSET AT THE N-BLDG OFFICE IS NOT LACKING W/KEY								
<u>Mario Apodaca</u>									
30493		Athletic Field			1/10/2008		174		\$0.00
Medium	Work In Progress				1/10/2008 3:07:55 PM				
Ontiveros, Guadalupe	Need Storage by home dug -out to be build of cinder block.As per Coach Yanes.								
<u>Guadalupe Ontiveros</u>									
30629					1/15/2008		169		\$0.00
Medium	Work In Progress				1/15/2008 10:06:31 AM				
Lara, Ralph	Requested by Commander Snarr Rm. 203 North Building-Room door is broken at hinges and swings open freely.								
<u>Velia Alarcon</u>									
30631		Stairway			1/15/2008		169		\$0.00
Medium	Work In Progress				1/15/2008 10:10:33 AM				
Ontiveros, Guadalupe	Requested by Julio Alcantar (SO1) for Softball Field-West fence by softball fields need repair for safety reasons.		1/16/08 - asp Mike route to Lupe						
<u>Velia Alarcon</u>									
30690	Agricultural				1/16/2008		168		\$0.00
Medium	Work In Progress				1/16/2008 2:47:00 PM				
Castillo, Carlos	THE GREENHOUSE BREAKER BOX NEED TOBE SERVICE								
<u>Mario Apodaca</u>									
30752					1/17/2008		167		\$0.00
Medium	Work In Progress				1/17/2008 2:49:53 PM				
Lara, Ralph	Requested by Velia-Two HJ11 keys are needed for, one for floating teacher and one for key box (room 660).								
<u>Velia Alarcon</u>									
30753					1/17/2008		167		\$0.00
Medium	Work In Progress				1/17/2008 2:53:59 PM				
Lara, Ralph	Requested by Velia-Three F3 keys are needed, one for Security Officer and two for key box.								
<u>Velia Alarcon</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
30755					1/17/2008		167		\$0.00
Medium	Work In Progress			1/17/2008 3:10:41 PM					
Lara, Ralph	Requested by Velia-Two 1HE25 keys are needed, one for I.A. an one for key box (room 200).								
Velia Alarcon									
30756					1/17/2008		167		\$0.00
Medium	Work In Progress			1/17/2008 3:12:10 PM					
Lara, Ralph	Requested by Velia-Five L Wrenches are needed for classrooms with panic bars.								
Velia Alarcon									
30792	North Building	Classroom			1/18/2008		166		\$0.00
Medium	Work In Progress			1/18/2008 1:05:29 PM					
Lara, Ralph	NEED TO REPLALE A DOOR AT ROOM 202 AT THE N-BLDG								
Mario Apodaca									
30793	North Building	Classroom			1/18/2008		166		\$0.00
Medium	Work In Progress			1/18/2008 1:07:28 PM					
Lara, Ralph	NEED TO REPLACE A DOOR AT ROOM 203 AT THE N-BLDG								
Mario Apodaca									
30795	Old English Bldg	Gym			1/18/2008		166		\$0.00
Medium	Work In Progress			1/18/2008 1:14:35 PM					
Castillo, Carlos	THE GIRLS GYM THE LAMPS NEED TOBE SERVICE BULBS NEED CHANGE-OUT								
Mario Apodaca									
30796	Computer	Computer Lab			1/18/2008		166		\$0.00
Medium	Work In Progress			1/18/2008 1:15:53 PM					
Castillo, Carlos	OUTSIDE LAMPS NEED TOBE SERVICE								
Mario Apodaca									
30929	Main Building	Restroom (Boys)			1/24/2008		160		\$0.00
Medium	Work In Progress			1/24/2008 3:04:11 PM					
Lara, Ralph	MENS RESTROOM AT THE MAIN BLDG NEED TOBE REKEY TO (H-E RO D) KEY								
Mario Apodaca									
30998	Cafeteria (1998)	Cafeteria			1/28/2008		156		\$0.00
Medium	Work In Progress			1/28/2008 3:46:49 PM					
Lara, Ralph	Requested by Marie for entrance to West Conference room in the Cafeteria-Her HE1 key does not open the door. She needs to access her Cum Files located in the West Conference storage room. Please repair as soon as possible.								
Velia Alarcon									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
31035		Dressing Room			1/29/2008		155		\$0.00
Medium	Work In Progress			1/29/2008 3:18:16 PM					
Lara, Ralph	Wrestling room (507) - Key cylinder spins but does not engage lock								
<u>Albert Vallejo</u>									
31036	North Building	Restroom (Boys)			1/29/2008		155		\$0.00
Medium	Work In Progress			1/29/2008 3:20:45 PM					
Lara, Ralph	North building (217) - Key will not unlock door (it IS the proper key)								
<u>Albert Vallejo</u>									
31174	Cafeteria (1998)	Cafeteria			2/1/2008		152		\$0.00
Medium	Work In Progress			2/1/2008 3:03:38 PM					
Moncayo, Fernando	NEED NEW BULBS SOCKET FOR THE COOLER AT THE SERVING LINE								
<u>Mario Apodaca</u>									
31319					2/5/2008		148		\$0.00
Medium	Work In Progress			2/5/2008 3:19:20 PM					
Lara, Ralph	Requested by Coach R. Yanez for Baseball Field-Extra keys to storage shed lock made for Assistant Coaches or format shed lock and office key to be the same for both. Shed lock key # CG2 (3 extra) Office key # HE43.								
<u>Velia Alarcon</u>									
31322	Library	Library			2/5/2008		148		\$0.00
Medium	Work In Progress			2/5/2008 3:23:48 PM					
Lara, Ralph	Requested by Mr. Grubaugh Rm. 275 Library-The front door to the Library is becoming very hard to open. It sticks even when it's unlocked.								
<u>Velia Alarcon</u>									
31340					2/5/2008		148		\$0.00
Medium	Work In Progress			2/5/2008 4:27:04 PM					
Lara, Ralph	Requested by Mr. Belle Rm. 315 Academic Building-WORK ORDER #29939 HAS NOT BEEN COMPLETED -Lock on file cabinet needs to be replaced. It is totally broken and it pulls out of the socket.								
<u>Velia Alarcon</u>									
31357					2/6/2008		147		\$0.00
Medium	Work In Progress			2/6/2008 10:32:04 AM					
Lara, Ralph	Requested by Mr. Belle Rm. 200 North Building-The lock on the classroom door needs to be fixed, keys do not lock the door.								
<u>Velia Alarcon</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
31358	North Building				2/6/2008		147		\$0.00
Medium	Work In Progress			2/6/2008 10:34:51 AM					
Lara, Ralph	Requested by Velia for Rm. 217 Men's Faculty Restroom in North Building-WORK ORDER #29469 HAS NOT BEEN COMPLETED-Teacher and custodian keys do not open door, something is wrong with cylinder.								
<u>Velia Alarcon</u>									
31360	Boys Gym				2/6/2008		147		\$0.00
Medium	Work In Progress			2/6/2008 10:39:21 AM					
Lara, Ralph	Requested by Mr. Mora Rm. 403 Boys Gym-Athletic training room door broke again, request a door that latches.								
<u>Velia Alarcon</u>									
31386	Grounds Shop	Athletic Field			2/7/2008		146		\$0.00
Medium	Work In Progress			2/7/2008 7:38:00 AM					
Castillo, Carlos	As per Raul Sanchez:disconnect irrigation pump to be pulled out by Anthony P ump. Will need to return and reconnect.								
<u>Carlos Castillo</u>									
31470	North Building	Classroom			2/11/2008		142		\$0.00
Medium	Work In Progress	221		2/11/2008 3:07:48 PM					
Lara, Ralph	The teachers key will not work on her classroom door.								
<u>Albert Vallejo</u>									
31471					2/11/2008		142		\$0.00
Medium	Work In Progress			2/11/2008 3:10:59 PM					
Ronquillo, Ruben	I am missing Eighteen (18) ABC Fire extinguishers								
<u>Albert Vallejo</u>									
31631					2/15/2008		138		\$0.00
Medium	Work In Progress			2/15/2008 1:50:31 PM					
Ronquillo, Ruben	Need to install a rack on Albert Vallejo truck.								
<u>Albert Vallejo</u>									
31833					2/25/2008		128		\$0.00
Medium	Work In Progress			2/25/2008 2:58:02 PM					
Lara, Ralph	Requested by Ms. Hamilton Rm. 562 Ag. Shop-Classroom door is sticking and can not be opened with key.								
<u>Velia Alarcon</u>									
31837					2/25/2008		128		\$0.00
Medium	Work In Progress			2/25/2008 3:05:19 PM					
Lara, Ralph	Requested by Velia for key box-Two M114 keys are needed (key to restrooms in Varsity Gym)								
<u>Velia Alarcon</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
31840	Auto Shop				2/25/2008		128		\$0.00
Medium	Work In Progress				2/25/2008 3:12:05 PM				
Castillo, Carlos	Requested by Mr. Carrasco Rm. 580 A Auto Shop-Need 10 rough service gowah bulbs.								
<u>Velia Alarcon</u>									
31844	Cafeteria (1998)	Cafeteria			2/25/2008		128		\$0.00
Medium	Work In Progress				2/25/2008 3:30:51 PM				
Ontiveros, Guadalupe	NEED TO DO A GENERAL CLEANING-UP OUTSIDE THE CAFE BLDG FOR THE BOARD METING ON THE 2-28-08								
<u>Mario Apodaca</u>									
31849	North Building	Classroom			2/25/2008		128		\$0.00
Medium	Work In Progress				2/25/2008 3:40:08 PM				
Castillo, Carlos	NEED NEW OUTLET FOR THE TOW NEW COMMERCIAL MICROWAVE AT THE N-BLDG TO ROOM 233 FOR NEXT SCHOOL YEAR								
<u>Mario Apodaca</u>									
31933					2/27/2008		126		\$0.00
Medium	Work In Progress				2/27/2008 11:35:58 AM				
Munoz, Joe	NEED TO CLEAN UP AREA (TRASH, OLD ENTRANCE MAT,CANS) WEST SIDE WALK BY GIRLS GYM NEXT TO BOILER ROOM AND ALSO LIFT STATION AREA BY BUS TURN AROUND NEXT TO ACADEMIC BUILDING.								
<u>Michael Munoz</u>									
31934					2/27/2008		126		\$0.00
Medium	Work In Progress				2/27/2008 11:46:45 AM				
Vallejo, Albert	NEED TO REPAIR SOFFITT ??? (OVERHANG) BY MAIN BUILDING ON SOUTH SIDE OF BLDG.								
<u>Michael Munoz</u>									
31941	Grounds Shop				2/27/2008		126		\$0.00
Medium	Work In Progress				2/27/2008 3:09:18 PM				
Castillo, Carlos	As per Coach Lopez, They want an electrical outlet installed at the field to accomodate a pitching machine.								
<u>Albert Vallejo</u>									
31944	Academic Bldg	Hallway/Corridor			2/27/2008		126		\$0.00
Medium	Work In Progress				2/27/2008 3:17:31 PM				
Castillo, Carlos	Only about 20% of the emergency lights in the hallways are functioning.								
<u>Albert Vallejo</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
32218					3/3/2008		121		\$0.00
High	Work In Progress			3/3/2008 2:40:40 PM					
Lara, Ralph	Requested by Mr. Grubaugh for Library-The emergency exit by the boy's bathroom has a broken lock. It needs to be chained nightly for security purposes. Please fix as soon as possible.								
Velia Alarcon									
32220					3/3/2008		121		\$0.00
Medium	Work In Progress			3/3/2008 2:46:43 PM					
Castillo, Carlos	the outside lights of the annex,weight room,boys need to be service								
Mario Apodaca									
32222					3/3/2008		121		\$0.00
Medium	Work In Progress			3/3/2008 2:58:22 PM					
Villalobos, David	Requested by Mr. Grubaugh for Boy's Restroom in Library-There is a urinal in the boy's restroom that has not worked in some time. The water in it is stagnant and foul smelling.								
Velia Alarcon									
32227		Athletic Field			3/3/2008		121		\$0.00
Medium	Work In Progress			3/3/2008 3:10:22 PM					
Castillo, Carlos	Requested by Coach A. Lopez for J.V. Softball-J.V.- electrical box behind baskstop for pitching machine.								
Velia Alarcon									
32289	Grounds Shop				3/5/2008		119		\$0.00
Medium	Work In Progress			3/5/2008 8:12:31 AM					
Castillo, Carlos	Needs outlets installed outside Grounds Shop.								
Guadalupe Ontiveros									
32338					3/6/2008		118		\$0.00
Medium	Work In Progress			3/6/2008 9:19:28 AM					
Castillo, Carlos	Please check switch at irrigation well.								
Guadalupe Ontiveros									
32481	Concession	Auditorium			3/11/2008		113		\$0.00
Medium	Work In Progress			3/11/2008 3:30:38 PM					
Castillo, Carlos	NEED #2 NEW OUTLET FOR THE NEW COMMERCIAL MICROWAVE OVENS AT THE OLD ENG CONCESSION STAND								
Mario Apodaca									
32697		Gym			3/25/2008		99		\$0.00
Medium	Work In Progress			3/25/2008 1:42:41 PM					
Ontiveros, Guadalupe	Need to landscape Area and install irrigation system. area to incould plants & trees.								
Guadalupe Ontiveros									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
32826	Boys Gym	Dressing Room			3/28/2008		96		\$0.00
Medium	Work In Progress				3/28/2008 3:29:00 PM				
Ronquillo, Ruben need two 16" x 48" x 1/4" wired glass. Albert Vallejo									
32848	Old English Bldg				3/31/2008		93		\$0.00
Medium	Work In Progress				3/31/2008 2:31:12 PM				
Villalobos, Margret Need to check all A/C with Tracer Summit. Jose Ambriz									
32851	Academic Bldg	Classroom			3/31/2008		93		\$0.00
Medium	Work In Progress				3/31/2008 3:13:27 PM				
Castillo, Carlos NEED NEW OUTLES FOR THE COMPUTERI AT ROOM 306 Mario Apodaca									
32940					4/3/2008		90		\$0.00
Medium	Work In Progress				4/3/2008 11:40:07 AM				
Ronquillo, Ruben Requeted by Coach Hite for J.V. Locker Room-Fix broken benches, new legs are needed. Safety hazard. Velia Alarcon									
33026					4/6/2008	4/14/2008	87		\$0.00
Medium	Work In Progress				4/6/2008 12:18:11 AM				
Apodaca, Mario Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details. Margret Villalobos									
33088					4/6/2008	4/14/2008	87		\$0.00
Medium	Work In Progress				4/6/2008 12:18:31 AM				
Apodaca, Mario Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details. Margret Villalobos									
33137					4/7/2008		86		\$0.00
Medium	Work In Progress				4/7/2008 12:34:30 PM				
Lara, Ralph Requested by Mr. Chambers Assistant Principal for Joe Munoz Head Custodian-Two Grand Masters with digits 6 & 7 for the entire school at G.H.S. Mr. Chambers had requested these keys over two years ago. These keys will be assigned to Mr. Chamber and Joe Munoz for those days that we might have emergencies on our campus. Velia Alarcon									
33187	Academic Bldg	Classroom			4/8/2008		85		\$0.00
Medium	Work In Progress				4/8/2008 11:44:00 AM				
Castillo, Carlos Requested by Mr. S. Hernandez Rm. 306 Academic Building (Journalism/Yearbook Classroom)-Need the data and electric outlets re-done. We are currently running computer (19) on 4 outlets. Re-wire classroom-- --4-5 columns in the back would be great. Velia Alarcon									

7/2/2008 10:38:02 AM

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
33398	Main Building	Classroom			4/14/2008		79		\$0.00
Medium	Work In Progress			4/14/2008 3:20:17 PM					
Ronquillo, Ruben	BROKEN WONDOW AT ROOM 126 (30X18) MAIN BLDG								
Mario Apodaca									
33627					4/22/2008		71		\$0.00
Medium	Work In Progress			4/22/2008 11:56:40 AM					
Vallejo, Albert	Requested by Coach Hite for Field House (Boy's Gym-Football Locker Rooms)-Paint all lockers in football dressing room areas (maroon).								
Velia Alarcon									
33629	Academic Bldg	Classroom			4/22/2008		71		\$0.00
Medium	Work In Progress			4/22/2008 1:25:34 PM					
Apodaca, Mario	Requested by Ms. Foote Rm. 332 Academic Building- One of the panels covering a ceiling light is falling off (1/2 way). I'm afraid it will fall completely off and hit a student. I need someone to come and push it up and in place.								
Velia Alarcon									
33630	Varsity Gym	Classroom			4/22/2008		71		\$0.00
Medium	Work In Progress			4/22/2008 1:27:58 PM					
Castillo, Carlos	Requested by Ms. Howard Rm. 245 Over Varsity Gym- Outlet on wall keeps tripping.								
Velia Alarcon									
33632	North Building	Classroom			4/22/2008		71		\$0.00
Medium	Work In Progress			4/22/2008 1:35:03 PM					
Lara, Ralph	Requested by Ms. Anderson Rm. 233 North Building- Door knob to classroom is loose.								
Velia Alarcon									
33633					4/22/2008		71		\$0.00
Medium	Work In Progress			4/22/2008 1:38:24 PM					
Lara, Ralph	Requested by Mr. Villa Rm. 510 Annex Building (Band Room)-Double door on south side-door prop mount came off from the top-inside of the door.								
Velia Alarcon									
33634	Cafeteria (1998)				4/22/2008		71		\$0.00
Medium	Work In Progress			4/22/2008 1:43:23 PM					
Castillo, Carlos	NEED TOW NEW LAMP FIXTURES FOR THE CAFE BLDG CUSTODIAN ROOMS (277V)								
Mario Apodaca									
33635	Football Stadium	Athletic Field			4/22/2008		71		\$0.00
Medium	Work In Progress			4/22/2008 1:51:17 PM					
Lara, Ralph	NEED A NEW DOOR SET FOR THE TRACK ROOM AT BY THE BLEACHERS								
Mario Apodaca									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
33817	Academic Bldg	Classroom			4/29/2008		64		\$0.00
Medium	Work In Progress			4/29/2008 2:05:46 PM					
Vallejo, Albert	Requested by Mr. Cordova Rm. 331 Academic Building- The wall on the back of the stage needs to be finished color being black. The light reflects off the white wall and makes teaching lighting to students impossible.								
Velia Alarcon									
33820					4/29/2008		64		\$0.00
Medium	Work In Progress			4/29/2008 2:55:45 PM					
Ontiveros, Guadalupe	Requested by Coach Hite for Varsity Game Field-Field has grubworms, spray insecticide to kill them.								
Velia Alarcon									
33822					4/29/2008		64		\$0.00
Medium	Work In Progress			4/29/2008 3:08:28 PM					
Apodaca, Mario	4-28-08				4/28 - 4				
1-ASSIST CARLOS C. ON FIXING OUTSIDE LAMPS									
1-WORK ON E/COOLER UNIT AT ROOM 569 WATER PUMP									
1-TURN-ON AND OFF THE E/COOLER UNIT TO THE OLD ENG BLDG									
4-CUT WOOD TO FIX TABLES W/O 301410									
1-IN PUT TO SCHOOL DUDE									
Mario Apodaca									
33911	North Building	Classroom			5/1/2008		62		\$0.00
Medium	Work In Progress	228		5/1/2008 3:15:21 PM					
Lara, Ralph	Mr. Palmers key broke off inside the cabinet lock (same as 15 other cabinets) I have the pieces of the key that needs to be made.								
Albert Vallejo									
34011					5/4/2008	5/12/2008	59		\$0.00
Medium	Work In Progress			5/4/2008 12:19:10 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
34084					5/6/2008		57		\$0.00
High	Work In Progress	Wastewater		5/6/2008 10:08:38 AM					
Sanchez, Raul	BDP-GHS-0002 - Broken line to Back Flow Preventor needs to be fixed, in order to test (asp PM 24385) 4/9/08								
Margret Villalobos									
34088	Agricultural				5/6/2008		57		\$0.00
Medium	Work In Progress			5/6/2008 11:58:49 AM					
Ronquillo, Ruben	NEED TO ORDER SUPPLY TOO FIX THE GREENHOUSE .								
Mario Apodaca									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
34107	Academic Bldg	Classroom			5/6/2008		57		\$0.00
Medium	Work In Progress	344			5/6/2008 3:38:09 PM				
Lara, Ralph	The lever in Room #344 is broken and in need of replacement								
<u>Albert Vallejo</u>									
34144	Varsity Gym				5/8/2008		55		\$0.00
Medium	Work In Progress				5/8/2008 1:55:50 PM				
Lara, Ralph	the key cylinder at locker room 238 not working w/the key								
<u>Mario Apodaca</u>									
34146	North Building	Classroom			5/8/2008		55		\$0.00
Medium	Work In Progress				5/8/2008 2:16:27 PM				
Moncayo, Fernando	the food deli cart cooler unit at room 233 is not working good								
<u>Mario Apodaca</u>									
34315					5/14/2008		49		\$0.00
Medium	Work In Progress				5/14/2008 2:07:40 PM				
Vallejo, Albert	Requested by Ms. Miller Rm. 344 Academic Building-Room number (and in Braille) fell, please put back up.								
<u>Velia Alarcon</u>									
34316					5/14/2008		49		\$0.00
Medium	Work In Progress				5/14/2008 2:52:41 PM				
Lara, Ralph	Requested by Velia-Three HK3 keys are needed. One was broken and I need two to keep in the key box.								
<u>Velia Alarcon</u>									
34356	Old English Bldg				5/15/2008		48		\$0.00
Medium	Work In Progress				5/15/2008 2:57:45 PM				
Ambriz, Jose	The evaporative cooler on the northwest side of the Old English Building needs to be replaced.								
<u>Albert Vallejo</u>									
34436	North Building	Classroom			5/20/2008		43		\$0.00
Medium	Work In Progress				5/20/2008 9:10:25 AM				
Vallejo, Albert	Requested by Ms. Pena for rooms 208 and 209 North Building-Paint classrooms, including kitchen cabinets. New paint is very needed.								
<u>Velia Alarcon</u>									
34437	Business	Classroom			5/20/2008		43		\$0.00
Medium	Work In Progress				5/20/2008 9:18:58 AM				
Castillo, Carlos	Requested by Ms. Munoz Rm. 610 Business Building-Electric outlets for sewing machines need to be repaired. Each table has three outlets, one under each sewing machine and one under table.								
<u>Velia Alarcon</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
34485					5/21/2008		42		\$0.00
Medium	Work In Progress			5/21/2008 12:08:51 PM					
Lara, Ralph	Requested by Coach Hite for Football Field House (Boy's Gym)-We are having a tough time keeping doors locked after hours. All doors need to be re-keyed going into the Football areas. See Coach Hite for type of key (if he wants it off master or not) and key number. Please complete as soon as possible.								
<u>Velia Alarcon</u>									
34543	Main Building	Hallway/Corridor			5/22/2008		41		\$0.00
Medium	Work In Progress			5/22/2008 3:20:11 PM					
Lara, Ralph	There is a foriegn object inserted into both entry doors making it impossible to lock or unlock either door.								
<u>Albert Vallejo</u>									
34557	Academic Bldg	Classroom			5/23/2008		40		\$0.00
Medium	Work In Progress			5/23/2008 8:32:46 AM					
Apodaca, Mario	Requested by Mrs. Gage Rm. 330 Academic Building- Paint classroom walls.								
<u>Velia Alarcon</u>									
34794					6/1/2008	6/9/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:21:58 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
34929	Cafeteria (1998)				6/3/2008		29		\$0.00
Medium	Work In Progress			6/3/2008 4:41:07 PM					
Moncayo, Fernando	Lamps need servicing in kitchen near dishwasher								
<u>Albert Vallejo</u>									
35011					6/9/2008		23		\$0.00
Medium	Work In Progress			6/9/2008 8:22:31 AM					
Appelzoller, Fred	Requested by Ms. Anderson Rm. 233 North Building Panther Hut-Washing machine leaking water still replace facet handle on back sink handle is in my desk drawer, right side top.								
<u>Velia Alarcon</u>									
35155					6/15/2008		17		\$0.00
Medium	Work In Progress			6/15/2008 12:18:04 AM					
Ontiveros, Guadalupe	Monthly - Gadsden HS Soil Sampling - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
35181		Parking Lot			6/16/2008		16		\$0.00
Medium	Work In Progress				6/16/2008 2:45:04 PM				
Castillo, Carlos	Requested by Velia for Faculty Parking Lot and Bus Turn Around-Replace the first two light bulbs that are very dim and almost burned out. Also, replace all the light bulbs on the bus turn around, they all have different light watts. It is very dark in the evening. If possible install light posts on the west side of the bus turn around. This will help when parents drive in throught the bus turn around to pick up students in the late evening.								
Velia Alarcon									
35250	Boys Gym	Restroom (Boys)			6/18/2008		14		\$0.00
Medium	Work In Progress				6/18/2008 3:59:43 PM				
Villalobos, David	NEED TO SERVICE THE SHOWER AT THE BOYS GYM FOOTBALL SIDE								
Mario Apodaca									
35417	Cafeteria (1998)	Cafeteria			6/26/2008		6		\$0.00
Medium	Work In Progress				6/26/2008 12:56:47 PM				
Ambriz, Jose	need a new water cooler at the cafe bldg								
Mario Apodaca									
Count: 167 Work Orders			Avg. Age of WO's	193		Total for Gadsden HS	0		\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden MS

28830	Cafeteria				11/2/2007		243		\$0.00
Medium	Work In Progress				11/2/2007 1:20:40 PM				
Ronquillo, Ruben	NEED A DOOR COVER FOR FIRE EXTINGUISHER ASP PM 27589.								
Sebastian Diaz									
24394					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David	Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24395					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:53 AM				
Villalobos, David	Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24956					7/20/2007		348		\$0.00
Medium	Work In Progress				7/20/2007 9:53:03 AM				
Acosta, Juan	NEED TO RELOCATE ATHLETICS TO OLD PURCHASING PORTABLE, PURCHASING (ALLL EXCETP CONFERENCETABLE) TO GM NURSHING AND GM NURSING TO ATHLETICS. CONTACT PERSONS WOULD BE MR. LOWENBERG & DR GARCIA								
Alfredo Holguin									
25755	Main Building	Hallway/Corridor			8/13/2007		324		\$0.00
Medium	Work In Progress	A.B WING			8/13/2007 8:23:16 AM				
Diaz, Sebastian	MAROON TILE IN HALLWAY WALLS ARE BROKEN OFF IN THE A.B WING AND CAFEARIA		Route to BM asp Mike- 8/13						
Juan Acosta									
26297					8/27/2007		310		\$0.00
Medium	Work In Progress				8/27/2007 1:23:52 PM				
Sotelo, Enrique	please provide power to sebastians morgan bldg. THXS								
Michael Munoz									
26752	Cafeteria				9/6/2007		300		\$0.00
Medium	Work In Progress				9/6/2007 2:03:39 PM				
Diaz, Sebastian	Replace the original tile on the walls by serving doors of cafeteria. (Asp Mike route to Sebastian 123086-Act)-mkv								
Michael Munoz									
26830	C-Wing	Portables			9/10/2007		296		\$0.00
Medium	Work In Progress	Athletic Office			9/10/2007 8:37:49 AM				
Lozoya, Manny	Repair cash boc barrel for key has broken and needs to be replaced.								
Terry Alvarado									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
26981					9/13/2007		293		\$0.00
Medium	Work In Progress				9/13/2007 7:48:15 AM				
Lozoya, Manny		9/13/07							
Sebastian Diaz		Need to fix all main entrance doors thank you							
27253		Gym			9/20/2007		286		\$0.00
High	Work In Progress	Gym/Lockerroom			9/20/2007 4:00:58 PM				
Diaz, Sebastian		Benches need to be replaced in boys lockerroom.							
Maricruz Carrasco									
27385		Office			9/24/2007		282		\$0.00
Medium	Work In Progress	Front Office			9/24/2007 9:48:29 PM				
Lozoya, Manny		Keys needed: (4) V8 for Gym (Outside doors) (1) A3 for Custodial Storage Room							
Maricruz Carrasco									
29876					12/6/2007		209		\$0.00
Medium	Work In Progress				12/6/2007 3:06:03 PM				
Appelzoller, Fred		2nd Request 4/8/08				4/8 - Need to replace a/s/a/p 2nd Request			
Sebastian Diaz		In room 140 need to relpace water fauset sink thank you.							
29927	Gym	Gym			12/8/2007		207		\$0.00
Medium	Work In Progress	Storage area			12/8/2007 11:56:48 AM				
Lozoya, Manny		Doors and hindges need to be replace and installed in the storage are located in the gym.							
Veronica Quinonez									
29945					12/10/2007		205		\$0.00
Medium	Work In Progress				12/10/2007 1:14:49 PM				
Lara, Ralph		12/10/07							
Sebastian Diaz		Need to fix door knob in couchers storage in the gym thank you							
30391					1/8/2008		176		\$0.00
Medium	Work In Progress				1/8/2008 12:03:19 PM				
Lozoya, Manny		1/8/08							
Sebastian Diaz		Need glass window in class door's three doors thank you							
30415	Gym	Dressing Room			1/9/2008		175		\$0.00
Medium	Work In Progress	Gym/Official's			1/9/2008 8:56:40 AM				
Lozoya, Manny		Replace cylinder in Official's dressing room. Hard to open.							
Maricruz Carrasco									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
30682		Office			1/16/2008		168		\$0.00
Medium	Work In Progress	Awing/SRO Office		1/16/2008 10:58:43 AM					
Lozoya, Manny		Need 3 keys to SRO Office- F3 as soon as possible. Thank you!							
<u>Maricruz Carrasco</u>									
30734					1/17/2008		167		\$0.00
Medium	Work In Progress			1/17/2008 10:58:02 AM					
Lozoya, Manny		1/17/08 Need fix main entrance doors not closeing rights thank you							
<u>Sebastian Diaz</u>									
30741					1/17/2008		167		\$0.00
Medium	Work In Progress	All GMS Lockers		1/17/2008 11:51:19 AM					
Lozoya, Manny		All lockers should have a screw on door so that students don't hide anything in there. To avoid students access to lockers.							
<u>Maricruz Carrasco</u>									
30817		Office			1/18/2008		166		\$0.00
Medium	Work In Progress	399/100/Secretar		1/18/2008 5:25:38 PM					
Lozoya, Manny		Glass doors needed for room 399, 100-Chacon's Lounge, Secretary's office, and SRO Office as soon as possible.							
<u>Maricruz Carrasco</u>									
31361	C-Wing	Classroom			2/6/2008		147		\$0.00
Medium	Work In Progress	Cwing/C-204/Ms.		2/6/2008 10:46:20 AM					
Lozoya, Manny		Door does not lock. Tried to fix once but still does not lock.							
<u>Maricruz Carrasco</u>									
31385	Main Building	Cafeteria			2/7/2008		146		\$0.00
Medium	Work In Progress			2/7/2008 4:41:34 AM					
Diaz, Sebastian		CAFETERIA ENTRANCE DOORS FLOOR TILES NEED REPLACING							
<u>Juan Acosta</u>									
31653	C-Wing				2/19/2008		0		\$0.00
Medium	Work In Progress	C-Wing		2/19/2008 9:26:22 AM		2/19/2008			
Sotelo, Enrique		Need to replace 2 emerg. lights and 1 exit sign asp PM 31207, 31212							
<u>Sebastian Diaz</u>									
31829					2/25/2008		128		\$0.00
Medium	Work In Progress			2/25/2008 12:16:19 PM					
Ontiveros, Guadalupe		Need to fix irrigation waters pipes in front main office thank you							
<u>Sebastian Diaz</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
32254		Office			3/4/2008		120		\$0.00
Medium	Work In Progress	GMS Front Office			3/4/2008 1:15:32 PM				
Lozoya, Manny		Cabinet needs lock, same as others in front office.							
Maricruz Carrasco									
32320	Band Room	Parking Lot			3/6/2008		118		\$0.00
Medium	Work In Progress				3/6/2008 5:30:58 AM				
Ontiveros, Guadalupe		IN FRONT OF CAFETERIA AND BAND ROOM SIDEWALKS THERE ARE SINK HOLES							
Juan Acosta									
32364					3/6/2008		0		\$0.00
Low	Work In Progress				3/6/2008 3:37:03 PM	3/6/2008			
Lozoya, Manny		Need to meet w/Mike Hogan w/Gencon at 1:00pm on 3-07-08 to make him keys where needed.							
Michael Munoz									
32500					3/12/2008		112		\$0.00
Medium	Work In Progress	All Automatic			3/11/2008 11:08:33 PM				
Lozoya, Manny		Need to make doors automatic for a student that needs easy access from Portable 501 to Awing to classrooms inside. All doors that are automatic need to be connected at all times for student to use.							
Maricruz Carrasco									
32502		Office			3/12/2008		112		\$0.00
Medium	Work In Progress	Awing/134/A.			3/11/2008 11:18:57 PM				
Lozoya, Manny		Please install locks on Mr. Salas' black filing cabinet and tan storage cabinet as well.							
Maricruz Carrasco									
32513	Main Building	Library			3/12/2008		112		\$0.00
Medium	Work In Progress				3/12/2008 11:06:39 AM				
Briones, Enrique		WE NEED TO HAVE OLD EQUIPMENT THAT IS IN THE LIBRARY PICKED UP FOR DISCARD. THE LIBRARIAN ALREADY HAS THE PAPERWORK WITH TAG AND SERIAL NUMBERS.							
Phillip Medina									
32763	C-Wing	Classroom			3/27/2008		97		\$0.00
Medium	Work In Progress	Cwing/204			3/26/2008 11:36:05 PM				
Lozoya, Manny		Need new door knob. It does not lock. Maintenance already tried to fix once.							
Maricruz Carrasco									
33309					4/10/2008		83		\$0.00
Medium	Work In Progress				4/10/2008 3:36:14 PM				
Lozoya, Manny		4/10/08 Need new locks for extinguisher boxes in AB wing thank you							
Sebastian Diaz									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
33460	Vocational	Classroom			4/17/2008		76		\$0.00
Medium	Work In Progress	Vocational/301			4/17/2008 9:53:49 AM				
Lozoya, Manny	Door lock will not close or sometimes opening is very hard. Door knob lock needs changing out or replaced "V" key.								
<u>Maricruz Carrasco</u>									
33618		Athletic Field			4/22/2008		71		\$0.00
High	Work In Progress				4/22/2008 7:46:45 AM				
Appelzoller, Fred	1st valve to backflow in fenced tank area is broken. need to replace ASAP. fields are not getting watered.thxs								
<u>Michael Munoz</u>									
33658	Cafeteria				4/23/2008		70		\$0.00
Medium	Work In Progress				4/23/2008 8:24:29 AM				
Miranda, Danny	as per our conversation, please fur-out ducting to cafeteria kitchen.thxs								
<u>Michael Munoz</u>									
34186	Cafeteria	Cafeteria			5/9/2008		54		\$0.00
Medium	Work In Progress				5/9/2008 9:11:20 AM				
Moncayo, Fernando	CONDENCER AT GMS WALK-IN REFRIG. NEEDS TO BE REPLACE.								
TERRY PORTILLO SNP MGR 882-2824									
<u>Jacqueline Aguilar</u>									
34322	Main Building				5/14/2008		49		\$0.00
Medium	Work In Progress	B-Wing			5/14/2008 3:35:30 PM				
Lozoya, Manny	Need fix main entrance door in B-Wing asap thank you								
<u>Sebastian Diaz</u>									
34414	Main Building				5/19/2008		44		\$0.00
Medium	Work In Progress	B-Wing			5/19/2008 10:42:09 AM				
Sotelo, Enrique	Rm 137 (Old Teachers Lounge)- Remove light next to comm. box.								
34738					5/30/2008		33		\$0.00
Medium	Work In Progress				5/30/2008 3:11:40 PM				
Acosta, Juan	JUAN ACOSTA TO MOVE FURNITURE FOR ABATEMENT AT GMS					ARTHUR CONTRERAS, HC @ CH WILL BE ASSISTING WITH THIS W.O. THRU MONTH OF JUNE AS PER CHUY			
<u>Jimmy Carbajal</u>									
34751		Classroom			5/30/2008		33		\$0.00
Medium	Work In Progress	GMS Campus			5/30/2008 4:52:35 PM				
Acosta, Juan	Moving of furniture, equipment and boxes of instructional supplies and materials to different locations in order to assist the construction team at Gadsden Middle School. This will apply until construction is complete at GMS. Thank you.								
<u>Maricruz Carrasco</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
34821					6/1/2008	6/17/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:07 AM					
Villalobos, Margret		Yearly - Gadsden MS June Chiller Insp. - Refer to PM schedule details.							
Margret Villalobos									
35003					6/6/2008		26		\$0.00
Medium	Work In Progress			6/6/2008 9:01:47 AM					
Garcia, Jose		need to repair or replace stuck 2 inch solenoid valve, also run irrigation to west side of football field and ppd park.							
Michael Munoz									
35015		Classroom			6/9/2008		23		\$0.00
Medium	Work In Progress	GMS/Front Office		6/9/2008 9:29:20 AM					
Lozoya, Manny		Report from Connie Avalos, GMS Clerk on Lost keys for 2007-2008 school year: Key WA4-Lost by Zulema De La Rosa, Room 110 Lost keys worth \$21.50. Thank you.							
Maricruz Carrasco									
35016		Classroom			6/9/2008		23		\$0.00
Medium	Work In Progress	GMS/Front Office		6/9/2008 10:58:22 AM					
Lozoya, Manny		Report from Connie Avalos, GMS Clerk on Lost keys for 2007-2008 school year: Key WA44-Lost by Ron Galla, Room 169 Lost keys worth \$21.50. Thank you.							
Maricruz Carrasco									
35017		Classroom			6/9/2008		23		\$0.00
Medium	Work In Progress	GMS/Front Office		6/9/2008 10:58:55 AM					
Lozoya, Manny		Report from Connie Avalos, GMS Clerk on Lost keys for 2007-2008 school year: Key WA108-Lost by Susana Gomez, Room 399 Lost keys worth \$21.50. Thank you.							
Maricruz Carrasco									
35019	Vocational	Classroom			6/9/2008		23		\$0.00
Medium	Work In Progress	Vocational		6/9/2008 11:08:45 AM					
Acosta, Juan		The floor needs a very good mopping with very hot water and/or painted.							
Maricruz Carrasco									
35022	Vocational	Classroom			6/9/2008		23		\$0.00
Medium	Work In Progress	Vocational/Room		6/9/2008 11:25:52 AM					
Diaz, Sebastian		<ol style="list-style-type: none"> 1. Drawers-80% of them off track or tracks destroyed (Can't slide in and out like they should; they tilt.) 2. Cabinets-Hinges broken on two doors; hinges loose on many. Top and bottom. 3. 1st station-wood pulled out right under sink (after school program)-probably thought it was a drawer and pulled on it. 							
Maricruz Carrasco									

7/2/2008 10:38:02 AM

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden MS

35024	Main Building	Office			6/9/2008		23		\$0.00
Medium	Work In Progress			6/9/2008 12:26:24 PM					
Estrada, Jesus		Repair snags on carpet, office and inner rooms							
Maricruz Carrasco									
35025	Band Room	Classroom			6/9/2008		23		\$0.00
Medium	Work In Progress			6/9/2008 12:27:12 PM					
Diaz, Sebastian		Finish instrument bins, Paint.							
Maricruz Carrasco									
35026	Band Room				6/9/2008		23		\$0.00
Medium	Work In Progress			6/9/2008 12:28:08 PM					
Lozoya, Manny		Repair North entrance inner door							
Maricruz Carrasco									
35027	Band Room				6/9/2008		23		\$0.00
Medium	Work In Progress			6/9/2008 12:28:56 PM					
Diaz, Sebastian		Replace door safety plates.							
Maricruz Carrasco									
35028	Band Room	Classroom			6/9/2008		23		\$0.00
Medium	Work In Progress			6/9/2008 12:29:37 PM					
Diaz, Sebastian		Repair holes in 101 and 106 the walls and Paint							
Maricruz Carrasco									
35029	Vocational	Classroom			6/9/2008		23		\$0.00
Medium	Work In Progress	Vocational/Room		6/9/2008 12:43:11 PM					
Villalobos, David		Station next to washer and dryer-leaky pipes (there are two buckets under right now)				Asp Mike route to David 6/18/08			
Maricruz Carrasco									
35031	Vocational	Classroom			6/9/2008		23		\$0.00
Medium	Work In Progress	Vocational/Room		6/9/2008 12:56:46 PM					
Diaz, Sebastian		<ol style="list-style-type: none"> 1. Table tops of several tables are loose. (Big slate science tables) 2. Latches on wooden cabinets need replacing. 3. Screens on windows need to be returned. 4. Window blinds need replacing. 5. Door glass cracked. 							
Maricruz Carrasco									
35032		Classroom			6/9/2008		23		\$0.00
Medium	Work In Progress	Bwing/Room		6/9/2008 12:58:04 PM					
Diaz, Sebastian		Room needs to be painted.							
Maricruz Carrasco									
35128					6/12/2008		20		\$0.00
Medium	Work In Progress	Mobile Home		6/12/2008 11:16:26 AM					
Jacquez, Ricardo		Please have one of the district plumbers replace the outside water filter at the mobile home.							
Yolie Jacquez									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden MS

35169					6/16/2008		16		\$0.00
Medium	Work In Progress			6/16/2008 8:51:59 AM					
Jacquez, Ricardo	Backflow Prevention Device next to storage tank - The device has a small leak. Repair as per NMED site inspection ASAP and submit completed work order to this office								
Alfredo Holguin									
35170					6/16/2008		16		\$0.00
Medium	Work In Progress			6/16/2008 9:04:59 AM					
Jacquez, Ricardo	Backflow Prevention Device (leaking) near Storage Device - Install concrete pad								
Alfredo Holguin									
35178	Cafeteria				6/16/2008		16	1	\$25.00
Medium	Work In Progress			6/16/2008 1:58:16 PM					
Diaz, Sebastian	A/C units not working, see Rosa.								
Juan Acosta									
35244	Main Building				6/18/2008		14		\$0.00
High	Work In Progress			6/18/2008 11:05:40 AM					
Lozoya, Manny	We need the following rooms re-keyed to off master. Rooms 117, 159, 203, 305 all computers are stored in these rooms. Give the key to Head Custodian Juan Acosta.								
Jesus Estrada									
35259	C-Wing				6/18/2008		14		\$0.00
Medium	Work In Progress			6/18/2008 4:54:23 PM					
Lozoya, Manny	I need a new lock put into the storage room C-212 in C-wing at GMS.								
35263	C-Wing	Classroom			6/19/2008		13		\$0.00
High	Work In Progress	Cwing/204/Sephr		6/19/2008 11:34:26 AM					
Lara, Ralph	Need new door knob. It does not lock. Need lock to be secure. 2nd request. 1st request on 3/27/08, Work order#32763. Thank you.								
Maricruz Carrasco									
35328					6/24/2008		8		\$0.00
Medium	Work In Progress	LINE LOCATE		6/24/2008 9:30:43 AM					
Sotelo, Enrique	NEED TO LINE LOCATE/MARK UTILITIES BETWEEN GYM AND THE MAIN BLDG TOMORROW FOR LYNCO ELECTRIC.								
Michael Munoz									
35428	Vocational				6/26/2008		6		\$0.00
Medium	Work In Progress			6/26/2008 4:01:53 PM					
Sotelo, Enrique	please connect electrical to kiln.Thaxs								
	Mr.Escarsicagas class								
Michael Munoz									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden MS

35429	Vocational				6/26/2008		6		\$0.00
Medium	Work In Progress				6/26/2008 4:03:55 PM				
Solis, Lorenzo	please connect vent to kiln. mr. escarsigas class. fyi purge motor is mounted on bottom. holes need to be drilled.thnks								

Michael Munoz

35430	Vocational				6/26/2008		6		\$0.00
Medium	Work In Progress				6/26/2008 4:06:31 PM				
Munoz, Michael	Need to secure kiln w/ fence and gate. Mr. Escarcigas class ,need 2 ft on sides and 3in front of kiln gate needs to swing out.								

Michael Munoz

35459					6/30/2008		2		\$0.00
High	Work In Progress	LINE LOCATE			6/30/2008 12:07:54 PM				
Appelzoller, Fred	Need a line location for gas, water, sewer and electrical from manhole outside of SNP office all the way out to GMS gym. The contact person for CSC is Daryl Stailey (mobile 505 621-6227) CSC will start to dig on Monday July 7th.								

Jesus Estrada

35460					6/30/2008		2		\$0.00
High	Work In Progress	LINE LOCATE			6/30/2008 12:14:47 PM				
Appelzoller, Fred	Need to locate all sprinkler lines so they can be dug up. This is in front of C,D and Cafe wings. The contact person is Scott Berry with Gencon (mobile 575 202-8028)								

Jesus Estrada

35461					6/30/2008		2		\$0.00
High	Work In Progress	LINE LOCATE			6/30/2008 1:25:48 PM				
Sotelo, Enrique	Need to locate all sprinkler lines so they can be dug up. This is in front of C,D and Cafe wings. The contact person is Scott Berry with Gencon (mobile 575 202-8028)								

Jesus Estrada

35462					6/30/2008		2		\$0.00
High	Work In Progress	LINE LOCATE			6/30/2008 1:28:37 PM				
Sotelo, Enrique	Need a line location for gas, water, sewer and electrical from manhole outside of SNP office all the way out to GMS gym. The contact person for CSC is Daryl Stailey (mobile 505 621-6227) CSC will start to dig on Monday July 7th.								

Jesus Estrada

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Gadsden MS							
35474					6/30/2008		2		\$0.00
Medium	Work In Progress				6/30/2008 3:57:40 PM				
Carbajal, Jimmy	WET & DRY MACHINE NOT WORKING AS PER MARIO. PLEASE PICK UP AND REPAIR								
Jesus Estrada									
35475					6/30/2008		2		\$0.00
Medium	Work In Progress				6/30/2008 3:58:22 PM				
Carbajal, Jimmy	ANOTHER (TOTAL OF 2) WET & DRY MACHINE NOT WORKING AS PER MARIO. PLEASE PICK UP AND REPAIR								
Jesus Estrada									
Count: 72 Work Orders	Avg. Age of WO's		100	Total for Gadsden MS				1	\$25.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
25129					7/26/2007		342		\$0.00
Medium	Work In Progress			7/26/2007 3:49:29 PM					
Lara, Ralph	7/26/07 Manny can you change door lock for classroom 210 (child safety). Thank you.								
Salvador Gonzalez									
25635					8/8/2007		0	0	\$25.00
Medium	Work In Progress			8/8/2007 3:47:37 PM	8/8/2007				
Gonzalez, Salvador	8/8/07 .5 Check school. - 1.0 Replace rubber seal for cafeteria door (\$10.00). - 2.5 Edging with weed eater. 1.5 Clipping. - 2.0 Paint in bathroom room 210 (15.00). - .5 Paper work.		8/8 - 8 Material -25.00						
Salvador Gonzalez									
26704					9/5/2007		301		\$0.00
Medium	Work In Progress			9/5/2007 3:26:36 PM					
Lara, Ralph	9/5/07 Door knob in classroom is not opening, something inside the cilinder is wrong.								
Salvador Gonzalez									
27864					10/4/2007		272		\$0.00
Medium	Work In Progress			10/4/2007 8:57:15 AM					
Villalobos, David	Need Electrician and Plumber to La Union for locates or can it be scheduled for today or tomorrow?								
Cora Ramirez									
27889					10/5/2007		271		\$0.00
Medium	Work In Progress			10/5/2007 8:00:33 AM					
Villalobos, David	10/5/07 David can you check comode in annex building is not flushing righth.								
Salvador Gonzalez									
30980		Parking Lot			1/28/2008		156		\$0.00
Medium	Work In Progress			1/28/2008 2:21:51 PM					
Ontiveros, Guadalupe	Relocate Marquee to area on right hand side of parent entrance where light pole small chinese elm is located. Power for lighting not requiered		2/4/08 - Asp Mike route to Lupe.						
Richard Chavez									
33619					4/22/2008		71		\$0.00
Medium	Work In Progress			4/22/2008 7:56:18 AM					
Castillo, Carlos	4-22-08 Can you help replacing burned out outdoor lighth bulbs in parking lot. Thanks.								
Salvador Gonzalez									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
33903	Main Building	Classroom			5/1/2008		62		\$0.00
Medium	Work In Progress			5/1/2008 10:55:51 AM					
Estrada, Jesus	The carpet in rooms 104 and 106 needs to be replaced with tile.								
<u>Jesus Estrada</u>									
33904	Main Building	Classroom			5/1/2008		62		\$0.00
Medium	Work In Progress			5/1/2008 11:09:51 AM					
Estrada, Jesus	We need half of the carpet removed in room 210(kitchen area East) and tiled.								
<u>Jesus Estrada</u>									
34803					6/1/2008	6/9/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:01 AM					
Gonzalez, Salvador	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
34953					6/4/2008		28		\$0.00
Medium	Work In Progress			6/4/2008 3:09:31 PM					
Lara, Ralph	6-4-08 Metal courtain in office is not working can you check it please.								
<u>Salvador Gonzalez</u>									
35001					6/5/2008		27		\$0.00
Medium	Work In Progress			6/5/2008 4:49:05 PM					
Castillo, Carlos	6-5-08 move electrical wire from back to front of cubicle in front office, (install a new circuit).								
<u>Salvador Gonzalez</u>									
35007					6/6/2008		26		\$0.00
Medium	Work In Progress			6/6/2008 4:48:18 PM					
Munoz, Michael	2water leaks where repaired on entrance driveway on the west side off main bldg. need to repair damaged asphalt.								
<u>Michael Munoz</u>									
Count: 13 Work Orders		Avg. Age of WO's 127			Total for La Union ES			0	\$25.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
26188					8/23/2007		314		\$0.00
Medium	Work In Progress			8/23/2007 11:27:05 AM					
Ontiveros, Guadalupe	LANDSCAPE/PLANT GRASS AND INSTALL A SPRINKLER SYSTEM BETWEEN WINGS.								
Alfredo Holguin									
27964					10/8/2007		178		\$0.00
Medium	Work In Progress			10/8/2007 1:16:59 PM		4/3/2008			
Sanchez, Raul	We need the filters changed for the domestic water.								
Rudy Arreola									
28459					10/24/2007		252		\$0.00
Medium	Work In Progress			10/24/2007 8:40:57 AM					
Lozoya, Manny	The door is hard to open have to push to lock and unlock and the key is hard to turn already tried some silicone spray but its still hard. Mens RR across mr Ramirez RM.								
Rudy Arreola									
29787					12/4/2007		211		\$0.00
Medium	Work In Progress			12/4/2007 10:29:53 AM					
Ronquillo, Ruben	We need a total of 17 blinds replaced through out the school Mr.Ronquillo allready has a sample of the blind.								
Rudy Arreola									
29788					12/4/2007		211		\$0.00
Medium	Work In Progress			12/4/2007 10:30:33 AM					
Lozoya, Manny	RM 106 Door handle is broken.								
Rudy Arreola									
29789					12/4/2007		211		\$0.00
Medium	Work In Progress			12/4/2007 10:31:11 AM					
Lozoya, Manny	Rm 204 Door is hard to close is hitting the frame of the door.								
Rudy Arreola									
31935					2/27/2008		126		\$0.00
Medium	Work In Progress			2/27/2008 1:43:57 PM					
Ontiveros, Joe	We need a water line installed to tap in for irrigation line on the southside of campus.								
Rudy Arreola									
32298					3/5/2008		119		\$0.00
High	Work In Progress			3/5/2008 10:03:28 AM					
Ontiveros, Guadalupe	start on new landscaping project for pto.								
Joe Munoz									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
32464					3/11/2008		113		\$0.00
Medium	Work In Progress			3/11/2008 8:29:28 AM					
Ontiveros, Joe	We have a water hose spicket that is stripped and leaking water on the southside of kitchen wall. needs to be replaced.								
Rudy Arreola									
33048					4/6/2008	4/27/2008	-10		\$0.00
Medium	Work In Progress			4/6/2008 12:18:18 AM		3/27/2008			
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
33775					4/28/2008		65		\$0.00
Medium	Work In Progress			4/28/2008 2:29:48 PM					
Holguin, Alfredo	Pour new sidewalks for ADA access to new shade strutures and playground equipment								
Alfredo Holguin									
34091		Parking Lot			5/6/2008		57		\$0.00
Safety	Work In Progress			5/6/2008 1:58:44 PM					
Holguin, Alfredo	Provide ADA access (sidewalks) to new playground equipment and metal canopies.								
Alfredo Holguin									
34199					5/9/2008		54		\$0.00
Medium	Work In Progress			5/9/2008 12:14:09 PM					
Lozoya, Manny	Manny, west side door hinge is broken, needs rewelding.								
Grace Alvarado									
34307					5/14/2008		49		\$0.00
Medium	Work In Progress			5/14/2008 9:20:54 AM					
Ontiveros, Guadalupe	AS PER ALFREDO H. DELIVER SAND TO NEW PLAYGROUND EQUIPMENT AREA.								
Alfredo Holguin									
34565					5/23/2008		40		\$0.00
Medium	Work In Progress			5/23/2008 1:43:23 PM					
Ambriz, Jose	Joe, needing new air system placed in PE room								
Grace Alvarado									
34765					6/1/2008	6/7/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:21:49 AM					
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
35361					6/25/2008		7		\$0.00
Medium	Work In Progress			6/25/2008 7:44:59 AM					
Arreola, Rudy	Need to paint marquee to match BLUE.								
Rudy Arreola									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Loma Linda ES							
35362					6/25/2008		7		\$0.00
Medium	Work In Progress				6/25/2008 7:46:05 AM				
Arreola, Rudy		Need to paint 1st grade wing.							
Rudy Arreola									
Count: 18 Work Orders		Avg. Age of WO's	113	Total for Loma Linda ES				0	\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
26748					9/6/2007		300		\$0.00
Medium	Work In Progress			9/6/2007 12:07:58 PM					
Lozoya, Manny		manny need new lock for filing cabinet,missing key.							
Romauldo Apodaca									
26940		Portables			9/12/2007		294		\$0.00
Medium	Work In Progress	room 601		9/12/2007 1:45:43 PM					
Lozoya, Manny		Change lock on closet in Portable room 601.							
Priscilla Martinez									
27986					10/9/2007		267		\$0.00
Medium	Work In Progress			10/9/2007 7:50:27 AM					
Ramirez, Joe		NEEDS TO REPLACED 10 TILES ON ROOM #111 THANK YOU LUIS							
Luis Saucedo									
27987					10/9/2007		267		\$0.00
Medium	Work In Progress			10/9/2007 7:52:37 AM					
Ramirez, Joe		ON PORTABLE #229 GIRLS RESTROOMS NEEDS TO REPLACED 9 TILES THANK YOU LUIS							
Luis Saucedo									
28019					10/10/2007		266		\$0.00
Medium	Work In Progress			10/10/2007 10:35:17					
Lozoya, Manny		Need three doors in the barracks to be replace, they are in very bad shape.							
Joe Ramirez									
28065					10/11/2007		265		\$0.00
Medium	Work In Progress			10/11/2007 2:16:24 PM					
Ramirez, Joe		NEED TO REPLEACE (10) TILES ON ROOM #110 THANK YOU LUIS, ANY QUESTIONS ASK LUIS.							
Luis Saucedo									
29133					11/13/2007		232		\$0.00
Medium	Work In Progress			11/13/2007 6:44:17 AM					
Lozoya, Manny		need to make a key for file cabinet please ask luis.							
		thank you. luis							
Luis Saucedo									
29340		Parking Lot			11/19/2007		226		\$0.00
Medium	Work In Progress	gate key		11/19/2007 2:16:04 PM					
Lozoya, Manny		Texas Migrant Council needs a gate key for the north entrance. Will Mr. Munoz or Mr. Holguin please approve this request, and direct me as to how the keys should be handed over. The director for the Texas Migrant Council is Olivia Hinojosa.							
Priscilla Martinez									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
29683					12/2/2007	12/3/2007	213		\$0.00
Medium	Work In Progress			12/2/2007 12:30:20 AM					
Ramirez, Joe	Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
29684					12/2/2007	12/3/2007	213		\$0.00
Medium	Work In Progress			12/2/2007 12:30:20 AM					
Ramirez, Joe	Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
29697					12/2/2007	12/3/2007	213		\$0.00
Medium	Work In Progress			12/2/2007 12:30:25 AM					
Ramirez, Joe	Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
29719					12/2/2007	12/3/2007	213		\$0.00
Medium	Work In Progress			12/2/2007 12:30:34 AM					
Ramirez, Joe	Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
30574					1/14/2008		170		\$0.00
Medium	Work In Progress			1/14/2008 6:39:55 AM					
Lozoya, Manny	the teacher staff bathroom in the 2nd grade wing door lock is not working. thank you luis								
<u>Luis Saucedo</u>									
30575					1/14/2008		170		\$0.00
Medium	Work In Progress			1/14/2008 6:46:08 AM					
Lozoya, Manny	need to make a key for file cabinet for room 204 sedillo class room thank you. luis								
<u>Luis Saucedo</u>									
30576					1/14/2008		170		\$0.00
Medium	Work In Progress			1/14/2008 7:40:44 AM					
Lozoya, Manny	need to replaced latched on girls & boys restrooms on north side of blg.thank you luis								
<u>Luis Saucedo</u>									
30679	Main Building	Office			1/16/2008		168		\$0.00
Medium	Work In Progress	front office		1/16/2008 10:19:41 AM					
Lozoya, Manny	Will you please make a door plaque for our new AP.								
		Jacob Montano Assistant Principal							
<u>Priscilla Martinez</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
31213					2/3/2008	2/11/2008	150		\$0.00
Medium	Work In Progress			2/3/2008 12:30:42 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
31223					2/3/2008	2/11/2008	150		\$0.00
Medium	Work In Progress			2/3/2008 12:30:46 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
31249					2/3/2008	2/9/2008	150		\$0.00
Medium	Work In Progress			2/3/2008 12:30:55 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
31260					2/4/2008		149		\$0.00
Medium	Work In Progress			2/4/2008 7:05:29 AM					
Ramirez, Joe	on south hallway under water fountain needs 10 tiles thank you luis								
<u>Luis Saucedo</u>									
31303					2/5/2008		148		\$0.00
Medium	Work In Progress			2/5/2008 9:54:13 AM					
Lozoya, Manny	needs to fix door lock inside of cafeteria by laundry room please thank you luis								
<u>Luis Saucedo</u>									
31341					2/6/2008		147		\$0.00
Medium	Work In Progress			2/6/2008 7:22:50 AM					
Ramirez, Joe	wall on north & SOUTH BOYS & girls restrooms entrance needs to be painted								
<u>Luis Saucedo</u>									
31496					2/12/2008		141		\$0.00
Medium	Work In Progress			2/12/2008 8:44:43 AM					
Ramirez, Joe	Rooms 111,110,113 tiles need to be replaced they are the old 6x6 or 8x8 they keep coming off and i believe they are asbestos type.								
<u>Joe Ramirez</u>									
31596					2/14/2008		139		\$0.00
Medium	Work In Progress			2/14/2008 12:02:20 PM					
Ontiveros, Guadalupe	I need some assistance with the sprinkler system timer and stations.								
<u>Joe Ramirez</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
32074					3/2/2008	3/8/2008	122		\$0.00
Medium	Work In Progress			3/2/2008 12:32:51 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
32106					3/2/2008	3/10/2008	122		\$0.00
Medium	Work In Progress			3/2/2008 12:33:05 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
32116					3/2/2008	3/10/2008	122		\$0.00
Medium	Work In Progress			3/2/2008 12:33:09 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
32150					3/2/2008		122		\$0.00
Medium	Work In Progress			3/2/2008 12:33:22 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual EVS - Refer to PM schedule details.								
Margret Villalobos									
32152					3/2/2008		122		\$0.00
Medium	Work In Progress			3/2/2008 12:33:23 AM					
Ramirez, Joe	Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.								
Margret Villalobos									
32155					3/2/2008		122		\$0.00
Medium	Work In Progress			3/2/2008 12:33:24 AM					
Ramirez, Joe	Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
Margret Villalobos									
32156					3/2/2008		122		\$0.00
Medium	Work In Progress			3/2/2008 12:33:25 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual MCD - Refer to PM schedule details.								
Margret Villalobos									
32157					3/2/2008		122		\$0.00
Medium	Work In Progress			3/2/2008 12:33:25 AM					
Ramirez, Joe	Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
32158					3/2/2008		122		\$0.00
Medium	Work In Progress			3/2/2008 12:33:26 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual UCD - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
32159					3/2/2008		122		\$0.00
Medium	Work In Progress			3/2/2008 12:33:26 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual UCS2 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
32160					3/2/2008		122		\$0.00
Medium	Work In Progress			3/2/2008 12:33:26 AM					
Ramirez, Joe	Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
32504	Main Building	Classroom			3/12/2008		112		\$0.00
Medium	Work In Progress	room 605		3/12/2008 9:00:13 AM					
Ramirez, Joe	this room has been cleared of old equipment, and we would like for it to be restored so that we may create a classroom environment for testing, our campus needs an area for bi-lingual testing and this is the only room available								
<u>Priscilla Martinez</u>									
32970					4/4/2008		89		\$0.00
Medium	Work In Progress			4/4/2008 9:48:39 AM					
Ontiveros, Guadalupe	need all grass areas fertilized								
<u>Joe Ramirez</u>									
33013					4/6/2008	4/12/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:06 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
33031					4/6/2008	4/14/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:12 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
33092					4/6/2008	4/14/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:33 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
33102					4/6/2008	4/14/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:36 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
33431					4/15/2008		78		\$0.00
Medium	Work In Progress			4/15/2008 2:43:47 PM					
Ontiveros, Joe	needs to replaced a hose bid is located on (b wing) out side of the blg. thank you.luis								
Luis Saucedo									
33983					5/4/2008	5/10/2008	59		\$0.00
Medium	Work In Progress			5/4/2008 12:19:00 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
34015					5/4/2008	5/12/2008	59		\$0.00
Medium	Work In Progress			5/4/2008 12:19:11 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
34025					5/4/2008	5/12/2008	59		\$0.00
Medium	Work In Progress			5/4/2008 12:19:15 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
34181					5/9/2008		54		\$0.00
Medium	Work In Progress			5/9/2008 8:09:28 AM					
Estrada, Jesus	The newly installed carpet in rm. 111 is coming apart at the seams.				5/8/08 - AS PER CHUY, CARPET WILL BE RE-DONE. 5/9- AS PER MICHAEL, IT WILL BE TAKEN CARE OF AFTER SCHOOL IS OUT. INSTALLERS DID NOT TAKE PRECAUTIONS AND IF HE WAS AWARE OF PROBLEM RIGHT AWAY, HE COULD HAVE REPAIRED. CARPET WAS GLUED - FLOOR CONTAINS ASBESTOS , WHICH HE USE PADDING UNDER CARPET. WILL CONTACT CHUY				
Joe Ramirez									
34766					6/1/2008	6/7/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:21:49 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
34798					6/1/2008	6/9/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:00 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
34808					6/1/2008	6/9/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:03 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
34834					6/1/2008		31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:15 AM					
Ramirez, Joe	Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
34836					6/1/2008		31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:15 AM					
Ramirez, Joe	Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
34837					6/1/2008		31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:16 AM					
Ramirez, Joe	Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
34838					6/1/2008		31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:16 AM					
Ramirez, Joe	Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35097					6/11/2008		21		\$0.00
Medium	Work In Progress			6/11/2008 9:11:59 AM					
Ronquillo, Ruben	need broken window replaced rm. 605.								
<u>Joe Ramirez</u>									
35295					6/20/2008		12		\$0.00
Medium	Work In Progress			6/20/2008 2:43:37 PM					
Ontiveros, Joe	please check all bathroom sinks for proper operation and that sensors are functioning.thxs								
<u>Michael Munoz</u>									
35296					6/20/2008		12		\$0.00
Medium	Work In Progress			6/20/2008 2:45:03 PM					
Ramirez, Joe	grass is looking nicer, need to cut grass and weed eat in coved areas.thxs								
<u>Michael Munoz</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Mesquite ES								
35298					6/20/2008		12		\$0.00	
Medium	Work In Progress			6/20/2008 2:53:57 PM						
Ramirez, Joe	front campus, trees need to be trimmed, and area including parking lot need to be weed eated.thxs									
Michael Munoz										
35299					6/20/2008		12		\$0.00	
Medium	Work In Progress			6/20/2008 2:55:46 PM						
Ramirez, Joe	starting from the front entrance, doors and jams need to be painted thru-out the site. thxs									
Michael Munoz										
35300					6/20/2008		12		\$0.00	
Medium	Work In Progress			6/20/2008 2:59:20 PM						
Ramirez, Joe	staring from the front , cove base needs to be changed thru out campus where needed.thxs									
Michael Munoz										
35403					6/26/2008		6		\$0.00	
Medium	Work In Progress			6/26/2008 8:59:33 AM						
Ramirez, Joe	CLEAN FENCE LINE ALONG THE CANAL AND AROUND PINE TREES.									
Michael Munoz										
35404					6/26/2008		6		\$0.00	
Medium	Work In Progress			6/26/2008 9:06:32 AM						
Ramirez, Joe	THIS IS ON MAINT.PLAN. GRASS NEEDS TO BE REMOVED ALONG BORDERS AND PLAYGROUND AREA.									
Michael Munoz										
35405					6/26/2008		6		\$0.00	
Medium	Work In Progress			6/26/2008 9:07:37 AM						
Ramirez, Joe	CLEAN BEHIND AND AROUND MORGAN BUILDINGS AND BACK PARKING LOT.									
Michael Munoz										
35406					6/26/2008		6		\$0.00	
Medium	Work In Progress			6/26/2008 9:08:15 AM						
Ramirez, Joe	REMOVE OLD A/C ON MORGAN AND COVER OPENING.									
Michael Munoz										
35411					6/26/2008		6		\$0.00	
Medium	Work In Progress			6/26/2008 10:30:46 AM						
Villalobos, Margret	Need price quote to spray for flies outside of bldg.		Faxed to PC 6/26							
Michael Munoz										
Count: 64 Work Orders	Avg. Age of WO's 115		Total for Mesquite ES				0	\$0.00		

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
33124					4/7/2008		86		\$0.00
Medium	Work In Progress			4/7/2008 9:30:32 AM					
Ontiveros, Joe	requesting special tool for diaphragm nut removal(flush valve)to prevent damage to fixtures .asap								
Danny Vega									
33706					4/24/2008		69		\$0.00
Medium	Work In Progress			4/24/2008 8:48:11 AM					
Orozco, Danny	have one ice maker that needs to be transported-by foods dept asap-								
Danny Vega									
33709					4/24/2008		69		\$0.00
Medium	Work In Progress			4/24/2008 8:57:16 AM					
Sotelo, Enrique	rm100 has one 4ft lamp only-this is used for testing-need additional lighting.								
Danny Vega									
33766					4/28/2008		65		\$0.00
Medium	Work In Progress			4/28/2008 11:00:20 AM					
Boyd, David	bad sewer oder in bldg over weekends-spoke to lenny hernandez with county.need to install ckeck valve on our end of line.had same problem at vado(is this warranty wk) this smell stays in bldg most of the day.								
Danny Vega									
34044					5/5/2008		58		\$0.00
Medium	Work In Progress	Basketball Courts		5/5/2008 10:07:03 AM					
Vega, Danny	Need #'s painted for students accountability and organization. (see attachment)								
Victor Prieto									
34138					5/8/2008		55		\$0.00
Medium	Work In Progress			5/8/2008 12:51:59 PM					
Gonzales, Angel	gas blower needs repair pullstringh recoil								
Javier Parra									
34300		Classroom			5/13/2008		50		\$0.00
Medium	Work In Progress	SPED Classroom		5/13/2008 4:18:52 PM					
Sotelo, Enrique	SPED Room - Please change type of light fixture (too bright) due to student's reaction to light.								
Selma Nevarez									
34516					5/22/2008		41		\$0.00
Medium	Work In Progress			5/22/2008 7:43:56 AM					
Sotelo, Enrique	We need an electrical outlet and cable port installed in our front office so that a VIZIO flat screen may be installed.								
Priscilla Martinez									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
34517					5/22/2008		41		\$0.00
Medium	Work In Progress			5/22/2008 7:45:26 AM					
Boyd, David	We also need to have someone check out a main doorway magnet unit that is falling off the wall and the magnet chain has extended too much.								
Priscilla Martinez									
34525		Library			5/22/2008		41		\$0.00
Medium	Work In Progress	room 200		5/22/2008 9:40:43 AM					
Sotelo, Enrique	cable drop in the library for the installation of the flat screen tv.		Please visit with Ms. Lucero(Librarian), for this request.						
Priscilla Martinez									
34768					6/1/2008	6/7/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:21:50 AM					
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
34801					6/1/2008	6/9/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:01 AM					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
34812					6/1/2008	6/9/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:04 AM					
Vega, Danny	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
34867		Classroom			6/2/2008		30		\$0.00
Medium	Work In Progress	room 106		6/2/2008 11:55:33 AM					
Estrada, Jesus	The door handle fell off both sides of door, please fix asap. Teacher will not be able to evacuate room through this outside door if an emergency arises. Our building mechanic is out today.								
Priscilla Martinez									
34987					6/5/2008		27		\$0.00
Medium	Work In Progress			6/5/2008 4:04:06 PM					
Boyd, David	FIRE PUMP KICKED ON DUE TO POWER FAILURE. NEED TO CHECK SYSTEM FOR PROPER OPERATION.								
Michael Munoz									
Count: 15 Work Orders		Avg. Age of WO's 48		Total for North Valley ES			0	\$0.00	

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
24401					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:54 AM					
Villalobos, David	Yearly - Northern Pre-K (LM) Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
26803					9/7/2007		299		\$0.00
Medium	Work In Progress			9/7/2007 3:00:03 PM					
Ontiveros, Guadalupe	Need to level area north of main bldg (Any ?'s call Alfredo)								
Alfredo Holguin									
28578	Main Building				10/26/2007		250		\$0.00
Medium	Work In Progress	Wilma Martinez		10/26/2007 10:14:50					
Lozoya, Manny	Need locks with keys installed onto 2 (two) cabinets that hold Migrant supplies. Please contact Wilma Martinez @ 575-649-4800.								
Lucy Meza									
29464					11/27/2007		218		\$0.00
Medium	Work In Progress			11/27/2007 3:54:41 PM					
Lozoya, Manny	Please have Manny reinstall the key cores in the new hardware sets at La Mesa. He removed the entire cores during const. and needs to be reinstalled. Thanks David								
David Boyd									
31747	Main Building	Office			2/21/2008		132		\$0.00
Medium	Work In Progress			2/21/2008 12:56:18 PM					
Vega, Danny	We have some furniture that needs to be assembled: 2 desks, 1 book shelf, 2 lateral files, and 2 hutches.								
Gilbert Trujillo									
31748	Main Building				2/21/2008		132		\$0.00
Medium	Work In Progress			2/21/2008 1:04:59 PM					
Vega, Danny	Trim hedges and spray for bees at entrance to school. (An adult with severe allergies to bees was stung by a bee on 2/20/08.)								
Gilbert Trujillo									
32256	Main Building	Athletic Field			3/4/2008		120		\$0.00
Medium	Work In Progress	Playground		3/4/2008 1:19:19 PM					
Ontiveros, Guadalupe	Refill two sand boxes.								
Concepcion Montalvo									
32603					3/14/2008		110		\$0.00
Medium	Work In Progress			3/14/2008 3:31:40 PM					
Vega, Danny	as per our conversation, need irrigation system installed behind main bldg. contact Rosie Reyes for details. trees to be planted by grounds.								
Michael Munoz									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
32606					3/14/2008		110		\$0.00
Medium	Work In Progress			3/14/2008 3:34:17 PM					
Ontiveros, Guadalupe	please install trees as needed behind main bldg.see Rosie reyes for locations and details. Also Danny Vega will be installing irrigation system. same location. get w/ him so that trees can be on system.								
Michael Munoz									
32843	Concession	Office			3/31/2008		93		\$0.00
Medium	Work In Progress			3/31/2008 12:46:57 PM					
Lozoya, Manny	unable to unlock 2 doors								
Gilbert Trujillo									
33580					4/21/2008		72		\$0.00
Medium	Work In Progress			4/21/2008 2:03:03 PM					
Vega, Danny	Need to get a/c's ready.								
Gilbert Trujillo									
34534					5/22/2008		41		\$0.00
Medium	Work In Progress	LM PRE-K-		5/22/2008 1:52:33 PM					
Ramirez, Joe	AS PER ANN S./ROSIE REYES-NEED TO HAVE A PLAY HOUSE ASSEMBLED AND SECURED TO THE GROUND OUTSIDE IN THE PLAYGROUND. (TALK W/ROSIE REYES BEFORE SECURING TO GROUND TO MAKE SURE WHERE IT'S GOING TO BE PLACED.)				6/26 - Asp Mike route to Joe				
Mary Garcia									
34763					6/1/2008	6/7/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:21:48 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
34793					6/1/2008	6/9/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:21:58 AM					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
34799					6/1/2008	6/9/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:00 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35331					6/24/2008		8		\$0.00
Medium	Work In Progress			6/24/2008 12:25:05 PM					
Sotelo, Enrique	need line indicater at la mesa pre-k north west of bldg.before spklr system								
Danny Vega									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Northern On-Track Pre-K (LM)							
35332					6/24/2008		8		\$0.00
Medium	Work In Progress				6/24/2008 12:26:55 PM				
Villalobos, David	need sewer line indicater at la mesa pre-k -before spklrs system								
Danny Vega									
Count: 17 Work Orders		Avg. Age of WO's	121		Total for Northern On-Track Pre-K (LM)		0		\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
32026	Maintenance				2/29/2008		124		\$0.00
Medium	Work In Progress				2/29/2008 8:40:43 AM				
Munoz, Michael	NEED 4' FENCE GATE EAST OF PPD PARK. WO FOR MIKE MUNOZ. THANK YOU!								
Ruben Ronquillo									
24409					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David	Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24410					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:55 AM				
Villalobos, David	Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24784					7/16/2007		352		\$0.00
Medium	Work In Progress				7/16/2007 8:03:38 AM				
Ronquillo, Ruben	FORKLIFT SHADE YELLOW CANVAS(MAINT.WHS-2, PUR.WHS-1, F.S. WHS.-1.								
Ruben Ronquillo									
27500	Motor Vehicle				9/27/2007		279		\$0.00
Medium	Work In Progress				9/27/2007 9:30:33 AM				
Gonzales, Angel	PLEASE CHECK WATER PUMP ENGINE, NOT STARTING. THANKS RUBEN								
Ruben Ronquillo									
27501	Motor Vehicle				9/27/2007		279		\$0.00
Medium	Work In Progress				9/27/2007 9:33:12 AM				
Gonzales, Angel	PLEASE CHECK YELLOW DOUBLE AIR TANK COMPRESSOR, IDLE IS NOT WORKING, IT WILL NOT IDLE DOWN WHEN TANKS ARE FULL. THANKS RUBEN								
Ruben Ronquillo									
27765					10/2/2007		274		\$0.00
Medium	Work In Progress				10/2/2007 3:03:33 PM				
Lara, Ralph	RELOCATE DOUBLE DOORS ON BARRACK #1.								
Ruben Ronquillo									
28418	Motor Vehicle				10/23/2007		253		\$0.00
Medium	Work In Progress				10/23/2007 2:10:41 PM				
Lozoya, Manny	Transp Office - Install a door stop.								
Norma Alvarado									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
30228	Maintenance	Custodial			12/19/2007		196		\$0.00
Medium	Work In Progress			12/19/2007 9:53:10 AM					
Gonzales, Angel	ANGEL THE BIG TRUCK #82 IS MAKING A LOT OF NOISE SAL WAS PULLED OVER BY THE POLICE AND WAS TOLD NOT TO USE IT UNTILL IT GETS FIXED.THANK YOU								
<u>Jimmy Carbajal</u>									
31380					2/6/2008		147		\$0.00
Medium	Work In Progress			2/6/2008 3:50:47 PM					
Ambriz, Jose	Need to recover the units pt from the GAC.								
<u>Guillermo Hernandez</u>									
31629					2/15/2008		138		\$0.00
Medium	Work In Progress			2/15/2008 1:10:46 PM					
Lozoya, Manny	ESA Construction needs the following Site Keys: CMS, CHE and LU (Need by the end of the day)								
<u>Peggy Jo Hernandez</u>									
31931	Maintenance				2/27/2008		126		\$0.00
Medium	Work In Progress	HVAC Shop		2/27/2008 10:42:18 AM					
Ontiveros, Joe	Former Hvac Shop restroom. please remove toilet, sand sink, but leave a drain and h2o suppy for the office for futhure sink install.please see me. thxs								
<u>Michael Munoz</u>									
32021					2/28/2008		125		\$0.00
Medium	Work In Progress			2/28/2008 4:20:32 PM					
Lozoya, Manny	I need the following plates: Yolanda Jacquez Michelle Tellez Mark Rios Rudy Castro Victoria T. Lopez								
	I would also like to get a couple of room number plaques made for the office doors: Office 1 Office 2								
<u>Vicky Lopez</u>									
32817	Purchasing				3/28/2008		96		\$0.00
Medium	Work In Progress			3/28/2008 11:18:06 AM					
Gonzales, Angel	The dilivery van needs the walls repaired priferable with some type of metal and also install new metal flooring. This needs to be accomplished as soon as possible.								
<u>Alfredo Holguin</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
32876	Purchasing				4/1/2008		92		\$0.00
Medium	Work In Progress				4/1/2008 1:17:58 PM				
Diaz, Sebastian	1.Cover the exposed insulation on the west wall above the garage door.								
	2.Seal the openings around the garage door								
	3.Seal the gaps along the west wall								
	4.Repair holes in northeast wall								
	5.Repair, replace, or adjust ceiling covering along the southwest wall so that the covering and insulation doesn't hang down from the ceiling.								
<u>Vicky Lopez</u>									
33224					4/9/2008		84		\$0.00
Medium	Work In Progress				4/9/2008 10:52:29 AM				
Miranda, Danny	NEED A SHELF PUT IN NEW WINDOW MARY'S OFFICE								
<u>Danny Miranda</u>									
33831	Maintenance				4/29/2008		64		\$0.00
Medium	Work In Progress				4/29/2008 4:07:14 PM				
Gonzales, Angel	#99 (Mike's Blazer) Fan is not working and there is water in the condensor.								
<u>Michael Munoz</u>									
34195	Motor Vehicle				5/9/2008		54		\$0.00
Medium	Work In Progress				5/9/2008 10:37:54 AM				
Gonzales, Angel	AS PER ALFREDO ORDER AND INSTALL A LOCKING GAS CAP FOR CHS BAND TRUCK.								
<u>Alfredo Holguin</u>									
34196	Maintenance				5/9/2008		54		\$0.00
Medium	Work In Progress				5/9/2008 10:55:18 AM				
Lozoya, Manny	Need to switch doors from old HVAC Shop (Double Doors w/Old Elec. Shop (Single Door). Any questions see Mike								
<u>Michael Munoz</u>									
34197	Maintenance				5/9/2008		54		\$0.00
Medium	Work In Progress				5/9/2008 10:57:38 AM				
Miranda, Danny	Need to extend old HVAC office (into new lounge).								
<u>Michael Munoz</u>									
34696					5/30/2008		33		\$0.00
Medium	Work In Progress				5/30/2008 12:20:05 AM				
Holguin, Alfredo	Yearly - PPD - Maintenance Plan - Refer to PM schedule details.								
Margret Villalobos									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
35202	Food Services				6/17/2008		15		\$0.00
Medium	Work In Progress			6/17/2008 8:46:12 AM					
Moncayo, Fernando		Freezer #3 is not working							
Johnny Lechuga									
35215		Restroom (Girls)			6/17/2008		15		\$0.00
Medium	Work In Progress			6/17/2008 1:30:57 PM					
Diaz, Sebastian		Sebastian! would you please check the sink in the girls restroom at the Custodial Warehouse the faucet is dripping. Thank you							
Guillermo Hernandez									
35242	Food Services	Cafeteria			6/18/2008		14		\$0.00
Medium	Work In Progress			6/18/2008 8:40:33 AM					
Moncayo, Fernando		SNP WAREHOUSE: FREEZERS #4 AND #5 MOTORS NEED TO BE REPLACED. GEORGE GOMEZ - SNP WHSE							
Jacqueline Aguilar									
35303					6/23/2008		9		\$0.00
Medium	Work In Progress			6/23/2008 6:56:00 AM					
Gonzales, Angel		Dump Truck - need to repair lights, need to install a pin hitch and need to repair air leak a/s/a/p.							
Guadalupe Ontiveros									
35304					6/23/2008		9		\$0.00
Medium	Work In Progress			6/23/2008 6:57:06 AM					
Gonzales, Angel		Gooseneck Trailer needs license plate and lights fixed.							
Guadalupe Ontiveros									
Count: 26 Work Orders		Avg. Age of WO's		139	Total for Physical Plant Complex			0	\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
26653					9/4/2007		302		\$0.00
Medium	Work In Progress			9/4/2007 10:32:36 AM					
Holguin, Alfredo	Provide services and materials for installation of new controller to control existing lighting.		Joe V. picked up PO on 9/4-mkv						
<u>Alfredo Holguin</u>									
28486		Cafeteria			10/24/2007		252		\$0.00
Medium	Work In Progress			10/24/2007 2:34:48 PM					
Moncayo, Fernando	Shelves need to be removed on next session (March, 2008) As per Environment Department - they inspected Riverside on 10/23/07 and their comments were that: Wood shelving in dry storage must be coated with paint or replaced - Repeat violation. Must be corrected within 60 days. Need to inform Maria Nevarez - Inspector, when corrected.								
Aida Salcedo, SNP Coordinator 882-6772 & Emilia Carrillo, SNP Manager 589-2550									
<u>Alma Terrell</u>									
28720					10/31/2007		245		\$0.00
Medium	Work In Progress			10/31/2007 9:23:23 AM					
Castillo, Carlos	AS PER OUR CONVERSATION, PLEASE PROVIDE A 120 OUTLET FOR THE ENVIRONMENT DEPT.								
<u>Michael Munoz</u>									
30226					12/19/2007		196		\$0.00
Medium	Work In Progress			12/19/2007 9:04:29 AM					
Lara, Ralph	MR MANNY LOZOYA SIR WE NEED TO REPLACE 3 THREE OUTSIDE LOCK FOR GATES ONE WAS BROKEN AND THE TWO OTHERS WERE STOLEN THEY ARE FOR OUT SIDE GATES THANK YOU SIR								
<u>Adan Duran</u>									
30851					1/22/2008		162		\$0.00
Medium	Work In Progress			1/22/2008 3:35:20 PM					
Ambriz, Jose	MR JOSE AMBRIZ SIR THE RELIEF VALVE ON THE BOILER ON NORTH WING IS STAYING OPEN NEED TO REPLACE WAS ABLE TO GET IT TO STOP FOR NOW THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
32611	New Wing 1/02	Classroom			3/14/2008		110		\$0.00
Medium	Work In Progress			3/14/2008 3:40:45 PM					
Villalobos, David	need to replace faucet								
<u>Carlos Hernandez</u>									
32707	New Wing 1/02	Hallway/Corridor			3/25/2008		99		\$0.00
Medium	Work In Progress			3/25/2008 3:26:50 PM					
Ronquillo, Ruben	Skylight was broken and sppd was notified made report case#sp2008000390 need to be replaced		6/24/08 - Asp Ruben will be repaired in July.						
<u>Carlos Hernandez</u>									
7/2/2008 10:38:03 AM									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
32713	New Wing 1/02	Classroom			3/25/2008		99		\$0.00
Medium	Work In Progress				3/25/2008 3:36:44 PM				
Villalobos, David	Need to replace faucet room 126								
Carlos Hernandez									
33263		Classroom			4/9/2008		0		\$0.00
Medium	Work In Progress				4/9/2008 3:31:09 PM	4/9/2008			
Castillo, Carlos	2 lights are out need ballest and 8 lights in hallway are out need light bulbs								
Carlos Hernandez									
34228					5/12/2008		51		\$0.00
Medium	Work In Progress				5/12/2008 10:03:52 AM				
Castillo, Carlos	Emergency Lights. - 1 light in kitchen and 3 in hallway not working asp PM 34017.								
Carlos Hernandez									
34229					5/12/2008		51		\$0.00
Medium	Work In Progress				5/12/2008 10:04:51 AM				
Castillo, Carlos	Exit Sign - 1 in kitchen not working asp PM 34028.								
Carlos Hernandez									
34545		Portables			5/22/2008		41		\$0.00
Medium	Work In Progress				5/22/2008 3:32:45 PM				
Ambriz, Jose	5-22-08 a/c unit portable #503 not cooling at times needs thermastate								
Carlos Hernandez									
34620	New Wing 1/02	Classroom			5/27/2008		36		\$0.00
Medium	Work In Progress				5/27/2008 3:38:01 PM				
Castillo, Carlos	5-27-08 need to install emergency light in bathroom in room 121								
Carlos Hernandez									
34965		Cafeteria			6/4/2008		28		\$0.00
Medium	Work In Progress				6/4/2008 4:32:55 PM				
Moncayo, Fernando	several lights in kitchen dont work								
Carlos Hernandez									
34992					6/5/2008		27		\$0.00
Medium	Work In Progress				6/5/2008 4:21:29 PM				
Carrasco, Danny	need lift to fix cable on flag pole								
Carlos Hernandez									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
35008					6/9/2008		23		\$0.00
Medium	Work In Progress			6/9/2008 6:50:53 AM					
Lara, Ralph	Cylinder Cores need to be cleaned (they are full of sand so key will not go in) on the following doors: Southwest Double Doors in Kinder Wing (addition)								
	Exterior Doors in room #123 and #125								
Peggy Jo Hernandez									
35056	New Wing 1/02	Classroom			6/10/2008		22		\$0.00
Medium	Work In Progress			6/10/2008 7:17:19 AM					
Lara, Ralph	need lock replaced cabinet in room 145 thank u								
Carlos Hernandez									
35285					6/19/2008		13		\$0.00
High	Work In Progress			6/19/2008 4:31:34 PM					
	Pick up trash all along northside fence line inside and out. This WO is for Daniel Mata (Head Custodian) not on the list.								
Jesus Estrada									
35413		Cafeteria			6/26/2008		6		\$0.00
Medium	Work In Progress			6/26/2008 11:59:48 AM					
Moncayo, Fernando	(5) Light Bulbs to Serving Line need to be replaced								
	Emilia Carrillo - SNP Manager 589-2550								
Alma Terrell									
35451		Cafeteria			6/30/2008		2		\$0.00
Medium	Work In Progress			6/30/2008 10:30:50 AM					
Orozco, Danny	ICE IS ACCUMULATING AROUND WALK-IN FREEZER DOOR -IT'S HARD TO CLOSE DOOR								
	EMILIA CARRILLO - SNP MANAGER 589-2550								
Alma Terrell									
Count: 20 Work Orders			Avg. Age of WO's	88			Total for Riverside ES	0	\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		San Miguel ES							
33909		Portables			5/1/2008		62		\$0.00
Medium	Work In Progress				5/1/2008 2:56:20 PM				
Holguin, Alfredo	Need to move Portable 5/9SM to Desert Pride Academy.								
Alfredo Holguin									
32044		Cafeteria			2/29/2008		124		\$0.00
High	Work In Progress				2/29/2008 2:33:50 PM				
Vega, Danny	need remove and dispose all desk, and unused furniture that is on southside. received complaint from community member.								
Michael Munoz									
33294					4/10/2008		83		\$0.00
High	Work In Progress				4/10/2008 11:36:55 AM				
Vega, Danny	need to move all tools, equipment, material etc to new location @ north valley asap. morgan bldg to be re-located. let me know when complete. there are plenty of shelves @ san miguel to use for proper storage in new area.								
Michael Munoz									
33467					4/17/2008		76		\$0.00
Medium	Work In Progress				4/17/2008 10:44:25 AM				
Ramirez, Joe	Please paint portable 5/9SM.								
Michael Munoz									
34043					5/5/2008		58		\$0.00
Medium	Work In Progress				5/5/2008 7:59:45 AM				
Estrada, Jesus	NEED TO REPLACE VCT WITH CARPET IN PORTABLE #5-SM9. THIS PORTABLE WILL BE RELOCATED TO DP. (NOTE: JOE RAMIREZ NEEDS TO PAINT BEFORE CARPET IS INSTALLED)								
Michael Munoz									
34865		Portables			6/2/2008		30		\$0.00
Medium	Work In Progress				6/2/2008 8:23:20 AM				
Holguin, Alfredo	Relocate Double Portable 77DW from San Miquel Elem to Desert View								
Alfredo Holguin									
34890		Portables			6/3/2008		29		\$0.00
Medium	Work In Progress				6/3/2008 9:17:47 AM				
Ontiveros, Guadalupe	Need to remove ramps from Double Portable 77DW will be relocated to Desert View.								
Michael Munoz									
35297		Parking Lot			6/20/2008		12		\$0.00
High	Work In Progress				6/20/2008 2:47:37 PM				
Vega, Danny	with 4th of july around the corner, this could be a fire hazard. please clean parking lot of pine needles and pine cones and underneath and around all pine trees.thxs								
Michael Munoz									

7/2/2008 10:38:03 AM

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: San Miguel ES

Count: 8 Work Orders Avg. Age of WO's 59 Total for San Miguel ES 0 \$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
24432					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:59 AM					
Villalobos, David	Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24433					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:59 AM					
Villalobos, David	Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
26342					8/28/2007		309		\$0.00
Medium	Work In Progress			8/28/2007 8:17:38 AM					
Ambriz, Jose	STERLING UNIT TO CAFET. PREP AREA IS NOT WORKING. ACTUATOR TO THE LOUVERS IS STUCK.								
Gerardo Marquez									
26772					9/6/2007		300		\$0.00
Medium	Work In Progress			9/6/2007 3:52:06 PM					
Villalobos, David	DAVID, NEED TO CHECK OUT MOP SINK IN C-WING (CASA ROJA) STILL LEAKING.								
Gerardo Marquez									
27366					9/24/2007		282		\$0.00
Medium	Work In Progress			9/24/2007 11:10:28 AM					
Castillo, Carlos	NEED TO CHECK OUT EXIT SIGNS THAT FAILED DURING M. INSP. THEY ARE AT RM. 211, LIBRARY MAIN ENTRANCE, & HALLWAY BY FACULTY RRMS.								
Gerardo Marquez									
29023					11/7/2007		238		\$0.00
Medium	Work In Progress			11/7/2007 8:46:04 AM					
Boyd, David	STUCCO IS STARTING TO CRACK AND CHIP AT PARAPETS. BLOCK WORK IS ALSO STARTING TO SEPARATE AT MORTAR JOINTS. SHEETROCK IS ALSO BREAKING ABOVE DOORS, AND AROUND DR. JAMBS. EXPANSION JOINTS IN FLOORS SEEM TO BE SEPARATING , THUS CAUSING VCT. TO CRACK.								
Gerardo Marquez									
30644					1/15/2008		169		\$0.00
Medium	Work In Progress			1/15/2008 1:26:14 PM					
Munoz, Michael	ATTN. MIKE. THE SLAB FOR THE DUMPSTERS HAS ALREADY BEEN POURED. NEED TO HAVE FENCE CONTRACTOR BUILD FENCE , AND GATES LIKE THE ONE IN THE PICTURE YOU SENT US. PLEASE BE SURE THEY INCLUDE THE SLATS.		Pending SB-9 Funding 4/23/08 - mm						
Gerardo Marquez									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa ES

31647	Main Building	Classroom			2/15/2008		138		\$0.00
Medium	Work In Progress	RM 108			2/15/2008 4:23:53 PM				
Marquez, Gerardo	RM 108 HAS A WIDE CRACK ON TOP OF THE ENTRY DOOR. PLEASE CHECK. THANKS.								

Rita Mendez

31826					2/25/2008		128		\$0.00
Medium	Work In Progress				2/25/2008 9:44:30 AM				

Ronquillo, Ruben

ATTN. RUBEN RONQUILLO
RUBEN, I NEED FOR YOU TO ORDER WINDOW SCREENS FOR PORTABLES E & F. WHEN DELIVERED THEY WERE MISSING THE SCREENS. HERE ARE THE SIZES AND QUANTITIES NEEDED. 2-- 27 5/8"X 28", 4--43 5/8"X16 1/8" THE FRAMES NEED TO BE BRONZE FINISH. THANKS.

Gerardo Marquez

31847					2/25/2008		128		\$0.00
Medium	Work In Progress				2/25/2008 3:37:27 PM				

Gonzales, Angel

ANGEL; AS PER MIKE MUNOZ HE WANTS US TO LET YOU KNOW THAT OUR MOWERS NEED TO BE SERVICED , SO THAT THELL BE READY FOR THE CUTTING SEASON. YOU CAN PICK IT UP AT YOUR EARLIEST CONVENIENCE. THANKS.

Gerardo Marquez

31848					2/25/2008		128		\$0.00
Medium	Work In Progress				2/25/2008 3:39:05 PM				

Gonzales, Angel

ANGEL, WE HAVE TWO BLOWERS THAT NEED TO BE SERVICED.

Gerardo Marquez

32415					3/10/2008		114		\$0.00
Medium	Work In Progress				3/10/2008 8:58:30 AM				

Gonzales, Angel

ANGEL;TRUCK 107 NEEDS TO HAVE THE OIL CHANGED, AND AND A TUNE UP . PLEASE LET ME KNOW WHEN TO TAKE IT IN. ALSO TRANSMISION SHIFTING REAL HARD.

Gerardo Marquez

32907					4/2/2008		91		\$0.00
Medium	Work In Progress				4/2/2008 9:23:16 AM				

Villalobos, David

DAVID, THE FAUCET IN THE CONFERENCE RM HAS A CONSTANT DRIP JUST LIKE THE NURSE OFFICE. NEED FOR YOU TO REPLACE IT. THANKS.

Gerardo Marquez

33333		Portables			4/11/2008		82		\$0.00
Medium	Work In Progress	ART PORTABLE			4/11/2008 1:39:17 PM				

Villalobos, David

PLEASE INSTALL SINK IN CLASSROOM. NEEDED FOR ART CLASSES. THANK YOU.

Rita Mendez

7/2/2008 10:38:03 AM

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									
Location: Santa Teresa ES									
33809		Classroom			4/29/2008		64		\$0.00
Medium	Work In Progress			4/29/2008 10:13:11 AM					
Marquez, Gerardo		WE RECEIVED FURNITURE THAT NEEDS TO BE PUT TOGETHER (SHELVES, CARTS ETC.). THANK YOU.							
Rita Mendez									
33810		Classroom			4/29/2008		64		\$0.00
Medium	Work In Progress	ALL		4/29/2008 10:21:51 AM					
Marquez, Gerardo		NEW TELEVISION SETS NEED TO BE SET UP IN THE CLASSROOMS ON HIGH STANDS. ASSISTANCE (AT LEAST 2 PEOPLE) NEEDED TO SET THEM UP. THANK YOU.							
Rita Mendez									
34332		Classroom			5/14/2008		49		\$0.00
Medium	Work In Progress	all areas		5/14/2008 3:59:09 PM					
Lara, Ralph		WE NEED 7 KEYS FOR THE FIRE ALARM BOXES (PULL BOXES). THANK YOU.							
Rita Mendez									
34333		Restroom (Girls)			5/14/2008		49		\$0.00
Medium	Work In Progress	ADULT		5/14/2008 4:05:10 PM					
Marquez, Gerardo		TOILET SEAT COVER DISPENSERS NEED TO BE INSTALLED IN THE RESTROOMS. THANKS.							
Rita Mendez									
34647		Classroom			5/28/2008		35		\$0.00
Medium	Work In Progress	ROOM 301		5/28/2008 9:47:26 AM					
Lara, Ralph		OUR TEACHER, MR. WADE CORNELIUS, LOST THE CLASSROOM KEY. PLEASE CHANGE THE DRUM IN THE DOOR. LOST KEY #1S19. THANK YOU.							
Rita Mendez									
34843					6/1/2008		31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:18 AM					
Marquez, Gerardo		Monthly - Santa Teresa ES A-11 Quarterly ERV - Refer to PM schedule details.							
Margret Villalobos									
34844					6/1/2008		31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:18 AM					
Marquez, Gerardo		Monthly - Santa Teresa ES C-6 Quarterly HP - Refer to PM schedule details.							
Margret Villalobos									
34916		Cafeteria			6/3/2008		29		\$0.00
Medium	Work In Progress			6/3/2008 3:36:47 PM					
Moncayo, Fernando		OVEN NOT WORKING							
		PAT SANCHEZ SNP MGR 589-3439							
Jacqueline Aguilar									
7/2/2008 10:38:03 AM									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Santa Teresa ES							
35246					6/18/2008		14		\$0.00
Medium	Work In Progress				6/18/2008 12:55:40 PM				
Ambriz, Jose	JOE, NEED TO REPLACE T-STAT IN PORTABLE -F. (ART ROOM.)								
Gerardo Marquez									
Count: 23 Work Orders		Avg. Age of WO's	139	Total for Santa Teresa ES				0	\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
24419					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:57 AM				
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24420					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24421					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24422					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24423					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24424					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24425					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24426					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress				7/1/2007 12:15:58 AM				
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
25499		Cafeteria			8/6/2007		331		\$0.00
Medium	Work In Progress			8/6/2007 10:44:10 AM					
Moncayo, Fernando		NEEDS WATER HOSE FOR USE NEAR DISHMACHINE (DANNY IS AWARE OF THIS REQUEST)							
		OLGA BUSTAMANTE - SNP MANAGER 589-5332							
Alma Terrell									
25748					8/13/2007		324		\$0.00
Medium	Work In Progress			8/13/2007 8:12:46 AM					
Ambriz, Jose		NEED SOME ASSISTANCE ON A.C. UNITS ON 600'S WING. BREAKERS #90 FOR EF-17, AND #94 FOR EC -2, WILL NOT STAY ON, NEED TO TROUBLE SHOOT.							
Arturo Nunez									
27496					9/27/2007		279		\$0.00
Medium	Work In Progress			9/27/2007 8:31:55 AM					
Lara, Ralph		NEED THREE (3) EA. HON LOCKS FOR FILING CABINETS, OVAL AND, ROUND.							
Arturo Nunez									
29446					11/27/2007		218		\$0.00
Medium	Work In Progress			11/27/2007 10:23:34					
Gonzales, Angel		MOFFLER NEEDS TO BE REPLACE FROM TRUCK #8 THANK YOU							
Joel Herrera									
30171					12/18/2007		197		\$0.00
Medium	Work In Progress			12/18/2007 9:40:57 AM					
Villalobos, Margret		NEED TO HAVE WORK STATION UP GRADE, CAN'T GET TEMP, DIANOSTICS, ETC. TO FAN COIL UNITS, AND AIR HANDLER UNITS.							
Arturo Nunez									
31135	Cafeteria (2005)	Cafeteria			1/31/2008		153		\$0.00
Medium	Work In Progress			1/31/2008 2:44:30 PM					
Moncayo, Fernando		WATER IS LEAKING FROM DISHMACHING - IGNACIA RELAYED MESSAGE TO SNP DEPT.							
		OLGA BUSTAMANTE - SNP MANAGER 589-5332							
Alma Terrell									
31252					2/3/2008	2/9/2008	150		\$0.00
Medium	Work In Progress			2/3/2008 12:30:56 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
31423	Gymnasium				2/8/2008		145		\$0.00
High	Work In Progress				2/8/2008 1:17:21 PM				
Nunez, Arturo	West side of porch, the sheetrock is missing. Please replace and tape and texture (paint). thxs								
Michael Munoz									
31867					2/26/2008		127		\$0.00
Medium	Work In Progress				2/26/2008 9:03:23 AM				
Villalobos, David	NEED A BELL AND GOSSET WATER CIRCULATING PUMP FOR WATER HEATER ON GIRLS RESSROOM.								
Arturo Nunez									
31870					2/26/2008		127		\$0.00
Medium	Work In Progress				2/26/2008 10:37:38 AM				
Ontiveros, Guadalupe	West of Bus Drop off Area- This area is apparently turing into the site dump. dispose of all trash and bring all salvagale itmes to the Physical plant yard.								
Alfredo Holguin									
32077					3/2/2008	3/8/2008	122		\$0.00
Medium	Work In Progress				3/2/2008 12:32:52 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
32083					3/2/2008	3/23/2008	122		\$0.00
Medium	Work In Progress				3/2/2008 12:32:55 AM				
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
32122					3/2/2008	3/10/2008	122		\$0.00
Medium	Work In Progress				3/2/2008 12:33:12 AM				
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
32520					3/12/2008		112		\$0.00
Medium	Work In Progress				3/12/2008 2:07:55 PM				
Lara, Ralph	NEED SIX SLIDE LOCKS FOR TROPHY CASES.								
Arturo Nunez									
32658					3/19/2008		105		\$0.00
Medium	Work In Progress				3/19/2008 10:39:14 AM				
Villalobos, David	NEED SOME ASSISTANCE ON BROKEN AND CRACKED CAST IRON VENT PIPES ON BOYS AND GIRLS RESTROOM ON 300'S WING. EMITTING FOUL SMELL INTO HALLWAY,AND CLASSROOMS.								
Arturo Nunez									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
32736					3/26/2008		98		\$0.00
Medium	Work In Progress			3/26/2008 11:14:50 AM					
Castillo, Carlos	Asp PM 32122 Gym Area - Missing 2 Emer. Lights Main Lobby - Missing 2 Emer. Lights Athletic Hall - Missing 1 Emer. Lights								
Manuel Prospero									
33065					4/6/2008	4/27/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:23 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
33869					4/30/2008		63		\$0.00
Medium	Work In Progress			4/30/2008 2:58:20 PM					
Lara, Ralph	NEED SIX (6) EA. LOCKS FOR CABINETS FOR ROOM #3. KEYED ALIKE. TO STORE EQUIPMENT.								
Arturo Nunez									
34073					5/5/2008		58		\$0.00
Medium	Work In Progress			5/5/2008 3:52:26 PM					
Castillo, Carlos	We have 4 Emergency Lights broken (asp PM 33098) 2 - Lobby Area and 2- Gym Area								
Manuel Prospero									
34077					5/5/2008		58		\$0.00
Medium	Work In Progress			5/5/2008 4:05:06 PM					
Castillo, Carlos	We have 3 exit signs broken on gym area and 1 in Locker Room (asp PM 33108)								
Manuel Prospero									
34573					5/23/2008		40		\$0.00
Medium	Work In Progress			5/23/2008 2:41:29 PM					
Ambriz, Jose	5/23/08. WE NEED TO REPLACE A/C MASTER COOL 65 ON ROOM 13. IS ON VERY BAD CONDITIONS. THIS WORK ORDER IS FOR JOSE AMBRIZ.								
Manuel Prospero									
34775					6/1/2008	6/22/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:21:52 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
34804					6/1/2008	6/9/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:02 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
34814					6/1/2008	6/9/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:05 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
34820					6/1/2008	6/17/2008	31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:07 AM					
Villalobos, Margret	Yearly - Santa Teresa HS June Chiller Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35064					6/10/2008		22		\$0.00
High	Work In Progress			6/10/2008 9:48:32 AM					
Valles, Johnny	corroedores in the bldg area(2) need to be cleaned up. there are weeds, grass, trash etc and trees need to be trimmed and watered.								
<u>Michael Munoz</u>									
35066	Dressing Rooms	Gym			6/10/2008		22		\$0.00
Medium	Work In Progress			6/10/2008 9:53:42 AM					
Villalobos, David	new boys locker room. one of the shower handles is missing and needs to be replaced also in the same area please check to see that all sensors to wash basin are operable. ckeck girls area also.thxs								
<u>Michael Munoz</u>									
35117	Gymnasium	Gym			6/11/2008		21		\$0.00
Medium	Work In Progress			6/11/2008 4:44:05 PM					
Lara, Ralph	MR.LOZOYA WE NEED OUR GYM DOORS LOCKES CHANGE ON JULY THE 21st WE ARE GOING TO WORK ON OUR GYM FLOOR THANKS.								
<u>Luis Murillo</u>									
35154					6/15/2008		17		\$0.00
Medium	Work In Progress			6/15/2008 12:18:04 AM					
Ontiveros, Guadalupe	Monthly - Santa Teresa HS Soil Sampling - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35254					6/18/2008		14		\$0.00
Medium	Work In Progress			6/18/2008 4:21:47 PM					
Prospero, Manuel	6/18/08. 10HRS FINISH PAINT RESTROMS ONSHOP 1 (WALLLS, PARTITION AND CEILING.		6/18-8						
Manuel Prospero									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

35367					6/25/2008		7		\$0.00
Medium	Work In Progress				6/25/2008 7:52:45 AM				
Ambriz, Jose	NEED A TRACER CONTROLLER TOUCH PAD FOR CHILLER. THE EXISTING ONE HAS A BAD ONE. IT IS BROKEN FACE GLASS AND IS WEATHER BEATEN, WILL HAVE TO RELOCATED INSIDE OF MECH. ROOM.								
Arturo Nunez									
35368					6/25/2008		7		\$0.00
Medium	Work In Progress				6/25/2008 7:58:42 AM				
Ambriz, Jose	NEED TWO WATER FOUNTAINS TO REPLACE THE ONES ON GYM. HALLWAY, ONE REGULAR, AND ONE THAT IS HANDICAP ASSESIBLE.								
Arturo Nunez									
35378					6/25/2008		7		\$0.00
Medium	Work In Progress				6/25/2008 12:35:20 PM				
Ambriz, Jose	NEED A BELIMO SOLINOID WATER CONTROL VALVE FOR LIBRARY A.H.U. , NOT CORESPONDING TO T 'STAT COMMAND, WILL NOT REGULATE WATER FLOW. #00623-40004-048 ACT 00400 CALIBRATED AT 0.6.08.								
Arturo Nunez									
35379					6/25/2008		7		\$0.00
Medium	Work In Progress				6/25/2008 12:41:28 PM				
Castillo, Carlos	NEED SOME ASSISTANCE ON TROUBLE SHOOTING LIGHTS ON OLD BOYS DRESSING ROOM. WILL NOT TURN OFF.								
Arturo Nunez									
Count: 42 Work Orders			Avg. Age of WO's	148		Total for Santa Teresa HS	0		\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
24431					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:59 AM					
Villalobos, David	Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24427					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:58 AM					
Villalobos, David	Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24428					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:58 AM					
Villalobos, David	Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24429					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:58 AM					
Villalobos, David	Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24430					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:58 AM					
Villalobos, David	Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24498					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:16:27 AM					
Mijarez, Jaime	Yearly - Santa Teresa MS Emer. Light Test: Annual - Refer to PM schedule details.								
Alfredo Holguin									
24501					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:16:29 AM					
Mijarez, Jaime	Yearly - Santa Teresa MS Exit Sign Test: Annual - Refer to PM schedule details.								
Alfredo Holguin									
25722	South Building	Classroom			8/10/2007		327		\$0.00
Medium	Work In Progress	ROOM 35		8/10/2007 2:28:12 PM					
Lara, Ralph	Need key for filing cabinet								
Laura Parra									
25723	South Building	Classroom			8/10/2007		327		\$0.00
Medium	Work In Progress	36 B		8/10/2007 2:33:23 PM					
Lara, Ralph	Need key for filing cabinet								
Laura Parra									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

25837					8/14/2007		323		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/14/2007 10:09:09 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ambriz, Jose
Please order for condensate pump replacement. 35 ea. little giant pumps cat#554200, vcc- 20uls or 2ouls, 35 ea. 1/2" 90 deg. ells. SlipxTHD, 35 ea. SPRTB-6 24x24 metal grilles, 35 ft 3/4"OD x 5/8" ID clear vinyl tube, box of 3 amp fuses, box of 1 amp fuses, box of orange electrical wire nuts, and box of insulated female and male solderless terminals.

Jaime Mijarez

25886	South Building	Classroom			8/15/2007		322		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	room 47		8/15/2007 11:06:16 AM					
--------	------------------	---------	--	-----------------------	--	--	--	--	--

Mijarez, Jaime
Install a new pencil sharpener in room 47

Dana Hamel

26272					8/27/2007		310		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/27/2007 8:51:27 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe
Storm drain in back of S.bldg has a section that is bent inward and sand is caving in through a hole. I showed Alfredo Holguin, please give the work order to Alfredo. ROUTE TO LUPE ASP MIKE 8/30

Jaime Mijarez

28417	North Building	Cafeteria			10/23/2007		253		\$0.00
-------	----------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress			10/23/2007 12:28:57					
--------	------------------	--	--	---------------------	--	--	--	--	--

Mijarez, Jaime
Baseboard and walls in kitchen by sinks and dishwashing area need to be replaced. This is by order of the NM Environmental Department and the report and the repair must be completed in 60 days. According to ED this is not the first warning about the repairs in an inspection report
Assign to Jaime and Gerry will assist asp Mike 11/13/07 -mkv

Dana Hamel

28722					10/31/2007		245		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress			10/31/2007 9:24:59 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Castillo, Carlos
AS PER OUR CONVERSATION, PLEASE PROVIDE A 120 OUTLET FOR THE ENVIRONMENT DEPT.

Michael Munoz

30823	Gym (1997)	Parking Lot			1/22/2008		162		\$0.00
-------	------------	-------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			1/22/2008 9:03:05 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David
Repair the dripping faucet that continues to cause freezing ice and dangerous conditions

Dana Hamel

30838	North Building	Restroom (Girls)			1/22/2008		162		\$0.00
-------	----------------	------------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			1/22/2008 2:09:24 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph
Unisex restroom top floor north building need to have a key CYLINDER THAT ANY KEY WILL OPEN, currently any coin will do and we have found students ditching there.

Dana Hamel

7/2/2008 10:38:04 AM

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
30843	South Building	Choral			1/22/2008		162		\$0.00
Medium	Work In Progress	Choir			1/22/2008 2:48:03 PM				
Lara, Ralph	Need signs over both doors that say " Choir Room"								
<u>Laura Parra</u>									
30935	South Building				1/24/2008		160		\$0.00
Medium	Work In Progress				1/24/2008 3:22:30 PM				
Castillo, Carlos	We are going to need electrical outlets installed at Santa Teresa Middle South Bld IDF. We have currently extended electrical using 15' power strips, but need the outlets relocated closer to the cabinets contact Silver.								
<u>Cora Ramirez</u>									
31013					1/29/2008		155		\$0.00
Medium	Work In Progress				1/29/2008 9:36:23 AM				
Villalobos, David	S.bldg water heater room. Need to replace water shut-off valves for irrigation and regulator.								
<u>Jaime Mijarez</u>									
31803	South Building				2/22/2008		131		\$0.00
Medium	Work In Progress				2/22/2008 3:20:24 PM				
Castillo, Carlos	Santa Teresa Middle South Bld IDF, We have currently extended electrical using 15' power strips, but need the outlets relocated closer to the cabinets.								
<u>Cora Ramirez</u>									
32247	North Building	Custodial			3/4/2008		120		\$0.00
Medium	Work In Progress				3/4/2008 9:05:20 AM				
Lara, Ralph	as,per ms .casillas we need to change the door handles in the boys and girls restrooms in the cafeteria for safety reasons.also mr.lara i will be needing 3 L wrenches for the panic bars.thank you see mr rodriguez.								
<u>Ismael Rodriguez</u>									
32407	North Building	Custodial			3/10/2008		114		\$0.00
Medium	Work In Progress				3/10/2008 7:30:08 AM				
Castillo, Carlos	also,the exterior lights in the front of the north lobby porch are also not working.								
<u>Ismael Rodriguez</u>									
32471	South Building				3/11/2008		113		\$0.00
Medium	Work In Progress				3/11/2008 1:28:07 PM				
Villalobos, David	need to replace two exterior water faucets in order to irrigate the front campus trees there in bad shape.thank you.								
<u>Ismael Rodriguez</u>									
32587	Gym (1997)	Gym			3/14/2008		110		\$0.00
Medium	Work In Progress				3/14/2008 1:48:26 PM				
Estrada, Jesus	Gym floor bubble up due to water leak. need to repair gym floor.								
<u>Michael Munoz</u>									
7/2/2008 10:38:04 AM									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
32692					3/25/2008		99		\$0.00
Medium	Work In Progress			3/25/2008 10:39:32 AM					
Mijarez, Jaime	A section of the floor in front of the custodial closet has been lifting up and seems to be getting worst. I have tried to dry it up and to put it back in place but had no luck. Could you send somebody please? Request was sent thru e-mail on Thursday 1/10/2008 10:05 am. Mike Munoz requested work order. Thank you.		Asp Mike assign to Chuy. 4-2-08 - REROUTED TO JAIME MINJAREZ AS PER CHUY, HE HAS TALKED TO HIM.						
<u>Jaime Mijarez</u>									
32733	South Building	Office			3/26/2008		98		\$0.00
Medium	Work In Progress	Assistant		3/26/2008 10:02:58 AM					
Lara, Ralph	Please place lock in refrigerator								
<u>Laura Parra</u>									
32810					2/26/2008		31		\$0.00
Medium	Work In Progress			3/28/2008 9:25:48 AM	3/28/2008				
Gonzales, Angel	Gooseneck Trailer lights were broken need to be replaced.								
<u>Manuel Barrientos</u>									
33229		Office			4/9/2008		84		\$0.00
Medium	Work In Progress			4/9/2008 11:17:36 AM					
Castillo, Carlos	N.bldg principals office. Need to relocate the light switch so that the lights can be turned on as the principal enters her office.								
<u>Jaime Mijarez</u>									
33232	South Building	Restroom (Girls)			4/9/2008		84		\$0.00
Medium	Work In Progress			4/9/2008 11:52:35 AM					
Castillo, Carlos	I need help with a emergency light fixture. I installed a new ballast, but can't get it to turn on.								
<u>Jaime Mijarez</u>									
33331	North Building	Cafeteria			4/11/2008		82		\$0.00
Medium	Work In Progress			4/11/2008 11:24:44 AM					
Moncayo, Fernando	Kitchen walk-in refrigerator, Troubleshoot condensing unit. Contactor needs to be changed. Due to power outage.								
<u>Jaime Mijarez</u>									
33699	North Building	Stairway			4/24/2008		69		\$0.00
Medium	Work In Progress			4/24/2008 8:07:33 AM					
Ontiveros, Guadalupe	lupe, i was talking to mr.soria about putting some windscreen along the stairway going from northbuilding to gym,this will keep the sand out of the stairway,so faculty and students have a better access.thank you.see mr. rodriguez.								
<u>Ismael Rodriguez</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
33953		Cafeteria			5/2/2008		61		\$0.00
Medium	Work In Progress			5/2/2008 3:32:52 PM					
Moncayo, Fernando		Need Freezer Outlet in the storage room							
Alma Terrell		Paula Sanchez - SNP Manager 589-9836							
33954		Cafeteria			5/2/2008		61		\$0.00
Medium	Work In Progress			5/2/2008 3:33:54 PM					
Moncayo, Fernando		Garbage disposal is still out of order							
Alma Terrell		Paula Sanchez - SNP Manager 589-9836							
34086		Cafeteria			5/6/2008		57		\$0.00
Medium	Work In Progress			5/6/2008 10:52:58 AM					
Castillo, Carlos		NEED ELECTRICAL OUTLETS FOR REACH-IN FREEZERS IN THE STORAGE ROOM.							
Alma Terrell									
34131		Cafeteria			5/8/2008		55		\$0.00
Medium	Work In Progress			5/8/2008 8:31:10 AM					
Moncayo, Fernando		Weather Stripping to Door needs to be replaced							
Alma Terrell		Paula Sanchez - SNP Manager 589-9836							
34132		Cafeteria			5/8/2008		55		\$0.00
Medium	Work In Progress			5/8/2008 8:34:31 AM					
Moncayo, Fernando		Kitchen needs to be repainted (new colors) Black on Doors and Gold on Walls and Ceiling (as per Principal's Request)							
Alma Terrell		Paula Sanchez - 589-9836							
34589	South Building	Office			5/23/2008		40		\$0.00
Medium	Work In Progress			5/23/2008 4:01:24 PM					
Estrada, Jesus		Requested by Yvonne Casillas assistant principal. Remove carpet south bldg office area, except Assistant Principals office, and is requesting tile.				5/29/08 - REVISED - NEED TO INSTALL CARPET INSTEAD OF VCT DUE TO ACM'S. COPY FAXED TO MICHAEL GARCIA			
Jaime Mijarez									
34937	North Building	Custodial			6/3/2008		29		\$0.00
Medium	Work In Progress			6/3/2008 5:23:57 PM					
Lara, Ralph		mr.manny, asper ms lovelace she want for you to rekey her office and ms parras office , ms casillas office, mechanicalrooms and also room 19.see principal.thank you.							
Ismael Rodriguez									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
34950	South Building	Office			6/4/2008		28		\$0.00
Medium	Work In Progress	South			6/4/2008 1:26:29 PM				
Castillo, Carlos		Need electrical socket for copy machine. Copy machine will be moved from original area.							
Laura Parra									
34973					6/4/2008		28		\$0.00
Medium	Work In Progress				6/4/2008 4:46:16 PM				
Carrasco, Danny		We are going to need the water pressure washer to wash spider webs and dirt from the outside walls and windows.							
Jaime Mijarez									
35004					6/6/2008		26		\$0.00
Medium	Work In Progress				6/6/2008 1:52:33 PM				
Mijarez, Jaime		norht bldg entrance, the concrete is seperating from the wall. It is full of sand, please blow out sand and prep a liquid concrete (slushy) and fill gab area.							
Michael Munoz									
35382	Gym (1997)	Gym			6/25/2008		7		\$0.00
Medium	Work In Progress				6/25/2008 3:13:01 PM				
Mijarez, Jaime		Gym. Paint over existing colors. First phase is paint over the pink color with gloss black, door frames gloss black, and doors vegas gold. 2nd phase is paint middle stripp vegas gold, and Mrs. Ace Sanchez wants another stripp of turquois paint color, 3rd phase is paint over the peach color with vanilla bean paint.							
Jaime Mijarez									
35383	Gym (1997)	Gym			6/25/2008		7		\$0.00
Medium	Work In Progress				6/25/2008 3:20:27 PM				
Carrasco, Danny		Gym. I Need 3 sections of scaffold including platforms by 6/30/08 to start on gym paint project.							
Jaime Mijarez									
Count: 43 Work Orders		Avg. Age of WO's 164		Total for Santa Teresa MS			0	\$0.00	

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Sunland Park ES									
28542					10/25/2007		251		\$0.00
Medium	Work In Progress			10/25/2007 1:24:32 PM					
Villalobos, David	CLASSROOM #24 - UNCLOG SINK								
Irene Trujillo									
24416					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:57 AM					
Villalobos, David	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24417					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:57 AM					
Villalobos, David	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24418					7/1/2007	8/1/2007	367		\$0.00
Medium	Work In Progress			7/1/2007 12:15:57 AM					
Villalobos, David	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
Alfredo Holguin									
24962					7/20/2007		348		\$0.00
Medium	Work In Progress			7/20/2007 11:45:33 AM					
Lara, Ralph	Please help open two filing cabinets that were accidentally locked during the summer break.								
Irene Trujillo									
25127	Main Building				7/26/2007		342		\$0.00
Medium	Work In Progress			7/26/2007 3:24:02 PM					
Herrera, Joel	2nd request - Tile in nurse's office is not level. Safety hazard concern, as student/staff may possibly trip and be injured.		8/2 - Route to M. Prospero. This issue was discussed w/him last year. Mike.						
Irene Trujillo									
25405					8/3/2007		334		\$0.00
Medium	Work In Progress			8/3/2007 3:33:00 PM					
Lara, Ralph	CLASSROOM 28 - PLEASE INSTALL A DOOR KNOB WITH A LOCK IN THE RESTROOM.								
Irene Trujillo									
26232					8/24/2007		313		\$0.00
Medium	Work In Progress			8/24/2007 1:20:27 PM					
Herrera, Joel	2ND REQUEST - PORTABLES NEED PAINTING.								
Irene Trujillo									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
26236					8/24/2007		313		\$0.00
Medium	Work In Progress			8/24/2007 1:31:54 PM					
Villalobos, David	CLASSROOM 25 - WATER FLUSING (IT IS STUCK) IN COMMODE. WATER RUNS FOR 15-20 MINS. THEN STOPS.								
Irene Trujillo									
26344					8/28/2007		309		\$0.00
Medium	Work In Progress			8/28/2007 8:31:05 AM					
Holguin, Alfredo	Provide services and materials for installation of new controller to control existing lighting.		Joe V. picked up PO on 9/4-mkv						
Alfredo Holguin									
26874					9/11/2007		295		\$0.00
Medium	Work In Progress			9/11/2007 10:10:09 AM					
Villalobos, David	9/11/07. WE HAVE A WATER LEAK ON MECHANICAL ROOM.(IS A WATER VALVE). THIS WORK ORDER IS FOR DAVID VILLALOBOS.								
Manuel Prospero									
27507					9/27/2007		279		\$0.00
Medium	Work In Progress			9/27/2007 12:32:18 PM					
Villalobos, David	classroom #41 - Toilet needs to be repaired. Do not have enough pressure.								
Irene Trujillo									
28178					10/16/2007		260		\$0.00
Medium	Work In Progress			10/16/2007 10:01:32					
Herrera, Joel	The ramps on portables need to be painted. Also, this is a reminder portables have not been painted (previously submitted request.)								
Irene Trujillo									
28192					10/16/2007		260		\$0.00
Medium	Work In Progress			10/16/2007 3:07:59 PM					
Herrera, Joel	2ND REQUEST TO HAVE THE PORTABLES PAINTED.								
Irene Trujillo									
28273					10/18/2007		258		\$0.00
Medium	Work In Progress			10/18/2007 1:55:04 PM					
Lara, Ralph	CLASSROOM 25 - THE DOOR WHICH LEADS TO THE OUTSIDE NEEDS TO BE REPLACED.								
Irene Trujillo									
28721					10/31/2007		245		\$0.00
Medium	Work In Progress			10/31/2007 9:24:25 AM					
Castillo, Carlos	AS PER OUR CONVERSATION, PLEASE PROVIDE A 120 OUTLET FOR THE ENVIRONMENT DEPT.								
Michael Munoz									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Sunland Park ES									
29221					11/14/2007		231		\$0.00
Medium	Work In Progress			11/14/2007 1:49:39 PM					
Herrera, Joel	PLEASE HANG 10 FRAMED POSTERS THROUGHOUT THE SCHOOL BUILDING.								
Irene Trujillo									
30712	Main Building	Athletic Field			1/16/2008		168		\$0.00
Medium	Work In Progress			1/16/2008 4:17:40 PM					
Ontiveros, Guadalupe	Clean out drains at main entrance. Also cut weeds around back stop and play area								
Guadalupe Ontiveros									
32904					4/2/2008		91		\$0.00
Medium	Work In Progress			4/2/2008 8:12:41 AM					
Lara, Ralph	KEY #TJ1 FOR ROOM 19 - PLEASE CHECK THE (3) KEYS WE HAVE. THESE DO NOT OPEN THE DOOR WITH THE NEW DOOR KNOB.								
Irene Trujillo									
33244		Classroom			4/9/2008		20	1	\$25.00
Medium	Work In Progress			4/9/2008 1:49:14 PM		4/29/2008			
Estrada, Jesus	REMOVE CARPET IN THE PRINCIPAL'S OFFICE AND CONFERENCE ROOM; TO BE REPLACED WITH FLOOR TILE.								
Irene Trujillo	4/29/08 - AS PER CHUY, THIS CAN WAIT UNTIL FURTHER NOTICE 5/9/08 - REOPENED - REQUESTED QUOTE								
33824					4/29/2008		64		\$0.00
Medium	Work In Progress			4/29/2008 3:47:44 PM					
Ontiveros, Guadalupe	WE NEED TO RE-MOVED MONKEY BARS AND DEAD TREES THANK YOU LUPE.....								
Joel Herrera									
34448					5/20/2008		43		\$0.00
Medium	Work In Progress			5/20/2008 2:52:51 PM					
Estrada, Jesus	WE NEED TO REPLACE FLOOR TILE AT PORTABLE P-C THANK YOU MR. ESTRADA								
Joel Herrera									
34526					5/22/2008		41		\$0.00
Medium	Work In Progress			5/22/2008 10:29:27 AM					
Lara, Ralph	PORT. F - PLEASE INSTALL WEATHER STRIPPING ON BOTH DOORS. DUST SEEPS THRU AND DAMAGES INSTRUMENTS.								
Irene Trujillo									
34729					5/30/2008		33		\$0.00
Medium	Work In Progress			5/30/2008 2:34:04 PM					
Gonzalez, Salvador	I NEED WELD TWO FRONT GATES AT MAIN ENTRANCE AREA								
Joel Herrera									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
34849					6/1/2008		31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:20 AM					
Herrera, Joel	Monthly - Sunland Park ES A-6 Quarterly PUG - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
34850					6/1/2008		31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:20 AM					
Herrera, Joel	Monthly - Sunland Park ES A-5 Quarterly SS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
34851					6/1/2008		31		\$0.00
Medium	Work In Progress			6/1/2008 12:22:20 AM					
Herrera, Joel	Monthly - Sunland Park ES A-13 Quarterly WREH - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
34868					6/2/2008		30		\$0.00
Medium	Work In Progress			6/2/2008 3:25:34 PM					
Villalobos, Margret	WE HAVE RATS AT PORTABLE D		Faxed to PC						
<u>Joel Herrera</u>									
34894	Main Building				6/3/2008		29		\$0.00
Medium	Work In Progress			6/3/2008 10:51:48 AM					
Lara, Ralph	THE AUTOMATIC HANDICAP DOORS DO NOT OPEN WHEN BUTTON IS PRESSED. THESE ARE BOTH DOORS; ONE AT THE MAIN ENTRANCE AND THE ONE AT THE BACK OF BUILDING. PLEASE CHECK ASAP.								
<u>Irene Trujillo</u>									
34896					6/3/2008		29		\$0.00
Medium	Work In Progress			6/3/2008 12:11:02 PM					
Lara, Ralph	WE NEED TREE KEYS FOR BOYS REST ROOMS LIGHTS								
<u>Joel Herrera</u>									
34948					6/4/2008		28		\$0.00
Medium	Work In Progress			6/4/2008 11:00:31 AM					
Ontiveros, Guadalupe	Level out circled area.								
<u>Michael Munoz</u>									
34981					6/5/2008		27		\$0.00
Medium	Work In Progress			6/5/2008 2:45:52 PM					
Miranda, Danny	WE NEED TO REPLACE PICE OF SHEETROCK WATERPROOF AT BOYS REST ROOM AT CLASS ROOM #25 MR. DANNY MIRANDA I NEED YOU HELP THANK YOU MR.								
<u>Joel Herrera</u>									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
35071					6/10/2008		22		\$0.00
Medium	Work In Progress				6/10/2008 2:09:16 PM				
Carrasco, Danny		WE NEED FOUR	1/2 INCH DRINKING BUBBLERS			Asp Mike route to Maint Warehouse			
Joel Herrera									
35175					6/16/2008		16		\$0.00
Medium	Work In Progress				6/16/2008 11:59:20 AM				
Villalobos, David		Kinder Plus Program is using Classroom # 41 we have a problem with the restroom. When the students flush the toilet, everything returns since there is low water pressure.							
Laura Pargas									
Count: 34 Work Orders			Avg. Age of WO's	173		Total for Sunland Park ES	1		\$25.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
30685		Classroom			1/16/2008		168		\$0.00
Medium	Work In Progress	p-8		1/16/2008 12:56:03 PM					
Lozoya, Manny		I need to have an extra key for portable 8 We will be having detention in this portable and our Coach will need access key # 1c88.							
Joanne Munoz									
31156					2/1/2008		152		\$0.00
Medium	Work In Progress			2/1/2008 7:56:27 AM					
Jacquez, Ricardo		BACK FENCE LINE,REQUESTING WIND SCREEN ESTIMATE LENGTH OF APPROX. 250'. THANKS							
Paul Quinones									
31962					2/27/2008		126		\$0.00
Medium	Work In Progress			2/27/2008 3:57:37 PM					
Sotelo, Enrique		NEED TO REPLACE BROKEN LAMP COVERS IN NURSES STATION,STAFFS REST RM. IN WING B,AND STAFFS REST RM.IN WING C. AS WELL.THANKS							
Paul Quinones									
32117					3/2/2008	3/10/2008	122		\$0.00
Medium	Work In Progress			3/2/2008 12:33:09 AM					
Quinones, Paul		Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
32778	Main Building	Portables			3/27/2008		97		\$0.00
Medium	Work In Progress	P-6 AND P-5		3/27/2008 1:49:42 PM					
Quinones, Paul		Need wheels on portable cabinets to be replaced or fixed one in each portable.							
Joanne Munoz									
32881					4/1/2008		92		\$0.00
Medium	Work In Progress			4/1/2008 3:08:51 PM					
Ontiveros, Guadalupe		REQUESTING AERATE BACK GRASS FIELD							
Paul Quinones									
33776					4/28/2008		65		\$0.00
Medium	Work In Progress			4/28/2008 2:47:31 PM					
Holguin, Alfredo		Run Electrical power to the new marquee							
Alfredo Holguin									
34188					5/9/2008		54		\$0.00
Medium	Work In Progress			5/9/2008 9:47:29 AM					
Ronquillo, Ruben		ATTN: RUBEN RON. BROKEN PLAY GROUND EQUIPMENT AS PER RUBEN REQUEST W/O IS NEEDED FOR P/O #.							
Paul Quinones									

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
34530	Main Building	Athletic Field			5/22/2008		41		\$0.00
Medium	Work In Progress	basketball courts			5/22/2008 1:08:05 PM				
Ontiveros, Guadalupe		Need line up spots and circle on Basketball courts. See Coach Roger for further details.							
<u>Joanne Munoz</u>									
34884	Main Building	Classroom			6/2/2008		30		\$0.00
Medium	Work In Progress	P-5			6/2/2008 6:39:09 PM				
Quinones, Paul		nEED TO REPAIR CASTERS ON BLUE CABINET IN P-5							
<u>Joanne Munoz</u>									
35096	Main Building	Classroom			6/11/2008		21		\$0.00
Medium	Work In Progress	p-7			6/11/2008 8:45:33 AM				
Quinones, Paul		In P-7 there will be a movement of the bulletin board the holes will need to be patched and the wall painted							
<u>Joanne Munoz</u>									
Count: 11 Work Orders		Avg. Age of WO's		88	Total for Sunrise ES			0	\$0.00

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
29332					11/19/2007		226		\$0.00
Medium	Work In Progress			11/19/2007 9:17:26 AM					
Sotelo, Enrique		need light covers for lights in restroom 100-wing							
Danny Miranda									
30436					1/9/2008		175		\$0.00
Medium	Work In Progress			1/9/2008 3:02:16 PM					
Lozoya, Manny		need to repair teachers restroom door knob door can't be opened from inside teachers are locking themselves inside							
Danny Miranda									
30943					1/24/2008		160		\$0.00
Medium	Work In Progress			1/24/2008 3:54:33 PM					
Villalobos, Margret		Asp Jose Ambriz the need to replace board on BCU. Unable to communicate w/site. (Please advise when someone will be coming out so we can send one of our Technicians) Thanks.							
Jose Ambriz									
30956					1/25/2008		159		\$0.00
Medium	Work In Progress			1/25/2008 1:06:11 PM					
Sotelo, Enrique		A-Wing - no power to several several classrooms.							
Enrique Sotelo									
31310	Main Building	Classroom			2/5/2008		148		\$0.00
Medium	Work In Progress			2/5/2008 1:02:35 PM					
Miranda, Danny		RAISE HANDICAP BAR IN SPECIAL NEEDS ROOM 101							
Debra Facio									
31592					2/14/2008		139		\$0.00
Medium	Work In Progress			2/14/2008 10:08:00 AM					
Lozoya, Manny		NEED TO REPLACE DOOR KNOB IN CUSTODIAL RM. 100-WING HANDLE WILL NOT STAY ON							
Danny Miranda									
31745					2/21/2008		132		\$0.00
Medium	Work In Progress			2/21/2008 12:23:59 PM					
Sotelo, Enrique		need to put in two lights in r.r. in rm. 103							
Danny Miranda									
31746					2/21/2008		132		\$0.00
Medium	Work In Progress			2/21/2008 12:25:04 PM					
Miranda, Danny		need to put in curtain divider in r.r. to rm. 103							
Danny Miranda									
33069					4/6/2008	4/27/2008	87		\$0.00
Medium	Work In Progress			4/6/2008 12:18:24 AM					
Orozco, Danny		Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									

7/2/2008 10:38:04 AM

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Vado ES								
33215					4/9/2008		84		\$0.00	
Medium	Work In Progress			4/9/2008 8:01:59 AM						
Lozoya, Manny		NEED TO CK. DEAD BOLT IN RM. 305								
Danny Miranda										
33217	Main Building	Hallway/Corridor			4/9/2008		84		\$0.00	
Medium	Work In Progress			4/9/2008 8:16:48 AM						
Ronquillo, Ruben		NEED BLINDS FOR TWO WINDOWS IN PARENT EMASSADOR ROOM-JOHANNA MORA 74X20 NEED SIX TOTAL, (74X32) NEED TWO TOTAL								
Debra Facio										
33393					4/14/2008		79		\$0.00	
Medium	Work In Progress			4/14/2008 2:08:56 PM						
Ronquillo, Ruben		NEED BALLAST FOR EMERGENCY LAMPS								
Danny Miranda										
34227					5/12/2008		51		\$0.00	
Medium	Work In Progress			5/12/2008 9:23:47 AM						
Gonzales, Angel		need bobcat for grounds back of school, and to remove sand around campus								
Danny Miranda										
34393					5/16/2008		47		\$0.00	
Medium	Work In Progress			5/16/2008 1:17:10 PM						
Solis, Lorenzo		NEED THREE MOTORS FOR COMM. & ELEC. RM'S								
Danny Miranda										
34528					5/22/2008		41		\$0.00	
Medium	Work In Progress			5/22/2008 10:36:32 AM						
Lozoya, Manny		NEED TO RETIME AND ADJUST ALL DEAD BOLTS BETWEEN CLASSROOM'S								
Danny Miranda										
34614					5/27/2008		36		\$0.00	
Medium	Work In Progress			5/27/2008 2:52:36 PM						
Ontiveros, Guadalupe		NEED FILL DIRT TO REDO WHAT WIND HAS BLOWN AWAY								
Danny Miranda										
34997					6/5/2008		27		\$0.00	
Medium	Work In Progress			6/5/2008 4:40:32 PM						
Lozoya, Manny		NEED TO CK. KEY IN LIBRARY THAT WILL NOT OPEN DOOR TO ROOM								
Danny Miranda										
35281					6/19/2008		13		\$0.00	
High	Work In Progress			6/19/2008 4:26:55 PM						
Diaz, Armando		Pick up trash all along the north and east fence line. (assign to Armando Diaz)								
Jesus Estrada										
Count: 18 Work Orders			Avg. Age of WO's	101				Total for Vado ES	0	\$0.00

7/2/2008 10:38:04 AM

934 - Work Orders In Progress (07-08 Fiscal Year)

Selected Date Range for Request Dates: 7/1/2007 - 6/30/2008 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Count: 934 Work Orders		Avg. Age of WO's 137			Grand Total			2	\$75.00