

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Anthony ES

35695					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:06 AM				
Villalobos, David	Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35986	Chapter I	Office			7/16/2008		110		\$0.00
Medium	Work In Progress				7/16/2008 9:38:50 AM				
Lozoya, Manny	chapter blg repair pannic bar a.s.a.p								
Hector Villalobos									
36176	Cafeteria	Cafeteria			7/24/2008		102		\$0.00
Medium	Work In Progress				7/24/2008 11:26:39 AM				
Ontiveros, Guadalupe	remove old tree next to cafeteria,health issue as per ms.marquez								
David Vega									
36311	Chapter I	Office			7/29/2008		97		\$0.00
Medium	Work In Progress				7/29/2008 8:10:42 AM				
Estrada, Jesus	chapter blg o.t.p. room carpet need to be replace .glue on carpet from vandalism					QUOTE REQUESTED PER CHUY 8/1/08			
Hector Villalobos									
36641	Drug Free Bldg.				8/5/2008		90		\$0.00
Medium	Work In Progress				8/5/2008 10:48:59 AM				
Sotelo, Enrique	please install a power strip for radios. please see irene for location.thxs								
Michael Munoz									
36672					8/6/2008		89		\$0.00
Medium	Work In Progress				8/6/2008 8:48:17 AM				
Lozoya, Manny	Primary blg storage need to charge lock								
Hector Villalobos									
36679	Annex Building	Classroom			8/6/2008		89		\$0.00
Medium	Work In Progress				8/6/2008 11:11:09 AM				
Estrada, Jesus	remove or install new carpet,carpet is tearing upas per teacher,potable 218								
David Vega									
37105	Chapter I	Office			8/15/2008		80		\$0.00
Medium	Work In Progress				8/15/2008 8:46:10 AM				
Lozoya, Manny	chapter blg o.t.p room needs 4 keys k50								
Hector Villalobos									
37112					8/15/2008		80		\$0.00
Medium	Work In Progress				8/15/2008 11:23:07 AM				
Estrada, Jesus	NEED TO REPLACE CARPET IN "SECURITY - DRUG FREE BARRACK.								
Michael Munoz									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

37170	Nurse Building				8/19/2008		76		\$0.00
Medium	Work In Progress				8/19/2008 7:36:40 AM				

Lozoya, Manny need to replace exit door
Hector Villalobos

37287	Cafeteria	Cafeteria			8/21/2008		74		\$0.00
Medium	Work In Progress				8/21/2008 11:49:08 AM				

Orozco, Danny SEAL TO WALK-IN REFRIGERATOR IS ALL TORN AND MOLDY, SEAL NEEDS TO BE REPLACED

BECKY SAENZ - 882-3507 (K-3 CAFETERIA)

Alma Terrell

37450	Original Main	Classroom			8/27/2008		68		\$0.00
Medium	Work In Progress	201			8/27/2008 12:39:44 PM				

Lozoya, Manny Need an additional key.....

Loraine Gandara

37451	Original Main	Classroom			8/27/2008		68		\$0.00
Medium	Work In Progress	201			8/27/2008 12:40:05 PM				

Lozoya, Manny Need an additional key.....

Loraine Gandara

37452	Original Main	Classroom			8/27/2008		68		\$0.00
Medium	Work In Progress	202			8/27/2008 12:41:04 PM				

Lozoya, Manny Need an additional key.....

Loraine Gandara

37521	Cafeteria	Cafeteria			8/29/2008		66		\$0.00
Medium	Work In Progress				8/29/2008 8:39:59 AM				

Gonzalez, Salvador (ANTHONY ELEMENTARY K-1 - OLD CAFETERIA)
TWO EXIT DOORS NEED TO HAVE WIDER RAMPS.
COMPLAINT OF FALLING CARTS WITH FOOD.
PLEASE HELP.

TERRY PORTILLO - SNP MANAGER 885-3507

Alma Terrell

37525	Annex Building	Classroom			8/29/2008		66		\$0.00
Medium	Work In Progress				8/29/2008 10:42:03 AM				

Villalobos, Hector Damage to a/c vent in room 206.
(Case# 08-08052) D. Allen #133

David Vega

37942					9/9/2008		55		\$0.00
Medium	Work In Progress				9/9/2008 10:36:36 AM				

Lozoya, Manny NEED 2 ADDITIONAL "H" KEY.....

Loraine Gandara

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Anthony ES

37962	Original Main				9/9/2008		55		\$0.00
Medium	Work In Progress	110		9/9/2008 2:44:04 PM					
Lozoya, Manny		NEED AN ADDITIONAL KEY FOR RM 110 KEY H11							
Loraine Gandara									
37994	Original Main	Office			9/10/2008		54		\$0.00
Medium	Work In Progress			9/10/2008 2:17:01 PM					
Gonzalez, Salvador		old main bld room 112 p.t.o needs window gurad							
Hector Villalobos									
38031	Original Main				9/11/2008		53		\$0.00
Medium	Work In Progress	POA OFFICE		9/11/2008 3:06:22 PM					
Lozoya, Manny		NEED A LOCK AND KEY FOR CABINETS.....							
Loraine Gandara									
38157	Original Main	Hallway/Corridor			9/17/2008		47		\$0.00
Medium	Work In Progress			9/17/2008 7:36:41 AM					
Lozoya, Manny		old main blg exit door hallway pannic bar will not lock .replace with new pannic bar. A.S.A.P							
Hector Villalobos									
38270					9/19/2008		45		\$0.00
Medium	Work In Progress	Corina		9/19/2008 4:08:26 PM					
Lozoya, Manny		Please install new locks on 2 file cabinets Tag# F00742 and the other one doesn't have a label. In Corina Valdespino's officce she is at the Village							
Lucia Almeraz									
38320	Main Building	Library			9/22/2008		42		\$0.00
Medium	Work In Progress			9/22/2008 2:54:34 PM					
Carrasco, Danny		need 5 boxes of u-bent fluorescent lamps. for library							
Hector Villalobos									
38494	Cafeteria	Cafeteria			9/29/2008		35		\$0.00
Medium	Work In Progress			9/29/2008 10:44:41 AM					
Orozco, Danny		AE K-2 CAMPUS - TIMERS ON BOTH OVENS ARE NOT WORKING.							
		TERRY PORTILLO - SNP MANAGER 882-3507							
Jacqueline Aguilar									
38783					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:04 AM					
Orozco, Danny		Monthly - Anthony ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
38839					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:25 AM					
Villalobos, Hector		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
11/3/2008 3:24:38 PM									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
38840					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:25 AM				
Villalobos, Hector		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
38841					10/5/2008	10/11/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:26 AM				
Villalobos, Hector		Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
38842					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:26 AM				
Villalobos, Hector		Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
38843					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:26 AM				
Villalobos, Hector		Yearly - Anthony ES H6 (Furnace Gas)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
38844					10/5/2008	10/21/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:27 AM				
Villalobos, Hector		Monthly - Anthony ES A3(Rooftop Unit)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
38845					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:27 AM				
Villalobos, Hector		Monthly - Anthony ES H11 (Elect.Heat)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
38846					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:27 AM				
Villalobos, Hector		Yearly - Anthony ES U2 (Gas Heat)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
38847					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:28 AM				
Villalobos, Hector		Monthly - Anthony ES C12(Chemical Feeder)(Monthly) - Refer to PM schedule details.							
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
38848					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:28 AM					
Villalobos, Hector		Yearly - Anthony ES I4 (Fan Coil)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
38849					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:28 AM					
Villalobos, Hector		Monthly - Anthony ES A16 (Fan Exhst.)(Semi. Ann.) - Refer to PM schedule details.							
Margret Villalobos									
38945					10/6/2008	10/27/2008	28		\$0.00
Medium	Work In Progress			10/6/2008 12:22:36 AM					
Villalobos, Hector		Monthly - PM Schedule created on 9/9/2008 - Refer to PM schedule details.							
Margret Villalobos									
38951					10/6/2008		28		\$0.00
Medium	Work In Progress			10/6/2008 7:37:11 AM					
Appelzoller, Fred		upper primary room 309 need to replace bathroom sink faucet							
Hector Villalobos									
39028					10/8/2008		26		\$0.00
Medium	Work In Progress			10/8/2008 10:07:55 AM					
Appelzoller, Fred		Outside water fountains mounted on concrete block columns located east of the Old Main Cafeteria are not working. REPAIR							
Alfredo Holguin									
39071	Main Building				10/9/2008		25		\$0.00
Medium	Work In Progress			10/9/2008 1:23:45 PM					
Appelzoller, Fred		Old Main Bldg RR - Demo and remodel restrooms as per conversation w/Mike (infested w/roaches).							
Michael Munoz									
39072	Main Building				10/9/2008		25		\$0.00
Medium	Work In Progress			10/9/2008 1:24:38 PM					
Miranda, Danny		Old Main Bldg RR - Demo and remodel restrooms as per conversation w/Mike (infested w/roaches).							
Michael Munoz									
39147					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress			10/12/2008 12:20:57					
Villalobos, Hector		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

39163					10/12/2008	10/28/2008	22		\$0.00
-------	--	--	--	--	------------	------------	----	--	--------

Medium	Work In Progress				10/12/2008 12:21:05				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, Hector Monthly - Anthony ES A4 (Rooftop Unit)(S.Annual) - Refer to PM schedule details.

Margret Villalobos

39165					10/13/2008	10/19/2008	21		\$0.00
-------	--	--	--	--	------------	------------	----	--	--------

Medium	Work In Progress				10/13/2008 12:20:24				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, Hector Monthly - Anthony ES A7 (Rooftop Unit)(Monthly) - Refer to PM schedule details.

Margret Villalobos

39172	Chapter I	Classroom			10/13/2008		21		\$0.00
-------	-----------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/13/2008 9:04:29 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Chapter blg music room needs deadbolts on two doors

Hector Villalobos

39238					10/14/2008		20		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/14/2008 3:47:09 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Hector NEED TO PAINT, TILE, AND PUT COVE BASE IN RESTROOM'S AT DRUG FREE

Hector Villalobos

39407					10/23/2008		11		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/23/2008 8:36:43 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Gonzales, Angel truck 153 thermostat is not working on heater

Hector Villalobos

39498	Cafeteria	Cafeteria			10/27/2008		7		\$0.00
-------	-----------	-----------	--	--	------------	--	---	--	--------

Medium	Work In Progress				10/27/2008 8:42:25 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny BACK DOOR NEEDS A DOOR SWEEP - THEY FOUND A MOUSE

TERRY PORTILLO - (TEMPORARILY AT AE-K2)
SNP MANAGER 882-3507

Alma Terrell

39499	Cafeteria	Cafeteria			10/27/2008		7		\$0.00
-------	-----------	-----------	--	--	------------	--	---	--	--------

Medium	Work In Progress				10/27/2008 8:43:46 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, Margret THEY HAVE A MOUSE PROBLEM - PLEASE CALL PEST CONTROL. THANK YOU

TERRY PORTILLO - (TEMPORARILY AT AE K-2)
SNP MANAGER 882-3507

Alma Terrell

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Anthony ES

39507	Main Building	Parking Lot			10/27/2008		7		\$0.00
Medium	Work In Progress				10/27/2008 10:31:47				

Arreola, Rudy
could you please support w/ the cutting of the weeds and spraying in the parking lot on the corner of 4th and church. if a schedule adjustment needs to be done please let me know ./
Thanks

Michael Munoz

39571	Cafeteria	Cafeteria			10/29/2008		5		\$0.00
High	Work In Progress				10/29/2008 10:29:22				

Orozco, Danny
old cafeteria, please demo the restroom walls as per our conversation.

Michael Munoz

39572	Cafeteria	Cafeteria			10/29/2008		5		\$0.00
Medium	Work In Progress				10/29/2008 10:31:06				

Orozco, Danny
please demo cafeteria walls as per our converstaion. old main cafeteria.
thxs

Michael Munoz

39592					10/30/2008		4		\$0.00
Medium	Work In Progress				10/30/2008 7:34:13 AM				

Lozoya, Manny
old cafeteria gate and drug free gate need a pad lock
H1

Hector Villalobos

39682					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:31 AM				

Villalobos, Hector
Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

39702					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:38 AM				

Villalobos, Hector
Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

39704					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:39 AM				

Villalobos, Hector
Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

39763	Cafeteria	Cafeteria			11/3/2008		0		\$0.00
Medium	Work In Progress				11/3/2008 7:58:06 AM				

Orozco, Danny
WATER LEAK BOTTOM OF SINK

Alma Terrell
CUCA PEREZ - SNP MANAGER 882-5607

11/3/2008 3:24:38 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

Count: 57 Work Orders Avg. Age of WO's 41 Total for Anthony ES 0 \$0.00

Location: Berino ES

35579 7/6/2008 7/27/2008 120 \$0.00

Medium Work In Progress 7/6/2008 12:19:29 AM

Orozco, Danny Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

35696 7/6/2008 8/6/2008 120 \$0.00

Medium Work In Progress 7/6/2008 12:20:06 AM

Villalobos, David Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

35767 7/7/2008 119 \$0.00

High Work In Progress 7/8/2008 3:20:01 PM

Duran, Adan Tag graffiti all over campus.
Dep. LGarcia 114 Case# 2008-06493

Jimmy Cortez

35915 7/13/2008 7/29/2008 113 \$0.00

Medium Work In Progress 7/13/2008 12:18:09 AM

Duran, Adan Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.

Margret Villalobos

36296 7/28/2008 98 \$0.00

Medium Work In Progress 7/28/2008 3:37:40 PM

Lozoya, Manny MR MANNY LOZOYA SIR IN PORTABLE 148 THE FILE CABINET GOT LOCK BY MASTAKE AND THEY DONT HAVE A KEY NEED TO REMOVE CYLINDER AND REPLACE WITH NEW ONE THAT HAS A KEY THANK YOU SIR AND GOD BLESS

Adan Duran

36707 8/6/2008 89 \$0.00

Medium Work In Progress 8/6/2008 3:31:30 PM

Ontiveros, Guadalupe MR LUPE ONTIVEROS SIR WE HAVE ABOUT 8 GALVNIZE PIPES 21 FT LOG THAT NEED TO BE PICKED UP AND HAUL OFF TO PPD YARD ALSO BIG BLOCKS OF CONCRETE THANK YOU SIR AND GOD BLESS

Adan Duran

36845 8/8/2008 87 \$0.00

Medium Work In Progress Mobile Home 8/8/2008 3:52:51 PM

Sotelo, Enrique Need to install utility hook-up for mobile home.
Michael Munoz

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

36850					8/10/2008	8/26/2008	85		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				8/10/2008 12:19:42 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Duran, Adan		Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.							
-------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

36879					8/11/2008		84		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/11/2008 9:01:25 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		MR LUPE ONTIVEROS SIR PER MR VALTIERRA HE WOULD LIKE THE SCHOOL CLEAN TO MANNY WEEDS PONDING AREA NEEDS CLEAN IN FRONT AND BACK AROUND PORTABLES ALONE FENCE IN FRONT OUTSIDE AND IN SIDE THANK YOU SIR							
----------------------	--	---	--	--	--	--	--	--	--

Adan Duran

37210					8/19/2008		76		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/19/2008 3:32:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo		MR LORENZO SOLIS SIR PORTABLE 139 HAS TWO AC WINDOW TYPE THE CLAM IS THAT ITS NOT COOLING ENOUGH IT USE TO BE MUSIC ROOM BUT ITS A CLASS ROOM NOW WOULD LIKE A BIGGER UNIT THANK YOU SIR AND GOD BLESS							
----------------	--	--	--	--	--	--	--	--	--

Adan Duran

37769		Portables			9/4/2008		60		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/4/2008 8:09:26 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Sotelo, Enrique		Please provide electrical connection to 3 Ton Bard unit.							
-----------------	--	--	--	--	--	--	--	--	--

Lorenzo Solis

37866					9/7/2008	9/23/2008	57		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				9/7/2008 12:27:28 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Duran, Adan		Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.							
-------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

38004					9/10/2008		54		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/10/2008 3:33:58 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		MR MANNY LOZOYA SIR WE ARE HAVE PROBLEMS WITH DOOR PORTABLE 135 OLD DOOR WILL NEED SOME HAREWARE WILL NOT LOCK KEEPS BLOWING OPEN WHEN WINDY THANK YOU SIR GOD BLESS							
---------------	--	--	--	--	--	--	--	--	--

Adan Duran

38128					9/16/2008		48		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/16/2008 10:30:21 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique		Emer. Light need replacing at west entrance and Custodial room.							
-----------------	--	---	--	--	--	--	--	--	--

Adan Duran

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

38159					9/17/2008		47		\$0.00
Medium	Work In Progress				9/17/2008 7:52:03 AM				
Lozoya, Manny	MR MANNY LOZOYA SIR WE NEED TO CHANGE OUTSIDE GATE PAD LOCKS SOMEONE IS OPENING OUR GATES CHANGE LOCKS AS SAME AS ENTRANCE DOOR THANK YOU SIR								
Adan Duran									
38442	Main Building				9/25/2008		39		\$0.00
Medium	Work In Progress				9/25/2008 3:59:37 PM				
Duran, Adan	Restrooms nest to multipurpose room- sand entrance doors and reseal								
Alfredo Holguin									
38444		Portables			9/25/2008		39		\$0.00
Medium	Work In Progress				9/25/2008 4:06:10 PM				
Duran, Adan	Last two Portables on south row east side - re-install blocks under beams.								
Alfredo Holguin									
38502					9/29/2008		35		\$0.00
Medium	Work In Progress	Mobile Home			9/29/2008 1:34:42 PM				
Duran, Adan	Need to remove fence on October 4, 2008 1st thing in the morning.								
Michael Munoz									
38529					9/30/2008		34		\$0.00
Medium	Work In Progress				9/30/2008 12:25:59 AM				
Duran, Adan	Monthly - Berino ES A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
38699					10/3/2008		31		\$0.00
Medium	Work In Progress	Mobile Home			10/3/2008 10:42:41 AM				
Lozoya, Manny	As per Alfredo, need a gate key for Guadalupe Quinones the new mobile home occupant at Berino. The mobile home will be placed at the school this weekend.								
Alfredo Holguin									
38737					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:23:47 AM				
Duran, Adan	Yearly - Berino ES I4 (Fan Coil)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
38738					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:23:48 AM				
Duran, Adan	Yearly - Berino ES R9 (Radiator Hot)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
11/3/2008 3:24:38 PM									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

38739					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:23:48 AM					
Duran, Adan	Yearly - Berino ES H6 (Furnace Gas)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
38740					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:23:48 AM					
Duran, Adan	Yearly - Berino ES U2 (Heat Gas)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
38778					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:02 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
38784					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:04 AM					
Orozco, Danny	Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
39057					10/9/2008		25		\$0.00
Medium	Work In Progress			10/9/2008 8:25:00 AM					
Munoz, Michael	need to repair fence @ mobile home occupant, and install 2 additional gates. please use double gates that are currently there.								
Alfredo Holguin									
39148					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress			10/12/2008 12:20:57					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
39168					10/13/2008		21		\$0.00
Medium	Work In Progress			10/13/2008 8:14:11 AM					
Appelzoller, Fred	MR FRED APPELZOLLER SIR MR VALTIERRA WOULD LIKE FOR YOU TO COME BY AND CHECK PORTABLE BATHROOM PORTABLE 143-144 BAD SMELL COMING IN THANK YOU SIR AND GOD BLESS								
Adan Duran									
39479					10/24/2008		10		\$0.00
Medium	Work In Progress			10/24/2008 3:26:04 PM					
Sotelo, Enrique	MR ENRIQUE SOTELO SIR EMERGENCY LIGHT FALL OFF WALL IN CAFETERIA NEED TO REPLACE BROKEN BURN ELEMENTS THE ONE IN CUSTODIAL ROOM ALSO THANK YOU SIR								
Adan Duran									
11/3/2008 3:24:38 PM									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

39480					10/24/2008		10		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress			10/24/2008 3:30:05 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Sotelo, Enrique
MR ENRIQUE SOTLEO SIR SOME OF THE OUTSIDE LIGHTS STAY ON TO LONG PORTABLE 143 AND 144 AND 154 COULD YOU CHECK PLEASE THANK YOU SIR

Adan Duran

39500		Cafeteria			10/27/2008		7		\$0.00
-------	--	-----------	--	--	------------	--	---	--	--------

Medium	Work In Progress			10/27/2008 10:00:34					
--------	------------------	--	--	---------------------	--	--	--	--	--

Orozco, Danny
WALK-IN REFRIG. TEMP. IS AT 40.

ELSA ORTEGA SNP MGR 882-2417

Jacqueline Aguilar

39574					10/29/2008		5		\$0.00
-------	--	--	--	--	------------	--	---	--	--------

Medium	Work In Progress			10/29/2008 11:23:56					
--------	------------------	--	--	---------------------	--	--	--	--	--

Carbajal, Jimmy
VACCUM NOT WORKING MOTOR

Jimmy Cortez

39634					10/30/2008		4		\$0.00
-------	--	--	--	--	------------	--	---	--	--------

Medium	Work In Progress			10/30/2008 3:37:39 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Solis, Lorenzo
MR LORENZO SOLIS SIR THE EXHAUST FAN IN THE BOYS RESTROOM IS BURN OUT NEED TO REPLACE ALSO NEED TO INSTALLED ONE IN THE WOMEN RESTROOM BAD SMELL WILL NEED TO RUN SOME WIRE THANK YOU SIR AND GOD BLESS

Adan Duran

39683					11/2/2008	11/8/2008	1		\$0.00
-------	--	--	--	--	-----------	-----------	---	--	--------

Medium	Work In Progress			11/2/2008 12:24:31 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Duran, Adan
Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.

Margret Villalobos

39703					11/2/2008	11/10/2008	1		\$0.00
-------	--	--	--	--	-----------	------------	---	--	--------

Medium	Work In Progress			11/2/2008 12:24:39 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Duran, Adan
Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

39706					11/2/2008	11/10/2008	1		\$0.00
-------	--	--	--	--	-----------	------------	---	--	--------

Medium	Work In Progress			11/2/2008 12:24:40 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Duran, Adan
Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

39765					11/3/2008		0		\$0.00
Medium	Work In Progress				11/3/2008 8:28:09 AM				
Munoz, Michael	Need to have fencing contractor install a 6ft high chain link fence around irrigation well to protect piping, fittings & electrical box from being vandalized. Dimension for the fence is 10ft wide by 10ft long with a walk-in gate.								
	Thanks, Raul								

Raul Sanchez

39773		Cafeteria			11/3/2008		0		\$0.00
Medium	Work In Progress				11/3/2008 10:00:56 AM				
Orozco, Danny	WALK IN REFRIG. TEMP IS GOING ABOVE 40.								
	ELSA ORTEGA - 882-2417								

Jacqueline Aguilar

Count: 39 Work Orders			Avg. Age of WO's 44				Total for Berino ES	0	\$0.00
------------------------------	--	--	----------------------------	--	--	--	----------------------------	----------	---------------

Location: Chaparral ES

37057					8/14/2008		81		\$0.00
Medium	Work In Progress				8/14/2008 10:17:19 AM				
Vargas, Juan	Sand need to be leveled in fall areas of all playground structures on site.								

Alfredo Holguin

35586					7/6/2008	7/27/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:32 AM				
Orozco, Danny	Monthly - Chaparral ES Range Hood Cleaning - Refer to PM schedule details.								

Margret Villalobos

35694					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:05 AM				
Villalobos, David	Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.								

Margret Villalobos

35944		Classroom			7/14/2008		112		\$0.00
Medium	Work In Progress	506			7/14/2008 10:05:07 AM				
Estrada, Jesus	carpet needs to be removed from this classroom and linoleum was going to be installed. Work order is for Jesus Estrada per Administrators and Mike Munoz request. Please call school if you have any questions speak to Ms. Beckford, Ms. Ballard, or Mr. Gardea							AS OF 7/14/08 - OH HOLD PER CHUY	

Jennifer Corral

36075		Office			7/18/2008		108		\$0.00
Medium	Work In Progress	PRE-K			7/18/2008 4:55:16 PM				
Vargas, Juan	AS PER ANN STEINHOFF-THERE IS MOLD ON THE CEILING IN THE WORK ROOM AT THE PRE-K								

Mary Garcia

11/3/2008 3:24:39 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
36214		Classroom			7/25/2008		101		\$0.00
Medium	Work In Progress			7/25/2008 10:15:35 AM					
Lozoya, Manny		need, to, check, all, doors, locks, keys, do, not, open, doors, locks.							
Daniel Ramirez									
36314					7/29/2008		97		\$0.00
Medium	Work In Progress	Room#208-		7/29/2008 10:16:15 AM					
Lozoya, Manny		Please install new locks to file cabinet -social worker will leave a sticky on the file cabinet							
Lucia Almeraz									
36581					8/4/2008		91		\$0.00
Medium	Work In Progress			8/4/2008 8:49:37 AM					
Vargas, Juan		barracas 406-408-410-412-414-416-418 need change master cools now have 3800 is to small need replace for 4500				Routed 8/11 - Assign to JC asp our conversation he needs to give units a good PM, where installed last year. Humidity is @ 70 and m/c swamps do not work well. m.munoz			
Juan Vargas									
36675		Office			8/6/2008		89		\$0.00
Medium	Work In Progress			8/6/2008 9:42:24 AM					
Lozoya, Manny		need, to, fix, door, lock, mrs, baderd, officef							
Daniel Ramirez									
36737		Office			8/7/2008		88		\$0.00
Medium	Work In Progress	front office		8/7/2008 7:51:44 AM					
Lozoya, Manny		secretary's door locks and can't open, need door to be able to lock only when used with the key stays locked and when there is a fire drill door needs to be closed but not locked and locks automatically. Administrative Intern's room also having trouble with lock door cannot open very hard custodians are having a difficult time opening. Please see front office							
Jennifer Corral									
36738					8/7/2008		88		\$0.00
Medium	Work In Progress			8/7/2008 7:59:01 AM					
Lozoya, Manny		chuy y mando nesecitan que les cambies las llaves por que batallan para abrir las puertas							
Juan Vargas									
36764		Cafeteria			8/7/2008		88		\$0.00
Medium	Work In Progress			8/7/2008 10:43:19 AM					
Orozco, Danny		MILK COOLER IS OUT OF ORDER							
		ESTHER CISNEROS - SNP MANAGER 824-0048							
Alma Terrell									
36773					8/7/2008		88		\$0.00
Medium	Work In Progress			8/7/2008 1:07:27 PM					
Ontiveros, Joe		kitchen r.room need replace toilet is broke							
Juan Vargas									
11/3/2008 3:24:39 PM									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral ES

37005		Classroom			8/13/2008		82		\$0.00	
Medium	Work In Progress	whole school		8/13/2008 10:45:16 AM						
Lozoya, Manny		work order to redo keys for custodians, can't open the doors to the classrooms. As per Manny Request.								
Jennifer Corral										
37055	2001 Classroom				8/14/2008		81		\$0.00	
Medium	Work In Progress			8/14/2008 10:11:15 AM						
Vargas, Juan		need to add large rocks or cobblestones in areas where roof gutters are causing erosion								
Alfredo Holguin										
37056					8/14/2008		81		\$0.00	
Medium	Work In Progress			8/14/2008 10:14:39 AM						
Vargas, Juan		All sidewalks with more than 4" drop need to have fill dirt added - Call Mike or Alfredo when work is complete								
Alfredo Holguin										
37135	West Central				8/18/2008		77		\$0.00	
Medium	Work In Progress			8/18/2008 9:11:53 AM						
Vargas, Juan		new doors are being installed in the esat and west barrack. please order paint so you can paint doors. thxs								
Michael Munoz										
37222		Custodial			8/20/2008		75		\$0.00	
Medium	Work In Progress	master		8/20/2008 9:40:22 AM						
Lozoya, Manny		need another key to be done for substitute custodian. One of the keys did not open the doors. Please see Danny head custodian for more explanation								
Jennifer Corral										
37226		Classroom			8/20/2008		75		\$0.00	
Medium	Work In Progress	103		8/20/2008 1:04:04 PM						
Sotelo, Enrique		need electrical setup to plug in computers and maybe move some to another location in the room. See Ms. Aguayo/Gary or Portillo								
Jennifer Corral										
37990		Cafeteria			9/10/2008		54		\$0.00	
Medium	Work In Progress			9/10/2008 1:49:03 PM						
Orozco, Danny		Side of grease trap caving in.								
Michael Munoz										
37993					9/10/2008		54		\$0.00	
Medium	Work In Progress			9/10/2008 2:16:48 PM						
Lozoya, Manny		Monday, September 15, 2008 @ 10:00, need to inventory J. Vargas keys to be transferred to Guillermo Hernandez.								
Michael Munoz										

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

38027		Athletic Field			9/11/2008		53		\$0.00
Medium	Work In Progress				9/11/2008 2:05:24 PM				
Ontiveros, Guadalupe		Lower Grades playground equipment located between classroom wings - Re layout plastic borders so they are around the remaining playground (slide) structure.							
Alfredo Holguin									
38240					9/18/2008		46		\$0.00
Medium	Work In Progress				9/18/2008 3:45:24 PM				
Lozoya, Manny		Would you please issue a key for me to use on the gate next to Chap Midd, they use the gate for the fire drill and the keys that I got dont have one. thank you							
Guillermo Hernandez									
38696					10/3/2008		31		\$0.00
Medium	Work In Progress				10/3/2008 9:01:13 AM				
Ontiveros, Joe		Would you please check the sink in the teachers lounche and Library, sinks are backing up. thank you							
Guillermo Hernandez									
38785					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:05 AM				
Orozco, Danny		Monthly - Chaparral ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
38831					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:22 AM				
Hernandez, Guillermo		Yearly - Chaparral ES H-6 Furnance Gas (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
38925					10/5/2008		29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:56 AM				
Jacquez, Ricardo		Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.							
Margret Villalobos									
39149					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress				10/12/2008 12:20:58				
Hernandez, Guillermo		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
39641					10/31/2008		3		\$0.00
Medium	Work In Progress				10/31/2008 12:27:35				
Jacquez, Ricardo		Monthly - Chaparral ES DP-91 - Refer to PM schedule details.							
Margret Villalobos									

11/3/2008 3:24:39 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

39649					10/31/2008		3		\$0.00
Medium	Work In Progress				10/31/2008 11:33:30				
Holguin, Alfredo		Purchase and install playground equipment and metal shade structures							
Alfredo Holguin									
39684					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:31 AM				
Hernandez, Guillermo		Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
39705					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:40 AM				
Hernandez, Guillermo		Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39745					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:54 AM				
Hernandez, Guillermo		Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39746					11/2/2008		1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:55 AM				
Jacquez, Ricardo		Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.							
Margret Villalobos									
39770					11/3/2008		0		\$0.00
Medium	Work In Progress				11/3/2008 9:53:57 AM				
Sotelo, Enrique		Need to replace out side lights :front parking lot,side of main building and front of portable 1 through portable 2.							
Guillermo Hernandez									
Count: 35 Work Orders			Avg. Age of WO's 60			Total for Chaparral ES	0		\$0.00

Location: Chaparral HS

35714					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:12 AM				
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
35869					7/11/2008		115		\$0.00
Medium	Work In Progress				7/11/2008 9:39:33 AM				
Lozoya, Manny		RE-KEY LEFT UPPER AND LOWER CABINETS FOR STORAGE LOCATED BEHIND THE RECEIPTIONST FOR THE REGISTRAR (HEMPHILL)							
Rosa Quezada									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

35870		Office			7/11/2008		115		\$0.00
Medium	Work In Progress	FRONT OFFICE			7/11/2008 9:41:05 AM				
Lozoya, Manny		RE-KEY RIGHT UPPER AND LOWER CABINETS FOR STORAGE LOCATED BEHIND THE RECEPTIONIST (GARCIA)							
Rosa Quezada									
35970		Mobile Home			7/15/2008		111		\$0.00
Medium	Work In Progress				7/15/2008 2:56:29 PM				
Ontiveros, Joe		SEPTIC AND WATER SYSTEMS NEED TO BE TIED IN FOR AN ON SITE MOBILE HOME.							
Eddie Baeza									
36093		Classroom			7/21/2008		105		\$0.00
Medium	Work In Progress	D-7			7/21/2008 3:47:12 PM				
Lozoya, Manny		NEED 1G032 SPARE KEY FOR FLAMABLE CABINET IN D-7(QUEZADA)							
Rosa Quezada									
36565					8/3/2008		92		\$0.00
Medium	Work In Progress				8/3/2008 12:20:34 AM				
Baeza, Eddie		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
36566					8/3/2008		92		\$0.00
Medium	Work In Progress				8/3/2008 12:20:34 AM				
Baeza, Eddie		Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
36567					8/3/2008		92		\$0.00
Medium	Work In Progress				8/3/2008 12:20:35 AM				
Baeza, Eddie		Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
36569					8/3/2008	9/3/2008	92		\$0.00
Medium	Work In Progress				8/3/2008 12:20:35 AM				
Baeza, Eddie		Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
36579		Classroom			8/4/2008		91		\$0.00
Medium	Work In Progress	F Wing - Rm. 5			8/4/2008 8:18:45 AM				
Lozoya, Manny		Need a CH73 key for classroom F-5. (Paul H. Geiger)							
Guadalupe Gonzalez									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral HS

36593		Classroom			8/4/2008		91		\$0.00
Medium	Work In Progress	R Wing - Rm. 1			8/4/2008 1:55:06 PM				
Lozoya, Manny		Due to high security requirements, the control room door key must be cored the same as the storage room door. It is to be "off master" like the storage room.							
<u>Guadalupe Gonzalez</u>									
36606	B-Wing	Classroom			8/4/2008		91		\$0.00
Medium	Work In Progress	Rm B-3			8/4/2008 3:13:25 PM				
Lozoya, Manny		Need keys D274AR & D273AR. (Emmanuel Okefor)							
<u>Guadalupe Gonzalez</u>									
36888					8/11/2008		84		\$0.00
Medium	Work In Progress				8/11/2008 1:32:00 PM				
Ontiveros, Joe		FAUCETS IN D-WING SCIENCE LABS NEED REPAIR AND REPLACEMENT.							
<u>Eddie Baeza</u>									
36959	A-Wing	Office			8/12/2008		83		\$0.00
Medium	Work In Progress				8/12/2008 3:11:57 PM				
Lozoya, Manny		Need to re-key mailroom to fit GM3 key.							
<u>Guadalupe Gonzalez</u>									
37177					8/19/2008		76		\$0.00
Medium	Work In Progress	Concession			8/19/2008 7:55:32 AM				
Lozoya, Manny		Need key to concession stand. (Mr. Sanchez)							
<u>Guadalupe Gonzalez</u>									
37220					8/20/2008		75		\$0.00
Medium	Work In Progress				8/20/2008 8:34:48 AM				
Lozoya, Manny		Need a CH73 key for classroom for F Wing - Rm. 5. (Paul H. Geiger)							
<u>Guadalupe Gonzalez</u>									
37394		Classroom			8/26/2008		69		\$0.00
Medium	Work In Progress	Nurse			8/26/2008 11:42:37 AM				
Lozoya, Manny		Need keys CH6 for Nurse's office and CH5 for the storage room in the Health Center. (Ana Castro)							
<u>Guadalupe Gonzalez</u>									
37432					8/27/2008		68		\$0.00
Medium	Work In Progress				8/27/2008 8:12:23 AM				
Gonzalez, Salvador		WELD GOOSENECK TO FOOTBALL GOAL POST.							
<u>Guadalupe Ontiveros</u>									
37528					8/29/2008		66		\$0.00
Medium	Work In Progress				8/29/2008 12:34:48 PM				
Sotelo, Enrique		THERE ARE 7 EXTERIOR POLE LIGHTS OUT AT PARKING LOTS							
<u>Eddie Baeza</u>									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

37560					8/31/2008	9/21/2008	64		\$0.00
Medium	Work In Progress				8/31/2008 12:25:17 AM				
Orozco, Danny		Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
37561					8/31/2008	9/21/2008	64		\$0.00
Medium	Work In Progress				8/31/2008 12:25:17 AM				
Orozco, Danny		Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
37783					9/4/2008		60		\$0.00
Medium	Work In Progress				9/4/2008 10:52:49 AM				
Lozoya, Manny		(65) LATCH PROTECTORS ARE REQUESTED FOR CLASS RMS AND OFFICE DOORS							
Eddie Baeza									
37893					9/8/2008		56		\$0.00
Medium	Work In Progress	q-4			9/8/2008 10:21:54 AM				
Lozoya, Manny		need a CH-1 for auto construction labs.							
Rosa Quezada									
38072					9/14/2008		50		\$0.00
Medium	Work In Progress				9/14/2008 12:23:08 AM				
Ontiveros, Guadalupe		Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.							
Margret Villalobos									
38306					9/22/2008		42		\$0.00
Medium	Work In Progress				9/22/2008 12:32:55 PM				
Gonzales, Angel		THE BOBCAT IS REQUESTED FOR THE CLEANING BETWEEN THE WINGS				9/24 - Asp Lupe route to Angel			
Eddie Baeza									
38307		Classroom			9/22/2008		42		\$0.00
Medium	Work In Progress	Q-7			9/22/2008 1:13:03 PM				
Lozoya, Manny		NEED CH-94 (2) FOR Q-2 FOR LAB AND CAGES ONE & TWO NEED CH-96 (2) FOR Q-6 FOR LAB AND CAGE KEYS (FOR PETE GALVAN)							
Rosa Quezada									
38324					9/22/2008		42		\$0.00
Medium	Work In Progress				9/22/2008 3:28:35 PM				
Lozoya, Manny		THERE ARE SEVERAL PANIC BARS AND LOCK-SETS THAT ARE NOT WORKING PROPERLY ON CAMPUS.							
Eddie Baeza									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral HS

38532					9/30/2008		34		\$0.00
Medium	Work In Progress			9/30/2008 12:26:00 AM					
Baeza, Eddie	Monthly - Chaparral HS A16 (Fan Exhst.)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
38577					9/30/2008		34		\$0.00
Medium	Work In Progress			9/30/2008 3:53:50 PM					
Lozoya, Manny	CHANGE THE LOCK ON THE TRAINERS ROOM OFF OF CH-86								
Eddie Baeza									
38578					9/30/2008		34		\$0.00
Medium	Work In Progress			9/30/2008 3:56:13 PM					
Lozoya, Manny	(4) DOORS IN THE LOCKER ROOMS NEED TO BE DOUBLE KEYED. (4) DOORS NEED TO BE CHANGED TO LATCH FOR SAFETY AND SECURITY REASONS								
Eddie Baeza									
38742					10/5/2008		29		\$0.00
Medium	Work In Progress			10/5/2008 12:23:49 AM					
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.		10/6/08 - Emailed to Ricky Borrego						
Margret Villalobos									
38812					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:15 AM					
Baeza, Eddie	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
38813					10/5/2008		29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:15 AM					
Baeza, Eddie	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
38814					10/5/2008		29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:15 AM					
Baeza, Eddie	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
38815					10/5/2008		29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:16 AM					
Baeza, Eddie	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
38816					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:16 AM				
Baeza, Eddie		Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
38817					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:16 AM				
Baeza, Eddie		Monthly - Chaparral HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
38818					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:17 AM				
Baeza, Eddie		Yearly - Chaparral HS H6 (Furnace)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
38819					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:17 AM				
Baeza, Eddie		Yearly - Chaparral HS U2 (G.Heater)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
38953		Office			10/6/2008		28		\$0.00
Medium	Work In Progress				10/6/2008 9:28:13 AM				
Solis, Lorenzo		air ducts need to be cleaned. Lots of dust coming in.							
Michael Munoz									
38989					10/7/2008		27		\$0.00
Medium	Work In Progress				10/7/2008 8:47:09 AM				
Lozoya, Manny		PAD LOCKS AT THE ATHLETIC FEILDS NEED TO BE SECURED SO THEY WILL NOT BE LOST.							
Eddie Baeza									
38995					10/7/2008		27		\$0.00
Medium	Work In Progress				10/7/2008 11:12:22 AM				
Lozoya, Manny		Need a Master Key for Trane Company. They will be working during Fall Break. (approved by A. Holguin)							
Alfredo Holguin									
39019					10/7/2008		27		\$0.00
Medium	Work In Progress				10/7/2008 3:55:21 PM				
Lozoya, Manny		Greenhouses attached to building - Change door hardware between building and greenhouse to appropriate type.							
Alfredo Holguin									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
39021		Athletic Field			10/7/2008		27		\$0.00
Medium	Work In Progress				10/7/2008 3:58:09 PM				
Munoz, Michael		Install fencing around lift station with gates as needed for the service.							
Alfredo Holguin									
39096		Cafeteria			10/10/2008		24		\$0.00
Medium	Work In Progress				10/10/2008 11:24:01				
Villalobos, Margret		THEY HAVE A BEE PROBLEM INSIDE THE CAFETERIA - THE LADIES ARE AFRAID OF BEING STUNG				E-Mailed Watson on 10/10/08 Open PO			
		JUANA MONTELONGO - SNP MANAGER 824-4461							
Alma Terrell									
39194					10/13/2008		21		\$0.00
Medium	Work In Progress	workroom Q & R			10/13/2008 3:43:04 PM				
Lozoya, Manny		NEED TO KEY Q & R WING WORKROOMS SO THAT ALL TEACHERS HAVE ACCESS TO COPIER (QUEZADA)							
Rosa Quezada									
39303	A-Wing	Custodial			10/20/2008		14		\$0.00
Medium	Work In Progress				10/20/2008 2:42:25 PM				
Lozoya, Manny		NEED 4 COPIES OF THE TRASH COMPACTOR KEY FOR HEAD CUSTODIAN ARMANDO RIVERA (QUEZADA)							
Rosa Quezada									
39306					10/20/2008		14		\$0.00
Medium	Work In Progress	SOCCER			10/20/2008 2:44:56 PM				
Lozoya, Manny		NEED 3 COPIES OF CH-86 KEYS FOR SOCCER COACHES							
Rosa Quezada									
39328					10/21/2008		13		\$0.00
Medium	Work In Progress				10/21/2008 8:25:53 AM				
Lozoya, Manny		(10) BEST PADLOCKS WITH LONG SHANKS ARE REQUESTED FOR EQUIPMENT IN NEW WEIGHT ROOM.							
Eddie Baeza									
39337					10/21/2008		13		\$0.00
Medium	Work In Progress				10/21/2008 1:12:48 PM				
Lozoya, Manny		WE ARE UNABLE TO OPEN VAULT AT MAIN OFFICE, AND KEY JUST KEEPS TURNING.							
Eddie Baeza									
39363	A-Wing	Classroom			10/22/2008		12		\$0.00
Medium	Work In Progress	storage room			10/22/2008 9:20:35 AM				
Lozoya, Manny		NEED TO CHANGE CORE IN MAIN STORAGE ROOM IN FRONT OFFICE TO FIT TO KEY GM3 (QUEZADA)							
Rosa Quezada									
11/3/2008 3:24:39 PM									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
39393					10/22/2008		12		\$0.00
Medium	Work In Progress			10/22/2008 3:50:18 PM					
Ontiveros, Guadalupe		(4) BATTING CAGES ARE REQUESTED FOR THE BASEBALL FIELDS.							
Eddie Baeza									
39551					10/28/2008		6		\$0.00
Medium	Work In Progress			10/28/2008 3:39:58 PM					
Carrasco, Danny		(10)BALLAST ARE REQUESTED FOR 70 WATT METAL HALIDE BULBS FOR EXTERIOR LIGHTS, AT WINGS.							
Eddie Baeza									
39748					11/2/2008		1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:56 AM					
Baeza, Eddie		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39749					11/2/2008		1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:56 AM					
Baeza, Eddie		Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
39750					11/2/2008		1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:56 AM					
Baeza, Eddie		Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39752					11/2/2008	12/3/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:57 AM					
Baeza, Eddie		Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
39768					11/3/2008		0		\$0.00
Medium	Work In Progress			11/3/2008 9:22:51 AM		11/3/2008			
Quinones, Paul		Asp Mike, please assist at CHS in cutting weeds starting today. Thanks							
Michael Munoz									
39771					11/3/2008		0		\$0.00
Medium	Work In Progress			11/3/2008 9:54:06 AM					
Parra, Juliet		A TRASH DUMPSTER IS REQUESTED FOR THE Q-WING							
Eddie Baeza									
Count: 59 Work Orders		Avg. Age of WO's 47		Total for Chaparral HS			0	\$0.00	

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

35580					7/6/2008	7/27/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:30 AM				
Orozco, Danny		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
35697					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:06 AM				
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36145	Main Building	Classroom			7/23/2008		103		\$0.00
Medium	Work In Progress	Room 207			7/23/2008 11:09:15 AM				
Lozoya, Manny		**URGENT** THIRD REQUEST FOR NEW KEY FOR ROOM 207 OLD KEY BENT AND BROKE							
Elena Palacios									
36315					7/29/2008		97		\$0.00
High	Work In Progress				7/29/2008 10:57:48 AM				
Lozoya, Manny		***URGENT*** NEED KEY LOCKS THAT WERE LOST AND ORDERED ACCORDING TO RAFA AND MANNY BACK IN SEPTEMBER OF 07, LOCKS AND KEYS STILL HAVE NOT BEEN REPLACED IN THEIR ENTIRETY							
Elena Palacios									
36316		Computer Lab			7/29/2008		97		\$0.00
High	Work In Progress	ROOM 207			7/29/2008 11:01:56 AM				
Lozoya, Manny		NEED NEW KEY MADE FOR ROOM 207							
Elena Palacios									
36767	Main Building	Classroom			8/7/2008		88		\$0.00
Medium	Work In Progress	ROOM 201			8/7/2008 12:10:58 PM				
Lozoya, Manny		NEEDS KEYS TO LOCK CABINETS							
Elena Palacios									
37050					8/14/2008		81		\$0.00
Medium	Work In Progress				8/14/2008 8:28:32 AM				
Ontiveros, Joe		need to replace shower columns in boys and girls reast rooms. Thxs							
Marti Muela									
37052		Athletic Field			8/14/2008		81		\$0.00
Medium	Work In Progress				8/14/2008 9:37:16 AM				
Ontiveros, Guadalupe		Purchase and Install new baseball backstop							
Richard Chavez									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

37191					8/19/2008		76		\$0.00
Medium	Work In Progress				8/19/2008 10:54:48 AM				
Lozoya, Manny		eight security window rod irons can not be locked in the 300 & 400 hallway. very easy to break into. those rooms are to the back and can not be seen from the street.							
Robert Gonzalez									
37404	Main Building	Classroom			8/26/2008		69		\$0.00
Medium	Work In Progress	ROOM 406			8/26/2008 3:43:07 PM				
Lozoya, Manny		NEED CABINET LOCKS							
Elena Palacios									
37822	Main Building	Portables			9/5/2008		59		\$0.00
High	Work In Progress	P-9			9/5/2008 9:09:01 AM				
Lozoya, Manny		Social Worker Berenice Holguin needs her file cabinet locked for very confidential paperwork. Her lock was taken by Manny but never replaced.							
Elena Palacios									
37823	Main Building	Classroom			9/5/2008		59		\$0.00
High	Work In Progress	Room 206			9/5/2008 9:10:55 AM				
Lozoya, Manny		Counselor James Wolf needs file cabinet lock back, to secure confidential paperwork. Was taken last year by Manny and not yet replaced.							
Elena Palacios									
37824	Main Building	Classroom			9/5/2008		59		\$0.00
High	Work In Progress	Room 404			9/5/2008 9:14:56 AM				
Lozoya, Manny		NEED CABINETS KEYED FOR MR. MORALES IN ROOM 406							
Elena Palacios									
38127		Gym			9/16/2008		48		\$0.00
Medium	Work In Progress				9/16/2008 10:22:53 AM				
Ronquillo, Ruben		Asp PM 37575 FXT-CHM -017 Need plexiglass cover. FXT-CHM-018 Need plexiglass cover.							
Eric Medina									
38437					9/25/2008		39		\$0.00
Medium	Work In Progress				9/25/2008 3:39:35 PM				
Sotelo, Enrique		need light covers plastic							
Eric Medina									
38633					10/1/2008		33		\$0.00
Medium	Work In Progress				10/1/2008 4:12:11 PM				
Gonzalez, Salvador		need to fix square tubing around 8 windows on the west and north side of building							
Eric Medina									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
38779					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:03 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
38786					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:05 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
39188					10/13/2008		21		\$0.00
Medium	Work In Progress			10/13/2008 3:24:04 PM					
Ronquillo, Ruben	large square glass partition in cafeteria was broken over weekend								
Eric Medina									
39416	Main Building				10/23/2008		11		\$0.00
Medium	Work In Progress			10/23/2008 1:49:20 PM					
Villalobos, Margret	Head Custodian reported a problem with spiders and beetles at this site.		10/23 - Faxed to Watson for quote						
Jesus Estrada									
39496	Main Building	Classroom			10/27/2008		7		\$0.00
Medium	Work In Progress	ROOM 203		10/27/2008 8:38:48 AM					
Lozoya, Manny	NEED EXTRA KEY MADE FOR ROOM 203 KEY 78 THANKS								
Elena Palacios									
39505					10/27/2008		7		\$0.00
Medium	Work In Progress			10/27/2008 10:22:17					
Medina, Eric	as per our conversaton friday. Please cut all weeds around the bldg and school site. The cove behind library is in dire needs of attention.								
Michael Munoz									
39546					10/28/2008		6		\$0.00
Medium	Work In Progress			10/28/2008 3:09:52 PM					
Ontiveros, Joe	Need to unngglove toilet with ball stuck in it								
Eric Medina									
39611					10/30/2008		4		\$0.00
Medium	Work In Progress			10/30/2008 12:30:11					
Lozoya, Manny	room 312 teacher complains door knob is loose								
Eric Medina									
39685					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:32 AM					
Medina, Eric	Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									

11/3/2008 3:24:39 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

39698					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:37 AM				

Medina, Eric Monthly - Chaparral MS Roof Inspection - Refer to PM schedule details.

Margret Villalobos

39707					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:40 AM				

Medina, Eric Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

39709					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:41 AM				

Medina, Eric Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

39751					11/2/2008		1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:57 AM				

Jacquez, Ricardo Monthly - Chaparral MS - DP-781 - Refer to PM schedule details.

Margret Villalobos

39754					11/2/2008	12/3/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:58 AM				

Medina, Eric Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

Count: 30 Work Orders			Avg. Age of WO's 45			Total for Chaparral MS	0		\$0.00
------------------------------	--	--	----------------------------	--	--	-------------------------------	----------	--	---------------

Location: Desert Pride

35839	Storage A	Mechanical Room			7/10/2008		116		\$0.00
Medium	Work In Progress				7/10/2008 12:44:57 PM				

Castillo, Carlos NEED TO MOVE RECEPTACLES LOWER OR INSTALL NEW ONE TO STORAGE ROOM TO PUMP HOUSE (WILL BE USING AS CUSTODIAL OFFICE)

David Acosta

36027					7/17/2008		109		\$0.00
Medium	Work In Progress	MORGAN BLDG.			7/17/2008 11:08:09 AM				

Castillo, Carlos NEED POWER TO RUN HEATING/COOLING & OUTLETS IN MORGAN BLDG.

David Acosta

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Pride							
36356		Classroom			7/30/2008		96		\$0.00
Medium	Work In Progress	11			7/30/2008 12:37:03 PM				
Castillo, Carlos		ONE LIGHT FIXTURE OUT NEED TO REPLACE BALLAST.							
David Acosta									
36451		Classroom			8/1/2008		94		\$0.00
Medium	Work In Progress	14,15			8/1/2008 7:22:52 AM				
Castillo, Carlos		EMER. LIGHT DO NOT TURN ON IN BOTH ROOMS WHEN TURNING OFF BREAKER SWITCH FOR TESTING.							
David Acosta									
36452		Library			8/1/2008		94		\$0.00
Medium	Work In Progress				8/1/2008 7:26:27 AM				
Castillo, Carlos		EMER LIGHT WON'T STAY ON VERY LONG WHEN DOING ANNUAL TEST.							
David Acosta									
37699		Classroom			9/2/2008		62		\$0.00
Medium	Work In Progress	1,2			9/2/2008 2:08:10 PM				
Castillo, Carlos		NEED MORE EMERG. EXIT SIGNS. (ASK BY STATE FIREMARSHAL TO REQUEST).							
David Acosta									
37701		Portables			9/2/2008		62		\$0.00
Medium	Work In Progress	ROOM #16			9/2/2008 2:13:46 PM				
Castillo, Carlos		NEED SECURITY NITE LIGHT FOR LAST PORTABLE.							
David Acosta									
38138					9/16/2008		48		\$0.00
Medium	Work In Progress				9/16/2008 2:14:50 PM				
Gonzalez, Salvador		Need blinds in the barracks.							
Michael Munoz									
38530					9/30/2008		34		\$0.00
Medium	Work In Progress				9/30/2008 12:25:59 AM				
Aguilar, Patricio		Monthly - Desert Pride HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.				Asp Mike route to Pat 10/21/08 - mkv			
Margret Villalobos									
38592		Hallway/Corridor			10/1/2008		33		\$0.00
Medium	Work In Progress	2ND BLDG.			10/1/2008 11:52:55 AM				
Castillo, Carlos		NEED TO INSTALL RECEPTACLE FOR CANDY MACH. WALL AS NO RECEPTACLE							
David Acosta									
38602		Portables			10/1/2008		33		\$0.00
Medium	Work In Progress	ROOM 6			10/1/2008 1:50:14 PM				
Castillo, Carlos		NEED TO CHECK FOR SHORT IN RECEPTACLE BEHIND LARGE BLACK COMPUTER TABLE							
David Acosta									

11/3/2008 3:24:39 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Pride

38605		Classroom			10/1/2008		33		\$0.00
Medium	Work In Progress	room 6			10/1/2008 2:09:21 PM				

Castillo, Carlos
Please send someone to check the electrical on one wall in Mr. Wymans room 6. Victor (tech) states that there may be a short in the wall. Would you please send someone to check.

Mary Telles

38771					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:00 AM				

Aguilar, Patricio
Monthly - Desert Pride HS H11 (E.Heater)(S.Annual) - Asp Mike route to Pat 10/21/08 - mkv
Refer to PM schedule details.

Margret Villalobos

39333		Portables			10/21/2008		13		\$0.00
Medium	Work In Progress	16			10/21/2008 11:07:07				

Castillo, Carlos
NEED EXIT SIGN AND EMER. LIGHT FOR LAST PORTABLE (ROOM 16).

David Acosta

39700					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:38 AM				

Acosta, David
Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

39710					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:42 AM				

Acosta, David
Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

39714					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:43 AM				

Acosta, David
Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

Count: 17 Work Orders			Avg. Age of WO's 51			Total for Desert Pride	0		\$0.00
------------------------------	--	--	----------------------------	--	--	-------------------------------	----------	--	---------------

Location: Desert Trail Intermediate

35581					7/6/2008	7/27/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:30 AM				

Orozco, Danny
Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

35698					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:07 AM				

Villalobos, David
Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

11/3/2008 3:24:39 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail Intermediate

35728					7/7/2008		119		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				7/7/2008 9:25:36 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny Please change core to doorknob in maintenance office to A-32.

Johnny Acuna

35816					7/10/2008		116		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/10/2008 7:55:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben Need an awning installed outdoors on top of the back door to the library. When it rains, water comes through the door wetting the new carpet.

Johnny Acuna

36381					7/30/2008		96		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/30/2008 9:32:01 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Springkler system is down on the westside, it has been uncovered for a couple of weeks. Please advise as to covering the system or will it be fixed before August 1, 2008.
School starts on the 4th.

Ruben Ortiz

36625					8/4/2008		91		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/4/2008 4:14:22 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Jacquez, Ricardo Replace lift station sewage pump.

Ricardo Jacquez

36822					8/8/2008		87		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/8/2008 9:41:58 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny Need 3 key cores to be installed in the new mulliums for the doors.

Johnny Acuna

36823					8/8/2008		87		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/8/2008 9:43:14 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny Need a lock installed in the new filing cabinet to room #398.
Mr. Varela.

Johnny Acuna

36887					8/11/2008		84		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	110			8/11/2008 11:51:39 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lozoya, Manny Marisela front office receptionist needs replacement of lost key for room #110 (J66) and also need one extra (J2) key.

Elizabeth Hernandez

36895					8/11/2008		84		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/11/2008 2:53:14 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Baseball backstop- Install a new one or renistall the one moved the CHS.

Richard Chavez

11/3/2008 3:24:39 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail Intermediate

37007	Main Building	Classroom			8/13/2008		82		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/13/2008 11:46:28 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Room 109 no se puede habrir. ---- J master esta doblada--- room 403 necesita llave---- banos 411 necesitan cambiar chapas---- puertas principales se atora la llave- GRACIAS

 Marisela Torres

37034					8/13/2008		82		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/13/2008 3:46:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Portable #408 Mr. West is having trouble unlocking door knob
key cylinder. Please send me some Graffite.

 Johnny Acuna

37197					8/19/2008		76		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/19/2008 2:56:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acuna, Johnny
.5-check lift station
7.5-Transport Bobcat tractor to Chaparral High and Help Eddie
cut weeds around the back of the main building.

 Johnny Acuna

37281	Main Building	Classroom			8/21/2008		74		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/21/2008 9:34:34 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Room # 409 la puerta tiene una parte quebrada y no se puede cerrar. Gracias.

 Marisela Torres

37286	Main Building	Office			8/21/2008		74		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/21/2008 11:32:48 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
Escritorio de enfermeria necesita candado de seguridad. Gracias.

 Marisela Torres

37797					9/4/2008		60		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/4/2008 3:33:27 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe
Need help in scraping fenceline areas and grounds with tractor to Chaparral Elem. and Desert Trail. Thank You....

 Johnny Acuna

37831	Main Building	Restroom (Boys)			9/5/2008		59		\$0.00
-------	---------------	-----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/5/2008 11:30:06 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Puerta bano maestros esta caida no cierra. puerta portable 404 esta caida no cierra. puerta principal se atora la llave. Gracias.

 Marisela Torres

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Trail Intermediate

38075	Main Building	Cafeteria			9/15/2008		49		\$0.00
Medium	Work In Progress				9/15/2008 8:14:18 AM				
Lozoya, Manny	LA CHAPA DE LA PUERTA SE QUEBRO Y NO SE PUEDE CERRAR.								
Marisela Torres									
38213					9/18/2008		46		\$0.00
Medium	Work In Progress				9/18/2008 12:09:20 PM				
Gonzalez, Salvador	Please weld extra metal to the top of the metal scraper to add on a little more weight to it. Thank You....								
Johnny Acuna									
38214					9/18/2008		46		\$0.00
Medium	Work In Progress				9/18/2008 12:11:28 PM				
Lozoya, Manny	Please install Lock to new filing cabinet in room #399 inside the main building.								
Johnny Acuna									
38277	Main Building	Computer Lab			9/22/2008		42		\$0.00
Medium	Work In Progress				9/22/2008 8:00:19 AM				
Sotelo, Enrique	Provide electrical supply to 5 ton unit, cooling only.								
Lorenzo Solis									
38553		Classroom			9/30/2008		34		\$0.00
Medium	Work In Progress				9/30/2008 9:21:04 AM				
Lozoya, Manny	se necesita recortar e instalar 2 puertas en cuarto 407 (fueron removidas porque instalaron alfombra) gracias.								
Marisela Torres									
38554	Main Building	Custodial			9/30/2008		34		\$0.00
Medium	Work In Progress				9/30/2008 9:24:04 AM				
Lozoya, Manny	se necesitan 2 name plates--- JAIME GUTIERREZ--- CUSTODIAL OFFICE . Gracias.								
Marisela Torres									
38634					10/1/2008		33		\$0.00
Medium	Work In Progress				10/1/2008 4:14:26 PM				
Lozoya, Manny	Physical Education Coach (Mrs. Murphy) has trouble opening her classroom door with her key. Portable #404								
Johnny Acuna									
38701	Main Building	Restroom (Girls)			10/3/2008		31		\$0.00
Medium	Work In Progress				10/3/2008 11:41:44 AM				
Lozoya, Manny	URGENTE, CAMBIAR LA CHAPA DE UN BANO DE OFICINA, SE QUEDA CERRADA. CUARTO #413 LA PUERTA ESTA CAIDA , NO CIERRA.								
Marisela Torres									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail Intermediate									
38780					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:03 AM				
Orozco, Danny		Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
38787					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:05 AM				
Orozco, Danny		Monthly - Desert Trail Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
38850					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:29 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
38851					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:29 AM				
Acuna, Johnny		Monthly - Desert Trail Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
38853					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:30 AM				
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
38855					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:31 AM				
Acuna, Johnny		Yearly - Desert Trail ES I4 (Fan Coil)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
38857					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:31 AM				
Acuna, Johnny		Yearly - Desert Trail ES U2 (Heat/Gas)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
38858					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:32 AM				
Acuna, Johnny		Yearly - Desert Trail ES R9(Radiation)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Trail Intermediate

39012					10/7/2008		27		\$0.00
Medium	Work In Progress			10/7/2008 3:30:52 PM					
Lozoya, Manny	Need a replacement Door and Door Frame for Portable #413 inside Restroom Door.								
Johnny Acuna									
39014					10/7/2008		27		\$0.00
Medium	Work In Progress			10/7/2008 3:33:24 PM					
Lozoya, Manny	Portable #410: Need a Replacement Metal Door.								
Johnny Acuna									
39122					10/10/2008		24		\$0.00
Medium	Work In Progress			10/10/2008 4:10:15 PM					
Ontiveros, Guadalupe	(Irrigation water pressure tank: Chaparral Elementary) Water leak next to the water pressure tank area.								
Johnny Acuna									
39150					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress			10/12/2008 12:20:58					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
39250					10/15/2008		19		\$0.00
Medium	Work In Progress			10/15/2008 10:19:49					
Sotelo, Enrique	Need light bulb covers for Main Office Area.								
Johnny Acuna									
39251					10/15/2008		19		\$0.00
Medium	Work In Progress			10/15/2008 10:22:04					
Sotelo, Enrique	Need 277v (2 bulb) Ballasts and flourecent light bulbs.								
Johnny Acuna									
39338		Cafeteria			10/21/2008		13		\$0.00
Medium	Work In Progress			10/21/2008 1:18:51 PM					
Orozco, Danny	WALK-IN FREEZER IS AT 32 DEGREES (INFORMED DANNY OROZCO OF THE SITUATION)								
	PATRICIA CISNEROS - SNP MANAGER 8234-3822								
Alma Terrell									
39379					10/22/2008		12		\$0.00
Medium	Work In Progress			10/22/2008 12:36:00					
Ontiveros, Joe	Need help with fixing waterheater in portable #408 leaking classroom sink.								
Johnny Acuna									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Trail Intermediate

39413					10/23/2008		11		\$0.00
Medium	Work In Progress				10/23/2008 12:20:38				
Ronquillo, Ruben	Asp PM 38534 Exhaust Fan, need to replace motor on the following: FED-001, FED-003, FED-017, FED-019, FED-023, FED-036, FED-039, FED-049, FED-077.								
Johnny Acuna									
39492					10/27/2008		7		\$0.00
Medium	Work In Progress				10/27/2008 8:10:22 AM				
Ontiveros, Joe	Portable # 412. Restroom sink faucet needs to be replaced.								
Johnny Acuna									
39532					10/28/2008		6		\$0.00
Medium	Work In Progress				10/28/2008 8:23:45 AM				
Ontiveros, Guadalupe	Need help with tractor scraper scraping front / back dirt areas and outside fencelines. Thank You,								
Johnny Acuna									
39642					10/31/2008		3		\$0.00
Medium	Work In Progress				10/31/2008 12:27:36				
Jacquez, Ricardo	Monthly - Desert Trail - Refer to PM schedule details.								
Margret Villalobos									
39643					10/31/2008		3		\$0.00
Medium	Work In Progress				10/31/2008 7:36:22 AM				
Lozoya, Manny	Need a Name Plate for Portable #411 that says: (Parent Center).								
Johnny Acuna									
39676					10/31/2008		3		\$0.00
Medium	Work In Progress				10/31/2008 4:07:18 PM				
Ontiveros, Guadalupe	Vice-principal and P.E. coach Murphy requesting to burn out lines in grass area to the soccer field and baseball field.								
Johnny Acuna									
39677					10/31/2008		3		\$0.00
Medium	Work In Progress				10/31/2008 4:09:15 PM				
Gonzalez, Salvador	Need to re-weld stainless sheetmetal sheet together that came apart in the kitchen sink area.								
Johnny Acuna									
39686					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:32 AM				
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Trail Intermediate

39708					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:41 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39713					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:43 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39759		Athletic Field			11/3/2008		0		\$0.00
Medium	Work In Progress			11/3/2008 7:38:23 AM					
Munoz, Michael	Basketball Courts in the outdoor playground are badly cracked and separating.								
Johnny Acuna									
39760					11/3/2008		0		\$0.00
Medium	Work In Progress			11/3/2008 7:40:41 AM					
Ronquillo, Ruben	Window frames in the side of the main doors in the NW hall needs to be replaced or repaired. There is too much corrosion.								
Johnny Acuna									
39761					11/3/2008		0		\$0.00
Medium	Work In Progress			11/3/2008 7:43:09 AM					
Carrasco, Danny	Need the scissor lift delivered to "Desert Trail Elementary" to hang up sign in the cafeteria above the stage and also service the Heating Equipment. Thank You.....								
Johnny Acuna									
Count: 54 Work Orders			Avg. Age of WO's 42			Total for Desert Trail Intermediate	0		\$0.00

Location: Desert View ES

35613					7/6/2008	7/14/2008	120		\$0.00
Medium	Work In Progress			7/6/2008 12:19:40 AM					
Aguilar, Patricio	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35617					7/6/2008	7/14/2008	120		\$0.00
Medium	Work In Progress			7/6/2008 12:19:41 AM					
Aguilar, Patricio	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert View ES

35699					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:07 AM				
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35961		Cafeteria			7/15/2008		111		\$0.00
Medium	Work In Progress				7/15/2008 7:33:37 AM				
Moncayo, Fernando	MILK COOLER IS NOT WORKING AT ALL.								
	DIANA LAZARIN SNP MGR 589-2425								
Jacqueline Aguilar									
36198					7/25/2008		101		\$0.00
Medium	Work In Progress				7/25/2008 7:12:16 AM				
Ortiz, Ruben	Perimeter Fence - clear trash and sand build up along fenceline.		Asp Lupe, route back to Ruben 9/19						
Alfredo Holguin									
36883					8/11/2008		84		\$0.00
Medium	Work In Progress	Hallways			8/11/2008 10:24:06 AM				
Castillo, Carlos	2 Emergency Lights not working in Middle and East Hallway asp PM 36530.								
Ruben Ortiz									
36939	Main Building				8/12/2008		83		\$0.00
Medium	Work In Progress				8/12/2008 8:37:50 AM				
Castillo, Carlos	Tested exit signs (4) are not working 2 in Gym and Cafeteria asp PM 36526.								
Ruben Ortiz									
37045					8/13/2008		82		\$0.00
Medium	Work In Progress				8/13/2008 8:46:58 PM				
Ortiz, Ruben	08/13/08 To: Lupe Ontiveros I am requesting to have the arroyo run off filled in and weeds scrapped. If possible with the tractors that are on the south schools area. Before the tractors are taken out.		Asp Lupe, route back to Ruben 9/19						
Ruben Ortiz									
37166					8/18/2008		77		\$0.00
Medium	Work In Progress				8/18/2008 5:24:18 PM				
Ortiz, Ruben	08/18/08 Called Danny Carrasco from warehouse for parts on the motor for the master cooler in room 32. Danny sent me a new motor and brace. Jose Ambriz took off a bracket from an old master cooler and brought to me to fix the master cooler in room 32. Both responded promptly. Thank you.								
Ruben Ortiz									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

37634					8/31/2008		64		\$0.00
Medium	Work In Progress				8/31/2008 12:25:41 AM				
Aguilar, Patricio		Monthly - Desert View ES A-2 Quarterly H/C IREH - Refer to PM schedule details.							
Margret Villalobos									
37635					8/31/2008		64		\$0.00
Medium	Work In Progress				8/31/2008 12:25:41 AM				
Aguilar, Patricio		Monthly - Desert View ES A-1 Semiannual MCD - Refer to PM schedule details.							
Margret Villalobos									
37636					8/31/2008		64		\$0.00
Medium	Work In Progress				8/31/2008 12:25:41 AM				
Aguilar, Patricio		Monthly - Desert View ES A-1 Semiannual MCS & MCS2 - Refer to PM schedule details.							
Margret Villalobos									
37637					8/31/2008		64		\$0.00
Medium	Work In Progress				8/31/2008 12:25:42 AM				
Aguilar, Patricio		Monthly - Desert View ES C-4 Quarterly MSS - Refer to PM schedule details.							
Margret Villalobos									
37639					8/31/2008		64		\$0.00
Medium	Work In Progress				8/31/2008 12:25:42 AM				
Aguilar, Patricio		Monthly - Desert View ES A-5 Quarterly SS - Refer to PM schedule details.							
Margret Villalobos									
37641					8/31/2008		64		\$0.00
Medium	Work In Progress				8/31/2008 12:25:43 AM				
Aguilar, Patricio		Monthly - Desert View ES A-13 Quarterly WREH - Refer to PM schedule details.							
Margret Villalobos									
37819					9/5/2008		59		\$0.00
Medium	Work In Progress				9/5/2008 8:38:49 AM				
Gonzalez, Salvador		Need to make a canopy for behind of cafeteria.							
Michael Munoz									
38108					9/15/2008		49		\$0.00
Medium	Work In Progress				9/15/2008 7:13:21 PM				
Villalobos, David		Requesting for plumber to check if two water faucets can be installed for cleaning purposes							
Ruben Ortiz									
38788					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:06 AM				
Orozco, Danny		Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									

11/3/2008 3:24:40 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

38908					10/5/2008	10/13/2008	29		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:50 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Aguilar, Patricio
Monthly - Desert View ES Roof Inpsection - Refer to PM schedule details.

Margret Villalobos

38927					10/5/2008	11/5/2008	29		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:57 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ortiz, Ruben
Yearly - Desert View ES I-04 Fan Coil Yearly - Refer to PM schedule details.

Margret Villalobos

38928					10/5/2008	11/5/2008	29		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:57 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ortiz, Ruben
Yearly - Desert View ES U-2 Unit Heat Gas Yearly - Refer to PM schedule details.

Margret Villalobos

39052					10/8/2008		26		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				10/8/2008 5:00:31 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose
To: Jose Abrise
Spoke to Mr. Carrasco, he would like the heaters turned on the first days of November 2008.

Ruben Ortiz

39053					10/8/2008		26		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				10/8/2008 5:07:00 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
To Mike Munoz
I was asked by Mr. Carrasco that he needs hot water and more water pressure for the shower in the Special Ed room. There is a child that needs to be bathed often and the water is too cold. He asked for an urgent work order.
Mr. Carrasco asked for this work order to be sent directly to you because he wants it ASAP 10/08/08. Child is being bathed in cold water. Thank you.

Ruben Ortiz

39054					10/8/2008		26		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				10/8/2008 5:09:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
To Angel
The tractor is stalling, need to be looked at. When you go by to see it, can you take more diesel for the tractor. Thank you. Ruben

Ruben Ortiz

39087					10/9/2008		25		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				10/9/2008 5:38:14 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
To David Villalobos
The faucet in the main office bathroom, it is leaking. Needs to be fixed asap, Teachers are complaining.

Ruben Ortiz

11/3/2008 3:24:40 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert View ES

39403					10/22/2008		12		\$0.00
Medium	Work In Progress				10/22/2008 9:07:16 PM				

Villalobos, David I am requesting that the kitchen sink in the SPED classroom to be worked on because the faucet is leaking water and needs new strainers in the sink.

Ruben Ortiz

39404					10/22/2008		12		\$0.00
Medium	Work In Progress				10/22/2008 9:10:57 PM				

Lara, Ralph Carlos Castillo
The button for the handicap door is not working on the southside of the building exit.

Ruben Ortiz

39650					10/31/2008		3		\$0.00
Medium	Work In Progress				10/31/2008 11:35:36				

Holguin, Alfredo Purchase and install new playground equipment and shade structures.

Alfredo Holguin

39687					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:33 AM				

Ortiz, Ruben Monthly - Desert View ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

39711					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:42 AM				

Ortiz, Ruben Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

39715					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:43 AM				

Ortiz, Ruben Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

Count: 31 Work Orders			Avg. Age of WO's 53			Total for Desert View ES	0		\$0.00
------------------------------	--	--	----------------------------	--	--	---------------------------------	----------	--	---------------

Location: GAC

35582					7/6/2008	7/27/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:30 AM				

Orozco, Danny Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

35700					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:07 AM				

Villalobos, David Yearly - GAC Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

11/3/2008 3:24:40 PM									
----------------------	--	--	--	--	--	--	--	--	--

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

35729					7/7/2008		119		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress	C - WING			7/7/2008 9:56:07 AM				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Castillo, Carlos
ELECTRICAL OUTLET NEEDS TO BE MOVED OR ADDED TO ANOTHER OFFICE - WILL BE MOVING PRINTER THAT IS CURRENTLY IN KARLA QUESADA'S OFFICE (PLEASE SEE LULU ESPARZA FOR DETAILS) THANK YOU

Cora Ramirez

35802	RTC	Office			7/9/2008		117		\$0.00
-------	-----	--------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	RTC ACROSS			7/9/2008 3:07:58 PM				
--------	------------------	------------	--	--	---------------------	--	--	--	--

Ambriz, Jose
AS PER GLORIA SAENZ-NEED TO HAVE THE AIR CONDITIONER UNIT CHECKED. SETTINGS ARE NOT WORKING PROPERLY.

Mary Garcia

36280					7/28/2008		98		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Back bottom road			7/28/2008 12:11:48 PM				
--------	------------------	------------------	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
need to apply dirt and crusherfine in back road due to running water after haevy rain.

Juan Ambriz

36281		Hallway/Corridor			7/28/2008		98		\$0.00
-------	--	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-Wing A/C unit			7/28/2008 12:13:33 PM				
--------	------------------	-----------------	--	--	-----------------------	--	--	--	--

Ambriz, Jose
Need to raplace relays in C-Wing unit not working properly

Juan Ambriz

36334		Parking Lot			7/29/2008		97		\$0.00
-------	--	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	bottom dirt			7/29/2008 3:47:57 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
Need to apply more crusherfine in bottom dirt parking lot accumulating water after rain

Juan Ambriz

36360					7/30/2008		96		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/30/2008 3:14:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Need to order new emergency lights for the server room not working total of two

Juan Ambriz

36949		Office			8/12/2008		83		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	A-WING			8/12/2008 10:35:44 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Ambriz, Juan
IF IT WOULD BE POSSIBLE TO HAVE THE AIR VENTS IN JESUS REYE'S OFFICE ADJUSTED. NOT ENOUGH AIR COMES THROUGH.

Mary Garcia

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

36962		Office			8/12/2008		83		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-WING			8/12/2008 3:29:08 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan

AS PER MS. AVILA-TO PLEASE HANG TWO PICTURES ON THE WALL BRHIND THE COMPUTER. PICTURES TO HANG SIDE BY SIDE ABOVE DESK AT EYE LEVEL. (PLEASE SEE MS. AVILA BEFORE HANGING)

Mary Garcia

37189		Office			8/19/2008		76		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	B-WING			8/19/2008 10:23:04 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Castillo, Carlos

AS PER ANNE- IN LUDYM'S OFFICE (NEW FINANCE DIRECTOR) ONE OF THE FLUORESCENT LIGHT FIXTURES DOES NOT HAVE A COVERING AND NEEDS ONE PLEASE.

Mary Garcia

37728		Electrical Room			9/3/2008		61		\$0.00
-------	--	-----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/3/2008 8:03:42 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos

Need to order two backup circuit breakers for technologies service.Existing breakers are running hotter than normal.

Carlos Castillo

37827		Office			9/5/2008		59		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	C-WING			9/5/2008 11:09:26 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Jose

AS PER MS. LOZANO-NEED TO HAVE A NEW AIR UNIT INSTALLED IN CARMEN MORRISSETT'S OFFICE/COPY ROOM. DUE TO NEW COPIERS ARE OVER HEATING.

Mary Garcia

APPROVED BY MR. CHAVEZ. ALSO, JUAN STATED HE TALKED W/JOE AMBRIZ AND ARE GOING TO REPLACE THE WINDOW UNITS FIRST AND IF THAT DOES NOT WORK THEN THEY WILL TRY GOING THROUGH THE ROOF. AS PER JOSE 2 NEW WINDOW UNITTS WILL TAKE CARE OF THE PROBLEM.

37828		Office			9/5/2008		59		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	B-WING			9/5/2008 11:13:08 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan

AS PER MS. BROWDER-WOULD LIKE TO HAVE HER WHOLE OFFICE PAINTED. IF IT WOULD BE POSSIBLE FOR THE DATES OF 9/16 OR 9/17TH, BEFORE FURNITURE COMES IN ON 9/18/08.

APPROVED BY MR. RICHARD G. CHAVEZ. AS PER JUAN, HE HAS ENOUGH PAINT.

Mary Garcia

37829		Office			9/5/2008		59		\$0.00
-------	--	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress	B-WING			9/5/2008 11:15:03 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Mary Garcia

AS PER MS. BROWDER-WOULD LIKE TO HAVE HER OFFICED WAXED, DUE TO GETTING NEW FURNITURE ON 9/18/09. IF THIS CAN BE DONE ON THE FOLLOWING DATES: 9/16 OR 9/17/08.

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
37844					9/5/2008		59		\$0.00
Medium	Work In Progress	Districts vehicle			9/5/2008 3:13:38 PM				
Gonzales, Angel		Need to do tune-up to maintenance vehicle # 140							
Juan Ambriz									
37912		Parking Lot			9/8/2008		56		\$0.00
Medium	Work In Progress	bottom dirt			9/8/2008 3:39:17 PM				
Ontiveros, Guadalupe		Need to level bottom parking lot with crusher fine to avoid accumulated water after rains							
Juan Ambriz									
37939					9/9/2008		55		\$0.00
Medium	Work In Progress	Back dirt road			9/9/2008 8:25:56 AM				
Ontiveros, Guadalupe		need to add dirt to back dirt road due to running water after rains. If possible add crusher fine.							
Juan Ambriz									
37978		Office			9/9/2008		55		\$0.00
Medium	Work In Progress	A-WING			9/9/2008 4:42:49 PM				
Castillo, Carlos		AS PER ELISA-NEED AN ELECTRICAL OUTLET TO BE INSTALLED IN THE SUPT. CONFERENCE CLOSET.							
Mary Garcia									
37979		Office			9/9/2008		55		\$0.00
Medium	Work In Progress	A-WING			9/9/2008 4:44:25 PM				
Castillo, Carlos		AS PER ELISA-NEED TO HAVE AN ELECTRICAL OUTLET IN HER OFFICE REMOVED.							
Mary Garcia									
37984		Office			9/10/2008		54		\$0.00
Medium	Work In Progress	C-WING			9/10/2008 10:29:18 AM				
Ambriz, Juan		AS PER MS. PHILLIPS-NEED TO HAVE A TV & DVD PLAYER STRAPPED DOWN TO THE CART THAT WAS PURCHASED.							
Mary Garcia									
38017		Office			9/11/2008		53		\$0.00
Medium	Work In Progress	C-WING			9/11/2008 8:29:31 AM				
Ambriz, Juan		AS PER MS. YTURREALDE-NEED TO HAVE A NEW BLALLAST INSTALLED. LIGHTS KEEP FLICKERING.							
Mary Garcia									
38082					9/15/2008		49		\$0.00
Medium	Work In Progress				9/15/2008 12:25:12 PM				
Castillo, Carlos		LIGHTS ON MAIN PARKING LOT AT (GAC) NOT WORKING .							
Manuel Prospero									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

38423		Cafeteria			9/25/2008		39		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/25/2008 8:29:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		DELI COOLER - CONDENSING UNIT ON ROOF NEEDS A POWER DISCONNECT FOR SAFETY -- TOP PRIORITY				10/27 - Asp Mike, route to Cali			
------------------	--	---	--	--	--	---------------------------------	--	--	--

		AIDA SALCEDO - SNP COORDINATOR 882-6772							
--	--	---	--	--	--	--	--	--	--

Alma Terrell

38458	Pre-K	Gym			9/26/2008		38		\$0.00
-------	-------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress	PRE-K			9/26/2008 9:09:27 AM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Ambriz, Juan		AS PER ALICE-HALLWAY LIGHT NEED TO BE REPLACED, BURNED OUT.				AS PER JUAN NEED A NEW BALLAST			
--------------	--	---	--	--	--	--------------------------------	--	--	--

Mary Garcia

38646					10/2/2008		32		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				10/2/2008 2:30:47 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		Asp PM 37606, still waiting on Emerg. Light for Board Rm and Sever Rm not working.							
------------------	--	--	--	--	--	--	--	--	--

Juan Ambriz

38781					10/5/2008	10/26/2008	29		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:03 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

38789					10/5/2008	10/26/2008	29		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:06 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny		Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

38878					10/5/2008	11/5/2008	29		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:39 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Juan		Yearly - GAC U-2 Unit Heater Gas Yearly - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

38879					10/5/2008	10/21/2008	29		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:39 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Juan		Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

38957		Office			10/6/2008		28		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	A-WING			10/6/2008 11:42:56 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Ambriz, Juan		AS PER ANNA-NEED TO HAVE A SIGN ATTACHED TO THEIR DOOR.							
--------------	--	---	--	--	--	--	--	--	--

Mary Garcia

11/3/2008 3:24:40 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

39009		Office			10/7/2008		27		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-Wing Ms.			10/7/2008 3:23:42 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Ambriz, Juan
As per Ms. Sheila Raihl need to paint office.

Juan Ambriz

39061	RTC	Classroom			10/9/2008		25		\$0.00
-------	-----	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	RTC ACROSS			10/9/2008 9:17:08 AM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Ambriz, Juan
AS PER GLORIA SAENZ-MR. JOHNSONS' CLASSROOM DOOR IS UNABLE TO OPEN. JUAN WILL BE TAKING A LOOK AT IT THIS MORNING.

Mary Garcia

39064		Office			10/9/2008		25		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-WING			10/9/2008 9:51:52 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan
AS PER MS YTURRALDE-NEED TO HAVE HER SECRETARIES OFFICE REARRANGED, DUE TO NEW PERSONNEL. IF POSSILBE NEXT WEEK (10/13-10/15). OKAY TO MOVE, NOT UNDER WARRANTY. TALKED W/JUAN AND SEEMS TO BE OKAY W/SCHEDULED DATES.

Mary Garcia

39065		Office			10/9/2008		25		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-WING			10/9/2008 9:54:56 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan
AS PER OFELIA, SALLY & JOSIE-NEED TO HAVE SOME LIGHT BULBS LOOSEN DUE TO TOO MUCH LIGHTING WITH IN THEIR OFFICE. ALREADY TAKEN CARE OF BY JUAN.

Mary Garcia

39066		Office			10/9/2008		25		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-WING			10/9/2008 9:56:10 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan
AS PER MS. NORMA DURAN-NEED TO HAVE SOME HOLES PATCHED UP, DUE TO REMOVAL OF SOME FILING CABINETS IN THE BILINGUAL OFFICE.

Mary Garcia

39152					10/12/2008	10/28/2008	22		\$0.00
-------	--	--	--	--	------------	------------	----	--	--------

Medium	Work In Progress				10/12/2008 12:20:59				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Juan
Monthly - GAC Playground Insp - Refer to PM schedule details.

Margret Villalobos

39248					10/15/2008		19		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	A-B-Wing and			10/15/2008 9:24:41 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Castillo, Carlos
Need to reroute electrical due to removal and reinstall new refrigerated units in A-B-Wing and Cafetria

Juan Ambriz

39249					10/15/2008		19		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	A-B-wing and			10/15/2008 9:26:41 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Villalobos, David
Need to reroute gas lines due to removing and reinstalling new refrigerated units in A-B-Wing and cafetria.

Juan Ambriz

11/3/2008 3:24:40 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: GAC

39366		Office			10/22/2008		12		\$0.00
Medium	Work In Progress	C-WING		10/22/2008 9:54:03 AM					
Ambriz, Juan	AS PER ALFREDO-GO AHEAD AND SEAL OFF THE WALL WHERE THE AIR UNIT WAS IN OFELIA'S OFFICE.		APPROVED BY ALFREDO						
Mary Garcia									
39540		Office			10/28/2008		6		\$0.00
Medium	Work In Progress	A-WING		10/28/2008 11:44:46					
Ambriz, Juan	AS PER ANNA-THERE IS A LOOSE TILE IN THE BUDGET OFFICE W/SPECIAL ED.								
Mary Garcia									
39570		Cafeteria			10/29/2008		5		\$0.00
Medium	Work In Progress			10/29/2008 9:59:43 AM					
Moncayo, Fernando	HOOD IS MAKING ALOT OF NOISE								
	GESSICA BLAZQUEZ - SNP MANAGER 882-6784								
Alma Terrell									
39678					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:29 AM					
Ambriz, Juan	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
39712					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:42 AM					
Ambriz, Juan	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39716					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:44 AM					
Ambriz, Juan	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39775		Hallway/Corridor			11/3/2008		0		\$0.00
Medium	Work In Progress	THROUGHT ALL		11/3/2008 10:25:53 AM					
Castillo, Carlos	AS PER MS. NAVA - NEED TO HAVE MOST OF ALL EMERGENCY LIGHTS TURNED OFF. (NEED TO WORK WITH CUSTODIAL AND BUILDING MECHANIC ON THIS.) THIS NEEDS TO BE DONE ASAP.		TALKED WITH RAFA ON THIS, HE HAD ALREADY TALKED WITH CALI REGARDING TURNING OFF SOME IF NOT MOST OF THE EMERGENCY LIGHTS. MAINTENANCE AND CUSTODIAL HAVE NO ACCESS IN TURNING THEM OFF. RAFA-EXHEAD CUSTODIAN DID THIS STUDY BACK SINCE MAY 2004.						
Mary Garcia									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

39776		Office			11/3/2008		0		\$0.00
Medium	Work In Progress	THROUGH OUT			11/3/2008 10:34:27 AM				
Ambriz, Juan		AS PER MS. NAVA-NEED TO GO THROUGH ALL GAC AND LOOSEN LIGHT BULBS EVERYWHERE THERE'S LIGHTS, LEAVING AT LEAST ONE BULB ON. THIS NEEDS TO BE DONE ASAP. (INCLUDES:ALL OFFICES, BATHROOMS, BISTRO LOBBY, CONFERENCE ROOMS, CLOSETS AND ANY STORAGE ROOMS & ETC.)				I TALKED AND EXPLAINED TO BUILDING MECHANIC AND CUSTODIAL TO DO THIS ASAP AS PER MS. NAVAS REQUEST.			

Mary Garcia

Count: 47 Work Orders		Avg. Age of WO's 48				Total for GAC	0		\$0.00
------------------------------	--	----------------------------	--	--	--	----------------------	----------	--	---------------

Location: Gadsden HS

35479	Football Stadium	Football Field			7/1/2008		125		\$0.00
Medium	Work In Progress				7/1/2008 8:20:32 AM				
Ontiveros, Guadalupe		The chain link fence by the guest bleachers need to be repaired at the football field.							

Mario Apodaca

35590					7/6/2008	7/27/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:33 AM				
Orozco, Danny		Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.							

Margret Villalobos

35701					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:08 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							

Margret Villalobos

35873	Main Building	Office			7/11/2008		115		\$0.00
Medium	Work In Progress				7/11/2008 2:16:35 PM				
Lara, Ralph		NEW NAME PLATES (3) MR. CAREY L. CHAMBERS							

Mario Apodaca

35876	Main Building	Office			7/11/2008		115		\$0.00
Medium	Work In Progress				7/11/2008 2:28:45 PM				
Carrasco, Danny		NEED NEW BLINDS FOR PRINCIPAL CHAMBERS OFFICE 1. 40" X 5' 2. 7' X 5'							

Mario Apodaca

35877	Main Building	Office			7/11/2008		115		\$0.00
Medium	Work In Progress				7/11/2008 2:32:00 PM				
Ambriz, Jose		NEW WINDOW AC UNIT FOR PRINCIPAL CHAMBERS							

Mario Apodaca

11/3/2008 3:24:40 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

35993	Boys Gym	Office			7/16/2008		110		\$0.00
-------	----------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			7/16/2008 2:28:31 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose
Requested by Coach Lawrence Rm. 401 Office in Boy's Gym-Room 401 does not have any air conditioning, would like to have a unit installed this summer of 2008, to review videos and to watch films for Soccer.

Velia Alarcon

36000	Library	Library			7/16/2008		110		\$0.00
-------	---------	---------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			7/16/2008 3:18:40 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe
An irrigation control box has a water leak underneath the asphalt outside the southwest exit.

Albert Vallejo

36066	North Building	Classroom			7/18/2008		108		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			7/18/2008 3:19:18 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben
NEED NEW WINDOW BLINDS (35"WX56"L) FOR ROOM 207 NEED 11 EA

Mario Apodaca

36067	Old English Bldg	Classroom			7/18/2008		108		\$0.00
-------	------------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			7/18/2008 3:21:06 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose
NEED A NEW HEATING CONDESER AT ROOM 141 DO TO VANDALISM

Mario Apodaca

36186	Cafeteria (1998)	Cafeteria			7/24/2008		102		\$0.00
-------	------------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			7/24/2008 3:18:50 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Moncayo, Fernando
WALK - IN FREEZER DOWN.

GHS SNP 882-5522

Jacqueline Aguilar

36231					7/25/2008		101		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			7/25/2008 3:04:45 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe
Requested by Coach Hite for Football Field-Football field is very uneven. Please level as it is very dangerous.

Velia Alarcon

36288	Vocational	Classroom			7/28/2008		98		\$0.00
-------	------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	568		7/28/2008 3:08:02 PM					
--------	------------------	-----	--	----------------------	--	--	--	--	--

Carrasco, Danny
Window frames in front of classroom are in bad repair and need to be completely replaced. Large amounts of water get through during rainstorms.

Albert Vallejo

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

36310	Cafeteria (1998)	Cafeteria			7/29/2008		97		\$0.00
Medium	Work In Progress				7/29/2008 8:10:33 AM				
Castillo, Carlos	NEED A SAFETY POWER DISCONNECT TO THE GHS WALK-IN'S (BOTH) ON THE CONDENSER UNITS ON THE ROOF								
Jacqueline Aguilar	MR. DEMETRIIOUS GIOVAS								
36359	Cafeteria				7/30/2008		96		\$0.00
Medium	Work In Progress				7/30/2008 3:02:54 PM				
Moncayo, Fernando	need to ck the ice maker compressors at the cafe it is tipping the circuit breaker								
Mario Apodaca									
36386	Main Building	Classroom			7/31/2008		95		\$0.00
Medium	Work In Progress	127			7/31/2008 8:53:23 AM				
Lara, Ralph	The double doors on room 127 need to be replaced. When closed, they are hard to open due to swelling. When closed, they are hard to close because the hinges no longer take firm purchase on the door or jamb.								
Albert Vallejo									
36403	Academic Bldg				7/31/2008		95		\$0.00
Medium	Work In Progress				7/31/2008 1:52:38 PM				
Lara, Ralph	Requested by Ms. Leahy Rm. 328 Academic Building- Put a lock on the left-hand built-in cabinet.								
Velia Alarcon									
36404	Boys Gym				7/31/2008		95		\$0.00
Medium	Work In Progress				7/31/2008 2:09:10 PM				
Vallejo, Albert	Requested by Coach Hite for J.V. Football Locker Room in Boy's Gym-Gray paint J.V. Football locker room floor around toilet/urinal area and sink area.								
Velia Alarcon									
36622					8/4/2008		91		\$0.00
Medium	Work In Progress	WWT			8/4/2008 4:10:54 PM				
Sanchez, Raul	Replace motor for Wastewater Treatment Plant Blowers.								
Raul Sanchez									
36774	Academic Bldg				8/7/2008		88		\$0.00
Medium	Work In Progress				8/7/2008 1:58:16 PM				
Lara, Ralph	Requested by Ms. Howard Rm. 307 Academic Building- A cylinder with two keys are needed for file cabinet in classroom. Cabinet has not cylinder.								
Velia Alarcon									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

36776	Old English Bldg				8/7/2008		88		\$0.00
-------	------------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/7/2008 2:19:22 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph Requested by Mr. Stemsrud Rm. 154 Old English Building-Need two keys made for file cabinet in classroom.

Velia Alarcon

36779	North Building				8/7/2008		88		\$0.00
-------	----------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/7/2008 2:39:56 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph Requested by Ms. Roth Rm. 213 North Building-The interior handle of the north door is missing and the door won't lock, please repair.

Velia Alarcon

36783	Academic Bldg				8/7/2008		88		\$0.00
-------	---------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/7/2008 2:58:49 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Apodaca, Mario Requested by Coach Hite-Paint Cactus Sculpture on south west corner of academic building.

Velia Alarcon

36801	North Building				8/7/2008		88		\$0.00
-------	----------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/7/2008 3:54:07 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph Requested by Mr. Palmer Rm. 205 North Building-Teacher's keys do not open Teacher Lounge in North Building. Please repair as soon as possible.

Velia Alarcon

36878	Boys Gym				8/11/2008		84		\$0.00
-------	----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/11/2008 8:35:04 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo new shower column was installed in girls dressing room. need to install tile to complete project.see mike. thxs

Michael Munoz

36896	Boys Gym	Gym			8/11/2008		84		\$0.00
-------	----------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/11/2008 2:55:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos NEED A NEW SWITCH FOR THE E/COOER UNIT AT THE BOYS GYM

Mario Apodaca

37049	Football Stadium	Football Field			8/14/2008		81		\$0.00
-------	------------------	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/14/2008 8:14:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael Some of the concrete piers that support the bleachers are cracked and need to be repaired.

Albert Vallejo

37094	Cafeteria (1998)	Cafeteria			8/14/2008		81		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/14/2008 3:40:19 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose ALL OUTSIDE DUCTS OF THE CAFE BLDG NEED TO BE RESEAL DOTO SUN AND WATER DAMAGE. ASAP

Mario Apodaca

11/3/2008 3:24:40 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

37099	Boys Gym	Gym			8/15/2008		80		\$0.00
Medium	Work In Progress				8/15/2008 7:44:21 AM				
Appelzoller, Fred	install collars to cover vents and water to showers in boys gym as per mike.								
Fred Appelzoller									
37143	New Vocational	Hallway/Corridor			8/18/2008		77		\$0.00
Medium	Work In Progress				8/18/2008 2:43:34 PM				
Ronquillo, Ruben	Need window glass replaced, Approximately 24" x 30" in size. (wired glass)								
Albert Vallejo									
37144	Computer	Electrical Room			8/18/2008		77		\$0.00
Medium	Work In Progress				8/18/2008 2:46:26 PM				
Castillo, Carlos	Contactor for computer outlets intermitently makes more noise than normal.								
Albert Vallejo									
37145					8/18/2008		77		\$0.00
Medium	Work In Progress				8/18/2008 2:48:35 PM				
Gonzalez, Salvador	The chain link fence directly south of the band room has been hit by a vehicle, one post is down and the mesh has been torn								
Albert Vallejo									
37232	Old English Bldg	Classroom			8/20/2008		75		\$0.00
Medium	Work In Progress				8/20/2008 2:03:04 PM				
Carrasco, Danny	NEED NEW WINDOW MINI BLINDS DOTO VANDALISM (W43 1/2" X L90") NEED #4								
Mario Apodaca									
37233	Academic Bldg				8/20/2008		75		\$0.00
Medium	Work In Progress				8/20/2008 2:15:18 PM				
Ambriz, Jose	AT THE ACADEMIC BLDG NEED NEW E/COOLER STANDS								
Mario Apodaca									
37234	Cafeteria (1998)				8/20/2008		75		\$0.00
Medium	Work In Progress				8/20/2008 2:17:31 PM				
Ambriz, Jose	AT THE CAFE BLDG NEED NEED NEW E/COOER STANDS								
Mario Apodaca									
37235	Cafeteria (1998)	Restroom (Boys)			8/20/2008		75		\$0.00
Medium	Work In Progress				8/20/2008 2:25:19 PM				
Lara, Ralph	NEED TO PUT A NEW DEADBOLTS ON THE TOW RESTROOMS DOORS .ASAP								
Mario Apodaca									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

37284					8/21/2008		74		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/21/2008 11:13:30 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ronquillo, Ruben 8 SIGNS (24 X 18) THAT READ THE FOLLOWING:

GHS IS A DRUG FREE CAMPUS
NO SMOKING
NO ALCOHOL
NO WEAPONS
NO PETS

Mario Apodaca

37295	Agricultural	Classroom			8/21/2008		74		\$0.00
-------	--------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/21/2008 2:52:32 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Appelzoller, Fred need a new sink and faucet set put-in at room 569

Mario Apodaca

37299					8/21/2008		74		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/21/2008 2:59:39 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Apodaca, Mario

8-20-08 8/20-8
6-painting a class room at the a.g bldg room 569
1-t/shoot a/c unit at the n-bldg too room 202
1-in put to school dude

Mario Apodaca

38570					9/30/2008		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/30/2008 3:20:12 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Gonzalez, Salvador need tow screen for vents at the girls gym

Mario Apodaca

37306					8/21/2008		74		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/21/2008 3:20:25 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Vallejo, Albert (8-21-08) 2 hrs - Troubleshoot and repair A/C unit on top of varsity gym; 2 hrs - Finish restroom wall and install urinal in boys gym; 3 hrs - repair partitions in boys restroom in cafeteria; 1 hr - Fire extinguisher inspections (work order #36494) 8/21-7

Albert Vallejo

37360	Grounds Shop				8/25/2008		70		\$0.00
-------	--------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/25/2008 12:51:17 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Castillo, Carlos I need an electrician to disconnect power to burned-out motor at wwtp and assist me in installing a new blower motor. We may need a small crane to lift new motor up to wwtp platform. Thanks, Raul

Raul Sanchez

37398					8/26/2008		69		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/26/2008 3:27:40 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Apodaca, Mario Requested by Mrs. Smith Rm. 127 Main Building- Need the overhead screen placed above chalkboard.

Velia Alarcon

11/3/2008 3:24:40 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

37400					8/26/2008		69		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/26/2008 3:35:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos Requested by Mr. Roberson for Rm. 127 Main Building- Install on/off switch for lights in room #127. When room was divided switch was left in room #128.

Velia Alarcon

37421					8/26/2008		69		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/26/2008 4:18:55 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Coach Yanez for Baseball Field-Remove frame from North Batting Cage and deliver to Softball Field.

See Coach Bones and Coach Lopez before beginning work.

Velia Alarcon

37423					8/26/2008		69		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/26/2008 4:21:08 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Coach Yanez for Baseball Field-Take nets off of north batting cage and place them on the south east batting cage.

See Coach Bones before beginning work.

Velia Alarcon

37426					8/26/2008		69		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/26/2008 4:28:51 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Requested by Mrs. Smith Rm. 127 Main Building-Can not lock or unlock door from the inside. This is a hazard during fire drills such as freezes or lock downs. This is an old door handle that should be replaced.

Velia Alarcon

37431					8/27/2008		68		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/27/2008 8:10:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador NEED TO CONSTRUCT SHADE AT GROUNDS DEPT. TO PROTECT IMPLEMENT.

Guadalupe Ontiveros

37442					8/27/2008		68		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/27/2008 10:51:46 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Coach Hite for Football Field-Sod bare areas on Football Field before first home game on September 12th.

Velia Alarcon

37444	Old English Bldg				8/27/2008		68		\$0.00
-------	------------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/27/2008 11:31:54 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario Requested by Mr. Stemsrud Rm. 154 Old English Building-Hang maps.

Velia Alarcon

11/3/2008 3:24:40 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

37686	Auto Shop				9/2/2008		62		\$0.00
-------	-----------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/2/2008 11:11:10 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Apodaca, Mario
Requested by Mr. Enriquez Rm. 580 Auto Shop-
Replace broken hydraulic line on Hunter Lift. Speak to
teacher before job is done. Safety Issue.

Velia Alarcon

37691	Academic Bldg				9/2/2008		62		\$0.00
-------	---------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/2/2008 11:42:35 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Apodaca, Mario
Requested by Ms. Luna Rm. 318 Academic Building-
Paint the office.

Velia Alarcon

37708	Cafeteria (1998)	Custodial			9/2/2008		62		\$0.00
-------	------------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/2/2008 2:46:32 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Gonzales, Angel
i have a preasure washer that will start but has very little
water preasure when operating

Joe Munoz

37996	Agricultural	Classroom			9/10/2008		54		\$0.00
-------	--------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/10/2008 3:10:19 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben
need new window blinds for room 568.ea 2 (60 1/2"x45")

Mario Apodaca

38074					9/14/2008		50		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/14/2008 12:23:09 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ontiveros, Guadalupe
Monthly - Gadsden HS Soil Sampling - Refer to PM
schedule details.

Margret Villalobos

38165	Cafeteria (1998)	Restroom (Boys)			9/17/2008		47		\$0.00
-------	------------------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/17/2008 8:25:05 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben
a cafe window need to be repairs at the boys restroom
do to vandalism (20"x20")

Mario Apodaca

38284					9/22/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/22/2008 9:40:57 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Vallejo, Albert
Requested by Mr. Roberson for Campus-Paint all
paintable surfaces on campus restrooms white.

Velia Alarcon

38286					9/22/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/22/2008 10:13:18 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Apodaca, Mario
Requested by Ms. Lam Rm. 104 Main Building-Holder of
the glass door of the south book shelf is broken.

Velia Alarcon

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

38287					9/22/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/22/2008 10:30:07 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David Requested by Ms. Lam Rm. 104 Main Building-Both cold and hot water of the faucet on the south side have sulfur smell.

Velia Alarcon

38288					9/22/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/22/2008 10:35:59 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vallejo, Albert Requested by Coach Hite and Coach Maxey Football Laundry Room-Remove old dryer and metal objects from laundry room. Also, tables and chairs that are broken and stored in there. Remove refrigerator from Football locker room.

Velia Alarcon

38290					9/22/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/22/2008 10:47:38 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Coach Yanez for Baseball Field-Pour cement in battiang cages (2) behind dugout.

Velia Alarcon

38292					9/22/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/22/2008 10:58:14 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario Requested by Ms. Aguilar Rm. 236 North Building-Replace burned out light bulbs.

Velia Alarcon

38293					9/22/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/22/2008 10:59:47 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario Requested by Ms. Leahy Rm. 328 Academic Building-Window does not have screen, please install one.

Velia Alarcon

38294					9/22/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/22/2008 11:05:39 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by Ms. Moreno Rm. 126 Main Building-The door is fallen and hard to close. The key is very hard to get out of the lock and the door sometimes gets stuck and students can not get out. This could be a problem during fire drills.

Velia Alarcon

38296					9/22/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/22/2008 11:16:00 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vallejo, Albert Requested by Ms. Roth Rm. 213 North Building-Legs are loose on various HEAVY lab tables and need to be tightened and possibly secured. Table tops are not attached to certain tables and also pose a safety hazard and noise maker.

Velia Alarcon

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

38297					9/22/2008		42		\$0.00
Medium	Work In Progress			9/22/2008 11:17:19 AM					
Lara, Ralph	Requested by Ms. Abler Rm. 309 Academic Building- The entire doorknob is broken.								
Velia Alarcon									
38302					9/22/2008		42		\$0.00
Medium	Work In Progress			9/22/2008 11:36:02 AM					
Lara, Ralph	Requested by Velia for Pre-School Play Ground-A pad lock with chain needs to be placed on gate into the Pre- School Play Ground.								
Velia Alarcon									
38303	Main Building	Custodial			9/22/2008		42		\$0.00
Medium	Work In Progress			9/22/2008 11:49:06 AM					
Gonzales, Angel	i have two weeders that will not start and needs maintnence								
Joe Munoz									
38305					9/22/2008		42		\$0.00
Medium	Work In Progress			9/22/2008 12:04:36 PM					
Vallejo, Albert	Requested by Coach Hite for Football Fieldhouse (Boy's Gym)-Please remove refrigerator, does not work.								
Velia Alarcon									
38429	Academic Bldg	Classroom			9/25/2008		39		\$0.00
Medium	Work In Progress			9/25/2008 2:39:13 PM					
Carrasco, Danny	need windos blinds (46 3/4" x 62") for the academic bldg need 10								
Mario Apodaca									
38465					9/26/2008		38		\$0.00
Medium	Work In Progress			9/26/2008 12:29:32 PM					
Lozoya, Manny	Mr. Chacon, Band Director needs a gate key.								
Michael Munoz									
38493					9/29/2008		35		\$0.00
Medium	Work In Progress			9/29/2008 10:43:07 AM					
Ontiveros, Guadalupe	Requested by Coach A. Lopez for Softball Field Varsity Batting Cage-Patio, cement inside of batting cage.								
Velia Alarcon									
38496	Boys Gym				9/29/2008		35		\$0.00
Medium	Work In Progress			9/29/2008 10:54:00 AM					
Apodaca, Mario	Requested by Coach S. Perez for Boys Gym-Holes on the Boy's Gym floor for Volleyball poles need to be recovered with medal flaps.								
Velia Alarcon									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

38497					9/29/2008		35		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/29/2008 10:57:19 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Carrasco, Danny Requested by Julio Alcantar for Student Parking Lot-
Need more electrical poles to help mark the parking spaces in the student parking lot.

Velia Alarcon

38501	Computer				9/29/2008		35		\$0.00
-------	----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/29/2008 11:05:11 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Apodaca, Mario Requested by Jenny Gonzalez Rm. 250 Computer Lab-
We have mice, please place mice traps.

Velia Alarcon

38538					9/30/2008		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/30/2008 12:26:03 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Apodaca, Mario Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) -
Refer to PM schedule details.

Margret Villalobos

38604					10/1/2008		33		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			10/1/2008 2:02:50 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose Requested by Ms. Hartmann Rm. 568 Classroom
between Ag. Shop and Wood Shop-Install an extracting fan to remove fumes coming into room 568, created by Auto and Ag engines. There's currently no way for fumes to exit from classroom. Fumes giving teacher and students headaches.

Velia Alarcon

38617		Athletic Field			10/1/2008		33		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			10/1/2008 3:32:18 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph Ag Teacher needs a small gauge Padlock for a diesel tank in the north alfalfa field near the pig farm. The lock should be keyed to F3.

Albert Vallejo

38659	Vocational	Classroom			10/2/2008		32		\$0.00
-------	------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	569		10/2/2008 3:33:49 PM					
--------	------------------	-----	--	----------------------	--	--	--	--	--

Villalobos, Margret There are ants in Room 569. 10/2 Emailed for price quote

Albert Vallejo

38662	Varsity Gym	Gym			10/2/2008		32		\$0.00
-------	-------------	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress			10/2/2008 3:35:55 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben Trophy case needs new tempered glass (ca. 5'x 6'x
"1/4)

Albert Vallejo

38744					10/5/2008		29		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			10/5/2008 12:23:50 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Holguin, Alfredo Monthly - Gadsden HS Generator PM (Quarterly) - Refer 10/6/08 - Emailed to Ricky Borrego
to PM schedule details.

Margret Villalobos

11/3/2008 3:24:40 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
38746					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:23:51 AM				
Vallejo, Albert		Monthly - Gadsden HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
38747					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:23:51 AM				
Vallejo, Albert		Yearly - Gadsden HS H6 (Furnace)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
38748					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:23:51 AM				
Vallejo, Albert		Yearly - Gadsden HS R9 (H.W.Radiator)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
38749					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:23:52 AM				
Vallejo, Albert		Yearly - Gadsden HS U2 (Heater)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
38790					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:06 AM				
Orozco, Danny		Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
38890					10/5/2008	10/21/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:43 AM				
Apodaca, Mario		Monthly - Gadsden HS A1 (Air Dryer)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
38891					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:44 AM				
Apodaca, Mario		Yearly - Gadsden HS I4 (Fan Coil)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
38892					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:44 AM				
Apodaca, Mario		Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

38893					10/5/2008	10/13/2008	29		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress			10/5/2008 12:24:44 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

38954	Cafeteria (1998)	Cafeteria			10/6/2008		28		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			10/6/2008 10:39:01 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Moncayo, Fernando	ICE MACHINE IS DOWN AGAIN - FERNANDO WAS AT GAC ON 10/3/08, I (ALMA) TOLD HIM OF THE PROBLEM.								
-------------------	---	--	--	--	--	--	--	--	--

SARA GARCIA - SNP ASST. MANAGER 882-5522

Alma Terrell

38974	Academic Bldg	Classroom			10/6/2008		28		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			10/6/2008 3:03:50 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose	need new e/cooler unit at the academic bldg need 20 e.a								
--------------	---	--	--	--	--	--	--	--	--

Mario Apodaca

38997	Main Building				10/7/2008		27		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			10/7/2008 11:33:11 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Munoz, Joe	Requested by Velia for Front Office in Main Building- Since air quality and mold are a concern today. There are several spots in the Front Office that have leaked when it rains and dark spots have started to grow in these areas. Please test areas for mold and clean them. Although this problem won't be resolved until the roof is either repaired or re-roofed. Main Building has several leaks through out the building.					10/7 - Asp Mike, rout to Custodial FAX W.O. TO JOE			
------------	---	--	--	--	--	--	--	--	--

Velia Alarcon

39030	Main Building				10/8/2008		26		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			10/8/2008 10:44:21 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lara, Ralph	lost a key to the book keerer office and the concession stand at the old eng bldg need to be rekey								
-------------	--	--	--	--	--	--	--	--	--

Mario Apodaca

39073	Agricultural	Classroom			10/9/2008		25		\$0.00
-------	--------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			10/9/2008 3:15:51 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben	need a window blind for room 569 (60"x48")								
------------------	--	--	--	--	--	--	--	--	--

Mario Apodaca

39097					10/10/2008		24		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress			10/10/2008 11:31:16					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lara, Ralph	Requested by Coach Letz for Storage Room in Girl's Gym-The door bolt came off the door knob, the loose bolt is in Velia's Office. Please pick it up when the door knob will be fixed.								
-------------	---	--	--	--	--	--	--	--	--

Velia Alarcon

11/3/2008 3:24:40 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

39132					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress				10/12/2008 12:20:51				
Munoz, Joe	Monthly - QRTL Y BLDG INSP REPORT (GH) - Refer to PM schedule details.								
Jesus Estrada									
39179	Main Building	Classroom			10/13/2008		21		\$0.00
Medium	Work In Progress				10/13/2008 11:47:30				
Ambriz, Jose	need #3 new heating unit for the main bldg do to the heat exchangers are on good. asap.								
Mario Apodaca									
39205	Football Stadium	Football Field			10/14/2008		20		\$0.00
Medium	Work In Progress				10/14/2008 8:00:12 AM				
Castillo, Carlos	As per Raul Sanchez, need to disconnect football field irrigation pump. Need to come back and reconnect after Anthony Pump services it.								
Carlos Castillo									
39252	Old English Bldg	Classroom			10/15/2008		19		\$0.00
Medium	Work In Progress				10/15/2008 12:27:17				
Ambriz, Jose	need a new damper motor for the heating unit at the old eng bldg								
Mario Apodaca									
39287					10/20/2008		14		\$0.00
Medium	Work In Progress				10/20/2008 10:53:12				
Castillo, Carlos	Requested by Velia for Marque in Front of School-The left side light to the marque is burned out or has no electricity running to it, please repair.								
Velia Alarcon									
39300	North Building	Classroom			10/20/2008		14		\$0.00
Medium	Work In Progress				10/20/2008 2:38:24 PM				
Moncayo, Fernando	the deli cart cooler is not working need to be fix ASAP.at room 233 n-bldg.								
Mario Apodaca									
39506	Academic Bldg				10/27/2008		7		\$0.00
High	Work In Progress				10/27/2008 10:25:31				
Castillo, Carlos	as per mr.chambers, the north end of the outside of the building is lacking lighting. this is a pick-up area and is safety issue.please see if exterior lighting can be placed. presently there is 1 exterior light. would like more lights that would illuminte more. thxs								
Carey Chambers									
39510					10/27/2008		7		\$0.00
Medium	Work In Progress				10/27/2008 10:59:35				
Lara, Ralph	Requested by Mr. Enriquez Rm. 580 Auto Shop-Repair damaged doors to storage room and office.								
Velia Alarcon									
11/3/2008 3:24:40 PM									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

39511	Academic Bldg				10/27/2008		7		\$0.00	
Medium	Work In Progress				10/27/2008 11:01:57					
Castillo, Carlos	Requested by Ms. Leahy Rm. 328 Academic Building- Check the outlets on the south wall and all wiring in the classroom. I keep blowing the bulb in the overhead projector.									
<u>Velia Alarcon</u>										
39514					10/27/2008		7		\$0.00	
Medium	Work In Progress				10/27/2008 1:56:08 PM					
Apodaca, Mario	Requested by Ms. Jaraba Rm. 124 Main Building-Hang white boards and 10 flags.									
<u>Velia Alarcon</u>										
39621	New Vocational	Classroom			10/30/2008		4		\$0.00	
High	Work In Progress				10/30/2008 2:08:48 PM					
Ambriz, Jose	the heating unit at rom 551 has a carbon monoxide of 5ppm need a new heating unit asap									
<u>Mario Apodaca</u>										
39646	Main Building				10/31/2008		3		\$0.00	
Medium	Work In Progress				10/31/2008 9:13:58 AM					
Gonzalez, Salvador	Make stands for new refrigeration units and reinforce beams. Talk to Mike									
<u>Salvador Gonzalez</u>										
39679					11/2/2008	11/8/2008	1		\$0.00	
Medium	Work In Progress				11/2/2008 12:24:29 AM					
Vallejo, Albert	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
39717					11/2/2008	11/10/2008	1		\$0.00	
Medium	Work In Progress				11/2/2008 12:24:44 AM					
Vallejo, Albert	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
39720					11/2/2008	11/10/2008	1		\$0.00	
Medium	Work In Progress				11/2/2008 12:24:45 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
39753					11/2/2008	12/3/2008	1		\$0.00	
Medium	Work In Progress				11/2/2008 12:24:58 AM					
Vallejo, Albert	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
Count: 112 Work Orders			Avg. Age of WO's	55				Total for Gadsden HS	0	\$0.00

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden MS

35702					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress			7/6/2008 12:20:08 AM					
Villalobos, David	Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35828	Annex	Classroom			7/10/2008		116		\$0.00
Medium	Work In Progress	Annex/Room 400		7/10/2008 10:15:00 AM					
Estrada, Jesus	Replace carpet in Room 400.								
Maricruz Carrasco									
35829	C-Wing	Classroom			7/10/2008		116		\$0.00
Medium	Work In Progress	Cwing/C-206		7/10/2008 10:16:48 AM					
Estrada, Jesus	Replace carpet in Room C-206.								
Maricruz Carrasco									
35947		Office			7/14/2008		112		\$0.00
High	Work In Progress	Awing/T. Urbina's		7/14/2008 11:29:19 AM					
Jacquez, Ricardo	Manhole located in T. Urbina's office needs to be sealed. The metal lid that is currently on that manhole is too small and is permitting vapors and putrid odors from the crawl space. We need a larger metal lid and to make sure that the access door is sealed in a manner that prohibits those odors into the room. This manhole poses a safety issue in that someone could fall into the access door and the odors can be a health risk to the person who is occupying the room. Please take care of this as soon as possible.								
Maricruz Carrasco									
35955					7/14/2008		112		\$0.00
Medium	Work In Progress			7/14/2008 3:35:17 PM					
Lozoya, Manny	Need fix main entrance doors the punish bar not work properly thank you								
Sebastian Diaz									
36222		Office			7/25/2008		101		\$0.00
Medium	Work In Progress	Awing/GMS Front		7/25/2008 11:40:57 AM					
Lozoya, Manny	Need to set up A57 key lock on new door in Ms. Quinonez's office as soon as possible.								
Maricruz Carrasco									
36627		Office			8/5/2008		90		\$0.00
Medium	Work In Progress	GMS Front		8/5/2008 5:44:35 AM					
Lozoya, Manny	Need A53 door lock on Nancy's door as soon as possible.								
Maricruz Carrasco									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

36628		Office			8/5/2008		90		\$0.00
Medium	Work In Progress	Awing/155/Dr.			8/5/2008 5:47:23 AM				
Lozoya, Manny		Door lock in Dr. Garcia's office supposed to be opened by M36 key only. W key can be used to open the door. Please check door lock.							
<u>Maricruz Carrasco</u>									
36630		Parking Lot			8/5/2008		90		\$0.00
Medium	Work In Progress	Parking			8/5/2008 5:56:11 AM				
Ronquillo, Ruben		Need two windows in security shed.							
<u>Maricruz Carrasco</u>									
36632		Parking Lot			8/5/2008		90		\$0.00
Medium	Work In Progress	Parking			8/5/2008 5:59:53 AM				
Lozoya, Manny		Need metal door installed in Security shed.							
<u>Maricruz Carrasco</u>									
36994	Cafeteria	Cafeteria			8/13/2008		82		\$0.00
Medium	Work In Progress				8/13/2008 8:10:48 AM				
Moncayo, Fernando		SNP WAREHOUSE A/C SOUTHSIDE HAS NO WATER. HOT AIR BLOWING.							
		JOHNNY LECHUGS SNP MGR WHSE 882-6927							
<u>Jacqueline Aguilar</u>									
36995	Cafeteria	Cafeteria			8/13/2008		82		\$0.00
Medium	Work In Progress				8/13/2008 8:12:29 AM				
Moncayo, Fernando		SNP WAREHOUSE: WALK IN REFRIG. NEEDS TO BE RECHECK TEMP. THIS MORNING WAS AT 42.							
		JOHNNY LECHUGA SNP MGR 882-6927							
<u>Jacqueline Aguilar</u>									
37002	Cafeteria	Cafeteria			8/13/2008		82		\$0.00
Medium	Work In Progress				8/13/2008 9:07:14 AM				
Orozco, Danny		SNP WAREHOUSE: FREEZER #2 NEEDS THE DOOR RUBBER SEALS TO BE REPLACED.							
		JOHNNY LECHUGA SNP MGR 882-6927							
<u>Jacqueline Aguilar</u>									
37267		Office			8/21/2008		74		\$0.00
Medium	Work In Progress	Awing/162/Securit			8/20/2008 10:01:58 PM				
Lozoya, Manny		"W" key is getting jammed.							
<u>Maricruz Carrasco</u>									
37270		Classroom			8/21/2008		74		\$0.00
Medium	Work In Progress	Awing/159/E.			8/20/2008 10:06:16 PM				
Lozoya, Manny		Door does not close and lock.							
<u>Maricruz Carrasco</u>									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

37358		Portables			8/25/2008		70		\$0.00
Medium	Work In Progress	Double Portable			8/25/2008 12:42:33 PM				
Solis, Lorenzo		Double Portable - Need to cover all registers properly.							
Michael Munoz									
37763	C-Wing	Classroom			9/3/2008		61		\$0.00
Medium	Work In Progress	Cwing/C-			9/3/2008 9:29:19 PM				
Lozoya, Manny		Door does not lock. Safety issue.							
Maricruz Carrasco									
37764	C-Wing	Office			9/3/2008		61		\$0.00
Medium	Work In Progress	Cwing/Dr. Montes			9/3/2008 9:30:21 PM				
Lozoya, Manny		Door does not lock.							
Maricruz Carrasco									
37770		Portables			9/4/2008		60		\$0.00
Medium	Work In Progress				9/4/2008 8:13:40 AM				
Sotelo, Enrique		Please provide electrical connection to 2 Bard units.							
Lorenzo Solis									
38113		Cafeteria			9/16/2008		48		\$0.00
Medium	Work In Progress				9/16/2008 8:22:32 AM				
Moncayo, Fernando		SNP WAREHOUSE FREEZER #4 NEEDS THE DOOR TO BE REPLACED.				9/29 - Asp Fernando door on freezer #4 was hit and bent by pallet jacks is not repairable, needs to be replaced.			
		JOHNNY LECHUGA SNP WHSE MGR 882-6927							
Jacqueline Aguilar									
38313	Cafeteria	Cafeteria			9/22/2008		42		\$0.00
Medium	Work In Progress				9/22/2008 2:40:39 PM				
Orozco, Danny		SNP WAREHOUSE -- NEEDS NEW WATER LINE							
		JOHNNY LECHUGA SNP MGR 882-6927							
Jacqueline Aguilar									
38384	Gym	Gym			9/24/2008		40		\$0.00
Medium	Work In Progress	Gym/Lockerroom			9/23/2008 10:02:16 PM				
Diaz, Sebastian		Lockers need to get fixed. Please check with Dr. Garcia for specific instructions.							
Maricruz Carrasco									
38385					9/24/2008		40		\$0.00
Medium	Work In Progress	All GMS Staff			9/23/2008 10:06:29 PM				
Lozoya, Manny		All staff restrooms to have latch placed on door for privacy reasons.							
Maricruz Carrasco									
38417	C-Wing				9/24/2008		40		\$0.00
Medium	Work In Progress				9/24/2008 3:44:29 PM				
Lozoya, Manny		New Portable - 1st thing tomorrow need to recore like GMS (see Mike if u have any questions).							
Michael Munoz									

11/3/2008 3:24:41 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden MS

38464	C-Wing				9/26/2008		38		\$0.00
Medium	Work In Progress			9/26/2008 12:26:38 PM					
Lozoya, Manny	Mr. Chacon, Band Director needs a gate key for gate by C-Wing.								
<u>Michael Munoz</u>									
38485					9/26/2008		38		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:32:43 PM					
Lozoya, Manny	Need three WA-83 keys. Need two V-3 keys.								
<u>Maricruz Carrasco</u>									
38486					9/26/2008		38		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:34:17 PM					
Lozoya, Manny	Need two keys made for golf cart.								
<u>Maricruz Carrasco</u>									
38487	C-Wing				9/26/2008		38		\$0.00
Medium	Work In Progress	C-wing/New		9/26/2008 4:35:35 PM					
Lozoya, Manny	Fix lock to main entrance on new portable-Health Center								
<u>Maricruz Carrasco</u>									
38651	Annex				10/2/2008		32		\$0.00
Medium	Work In Progress			10/2/2008 3:20:00 PM					
Lozoya, Manny	Need fix handi cup door in annex bldg thank you								
<u>Sebastian Diaz</u>									
38731					10/5/2008	10/21/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:23:45 AM					
Villalobos, Margret	Yearly - Gadsden MS October Chiller Insp. - Refer to PM schedule details.		10/6-		Emailed to Johnson Controls				
<u>Margret Villalobos</u>									
38791					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:07 AM					
Orozco, Danny	Monthly - Gadsden MS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39040					10/8/2008		26		\$0.00
Medium	Work In Progress			10/8/2008 3:45:14 PM					
Ronquillo, Ruben	Need 4 window blinds for new portable 30"X60 thank you								
<u>Sebastian Diaz</u>									
39069	C-Wing				10/9/2008		25		\$0.00
High	Work In Progress			10/9/2008 10:54:49 AM					
Munoz, Michael	need to paint entrance curb from washington st. to where asplalt ends no parking, also around new portable and in front of c-wing.								
Alfredo Holguin									

11/3/2008 3:24:41 PM

Page 66 of 118

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
39133					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress				10/12/2008 12:20:52				
Acosta, Juan		Monthly - QRTLY BLDG INSP REPORT (GM) - Refer to PM schedule details.							
<u>Jesus Estrada</u>									
39211	C-Wing	Office			10/14/2008		20		\$0.00
Medium	Work In Progress	c-wing/health			10/14/2008 9:40:40 AM				
Gonzalez, Salvador		Cement by rampway entrance to the clinic. Emergency services had a very difficult time accessing the building.							
<u>Maricruz Carrasco</u>									
39212	Gym	Gym			10/14/2008		20		\$0.00
Medium	Work In Progress	Gym/Boys Locker			10/14/2008 9:44:16 AM				
Diaz, Sebastian		Lockers need to be reinforced with plywood. Please see Mr. Mitchell for more information.							
<u>Maricruz Carrasco</u>									
39213		Office			10/14/2008		20		\$0.00
Medium	Work In Progress	Dr. Garcia's			10/14/2008 9:56:39 AM				
Lozoya, Manny		Install lock on black storage cabinet for Maricruz.							
<u>Maricruz Carrasco</u>									
39563	C-Wing				10/28/2008		6		\$0.00
Medium	Work In Progress				10/28/2008 4:07:03 PM				
Ontiveros, Guadalupe		please remove flag pole and install at PPD park. Thankyou							
<u>Michael Munoz</u>									
39603					10/30/2008		4		\$0.00
Medium	Work In Progress	GMS			10/30/2008 12:02:54				
Diaz, Sebastian		Remove light bulbs from specific areas. See Nancy for a list.							
<u>Maricruz Carrasco</u>									
39654		Athletic Field			10/31/2008		3		\$0.00
Medium	Work In Progress				10/31/2008 11:45:31				
Gonzalez, Maritza		Arrange for rental and set up of shade canopy for students							
<u>Alfredo Holguin</u>									
39688					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:33 AM				
Diaz, Sebastian		Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
39718					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:45 AM				
Diaz, Sebastian		Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									

11/3/2008 3:24:41 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

39723					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:46 AM				
Diaz, Sebastian		Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.							

Margret Villalobos

Count: 43 Work Orders		Avg. Age of WO's 53				Total for Gadsden MS	0		\$0.00
------------------------------	--	----------------------------	--	--	--	-----------------------------	----------	--	---------------

Location: La Union - JTP Alvarez Farms

37476					8/28/2008		67		\$0.00
Medium	Work In Progress				8/28/2008 7:46:35 AM				
Castillo, Carlos		Asp e-mail w/o for the replacement of the outside lights.							

Selma Nevarez

Count: 1 Work Orders		Avg. Age of WO's 67				Total for La Union - JTP Alvarez Farms	0		\$0.00
-----------------------------	--	----------------------------	--	--	--	---	----------	--	---------------

Location: La Union ES

35705					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:09 AM				
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							

Margret Villalobos

35791		Cafeteria			7/9/2008		117		\$0.00
Medium	Work In Progress				7/9/2008 1:48:49 PM				
Moncayo, Fernando		OVENS NEED TO BE CHECKED. SOMETIMES THEY WILL HEAT UP AND THEN STOP HEATING ALL OF A SUDDEN.							

LINDA YANAGA SNP MGR 589-2040

Jacqueline Aguilar

35792		Cafeteria			7/9/2008		117		\$0.00
Medium	Work In Progress				7/9/2008 1:49:55 PM				
Moncayo, Fernando		PASS THRU REFRIG. IS FREEZING UP.							

LINDA YANAGA LU SNP MGR 589-2040

Jacqueline Aguilar

35921					7/13/2008	7/29/2008	113		\$0.00
Medium	Work In Progress				7/13/2008 12:18:11 AM				
Gonzalez, Salvador		Monthly - La Union ES Playground Insp - Refer to PM schedule details.							

Margret Villalobos

36544					8/3/2008	8/11/2008	92		\$0.00
Medium	Work In Progress				8/3/2008 12:20:27 AM				
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.							

Margret Villalobos

11/3/2008 3:24:41 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: La Union ES

36590					8/4/2008		91		\$0.00
Medium	Work In Progress			8/4/2008 10:36:40 AM					
Castillo, Carlos	Run elect. to morgom maint storage - would be nice to use fan								
Patricio Aguilar									
36891		Athletic Field			8/11/2008		84		\$0.00
Medium	Work In Progress			8/11/2008 2:47:10 PM					
Aguilar, Patricio	Provide backfill around new concret under new canopy- build a gradual slope from the concrete to the grass.								
Alfredo Holguin									
36996		Cafeteria			8/13/2008		82		\$0.00
Medium	Work In Progress			8/13/2008 8:23:00 AM					
Moncayo, Fernando	REACH THRU REFRIG. DOES NOT COOL TEMP IS AT 50								
	LINDA YANAGA SNP MGR 589-2040								
Jacqueline Aguilar									
37040	Annex Building				8/13/2008		82		\$0.00
Medium	Work In Progress			8/13/2008 4:17:56 PM					
Castillo, Carlos	Install electrical for kiln in room # 203								
Alfredo Holguin									
37041	Annex Building				8/13/2008		82		\$0.00
Medium	Work In Progress			8/13/2008 4:18:39 PM					
Ambriz, Jose	Install venting for kiln in room # 203								
Alfredo Holguin									
37120					8/15/2008		80		\$0.00
Medium	Work In Progress			8/15/2008 3:17:51 PM					
Carrasco, Danny	Need 3 gfi elect out lets #202								
Patricio Aguilar									
37710					9/2/2008		62		\$0.00
Medium	Work In Progress			9/2/2008 3:15:32 PM					
Ontiveros, Guadalupe	Need the back stop moved to the south end of playground -see alfredo holguin about this								
Patricio Aguilar									
37960					9/9/2008		55		\$0.00
Medium	Work In Progress			9/9/2008 2:37:27 PM					
Castillo, Carlos	NEED TO HAVE LIGHT POLES, AND LIGHTS ON WEST PARKING LOT CHECKED THEY ARE OFF, ONLY A FEW LIGHTS COME ON, POSSIBLE LIGHTING DAMAGE.								
Arturo Nunez									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: La Union ES

38034					9/11/2008		53		\$0.00
Medium	Work In Progress			9/11/2008 3:14:33 PM					
Villalobos, David	pat aguilar need rubber bushing for water faucet - thank you								
Patricio Aguilar									
38036					9/11/2008		53		\$0.00
Medium	Work In Progress			9/11/2008 3:22:31 PM					
Solis, Lorenzo	pat aguilar wants her refrigerated ac replaced - that it is to loud								
Patricio Aguilar									
38079		Athletic Field			9/15/2008		49		\$0.00
Medium	Work In Progress			9/15/2008 11:12:21 AM					
Ontiveros, Guadalupe	Baseball Backstop - Relocate to south side of playground . Check with Ms. Adreas and Ms. Valtierra on the new location.								
Alfredo Holguin									
38110	Annex Building	Hallway/Corridor			9/16/2008		48		\$0.00
Medium	Work In Progress			9/16/2008 8:00:41 AM					
Villalobos, David	installation of 6" storm drain pipe for annex building and new playground								
David Villalobos									
38186		Restroom (Girls)			9/17/2008		47		\$0.00
Medium	Work In Progress			9/17/2008 3:28:46 PM					
Lara, Ralph	The door knob for female rest room will not lock - thank you								
Patricio Aguilar									
38793					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:08 AM					
Orozco, Danny	Monthly - La Union ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38900					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:47 AM					
Aguilar, Patricio	Yearly - La Union ES I-4 Fan Coil Unit Yearly - Refer to PM schedule details.								
Margret Villalobos									
38901					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:47 AM					
Aguilar, Patricio	Yearly - La Union ES H-6 Furance Gas Yearly - Refer to PM schedule details.								
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
38902					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:48 AM					
Aguilar, Patricio	Yearly - La Union ES R-9 Radiator Ht Water Yearly - Refer to PM schedule details.								
Margret Villalobos									
38903					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:48 AM					
Aguilar, Patricio	Monthly - La Union ES H-11 Unit Elec Ht Semiannual - Refer to PM schedule details.								
Margret Villalobos									
38904					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:48 AM					
Aguilar, Patricio	Yearly - La Union ES U-2 Unit Heater Gas Yearly - Refer to PM schedule details.								
Margret Villalobos									
38907					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:50 AM					
Aguilar, Patricio	Monthly - La Union ES Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
39154					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress			10/12/2008 12:20:59					
Aguilar, Patricio	Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
39282	La Union JTP	Electrical Room			10/20/2008		14		\$0.00
Medium	Work In Progress			10/20/2008 9:24:24 AM					
Castillo, Carlos	J.T.P NEED OUTSIDE LIGHT REPLACED.								
Santos Galindo									
39473		Athletic Field			10/24/2008		10		\$0.00
Medium	Work In Progress			10/24/2008 3:18:48 PM					
Ontiveros, Guadalupe	pat aguilar set up 2 sets of soccer goals - relocate soccer goals - level the walking path								
Patricio Aguilar									
39651					10/31/2008		3		\$0.00
Medium	Work In Progress			10/31/2008 11:37:36					
Holguin, Alfredo	Purchase and install playground equipment including metal shade structures								
Alfredo Holguin									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: La Union ES

39690					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:34 AM				
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
39721					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:46 AM				
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39729					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:49 AM				
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39767					11/3/2008		0		\$0.00
Medium	Work In Progress				11/3/2008 8:32:12 AM				
Villalobos, David	NEED TO HAVE WATER LEAK ON WEST SIDE OF BUILDING DRIVE WAY CHECKED. A WATER LEAK HAS SPRUNG. OVER THE WEEK END. THANK YOU,								
Arturo Nunez									
Count: 33 Work Orders			Avg. Age of WO's	51		Total for La Union ES	0		\$0.00

Location: Loma Linda ES

35583					7/6/2008	7/27/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:31 AM				
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
35703					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:08 AM				
Villalobos, David	Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36116					7/22/2008		104		\$0.00
Medium	Work In Progress				7/22/2008 12:27:51 PM				
Lozoya, Manny	Manny, needing door in room 212 repaired								
Grace Alvarado									
36408					7/31/2008		95		\$0.00
Medium	Work In Progress				7/31/2008 2:26:46 PM				
Ronquillo, Ruben	Need to replace 10 more blinds.								
Rudy Arreola									

11/3/2008 3:24:41 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
36686					8/6/2008		89		\$0.00
Medium	Work In Progress			8/6/2008 3:03:22 PM					
Lozoya, Manny	Rm 111 needs to have lock installed in her filing cabinet.								
Rudy Arreola									
36898					8/11/2008		84		\$0.00
Medium	Work In Progress			8/11/2008 3:03:50 PM					
Lozoya, Manny	We need a lock installed in a filing cabinet in RM 201								
Rudy Arreola									
37058		Portables			8/14/2008		81		\$0.00
Medium	Work In Progress			8/14/2008 10:22:44 AM					
Arreola, Rudy	Complete skirting installation on double portable								
Alfredo Holguin									
37174		Classroom			8/19/2008		76		\$0.00
Medium	Work In Progress			8/19/2008 7:48:48 AM					
Sotelo, Enrique	Rm 111 the emergency light is out not working at all.								
Rudy Arreola									
37711		Athletic Field			9/2/2008		62		\$0.00
Medium	Work In Progress			9/2/2008 3:15:39 PM					
Ontiveros, Guadalupe	Water leak from one of the irrigation line its coming from under the cement. by the basketball courts area.								
Rudy Arreola									
38220		Classroom			9/18/2008		46		\$0.00
Medium	Work In Progress			9/18/2008 2:36:13 PM					
Ronquillo, Ruben	Windows in RM 205 are hard to open and wont stay up.TOTAL of 3								
Rudy Arreola									
38221		Classroom			9/18/2008		46		\$0.00
Medium	Work In Progress			9/18/2008 2:37:10 PM					
Ronquillo, Ruben	Windows in RM 201 is very hard to open TOTAL of 2.								
Rudy Arreola									
38222					9/18/2008		46		\$0.00
Medium	Work In Progress			9/18/2008 2:37:50 PM					
Ronquillo, Ruben	Window in RM 204 wont stay up TOTAL of 1.								
Rudy Arreola									
38782					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:04 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Loma Linda ES

38794					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:08 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38964					10/6/2008		28		\$0.00
Medium	Work In Progress			10/6/2008 1:40:46 PM					
Carrasco, Danny	Need pressure washer and hose to wash off wall of the east side of main bldg.								
Rudy Arreola									
38973					10/6/2008		28		\$0.00
Medium	Work In Progress			10/6/2008 2:55:14 PM					
Sotelo, Enrique	We need more outlets in coaches office.								
Rudy Arreola									
39414					10/23/2008		11		\$0.00
Medium	Work In Progress			10/23/2008 12:22:29					
Sotelo, Enrique	Asp PM 38922 Emerg. Light not workin in boys rr and entrance. (ck w/Rudy for location)								
Rudy Arreola									
39613					10/30/2008		4		\$0.00
Medium	Work In Progress			10/30/2008 1:29:28 PM					
Lozoya, Manny	Need new lock for popcorn machine.								
Rudy Arreola									
39614					10/30/2008		4		\$0.00
Medium	Work In Progress			10/30/2008 1:30:36 PM					
Lozoya, Manny	Door handle is broken in RM 212								
Rudy Arreola									
39615					10/30/2008		4		\$0.00
Medium	Work In Progress			10/30/2008 1:32:10 PM					
Lozoya, Manny	Library door is getting stuck.								
Rudy Arreola									
39616					10/30/2008		4		\$0.00
Medium	Work In Progress			10/30/2008 1:34:22 PM					
Lozoya, Manny	Door handle is getting stuck in womens rr.								
Rudy Arreola									
39652					10/31/2008		3		\$0.00
Medium	Work In Progress			10/31/2008 11:39:17					
Holguin, Alfredo	Purchase and install new playground equipment including metal shade structures.								
Alfredo Holguin									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

39691					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:34 AM				
Arreola, Rudy		Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
39722					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:46 AM				
Arreola, Rudy		Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39731					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:49 AM				
Arreola, Rudy		Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39762					11/3/2008		0		\$0.00
Medium	Work In Progress				11/3/2008 7:52:22 AM				
Ronquillo, Ruben		Need 6 signs that say NO PARKING 7.AM. TO 4P.M. MOM THRU FRIDAY							
Rudy Arreola									
Count: 26 Work Orders			Avg. Age of WO's 43			Total for Loma Linda ES	0		\$0.00

Location: Mesquite ES

35549					7/6/2008	7/12/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:20 AM				
Ramirez, Joe		Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
35567					7/6/2008	7/14/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:26 AM				
Ramirez, Joe		Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
35626					7/6/2008	7/14/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:44 AM				
Ramirez, Joe		Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
35636					7/6/2008	7/14/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:47 AM				
Ramirez, Joe		Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

35661					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:55 AM				
Ramirez, Joe		Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
35684					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:02 AM				
Ramirez, Joe		Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
35706					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:09 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
36109					7/22/2008		104		\$0.00
Medium	Work In Progress				7/22/2008 10:11:48 AM				
Lozoya, Manny		on (work room) needs a cylinder with a key they have school files need to be lock all the time as per montano principal asap. thank you. luis							
<u>Luis Saucedo</u>									
36147	Main Building	Office			7/23/2008		103		\$0.00
Medium	Work In Progress	Main office area			7/23/2008 12:29:38 PM				
Lozoya, Manny		Main office need's (4) engraved plaque's for front office door. Name and Title (Jacob Montano, Principal), (Sandra Mora, Secretary), (Dora Lerma, Data-Entry Clerk), (Maribel Villela, Receptionist-Clerk) for Manny Lozoya.							
<u>Sandra Mora</u>									
36227		Portables			7/25/2008		101		\$0.00
Medium	Work In Progress				7/25/2008 2:11:53 PM				
Lozoya, Manny		Ms. Flores room # 801 has filing cabinet that doesn't have a key, need's to be re-key.							
<u>Sandra Mora</u>									
37626					8/31/2008	9/6/2008	64		\$0.00
Medium	Work In Progress				8/31/2008 12:25:38 AM				
Ramirez, Joe		Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
36245					7/28/2008		98		\$0.00
Medium	Work In Progress				7/28/2008 7:44:32 AM				
Ramirez, Joe		please need to check water pump we have flood on barracks on 7/29/08 between the blds. thank you.							
<u>Luis Saucedo</u>									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Mesquite ES

36256	2003 Classroom	Classroom			7/28/2008		98		\$0.00
Medium	Work In Progress	Portable room #		7/28/2008 8:30:02 AM					
Lozoya, Manny	Ms. Jimenez, portable room # 506 she has a storage cabinet needs to be re-key.								
<u>Sandra Mora</u>									
36259	2003 Classroom	Classroom			7/28/2008		98		\$0.00
Medium	Work In Progress	Kinder hallway,		7/28/2008 8:58:17 AM					
Lozoya, Manny	Need a master for that room # 405 for our inventory, and key # 305.								
<u>Sandra Mora</u>									
36507					8/3/2008	8/9/2008	92		\$0.00
Medium	Work In Progress			8/3/2008 12:20:15 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36539					8/3/2008	8/11/2008	92		\$0.00
Medium	Work In Progress			8/3/2008 12:20:26 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36549					8/3/2008	8/11/2008	92		\$0.00
Medium	Work In Progress			8/3/2008 12:20:29 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36577					8/4/2008		91		\$0.00
Medium	Work In Progress			8/4/2008 5:44:47 AM					
Ramirez, Joe	please need to chek the roof this mornig we got a few big leak in the cafeteeria from the rain.thank you luis.								
<u>Luis Saucedo</u>									
36885	Main Building	Office			8/11/2008		84		\$0.00
Medium	Work In Progress	Office area		8/11/2008 11:09:39 AM					
Lozoya, Manny	(1) engraved plaque for front office door. Name and Title (Norma Sierra, Assistant Principal) for Manny Lozoya								
<u>Sandra Mora</u>									
37428					8/27/2008		68		\$0.00
Medium	Work In Progress			8/27/2008 5:27:42 AM					
Ramirez, Joe	this morning we have a few leaks in the cafeteria by south side corner. thank you luis								
<u>Luis Saucedo</u>									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Mesquite ES

37490					8/28/2008		67		\$0.00
Medium	Work In Progress			8/28/2008 3:06:30 PM					
Ramirez, Joe	continue the condensation line to a proper area for drainage.								
Michael Munoz									
37617					8/31/2008		64		\$0.00
Medium	Work In Progress			8/31/2008 12:25:35 AM					
Ramirez, Joe	Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
Margret Villalobos									
37618					8/31/2008		64		\$0.00
Medium	Work In Progress			8/31/2008 12:25:35 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual MCD - Refer to PM schedule details.								
Margret Villalobos									
37619					8/31/2008		64		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos									
37620					8/31/2008		64		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual UCD - Refer to PM schedule details.								
Margret Villalobos									
37621					8/31/2008		64		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual UCS2 - Refer to PM schedule details.								
Margret Villalobos									
37622					8/31/2008		64		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.								
Margret Villalobos									
37623					8/31/2008	9/8/2008	64		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Mesquite ES

37624					8/31/2008		64		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.								
Margret Villalobos									
37625					8/31/2008		64		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual EVS - Refer to PM schedule details.								
Margret Villalobos									
37627					8/31/2008	9/8/2008	64		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
38209					9/18/2008		46		\$0.00
Medium	Work In Progress			9/18/2008 9:17:37 AM					
Sotelo, Enrique	pole lights on the eastside of campus not working.								
Joe Ramirez									
38210					9/18/2008		46		\$0.00
Medium	Work In Progress			9/18/2008 9:18:18 AM					
Sotelo, Enrique	marquee lights not working.								
Joe Ramirez									
38537					9/30/2008		34		\$0.00
Medium	Work In Progress			9/30/2008 12:26:03 AM					
Ramirez, Joe	Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
Margret Villalobos									
38589					10/1/2008		33		\$0.00
Medium	Work In Progress			10/1/2008 9:13:56 AM					
Sotelo, Enrique	front porch entrance lights not working need to replace ballasts.								
Joe Ramirez									
38663	Pump House				10/2/2008		32		\$0.00
Medium	Work In Progress			10/2/2008 3:36:10 PM					
Ramirez, Joe	Remove all materials equipment and other supplies stored in this area. This is not a storeroom.								
Alfredo Holguin									
38795					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:08 AM					
Orozco, Danny	Monthly - Mesquite ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									

11/3/2008 3:24:41 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

38881					10/5/2008	10/11/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:40 AM				
Ramirez, Joe		Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
38882					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:41 AM				
Ramirez, Joe		Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
38883					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:41 AM				
Ramirez, Joe		Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
38884					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:41 AM				
Ramirez, Joe		Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
38885					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:42 AM				
Ramirez, Joe		Yearly - Mesquite ES I-4 Fan Coil Unit Yearly - Refer to PM schedule details.							
Margret Villalobos									
38886					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:42 AM				
Ramirez, Joe		Yearly - Mesquite ES H-6 Rooftop Furnance Yearly - Refer to PM schedule details.							
Margret Villalobos									
38887					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:42 AM				
Ramirez, Joe		Yearly - Mesquite ES R-9 Rad Hot Water 2 years - Refer to PM schedule details.							
Margret Villalobos									
38888					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:43 AM				
Ramirez, Joe		Yearly - Mesquite ES U-2 Unit Heater Gas Yearly - Refer to PM schedule details.							
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Mesquite ES

38889					10/5/2008	10/21/2008	29		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress			10/5/2008 12:24:43 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.

Margret Villalobos

39093					10/10/2008		24		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress			10/10/2008 8:24:02 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Carbajal, Jimmy The scrubber machine # 1253524 & g.i.s.d. tag # 99-00031 is not working is too old, if possible to exchange for new scrubber machine.

Thank you.

Luis

Luis Saucedo

39278		Cafeteria			10/20/2008		14		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress			10/20/2008 8:28:13 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Orozco, Danny WIRE INSIDE WALK-IN (LEFT HAND SIDE) TO TEMP. GAUAGE ON THE OUTSIDE BROKE OFF.

LAURA HERRERA - MQ 233-2341

Jacqueline Aguilar

39331					10/21/2008		13		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress			10/21/2008 9:33:29 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Sotelo, Enrique need electrical power run to new water heater installed in the kitchen.

Joe Ramirez

39516					10/27/2008		7		\$0.00
-------	--	--	--	--	------------	--	---	--	--------

Medium	Work In Progress			10/27/2008 3:08:58 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ramirez, Joe CLEAN AND SERVICE ALL HEATERS AS PER OUR CONVERSATION. POSSIBLE SAFETY AND FIRE HAZARD. WILL BE INSPECTED.

10/27 - AS PER MIKE, ONCE W.O. 39516 FOR MQ IS COMPLETED, PLEASE GIVE TO MIKE FOR HIS REVIEW. THANKS MG

Michael Munoz

39517					10/27/2008		7		\$0.00
-------	--	--	--	--	------------	--	---	--	--------

Medium	Work In Progress			10/27/2008 3:09:56 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ramirez, Joe WEED EAT AROUND CAMPUS (AROUND PICNIC TABLES, TREES ETC.)

Michael Munoz

39518					10/27/2008		7		\$0.00
-------	--	--	--	--	------------	--	---	--	--------

Medium	Work In Progress			10/27/2008 3:10:45 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ramirez, Joe REPAIR HOLE IN SHEET ROCK AND INSTALL DOOR STOP BY LARRY SEDILLO'S ROOM.

Michael Munoz

11/3/2008 3:24:41 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Mesquite ES

39519					10/27/2008		7		\$0.00
Medium	Work In Progress				10/27/2008 3:11:39 PM				
Ramirez, Joe	GRASS IS GROWING IN DRAIN GRID BY BUS TURN AROUND.								
Michael Munoz									
39692					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:35 AM				
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
39724					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:47 AM				
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39734					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:50 AM				
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39774		Cafeteria			11/3/2008		0		\$0.00
Medium	Work In Progress				11/3/2008 10:04:57 AM				
Orozco, Danny	WALK IN REFRIG. TEMP. IS GOING ABOVE 40								
	LAURA HERRERA MQ SNP 233-2341								
Jacqueline Aguilar									
Count: 57 Work Orders			Avg. Age of WO's	58		Total for Mesquite ES	0		\$0.00

Location: North Valley ES

36463		Office			8/1/2008		94		\$0.00
Medium	Work In Progress	room 400			8/1/2008 11:44:39 AM				
Lozoya, Manny	Hello Manny,								
	The alarm box key was broken off, please replace.								
Priscilla Martinez									
37136		Office			8/18/2008		77		\$0.00
Medium	Work In Progress	video			8/18/2008 10:18:19 AM				
Lozoya, Manny	could not locate a key						Need a black box located in our office to be opened, could not locate the correct key in our vault		
Priscilla Martinez									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: North Valley ES

37221		Classroom			8/20/2008		75		\$0.00
Medium	Work In Progress	various		8/20/2008 9:15:00 AM					
Lozoya, Manny	Send Lozoya to make various keys for various classrooms, desks, cabinets, filing cabinets, storage closets,		please visit the front office for this list of keys that are needed, thanks Priscilla						
Priscilla Martinez									
37326					8/22/2008		73		\$0.00
Medium	Work In Progress			8/22/2008 7:29:45 AM					
Munoz, Michael	need cement slab at marquee sign 12x12 very harzardous to place ladder on dirt uneven grd due to rain erosion on ponding area								
Danny Vega									
37675					9/2/2008		62		\$0.00
Medium	Work In Progress			9/2/2008 9:01:54 AM					
Munoz, Michael	need a 4ft gate door by marquee by 12ft by 12ft slab (facing north) spoke to jaun v. on this								
Danny Vega									
37765		Classroom			9/4/2008		60		\$0.00
Medium	Work In Progress	room 401		9/4/2008 7:52:35 AM					
Vega, Danny	Our nurse needs to hang curtain railing in her office for a special need student.		Thank you very much						
Priscilla Martinez									
37766		Office			9/4/2008		60		\$0.00
Medium	Work In Progress	room 400		9/4/2008 7:54:21 AM					
Vega, Danny	Hang a bulletin board in the front office.		Thank you,						
Priscilla Martinez									
38084		Classroom			9/15/2008		49		\$0.00
Medium	Work In Progress			9/15/2008 1:35:12 PM					
Lozoya, Manny	need a key made for Larry Roybal (Deputy Dona Ana County Sheriff) for the gates at North Valley Elementary								
Priscilla Martinez									
38743					10/5/2008		29		\$0.00
Medium	Work In Progress			10/5/2008 12:23:50 AM					
Holguin, Alfredo	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.		10/6/08 - Emailed to Ricky Borrego						
Margret Villalobos									
38797					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:09 AM					
Orozco, Danny	Monthly - North Valley ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: North Valley ES

38805					10/5/2008	10/11/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:12 AM				
Vega, Danny		Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
38807					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:13 AM				
Vega, Danny		Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
38810					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:14 AM				
Vega, Danny		Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
38811					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:14 AM				
Vega, Danny		Monthly - North Valley ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
39280					10/20/2008		14		\$0.00
Medium	Work In Progress				10/20/2008 9:11:35 AM				
Lozoya, Manny		need new pad lock for bus exit gate/had to cut old lock this morning-key didnt turn core							
Danny Vega									
39383					10/22/2008		12		\$0.00
Medium	Work In Progress				10/22/2008 1:41:03 PM				
Lozoya, Manny		p.e coaches office door will not open -core will not turn with key-please ck out asap							
Danny Vega									
39456		Classroom			10/24/2008		10		\$0.00
Medium	Work In Progress	room 210			10/24/2008 12:13:11				
Lozoya, Manny		black file cabinet w/blue sticker does not lock.							
Priscilla Martinez									
39694					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:35 AM				
Vega, Danny		Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
39727					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:48 AM				
Vega, Danny		Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

11/3/2008 3:24:41 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: North Valley ES

39738					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:52 AM				
Vega, Danny		Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.							

Margret Villalobos

Count: 20 Work Orders		Avg. Age of WO's 38				Total for North Valley ES	0		\$0.00
------------------------------	--	----------------------------	--	--	--	----------------------------------	----------	--	---------------

Location: Northern On-Track Pre-K (LM)

35704					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:09 AM				
Villalobos, David		Yearly - Northern Pre-K (LM) Backflow Inspection - Refer to PM schedule details.							

Margret Villalobos

36220	Main Building				7/25/2008		101		\$0.00
Medium	Work In Progress				7/25/2008 11:25:22 AM				
Vega, Danny		Hedge in front of Main Entrance - needs to be trimmed also a sprout in the Planter on the west side of the entrance needs to be removed and the hedge growing against the building directly next to it also.							

Alfredo Holguin

36483					8/1/2008		94		\$0.00
Medium	Work In Progress				8/1/2008 3:34:14 PM				
Sotelo, Enrique		need to install control panels in pump house and main bldg for new electric valves /wire is running in trench already							

Danny Vega

36680					8/6/2008		89		\$0.00
Medium	Work In Progress	Playground			8/6/2008 11:23:04 AM				
Vega, Danny		New playground structure is complete. We need plastic lining and Round-up applied so that area can be filled in with sand. We also need a sand box moved, enlarged and filled with sand.				8/11 - Asp Lupe route to D. Vega			

Gilbert Trujillo

36884	Cafeteria	Custodial			8/11/2008		84		\$0.00
Medium	Work In Progress	room 16			8/11/2008 10:49:59 AM				
Vega, Danny		roof is leaking, ceiling fell off.							

Gilbert Trujillo

37300					8/21/2008		74		\$0.00
Medium	Work In Progress				8/21/2008 3:03:06 PM				
Vega, Danny		8-18-08 .5-ck wk ods in office nve 2.5-ck and clean a/c unit distributors la mesa pre-k 5-cut weeds and spray round-up at la mesa				8/18-8			

Danny Vega

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Northern On-Track Pre-K (LM)

37774		Athletic Field			9/4/2008		60		\$0.00
Medium	Work In Progress			9/4/2008 8:52:16 AM					
Lozoya, Manny	send us the lock and chain to secure the west gate								
Gilbert Trujillo									
37775	Main Building	Restroom (Girls)			9/4/2008		60		\$0.00
Medium	Work In Progress	classroom 114		9/4/2008 9:33:49 AM					
Lozoya, Manny	Bathroom door in the baby room won't close.								
Concepcion Montalvo									
37976					9/9/2008		55		\$0.00
Medium	Work In Progress			9/9/2008 3:55:29 PM					
Vega, Danny	A/C UNIT LEAKING WATER. CAN THIS UNIT BE MOVED IT IS RIGHT ON TOP OF THE PBX UNIT AND LEAKING WATER. PHONES ARE TURN OFF BECAUSE OF THIS								
Cora Ramirez									
38655	Pump House				10/2/2008		32		\$0.00
Medium	Work In Progress			10/2/2008 3:30:57 PM					
Vega, Danny	Remove all equipment, material, toys currently stored in this area.								
Alfredo Holguin									
38792					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:07 AM					
Orozco, Danny	Monthly - La Mesa ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38804					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:12 AM					
Vega, Danny	Monthly - La Mesa ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
38806					10/5/2008	10/11/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:12 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
38808					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:13 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

38809					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:14 AM				
Vega, Danny		Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39156					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress				10/12/2008 12:21:00				
Vega, Danny		Monthly - Northern On-Track Pre-K Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
39447		Classroom			10/24/2008		10		\$0.00
Medium	Work In Progress				10/24/2008 8:28:25 AM				
Vega, Danny		parent center needs a desk and hutch assembled							
Gilbert Trujillo									
39535	Pump House	Pump House			10/28/2008		6		\$0.00
Medium	Work In Progress				10/28/2008 8:37:18 AM				
Jacquez, Ricardo		need to replace air compressor on irrigation well thanks							
Ricardo Jacquez									
39602	Pump House	Pump House			10/30/2008		4		\$0.00
Medium	Work In Progress				10/30/2008 9:07:18 AM				
Lozoya, Manny		please change lock back to original lock on irrigation well thanks							
Ricardo Jacquez									
39689					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:33 AM				
Vega, Danny		Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
39719					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:45 AM				
Vega, Danny		Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39725					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:47 AM				
Vega, Danny		Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39769		Hallway/Corridor			11/3/2008		0		\$0.00
Medium	Work In Progress				11/3/2008 9:40:06 AM				
Sotelo, Enrique		hallway lights need bulbs replaced.							
Gilbert Trujillo									

11/3/2008 3:24:41 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

Count: 23 Work Orders Avg. Age of WO's 42 Total for Northern On-Track Pre-K (LM) 0 \$0.00

Location: Physical Plant Complex

35707 7/6/2008 8/6/2008 120 \$0.00

Medium Work In Progress 7/6/2008 12:20:10 AM

Villalobos, David Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

35864 7/11/2008 115 \$0.00

Medium Work In Progress 7/11/2008 8:59:27 AM

Jacquez, Ricardo 7-9-08 7/9-2
ppd-1.5 ck wwtp
cms-6 wo# 33549
ppd-.5 daily o&m on wwtp

Ricardo Jacquez

36213 Maintenance 7/25/2008 101 \$0.00

Medium Work In Progress 7/25/2008 10:15:21 AM

Sotelo, Enrique please install electrical outlet to cooling duct fan and pilot switch.
Thxs

Michael Munoz

36291 7/28/2008 98 \$0.00

Medium Work In Progress 7/28/2008 3:26:53 PM

Ronquillo, Ruben Purchase a new water tank

Alfredo Holguin

36355 Food Services Parking Lot 7/30/2008 96 \$0.00

Medium Work In Progress SNP 7/30/2008 12:01:33 PM

Ontiveros, Guadalupe AS PER MR. GIOVAS-IF NEAR THE WAREHOUSE GOING FROM THE SHADED AREA TO THE STAIR WAY INTO THE WAREHOUSE IF THEY CAN LEVEL OUT THE PATH WAY. (PLEASE SEE JOHNNY L. IF NEED DIRECTION.)

Mary Garcia

36759 Maintenance 8/7/2008 88 \$0.00

Medium Work In Progress 8/7/2008 9:53:28 AM

Munoz, Michael Need price quote to build an architect table for Tech's Office.

Michael Munoz

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Physical Plant Complex

37066					8/14/2008		81		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/14/2008 11:15:18 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ronquillo, Ruben

Purchase new individual signs to go above doors outside Bldg. indicating as follows:
 -Purchasing Warehouse
 -Instructional Materials
 -Physical Plant Dept./ Construction Dept./Custodial Dept.
 -Custodial Shipping/Receiving
 Also 1 sign for Main Entrance by Nurse Complex indicating as follows:
 Construction Dept.
 Instructional Materials
 Student Nutrition Warehouse
 Student Records
 Transportation
 Physical Plant Department
 Custodial Dept.
 Maintenance Dept.
 Motor Pool
 Purchasing Warehouse
 SEE ALFREDO IF ANY QUESTIONS.

Alfredo Holguin

37074	Food Services				8/14/2008		81		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/14/2008 2:23:06 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph

As per Mike, remove doubled doors and replace with a rolling door. Please see Mike if you have any questions.

Michael Munoz

37767					9/4/2008		60		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/4/2008 8:02:44 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lozoya, Manny

need to replace door lock on water department office does not lock
 thanks

Ricardo Jacquez

37791	Purchasing				9/4/2008		60		\$0.00
-------	------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/4/2008 2:35:30 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Sotelo, Enrique

I would like to have a light switch in my office to control the lights. Currently the switch is in the hall and the one switch controls my office and hallway.

Vicky Lopez

37882	Food Services				9/8/2008		56		\$0.00
-------	---------------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/8/2008 8:10:34 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ontiveros, Guadalupe

Need to add Crusher fines to dock area.

Alfredo Holguin

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Physical Plant Complex
-----------	------------------------

37888		Parking Lot			9/8/2008		56		\$0.00
-------	--	-------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/8/2008 8:19:17 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ronquillo, Ruben		Designate Handicap Parking for Building and Install signage				9/29 - asp Mike route to Ruben			
------------------	--	---	--	--	--	--------------------------------	--	--	--

Alfredo Holguin

37889		Parking Lot			9/8/2008		56		\$0.00
-------	--	-------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/8/2008 8:23:48 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ronquillo, Ruben		Purchase and Install Parking Signs for the entire PPD Complex. (Vistiors Parking, Employee Parking, No Parking- Loading Zone)							
------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

37944					9/9/2008		55		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/9/2008 12:13:23 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador		PLEASE MAKE SCRAPERS/DRAGERS. PLEASE SEE MIKE.							
--------------------	--	--	--	--	--	--	--	--	--

Michael Munoz

38130		Parking Lot			9/16/2008		48		\$0.00
-------	--	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				9/16/2008 11:39:13 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben		Purchase Sign for Physical Plant Parking Plan as per the layout provided. Signs need to be larger than the standard size.							
------------------	--	---	--	--	--	--	--	--	--

Alfredo Holguin

38639	Maintenance	Office			10/2/2008		32		\$0.00
-------	-------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				10/2/2008 9:08:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben		SERVICE FOR ASBESTOS ABATEMENT AND CUT OPENING TO BE DONE IN BETWEEN THE PLUMBING AND THE MAINT. WHS.							
------------------	--	---	--	--	--	--	--	--	--

Ruben Ronquillo

38722	Maintenance				10/3/2008		31		\$0.00
-------	-------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				10/3/2008 3:58:39 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben		Need to install a Fire Extinguisher outside Maint Bldg. (see Mike for details)							
------------------	--	--	--	--	--	--	--	--	--

Michael Munoz

39200	Purchasing				10/13/2008		21		\$0.00
-------	------------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/13/2008 3:55:34 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Gonzales, Angel		Mail Van - Windshield has a crack please replace or repair							
-----------------	--	--	--	--	--	--	--	--	--

Alfredo Holguin

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Physical Plant Complex

39411	Motor Vehicle				10/23/2008		11		\$0.00
Medium	Work In Progress				10/23/2008 10:38:12				
Gonzales, Angel	Purchasing Warehouse Delivery Van - Secure necessary parts (fuel Pump and others) and perform maintenance and repairs as necessary. When ready to do work notify me so i can make arrangements for a loaner vehicle.								

Alfredo Holguin

39604	Purchasing				10/30/2008		4		\$0.00
Medium	Work In Progress				10/30/2008 12:03:22				
Diaz, Sebastian	Could you please have our air unit checked, it has a light on indicating that the filter needs to be checked or replaced.								

Michelle Tellez

39701					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:38 AM				
Diaz, Sebastian	Monthly - Physical Plant FE Inspection - Refer to PM schedule details.								

Margret Villalobos

39757					11/3/2008		0		\$0.00
Medium	Work In Progress				11/3/2008 12:24:08 AM				
Villalobos, Margret	Monthly - PPD - Quarterly Meeting - Refer to PM schedule details.								

Margret Villalobos

Count: 22 Work Orders	Avg. Age of WO's	58	Total for Physical Plant Complex	0	\$0.00				
------------------------------	-------------------------	-----------	---	----------	---------------	--	--	--	--

Location: Riverside ES

35708					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:10 AM				
Villalobos, David	Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.								

Margret Villalobos

35753	New Wing 1/02				7/8/2008		118		\$0.00
Medium	Work In Progress				7/8/2008 10:29:47 AM				
Ronquillo, Ruben	Need window repaired room 137 due to break in 20x21 Add two more broken windows custodian found windows in corrdor by cafe.								

Carlos Hernandez

36586	Cafeteria				8/4/2008		91		\$0.00
Medium	Work In Progress				8/4/2008 9:53:07 AM				
Moncayo, Fernando	Oven with Grill is not working/heating up at all.								
Alma Terrell	Emilia Carrillo - SNP Manager 589-2550								

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Riverside ES

36587		Cafeteria			8/4/2008		91		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/4/2008 9:54:27 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Moncayo, Fernando Walk-In Refrigerator is leaking alot of water

Emilia Carrillo - SNP Manager 589-2550

Alma Terrell

36669					8/6/2008		89		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			8/6/2008 8:39:54 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Carrasco, Danny need fuses for a/c units

Carlos Hernandez

36987					8/12/2008		83		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/12/2008 4:12:40 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Hernandez, Carlos weeds are taking over along all fence lines and in parking area. please address. once cut.treat fence lines to prevent growth. call mike if you have questions. thxs

Michael Munoz

37148	New Wing 1/02				8/18/2008		77		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/18/2008 3:12:30 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph need to change door locks on classrooms outter door (principal dosn't want door handles on on outside doors)

Carlos Hernandez

37255	Main Building				8/20/2008		75		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/20/2008 3:43:37 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos need electrical outlet in storage room

Carlos Hernandez

37259	Main Building				8/20/2008		75		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/20/2008 3:45:59 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos need to install light fixture in nurses office (bathroom) and need light switch for middle wing bathroom

Carlos Hernandez

37260	Main Building	Library			8/20/2008		75		\$0.00
-------	---------------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/20/2008 3:46:58 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos need to install electrical outlet

Carlos Hernandez

37440		Portables			8/27/2008		68		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/27/2008 9:30:51 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben broken window on new portable due to vandalism (Case# 2008-1239)

Carlos Hernandez

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Riverside ES

37732		Portables			9/3/2008		61		\$0.00
Medium	Work In Progress			9/3/2008 8:16:37 AM					
Ronquillo, Ruben	need glass repaired new portable rear glass 40 3/4 by 12 1/2 thanks								
Carlos Hernandez									
37820					9/5/2008		59		\$0.00
Medium	Work In Progress			9/5/2008 8:39:36 AM					
Gonzalez, Salvador	Need to make a canopy for behind of cafeteria.								
Michael Munoz									
38762					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:23:56 AM					
Hernandez, Carlos	Yearly - Riverside ES U-2 Unit Heater Gas Yearly - Refer to PM schedule details.								
Margret Villalobos									
38796					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:09 AM					
Orozco, Danny	Monthly - Riverside ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38956		Cafeteria			10/6/2008		28		\$0.00
Medium	Work In Progress			10/6/2008 10:43:44 AM					
Moncayo, Fernando	TUBING INSIDE DISHMACHINE KEEPS ON DRIPPING WATER -EVEN WHEN MACHINE IS OFF. EMILIA CARRILLO - SNP MANAGER 589-2550								
Alma Terrell									
38999					10/7/2008		27		\$0.00
Medium	Work In Progress			10/7/2008 12:27:59 PM					
Hernandez, Carlos	please re-install fence that was removed.Thanks								
Alfredo Holguin									
39417	Main Building	Cafeteria			10/23/2008		11		\$0.00
Medium	Work In Progress			10/23/2008 1:57:07 PM					
Castillo, Carlos	Asp PM 38766 1- Exit Sign in Cafeteria not working.								
Carlos Hernandez									
39503					10/27/2008		7		\$0.00
Medium	Work In Progress			10/27/2008 10:18:49					
Carbajal, Jimmy	I HAVE A VAC THAT NEEDS TO BE FIXED,THKS								
Daniel Mata									
39504					10/27/2008		7		\$0.00
Medium	Work In Progress			10/27/2008 10:20:07					
Carbajal, Jimmy	I HAVE A DOLLY THAT ITS TIRES ARE FLAT. THANKS								
Daniel Mata									

11/3/2008 3:24:42 PM

Page 93 of 118

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Riverside ES

39543					10/28/2008		6		\$0.00
Medium	Work In Progress			10/28/2008 1:28:41 PM					
Lozoya, Manny	remove lock from the flashing lights -								
Cora Ramirez									
39660					10/31/2008		3		\$0.00
Medium	Work In Progress			10/31/2008 3:06:06 PM					
Lara, Ralph	needs parts for handicap automatic door opener westside door								
Carlos Hernandez									
39693					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:35 AM					
Hernandez, Carlos	Monthly - Riverside ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
39726					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:47 AM					
Hernandez, Carlos	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39737					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:51 AM					
Hernandez, Carlos	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
Count: 25 Work Orders			Avg. Age of WO's 49			Total for Riverside ES	0		\$0.00

Location: San Miguel ES

35664					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress			7/6/2008 12:19:56 AM					
Vega, Danny	Yearly - San Miguel ES Emer. Light Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
35687					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress			7/6/2008 12:20:03 AM					
Vega, Danny	Yearly - San Miguel ES Exit Sign Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
37343					8/22/2008		73		\$0.00
Medium	Work In Progress			8/22/2008 3:24:23 PM					
Lozoya, Manny	Asp Mike, please core back to GM 6 or 7 pin.								

11/3/2008 3:24:42 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: San Miguel ES

38658	Pump House				10/2/2008		32		\$0.00
Medium	Work In Progress				10/2/2008 3:33:23 PM				
Vega, Danny		Remove all material, equipment and any other items stored in this area. this is not a storage area.							
Alfredo Holguin									
39326					10/21/2008		13		\$0.00
High	Work In Progress				10/21/2008 7:40:12 AM				
Ontiveros, Joe		need to open gas valve to boiler and check for leaks so HVACR can do the start-up. Thxs							
Michael Munoz									
39334	Portables				10/21/2008		13		\$0.00
Medium	Work In Progress				10/21/2008 11:17:54				
Estrada, Jesus		Please re-carpet dbl portable northwest corner mescalero.Thxs(#42/goose)							
Michael Munoz									
39565	Main Building				10/29/2008		5		\$0.00
Medium	Work In Progress				10/29/2008 7:32:46 AM				
Lozoya, Manny		please change cores to where the techs can have access to the back door of the boiler room so they can service equipment.							
Michael Munoz									
Count: 7 Work Orders			Avg. Age of WO's 54				Total for San Miguel ES	0	\$0.00

Location: Santa Teresa ES

35630					7/6/2008	7/14/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:45 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
35641					7/6/2008	7/14/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:48 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
35713					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:12 AM				
Villalobos, David		Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

36676					8/6/2008		89		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/6/2008 9:53:35 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
 MANNY; THE BOTTOM LOCKING PIN TO THE DR. AT THE MAINT. STORAGE RM. BROKE. WOULD YOU CHECK IT OUT SO WE CAN SECURE THIS RM. THANKS.

Gerardo Marquez

37063	Main Building	Classroom			8/14/2008		81		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	CASA AZUL			8/14/2008 11:10:59 AM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Marquez, Gerardo
 PE COACH NEEDS A PEGBOARD CONSTRUCTED AND SET UP (FOR PE EQUIP.) THANKS.

Rita Mendez

37139					8/18/2008		77		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/18/2008 11:44:10 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
 CALI; HAND DRYER IN BOYS RRM. DOES NOT SHUT OFF AT TIMES, AND SOMETIMES STARTS BY ITSELF. NEED FOR YOU TO CHECK IT OUT. I TURNED THE BREAKER OFF , BECAUSE A STUDENT BURNED HIMSELF ON IT AND REPORTED IT TO THE OFFICE.

Gerardo Marquez

37581					8/31/2008		64		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				8/31/2008 12:25:24 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo
 Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.

Margret Villalobos

37687		Classroom			9/2/2008		62		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/2/2008 11:24:37 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben
 One window on Portable is jammed intruder tried to get in thru window on east portable, also middle hallway workroom broken (window) cracked -B-Wing. (Case# 2008-08926)

Pablo Diaz

37927					9/8/2008		56		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				9/8/2008 3:57:59 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo		9/4/08				9/4-8			
------------------	--	--------	--	--	--	-------	--	--	--

1-INSP. BLDG. & GRNDS. PICKED UP TRASH.
 2-CLEANED OFF ENTRANCES & SIDEWALKS.
 1-CLEANED & IJNSP. P.G. AREAS.
 2-ADJ. LOCKSETS, & DR. CLOSERS @ PORTABLES A, & B.
 2-CLEANED & INSP. MECH. RMS.

Gerardo Marquez

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
38528					9/30/2008		34		\$0.00
Medium	Work In Progress			9/30/2008 12:25:58 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES-A-16 Fan Exhaust (SemiA) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38798					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:10 AM					
Orozco, Danny	Monthly - Santa Teresa ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38835					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:23 AM					
Marquez, Gerardo	Yearly - Santa Teresa ES-H6 Rooftop Fur (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38836					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:24 AM					
Marquez, Gerardo	Yearly - Santa Teresa ES-U2 Heat Gas (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39140					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress			10/12/2008 12:20:54					
Diaz, Pablo	Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
39158					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress			10/12/2008 12:21:01					
Marquez, Gerardo	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39449	Main Building	Portables			10/24/2008		10		\$0.00
Medium	Work In Progress	ART PORTABLE		10/24/2008 9:06:50 AM					
Marquez, Gerardo	A PAPER RACK IS NEEDED TO BE SET UP IN THE CLASSROOM. THANKS.								
<u>Rita Mendez</u>									
39454	Main Building	Portables			10/24/2008		10		\$0.00
Medium	Work In Progress	ART PORTABLE		10/24/2008 10:59:50					
Marquez, Gerardo	BRACKETS AND SHELF NEED TO BE SET UP IN CLASSROOM. THANKS.								
<u>Rita Mendez</u>									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

39559					10/28/2008		6		\$0.00
Medium	Work In Progress				10/28/2008 3:54:22 PM				
Gonzales, Angel		ANGEL, STILL NEED BOBCAT TO FILL IN WASHOUTS , WHENEVER ITS FREED UP.							
Gerardo Marquez									
39680					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:30 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
39728					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:48 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39739					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:52 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
Count: 21 Work Orders		Avg. Age of WO's 47				Total for Santa Teresa ES	0		\$0.00

Location: Santa Teresa HS

35520		Football Field			7/2/2008		124		\$0.00
Medium	Work In Progress				7/2/2008 8:03:34 AM				
Castillo, Carlos		NEED TO HAVE ONE LIGHT AT FOOBALL FIELD CHECKED, NOT LIGHTING, WESTSIDE OF FIELD, BEHIND PRESSBOX.							
Arturo Nunez									
35552					7/6/2008	7/12/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:21 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
35569					7/6/2008	7/14/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:26 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
35598					7/6/2008	7/27/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:19:35 AM				
Orozco, Danny		Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

35666					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress			7/6/2008 12:19:56 AM					
Nunez, Arturo	Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35689					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress			7/6/2008 12:20:04 AM					
Nunez, Arturo	Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35711					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress			7/6/2008 12:20:11 AM					
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35756		Athletic Field			7/8/2008		118		\$0.00
Medium	Work In Progress			7/8/2008 11:03:17 AM					
Ontiveros, Guadalupe	Remove goal post and install at CMS.								
<u>Terry Alvarado</u>									
36329	Gymnasium				7/29/2008		97		\$0.00
Medium	Work In Progress			7/29/2008 3:45:02 PM					
Boyd, David	Locker Room and Offices water leak on the roof.								
<u>Manuel Prospero</u>									
36384					7/31/2008		95		\$0.00
Medium	Work In Progress			7/31/2008 8:05:50 AM					
Prospero, Manuel	7/30/08. 8 HRS FINISH PAINTING 300'S HALLWAY.		7/30 - 8						
<u>Manuel Prospero</u>									
36510					8/3/2008	8/9/2008	92		\$0.00
Medium	Work In Progress			8/3/2008 12:20:16 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36645	Cafeteria (2005)	Cafeteria			8/5/2008		90		\$0.00
Medium	Work In Progress			8/5/2008 1:01:49 PM					
Moncayo, Fernando	WATER IS LEAKING FROM UNDERNEATH THE DISHWASHING MACHINE								
	OLGA BUSTAMANTE - SNP MANAGER 589-9836								
Alma Terrell									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

37137	Cafeteria (2005)	Cafeteria			8/18/2008		77		\$0.00
Medium	Work In Progress			8/18/2008 11:08:29 AM					

Moncayo, Fernando
Washing Machine is leaking water (underneath machine) - Left message with Fernando

Olga Bustamante - SNP Manager 589-5332

Alma Terrell

37359	Applied Science				8/25/2008		70		\$0.00
Medium	Work In Progress			8/25/2008 12:49:37 PM					

Ontiveros, Guadalupe
backfill against perimeter sidewalks so that there is less than a 4" drop.

Alfredo Holguin

37386					8/26/2008		69		\$0.00
Medium	Work In Progress			8/26/2008 7:30:49 AM					

Ontiveros, Guadalupe
Pedestrian Gate on South side that goes to the Bluffs. - Install taller gate to prevent access through bottom of gate.

Alfredo Holguin

37545					8/31/2008	9/6/2008	64		\$0.00
Medium	Work In Progress			8/31/2008 12:25:12 AM					

Nunez, Arturo
Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

37562					8/31/2008	9/21/2008	64		\$0.00
Medium	Work In Progress			8/31/2008 12:25:18 AM					

Orozco, Danny
Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

37958					9/9/2008		55		\$0.00
Medium	Work In Progress			9/9/2008 2:33:14 PM					

Castillo, Carlos
NEED SOME ASSISTANCE ON CHECKING OUTSIDE LIGHTING ON CAF. NEW BUILDING, VOC. BUILDING, AND MAIN BUILDING.

Arturo Nunez

38018					9/11/2008		53		\$0.00
Medium	Work In Progress			9/11/2008 9:07:28 AM					

Prospero, Manuel
9/9/08. 4HRS FIX WATER LEAK ON GYM ROOF. 4HRS CHANGED CEILIN TILES ON ROOMS2,4,6.

Manuel Prospero

38073					9/14/2008		50		\$0.00
Medium	Work In Progress			9/14/2008 12:23:08 AM					

Ontiveros, Guadalupe
Monthly - Santa Teresa HS Soil Sampling - Refer to PM schedule details.

Margret Villalobos

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

38255		Classroom			9/19/2008		45		\$0.00
Medium	Work In Progress	RM 207			9/19/2008 12:14:53 PM				
Villalobos, Margret		Unit is working fine, problem with comm link, need to contact Trane.				Asp Jose Ambriz, need to schedule, when there is no students. E-mailed to J. Velasquez 9/19/08			
<u>Jose Ambriz</u>									
38257					9/19/2008		45		\$0.00
Medium	Work In Progress				9/19/2008 2:26:25 PM				
Ambriz, Jose		WE NEED SOME INSULATION FOR DUCTWORK IN ROOM 12.							
<u>Manuel Prospero</u>									
38346					9/23/2008		41		\$0.00
Medium	Work In Progress				9/23/2008 9:02:34 AM				
Ambriz, Jose		THE FOLLOWING F.C.U.'S HAVE A COMMUNICATION PROBLEM BETWEEN MASTER AND SLAVE, 207M SCC IS OF LINE, 205M SCC IS OFF LINE, AND 203 SCC IS IF LINE. CAN WE PLEASE HAVE THEN CHECKED. THANK YOU.							
<u>Arturo Nunez</u>									
38539					9/30/2008		34		\$0.00
Medium	Work In Progress				9/30/2008 12:26:04 AM				
Prospero, Manuel		Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
38544	Cafeteria (2005)	Cafeteria			9/30/2008		34		\$0.00
Medium	Work In Progress				9/30/2008 8:10:55 AM				
Moncayo, Fernando		Comments from Ecolab Report: Dishwasher is not filling up. Pre-spray hose id damaged & should be replaced. Olga Bustamante SNP MANAGER 58905332							
<u>Jacqueline Aguilar</u>									
38595	Gymnasium				10/1/2008		33		\$0.00
Medium	Work In Progress				10/1/2008 12:31:34 PM				
Nunez, Arturo		REPLACE STAINED AND BROKEN CIELING TILES							
<u>Michael Munoz</u>									
38685	Concession				10/2/2008		32		\$0.00
Medium	Work In Progress				10/2/2008 3:53:46 PM				
Villalobos, David		CONSESSION STAND HANDI-CAP COMMODE WILL NOT FLASH ON BOYS BATHROOM NEED TO BE REPAIR,HAVEING FOOTBOLL GAMES.							
<u>Manuel Prospero</u>									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

38691					10/3/2008		31		\$0.00
Medium	Work In Progress			10/3/2008 7:59:21 AM					
Munoz, Michael	FRONT GATE NEEDS A GATE STOPER 6 GATE HINGES POLE IS 7 INCH WIDE 1 GATESTOPPER 1 POLE FOR GATE STOPPER.								
Manuel Prospero									
38753					10/5/2008	10/11/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:23:53 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
38754					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:23:53 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
38755					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
Margret Villalobos									
38756					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Yearly - Santa Teresa HS H-6 Rftop Furn Yearly - Refer to PM schedule details.								
Margret Villalobos									
38757					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Yearly - Santa Teresa HS R-9 Radiator Ht Wtr 2yr - Refer to PM schedule details.								
Margret Villalobos									
38758					10/5/2008	10/21/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:23:55 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
Margret Villalobos									
38799					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress			10/5/2008 12:24:10 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

38896					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:46 AM				
Prospero, Manuel		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
38897					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:46 AM				
Prospero, Manuel		Yearly - Santa Teresa HS I-4 Fan Coil Unit Yearly - Refer to PM schedule details.							
Margret Villalobos									
38898					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:46 AM				
Prospero, Manuel		Monthly - Santa Teresa HS C-12 Chm Feeder Semimntly - Refer to PM schedule details.							
Margret Villalobos									
38899					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:47 AM				
Prospero, Manuel		Yearly - Santa Teresa HS U-2 Unit Ht Gas Yearly - Refer to PM schedule details.							
Margret Villalobos									
38992	Library				10/7/2008		27		\$0.00
Medium	Work In Progress				10/7/2008 9:54:07 AM				
Lara, Ralph		LIBRARY CONFERENCE ROOM LOCK ON DOOR TO HALLWAY IS BROCK							
Manuel Prospero									
39059	Library	Library			10/9/2008		25		\$0.00
Medium	Work In Progress				10/9/2008 9:00:13 AM				
Lara, Ralph		Key tumblers have fallen out on two doors Multi media and lib conf room							
Rosa Hood									
39164					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress				10/12/2008 12:21:05				
Nunez, Arturo		Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.							
Margret Villalobos									
39344					10/21/2008		13		\$0.00
Medium	Work In Progress				10/21/2008 3:13:05 PM				
Villalobos, David		NEED SOME ASSISTANCE ON LEAK TEST GAS LINES ON WELDING BOTHS, THERE SEEMS TO BE A GAS LEAK, BUT CAN'T LOCATE.							
Arturo Nunez									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

39396	Main Building	Choral			10/22/2008		12		\$0.00
Medium	Work In Progress				10/22/2008 3:57:04 PM				

Lara, Ralph
Door from Band Room Top Corner broken, needs to be replaced
Thank you,
Rosa

Rosa Hood

39398	Main Building	Hallway/Corridor			10/22/2008		12		\$0.00
Medium	Work In Progress				10/22/2008 3:59:35 PM				

Prospero, Manuel
Remove lockers in hallway near counseling area and across from Main office
Thank you,
Rosa

Rosa Hood

39399	Main Building	Office			10/22/2008		12		\$0.00
Medium	Work In Progress				10/22/2008 4:01:51 PM				

Estrada, Jesus
Mr. Kelch our principal would like new carpet installed in all the offices in the main office area
Thank you,
Rosa
Mr. Nunez has already begun the painting

Rosa Hood

39400	Main Building	Hallway/Corridor			10/22/2008		12		\$0.00
Medium	Work In Progress				10/22/2008 4:04:16 PM				

Prospero, Manuel
Mr. Kelch would like the all the hallways painted
Thank you,
Rosa
Mr. Nunez is painting the office in the main office area

Rosa Hood

39412	Dressing Rooms				10/23/2008		11		\$0.00
Medium	Work In Progress				10/23/2008 11:11:35				

Lara, Ralph
NEED TO HAVE A RESTROOM PILLASTER REPLACED FOR BOYS FOOTBALL DRESSING RESTROOM , TO INSTALL DOOR AT H.C. COMMODE. SIZES WERE FAXED TO MR. RONQUILLO THANK YOU.

Arturo Nunez

39541	Main Building	Office			10/28/2008		6		\$0.00
Medium	Work In Progress				10/28/2008 1:14:24 PM				

Lara, Ralph
We need the locks on the attendacne (Anna Perez) door to be the same so that admin can open both top and bottom parts of the door with one key
Thank you,
Rosa

Rosa Hood

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

39542	Main Building	Office			10/28/2008		6		\$0.00
-------	---------------	--------	--	--	------------	--	---	--	--------

Medium	Work In Progress			10/28/2008 1:18:25 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ronquillo, Ruben
We need signs to indicate what building is what since we do not have a front entrance. Please feel free to call me or Art Nunez so that we can be more specific
Thank you,
Rosa

Rosa Hood

39573	Cafeteria (2005)				10/29/2008		5		\$0.00
-------	------------------	--	--	--	------------	--	---	--	--------

High	Work In Progress			10/29/2008 10:36:44					
------	------------------	--	--	---------------------	--	--	--	--	--

Orozco, Danny
doors to serving area went down on when the alarm went off. this is a safety issue because doors slams down w/o waring. please contact company to reveiw and see if an anticipator can and could be installed as per our conversation.
thxs

Michael Munoz

39648					10/31/2008		3		\$0.00
-------	--	--	--	--	------------	--	---	--	--------

Medium	Work In Progress			10/31/2008 9:49:48 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Castillo, Carlos
NEED SOME ASSISTANCE WITH A WALL PLUG, AND PIG TAIL FOR KILN IN ROOM # 601. THEY ARE FRIED, NEED TO BE REPLACED.

Arturo Nunez

39695					11/2/2008	11/8/2008	1		\$0.00
-------	--	--	--	--	-----------	-----------	---	--	--------

Medium	Work In Progress			11/2/2008 12:24:36 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Nunez, Arturo
Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

39730					11/2/2008	11/10/2008	1		\$0.00
-------	--	--	--	--	-----------	------------	---	--	--------

Medium	Work In Progress			11/2/2008 12:24:49 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Prospero, Manuel
Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

39740					11/2/2008	11/10/2008	1		\$0.00
-------	--	--	--	--	-----------	------------	---	--	--------

Medium	Work In Progress			11/2/2008 12:24:53 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Prospero, Manuel
Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

39756					11/2/2008	12/3/2008	1		\$0.00
-------	--	--	--	--	-----------	-----------	---	--	--------

Medium	Work In Progress			11/2/2008 12:24:59 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Prospero, Manuel
Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

Count: 56 Work Orders			Avg. Age of WO's 47			Total for Santa Teresa HS	0		\$0.00
------------------------------	--	--	----------------------------	--	--	----------------------------------	----------	--	---------------

11/3/2008 3:24:42 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

35599					7/6/2008	7/27/2008	120		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress				7/6/2008 12:19:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

35712					7/6/2008	8/6/2008	120		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/6/2008 12:20:11 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

36170	North Building	Custodial			7/24/2008		102		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/24/2008 7:42:22 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel pete, the truck 39 needs a complete tune up i need to have it ready for the school year. thank you.

Ismael Rodriguez

36511					8/3/2008	8/9/2008	92		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				8/3/2008 12:20:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

36757					8/7/2008		88		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				8/7/2008 9:33:54 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose Please order condensation pump replacement. 40 ea. little giant low rise pumps cat#554200, vcc-20ul or 2ouls, 40 ea. 1/2" 90 deg. ells. Slipxthd fmle, 40 ea. SPRTB-6 24x24 metal grilles, 40 ft. 3/4"ODx 5/8"ID clear vinyl tube, 60 ea. 3 amp fuses, box of orange electrical wire nuts, and box of insulated female and male solderless terminals. I need this asap when old condensate pumps stop working i can't repair them anymore.

Jaime Mijarez

36903	North Building	Classroom			8/11/2008		84		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room 3A			8/11/2008 3:12:40 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Mijarez, Jaime 1. Portable leaks when it rains.

Laura Parra

37603					8/31/2008	9/6/2008	64		\$0.00
-------	--	--	--	--	-----------	----------	----	--	--------

Medium	Work In Progress				8/31/2008 12:25:31 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Mijarez, Jaime Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

37771	Gym (1997)				9/4/2008		60		\$0.00
High	Work In Progress				9/4/2008 8:21:25 AM				
Mijarez, Jaime		please reroute overflow lines from a/c. do not drain into mop sink and install strainer also. this will prevent from sink overflowing and damaging gym floor. (2nd time)							
Michael Munoz									
37808					9/4/2008		60		\$0.00
Medium	Work In Progress				9/4/2008 4:13:04 PM				
Munoz, Michael		North Bldg. - Build concrete Pad for dumpsters.							
Alfredo Holguin									
38251	Library	Library			9/19/2008		45		\$0.00
Medium	Work In Progress	Ms. Swaim-			9/19/2008 10:10:45 AM				
Castillo, Carlos		Need power strip for the wall. The outlets are overloaded. Wires and cords need to be contained.							
Parra, Laura									
38390		Parking Lot			9/24/2008		40		\$0.00
Medium	Work In Progress				9/24/2008 8:34:16 AM				
Ontiveros, Guadalupe		Need to sweep all of the parking lot for new stripping. (Check w/Alfredo on date of when contractor will be coming out).							
Alfredo Holguin									
38505					9/29/2008		35		\$0.00
Medium	Work In Progress				9/29/2008 1:43:22 PM				
Mijarez, Jaime		Need to install signs. Below is the recommendaton, but please ck w/site administrator first on location.							
Daniel Rosales									
38535					9/30/2008		34		\$0.00
Medium	Work In Progress				9/30/2008 12:26:01 AM				
Mijarez, Jaime		Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.							
Margret Villalobos									
38596					10/1/2008		33		\$0.00
Medium	Work In Progress				10/1/2008 12:33:20 PM				
Soria, Mike		CUT WEEDS AT NEW LANDSCAPING IN FRONT OF SOUTH BUILDING.							
Michael Munoz									
38597					10/1/2008		33		\$0.00
Medium	Work In Progress				10/1/2008 12:34:21 PM				
Soria, Mike		OPEN DRAIN BY MORGAN BUILDING. CUT WEEDS AND BARRICADE. SAFETY HAZARD.							
Michael Munoz									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

38800					10/5/2008	10/26/2008	29		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:10 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny Monthly - Santa Teresa MS Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

38869					10/5/2008	11/5/2008	29		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:36 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Mijarez, Jaime Yearly - Santa Teresa MS U2 (Heat Gas)(Yearly) - Refer to PM schedule details.

Margret Villalobos

39102	North Building	Classroom			10/10/2008		24		\$0.00
-------	----------------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	Room 1			10/10/2008 2:36:56 PM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Mijarez, Jaime Hand made wooden case in recognition hall needs to be installed on the wall. The case will need a 2x6 wooden base, plexiglass doors and mounting hardware

Laura Parra

39103	South Building	Office			10/10/2008		24		\$0.00
-------	----------------	--------	--	--	------------	--	----	--	--------

Medium	Work In Progress	Social Worker-			10/10/2008 2:38:07 PM				
--------	------------------	----------------	--	--	-----------------------	--	--	--	--

Mijarez, Jaime Ceiling is leaking next to the window

Laura Parra

39113	South Building	Office			10/10/2008		24		\$0.00
-------	----------------	--------	--	--	------------	--	----	--	--------

Medium	Work In Progress	Assistant			10/10/2008 3:39:59 PM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Castillo, Carlos Need computer outlet and phone outlet to be placed on the opposite wall as to where its actually at

Laura Parra

39295					10/20/2008		14		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/20/2008 1:44:20 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben North bldg office exterior window needs to be replaced and also metal molding around window needs to be replaced.

Jaime Mijarez

39335					10/21/2008		13		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/21/2008 12:48:47				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose N.bldg Hp 36 lobby has a bad motor that is making a loud noise.

Jaime Mijarez

39406					10/23/2008		11		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/23/2008 7:58:22 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos See if we can repair the timers and order additional triggers.
(see Jaime if you have any questions).

Michael Munoz

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

39438	South Building	Hallway/Corridor			10/23/2008		11		\$0.00
Medium	Work In Progress			10/23/2008 3:54:21 PM					
Ambriz, Jose	Leak in lines.								
Jose Ambriz									
39544	North Building	Custodial			10/28/2008		6		\$0.00
Medium	Work In Progress			10/28/2008 1:40:16 PM					
Lara, Ralph	rafa,i need for you to change a cylinder for a choirs teacher storage room.thank you.								
Ismael Rodriguez									
39575	North Building	Custodial			10/29/2008		5		\$0.00
Medium	Work In Progress			10/29/2008 1:28:03 PM					
Carbajal, Jimmy	jimmy, i need for you to check a vaccum the wiring is makeing electrical shorts.the serial number is #0085								
Ismael Rodriguez									
39696					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:36 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
39732					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:50 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39741					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:53 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39755					11/2/2008	12/3/2008	1		\$0.00
Medium	Work In Progress			11/2/2008 12:24:58 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 30 Work Orders			Avg. Age of WO's	40	Total for Santa Teresa MS		0		\$0.00

Location: Sunland Park ES

35710					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress			7/6/2008 12:20:11 AM					
Villalobos, David	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									

11/3/2008 3:24:42 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
35734					7/7/2008		119		\$0.00
Medium	Work In Progress				7/7/2008 3:30:23 PM				
Lara, Ralph		WE NEED EXTRA KEY FROM LIBRARY							
Joel Herrera									
37362					8/25/2008		70		\$0.00
Medium	Work In Progress				8/25/2008 2:14:46 PM				
Lara, Ralph		WE NEED REPLACE CLASS ROOMS DOORS THEY ARE TO RUSTING							
Joel Herrera									
37593					8/31/2008		64		\$0.00
Medium	Work In Progress				8/31/2008 12:25:27 AM				
Herrera, Joel		Monthly - Sunland Park ES A-1 Semiannual MCD - Refer to PM schedule details.							
Margret Villalobos									
37594					8/31/2008		64		\$0.00
Medium	Work In Progress				8/31/2008 12:25:28 AM				
Herrera, Joel		Monthly - Sunland Park ES A-1 Semiannual MCS2 - Refer to PM schedule details.							
Margret Villalobos									
37597					8/31/2008		64		\$0.00
Medium	Work In Progress				8/31/2008 12:25:29 AM				
Herrera, Joel		Monthly - Sunland Park ES A-13 Quarterly WREH - Refer to PM schedule details.							
Margret Villalobos									
37891	Main Building				9/8/2008		56		\$0.00
Medium	Work In Progress				9/8/2008 9:02:24 AM				
Ronquillo, Ruben		FXT-SP-030 - Missing Boiler Room (S) asp PM 37589							
Joel Herrera									
38310					9/22/2008		42		\$0.00
Medium	Work In Progress	outside			9/22/2008 2:14:13 PM				
Herrera, Joel		Please replace broken tiles located by the main entrance.							
Jessica Lopez									
38335		Portables			9/22/2008		42		\$0.00
High	Work In Progress				9/22/2008 4:27:02 PM				
Acuna, Sal		Sal and Jimmy I need your help in moving furniture out of portable "C" at Sunland Park Elem. Aztec flooring will start on Wednesday 9/23 at 9:00 am.							
Jesus Estrada									
38349					9/23/2008		41		\$0.00
Medium	Work In Progress	Portable D & E			9/23/2008 10:00:06 AM				
Estrada, Jesus		Please install carpet in Portable D and E.							
Jessica Lopez									

11/3/2008 3:24:42 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Sunland Park ES

38355					9/23/2008		41		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	38		9/23/2008 2:13:10 PM					
--------	------------------	----	--	----------------------	--	--	--	--	--

Herrera, Joel
Mr. Herrera please assemble kidney table found in storage unit. And please take it to Ms. Gardea room #38.

Jessica Lopez

38468					9/26/2008		38		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/26/2008 1:25:56 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos
MS. PEREZ WANTS TWO OUTLETS AT PLAYGROUNDS AREA IF WE CAN DO POSSIBLE. THANK YOU CALI

Joel Herrera

38567					9/30/2008		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/30/2008 2:42:50 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph
DOOR'S KNOB HAS A PIECE OF PENCIL LEAD STUCK IN KEY OPENING AND DOOR CAN'T BE UNLOCKED AT CLASS ROOM #28

Joel Herrera

38568					9/30/2008		34		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/30/2008 3:01:23 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph
NEED TO FIXED HALL WAY DOOR IN SOUTH SIDE ALSO G.Y.M DOOR IS NOT WORKING

Joel Herrera

38650					10/2/2008		32		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Playground		10/2/2008 3:19:23 PM					
--------	------------------	------------	--	----------------------	--	--	--	--	--

Villalobos, Margret
WE HAVE ANT HILL ON KINDERS PLAYGROUNDS AREA 10/2 - Emailed Watson

Joel Herrera

38801					10/5/2008	10/26/2008	29		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress			10/5/2008 12:24:11 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Orozco, Danny
Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

38860					10/5/2008	11/5/2008	29		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress			10/5/2008 12:24:33 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Herrera, Joel
Yearly - Sunland Park ES H-6 Furnance Yearly - Refer to PM schedule details.

Margret Villalobos

38861					10/5/2008	11/5/2008	29		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress			10/5/2008 12:24:33 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Herrera, Joel
Yearly - Sunland Park ES I-4 Fan Coil Yearly - Refer to PM schedule details.

Margret Villalobos

11/3/2008 3:24:42 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

38862					10/5/2008	11/5/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:33 AM				
Herrera, Joel		Yearly - Sunland Park ES U-2 Gas Heater Yearly - Refer to PM schedule details.							
Margret Villalobos									
38864					10/5/2008	10/11/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:34 AM				
Herrera, Joel		Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
38865					10/5/2008	10/13/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:34 AM				
Herrera, Joel		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
38958					10/6/2008		28	1	\$25.00
Medium	Work In Progress	library			10/6/2008 12:29:14 PM				
Herrera, Joel		Attach electrical strip to new computer cart.							
Jessica Lopez						10/24 -NON ELECTRICAL, NEED BM TO OBTAIN A POWER SURGE STRIP AND INSTALL HIMSELF. C. CASTILLO. Route to Joel 11/3/08			
39143					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress				10/12/2008 12:20:55				
De Santiago, Baudelio		Monthly - QRTLY BDLG INSP REPORT (SP) - Refer to PM schedule details.							
Margret Villalobos									
39160					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress				10/12/2008 12:21:04				
Herrera, Joel		Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
39348	Main Building	Restroom (Girls)			10/21/2008		13		\$0.00
Medium	Work In Progress				10/21/2008 3:31:59 PM				
Villalobos, David		WE HAVE GIRLS RESTROOM'S SINK CLOGGED							
Joel Herrera									
39539	Main Building				10/28/2008		6		\$0.00
Medium	Work In Progress				10/28/2008 11:18:00				
Estrada, Jesus		Tile is needed in lounge #34.							
Jesus Estrada									
39617	Main Building	Cafeteria			10/30/2008		4		\$0.00
Medium	Work In Progress				10/30/2008 1:52:44 PM				
Carbajal, Jimmy		maquina para pulir el piso. El piso necesita brillo. Polish the floor.							
Baudelio De Santiago									

11/3/2008 3:24:42 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

39653					10/31/2008		3		\$0.00
Medium	Work In Progress				10/31/2008 11:41:18				
Holguin, Alfredo		Purchase and install playground equipment including metal shade structures.							
Alfredo Holguin									
39697					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:37 AM				
Herrera, Joel		Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
39733					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:50 AM				
Herrera, Joel		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39742					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:53 AM				
Herrera, Joel		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
Count: 31 Work Orders			Avg. Age of WO's 37			Total for Sunland Park ES	1		\$25.00

Location: Sunrise ES

35709					7/6/2008	8/6/2008	120		\$0.00
Medium	Work In Progress				7/6/2008 12:20:10 AM				
Villalobos, David		Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36205					7/25/2008		101		\$0.00
Medium	Work In Progress				7/25/2008 8:27:04 AM				
Lozoya, Manny		CLASSS RM. 207 DOOR HANDLE,AND LOCK CYLINDER NOT OPENING DOOR PROPERLY. THANKS							
Paul Quinones									
36336					7/29/2008		97		\$0.00
Medium	Work In Progress				7/29/2008 3:57:08 PM				
Ronquillo, Ruben		BROKEN WALL WINDOW IN WING 1,LOCATION RM.107 WINDOW SIZE 2'X2' DOUBLE PANE GLASS WINDOW W/ TINT. THANKS							
Paul Quinones									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Sunrise ES

36378					7/30/2008		96		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			7/30/2008 4:19:55 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny DOOR IN WING B ELSOL HALL WAY.DURING FIRE DRILL IN THE MORNING 7-30-08.RIGHT SIDE DOOR WOULD NOT CLOSE DURING DRILL.

Paul Quinones

37422					8/26/2008		69		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/26/2008 4:19:28 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Joe HOSE BIBB ON WALL NEXT TO UPPER PLAY GROUND WATER LEAKING,BROKEN HANDLE.

Paul Quinones

38008	Main Building	Classroom			9/10/2008		54		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/10/2008 4:02:35 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny Need key # for room 206 1c 32. The key is bent

Joanne Munoz

38009	Main Building	Classroom			9/10/2008		54		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Estrellita work		9/10/2008 4:18:59 PM					
--------	------------------	-----------------	--	----------------------	--	--	--	--	--

Lozoya, Manny Alma Castillo, testing room estrellita hallway, has a filing cabinet in her room that is locked and we do not have a key for it. CAN a new key be made or reinstall a new lock? Thank you.

Joanne Munoz

38329					9/22/2008		42		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			9/22/2008 3:45:45 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Quinones, Paul	9-17-08			9/17-8					
----------------	---------	--	--	--------	--	--	--	--	--

.5,CHECK IN W/OFFICE FOR PLAN OF THE DAY
7.5,REMOVE BLEACHERS FROM CHAP MID.TO
C.H.S FOOT
BALL STADIUM,AND RELOCATE SOCCER
BLEACHERS
TO FOOTBALL STADIUM AS WELL

Paul Quinones

38425	Main Building	Hallway/Corridor			9/25/2008		39		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Safety	Work In Progress	sol		9/25/2008 10:54:05 AM					
--------	------------------	-----	--	-----------------------	--	--	--	--	--

Lozoya, Manny The 1st door in el sol hallway is not releasing during fire drill. Needs to be checked out.

Joanne Munoz

38802					10/5/2008	10/26/2008	29		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress			10/5/2008 12:24:11 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Orozco, Danny Monthly - Sunrise ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

11/3/2008 3:24:42 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunrise ES

38914					10/5/2008	10/26/2008	29		\$0.00
-------	--	--	--	--	-----------	------------	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:52 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Quinones, Paul Monthly - Sunrise ES C12 (Chem.Feeder)(Monthly) - Refer to PM schedule details.

Margret Villalobos

38915					10/5/2008	11/5/2008	29		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:52 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Quinones, Paul Yearly - Sunrise ES H6 (Furnace)(Yearly) - Refer to PM schedule details.

Margret Villalobos

38916					10/5/2008	11/5/2008	29		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:53 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Quinones, Paul Yearly - Sunrise ES U2 (Gas Heater)(Yearly) - Refer to PM schedule details.

Margret Villalobos

38926					10/5/2008		29		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				10/5/2008 12:24:56 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Jacquez, Ricardo Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.

Margret Villalobos

39068					10/9/2008		25		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				10/9/2008 10:49:34 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenzo PUMP HOUSING TO A/C IN RM.105 NEEDS TO BE REPLACED LIKE THE ONE THAT WAS REPLACED IN RM.210 THANKS

Paul Quinones

39161					10/12/2008	10/28/2008	22		\$0.00
-------	--	--	--	--	------------	------------	----	--	--------

Medium	Work In Progress				10/12/2008 12:21:04				
--------	------------------	--	--	--	---------------------	--	--	--	--

Quinones, Paul Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.

Margret Villalobos

39588					10/29/2008		5		\$0.00
-------	--	--	--	--	------------	--	---	--	--------

Medium	Work In Progress				10/29/2008 4:11:14 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny HANDI CAP DOOR CLOSER NOT WORKING PROPERLY, DOOR STAYS OPEN. FRONT ENTRANCE AREA.

Paul Quinones

39672					10/31/2008		3		\$0.00
-------	--	--	--	--	------------	--	---	--	--------

Medium	Work In Progress				10/31/2008 3:51:55 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe REQUESTING PLAY GROUND SAND FOR PRIMARY PLAYGROUND 2 DUMP TRUCK LOADS WILL BE NEEDED THANKS.

Paul Quinones

11/3/2008 3:24:43 PM

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunrise ES

39681					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:30 AM				
Quinones, Paul		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
39735					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:51 AM				
Quinones, Paul		Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39743					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:54 AM				
Quinones, Paul		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39747					11/2/2008		1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:55 AM				
Jacquez, Ricardo		Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.							
Margret Villalobos									
Count: 22 Work Orders			Avg. Age of WO's 40				Total for Sunrise ES	0	\$0.00

Location: Vado ES

36103					7/22/2008		104		\$0.00
Medium	Work In Progress				7/22/2008 8:39:31 AM				
Sotelo, Enrique		NEED TO REPLACE 4 EXIT SIGNS							
Danny Miranda									
36104					7/22/2008		104		\$0.00
Medium	Work In Progress				7/22/2008 8:40:50 AM				
Sotelo, Enrique		NEED TO REPLACE 6 EMER. LIGHTS							
Danny Miranda									
36175	Main Building	Classroom			7/24/2008		102		\$0.00
Medium	Work In Progress				7/24/2008 11:22:30 AM				
Ronquillo, Ruben		NEED TO HAVE A COVER PUT OVER THE FIRE ALARM IN THE SPECIAL NEEDS CLASSROOM. ROOM101- PER DANNY MIRANDA							
Debra Facio									
36221					7/25/2008		101		\$0.00
Medium	Work In Progress				7/25/2008 11:32:11 AM				
Lozoya, Manny		NEED A NEW DOOR CLOSER IN RM. 308, (LCN 4041)							
Danny Miranda									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Vado ES

37940					9/9/2008		55		\$0.00
Medium	Work In Progress				9/9/2008 10:02:37 AM				
Lozoya, Manny		need locks with long shank for outside gates custodians have trouble locking the ones that are there total of six gates							
Danny Miranda									
38100		Classroom			9/15/2008		49		\$0.00
High	Work In Progress				9/15/2008 3:46:51 PM				
Ronquillo, Ruben		Broken window in room 203. (CASE# 2008-08888) Est. Damage 255.00							
Alfredo Holguin									
38139					9/16/2008		48		\$0.00
Medium	Work In Progress	Outside			9/16/2008 2:30:16 PM				
Miranda, Danny		Paint outside trashcans.							
Michael Munoz									
38351		Library			9/23/2008		41		\$0.00
Medium	Work In Progress				9/23/2008 11:07:26 AM				
Munoz, Michael		Need to purchase new modular partitions for class room to be.							
Alfredo Holguin									
38694	Main Building	Custodial			10/3/2008		31		\$0.00
Medium	Work In Progress				10/3/2008 8:43:53 AM				
Carbajal, Jimmy		AUTO SCRUBBER NEEDS BATTERYS.							
Armando Diaz									
38773					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:00 AM				
Orozco, Danny		Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.							
Margret Villalobos									
38803					10/5/2008	10/26/2008	29		\$0.00
Medium	Work In Progress				10/5/2008 12:24:11 AM				
Orozco, Danny		Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
39145					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress				10/12/2008 12:20:56				
Diaz, Armando		Monthly - QRTLY BLDG INSP REPORT (VE) - Refer to PM schedule details.							
Jesus Estrada									

917 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
39162					10/12/2008	10/28/2008	22		\$0.00
Medium	Work In Progress				10/12/2008 12:21:04				
Miranda, Danny		Monthly - Vado ES Playground Insp - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
39415					10/23/2008		11		\$0.00
Medium	Work In Progress				10/23/2008 12:37:51				
Solis, Lorenzo		Need to replace motor exhaust fan asp PM 38531. VE-002 - needs replacement							
<u>Danny Miranda</u>									
39655	Main Building	Classroom			10/31/2008		3		\$0.00
Medium	Work In Progress				10/31/2008 1:05:08 PM				
Sotelo, Enrique		ELECTRICIAN FOR A COST AND ENERGY ANALYSIS ON LIGHT FIXTURES-PER MS. SERVIN							
<u>Debra Facio</u>									
39699					11/2/2008	11/8/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:37 AM				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
39736					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:51 AM				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
39744					11/2/2008	11/10/2008	1		\$0.00
Medium	Work In Progress				11/2/2008 12:24:54 AM				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
39777					11/3/2008		0		\$0.00
Medium	Work In Progress				11/3/2008 12:27:44 PM				
Ontiveros, Joe		NEED TO REPAIR SINK IN GIRLS R.R. 200-WING							
<u>Danny Miranda</u>									
Count: 19 Work Orders			Avg. Age of WO's	40		Total for Vado ES	0	\$0.00	
Count: 917 Work Orders			Avg. Age of WO's	48		Grand Total	1	\$25.00	