

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
35695					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:06 AM					
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
35986	Chapter I	Office			7/16/2008		138		\$0.00
Medium	Work In Progress			7/16/2008 9:38:50 AM					
Lozoya, Manny		chapter blg repair pannic bar a.s.a.p							
Hector Villalobos									
36176	Cafeteria	Cafeteria			7/24/2008		130		\$0.00
Medium	Work In Progress			7/24/2008 11:26:39 AM					
Ontiveros, Guadalupe		remove old tree next to cafeteria,health issue as per ms.marquez							
David Vega									
36311	Chapter I	Office			7/29/2008		125		\$0.00
Medium	Work In Progress			7/29/2008 8:10:42 AM					
Estrada, Jesus		chapter blg o.t.p. room carpet need to be replace .glue on carpet from vandalism				QUOTE REQUESTED PER CHUY 8/1/08			
Hector Villalobos									
36641	Drug Free Bldg.				8/5/2008		118		\$0.00
Medium	Work In Progress			8/5/2008 10:48:59 AM					
Sotelo, Enrique		please install a power strip for radios. please see irene for location.thxs							
Michael Munoz									
36672					8/6/2008		117		\$0.00
Medium	Work In Progress			8/6/2008 8:48:17 AM					
Lozoya, Manny		Primary blg storage need to charge lock							
Hector Villalobos									
37105	Chapter I	Office			8/15/2008		108		\$0.00
Medium	Work In Progress			8/15/2008 8:46:10 AM					
Lozoya, Manny		chapter blg o.t.p room needs 4 keys k50							
Hector Villalobos									
37170	Nurse Building				8/19/2008		104		\$0.00
Medium	Work In Progress			8/19/2008 7:36:40 AM					
Lozoya, Manny		need to replace exit door							
Hector Villalobos									
37287	Cafeteria	Cafeteria			8/21/2008		102		\$0.00
Medium	Work In Progress			8/21/2008 11:49:08 AM					
Orozco, Danny		SEAL TO WALK-IN REFRIGERATOR IS ALL TORN AND MOLDY, SEAL NEEDS TO BE REPLACED							
Alma Terrell		BECKY SAENZ - 882-3507 (K-3 CAFETERIA)							

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
37450	Original Main	Classroom			8/27/2008		96		\$0.00
Medium	Work In Progress	201		8/27/2008 12:39:44 PM					
Lozoya, Manny Loraine Gandara Need an additional key.....									
37451	Original Main	Classroom			8/27/2008		96		\$0.00
Medium	Work In Progress	201		8/27/2008 12:40:05 PM					
Lozoya, Manny Loraine Gandara Need an additional key.....									
37452	Original Main	Classroom			8/27/2008		96		\$0.00
Medium	Work In Progress	202		8/27/2008 12:41:04 PM					
Lozoya, Manny Loraine Gandara Need an additional key.....									
37942					9/9/2008		83		\$0.00
Medium	Work In Progress			9/9/2008 10:36:36 AM					
Lozoya, Manny Loraine Gandara NEED 2 ADDITIONAL "H" KEY.....									
37962	Original Main				9/9/2008		83		\$0.00
Medium	Work In Progress	110		9/9/2008 2:44:04 PM					
Lozoya, Manny Loraine Gandara NEED AN ADDITIONAL KEY FOR RM 110 KEY H11									
37994	Original Main	Office			9/10/2008		82		\$0.00
Medium	Work In Progress			9/10/2008 2:17:01 PM					
Gonzalez, Salvador Hector Villalobos old main bld room 112 p.t.o needs window gurad									
38031	Original Main				9/11/2008		81		\$0.00
Medium	Work In Progress	POA OFFICE		9/11/2008 3:06:22 PM					
Lozoya, Manny Loraine Gandara NEED A LOCK AND KEY FOR CABINETS.....									
38157	Original Main	Hallway/Corridor			9/17/2008		75		\$0.00
Medium	Work In Progress			9/17/2008 7:36:41 AM					
Lozoya, Manny Hector Villalobos old main blg exit door hallway pannic bar will not lock .replace with new pannic bar. A.S.A.P									
38270					9/19/2008		73		\$0.00
Medium	Work In Progress	Corina		9/19/2008 4:08:26 PM					
Lozoya, Manny Lucia Almeraz Please install new locks on 2 file cabinets Tag# F00742 and the other one doesn't have a label. In Corina Valdespino's officce she is at the Village									
38320	Main Building	Library			9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 2:54:34 PM					
Carrasco, Danny Hector Villalobos need 5 boxes of u-bent fluorescent lamps. for library									

12/1/2008 2:38:42 PM

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
38783					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:04 AM					
Orozco, Danny	Monthly - Anthony ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
39028		Athletic Field			10/8/2008		54		\$0.00
Medium	Work In Progress			10/8/2008 10:07:55 AM					
Appelzoller, Fred	Outside water fountains mounted on concrete block columns located east of the Old Main Cafeteria are not working. REPAIR								
Alfredo Holguin									
39071	Main Building				10/9/2008		53		\$0.00
Medium	Work In Progress	Old Main		10/9/2008 1:23:45 PM					
Appelzoller, Fred	Old Main Bldg RR - Demo and remodel restrooms as per conversation w/Mike (infested w/roaches).								
Michael Munoz									
39172	Chapter I	Classroom			10/13/2008		49		\$0.00
Medium	Work In Progress			10/13/2008 9:04:29 AM					
Lozoya, Manny	Chapter blg music room needs deadbolts on two doors								
Hector Villalobos									
39407					10/23/2008		39		\$0.00
Medium	Work In Progress			10/23/2008 8:36:43 AM					
Gonzales, Angel	truck 153 thermostat is not working on heater								
Hector Villalobos									
39592					10/30/2008		32		\$0.00
Medium	Work In Progress			10/30/2008 7:34:13 AM					
Lozoya, Manny	old cafeteria gate and drug free gate need a pad lock H1								
Hector Villalobos									
39682					11/2/2008	11/8/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:31 AM					
Villalobos, Hector	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
39702					11/2/2008	11/10/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:38 AM					
Villalobos, Hector	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39704					11/2/2008	11/10/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:39 AM					
Villalobos, Hector	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

12/1/2008 2:38:42 PM

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
39763	Cafeteria	Cafeteria			11/3/2008		28		\$0.00
Medium	Work In Progress				11/3/2008 7:58:06 AM				
Orozco, Danny		WATER LEAK BOTTOM OF SINK							
Alma Terrell		CUCA PEREZ - SNP MANAGER 882-5607							
39847	Main Building	Custodial			11/5/2008		26		\$0.00
Medium	Work In Progress				11/5/2008 9:38:37 AM				
Lozoya, Manny		custodial office does not lock							
David Vega									
39848	Main Building	Custodial			11/5/2008		26		\$0.00
Medium	Work In Progress				11/5/2008 9:40:28 AM				
Lozoya, Manny		need to replace k master key							
David Vega									
39957					11/9/2008	11/25/2008	22		\$0.00
Medium	Work In Progress				11/9/2008 12:28:34 AM				
Villalobos, Hector		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									
39973					11/10/2008	11/16/2008	21		\$0.00
Medium	Work In Progress				11/10/2008 12:19:34				
Villalobos, Hector		Monthly - Anthony ES A7 (Rooftop Unit)(Monthly) - Refer to PM schedule details.							
Margret Villalobos									
40015	Office				11/12/2008		19		\$0.00
Medium	Work In Progress				11/12/2008 7:22:02 AM				
Lozoya, Manny		On track Pre-k code came out of lock eixt door . secure door by today							
Hector Villalobos									
40016	Cafeteria	Cafeteria			11/12/2008		19		\$0.00
Medium	Work In Progress				11/12/2008 7:52:56 AM				
Sotelo, Enrique		please install light fixture in bathoom, old main cafeteria where remodeling is being done. thxs							
Michael Munoz									
40021	Original Main	Classroom			11/12/2008		19		\$0.00
Medium	Work In Progress				11/12/2008 9:29:47 AM				
Lozoya, Manny		old main blg room 101 door will not lock							
Hector Villalobos									
40039	Drug Free Bldg.	Custodial			11/13/2008		18		\$0.00
Medium	Work In Progress				11/13/2008 7:10:57 AM				
Carbajal, Jimmy		need to borrow aa appliance dolley for movement of drug free furniyure							
David Vega									

12/1/2008 2:38:42 PM

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
40041	Office	Portables			11/13/2008		18		\$0.00
Medium	Work In Progress			11/13/2008 7:36:52 AM					
Lozoya, Manny		Pt on track -Prek eixt door will not lock							
Hector Villalobos									
40083		Portables			11/14/2008		17		\$0.00
Medium	Work In Progress			11/14/2008 8:43:39 AM					
Appelzoller, Fred		pt 219 and 220 water heater is leaking							
Hector Villalobos									
40308	Cafeteria	Cafeteria			11/24/2008		7		\$0.00
High	Work In Progress			11/24/2008 8:21:17 AM					
Villalobos, Hector		Lucky, could you please tile the restroom when everyone is complete. Thanks							
Michael Munoz									
40310					11/24/2008		7		\$0.00
Medium	Work In Progress			11/24/2008 10:29:21					
Lozoya, Manny		NEED TO PUT IN NEW DOOR & FRAME IN R.R. ANTHONY ELEM. CAFETERIA							
Danny Miranda									
40328	Main Building	Cafeteria			11/25/2008		6		\$0.00
Medium	Work In Progress			11/25/2008 7:32:53 AM					
Orozco, Danny		Mid cafetetria water heater is not working							
Hector Villalobos									
40405					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:43					
Villalobos, Hector		Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.							
George ZZ Gabaldon									
40406					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:43					
Villalobos, Hector		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40407					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:43					
Villalobos, Hector		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
Count: 45 Work Orders		Avg. Age of WO's 57		Total for Anthony ES			0	\$0.00	

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
35579					7/6/2008	7/27/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:29 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35696					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:06 AM					
Villalobos, David	Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35767					7/7/2008		147		\$0.00
High	Work In Progress			7/8/2008 3:20:01 PM					
Duran, Adan	Tag graffiti all over campus. Dep. LGarcia 114 Case# 2008-06493								
<u>Jimmy Cortez</u>									
35915					7/13/2008	7/29/2008	141		\$0.00
Medium	Work In Progress			7/13/2008 12:18:09 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36296					7/28/2008		126		\$0.00
Medium	Work In Progress			7/28/2008 3:37:40 PM					
Lozoya, Manny	MR MANNY LOZOYA SIR IN PORTABLE 148 THE FILE CABINET GOT LOCK BY MASTAKE AND THEY DONT HAVE A KEY NEED TO REMOVE CYLINDER AND REPLACE WITH NEW ONE THAT HAS A KEY THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
36707					8/6/2008		117		\$0.00
Medium	Work In Progress			8/6/2008 3:31:30 PM					
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR WE HAVE ABOUT 8 GALVNIZE PIPES 21 FT LOG THAT NEED TO BE PICKED UP AND HAUL OFF TO PPD YARD ALSO BIG BLOCKS OF CONCRETE THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
36845					8/8/2008		115		\$0.00
Medium	Work In Progress	Mobile Home		8/8/2008 3:52:51 PM					
Sotelo, Enrique	Need to install utility hook-up for mobile home.								
<u>Michael Munoz</u>									
36850					8/10/2008	8/26/2008	113		\$0.00
Medium	Work In Progress			8/10/2008 12:19:42 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
36879					8/11/2008		112		\$0.00
Medium	Work In Progress				8/11/2008 9:01:25 AM				
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR PER MR VALTIERRA HE WOULD LIKE THE SCHOOL CLEAN TO MANNY WEEDS PONDING AREA NEEDS CLEAN IN FRONT AND BACK AROUND PORTABLES ALONE FENCE IN FRONT OUTSIDE AND IN SIDE THANK YOU SIR								
Adan Duran									
37210					8/19/2008		104		\$0.00
Medium	Work In Progress				8/19/2008 3:32:05 PM				
Solis, Lorenzo	MR LORENZO SOLIS SIR PORTABLE 139 HAS TWO AC WINDOW TYPE THE CLAM IS THAT ITS NOT COOLING ENOUGH IT USE TO BE MUSIC ROOM BUT ITS A CLASS ROOM NOW WOULD LIKE A BIGGER UNIT THANK YOU SIR AND GOD BLESS								
Adan Duran									
37769		Portables			9/4/2008		88		\$0.00
Medium	Work In Progress				9/4/2008 8:09:26 AM				
Sotelo, Enrique Lorenzo Solis	Please provide electrical connection to 3 Ton Bard unit.								
37866					9/7/2008	9/23/2008	85		\$0.00
Medium	Work In Progress				9/7/2008 12:27:28 AM				
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
38004					9/10/2008		82		\$0.00
Medium	Work In Progress				9/10/2008 3:33:58 PM				
Lozoya, Manny	MR MANNY LOZOYA SIR WE ARE HAVE PROBLEMS WITH DOOR PORTABLE 135 OLD DOOR WILL NEED SOME HAREWARE WILL NOT LOCK KEEPS BLOWING OPEN WHEN WINDY THANK YOU SIR GOD BLESS								
Adan Duran									
38128					9/16/2008		76		\$0.00
Medium	Work In Progress				9/16/2008 10:30:21 AM				
Sotelo, Enrique	Emer. Light need replacing at west entrance and Custodial room.								
Adan Duran									
38159					9/17/2008		75		\$0.00
Medium	Work In Progress				9/17/2008 7:52:03 AM				
Lozoya, Manny	MR MANNY LOZOYA SIR WE NEED TO CHANGE OUTSIDE GATE PAD LOCKS SOMEONE IS OPENING OUR GATES CHANGE LOCKS AS SAME AS ENTRANCE DOOR THANK YOU SIR								
Adan Duran									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
38442	Main Building				9/25/2008		67		\$0.00
Medium	Work In Progress			9/25/2008 3:59:37 PM					
Duran, Adan	Restrooms next to multipurpose room- sand entrance doors and reseal								
Alfredo Holguin									
38444		Portables			9/25/2008		67		\$0.00
Medium	Work In Progress			9/25/2008 4:06:10 PM					
Duran, Adan	Last two Portables on south row east side - re-install blocks under beams.								
Alfredo Holguin									
38502					9/29/2008		63		\$0.00
Medium	Work In Progress	Mobile Home		9/29/2008 1:34:42 PM					
Duran, Adan	Need to remove fence on October 4, 2008 1st thing in the morning.								
Michael Munoz									
38529					9/30/2008		62		\$0.00
Medium	Work In Progress			9/30/2008 12:25:59 AM					
Duran, Adan	Monthly - Berino ES A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
38699					10/3/2008		59		\$0.00
Medium	Work In Progress	Mobile Home		10/3/2008 10:42:41 AM					
Lozoya, Manny	As per Alfredo, need a gate key for Guadalupe Quinones the new mobile home occupant at Berino. The mobile home will be placed at the school this weekend.								
Alfredo Holguin									
38737					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:23:47 AM					
Duran, Adan	Yearly - Berino ES I4 (Fan Coil)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
38738					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:23:48 AM					
Duran, Adan	Yearly - Berino ES R9 (Radiator Hot)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
38739					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:23:48 AM					
Duran, Adan	Yearly - Berino ES H6 (Furnace Gas)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
38740					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:23:48 AM					
Duran, Adan	Yearly - Berino ES U2 (Heat Gas)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
38778					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:02 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
38784					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:04 AM					
Orozco, Danny	Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
39057					10/9/2008		53		\$0.00
Medium	Work In Progress			10/9/2008 8:25:00 AM					
Munoz, Michael	need to repair fence @ mobile home occupant, and install 2 additional gates. please use double gates that are currently there.								
Alfredo Holguin									
39148					10/12/2008	10/28/2008	50		\$0.00
Medium	Work In Progress			10/12/2008 12:20:57					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
39479					10/24/2008		38		\$0.00
Medium	Work In Progress			10/24/2008 3:26:04 PM					
Sotelo, Enrique	MR ENRIQUE SOTELO SIR EMERGENCY LIGHT FALL OFF WALL IN CAFETERIA NEED TO REPLACE BROKEN BURN ELEMENTS THE ONE IN CUSTODIAL ROOM ALSO THANK YOU SIR								
Adan Duran									
39958					11/9/2008	11/25/2008	22		\$0.00
Medium	Work In Progress			11/9/2008 12:28:34 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
40073					11/13/2008		18		\$0.00
Medium	Work In Progress			11/13/2008 4:10:00 PM					
Lozoya, Manny	MR MANNY LOZOYA SIR WE NEED TO REPLACEMENT KEY THE TRASH MAN HAS B KEY BUT WE CHANGE GATE LOCKS TO B-1 HE COULD NOT GET IN MONDAY MUNCHO TRASH THANK YOU SIR								
Adan Duran									
12/1/2008 2:38:42 PM									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
40137					11/17/2008		14		\$0.00
High	Work In Progress			11/17/2008 11:07:56					
Lozoya, Manny	manny, you changed the core to the gates from a b to a b-1. the thrash guy does not have access. please make a new key for them and give to adan. he has the b for you.								
Michael Munoz									
40260					11/20/2008		11		\$0.00
Medium	Work In Progress			11/20/2008 1:53:26 PM					
Solis, Lorenzo	t-stat wire is exposed on refrigeration unit to nurce. please correct the install fro roofers to continue. thxs								
Michael Munoz									
40322					11/24/2008		7		\$0.00
Medium	Work In Progress			11/24/2008 3:47:16 PM					
Appelzoller, Fred	MR FRED APPELZOLLER SIR THE COMODE PORTABLE 152 AND 153 IS PLUGED USED CLOSET OGER 4 TIMES THE PLUNGER STILL WON'T GO NEED THE LONG CABLE THANK YOU SIR AND GOD BLESS								
Adan Duran									
40333		Cafeteria			11/25/2008		6		\$0.00
Medium	Work In Progress			11/25/2008 8:17:01 AM					
Moncayo, Fernando	SLICER NOT WORKING. WILL NOT START								
	ELSA ORTEGA SNP MGR 882-2417								
Jacqueline Aguilar									
40347					11/25/2008		6		\$0.00
Medium	Work In Progress			11/25/2008 3:30:06 PM					
Carrasco, Danny	MR RUBEN RONQILLO SIR WILL NEED TO BORROW HI-LIFT TO CHANGE OUT FILTERS HEATING UNITS IN GYM VERY HIGH THANK YOU SIR AND GOD BLESS								
Adan Duran									
40359					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:27					
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
George ZZ_Gabaldon									
40360					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:28					
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
George ZZ_Gabaldon									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Berino ES							
40361					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress		11/30/2008 12:23:28						
Duran, Adan		Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
Count: 39 Work Orders		Avg. Age of WO's 66		Total for Berino ES				0	\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral ES								
35694					7/6/2008	8/6/2008	148		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:05 AM						
Villalobos, David		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
36075		Office			7/18/2008		136		\$0.00	
Medium	Work In Progress	PRE-K		7/18/2008 4:55:16 PM						
Vargas, Juan		AS PER ANN STEINHOFF-THERE IS MOLD ON THE CEILING IN THE WORK ROOM AT THE PRE-K								
Mary Garcia										
36214		Classroom			7/25/2008		129		\$0.00	
Medium	Work In Progress			7/25/2008 10:15:35 AM						
Lozoya, Manny		need,to,check,all,doors,locks,keys,do,not,open,doors,locks.								
Daniel Ramirez										
36314					7/29/2008		125		\$0.00	
Medium	Work In Progress	Room#208-		7/29/2008 10:16:15 AM						
Lozoya, Manny		Please install new locks to file cabinet -social worker will leave a sticky on the file cabinet								
Lucia Almeraz										
36581					8/4/2008		119		\$0.00	
Medium	Work In Progress			8/4/2008 8:49:37 AM						
Vargas, Juan		barracas 406-408-410-412-414-416-418 need change master cools now have 3800 is to small need replace for 4500				Routed 8/11 - Assign to JC asp our conversation he needs to give units a good PM, where installed last year. Humidity is @ 70 and m/c swamps do not work well. m.munoz				
Juan Vargas										
36675		Office			8/6/2008		117		\$0.00	
Medium	Work In Progress			8/6/2008 9:42:24 AM						
Lozoya, Manny		need,to,fix,door,lock,mrs,baderd,officef								
Daniel Ramirez										
36737		Office			8/7/2008		116		\$0.00	
Medium	Work In Progress	front office		8/7/2008 7:51:44 AM						
Lozoya, Manny		secretary's door locks and can't open, need door to be able to lock only when used with the key stays locked and when there is a fire drill door needs to be closed but not locked and locks automatically.Administrative Intern's room also having trouble with lock door cannot open very hard custodians are having a difficult time opening. Please see front office								
Jennifer Corral										
36738					8/7/2008		116		\$0.00	
Medium	Work In Progress			8/7/2008 7:59:01 AM						
Lozoya, Manny		chuy y mando nesecitan que les cambies las llaves por que batallan para abrir las puertas								
Juan Vargas										
12/1/2008 2:38:42 PM										

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
36773					8/7/2008		116		\$0.00
Medium	Work In Progress			8/7/2008 1:07:27 PM					
Ontiveros, Joe	kitchen r.room need replace toilet is broke								
Juan Vargas					8/13/2008		110		\$0.00
37005	Classroom				8/13/2008 10:45:16 AM				
Medium	Work In Progress	whole school							
Lozoya, Manny	work order to redo keys for custodians, can't open the doors to the classrooms. As per Manny Request.								
Jennifer Corral					8/14/2008		109		\$0.00
37055	2001 Classroom				8/14/2008 10:11:15 AM				
Medium	Work In Progress								
Vargas, Juan	need to add large rocks or cobblestones in areas where roof gutters are causing erosion								
Alfredo Holguin					8/14/2008		109		\$0.00
37056					8/14/2008 10:14:39 AM				
Medium	Work In Progress								
Vargas, Juan	All sidewalks with more than 4" drop need to have fill dirt added - Call Mike or Alfredo when work is complete								
Alfredo Holguin					8/14/2008		109		\$0.00
37057					8/14/2008 10:17:19 AM				
Medium	Work In Progress								
Vargas, Juan	Sand need to be leveled in fall areas of all playground structures on site.								
Alfredo Holguin					8/18/2008		105		\$0.00
37135	West Central				8/18/2008 9:11:53 AM				
Medium	Work In Progress								
Vargas, Juan	new doors are being installed in the esat and west barrack. please order paint so you can paint doors. thxs								
Michael Munoz					8/20/2008		103		\$0.00
37222	Custodial				8/20/2008 9:40:22 AM				
Medium	Work In Progress	master							
Lozoya, Manny	need another key to be done for substitute custodian. One of the keys did not open the doors. Please see Danny head custodian for more explanation								
Jennifer Corral					8/20/2008		103		\$0.00
37226	Classroom				8/20/2008 1:04:04 PM				
Medium	Work In Progress	103							
Sotelo, Enrique	need electrical setup to plug in computers and maybe move some to another location in the room. See Ms. Aguayo/Gary or Portillo								
Jennifer Corral									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
37990		Cafeteria			9/10/2008		82		\$0.00
Medium	Work In Progress			9/10/2008 1:49:03 PM					
Orozco, Danny		Side of grease trap caving in.							
Michael Munoz									
37993					9/10/2008		82		\$0.00
Medium	Work In Progress			9/10/2008 2:16:48 PM					
Lozoya, Manny		Monday, September 15, 2008 @ 10:00, need to inventory J. Vargas keys to be transferred to Guillermo Hernandez.							
Michael Munoz									
38027		Athletic Field			9/11/2008		81		\$0.00
Medium	Work In Progress			9/11/2008 2:05:24 PM					
Ontiveros, Guadalupe		Lower Grades playground equipment located between classroom wings - Re layout plastic borders so they are around the remaining playground (slide) structure.							
Alfredo Holguin									
38240					9/18/2008		74		\$0.00
Medium	Work In Progress			9/18/2008 3:45:24 PM					
Lozoya, Manny		Would you please issue a key for me to use on the gate next to Chap Midd, they use the gate for the fire drill and the keys that I got dont have one. thank you							
Guillermo Hernandez									
38785					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:05 AM					
Orozco, Danny		Monthly - Chaparral ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
39746					11/2/2008		29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:55 AM					
Jacquez, Ricardo		Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.							
Margret Villalobos									
39770					11/3/2008		28		\$0.00
Medium	Work In Progress			11/3/2008 9:53:57 AM					
Sotelo, Enrique		Need to replace out side lights :front parking lot,side of main building and front of portable 1 through portable 2.							
Guillermo Hernandez									
39772		Custodial			11/3/2008		28	2	\$71.44
Medium	Work In Progress			11/3/2008 9:57:12 AM					
Carbajal, Jimmy		vaccum,handle,broken							
Daniel Ramirez		REPAIRED AND REPLACED REAR WHEEL AXLE ASSEMBLY (WITH USED ONE)							

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Chaparral ES								
39939	E. Building	Classroom			11/7/2008		24		\$0.00	
Medium	Work In Progress	509		11/7/2008 10:55:11 AM						
Lozoya, Manny		need cabinet to be relocked. Need new lock for it and key. Teacher for Visually impaired will be storing important and expensive merchandise in there and needs for it to be safe. See Ms. Kayce speech Teacher								
<u>Jennifer Corral</u>										
40051		Classroom			11/13/2008		18		\$0.00	
Medium	Work In Progress	512		11/13/2008 12:36:13						
Lozoya, Manny		need cabinet in rm to place belongings very expensive but does not have a key. So would like it to be redone and get a key for it. See Ms. Kayce SLP Speech Teacher. As soon as possible								
<u>Jennifer Corral</u>										
40162					11/17/2008		14		\$0.00	
Medium	Work In Progress			11/17/2008 4:02:20 PM						
Sotelo, Enrique		Need assistance to replace emergency light in portable #1 and #2.								
<u>Guillermo Hernandez</u>										
40238					11/19/2008		12		\$0.00	
Medium	Work In Progress			11/19/2008 3:45:57 PM						
Ontiveros, Joe		would you please replace lavatory faucets in the girls restroom on the north hallway. Thank you								
<u>Guillermo Hernandez</u>										
40239					11/19/2008		12		\$0.00	
Medium	Work In Progress			11/19/2008 3:48:17 PM						
Lozoya, Manny		would you please check the automatic door opener for handicap on the north side of the main hallway. Thank you								
<u>Guillermo Hernandez</u>										
40250	Main Building	Restroom (Boys)			11/20/2008		11		\$0.00	
High	Work In Progress			11/20/2008 9:04:36 AM						
Ramirez, Daniel		Both bathrooms boys and girls in front lobby need detail cleaning. Walls, stalls, floors and toilets all need immediate attention. See me for products to be used.								
<u>Jesus Estrada</u>										
40397					11/30/2008	12/8/2008	1		\$0.00	
Medium	Work In Progress			11/30/2008 12:23:40						
Hernandez, Guillermo		Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>George ZZ_Gabaldon</u>										
40398					11/30/2008	12/6/2008	1		\$0.00	
Medium	Work In Progress			11/30/2008 12:23:40						
Hernandez, Guillermo		Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.								
<u>George ZZ_Gabaldon</u>										
12/1/2008 2:38:43 PM										

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Chaparral ES									
40399					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:41				
Hernandez, Guillermo	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40400					11/30/2008		1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:41				
Hernandez, Guillermo	Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.								
George ZZ Gabaldon									
40441					11/30/2008		1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:55				
Jacquez, Ricardo	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
George ZZ Gabaldon									
40450		Classroom			12/1/2008		0		\$0.00
Medium	Work In Progress	403			12/1/2008 8:05:14 AM				
Lozoya, Manny	Teacher lost key and needs a replacement. See Ms. DeGeeter								
Jennifer Corral									
Count: 36 Work Orders			Avg. Age of WO's	67		Total for Chaparral ES	2	\$71.44	

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
37220					8/20/2008		103		\$0.00
Medium	Work In Progress			8/20/2008 8:34:48 AM					
Lozoya, Manny		Need a CH73 key for classroom for F Wing - Rm. 5. (Paul H. Geiger)							
Guadalupe Gonzalez									
35714					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:12 AM					
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
35869					7/11/2008		143		\$0.00
Medium	Work In Progress			7/11/2008 9:39:33 AM					
Lozoya, Manny		RE-KEY LEFT UPPER AND LOWER CABINETS FOR STORAGE LOCATED BEHIND THE RECEPTIONST FOR THE REGISTRAR (HEMPHILL)							
Rosa Quezada									
35870		Office			7/11/2008		143		\$0.00
Medium	Work In Progress	FRONT OFFICE		7/11/2008 9:41:05 AM					
Lozoya, Manny		RE-KEY RIGHT UPPER AND LOWER CABINETS FOR STORAGE LOCATED BEHIND THE RECEPTIONIST (GARCIA)							
Rosa Quezada									
35970					7/15/2008		139		\$0.00
Medium	Work In Progress	Mobile Home		7/15/2008 2:56:29 PM					
Ontiveros, Joe		SEPTIC AND WATER SYSTEMS NEED TO BE TIED IN FOR AN ON SITE MOBILE HOME.							
Eddie Baeza									
36093		Classroom			7/21/2008		133		\$0.00
Medium	Work In Progress	D-7		7/21/2008 3:47:12 PM					
Lozoya, Manny		NEED 1G032 SPARE KEY FOR FLAMABLE CABINET IN D-7(QUEZADA)							
Rosa Quezada									
36569					8/3/2008	9/3/2008	120		\$0.00
Medium	Work In Progress			8/3/2008 12:20:35 AM					
Baeza, Eddie		Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
36579		Classroom			8/4/2008		119		\$0.00
Medium	Work In Progress	F Wing - Rm. 5		8/4/2008 8:18:45 AM					
Lozoya, Manny		Need a CH73 key for classroom F-5. (Paul H. Geiger)							
Guadalupe Gonzalez									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
36593		Classroom			8/4/2008		119		\$0.00
Medium	Work In Progress	R Wing - Rm. 1			8/4/2008 1:55:06 PM				
Lozoya, Manny		Due to high security requirements, the control room door key must be cored the same as the storage room door. It is to be "off master" like the storage room.							
<u>Guadalupe Gonzalez</u>									
36606	B-Wing	Classroom			8/4/2008		119		\$0.00
Medium	Work In Progress	Rm B-3			8/4/2008 3:13:25 PM				
Lozoya, Manny		Need keys D274AR & D273AR. (Emmanuel Okefor)							
<u>Guadalupe Gonzalez</u>									
36888					8/11/2008		112		\$0.00
Medium	Work In Progress				8/11/2008 1:32:00 PM				
Ontiveros, Joe		FAUCETS IN D-WING SCIENCE LABS NEED REPAIR AND REPLACEMENT.							
<u>Eddie Baeza</u>									
36959	A-Wing	Office			8/12/2008		111		\$0.00
Medium	Work In Progress				8/12/2008 3:11:57 PM				
Lozoya, Manny		Need to re-key mailroom to fit GM3 key.							
<u>Guadalupe Gonzalez</u>									
37177					8/19/2008		104		\$0.00
Medium	Work In Progress	Concession			8/19/2008 7:55:32 AM				
Lozoya, Manny		Need key to concession stand. (Mr. Sanchez)							
<u>Guadalupe Gonzalez</u>									
37394		Classroom			8/26/2008		97		\$0.00
Medium	Work In Progress	Nurse			8/26/2008 11:42:37 AM				
Lozoya, Manny		Need keys CH6 for Nurse's office and CH5 for the storage room in the Health Center. (Ana Castro)							
<u>Guadalupe Gonzalez</u>									
37432					8/27/2008		96		\$0.00
Medium	Work In Progress				8/27/2008 8:12:23 AM				
Gonzalez, Salvador		WELD GOOSENECK TO FOOTBALL GOAL POST.							
<u>Guadalupe Ontiveros</u>									
37528					8/29/2008		94		\$0.00
Medium	Work In Progress				8/29/2008 12:34:48 PM				
Sotelo, Enrique		THERE ARE 7 EXTERIOR POLE LIGHTS OUT AT PARKING LOTS							
<u>Eddie Baeza</u>									
37560					8/31/2008	9/21/2008	92		\$0.00
Medium	Work In Progress				8/31/2008 12:25:17 AM				
Orozco, Danny		Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
37561					8/31/2008	9/21/2008	92		\$0.00
Medium	Work In Progress			8/31/2008 12:25:17 AM					
Orozco, Danny		Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
37783					9/4/2008		88		\$0.00
Medium	Work In Progress			9/4/2008 10:52:49 AM					
Lozoya, Manny		(65) LATCH PROTECTORS ARE REQUESTED FOR CLASS RMS AND OFFICE DOORS							
Eddie Baeza									
37893					9/8/2008		84		\$0.00
Medium	Work In Progress	q-4		9/8/2008 10:21:54 AM					
Lozoya, Manny		need a CH-1 for auto construction labs.							
Rosa Quezada									
38072					9/14/2008		78		\$0.00
Medium	Work In Progress			9/14/2008 12:23:08 AM					
Ontiveros, Guadalupe		Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.							
Margret Villalobos									
38307		Classroom			9/22/2008		70		\$0.00
Medium	Work In Progress	Q-7		9/22/2008 1:13:03 PM					
Lozoya, Manny		NEED CH-94 (2) FOR Q-2 FOR LAB AND CAGES ONE & TWO NEED CH-96 (2) FOR Q-6 FOR LAB AND CAGE KEYS (FOR PETE GALVAN)							
Rosa Quezada									
38324					9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 3:28:35 PM					
Lozoya, Manny		THERE ARE SEVERAL PANIC BARS AND LOCK-SETS THAT ARE NOT WORKING PROPERLY ON CAMPUS.							
Eddie Baeza									
38532					9/30/2008		62		\$0.00
Medium	Work In Progress			9/30/2008 12:26:00 AM					
Baeza, Eddie		Monthly - Chaparral HS A16 (Fan Exhst.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
38577					9/30/2008		62		\$0.00
Medium	Work In Progress			9/30/2008 3:53:50 PM					
Lozoya, Manny		CHANGE THE LOCK ON THE TRAINERS ROOM OFF OF CH-86							
Eddie Baeza									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
38578					9/30/2008		62		\$0.00
Medium	Work In Progress			9/30/2008 3:56:13 PM					
Lozoya, Manny	(4) DOORS IN THE LOCKER ROOMS NEED TO BE DOUBLE KEYED. (4) DOORS NEED TO BE CHANGED TO LATCH FOR SAFETY AND SECURITY REASONS								
<u>Eddie Baeza</u>									
38742					10/5/2008		57		\$0.00
Medium	Work In Progress			10/5/2008 12:23:49 AM					
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.		10/6/08 - Emailed to Ricky Borrego						
<u>Margret Villalobos</u>									
38817					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:16 AM					
Baeza, Eddie	Monthly - Chaparral HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38818					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:17 AM					
Baeza, Eddie	Yearly - Chaparral HS H6 (Furnace)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38819					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:17 AM					
Baeza, Eddie	Yearly - Chaparral HS U2 (G.Heater)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38989					10/7/2008		55		\$0.00
Medium	Work In Progress			10/7/2008 8:47:09 AM					
Lozoya, Manny	PAD LOCKS AT THE ATHLETIC FEILDS NEED TO BE SECURED SO THEY WILL NOT BE LOST.								
<u>Eddie Baeza</u>									
38995					10/7/2008		55		\$0.00
Medium	Work In Progress			10/7/2008 11:12:22 AM					
Lozoya, Manny	Need a Master Key for Trane Company. They will be working during Fall Break. (approved by A. Holguin)								
<u>Alfredo Holguin</u>									
39019					10/7/2008		55		\$0.00
Medium	Work In Progress			10/7/2008 3:55:21 PM					
Lozoya, Manny	Greenhouses attached to building - Change door hardware between building and greenhouse to appropriate type.								
<u>Alfredo Holguin</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
39021		Athletic Field			10/7/2008		55		\$0.00
Medium	Work In Progress				10/7/2008 3:58:09 PM				
Jacquez, Ricardo	Install fencing around lift station with gates as needed for the service.		11/18 - Asp Mike route to Rick						
<u>Alfredo Holguin</u>									
39194					10/13/2008		49		\$0.00
Medium	Work In Progress	workroom Q & R			10/13/2008 3:43:04 PM				
Lozoya, Manny	NEED TO KEY Q & R WING WORKROOMS SO THAT ALL TEACHERS HAVE ACCESS TO COPIER (QUEZADA)								
<u>Rosa Quezada</u>									
39303	A-Wing	Custodial			10/20/2008		42		\$0.00
Medium	Work In Progress				10/20/2008 2:42:25 PM				
Lozoya, Manny	NEED 4 COPIES OF THE TRASH COMPACTOR KEY FOR HEAD CUSTODIAN ARMANDO RIVERA (QUEZADA)								
<u>Rosa Quezada</u>									
39306					10/20/2008		42		\$0.00
Medium	Work In Progress	SOCCER			10/20/2008 2:44:56 PM				
Lozoya, Manny	NEED 3 COPIES OF CH-86 KEYS FOR SOCCER COACHES								
<u>Rosa Quezada</u>									
39328					10/21/2008		41		\$0.00
Medium	Work In Progress				10/21/2008 8:25:53 AM				
Lozoya, Manny	(10) BEST PADLOCKS WITH LONG SHANKS ARE REQUESTED FOR EQUIPMENT IN NEW WEIGHT ROOM.								
<u>Eddie Baeza</u>									
39337					10/21/2008		41		\$0.00
Medium	Work In Progress				10/21/2008 1:12:48 PM				
Lozoya, Manny	WE ARE UNABLE TO OPEN VAULT AT MAIN OFFICE, AND KEY JUST KEEPS TURNING.								
<u>Eddie Baeza</u>									
39363	A-Wing	Classroom			10/22/2008		40		\$0.00
Medium	Work In Progress	storage room			10/22/2008 9:20:35 AM				
Lozoya, Manny	NEED TO CHANGE CORE IN MAIN STORAGE ROOM IN FRONT OFFICE TO FIT TO KEY GM3 (QUEZADA)								
<u>Rosa Quezada</u>									
39393					10/22/2008		40		\$0.00
Medium	Work In Progress				10/22/2008 3:50:18 PM				
Ontiveros, Guadalupe	(4) BATTING CAGES ARE REQUESTED FOR THE BASEBALL FIELDS.								
<u>Eddie Baeza</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
39551					10/28/2008		34		\$0.00
Medium	Work In Progress			10/28/2008 3:39:58 PM					
Carrasco, Danny	(10)BALLAST ARE REQUESTED FOR 70 WATT METAL HALIDE BULBS FOR EXTERIOR LIGHTS, AT WINGS.								
Eddie Baeza									
39748					11/2/2008		29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:56 AM					
Baeza, Eddie	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39749					11/2/2008		29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:56 AM					
Baeza, Eddie	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
39750					11/2/2008		29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:56 AM					
Baeza, Eddie	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39752					11/2/2008	12/3/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:57 AM					
Baeza, Eddie	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
39768					11/3/2008		0		\$0.00
Medium	Work In Progress			11/3/2008 9:22:51 AM		11/3/2008			
Quinones, Paul	Asp Mike, please assist at CHS in cutting weeds starting today. Thanks								
Michael Munoz									
39771					11/3/2008		28		\$0.00
Medium	Work In Progress			11/3/2008 9:54:06 AM					
Parra, Juliet	A TRASH DUMPSTER IS REQUESTED FOR THE Q-WING								
Eddie Baeza									
39778		Cafeteria			11/3/2008		28		\$0.00
Medium	Work In Progress			11/3/2008 1:26:58 PM					
Orozco, Danny	NEON LIGHTS ARE OUT ON - ON THE BUN LINE								
Alma Terrell	JUANA MONTELONGO - SNP MANAGER 824-4461								

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
39780		Cafeteria			11/3/2008		28		\$0.00
Medium	Work In Progress			11/3/2008 1:29:12 PM					
Orozco, Danny	OLD FAVORITE LINE - 2 OF THE 4 LIGHTS ARE OUT								
Alma Terrell	JUANA MONTELONGO - SNP MANAGER 824-4461								
39792					11/3/2008		28		\$0.00
Medium	Work In Progress			11/3/2008 3:49:01 PM					
Ontiveros, Joe	THERE IS A BAD ODOR COMING FROM DRAINS IN THE HEALTH CENTER REST ROOM								
Eddie Baeza									
39914					11/6/2008		25		\$0.00
Medium	Work In Progress			11/6/2008 2:57:19 PM					
Baeza, Eddie	please cut weeds along fence next to the outside basketball courts and immediate areas. also along lobo lane and parking lot islands.thxs								
Michael Munoz									
39916		Gym			11/6/2008		25		\$0.00
Medium	Work In Progress			11/6/2008 3:03:56 PM					
Baeza, Eddie	I saw where the acs where drained and the pan was not cleaned. please clean pan to prevent rusting in the future. also clean salt build up on pumps.thxs								
Michael Munoz									
39983	A-Wing	Office			11/11/2008		20		\$0.00
Medium	Work In Progress	front main door		11/11/2008 9:09:53 AM					
Lozoya, Manny	NEED TO REKEY FRONT MAIN DOOR TO CH-86 (DIGGS)								
Rosa Quezada									
39984					11/11/2008		20		\$0.00
Medium	Work In Progress	CONCESSION		11/11/2008 9:10:50 AM					
Lozoya, Manny	NEED TO RE-KEY CONCESSION ROOM TO OPEN ON MASTER								
Rosa Quezada									
39991		Cafeteria			11/11/2008		20		\$0.00
Medium	Work In Progress			11/11/2008 11:10:02					
Orozco, Danny	Milk Cooler located on ON the BUN line, broke. Juanita said that the lever that holds the milk crate(s) broke, all the milk fell into the container								
Alma Terrell	Juanita Montelongo - SNP Manager 824-4461								

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
40053					11/13/2008		18		\$0.00
Medium	Work In Progress	Roof Top		11/13/2008 1:51:22 PM					
Baeza, Eddie		Need to assist in removing sand from roof top asp e-mail. JOHNNY ACUNA; GUILLERMO G. HERNANDEZ; Eric R. Medina; PAUL A. QUINONES; DANNY OROZCO							
Michael Munoz									
40133					11/17/2008		14		\$0.00
Medium	Work In Progress	Storage Area		11/17/2008 10:18:06					
Lozoya, Manny		The storage for the building mechanic at CHS needs to be keyed so Mike and I have access to it. When we were there last week our key would not work. please correct this.							
Alfredo Holguin									
40350	A-Wing	Office			11/25/2008		6		\$0.00
Medium	Work In Progress	TESTING		11/25/2008 3:46:50 PM					
Lozoya, Manny		NEED TO REKEY TESTING STORAGE ROOM LOCATED IN THE MAIN OFFICE.							
Rosa Quezada									
40375					11/30/2008	12/21/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:33					
Orozco, Danny		Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.							
George ZZ_Gabaldon									
40388					11/30/2008		1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:37					
Baeza, Eddie		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
George ZZ_Gabaldon									
40389					11/30/2008		1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:37					
Baeza, Eddie		Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.							
George ZZ_Gabaldon									
40390					11/30/2008		1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:38					
Baeza, Eddie		Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
George ZZ_Gabaldon									
40391					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:38					
Baeza, Eddie		Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.							
George ZZ_Gabaldon									

12/1/2008 2:38:43 PM

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Chaparral HS							
40392					11/30/2008	12/31/2008	1		\$0.00
Medium	Work In Progress		11/30/2008 12:23:38						
Baeza, Eddie		Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.							
George ZZ Gabaldon									
Count: 65 Work Orders		Avg. Age of WO's 59		Total for Chaparral HS				0	\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
35580					7/6/2008	7/27/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:30 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
35697					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:06 AM					
Villalobos, David	Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36145	Main Building	Classroom			7/23/2008		131		\$0.00
Medium	Work In Progress	Room 207		7/23/2008 11:09:15 AM					
Lozoya, Manny	**URGENT** THIRD REQUEST FOR NEW KEY FOR ROOM 207 OLD KEY BENT AND BROKE								
Elena Palacios									
36315					7/29/2008		125		\$0.00
High	Work In Progress			7/29/2008 10:57:48 AM					
Lozoya, Manny	***URGENT*** NEED KEY LOCKS THAT WERE LOST AND ORDERED ACCORDING TO RAFA AND MANNY BACK IN SEPTEMBER OF 07, LOCKS AND KEYS STILL HAVE NOT BEEN REPLACED IN THEIR ENTIRETY								
Elena Palacios									
36316		Computer Lab			7/29/2008		125		\$0.00
High	Work In Progress	ROOM 207		7/29/2008 11:01:56 AM					
Lozoya, Manny	NEED NEW KEY MADE FOR ROOM 207								
Elena Palacios									
36767	Main Building	Classroom			8/7/2008		116		\$0.00
Medium	Work In Progress	ROOM 201		8/7/2008 12:10:58 PM					
Lozoya, Manny	NEEDS KEYS TO LOCK CABINETS								
Elena Palacios									
37050					8/14/2008		109		\$0.00
Medium	Work In Progress			8/14/2008 8:28:32 AM					
Ontiveros, Joe	need to replace shower columns in boys and girls reast rooms. Thxs								
Marti Muela									
37191					8/19/2008		104		\$0.00
Medium	Work In Progress			8/19/2008 10:54:48 AM					
Lozoya, Manny	eight security window rod irons can not be locked in the 300 & 400 hallway. very easy to break into. those rooms are to the back and can not be seen from the street.								
Robert Gonzalez									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
37404	Main Building	Classroom			8/26/2008		97		\$0.00
Medium	Work In Progress	ROOM 406		8/26/2008 3:43:07 PM					
Lozoya, Manny		NEED CABINET LOCKS							
Elena Palacios									
37822	Main Building	Portables			9/5/2008		87		\$0.00
High	Work In Progress	P-9		9/5/2008 9:09:01 AM					
Lozoya, Manny		Social Worker Berenice Holguin needs her file cabinet locked for very confidential paperwork. Her lock was taken by Manny but never replaced.							
Elena Palacios									
37823	Main Building	Classroom			9/5/2008		87		\$0.00
High	Work In Progress	Room 206		9/5/2008 9:10:55 AM					
Lozoya, Manny		Counselor James Wolf needs file cabinet lock back, to secure confidential paperwork. Was taken last year by Manny and not yet replaced.							
Elena Palacios									
37824	Main Building	Classroom			9/5/2008		87		\$0.00
High	Work In Progress	Room 404		9/5/2008 9:14:56 AM					
Lozoya, Manny		NEED CABINETS KEYED FOR MR. MORALES IN ROOM 406							
Elena Palacios									
38127	Main Building	Gym			9/16/2008		76		\$0.00
Medium	Work In Progress			9/16/2008 10:22:53 AM					
Ronquillo, Ruben		Asp PM 37575 FXT-CHM -017 Need plexiglass cover. FXT-CHM-018 Need plexiglass cover.							
Eric Medina									
38437					9/25/2008		67		\$0.00
Medium	Work In Progress			9/25/2008 3:39:35 PM					
Sotelo, Enrique		need light covers plastic							
Eric Medina									
38633					10/1/2008		61		\$0.00
Medium	Work In Progress			10/1/2008 4:12:11 PM					
Gonzalez, Salvador		need to fix square tubing around 8 windows on the west and north side of building							
Eric Medina									
38779					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:03 AM					
Orozco, Danny		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
38786					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:05 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39188					10/13/2008		49		\$0.00
Medium	Work In Progress			10/13/2008 3:24:04 PM					
Ronquillo, Ruben	large square glass partition in cafeteria was broken over weekend								
<u>Eric Medina</u>									
39416	Main Building				10/23/2008		39		\$0.00
Medium	Work In Progress			10/23/2008 1:49:20 PM					
Villalobos, Margret	Head Custodian reported a problem with spiders and beetles at this site.				10/23 - Faxed to Watson for quote				
<u>Jesus Estrada</u>									
39496	Main Building	Classroom			10/27/2008		35		\$0.00
Medium	Work In Progress	ROOM 203		10/27/2008 8:38:48 AM					
Lozoya, Manny	NEED EXTRA KEY MADE FOR ROOM 203 KEY 78 THANKS								
<u>Elena Palacios</u>									
39505					10/27/2008		35		\$0.00
Medium	Work In Progress			10/27/2008 10:22:17					
Medina, Eric	as per our conversaton friday.Please cut all weeds around the bldg and school site. The cove behind library is in dire needs of attention.								
<u>Michael Munoz</u>									
39611					10/30/2008		32		\$0.00
Medium	Work In Progress			10/30/2008 12:30:11					
Lozoya, Manny	room 312 teacher complains door knob is loose								
<u>Eric Medina</u>									
39912		Parking Lot			11/6/2008		25		\$0.00
High	Work In Progress			11/6/2008 2:51:44 PM					
Medina, Eric	need to cut weeds along the east fence line,bus turn around,cove area behind library. also along west fence behind building along pine trees. i have asked you verbally to complete these task and i have not seen progress. call me when complete so i can inspect areas.								
<u>Michael Munoz</u>									
39938	Main Building	Gym			11/7/2008		24		\$0.00
Medium	Work In Progress			11/7/2008 9:41:00 AM					
Lozoya, Manny	Need to replace panic bar in boys locker room due to vandalism.								
Manny Lozoya									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
40024					11/12/2008		19		\$0.00
Medium	Work In Progress				11/12/2008 10:54:32				
Ontiveros, Guadalupe		need to order a couple of loads of gravel or base for exposed plumbing in nurses portable							
Eric Medina									
40219		Gym			11/19/2008		12		\$0.00
Medium	Work In Progress				11/19/2008 1:20:44 PM				
Sotelo, Enrique		Main light switch in the gym as you go in is very old, very hard to turn on and very hard to turn off. it's a four way switch. THANK YOU							
Robert Gonzalez									
40393					11/30/2008	12/31/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:39				
Medina, Eric		Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.							
George ZZ Gabaldon									
40394					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:39				
Medina, Eric		Monthly - Chaparral MS Monthly FE Inspection - Refer to PM schedule details.							
George ZZ Gabaldon									
40395					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:39				
Medina, Eric		Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40396					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:40				
Medina, Eric		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
Count: 30 Work Orders		Avg. Age of WO's 65		Total for Chaparral MS			0	\$0.00	

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Pride

35839	Storage A	Mechanical Room			7/10/2008		144		\$0.00
Medium	Work In Progress				7/10/2008 12:44:57 PM				
Castillo, Carlos	NEED TO MOVE RECEPTACLES LOWER OR INSTALL NEW ONE TO STORAGE ROOM TO PUMP HOUSE (WILL BE USING AS CUSTODIAL OFFICE)								

David Acosta									
36027					7/17/2008		137		\$0.00
Medium	Work In Progress	MORGAN BLDG.			7/17/2008 11:08:09 AM				
Castillo, Carlos	NEED POWER TO RUN HEATING/COOLING & OUTLETS IN MORGAN BLDG.								

David Acosta									
36356		Classroom			7/30/2008		124		\$0.00
Medium	Work In Progress	11			7/30/2008 12:37:03 PM				
Castillo, Carlos	ONE LIGHT FIXTURE OUT NEED TO REPLACE BALLAST.								

David Acosta									
36451		Classroom			8/1/2008		122		\$0.00
Medium	Work In Progress	14,15			8/1/2008 7:22:52 AM				
Castillo, Carlos	EMER. LIGHT DO NOT TURN ON IN BOTH ROOMS WHEN TURNING OFF BREAKER SWITCH FOR TESTING.								

David Acosta									
36452		Library			8/1/2008		122		\$0.00
Medium	Work In Progress				8/1/2008 7:26:27 AM				
Castillo, Carlos	EMER LIGHT WON'T STAY ON VERY LONG WHEN DOING ANNUAL TEST.								

David Acosta									
37699		Classroom			9/2/2008		90		\$0.00
Medium	Work In Progress	1,2			9/2/2008 2:08:10 PM				
Castillo, Carlos	NEED MORE EMERG. EXIT SIGNS. (ASK BY STATE FIREMARSHAL TO REQUEST).								

David Acosta									
37701		Portables			9/2/2008		90		\$0.00
Medium	Work In Progress	ROOM #16			9/2/2008 2:13:46 PM				
Castillo, Carlos	NEED SECURITY NITE LIGHT FOR LAST PORTABLE.								

David Acosta									
38592		Hallway/Corridor			10/1/2008		61		\$0.00
Medium	Work In Progress	2ND BLDG.			10/1/2008 11:52:55 AM				
Castillo, Carlos	NEED TO INSTALL RECEPTACLE FOR CANDY MACH. WALL AS NO RECEPTACLE								

David Acosta

12/1/2008 2:38:43 PM

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Desert Pride								
39333		Portables			10/21/2008		41		\$0.00	
Medium	Work In Progress	16		10/21/2008 11:07:07						
Castillo, Carlos		NEED EXIT SIGN AND EMER. LIGHT FOR LAST PORTABLE (ROOM 16).								
David Acosta										
39806		Pump House			11/4/2008		27		\$0.00	
Medium	Work In Progress			11/4/2008 11:19:45 AM						
Castillo, Carlos		NIGHT LIGHT DOES NOT TURN ON.								
David Acosta										
39845					11/5/2008		26		\$0.00	
Medium	Work In Progress			11/5/2008 8:44:00 AM						
Apodaca, Mario		Need to dispose of skunk								
David Acosta										
40369					11/30/2008	12/8/2008	1		\$0.00	
Medium	Work In Progress			11/30/2008 12:23:31						
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon										
40370					11/30/2008	12/8/2008	1		\$0.00	
Medium	Work In Progress			11/30/2008 12:23:31						
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon										
40371					11/30/2008	12/6/2008	1		\$0.00	
Medium	Work In Progress			11/30/2008 12:23:31						
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
George ZZ Gabaldon										
Count: 14 Work Orders		Avg. Age of WO's		71		Total for Desert Pride		0	\$0.00	

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
35581					7/6/2008	7/27/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:30 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35698					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:07 AM					
Villalobos, David	Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35728					7/7/2008		147		\$0.00
Medium	Work In Progress			7/7/2008 9:25:36 AM					
Lozoya, Manny	Please change core to doorknob in maintenance office to A-32.								
<u>Johnny Acuna</u>									
35816					7/10/2008		144		\$0.00
Medium	Work In Progress			7/10/2008 7:55:15 AM					
Ronquillo, Ruben	Need an awning installed outdoors on top of the back door to the library. When it rains, water comes through the door wetting the new carpet.								
<u>Johnny Acuna</u>									
36381					7/30/2008		124		\$0.00
Medium	Work In Progress			7/30/2008 9:32:01 PM					
Ontiveros, Guadalupe	Springkler system is down on the westside, it has been uncovered for a couple of weeks. Please advise as to covering the system or will it be fixed before August 1, 2008. School starts on the 4th.								
<u>Ruben Ortiz</u>									
36625					8/4/2008		119		\$0.00
Medium	Work In Progress			8/4/2008 4:14:22 PM					
Jacquez, Ricardo	Replace lift station sewage pump.								
<u>Ricardo Jacquez</u>									
36822					8/8/2008		115		\$0.00
Medium	Work In Progress			8/8/2008 9:41:58 AM					
Lozoya, Manny	Need 3 key cores to be installed in the new mulliums for the doors.								
<u>Johnny Acuna</u>									
36823					8/8/2008		115		\$0.00
Medium	Work In Progress			8/8/2008 9:43:14 AM					
Lozoya, Manny	Need a lock installed in the new filing cabinet to room #398. Mr. Varela.								
<u>Johnny Acuna</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Desert Trail Intermediate								
36887					8/11/2008		112		\$0.00	
Medium	Work In Progress	110		8/11/2008 11:51:39 AM						
Lozoya, Manny		Marisela front office receptionist needs replacement of lost key for room #110 (J66) and also need one extra (J2) key.								
Elizabeth Hernandez										
37007	Main Building	Classroom			8/13/2008		110		\$0.00	
Medium	Work In Progress			8/13/2008 11:46:28 AM						
Lozoya, Manny		Room 109 no se puede habrir. ---- J master esta doblada--- room 403 necesita llave---- banos 411 necesitan cambiar chapas---- puertas principales se atora la llave- GRACIAS								
Marisela Torres										
37034					8/13/2008		110		\$0.00	
Medium	Work In Progress			8/13/2008 3:46:59 PM						
Lozoya, Manny		Portable #408 Mr. West is having trouble unlocking door knob key cylinder. Please send me some Graffite.								
Johnny Acuna										
37197					8/19/2008		104		\$0.00	
Medium	Work In Progress			8/19/2008 2:56:15 PM						
Acuna, Johnny		.5-check lift station 7.5-Transport Bobcat tractor to Chaparral High and Help Eddie cut weeds around the back of the main building.								
Johnny Acuna										
37281	Main Building	Classroom			8/21/2008		102		\$0.00	
Medium	Work In Progress			8/21/2008 9:34:34 AM						
Lozoya, Manny		Room # 409 la puerta tiene una parte quebrada y no se puede cerrar. Gracias.								
Marisela Torres										
37286	Main Building	Office			8/21/2008		102		\$0.00	
Medium	Work In Progress			8/21/2008 11:32:48 AM						
Lozoya, Manny		Escritorio de enfermeria necesita candado de seguridad.Gracias.								
Marisela Torres										
37831	Main Building	Restroom (Boys)			9/5/2008		87		\$0.00	
Medium	Work In Progress			9/5/2008 11:30:06 AM						
Lozoya, Manny		Puerta bano maestros esta caida no cierra. puerta portable 404 esta caida no cierra. puerta principal se atora la llave. Gracias.								
Marisela Torres										

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
38075	Main Building	Cafeteria			9/15/2008		77		\$0.00
Medium	Work In Progress				9/15/2008 8:14:18 AM				
Lozoya, Manny		LA CHAPA DE LA PUERTA SE QUEBRO Y NO SE PUEDE CERRAR.							
Marisela Torres									
38213					9/18/2008		74		\$0.00
Medium	Work In Progress				9/18/2008 12:09:20 PM				
Gonzalez, Salvador		Please weld extra metal to the top of the metal scraper to add on a little more weight to it. Thank You....							
Johnny Acuna									
38214					9/18/2008		74		\$0.00
Medium	Work In Progress				9/18/2008 12:11:28 PM				
Lozoya, Manny		Please install Lock to new filing cabinet in room #399 inside the main building.							
Johnny Acuna									
38277	Main Building	Computer Lab			9/22/2008		70		\$0.00
Medium	Work In Progress				9/22/2008 8:00:19 AM				
Sotelo, Enrique		Provide electrical supply to 5 ton unit, cooling only.							
Lorenzo Solis									
38553		Classroom			9/30/2008		62		\$0.00
Medium	Work In Progress				9/30/2008 9:21:04 AM				
Lozoya, Manny		se necesita recortar e instalar 2 puertas en cuarto 407 (fueron removidas porque instalaron alfombra) gracias.							
Marisela Torres									
38554	Main Building	Custodial			9/30/2008		62		\$0.00
Medium	Work In Progress				9/30/2008 9:24:04 AM				
Lozoya, Manny		se necesitan 2 name plates--- JAIME GUTIERREZ--- CUSTODIAL OFFICE . Gracias.							
Marisela Torres									
38634					10/1/2008		61		\$0.00
Medium	Work In Progress				10/1/2008 4:14:26 PM				
Lozoya, Manny		Physical Education Coach (Mrs. Murphy) has trouble opening her classroom door with her key. Portable #404							
Johnny Acuna									
38701	Main Building	Restroom (Girls)			10/3/2008		59		\$0.00
Medium	Work In Progress				10/3/2008 11:41:44 AM				
Lozoya, Manny		URGENTE, CAMBIAR LA CHAPA DE UN BANO DE OFICINA, SE QUEDA CERRADA. CUARTO #413 LA PUERTA ESTA CAIDA , NO CIERRA.							
Marisela Torres									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
38780					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:03 AM					
Orozco, Danny		Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
38787					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:05 AM					
Orozco, Danny		Monthly - Desert Trail Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
39012					10/7/2008		55		\$0.00
Medium	Work In Progress			10/7/2008 3:30:52 PM					
Lozoya, Manny		Need a replacement Door and Door Frame for Portable #413 inside Restroom Door.							
Johnny Acuna									
39014					10/7/2008		55		\$0.00
Medium	Work In Progress			10/7/2008 3:33:24 PM					
Lozoya, Manny		Portable #410: Need a Replacement Metal Door.							
Johnny Acuna									
39122					10/10/2008		52		\$0.00
Medium	Work In Progress			10/10/2008 4:10:15 PM					
Ontiveros, Guadalupe		(Irrigation water pressure tank: Chaparral Elementary) Water leak next to the water pressure tank area.							
Johnny Acuna									
39413					10/23/2008		39		\$0.00
Medium	Work In Progress			10/23/2008 12:20:38					
Ronquillo, Ruben		Asp PM 38534 Exhaust Fan, need to replace motor on the following: FED-001, FED-003, FED-017, FED-019, FED-023, FED-036. FED-039, FED-049, FED-077.							
Johnny Acuna									
39492					10/27/2008		35		\$0.00
Medium	Work In Progress			10/27/2008 8:10:22 AM					
Ontiveros, Joe		Portable # 412. Restroom sink faucet needs to be replaced.							
Johnny Acuna									
39643					10/31/2008		31		\$0.00
Medium	Work In Progress			10/31/2008 7:36:22 AM					
Lozoya, Manny		Need a Name Plate for Portable #411 that says: (Parent Center).							
Johnny Acuna									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
39677					10/31/2008		31		\$0.00
Medium	Work In Progress			10/31/2008 4:09:15 PM					
Gonzalez, Salvador		Need to re-weld stainless sheetmetal sheet together that came apart in the kitchen sink area.							
Johnny Acuna									
39708					11/2/2008	11/10/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:41 AM					
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39759		Athletic Field			11/3/2008		28		\$0.00
Medium	Work In Progress			11/3/2008 7:38:23 AM					
Acuna, Johnny		Basketball Courts in the outdoor playground are badly cracked and separating.				Asp Mike, route back to Johnny, to order joint and filler thru Maint. Warehouse. 11/5/08			
Johnny Acuna									
39760					11/3/2008		28		\$0.00
Medium	Work In Progress			11/3/2008 7:40:41 AM					
Ronquillo, Ruben		Window frames in the side of the main doors in the NW hall needs to be replaced or repaired. There is too much corrosion.							
Johnny Acuna									
39840					11/4/2008		27		\$0.00
Medium	Work In Progress			11/4/2008 4:02:54 PM					
Ontiveros, Joe		Need to replace broken gooseneck waterfaucet in room #116.							
Johnny Acuna									
39852	Main Building	Office			11/5/2008		26		\$0.00
Medium	Work In Progress			11/5/2008 11:52:46 AM					
Lozoya, Manny		PUERTA ENTRADA PRINCIPAL, NO SE PUEDE CERRAR. GR							
Marisela Torres									
40131					11/17/2008		14		\$0.00
Medium	Work In Progress			11/17/2008 10:01:30					
Lozoya, Manny		Need to install Locks in Filing cabinets to room # 212 and Portable #412.							
Johnny Acuna									
40135					11/17/2008		14		\$0.00
Medium	Work In Progress			11/17/2008 10:49:05					
Lozoya, Manny		Need (1) key for Rm. #511 that also opens staff Restrooms. And (1) Key for Rm. #304 that also opens staff Restrooms.							
Johnny Acuna									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
40174					11/18/2008		13		\$0.00
Medium	Work In Progress				11/18/2008 10:30:37				
Ontiveros, Joe	Need to replace urinal in the Southwest hall Boy's Restroom.								
<u>Johnny Acuna</u>									
40307					11/24/2008		7		\$0.00
Medium	Work In Progress				11/24/2008 7:46:01 AM				
Lozoya, Manny	Portable #403 (Mrs. Rios) Needing a cabinet lock for wood storage cabinet. (Same as the ones installed in the workroom and Old nurse's office cabinets).								
<u>Johnny Acuna</u>									
40329		Mechanical Room			11/25/2008		6		\$0.00
Medium	Work In Progress				11/25/2008 7:36:30 AM				
Jacquez, Ricardo	Water Pressure Gauge inline with the filter inside the mechanical room is leaking oil on the floor. (Glycerine Filled)								
<u>Johnny Acuna</u>									
40408					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:44				
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40409					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:44				
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40410					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:44				
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
Count: 45 Work Orders		Avg. Age of WO's 65		Total for Desert Trail Intermediate				0	\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert View ES

35613					7/6/2008	7/14/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:40 AM					
Aguilar, Patricio	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35617					7/6/2008	7/14/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:41 AM					
Aguilar, Patricio	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35699					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:07 AM					
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35961		Cafeteria			7/15/2008		139		\$0.00
Medium	Work In Progress			7/15/2008 7:33:37 AM					
Moncayo, Fernando	MILK COOLER IS NOT WORKING AT ALL. DIANA LAZARIN SNP MGR 589-2425								
Jacqueline Aguilar									
36198					7/25/2008		129		\$0.00
Medium	Work In Progress			7/25/2008 7:12:16 AM					
Ortiz, Ruben	Perimeter Fence - clear trash and sand build up along fenceline.		Asp Lupe, route back to Ruben 9/19						
Alfredo Holguin									
36883					8/11/2008		112		\$0.00
Medium	Work In Progress	Hallways		8/11/2008 10:24:06 AM					
Hernandez, Carlos	2 Emergency Lights not working in Middle and East Hallway asp PM 36530.		Need to order thru material request and complete wo once they are replaced.						
Ruben Ortiz									
36939	Main Building				8/12/2008		111		\$0.00
Medium	Work In Progress			8/12/2008 8:37:50 AM					
Ortiz, Ruben	Tested exit signs (4) are not working 2 in Gym and Cafeteria asp PM 36526.		Need to order thru material request and complete wo once they are replaced.						
Ruben Ortiz									
37045					8/13/2008		110		\$0.00
Medium	Work In Progress			8/13/2008 8:46:58 PM					
Ortiz, Ruben	08/13/08 To: Lupe Ontiveros I am requesting to have the arroyo run off filled in and weeds scrapped. If possible with the tractors that are on the south schools area. Before the tractors are taken out.		Asp Lupe, route back to Ruben 9/19						
Ruben Ortiz									

12/1/2008 2:38:43 PM

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
37166					8/18/2008		105		\$0.00
Medium	Work In Progress				8/18/2008 5:24:18 PM				
Ortiz, Ruben	08/18/08 Called Danny Carrasco from warehouse for parts on the motor for the master cooler in room 32. Danny sent me a new motor and brace. Jose Ambriz took off a bracket from an old master cooler and brought to me to fix the master cooler in room 32. Both responded promptly. Thank you.								
Ruben Ortiz									
37634					8/31/2008		92		\$0.00
Medium	Work In Progress				8/31/2008 12:25:41 AM				
Aguilar, Patricio	Monthly - Desert View ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
Margret Villalobos									
37635					8/31/2008		92		\$0.00
Medium	Work In Progress				8/31/2008 12:25:41 AM				
Aguilar, Patricio	Monthly - Desert View ES A-1 Semiannual MCD - Refer to PM schedule details.								
Margret Villalobos									
37636					8/31/2008		92		\$0.00
Medium	Work In Progress				8/31/2008 12:25:41 AM				
Aguilar, Patricio	Monthly - Desert View ES A-1 Semiannual MCS & MCS2 - Refer to PM schedule details.								
Margret Villalobos									
37637					8/31/2008		92		\$0.00
Medium	Work In Progress				8/31/2008 12:25:42 AM				
Aguilar, Patricio	Monthly - Desert View ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos									
37639					8/31/2008		92		\$0.00
Medium	Work In Progress				8/31/2008 12:25:42 AM				
Aguilar, Patricio	Monthly - Desert View ES A-5 Quarterly SS - Refer to PM schedule details.								
Margret Villalobos									
37641					8/31/2008		92		\$0.00
Medium	Work In Progress				8/31/2008 12:25:43 AM				
Aguilar, Patricio	Monthly - Desert View ES A-13 Quarterly WREH - Refer to PM schedule details.								
Margret Villalobos									
38108					9/15/2008		77		\$0.00
Medium	Work In Progress				9/15/2008 7:13:21 PM				
Villalobos, David	Requesting for plumber to check if two water faucets can be installed for cleaning purposes								
Ruben Ortiz									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
38788					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:06 AM					
Orozco, Danny	Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38927					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:57 AM					
Ortiz, Ruben	Yearly - Desert View ES I-04 Fan Coil Yearly - Refer to PM schedule details.								
Margret Villalobos									
38928					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:57 AM					
Ortiz, Ruben	Yearly - Desert View ES U-2 Unit Heat Gas Yearly - Refer to PM schedule details.								
Margret Villalobos									
39053					10/8/2008		54		\$0.00
Medium	Work In Progress			10/8/2008 5:07:00 PM					
Villalobos, David	To Mike Munoz I was asked by Mr. Carrasco that he needs hot water and more water pressure for the shower in the Special Ed room. There is a child that needs to be bathed often and the water is too cold. He asked for an urgent work order. Mr. Carrasco asked for this work order to be sent directly to you because he wants it ASAP 10/08/08. Child is being bathed in cold water. Thank you.								
Ruben Ortiz									
39087					10/9/2008		53		\$0.00
Medium	Work In Progress			10/9/2008 5:38:14 PM					
Villalobos, David	To David Villalobos The faucet in the main office bathroom, it is leaking. Needs to be fixed asap, Teachers are complaining.								
Ruben Ortiz									
39403					10/22/2008		40		\$0.00
Medium	Work In Progress			10/22/2008 9:07:16 PM					
Villalobos, David	I am requesting that the kitchen sink in the SPED classroom to be worked on because the faucet is leaking water and needs new strainers in the sink.								
Ruben Ortiz									
39404					10/22/2008		40		\$0.00
Medium	Work In Progress			10/22/2008 9:10:57 PM					
Lara, Ralph	Carlos Castillo The button for the handicap door is not working on the southside of the building exit.								
Ruben Ortiz									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
40078					11/13/2008		18		\$0.00
Medium	Work In Progress				11/13/2008 8:07:57 PM				
Ambriz, Jose	Heater not working in portable 3 room 5, need it fixed. Called Jose Ambris.								
Ruben Ortiz									
40115					11/14/2008		17		\$0.00
Medium	Work In Progress				11/14/2008 3:16:34 PM				
Rivera, Hector	Pick up the trash all along the north side fence.								
Jesus Estrada									
40443					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:55				
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40444					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:56				
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
George ZZ Gabaldon									
40445					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:56				
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
Count: 28 Work Orders			Avg. Age of WO's	78		Total for Desert View ES	0		\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
35582					7/6/2008	7/27/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:30 AM					
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
35700					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:07 AM					
Villalobos, David	Yearly - GAC Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35802	RTC	Office			7/9/2008		145		\$0.00
Medium	Work In Progress	RTC ACROSS		7/9/2008 3:07:58 PM					
Ambriz, Jose	AS PER GLORIA SAENZ-NEED TO HAVE THE AIR CONDITIONER UNIT CHECKED. SETTINGS ARE NOT WORKING PROPERLY.								
Mary Garcia									
36280					7/28/2008		126		\$0.00
Medium	Work In Progress	Back bottom road		7/28/2008 12:11:48 PM					
Ontiveros, Guadalupe	need to apply dirt and crusherfine in back road due to running water after haevy rain.								
Juan Ambriz									
36281		Hallway/Corridor			7/28/2008		126		\$0.00
Medium	Work In Progress	C-Wing A/C unit		7/28/2008 12:13:33 PM					
Ambriz, Jose	Need to raplace relays in C-Wing unit not working properly								
Juan Ambriz									
36334		Parking Lot			7/29/2008		125		\$0.00
Medium	Work In Progress	bottom dirt		7/29/2008 3:47:57 PM					
Ontiveros, Guadalupe	Need to apply more crusherfine in bottom dirt parking lot accumulating water after rain								
Juan Ambriz									
36360					7/30/2008		124		\$0.00
Medium	Work In Progress			7/30/2008 3:14:05 PM					
Castillo, Carlos	Need to order new emergency lights for the server room not working total of two								
Juan Ambriz									
36949		Office			8/12/2008		111		\$0.00
Medium	Work In Progress	A-WING		8/12/2008 10:35:44 AM					
Ambriz, Juan	IF IT WOULD BE POSSIBLE TO HAVE THE AIR VENTS IN JESUS REYE'S OFFICE ADJUSTED. NOT ENOUGH AIR COMES THROUGH.								
Mary Garcia									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
37189		Office			8/19/2008		104		\$0.00
Medium	Work In Progress	B-WING		8/19/2008 10:23:04 AM					
Castillo, Carlos	AS PER ANNE- IN LUDYM'S OFFICE (NEW FINANCE DIRECTOR) ONE OF THE FLUORESCENT LIGHT FIXTURES DOES NOT HAVE A COVERING AND NEEDS ONE PLEASE.								
Mary Garcia									
37827		Office			9/5/2008		87		\$0.00
Medium	Work In Progress	C-WING		9/5/2008 11:09:26 AM					
Ambriz, Jose	AS PER MS. LOZANO-NEED TO HAVE A NEW AIR UNIT INSTALLED IN CARMEN MORRISSETT'S OFFICE/COPY ROOM. DUE TO NEW COPIERS ARE OVER HEATING.		APPROVED BY MR. CHAVEZ. ALSO, JUAN STATED HE TALKED W/JOE AMBRIZ AND ARE GOING TO REPLACE THE WINDOW UNITS FIRST AND IF THAT DOES NOT WORK THEN THEY WILL TRY GOING THROUGH THE ROOF. AS PER JOSE 2 NEW WINDOW UNITS WILL TAKE CARE OF THE PROBLEM.						
Mary Garcia									
37828		Office			9/5/2008		87		\$0.00
Medium	Work In Progress	B-WING		9/5/2008 11:13:08 AM					
Ambriz, Juan	AS PER MS. BROWDER-WOULD LIKE TO HAVE HER WHOLE OFFICE PAINTED. IF IT WOULD BE POSSIBLE FOR THE DATES OF 9/16 OR 9/17TH, BEFORE FURNITURE COMES IN ON 9/18/08.		APPROVED BY MR. RICHARD G. CHAVEZ. AS PER JUAN, HE HAS ENOUGH PAINT.						
Mary Garcia									
37829		Office			9/5/2008		87		\$0.00
Medium	Work In Progress	B-WING		9/5/2008 11:15:03 AM					
Mary Garcia	AS PER MS. BROWDER-WOULD LIKE TO HAVE HER OFFICE WAXED, DUE TO GETTING NEW FURNITURE ON 9/18/09. IF THIS CAN BE DONE ON THE FOLLOWING DATES: 9/16 OR 9/17/08.								
37844					9/5/2008		87		\$0.00
Medium	Work In Progress	Districts vehicle		9/5/2008 3:13:38 PM					
Gonzales, Angel	Need to do tune-up to maintenance vehicle # 140								
Juan Ambriz									
37912		Parking Lot			9/8/2008		84		\$0.00
Medium	Work In Progress	bottom dirt		9/8/2008 3:39:17 PM					
Ontiveros, Guadalupe	Need to level bottom parking lot with crusher fine to avoid accumulated water after rains								
Juan Ambriz									
37939					9/9/2008		83		\$0.00
Medium	Work In Progress	Back dirt road		9/9/2008 8:25:56 AM					
Ontiveros, Guadalupe	need to add dirt to back dirt road due to running water after rains. If possible add crusher fine.								
Juan Ambriz									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
37978		Office			9/9/2008		83		\$0.00
Medium	Work In Progress	A-WING		9/9/2008 4:42:49 PM					
Castillo, Carlos		AS PER ELISA-NEED AN ELECTRICAL OUTLET TO BE INSTALLED IN THE SUPT. CONFERENCE CLOSET.							
Mary Garcia									
37979		Office			9/9/2008		83		\$0.00
Medium	Work In Progress	A-WING		9/9/2008 4:44:25 PM					
Castillo, Carlos		AS PER ELISA-NEED TO HAVE AN ELECTRICAL OUTLET IN HER OFFICE REMOVED.							
Mary Garcia									
37984		Office			9/10/2008		82		\$0.00
Medium	Work In Progress	C-WING		9/10/2008 10:29:18 AM					
Ambriz, Juan		AS PER MS. PHILLIPS-NEED TO HAVE A TV & DVD PLAYER STRAPPED DOWN TO THE CART THAT WAS PURCHASED.							
Mary Garcia									
38423		Cafeteria			9/25/2008		67		\$0.00
Medium	Work In Progress			9/25/2008 8:29:48 AM					
Moncayo, Fernando		DELI COOLER - CONDENSING UNIT ON ROOF NEEDS A POWER DISCONNECT FOR SAFETY -- TOP PRIORITY				10/27 - Asp Mike, route to Cali 11/18 - Route back to Fernie asp Mike			
		AIDA SALCEDO - SNP COORDINATOR 882-6772							
Alma Terrell									
38646					10/2/2008		60		\$0.00
Medium	Work In Progress			10/2/2008 2:30:47 PM					
Castillo, Carlos		Asp PM 37606, still waiting on Emerg. Light for Board Rm and Sever Rm not working.							
Juan Ambriz									
38781					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:03 AM					
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
38789					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:06 AM					
Orozco, Danny		Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
38879					10/5/2008	10/21/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:39 AM					
Ambriz, Juan		Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.							
Margret Villalobos									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
39066		Office			10/9/2008		53		\$0.00
Medium	Work In Progress	C-WING		10/9/2008 9:56:10 AM					
Ambriz, Juan	AS PER MS. NORMA DURAN-NEED TO HAVE SOME HOLES PATCHED UP, DUE TO REMOVAL OF SOME FILING CABINETS IN THE BILINGUAL OFFICE.								
Mary Garcia									
39366		Office			10/22/2008		40		\$0.00
Medium	Work In Progress	C-WING		10/22/2008 9:54:03 AM					
Ambriz, Juan	AS PER ALFREDO-GO AHEAD AND SEAL OFF THE WALL WHERE THE AIR UNIT WAS IN OFELIA'S OFFICE.		APPROVED BY ALFREDO						
Mary Garcia									
40020		Cafeteria			11/12/2008		19		\$0.00
Medium	Work In Progress			11/12/2008 9:26:48 AM					
Moncayo, Fernando	DELI UNIT IS NOT WORKING - COOLING								
	GESSICA BLAZQUEZ - SNP MANAGER 882-6784								
Alma Terrell									
40223		Office			11/19/2008		12		\$0.00
Medium	Work In Progress	B-WING		11/19/2008 2:24:32 PM					
Villalobos, David	AS PER MR. CHAVEZ-NEED TO HAVE THE PLUMBER COME IN AND CHECK OUT THE SINK BEHIND RECEPTIONIST AREA IN B WING, OVER WITH VANESSA. THERE IS A REAL BAD SEWER SMELL.		JUAN HAS ALREADY TAKEN A LOOK AT THIS AND SMELL STILL CONTINUES.						
Mary Garcia									
40258		Office			11/20/2008		11		\$0.00
Medium	Work In Progress	A-WING		11/20/2008 10:10:30					
Ambriz, Jose	AS PER JUAN AMBRIZ-ANN'S OFFICE HEATER IS THROWING COLD AIR.		JUAN ALREADY TALKED W/JOSE AMBRIZ AND WAITING FOR A PART FOR HEATER UNIT.						
Mary Garcia									
40275		Office			11/20/2008		11		\$0.00
Medium	Work In Progress	A-WING		11/20/2008 3:59:32 PM					
Carrasco, Danny	AS PER JULIE & ANN-NEED TO BORROW A PORTABLE HEATER FOR FIRST THING TOMORROW MORNING. (APPROVED BY MR. RICHARD G. CHAVEZ)								
Mary Garcia									
40418					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:47					
Ambriz, Juan	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.								
George ZZ_Gabaldon									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
40419					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:47				
Ambriz, Juan		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40420					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:48				
Ambriz, Juan		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
Count: 32 Work Orders			Avg. Age of WO's	74			Total for GAC	0	\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
35479	Football Stadium	Football Field			7/1/2008		153		\$0.00
Medium	Work In Progress				7/1/2008 8:20:32 AM				
Ontiveros, Guadalupe		The chain link fence by the guest bleachers need to be repaired at the football field.							
<u>Mario Apodaca</u>									
35701					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress				7/6/2008 12:20:08 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
35873	Main Building	Office			7/11/2008		143		\$0.00
Medium	Work In Progress				7/11/2008 2:16:35 PM				
Lara, Ralph		NEW NAME PLATES (3) MR. CAREY L. CHAMBERS							
<u>Mario Apodaca</u>									
35876	Main Building	Office			7/11/2008		143		\$0.00
Medium	Work In Progress				7/11/2008 2:28:45 PM				
Carrasco, Danny		NEED NEW BLINDS FOR PRINCIPAL CHAMBERS OFFICE 1. 40" X 5' 2. 7' X 5'							
<u>Mario Apodaca</u>									
35877	Main Building	Office			7/11/2008		143		\$0.00
Medium	Work In Progress				7/11/2008 2:32:00 PM				
Ambriz, Jose		NEW WINDOW AC UNIT FOR PRINCIPAL CHAMBERS							
<u>Mario Apodaca</u>									
35993	Boys Gym	Office			7/16/2008		138		\$0.00
Medium	Work In Progress				7/16/2008 2:28:31 PM				
Ambriz, Jose		Requested by Coach Lawrence Rm. 401 Office in Boy's Gym-Room 401 does not have any air conditioning, would like to have a unit installed this summer of 2008, to review videos and to watch films for Soccer.							
<u>Velia Alarcon</u>									
36000	Library	Library			7/16/2008		138		\$0.00
Medium	Work In Progress				7/16/2008 3:18:40 PM				
Ontiveros, Guadalupe		An irrigation control box has a water leak underneath the asphalt outside the southwest exit.							
<u>Albert Vallejo</u>									
36066	North Building	Classroom			7/18/2008		136		\$0.00
Medium	Work In Progress				7/18/2008 3:19:18 PM				
Ronquillo, Ruben		NEED NEW WINDOW BLINDS (35"WX56"L) FOR ROOM 207 NEED 11 EA							
<u>Mario Apodaca</u>									
12/1/2008 2:38:44 PM									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
36067	Old English Bldg	Classroom			7/18/2008		136		\$0.00
Medium	Work In Progress				7/18/2008 3:21:06 PM				
Ambriz, Jose	NEED A NEW HEATING CONDESER AT ROOM 141 DO TO VANDALISM								
Mario Apodaca									
36186	Cafeteria (1998)	Cafeteria			7/24/2008		130		\$0.00
Medium	Work In Progress				7/24/2008 3:18:50 PM				
Moncayo, Fernando	WALK - IN FREEZER DOWN.								
GHS SNP 882-5522									
Jacqueline Aguilar									
36231					7/25/2008		129		\$0.00
Medium	Work In Progress				7/25/2008 3:04:45 PM				
Ontiveros, Guadalupe	Requested by Coach Hite for Football Field-Football field is very uneven. Please level as it is very dangerous.								
Velia Alarcon									
36288	Vocational	Classroom			7/28/2008		126		\$0.00
Medium	Work In Progress	568			7/28/2008 3:08:02 PM				
Carrasco, Danny	Window frames in front of classroom are in bad repair and need to be completely replaced. Large amounts of water get through during rainstorms.								
Albert Vallejo									
36310	Cafeteria (1998)	Cafeteria			7/29/2008		125		\$0.00
Medium	Work In Progress				7/29/2008 8:10:33 AM				
Moncayo, Fernando	NEED A SAFETY POWER DISCONNECT TO THE GHS WALK-IN'S (BOTH) ON THE CONDENSER UNITS ON THE ROOF						11/18 - Asp Mike route to Fernie		
MR. DEMETRIIOUS GIOVAS									
Jacqueline Aguilar									
36359		Cafeteria			7/30/2008		124		\$0.00
Medium	Work In Progress				7/30/2008 3:02:54 PM				
Moncayo, Fernando	need to ck the ice maker compressors at the cafe it is tipping the circuit breaker								
Mario Apodaca									
36386	Main Building	Classroom			7/31/2008		123		\$0.00
Medium	Work In Progress	127			7/31/2008 8:53:23 AM				
Lara, Ralph	The double doors on room 127 need to be replaced. When closed, they are hard to open due to swelling. When closed, they are hard to close because the hinges no longer take firm purchase on the door or jamb.								
Albert Vallejo									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
36403	Academic Bldg				7/31/2008		123		\$0.00
Medium	Work In Progress				7/31/2008 1:52:38 PM				
Lara, Ralph	Requested by Ms. Leahy Rm. 328 Academic Building- Put a lock on the left-hand built-in cabinet.								
<u>Velia Alarcon</u>									
36622					8/4/2008		119		\$0.00
Medium	Work In Progress	WWT			8/4/2008 4:10:54 PM				
Sanchez, Raul	Replace motor for Wastewater Treatment Plant Blowers.								
<u>Raul Sanchez</u>									
36774	Academic Bldg				8/7/2008		116		\$0.00
Medium	Work In Progress				8/7/2008 1:58:16 PM				
Lara, Ralph	Requested by Ms. Howard Rm. 307 Academic Building- A cylinder with two keys are needed for file cabinet in classroom. Cabinet has not cylinder.								
<u>Velia Alarcon</u>									
36776	Old English Bldg				8/7/2008		116		\$0.00
Medium	Work In Progress				8/7/2008 2:19:22 PM				
Lara, Ralph	Requested by Mr. Stemsrud Rm. 154 Old English Building-Need two keys made for file cabinet in classroom.								
<u>Velia Alarcon</u>									
36783	Academic Bldg				8/7/2008		116		\$0.00
Medium	Work In Progress				8/7/2008 2:58:49 PM				
Apodaca, Mario	Requested by Coach Hite-Paint Cactus Sculpture on south west corner of academic building.								
<u>Velia Alarcon</u>									
36878	Boys Gym				8/11/2008		112		\$0.00
Medium	Work In Progress				8/11/2008 8:35:04 AM				
Marquez, Gerardo	new shower column was installed in girls dressing room. need to install tile to complete project.see mike. thxs								
<u>Michael Munoz</u>									
36896	Boys Gym	Gym			8/11/2008		112		\$0.00
Medium	Work In Progress				8/11/2008 2:55:29 PM				
Castillo, Carlos	NEED A NEW SWITCH FOR THE E/COOER UNIT AT THE BOYS GYM								
<u>Mario Apodaca</u>									
37049	Football Stadium	Football Field			8/14/2008		109		\$0.00
Medium	Work In Progress				8/14/2008 8:14:03 AM				
Munoz, Michael	Some of the concrete piers that support the bleachers are cracked and need to be repaired.								
<u>Albert Vallejo</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
37094	Cafeteria (1998)	Cafeteria			8/14/2008		109		\$0.00
Medium	Work In Progress				8/14/2008 3:40:19 PM				
Ambriz, Jose	ALL OUTSIDE DUCTS OF THE CAFE BLDG NEED TO BE RESEAL DOTO SUN AND WATER DAMAGE. ASAP								
Mario Apodaca									
37099	Boys Gym	Gym			8/15/2008		108		\$0.00
Medium	Work In Progress				8/15/2008 7:44:21 AM				
Appelzoller, Fred	install collars to cover vents and water to showers in boys gym as per mike.								
Fred Appelzoller									
37143	New Vocational	Hallway/Corridor			8/18/2008		105		\$0.00
Medium	Work In Progress				8/18/2008 2:43:34 PM				
Ronquillo, Ruben	Need window glass replaced, Approximately 24" x 30" in size. (wired glass)								
Albert Vallejo									
37144	Computer	Electrical Room			8/18/2008		105		\$0.00
Medium	Work In Progress				8/18/2008 2:46:26 PM				
Castillo, Carlos	Contactor for computer outlets intermitently makes more noise than normal.								
Albert Vallejo									
37145					8/18/2008		105		\$0.00
Medium	Work In Progress				8/18/2008 2:48:35 PM				
Gonzalez, Salvador	The chain link fence directly south of the band room has been hit by a vehicle, one post is down and the mesh has been torn								
Albert Vallejo									
37232	Old English Bldg	Classroom			8/20/2008		103		\$0.00
Medium	Work In Progress				8/20/2008 2:03:04 PM				
Carrasco, Danny	NEED NEW WINDOW MINI BLINDS DOTO VANDALISM (W43 1/2"X L90") NEED #4								
Mario Apodaca									
37233	Academic Bldg				8/20/2008		103		\$0.00
Medium	Work In Progress				8/20/2008 2:15:18 PM				
Ambriz, Jose	AT THE ACADEMIC BLDG NEED NEW E/COOLER STANDS								
Mario Apodaca									
37234	Cafeteria (1998)				8/20/2008		103		\$0.00
Medium	Work In Progress				8/20/2008 2:17:31 PM				
Ambriz, Jose	AT THE CAFE BLDG NEED NEED NEW E/COOER STANDS								
Mario Apodaca									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
37235	Cafeteria (1998)	Restroom (Boys)			8/20/2008		103		\$0.00
Medium	Work In Progress				8/20/2008 2:25:19 PM				
Lara, Ralph	NEED TO PUT A NEW DEADBOLTS ON THE TOW RESTROOMS DOORS .ASAP								
Mario Apodaca									
37284					8/21/2008		102		\$0.00
Medium	Work In Progress				8/21/2008 11:13:30 AM				
Ronquillo, Ruben	8 SIGNS (24 X 18) THAT READ THE FOLLOWING: GHS IS A DRUG FREE CAMPUS NO SMOKING NO ALCOHOL NO WEAPONS NO PETS								
Mario Apodaca									
37295	Agricultural	Classroom			8/21/2008		102		\$0.00
Medium	Work In Progress				8/21/2008 2:52:32 PM				
Appelzoller, Fred	need a new sink and faucet set put-in at room 569								
Mario Apodaca									
37299					8/21/2008		102		\$0.00
Medium	Work In Progress				8/21/2008 2:59:39 PM				
Apodaca, Mario	8-20-08					8/20-8			
	6-painting a class room at the a.g bldg room 569 1-t/shoot a/c unit at the n-bldg too room 202 1-in put to school dude								
Mario Apodaca									
37306					8/21/2008		102		\$0.00
Medium	Work In Progress				8/21/2008 3:20:25 PM				
Vallejo, Albert	(8-21-08) 2 hrs - Troubleshoot and repair A/C unit on top of varsity gym; 2 hrs - Finish restroom wall and install urinal in boys gym; 3 hrs - repair partitions in boys restroom in cafeteria; 1 hr - Fire extinguisher inspections (work order #36494)					8/21-7			
Albert Vallejo									
37360	Grounds Shop				8/25/2008		98		\$0.00
Medium	Work In Progress				8/25/2008 12:51:17 PM				
Castillo, Carlos	I need an electrician to disconnect power to burned-out motor at wwtp and assist me in installing a new blower motor. We may need a small crane to lift new motor up to wwtp platform. Thanks, Raul								
Raul Sanchez									
37398					8/26/2008		97		\$0.00
Medium	Work In Progress				8/26/2008 3:27:40 PM				
Apodaca, Mario	Requested by Mrs. Smith Rm. 127 Main Building- Need the overhead screen placed above chalkboard.								
Velia Alarcon									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
37400					8/26/2008		97		\$0.00
Medium	Work In Progress			8/26/2008 3:35:15 PM					
Castillo, Carlos	Requested by Mr. Roberson for Rm. 127 Main Building-Install on/off switch for lights in room #127. When room was divided switch was left in room #128.								
Velia Alarcon									
37421					8/26/2008		97		\$0.00
Medium	Work In Progress			8/26/2008 4:18:55 PM					
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Remove frame from North Batting Cage and deliver to Softball Field.								
	See Coach Bones and Coach Lopez before beginning work.								
Velia Alarcon									
37423					8/26/2008		97		\$0.00
Medium	Work In Progress			8/26/2008 4:21:08 PM					
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Take nets off of north batting cage and place them on the south east batting cage.								
	See Coach Bones before beginning work.								
Velia Alarcon									
37426					8/26/2008		97		\$0.00
Medium	Work In Progress			8/26/2008 4:28:51 PM					
Lara, Ralph	Requested by Mrs. Smith Rm. 127 Main Building-Can not lock or unlock door from the inside. This is a hazard during fire drills such as freezes or lock downs. This is an old door handle that should be replaced.								
Velia Alarcon									
37431					8/27/2008		96		\$0.00
Medium	Work In Progress			8/27/2008 8:10:43 AM					
Gonzalez, Salvador	NEED TO CONSTRUCT SHADE AT GROUNDS DEPT. TO PROTECT IMPLEMENT.								
Guadalupe Ontiveros									
37442					8/27/2008		96		\$0.00
Medium	Work In Progress			8/27/2008 10:51:46 AM					
Ontiveros, Guadalupe	Requested by Coach Hite for Football Field-Sod bare areas on Football Field before first home game on September 12th.								
Velia Alarcon									
37444	Old English Bldg				8/27/2008		96		\$0.00
Medium	Work In Progress			8/27/2008 11:31:54 AM					
Apodaca, Mario	Requested by Mr. Stemsrud Rm. 154 Old English Building-Hang maps.								
Velia Alarcon									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
37691	Academic Bldg				9/2/2008		90		\$0.00
Medium	Work In Progress			9/2/2008 11:42:35 AM					
Apodaca, Mario	Requested by Ms. Luna Rm. 318 Academic Building- Paint the office.								
<u>Velia Alarcon</u>									
37708	Cafeteria (1998)	Custodial			9/2/2008		90		\$0.00
Medium	Work In Progress			9/2/2008 2:46:32 PM					
Gonzales, Angel	i have a preasure washer that will start but has very little water preasure when operating								
<u>Joe Munoz</u>									
37996	Agricultural	Classroom			9/10/2008		82		\$0.00
Medium	Work In Progress			9/10/2008 3:10:19 PM					
Ronquillo, Ruben	need new window blinds for room 568.ea 2 (60 1/2"x45")								
<u>Mario Apodaca</u>									
38074					9/14/2008		78		\$0.00
Medium	Work In Progress			9/14/2008 12:23:09 AM					
Ontiveros, Guadalupe	Monthly - Gadsden HS Soil Sampling - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38165	Cafeteria (1998)	Restroom (Boys)			9/17/2008		75		\$0.00
Medium	Work In Progress			9/17/2008 8:25:05 AM					
Ronquillo, Ruben	a cafe window need to be repairs at the boys restroom do to vandalism (20"x20")								
<u>Mario Apodaca</u>									
38284					9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 9:40:57 AM					
Vallejo, Albert	Requested by Mr. Roberson for Campus-Paint all paintable surfaces on campus restrooms white.								
<u>Velia Alarcon</u>									
38286					9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 10:13:18 AM					
Apodaca, Mario	Requested by Ms. Lam Rm. 104 Main Building-Holder of the glass door of the south book shelf is broken.								
<u>Velia Alarcon</u>									
38287					9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 10:30:07 AM					
Villalobos, David	Requested by Ms. Lam Rm. 104 Main Building-Both cold and hot water of the faucet on the south side have sulfur smell.								
<u>Velia Alarcon</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

38288					9/22/2008		70	1	\$25.00
Medium	Work In Progress			9/22/2008 10:35:59 AM					
Briones, Enrique	Requested by Coach Hite and Coach Maxey Football Laundry Room-Remove old dryer and metal objects from laundry room. Also, tables and chairs that are broken and stored in there. Remove refrigerator from Football locker room.		11/17/08 Items are on inventory, forwarded to purchasing warehouse for pickup.						
Velia Alarcon									
38290					9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 10:47:38 AM					
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Pour cement in battiang cages (2) behind dugout.								
Velia Alarcon									
38292					9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 10:58:14 AM					
Apodaca, Mario	Requested by Ms. Aguilar Rm. 236 North Building-Replace burned out light bulbs.								
Velia Alarcon									
38293					9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 10:59:47 AM					
Apodaca, Mario	Requested by Ms. Leahy Rm. 328 Academic Building-Window does not have screen, please install one.								
Velia Alarcon									
38294					9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 11:05:39 AM					
Lara, Ralph	Requested by Ms. Moreno Rm. 126 Main Building-The door is fallen and hard to close. The key is very hard to get out of the lock and the door sometimes gets stuck and students can not get out. This could be a problem during fire drills.								
Velia Alarcon									
38296					9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 11:16:00 AM					
Vallejo, Albert	Requested by Ms. Roth Rm. 213 North Building-Legs are loose on various HEAVY lab tables and need to be tightened and possibly secured. Table tops are not attached to certain tables and also pose a safety hazard and noise maker.								
Velia Alarcon									
38302					9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 11:36:02 AM					
Lara, Ralph	Requested by Velia for Pre-School Play Ground-A pad lock with chain needs to be placed on gate into the Pre-School Play Ground.								
Velia Alarcon									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
38303	Main Building	Custodial			9/22/2008		70		\$0.00
Medium	Work In Progress				9/22/2008 11:49:06 AM				
Gonzales, Angel		i have two weeders that will not start and needs maintnence							
Joe Munoz									
38305					9/22/2008		70		\$0.00
Medium	Work In Progress				9/22/2008 12:04:36 PM				
Briones, Enrique		Requested by Coach Hite for Football Fieldhouse (Boy's Gym)-Please remove refrigerator, does not work.				11/17/08 Items are on inventory, forwarded to purchasing warehouse for pickup.			
Velia Alarcon									
38429	Academic Bldg	Classroom			9/25/2008		67		\$0.00
Medium	Work In Progress				9/25/2008 2:39:13 PM				
Carrasco, Danny		need windos blinds (46 3/4" x 62") for the academic bldg need 10							
Mario Apodaca									
38465					9/26/2008		66		\$0.00
Medium	Work In Progress				9/26/2008 12:29:32 PM				
Lozoya, Manny		Mr. Chacon, Band Director needs a gate key.							
Michael Munoz									
38493					9/29/2008		63		\$0.00
Medium	Work In Progress				9/29/2008 10:43:07 AM				
Ontiveros, Guadalupe		Requested by Coach A. Lopez for Softball Field Varsity Batting Cage-Patio, cement inside of batting cage.							
Velia Alarcon									
38497					9/29/2008		63		\$0.00
Medium	Work In Progress				9/29/2008 10:57:19 AM				
Carrasco, Danny		Requested by Julio Alcantar for Student Parking Lot-Need more electrical poles to help mark the parking spaces in the student parking lot.							
Velia Alarcon									
38538					9/30/2008		62		\$0.00
Medium	Work In Progress				9/30/2008 12:26:03 AM				
Apodaca, Mario		Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
38570					9/30/2008		62		\$0.00
Medium	Work In Progress				9/30/2008 3:20:12 PM				
Gonzalez, Salvador		need tow screen for vents at the girls gym							
Mario Apodaca									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
38604					10/1/2008		61		\$0.00
Medium	Work In Progress			10/1/2008 2:02:50 PM					
Ambriz, Jose	Requested by Ms. Hartmann Rm. 568 Classroom between Ag. Shop and Wood Shop-Install an extracting fan to remove fumes coming into room 568, created by Auto and Ag engines. There's currently no way for fumes to exit from classroom. Fumes giving teacher and students headaches.								
<u>Velia Alarcon</u>									
38617		Athletic Field			10/1/2008		61		\$0.00
Medium	Work In Progress			10/1/2008 3:32:18 PM					
Lara, Ralph	Ag Teacher needs a small gauge Padlock for a diesel tank in the north alfalfa field near the pig farm. The lock should be keyed to F3.								
<u>Albert Vallejo</u>									
38744					10/5/2008		57		\$0.00
Medium	Work In Progress			10/5/2008 12:23:50 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.		10/6/08 - Emailed to Ricky Borrego						
<u>Margret Villalobos</u>									
38746					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:23:51 AM					
Vallejo, Albert	Monthly - Gadsden HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38747					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:23:51 AM					
Vallejo, Albert	Yearly - Gadsden HS H6 (Furnace)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38748					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:23:51 AM					
Vallejo, Albert	Yearly - Gadsden HS R9 (H.W.Radiator)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38790					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:06 AM					
Orozco, Danny	Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38891					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:44 AM					
Apodaca, Mario	Yearly - Gadsden HS I4 (Fan Coil)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
12/1/2008 2:38:44 PM									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
38893					10/5/2008	10/13/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:44 AM					
Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38954	Cafeteria (1998)	Cafeteria			10/6/2008		56		\$0.00
Medium	Work In Progress			10/6/2008 10:39:01 AM					
Moncayo, Fernando	ICE MACHINE IS DOWN AGAIN - FERNANDO WAS AT GAC ON 10/3/08, I (ALMA) TOLD HIM OF THE PROBLEM.								
	SARA GARCIA - SNP ASST. MANAGER 882-5522								
<u>Alma Terrell</u>									
38974	Academic Bldg	Classroom			10/6/2008		56		\$0.00
Medium	Work In Progress			10/6/2008 3:03:50 PM					
Ambriz, Jose	need new e/cooler unit at the academic bldg need 20 e.a								
<u>Mario Apodaca</u>									
38997	Main Building				10/7/2008		55		\$0.00
Medium	Work In Progress			10/7/2008 11:33:11 AM					
Munoz, Joe	Requested by Velia for Front Office in Main Building- Since air quality and mold are a concern today. There are several spots in the Front Office that have leaked when it rains and dark spots have started to grow in these areas. Please test areas for mold and clean them. Although this problem won't be resolved until the roof is either repaired or re-roofed. Main Building has several leaks through out the building.					10/7 - Asp Mike, rout to Custodial FAX W.O. TO JOE			
<u>Velia Alarcon</u>									
39030	Main Building				10/8/2008		54		\$0.00
Medium	Work In Progress			10/8/2008 10:44:21 AM					
Lara, Ralph	lost a key to the book keerer office and the concession stand at the old eng bldg need to be rekey								
<u>Mario Apodaca</u>									
39073	Agricultural	Classroom			10/9/2008		53		\$0.00
Medium	Work In Progress			10/9/2008 3:15:51 PM					
Ronquillo, Ruben	need a window blind for room 569 (60"x48")								
<u>Mario Apodaca</u>									
39097					10/10/2008		52		\$0.00
Medium	Work In Progress			10/10/2008 11:31:16					
Lara, Ralph	Requested by Coach Letz for Storage Room in Girl's Gym-The door bolt came off the door knob, the loose bolt is in Velia's Office. Please pick it up when the door knob will be fixed.								
<u>Velia Alarcon</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
39132					10/12/2008	10/28/2008	50		\$0.00
Medium	Work In Progress			10/12/2008 12:20:51					
Munoz, Joe	Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
39205	Football Stadium	Football Field			10/14/2008		48		\$0.00
Medium	Work In Progress			10/14/2008 8:00:12 AM					
Castillo, Carlos	As per Raul Sanchez, need to disconnect football field irrigation pump. Need to come back and reconnect after Anthony Pump services it.								
<u>Carlos Castillo</u>									
39252	Old English Bldg	Classroom			10/15/2008		47		\$0.00
Medium	Work In Progress			10/15/2008 12:27:17					
Ambriz, Jose	need a new damper motor for the heating unit at the old eng bldg								
<u>Mario Apodaca</u>									
39287					10/20/2008		42		\$0.00
Medium	Work In Progress			10/20/2008 10:53:12					
Castillo, Carlos	Requested by Velia for Marque in Front of School-The left side light to the marque is burned out or has no electricity running to it, please repair.								
<u>Velia Alarcon</u>									
39300	North Building	Classroom			10/20/2008		42		\$0.00
Medium	Work In Progress			10/20/2008 2:38:24 PM					
Moncayo, Fernando	the deli cart cooler is not working need to be fix ASAP.at room 233 n-bldg.								
<u>Mario Apodaca</u>									
39506	Academic Bldg				10/27/2008		35		\$0.00
High	Work In Progress			10/27/2008 10:25:31					
Castillo, Carlos	as per mr.chambers, the north end of the outside of the building is lacking lighting. this is a pick-up area and is safety issue.please see if exterior lighting can be placed. presently there is 1 exterior light. would like more lights that would illuminte more. thxs								
<u>Carey Chambers</u>									
39510					10/27/2008		35		\$0.00
Medium	Work In Progress			10/27/2008 10:59:35					
Lara, Ralph	Requested by Mr. Enriquez Rm. 580 Auto Shop-Repair damaged doors to storage room and office.								
<u>Velia Alarcon</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
39511	Academic Bldg				10/27/2008		35		\$0.00
Medium	Work In Progress			10/27/2008 11:01:57					
Castillo, Carlos	Requested by Ms. Leahy Rm. 328 Academic Building- Check the outlets on the south wall and all wiring in the classroom. I keep blowing the bulb in the overhead projector.								
<u>Velia Alarcon</u>									
39621	New Vocational	Classroom			10/30/2008		32		\$0.00
High	Work In Progress			10/30/2008 2:08:48 PM					
Ambriz, Jose	the heating unit at rom 551 has a carbon monoxide of 5ppm need a new heating unit asap								
<u>Mario Apodaca</u>									
39646	Main Building				10/31/2008		31		\$0.00
Medium	Work In Progress			10/31/2008 9:13:58 AM					
Gonzalez, Salvador	Make stands for new refrigeration units and reinforce beams. Talk to Mike								
<u>Salvador Gonzalez</u>									
39679					11/2/2008	11/8/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:29 AM					
Vallejo, Albert	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39717					11/2/2008	11/10/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:44 AM					
Vallejo, Albert	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39753					11/2/2008	12/3/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:58 AM					
Vallejo, Albert	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39823	Auto Shop	Classroom			11/4/2008		27		\$0.00
Medium	Work In Progress			11/4/2008 3:05:39 PM					
Lara, Ralph	need 2 new doors at the auto shop the doors are broken do to vandalism								
<u>Mario Apodaca</u>									
39924	Business	Classroom			11/6/2008		25		\$0.00
Medium	Work In Progress			11/6/2008 3:41:13 PM					
Ambriz, Jose	need a new gas valve for the heating unit at room 660 at the bus bldg it is a york unit								
<u>Mario Apodaca</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

40007 11/11/2008 20 \$0.00

Medium Work In Progress 11/11/2008 3:32:35 PM

Orozco, Danny I need to have someone operate a bucket truck or a small crane to remove a bad motor and blower from atop of wastewater plant. The person operating then has to put in place a new motor and blower that I have in stock. Thanks, Raul Sanchez

Raul Sanchez

40054 Old English Bldg Gym 11/13/2008 18 \$0.00

Medium Work In Progress 11/13/2008 3:05:05 PM

Munoz, Michael the girls gym need work on the gym floor do to roof leaks . A.S.A.P

Mario Apodaca

40139 Cafeteria (1998) Cafeteria 11/17/2008 14 \$0.00

Medium Work In Progress 11/17/2008 12:11:14

Moncayo, Fernando need to put new lamps and ballast at the mens restroom at the kitchen

Mario Apodaca

40142 11/17/2008 14 \$0.00

Medium Work In Progress 11/17/2008 12:26:28

Apodaca, Mario 11-14-08 11/14-8
 1.5-went to the p.p.d for supplies and gas-up
 1.5-ck water boiler unit at bldg
 2-t/shoot heating unit at the n-bldg at the annex bldg
 1-fix a door lever set at the academic bldg to room 331
 1-went to put new traps at camp lab
 1-ck the electrical heater unit at the main bldg

Mario Apodaca

40175 Library 11/18/2008 13 \$0.00

Medium Work In Progress 11/18/2008 12:07:45

Appelzoller, Fred Requested by Dolores Nanez for Girl's Restroom in Library-Faucet in girl's restroom licks on the floor because the water flow doesn't shut off.

Velia Alarcon

40177 11/18/2008 13 \$0.00

Medium Work In Progress 11/18/2008 12:10:04

Lara, Ralph Requested by Mr. Villa Rm. 510 Band Room-Double door on south side, door drop mount came off from the top inside of the door.

Velia Alarcon

40178 11/18/2008 13 \$0.00

Medium Work In Progress 11/18/2008 12:12:05

Vallejo, Albert Requested by Mr. Villa Rm. 510 Band Room-Window on the south west corner of the band room is not sealed and allows dirt and dust to come into the band room.

Velia Alarcon

12/1/2008 2:38:44 PM

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Gadsden HS								
40179	North Building	Classroom			11/18/2008		13		\$0.00	
Medium	Work In Progress				11/18/2008 12:43:04					
Ambriz, Jose		need a new fan limit control for a heating unit at the n-bldg to room 213								
Mario Apodaca										
40180	North Building	Classroom			11/18/2008		13		\$0.00	
Medium	Work In Progress				11/18/2008 12:45:52					
Ambriz, Jose		need new fan limit control for a heating unit at the n-bldg to room 233								
Mario Apodaca										
40181	Business	Classroom			11/18/2008		13		\$0.00	
Medium	Work In Progress				11/18/2008 12:48:04					
Ambriz, Jose		need a new gas valve for a heating unit at the bus bldg to room 659								
Mario Apodaca										
40182	Auto Shop	Classroom			11/18/2008		13		\$0.00	
Medium	Work In Progress				11/18/2008 1:01:06 PM					
Moncayo, Fernando		NEED TO REMOVE THE OLD WASHER AT STORED IN THE AUTO SHOP. AT WAS IN THE KITCHEN ASAP.								
Mario Apodaca										
40208	Main Building				11/19/2008		12		\$0.00	
Medium	Work In Progress				11/19/2008 9:17:56 AM					
Appelzoller, Fred		Need gas hook-up for heating units.								
Michael Munoz										
40209	Main Building				11/19/2008		12		\$0.00	
Medium	Work In Progress				11/19/2008 9:18:48 AM					
Castillo, Carlos		Need electrical hook-up for heating units.								
Michael Munoz										
40298	Agricultural	Classroom			11/21/2008		10		\$0.00	
Medium	Work In Progress				11/21/2008 3:13:24 PM					
Ambriz, Jose		need a new pilot ignition control for a heating unit at room 568								
Mario Apodaca										
40299	North Building	Classroom			11/21/2008		10		\$0.00	
Medium	Work In Progress				11/21/2008 3:15:57 PM					
Appelzoller, Fred		need to put new gas conneator for the heating unit 36" need 13 ea.								
Mario Apodaca										
40362					11/30/2008	12/6/2008	1		\$0.00	
Medium	Work In Progress				11/30/2008 12:23:28					
Vallejo, Albert		Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
George ZZ_Gabaldon										

12/1/2008 2:38:44 PM

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Gadsden HS									
40363					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:29				
Vallejo, Albert	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40364					11/30/2008	12/31/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:29				
Vallejo, Albert	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
George ZZ Gabaldon									
40424					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:49				
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
Count: 117 Work Orders			Avg. Age of WO's	72		Total for Gadsden HS	1		\$25.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
35702					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:08 AM					
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
35828	Annex	Classroom			7/10/2008		144		\$0.00
Medium	Work In Progress	Annex/Room 400		7/10/2008 10:15:00 AM					
Estrada, Jesus		Replace carpet in Room 400.							
<u>Maricruz Carrasco</u>									
35829	C-Wing	Classroom			7/10/2008		144		\$0.00
Medium	Work In Progress	Cwing/C-206		7/10/2008 10:16:48 AM					
Estrada, Jesus		Replace carpet in Room C-206.							
<u>Maricruz Carrasco</u>									
35947		Office			7/14/2008		140		\$0.00
High	Work In Progress	Awing/T. Urbina's		7/14/2008 11:29:19 AM					
Jacquez, Ricardo		Manhole located in T. Urbina's office needs to be sealed. The metal lid that is currently on that manhole is too small and is permitting vapors and putrid odors from the crawl space. We need a larger metal lid and to make sure that the access door is sealed in a manner that prohibits those odors into the room. This manhole poses a safety issue in that someone could fall into the access door and the odors can be a health risk to the person who is occupying the room. Please take care of this as soon as possible.							
<u>Maricruz Carrasco</u>									
35955					7/14/2008		140		\$0.00
Medium	Work In Progress			7/14/2008 3:35:17 PM					
Lozoya, Manny		Need fix main entrance doors the punish bar not work properly thank you							
<u>Sebastian Diaz</u>									
36222		Office			7/25/2008		129		\$0.00
Medium	Work In Progress	Awing/GMS Front		7/25/2008 11:40:57 AM					
Lozoya, Manny		Need to set up A57 key lock on new door in Ms. Quinonez's office as soon as possible.							
<u>Maricruz Carrasco</u>									
36627		Office			8/5/2008		118		\$0.00
Medium	Work In Progress	GMS Front		8/5/2008 5:44:35 AM					
Lozoya, Manny		Need A53 door lock on Nancy's door as soon as possible.							
<u>Maricruz Carrasco</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
36628		Office			8/5/2008		118		\$0.00
Medium	Work In Progress	Awing/155/Dr.			8/5/2008 5:47:23 AM				
Lozoya, Manny Door lock in Dr. Garcia's office supposed to be opened by M36 key only. W key can be used to open the door. Please check door lock.									
<u>Maricruz Carrasco</u>									
36630		Parking Lot			8/5/2008		118		\$0.00
Medium	Work In Progress	Parking			8/5/2008 5:56:11 AM				
Ronquillo, Ruben Need two windows in security shed.									
<u>Maricruz Carrasco</u>									
36632		Parking Lot			8/5/2008		118		\$0.00
Medium	Work In Progress	Parking			8/5/2008 5:59:53 AM				
Lozoya, Manny Need metal door installed in Security shed.									
<u>Maricruz Carrasco</u>									
36994	Cafeteria	Cafeteria			8/13/2008		110		\$0.00
Medium	Work In Progress				8/13/2008 8:10:48 AM				
Moncayo, Fernando SNP WAREHOUSE A/C SOUTHSIDE HAS NO WATER. HOT AIR BLOWING. JOHNNY LECHUGS SNP MGR WHSE 882-6927									
<u>Jacqueline Aguilar</u>									
36995	Cafeteria	Cafeteria			8/13/2008		110		\$0.00
Medium	Work In Progress				8/13/2008 8:12:29 AM				
Moncayo, Fernando SNP WAREHOUSE: WALK IN REFRIG. NEEDS TO BE RECHECK TEMP. THIS MORNING WAS AT 42. JOHNNY LECHUGA SNP MGR 882-6927									
<u>Jacqueline Aguilar</u>									
37002	Cafeteria	Cafeteria			8/13/2008		110		\$0.00
Medium	Work In Progress				8/13/2008 9:07:14 AM				
Orozco, Danny SNP WAREHOUSE: FREEZER #2 NEEDS THE DOOR RUBBER SEALS TO BE REPLACED. JOHNNY LECHUGA SNP MGR 882-6927									
<u>Jacqueline Aguilar</u>									
37267		Office			8/21/2008		102		\$0.00
Medium	Work In Progress	Awing/162/Securit			8/20/2008 10:01:58 PM				
Lozoya, Manny "W" key is getting jammed.									
<u>Maricruz Carrasco</u>									
37270		Classroom			8/21/2008		102		\$0.00
Medium	Work In Progress	Awing/159/E.			8/20/2008 10:06:16 PM				
Lozoya, Manny Door does not close and lock.									
<u>Maricruz Carrasco</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
37358		Portables			8/25/2008		98		\$0.00
Medium	Work In Progress	Double Portable		8/25/2008 12:42:33 PM					
Solis, Lorenzo		Double Portable - Need to cover all registers properly.							
Michael Munoz									
37763	C-Wing	Classroom			9/3/2008		89		\$0.00
Medium	Work In Progress	Cwing/C-		9/3/2008 9:29:19 PM					
Lozoya, Manny		Door does not lock. Safety issue.							
Maricruz Carrasco									
37764	C-Wing	Office			9/3/2008		89		\$0.00
Medium	Work In Progress	Cwing/Dr. Montes		9/3/2008 9:30:21 PM					
Lozoya, Manny		Door does not lock.							
Maricruz Carrasco									
37770		Portables			9/4/2008		88		\$0.00
Medium	Work In Progress			9/4/2008 8:13:40 AM					
Sotelo, Enrique		Please provide electrical connection to 2 Bard units.							
Lorenzo Solis									
38313	Cafeteria	Cafeteria			9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 2:40:39 PM					
Orozco, Danny		SNP WAREHOUSE -- NEEDS NEW WATER LINE							
		JOHNNY LECHUGA SNP MGR 882-6927							
Jacqueline Aguilar									
38384	Gym	Gym			9/24/2008		68		\$0.00
Medium	Work In Progress	Gym/Lockerroom		9/23/2008 10:02:16 PM					
Diaz, Sebastian		Lockers need to get fixed. Please check with Dr. Garcia for specific instructions.							
Maricruz Carrasco									
38385					9/24/2008		68		\$0.00
Medium	Work In Progress	All GMS Staff		9/23/2008 10:06:29 PM					
Lozoya, Manny		All staff restrooms to have latch placed on door for privacy reasons.							
Maricruz Carrasco									
38417	C-Wing				9/24/2008		68		\$0.00
Medium	Work In Progress			9/24/2008 3:44:29 PM					
Lozoya, Manny		New Portable - 1st thing tomorrow need to recore like GMS (see Mike if u have any questions).							
Michael Munoz									
38464	C-Wing				9/26/2008		66		\$0.00
Medium	Work In Progress			9/26/2008 12:26:38 PM					
Lozoya, Manny		Mr. Chacon, Band Director needs a gate key for gate by C-Wing.							
Michael Munoz									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
38485					9/26/2008		66		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:32:43 PM					
Lozoya, Manny		Need three WA-83 keys. Need two V-3 keys.							
<u>Maricruz Carrasco</u>									
38486					9/26/2008		66		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:34:17 PM					
Lozoya, Manny		Need two keys made for golf cart.							
<u>Maricruz Carrasco</u>									
38487	C-Wing	Portables			9/26/2008		66		\$0.00
Medium	Work In Progress	C-wing/New		9/26/2008 4:35:35 PM					
Lozoya, Manny		Fix lock to main entrance on new portable-Health Center							
<u>Maricruz Carrasco</u>									
38651	Annex				10/2/2008		60		\$0.00
Medium	Work In Progress			10/2/2008 3:20:00 PM					
Lozoya, Manny		Need fix handi cup door in annex bldg thank you							
<u>Sebastian Diaz</u>									
38731					10/5/2008	10/21/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:23:45 AM					
Villalobos, Margret		Yearly - Gadsden MS October Chiller Insp. - Refer to				10/6- Emailed to Johnson Controls			
		PM schedule details.							
<u>Margret Villalobos</u>									
38791					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:07 AM					
Orozco, Danny		Monthly - Gadsden MS Fire Suppression Insp. - Refer to							
		PM schedule details.							
<u>Margret Villalobos</u>									
39040					10/8/2008		54		\$0.00
Medium	Work In Progress			10/8/2008 3:45:14 PM					
Ronquillo, Ruben		Need 4 window blinds for new portable 30"X60 thank							
		you							
<u>Sebastian Diaz</u>									
39211	C-Wing	Office			10/14/2008		48		\$0.00
Medium	Work In Progress	c-wing/health		10/14/2008 9:40:40 AM					
Gonzalez, Salvador		Cement by rampway entrance to the clinic. Emergency							
		services had a very difficult time accessing the building.							
<u>Maricruz Carrasco</u>									
39212	Gym	Gym			10/14/2008		48		\$0.00
Medium	Work In Progress	Gym/Boys Locker		10/14/2008 9:44:16 AM					
Diaz, Sebastian		Lockers need to be reinforced with plywood. Please see							
		Mr. Mitchell for more information.							
<u>Maricruz Carrasco</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
39213		Office			10/14/2008		48		\$0.00
Medium	Work In Progress	Dr. Garcia's		10/14/2008 9:56:39 AM					
Lozoya, Manny		Install lock on black storage cabinet for Maricruz.							
Maricruz Carrasco									
39603					10/30/2008		32		\$0.00
Medium	Work In Progress	GMS		10/30/2008 12:02:54					
Diaz, Sebastian		Remove light bulbs from specific areas. See Nancy for a list.							
Maricruz Carrasco									
39654		Athletic Field			10/31/2008		31		\$0.00
Medium	Work In Progress			10/31/2008 11:45:31					
Gonzalez, Maritza		Arrange for rental and set up of shade canopy for students							
Alfredo Holguin									
39856					11/5/2008		26		\$0.00
Medium	Work In Progress			11/5/2008 2:20:53 PM					
Lozoya, Manny		Controls contractor (Trane) Needs keys to access building on Monday Nov. 10							
Alfredo Holguin									
39910	C-Wing	Portables			11/6/2008		25		\$0.00
Medium	Work In Progress			11/6/2008 2:25:24 PM					
Holguin, Alfredo		Connect Electrical service to new portable for School Based Health Clinic							
Alfredo Holguin									
40085	C-Wing				11/14/2008		17		\$0.00
Medium	Work In Progress			11/14/2008 9:34:51 AM					
Sotelo, Enrique		PLEASE INSTALL FACE PLATES AND SECURE EXPOSED ELECTRICAL WIRES. PLEASE SEE MIKE MUNOZ.							
Michael Munoz									
40147	C-Wing				11/17/2008		14		\$0.00
Medium	Work In Progress			11/17/2008 2:29:35 PM					
Lozoya, Manny		Nursing Coordinator Offices - Rekey - check with Ms. Cregan on keying							
Alfredo Holguin									
40271	C-Wing				11/20/2008		11		\$0.00
Medium	Work In Progress			11/20/2008 3:49:51 PM					
Diaz, Sebastian		need intall signs in C wing parking lot thank you							
Sebastian Diaz									
40276	C-Wing	Office			11/20/2008		11		\$0.00
Medium	Work In Progress			11/20/2008 5:06:42 PM					
Lozoya, Manny		Re-key the Nursing Department three offices and to be placed on a master key system.				This is requested so custodial services can have before and after hour access to the nursing office area.			
Judy Creegan									

12/1/2008 2:38:44 PM

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Gadsden MS							
40447					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:57				
Diaz, Sebastian	Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.								
George ZZ Gabaldon									
40448					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:57				
Diaz, Sebastian	Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40449					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:57				
Diaz, Sebastian	Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
Count: 45 Work Orders		Avg. Age of WO's		73	Total for Gadsden MS			0	\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		La Union - JTP Alvarez Farms							
40167		Classroom			11/18/2008		13		\$0.00
Medium	Work In Progress	LA UNION JTP			11/18/2008 8:56:05 AM				
Ambriz, Jose	AS PER IRNA LAZARIN-OVER THE JTP, THEY HAVE NO HEAT.								
Mary Garcia									
Count: 1 Work Orders		Avg. Age of WO's	13	Total for La Union - JTP Alvarez Farms				0	\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		La Union ES								
35705					7/6/2008	8/6/2008	148		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:09 AM						
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
35791		Cafeteria			7/9/2008		145		\$0.00	
Medium	Work In Progress			7/9/2008 1:48:49 PM						
Moncayo, Fernando		OVENS NEED TO BE CHECKED. SOMETIMES THEY WILL HEAT UP AND THEN STOP HEATING ALL OF A SUDDEN.								
		LINDA YANAGA SNP MGR 589-2040								
<u>Jacqueline Aguilar</u>										
35792		Cafeteria			7/9/2008		145		\$0.00	
Medium	Work In Progress			7/9/2008 1:49:55 PM						
Moncayo, Fernando		PASS THRU REFRIG. IS FREEZING UP.								
		LINDA YANAGA LU SNP MGR 589-2040								
<u>Jacqueline Aguilar</u>										
35921					7/13/2008	7/29/2008	141		\$0.00	
Medium	Work In Progress			7/13/2008 12:18:11 AM						
Gonzalez, Salvador		Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
36544					8/3/2008	8/11/2008	120		\$0.00	
Medium	Work In Progress			8/3/2008 12:20:27 AM						
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
36590					8/4/2008		119		\$0.00	
Medium	Work In Progress			8/4/2008 10:36:40 AM						
Castillo, Carlos		Run elect. to morgom maint storage - would be nice to use fan								
<u>Patricio Aguilar</u>										
36996		Cafeteria			8/13/2008		110		\$0.00	
Medium	Work In Progress			8/13/2008 8:23:00 AM						
Moncayo, Fernando		REACH THRU REFRIG. DOES NOT COOL TEMP IS AT 50								
		LINDA YANAGA SNP MGR 589-2040								
<u>Jacqueline Aguilar</u>										
37040	Annex Building				8/13/2008		110		\$0.00	
Medium	Work In Progress			8/13/2008 4:17:56 PM						
Castillo, Carlos		Install electrical for kiln in room # 203								
Alfredo Holguin										
12/1/2008 2:38:45 PM										

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
37041	Annex Building				8/13/2008		110		\$0.00
Medium	Work In Progress			8/13/2008 4:18:39 PM					
Ambriz, Jose	Install venting for kiln in room # 203								
Alfredo Holguin									
37120					8/15/2008		108		\$0.00
Medium	Work In Progress			8/15/2008 3:17:51 PM					
Carrasco, Danny	Need 3 gfi elect out lets #202								
Patricio Aguilar									
37960					9/9/2008		83		\$0.00
Medium	Work In Progress			9/9/2008 2:37:27 PM					
Castillo, Carlos	NEED TO HAVE LIGHT POLES, AND LIGHTS ON WEST PARKING LOT CHECKED THEY ARE OFF, ONLY A FEW LIGHTS COME ON, POSSIBLE LIGHTING DAMAGE.								
Arturo Nunez									
38034					9/11/2008		81		\$0.00
Medium	Work In Progress			9/11/2008 3:14:33 PM					
Villalobos, David	pat aguilar need rubber bushing for water faucet - thank you								
Patricio Aguilar									
38036					9/11/2008		81		\$0.00
Medium	Work In Progress			9/11/2008 3:22:31 PM					
Solis, Lorenzo	pat aguilar wants her refrigerated ac replaced - that it is to loud								
Patricio Aguilar									
38186	Restroom (Girls)				9/17/2008		75		\$0.00
Medium	Work In Progress			9/17/2008 3:28:46 PM					
Lara, Ralph	The door knob for female rest room will not lock - thank you								
Patricio Aguilar									
38793					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:08 AM					
Orozco, Danny	Monthly - La Union ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
39154					10/12/2008	10/28/2008	50		\$0.00
Medium	Work In Progress			10/12/2008 12:20:59					
Aguilar, Patricio	Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
40213					11/19/2008		12		\$0.00
Medium	Work In Progress	PSFA Site Vist			11/19/2008 9:47:07 AM				
Aguilar, Patricio		Heating Unit on new bldg has a bee hive, open w/caution and remove. Also, please ck filter to see if it needs to be replaced.							
Michael Munoz									
40214					11/19/2008		12		\$0.00
Medium	Work In Progress	PSFA Site Vist			11/19/2008 9:49:02 AM				
Aguilar, Patricio		Rooftop - where rain accumulates dirt needs to be swept off (by drains), and when it rains water needs to be swept off immediately to prevent leaking into classrooms.							
Michael Munoz									
40428					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:50				
Aguilar, Patricio		Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40429					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:51				
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40430					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:51				
Aguilar, Patricio		Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.							
George ZZ Gabaldon									
Count: 21 Work Orders		Avg. Age of WO's	81			Total for La Union ES	0		\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
35583					7/6/2008	7/27/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:31 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
35703					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:08 AM					
Villalobos, David	Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36116					7/22/2008		132		\$0.00
Medium	Work In Progress			7/22/2008 12:27:51 PM					
Lozoya, Manny	Manny, needing door in room 212 repaired								
Grace Alvarado									
36408					7/31/2008		123		\$0.00
Medium	Work In Progress			7/31/2008 2:26:46 PM					
Ronquillo, Ruben	Need to replace 10 more blinds.								
Rudy Arreola									
36686					8/6/2008		117		\$0.00
Medium	Work In Progress			8/6/2008 3:03:22 PM					
Lozoya, Manny	Rm 111 needs to have lock installed in her filing cabinet.								
Rudy Arreola									
36898					8/11/2008		112		\$0.00
Medium	Work In Progress			8/11/2008 3:03:50 PM					
Lozoya, Manny	We need a lock installed in a filing cabinet in RM 201								
Rudy Arreola									
37058		Portables			8/14/2008		109		\$0.00
Medium	Work In Progress			8/14/2008 10:22:44 AM					
Arreola, Rudy	Complete skirting installation on double portable								
Alfredo Holguin									
37174		Classroom			8/19/2008		104		\$0.00
Medium	Work In Progress			8/19/2008 7:48:48 AM					
Sotelo, Enrique	Rm 111 the emergency light is out not working at all.								
Rudy Arreola									
37711		Athletic Field			9/2/2008		90		\$0.00
Medium	Work In Progress			9/2/2008 3:15:39 PM					
Ontiveros, Guadalupe	Water leak from one of the irrigation line its coming from under the cement. by the basketball courts area.								
Rudy Arreola									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
38220		Classroom			9/18/2008		74		\$0.00
Medium	Work In Progress			9/18/2008 2:36:13 PM					
Ronquillo, Ruben	Windows in RM 205 are hard to open and wont stay up.TOTAL of 3								
Rudy Arreola									
38221		Classroom			9/18/2008		74		\$0.00
Medium	Work In Progress			9/18/2008 2:37:10 PM					
Ronquillo, Ruben	Windows in RM 201 is very hard to open TOTAL of 2.								
Rudy Arreola									
38222					9/18/2008		74		\$0.00
Medium	Work In Progress			9/18/2008 2:37:50 PM					
Ronquillo, Ruben	Window in RM 204 wont stay up TOTAL of 1.								
Rudy Arreola									
38782					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:04 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
38794					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:08 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38964					10/6/2008		56		\$0.00
Medium	Work In Progress			10/6/2008 1:40:46 PM					
Carrasco, Danny	Need pressure washer and hose to wash off wall of the east side of main bldg.								
Rudy Arreola									
38973					10/6/2008		56		\$0.00
Medium	Work In Progress			10/6/2008 2:55:14 PM					
Sotelo, Enrique	We need more outlets in coaches office.								
Rudy Arreola									
39414					10/23/2008		39		\$0.00
Medium	Work In Progress			10/23/2008 12:22:29					
Sotelo, Enrique	Asp PM 38922 Emerg. Light not workin in boys rr and entrance. (ck w/Rudy for location)								
Rudy Arreola									
39613					10/30/2008		32		\$0.00
Medium	Work In Progress			10/30/2008 1:29:28 PM					
Lozoya, Manny	Need new lock for popcorn machine.								
Rudy Arreola									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
39614					10/30/2008		32		\$0.00
Medium	Work In Progress			10/30/2008 1:30:36 PM					
Lozoya, Manny	Door handle is broken in RM 212								
Rudy Arreola									
39615					10/30/2008		32		\$0.00
Medium	Work In Progress			10/30/2008 1:32:10 PM					
Lozoya, Manny	Library door is getting stuck.								
Rudy Arreola									
39616					10/30/2008		32		\$0.00
Medium	Work In Progress			10/30/2008 1:34:22 PM					
Lozoya, Manny	Door handle is getting stuck in womens rr.								
Rudy Arreola									
39762					11/3/2008		28		\$0.00
Medium	Work In Progress			11/3/2008 7:52:22 AM					
Ronquillo, Ruben	Need 6 signs that say NO PARKING 7.AM. TO 4P.M. MOM THRU FRIDAY								
Rudy Arreola									
39955					11/7/2008		24		\$0.00
Medium	Work In Progress			11/7/2008 4:11:09 PM					
Ronquillo, Ruben	NEED NEW STANDS FOR A/C'S								
Ruben Ronquillo									
40091					11/14/2008		17		\$0.00
Medium	Work In Progress			11/14/2008 1:23:35 PM					
Arreola, Rudy	Need a plate for bottom of poles to relocate handicapp spaces total of 4.				11/21/08				
Rudy Arreola					Asp Sal route to Rudy, plates will not hold sign. Asphalt will break and is weak. Rudy needs to break asphalt w/Hilti make hole w/post hole dig and pour concrete. Thanks Mike				
40092					11/14/2008		17		\$0.00
Medium	Work In Progress			11/14/2008 1:24:17 PM					
Munoz, Michael	Need walking gate for new cross walk on north side exit.								
Rudy Arreola									
40216	Main Building	Restroom (Boys)			11/19/2008		12		\$0.00
Medium	Work In Progress			11/19/2008 11:20:53					
Arreola, Rudy	Boys RR Eastside by cafe -Check and reappear Exhaust Fan, smells like urine. (When complete, please contact M.Munoz for inspection)								
Michael Munoz									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Loma Linda ES							
40438					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:54				
Arreola, Rudy	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40439					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:54				
Arreola, Rudy	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40440					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:54				
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
George ZZ Gabaldon									
Count: 29 Work Orders		Avg. Age of WO's		62	Total for Loma Linda ES			0	\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
35549					7/6/2008	7/12/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:20 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35567					7/6/2008	7/14/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:26 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35626					7/6/2008	7/14/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:44 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35636					7/6/2008	7/14/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:47 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35661					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:55 AM					
Ramirez, Joe	Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35684					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:02 AM					
Ramirez, Joe	Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35706					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:09 AM					
Villalobos, David	Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
36109					7/22/2008		132		\$0.00
Medium	Work In Progress			7/22/2008 10:11:48 AM					
Lozoya, Manny	on (work room) needs a cylinder with a key they have school files need to be lock all the time as per montano principal asap. thank you. luis								
<u>Luis Saucedo</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
36147	Main Building	Office			7/23/2008		131		\$0.00
Medium	Work In Progress	Main office area		7/23/2008 12:29:38 PM					
Lozoya, Manny Main office need's (4) engraved plaque's for front office door. Name and Title (Jacob Montano, Principal), (Sandra Mora, Secretary), (Dora Lerma, Data-Entry Clerk), (Maribel Villela, Receptionist-Clerk) for Manny Lozoya.									
<u>Sandra Mora</u>									
36227		Portables			7/25/2008		129		\$0.00
Medium	Work In Progress			7/25/2008 2:11:53 PM					
Lozoya, Manny Ms. Flores room # 801 has filing cabinet that doesn't have a key, need's to be re-key.									
<u>Sandra Mora</u>									
36245					7/28/2008		126		\$0.00
Medium	Work In Progress			7/28/2008 7:44:32 AM					
Ramirez, Joe please need to check water pump we have flood on barracks on 7/29/08 between the blds. thank you.									
<u>Luis Saucedo</u>									
36256	2003 Classroom	Classroom			7/28/2008		126		\$0.00
Medium	Work In Progress	Portable room #		7/28/2008 8:30:02 AM					
Lozoya, Manny Ms. Jimenez, portable room # 506 she has a storage cabinet needs to be re-key.									
<u>Sandra Mora</u>									
36259	2003 Classroom	Classroom			7/28/2008		126		\$0.00
Medium	Work In Progress	Kinder hallway,		7/28/2008 8:58:17 AM					
Lozoya, Manny Need a master for that room # 405 for our inventory, and key # 305.									
<u>Sandra Mora</u>									
36507					8/3/2008	8/9/2008	120		\$0.00
Medium	Work In Progress			8/3/2008 12:20:15 AM					
Ramirez, Joe Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.									
<u>Margret Villalobos</u>									
36539					8/3/2008	8/11/2008	120		\$0.00
Medium	Work In Progress			8/3/2008 12:20:26 AM					
Ramirez, Joe Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>									
36549					8/3/2008	8/11/2008	120		\$0.00
Medium	Work In Progress			8/3/2008 12:20:29 AM					
Ramirez, Joe Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
Margret Villalobos									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
36577					8/4/2008		119		\$0.00
Medium	Work In Progress			8/4/2008 5:44:47 AM					
Ramirez, Joe	please need to chek the roof this mornig we got a few big leak in the cafeteeria from the rain.thank you luis.								
<u>Luis Saucedo</u>									
36885	Main Building	Office			8/11/2008		112		\$0.00
Medium	Work In Progress	Office area		8/11/2008 11:09:39 AM					
Lozoya, Manny	(1) engraved plaque for front office door. Name and Title (Norma Sierra, Assistant Principal) for Manny Lozoya								
<u>Sandra Mora</u>									
37428					8/27/2008		96		\$0.00
Medium	Work In Progress			8/27/2008 5:27:42 AM					
Ramirez, Joe	this morning we have a few leaks in the cafeteria by south side corner. thank you luis								
<u>Luis Saucedo</u>									
37490					8/28/2008		95		\$0.00
Medium	Work In Progress			8/28/2008 3:06:30 PM					
Ramirez, Joe	continue the condensation line to a proper area for drainage.								
<u>Michael Munoz</u>									
37617					8/31/2008		92		\$0.00
Medium	Work In Progress			8/31/2008 12:25:35 AM					
Ramirez, Joe	Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37618					8/31/2008		92		\$0.00
Medium	Work In Progress			8/31/2008 12:25:35 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual MCD - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37619					8/31/2008		92		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37620					8/31/2008		92		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual UCD - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
37621					8/31/2008		92		\$0.00
Medium	Work In Progress			8/31/2008 12:25:36 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual UCS2 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37622					8/31/2008		92		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37623					8/31/2008	9/8/2008	92		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37624					8/31/2008		92		\$0.00
Medium	Work In Progress			8/31/2008 12:25:37 AM					
Ramirez, Joe	Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37625					8/31/2008		92		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual EVS - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37626					8/31/2008	9/6/2008	92		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37627					8/31/2008	9/8/2008	92		\$0.00
Medium	Work In Progress			8/31/2008 12:25:38 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38209					9/18/2008		74		\$0.00
Medium	Work In Progress			9/18/2008 9:17:37 AM					
Sotelo, Enrique	pole lights on the eastside of campus not working.								
<u>Joe Ramirez</u>									
38210					9/18/2008		74		\$0.00
Medium	Work In Progress			9/18/2008 9:18:18 AM					
Sotelo, Enrique	marquee lights not working.								
<u>Joe Ramirez</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
38537					9/30/2008		62		\$0.00
Medium	Work In Progress			9/30/2008 12:26:03 AM					
Ramirez, Joe	Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38589					10/1/2008		61		\$0.00
Medium	Work In Progress			10/1/2008 9:13:56 AM					
Sotelo, Enrique	front porch entrance lights not working need to replace ballasts.								
<u>Joe Ramirez</u>									
38663	Pump House				10/2/2008		60		\$0.00
Medium	Work In Progress			10/2/2008 3:36:10 PM					
Ramirez, Joe	Remove all materials equipment and other supplies stored in this area. This is not a storeroom.		e- mailed 11/5/08 - Please resubmit the work orders to clean out the pump rooms at La Mesa, San Miguel, and Mesquite with notes on them to notify me when they are complete.						
<u>Alfredo Holguin</u>									
38795					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:08 AM					
Orozco, Danny	Monthly - Mesquite ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38881					10/5/2008	10/11/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:40 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38882					10/5/2008	10/13/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:41 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38883					10/5/2008	10/13/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:41 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38884					10/5/2008	10/13/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:41 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
38885					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:42 AM					
Ramirez, Joe	Yearly - Mesquite ES I-4 Fan Coil Unit Yearly - Refer to PM schedule details.								
Margret Villalobos									
38886					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:42 AM					
Ramirez, Joe	Yearly - Mesquite ES H-6 Rooftop Furnance Yearly - Refer to PM schedule details.								
Margret Villalobos									
38887					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:42 AM					
Ramirez, Joe	Yearly - Mesquite ES R-9 Rad Hot Water 2 years - Refer to PM schedule details.								
Margret Villalobos									
38888					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:43 AM					
Ramirez, Joe	Yearly - Mesquite ES U-2 Unit Heater Gas Yearly - Refer to PM schedule details.								
Margret Villalobos									
38889					10/5/2008	10/21/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:43 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.								
Margret Villalobos									
39093					10/10/2008		52		\$0.00
Medium	Work In Progress			10/10/2008 8:24:02 AM					
Carbajal, Jimmy	The scrubber machine # 1253524 & g.i.s.d. tag # 99-00031 is not working is too old, if possible to exchange for new scrubber machine.								
	Thank you.								
	Luis								
Luis Saucedo									
39516					10/27/2008		35		\$0.00
Medium	Work In Progress			10/27/2008 3:08:58 PM					
Ramirez, Joe	CLEAN AND SERVICE ALL HEATERS AS PER OUR CONVERSATION. POSSIBLE SAFETY AND FIRE HAZARD. WILL BE INSPECTED.		10/27 - AS PER MIKE, ONCE W.O. 39516 FOR MQ IS COMPLETED, PLEASE GIVE TO MIKE FOR HIS REVIEW. THANKS MG						
Michael Munoz									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
39517					10/27/2008		35		\$0.00
Medium	Work In Progress			10/27/2008 3:09:56 PM					
Ramirez, Joe	WEED EAT AROUND CAMPUS (AROUND PICNIC TABLES, TREES ETC.)								
Michael Munoz									
39518					10/27/2008		35		\$0.00
Medium	Work In Progress			10/27/2008 3:10:45 PM					
Ramirez, Joe	REPAIR HOLE IN SHEET ROCK AND INSTALL DOOR STOP BY LARRY SEDILLO'S ROOM.								
Michael Munoz									
39519					10/27/2008		35		\$0.00
Medium	Work In Progress			10/27/2008 3:11:39 PM					
Ramirez, Joe	GRASS IS GROWING IN DRAIN GRID BY BUS TURN AROUND.								
Michael Munoz									
39692					11/2/2008	11/8/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:35 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
39724					11/2/2008	11/10/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:47 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39734					11/2/2008	11/10/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:50 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39854	Pump House				11/5/2008		26		\$0.00
Medium	Work In Progress			11/5/2008 2:17:45 PM					
Ramirez, Joe	Remove roof turbin/ventilator and patch roof.								
Alfredo Holguin									
39993					11/11/2008		6	2	\$50.00
Medium	Work In Progress			11/11/2008 1:16:38 PM	11/17/2008				
Carbajal, Jimmy	please the handle from the vaccum is broken. thank you.		REPAIRED AND DID P.M.						
Luis Saucedo									
40136					11/17/2008		14		\$0.00
Medium	Work In Progress			11/17/2008 10:56:13					
Sotelo, Enrique	need special ballast replaced in the bathroom between rms 404,405.								
Joe Ramirez									
12/1/2008 2:38:45 PM									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
40256					11/20/2008		11		\$0.00
Medium	Work In Progress				11/20/2008 9:34:58 AM				
Lozoya, Manny	file cabinet in rm 405 needs a new lock installed the other was damaged.								
Joe Ramirez									
40257					11/20/2008		11		\$0.00
Medium	Work In Progress	Playground			11/20/2008 9:36:12 AM				
Ontiveros, Guadalupe	need 3 loads of sand for playground area.								
Joe Ramirez									
40421					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:48				
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40422					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:48				
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40423					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:49				
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
George ZZ Gabaldon									
Count: 62 Work Orders			Avg. Age of WO's	78		Total for Mesquite ES	2		\$50.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
36463		Office			8/1/2008		122		\$0.00
Medium	Work In Progress	room 400		8/1/2008 11:44:39 AM					
Lozoya, Manny		Hello Manny, The alarm box key was broken off, please replace.							
<u>Priscilla Martinez</u>									
37136		Office			8/18/2008		105		\$0.00
Medium	Work In Progress	video		8/18/2008 10:18:19 AM					
Lozoya, Manny		could not locate a key							
Priscilla Martinez		Need a black box located in our office to be opened, could not locate the correct key in our vault							
37221		Classroom			8/20/2008		103		\$0.00
Medium	Work In Progress	various		8/20/2008 9:15:00 AM					
Lozoya, Manny		Send Lozoya to make various keys for various classrooms, desks, cabinets, filing cabinets, storage closets,							
Priscilla Martinez		please visit the front office for this list of keys that are needed, thanks Priscilla							
<u>Priscilla Martinez</u>									
37675					9/2/2008		90		\$0.00
Medium	Work In Progress			9/2/2008 9:01:54 AM					
Munoz, Michael		need a 4ft gate door by marquee by 12ft by 12ft slab (facing north) spoke to jaun v. on this							
<u>Danny Vega</u>									
37765		Classroom			9/4/2008		88		\$0.00
Medium	Work In Progress	room 401		9/4/2008 7:52:35 AM					
Vega, Danny		Our nurse needs to hang curtain railing in her office for a special need student.							
Priscilla Martinez		Thank you very much							
<u>Priscilla Martinez</u>									
37766		Office			9/4/2008		88		\$0.00
Medium	Work In Progress	room 400		9/4/2008 7:54:21 AM					
Vega, Danny		Hang a bulletin board in the front office.							
Priscilla Martinez		Thank you,							
38084		Classroom			9/15/2008		77		\$0.00
Medium	Work In Progress			9/15/2008 1:35:12 PM					
Lozoya, Manny		need a key made for Larry Roybal (Deputy Dona Ana County Sheriff) for the gates at North Valley Elementary							
<u>Priscilla Martinez</u>									
38743					10/5/2008		57		\$0.00
Medium	Work In Progress			10/5/2008 12:23:50 AM					
Holguin, Alfredo		Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos		10/6/08 - Emailed to Ricky Borrego							

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
38797					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:09 AM					
Orozco, Danny	Monthly - North Valley ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
39280					10/20/2008		42		\$0.00
Medium	Work In Progress			10/20/2008 9:11:35 AM					
Lozoya, Manny	need new pad lock for bus exit gate/had to cut old lock this morning-key didnt turn core								
Danny Vega									
39383					10/22/2008		40		\$0.00
Medium	Work In Progress			10/22/2008 1:41:03 PM					
Lozoya, Manny	p.e coaches office door will not open -core will not turn with key-please ck out asap								
Danny Vega									
39456		Classroom			10/24/2008		38		\$0.00
Medium	Work In Progress	room 210		10/24/2008 12:13:11					
Lozoya, Manny	black file cabinet w/blue sticker does not lock.								
Priscilla Martinez									
39804					11/4/2008		27		\$0.00
Medium	Work In Progress			11/4/2008 9:20:53 AM					
Lozoya, Manny	need key made for rm 304 art rm/cabinet key broke in core-need to lock-up supplys asap								
Danny Vega									
40252		Choral			11/20/2008		11		\$0.00
Medium	Work In Progress			11/20/2008 9:11:42 AM					
Sotelo, Enrique	lights switch broke. can't turn off lights in the cafeteria.								
Javier Parra									
40294					11/21/2008		10		\$0.00
Medium	Work In Progress			11/21/2008 12:32:18					
Carbajal, Jimmy	vacum wheels broke,doesn't walk straight								
Javier Parra									
40295					11/21/2008		10		\$0.00
Medium	Work In Progress			11/21/2008 12:33:23					
Carbajal, Jimmy	vacum handle does not stay in place								
Javier Parra									
40338					11/25/2008		6		\$0.00
Medium	Work In Progress			11/25/2008 12:13:51					
Carbajal, Jimmy	flat dolly wheel								
Javier Parra									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: North Valley ES									
40339					11/25/2008		6		\$0.00
Medium	Work In Progress			11/25/2008 12:15:14					
Carbajal, Jimmy	dolly wheels not rolling strait								
Javier Parra									
40377					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:33					
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.								
George ZZ Gabaldon									
40379					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:34					
Vega, Danny	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40381					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:35					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
40386					11/30/2008		1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:36					
Vega, Danny	Monthly - North Valley ES A16 (Fan Exhst)(S.Ann.) - Refer to PM schedule details.								
George ZZ Gabaldon									
40387					11/30/2008	12/21/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:37					
Vega, Danny	Monthly - North Valley ES H11(E.Heat)(S.Annual) - Refer to PM schedule details.								
George ZZ Gabaldon									
Count: 23 Work Orders			Avg. Age of WO's 43			Total for North Valley ES	0		\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Northern On-Track Pre-K (LM)								
35704					7/6/2008	8/6/2008	148		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:09 AM						
Villalobos, David		Yearly - Northern Pre-K (LM) Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
36220	Main Building				7/25/2008		129		\$0.00	
Medium	Work In Progress			7/25/2008 11:25:22 AM						
Vega, Danny		Hedge in front of Main Entrance - needs to be trimmed also a sprout in the Planter on the west side of the entrance needs to be removed and the hedge growing against the building directly next to it also.								
Alfredo Holguin										
36680					8/6/2008		117		\$0.00	
Medium	Work In Progress	Playground		8/6/2008 11:23:04 AM						
Vega, Danny		New playground structure is complete. We need plastice lining and Round-up applied so that area can be filled in with sand. We also need a sand box moved, enlarged and filled with sand.				8/11 - Asp Lupe route to D. Vega				
Gilbert Trujillo										
36884	Cafeteria	Custodial			8/11/2008		112		\$0.00	
Medium	Work In Progress	room 16		8/11/2008 10:49:59 AM						
Vega, Danny		roof is leaking, ceiling fell off.								
Gilbert Trujillo										
37300					8/21/2008		102		\$0.00	
Medium	Work In Progress			8/21/2008 3:03:06 PM						
Vega, Danny		8-18-08 .5-ck wk ods in office nve 2.5-ck and clean a/c unit distributors la mesa pre-k 5-cut weeds and spray round-up at la mesa				8/18-8				
Danny Vega										
37774		Athletic Field			9/4/2008		88		\$0.00	
Medium	Work In Progress			9/4/2008 8:52:16 AM						
Lozoya, Manny		send us the lock and chain to secure the west gate								
Gilbert Trujillo										
37775	Main Building	Restroom (Girls)			9/4/2008		88		\$0.00	
Medium	Work In Progress	classroom 114		9/4/2008 9:33:49 AM						
Lozoya, Manny		Bathroom door in the baby room won't close.								
Concepcion Montalvo										
39535	Pump House	Pump House			10/28/2008		34		\$0.00	
Medium	Work In Progress			10/28/2008 8:37:18 AM						
Jacquez, Ricardo		need to replace air compressor on irrigation well thanks								
Ricardo Jacquez										

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
39602	Pump House	Pump House			10/30/2008		32		\$0.00
Medium	Work In Progress				10/30/2008 9:07:18 AM				
Lozoya, Manny		please change lock back to original lock on irrigation well thanks							
Ricardo Jacquez									
39769		Hallway/Corridor			11/3/2008		28		\$0.00
Medium	Work In Progress				11/3/2008 9:40:06 AM				
Sotelo, Enrique		hallway lights need bulbs replaced.							
Gilbert Trujillo									
39905		Restroom (Boys)			11/6/2008		25		\$0.00
Medium	Work In Progress				11/6/2008 10:29:38 AM				
Lozoya, Manny		alma de valle restroom door need to be worked on.							
Gilbert Trujillo									
39966					11/9/2008	11/25/2008	22		\$0.00
Medium	Work In Progress				11/9/2008 12:28:37 AM				
Vega, Danny		Monthly - Northern On-Track Pre-K Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
40019	Main Building	Classroom			11/12/2008		19		\$0.00
Medium	Work In Progress				11/12/2008 8:35:22 AM				
Sotelo, Enrique		classroom plug switch is shorted out.room 112							
Gilbert Trujillo									
40148		Athletic Field			11/17/2008		14		\$0.00
Medium	Work In Progress				11/17/2008 2:32:41 PM				
Vega, Danny		Re-attach wind screen coming lose from fence on north side.							
Alfredo Holguin									
40149		Athletic Field			11/17/2008		14		\$0.00
Medium	Work In Progress				11/17/2008 2:34:09 PM				
Ontiveros, Guadalupe		Remove concret rock from sand box							
Alfredo Holguin									
40222	Main Building	Classroom			11/19/2008		12		\$0.00
Medium	Work In Progress	114			11/19/2008 2:24:19 PM				
Lozoya, Manny		Urgent - Toddlers are opening doors and going out of babyroom. Manny is aware of this problem. Please, solve this problem asap. Thank You, Maria Gonzales.							
Concepcion Montalvo									
40378					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:34				
Vega, Danny		Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.							
George ZZ_Gabaldon									

12/1/2008 2:38:45 PM

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Northern On-Track Pre-K (LM)									
40380					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:34					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40382					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:35					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40383					11/30/2008	12/21/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:35					
Vega, Danny	Monthly - Northern Prek C12(Chem.Feeder)(S.Annual) - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40384					11/30/2008		1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:36					
Vega, Danny	Monthly - Northern Prek A16(Fan Exhst)(S. Annual) - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
40385					11/30/2008	12/21/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:36					
Vega, Danny	Monthly - Northern Prek H11(E.Heat)(S.Annual) - Refer to PM schedule details.								
<u>George ZZ Gabaldon</u>									
Count: 22 Work Orders			Avg. Age of WO's 45		Total for Northern On-Track Pre-K (LM)		0		\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
35707					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:10 AM					
Villalobos, David	Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
35864					7/11/2008		143		\$0.00
Medium	Work In Progress			7/11/2008 8:59:27 AM					
Jacquez, Ricardo	7-9-08	7/9-2							
	ppd-1.5 ck wwtp								
	cms-6 wo# 33549								
	ppd-.5 daily o&m on wwtp								
<u>Ricardo Jacquez</u>									
36213	Maintenance				7/25/2008		129		\$0.00
Medium	Work In Progress			7/25/2008 10:15:21 AM					
Sotelo, Enrique	please install electrical outlet to cooling duct fan and pilot switch.								
	Thxs								
<u>Michael Munoz</u>									
36291					7/28/2008		126		\$0.00
Medium	Work In Progress			7/28/2008 3:26:53 PM					
Ronquillo, Ruben	Purchase a new water tank								
<u>Alfredo Holguin</u>									
36355	Food Services	Parking Lot			7/30/2008		124		\$0.00
Medium	Work In Progress	SNP		7/30/2008 12:01:33 PM					
Ontiveros, Guadalupe	AS PER MR. GIOVAS-IF NEAR THE WAREHOUSE GOING FROM THE SHADED AREA TO THE STAIR WAY INTO THE WAREHOUSE IF THEY CAN LEVEL OUT THE PATH WAY. (PLEASE SEE JOHNNY L. IF NEED DIRECTION.)								
<u>Mary Garcia</u>									
36759	Maintenance				8/7/2008		116		\$0.00
Medium	Work In Progress			8/7/2008 9:53:28 AM					
Munoz, Michael	Need price quote to build an architect table for Tech's Office.								

Michael Munoz

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
37066					8/14/2008		109		\$0.00
Medium	Work In Progress			8/14/2008 11:15:18 AM					
Ronquillo, Ruben	Purchase new individual signs to go above doors outside Bldg. indicating as follows: -Purchasing Warehouse -Instructional Materials -Physical Plant Dept./ Construction Dept./Custodial Dept. -Custodial Shipping/Receiving Also 1 sign for Main Entrance by Nurse Complex indicating as follows: Construction Dept. Instructional Materials Student Nutrition Warehouse Student Records Transportation Physical Plant Department Custodial Dept. Maintenance Dept. Motor Pool Purchasing Warehouse SEE ALFREDO IF ANY QUESTIONS.								
<u>Alfredo Holguin</u>									
37074	Food Services				8/14/2008		109		\$0.00
Medium	Work In Progress			8/14/2008 2:23:06 PM					
Lara, Ralph	As per Mike, remove doubled doors and replace with a rolling door. Please see Mike if you have any questions.								
<u>Michael Munoz</u>									
37767					9/4/2008		88		\$0.00
Medium	Work In Progress			9/4/2008 8:02:44 AM					
Lozoya, Manny	need to replace door lock on water department office does not lock thanks								
<u>Ricardo Jacquez</u>									
37791	Purchasing				9/4/2008		88		\$0.00
Medium	Work In Progress			9/4/2008 2:35:30 PM					
Sotelo, Enrique	I would like to have a light switch in my office to control the lights. Currently the switch is in the hall and the one switch controls my office and hallway.								
<u>Vicky Lopez</u>									
37882	Food Services				9/8/2008		84		\$0.00
Medium	Work In Progress			9/8/2008 8:10:34 AM					
Ontiveros, Guadalupe	Need to add Crusher fines to dock area.								
Alfredo Holguin									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
37888		Parking Lot			9/8/2008		84		\$0.00
Medium	Work In Progress			9/8/2008 8:19:17 AM					
Ronquillo, Ruben		Desigate Handicap Parking for Building and Install signage			9/29 - asp Mike route to Ruben				
Alfredo Holguin									
37889		Parking Lot			9/8/2008		84		\$0.00
Medium	Work In Progress			9/8/2008 8:23:48 AM					
Ronquillo, Ruben		Purchase and Install Parking Signs for the entire PPD Complex. (Vistiors Parking, Employee Parking, No Parking- Loading Zone)							
Alfredo Holguin									
37944					9/9/2008		83		\$0.00
Medium	Work In Progress			9/9/2008 12:13:23 PM					
Gonzalez, Salvador		PLEASE MAKE SCRAPERS/DRAGERS. PLEASE SEE MIKE.							
Michael Munoz									
38130		Parking Lot			9/16/2008		76		\$0.00
Medium	Work In Progress			9/16/2008 11:39:13 AM					
Ronquillo, Ruben		Purchase Sign for Physical Plant Parking Plan as per the layout provided. Signs need to be larger than the standard size.							
Alfredo Holguin									
38639	Maintenance	Office			10/2/2008		60		\$0.00
Medium	Work In Progress			10/2/2008 9:08:26 AM					
Ronquillo, Ruben		SERVICE FOR ASBESTOS ABATEMENT AND CUT OPENING TO BE DONE IN BETWEEN THE PLUMBING AND THE MAINT. WHS.							
Ruben Ronquillo									
39757					11/3/2008		28		\$0.00
Medium	Work In Progress			11/3/2008 12:24:08 AM					
Villalobos, Margret		Monthly - PPD - Quarterly Meeting - Refer to PM schedule details.							
Margret Villalobos									
39941					11/7/2008		24		\$0.00
Medium	Work In Progress			11/7/2008 1:06:01 PM					
Ontiveros, Guadalupe		Gooseneck Trailers 2 ea. - Replace damaged floor boards							
Alfredo Holguin									
39986		Pump House			11/11/2008		20		\$0.00
Medium	Work In Progress			11/11/2008 9:16:37 AM					
Jacquez, Ricardo		need to calibrate flow meters at GMS,GHS,CMS & SRE thanks							
Ricardo Jacquez									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Physical Plant Complex							
40446					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:56				
Diaz, Sebastian	Monthly - Physical Plant FE Inspection - Refer to PM schedule details.								
George ZZ Gabaldon									
Count: 20 Work Orders		Avg. Age of WO's	86	Total for Physical Plant Complex				0	\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Riverside ES

35708					7/6/2008	8/6/2008	148		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress			7/6/2008 12:20:10 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

35753	New Wing 1/02				7/8/2008		146		\$0.00
-------	---------------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress			7/8/2008 10:29:47 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben Need window repaired room 137 due to break in 20x21
Add two more broken windows custodian found windows
in corrdor by cafe.

Carlos Hernandez

36586		Cafeteria			8/4/2008		119		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress			8/4/2008 9:53:07 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Moncayo, Fernando Oven with Grill is not working/heating up at all.

Emilia Carrillo - SNP Manager 589-2550

Alma Terrell

36587		Cafeteria			8/4/2008		119		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress			8/4/2008 9:54:27 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Moncayo, Fernando Walk-In Refrigerator is leaking alot of water

Emilia Carrillo - SNP Manager 589-2550

Alma Terrell

36669					8/6/2008		117		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress			8/6/2008 8:39:54 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Carrasco, Danny need fuses for a/c units

Carlos Hernandez

36987					8/12/2008		111		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/12/2008 4:12:40 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Hernandez, Carlos weeds are taking over along all fence lines and in
parking area. please address. once cut.treat fence lines
to prevent growth. call mike if you have questions.
thxs

Michael Munoz

37440		Portables			8/27/2008		96		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			8/27/2008 9:30:51 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben broken window on new portable due to vandalism
(Case# 2008-1239)

Carlos Hernandez

37732		Portables			9/3/2008		89		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			9/3/2008 8:16:37 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ronquillo, Ruben need glass repaired new portable rear glass 40 3/4 by
12 1/2
thanks

Carlos Hernandez

12/1/2008 2:38:45 PM

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
37820					9/5/2008		87		\$0.00
Medium	Work In Progress			9/5/2008 8:39:36 AM					
Gonzalez, Salvador	Need to make a canopy for behind of cafeteria.								
Michael Munoz									
38796					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:09 AM					
Orozco, Danny	Monthly - Riverside ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38956		Cafeteria			10/6/2008		56		\$0.00
Medium	Work In Progress			10/6/2008 10:43:44 AM					
Moncayo, Fernando	TUBING INSIDE DISHMACHINE KEEPS ON DRIPPING WATER -EVEN WHEN MACHINE IS OFF.								
	EMILIA CARRILLO - SNP MANAGER 589-2550								
Alma Terrell									
39543					10/28/2008		34		\$0.00
Medium	Work In Progress			10/28/2008 1:28:41 PM					
Lozoya, Manny	remove lock from the flashing lights -								
Cora Ramirez									
39660					10/31/2008		31		\$0.00
Medium	Work In Progress			10/31/2008 3:06:06 PM					
Lara, Ralph	needs parts for handicap automatic door opener westside door								
Carlos Hernandez									
39817		Cafeteria			11/4/2008		27		\$0.00
Medium	Work In Progress			11/4/2008 2:52:35 PM					
Moncayo, Fernando	SANITIZER STILL NOT WORKING IN THE DISHMACHINE AREA - PART HAS NOT BEEN REPLACED								
	EMILIA CARRILLO AND AIDA SALCEDO - 589-2550 & 882-6772								
Alma Terrell									
40130					11/17/2008		14		\$0.00
Medium	Work In Progress			11/17/2008 8:09:25 AM					
Ambriz, Jose	need thermastate for portable 503 old one burnt out								
Carlos Hernandez									
40152					11/17/2008		14		\$0.00
Medium	Work In Progress			11/17/2008 3:21:29 PM					
Ambriz, Jose	need thermo coupler for heater in mech room								
Carlos Hernandez									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
40264					11/20/2008		11		\$0.00
Medium	Work In Progress				11/20/2008 3:11:28 PM				
Gonzales, Angel		truck seat needs repair truck #21							
Carlos Hernandez									
40366					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:30				
Hernandez, Carlos		Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.							
George ZZ Gabaldon									
40367					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:30				
Hernandez, Carlos		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40368					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:30				
Hernandez, Carlos		Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
Count: 20 Work Orders			Avg. Age of WO's	64		Total for Riverside ES	0		\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		San Miguel ES							
35664					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:56 AM					
Vega, Danny		Yearly - San Miguel ES Emer. Light Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35687					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:03 AM					
Vega, Danny		Yearly - San Miguel ES Exit Sign Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
37343					8/22/2008		101		\$0.00
Medium	Work In Progress			8/22/2008 3:24:23 PM					
Lozoya, Manny		Asp Mike, please core back to GM 6 or 7 pin.							
39334		Portables			10/21/2008		41		\$0.00
Medium	Work In Progress			10/21/2008 11:17:54					
Estrada, Jesus		Please re-carpet dbl portable northwest corner mescalero.Thxs(#42/goose)							
Michael Munoz									
39565	Main Building				10/29/2008		33		\$0.00
Medium	Work In Progress			10/29/2008 7:32:46 AM					
Lozoya, Manny		please change cores to where the techs can have access to the back door of the boiler room so they can service equipment.							
Michael Munoz									
Count: 5 Work Orders		Avg. Age of WO's		94	Total for San Miguel ES			0	\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
35630					7/6/2008	7/14/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:45 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35641					7/6/2008	7/14/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:48 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
35713					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:12 AM					
Villalobos, David	Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
37139					8/18/2008		105		\$0.00
Medium	Work In Progress			8/18/2008 11:44:10 AM					
Castillo, Carlos	CALI; HAND DRYER IN BOYS RRM. DOES NOT SHUT OFF AT TIMES, AND SOMETIMES STARTS BY ITSELF. NEED FOR YOU TO CHECK IT OUT. I TURNED THE BREAKER OFF , BECAUSE A STUDENT BURNED HIMSELF ON IT AND REPORTED IT TO THE OFFICE.								
Gerardo Marquez									
37687		Classroom			9/2/2008		90		\$0.00
Medium	Work In Progress			9/2/2008 11:24:37 AM					
Ronquillo, Ruben	One window on Portable is jammed intruder tried to get in thru window on east portable, also middle hallway workroom broken (window) cracked -B-Wing. (Case# 2008-08926)								
Pablo Diaz									
37927					9/8/2008		84		\$0.00
Medium	Work In Progress			9/8/2008 3:57:59 PM					
Marquez, Gerardo	9/4/08					9/4-8			
		1-INSP. BLDG. & GRNDS. PICKED UP TRASH. 2-CLEANED OFF ENTRANCES & SIDEWALKS. 1-CLEANED & IJNSP. P.G. AREAS. 2-ADJ. LOCKSETS, & DR. CLOSERS @ PORTABLES A, & B. 2-CLEANED & INSP. MECH. RMS.							
Gerardo Marquez									
38798					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:10 AM					
Orozco, Danny	Monthly - Santa Teresa ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
39140					10/12/2008	10/28/2008	50		\$0.00
Medium	Work In Progress			10/12/2008 12:20:54					
Diaz, Pablo	Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
39449	Main Building	Portables			10/24/2008		38		\$0.00
Medium	Work In Progress	ART PORTABLE		10/24/2008 9:06:50 AM					
Marquez, Gerardo	A PAPER RACK IS NEEDED TO BE SET UP IN THE CLASSROOM. THANKS.								
<u>Rita Mendez</u>									
39454	Main Building	Portables			10/24/2008		38		\$0.00
Medium	Work In Progress	ART PORTABLE		10/24/2008 10:59:50					
Marquez, Gerardo	BRACKETS AND SHELF NEED TO BE SET UP IN CLASSROOM. THANKS.								
<u>Rita Mendez</u>									
39559					10/28/2008		34		\$0.00
Medium	Work In Progress			10/28/2008 3:54:22 PM					
Gonzales, Angel	ANGEL, STILL NEED BOBCAT TO FILL IN WASHOUTS , WHENEVER ITS FREED UP.								
<u>Gerardo Marquez</u>									
39918	Main Building	Restroom (Girls)			11/6/2008		25		\$0.00
Medium	Work In Progress	ladies restroom		11/6/2008 3:11:24 PM					
Marquez, Gerardo	Large spacing in between the wall and other toilet partition needs to be covered. The gap is large enough to see other people inside the stall. Thank you.								
<u>Rita Mendez</u>									
40401					11/30/2008		1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:41					
Marquez, Gerardo	Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.								
<u>George ZZ_Gabaldon</u>									
40402					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:42					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>George ZZ_Gabaldon</u>									
40403					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:42					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>George ZZ_Gabaldon</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Santa Teresa ES							
40404					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress		11/30/2008 12:23:42						
Marquez, Gerardo		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.							
George ZZ Gabaldon									
Count: 16 Work Orders		Avg. Age of WO's	61	Total for Santa Teresa ES				0	\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
35520		Football Field			7/2/2008		152		\$0.00
Medium	Work In Progress			7/2/2008 8:03:34 AM					
Castillo, Carlos		NEED TO HAVE ONE LIGHT AT FOOTBALL FIELD CHECKED, NOT LIGHTING, WESTSIDE OF FIELD, BEHIND PRESSBOX.							
Arturo Nunez									
35552					7/6/2008	7/12/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:21 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
35569					7/6/2008	7/14/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:26 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
35666					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:19:56 AM					
Nunez, Arturo		Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35689					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:04 AM					
Nunez, Arturo		Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35711					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:11 AM					
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
35756		Athletic Field			7/8/2008		146		\$0.00
Medium	Work In Progress			7/8/2008 11:03:17 AM					
Ontiveros, Guadalupe		Remove goal post and install at CMS.							
Terry Alvarado									
36329	Gymnasium				7/29/2008		125		\$0.00
Medium	Work In Progress			7/29/2008 3:45:02 PM					
Boyd, David		Locker Room and Offices water leak on the roof.							
Manuel Prospero									
36384					7/31/2008		123		\$0.00
Medium	Work In Progress			7/31/2008 8:05:50 AM					
Prospero, Manuel		7/30/08. 8 HRS FINISH PAINTING 300'S HALLWAY.			7/30 - 8				
Manuel Prospero									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Santa Teresa HS								
36510					8/3/2008	8/9/2008	120		\$0.00	
Medium	Work In Progress			8/3/2008 12:20:16 AM						
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos										
36645	Cafeteria (2005)	Cafeteria			8/5/2008		118		\$0.00	
Medium	Work In Progress			8/5/2008 1:01:49 PM						
Moncayo, Fernando		WATER IS LEAKING FROM UNDERNEATH THE DISHWASHING MACHINE								
		OLGA BUSTAMANTE - SNP MANAGER 589-9836								
Alma Terrell										
37137	Cafeteria (2005)	Cafeteria			8/18/2008		105		\$0.00	
Medium	Work In Progress			8/18/2008 11:08:29 AM						
Moncayo, Fernando		Washing Machine is leaking water (underneath machine) - Left message with Fernando								
		Olga Bustamante - SNP Manager 589-5332								
Alma Terrell										
37359	Applied Science				8/25/2008		98		\$0.00	
Medium	Work In Progress			8/25/2008 12:49:37 PM						
Ontiveros, Guadalupe		backfill against perimeter sidewalks so that there is less than a 4" drop.								
Alfredo Holguin										
37386					8/26/2008		97		\$0.00	
Medium	Work In Progress			8/26/2008 7:30:49 AM						
Ontiveros, Guadalupe		Pedestrian Gate on South side that goes to the Bluffs. - Install taller gate to prevent access through bottom of gate.								
Alfredo Holguin										
37545					8/31/2008	9/6/2008	92		\$0.00	
Medium	Work In Progress			8/31/2008 12:25:12 AM						
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos										
37562					8/31/2008	9/21/2008	92		\$0.00	
Medium	Work In Progress			8/31/2008 12:25:18 AM						
Orozco, Danny		Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos										
37958					9/9/2008		83		\$0.00	
Medium	Work In Progress			9/9/2008 2:33:14 PM						
Castillo, Carlos		NEED SOME ASSISTANCE ON CHECKING OUTSIDE LIGHTING ON CAF. NEW BUILDING, VOC. BUILDING, AND MAIN BUILDING.								
Arturo Nunez										
12/1/2008 2:38:46 PM										

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
38018					9/11/2008		81		\$0.00
Medium	Work In Progress				9/11/2008 9:07:28 AM				
Prospero, Manuel		9/9/08. 4HRS FIX WATER LEAK ON GYM ROOF. 4HRS CHANGED CEILIN TILES ON ROOMS2,4,6.				9/9 - 8			
Manuel Prospero									
38073					9/14/2008		78		\$0.00
Medium	Work In Progress				9/14/2008 12:23:08 AM				
Ontiveros, Guadalupe		Monthly - Santa Teresa HS Soil Sampling - Refer to PM schedule details.							
Margret Villalobos									
38255		Classroom			9/19/2008		73		\$0.00
Medium	Work In Progress	RM 207			9/19/2008 12:14:53 PM				
Villalobos, Margret		Unit is working fine, problem with comm link, need to contact Trane.				Asp Jose Ambriz, need to schedule, when there is no students. E-mailed to J. Velasquez 9/19/08			
Jose Ambriz									
38257					9/19/2008		73		\$0.00
Medium	Work In Progress				9/19/2008 2:26:25 PM				
Ambriz, Jose		WE NEED SOME INSOLATION FOR DUCTWORK IN ROOM 12.							
Manuel Prospero									
38346					9/23/2008		69		\$0.00
Medium	Work In Progress				9/23/2008 9:02:34 AM				
Ambriz, Jose		THE FOLLOWING F.C.U.'S HAVE A COMMUNICATION PROBLEM BETWEEN MASTER AND SLAVE, 207M SCC IS OF LINE, 205M SCC IS OFF LINE, AND 203 SCC IS IF LINE. CAN WE PLEASE HAVE THEN CHECKED. THANK YOU.							
Arturo Nunez									
38539					9/30/2008		62		\$0.00
Medium	Work In Progress				9/30/2008 12:26:04 AM				
Prospero, Manuel		Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.							
Margret Villalobos									
38544	Cafeteria (2005)	Cafeteria			9/30/2008		62		\$0.00
Medium	Work In Progress				9/30/2008 8:10:55 AM				
Moncayo, Fernando		Comments from Ecolab Report: Dishwasher is not filling up. Pre-spray hose id damaged & should be replaced. Olga Bustamante SNP MANAGER 58905332							
Jacqueline Aguilar									
38595	Gymnasium				10/1/2008		61		\$0.00
Medium	Work In Progress				10/1/2008 12:31:34 PM				
Nunez, Arturo		REPLACE STAINED AND BROKEN CIELING TILES							
Michael Munoz									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
38685	Concession				10/2/2008		60		\$0.00
Medium	Work In Progress				10/2/2008 3:53:46 PM				
Villalobos, David	CONSESSION STAND HANDI-CAP COMMODE WILL NOT FLASH ON BOYS BATHROOM NEED TO BE REPAIR,HAVEING FOOTBOLL GAMES.								
<u>Manuel Prospero</u>									
38691					10/3/2008		59		\$0.00
Medium	Work In Progress				10/3/2008 7:59:21 AM				
Munoz, Michael	FRONT GATE NEEDS A GATE STOPER 6 GATE HINGES POLE IS 7 INCH WIDE 1 GATESTOPPER 1 POLE FOR GATE STOPPER.								
<u>Manuel Prospero</u>									
38753					10/5/2008	10/11/2008	57		\$0.00
Medium	Work In Progress				10/5/2008 12:23:53 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38754					10/5/2008	10/13/2008	57		\$0.00
Medium	Work In Progress				10/5/2008 12:23:53 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38755					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress				10/5/2008 12:23:54 AM				
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38756					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress				10/5/2008 12:23:54 AM				
Nunez, Arturo	Yearly - Santa Teresa HS H-6 Rftop Furn Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38757					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress				10/5/2008 12:23:54 AM				
Nunez, Arturo	Yearly - Santa Teresa HS R-9 Radiator Ht Wtr 2yr - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38758					10/5/2008	10/21/2008	57		\$0.00
Medium	Work In Progress				10/5/2008 12:23:55 AM				
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
38799					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:10 AM					
Orozco, Danny		Monthly - Santa Teresa HS Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
38896					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:46 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
38897					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:46 AM					
Prospero, Manuel		Yearly - Santa Teresa HS I-4 Fan Coil Unit Yearly - Refer to PM schedule details.							
Margret Villalobos									
38898					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:46 AM					
Prospero, Manuel		Monthly - Santa Teresa HS C-12 Chm Feeder Semimntly - Refer to PM schedule details.							
Margret Villalobos									
38899					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:47 AM					
Prospero, Manuel		Yearly - Santa Teresa HS U-2 Unit Ht Gas Yearly - Refer to PM schedule details.							
Margret Villalobos									
38992	Library				10/7/2008		55		\$0.00
Medium	Work In Progress			10/7/2008 9:54:07 AM					
Lara, Ralph		LIBRARY CONFERENCE ROOM LOCK ON DOOR TO HALLWAY IS BROCK							
Manuel Prospero									
39059	Library	Library			10/9/2008		53		\$0.00
Medium	Work In Progress			10/9/2008 9:00:13 AM					
Lara, Ralph		Key tumblers have fallen out on two doors Multi media and lib conf room							
Rosa Hood									
39164					10/12/2008	10/28/2008	50		\$0.00
Medium	Work In Progress			10/12/2008 12:21:05					
Nunez, Arturo		Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.							
Margret Villalobos									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
39344					10/21/2008		41		\$0.00
Medium	Work In Progress			10/21/2008 3:13:05 PM					
Villalobos, David	NEED SOME ASSISTANCE ON LEAK TEST GAS LINES ON WELDING BOTHS, THERE SEEMS TO BE A GAS LEAK, BUT CAN'T LOCATE.								
Arturo Nunez									
39396	Main Building	Choral			10/22/2008		40		\$0.00
Medium	Work In Progress			10/22/2008 3:57:04 PM					
Lara, Ralph	Door from Band Room Top Corner broken, needs to be replaced Thank you, Rosa								
Rosa Hood									
39398	Main Building	Hallway/Corridor			10/22/2008		40		\$0.00
Medium	Work In Progress			10/22/2008 3:59:35 PM					
Prospero, Manuel	Remove lockers in hallway near counseling area and across from Main office Thank you, Rosa								
Rosa Hood									
39399	Main Building	Office			10/22/2008		40		\$0.00
Medium	Work In Progress			10/22/2008 4:01:51 PM					
Estrada, Jesus	Mr. Kelch our principal would like new carpet installed in all the offices in the main office area Thank you, Rosa		Mr. Nunez has already begun the painting						
Rosa Hood									
39400	Main Building	Hallway/Corridor			10/22/2008		40		\$0.00
Medium	Work In Progress			10/22/2008 4:04:16 PM					
Prospero, Manuel	Mr. Kelch would like the all the hallways painted Thank you, Rosa		Mr. Nunez is painting the office in the main office area						
Rosa Hood									
39412	Dressing Rooms				10/23/2008		39		\$0.00
Medium	Work In Progress			10/23/2008 11:11:35					
Lara, Ralph	NEED TO HAVE A RESTROOM PILLASTER REPLACED FOR BOYS FOOTBALL DRESSING RESTROOM , TO INSTALL DOOR AT H.C. COMMODE. SIZES WERE FAXED TO MR. RONQUILLO THANK YOU.								
Arturo Nunez									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
39541	Main Building	Office			10/28/2008		34		\$0.00
Medium	Work In Progress			10/28/2008 1:14:24 PM					
Lara, Ralph	We need the locks on the attendacne (Anna Perez) door to be the same so that admin can open both top and bottom parts of the door with one key Thank you, Rosa								
Rosa Hood									
39542	Main Building	Office			10/28/2008		34		\$0.00
Medium	Work In Progress			10/28/2008 1:18:25 PM					
Ronquillo, Ruben	We need signs to indicate what building is what since we do not have a front entrance. Please feel free to call me or Art Nunez so that we can be more specific Thank you, Rosa								
Rosa Hood									
39648					10/31/2008		31		\$0.00
Medium	Work In Progress			10/31/2008 9:49:48 AM					
Castillo, Carlos	NEED SOME ASSISTANCE WITH A WALL PLUG, AND PIG TAIL FOR KILN IN ROOM # 601. THEY ARE FRIED, NEED TO BE REPLACED.								
Arturo Nunez									
39695					11/2/2008	11/8/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:36 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
39730					11/2/2008	11/10/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:49 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39740					11/2/2008	11/10/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:53 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39756					11/2/2008	12/3/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:59 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
39969					11/9/2008	11/25/2008	22		\$0.00
Medium	Work In Progress				11/9/2008 12:28:38 AM				
Prospero, Manuel		Monthly - Santa Teresa HS Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
40146					11/6/2008		25		\$0.00
Medium	Work In Progress				11/17/2008 2:07:57 PM				
Ronquillo, Ruben		BROKEN WINDOW IN SHOP 2.							
Jose Angelo									
40332		Custodial			11/25/2008		6		\$0.00
Medium	Work In Progress				11/25/2008 7:51:43 AM				
Carbajal, Jimmy		ROYAL BURNISHER TURNING OFF BY IT SELF / NEED TO BE CHECKED OUT THANK YOU.							
Luis Murillo									
40365					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:29				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
George ZZ Gabaldon									
40376					11/30/2008	12/21/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:33				
Orozco, Danny		Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.							
George ZZ Gabaldon									
40425					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:49				
Prospero, Manuel		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40426					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:50				
Prospero, Manuel		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40427					11/30/2008	12/31/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:50				
Prospero, Manuel		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
George ZZ Gabaldon									
Count: 62 Work Orders			Avg. Age of WO's	66		Total for Santa Teresa HS	0		\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Santa Teresa MS								
35712					7/6/2008	8/6/2008	148		\$0.00	
Medium	Work In Progress			7/6/2008 12:20:11 AM						
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos										
36170	North Building	Custodial			7/24/2008		130		\$0.00	
Medium	Work In Progress			7/24/2008 7:42:22 AM						
Gonzales, Angel		pete, the truck 39 needs a complete tune up i need to have it ready for the school year. thank you.								
Ismael Rodriguez										
36511					8/3/2008	8/9/2008	120		\$0.00	
Medium	Work In Progress			8/3/2008 12:20:17 AM						
Mijarez, Jaime		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos										
36757					8/7/2008		116		\$0.00	
Medium	Work In Progress			8/7/2008 9:33:54 AM						
Ambriz, Jose		Please order condensation pump replacement. 40 ea. little giant low rise pumps cat#554200, vcc-20ul or 2ouls, 40 ea. 1/2" 90 deg. ells. Slipxthd fmle, 40 ea. SPRTB-6 24x24 metal grilles, 40 ft. 3/4"ODx 5/8"ID clear vinyl tube, 60 ea. 3 amp fuses, box of orange electrical wire nuts, and box of insulated female and male solderless terminals. I need this asap when old condensate pumps stop working i can't repair them anymore.								
Jaime Mijarez										
36903	North Building	Classroom			8/11/2008		112		\$0.00	
Medium	Work In Progress	Room 3A		8/11/2008 3:12:40 PM						
Mijarez, Jaime		1. Portable leaks when it rains.								
Laura Parra										
37603					8/31/2008	9/6/2008	92		\$0.00	
Medium	Work In Progress			8/31/2008 12:25:31 AM						
Mijarez, Jaime		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos										
37771	Gym (1997)				9/4/2008		88		\$0.00	
High	Work In Progress			9/4/2008 8:21:25 AM						
Mijarez, Jaime		please reroute overflow lines from a/c. do not drain into mop sink and install strainer also. this will prevent from sink overflowing and damaging gym floor. (2nd time)								
Michael Munoz										
37808					9/4/2008		88		\$0.00	
Medium	Work In Progress			9/4/2008 4:13:04 PM						
Munoz, Michael		North Bldg. - Build concrete Pad for dumpsters.								
Alfredo Holguin										
12/1/2008 2:38:46 PM										

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
38251	Library	Library			9/19/2008		73		\$0.00
Medium	Work In Progress	Ms. Swaim-		9/19/2008 10:10:45 AM					
Castillo, Carlos		Need power strip for the wall. The outlets are overloaded. Wires and cords need to be contained.							
Parra, Laura									
38505					9/29/2008		63		\$0.00
Medium	Work In Progress			9/29/2008 1:43:22 PM					
Mijarez, Jaime		Need to install signs. Below is the recommendaton, but please ck w/site administrator first on location.							
Daniel Rosales									
38535					9/30/2008		62		\$0.00
Medium	Work In Progress			9/30/2008 12:26:01 AM					
Mijarez, Jaime		Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.							
Margret Villalobos									
38596					10/1/2008		61		\$0.00
Medium	Work In Progress			10/1/2008 12:33:20 PM					
Soria, Mike		CUT WEEDS AT NEW LANDSCAPING IN FRONT OF SOUTH BUILDING.							
Michael Munoz									
38597					10/1/2008		61		\$0.00
Medium	Work In Progress			10/1/2008 12:34:21 PM					
Soria, Mike		OPEN DRAIN BY MORGAN BUILDING. CUT WEEDS AND BARRICADE. SAFETY HAZARD.							
Michael Munoz									
38800					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:10 AM					
Orozco, Danny		Monthly - Santa Teresa MS Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
38869					10/5/2008	11/5/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:36 AM					
Mijarez, Jaime		Yearly - Santa Teresa MS U2 (Heat Gas)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
39102	North Building	Classroom			10/10/2008		52		\$0.00
Medium	Work In Progress	Room 1		10/10/2008 2:36:56 PM					
Mijarez, Jaime		Hand made wooden case in recognition hall needs to be installed on the wall. The case will need a 2x6 wooden base, plexiglass doors and mounting hardware							
Laura Parra									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
39103	South Building	Office			10/10/2008		52		\$0.00
Medium	Work In Progress	Social Worker-			10/10/2008 2:38:07 PM				
Mijarez, Jaime	Ceiling is leaking next to the window								
Laura Parra									
39113	South Building	Office			10/10/2008		52		\$0.00
Medium	Work In Progress	Assistant			10/10/2008 3:39:59 PM				
Castillo, Carlos	Need computer outlet and phone outlet to be placed on the opposite wall as to where its actually at								
Laura Parra									
39335					10/21/2008		41		\$0.00
Medium	Work In Progress				10/21/2008 12:48:47				
Ambriz, Jose	N.bldg Hp 36 lobby has a bad motor that is making a loud noise.								
Jaime Mijarez									
39406					10/23/2008		39		\$0.00
Medium	Work In Progress				10/23/2008 7:58:22 AM				
Castillo, Carlos	See if we can repair the timers and order additional triggers. (see Jaime if you have any questions).								
Michael Munoz									
39438	South Building	Hallway/Corridor			10/23/2008		39		\$0.00
Medium	Work In Progress				10/23/2008 3:54:21 PM				
Ambriz, Jose	Leak in lines.								
Jose Ambriz									
39696					11/2/2008	11/8/2008	29		\$0.00
Medium	Work In Progress				11/2/2008 12:24:36 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
39873	Gym (1997)				11/5/2008		26		\$0.00
Medium	Work In Progress				11/5/2008 3:41:57 PM				
Marquez, Gerardo	as per our meeting, please cut edges of gym floor for expansion. Thankyou								
Michael Munoz									
40169					11/18/2008		13		\$0.00
Medium	Work In Progress				11/18/2008 9:33:58 AM				
Ronquillo, Ruben	N.bldg office exterior windows. Replace 2nd glass window with new aluminum molding. Existing molding is to corroded. Replace aluminum molding around glass window that was replaced for W/O #39295. I checked molding around window and it is too damaged.								
Jaime Mijarez									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
40414					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:46				
Mijarez, Jaime		Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40415					11/30/2008	12/31/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:46				
Mijarez, Jaime		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.							
George ZZ Gabaldon									
40416					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:46				
Mijarez, Jaime		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40417					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:47				
Mijarez, Jaime		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.							
George ZZ Gabaldon									
Count: 28 Work Orders			Avg. Age of WO's	60		Total for Santa Teresa MS	0	0	\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
35710					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:11 AM					
Villalobos, David	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35734					7/7/2008		147		\$0.00
Medium	Work In Progress			7/7/2008 3:30:23 PM					
Lara, Ralph	WE NEED EXTRA KEY FROM LIBRARY								
Joel Herrera									
37362					8/25/2008		98		\$0.00
Medium	Work In Progress			8/25/2008 2:14:46 PM					
Lara, Ralph	WE NEED REPLACE CLASS ROOMS DOORS THEY ARE TO RUSTING								
Joel Herrera									
37891	Main Building				9/8/2008		84		\$0.00
Medium	Work In Progress			9/8/2008 9:02:24 AM					
Ronquillo, Ruben	FXT-SP-030 - Missing Boiler Room (S) asp PM 37589								
Joel Herrera									
38310					9/22/2008		70		\$0.00
Medium	Work In Progress	outside		9/22/2008 2:14:13 PM					
Herrera, Joel	Please replace broken tiles located by the main entrance.								
Jessica Lopez									
38335		Portables			9/22/2008		70		\$0.00
High	Work In Progress			9/22/2008 4:27:02 PM					
Acuna, Sal	Sal and Jimmy I need your help in moving furniture out of portable "C" at Sunland Park Elem. Aztec flooring will start on Wednesday 9/23 at 9:00 am.								
Jesus Estrada									
38355					9/23/2008		69		\$0.00
Medium	Work In Progress	38		9/23/2008 2:13:10 PM					
Herrera, Joel	Mr. Herrera please assemble kidney table found in storage unit. And please take it to Ms. Gardea room #38.								
Jessica Lopez									
38468					9/26/2008		66		\$0.00
Medium	Work In Progress			9/26/2008 1:25:56 PM					
Castillo, Carlos	MS. PEREZ WANTS TWO OUTLETS AT PLAYGROUNDS AREA IF WE CAN DO POSSIBLE. THANK YOU CALI								
Joel Herrera									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
38567					9/30/2008		62		\$0.00
Medium	Work In Progress			9/30/2008 2:42:50 PM					
Lara, Ralph	DOOR'S KNOB HAS A PIECE OF PENCIL LEAD STUCK IN KEY OPENING AND DOOR CAN'T BE UNLOCKED AT CLASS ROOM #28								
Joel Herrera									
38568					9/30/2008		62		\$0.00
Medium	Work In Progress			9/30/2008 3:01:23 PM					
Lara, Ralph	NEED TO FIXED HALL WAY DOOR IN SOUTH SIDE ALSO G.Y.M DOOR IS NOT WORKING								
Joel Herrera									
38801					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:11 AM					
Orozco, Danny	Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38865					10/5/2008	10/13/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:34 AM					
Herrera, Joel	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
38958					10/6/2008		56	1	\$25.00
Medium	Work In Progress	library		10/6/2008 12:29:14 PM					
Herrera, Joel Jessica Lopez	Attach electrical strip to new computer cart.					10/24 -NON ELECTRICAL, NEED BM TO OBTAIN A POWER SURGE STRIP AND INSTALL HIMSELF. C. CASTILLO. Route to Joel 11/3/08			
39539	Main Building				10/28/2008		34		\$0.00
Medium	Work In Progress			10/28/2008 11:18:00					
Estrada, Jesus Jesus Estrada	Tile is needed in lounge #34.								
39810	Main Building	Library			11/4/2008		27		\$0.00
Medium	Work In Progress			11/4/2008 1:13:33 PM					
Herrera, Joel Jessica Lopez	Mr. Herrera please assemble tv cart. Location-Library								
39811	Main Building	Classroom			11/4/2008		27		\$0.00
Medium	Work In Progress	Room #39		11/4/2008 1:22:08 PM					
Villalobos, David Jessica Lopez	Both sinks are not working correctly. They seem to be clogged. Location Room #39								

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
39888					11/6/2008		25		\$0.00
Medium	Work In Progress			11/6/2008 8:12:18 AM					
		WE NEED REPLACE CONCRET WALL AND STEEL GATE AT OUTSIDE AREA							
Joel Herrera									
39891					11/6/2008		25		\$0.00
Medium	Work In Progress			11/6/2008 8:20:54 AM					
		WE NEED CLEAN UP OUTSIDE CONCRET WALL							
Ontiveros, Guadalupe									
Joel Herrera									
40052					11/13/2008		18		\$0.00
Medium	Work In Progress	Room # 41		11/13/2008 1:19:38 PM					
		Mr. Herrera, Ms. Cordero needs a new sharpener. Room # 41							
Herrera, Joel									
Jessica Lopez									
40113					11/14/2008		0		\$0.00
Medium	Work In Progress			11/14/2008 3:14:33 PM	11/14/2008				
		Pick up trash all along the north side fence.							
Rivera, Hector									
Jesus Estrada									
40262					11/20/2008		11		\$0.00
Medium	Work In Progress			11/20/2008 3:03:51 PM					
		Mr. Herrera please clean rain gutters around the school. Thank You							
Herrera, Joel									
Jessica Lopez									
40263					11/20/2008		11		\$0.00
Medium	Work In Progress			11/20/2008 3:05:24 PM					
		Mr. De Santiago please shampoo Ms. Oaxaca's rug. Thank You							
De Santiago, Baudelio									
Jessica Lopez									
40288					11/21/2008		10		\$0.00
Medium	Work In Progress			11/21/2008 9:15:30 AM					
		Mr. Herrera please paint the red emergency lines located in front of the school.							
Herrera, Joel									
Jessica Lopez									
40411					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:45					
		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.							
Herrera, Joel									
George ZZ_Gabaldon									
40412					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:45					
		Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.							
Herrera, Joel									
George ZZ_Gabaldon									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
40413					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress		11/30/2008 12:23:45						
Herrera, Joel	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
George ZZ Gabaldon									
Count: 26 Work Orders		Avg. Age of WO's	48	Total for Sunland Park ES				1	\$25.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
35709					7/6/2008	8/6/2008	148		\$0.00
Medium	Work In Progress			7/6/2008 12:20:10 AM					
Villalobos, David		Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36205					7/25/2008		129		\$0.00
Medium	Work In Progress			7/25/2008 8:27:04 AM					
Lozoya, Manny		CLASSS RM. 207 DOOR HANDLE,AND LOCK CYLINDER NOT OPENING DOOR PROPERLY. THANKS							
Paul Quinones									
36336					7/29/2008		125		\$0.00
Medium	Work In Progress			7/29/2008 3:57:08 PM					
Ronquillo, Ruben		BROKEN WALL WINDOW IN WING 1,LOCATION RM.107 WINDOW SIZE 2'X2' DOUBLE PANE GLASS WINDOW W/ TINT. THANKS							
Paul Quinones									
36378					7/30/2008		124		\$0.00
Medium	Work In Progress			7/30/2008 4:19:55 PM					
Lozoya, Manny		DOOR IN WING B ELSOL HALL WAY.DURING FIRE DRILL IN THE MORNING 7-30-08.RIGHT SIDE DOOR WOULD NOT CLOSE DURING DRILL.							
Paul Quinones									
37422					8/26/2008		97		\$0.00
Medium	Work In Progress			8/26/2008 4:19:28 PM					
Ontiveros, Joe		HOSE BIBB ON WALL NEXT TO UPPER PLAY GROUND WATER LEAKING,BROKEN HANDLE.							
Paul Quinones									
38008	Main Building	Classroom			9/10/2008		82		\$0.00
Medium	Work In Progress			9/10/2008 4:02:35 PM					
Lozoya, Manny		Need key # for room 206 1c 32. The key is bent							
Joanne Munoz									
38009	Main Building	Classroom			9/10/2008		82		\$0.00
Medium	Work In Progress	Estrellita work		9/10/2008 4:18:59 PM					
Lozoya, Manny		Alma Castillo, testing room estrellita hallway, has a filing cabinet in her room that is locked and we do not have a key for it. CAN a new key be made or reinstall a new lock? Thank you.							
Joanne Munoz									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
38329					9/22/2008		70		\$0.00
Medium	Work In Progress			9/22/2008 3:45:45 PM					
Quinones, Paul		9-17-08			9/17-8				
		.5,CHECK IN W/OFFICE FOR PLAN OF THE DAY 7.5,REMOVE BLEACHERS FROM CHAP MID.TO C.H.S FOOT BALL STADIUM,AND RELOCATE SOCCER BLEACHERS TO FOOTBALL STADIUM AS WELL							
Paul Quinones									
38425	Main Building	Hallway/Corridor			9/25/2008		67		\$0.00
Safety	Work In Progress	sol		9/25/2008 10:54:05 AM					
Lozoya, Manny		The 1st door in el sol hallway is not releasing during fire drill. Needs to be checked out.							
Joanne Munoz									
38802					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:11 AM					
Orozco, Danny		Monthly - Sunrise ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
39068					10/9/2008		53		\$0.00
Medium	Work In Progress			10/9/2008 10:49:34 AM					
Solis, Lorenzo		PUMP HOUSING TO A/C IN RM.105 NEEDS TO BE REPLACED LIKE THE ONE THAT WAS REPLACED IN RM.210 THANKS							
Paul Quinones									
39161					10/12/2008	10/28/2008	50		\$0.00
Medium	Work In Progress			10/12/2008 12:21:04					
Quinones, Paul		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
39588					10/29/2008		33		\$0.00
Medium	Work In Progress			10/29/2008 4:11:14 PM					
Lozoya, Manny		HANDI CAP DOOR CLOSER NOT WORKING PROPERLY,DOOR STAYS OPEN.FRONT ENTRANCE AREA.							
Paul Quinones									
39681					11/2/2008	11/8/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:30 AM					
Quinones, Paul		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
39735					11/2/2008	11/10/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:51 AM					
Quinones, Paul	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39743					11/2/2008	11/10/2008	29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:54 AM					
Quinones, Paul	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
39747					11/2/2008		29		\$0.00
Medium	Work In Progress			11/2/2008 12:24:55 AM					
Jacquez, Ricardo	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									
39872					11/5/2008		26		\$0.00
Medium	Work In Progress			11/5/2008 3:35:43 PM					
Jacquez, Ricardo	REQUESTING WIND SCREEN FOR BACK CHAIN LINK FENCING AREA,LIFT STATION AREAS. BALL PARK FIGURE 200' WILL BE NEEDED @ 4' HIGH THANK YOU VERY MUCH								
Paul Quinones									
39895					11/6/2008		25		\$0.00
Medium	Work In Progress			11/6/2008 9:05:37 AM					
Sotelo, Enrique	LIGHTING PROBLEM IN REAR ENTRANCE OF SCHOOL,BURNED ELECTRICAL WIRING FROM INSIDE LIGHTING FIXTURE.								
Paul Quinones									
39902					11/6/2008		25		\$0.00
Medium	Work In Progress			11/6/2008 10:16:20 AM					
Solis, Lorenzo	RM.108 UNIT STAYS RUNNING TOO LONG,IN COOLING,AND IN HEATING.CLASS RM GETS TOO COLD,AND TOO HOT.								
Paul Quinones									
39903					11/6/2008		25		\$0.00
Medium	Work In Progress			11/6/2008 10:20:57 AM					
Solis, Lorenzo	RM.210 CIRCULATING PUMP MOTOR STAYS ON WHILE UNIT IS NOT CALLING FOR HEATING,AND COOLING.								
Paul Quinones									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
39904					11/6/2008		25		\$0.00
Medium	Work In Progress			11/6/2008 10:25:56 AM					
Solis, Lorenzo		RM.105 PUMP SEAL HOUSING NEEDS TO BE REPLACED TO UNIT IN CLASS RM.							
Paul Quinones									
39971					11/9/2008	11/25/2008	22		\$0.00
Medium	Work In Progress			11/9/2008 12:28:38 AM					
Quinones, Paul		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
40017	Main Building	Hallway/Corridor			11/12/2008		19		\$0.00
Medium	Work In Progress	VARIOUS		11/12/2008 8:05:43 AM					
Quinones, Paul		Need to have selected bulbs removed in the hallway.							
Joanne Munoz									
40018		Classroom			11/12/2008		19		\$0.00
Medium	Work In Progress	Parent Room		11/12/2008 8:11:32 AM					
Sotelo, Enrique		Check outlet with built in breaker, in Parent Room, by office, it keeps tripping.							
Joanne Munoz									
40050		Classroom			11/13/2008		18		\$0.00
Medium	Work In Progress	various		11/13/2008 11:30:13					
Quinones, Paul		Need to have a tv and/ or vcr and/or dvd in the following rooms:304,305,309,310,301,portables 3,4,5,6 and POA room See Mr. Wiggs for exact rooms and items							
Joanne Munoz									
40168					11/18/2008		13		\$0.00
Medium	Work In Progress			11/18/2008 9:12:56 AM					
Lozoya, Manny		DOOR HANDLE IN SPEECH THERAPIST DOOR ENTRANCE STICKING,AND WIIL NOT CLOSE DOOR PROPERLY.							
Paul Quinones									
40236					11/19/2008		12		\$0.00
Medium	Work In Progress			11/19/2008 3:44:08 PM					
Ontiveros, Joe		WATER LINE ON ROOF LEAKING WATER,VALVE INSIDE HALL WAY THAT SHUTS OFF WATER LINE IS SHUT OFF FRON INSIDE BUILDING NEXT TO THE ADMIN.OFFICE							
Paul Quinones									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
40289		Classroom			11/21/2008		10		\$0.00
Medium	Work In Progress	VARIOUS		11/21/2008 9:41:43 AM					
Quinones, Paul	PLEASE INSTALL PENCIL SHARPENERS IN THE FOLLOWING ROOMS 310,P-4,AND 302 WE HAVE THE SHARPENERS HERE AND READY TO BE INSTALLED								
Joanne Munoz									
40431					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:51					
Quinones, Paul	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
George ZZ_Gabaldon									
40432					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:52					
Quinones, Paul	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
George ZZ_Gabaldon									
40433					11/30/2008		1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:52					
Quinones, Paul	Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM schedule details.								
George ZZ_Gabaldon									
40434					11/30/2008		1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:52					
Quinones, Paul	Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM schedule details.								
George ZZ_Gabaldon									
40435					11/30/2008		1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:53					
Quinones, Paul	Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details.								
George ZZ_Gabaldon									
40436					11/30/2008		1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:53					
Quinones, Paul	Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.								
George ZZ_Gabaldon									
40437					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress			11/30/2008 12:23:53					
Quinones, Paul	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
George ZZ_Gabaldon									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Sunrise ES							
40442					11/30/2008		1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:55				
Jacquez, Ricardo	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
George ZZ Gabaldon									
Count: 37 Work Orders		Avg. Age of WO's	40	Total for Sunrise ES				0	\$0.00

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
38351		Library			9/23/2008		69		\$0.00
Medium	Work In Progress			9/23/2008 11:07:26 AM					
Munoz, Michael	Need to purchase new modular partitions for class room to be.								
Alfredo Holguin									
36103					7/22/2008		132		\$0.00
Medium	Work In Progress			7/22/2008 8:39:31 AM					
Sotelo, Enrique	NEED TO REPLACE 4 EXIT SIGNS								
Danny Miranda									
36104					7/22/2008		132		\$0.00
Medium	Work In Progress			7/22/2008 8:40:50 AM					
Sotelo, Enrique	NEED TO REPLACE 6 EMER. LIGHTS								
Danny Miranda									
36175	Main Building	Classroom			7/24/2008		130		\$0.00
Medium	Work In Progress			7/24/2008 11:22:30 AM					
Ronquillo, Ruben	NEED TO HAVE A COVER PUT OVER THE FIRE ALARM IN THE SPECIAL NEEDS CLASSROOM. ROOM101- PER DANNNY MIRANDA								
Debra Facio									
36221					7/25/2008		129		\$0.00
Medium	Work In Progress			7/25/2008 11:32:11 AM					
Lozoya, Manny	NEED A NEW DOOR CLOSER IN RM. 308, (LCN 4041)								
Danny Miranda									
37940					9/9/2008		83		\$0.00
Medium	Work In Progress			9/9/2008 10:02:37 AM					
Lozoya, Manny	need locks with long shank for outside gates custodians have trouble locking the ones that are there total of six gates								
Danny Miranda									
38100		Classroom			9/15/2008		77		\$0.00
High	Work In Progress			9/15/2008 3:46:51 PM					
Ronquillo, Ruben	Broken window in room 203. (CASE# 2008-08888) Est. Damage 255.00								
Alfredo Holguin									
38773					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:00 AM					
Orozco, Danny	Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.								
Margret Villalobos									

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
38803					10/5/2008	10/26/2008	57		\$0.00
Medium	Work In Progress			10/5/2008 12:24:11 AM					
Orozco, Danny	Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
39777					11/3/2008		28		\$0.00
Medium	Work In Progress			11/3/2008 12:27:44 PM					
Ontiveros, Joe	NEED TO REPAIR SINK IN GIRLS R.R. 200-WING								
Danny Miranda									
39782					11/3/2008		28		\$0.00
Medium	Work In Progress			11/3/2008 3:03:07 PM					
Ontiveros, Joe	NEED TO REPAIR WATER LEAK IN 2" LINE IN 200-WING HALLWAY								
Danny Miranda									
40046					11/13/2008		18		\$0.00
Medium	Work In Progress			11/13/2008 9:12:21 AM					
Miranda, Danny	NEED NEW EXIT SIGN IN GYM & 200-WING HALLWAY		Request thru Material Request Form. (e-mailed) mkv						
Danny Miranda									
40047					11/13/2008		18		\$0.00
Medium	Work In Progress			11/13/2008 9:13:38 AM					
Sotelo, Enrique	NEED TO CK. LIGHT IN 100-WING R.R. STAFF								
Danny Miranda									
40048	Main Building	Restroom (Boys)			11/13/2008		18		\$0.00
Medium	Work In Progress			11/13/2008 9:15:32 AM					
Sotelo, Enrique	NEED TO CK. LIGHT IN BOYS R.R. EMERGENCY LIGHT NOTCOMMING ON								
Danny Miranda									
40049					11/13/2008		18		\$0.00
Medium	Work In Progress			11/13/2008 10:49:45					
Miranda, Danny	NEED SOME BATTERIES FOR EXIT SIGNES # NICO148 80AAS 1.2 V								
Danny Miranda									
40212	Main Building				11/19/2008		12		\$0.00
Medium	Work In Progress	PSFA Site Visit		11/19/2008 9:44:32 AM					
Miranda, Danny	Roof top (Center) Recovery wheel is squeaking, please look into it and see what needs to be done.								
Michael Munoz									
40232					11/19/2008		12		\$0.00
Medium	Work In Progress			11/19/2008 3:37:49 PM					
Sotelo, Enrique	NEED ELECRICAL TO BE TIED INTO NEW PARTITION WAALS TO NEW CLASSROOM								
Danny Miranda									

12/1/2008 2:38:46 PM

888 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Vado ES							
40372					11/30/2008	12/6/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:32				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
George ZZ Gabaldon									
40373					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:32				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
40374					11/30/2008	12/8/2008	1		\$0.00
Medium	Work In Progress				11/30/2008 12:23:32				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.							
George ZZ Gabaldon									
Count: 20 Work Orders		Avg. Age of WO's		51	Total for Vado ES			0	\$0.00
Count: 888 Work Orders		Avg. Age of WO's		65	Grand Total			6	\$171.44