

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Anthony ES

35695					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:06 AM				
Villalobos, David	Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
35986	Chapter I	Office			7/16/2008		209		\$0.00
Medium	Work In Progress				7/16/2008 9:38:50 AM				
Lozoya, Manny	chapter blg repair pannic bar a.s.a.p								
Hector Villalobos									
36176	Cafeteria	Cafeteria			7/24/2008		201		\$0.00
Medium	Work In Progress				7/24/2008 11:26:39 AM				
Ontiveros, Guadalupe	remove old tree next to cafeteria,health issue as per ms.marquez								
David Vega									
36641	Drug Free Bldg.				8/5/2008		189		\$0.00
Medium	Work In Progress				8/5/2008 10:48:59 AM				
Sotelo, Enrique	please install a power strip for radios. please see irene for location.thxs								
Michael Munoz									
36672					8/6/2008		188		\$0.00
Medium	Work In Progress				8/6/2008 8:48:17 AM				
Lozoya, Manny	Primary blg storage need to charge lock								
Hector Villalobos									
37105	Chapter I	Office			8/15/2008		179		\$0.00
Medium	Work In Progress				8/15/2008 8:46:10 AM				
Lozoya, Manny	chapter blg o.t.p room needs 4 keys k50								
Hector Villalobos									
37170	Nurse Building				8/19/2008		175		\$0.00
Medium	Work In Progress				8/19/2008 7:36:40 AM				
Lozoya, Manny	need to replace exit door								
Hector Villalobos									
37287	Cafeteria	Cafeteria			8/21/2008		173		\$0.00
Medium	Work In Progress				8/21/2008 11:49:08 AM				
Orozco, Danny	SEAL TO WALK-IN REFRIGERATOR IS ALL TORN AND MOLDY, SEAL NEEDS TO BE REPLACED								
	BECKY SAENZ - 882-3507 (K-3 CAFETERIA)								
Alma Terrell									
37450	Original Main	Classroom			8/27/2008		167		\$0.00
Medium	Work In Progress	201			8/27/2008 12:39:44 PM				
Lozoya, Manny	Need an additional key.....								
Loraine Gandara									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Anthony ES

37451	Original Main	Classroom			8/27/2008		167		\$0.00
Medium	Work In Progress	201		8/27/2008 12:40:05 PM					
Lozoya, Manny		Need an additional key.....							
Loraine Gandara									
37452	Original Main	Classroom			8/27/2008		167		\$0.00
Medium	Work In Progress	202		8/27/2008 12:41:04 PM					
Lozoya, Manny		Need an additional key.....							
Loraine Gandara									
37942					9/9/2008		154		\$0.00
Medium	Work In Progress			9/9/2008 10:36:36 AM					
Lozoya, Manny		NEED 2 ADDITIONAL "H" KEY.....							
Loraine Gandara									
37962	Original Main				9/9/2008		154		\$0.00
Medium	Work In Progress	110		9/9/2008 2:44:04 PM					
Lozoya, Manny		NEED AN ADDITIONAL KEY FOR RM 110 KEY H11							
Loraine Gandara									
37994	Original Main	Office			9/10/2008		153		\$0.00
Medium	Work In Progress			9/10/2008 2:17:01 PM					
Gonzalez, Salvador		old main bld room 112 p.t.o needs window gurad							
Hector Villalobos									
38031	Original Main				9/11/2008		152		\$0.00
Medium	Work In Progress	POA OFFICE		9/11/2008 3:06:22 PM					
Lozoya, Manny		NEED A LOCK AND KEY FOR CABINETS.....							
Loraine Gandara									
38157	Original Main	Hallway/Corridor			9/17/2008		146		\$0.00
Medium	Work In Progress			9/17/2008 7:36:41 AM					
Lozoya, Manny		old main blg exit door hallway pannic bar will not lock .replace with new pannic bar. A.S.A.P							
Hector Villalobos									
38270					9/19/2008		144		\$0.00
Medium	Work In Progress	Corina		9/19/2008 4:08:26 PM					
Lozoya, Manny		Please install new locks on 2 file cabinets Tag# F00742 and the other one doesn't have a label. In Corina Valdespino's officce she is at the Village							
Lucia Almeraz									
39028		Athletic Field			10/8/2008		125		\$0.00
Medium	Work In Progress			10/8/2008 10:07:55 AM					
Appelzoller, Fred		Outside water fountains mounted on concrete block columns located east of the Old Main Cafeteria are not working. REPAIR							
Alfredo Holguin									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Anthony ES

39172	Chapter I	Classroom			10/13/2008		120		\$0.00
Medium	Work In Progress			10/13/2008 9:04:29 AM					
Lozoya, Manny		Chapter blg music room needs deadbolts on two doors							
Hector Villalobos									
39592					10/30/2008		103		\$0.00
Medium	Work In Progress			10/30/2008 7:34:13 AM					
Lozoya, Manny		old cafeteria gate and drug free gate need a pad lock H1							
Hector Villalobos									
39847	Main Building	Custodial			11/5/2008		97		\$0.00
Medium	Work In Progress			11/5/2008 9:38:37 AM					
Lozoya, Manny		custodial office does not lock							
David Vega									
39848	Main Building	Custodial			11/5/2008		97		\$0.00
Medium	Work In Progress			11/5/2008 9:40:28 AM					
Lozoya, Manny		need to replace k master key							
David Vega									
40015	Office				11/12/2008		90		\$0.00
Medium	Work In Progress			11/12/2008 7:22:02 AM					
Lozoya, Manny		On track Pre-k code came out of lock eixt door . secure door by today							
Hector Villalobos									
40016	Cafeteria	Cafeteria			11/12/2008		90		\$0.00
Medium	Work In Progress			11/12/2008 7:52:56 AM					
Sotelo, Enrique		please install light fixture in bathroom, old main cafeteria where remodeling is being done. thxs							
Michael Munoz									
40021	Original Main	Classroom			11/12/2008		90		\$0.00
Medium	Work In Progress			11/12/2008 9:29:47 AM					
Lozoya, Manny		old main blg room 101 door will not lock							
Hector Villalobos									
40041	Office	Portables			11/13/2008		89		\$0.00
Medium	Work In Progress			11/13/2008 7:36:52 AM					
Lozoya, Manny		Pt on track -Prek eixt door will not lock							
Hector Villalobos									
40310					11/24/2008		78		\$0.00
Medium	Work In Progress			11/24/2008 10:29:21					
Lozoya, Manny		NEED TO PUT IN NEW DOOR & FRAME IN R.R. ANTHONY ELEM. CAFETERIA							
Danny Miranda									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
40616	Main Building	Classroom			12/5/2008		67		\$0.00
Medium	Work In Progress			12/5/2008 12:36:05 PM					
Ronquillo, Ruben		missing 2 10 lbs and 9 5lbs fire extinguishers							
Hector Villalobos									
41163	Original Main	Athletic Field			1/5/2009		36		\$0.00
Medium	Work In Progress			1/5/2009 2:35:27 PM					
Holguin, Alfredo		Canopy tore in pieces by wind need to replace old main blg side palyground equipment							
Hector Villalobos									
41265		Athletic Field			1/8/2009		33		\$0.00
Medium	Work In Progress			1/8/2009 9:09:39 AM					
Ronquillo, Ruben		mild blg playground equipment slide needs to be replaced. Before someone cut themselves.							
Hector Villalobos									
41473	Main Building	Custodial			1/14/2009		27		\$0.00
Medium	Work In Progress			1/14/2009 7:10:53 AM					
Carbajal, Jimmy		vaccum cleaner needs repair							
David Vega									
41625	Main Building	Classroom			1/20/2009		21		\$0.00
Medium	Work In Progress			1/20/2009 7:23:55 AM					
Lozoya, Manny		room 16 needs keys made for cabinet							
Hector Villalobos									
41626	Original Main	Office			1/20/2009		21		\$0.00
Medium	Work In Progress			1/20/2009 7:28:24 AM					
Lozoya, Manny		Room 112 needs adoor guard for door lock handle							
Hector Villalobos									
41627		Electrical Room			1/20/2009		21		\$0.00
Medium	Work In Progress			1/20/2009 7:39:20 AM					
Solis, Lorenzo		Mild blg collaborative room need to order a new remoto contoller for unit							
Hector Villalobos									
41793	Main Building	Custodial			1/23/2009		18		\$0.00
Medium	Work In Progress			1/23/2009 12:04:13 PM					
Carbajal, Jimmy		vaccum cleaner needs repair							
David Vega									
41794	Main Building	Custodial			1/23/2009		18		\$0.00
Medium	Work In Progress			1/23/2009 12:05:03 PM					
Carbajal, Jimmy		vaccum cleaner needs repair							
David Vega									
41846	Original Main	Classroom			1/26/2009		15		\$0.00
Medium	Work In Progress	214 H5			1/26/2009 12:43:46 PM				
Lozoya, Manny		NEED AN ADDITIONAL KEY TO ROOM 214				WOULD GREATLY APPRECIATE IF THIS CAN BE DONE ASAP			
Loraine Gandara									

2/10/2009 3:17:24 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Anthony ES

41944	Original Main				1/28/2009		13		\$0.00
Medium	Work In Progress			1/28/2009 1:26:53 PM					
Lozoya, Manny	old main blg stoage supplie room needs door handle lock guard								
Hector Villalobos									
41978	Main Building	Custodial			1/29/2009		12		\$0.00
Medium	Work In Progress			1/29/2009 8:15:24 AM					
Carbajal, Jimmy	roto machine needs repair								
David Vega									
42084					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:38 AM					
Villalobos, Hector	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
42085					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:38 AM					
Villalobos, Hector	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42086					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:39 AM					
Villalobos, Hector	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42225					2/4/2009		6		\$0.00
Medium	Work In Progress			2/4/2009 11:28:27 AM					
Ronquillo, Ruben	Missing (11) - 5lb Fire Extinguishers asp PM 41029.								
Hector Villalobos									
42312	Cafeteria	Cafeteria			2/6/2009		4		\$0.00
Medium	Work In Progress			2/6/2009 9:55:57 AM					
Orozco, Danny	ANTHONY 3-6 CAMPUS. REACH - IN FREEZER DOWN AGAIN FOR THE 3RD TIME.								
	TERRY PORTILLO SNP MGR 882-3507								
Jacqueline Aguilar									
42323	Cafeteria	Cafeteria			2/6/2009		4		\$0.00
Medium	Work In Progress			2/6/2009 2:21:29 PM					
Orozco, Danny	DRAIN PIPE UNDER DISHMACHINE FELL OFF								
	MARIA (CUCA) PEREZ - SNP MANAGER 882-5607								
Alma Terrell									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
42338					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress				2/8/2009 12:19:26 AM				
Villalobos, Hector		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
42356					2/9/2009	2/15/2009	1		\$0.00
Medium	Work In Progress				2/9/2009 12:18:08 AM				
Villalobos, Hector		Monthly - Anthony ES A7 (Rooftop Unit)(Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
42372					2/9/2009		1		\$0.00
Medium	Work In Progress				2/9/2009 12:43:22 PM				
Lozoya, Manny		Need to ck padlock or issue a new key for the gate on church street, where the NM Environment Dept goes in. She said her key does not open that lock.							
<u>Margret Villalobos</u>									
42375		Cafeteria			2/9/2009		1		\$0.00
Medium	Work In Progress				2/9/2009 1:28:11 PM				
Villalobos, Hector		Cafeteria - Floors and baseboards need to be repaired asp AE Health Inspection. Terry Portillo							
<u>Aida Salcedo</u>									
42376	Cafeteria				2/9/2009		1		\$0.00
Medium	Work In Progress				2/9/2009 1:30:16 PM				
		Cafeteria - Light fixture covers need to be removed and cleaned immediately (bugs and debris could contaminate food) asp AE Health Inspection. Terry Portillo							
<u>Aida Salcedo</u>									
42377	Cafeteria				2/9/2009		1		\$0.00
Medium	Work In Progress				2/9/2009 1:31:36 PM				
Villalobos, Hector		Ceiling tiles missing, need to be replace (insulation is loose and need to be contained) asp AE Health Inspection. Terry Portillo							
<u>Aida Salcedo</u>									
42404	Cafeteria	Cafeteria			2/10/2009		0		\$0.00
Medium	Work In Progress				2/10/2009 9:23:00 AM				
Orozco, Danny		WALK-IN REFRIGERATOR - FAN IS LOOSE (MAKING ALOT OF NOISE)							
		CUCA PEREZ - SNP MANAGER 882-5607							
<u>Alma Terrell</u>									
Count: 52 Work Orders		Avg. Age of WO's 82			Total for Anthony ES			0	\$0.00

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

35696					7/6/2008	8/6/2008	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				7/6/2008 12:20:06 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David		Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.							
-------------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

36296					7/28/2008		197		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/28/2008 3:37:40 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		MR MANNY LOZOYA SIR IN PORTABLE 148 THE FILE CABINET GOT LOCK BY MASTAKE AND THEY DONT HAVE A KEY NEED TO REMOVE CYLINDER AND REPLACE WITH NEW ONE THAT HAS A KEY THANK YOU SIR AND GOD BLESS							
---------------	--	---	--	--	--	--	--	--	--

Adan Duran

36707					8/6/2008		188		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/6/2008 3:31:30 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe		MR LUPE ONTIVEROS SIR WE HAVE ABOUT 8 GALVNIZE PIPES 21 FT LOG THAT NEED TO BE PICKED UP AND HAUL OFF TO PPD YARD ALSO BIG BLOCKS OF CONCRETE THANK YOU SIR AND GOD BLESS							
----------------------	--	---	--	--	--	--	--	--	--

Adan Duran

36845					8/8/2008		186		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress	Mobile Home			8/8/2008 3:52:51 PM				
--------	------------------	-------------	--	--	---------------------	--	--	--	--

Sotelo, Enrique		Need to install utility hook-up for mobile home.							
-----------------	--	--	--	--	--	--	--	--	--

Michael Munoz

36879					8/11/2008		183		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/11/2008 9:01:25 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		MR LUPE ONTIVEROS SIR PER MR VALTIERRA HE WOULD LIKE THE SCHOOL CLEAN TO MANNY WEEDS PONDING AREA NEEDS CLEAN IN FRONT AND BACK AROUND PORTABLES ALONE FENCE IN FRONT OUTSIDE AND IN SIDE THANK YOU SIR							
----------------------	--	---	--	--	--	--	--	--	--

Adan Duran

38004					9/10/2008		153		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/10/2008 3:33:58 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		MR MANNY LOZOYA SIR WE ARE HAVE PROBLEMS WITH DOOR PORTABLE 135 OLD DOOR WILL NEED SOME HAREWARE WILL NOT LOCK KEEPS BLOWING OPEN WHEN WINDY THANK YOU SIR GOD BLESS							
---------------	--	--	--	--	--	--	--	--	--

Adan Duran

38128					9/16/2008		147		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/16/2008 10:30:21 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique		Emer. Light need replacing at west entrance and Custodial room.							
-----------------	--	---	--	--	--	--	--	--	--

Adan Duran

2/10/2009 3:17:24 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

38159					9/17/2008		146		\$0.00
Medium	Work In Progress				9/17/2008 7:52:03 AM				
Lozoya, Manny	MR MANNY LOZOYA SIR WE NEED TO CHANGE OUTSIDE GATE PAD LOCKS SOMEONE IS OPENING OUR GATES CHANGE LOCKS AS SAME AS ENTRANCE DOOR THANK YOU SIR								
Adan Duran									
38442	Main Building				9/25/2008		138		\$0.00
Medium	Work In Progress				9/25/2008 3:59:37 PM				
Duran, Adan	Restrooms nest to multipurpose room- sand entrance doors and reseal								
Alfredo Holguin									
38444	Portables				9/25/2008		138		\$0.00
Medium	Work In Progress				9/25/2008 4:06:10 PM				
Duran, Adan	Last two Portables on south row east side - re-install blocks under beams.								
Alfredo Holguin									
38699					10/3/2008		130		\$0.00
Medium	Work In Progress	Mobile Home			10/3/2008 10:42:41 AM				
Lozoya, Manny	As per Alfredo, need a gate key for Guadalupe Quinones the new mobile home occupant at Berino. The mobile home will be placed at the school this weekend.								
Alfredo Holguin									
38738					10/5/2008	11/5/2008	128		\$0.00
Medium	Work In Progress				10/5/2008 12:23:48 AM				
Duran, Adan	Yearly - Berino ES R9 (Radiator Hot)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
38778					10/5/2008	10/26/2008	128		\$0.00
Medium	Work In Progress				10/5/2008 12:24:02 AM				
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
39479					10/24/2008		109		\$0.00
Medium	Work In Progress				10/24/2008 3:26:04 PM				
Sotelo, Enrique	MR ENRIQUE SOTELO SIR EMERGENCY LIGHT FALL OFF WALL IN CAFETERIA NEED TO REPLACE BROKEN BURN ELEMENTS THE ONE IN CUSTODIAL ROOM ALSO THANK YOU SIR								
Adan Duran									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

40073					11/13/2008		89		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2008 4:10:00 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny

MR MANNY LOZOYA SIR WE NEED TO REPLACEMENT KEY THE TRASH MAN HAS B KEY BUT WE CHANGE GATE LOCKS TO B-1 HE COULD NOT GET IN MONDAY MUNCHO TRASH THANK YOU SIR

Adan Duran

40137					11/17/2008		85		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

High	Work In Progress				11/17/2008 11:07:56				
------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny

manny, you changed the core to the gates from a b to a b-1. the thrash guy does not have access. please make a new key for them and give to adan. he has the b for you.

Michael Munoz

40507					12/2/2008		70		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/2/2008 4:09:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe

Need to top dress playing field.

Michael Munoz

40921					12/16/2008		56		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/16/2008 3:45:59 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenzo

MR LORENZO SOLIS SIR THE HEATING UNIT IN THE GYM WILL NOT KICK ON NEED TO CHECK THANK YOU AND GOD BLESS

Adan Duran

40997					12/18/2008		54		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

High	Work In Progress				12/18/2008 4:24:02 PM				
------	------------------	--	--	--	-----------------------	--	--	--	--

Miranda, Danny

as epr our conversation, the wall to the entrance of the boys restroom on the east wing has been kicked in. please replace w/ durock as discussed. if other areas at site need the same please take of them.
Thxs

Michael Munoz

41069					1/4/2009	1/25/2009	37		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/4/2009 12:18:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny

Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

41153					1/5/2009		36		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/5/2009 8:18:40 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny

MR MANNY LOZOYA HAPPY NEW YEAR AND GOD BLESS MR LOZOYS SIR WE HAVE A BROKEN KEY IN GATE LOCK WEST GATE NEED TO REPLACE WILL NEED TO LOCK TO NIGHT THANK YOU SIR

Adan Duran

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

41506					1/14/2009		27		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/14/2009 3:48:50 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Gonzalez, Salvador	MR SAL GONZALEZ SIR THE SWING SET PLAY GROUND HAS A BENT PIPE NEED TO CUT REWELD OR REPLACE NEED TO LOOK AT IT THANK YOU SIR AND GOD BLESS								
--------------------	--	--	--	--	--	--	--	--	--

Adan Duran

41691					1/21/2009		20		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/21/2009 12:09:12 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ontiveros, Guadalupe	Plam tree issue; for more information please see Mike Muñoz. Thank you!								
----------------------	---	--	--	--	--	--	--	--	--

Sandra Almeraz

41707					1/21/2009		20		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/21/2009 3:39:44 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Gonzalez, Salvador	MR SAL GONZALES SIR THE BLEACHERS IN OUR PLAYGROUND HAVE BEEN VANDALISE TWO STEPS WHERE STOLEN NEED TO REPLACE 27 FEET LONG AND 9" WIDE I THINK 1/8 CHANNEL WILL DO NEED TO WELD ON ANGLE THANK YOU SIR AND GOD BLESS								
--------------------	---	--	--	--	--	--	--	--	--

Adan Duran

41940					1/28/2009		13		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	LINE LOCATE		1/28/2009 11:32:17 AM					
--------	------------------	-------------	--	-----------------------	--	--	--	--	--

Ontiveros, Joe	Need to line locate by Palm Tree loacted on southwest area, where camera is located.								
----------------	--	--	--	--	--	--	--	--	--

Guadalupe Ontiveros

42002					1/29/2009		12		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/29/2009 3:19:45 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Sotelo, Enrique	MR ENRIQUE SOTELO SIR NEED TO CHECK MOTOR ON EXHUAST FAN ROOMS 105 AND 106 ALSO CHECK SWITCHS FANS NOT WORKING THANK YOU AND GOD BLESS								
-----------------	--	--	--	--	--	--	--	--	--

Adan Duran

42051					2/1/2009	2/7/2009	9		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress			2/1/2009 12:24:26 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
-------------	---	--	--	--	--	--	--	--	--

Margret Villalobos

42052					2/1/2009	2/9/2009	9		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress			2/1/2009 12:24:26 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
-------------	---	--	--	--	--	--	--	--	--

Margret Villalobos

2/10/2009 3:17:24 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

42053					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:27 AM					

Duran, Adan Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

42325					2/6/2009		4		\$0.00
Medium	Work In Progress			2/6/2009 2:24:00 PM					

Duran, Adan 2/6/09 2/6-8
 1/2 SIGN IN CHECK BUILDINGS GROUNDS CLOSE WEST GATE
 1/2 CHECK BOILERS TEMP 150/140 LOG IN
 1 CHANGE OUT FLUORECENT BULBS TEACHERS LOUNGE
 1 PIPE DRAG WEST PARKING AREA
 1 COVER AND PATCH UP HOLE BOYS GANG RESTROOM
 2 PAINT GANG RESTROOM FULL OF GRAFFITTI
 1 CHECK FOR GAS LEAK ON ROOF TURN OFF
 1/2 CLOSE EAST GATES
 1/2 FILE DAILY LOG AND SIGN OUT

Adan Duran

42339					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress			2/8/2009 12:19:27 AM					

Duran, Adan Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.

Margret Villalobos

Count: 31 Work Orders	Avg. Age of WO's 88	Total for Berino ES	0	\$0.00					
------------------------------	----------------------------	----------------------------	----------	---------------	--	--	--	--	--

Location: Chaparral ES

35694					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress			7/6/2008 12:20:05 AM					

Villalobos, David Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

36075		Office			7/18/2008		207		\$0.00
Medium	Work In Progress	PRE-K		7/18/2008 4:55:16 PM					

Vargas, Juan AS PER ANN STEINHOFF-THERE IS MOLD ON THE CEILING IN THE WORK ROOM AT THE PRE-K

Mary Garcia

36581					8/4/2008		190		\$0.00
Medium	Work In Progress			8/4/2008 8:49:37 AM					

Vargas, Juan barracas 406-408-410-412-414-416-418 need change master cools now have 3800 is to small need replace for 4500 Routed 8/11 - Assign to JC asp our conversation he needs to give units a good PM, where installed last year. Humidity is @ 70 and m/c swamps do not work well. m.munoz

Juan Vargas

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
37055	2001 Classroom				8/14/2008		180		\$0.00
Medium	Work In Progress			8/14/2008 10:11:15 AM					
Vargas, Juan	need to add large rocks or cobblestones in areas where roof gutters are causing erosion								
Alfredo Holguin									
37056					8/14/2008		180		\$0.00
Medium	Work In Progress			8/14/2008 10:14:39 AM					
Vargas, Juan	All sidewalks with more than 4" drop need to have fill dirt added - Call Mike or Alfredo when work is complete								
Alfredo Holguin									
37057					8/14/2008		180		\$0.00
Medium	Work In Progress			8/14/2008 10:17:19 AM					
Vargas, Juan	Sand need to be leveled in fall areas of all playground structures on site.								
Alfredo Holguin									
37135	West Central				8/18/2008		176		\$0.00
Medium	Work In Progress			8/18/2008 9:11:53 AM					
Vargas, Juan	new doors are being installed in the esat and west barrack. please order paint so you can paint doors. thxs								
Michael Munoz									
37990	Cafeteria				9/10/2008		153		\$0.00
Medium	Work In Progress			9/10/2008 1:49:03 PM					
Orozco, Danny	Side of grease trap caving in.								
Michael Munoz									
38027	Athletic Field				9/11/2008		152		\$0.00
Medium	Work In Progress			9/11/2008 2:05:24 PM					
Ontiveros, Guadalupe	Lower Grades playground equipment located between classroom wings - Re layout plastic borders so they are around the remaining playground (slide) structure.								
Alfredo Holguin									
39939	E. Building	Classroom			11/7/2008		95		\$0.00
Medium	Work In Progress	509		11/7/2008 10:55:11 AM					
Lozoya, Manny	need cabinet to be relocked. Need new lock for it and key. Teacher for Visually impaired will be storing important and expensive merchandise in there and needs for it to be safe. See Ms. Kayce speech Teacher								
Jennifer Corral									
42318	Custodial				2/6/2009		4		\$0.00
Medium	Work In Progress			2/6/2009 10:54:22 AM					
Carbajal, Jimmy	the,advance,polishing,machine,not,working								
Daniel Ramirez									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

40051		Classroom			11/13/2008		89		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	512			11/13/2008 12:36:13				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Lozoya, Manny
need cabinet in rm to place belongings very expensive but does not have a key. So would like it to be redone and get a key for it. See Ms. Kayce SLP Speech Teacher. As soon as possible

Jennifer Corral

40239					11/19/2008		83		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/19/2008 3:48:17 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
would you please check the automatic door opener for handicap on the north side of the main hallway. Thank you

Guillermo Hernandez

40604					12/4/2008		68		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/4/2008 4:46:38 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Need assistance to replace two outside light fixtures of portable 34DW (#402 and #404)

Guillermo Hernandez

40796		Cafeteria			12/11/2008		61		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/11/2008 1:44:34 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Danny
IT'S LEAKING ALOT OF WATER FROM CEILING (INSIDE WALK-IN REFRIGERATOR)

ESTHER CISNEROS - SNP MANAGER 824-0048

Alma Terrell

41137					1/4/2009		37		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/4/2009 12:19:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Jacquez, Ricardo
Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.

Margret Villalobos

41418		Custodial			1/13/2009		28		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/13/2009 7:28:20 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Carbajal, Jimmy
NEED, TO, FIX, VACCUM, CLEANER, BROKEN

Daniel Ramirez

41467					1/13/2009		28		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/13/2009 4:03:57 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo
Need assistance to replace an exhaust fan in the Boy's restroom by the nurse office. Thank you

Guillermo Hernandez

41831					1/26/2009		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/26/2009 7:56:12 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe
Faucet leaking in teacher's lounge main building, broken seals. Thank you

Guillermo Hernandez

2/10/2009 3:17:24 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
41968					1/28/2009		13		\$0.00
Medium	Work In Progress			1/28/2009 3:46:13 PM					
Ontiveros, Joe	Need to replace two bubblers on the water fountain by the field and one by E wing. Thank you.								
Guillermo Hernandez									
41982					1/29/2009		12		\$0.00
Medium	Work In Progress			1/29/2009 9:19:23 AM					
Hernandez, Guillermo	Please install gutters on portable 34DW.								
Guillermo Hernandez									
41984		Custodial			1/29/2009		12		\$0.00
Medium	Work In Progress			1/29/2009 9:57:07 AM					
Carbajal, Jimmy	dolley,needs,to,be,fix,flat,tired.								
Daniel Ramirez									
42078					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:36 AM					
Hernandez, Guillermo	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42079					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:36 AM					
Hernandez, Guillermo	Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
42080					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:37 AM					
Hernandez, Guillermo	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42120					2/1/2009		9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:51 AM					
Jacquez, Ricardo	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									
42180					2/3/2009		7		\$0.00
Medium	Work In Progress			2/3/2009 11:54:25 AM					
Estrada, Jesus	ROOM 504 - SEAM COMING UNDONE CARPET WAS INSTALLED APPROX. MARCH/APRIL OF 2007, REF W.O. #19573								
Jesus Estrada									
42286					2/5/2009		5		\$0.00
Medium	Work In Progress			2/5/2009 3:39:10 PM					
Sotelo, Enrique	Need assistance to replace ballasts in Portable #P-1 & #P-2 (2 lamp ballast) Thank you								
Guillermo Hernandez									
2/10/2009 3:17:24 PM									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral ES

42288					2/5/2009		5		\$0.00
Medium	Work In Progress				2/5/2009 3:41:08 PM				
Sotelo, Enrique		Need assistance to replace ballasts in # P-7 Pre-K (4 lamp ballast) Thank you.							
Guillermo Hernandez									
42306		Lift Station			2/6/2009		4		\$0.00
Medium	Work In Progress				2/6/2009 9:16:34 AM				
Jacquez, Ricardo		please repair pumps @ lift station (2)							
Ricardo Jacquez									
42340					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress				2/8/2009 12:19:27 AM				
Hernandez, Guillermo		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
Count: 31 Work Orders		Avg. Age of WO's	72			Total for Chaparral ES	0		\$0.00

Location: Chaparral HS

35714					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:12 AM				
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
35869					7/11/2008		214		\$0.00
Medium	Work In Progress				7/11/2008 9:39:33 AM				
Lozoya, Manny		RE-KEY LEFT UPPER AND LOWER CABINETS FOR STORAGE LOCATED BEHIND THE RECEPTIONST FOR THE REGISTRAR (HEMPHILL)							
Rosa Quezada									
35870		Office			7/11/2008		214		\$0.00
Medium	Work In Progress	FRONT OFFICE			7/11/2008 9:41:05 AM				
Lozoya, Manny		RE-KEY RIGHT UPPER AND LOWER CABINETS FOR STORAGE LOCATED BEHIND THE RECEPTIONIST (GARCIA)							
Rosa Quezada									
35970					7/15/2008		210		\$0.00
Medium	Work In Progress	Mobile Home			7/15/2008 2:56:29 PM				
Ontiveros, Joe		SEPTIC AND WATER SYSTEMS NEED TO BE TIED IN FOR AN ON SITE MOBILE HOME.							
Eddie Baeza									
36093		Classroom			7/21/2008		204		\$0.00
Medium	Work In Progress	D-7			7/21/2008 3:47:12 PM				
Lozoya, Manny		NEED 1G032 SPARE KEY FOR FLAMABLE CABINET IN D-7(QUEZADA)							
Rosa Quezada									

2/10/2009 3:17:24 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
36579		Classroom			8/4/2008		190		\$0.00
Medium	Work In Progress	F Wing - Rm. 5			8/4/2008 8:18:45 AM				
Lozoya, Manny		Need a CH73 key for classroom F-5. (Paul H. Geiger)							
Guadalupe Gonzalez									
36593		Classroom			8/4/2008		190		\$0.00
Medium	Work In Progress	R Wing - Rm. 1			8/4/2008 1:55:06 PM				
Lozoya, Manny		Due to high security requirements, the control room door key must be cored the same as the storage room door. It is to be "off master" like the storage room.							
Guadalupe Gonzalez									
36606	B-Wing	Classroom			8/4/2008		190		\$0.00
Medium	Work In Progress	Rm B-3			8/4/2008 3:13:25 PM				
Lozoya, Manny		Need keys D274AR & D273AR. (Emmanuel Okeafor)							
Guadalupe Gonzalez									
36888					8/11/2008		183		\$0.00
Medium	Work In Progress				8/11/2008 1:32:00 PM				
Ontiveros, Joe		FAUCETS IN D-WING SCIENCE LABS NEED REPAIR AND REPLACEMENT.							
Eddie Baeza									
36959	A-Wing	Office			8/12/2008		182		\$0.00
Medium	Work In Progress				8/12/2008 3:11:57 PM				
Lozoya, Manny		Need to re-key mailroom to fit GM3 key.							
Guadalupe Gonzalez									
37177					8/19/2008		175		\$0.00
Medium	Work In Progress	Concession			8/19/2008 7:55:32 AM				
Lozoya, Manny		Need key to concession stand. (Mr. Sanchez)							
Guadalupe Gonzalez									
37220					8/20/2008		174		\$0.00
Medium	Work In Progress				8/20/2008 8:34:48 AM				
Lozoya, Manny		Need a CH73 key for classroom for F Wing - Rm. 5. (Paul H. Geiger)							
Guadalupe Gonzalez									
37394		Classroom			8/26/2008		168		\$0.00
Medium	Work In Progress	Nurse			8/26/2008 11:42:37 AM				
Lozoya, Manny		Need keys CH6 for Nurse's office and CH5 for the storage room in the Health Center. (Ana Castro)							
Guadalupe Gonzalez									
37432					8/27/2008		167		\$0.00
Medium	Work In Progress				8/27/2008 8:12:23 AM				
Gonzalez, Salvador		WELD GOOSENECK TO FOOTBALL GOAL POST.							
Guadalupe Ontiveros									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

37783					9/4/2008		159		\$0.00
Medium	Work In Progress				9/4/2008 10:52:49 AM				
Lozoya, Manny		(65) LATCH PROTECTORS ARE REQUESTED FOR CLASS RMS AND OFFICE DOORS							
Eddie Baeza									
37893					9/8/2008		155		\$0.00
Medium	Work In Progress	q-4			9/8/2008 10:21:54 AM				
Lozoya, Manny		need a CH-1 for auto construction labs.							
Rosa Quezada									
38072					9/14/2008		149		\$0.00
Medium	Work In Progress				9/14/2008 12:23:08 AM				
Ontiveros, Guadalupe		Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.							
Margret Villalobos									
38307		Classroom			9/22/2008		141		\$0.00
Medium	Work In Progress	Q-7			9/22/2008 1:13:03 PM				
Lozoya, Manny		NEED CH-94 (2) FOR Q-2 FOR LAB AND CAGES ONE & TWO NEED CH-96 (2) FOR Q-6 FOR LAB AND CAGE KEYS (FOR PETE GALVAN)							
Rosa Quezada									
38324					9/22/2008		141		\$0.00
Medium	Work In Progress				9/22/2008 3:28:35 PM				
Lozoya, Manny		THERE ARE SEVERAL PANIC BARS AND LOCK-SETS THAT ARE NOT WORKING PROPERLY ON CAMPUS.							
Eddie Baeza									
38577					9/30/2008		133		\$0.00
Medium	Work In Progress				9/30/2008 3:53:50 PM				
Lozoya, Manny		CHANGE THE LOCK ON THE TRAINERS ROOM OFF OF CH-86							
Eddie Baeza									
38578					9/30/2008		133		\$0.00
Medium	Work In Progress				9/30/2008 3:56:13 PM				
Lozoya, Manny		(4) DOORS IN THE LOCKER ROOMS NEED TO BE DOUBLE KEYED. (4) DOORS NEED TO BE CHANGED TO LATCH FOR SAFETY AND SECURITY REASONS							
Eddie Baeza									
38742					10/5/2008		128		\$0.00
Medium	Work In Progress				10/5/2008 12:23:49 AM				
Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.				10/6/08 - Emailed to Ricky Borrego			
Margret Villalobos									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

38989					10/7/2008		126		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/7/2008 8:47:09 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny PAD LOCKS AT THE ATHLETIC FEILDS NEED TO BE SECURED SO THEY WILL NOT BE LOST.

Eddie Baeza

38995					10/7/2008		126		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/7/2008 11:12:22 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny Need a Master Key for Trane Company. They will be working during Fall Break. (approved by A. Holguin)

Alfredo Holguin

39019					10/7/2008		126		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/7/2008 3:55:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny Greenhouses attached to building - Change door hardware between building and greenhouse to appropriate type.

Alfredo Holguin

39194					10/13/2008		120		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress	workroom Q & R			10/13/2008 3:43:04 PM				
--------	------------------	----------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny NEED TO KEY Q & R WING WORKROOMS SO THAT ALL TEACHERS HAVE ACCESS TO COPIER (QUEZADA)

Rosa Quezada

39303	A-Wing	Custodial			10/20/2008		113		\$0.00
-------	--------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/20/2008 2:42:25 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny NEED 4 COPIES OF THE TRASH COMPACTOR KEY FOR HEAD CUSTODIAN ARMANDO RIVERA (QUEZADA)

Rosa Quezada

39306					10/20/2008		113		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress	SOCCER			10/20/2008 2:44:56 PM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Lozoya, Manny NEED 3 COPIES OF CH-86 KEYS FOR SOCCER COACHES

Rosa Quezada

39328					10/21/2008		112		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/21/2008 8:25:53 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny (10) BEST PADLOCKS WITH LONG SHANKS ARE REQUESTED FOR EQUIPMENT IN NEW WEIGHT ROOM.

Eddie Baeza

39337					10/21/2008		112		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/21/2008 1:12:48 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny WE ARE UNABLE TO OPEN VAULT AT MAIN OFFICE, AND KEY JUST KEEPS TURNING.

Eddie Baeza

2/10/2009 3:17:24 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
39363	A-Wing	Classroom			10/22/2008		111		\$0.00
Medium	Work In Progress	storage room			10/22/2008 9:20:35 AM				
Lozoya, Manny		NEED TO CHANGE CORE IN MAIN STORAGE ROOM IN FRONT OFFICE TO FIT TO KEY GM3 (QUEZADA)							
Rosa Quezada									
39393					10/22/2008		111		\$0.00
Medium	Work In Progress				10/22/2008 3:50:18 PM				
Ontiveros, Guadalupe		(4) BATTING CAGES ARE REQUESTED FOR THE BASEBALL FIELDS.							
Eddie Baeza									
39768					11/3/2008		0		\$0.00
Medium	Work In Progress				11/3/2008 9:22:51 AM	11/3/2008			
Quinones, Paul		Asp Mike, please assist at CHS in cutting weeds starting today. Thanks							
Michael Munoz									
39771					11/3/2008		99		\$0.00
Medium	Work In Progress				11/3/2008 9:54:06 AM				
Parra, Juliet		A TRASH DUMPSTER IS REQUESTED FOR THE Q-WING							
Eddie Baeza									
39983	A-Wing	Office			11/11/2008		91		\$0.00
Medium	Work In Progress	front main door			11/11/2008 9:09:53 AM				
Lozoya, Manny		NEED TO REKEY FRONT MAIN DOOR TO CH-86 (DIGGS)							
Rosa Quezada									
39984					11/11/2008		91		\$0.00
Medium	Work In Progress	CONCESSION			11/11/2008 9:10:50 AM				
Lozoya, Manny		NEED TO RE-KEY CONCESSION ROOM TO OPEN ON MASTER							
Rosa Quezada									
40133					11/17/2008		85		\$0.00
Medium	Work In Progress	Storage Area			11/17/2008 10:18:06				
Lozoya, Manny		The storage for the building mechanic at CHS needs to be keyed so Mike and I have access to it. When we were there last week our key would not work. please correct this.							
Alfredo Holguin									
40350	A-Wing	Office			11/25/2008		77		\$0.00
Medium	Work In Progress	TESTING			11/25/2008 3:46:50 PM				
Lozoya, Manny		NEED TO REKEY TESTING STORAGE ROOM LOCATED IN THE MAIN OFFICE.							
Rosa Quezada									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

40485	A-Wing	Classroom			12/2/2008		70		\$0.00
Medium	Work In Progress	A Wing - Rm. 106			12/2/2008 10:03:48 AM				
Quinones, Paul		The platform on which the piano sits is not holding together when the piano is moved. It keeps separating and the piano falls. (Gonzalez)				12/2/08 - Asp David this would be under the furniture manuf. and installer, not construction.			
Guadalupe Gonzalez						12/3 - Routed to Paul to see if it is warranty. - mkv			

40562					12/3/2008		69		\$0.00
Medium	Work In Progress				12/3/2008 3:52:43 PM				
Lozoya, Manny		Check w/Paul to see if there is any other keys he needs for this site. He already has a GM.							

Michael Munoz

40705		Gym			12/9/2008		63		\$0.00
Medium	Work In Progress	Gym			12/9/2008 2:10:35 PM				
Lozoya, Manny		Left gym door does not lock. (Mr. Sanchez)							

Guadalupe Gonzalez

40735		Classroom			12/10/2008		62		\$0.00
Medium	Work In Progress	F Wing -			12/10/2008 10:10:47				
Lozoya, Manny		Replace lock in Teacher's Lounge, it doesn't lock.							

Guadalupe Gonzalez

40736		Office			12/10/2008		62		\$0.00
Medium	Work In Progress	Office			12/10/2008 10:12:29				
Lozoya, Manny		Replace the lock to the door in the west side of the front office. It doesn't lock.							

Guadalupe Gonzalez

40739	D-Wing	Classroom			12/10/2008		62		\$0.00
Medium	Work In Progress	Rm.7			12/10/2008 10:51:44				
Ontiveros, Joe		No Water in classroom. (Ms. Selwyn)							

Guadalupe Gonzalez

40740	D-Wing	Classroom			12/10/2008		62		\$0.00
Medium	Work In Progress	Rm.7			12/10/2008 10:52:49				
Ontiveros, Joe		No gas in classroom. (Ms. Selwyn)							

Guadalupe Gonzalez

40782	A-Wing				12/11/2008		61		\$0.00
Medium	Work In Progress				12/11/2008 9:11:02 AM				
Quinones, Paul		Need to install pencil sharpeners in the A Wing. (Ms. Ballard)							

Guadalupe Gonzalez

40783		Classroom			12/11/2008		61		\$0.00
Medium	Work In Progress	R Wing - Rm. 1			12/11/2008 9:15:05 AM				
Lozoya, Manny		Plate needs to be installed over door latch/jamb to prevent unauthorized entry into the studio facility. As soon as possible. (Mr. Gabaldon)							

Guadalupe Gonzalez

2/10/2009 3:17:25 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral HS

40824					12/12/2008		60		\$0.00
Medium	Work In Progress			12/12/2008 8:53:14 AM					
Lozoya, Manny	Need to issue a key to J. Acuna for Paul Quinones office.								
Michael Munoz									
40851					12/14/2008		58		\$0.00
Medium	Work In Progress			12/14/2008 12:16:33					
Ontiveros, Guadalupe	Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.								
George ZZ Gabaldon									
40870		Classroom			12/15/2008		57		\$0.00
Medium	Work In Progress	R Wing - Rm. 2		12/15/2008 2:29:31 PM					
Lozoya, Manny	Door will not lock properly in R Wing - Rm. 2 (Mr. Aguilar)								
Guadalupe Gonzalez									
40904					12/16/2008		56		\$0.00
Medium	Work In Progress			12/16/2008 11:12:15					
Lozoya, Manny	Paper Recycle Bins - Install regular master padlocks on them. (Any ?'s see Alfredo) - Please let him know when it is complete.								
Alfredo Holguin									
40973					12/18/2008		54		\$0.00
Medium	Work In Progress			12/18/2008 11:05:11					
Lozoya, Manny	PROTECTOR LATCHES,AND DOOR STOPS ARE NEEDED TO ALL CLASS RM. DOORS,AND OTHER DOORS REQUESTED BY CHS PRINCAPLE.ADDITIONAL HELP WILL HELP AS PROJECT STARTS.THANKS MANNY								
Paul Quinones									
41139					1/4/2009		37		\$0.00
Medium	Work In Progress			1/4/2009 12:19:18 AM					
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41140					1/4/2009		37		\$0.00
Medium	Work In Progress			1/4/2009 12:19:19 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
41141					1/4/2009		37		\$0.00
Medium	Work In Progress			1/4/2009 12:19:19 AM					
Quinones, Paul	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41142					1/4/2009	1/12/2009	37		\$0.00
Medium	Work In Progress			1/4/2009 12:19:20 AM					
Quinones, Paul	Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41144					1/4/2009	2/4/2009	37		\$0.00
Medium	Work In Progress			1/4/2009 12:19:21 AM					
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41150					1/4/2009		37		\$0.00
Medium	Work In Progress			1/4/2009 12:19:23 AM					
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.					1/6/09 e-mailed to ricky.borrego@cummins.com - mkv			
<u>Margret Villalobos</u>									
41178					1/5/2009		36		\$0.00
Medium	Work In Progress	R-Bldg		1/5/2009 3:59:51 PM					
Lozoya, Manny	DOOR IN R-2 BUILDING DOOR DOESNT LOCK DOOR ENTRANCE.								
<u>Paul Quinones</u>									
41180					1/5/2009		36		\$0.00
Medium	Work In Progress			1/5/2009 4:02:23 PM					
Lozoya, Manny	DOOR NEXT TO FRONT ENTRANCE WILL NOT LOCK WITH KEY.ON THE LEFT SIDE OF DOOR.								
<u>Paul Quinones</u>									
41479					1/14/2009		27		\$0.00
Medium	Work In Progress	SECURITY		1/14/2009 9:12:39 AM					
Lozoya, Manny	RE-KEY SECURITY SHACK WHEN COMPLETED WITH A CH-1 KEY. (DE SANTIAGO)								
<u>Rosa Quezada</u>									
41522					1/15/2009		26		\$0.00
Medium	Work In Progress			1/15/2009 9:42:20 AM					
Ontiveros, Joe	SCIENCE CLASS ROOMS SOLENOID VALVES USED FOR WATER,GAS,AND ELECTRICAL.VALVES ARE LEAKING NEED TO BE REPLACED.RM.C-6. THANK YOU								
<u>Paul Quinones</u>									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral HS

41529		Computer Lab			1/15/2009		26		\$0.00
-------	--	--------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	B Wing -		1/15/2009 2:15:39 PM					
--------	------------------	----------	--	----------------------	--	--	--	--	--

Lozoya, Manny
Right entrance door to the classroom can not be unlocked with the key. Please check. (Ms. Duran-Campbell)

Guadalupe Gonzalez

41607					1/16/2009		25		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/16/2009 3:12:37 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny
FIELD HOUSE BUILDING,BOYS WEIGHT RM.DOOR ENTRANCE
KEY CYLINDERS DEED TO BE REPLACED FROM MULLEN TO
BEST 2 DOORS.GIRLS LOCKER RM.3 CYLINDERS WILL BE
NEEDED,AND BOYS LOCKER RM.4 CYLINDERS WILL BE
NEEDED TO PANIC BARS THANKS

Paul Quinones

41608					1/16/2009		25		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/16/2009 3:18:26 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Sotelo, Enrique
Q,AND R BUILDING BUILDING ELECTRICAL KEY SWITCHES
NEED TO BE REPLACED IN RES RMS.,AND HALL WAYS.
CUSTODIANS HAVIING PROBLEMS TURNING OFF LIGHTS.
MUCHOS GRACIAS HENRY.

Paul Quinones

41610					1/16/2009		25		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/16/2009 3:23:48 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny
REAR GATE TO KITCHEN REAR ENTRANCE.HOLES ARE NEEDED TO BE PLACED ON FLOOR TO SECURE GATE LATCHES

Paul Quinones

41612					1/16/2009		25		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/16/2009 3:28:00 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny
GYM ENTRANCE DOORS HOLES NEED TO BE PLACED TO SECURE DOOR LATCHES

Paul Quinones

41787					1/23/2009		18		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/23/2009 9:47:49 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Quinones, Paul
AS PER MIKE WEEDS NEED TO BE CUT AND CLEANED. FOCUS ON FRONT OF SCHOOL, ISLANDS, COVES AND FENCE LINES.

Michael Munoz

2/10/2009 3:17:25 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

41847					1/26/2009		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/26/2009 1:29:02 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny
Need key CH86 and padlock with key MD7 made for new grounds keeper (Johnny Valles). If you have any questions contact Lupe Ontiveros.

Guadalupe Ontiveros

41896		Mechanical Room			1/27/2009		14		\$0.00
-------	--	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	field house by			1/27/2009 2:15:28 PM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Lozoya, Manny
change keys to field house by football field to CH-Master (jdiggs)

Rosa Quezada

41898	E-Wing	Custodial			1/27/2009		14		\$0.00
-------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/27/2009 2:50:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Carbajal, Jimmy
SCRUBER AUTO PROBLEM WITH THE BATTERIES NOT HOLDING CHARGE

Armando Rivera

41922					1/28/2009		13		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/28/2009 7:49:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Acuna, Johnny
To: Johnny Acuña (Help paul cut weeds at chaparral high school grounds and fencelines)

Johnny Acuna

41923		Cafeteria			1/28/2009		13		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/28/2009 8:00:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny
RUBBER SEAL TO SPRAYER (IN WASHROOM AREA) FELL OFF AGAIN

JUANA MONTELONGO - SNP MANAGER - 824-4461

Alma Terrell

41973					1/28/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

High	Work In Progress				1/28/2009 4:21:00 PM	1/28/2009			
------	------------------	--	--	--	----------------------	-----------	--	--	--

Lozoya, Manny
Head Custodian Armando Rivera needs his desk to lock so he can keep documents locked up.

Jesus Estrada

42026					1/30/2009		11		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/30/2009 12:54:31 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Jacquez, Ricardo
DOMESTIC WATER VALVES IN HOT BOX LEAKING WATER FROM INSIDE HOT BOX, LOCATED NORTH END FENCE LINE COUNTY LINE RD.

Paul Quinones

42027					1/30/2009		11		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/30/2009 12:56:48 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny
NEED TO REPLACE LOCKS IN HOT BOX FENCE AREA NORTH END FENCE LINE.

Paul Quinones

2/10/2009 3:17:25 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
42113					2/1/2009		9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:48 AM					
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42114					2/1/2009		9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:49 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42115					2/1/2009		9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:49 AM					
Quinones, Paul	Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42116					2/1/2009	3/4/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:49 AM					
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42151					2/2/2009		8		\$0.00
Medium	Work In Progress			2/2/2009 3:05:54 PM					
Acuna, Johnny	(To: Johnny Acuña) Please check water break at Chaparral High School in the weight room.								
<u>Johnny Acuna</u>									
42182					2/3/2009		7		\$0.00
Medium	Work In Progress			2/3/2009 12:59:06 PM					
Lozoya, Manny	PANIC BAR IN REAR ENTRANCE KITCHEN NEEDS TO BE SECURED TO DOOR FOR SAFETY PURPOSES, AND TO LOCK DOOR								
<u>Paul Quinones</u>									
42183					2/3/2009		7		\$0.00
Medium	Work In Progress			2/3/2009 1:04:18 PM					
Lozoya, Manny	ADMIN.OFFICE NEEDS CAM LOCK TO SECURE PARTITION IN OFFICE AREA NEXT TO MR.DIGGS OFFICE								
<u>Paul Quinones</u>									
42184					2/3/2009		7		\$0.00
Medium	Work In Progress			2/3/2009 1:07:28 PM					
Ontiveros, Joe	ARMSTRONG CIRCULATING PUMP SEAL LEAKING, SECURE RETURN HOT WATER DOMESTIC WATER LINE TO BOILER								
<u>Paul Quinones</u>									
2/10/2009 3:17:25 PM									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

42197					2/3/2009		7		\$0.00
Medium	Work In Progress				2/3/2009 3:32:47 PM				
Lozoya, Manny		OUTSIDE DOOR HEALTHCENTER AREA DOOR WILL NOT CLOSE DOOR FROM CYLINDER, AND THE PANIC BAR KEY CYLINDER AS WELL.							
Paul Quinones									
42322	E-Wing	Custodial			2/6/2009		4		\$0.00
Medium	Work In Progress				2/6/2009 1:48:25 PM				
Carbajal, Jimmy		repleace dolly wheels (2)							
Armando Rivera									
42373	A-Wing				2/9/2009		1		\$0.00
Medium	Work In Progress	VAULT IN			2/9/2009 1:13:04 PM				
Lozoya, Manny		VAULT DOOR IS TOO HARD TO OPEN. THE HANDLE IS HARD AND SO IS THE DOOR. WE HAVE A HARD TIME OPENING IT. ALSO, THE COMBINATION WHEEL IS NOT WORKING PROPERLY. WE HAVE TO MAKE 4-5 ATTEMPTS BEFORE IT WILL OPEN THE VAULT. (QUEZADA)							
Rosa Quezada									
42374	A-Wing				2/9/2009		1		\$0.00
Medium	Work In Progress	VAULT - FRONT			2/9/2009 1:24:52 PM				
Lozoya, Manny		PLEASE FIX THE VAULT DOOR QUICKLY. OUR RIGHT HANDS, SHOULDERS, ARMS, ARE HURTING FROM CONSTANTLY TRYING TO OPEN THE VAULT. (HEMPHILL, GONZALEZ, QUEZADA)							
Rosa Quezada									
42403					2/10/2009		0		\$0.00
Medium	Work In Progress				2/10/2009 8:31:08 AM				
Sotelo, Enrique		NEED TO INSTALL OUTLETS IN NEW GROUNDS STORAGE.							
Guadalupe Ontiveros									
Count: 89 Work Orders			Avg. Age of WO's 78				Total for Chaparral HS	0	\$0.00

Location: Chaparral MS

35697					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:06 AM				
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36145	Main Building	Classroom			7/23/2008		202		\$0.00
Medium	Work In Progress	Room 207			7/23/2008 11:09:15 AM				
Lozoya, Manny		**URGENT** THIRD REQUEST FOR NEW KEY FOR ROOM 207 OLD KEY BENT AND BROKE							
Elena Palacios									

2/10/2009 3:17:25 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

36315					7/29/2008		196		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

High	Work In Progress			7/29/2008 10:57:48 AM					
------	------------------	--	--	-----------------------	--	--	--	--	--

Lozoya, Manny

URGENT

NEED KEY LOCKS THAT WERE LOST AND ORDERED ACCORDING TO RAFA AND MANNY BACK IN SEPTEMBER OF 07, LOCKS AND KEYS STILL HAVE NOT BEEN REPLACED IN THEIR ENTIRETY

Elena Palacios

36316		Computer Lab			7/29/2008		196		\$0.00
-------	--	--------------	--	--	-----------	--	-----	--	--------

High	Work In Progress	ROOM 207		7/29/2008 11:01:56 AM					
------	------------------	----------	--	-----------------------	--	--	--	--	--

Lozoya, Manny

NEED NEW KEY MADE FOR ROOM 207

Elena Palacios

36767	Main Building	Classroom			8/7/2008		187		\$0.00
-------	---------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	ROOM 201		8/7/2008 12:10:58 PM					
--------	------------------	----------	--	----------------------	--	--	--	--	--

Lozoya, Manny

NEEDS KEYS TO LOCK CABINETS

Elena Palacios

37050					8/14/2008		180		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/14/2008 8:28:32 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Joe

need to replace shower columns in boys and girls reast rooms.
Thxs

Marti Muela

37191					8/19/2008		175		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/19/2008 10:54:48 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lozoya, Manny

eight security window rod irons can not be locked in the 300 & 400 hallway. very easy to break into. those rooms are to the back and can not be seen from the street.

Robert Gonzalez

37404	Main Building	Classroom			8/26/2008		168		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	ROOM 406		8/26/2008 3:43:07 PM					
--------	------------------	----------	--	----------------------	--	--	--	--	--

Lozoya, Manny

NEED CABINET LOCKS

Elena Palacios

37822	Main Building	Portables			9/5/2008		158		\$0.00
-------	---------------	-----------	--	--	----------	--	-----	--	--------

High	Work In Progress	P-9		9/5/2008 9:09:01 AM					
------	------------------	-----	--	---------------------	--	--	--	--	--

Lozoya, Manny

Social Worker Berenice Holguin needs her file cabinet locked for very confidential paperwork. Her lock was taken by Manny but never replaced.

Elena Palacios

37823	Main Building	Classroom			9/5/2008		158		\$0.00
-------	---------------	-----------	--	--	----------	--	-----	--	--------

High	Work In Progress	Room 206		9/5/2008 9:10:55 AM					
------	------------------	----------	--	---------------------	--	--	--	--	--

Lozoya, Manny

Counselor James Wolf needs file cabinet lock back, to secure confidential paperwork. Was taken last year by Manny and not yet replaced.

Elena Palacios

2/10/2009 3:17:25 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

37824	Main Building	Classroom			9/5/2008		158		\$0.00
High	Work In Progress	Room 404			9/5/2008 9:14:56 AM				
Lozoya, Manny		NEED CABINETS KEYED FOR MR. MORALES IN ROOM 406							
Elena Palacios									
38127		Gym			9/16/2008		147		\$0.00
Medium	Work In Progress				9/16/2008 10:22:53 AM				
Ronquillo, Ruben		Asp PM 37575 FXT-CHM -017 Need plexiglass cover. FXT-CHM-018 Need plexiglass cover.							
Eric Medina									
38437					9/25/2008		138		\$0.00
Medium	Work In Progress				9/25/2008 3:39:35 PM				
Sotelo, Enrique		need light covers plastic							
Eric Medina									
38779					10/5/2008	10/26/2008	128		\$0.00
Medium	Work In Progress				10/5/2008 12:24:03 AM				
Orozco, Danny		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
39496	Main Building	Classroom			10/27/2008		106		\$0.00
Medium	Work In Progress	ROOM 203			10/27/2008 8:38:48 AM				
Lozoya, Manny		NEED EXTRA KEY MADE FOR ROOM 203 KEY 78 THANKS							
Elena Palacios									
39611					10/30/2008		103		\$0.00
Medium	Work In Progress				10/30/2008 12:30:11				
Lozoya, Manny		room 312 teacher complains door knob is loose							
Eric Medina									
39938	Main Building	Gym			11/7/2008		95		\$0.00
Medium	Work In Progress				11/7/2008 9:41:00 AM				
Lozoya, Manny		Need to replace panic bar in boys locker room due to vandalism.							
Manny Lozoya									
40024					11/12/2008		90		\$0.00
Medium	Work In Progress				11/12/2008 10:54:32				
Ontiveros, Guadalupe		need to order a couple of loads of gravel or base for exposed plumbing in nurses portable							
Eric Medina									
40703					12/9/2008		63		\$0.00
Medium	Work In Progress				12/9/2008 1:44:35 PM				
Ontiveros, Joe		need to order new water heater for nurses portable # 5							
Eric Medina									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

40741					12/10/2008		62		\$0.00
Medium	Work In Progress				12/10/2008 11:12:20				
Medina, Eric	About 8 of the exhaust fans in the restrooms or the custodial closets have not been working for a while.		12/16 - Asp Mike route to Eric.						

Robert Gonzalez

40744					12/10/2008		62		\$0.00
Medium	Work In Progress				12/10/2008 11:20:18				
Medina, Eric	The floors in the boys and girls locker rooms need painting . They look very bad. Mike painted them about five years ago.								

Robert Gonzalez

40837		Cafeteria			12/12/2008		60		\$0.00
Medium	Work In Progress				12/12/2008 3:24:23 PM				
Orozco, Danny	DRYER NOT DRYING PROPERLY - TAKES AT LEAST 3 TO 4 CYCLES TO DRY								
	SANDRA DIAZ - SNP MANAGER 824-4376								

Alma Terrell

41070					1/4/2009	1/25/2009	37		\$0.00
Medium	Work In Progress				1/4/2009 12:18:49 AM				
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								

Margret Villalobos

41229					1/7/2009		34		\$0.00
Medium	Work In Progress				1/7/2009 9:19:22 AM				
Solis, Lorenzo	need to replace water fountain in main hallway near 200 entrance								

Eric Medina

41253	Main Building	Classroom			1/7/2009		34		\$0.00
Medium	Work In Progress	Room 303, 406,			1/7/2009 3:55:06 PM				
Lozoya, Manny	***URGENT THIRD REQUEST*** NEED KEYS FOR THEIR FILING CABINET HAVE VERY PRIVATE SPED INFO THAT NEEDS TO BE LOCKED UP								

Elena Palacios

41563					1/16/2009		25		\$0.00
Medium	Work In Progress				1/16/2009 9:16:01 AM				
Ronquillo, Ruben	ruben i need you to order metal clips for maps in the class room please								

Eric Medina

41651		Classroom			1/20/2009		21		\$0.00
Medium	Work In Progress	ROOM 203			1/20/2009 2:34:58 PM				
Lozoya, Manny	DRAWERS IN HOME EC ROOM DO NOT OPEN NEED TO HAVE THE KEY LOCKS REMOVED								

Elena Palacios

2/10/2009 3:17:25 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

41653					1/20/2009		21		\$0.00
Medium	Work In Progress				1/20/2009 2:56:17 PM				
Lozoya, Manny	manny need to fix loose door handle in portable 14 and straightend the door for room 312								
Eric Medina									
41877					1/27/2009		14		\$0.00
Medium	Work In Progress	OUTSIDE AND			1/27/2009 9:57:18 AM				
Orozco, Danny	NEED FOR DIMAR TO COME AND CK LEAKING SPRINKLER HEAD.								
Eric Medina									
41954					1/28/2009		13		\$0.00
Medium	Work In Progress				1/28/2009 3:14:33 PM				
Estrada, Jesus	NEED CARPET REPLACED IN BAND ROOM.				1/28/09 - FAXED TO MICHAEL @ AZTEC				
Jesus Estrada									
41979					1/29/2009		12		\$0.00
Medium	Work In Progress				1/29/2009 8:16:06 AM				
Gonzalez, Salvador	new tables for outside canopies need to be installed and assemble.eric will support.								
Michael Munoz									
41980					1/29/2009		12		\$0.00
Medium	Work In Progress				1/29/2009 8:17:34 AM				
Medina, Eric	please order and replace all window screens that are damaged. thxs								
Michael Munoz									
42032					1/30/2009		11		\$0.00
Medium	Work In Progress				1/30/2009 3:03:37 PM				
Ontiveros, Joe	joe i need you to look at the toilet in the womens faculty rr								
Eric Medina									
42073					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:34 AM				
Medina, Eric	Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
42074					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:34 AM				
Medina, Eric	Monthly - Chapparral MS Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									

2/10/2009 3:17:25 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

42075					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:35 AM					
Medina, Eric	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42076					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:35 AM					
Medina, Eric	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42077					2/1/2009	3/4/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:35 AM					
Medina, Eric	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
42122					2/1/2009		9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:51 AM					
Jacquez, Ricardo	Monthly - Chaparral MS - DP-781 - Refer to PM schedule details.								
Margret Villalobos									
42142					2/2/2009		8		\$0.00
Medium	Work In Progress			2/2/2009 9:50:09 AM					
Lozoya, Manny	I NEED TWO XX2 KEYS ONE FOR CARMEN THE CUSTODIAN THAT CLEANS THAT ROOM 405A AND ONE FOR MYSELF. I LOAN MINE TO THE COMPUTOR TECH THATS IN THAT ROOM								
Robert Gonzalez									
42155					2/2/2009		8		\$0.00
Medium	Work In Progress			2/2/2009 3:41:16 PM					
Medina, Eric	need to retexture walls, replace frp board, and paint boys locker room in 200 hallway								
Eric Medina									
42177		Cafeteria			2/3/2009		7		\$0.00
Medium	Work In Progress			2/3/2009 9:36:00 AM					
Orozco, Danny	Milk Unit is running very warm (at 60 degrees) call was received on Monday morning at 10:09 am								
	Glenda Gore - SNP Asst. Manager 824-4376								
Alma Terrell									
42249					2/4/2009		6		\$0.00
Medium	Work In Progress			2/4/2009 4:04:26 PM					
Solis, Lorenzo	lorenzo i need you to come check out the boiler it is not working								
Eric Medina									

2/10/2009 3:17:25 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

42314					2/6/2009		4		\$0.00
Medium	Work In Progress			2/6/2009 10:20:05 AM					
Medina, Eric	need to replace floor tiles in portable 6. kids glogged toilet and let run overnight soaking floor tile and lifting tiles, (two boxes of tiles)		2/10 - Emailed Eric, need to submit tile sample and order thru material request form. Keep this work order and fill out once it is complete.						
Eric Medina									

42320		Cafeteria			2/6/2009		4		\$0.00
Medium	Work In Progress			2/6/2009 11:05:24 AM					
Orozco, Danny	FIX OR INSTALL BELL (DELIVERY DOOR)		DEMETRIOS P. GIOVAS - SNP DIRECTOR 882-6771						
Alma Terrell									

Count: 45 Work Orders	Avg. Age of WO's	75	Total for Chaparral MS	0	\$0.00				
------------------------------	-------------------------	-----------	-------------------------------	----------	---------------	--	--	--	--

Location: Desert Pride

35839	Storage A	Mechanical Room			7/10/2008		215		\$0.00
Medium	Work In Progress			7/10/2008 12:44:57 PM					
Castillo, Carlos	NEED TO MOVE RECEPTACLES LOWER OR INSTALL NEW ONE TO STORAGE ROOM TO PUMP HOUSE (WILL BE USING AS CUSTODIAL OFFICE)								
David Acosta									

36027					7/17/2008		208		\$0.00
Medium	Work In Progress	MORGAN BLDG.		7/17/2008 11:08:09 AM					
Castillo, Carlos	NEED POWER TO RUN HEATING/COOLING & OUTLETS IN MORGAN BLDG.								
David Acosta									

36451		Classroom			8/1/2008		193		\$0.00
Medium	Work In Progress	14,15		8/1/2008 7:22:52 AM					
Castillo, Carlos	EMER. LIGHT DO NOT TURN ON IN BOTH ROOMS WHEN TURNING OFF BREAKER SWITCH FOR TESTING.								
David Acosta									

36452		Library			8/1/2008		193		\$0.00
Medium	Work In Progress			8/1/2008 7:26:27 AM					
Castillo, Carlos	EMER LIGHT WON'T STAY ON VERY LONG WHEN DOING ANNUAL TEST.								
David Acosta									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Pride							
37699		Classroom			9/2/2008		161		\$0.00
Medium	Work In Progress	1,2			9/2/2008 2:08:10 PM				
Castillo, Carlos		NEED MORE EMERG. EXIT SIGNS. (ASK BY STATE FIREMARSHAL TO REQUEST).							
David Acosta									
37701		Portables			9/2/2008		161		\$0.00
Medium	Work In Progress	ROOM #16			9/2/2008 2:13:46 PM				
Castillo, Carlos		NEED SECURITY NITE LIGHT FOR LAST PORTABLE.							
David Acosta									
38592		Hallway/Corridor			10/1/2008		132		\$0.00
Medium	Work In Progress	2ND BLDG.			10/1/2008 11:52:55 AM				
Castillo, Carlos		NEED TO INSTALL RECEPTACLE FOR CANDY MACH. WALL AS NO RECEPTACLE							
David Acosta									
39333		Portables			10/21/2008		112		\$0.00
Medium	Work In Progress	16			10/21/2008 11:07:07				
Castillo, Carlos		NEED EXIT SIGN AND EMER. LIGHT FOR LAST PORTABLE (ROOM 16).							
David Acosta									
39845					11/5/2008		97		\$0.00
Medium	Work In Progress				11/5/2008 8:44:00 AM				
Apodaca, Mario		Need to dispose of skunk							
David Acosta									
40669		Portables			12/8/2008		64		\$0.00
Medium	Work In Progress	room 1			12/8/2008 11:46:00 AM				
Estrada, Jesus		ATT: MIKE MUNOZ-ROOM 1 (PORTABLE) NEEDS TO REPLACE SOME FLOOR TILE BUT MAY NEED TO REPLACE A SECTION OF FLOOR BY DOOR ENTRANCE.				1/12/09 - PENDING AS PER CHUY			
David Acosta									
41209					1/6/2009		35		\$0.00
Medium	Work In Progress				1/6/2009 3:43:53 PM				
Gonzalez, Salvador		please install ballards on the sidewalk from the 3rd bldg to the barrack.please see mike.thxs							
Michael Munoz									
42061					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:30 AM				
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Pride

42062					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:30 AM				

Acosta, David Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

42063					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:30 AM				

Acosta, David Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

42224		Portables			2/4/2009		6		\$0.00
Medium	Work In Progress	6			2/4/2009 11:22:54 AM				

Castillo, Carlos BALLAST TO LIGHT FIXTURE NEEDS TO BE REPLACES

David Acosta

Count: 15 Work Orders			Avg. Age of WO's 107				Total for Desert Pride	0	\$0.00
------------------------------	--	--	-----------------------------	--	--	--	-------------------------------	----------	---------------

Location: Desert Trail Intermediate

35698					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:07 AM				

Villalobos, David Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

35728					7/7/2008		218		\$0.00
Medium	Work In Progress				7/7/2008 9:25:36 AM				

Lozoya, Manny Please change core to doorknob in maintenance office to A-32.

Johnny Acuna

35816					7/10/2008		215		\$0.00
Medium	Work In Progress				7/10/2008 7:55:15 AM				

Ronquillo, Ruben Need an awning installed outdoors on top of the back door to the library. When it rains, water comes through the door wetting the new carpet.

Johnny Acuna

36381					7/30/2008		195		\$0.00
Medium	Work In Progress				7/30/2008 9:32:01 PM				

Ontiveros, Guadalupe Springkler system is down on the westside, it has been uncovered for a couple of weeks. Please advise as to covering the system or will it be fixed before August 1, 2008.
School starts on the 4th.

Ruben Ortiz

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Trail Intermediate

36822					8/8/2008		186		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress			8/8/2008 9:41:58 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lozoya, Manny Need 3 key cores to be installed in the new mulliums for the doors.

Johnny Acuna

36823					8/8/2008		186		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress			8/8/2008 9:43:14 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lozoya, Manny Need a lock installed in the new filing cabinet to room #398.
Mr. Varela.

Johnny Acuna

36887					8/11/2008		183		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	110		8/11/2008 11:51:39 AM					
--------	------------------	-----	--	-----------------------	--	--	--	--	--

Lozoya, Manny Marisela front office receptionist needs replacement of lost key for room #110 (J66) and also need one extra (J2) key.

Elizabeth Hernandez

37007	Main Building	Classroom			8/13/2008		181		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/13/2008 11:46:28 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lozoya, Manny Room 109 no se puede habrir. ---- J master esta doblada--- room 403 necesita llave---- banos 411 necesitan cambiar chapas---- puertas principales se atora la llave- GRACIAS

Marisela Torres

37034					8/13/2008		181		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/13/2008 3:46:59 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny Portable #408 Mr. West is having trouble unlocking door knob
key cylinder. Please send me some Graffite.

Johnny Acuna

37281	Main Building	Classroom			8/21/2008		173		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/21/2008 9:34:34 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny Room # 409 la puerta tiene una parte quebrada y no se puede cerrar. Gracias.

Marisela Torres

37286	Main Building	Office			8/21/2008		173		\$0.00
-------	---------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/21/2008 11:32:48 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lozoya, Manny Escritorio de enfermeria necesita candado de seguridad.Gracias.

Marisela Torres

38213					9/18/2008		145		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/18/2008 12:09:20 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Gonzalez, Salvador Please weld extra metal to the top of the metal scraper to add on a little more weight to it. Thank You....

Johnny Acuna

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail Intermediate									
38277	Main Building	Computer Lab			9/22/2008		141		\$0.00
Medium	Work In Progress				9/22/2008 8:00:19 AM				
Sotelo, Enrique Lorenzo Solis Provide electrical supply to 5 ton unit, cooling only.									
38780					10/5/2008	10/26/2008	128		\$0.00
Medium	Work In Progress				10/5/2008 12:24:03 AM				
Orozco, Danny Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.									
Margret Villalobos									
39012					10/7/2008		126		\$0.00
Medium	Work In Progress				10/7/2008 3:30:52 PM				
Lozoya, Manny Need a replacement Door and Door Frame for Portable #413 inside Restroom Door.									
Johnny Acuna									
39014					10/7/2008		126		\$0.00
Medium	Work In Progress				10/7/2008 3:33:24 PM				
Lozoya, Manny Portable #410: Need a Replacement Metal Door.									
Johnny Acuna									
39122					10/10/2008		123		\$0.00
Medium	Work In Progress				10/10/2008 4:10:15 PM				
Ontiveros, Guadalupe (Irrigation water pressure tank: Chaparral Elementary) Water leak next to the water pressure tank area.									
Johnny Acuna									
39413					10/23/2008		110		\$0.00
Medium	Work In Progress				10/23/2008 12:20:38				
Ronquillo, Ruben Asp PM 38534 Exhaust Fan, need to replace motor on the following: FED-001, FED-003, FED-017, FED-019, FED-023, FED-036. FED-039, FED-049, FED-077.									
Johnny Acuna									
39677					10/31/2008		102		\$0.00
Medium	Work In Progress				10/31/2008 4:09:15 PM				
Gonzalez, Salvador Need to re-weld stainless sheetmetal sheet together that came apart in the kitchen sink area.									
Johnny Acuna									
39759		Athletic Field			11/3/2008		99		\$0.00
Medium	Work In Progress				11/3/2008 7:38:23 AM				
Acuna, Johnny Basketball Courts in the outdoor playground are badly cracked and separating. Asp Mike, route back to Johnny, to order joint and filler thru Maint. Warehouse. 11/5/08									
Johnny Acuna									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
39760					11/3/2008		99		\$0.00
Medium	Work In Progress			11/3/2008 7:40:41 AM					
Ronquillo, Ruben	Window frames in the side of the main doors in the NW hall needs to be replaced or repaired. There is too much corrosion.								
Johnny Acuna									
41071					1/4/2009	1/25/2009	37		\$0.00
Medium	Work In Progress			1/4/2009 12:18:50 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
41192					1/6/2009		35		\$0.00
Medium	Work In Progress			1/6/2009 12:08:50 PM					
Lozoya, Manny	Room #117: need assistance in adjusting door frame and door.								
Johnny Acuna									
41193					1/6/2009		35		\$0.00
Medium	Work In Progress			1/6/2009 12:10:21 PM					
Lozoya, Manny	Portable #412: Door knob is very loose and teacher has problems opening door.								
Johnny Acuna									
41199	Main Building	Classroom			1/6/2009		35		\$0.00
Medium	Work In Progress			1/6/2009 2:18:47 PM					
Lozoya, Manny	Urgente. Cuarto 410 la chapa se quebro, y no se puede cerrar. gracias								
Marisela Torres									
41345					1/11/2009	1/27/2009	30		\$0.00
Medium	Work In Progress			1/11/2009 12:17:19 AM					
Torres, Marisela	Monthly - QRTLY BLDG INSP REPORTS (DT) - Refer to PM schedule details.								
Jesus Estrada									
41414					1/12/2009		29		\$0.00
Medium	Work In Progress			1/12/2009 4:08:44 PM					
Lozoya, Manny	Portable #403: (Mrs. Rios): Need to install a new door knob to Portable #403. Has been repaired several times. Door knob gets stuck and the teacher and student's sometimes cannot come out of the classroom. It's the only door to their classroom. (Safety Issue in case of an Emergency).								
Johnny Acuna									
41494					1/14/2009		27		\$0.00
Medium	Work In Progress			1/14/2009 1:33:10 PM					
Ontiveros, Guadalupe	(Need Assistance): Need tractor to dig up 6'ft. in all directions around 2 sets of swings in the playground area and fill in with playground sand. Thank You.....								
Johnny Acuna									
2/10/2009 3:17:25 PM									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail Intermediate

41496					1/14/2009		27		\$0.00
Medium	Work In Progress				1/14/2009 1:45:26 PM				
Lozoya, Manny		Need an oval lock for filing cabinet to the nurse's office. (Student Records).							
Johnny Acuna									
41594		Cafeteria			1/16/2009		25		\$0.00
Medium	Work In Progress				1/16/2009 11:58:05 AM				
Orozco, Danny		Plastic Handle fell off to Sprayer in Dishwashing Area							
Pat Cisneros - SNP Manager 824-3822									
Alma Terrell									
41789	Main Building	Custodial			1/23/2009		18		\$0.00
Medium	Work In Progress				1/23/2009 11:07:35 AM				
Carbajal, Jimmy		Aspiradora # 0214 esta quebrada . Gracias							
Marisela Torres									
41790	Main Building	Custodial			1/23/2009		18		\$0.00
Medium	Work In Progress				1/23/2009 11:10:22 AM				
Carbajal, Jimmy		Podria prestarme el extractor de 2 galones?. Gracias.							
Marisela Torres									
41976	Main Building	Custodial			1/29/2009		12		\$0.00
Medium	Work In Progress				1/29/2009 8:04:06 AM				
		Aspiradora#105B00000255 no detiene la bolsa y hace mucho ruido, Gracias							
Marisela Torres									
41985					1/29/2009		12		\$0.00
Medium	Work In Progress				1/29/2009 10:16:23 AM				
Gonzalez, Salvador		Please re-weld stainless steel sink that came apart in the left corner of the sink tub. (kitchen) (South sink)							
Johnny Acuna									
41986					1/29/2009		12		\$0.00
Medium	Work In Progress				1/29/2009 10:21:43 AM				
Gonzalez, Salvador		Please re-weld hood vent cover to exhaust fans inside the kitchen. (Hood System)							
Johnny Acuna									
42029	Main Building	Hallway/Corridor			1/30/2009		11		\$0.00
Medium	Work In Progress				1/30/2009 1:01:18 PM				
Lozoya, Manny		Puerta principal (pasillo kinder) esta caida,							
Marisela Torres									
42087					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:39 AM				
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

2/10/2009 3:17:25 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Trail Intermediate

42088					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:39 AM				
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
42089					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:40 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
42144					2/2/2009		8		\$0.00
Medium	Work In Progress				2/2/2009 12:12:43 PM				
Gonzales, Angel		Please repair Echo Blower. (Desert Trail) Got sent over to Auto shop by Memo on Payday. (1/30/09)							
Johnny Acuna									
42341					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress				2/8/2009 12:19:28 AM				
Acuna, Johnny		Monthly - Desert Trail Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
Count: 41 Work Orders		Avg. Age of WO's 90				Total for Desert Trail Intermediate	0		\$0.00

Location: Desert View ES

35699					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:07 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
35961		Cafeteria			7/15/2008		210		\$0.00
Medium	Work In Progress				7/15/2008 7:33:37 AM				
Moncayo, Fernando		MILK COOLER IS NOT WORKING AT ALL. DIANA LAZARIN SNP MGR 589-2425							
Jacqueline Aguilar									
36939	Main Building				8/12/2008		182		\$0.00
Medium	Work In Progress				8/12/2008 8:37:50 AM				
Ortiz, Ruben		Tested exit signs (4) are not working 2 in Gym and Cafeteria asp PM 36526.				Need to order thru material request and complete wo once they are replaced.			
Ruben Ortiz									
37634					8/31/2008		163		\$0.00
Medium	Work In Progress				8/31/2008 12:25:41 AM				
Aguilar, Patricio		Monthly - Desert View ES A-2 Quarterly H/C IREH - Refer to PM schedule details.							
Margret Villalobos									
2/10/2009 3:17:25 PM									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

38108					9/15/2008		148		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/15/2008 7:13:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Requesting for plumber to check if two water faucets can be installed for cleaning purposes

Ruben Ortiz

39053					10/8/2008		125		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/8/2008 5:07:00 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David To Mike Munoz
 I was asked by Mr. Carrasco that he needs hot water and more water pressure for the shower in the Special Ed room. There is a child that needs to be bathed often and the water is too cold. He asked for an urgent work order.
 Mr. Carrasco asked for this work order to be sent directly to you because he wants it ASAP 10/08/08. Child is being bathed in cold water. Thank you.

Ruben Ortiz

39404					10/22/2008		111		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/22/2008 9:10:57 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Carlos Castillo
 The button for the handicap door is not working on the southside of the building exit.

Ruben Ortiz

40528		Gym			12/3/2008		69		\$0.00
-------	--	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/3/2008 12:28:54 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Briones, Enrique This work order is for warehouse we need from you guys to come for some furniture and some chairs because the principal wants the gym all clear for the spelling b next week and for christmas dance. THANK YOU IN ADVANCED.

Hector Rivera

40871		Cafeteria			12/15/2008		57		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/15/2008 2:35:04 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando AS PER DIMAR SYSTEM, RANGE HOOD SYSTEMS REPORT DATED 12/15/08, EXHAUST FAN IS NOT OPERATING.

DIANA LAZARIN SNP MGR 589-2425

Jacqueline Aguilar

41185					1/5/2009		36		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/5/2009 9:21:52 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David leaking valves in the pump room, need plumber.
 Thank you, Ruben

Ruben Ortiz

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert View ES

41886		Portables			1/27/2009		14		\$0.00
Medium	Work In Progress			1/27/2009 12:55:42 PM					
Ortiz, Ruben	please cut branches to tree that are against the portable the hvac unit. portable # 8		thxs						
Michael Munoz									
41887					1/27/2009		14		\$0.00
Medium	Work In Progress			1/27/2009 12:56:50 PM					
Lara, Ralph	please replace exterior door to rm 25.		thxs						
Michael Munoz									
41888					1/27/2009		14		\$0.00
Medium	Work In Progress			1/27/2009 12:58:48 PM					
Ortiz, Ruben	please schedule the aerator order seed and fertilizer for the areas on campus that do no have grass in the circle.		thxs						
Michael Munoz									
41890		Portables			1/27/2009		14		\$0.00
Medium	Work In Progress			1/27/2009 1:04:21 PM					
Ortiz, Ruben	please cut tree branches that against portable and unit as per our conversation.		thxs						
Michael Munoz									
41921					1/28/2009		13		\$0.00
Medium	Work In Progress			1/28/2009 6:49:22 AM					
Moncayo, Fernando	Ladies in cafeteria need a lock for their file cabinet. Hinges on the walk in refrigerator are broken having trouble locking it. Thank you.								
Ruben Ortiz									
41975					1/28/2009		13		\$0.00
Medium	Work In Progress			1/28/2009 8:34:35 PM					
Carrasco, Danny	Requesting a small chainsaw to cut thick branches and a pull saw for pruning. Thank you.								
Ruben Ortiz									
42123					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:52 AM					
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42124					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:52 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									

2/10/2009 3:17:25 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

42125					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:52 AM				

Ortiz, Ruben Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

42165					2/2/2009		8		\$0.00
Medium	Work In Progress				2/2/2009 9:33:14 PM				

Lara, Ralph Need a door replaced in room 25; 2 inches from the bottom of the door is rusted through; the replacement has been request by Principal Carrasco. Thank you, Ruben

Ruben Ortiz

42230		Portables			2/4/2009		6		\$0.00
Medium	Work In Progress				2/4/2009 2:49:07 PM				

Gonzalez, Salvador Need to install ramps to portable (see Mike).

Michael Munoz

42298					2/5/2009		5		\$0.00
Medium	Work In Progress				2/5/2009 8:59:12 PM				

Gonzalez, Salvador Need parking poles welded back up, have been a tripping hazard. Thank you, Ruben

Ruben Ortiz

42342					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress				2/8/2009 12:19:28 AM				

Ortiz, Ruben Monthly - Desert View ES Playground Insp - Refer to PM schedule details.

Margret Villalobos

Count: 23 Work Orders		Avg. Age of WO's 63				Total for Desert View ES	0		\$0.00
------------------------------	--	----------------------------	--	--	--	---------------------------------	----------	--	---------------

Location: GAC

35700					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:07 AM				

Villalobos, David Yearly - GAC Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

35802	RTC	Office			7/9/2008		216		\$0.00
Medium	Work In Progress	RTC ACROSS			7/9/2008 3:07:58 PM				

Ambriz, Jose AS PER GLORIA SAENZ-NEED TO HAVE THE AIR CONDITIONER UNIT CHECKED. SETTINGS ARE NOT WORKING PROPERLY.

Mary Garcia

36280					7/28/2008		197		\$0.00
Medium	Work In Progress	Back bottom road			7/28/2008 12:11:48 PM				

Ontiveros, Guadalupe need to apply dirt and crusherfine in back road due to running water after haevy rain.

Juan Ambriz

2/10/2009 3:17:25 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

36281		Hallway/Corridor			7/28/2008		197		\$0.00
-------	--	------------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	C-Wing A/C unit			7/28/2008 12:13:33 PM				
--------	------------------	-----------------	--	--	-----------------------	--	--	--	--

Ambriz, Jose
Need to raplace relays in C-Wing unit not working properly

Juan Ambriz

36334		Parking Lot			7/29/2008		196		\$0.00
-------	--	-------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	bottom dirt			7/29/2008 3:47:57 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
Need to apply more crusherfine in bottom dirt parking lot accumulating water after rain

Juan Ambriz

36360					7/30/2008		195		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/30/2008 3:14:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Need to order new emergency lights for the server room not working total of two

Juan Ambriz

36949		Office			8/12/2008		182		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	A-WING			8/12/2008 10:35:44 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Ambriz, Juan
IF IT WOULD BE POSSIBLE TO HAVE THE AIR VENTS IN JESUS REYE'S OFFICE ADJUSTED. NOT ENOUGH AIR COMES THROUGH.

Mary Garcia

37189		Office			8/19/2008		175		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	B-WING			8/19/2008 10:23:04 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Castillo, Carlos
AS PER ANNE- IN LUDYM'S OFFICE (NEW FINANCE DIRECTOR) ONE OF THE FLUORESCENT LIGHT FIXTURES DOES NOT HAVE A COVERING AND NEEDS ONE PLEASE.

Mary Garcia

37828		Office			9/5/2008		158		\$0.00
-------	--	--------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	B-WING			9/5/2008 11:13:08 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan
AS PER MS. BROWDER-WOULD LIKE TO HAVE HER WHOLE OFFICE PAINTED. IF IT WOULD BE POSSIBLE FOR THE DATES OF 9/16 OR 9/17TH, BEFORE FURNITURE COMES IN ON 9/18/08.
APPROVED BY MR. RICHARD G. CHAVEZ.
AS PER JUAN, HE HAS ENOUGH PAINT.

Mary Garcia

37912		Parking Lot			9/8/2008		155		\$0.00
-------	--	-------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	bottom dirt			9/8/2008 3:39:17 PM				
--------	------------------	-------------	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe
Need to level bottom parking lot with crusher fine to avoid accumulated water after rains

Juan Ambriz

37939					9/9/2008		154		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress	Back dirt road			9/9/2008 8:25:56 AM				
--------	------------------	----------------	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe
need to add dirt to back dirt road due to running water after rains. If possible add crusher fine.

Juan Ambriz

2/10/2009 3:17:25 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

37978		Office			9/9/2008		154		\$0.00
Medium	Work In Progress	A-WING			9/9/2008 4:42:49 PM				
Castillo, Carlos		AS PER ELISA-NEED AN ELECTRICAL OUTLET TO BE INSTALLED IN THE SUPT. CONFERENCE CLOSET.							
Mary Garcia									
37984		Office			9/10/2008		153		\$0.00
Medium	Work In Progress	C-WING			9/10/2008 10:29:18 AM				
Ambriz, Juan		AS PER MS. PHILLIPS-NEED TO HAVE A TV & DVD PLAYER STRAPPED DOWN TO THE CART THAT WAS PURCHASED.							
Mary Garcia									
38646					10/2/2008		131		\$0.00
Medium	Work In Progress				10/2/2008 2:30:47 PM				
Castillo, Carlos		Asp PM 37606, still waiting on Emerg. Light for Board Rm and Sever Rm not working.							
Juan Ambriz									
38781					10/5/2008	10/26/2008	128		\$0.00
Medium	Work In Progress				10/5/2008 12:24:03 AM				
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
39366		Office			10/22/2008		111		\$0.00
Medium	Work In Progress	C-WING			10/22/2008 9:54:03 AM				
Ambriz, Juan		AS PER ALFREDO-GO AHEAD AND SEAL OFF THE WALL WHERE THE AIR UNIT WAS IN OFELIA'S OFFICE.				APPROVED BY ALFREDO			
Mary Garcia									
40020		Cafeteria			11/12/2008		90		\$0.00
Medium	Work In Progress				11/12/2008 9:26:48 AM				
Moncayo, Fernando		DELI UNIT IS NOT WORKING - COOLING							
		GESSICA BLAZQUEZ - SNP MANAGER 882-6784							
Alma Terrell									
40223		Office			11/19/2008		83		\$0.00
Medium	Work In Progress	B-WING			11/19/2008 2:24:32 PM				
Villalobos, David		AS PER MR. CHAVEZ-NEED TO HAVE THE PLUMBER COME IN AND CHECK OUT THE SINK BEHIND RECEPTIONIST AREA IN B WING, OVER WITH VANESSA. THERE IS A REAL BAD SEWER SMELL.				JUAN HAS ALREADY TAKEN A LOOK AT THIS AND SMELL STILL CONTINUES.			
Mary Garcia									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	GAC
------------------	------------

40275		Office			11/20/2008		82		\$0.00
-------	--	--------	--	--	------------	--	----	--	--------

Medium	Work In Progress	A-WING			11/20/2008 3:59:32 PM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Carrasco, Danny		AS PER JULIE & ANN-NEED TO BORROW A PORTABLE HEATER FOR FIRST THING TOMORROW MORNING. (APPROVED BY MR. RICHARD G. CHAVEZ)							
-----------------	--	---	--	--	--	--	--	--	--

Mary Garcia

40591		Office			12/4/2008		68		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-WING			12/4/2008 3:04:50 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan		AS PER MS. YTURRALDE-NEED TO HAVE HOLES IN WALL FILLED.							
--------------	--	---	--	--	--	--	--	--	--

Mary Garcia

40605	RTC	Office			12/4/2008		68		\$0.00
-------	-----	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	RTC ACROSS			12/4/2008 5:01:11 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Ambriz, Juan		AS PER GLORIA SAENZ-NEED TO FIX DOOR STOPPER							
--------------	--	--	--	--	--	--	--	--	--

Mary Garcia

40674	RTC	Parking Lot			12/8/2008		64		\$0.00
-------	-----	-------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	RTC ACROSS			12/8/2008 2:30:07 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		AS PER GLORIA SAENZ-NEED TO HAVE THE DIRT REMOVED FROM THE PARKING LOT.							
----------------------	--	---	--	--	--	--	--	--	--

Mary Garcia

40806		Parking Lot			12/11/2008		61		\$0.00
-------	--	-------------	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/11/2008 2:43:32 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Michael		Pour concret pad for trash dumpsters							
----------------	--	--------------------------------------	--	--	--	--	--	--	--

Alfredo Holguin

40892	RTC	Office			12/16/2008		56		\$0.00
-------	-----	--------	--	--	------------	--	----	--	--------

Medium	Work In Progress	RTC ACROSS			12/16/2008 9:19:21 AM				
--------	------------------	------------	--	--	-----------------------	--	--	--	--

Ambriz, Juan		AS PER GLORIA-DOOR LOCKS ARE FULL OF DIRT AND WILL NOT TURN THE KEY TO OPEN OR CLOSE				JUAN IS ALREADY LOOKING INTO THIS			
--------------	--	--	--	--	--	-----------------------------------	--	--	--

Mary Garcia

40994		Cafeteria			12/18/2008		54		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/18/2008 3:50:21 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose		AS PER OUR CONVERSATION (MIKE MUNOZ) ON 12/18/08 PLEASE ORDER BUTTERFLY VENTS FOR DINING ROOM AND KITCHEN				1/6/09 - Route to Jose asp Mike.			
--------------	--	---	--	--	--	----------------------------------	--	--	--

		SNP 882-6772							
--	--	--------------	--	--	--	--	--	--	--

Alma Terrell

41072					1/4/2009	1/25/2009	37		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/4/2009 12:18:50 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

2/10/2009 3:17:26 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									
Location: GAC									
41187		Office			1/6/2009		35		\$0.00
Medium	Work In Progress	C-WING		1/6/2009 9:53:19 AM					
Ambriz, Juan		AS PER MS. SHIELA RAIHL-FLOOR TILE IS LIFTING UP AND THE SHOES ARE GETTING STUCK ON THE TILE, NEEDS TO BE REPLACED OR REPAIRED.							
Mary Garcia									
41203		Hallway/Corridor			1/6/2009		35		\$0.00
Medium	Work In Progress	B-WING		1/6/2009 2:57:15 PM					
Estrada, Jesus		AS PER MR. SUTTMILLER-THE FLOOR TILE ENTERING B-WING NEEDS TO BE REPLACED OR REPAIRED, IT IS LIFTING.							
Mary Garcia									
41471		Hallway/Corridor			1/13/2009		28		\$0.00
Medium	Work In Progress	A-WING SUPT'S		1/13/2009 4:47:38 PM					
Lara, Ralph		AS PER MR. YTURRALDE-NEED TO HAVE THE DOOR LOCK GOING INTO THE SUPT'S HALLWAY CHANGED TO A PAD LOCK COMBINATION OR PUSH BUTTON LOCK. (WHERE IT OPENS THROUGH A ONE WAY ONLY.) SEE MR. YTURRALDE OR MARY GARCIA BEFORE INSTALLING.							
Mary Garcia									
41521	RTC	Portables			1/15/2009		26		\$0.00
Medium	Work In Progress	RTC-ACROSS		1/15/2009 9:40:00 AM					
Ambriz, Juan		AS PER MS. SAENZ-THEY HAVE A BROKEN WINDOW THAT DOES NOT LOCK.				1/26 - Route to Juan asp Ruben			
Mary Garcia									
41571		Office			1/16/2009		25		\$0.00
Medium	Work In Progress	C-WING		1/16/2009 9:58:30 AM					
Ambriz, Juan		AS PER MS. IDA GARCIA-NEED TO HAVE TERESA ALLEN'S OFFICE PAINTED. (SHE HAS BROUGHT HER OWN PAINT, IT IS IN HER OFFICE.)				AS PER MR. CHAVEZ, GO AHEAD AND PAINT THE OFFICE, WHEN EVER YOU HAVE TIME IN BETWEEN YOU WORKING SCHEDULE. REMEMBER NOT A PRIORITY.			
Mary Garcia									
41669		Office			1/20/2009		21		\$0.00
Medium	Work In Progress	C-WING		1/20/2009 3:50:11 PM					
Ambriz, Juan		AS PER DAVID AVILA-LIGHT FIXTURES NEED TO BE CHECKED IN ANN STEINHOFF'S OFFICE. LIGHTS KEEP ON FLICKERING.							
Mary Garcia									
41722					1/22/2009		19		\$0.00
Medium	Work In Progress			1/22/2009 8:46:30 AM					
Castillo, Carlos		IT Room - Remove unused conduit and electrical outlet next to new chiller. Check with Calixo or contractor on specifics.							
Alfredo Holguin									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

41865					1/26/2009		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	OUTSIDE AND			1/26/2009 4:09:18 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Orozco, Danny		AS PER JUAN AMBRIZ-NEED FOR DIMAR TO COME IN AN RECAP A PIPE THAT IS LEAKING WATER. (TO ASK FOR JUAN WHEN DIMAR COMES IN)				DAVID VILLALOBOS ALREADY LOOKING INTO THIS SITUATION AND SUGGESTED FOR JUAN TO PUT IN A WORK ORDER FOR DIMAR TO TAKE CARE OF THIS.			
Mary Garcia									

41897		Office			1/27/2009		14		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	C-WING			1/27/2009 2:26:47 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan		AS PER ANN STEINHOFF-OVER IS MS. LUZ AVILA'S OFFICE, NEED TO HAVE SOME FLIPPER DRAWERS AND FILING CABINETS INSTALLED. (IF YOU HAVE ANY QUESTIONS, ASK FOR DAVID AVILA OR MS. STEINHOFF.)							
--------------	--	--	--	--	--	--	--	--	--

Mary Garcia

41937	RTC	Portables			1/28/2009		13		\$0.00
-------	-----	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	RTC ACROSS			1/28/2009 10:42:26 AM				
--------	------------------	------------	--	--	-----------------------	--	--	--	--

Ambriz, Juan		AS PER GLORIA SAENZ-KEYS UNABLE TO OPEN CLASSROOM-MS. MORALES, MAYBE DUE TO DUST.							
--------------	--	---	--	--	--	--	--	--	--

Mary Garcia

42097					2/1/2009	2/9/2009	9		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/1/2009 12:24:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Juan		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

42098					2/1/2009	2/7/2009	9		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/1/2009 12:24:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Juan		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

42099					2/1/2009	2/9/2009	9		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/1/2009 12:24:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Juan		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

42174		Office			2/3/2009		7		\$0.00
-------	--	--------	--	--	----------	--	---	--	--------

Medium	Work In Progress	C-WING			2/3/2009 8:48:11 AM				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Ambriz, Juan		AS PER MS. FERNANDEZ-NEED TO HAVE A MIRROR HUNG IN HER OFFICE AND AN EXTRA SCREW/BOLT FOR A FILING CABINET THAT'S FALLING APART.							
--------------	--	--	--	--	--	--	--	--	--

Mary Garcia

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: GAC

42278					2/5/2009		5		\$0.00
Medium	Work In Progress				2/5/2009 2:35:12 PM				
Ambriz, Juan	Please pick up the 55 gallon drum with diesel (it's about ½ or less full), two electrical boxes and the old generator vibration isolators and bring them here to PPD.								

Alfredo Holguin

42343					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress				2/8/2009 12:19:29 AM				
Ambriz, Juan	Monthly - GAC Playground Insp - Refer to PM schedule details.								

Margret Villalobos

42412		Office			2/10/2009		0		\$0.00
Medium	Work In Progress	C-WING			2/10/2009 10:58:46 AM				
Lara, Ralph	AS PE MS. IDA GARCIA-NEED TO HAVE KEYS MADE TO OPEN TERESA ALLEN'S DESK DRAWER. (NO KEYS)								

Mary Garcia

42414	Pre-K	Cafeteria			2/10/2009		0		\$0.00
Medium	Work In Progress	PRE-K			2/10/2009 11:21:26 AM				
Ambriz, Juan	AS PER MS. BERRY- NEED HELP W/ 2 WALL HANINGS IN THE CAFETERIA.								

Mary Garcia

Count: 44 Work Orders			Avg. Age of WO's 83				Total for GAC	0	\$0.00
------------------------------	--	--	----------------------------	--	--	--	----------------------	----------	---------------

Location: Gadsden HS

37233	Academic Bldg				8/20/2008		174		\$0.00
Medium	Work In Progress				8/20/2008 2:15:18 PM				
Ambriz, Jose	AT THE ACADEMIC BLDG NEED NEW E/COOLER STANDS								

Mario Apodaca

37234	Cafeteria (1998)				8/20/2008		174		\$0.00
Medium	Work In Progress				8/20/2008 2:17:31 PM				
Ambriz, Jose	AT THE CAFE BLDG NEED NEED NEW E/COOLER STANDS								

Mario Apodaca

35701					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:08 AM				
Villalobos, David	Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.								

Margret Villalobos

2/10/2009 3:17:26 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

35876	Main Building	Office			7/11/2008		214		\$0.00
Medium	Work In Progress				7/11/2008 2:28:45 PM				
Carrasco, Danny		NEED NEW BLINDS FOR PRINCIPAL CHAMBERS OFFICE							
		1. 40" X 5'							
		2. 7' X 5'							

Mario Apodaca

35993	Boys Gym	Office			7/16/2008		209		\$0.00
Medium	Work In Progress				7/16/2008 2:28:31 PM				
Ambriz, Jose		Requested by Coach Lawrence Rm. 401 Office in Boy's Gym-Room 401 does not have any air conditioning, would like to have a unit installed this summer of 2008, to review videos and to watch films for Soccer.							

Velia Alarcon

36000	Library	Library			7/16/2008		209		\$0.00
Medium	Work In Progress				7/16/2008 3:18:40 PM				
Ontiveros, Guadalupe		An irrigation control box has a water leak underneath the asphalt outside the southwest exit.							

Albert Vallejo

36066	North Building	Classroom			7/18/2008		207		\$0.00
Medium	Work In Progress				7/18/2008 3:19:18 PM				
Ronquillo, Ruben		NEED NEW WINDOW BLINDS (35"WX56"L) FOR ROOM 207 NEED 11 EA							

Mario Apodaca

36067	Old English Bldg	Classroom			7/18/2008		207		\$0.00
Medium	Work In Progress				7/18/2008 3:21:06 PM				
Ambriz, Jose		NEED A NEW HEATING CONDESER AT ROOM 141 DO TO VANDALISM							

Mario Apodaca

36186	Cafeteria (1998)	Cafeteria			7/24/2008		201		\$0.00
Medium	Work In Progress				7/24/2008 3:18:50 PM				
Moncayo, Fernando		WALK - IN FREEZER DOWN.							
		GHS SNP 882-5522							

Jacqueline Aguilar

36231					7/25/2008		200		\$0.00
Medium	Work In Progress				7/25/2008 3:04:45 PM				
Ontiveros, Guadalupe		Requested by Coach Hite for Football Field-Football field is very uneven. Please level as it is very dangerous.							

Velia Alarcon

36288	Vocational	Classroom			7/28/2008		197		\$0.00
Medium	Work In Progress	568			7/28/2008 3:08:02 PM				
Carrasco, Danny		Window frames in front of classroom are in bad repair and need to be completely replaced. Large amounts of water get through during rainstorms.							

Albert Vallejo

2/10/2009 3:17:26 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

36310	Cafeteria (1998)	Cafeteria			7/29/2008		196		\$0.00
-------	------------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/29/2008 8:10:33 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando		NEED A SAFETY POWER DISCONNECT TO THE GHS WALK-IN'S (BOTH) ON THE CONDENSER UNITS ON THE ROOF				11/18 - Asp Mike route to Fernie			
-------------------	--	---	--	--	--	----------------------------------	--	--	--

MR. DEMETRIIOUS GIOVAS

Jacqueline Aguilar

36359		Cafeteria			7/30/2008		195		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/30/2008 3:02:54 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando		need to ck the ice maker compressors at the cafe it is tipping the circuit breaker							
-------------------	--	--	--	--	--	--	--	--	--

Mario Apodaca

36622					8/4/2008		190		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress	WWT			8/4/2008 4:10:54 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Sanchez, Raul		Replace motor for Wastewater Treatment Plant Blowers.							
---------------	--	---	--	--	--	--	--	--	--

Raul Sanchez

36878	Boys Gym				8/11/2008		183		\$0.00
-------	----------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/11/2008 8:35:04 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo		new shower column was installed in girls dressing room. need to install tile to complete project. see mike. thxs							
------------------	--	--	--	--	--	--	--	--	--

Michael Munoz

36896	Boys Gym	Gym			8/11/2008		183		\$0.00
-------	----------	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/11/2008 2:55:29 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		NEED A NEW SWITCH FOR THE E/COOER UNIT AT THE BOYS GYM							
------------------	--	--	--	--	--	--	--	--	--

Mario Apodaca

37049	Football Stadium	Football Field			8/14/2008		180		\$0.00
-------	------------------	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/14/2008 8:14:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael		Some of the concrete piers that support the bleachers are cracked and need to be repaired.							
----------------	--	--	--	--	--	--	--	--	--

Albert Vallejo

37094	Cafeteria (1998)	Cafeteria			8/14/2008		180		\$0.00
-------	------------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/14/2008 3:40:19 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		ALL OUTSIDE DUCTS OF THE CAFE BLDG NEED TO BE RESEAL DOTO SUN AND WATER DAMAGE. ASAP							
--------------	--	--	--	--	--	--	--	--	--

Mario Apodaca

37099	Boys Gym	Gym			8/15/2008		179		\$0.00
-------	----------	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/15/2008 7:44:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred		install collars to cover vents and water to showers in boys gym as per mike.							
-------------------	--	--	--	--	--	--	--	--	--

Fred Appelzoller

2/10/2009 3:17:26 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

37143	New Vocational	Hallway/Corridor			8/18/2008		176		\$0.00
Medium	Work In Progress				8/18/2008 2:43:34 PM				

Ronquillo, Ruben
Need window glass replaced, Approximately 24" x 30" in size. (wired glass)

Albert Vallejo

37145					8/18/2008		176		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/18/2008 2:48:35 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador
The chain link fence directly south of the band room has been hit by a vehicle, one post is down and the mesh has been torn

Albert Vallejo

37232	Old English Bldg	Classroom			8/20/2008		174		\$0.00
-------	------------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2008 2:03:04 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Carrasco, Danny
NEED NEW WINDOW MINI BLINDS DOTO VANDALISM (W43 1/2"X L90") NEED #4

Mario Apodaca

37284					8/21/2008		173		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2008 11:13:30 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben
8 SIGNS (24 X 18) THAT READ THE FOLLOWING:

GHS IS A DRUG FREE CAMPUS
NO SMOKING
NO ALCOHOL
NO WEAPONS
NO PETS

Mario Apodaca

37295	Agricultural	Classroom			8/21/2008		173		\$0.00
-------	--------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2008 2:52:32 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred
need a new sink and faucet set put-in at room 569

Mario Apodaca

37299					8/21/2008		173		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2008 2:59:39 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Apodaca, Mario	8-20-08				8/20-8				
----------------	---------	--	--	--	--------	--	--	--	--

6-painting a class room at the a.g bldg room 569
1-t/shoot a/c unit at the n-bldg too room 202
1-in put to school dude

Mario Apodaca

37360	Grounds Shop				8/25/2008		169		\$0.00
-------	--------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/25/2008 12:51:17 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
I need an electrician to disconnect power to burned-out motor at wwtp and assist me in installing a new blower motor. We may need a small crane to lift new motor up to wwtp platform. Thanks, Raul

Raul Sanchez

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

37400					8/26/2008		168		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/26/2008 3:35:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos Requested by Mr. Roberson for Rm. 127 Main Building-
Install on/off switch for lights in room #127. When room
was divided switch was left in room #128.

Velia Alarcon

37431					8/27/2008		167		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/27/2008 8:10:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador NEED TO CONSTRUCT SHADE AT GROUNDS DEPT.
TO PROTECT IMPLEMENT.

Guadalupe Ontiveros

37442					8/27/2008		167		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/27/2008 10:51:46 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Coach Hite for Football Field-Sod bare
areas on Football Field before first home game on
September 12th.

Velia Alarcon

37996	Agricultural	Classroom			9/10/2008		153		\$0.00
-------	--------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/10/2008 3:10:19 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben need new window blinds for room 568.ea 2 (60 1/2"x45")

Mario Apodaca

38074					9/14/2008		149		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/14/2008 12:23:09 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe Monthly - Gadsden HS Soil Sampling - Refer to PM
schedule details.

Margret Villalobos

38165	Cafeteria (1998)	Restroom (Boys)			9/17/2008		146		\$0.00
-------	------------------	-----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/17/2008 8:25:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben a cafe window need to be repairs at the boys restroom
do to vandalism (20"x20")

Mario Apodaca

38286					9/22/2008		141		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/22/2008 10:13:18 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario Requested by Ms. Lam Rm. 104 Main Building-Holder of
the glass door of the south book shelf is broken.

Velia Alarcon

38287					9/22/2008		141		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/22/2008 10:30:07 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David Requested by Ms. Lam Rm. 104 Main Building-Both
cold and hot water of the faucet on the south side have
sulfur smell.

Velia Alarcon

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

38288					9/22/2008		141	1	\$25.00
-------	--	--	--	--	-----------	--	-----	---	---------

Medium	Work In Progress			9/22/2008 10:35:59 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Briones, Enrique	Requested by Coach Hite and Coach Maxey Football Laundry Room-Remove old dryer and metal objects from laundry room. Also, tables and chairs that are broken and stored in there. Remove refrigerator from Football locker room.		11/17/08 Items are on inventory, forwarded to purchasing warehouse for pickup.						
------------------	---	--	--	--	--	--	--	--	--

Velia Alarcon

38292					9/22/2008		141		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/22/2008 10:58:14 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Apodaca, Mario	Requested by Ms. Aguilar Rm. 236 North Building-Replace burned out light bulbs.								
----------------	---	--	--	--	--	--	--	--	--

Velia Alarcon

38296					9/22/2008		141		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/22/2008 11:16:00 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Vallejo, Albert	Requested by Ms. Roth Rm. 213 North Building-Legs are loose on various HEAVY lab tables and need to be tightened and possibly secured. Table tops are not attached to certain tables and also pose a safety hazard and noise maker.								
-----------------	---	--	--	--	--	--	--	--	--

Velia Alarcon

38305					9/22/2008		141		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/22/2008 12:04:36 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Briones, Enrique	Requested by Coach Hite for Football Fieldhouse (Boy's Gym)-Please remove refrigerator, does not work.		11/17/08 Items are on inventory, forwarded to purchasing warehouse for pickup.						
------------------	--	--	--	--	--	--	--	--	--

Velia Alarcon

38429	Academic Bldg	Classroom			9/25/2008		138		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/25/2008 2:39:13 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Carrasco, Danny	need windos blinds (46 3/4" x 62") for the academic bldg need 10								
-----------------	--	--	--	--	--	--	--	--	--

Mario Apodaca

38465					9/26/2008		137		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/26/2008 12:29:32 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lozoya, Manny	Mr. Chacon, Band Director needs a gate key.								
---------------	---	--	--	--	--	--	--	--	--

Michael Munoz

38493					9/29/2008		134		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/29/2008 10:43:07 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ontiveros, Guadalupe	Requested by Coach A. Lopez for Softball Field Varsity Batting Cage-Patio, cement inside of batting cage.								
----------------------	---	--	--	--	--	--	--	--	--

Velia Alarcon

38497					9/29/2008		134		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/29/2008 10:57:19 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Carrasco, Danny	Requested by Julio Alcantar for Student Parking Lot-Need more electrical poles to help mark the parking spaces in the student parking lot.								
-----------------	--	--	--	--	--	--	--	--	--

Velia Alarcon

2/10/2009 3:17:26 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

38538					9/30/2008		133		\$0.00
Medium	Work In Progress			9/30/2008 12:26:03 AM					
Apodaca, Mario	Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
38604					10/1/2008		132		\$0.00
Medium	Work In Progress			10/1/2008 2:02:50 PM					
Ambriz, Jose	Requested by Ms. Hartmann Rm. 568 Classroom between Ag. Shop and Wood Shop-Install an extracting fan to remove fumes coming into room 568, created by Auto and Ag engines. There's currently no way for fumes to exit from classroom. Fumes giving teacher and students headaches.								
Velia Alarcon									
38744					10/5/2008		128		\$0.00
Medium	Work In Progress			10/5/2008 12:23:50 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.		10/6/08 - Emailed to Ricky Borrego						
Margret Villalobos									
38748					10/5/2008	11/5/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:23:51 AM					
Vallejo, Albert	Yearly - Gadsden HS R9 (H.W.Radiator)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
38790					10/5/2008	10/26/2008	99		\$0.00
Medium	Work In Progress			10/5/2008 12:24:06 AM		1/12/2009			
Orozco, Danny	Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38893					10/5/2008	10/13/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:24:44 AM					
Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
38954	Cafeteria (1998)	Cafeteria			10/6/2008		127		\$0.00
Medium	Work In Progress			10/6/2008 10:39:01 AM					
Moncayo, Fernando	ICE MACHINE IS DOWN AGAIN - FERNANDO WAS AT GAC ON 10/3/08, I (ALMA) TOLD HIM OF THE PROBLEM.								
	SARA GARCIA - SNP ASST. MANAGER 882-5522								
Alma Terrell									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

38974	Academic Bldg	Classroom			10/6/2008		127		\$0.00
Medium	Work In Progress				10/6/2008 3:03:50 PM				
Ambriz, Jose	need new e/cooler unit at the academic bldg need 20 e.a								

Mario Apodaca

38997	Main Building				10/7/2008		126		\$0.00
Medium	Work In Progress				10/7/2008 11:33:11 AM				

Munoz, Joe

Requested by Velia for Front Office in Main Building- Since air quality and mold are a concern today. There are several spots in the Front Office that have leaked when it rains and dark spots have started to grow in these areas. Please test areas for mold and clean them. Although this problem won't be resolved until the roof is either repaired or re-roofed. Main Building has several leaks through out the building.

10/7 - Asp Mike, rout to Custodial
FAX W.O. TO JOE
12/03- REFAXED TO JOE
12/17- REFAXED TO JOE.
1/8/09 - REFAXED TO JOE.

Velia Alarcon

39073	Agricultural	Classroom			10/9/2008		124		\$0.00
Medium	Work In Progress				10/9/2008 3:15:51 PM				

Ronquillo, Ruben

need a window blind for room 569 (60"x48")

Mario Apodaca

39300	North Building	Classroom			10/20/2008		113		\$0.00
Medium	Work In Progress				10/20/2008 2:38:24 PM				

Moncayo, Fernando

the deli cart cooer is not working need to be fix ASAP.at room 233 n-bldg.

Mario Apodaca

39506	Academic Bldg				10/27/2008		106		\$0.00
High	Work In Progress				10/27/2008 10:25:31				

Castillo, Carlos

as per mr.chambers, the north end of the outside of the building is lacking lighting. this is a pick-up area and is safety issue.please see if exterior lighting can be placed. presently there is 1 exterior light. would like more lights that would illuminte more.
thxs

Carey Chambers

39621	New Vocational	Classroom			10/30/2008		103		\$0.00
High	Work In Progress				10/30/2008 2:08:48 PM				

Ambriz, Jose

the heating unit at rom 551 has a carbon monoxide of 5ppm need a new heating unit asap

Mario Apodaca

39823	Auto Shop	Classroom			11/4/2008		98		\$0.00
Medium	Work In Progress				11/4/2008 3:05:39 PM				

Lara, Ralph

need 2 new doors at the auto shop the doors are broken do to vandalism

Mario Apodaca

2/10/2009 3:17:26 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

40054	Old English Bldg	Gym			11/13/2008		89		\$0.00
-------	------------------	-----	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2008 3:05:05 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Michael the girls gym need work on the gym floor do to roof leaks . A.S.A.P

Mario Apodaca

40142					11/17/2008		85		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/17/2008 12:26:28				
--------	------------------	--	--	--	---------------------	--	--	--	--

Apodaca, Mario		11-14-08				11/14-8			
----------------	--	----------	--	--	--	---------	--	--	--

1.5-went to the p.p.d for supplies and gas-up
 1.5-ck water boiler unit at bldg
 2-t/shoot heating unit at the n-bldg at the annex bldg
 1-fix a door lever set at the academic bldg to room 331
 1-went to put new traps at camp lab
 1-ck the electrical heater unit at the main bldg

Mario Apodaca

40182	Auto Shop	Classroom			11/18/2008		84		\$0.00
-------	-----------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/18/2008 1:01:06 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando NEED TO REMOVE THE OLD WASHER AT STORED IN THE AUTO SHOP. AT WAS IN THE KITCHEN ASAP.

Mario Apodaca

40424					11/30/2008	12/8/2008	72		\$0.00
-------	--	--	--	--	------------	-----------	----	--	--------

Medium	Work In Progress				11/30/2008 12:23:49				
--------	------------------	--	--	--	---------------------	--	--	--	--

Apodaca, Mario Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.

George ZZ Gabaldon

40517	Main Building				12/3/2008		69		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/3/2008 8:08:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos Run new electrical for new units installed.

Michael Munoz

40525	Cafeteria (1998)	Cafeteria			12/3/2008		69		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/3/2008 11:34:13 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando Bottom Blodgett Oven is not working

Sara Garcia - Asst. Manager 882-5522

Alma Terrell

40526	Cafeteria (1998)	Cafeteria			12/3/2008		69		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/3/2008 11:35:42 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Moncayo, Fernando The pilot to one of the Ovens is not working

Sara Garcia - SNP Asst. Manager 882-5522

Alma Terrell

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

40542	Old English Bldg	Restroom (Girls)			12/3/2008		69		\$0.00
-------	------------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			12/3/2008 2:51:58 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph
need a new door for the girls restroom at the old eng bldg at the top floor. asap.

Mario Apodaca

40695	Old English Bldg				12/9/2008		63		\$0.00
-------	------------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			12/9/2008 12:33:28 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ambriz, Jose
Girls Gym - Need to check heating and control dampers in gym.

Michael Munoz

40700					12/9/2008		63		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			12/9/2008 12:41:33 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Estrada, Jesus
NEED TO LOOK @ INTERLOCKING TILE IN BOYS GYM (SOUTH SIDE), MEASURE AND ORDER SAME MATERIAL FOR GIRLS VARSITY GYM. ALSO NEED TO ORDER SAME SHOWER MATTING THAT IS IN THE BOYS GYM FOR GIRLS GYMS.

12/10/08 - MICHAEL TO GO OUT TO GH AND QUOTE ON SAME FLOORING PRODUCT (WHICH HE DOES NOT RECOMMEND) AND QUOTE ON WHAT HE DOES RECOMMEND. WILL PRICE QUOTE MATTING FROM FLOORSURFAES.COM / MILO CRIPPS 805-275-4087
1/12/09 - PENDING PURCHASE ORDER

Michael Munoz

40707	Library	Library			12/9/2008		63		\$0.00
-------	---------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			12/9/2008 2:59:42 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose
NEED A NEW GAS VALVE FOR A HEATING UNIT AT THE LIBRARY

Mario Apodaca

40853					12/14/2008		58		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress			12/14/2008 12:16:34					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ontiveros, Guadalupe
Monthly - Gadsden HS Soil Sampling - Refer to PM schedule details.

George ZZ Gabaldon

40893		Athletic Field			12/16/2008		56		\$0.00
-------	--	----------------	--	--	------------	--	----	--	--------

Medium	Work In Progress			12/16/2008 9:23:01 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ontiveros, Guadalupe
Requested by Mr. Lawrence for Soccer Field-Over seed soccer field, top soil for soccer field.

Velia Alarcon

40898					12/16/2008		56		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress			12/16/2008 10:00:05					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ronquillo, Ruben
Requested by Coach Hite Football J.V. Locker Room in Boy's Gym-Install a mirror in J.V. locker room. Please make mirror as large as possible, alot of students need to use it at the same time.

Velia Alarcon

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

40899	Boys Gym				12/16/2008		56		\$0.00
Medium	Work In Progress				12/16/2008 10:02:41				
Apodaca, Mario	Requested by Coach Hite for Football Locker Room in Boy's Gym-Repair all lockers in the varsity locker room.								
<u>Velia Alarcon</u>									
41052					1/4/2009	1/12/2009	37		\$0.00
Medium	Work In Progress				1/4/2009 12:18:42 AM				
Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41111					1/4/2009	1/12/2009	37		\$0.00
Medium	Work In Progress				1/4/2009 12:19:05 AM				
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41149					1/4/2009		37		\$0.00
Medium	Work In Progress				1/4/2009 12:19:23 AM				
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.					1/6/09 - E-mailed to ricky.borrego@cummins.com'			
<u>Margret Villalobos</u>									
41205	Academic Bldg				1/6/2009		35		\$0.00
Medium	Work In Progress				1/6/2009 3:21:19 PM				
Ambriz, Jose	the heating unit at the greenhous need a new fan moter								
<u>Mario Apodaca</u>									
41259					1/7/2009		34		\$0.00
Medium	Work In Progress				1/7/2009 4:28:40 PM				
Ronquillo, Ruben	Requested by Mr. Cordova for Stage Curtains in Varsity Gym-Repair the stage curtains in the Varsity Gym, curtains were made by Rodriguez Upholstery.								
<u>Velia Alarcon</u>									
41271	North Building	Gym			1/8/2009		33		\$0.00
Medium	Work In Progress				1/8/2009 2:36:51 PM				
Ronquillo, Ruben	NEED A NEW GLASS SHELVE PUT IN AT THE DISPLAY CASES(76"X12"1/4")								
<u>Mario Apodaca</u>									
41279	North Building				1/8/2009		33		\$0.00
Medium	Work In Progress				1/8/2009 3:19:24 PM				
Lara, Ralph	Need to change cores in room #236 in the North Building so that teachers will have keys that correspond with the rest of the building, allowing them access to the lounge. Will require six (6) keys.								
<u>Albert Vallejo</u>									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Gadsden HS							
41301	Nursing Center	Office			1/8/2009		33		\$0.00
Medium	Work In Progress	900			1/8/2009 4:37:19 PM				
Castillo, Carlos		Jan.16 the RN office is receiving a sleep pod for students. It requires electricity, so we will need an electrical outlet on the East wall, on the boys side. Thanks, Colleen							
Colleen Runyan									
41347					1/11/2009	1/27/2009	30		\$0.00
Medium	Work In Progress				1/11/2009 12:17:20 AM				
Munoz, Joe		Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.							
Jesus Estrada									
41446	Football Stadium	Athletic Field			1/13/2009		28		\$0.00
Medium	Work In Progress				1/13/2009 3:12:12 PM				
Ontiveros, Guadalupe		need new fence for football on the s-side							
Mario Apodaca									
41484		Athletic Field			1/14/2009		27		\$0.00
Medium	Work In Progress				1/14/2009 12:25:58 PM				
Ontiveros, Guadalupe		Requested by Coach Maxey for Track Field-Clean up the track area and blow the track of debris. Please do this the week before the meet which is March 7, 2009. FOR FURTHER INSTRUCTION SEE COACH MAXEY.							
Velia Alarcon									
41485	Concession				1/14/2009		27		\$0.00
Medium	Work In Progress				1/14/2009 12:28:25 PM				
Apodaca, Mario		Requested by Coach Maxey For Football Concession Stand-Turn on ice machine on March 5th so we can use it for the meet which will be held on March 7, 2009.							
Velia Alarcon									
41515					1/15/2009		26		\$0.00
Medium	Work In Progress				1/15/2009 8:12:48 AM				
Vallejo, Albert		(1-12-09) 2 hrs - Troubleshoot heaters on North Building; 2 hrs - troubleshoot and repair Heater on Portable room #823; 2 hrs - Repair laminating machine in Library; 2 hrs - Rearrange and hang new flags in room #124.				1/12-8			
Albert Vallejo									
41528		Portables			1/15/2009		26		\$0.00
Medium	Work In Progress				1/15/2009 12:41:07 PM				
Munoz, Joe		Elena Rodriguez (POA) needs a filing cabinet from the Parents office at GHS to be transported to Desert Pride.							
Jesus Estrada									
41544					1/15/2009		26		\$0.00
Medium	Work In Progress				1/15/2009 3:39:09 PM				
Gonzalez, Salvador		WE NEED 20 E.A BASE FOR THE INFOCUS (8X9)							
Mario Apodaca									
2/10/2009 3:17:26 PM									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
41560		Gym			1/16/2009		25		\$0.00
Medium	Work In Progress			1/16/2009 8:36:45 AM					
Gonzalez, Salvador		windows need to be covered with mesh.							
Salvador Gonzalez									
41633	Old English Bldg	Classroom			1/20/2009		21		\$0.00
High	Work In Progress			1/20/2009 8:52:37 AM					
Vallejo, Albert		as per conversation please look into repairing leak in girls gym. get back to me.thxs							
Michael Munoz									
41640					1/20/2009		21		\$0.00
Medium	Work In Progress			1/20/2009 10:53:12 AM					
Jacquez, Ricardo		CHECK BOOSTER PUMP							
Guadalupe Ontiveros									
41678					1/21/2009		20		\$0.00
Medium	Work In Progress			1/21/2009 7:53:21 AM					
Appelzoller, Fred		NEED TO REPLACE ALL LEAKING FAUCETS AT ALL BOYS AND GIRLS RESTROOM AT CONTRACTOR PUT ON DO TOO THE METERING FAUCETS ARE NOT CLOSING							
Mario Apodaca									
41688					1/21/2009		20		\$0.00
Medium	Work In Progress			1/21/2009 9:42:02 AM					
Ontiveros, Guadalupe		Requested by Coach Yanez for Baseball Field-Cut out warning track along the inside of the whole baseball field to the fence surrounding the field. (Spoke with Bobby Aldaz)							
Velia Alarcon									
41689					1/21/2009		20		\$0.00
Medium	Work In Progress			1/21/2009 10:04:33 AM					
Apodaca, Mario		Requested by Mr. Contaldo Rm. 103 Main Building-Mount 2 posters on walls.							
Velia Alarcon									
41731	Nursing Center	Office			1/22/2009		19		\$0.00
Medium	Work In Progress			1/22/2009 12:27:47 PM					
Castillo, Carlos		NEED TO RUN A NEW OUTLET AT THE NURSE							
Mario Apodaca									
41732	Cafeteria (1998)	Cafeteria			1/22/2009		19		\$0.00
Medium	Work In Progress			1/22/2009 12:38:06 PM					
Moncayo, Fernando		THE WHEELS ON THE CAFE TABLES NEED TO BE ADJUST ON ALL TABLES. A.S.A.P!!!!!!							
Mario Apodaca									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

41733	Cafeteria (1998)	Cafeteria			1/22/2009		19		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/22/2009 12:44:35 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Moncayo, Fernando
A FLUORESCENT FIXTURES IS OUT AT THE KITCHEN NEED TO BE FIX

Mario Apodaca

41798	North Building	Classroom			1/23/2009		18		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/23/2009 2:36:08 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose
NEED NEW EXH FAN MOTER FOR THE N-BLDG (5 e.a)

Mario Apodaca

41799	Main Building	Office			1/23/2009		18		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/23/2009 2:38:36 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph
NEED A NEW DOOR FOR MR. CHEMBERS OFFICE. A.S.A.P

Mario Apodaca

41834	North Building	Classroom			1/26/2009		15		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/26/2009 8:45:35 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos
Need to ck breakers in N. Bldg, that feed rooms 220,222,223 (Science)

Mario Apodaca

41841	Cafeteria (1998)	Custodial			1/26/2009		15		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/26/2009 10:51:26 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Appelzoller, Fred
the hot water at the custodial storage cannot be completely shut of it keeps running . it is by the boys restroom at the cafeteria

Joe Munoz

41904	Old English Bldg	Classroom			1/27/2009		14		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/27/2009 3:35:33 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose
NEED TO SET-UP A NEW E/COOLER UNIT ON THE ROOF TOP AT THE OLD ENG BLDGING FOR THE CLASSROOMS

Mario Apodaca

41950	Boys Gym	Dressing Room			1/28/2009		13		\$0.00
-------	----------	---------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/28/2009 2:59:06 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph
A DOOR LOCK SET NEED WORK AT THE BOYS GYM LOCKERROOM 400

Mario Apodaca

42049	Academic Bldg	Classroom			1/30/2009		11		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Academic 306		1/30/2009 4:00:26 PM					
--------	------------------	--------------	--	----------------------	--	--	--	--	--

Castillo, Carlos
I'm also running 10 computers off of 3 power outlets. I have talked to Victor and he agrees that the wiring in my room is a problem. I did ask for this last year and I was told that it would be taken care of but I have not been told when that will happen.

Erica Acosta

2/10/2009 3:17:26 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

42054					2/1/2009	2/7/2009	9		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/1/2009 12:24:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert		Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.							
-----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

42055					2/1/2009	2/9/2009	9		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/1/2009 12:24:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.							
-----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

42056					2/1/2009	3/4/2009	9		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/1/2009 12:24:28 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert		Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.							
-----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

42105					2/1/2009	2/9/2009	9		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/1/2009 12:24:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Apodaca, Mario		Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

42141					2/2/2009		8		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/2/2009 9:42:05 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Gonzalez, Salvador		Make tool setup for yellow safety top rail on fence at softball field.							
--------------------	--	--	--	--	--	--	--	--	--

Albert Vallejo

42214	North Building	Classroom			2/4/2009		6		\$0.00
-------	----------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	209			2/4/2009 8:42:05 AM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Munoz, Michael		The cabinets in the home economics room are in need of being replaced. They are not functional and look very bad.							
----------------	--	---	--	--	--	--	--	--	--

Albert Vallejo

42220					2/4/2009		6		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/4/2009 9:39:52 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph		Requested by Ms. Anderson Rm. 233 North Building-Re-key room and kitchen with two keys for Ms. Anderson, one key for Charlie the Building Custodian, and two keys for key box. Kitchen key was lent out to Chief Arms (Staff Member) for a tamale fundraising event for R.O.T.C. and Chief Arms misplaced or lost key.							
-------------	--	--	--	--	--	--	--	--	--

Velia Alarcon

42301	New Vocational				2/6/2009		4		\$0.00
-------	----------------	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/6/2009 8:27:10 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph		need new restroom toilet partitons at the boys restroom. do to vandalism							
-------------	--	--	--	--	--	--	--	--	--

Mario Apodaca

2/10/2009 3:17:26 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
42319	Cafeteria (1998)	Cafeteria			2/6/2009		4		\$0.00
Medium	Work In Progress				2/6/2009 11:04:33 AM				
Moncayo, Fernando	FIX OR INSTALL BELL (DELIVERY DOOR)								
Alma Terrell	DEMETRIOUS P. GIOVAS - SNP DIRECTOR 882-6771								
42337	Business				2/6/2009		4		\$0.00
Medium	Work In Progress				2/6/2009 4:36:55 PM				
Munoz, Michael	need to purchase 24 bobbin case cb hook for sewing machines								
Velia Alarcon									
42344					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress				2/8/2009 12:19:30 AM				
Vallejo, Albert	Monthly - Gadsden HS Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
42363	Business				2/9/2009		1		\$0.00
Medium	Work In Progress				2/9/2009 8:48:22 AM				
Apodaca, Mario	Requested by Mr. Gomez Rm. 602 Business Building- Put up a white board.								
Velia Alarcon									
42364	Main Building				2/9/2009		1		\$0.00
Medium	Work In Progress				2/9/2009 8:50:19 AM				
Lara, Ralph	Requested by Ms. Lam Rm. 104 Main Building-The lock for the north door is loose.								
Velia Alarcon									
42365	North Building				2/9/2009		1		\$0.00
Medium	Work In Progress				2/9/2009 8:53:36 AM				
Lara, Ralph	Requested by Ms. Roth Rm. 213 North Building-Repair door, can be unlocked using a student's ID card since the door is damaged/missing a part where the lock goes in.								
Velia Alarcon									
42368					2/9/2009		1		\$0.00
Medium	Work In Progress				2/9/2009 9:21:51 AM				
Vallejo, Albert	(02-04-09) 1 hr - Install new circuit for sleep chair in nurses office; 2 hrs - (42056) Bleacher inspections; 5 hrs - (39506) Install light fixtures on North side of academic building.					2/4-1			
Albert Vallejo									
42389					2/9/2009		1		\$0.00
Medium	Work In Progress				2/9/2009 3:26:54 PM				
Moncayo, Fernando	THE DELI CART AT ROOM 233 IS AT 49 NEED TO BE AT 38 OR LOWER. ASAP.								
Mario Apodaca									
2/10/2009 3:17:26 PM									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

Count: 118 Work Orders Avg. Age of WO's 91 Total for Gadsden HS 1 \$25.00

Location: Gadsden MS

35702 7/6/2008 8/6/2008 219 \$0.00

Medium Work In Progress 7/6/2008 12:20:08 AM

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

35955 7/14/2008 211 \$0.00

Medium Work In Progress 7/14/2008 3:35:17 PM

Lozoya, Manny Need fix main entrance doors the punish bar not work properly thank you

Sebastian Diaz

36222 Office 7/25/2008 200 \$0.00

Medium Work In Progress Awing/GMS Front 7/25/2008 11:40:57 AM

Lozoya, Manny Need to set up A57 key lock on new door in Ms. Quinonez's office as soon as possible.

Maricruz Carrasco

36627 Office 8/5/2008 189 \$0.00

Medium Work In Progress GMS Front 8/5/2008 5:44:35 AM

Lozoya, Manny Need A53 door lock on Nancy's door as soon as possible.

Maricruz Carrasco

36628 Office 8/5/2008 189 \$0.00

Medium Work In Progress Awing/155/Dr. 8/5/2008 5:47:23 AM

Lozoya, Manny Door lock in Dr. Garcia's office supposed to be opened by M36 key only. W key can be used to open the door. Please check door lock.

Maricruz Carrasco

36630 Parking Lot 8/5/2008 189 \$0.00

Medium Work In Progress Parking 8/5/2008 5:56:11 AM

Ronquillo, Ruben Need two windows in security shed.

Maricruz Carrasco

36632 Parking Lot 8/5/2008 189 \$0.00

Medium Work In Progress Parking 8/5/2008 5:59:53 AM

Lozoya, Manny Need metal door installed in Security shed.

Maricruz Carrasco

36994 Cafeteria Cafeteria 8/13/2008 181 \$0.00

Medium Work In Progress 8/13/2008 8:10:48 AM

Moncayo, Fernando SNP WAREHOUSE A/C SOUTHSIDE HAS NO WATER. HOT AIR BLOWING.

JOHNNY LECHUGS SNP MGR WHSE 882-6927

Jacqueline Aguilar

2/10/2009 3:17:26 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden MS

36995	Cafeteria	Cafeteria			8/13/2008		181		\$0.00
Medium	Work In Progress				8/13/2008 8:12:29 AM				
Moncayo, Fernando	SNP WAREHOUSE: WALK IN REFRIG. NEEDS TO BE RECHECK TEMP. THIS MORNING WAS AT 42.								
Jacqueline Aguilar	JOHNNY LECHUGA SNP MGR 882-6927								
37267	Office	Office			8/21/2008		173		\$0.00
Medium	Work In Progress	Awing/162/Securit			8/20/2008 10:01:58 PM				
Lozoya, Manny	"W" key is getting jammed.								
Maricruz Carrasco									
37270	Classroom	Classroom			8/21/2008		173		\$0.00
Medium	Work In Progress	Awing/159/E.			8/20/2008 10:06:16 PM				
Lozoya, Manny	Door does not close and lock.								
Maricruz Carrasco									
37763	C-Wing	Classroom			9/3/2008		160		\$0.00
Medium	Work In Progress	Cwing/C-			9/3/2008 9:29:19 PM				
Lozoya, Manny	Door does not lock. Safety issue.								
Maricruz Carrasco									
37764	C-Wing	Office			9/3/2008		160		\$0.00
Medium	Work In Progress	Cwing/Dr. Montes			9/3/2008 9:30:21 PM				
Lozoya, Manny	Door does not lock.								
Maricruz Carrasco									
37770	Portables	Portables			9/4/2008		159		\$0.00
Medium	Work In Progress				9/4/2008 8:13:40 AM				
Sotelo, Enrique	Please provide electrical connection to 2 Bard units.								
Lorenzo Solis									
38385					9/24/2008		139		\$0.00
Medium	Work In Progress	All GMS Staff			9/23/2008 10:06:29 PM				
Lozoya, Manny	All staff restrooms to have latch placed on door for privacy reasons.								
Maricruz Carrasco									
38417	C-Wing				9/24/2008		139		\$0.00
Medium	Work In Progress				9/24/2008 3:44:29 PM				
Lozoya, Manny	New Portable - 1st thing tomorrow need to recore like GMS (see Mike if u have any questions).								
Michael Munoz									
38464	C-Wing				9/26/2008		137		\$0.00
Medium	Work In Progress				9/26/2008 12:26:38 PM				
Lozoya, Manny	Mr. Chacon, Band Director needs a gate key for gate by C-Wing.								
Michael Munoz									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden MS

38485					9/26/2008		137		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:32:43 PM					
Lozoya, Manny		Need three WA-83 keys. Need two V-3 keys.							
<u>Maricruz Carrasco</u>									
38486					9/26/2008		137		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:34:17 PM					
Lozoya, Manny		Need two keys made for golf cart.							
<u>Maricruz Carrasco</u>									
38487	C-Wing	Portables			9/26/2008		137		\$0.00
Medium	Work In Progress	C-wing/New		9/26/2008 4:35:35 PM					
Lozoya, Manny		Fix lock to main entrance on new portable-Health Center							
<u>Maricruz Carrasco</u>									
38651	Annex				10/2/2008		131		\$0.00
Medium	Work In Progress			10/2/2008 3:20:00 PM					
Lozoya, Manny		Need fix handi cup door in annex bldg thank you							
<u>Sebastian Diaz</u>									
39040					10/8/2008		125		\$0.00
Medium	Work In Progress			10/8/2008 3:45:14 PM					
Ronquillo, Ruben		Need 4 window blinds for new portable 30"X60 thank you							
<u>Sebastian Diaz</u>									
39213		Office			10/14/2008		119		\$0.00
Medium	Work In Progress	Dr. Garcia's		10/14/2008 9:56:39 AM					
Lozoya, Manny		Install lock on black storage cabinet for Maricruz.							
<u>Maricruz Carrasco</u>									
39856					11/5/2008		97		\$0.00
Medium	Work In Progress			11/5/2008 2:20:53 PM					
Lozoya, Manny		Controls contractor (Trane) Needs keys to acces building on Monday Nov. 10							
<u>Alfredo Holguin</u>									
39910	C-Wing	Portables			11/6/2008		96		\$0.00
Medium	Work In Progress			11/6/2008 2:25:24 PM					
Holguin, Alfredo		Connect Electrical service to new portable for School Based Health Clinic							
<u>Alfredo Holguin</u>									
40147	C-Wing				11/17/2008		85		\$0.00
Medium	Work In Progress			11/17/2008 2:29:35 PM					
Lozoya, Manny		Nursing Coordinator Offices - Rekey - check with Ms. Cregan on keying							
<u>Alfredo Holguin</u>									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
40601		Cafeteria			12/4/2008		68		\$0.00
Medium	Work In Progress				12/4/2008 4:02:49 PM				
Moncayo, Fernando		SNP Warehouse - Some windows are broken and seals are poor in existing windows allowing a large amount of dust to come in where food is being stored. Good lighting is available therefore, we are requesting that the windows be covered with plywood and sealed to prevent contamination of food items.							
		Johnny Lechuga - SNP Warehouse							
Alma Terrell									
40612	Cafeteria	Cafeteria			12/5/2008		67		\$0.00
Medium	Work In Progress				12/5/2008 8:16:38 AM				
Ontiveros, Guadalupe		SNP Warehouse: The SNP Warehouse docking area ground has become unlevelled creating pot holes that hold water and dirt is very loose. Please level and install gravel/crusher fine to eliminate the loose dust.							
Jacqueline Aguilar									
40785					12/11/2008		61		\$0.00
Medium	Work In Progress	A wing / Sped			12/11/2008 10:29:02				
Lozoya, Manny		Re-Key File Cabinet							
Maricruz Carrasco									
40786		Classroom			12/11/2008		61		\$0.00
Medium	Work In Progress	A wing / 178			12/11/2008 10:30:20				
Lozoya, Manny		Repair Lock to File Cabinet							
Maricruz Carrasco									
40787					12/11/2008		61		\$0.00
Medium	Work In Progress	B Wing / New			12/11/2008 10:31:39				
Lozoya, Manny		Re-Key to A53							
Maricruz Carrasco									
41220	Annex				1/6/2009		35		\$0.00
Medium	Work In Progress	GMS			1/6/2009 4:52:10 PM				
Ontiveros, Guadalupe		Two large holes between Annex and portable need to be filled with dirt. Please see Dr. Garcia for more information.							
Maricruz Carrasco									
41221					1/6/2009		35		\$0.00
Medium	Work In Progress	GMS Campus			1/6/2009 4:53:38 PM				
Ontiveros, Guadalupe		Uprooted tree needs to be covered with dirt. Please see Dr. Garcia for more information.							
Maricruz Carrasco									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
41222					1/6/2009		35		\$0.00
Medium	Work In Progress	GMS Campus			1/6/2009 4:56:28 PM				
Ontiveros, Guadalupe		GMS tables/benches stored in warehouse need to be set up on GMS Campus. Please see Dr. Garcia for more information.							
<u>Maricruz Carrasco</u>									
41266					1/8/2009		33		\$0.00
Medium	Work In Progress				1/8/2009 10:14:34 AM				
Lozoya, Manny		NEED TO INSTALL CORES IN NEW ANNEX BUILDING.							
41379	Band Room	Portables			1/11/2009		30		\$0.00
Safety	Work In Progress	C-213 and Band			1/11/2009 12:27:24 AM				
Munoz, Michael		Fence needs to be placed to close the campus by C-213, Mr. Martinez's classroom and the Band room. This will help stop the ditching in that area and also stop any vandalism to the vehicles							
<u>Maricruz Carrasco</u>									
41382	Gym	Gym			1/11/2009		30		\$0.00
Medium	Work In Progress	Gym/Boys and			1/11/2009 12:34:27 AM				
Appelzoller, Fred		Toilets in both coaches offices restrooms leak when flushed.							
<u>Maricruz Carrasco</u>									
41386		Library			1/11/2009		30		\$0.00
Medium	Work In Progress	Awing/GMS New			1/11/2009 12:52:18 AM				
Acosta, Juan		Clean shelves to be placed in New Library.							
<u>Maricruz Carrasco</u>									
41393	C-Wing	Office			1/12/2009		29		\$0.00
Medium	Work In Progress	201			1/12/2009 10:26:12 AM				
Diaz, Sebastian		Heater in Irene Ortiz's room does not work							
<u>Colleen Runyan</u>									
41469	Annex	Classroom			1/13/2009		28		\$0.00
High	Work In Progress				1/13/2009 4:42:58 PM				
Acosta, Juan		Furniture needs to be moved into classrooms in Annex 400-410.							
<u>Jesus Estrada</u>									
41573					1/16/2009		25		\$0.00
Medium	Work In Progress	War room in			1/16/2009 10:54:08 AM				
Lozoya, Manny		Secure storage cabinet with clasp in WAR Room							
<u>Maricruz Carrasco</u>									
41575	C-Wing				1/16/2009		25		\$0.00
Medium	Work In Progress	C wing/ Elev. 8			1/16/2009 10:57:09 AM				
Lozoya, Manny		Lock change for storage room in the Elev. 8 room. (See Shirley Baca)							
<u>Maricruz Carrasco</u>									

2/10/2009 3:17:26 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
41578		Cafeteria			1/16/2009		25		\$0.00
Medium	Work In Progress	War room		1/16/2009 11:04:53 AM					
Lozoya, Manny		Re-key off Master to M36, same as Dr. Garcia's office							
Maricruz Carrasco									
41588		Computer Lab			1/16/2009		25		\$0.00
Medium	Work In Progress	rooms next to		1/16/2009 11:25:41 AM					
Lozoya, Manny		Need construction Core removed from computer labs next to library and Keyed to GISD Key Core. ASAP							
Maricruz Carrasco									
41590					1/16/2009		25		\$0.00
Medium	Work In Progress			1/16/2009 11:30:43 AM					
Lozoya, Manny		Need extra copy of key 56 for boiler room for Dr. Garcia							
Maricruz Carrasco									
41743	C-Wing				1/22/2009		19		\$0.00
Medium	Work In Progress	C		1/22/2009 3:06:47 PM					
Diaz, Sebastian		Set up 4 parking spaces for 1. POA 2. PTO president 3. Parent Volunteer 4. Parent Volunteer (see maricruz)							
Maricruz Carrasco									
41788		Classroom			1/23/2009		18		\$0.00
Medium	Work In Progress	B wing/ room 109		1/23/2009 10:56:22 AM					
Lozoya, Manny		Need two new locks for cabinets							
Maricruz Carrasco									
41792	Annex				1/23/2009		18		\$0.00
Medium	Work In Progress	Home Ec/ room		1/23/2009 11:54:39 AM					
Lozoya, Manny		Lock to storage cabinet (see mr. kohl)							
Maricruz Carrasco									
41853					1/26/2009		15		\$0.00
Medium	Work In Progress	A Wing/ Front		1/26/2009 3:37:20 PM					
Lozoya, Manny		8 keys to Basketball goals (Connie) 3 set's of keys to Partition Doors in Multipurpose rooms (Connie) Change Lock in Multipurpose Room (Mrs. Williams)							
Maricruz Carrasco									
41903					1/27/2009		14		\$0.00
Medium	Work In Progress			1/27/2009 3:34:39 PM					
Diaz, Sebastian		Need to install rain gutters in B wig entrances thank you							
Sebastian Diaz									
41905	C-Wing				1/27/2009		14		\$0.00
Medium	Work In Progress			1/27/2009 3:35:53 PM					
Diaz, Sebastian		Need to intall rain gutters in C wing area thank you							
Sebastian Diaz									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
41924					1/28/2009		13		\$0.00
Medium	Work In Progress			1/28/2009 8:15:30 AM					
Lozoya, Manny		Need to fix door handal in room 303 vocatinal bldg thank you							
Sebastian Diaz									
41932					1/28/2009		13		\$0.00
Medium	Work In Progress	room 146 and		1/28/2009 10:15:28 AM					
Lozoya, Manny		Key new computer labs, rooms 146 and 148.							
Need 5 keys of the V8 (Connie)									
Maricruz Carrasco									
41938					1/28/2009		13		\$0.00
Medium	Work In Progress	Library		1/28/2009 11:19:35 AM					
Lozoya, Manny		Rekey inside new library							
Maricruz Carrasco									
41948	Gym	Classroom			1/28/2009		13		\$0.00
Medium	Work In Progress	Gym/Multipurpos		1/28/2009 2:34:23 PM					
Acosta, Juan		Move Chacon/Band to new area-Multi-Purpose room.							
1/28/09 - FAXED TO JUAN									
Maricruz Carrasco									
41988					1/29/2009		12		\$0.00
Medium	Work In Progress			1/29/2009 11:28:47 AM					
Ontiveros, Guadalupe		could you please support w/ the irrigation system in the front of the campus to include the backflow preventer. no water thxs							
Michael Munoz									
41989					1/29/2009		12		\$0.00
Medium	Work In Progress			1/29/2009 11:32:40 AM					
Appelzoller, Fred		please provide and check all hose bibbs around campus for water hose hook ups. thxs							
Michael Munoz									
42020					1/30/2009		11		\$0.00
Medium	Work In Progress			1/30/2009 11:37:16 AM					
Lozoya, Manny		Need to check key and lock in computer lab thank you							
Sebastian Diaz									
42021					1/30/2009		11		\$0.00
Medium	Work In Progress			1/30/2009 11:39:56 AM					
Lozoya, Manny		Need to change lock in new annex bldg electrical room thank you							
Sebastian Diaz									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

42127					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:53 AM				
Diaz, Sebastian		Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
42128					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:54 AM				
Diaz, Sebastian		Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
42129					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:54 AM				
Diaz, Sebastian		Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
42187					2/3/2009		7		\$0.00
Medium	Work In Progress				2/3/2009 2:10:28 PM				
Diaz, Sebastian		Assemble and Install 6 ea. 48" square tables - Location to be determined by Principal							
Alfredo Holguin									
42267		Computer Lab			2/5/2009		5		\$0.00
Medium	Work In Progress	Rm 146			2/5/2009 10:49:02 AM				
Diaz, Sebastian		Istall Pencil Sharpener							
Maricruz Carrasco									
42269		Computer Lab			2/5/2009		5		\$0.00
Medium	Work In Progress	Rm 148			2/5/2009 10:56:05 AM				
Diaz, Sebastian		Move mirrors from old classroom (Rm 117) to new computer lab Rm 148							
Maricruz Carrasco									
42317	C-Wing	Custodial			2/6/2009		4		\$0.00
Medium	Work In Progress				2/6/2009 10:48:40 AM				
Estrada, Jesus		LIKE TO ORDER 2 AIR BLOWERS AND 1 WEED EATER							
Juan Acosta									
42398	Gym	Gym			2/9/2009		1		\$0.00
Medium	Work In Progress	Gym/Boys			2/9/2009 4:15:46 PM				
Lozoya, Manny		New lock needed for Boys Basketball Storage. See Connie for more information.							
Maricruz Carrasco									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

42411					2/10/2009		0		\$0.00
Medium	Work In Progress				2/10/2009 10:47:51 AM				
Acosta, Juan		ON MONDAY, FEBRUARY 16 (HOLIDAY) NEED TO DISARM ALARMS FOR ENTIRE SCHOOL @ 8:00 A.M. AND THEN REARM THEM @ 5:00 PM. PLEASE DO A SCHEDULE.							

Alfredo Holguin

Count: 68 Work Orders		Avg. Age of WO's 74				Total for Gadsden MS	0		\$0.00
------------------------------	--	----------------------------	--	--	--	-----------------------------	----------	--	---------------

Location: La Union - JTP Alvarez Farms

41895					1/27/2009		14		\$0.00
Medium	Work In Progress	ENTIRE			1/27/2009 2:12:34 PM				
Villalobos, Margret		PLEASE spray for bugs inside and outside of the building.							

Margaret Villalobos

Count: 1 Work Orders		Avg. Age of WO's 14				Total for La Union - JTP Alvarez Farms	0		\$0.00
-----------------------------	--	----------------------------	--	--	--	---	----------	--	---------------

Location: La Union ES

35705					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:09 AM				
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							

Margret Villalobos

35791		Cafeteria			7/9/2008		216		\$0.00
Medium	Work In Progress				7/9/2008 1:48:49 PM				
Moncayo, Fernando		OVENS NEED TO BE CHECKED. SOMETIMES THEY WILL HEAT UP AND THEN STOP HEATING ALL OF A SUDDEN.							

LINDA YANAGA SNP MGR 589-2040

Jacqueline Aguilar

35792		Cafeteria			7/9/2008		216		\$0.00
Medium	Work In Progress				7/9/2008 1:49:55 PM				
Moncayo, Fernando		PASS THRU REFRIG. IS FREEZING UP.							

LINDA YANAGA LU SNP MGR 589-2040

Jacqueline Aguilar

35921					7/13/2008	7/29/2008	212		\$0.00
Medium	Work In Progress				7/13/2008 12:18:11 AM				
Gonzalez, Salvador		Monthly - La Union ES Playground Insp - Refer to PM schedule details.							

Margret Villalobos

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
36590					8/4/2008		190		\$0.00
Medium	Work In Progress				8/4/2008 10:36:40 AM				
Castillo, Carlos		Run elect. to morgom maint storage - would be nice to use fan							
Patricio Aguilar									
36996		Cafeteria			8/13/2008		181		\$0.00
Medium	Work In Progress				8/13/2008 8:23:00 AM				
Moncayo, Fernando		REACH THRU REFRIG. DOES NOT COOL TEMP IS AT 50							
		LINDA YANAGA SNP MGR 589-2040							
Jacqueline Aguilar									
37040	Annex Building				8/13/2008		181		\$0.00
Medium	Work In Progress				8/13/2008 4:17:56 PM				
Castillo, Carlos		Install electrical for kiln in room # 203							
Alfredo Holguin									
37120					8/15/2008		179		\$0.00
Medium	Work In Progress				8/15/2008 3:17:51 PM				
Carrasco, Danny		Need 3 gfi elect out lets #202							
Patricio Aguilar									
37960					9/9/2008		154		\$0.00
Medium	Work In Progress				9/9/2008 2:37:27 PM				
Castillo, Carlos		NEED TO HAVE LIGHT POLES, AND LIGHTS ON WEST PARKING LOT CHECKED THEY ARE OFF, ONLY A FEW LIGHTS COME ON, POSSIBLE LIGHTING DAMAGE.							
Arturo Nunez									
38034					9/11/2008		152		\$0.00
Medium	Work In Progress				9/11/2008 3:14:33 PM				
Villalobos, David		pat aguilar need rubber bushing for water faucet - thank you							
Patricio Aguilar									
38036					9/11/2008		152		\$0.00
Medium	Work In Progress				9/11/2008 3:22:31 PM				
Ambriz, Jose		pat aguilar wants her refrigerated ac replaced - that it is to loud							
Patricio Aguilar									
40988					12/18/2008		54		\$0.00
Medium	Work In Progress				12/18/2008 3:20:23 PM				
Ambriz, Jose		pat aguilar the thermostat not working right - dayton electric heater model 2e441 ser 143933 volts 240/208 wats 4800/2500 60 hz 13tu 16382/11946							
Patricio Aguilar									
2/10/2009 3:17:27 PM									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

41167					1/5/2009		36		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/5/2009 3:33:50 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ambriz, Jose
 pat aguilar
 heater boiler pump
 taco model fm1207
 has a bad bearing

 Patricio Aguilar

41244					1/7/2009		34		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/7/2009 3:11:39 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
 pat aguilar
 need a new frame & door for rest room r210

 Patricio Aguilar

41245					1/7/2009		34		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/7/2009 3:14:33 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
 pat aguilar
 need same kind of lock on door to keep children in

 Patricio Aguilar

41349					1/11/2009	1/27/2009	30		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				1/11/2009 12:17:21 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Galindo, Santos
 Monthly - QRTLY BLDG INSP REPORT (LU) - Refer to
 PM schedule details. pending completed work order with
 signature as of 2/5/09

 Jesus Estrada

41883		Classroom			1/27/2009		14		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/27/2009 10:12:35 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose
 The thermostat not working will not cut off set tempiter
 rm 303

 Patricio Aguilar

41999					1/29/2009		12		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/29/2009 3:09:17 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose
 pat aguilar
 need to replace a 1/2" ball vale on heater pump

 Patricio Aguilar

42109					2/1/2009	2/9/2009	9		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/1/2009 12:24:47 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Aguilar, Patricio
 Monthly - La Union ES Emer. Light Test: Monthly -
 Refer to PM schedule details.

 Margret Villalobos

42110					2/1/2009	2/9/2009	9		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/1/2009 12:24:47 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Aguilar, Patricio
 Monthly - La Union ES Exit Sign Insp: Monthly - Refer to
 PM schedule details.

 Margret Villalobos

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

42111					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:47 AM				
Aguilar, Patricio		Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
42202					2/3/2009		7		\$0.00
Medium	Work In Progress				2/3/2009 3:44:11 PM				
Gonzales, Angel		Need to use sweeper for drive ways							
Patricio Aguilar									
42256		Cafeteria			2/5/2009		5		\$0.00
Medium	Work In Progress				2/5/2009 8:20:41 AM				
Moncayo, Fernando		WALK - IN FREEZER TEMP AT 33.							
		LINDA YANAGA SNP MGR 589-2040							
Jacqueline Aguilar									
42345					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress				2/8/2009 12:19:30 AM				
Aguilar, Patricio		Monthly - La Union ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
Count: 24 Work Orders			Avg. Age of WO's 96				Total for La Union ES	0	\$0.00

Location: Loma Linda ES

35703					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:08 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36408					7/31/2008		194		\$0.00
Medium	Work In Progress				7/31/2008 2:26:46 PM				
Ronquillo, Ruben		Need to replace 10 more blinds.							
Rudy Arreola									
37058		Portables			8/14/2008		180		\$0.00
Medium	Work In Progress				8/14/2008 10:22:44 AM				
Arreola, Rudy		Complete skirting installation on double portable				1/26/09 - Waiting on siding asp report			
Alfredo Holguin									
37711		Athletic Field			9/2/2008		161		\$0.00
Medium	Work In Progress				9/2/2008 3:15:39 PM				
Ontiveros, Guadalupe		Water leak from one of the irrigation line its coming from under the cement. by the basketball courts area.							
Rudy Arreola									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Loma Linda ES

38220		Classroom			9/18/2008		145		\$0.00
Medium	Work In Progress			9/18/2008 2:36:13 PM					
Ronquillo, Ruben	Windows in RM 205 are hard to open and wont stay up.TOTAL of 3								
Rudy Arreola									
38221		Classroom			9/18/2008		145		\$0.00
Medium	Work In Progress			9/18/2008 2:37:10 PM					
Ronquillo, Ruben	Windows in RM 201 is very hard to open TOTAL of 2.								
Rudy Arreola									
38222					9/18/2008		145		\$0.00
Medium	Work In Progress			9/18/2008 2:37:50 PM					
Ronquillo, Ruben	Window in RM 204 wont stay up TOTAL of 1.								
Rudy Arreola									
38782					10/5/2008	10/26/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:24:04 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
38964					10/6/2008		127		\$0.00
Medium	Work In Progress			10/6/2008 1:40:46 PM					
Carrasco, Danny	Need pressure washer and hose to wash off wall of the east side of main bldg.								
Rudy Arreola									
39762					11/3/2008		99		\$0.00
Medium	Work In Progress			11/3/2008 7:52:22 AM					
Ronquillo, Ruben	Need 6 signs that say NO PARKING 7.AM. TO 4P.M. MOM THRU FRIDAY								
Rudy Arreola									
40791					12/11/2008		61		\$0.00
Medium	Work In Progress			12/11/2008 12:35:13					
Lozoya, Manny	We need a new lock for new gate that was installed								
Rudy Arreola									
40792					12/11/2008		61		\$0.00
Medium	Work In Progress			12/11/2008 12:37:00					
Lozoya, Manny	Overhead file cabinet does not lock need a new lock installed.								
Rudy Arreola									
40793					12/11/2008		61		\$0.00
Medium	Work In Progress			12/11/2008 12:38:32					
Carrasco, Danny	Total of 180 ceiling tiles that were damaged on 12/9/09-12/10/08.								
Rudy Arreola									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Loma Linda ES

41073					1/4/2009	1/25/2009	37		\$0.00
Medium	Work In Progress				1/4/2009 12:18:50 AM				
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
41263	Main Building	Library			1/8/2009		33		\$0.00
Medium	Work In Progress				1/8/2009 8:30:20 AM				
Solis, Luis	Shampoo and extract carpet, coordinate with your building mechanic. The carpet cleaning will take place after the walls are painted. If you have any questions call me.								
Jesus Estrada									
41564					1/16/2009		25		\$0.00
Medium	Work In Progress				1/16/2009 9:16:24 AM				
Arreola, Rudy	Need to replace a total of 180 ceiling tiles that were damaged on 12/9/09-12/10/08.								
Michael Munoz									
42117					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:50 AM				
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
42118					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:50 AM				
Arreola, Rudy	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42119					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:50 AM				
Arreola, Rudy	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42146					2/2/2009		8		\$0.00
Medium	Work In Progress				2/2/2009 2:22:39 PM				
Gonzales, Angel	Riding mower needs service and new blades also back tires are low.								
Rudy Arreola									
42147					2/2/2009		8		\$0.00
Medium	Work In Progress				2/2/2009 2:23:29 PM				
Lozoya, Manny Rudy Arreola	Lock in room 107 was getting stuck and hard to lock.								

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Loma Linda ES

42148					2/2/2009		8		\$0.00
Medium	Work In Progress				2/2/2009 2:25:08 PM				
Lozoya, Manny	Door closure came off door in RM 211								
Rudy Arreola									
42259	Main Building	Classroom			2/5/2009		5		\$0.00
Medium	Work In Progress				2/5/2009 8:53:21 AM				
Lozoya, Manny	RM 317 Music Room - Having trouble opening door.								
Luis Solis									
42276					2/5/2009		5		\$0.00
Medium	Work In Progress				2/5/2009 2:03:22 PM				
Lozoya, Manny	We need to have 2 sets of RR have the door handle changed so we can lock the RR One is front lobby and the other is cafeteria lobby. BOYS AND GIRLS								
Rudy Arreola									
42346					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress				2/8/2009 12:19:31 AM				
Arreola, Rudy	Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
42402					2/10/2009		0		\$0.00
Medium	Work In Progress				2/10/2009 8:04:10 AM				
Castillo, Carlos	Need to relocate outlet in library so they can install new shelving URGENT!!!!!! Mrs torre really need the outlet.								
Rudy Arreola									
Count: 26 Work Orders		Avg. Age of WO's 72		Total for Loma Linda ES			0	\$0.00	

Location: Mesquite ES

35549					7/6/2008	7/12/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:19:20 AM				
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
35567					7/6/2008	7/14/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:19:26 AM				
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
35626					7/6/2008	7/14/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:19:44 AM				
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

35636					7/6/2008	7/14/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:19:47 AM				
Ramirez, Joe		Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
35661					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:19:55 AM				
Ramirez, Joe		Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35684					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:02 AM				
Ramirez, Joe		Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35706					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:09 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36109					7/22/2008		203		\$0.00
Medium	Work In Progress				7/22/2008 10:11:48 AM				
Lozoya, Manny		on (work room) needs a cylinder with a key they have school files need to be lock all the time as per montano principal asap. thank you. luis							
Luis Saucedo									
36147	Main Building	Office			7/23/2008		202		\$0.00
Medium	Work In Progress	Main office area			7/23/2008 12:29:38 PM				
Lozoya, Manny		Main office need's (4) engraved plaque's for front office door. Name and Title (Jacob Montano, Principal), (Sandra Mora, Secretary), (Dora Lerma, Data-Entry Clerk), (Maribel Villela, Receptionist-Clerk) for Manny Lozoya.							
Sandra Mora									
36227		Portables			7/25/2008		200		\$0.00
Medium	Work In Progress				7/25/2008 2:11:53 PM				
Lozoya, Manny		Ms. Flores room # 801 has filing cabinet that doesn't have a key, need's to be re-key.							
Sandra Mora									
36256	2003 Classroom	Classroom			7/28/2008		197		\$0.00
Medium	Work In Progress	Portable room #			7/28/2008 8:30:02 AM				
Lozoya, Manny		Ms. Jimenez, portable room # 506 she has a storage cabinet needs to be re-key.							
Sandra Mora									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Mesquite ES

36259	2003 Classroom	Classroom			7/28/2008		197		\$0.00
Medium	Work In Progress	Kinder hallway,			7/28/2008 8:58:17 AM				
Lozoya, Manny	Need a master for that room # 405 for our inventory, and key # 305.								
Sandra Mora									
36507					8/3/2008	8/9/2008	191		\$0.00
Medium	Work In Progress				8/3/2008 12:20:15 AM				
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
36539					8/3/2008	8/11/2008	191		\$0.00
Medium	Work In Progress				8/3/2008 12:20:26 AM				
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36549					8/3/2008	8/11/2008	191		\$0.00
Medium	Work In Progress				8/3/2008 12:20:29 AM				
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
36885	Main Building	Office			8/11/2008		183		\$0.00
Medium	Work In Progress	Office area			8/11/2008 11:09:39 AM				
Lozoya, Manny	(1) engraved plaque for front office door. Name and Title (Norma Sierra, Assistant Principal) for Manny Lozoya								
Sandra Mora									
37617					8/31/2008		163		\$0.00
Medium	Work In Progress				8/31/2008 12:25:35 AM				
Ramirez, Joe	Monthly - Mesquite ES A-2 Quarterly H/C IREH - Refer to PM schedule details.								
Margret Villalobos									
37618					8/31/2008		163		\$0.00
Medium	Work In Progress				8/31/2008 12:25:35 AM				
Ramirez, Joe	Monthly - Mesquite ES A-1 Semiannual MCD - Refer to PM schedule details.								
Margret Villalobos									
37619					8/31/2008		163		\$0.00
Medium	Work In Progress				8/31/2008 12:25:36 AM				
Ramirez, Joe	Monthly - Mesquite ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

37620					8/31/2008		163		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/31/2008 12:25:36 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-1 Semiannual UCD - Refer to PM schedule details.							
--------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

37621					8/31/2008		163		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/31/2008 12:25:36 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-1 Semiannual UCS2 - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

37622					8/31/2008		163		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/31/2008 12:25:37 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-13 Quarterly WREH - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

37623					8/31/2008	9/8/2008	163		\$0.00
-------	--	--	--	--	-----------	----------	-----	--	--------

Medium	Work In Progress				8/31/2008 12:25:37 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

37624					8/31/2008		163		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/31/2008 12:25:37 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-8 Quarterly HPW - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

37625					8/31/2008		163		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/31/2008 12:25:38 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES A-1 Semiannual EVS - Refer to PM schedule details.							
--------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

37626					8/31/2008	9/6/2008	163		\$0.00
-------	--	--	--	--	-----------	----------	-----	--	--------

Medium	Work In Progress				8/31/2008 12:25:38 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

37627					8/31/2008	9/8/2008	163		\$0.00
-------	--	--	--	--	-----------	----------	-----	--	--------

Medium	Work In Progress				8/31/2008 12:25:38 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ramirez, Joe		Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.							
--------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

38210					9/18/2008		145		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/18/2008 9:18:18 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique Joe Ramirez		marquee lights not working.							
--------------------------------	--	-----------------------------	--	--	--	--	--	--	--

2/10/2009 3:17:27 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Mesquite ES

38537					9/30/2008		133		\$0.00
Medium	Work In Progress			9/30/2008 12:26:03 AM					
Ramirez, Joe	Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.								
Margret Villalobos									
38881					10/5/2008	10/11/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:24:40 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
38882					10/5/2008	10/13/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:24:41 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
38883					10/5/2008	10/13/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:24:41 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
38884					10/5/2008	10/13/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:24:41 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
38885					10/5/2008	11/5/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:24:42 AM					
Ramirez, Joe	Yearly - Mesquite ES I-4 Fan Coil Unit Yearly - Refer to PM schedule details.								
Margret Villalobos									
38886					10/5/2008	11/5/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:24:42 AM					
Ramirez, Joe	Yearly - Mesquite ES H-6 Rooftop Furnance Yearly - Refer to PM schedule details.								
Margret Villalobos									
38887					10/5/2008	11/5/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:24:42 AM					
Ramirez, Joe	Yearly - Mesquite ES R-9 Rad Hot Water 2 years - Refer to PM schedule details.								
Margret Villalobos									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Mesquite ES

38888					10/5/2008	11/5/2008	128		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium Work In Progress 10/5/2008 12:24:43 AM

Ramirez, Joe Yearly - Mesquite ES U-2 Unit Heater Gas Yearly - Refer to PM schedule details.

Margret Villalobos

38889					10/5/2008	10/21/2008	128		\$0.00
-------	--	--	--	--	-----------	------------	-----	--	--------

Medium Work In Progress 10/5/2008 12:24:43 AM

Ramirez, Joe Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.

Margret Villalobos

39519					10/27/2008		106		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium Work In Progress 10/27/2008 3:11:39 PM

Ramirez, Joe GRASS IS GROWING IN DRAIN GRID BY BUS TURN AROUND.

Michael Munoz

39692					11/2/2008	11/8/2008	100		\$0.00
-------	--	--	--	--	-----------	-----------	-----	--	--------

Medium Work In Progress 11/2/2008 12:24:35 AM

Ramirez, Joe Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.

Margret Villalobos

39724					11/2/2008	11/10/2008	100		\$0.00
-------	--	--	--	--	-----------	------------	-----	--	--------

Medium Work In Progress 11/2/2008 12:24:47 AM

Ramirez, Joe Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

39734					11/2/2008	11/10/2008	100		\$0.00
-------	--	--	--	--	-----------	------------	-----	--	--------

Medium Work In Progress 11/2/2008 12:24:50 AM

Ramirez, Joe Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

40256					11/20/2008		82		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium Work In Progress 11/20/2008 9:34:58 AM

Lozoya, Manny file cabinet in rm 405 needs a new lock installed the other was damaged.

Joe Ramirez

41227	Main Building	Classroom			1/7/2009		34		\$0.00
-------	---------------	-----------	--	--	----------	--	----	--	--------

Medium Work In Progress Room # 203 1/7/2009 8:59:31 AM

Lozoya, Manny Key is needed for Pamela Uribe IA to that classroom.

Sandra Mora

41305		Classroom			1/9/2009		32		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium Work In Progress 1/9/2009 8:12:50 AM

Lozoya, Manny Rm 608 (Wendy Tow) - Door continues to stick, even after it has been fixed.

Joe Ramirez

2/10/2009 3:17:27 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
41567					1/16/2009		25		\$0.00
Medium	Work In Progress			1/16/2009 9:32:05 AM					
Ontiveros, Joe	outside drinking fountain one bubbler missing the other one doesn't work need to be replaced.								
<u>Joe Ramirez</u>									
41690	Main Building	Classroom			1/21/2009		20		\$0.00
Medium	Work In Progress	Room # 203		1/21/2009 10:37:15 AM					
Lozoya, Manny	Pamela Uribe IA needs key we don't have another in key box for that room.								
<u>Sandra Mora</u>									
41977					1/29/2009		12		\$0.00
High	Work In Progress			1/29/2009 8:14:01 AM					
Gonzalez, Salvador	covers to lift station are rusty and old and need replacement ASAP. safty thxs								
<u>Michael Munoz</u>									
42102					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:44 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42103					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:45 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42104					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:45 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42223		Portables			2/4/2009		6		\$0.00
Medium	Work In Progress			2/4/2009 10:26:45 AM					
Ronquillo, Ruben	Portable Rm 605 - Need a Fire Extinguisher installed asp PM 41039.								
<u>Joe Ramirez</u>									
42308					2/6/2009		4		\$0.00
Medium	Work In Progress			2/6/2009 9:31:18 AM					
Ontiveros, Guadalupe	trees in front of school need to be pruned. mr. sedillo talked to mike about this.								
<u>Joe Ramirez</u>									
Count: 53 Work Orders			Avg. Age of WO's	135			Total for Mesquite ES	0	\$0.00

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: North Valley ES

36463		Office			8/1/2008		193		\$0.00
Medium	Work In Progress	room 400			8/1/2008 11:44:39 AM				
Lozoya, Manny		Hello Manny, The alarm box key was broken off, please replace.							
<u>Priscilla Martinez</u>									
37136		Office			8/18/2008		176		\$0.00
Medium	Work In Progress	video			8/18/2008 10:18:19 AM				
Lozoya, Manny		could not locate a key							
Priscilla Martinez		Need a black box located in our office to be opened, could not locate the correct key in our vault							
37221		Classroom			8/20/2008		174		\$0.00
Medium	Work In Progress	various			8/20/2008 9:15:00 AM				
Lozoya, Manny		Send Lozoya to make various keys for various classrooms, desks, cabinets, filing cabinets, storage closets,							
Priscilla Martinez		please visit the front office for this list of keys that are needed, thanks Priscilla							
38084		Classroom			9/15/2008		148		\$0.00
Medium	Work In Progress				9/15/2008 1:35:12 PM				
Lozoya, Manny		need a key made for Larry Roybal (Deputy Dona Ana County Sheriff) for the gates at North Valley Elementary							
<u>Priscilla Martinez</u>									
38743					10/5/2008		128		\$0.00
Medium	Work In Progress				10/5/2008 12:23:50 AM				
Holguin, Alfredo		Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos		10/6/08 - Emailed to Ricky Borrego							
39280					10/20/2008		113		\$0.00
Medium	Work In Progress				10/20/2008 9:11:35 AM				
Lozoya, Manny		need new pad lock for bus exit gate/had to cut old lock this morning-key didnt turn core							
<u>Danny Vega</u>									
39383					10/22/2008		111		\$0.00
Medium	Work In Progress				10/22/2008 1:41:03 PM				
Lozoya, Manny		p.e coaches office door will not open -core will not turn with key-please ck out asap							
<u>Danny Vega</u>									
39456		Classroom			10/24/2008		109		\$0.00
Medium	Work In Progress	room 210			10/24/2008 12:13:11				
Lozoya, Manny		black file cabinet w/blue sticker does not lock.							
Priscilla Martinez									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: North Valley ES

39804					11/4/2008		98		\$0.00
Medium	Work In Progress				11/4/2008 9:20:53 AM				
Lozoya, Manny	need key made for rm 304 art rm/cabinet key broke in core-need to lock-up supplies asap								
Danny Vega									
40891					12/16/2008		56		\$0.00
Medium	Work In Progress				12/16/2008 8:10:47 AM				
Lozoya, Manny	need duplicate from rm 306/cabinet keys- parent center (402) has 01 and 06 key locks-need to give rm 402 a 06 key								
Danny Vega									
41151					1/4/2009		37		\$0.00
Medium	Work In Progress				1/4/2009 12:19:23 AM				
Holguin, Alfredo	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.		1/6/09 - E-mailed to ricky.borrego@cummins.com'						
Margret Villalobos									
41646					1/20/2009		21		\$0.00
Medium	Work In Progress				1/20/2009 12:14:58 PM				
Ontiveros, Joe	rm #201 faucet leaks wont stop running .please ck out.i have cleaned it twice already .leaks worse								
Danny Vega									
42067					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:32 AM				
Vega, Danny	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42069					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:32 AM				
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42071					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:33 AM				
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
42140		Cafeteria			2/2/2009		8		\$0.00
Medium	Work In Progress				2/2/2009 9:35:53 AM				
Orozco, Danny	Drain pipe connected to the Dishwasher has rusted out and is leaking.								
	Eva Miranda - SNP Manager 233-3658								
Jacqueline Aguilar									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: North Valley ES

42354					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress				2/8/2009 12:19:34 AM				
Vega, Danny	Monthly - North Valley ES Playground Inspection - Refer to PM schedule details.								

Margret Villalobos

Count: 17 Work Orders	Avg. Age of WO's 82	Total for North Valley ES	0	\$0.00
------------------------------	----------------------------	----------------------------------	----------	---------------

Location: Northern On-Track Pre-K (LM)

35704					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:09 AM				
Villalobos, David	Yearly - Northern Pre-K (LM) Backflow Inspection - Refer to PM schedule details.								

Margret Villalobos

37774		Athletic Field			9/4/2008		159		\$0.00
Medium	Work In Progress				9/4/2008 8:52:16 AM				

Lozoya, Manny send us the lock and chain to secure the west gate

Gilbert Trujillo

37775	Main Building	Restroom (Girls)			9/4/2008		159		\$0.00
Medium	Work In Progress	classroom 114			9/4/2008 9:33:49 AM				

Lozoya, Manny Bathroom door in the baby room won't close.

Concepcion Montalvo

39602	Pump House	Pump House			10/30/2008		103		\$0.00
Medium	Work In Progress				10/30/2008 9:07:18 AM				

Lozoya, Manny please change lock back to original lock on irrigation well thanks

Ricardo Jacquez

39905		Restroom (Boys)			11/6/2008		96		\$0.00
Medium	Work In Progress				11/6/2008 10:29:38 AM				

Lozoya, Manny alma de valle restroom door need to be worked on.

Gilbert Trujillo

40019	Main Building	Classroom			11/12/2008		90		\$0.00
Medium	Work In Progress				11/12/2008 8:35:22 AM				

Sotelo, Enrique classroom plug switch is shorted out.room 112

Gilbert Trujillo

41519		Football Field			1/15/2009		26		\$0.00
Medium	Work In Progress				1/15/2009 9:36:04 AM				

Gonzalez, Salvador attn. chava gonzales i need a bolt bell opener please.

Gilbert Trujillo

41836		Custodial			1/26/2009		15		\$0.00
Medium	Work In Progress				1/26/2009 8:48:19 AM				

Carbajal, Jimmy i need a front vacuum cleaner cover replaced .

Gilbert Trujillo

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location:		Northern On-Track Pre-K (LM)							
41981	Cafeteria				1/29/2009		12		\$0.00
Medium	Work In Progress				1/29/2009 8:40:25 AM				
Carrasco, Danny		please pick-up shelving that belongs to gms and deliver to sunland carpentry, so they can make adjustments for installation at loma linda. as per ida garcia and phillip medina							
Michael Munoz									
42068					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:32 AM				
Vega, Danny		Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
42070					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:33 AM				
Vega, Danny		Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
42072					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:33 AM				
Vega, Danny		Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
42261	Main Building				2/5/2009		5		\$0.00
Medium	Work In Progress				2/5/2009 8:58:11 AM				
Ontiveros, Guadalupe		we have 3 broken sprinklers in the soccer field.							
Gilbert Trujillo									
42347					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress				2/8/2009 12:19:31 AM				
Vega, Danny		Monthly - Northern On-Track Pre-K Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
42378	Pump House				2/9/2009		1		\$0.00
Medium	Work In Progress				2/9/2009 1:38:58 PM				
Vega, Danny		air conditioner cover is loose.							
Gilbert Trujillo									
Count: 15 Work Orders		Avg. Age of WO's 61		Total for Northern On-Track Pre-K (LM)				0	\$0.00

Location:		Physical Plant Complex							
35707					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:10 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Physical Plant Complex

36213	Maintenance				7/25/2008		200		\$0.00
-------	-------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			7/25/2008 10:15:21 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Sotelo, Enrique please install electrical outlet to cooling duct fan and pilot switch.
Thxs

Michael Munoz

36291					7/28/2008		197		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			7/28/2008 3:26:53 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben Purchase a new water tank

Alfredo Holguin

36355	Food Services	Parking Lot			7/30/2008		195		\$0.00
-------	---------------	-------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	SNP		7/30/2008 12:01:33 PM					
--------	------------------	-----	--	-----------------------	--	--	--	--	--

Ontiveros, Guadalupe AS PER MR. GIOVAS-IF NEAR THE WAREHOUSE GOING FROM THE SHADED AREA TO THE STAIR WAY INTO THE WAREHOUSE IF THEY CAN LEVEL OUT THE PATH WAY. (PLEASE SEE JOHNNY L. IF NEED DIRECTION.)

Mary Garcia

36759	Maintenance				8/7/2008		187		\$0.00
-------	-------------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress			8/7/2008 9:53:28 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Munoz, Michael Need price quote to build an architect table for Tech's Office.

Michael Munoz

37066					8/14/2008		180		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/14/2008 11:15:18 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ronquillo, Ruben Purchase new individual signs to go above doors outside

Bldg. indicating as follows:
 -Purchasing Warehouse
 -Instructional Materials
 -Physical Plant Dept./ Construction Dept./Custodial Dept.
 -Custodial Shipping/Receiving
 Also 1 sign for Main Entrance by Nurse Complex indicating as follows:
 Construction Dept.
 Instructional Materials
 Student Nutrition Warehouse
 Student Records
 Transportation
 Physical Plant Department
 Custodial Dept.
 Maintenance Dept.
 Motor Pool
 Purchasing Warehouse
 SEE ALFREDO IF ANY QUESTIONS.

Alfredo Holguin

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

37074	Food Services				8/14/2008		180		\$0.00
Medium	Work In Progress				8/14/2008 2:23:06 PM				
Lara, Ralph		As per Mike, remove doubled doors and replace with a rolling door. Please see Mike if you have any questions.							
Michael Munoz									
37767					9/4/2008		159		\$0.00
Medium	Work In Progress				9/4/2008 8:02:44 AM				
Lozoya, Manny		need to replace door lock on water department office does not lock thanks							
Ricardo Jacquez									
37791	Purchasing				9/4/2008		159		\$0.00
Medium	Work In Progress				9/4/2008 2:35:30 PM				
Sotelo, Enrique		I would like to have a light switch in my office to control the lights. Currently the switch is in the hall and the one switch controls my office and hallway.							
Vicky Lopez									
37882	Food Services				9/8/2008		155		\$0.00
Medium	Work In Progress				9/8/2008 8:10:34 AM				
Ontiveros, Guadalupe		Need to add Crusher fines to dock area.							
Alfredo Holguin									
37888	Parking Lot				9/8/2008		155		\$0.00
Medium	Work In Progress				9/8/2008 8:19:17 AM				
Ronquillo, Ruben		Desigate Handicap Parking for Building and Install signage				9/29 - asp Mike route to Ruben			
Alfredo Holguin									
37889	Parking Lot				9/8/2008		155		\$0.00
Medium	Work In Progress				9/8/2008 8:23:48 AM				
Ronquillo, Ruben		Purchase and Install Parking Signs for the entire PPD Complex. (Vistiors Parking, Employee Parking, No Parking- Loading Zone)							
Alfredo Holguin									
37944					9/9/2008		154		\$0.00
Medium	Work In Progress				9/9/2008 12:13:23 PM				
Gonzalez, Salvador		PLEASE MAKE SCRAPERS/DRAGERS. PLEASE SEE MIKE.							
Michael Munoz									
38130	Parking Lot				9/16/2008		147		\$0.00
Medium	Work In Progress				9/16/2008 11:39:13 AM				
Ronquillo, Ruben		Purchase Sign for Physical Plant Parking Plan as per the layout provided. Signs need to be larger than the standard size.							

Alfredo Holguin

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
38639	Maintenance	Office			10/2/2008		131		\$0.00
Medium	Work In Progress				10/2/2008 9:08:26 AM				
Ronquillo, Ruben	SERVICE FOR ASBESTOS ABATEMENT AND CUT OPENING TO BE DONE IN BETWEEN THE PLUMBING AND THE MAINT. WHS.								
Ruben Ronquillo									
39941					11/7/2008		95		\$0.00
Medium	Work In Progress				11/7/2008 1:06:01 PM				
Ontiveros, Guadalupe	Gooseneck Trailers 2 ea. - Replace damaged floor boards								
Alfredo Holguin									
39986		Pump House			11/11/2008		91		\$0.00
Medium	Work In Progress				11/11/2008 9:16:37 AM				
Jacquez, Ricardo	need to calibrate flow meters at GMS,GHS,CMS & SRE thanks								
Ricardo Jacquez									
41474	Maintenance				1/14/2009		27		\$0.00
Medium	Work In Progress				1/14/2009 8:35:53 AM				
Lara, Ralph	Need to install a new door 46" for new lounge.								
Michael Munoz									
41518	Food Services	Cafeteria			1/15/2009		26		\$0.00
Medium	Work In Progress				1/15/2009 9:29:05 AM				
Moncayo, Fernando	WORK ORDER FOR GADSDEN STUDENT NUTRITION PROGRAM WAREHOUSE - -- MOTOR WENT OUT TO THE FURNACE								
	JOHNNY LECHUGA - SNP WAREHOUSE MGR 882-6927								
Alma Terrell									
41845					1/26/2009		15		\$0.00
Medium	Work In Progress				1/26/2009 12:19:49 PM				
Carbajal, Jimmy	PLEASE DELIVER PADDED CHAIRS TO MESQUITE ELEMENTARY BY JANUARY 28 AND PICK UP ON JANUARY 29 MORNING. REF USE OF BLDG #2009-PENDING								
Jesus Estrada									
41915					1/27/2009		14		\$0.00
Medium	Work In Progress				1/27/2009 4:07:07 PM				
Gonzales, Angel	Mail Van - driver side seat needs additional padding call Alfredo Holguin if you have questions								
Alfredo Holguin									
42126					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:53 AM				
Diaz, Sebastian	Monthly - Physical Plant FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
2/10/2009 3:17:27 PM									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Physical Plant Complex								
42131					2/2/2009		8		\$0.00	
Medium	Work In Progress			2/2/2009 12:23:18 AM						
Villalobos, Margret		Monthly - PPD - Quarterly Meeting - Refer to PM schedule details.								
Margret Villalobos										
42175		Pump House			2/3/2009		7		\$0.00	
Medium	Work In Progress			2/3/2009 8:55:23 AM						
Jacquez, Ricardo		please order water filters for water treatment @ GHS & GMS Thanks								
Ricardo Jacquez										
42215	Maintenance				2/4/2009		6		\$0.00	
Medium	Work In Progress			2/4/2009 8:52:47 AM						
Sotelo, Enrique		Need to remove electrical from old HVAC Shop.								
Manny Lozoya										
42228	Maintenance				2/4/2009		6		\$0.00	
Medium	Work In Progress			2/4/2009 1:23:11 PM						
Miranda, Danny		FRAME AND FURR MAINT.WHS. OPENING TO PLUMBING DANNY MIRANDA								
Danny Carrasco										
42234	Maintenance				2/4/2009		6		\$0.00	
Medium	Work In Progress			2/4/2009 3:22:07 PM						
Lozoya, Manny		NEED TO INSTALL BARREL BOLT ON PLUMB. EXIT DOUBLE DOOR								
Ruben Ronquillo										
42264	Maintenance				2/5/2009		5		\$0.00	
Medium	Work In Progress			2/5/2009 10:40:01 AM						
Sotelo, Enrique		Need to change bulbs in my office.								
Margret Villalobos										
42336					2/6/2009		4		\$0.00	
Medium	Work In Progress			2/6/2009 4:25:43 PM						
Munoz, Michael		need drafting table for tech room.								
Michael Munoz										
42359	Food Services	Electrical Room			2/9/2009		1		\$0.00	
Medium	Work In Progress			2/9/2009 8:24:32 AM						
Sotelo, Enrique		need to Relocated swich box where they installed the new door frame. thank you								
Ralph Lara										
42417	Purchasing				2/10/2009		0		\$0.00	
Medium	Work In Progress			2/10/2009 11:57:17 AM						
Munoz, Michael		Paper Shredder - Shredder gets jamed when more that one sheet of paper is feed into it.								
Alfredo Holguin										

2/10/2009 3:17:27 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

Count: 31 Work Orders Avg. Age of WO's 93 Total for Physical Plant Complex 0 \$0.00

Location: Riverside ES

35708 7/6/2008 8/6/2008 219 \$0.00

Medium Work In Progress 7/6/2008 12:20:10 AM

Villalobos, David Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

35753 New Wing 1/02 7/8/2008 217 \$0.00

Medium Work In Progress 7/8/2008 10:29:47 AM

Ronquillo, Ruben Need window repaired room 137 due to break in 20x21 Add two more broken windows custodian found windows in corrdor by cafe.

Carlos Hernandez

36586 Cafeteria 8/4/2008 190 \$0.00

Medium Work In Progress 8/4/2008 9:53:07 AM

Moncayo, Fernando Oven with Grill is not working/heating up at all.

Emilia Carrillo - SNP Manager 589-2550

Alma Terrell

36587 Cafeteria 8/4/2008 190 \$0.00

Medium Work In Progress 8/4/2008 9:54:27 AM

Moncayo, Fernando Walk-In Refrigerator is leaking alot of water

Emilia Carrillo - SNP Manager 589-2550

Alma Terrell

36669 Cafeteria 8/6/2008 188 \$0.00

Medium Work In Progress 8/6/2008 8:39:54 AM

Carrasco, Danny need fuses for a/c units

Carlos Hernandez

37440 Portables 8/27/2008 167 \$0.00

Medium Work In Progress 8/27/2008 9:30:51 AM

Ronquillo, Ruben broken window on new portable due to vandalism (Case# 2008-1239)

Carlos Hernandez

37732 Portables 9/3/2008 160 \$0.00

Medium Work In Progress 9/3/2008 8:16:37 AM

Ronquillo, Ruben need glass repaired new portable rear glass 40 3/4 by 12 1/2 thanks

Carlos Hernandez

37820 9/5/2008 158 \$0.00

Medium Work In Progress 9/5/2008 8:39:36 AM

Gonzalez, Salvador Need to make a canopy for behind of cafeteria.

Michael Munoz

2/10/2009 3:17:27 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
39543					10/28/2008		105		\$0.00
Medium	Work In Progress			10/28/2008 1:28:41 PM					
Lozoya, Manny		remove lock from the flashing lights -							
Cora Ramirez									
39660					10/31/2008		102		\$0.00
Medium	Work In Progress			10/31/2008 3:06:06 PM					
Lara, Ralph		needs parts for handicap automatic door opener westside door							
Carlos Hernandez									
40264					11/20/2008		82		\$0.00
Medium	Work In Progress			11/20/2008 3:11:28 PM					
Gonzales, Angel		truck seat needs repair truck #21							
Carlos Hernandez									
40877		Cafeteria			12/15/2008		2	1	\$25.00
Medium	Work In Progress			12/15/2008 3:27:13 PM		12/17/2008			
Moncayo, Fernando		alarm showing dirty duct in cafeteria and dirty 2, 16				12/17/08 ck Dimar Report was showing exhaust fan in kitchen alarm. Ck inside and it reflects to kitchen equip, route to Fernie.			
Carlos Hernandez		- J. Ambriz							
40950					12/17/2008		55		\$0.00
Medium	Work In Progress			12/17/2008 3:08:54 PM					
Moncayo, Fernando		range hood systems exhaust fan not operating							
Carlos Hernandez									
41566					1/16/2009		25		\$0.00
Medium	Work In Progress			1/16/2009 9:25:44 AM					
Carbajal, Jimmy		Mr. Carbajal can you fix are wheelbarrow. It's flat, thks dm							
Daniel Mata									
41861		Classroom			1/26/2009		15		\$0.00
Medium	Work In Progress			1/26/2009 3:57:10 PM					
Castillo, Carlos		As per building mechanic no power to part of school							
Carlos Castillo									
42168					2/3/2009		7		\$0.00
Medium	Work In Progress			2/3/2009 8:10:05 AM					
Castillo, Carlos		need plug for main hallway shorted out							
Carlos Hernandez									
42324					2/6/2009		4		\$0.00
Medium	Work In Progress			2/6/2009 2:23:41 PM					
Carbajal, Jimmy		Jimmy we have a vaccum that is not working. thks							
Daniel Mata									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

42327					2/6/2009		4		\$0.00
Medium	Work In Progress				2/6/2009 3:05:29 PM				
Lara, Ralph		need new core for lock on teachers outside bathroom							
Carlos Hernandez									
42348					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress				2/8/2009 12:19:31 AM				
Hernandez, Carlos		Monthly - Riverside ES Playground Insp - Refer to PM schedule details.							

Margret Villalobos

Count: 19 Work Orders Avg. Age of WO's 100 Total for Riverside ES 1 \$25.00

Location: San Miguel ES

37343					8/22/2008		172		\$0.00
Medium	Work In Progress				8/22/2008 3:24:23 PM				
Lozoya, Manny		Asp Mike, please core back to GM 6 or 7 pin.							
39334		Portables			10/21/2008		112		\$0.00
Medium	Work In Progress				10/21/2008 11:17:54				
Estrada, Jesus		Please re-carpet dbl portable northwest corner mescalero.Thxs(#42/goose)				1/12/09 - PENDING AS OF TODAY PER CHUY			

Michael Munoz

39565	Main Building				10/29/2008		104		\$0.00
Medium	Work In Progress				10/29/2008 7:32:46 AM				
Lozoya, Manny		please change cores to where the techs can have access to the back door of the boiler room so they can service equipment.							

Michael Munoz

42231		Portables			2/4/2009		6		\$0.00
Medium	Work In Progress				2/4/2009 2:51:05 PM				
Vega, Danny		Need to clean area where portable was removed.							

Michael Munoz

42335					2/6/2009		4		\$0.00
High	Work In Progress				2/6/2009 4:10:46 PM				
Munoz, Michael		need to pour concrete in a u shape to help divert the rain water to the parking lot for proper drainage and to prevent erosion on the front playground area.							

Michael Munoz

Count: 5 Work Orders Avg. Age of WO's 80 Total for San Miguel ES 0 \$0.00

Location: Santa Teresa ES

35713					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:12 AM				
Villalobos, David		Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.							

Margret Villalobos

2/10/2009 3:17:28 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

37139					8/18/2008		176		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/18/2008 11:44:10 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos		CALI; HAND DRYER IN BOYS RRM. DOES NOT SHUT OFF AT TIMES, AND SOMETIMES STARTS BY ITSELF. NEED FOR YOU TO CHECK IT OUT. I TURNED THE BREAKER OFF , BECAUSE A STUDENT BURNED HIMSELF ON IT AND REPORTED IT TO THE OFFICE.							
------------------	--	--	--	--	--	--	--	--	--

Gerardo Marquez

37687		Classroom			9/2/2008		161		\$0.00
-------	--	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/2/2008 11:24:37 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ronquillo, Ruben		One window on Portable is jammed intruder tried to get in thru window on east portable, also middle hallway workroom broken (window) cracked -B-Wing. (Case# 2008-08926)							
------------------	--	--	--	--	--	--	--	--	--

Pablo Diaz

37927					9/8/2008		155		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/8/2008 3:57:59 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo		9/4/08				9/4-8			
		1-INSP. BLDG. & GRNDS. PICKED UP TRASH. 2-CLEANED OFF ENTRANCES & SIDEWALKS. 1-CLEANED & IJNSP. P.G. AREAS. 2-ADJ. LOCKSETS, & DR. CLOSERS @ PORTABLES A, & B. 2-CLEANED & INSP. MECH. RMS.							

Gerardo Marquez

39918	Main Building	Restroom (Girls)			11/6/2008		96		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	ladies restroom			11/6/2008 3:11:24 PM				
--------	------------------	-----------------	--	--	----------------------	--	--	--	--

Marquez, Gerardo		Large spacing in between the wall and other toilet partition needs to be covered. The gap is large enough to see other people inside the stall. Thank you.							
------------------	--	--	--	--	--	--	--	--	--

Rita Mendez

41235		Cafeteria			1/7/2009		34		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/7/2009 10:45:02 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando		NEED DOOR BELL FOR BACK DOO (DELIVERY)							
-------------------	--	--	--	--	--	--	--	--	--

		PAT SANCHEZ STE SNP MGR 589-3439							
--	--	----------------------------------	--	--	--	--	--	--	--

Jacqueline Aguilar

41278		Classroom			1/8/2009		33		\$0.00
-------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	RM 102			1/8/2009 3:18:53 PM				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Marquez, Gerardo		NEED RACK FOR JACKETS TO SET UP IN CLASSROOM 102							
------------------	--	--	--	--	--	--	--	--	--

Rita Mendez

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa ES

41431					1/13/2009		28		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/13/2009 10:52:36 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Villalobos, David
 DAVID, FAUCET @ SINK IN TEACHERS LOUNGE NEEDS TO BE REPLACED. (FAUCET HAS BEEN LEAKING, AND IS GETTING WORSE.) THANKS.

Gerardo Marquez

41432					1/13/2009		28		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/13/2009 10:54:08 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Villalobos, David
 DAVID, FAUCET TO SINK IN B. RRM. NEEDS TO BE REPLACED. (FAUCET WILL NOT SHUT OFF.)

Gerardo Marquez

41433					1/13/2009		28		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/13/2009 10:57:59 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Villalobos, David
 DAVID, FLUSH LEVERS IN TEACHERS RRMS. IN B, & C WING NEED TO BE REPLACED. HANDLES ARE BROKEN.

Gerardo Marquez

41480					1/14/2009		27		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/14/2009 10:43:44 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ronquillo, Ruben
 RUBEN/CALI;
 AS PER YOUR REQUEST I AM RESUBMITTING MY REQUEST FOR A REPLACEMENT COVER FOR THE LIGHT FIXTURE ABOVE THE MAIN LIBRARY ENTRANCE. GEORGE W/CED HAS ALREADY COME TO STE, AND HAS ALL THE INFORMATION ABOUT THE FIXTURE. THANKS.

Gerardo Marquez

41525	Main Building	Portables			1/15/2009		26		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	music portable		1/15/2009 9:57:13 AM					
--------	------------------	----------------	--	----------------------	--	--	--	--	--

Marquez, Gerardo
 3 MUSIC STANDS NEED TO BE ASSEMBLED.

Rita Mendez

41990					1/29/2009		12		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/29/2009 1:38:38 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Moncayo, Fernando
 FERNIE; THE HANDWASHING STATIONS IN THE CAFET. PREP AREA ARE BOTH RUNNING CONTINUOUSLY. WOULD YOU PLEASE CORRECT THE PROBLEM.

Gerardo Marquez

42045					1/30/2009		11		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

High	Work In Progress			1/30/2009 3:31:19 PM					
------	------------------	--	--	----------------------	--	--	--	--	--

Munoz, Michael
 sidewalk was washed out when it rained. need to replace sidewalk.

Michael Munoz

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

42081					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:37 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
42082					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:37 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
42083					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:38 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
42226	Main Building	Parking Lot			2/4/2009		6		\$0.00
Medium	Work In Progress	BUS			2/4/2009 12:02:12 PM				
Marquez, Gerardo		NEED LANES PAINTED AT BUS PICKUP AREA. LANES NEEDED TO LINE UP STUDENTS FOR BUS LOADING. THANK YOU.							
Rita Mendez									
42349					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress				2/8/2009 12:19:32 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
42406	Main Building	Hallway/Corridor			2/10/2009		0		\$0.00
Medium	Work In Progress	hallway			2/10/2009 9:38:34 AM				
Marquez, Gerardo		4 large bulleting boards need to be set up in the hallways. need assistance in setting them up due to the size of board. thanks.							
Rita Mendez									
Count: 20 Work Orders								Total for Santa Teresa ES	0
									\$0.00

Location: Santa Teresa HS

35520		Football Field			7/2/2008		223		\$0.00
Medium	Work In Progress				7/2/2008 8:03:34 AM				
Castillo, Carlos		NEED TO HAVE ONE LIGHT AT FOOTBALL FIELD CHECKED, NOT LIGHTING, WESTSIDE OF FIELD, BEHIND PRESSBOX.							
Arturo Nunez									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

35552					7/6/2008	7/12/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:19:21 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
35569					7/6/2008	7/14/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:19:26 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
35666					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:19:56 AM				
Nunez, Arturo		Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35689					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:04 AM				
Nunez, Arturo		Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35711					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:11 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36510					8/3/2008	8/9/2008	191		\$0.00
Medium	Work In Progress				8/3/2008 12:20:16 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
36645	Cafeteria (2005)	Cafeteria			8/5/2008		189		\$0.00
Medium	Work In Progress				8/5/2008 1:01:49 PM				
Moncayo, Fernando		WATER IS LEAKING FROM UNDERNEATH THE DISHWASHING MACHINE							
		OLGA BUSTAMANTE - SNP MANAGER 589-9836							
Alma Terrell									
37137	Cafeteria (2005)	Cafeteria			8/18/2008		176		\$0.00
Medium	Work In Progress				8/18/2008 11:08:29 AM				
Moncayo, Fernando		Washing Machine is leaking water (underneath machine) - Left message with Fernando							
		Olga Bustamante - SNP Manager 589-5332							
Alma Terrell									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

37386					8/26/2008		168		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/26/2008 7:30:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Pedestrian Gate on South side that goes to the Bluffs. - Install taller gate to prevent access through bottom of gate.

Alfredo Holguin

37545					8/31/2008	9/6/2008	163		\$0.00
-------	--	--	--	--	-----------	----------	-----	--	--------

Medium	Work In Progress				8/31/2008 12:25:12 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Nunez, Arturo Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

37958					9/9/2008		154		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/9/2008 2:33:14 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos NEED SOME ASSISTANCE ON CHECKING OUTSIDE LIGHTING ON CAF. NEW BUILDING, VOC. BUILDING, AND MAIN BUILDING.

Arturo Nunez

38073					9/14/2008		149		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/14/2008 12:23:08 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe Monthly - Santa Teresa HS Soil Sampling - Refer to PM schedule details.

Margret Villalobos

38255		Classroom			9/19/2008		144		\$0.00
-------	--	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	RM 207			9/19/2008 12:14:53 PM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Villalobos, Margret Unit is working fine, problem with comm link, need to contact Trane. Asp Jose Ambriz, need to schedule, when there is no students.

Jose Ambriz

38257					9/19/2008		144		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/19/2008 2:26:25 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose WE NEED SOME INSULATION FOR DUCTWORK IN ROOM 12.

Manuel Prospero

38346					9/23/2008		140		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/23/2008 9:02:34 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose THE FOLLOWING F.C.U.'S HAVE A COMMUNICATION PROBLEM BETWEEN MASTER AND SLAVE, 207M SCC IS OF LINE, 205M SCC IS OFF LINE, AND 203 SCC IS IF LINE. CAN WE PLEASE HAVE THEN CHECKED. THANK YOU.

Arturo Nunez

38539					9/30/2008		133		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/30/2008 12:26:04 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Prospero, Manuel Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.

Margret Villalobos

2/10/2009 3:17:28 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

38544	Cafeteria (2005)	Cafeteria			9/30/2008		133		\$0.00
Medium	Work In Progress			9/30/2008 8:10:55 AM					
Moncayo, Fernando	Comments from Ecolab Report: Dishwasher is not filling up. Pre-spray hose id damaged & should be replaced. Olga Bustamante SNP MANAGER 58905332								
Jacqueline Aguilar									
38595	Gymnasium				10/1/2008		132		\$0.00
Medium	Work In Progress			10/1/2008 12:31:34 PM					
Nunez, Arturo	REPLACE STAINED AND BROKEN CIELING TILES								
Michael Munoz									
38691					10/3/2008		130		\$0.00
Medium	Work In Progress			10/3/2008 7:59:21 AM					
Gonzalez, Salvador	FRONT GATE NEEDS A GATE STOPER 6 GATE HINGES POLE IS 7 INCH WIDE 1 GATESTOPPER 1 POLE FOR GATE STOPPER.					12/17 - Asp Mike route to Sal.			
Manuel Prospero									
38753					10/5/2008	10/11/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:23:53 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
38754					10/5/2008	10/13/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:23:53 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
38755					10/5/2008	10/26/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
Margret Villalobos									
38756					10/5/2008	11/5/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Yearly - Santa Teresa HS H-6 Rftop Furn Yearly - Refer to PM schedule details.								
Margret Villalobos									
38757					10/5/2008	11/5/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Yearly - Santa Teresa HS R-9 Radiator Ht Wtr 2yr - Refer to PM schedule details.								
Margret Villalobos									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

38758					10/5/2008	10/21/2008	128		\$0.00
Medium	Work In Progress			10/5/2008 12:23:55 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
Margret Villalobos									
39164					10/12/2008	10/28/2008	121		\$0.00
Medium	Work In Progress			10/12/2008 12:21:05					
Nunez, Arturo	Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.								
Margret Villalobos									
39344					10/21/2008		112		\$0.00
Medium	Work In Progress			10/21/2008 3:13:05 PM					
Villalobos, David	NEED SOME ASSISTANCE ON LEAK TEST GAS LINES ON WELDING BOTHS, THERE SEEMS TO BE A GAS LEAK, BUT CAN'T LOCATE.								
Arturo Nunez									
39396	Main Building	Choral			10/22/2008		111		\$0.00
Medium	Work In Progress			10/22/2008 3:57:04 PM					
Lara, Ralph	Door from Band Room Top Corner broken, needs to be replaced Thank you, Rosa								
Rosa Hood									
39398	Main Building	Hallway/Corridor			10/22/2008		111		\$0.00
Medium	Work In Progress			10/22/2008 3:59:35 PM					
Prospero, Manuel	Remove lockers in hallway near counseling area and across from Main office Thank you, Rosa								
Rosa Hood									
39542	Main Building	Office			10/28/2008		105		\$0.00
Medium	Work In Progress			10/28/2008 1:18:25 PM					
Nunez, Arturo	We need signs to indicate what building is what since we do not have a front entrance. Please feel free to call me or Art Nunez so that we can be more specific Thank you, Rosa		1/23/09 - Art asp our conversation you would take care of it and asp Mike please submit request for signs. - Thank You Ruben						
Rosa Hood									
39648					10/31/2008		102		\$0.00
Medium	Work In Progress			10/31/2008 9:49:48 AM					
Castillo, Carlos	NEED SOME ASSISTANCE WITH A WALL PLUG, AND PIG TAIL FOR KILN IN ROOM # 601. THEY ARE FRIED, NEED TO BE REPLACED.								
Arturo Nunez									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

39695					11/2/2008	11/8/2008	100		\$0.00
Medium	Work In Progress				11/2/2008 12:24:36 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
39730					11/2/2008	11/10/2008	100		\$0.00
Medium	Work In Progress				11/2/2008 12:24:49 AM				
Prospero, Manuel		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39740					11/2/2008	11/10/2008	100		\$0.00
Medium	Work In Progress				11/2/2008 12:24:53 AM				
Prospero, Manuel		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
40146					11/6/2008		96		\$0.00
Medium	Work In Progress				11/17/2008 2:07:57 PM				
Ronquillo, Ruben		BROKEN WINDOW IN SHOP 2.							
Jose Angelo									
40365					11/30/2008	12/6/2008	72		\$0.00
Medium	Work In Progress				11/30/2008 12:23:29				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
George ZZ_Gabaldon									
40425					11/30/2008	12/8/2008	72		\$0.00
Medium	Work In Progress				11/30/2008 12:23:49				
Prospero, Manuel		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
George ZZ_Gabaldon									
40426					11/30/2008	12/8/2008	72		\$0.00
Medium	Work In Progress				11/30/2008 12:23:50				
Prospero, Manuel		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
George ZZ_Gabaldon									
40653					12/7/2008	12/23/2008	65		\$0.00
Medium	Work In Progress				12/7/2008 12:16:16 AM				
Prospero, Manuel		Monthly - Santa Teresa HS Playground Insp - Refer to PM schedule details.							
George ZZ_Gabaldon									
40852					12/14/2008		58		\$0.00
Medium	Work In Progress				12/14/2008 12:16:33				
Ontiveros, Guadalupe		Monthly - Santa Teresa HS Soil Sampling - Refer to PM schedule details.							
George ZZ_Gabaldon									

2/10/2009 3:17:28 PM

Page 103 of 124

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

40873					12/15/2008		57		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/15/2008 2:57:45 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos
NEED A 115V ELEC. OUTLET INSTALLED ON CONFERENCE ROOM IN LIBRARY, FOR POWER POINT PROJECTOR.

Arturo Nunez

41042					1/4/2009	1/10/2009	37		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/4/2009 12:18:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo
Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

41059					1/4/2009	1/12/2009	37		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				1/4/2009 12:18:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo
Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.

Margret Villalobos

41154					1/5/2009		36		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/5/2009 8:52:07 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David
NEED SOME ASSISTANCE ON CHECKING MANHOLE BY GAS METER, ON EAST SIDE. METHANE GAS LEVEL READING IS A 8 , AS PER P.N.M. TECH. WOULD LIKE TO HAVE IT CHECKED OUT.

Arturo Nunez

41307	Dressing Rooms	Dressing Room			1/9/2009		32		\$0.00
-------	----------------	---------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/9/2009 8:54:39 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Nunez, Arturo
Boys athletic lockers need to be bolted down for safety reasons
This is the second request
Someone is going to get hurt with a falling bank of lockers
Art Nunez had previously submitted a work order and has spokent to someone at the GAC/Warehouse regarding this situation
1/15 - Route to Art asp Mike

Rosa Hood

41316	Main Building	Office			1/9/2009		32		\$0.00
-------	---------------	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/9/2009 12:47:04 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Estrada, Jesus
Main Office carpet needs to be replaced
Carpet is at least 15 years old
It is a safety issue - duct tape is holding it together at door entrances
Mr. Kelch and Mrs. Hood
Was measured
picked color

Rosa Hood

41337		Athletic Field			1/10/2009		31		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/10/2009 9:40:16 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
Track was damaged last year when work was being done on irrigation system. The track has not been repaired and this is a safety issue for all our students for this Track season. Please see coach Solis or Mrs. Hood

Rosa Hood

2/10/2009 3:17:28 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Santa Teresa HS								
41374					1/11/2009	1/27/2009	30		\$0.00	
Medium	Work In Progress			1/11/2009 12:17:30 AM						
Prospero, Manuel	Monthly - Santa Teresa HS Playground Insp - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
41535					1/15/2009		26		\$0.00	
Medium	Work In Progress			1/15/2009 3:17:47 PM						
Castillo, Carlos	NEED TO HAVE ELECTRICIAN COME AND SEE IF ELEC. SERVICE CAN BE INSTALLED ON ROOM # 30 WHERE NEW KILNS WILL BE INSTALLED. WILL NEED TWO DISCONNECT BOXES, ONE WITH 90A FUSES. ANOTHER WITH 40 A. FUSES.									
<u>Arturo Nunez</u>										
41538					1/15/2009		26		\$0.00	
Medium	Work In Progress			1/15/2009 3:24:46 PM						
Ambriz, Jose	NEED SOME ASSISTANCE ON CHECKING F.C.U. ON NEW ROOMS MASTER AND SLAVES ARE NOT COMMUNICATING WITH EACH OTHER AND ARE DOING THEIR OWN THING.									
<u>Arturo Nunez</u>										
41629					1/20/2009		21		\$0.00	
Medium	Work In Progress			1/20/2009 8:21:41 AM						
Ontiveros, Guadalupe	Remove equipment asp attached pictures and e-mail.									
<u>Michael Munoz</u>										
41641	Concession	Athletic Field			1/20/2009		21		\$0.00	
Medium	Work In Progress			1/20/2009 11:07:51 AM						
Ontiveros, Guadalupe	Mr. Bailon baseball coach needs a concession stand moved to the baseball field This has been approved by Mr. Phelps and Mr. Kelch Thank you, Rosa					Coach Bailon bought a concession stand for the baseball field Thank you, Rosa				
<u>Rosa Hood</u>										
41643	Applied Science	Classroom			1/20/2009		21		\$0.00	
Medium	Work In Progress			1/20/2009 11:12:21 AM						
Castillo, Carlos	A storagae room is being turned back into an art studio we need the electrical for the kiln. Please see Art Nunez Thank you, Rosa					Mr. Kelch has approved the use of the storage room be transformed into an art studio. Art Nunez is aware of what electrical set up is needed. If there is a cost we need an estimate. Mr. Kelch only has \$200 to work on this project. Thank you, Rosa				
<u>Rosa Hood</u>										
41676		Mechanical Room			1/21/2009		20		\$0.00	
Medium	Work In Progress			1/21/2009 7:46:29 AM						
Castillo, Carlos	As per M.Munoz,contact EPEC about severe electrical phase inbalance at Sta.Teresa Hi affecting the chiller.									
<u>Carlos Castillo</u>										
2/10/2009 3:17:28 PM										

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

41699	Gymnasium	Hallway/Corridor			1/21/2009		20		\$0.00
-------	-----------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/21/2009 2:21:21 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel		Mr. Kelch has asked that we retile the hallway between the old and new gym. He spoke with Manuel Prospero about the tiles (they need to be the same color and pattern) Thank you, Rosa				Mr. Kelch has spoken with Manny Prospero regarding tiles that need to be ordered and changed throughout the building Thank you, Rosa			
------------------	--	--	--	--	--	--	--	--	--

Rosa Hood

41751	Annex Building	Classroom			1/22/2009		19		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/22/2009 3:19:52 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo		Anchor the serving sets to the ground and need to make a safety zone under the servings Thank you				License inspection 1-15-09 2/9 - Mailed to Art asp Mike			
---------------	--	--	--	--	--	--	--	--	--

Rosa Hood

41752	Annex Building	Classroom			1/22/2009		19		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	DAYCARE			1/22/2009 3:21:49 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Nunez, Arturo		Replace all stained ceiling tiles Thank you, Rosa				License inspection 1-15-09			
---------------	--	---	--	--	--	----------------------------	--	--	--

Rosa Hood

41753	Annex Building	Classroom			1/22/2009		19		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/22/2009 3:23:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Estrada, Jesus		Linolium in both bathrms need to be replaced and floor tiles at each exit need to be replace and any around the day care center Thank you, Rosa				License inspection 1-15-09			
----------------	--	---	--	--	--	----------------------------	--	--	--

Rosa Hood

41929		Classroom			1/28/2009		13		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	MR.			1/28/2009 9:21:25 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Nunez, Arturo		NEED TO INSTALL PROJECTION TV-DIGITAL RECORDING SYSTEM-PROJECTION SCREEN-AND TIE IN HD DVD-MULTI CHANNEL AV RECEIVER-STEREO CASSETTE DECK-BBE PROCESSOR. PLEASE VISIT WITH MR. RIVERA ON THESE INSTALLATIONS.							
---------------	--	---	--	--	--	--	--	--	--

Jimenez, Marylou

42057					2/1/2009	2/7/2009	9		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/1/2009 12:24:28 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

2/10/2009 3:17:28 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
42106					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:46 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42107					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:46 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42108					2/1/2009	3/4/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:46 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
42179					2/3/2009		7		\$0.00
Medium	Work In Progress	DAYCARE		2/3/2009 11:20:50 AM					
Prospero, Manuel	WE NEED A THERMOCOUPLE TO CHANGED ON DAY CARE HEATER.		2/10 - Asp Mike route back to Manuel.						
Manuel Prospero									
42254	Cafeteria (2005)	Cafeteria			2/5/2009		5		\$0.00
Medium	Work In Progress			2/5/2009 8:03:17 AM					
Carrasco, Danny	Need to deliver scissor lift to Sta.Teresa Hi as early as possible on 2-12-09.Danny Carrasco.								
Carlos Castillo									
42262	Main Building	Office			2/5/2009		5		\$0.00
Medium	Work In Progress			2/5/2009 9:16:53 AM					
Lara, Ralph	We need to repair locks on fire proof cabinets in the counseling office that house student records Make an extra set of keys for all cabinet in the counseling center Thank you, Rosa		We have spoken with Rafa (Mr. Lara and Art Nunez)						
Rosa Hood									
42350					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress			2/8/2009 12:19:32 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
42371					2/9/2009		1		\$0.00
Medium	Work In Progress			2/9/2009 10:06:22 AM					
Prospero, Manuel	1HR STARTED 600;S HEATERS. 3HRS WORKING ON LIBRARY HEATER. 4HRS MOVE OLD FURNITURE TO ANTHONY, MITTIN WIHT MIKE MUNOS AND CHEK WORK TROCK.		2/6-8						
Manuel Prospero									
2/10/2009 3:17:28 PM									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

42379					2/9/2009		1		\$0.00
Medium	Work In Progress			2/9/2009 1:51:03 PM					
Ambriz, Jose	Need to check chiller, EP Electric did their part already.								
Michael Munoz									
42380	Main Building	Classroom			2/9/2009		1		\$0.00
Medium	Work In Progress			2/9/2009 2:48:13 PM					
Lara, Ralph	Need to replace door knob for room 308 please					Mr. Nunez has already removed the door knob			
	Thank you, Rosa								
Rosa Hood									
42416	Applied Science	Classroom			2/10/2009		0		\$0.00
Medium	Work In Progress			2/10/2009 11:50:45 AM					
Lara, Ralph	Room 14 Mrs. Hyde needs to be re keyed please					Cleared with Mr. Phelps			
	Thank you, Rosa								
Rosa Hood									
Count: 72 Work Orders			Avg. Age of WO's 86			Total for Santa Teresa HS	0		\$0.00

Location: Santa Teresa MS

35712					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress			7/6/2008 12:20:11 AM					
Villalobos, David	Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
36170	North Building	Custodial			7/24/2008		201		\$0.00
Medium	Work In Progress			7/24/2008 7:42:22 AM					
Gonzales, Angel	pete,the truck 39 needs a complete tune up i need to have it ready for the school year.thank you.								
Ismael Rodriguez									
36511					8/3/2008	8/9/2008	191		\$0.00
Medium	Work In Progress			8/3/2008 12:20:17 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
36903	North Building	Classroom			8/11/2008		183		\$0.00
Medium	Work In Progress	Room 3A			8/11/2008 3:12:40 PM				
Mijarez, Jaime	1. Portable leaks when it rains.								
Laura Parra									
37603					8/31/2008	9/6/2008	163		\$0.00
Medium	Work In Progress			8/31/2008 12:25:31 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

2/10/2009 3:17:28 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

37771	Gym (1997)				9/4/2008		159		\$0.00
High	Work In Progress				9/4/2008 8:21:25 AM				
Mijarez, Jaime	please reroute overflow lines from a/c. do not drain into mop sink and install strainer also. this will prevent from sink overflowing and damaging gym floor. (2nd time)								
Michael Munoz									
37808					9/4/2008		159		\$0.00
Medium	Work In Progress				9/4/2008 4:13:04 PM				
Munoz, Michael	North Bldg. - Build concrete Pad for dumpsters.								
Alfredo Holguin									
38251	Library	Library			9/19/2008		144		\$0.00
Medium	Work In Progress	Ms. Swaim-			9/19/2008 10:10:45 AM				
Castillo, Carlos	Need power strip for the wall. The outlets are overloaded. Wires and cords need to be contained.								
Parra, Laura									
38535					9/30/2008		133		\$0.00
Medium	Work In Progress				9/30/2008 12:26:01 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.								
Margret Villalobos									
38596					10/1/2008		132		\$0.00
Medium	Work In Progress				10/1/2008 12:33:20 PM				
Soria, Mike	CUT WEEDS AT NEW LANDSCAPING IN FRONT OF SOUTH BUILDING.								
Michael Munoz									
38597					10/1/2008		132		\$0.00
Medium	Work In Progress				10/1/2008 12:34:21 PM				
Soria, Mike	OPEN DRAIN BY MORGAN BUILDING. CUT WEEDS AND BARRICADE. SAFETY HAZARD.								
Michael Munoz									
38869					10/5/2008	11/5/2008	128		\$0.00
Medium	Work In Progress				10/5/2008 12:24:36 AM				
Mijarez, Jaime	Yearly - Santa Teresa MS U2 (Heat Gas)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
39102	North Building	Classroom			10/10/2008		123		\$0.00
Medium	Work In Progress	Room 1			10/10/2008 2:36:56 PM				
Mijarez, Jaime	Hand made wooden case in recognition hall needs to be installed on the wall. The case will need a 2x6 wooden base, plexiglass doors and mounting hardware								
Laura Parra									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

39113	South Building	Office			10/10/2008		123		\$0.00
Medium	Work In Progress	Assistant			10/10/2008 3:39:59 PM				
Castillo, Carlos		Need computer outlet and phone outlet to be placed on the opposite wall as to where its actually at							
Laura Parra									
39335					10/21/2008		112		\$0.00
Medium	Work In Progress				10/21/2008 12:48:47				
Ambriz, Jose		N.bldg Hp 36 lobby has a bad motor that is making a loud noise.							
Jaime Mijarez									
39406					10/23/2008		110		\$0.00
Medium	Work In Progress				10/23/2008 7:58:22 AM				
Castillo, Carlos		See if we can repair the timers and order additional triggers. (see Jaime if you have any questions).							
Michael Munoz									
40169					11/18/2008		84		\$0.00
Medium	Work In Progress				11/18/2008 9:33:58 AM				
Ronquillo, Ruben		N.bldg office exterior windows. Replace 2nd glass window with new aluminum molding. Existing molding is to corroded. Replace aluminum molding around glass window that was replaced for W/O #39295. I checked molding around window and it is too damaged.							
Jaime Mijarez									
40475	South Building	Choral			12/2/2008		70		\$0.00
Medium	Work In Progress	Outside Choir			12/2/2008 8:05:57 AM				
Gonzalez, Salvador		Replace the old worn out gate behind the south building and relocate by the corner of the south building with a new one. (A safety measure)							
Laura Parra									
40476	North Building	Portables			12/2/2008		70		\$0.00
Medium	Work In Progress	Outside by			12/2/2008 8:09:53 AM				
Gonzalez, Salvador		North building by the portable-- Place a gate by the portables so we could keep people from driving their cars around the north building to get to the gym. (A SAFETY MEASURE)							
Laura Parra									
40826					12/12/2008		60		\$0.00
Medium	Work In Progress				12/12/2008 9:18:30 AM				
Castillo, Carlos		Nurses office. I am loosing power to recepticles on one section of walls. I am going to need your help on this one, I am having a hard time pin pointing the problem.							
Jaime Mijarez									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

41024					12/31/2008		41		\$0.00
Medium	Work In Progress				12/31/2008 12:18:22				
Mijarez, Jaime	Yearly - Santa Teresa MS H6(Roof Furnace)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
41216	South Building				1/6/2009		35		\$0.00
Medium	Work In Progress				1/6/2009 4:25:30 PM				
Soria, Mike	please cut weeds in culvert by ground morgan bldg.								
Michael Munoz									
41530					1/15/2009		26		\$0.00
Medium	Work In Progress				1/15/2009 2:58:36 PM				
Villalobos, David	Install new septic tank.								
Michael Munoz									
41632	North Building	Custodial			1/20/2009		21		\$0.00
Medium	Work In Progress				1/20/2009 8:39:52 AM				
Gonzales, Angel	pete, the truck 39 needs the the oil change i will be taking it in during this week thank you.								
Ismael Rodriguez									
41839	North Building	Office			1/26/2009		15		\$0.00
Medium	Work In Progress				1/26/2009 10:05:06 AM				
Ronquillo, Ruben	N.bldg office. Need to replace one more window.								
Jaime Mijarez									
42093					2/1/2009	3/4/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:41 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
42094					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:42 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
42095					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:42 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42096					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:42 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

42136					2/2/2009		8		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress			2/2/2009 8:11:10 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ambriz, Jose
Portable has no heat. One of the units went down and teacher will be using library with students, classroom is to cold.

Jaime Mijarez

42145					2/2/2009		8		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress			2/2/2009 12:33:14 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose
Both Mr Meraz and Salaz portables will need new thermostats. Joe already did the troubleshooting on both units.

Jaime Mijarez

42186	Gym (1997)	Gym			2/3/2009		7		\$0.00
-------	------------	-----	--	--	----------	--	---	--	--------

Medium	Work In Progress			2/3/2009 1:28:34 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Villalobos, David
theres a urinal that is overflowing in the boys dressing room . i tried it with a plunger but the problem doesnt seem to work.thank you.

Ismael Rodriguez

42210	North Building	Portables			2/4/2009		6		\$0.00
-------	----------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress			2/4/2009 7:52:53 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ontiveros, Guadalupe
Lupe can you send a small tractor to clear the sand that is build up around the ramps and stairways of the portables.so can you let us borrow a small tractor and i will help mr. soria. And also along the sidewalks of the northbuilding thank you.

Ismael Rodriguez

42307	North Building	Classroom			2/6/2009		4		\$0.00
-------	----------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	Room 9		2/6/2009 9:25:56 AM					
--------	------------------	--------	--	---------------------	--	--	--	--	--

Lara, Ralph
Lost classroom room key. Need a new key

Laura Parra

42366	Gym (1997)	Gym			2/9/2009		1		\$0.00
-------	------------	-----	--	--	----------	--	---	--	--------

Medium	Work In Progress	Mr. Richardson		2/9/2009 9:18:48 AM					
--------	------------------	----------------	--	---------------------	--	--	--	--	--

Lara, Ralph
Filing cabinet has been re-keyed but key that was issued does not work.

Laura Parra

42386					2/9/2009		1		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress			2/9/2009 3:06:45 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Gonzalez, Salvador
Gym metal door girls dressing room. Need welder and help to repair exterior metal door.

Jaime Mijarez

42405	South Building				2/10/2009		0		\$0.00
-------	----------------	--	--	--	-----------	--	---	--	--------

Safety	Work In Progress			2/10/2009 9:34:32 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben
Missing Fire Extinguisher - FXT-029 and FXT-033 asp PM 41043.

Jaime Mijarez

2/10/2009 3:17:28 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

42409	North Building	Office			2/10/2009		0		\$0.00
Medium	Work In Progress	Ms. Casillas/Ms.			2/10/2009 10:34:31 AM				
Lara, Ralph	Please re-key Ms. Lovelace's and Ms. Casillas office for testing materials to be stored.								

Laura Parra

Count: 38 Work Orders	Avg. Age of WO's 76	Total for Santa Teresa MS	0	\$0.00
------------------------------	----------------------------	----------------------------------	----------	---------------

Location: Sunland Park ES

35710					7/6/2008	8/6/2008	219		\$0.00
Medium	Work In Progress				7/6/2008 12:20:11 AM				
Villalobos, David	Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.								

Margret Villalobos

37362					8/25/2008		169		\$0.00
Medium	Work In Progress				8/25/2008 2:14:46 PM				

Lara, Ralph WE NEED REPLACE CLASS ROOMS DOORS THEY ARE TO RUSTING

Joel Herrera

37891	Main Building				9/8/2008		155		\$0.00
Medium	Work In Progress				9/8/2008 9:02:24 AM				

Ronquillo, Ruben FXT-SP-030 - Missing Boiler Room (S) asp PM 37589

Joel Herrera

38310					9/22/2008		141		\$0.00
Medium	Work In Progress	outside			9/22/2008 2:14:13 PM				

Herrera, Joel Please replace broken tiles located by the main entrance.

Jessica Lopez

38468					9/26/2008		137		\$0.00
Medium	Work In Progress				9/26/2008 1:25:56 PM				

Castillo, Carlos MS. PEREZ WANTS TWO OUTLETS AT PLAYGROUNDS AREA IF WE CAN DO POSSIBLE. THANK YOU CALI

Joel Herrera

38801					10/5/2008	10/26/2008	128		\$0.00
Medium	Work In Progress				10/5/2008 12:24:11 AM				

Orozco, Danny Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

38958					10/6/2008		127	1	\$25.00
Medium	Work In Progress	library			10/6/2008 12:29:14 PM				

Herrera, Joel Attach electrical strip to new computer cart.

Jessica Lopez

10/24 -NON ELECTRICAL, NEED BM TO OBTAIN A POWER SURGE STRIP AND INSTALL HIMSELF. C. CASTILLO. Route to Joel 11/3/08

2/10/2009 3:17:28 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

39888					11/6/2008		96		\$0.00
Medium	Work In Progress				11/6/2008 8:12:18 AM				
Gonzalez, Salvador		WE NEED REPLACE CONCRET WALL AND STEEL GATE AT OUTSIDE AREA							
Joel Herrera									
40113					11/14/2008		0		\$0.00
Medium	Work In Progress				11/14/2008 3:14:33 PM	11/14/2008			
Rivera, Hector		Pick up trash all along the north side fence.				12/3/08 REFAXED TO HECTOR			
Jesus Estrada									
40288					11/21/2008		81		\$0.00
Medium	Work In Progress				11/21/2008 9:15:30 AM				
Herrera, Joel		Mr. Herrera please paint the red emergency lines located in front of the school.							
Jessica Lopez									
40679		Cafeteria			12/8/2008		64		\$0.00
Medium	Work In Progress				12/8/2008 3:30:26 PM				
Moncayo, Fernando		DISHWASHER NEEDS TO BE REPAIRED. NOT WORKING AT ALL.							
		MARINA RAMIREZ SNP MGR 589-2545							
Jacqueline Aguilar									
41299		Cafeteria			1/8/2009		33		\$0.00
Medium	Work In Progress				1/8/2009 4:08:12 PM				
Moncayo, Fernando		Dishwasher is down - System corroded - Not working at all							
		Marina Ramirez - SNP Manager 589-2545							
Alma Terrell									
41300		Cafeteria			1/8/2009		33		\$0.00
Medium	Work In Progress				1/8/2009 4:09:11 PM				
Moncayo, Fernando		Hobart Mixer - Dropping oil and making a grinding sound							
		Marina Ramirez - SNP Manager 589-2545							
Alma Terrell									
41497		Cafeteria			1/14/2009		27		\$0.00
Medium	Work In Progress				1/14/2009 2:24:17 PM				
Moncayo, Fernando		Hose to dishwashing area is all cracked - leaking water everywhere							
		Marina Ramirez - SNP Manager 589-2545							
Alma Terrell									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Sunland Park ES

41647					1/20/2009		21		\$0.00
Medium	Work In Progress			1/20/2009 12:22:40 PM					
Ontiveros, Guadalupe	Ms. Perez would like speed bumps to go around the school.								
Jessica Lopez									
41960					1/28/2009		13		\$0.00
Medium	Work In Progress			1/28/2009 3:28:44 PM					
Ambriz, Jose	MR. AMBRIZ WE NEED TO REPLACE MASTERCOOLS 65S AT CLASS ROOMS 10, 11, 17 AND 23 THANK YOU JOSE								
Joel Herrera									
42090					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:40 AM					
Herrera, Joel	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42091					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:40 AM					
Herrera, Joel	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
42092					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:41 AM					
Herrera, Joel	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42161		Cafeteria			2/2/2009		8		\$0.00
Medium	Work In Progress			2/2/2009 4:00:22 PM					
Moncayo, Fernando	2-compartment Veg. Sink is leaking.								
	Marina Ramirez SNP Mgr 589-2545								
Jacqueline Aguilar									
42235					2/4/2009		6		\$0.00
Medium	Work In Progress			2/4/2009 3:26:24 PM					
Lara, Ralph	WE NEED TO SECURED MALLEN ON SOUTH SIDE EXIT DOOR'S A.S.P THANK YOU RAFA								
Joel Herrera									
42260					2/5/2009		5		\$0.00
Medium	Work In Progress			2/5/2009 8:57:09 AM					
Ontiveros, Guadalupe	LUPE WE NEED TO REPLACE SPRINKLES TIMER IT DOESNT WORK THANK YOU								
Joel Herrera									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Sunland Park ES

42277					2/5/2009		5		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress			2/5/2009 2:28:04 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lara, Ralph WE NEED TO REPLACE CAMLOCK CABINETS AT NURSE OFFICE THANK YOU RAFA

Joel Herrera

42313					2/6/2009		4		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress			2/6/2009 10:05:17 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, Margret LICE IN 4 CLASS ROOMS (#39, 17, 24 & 27). NEED TO HAVE WATSON EXTERMINATE THIS AFTERNOON ANY TIME AFTER NOON TIME (PLEASE LET US KNOW APPROX WHAT TIME THEY CAN BE THERE).THANKS! Watson will be going out this afternoon. 2/6/09 - mkv

Jesus Estrada

42351					2/8/2009	2/24/2009	2		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress			2/8/2009 12:19:33 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Herrera, Joel Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.

Margret Villalobos

42407					2/10/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Room # 27		2/10/2009 9:50:38 AM					
--------	------------------	-----------	--	----------------------	--	--	--	--	--

Lara, Ralph Blanca Moran needs a key for room # 27- TA21

Jessica Lopez

42410					2/10/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			2/10/2009 10:45:29 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ronquillo, Ruben URGENTE; BROKEN WINDOW INTO THE G.Y.M AREA SINGLE GLASS SIZE 10 1/2 X 15 1/2 INCHES

Joel Herrera

Count: 27 Work Orders			Avg. Age of WO's 56			Total for Sunland Park ES	1		\$25.00
------------------------------	--	--	----------------------------	--	--	----------------------------------	----------	--	----------------

Location: Sunrise ES

35709					7/6/2008	8/6/2008	219		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress			7/6/2008 12:20:10 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

36205					7/25/2008		200		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			7/25/2008 8:27:04 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny CLASSS RM. 207 DOOR HANDLE,AND LOCK CYLINDER NOT OPENING DOOR PROPERLY. THANKS

Paul Quinones

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Sunrise ES

36336					7/29/2008		196		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			7/29/2008 3:57:08 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben
 BROKEN WALL WINDOW IN WING 1, LOCATION RM.107
 WINDOW SIZE 2'X2' DOUBLE PANE GLASS WINDOW W/
 TINT. THANKS

Paul Quinones

36378					7/30/2008		195		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			7/30/2008 4:19:55 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny
 DOOR IN WING B ELSOL HALL WAY.DURING FIRE DRILL
 IN THE MORNING 7-30-08.RIGHT SIDE DOOR WOULD NOT
 CLOSE DURING DRILL.

Paul Quinones

37422					8/26/2008		168		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			8/26/2008 4:19:28 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Joe
 HOSE BIBB ON WALL NEXT TO UPPER PLAY GROUND WATER
 LEAKING,BROKEN HANDLE.

Paul Quinones

38008	Main Building	Classroom			9/10/2008		153		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/10/2008 4:02:35 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny
 Need key # for room 206 1c 32. The key is bent

Joanne Munoz

38009	Main Building	Classroom			9/10/2008		153		\$0.00
-------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Estrellita work		9/10/2008 4:18:59 PM					
--------	------------------	-----------------	--	----------------------	--	--	--	--	--

Lozoya, Manny
 Alma Castillo, testing room estrellita hallway, has a filing cabinet in her room that is locked and we do not have a key for it. CAn a new key be made or reinstall a new lock? Thank you.

Joanne Munoz

38329					9/22/2008		141		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			9/22/2008 3:45:45 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Quinones, Paul
 9-17-08
 .5,CHECK IN W/OFFICE FOR PLAN OF THE DAY
 7.5,REMOVE BLEACHERS FROM CHAP MID.TO C.H.S FOOT
 BALL STADIUM,AND RELOCATE SOCCER BLEACHERS
 TO FOOTBALL STADIUM AS WELL

Paul Quinones

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
39161					10/12/2008	10/28/2008	121		\$0.00
Medium	Work In Progress				10/12/2008 12:21:04				
Quinones, Paul		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
39681					11/2/2008	11/8/2008	100		\$0.00
Medium	Work In Progress				11/2/2008 12:24:30 AM				
Quinones, Paul		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
39735					11/2/2008	11/10/2008	100		\$0.00
Medium	Work In Progress				11/2/2008 12:24:51 AM				
Quinones, Paul		Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39743					11/2/2008	11/10/2008	100		\$0.00
Medium	Work In Progress				11/2/2008 12:24:54 AM				
Quinones, Paul		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
39872					11/5/2008		97		\$0.00
Medium	Work In Progress				11/5/2008 3:35:43 PM				
Jacquez, Ricardo		REQUESTING WIND SCREEN FOR BACK CHAIN LINK FENCING AREA,LIFT STATION AREAS. BALL PARK FIGURE 200' WILL BE NEEDED @ 4' HIGH THANK YOU VERY MUCH							
Paul Quinones									
39971					11/9/2008	11/25/2008	93		\$0.00
Medium	Work In Progress				11/9/2008 12:28:38 AM				
Quinones, Paul		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
40017	Main Building	Hallway/Corridor			11/12/2008		90		\$0.00
Medium	Work In Progress	VARIOUS			11/12/2008 8:05:43 AM				
Quinones, Paul		Need to have selected bulbs removed in the hallway.							
Joanne Munoz									
40018		Classroom			11/12/2008		90		\$0.00
Medium	Work In Progress	Parent Room			11/12/2008 8:11:32 AM				
Sotelo, Enrique		Check outlet with built in breaker, in Parent Room, by office, it keeps tripping.							
Joanne Munoz									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunrise ES

40050		Classroom			11/13/2008		89		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	various			11/13/2008 11:30:13				
--------	------------------	---------	--	--	---------------------	--	--	--	--

Quinones, Paul
 Need to have a tv and/ or vcr and/or dvd in the following rooms:304,305,309,310,301,portables 3,4,5,6 and POA room
 See Mr. Wiggs for exact rooms and items

Joanne Munoz

40289		Classroom			11/21/2008		81		\$0.00
-------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	VARIOUS			11/21/2008 9:41:43 AM				
--------	------------------	---------	--	--	-----------------------	--	--	--	--

Quinones, Paul
 PLEASE INSTALL PENCIL SHARPENERS IN THE FOLLOWING ROOMS 310,P-4,AND 302 WE HAVE THE SHARPENERS HERE AND READY TO BE INSTALLED

Joanne Munoz

40431					11/30/2008	12/6/2008	72		\$0.00
-------	--	--	--	--	------------	-----------	----	--	--------

Medium	Work In Progress				11/30/2008 12:23:51				
--------	------------------	--	--	--	---------------------	--	--	--	--

Quinones, Paul
 Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.

George ZZ_Gabaldon

40432					11/30/2008	12/8/2008	72		\$0.00
-------	--	--	--	--	------------	-----------	----	--	--------

Medium	Work In Progress				11/30/2008 12:23:52				
--------	------------------	--	--	--	---------------------	--	--	--	--

Quinones, Paul
 Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.

George ZZ_Gabaldon

40433					11/30/2008		72		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/30/2008 12:23:52				
--------	------------------	--	--	--	---------------------	--	--	--	--

Quinones, Paul
 Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM schedule details.

George ZZ_Gabaldon

40434					11/30/2008		72		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/30/2008 12:23:52				
--------	------------------	--	--	--	---------------------	--	--	--	--

Quinones, Paul
 Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM schedule details.

George ZZ_Gabaldon

40435					11/30/2008		72		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/30/2008 12:23:53				
--------	------------------	--	--	--	---------------------	--	--	--	--

Quinones, Paul
 Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details.

George ZZ_Gabaldon

40436					11/30/2008		72		\$0.00
-------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/30/2008 12:23:53				
--------	------------------	--	--	--	---------------------	--	--	--	--

Quinones, Paul
 Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.

George ZZ_Gabaldon

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Sunrise ES

40437					11/30/2008	12/8/2008	72		\$0.00
Medium	Work In Progress				11/30/2008 12:23:53				
Quinones, Paul			Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.						
<u>George ZZ Gabaldon</u>									
40522		Cafeteria			12/3/2008		69		\$0.00
Medium	Work In Progress				12/3/2008 10:00:31 AM				
Orozco, Danny			INSIDE THE WALK-IN REFRIGERATOR FLOOR, THERE IS A PIECE OF METAL THAT IS LIFTING UP.						
			VIRGINIA PRUIT - SNP MANAGER 824-3194						
<u>Alma Terrell</u>									
40655					12/7/2008	12/23/2008	65		\$0.00
Medium	Work In Progress				12/7/2008 12:16:17 AM				
Quinones, Paul			Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.						
<u>George ZZ Gabaldon</u>									
41164		Classroom			1/5/2009		36		\$0.00
Medium	Work In Progress	102			1/5/2009 2:51:54 PM				
Lara, Ralph			I will need a extra key for our RPT key # 1c38						
<u>Joanne Munoz</u>									
41441	Main Building				1/13/2009		28		\$0.00
Medium	Work In Progress				1/13/2009 1:49:07 PM				
Carbajal, Jimmy			VACUM DOES NOT WORK CO2A 00003435						
<u>Jesus Urquidi</u>									
41559					1/16/2009		25		\$0.00
Medium	Work In Progress				1/16/2009 8:17:12 AM				
Sotelo, Enrique			DRYER HANDS BOYS AND GRLS. NEED REPLCE SENSOR NOT WORK						
<u>Juan Vargas</u>									
41786		Lift Station			1/23/2009		18		\$0.00
Medium	Work In Progress				1/23/2009 9:31:44 AM				
Jacquez, Ricardo			please installe air valve on lift station						
<u>Ricardo Jacquez</u>									
41885					1/27/2009		14		\$0.00
Medium	Work In Progress				1/27/2009 12:11:40 PM				
Carbajal, Jimmy			Handle release on vaccum f07000000029 is broke.						
<u>Jesus Urquidi</u>									
42100					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress				2/1/2009 12:24:44 AM				
Vargas, Juan			Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.						
Margret Villalobos									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Sunrise ES

42101					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:44 AM					
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
42112					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:48 AM					
Quinones, Paul	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
42121					2/1/2009		9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:51 AM					
Jacquez, Ricardo	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									
42316					2/6/2009		4		\$0.00
Medium	Work In Progress			2/6/2009 10:24:12 AM					
Ontiveros, Joe	luna hall boys r.room need fix urinal								
Juan Vargas									
42352					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress			2/8/2009 12:19:33 AM					
Vargas, Juan	Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
Count: 38 Work Orders			Avg. Age of WO's 84			Total for Sunrise ES	0		\$0.00

Location: Vado ES

36103					7/22/2008		203		\$0.00
Medium	Work In Progress			7/22/2008 8:39:31 AM					
Sotelo, Enrique	NEED TO REPLACE 4 EXIT SIGNS								
Danny Miranda									
36104					7/22/2008		203		\$0.00
Medium	Work In Progress			7/22/2008 8:40:50 AM					
Sotelo, Enrique	NEED TO REPLACE 6 EMER. LIGHTS								
Danny Miranda									
36175	Main Building	Classroom			7/24/2008		201		\$0.00
Medium	Work In Progress			7/24/2008 11:22:30 AM					
Ronquillo, Ruben	NEED TO HAVE A COVER PUT OVER THE FIRE ALARM IN THE SPECIAL NEEDS CLASSROOM. ROOM101- PER DANNY MIRANDA								
Debra Facio									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Vado ES

38100		Classroom			9/15/2008		148		\$0.00
High	Work In Progress			9/15/2008 3:46:51 PM					
Ronquillo, Ruben	Broken window in room 203. (CASE# 2008-08888) Est. Damage 255.00								
Alfredo Holguin									
40049					11/13/2008		89		\$0.00
Medium	Work In Progress			11/13/2008 10:49:45					
Miranda, Danny	NEED SOME BATTERIES FOR EXIT SIGNES # NICO148 80AAS 1.2 V								
Danny Miranda									
41189					1/6/2009		35		\$0.00
Medium	Work In Progress			1/6/2009 10:43:25 AM					
Sotelo, Enrique	NEED TO REPAIR THREE POWER POLES IN KITCHEN								
Danny Miranda									
41360					1/11/2009	1/27/2009	30		\$0.00
Medium	Work In Progress			1/11/2009 12:17:25 AM					
Diaz, Armando	Monthly - QRTLY BLDG INSP REPORT (VE) - Refer to PM schedule details.								
Jesus Estrada									
41569					1/16/2009		25		\$0.00
Medium	Work In Progress			1/16/2009 9:52:29 AM					
Lozoya, Manny	NEED TOCK. DOOR KNOB IN CUSTODIAL ROOM AT 300-WING HANDLE CAME OUT								
Danny Miranda									
41848	Main Building	Classroom			1/26/2009		15		\$0.00
Medium	Work In Progress			1/26/2009 2:01:36 PM					
Lozoya, Manny	NEED A KEY FOR ROOM 101 CLOSET DOOR FOR P.E. TEACHER MR. GONZALES								
Debra Facio									
41880					1/27/2009		14		\$0.00
Medium	Work In Progress			1/27/2009 10:03:30 AM					
Lozoya, Manny	NEED TO PUT CHANGE DOOR KNOB AND TWO KEYS TO BEST IN NEW CLASSROOM AT LIBUERY								
Danny Miranda									
41947					1/28/2009		13		\$0.00
Medium	Work In Progress			1/28/2009 2:23:55 PM					
Lozoya, Manny	NEED TO CK. CORE ON DOOR KNOB TO BACK ELECTRICAL ROOM KEY WILL NOT LOCK								
Danny Miranda									

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
42030					1/30/2009		11		\$0.00
Medium	Work In Progress			1/30/2009 1:41:26 PM					
Gonzales, Angel		NEED BOBCAT FOR THE NEW GRANT PROJECT BETWEEN PATIOS							
Danny Miranda									
42064					2/1/2009	2/7/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:31 AM					
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
42065					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:31 AM					
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
42066					2/1/2009	2/9/2009	9		\$0.00
Medium	Work In Progress			2/1/2009 12:24:31 AM					
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
42133	Main Building	Athletic Field			2/2/2009		8		\$0.00
Medium	Work In Progress			2/2/2009 7:54:15 AM					
Miranda, Danny		NEED TO HAVE TREES WATERED OUTSIDE.							
Debra Facio									
42134	Main Building	Athletic Field			2/2/2009		8		\$0.00
Medium	Work In Progress			2/2/2009 7:58:56 AM					
Ontiveros, Guadalupe		NEED DIRT DUG UP 6 INCHES OUTSIDE ON PATIO WINDOWS							
Debra Facio									
42305	Main Building	Custodial			2/6/2009		4		\$0.00
Medium	Work In Progress			2/6/2009 9:09:37 AM					
Carbajal, Jimmy		Need new vacuum cleaner if possible. The one I have no mas no book . Thank you .							
Armando Diaz									
42353					2/8/2009	2/24/2009	2		\$0.00
Medium	Work In Progress			2/8/2009 12:19:34 AM					
Miranda, Danny		Monthly - Vado ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
42360	Main Building	Parking Lot			2/9/2009		1		\$0.00
Medium	Work In Progress			2/9/2009 8:37:01 AM					
Miranda, Danny		START UP OF RAYS GARDENS FOR OUTSIDE PATIO							
Debra Facio									

2/10/2009 3:17:29 PM

967 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Vado ES							
42361					2/9/2009		1		\$0.00
Medium	Work In Progress				2/9/2009 8:38:06 AM				
Miranda, Danny		TREES NEED WATERING							
Debra Facio									
42362	Main Building	Parking Lot			2/9/2009		1		\$0.00
Medium	Work In Progress				2/9/2009 8:39:43 AM				
Miranda, Danny		NEE TO HAVE RED PAINT IN THE EMERGENCY LANES							
Debra Facio									
42408					2/2/2009		8		\$0.00
Medium	Work In Progress				2/10/2009 10:30:30 AM				
Munoz, Michael		East fence damaged in 3 places. This has happened before on two other occasions.							
Danny Miranda									
42418	Main Building	Library			2/10/2009		0		\$0.00
Medium	Work In Progress				2/10/2009 12:05:36 PM				
Carbajal, Jimmy		VACUUM NEEDS SOME REPAIR							
Jimmy Carbajal									
Count: 24 Work Orders		Avg. Age of WO's 44				Total for Vado ES		0	\$0.00
Count: 967 Work Orders		Avg. Age of WO's 83				Grand Total		3	\$75.00