

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Anthony ES

36176	Cafeteria	Cafeteria			7/24/2008		286		\$0.00
Medium	Work In Progress				7/24/2008 11:26:39 AM				
Ontiveros, Guadalupe		remove old tree next to cafeteria, health issue as per ms.marquez							
David Vega									
36641	Drug Free Bldg.				8/5/2008		274		\$0.00
Medium	Work In Progress				8/5/2008 10:48:59 AM				
Sotelo, Enrique		please install a power strip for radios. please see irene for location.thxs							
Michael Munoz									
37287	Cafeteria	Cafeteria			8/21/2008		258		\$0.00
Medium	Work In Progress				8/21/2008 11:49:08 AM				
Orozco, Danny		SEAL TO WALK-IN REFRIGERATOR IS ALL TORN AND MOLDY, SEAL NEEDS TO BE REPLACED							
		BECKY SAENZ - 882-3507 (K-3 CAFETERIA)							
Alma Terrell									
39028		Athletic Field			10/8/2008		210		\$0.00
Medium	Work In Progress				10/8/2008 10:07:55 AM				
Appelzoller, Fred		Outside water fountains mounted on concrete block columns located east of the Old Main Cafeteria are not working. REPAIR							
Alfredo Holguin									
40016	Cafeteria	Cafeteria			11/12/2008		175		\$0.00
Medium	Work In Progress				11/12/2008 7:52:56 AM				
Sotelo, Enrique		please install light fixture in bathroom, old main cafeteria where remodeling is being done. thxs							
Michael Munoz									
41163	Original Main	Athletic Field			1/5/2009		121		\$0.00
Medium	Work In Progress				1/5/2009 2:35:27 PM				
Holguin, Alfredo		Canopy tore in pieces by wind need to replace old main blg side palyground equipment							
Hector Villalobos									
41625	Main Building	Classroom			1/20/2009		106		\$0.00
Medium	Work In Progress				1/20/2009 7:23:55 AM				
Lozoya, Manny		room 16 needs keys made for cabinet							
Hector Villalobos									
41626	Original Main	Office			1/20/2009		106		\$0.00
Medium	Work In Progress				1/20/2009 7:28:24 AM				
Lozoya, Manny		Room 112 needs adoor guard for door lock handle							
Hector Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

41944	Original Main				1/28/2009		98		\$0.00
Medium	Work In Progress				1/28/2009 1:26:53 PM				
Lozoya, Manny		old main blg stoage supplie room needs door handle lock guard							
Hector Villalobos									
42372					2/9/2009		86		\$0.00
Medium	Work In Progress				2/9/2009 12:43:22 PM				
Lozoya, Manny		Need to ck padlock or issue a new key for the gate on church street, where the NM Environment Dept goes in. She said her key does not open that lock.							
Margret Villalobos									
42600	Original Main	Mechanical Room			2/17/2009		78		\$0.00
Medium	Work In Progress				2/17/2009 9:14:54 AM				
Solis, Lorenzo		old main blg boilers room pump is leaking							
Hector Villalobos									
42826	Main Building	Restroom (Boys)			2/24/2009		71		\$0.00
Medium	Work In Progress				2/24/2009 7:53:02 AM				
Appelzoller, Fred		lav's in boys r-rms need replacement from 8" c-set to 4" c-set for better maintenance and up keep.							
Fred Appelzoller									
42895		Parking Lot			2/25/2009		70		\$0.00
Medium	Work In Progress				2/25/2009 8:28:10 AM				
Villalobos, David		Have contractor(s) see about installation of Backflow preventer for the school site to be located at far northwest end of campus next to main water meter							
David Villalobos									
42912		Classroom			2/25/2009		70		\$0.00
Medium	Work In Progress	ON TRACK PRE			2/25/2009 11:11:40 AM				
Ronquillo, Ruben		SCREENS & BLINDS FOR 4 CLASSROOMS * SCREENS FOR 20 WINDOWS 31 1/2 " H X 4 FT 11" W * BLINDS FOR 20 WINDOWS 54" H X 63" W BLINDS FOR OFFICE * 2 WINDOWS 38" H X 95" W * 2 WINDOWS 62" H X 34" W							
Lucy Meza									
42913					2/25/2009		70		\$0.00
Medium	Work In Progress	Anthony On Track			2/25/2009 11:12:28 AM				
Ronquillo, Ruben		Blinds for windows (6) in office portable and in two classrooms. 4- 47 x 37 2- 33 x 62							
Lucy Meza									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
42914		Classroom			2/25/2009		70		\$0.00
Medium	Work In Progress	Pre - K			2/25/2009 11:13:20 AM				
Ronquillo, Ruben		P.R.E.K headstart rooms 306 307 blinds 12 63x54							
Hector Villalobos									
42964					2/26/2009		69		\$0.00
Medium	Work In Progress				2/26/2009 8:23:36 AM				
Appelzoller, Fred		Upper Primary - Need to relocate spikett.				Summer Project			
Michael Munoz									
43231	Annex Building	Office			3/2/2009		65		\$0.00
Medium	Work In Progress				3/2/2009 12:56:02 PM				
Lozoya, Manny		room 212 door lock handle broken off need to replace it annex blg							
Hector Villalobos									
43774	Main Building				3/17/2009		50		\$0.00
Medium	Work In Progress				3/17/2009 8:05:30 AM				
Appelzoller, Fred		Some kind of water problem in main bldg.							
Michael Munoz									
44020					3/25/2009		42		\$0.00
Medium	Work In Progress				3/25/2009 2:56:57 PM				
Villalobos, Hector		3/25/09 7.5 chapter o. therapy room relocate bulletin boards paint walls Q-7-36-P 4 gals \$80 1 painters caulk \$3. 85 suspended ceiling 2 boxes \$27.95 \$139.75 5 log on work order log				3/25-8 Material 251.55			
Hector Villalobos									
44256					4/3/2009		33		\$0.00
Medium	Work In Progress				4/3/2009 2:10:33 PM				
Villalobos, David		Need to ck pressure on water entering site, and see if water pressure could be reduced. Make sure piping is strapped properly.							
Michael Munoz									
44318					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:43 AM				
Orozco, Danny		Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
44474	Main Building	Custodial			4/6/2009		30		\$0.00
Medium	Work In Progress				4/6/2009 3:37:22 PM				
Lozoya, Manny		Room 16 needs to make new lock for cabinet							
Hector Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
44646					4/12/2009	4/28/2009	24		\$0.00
Medium	Work In Progress			4/12/2009 12:21:27 AM					
Villalobos, Hector		Monthly - Anthony ES A4 (Rooftop Unit)(S.Annual) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
44817	Boiler Room	Pump House			4/20/2009		16		\$0.00
Medium	Work In Progress			4/20/2009 8:05:45 AM					
Gonzalez, Salvador		PLEASE CUT 3 INCH PIPE FOR CIRCULATING PUMP AND RE-WELD. THANKS!							
<u>Lorenzo Solis</u>									
45095		Classroom			4/28/2009		8		\$0.00
Medium	Work In Progress	1st - 5th grade		4/28/2009 11:43:34 AM					
Villalobos, Hector		Furniture for computers delivered to the school please set up in classrooms first to fifth grade. Furniture will be delivered on April 29. Thank you.							
<u>Sandra Almeraz</u>									
45193					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:35 AM					
Villalobos, Hector		Yearly - Anthony ES C11 (Evap.Down)(Yearly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
45232	Main Building	Classroom			5/1/2009		5		\$0.00
Medium	Work In Progress			5/1/2009 7:34:07 AM					
Solis, Lorenzo		mild blg room 3 refrigeration not cooling							
<u>Hector Villalobos</u>									
45290					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:38 AM					
Villalobos, Hector		Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
45291					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:39 AM					
Villalobos, Hector		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
45292					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:39 AM					
Villalobos, Hector		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Anthony ES

45355	Pump House	Pump House			5/4/2009		2		\$0.00	
Medium	Work In Progress				5/4/2009 1:32:11 PM					
Jacquez, Ricardo	upper primary pump houes . pump is not working									
Hector Villalobos										
45356	Main Building				5/4/2009		2		\$0.00	
Medium	Work In Progress				5/4/2009 1:36:01 PM					
Solis, Lorenzo	mild blg south side need to replace waterfountain handles									
Hector Villalobos										
45357	Main Building	Hallway/Corridor			5/4/2009		2		\$0.00	
Medium	Work In Progress				5/4/2009 1:38:14 PM					
Lozoya, Manny	mild blg north doors need to replace mild bar for doors									
Hector Villalobos										
45368	Cafeteria	Cafeteria			5/4/2009		2		\$0.00	
Medium	Work In Progress				5/4/2009 2:29:45 PM					
Orozco, Danny	TILT SKILLET IS NOT WORKING AT ATHONY ELEMENTARY (OLD SCHOOL)									
	TERRY PORTILLO - SNP MANAGER 882-3507									
Alma Terrell										
Count: 35 Work Orders	Avg. Age of WO's 73		Total for Anthony ES				0	\$0.00		

Location: Berino ES

36845					8/8/2008		271		\$0.00
Medium	Work In Progress	Mobile Home			8/8/2008 3:52:51 PM				
Sotelo, Enrique	Need to install utility hook-up for mobile home.								
Michael Munoz									
36879					8/11/2008		268		\$0.00
Medium	Work In Progress				8/11/2008 9:01:25 AM				
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR PER MR VALTIERRA HE WOULD LIKE THE SCHOOL CLEAN TO MANNY WEEDS PONDING AREA NEEDS CLEAN IN FRONT AND BACK AROUND PORTABLES ALONE FENCE IN FRONT OUTSIDE AND IN SIDE THANK YOU SIR								
Adan Duran									
38128					9/16/2008		232		\$0.00
Medium	Work In Progress				9/16/2008 10:30:21 AM				
Sotelo, Enrique	Emer. Light need replacing at west entrance and Custodial room.								
Adan Duran									
38442	Main Building				9/25/2008		223		\$0.00
Medium	Work In Progress				9/25/2008 3:59:37 PM				
Duran, Adan	Restrooms nest to multipurpose room- sand entrance doors and reseal								
Alfredo Holguin									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

39479					10/24/2008		194		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress			10/24/2008 3:26:04 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Sotelo, Enrique

MR ENRIQUE SOTELO SIR EMERGENCY LIGHT
FALL OFF WALL IN CAFETERIA NEED TO REPLACE
BROKEN BURN ELEMENTS THE ONE IN
CUSTODIAL ROOM ALSO THANK YOU SIR

Adan Duran

40997					12/18/2008		139		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

High	Work In Progress			12/18/2008 4:24:02 PM					
------	------------------	--	--	-----------------------	--	--	--	--	--

Miranda, Danny

as epr our conversation, the wall to the entrance of the
boys restroom on the east wing has been kicked in.
please replace w/ durock as discussed. if other areas at
site need the same please take of them.
Thxs

Michael Munoz

41069					1/4/2009	1/25/2009	122		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress			1/4/2009 12:18:49 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Orozco, Danny

Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM
schedule details.

Margret Villalobos

41153					1/5/2009		121		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress			1/5/2009 8:18:40 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lozoya, Manny

MR MANNY LOZOYA HAPPY NEW YEAR AND GOD
BLESS MR LOZOYS SIR WE HAVE A BROKEN KEY
IN GATE LOCK WEST GATE NEED TO REPLACE
WILL NEED TO LOCK TO NIGHT THANK YOU SIR

Adan Duran

42002					1/29/2009		97		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			1/29/2009 3:19:45 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Sotelo, Enrique

MR ENRIQUE SOTELO SIR NEED TO CHECK
MOTOR ON EXHUAST FAN ROOMS 105 AND 106
ALSO CHECK SWITCHS FANS NOT WORKING
THANK YOU AND GOD BLESS

Adan Duran

43055					2/27/2009		68		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/27/2009 3:22:22 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Sotelo, Enrique

MR ENRIQUE SOTELO PER MR VALTIERRA NEED
TO REPLACE LIGHT BULBS GYM STAGE SOME ARE
COLORED THANK YOU SIR AND GOD BLESS

Adan Duran

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

43608					3/11/2009		56		\$0.00
Medium	Work In Progress			3/11/2009 3:01:11 PM					
Ontiveros, Guadalupe	MRS MARGRET VILLALOBOS PER MIKE MUNOZ NEED 6 LOADS OF CRUCHER FINE ALSO WILL NEED TRACTOR WITH SCRAPER TO SPREAD AROUND PORTABLES THANK YOU AND GOD BLESS								

Adan Duran

43707					3/13/2009		54		\$0.00
Medium	Work In Progress	Playground		3/13/2009 3:38:18 PM					
Ontiveros, Guadalupe	MRS MARGRET VILLALOBOS PER MIKE MUNOZ THE PLAYGROUND HERE AT BERINO NEEDS SOME WORK UNEVEN HOLES NEED SOME TOP SOIL ECT NEED YOUR ASSISTANCE IN THIS THANK YOU SIR AND GOD BLESS								

Adan Duran

43869		Cafeteria			3/19/2009		48		\$0.00
Medium	Work In Progress			3/19/2009 10:53:01 AM					
Orozco, Danny	DISHWASHER: CHECK OUT PRE RINSE DRAIN UNIT								
	MR. G. SNP DIRECTOR 882-6771								

Jacqueline Aguilar

44021					3/25/2009		42		\$0.00
Medium	Work In Progress			3/25/2009 3:00:16 PM					
Duran, Adan	3/25/09					3/25-8			
	1/2 SIGN IN CHECK SCHOOL BUILDING GROUNDS 1 WATER NEW PLANTED PINE TREES 41/2 WORKED ON AC UNITS CLEAN HOOK UP 1/2 OPEN DOORS FOR PALAN-B CAMERA HOOK UP 1/2 SHUT DOWN MARQUEE PULL OUT FUESES FROM BREAKER BOX 1 FILE DAILY LOG AND SIGN OUT								

Adan Duran

44075					3/31/2009		36		\$0.00
Medium	Work In Progress			3/31/2009 12:22:42 AM					
Duran, Adan	Monthly - Berino ES A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								

Margret Villalobos

44313					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:41 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

44556					4/8/2009		28		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	Playground		4/8/2009 3:20:23 PM					
--------	------------------	------------	--	---------------------	--	--	--	--	--

Ontiveros, Guadalupe
 MRS MARGRET VILLALOBOS PER MR MUNOZ
 NEED TO REMOVE CHIN-UP BARS WEST SIDE AND
 EAST SIDE HAD A MISSHAB LITTLE GIRL FELL DIS-
 LOCATED SHOULDER UNSAFE THANK YOU AND
 GOD BLESS

Adan Duran

44849					4/21/2009		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			4/21/2009 7:56:02 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny
 MR MANNY LOZOYA SIR THE LOBBOY DOORS IN
 FRONT ARE NOT LOCKING NEED YOUR
 ASSISTANCE IT HAS THE LITTLE LEVER THAT
 PUSH UP AND DOWN TO LOCK AND OPEN THANK
 YOU SIR AND GOD BLESS

Adan Duran

44934					4/22/2009		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			4/22/2009 3:00:04 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, Margret
 AS PER MR VALTIERRA THERE WHERE FOUND IN
 ROOM 106 GRADE EC ABOUT 20 ROACHS UNDER
 BOOKSHELF COULD WE PLEASE HAVE IT SPRAY
 WITH PESTICIDE THANK YOU

Adan Duran

45050					4/27/2009		9		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			4/27/2009 2:48:15 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Solis, Lorenzo
 MR LORENZO SOLIS SIR WE WILL NEED 3 MORE
 AC 6800 AND TWO 4500 KITCHEN AND OFFICE
 THE 6800 ONE FOR MR MORENOS OFFICE ROOM
 106 AND ROOM 123 THANK YOU SIR AND GOD
 BLESS

Adan Duran

45093		Classroom			4/28/2009		8		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	1st - 5th grade		4/28/2009 11:34:32 AM					
--------	------------------	-----------------	--	-----------------------	--	--	--	--	--

Duran, Adan
 Furniture for computers was delivered on April 27th to
 school please set up in classrooms first to fifth grade.
 Thank you.

Sandra Almeraz

45121					4/28/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			4/28/2009 3:32:33 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lozoya, Manny
 MR MANNY LOZOYA SIR WILL NEED A NAME PLATE
 FOR DOOR RM 129 NEW TEACHER HER NAME IS
 R. S. SEPULVEDA THANK YOU SIR AND GOD
 BLESS

Adan Duran

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Berino ES

45185					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:31 AM					
Duran, Adan	Yearly - Berino ES C11 (Evap.Down)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
45207					4/30/2009		6		\$0.00
Medium	Work In Progress			4/30/2009 9:10:40 AM					
Carbajal, Jimmy	EXTRACTER IS NOT WORKING AND NEEDS NEW LID								
Jimmy Cortez									
45251					5/1/2009		5		\$0.00
Medium	Work In Progress			5/1/2009 3:19:46 PM					
Villalobos, Margret	MRS MARGRET VILLALOBOS PER MR VALTIERRA ROOMS 111 AND 106 NEED TO BE SPRAYED WITH PESTICIDE PROBLEM WITH ROACHES BAD THANK YOU AND GOD BLESS								
Adan Duran									
45257					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:26 AM					
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
45258					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:26 AM					
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45259					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:27 AM					
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
Count: 28 Work Orders			Avg. Age of WO's 75			Total for Berino ES	0		\$0.00

Location: Chaparral ES

37135	West Central				8/18/2008		261		\$0.00
Medium	Work In Progress			8/18/2008 9:11:53 AM					
Hernandez, Guillermo	new doors are being installed in the esat and west barrack. please order paint so you can paint doors. thxs		Left by J. Vargas 4/6/09						
Michael Munoz									
37990	Cafeteria				9/10/2008		238		\$0.00
Medium	Work In Progress			9/10/2008 1:49:03 PM					
Orozco, Danny	Side of grease trap caving in.								
Michael Munoz									

5/6/2009 11:28:08 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
38027		Athletic Field			9/11/2008		237		\$0.00
Medium	Work In Progress			9/11/2008 2:05:24 PM					
Ontiveros, Guadalupe	Lower Grades playground equipment located between classroom wings - Re layout plastic borders so they are around the remaining playground (slide) structure.								
Alfredo Holguin									
40604					12/4/2008		153		\$0.00
Medium	Work In Progress			12/4/2008 4:46:38 PM					
Sotelo, Enrique	Need assistance to replace two outside light fixtures of portable 34DW (#402 and #404)								
Guillermo Hernandez									
41137					1/4/2009		122		\$0.00
Medium	Work In Progress			1/4/2009 12:19:17 AM					
Jacquez, Ricardo	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									
41968					1/28/2009		98		\$0.00
Medium	Work In Progress			1/28/2009 3:46:13 PM					
Ontiveros, Joe	Need to replace two bubblers on the water fountain by the field and one by E wing. Thank you.								
Guillermo Hernandez									
42286					2/5/2009		90		\$0.00
Medium	Work In Progress			2/5/2009 3:39:10 PM					
Sotelo, Enrique	Need assistance to replace ballasts in Portable #P-1 & #P-2 (2 lamp ballast) Thank you								
Guillermo Hernandez									
42288					2/5/2009		90		\$0.00
Medium	Work In Progress			2/5/2009 3:41:08 PM					
Sotelo, Enrique	Need assistance to replace ballasts in # P-7 Pre-K (4 lamp ballast) Thank you.								
Guillermo Hernandez									
43069					2/27/2009		68		\$0.00
Medium	Work In Progress			2/27/2009 3:58:35 PM					
Ontiveros, Joe	Would you please replace the flushing valves to the comodes in the boy's and girl's restrooms. Thank you								
Guillermo Hernandez									
43941					3/20/2009		47		\$0.00
Medium	Work In Progress			3/20/2009 3:38:04 PM					
Ontiveros, Joe	Would you please check the faucet on the lavatory may be bad seal in the boy's restroom at E wing. Thank you								
Guillermo Hernandez									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
44198					4/1/2009		35		\$0.00
Medium	Work In Progress			4/1/2009 3:53:55 PM					
Ontiveros, Joe	No hot water on the New addition 200's, Reversing valve on the Water heater not working. thank you								
Guillermo Hernandez									
44425					4/5/2009		31		\$0.00
Medium	Work In Progress			4/5/2009 12:23:19 AM					
Jacquez, Ricardo	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									
44813					4/17/2009		19		\$0.00
Medium	Work In Progress			4/17/2009 4:13:48 PM					
Ontiveros, Joe	Would you please replace the water faucet in the teacher lounge sink. Thank you.								
Guillermo Hernandez									
45000					4/24/2009		12		\$0.00
Medium	Work In Progress			4/24/2009 8:01:45 AM					
Hernandez, Guillermo	Need to repair air bubbles on Main building roof. Thank you								
Guillermo Hernandez									
45036		Custodial			4/27/2009		9		\$0.00
Medium	Work In Progress			4/27/2009 10:04:47 AM					
Carbajal, Jimmy	need,to,fix,vaccum,back,wheel,								
Daniel Ramirez									
45069					4/27/2009		9		\$0.00
Medium	Work In Progress			4/27/2009 4:00:38 PM					
Ontiveros, Joe	Need to replace wax ring on the urinals in the boy's restroom on the hallway for kinder. Thank you.								
Guillermo Hernandez									
45103		Classroom			4/28/2009		8		\$0.00
Medium	Work In Progress	1st to 5th grade		4/28/2009 1:29:51 PM					
Hernandez, Guillermo	Furniture for computers will be delivered to the school on May 6 please set up in classrooms first to fifth grade. Thank you.								
Sandra Almeraz									
45192					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:34 AM					
Hernandez, Guillermo	Yearly - Chaparral ES C-11 Evap (Annual) - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral ES

45201					4/30/2009		6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:38 AM					
Jacquez, Ricardo	Monthly - Chaparral ES DP-91 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45284					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:36 AM					
Hernandez, Guillermo	Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45285					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:36 AM					
Hernandez, Guillermo	Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45286					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:37 AM					
Hernandez, Guillermo	Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45326					5/3/2009		3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:51 AM					
Jacquez, Ricardo	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 23 Work Orders			Avg. Age of WO's 67			Total for Chaparral ES	0		\$0.00

Location: Chaparral HS

40782	A-Wing				12/11/2008		146		\$0.00
Medium	Work In Progress			12/11/2008 9:11:02 AM					
Quinones, Paul	Need to install pencil sharpeners in the A Wing. (Ms. Ballard)								
<u>Guadalupe Gonzalez</u>									
35714					7/6/2008	8/6/2008	304		\$0.00
Medium	Work In Progress			7/6/2008 12:20:12 AM					
Villalobos, David	Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
37783					9/4/2008		244		\$0.00
Medium	Work In Progress			9/4/2008 10:52:49 AM					
Lozoya, Manny	(65) LATCH PROTECTORS ARE REQUESTED FOR CLASS RMS AND OFFICE DOORS								
<u>Eddie Baeza</u>									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

38742					10/5/2008		213		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				10/5/2008 12:23:49 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.				10/6/08 - Emailed to Ricky Borrego			
------------------	--	---	--	--	--	------------------------------------	--	--	--

Margret Villalobos

39393					10/22/2008		196		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				10/22/2008 3:50:18 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe		(4) BATTING CAGES ARE REQUESTED FOR THE BASEBALL FIELDS.							
----------------------	--	--	--	--	--	--	--	--	--

Eddie Baeza

40973					12/18/2008		139		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/18/2008 11:05:11				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny		PROTECTOR LATCHES, AND DOOR STOPS ARE NEEDED TO ALL CLASS RM. DOORS, AND OTHER DOORS REQUESTED BY CHS PRINCIPLE. ADDITIONAL HELP WILL HELP AS PROJECT STARTS. THANKS MANNY							
---------------	--	--	--	--	--	--	--	--	--

Paul Quinones

41139					1/4/2009		122		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				1/4/2009 12:19:18 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

41140					1/4/2009		122		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				1/4/2009 12:19:19 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul		Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.							
----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

41141					1/4/2009		122		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				1/4/2009 12:19:19 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul		Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

41142					1/4/2009	1/12/2009	122		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress				1/4/2009 12:19:20 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul		Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.							
----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

41144					1/4/2009	2/4/2009	122		\$0.00
-------	--	--	--	--	----------	----------	-----	--	--------

Medium	Work In Progress				1/4/2009 12:19:21 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul		Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.							
----------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

5/6/2009 11:28:08 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

41150					1/4/2009		122		\$0.00
Medium	Work In Progress				1/4/2009 12:19:23 AM				
Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.				1/6/09 e-mailed to ricky.borrego@cummins.com - mkv			
Margret Villalobos									
41178					1/5/2009		121		\$0.00
Medium	Work In Progress	R-Bldg			1/5/2009 3:59:51 PM				
Lozoya, Manny		DOOR IN R-2 BUILDING DOOR DOESNT LOCK DOOR ENTRANCE.							
Paul Quinones									
41180					1/5/2009		121		\$0.00
Medium	Work In Progress				1/5/2009 4:02:23 PM				
Lozoya, Manny		DOOR NEXT TO FRONT ENTRANCE WILL NOT LOCK WITH KEY.ON THE LEFT SIDE OF DOOR.							
Paul Quinones									
41479					1/14/2009		112		\$0.00
Medium	Work In Progress	SECURITY			1/14/2009 9:12:39 AM				
Lozoya, Manny		RE-KEY SECURITY SHACK WHEN COMPLETED WITH A CH-1 KEY. (DE SANTIAGO)							
Rosa Quezada									
41529		Computer Lab			1/15/2009		111		\$0.00
Medium	Work In Progress	B Wing -			1/15/2009 2:15:39 PM				
Lozoya, Manny		Right entrance door to the classroom can not be unlocked with the key. Please check. (Ms. Duran-Campbell)							
Guadalupe Gonzalez									
41607					1/16/2009		110		\$0.00
Medium	Work In Progress				1/16/2009 3:12:37 PM				
Lozoya, Manny		FIELD HOUSE BUILDING,BOYS WEIGHT RM.DOOR ENTRANCE KEY CYLINDERS DEED TO BE REPLACED FROM MULLEN TO BEST 2 DOORS.GIRLS LOCKER RM.3 CYLINDERS WILL BE NEEDED,AND BOYS LOCKER RM.4 CYLINDERS WILL BE NEEDED TO PANIC BARS THANKS							
Paul Quinones									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

41608					1/16/2009		110		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/16/2009 3:18:26 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique Q,AND R BUILDING BUILDING ELECTRICAL KEY SWITCHES
NEED TO BE REPLACED IN RES RMS.,AND HALL WAYS.
CUSTODIANS HAVIING PROBLEMS TURNING OFF LIGHTS.
MUCHOS GRACIAS HENRY.

Paul Quinones

41610					1/16/2009		110		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/16/2009 3:23:48 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny REAR GATE TO KITCHEN REAR ENTRANCE.HOLES ARE NEEDED TO BE PLACED ON FLOOR TO SECURE GATE LATCHES

Paul Quinones

41612					1/16/2009		110		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/16/2009 3:28:00 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny GYM ENTRANCE DOORS HOLES NEED TO BE PLACED TO SECURE DOOR LATCHES

Paul Quinones

41973					1/28/2009		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

High	Work In Progress				1/28/2009 4:21:00 PM	1/28/2009			
------	------------------	--	--	--	----------------------	-----------	--	--	--

Lozoya, Manny Head Custodian Armando Rivera needs his desk to lock so he can keep documents locked up.

Jesus Estrada

42027					1/30/2009		96		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/30/2009 12:56:48 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lozoya, Manny NEED TO REPLACE LOCKS IN HOT BOX FENCE AREA NORTH END FENCE LINE.

Paul Quinones

42113					2/1/2009		94		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/1/2009 12:24:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

42115					2/1/2009		94		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/1/2009 12:24:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Quinones, Paul Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

42182					2/3/2009		92		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/3/2009 12:59:06 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lozoya, Manny		PANIC BAR IN REAR ENTRANCE KITCHEN NEEDS TO BE SECURED TO DOOR FOR SAFETY PURPOSES, AND TO LOCK DOOR							
---------------	--	--	--	--	--	--	--	--	--

Paul Quinones

42183					2/3/2009		92		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/3/2009 1:04:18 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny		ADMIN.OFFICE NEEDS CAM LOCK TO SECURE PARTITION IN OFFICE AREA NEXT TO MR.DIGGS OFFICE							
---------------	--	--	--	--	--	--	--	--	--

Paul Quinones

42197					2/3/2009		92		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				2/3/2009 3:32:47 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny		OUTSIDE DOOR HEALTHCENTER AREA DOOR WILL NOT CLOSE DOOR FROM CYLINDER, AND THE PANIC BAR KEY CYLINDER AS WELL.							
---------------	--	--	--	--	--	--	--	--	--

Paul Quinones

42403					2/10/2009		85		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/10/2009 8:31:08 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique		NEED TO INSTALL OUTLETS IN NEW GROUNDS STORAGE.							
-----------------	--	---	--	--	--	--	--	--	--

Guadalupe Ontiveros

42479	A-Wing	Library			2/11/2009		84		\$0.00
-------	--------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	trophy case			2/11/2009 11:14:25 AM				
--------	------------------	-------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny		replace lock on display case (middle one) for the library							
---------------	--	---	--	--	--	--	--	--	--

Rosa Quezada

42480					2/11/2009		84		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	whole school			2/11/2009 11:18:00 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Lozoya, Manny		NEED A CH-1 FOR JOHNNY VALLES (GROUNDSMAN) QUEZADA							
---------------	--	--	--	--	--	--	--	--	--

Rosa Quezada

43104					3/1/2009	3/22/2009	66		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				3/1/2009 12:22:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

43122					3/1/2009		66		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/1/2009 12:23:02 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Yearly - Chaparral HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
---------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

5/6/2009 11:28:08 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
43227		Cafeteria			3/2/2009		18		\$0.00
Medium	Work In Progress			3/2/2009 9:26:05 AM	3/20/2009				
Carbajal, Jimmy	scrubber-auto bearings from motor making to much noise droning battery		3/20/09 - AS PER JIMMY, NO PARTS AND HAVE NOT HAD A CHANCE TO CHECK OUT MACHINE. 4/20/09 - STILL PENDING?						
Armando Rivera									
43253		Athletic Field			3/3/2009		64		\$0.00
High	Work In Progress			3/3/2009 8:21:36 AM					
Valles, Johnny	need to install gates behind home site blachers.Also need gate by grounds storage to secure area.								
Guadalupe Ontiveros									
43264		Classroom			3/3/2009		64		\$0.00
Medium	Work In Progress	Q-2		3/3/2009 2:02:58 PM					
Lozoya, Manny	KEY BROKE IN LOCK ON TOOL CAGE IN CONSTRUCTION ROOM Q-2 - PLEASE SEND MANNY OUT A.S.A.P. (QUEZADA)								
Rosa Quezada									
43483		Athletic Field			3/9/2009		58		\$0.00
Medium	Work In Progress			3/9/2009 10:14:22 AM					
Ontiveros, Guadalupe	need to install gate behind home bleachers to have access, to clean area. Also need two 10' gates by grounds storage to secure area.								
Guadalupe Ontiveros									
43575					3/11/2009		56		\$0.00
Medium	Work In Progress			3/11/2009 8:37:51 AM					
Ontiveros, Joe	MECHANICAL RM. IN BACK OF KITCHEN ENTRANCE AREA WATER BOOSTER PUMPS LEAKING FROM RELIEF VALVES								
Paul Quinones									
43719					3/15/2009		52		\$0.00
Medium	Work In Progress			3/15/2009 12:19:48 AM					
Ontiveros, Guadalupe	Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.								
Margret Villalobos									
43743		Parking Lot			3/16/2009		51		\$0.00
Medium	Work In Progress	install signs		3/16/2009 2:40:01 PM					
Quinones, Paul	NEED TO SETUP SIGNS IN THE FRONT OF THE BUILDING BY PARKING LOT FOR VISITORS THAT COME ON CAMPUS (DE SANTIAGO)								
Rosa Quezada									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

43871		Athletic Field			3/19/2009		48		\$0.00
Medium	Work In Progress	FIELD HOUSE			3/19/2009 12:24:45 PM				
Lozoya, Manny		THE FIELD HAS HAS BEEN RELEASED TO US. NEED MANNY TO COME OUT AND ISSUE KEYS. (DIGGS)							
<u>Rosa Quezada</u>									
44195					4/1/2009		35		\$0.00
Medium	Work In Progress				4/1/2009 3:50:34 PM				
Ontiveros, Joe		DRAINING PROBLEM FIRE PUMP STATION REQUESTING 1 1/4" PIPING FOR WATER DRAINAGE WHILE PUMP STATION IS IN TEST MODE.							
<u>Paul Quinones</u>									
44215					4/2/2009		34		\$0.00
Medium	Work In Progress				4/2/2009 9:03:21 AM				
Quinones, Paul		REPLACE WATER PUMPS, AND WATER FLOATS TO EVAP. AIR HANDLERS IN GYM AREA.							
<u>Paul Quinones</u>									
44220	E-Wing	Custodial			4/2/2009		34		\$0.00
Medium	Work In Progress				4/2/2009 10:54:33 AM				
Lozoya, Manny		custodial office desk, replace key							
<u>Armando Rivera</u>									
44288					4/5/2009		31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:30 AM				
Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.				4/7/09 E-mailed PM to Ricky and Garrett at Rocky Mtn.			
<u>Margret Villalobos</u>									
44338					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:50 AM				
Orozco, Danny		Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
44415					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:16 AM				
Quinones, Paul		Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
44417					4/5/2009		31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:16 AM				
Quinones, Paul		Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
44532		Pump House			4/8/2009		28		\$0.00
Medium	Work In Progress			4/8/2009 8:58:23 AM					
Jacquez, Ricardo	need to fix leaking irrigation pump Thanks								
Ricardo Jacquez									
44787					4/17/2009		19		\$0.00
Medium	Work In Progress			4/17/2009 1:16:20 PM					
Ontiveros, Joe	BOYS LOCKER RM.WATER WASH FOUNTAIN WATER WILL NOT SHUT OFF FROM BOTTOM SOLENOID VALVE								
Paul Quinones									
44788					4/17/2009		19		\$0.00
Medium	Work In Progress			4/17/2009 1:19:24 PM					
Ontiveros, Joe	BOOSTER PUMP FOR CIRCULATING WATER NEEDS TO BE REPLACED IN BOILER RM. IN WING B. HEALTH CENTER NEEDS WARM WATER.								
Paul Quinones									
44822					4/20/2009		16		\$0.00
Medium	Work In Progress			4/20/2009 9:59:00 AM					
Quinones, Paul	AS PER MR.DIGGS TROPHY CASES IN FRONT OF CAFETERIA SERVING LINES NEED TO BE REMOVED DUE TO STUDENT BUILD UP DURING A,AND B LUNCH SHIFTS.								
Paul Quinones									
44826					4/20/2009		16		\$0.00
Medium	Work In Progress			4/20/2009 10:25:43 AM					
Carrasco, Danny	LIGHTING IN GYM LIGHT BULBS NEED TO BE REPLACED SISSER LIFT WILL BE NEEDED TO REMOVE LIGHTS BULBS.								
Paul Quinones									
44827					4/20/2009		16		\$0.00
Medium	Work In Progress			4/20/2009 11:15:43 AM					
Quinones, Paul	MAIL BOX NEEDED FOR C.H.S. NEED A MUCH LARGER MAILBOX.								
Paul Quinones			4/20 Paul, this is a request for material. Go ahead and use this work order so you can complete the task and let Ruben know how big you want the mailbox(example 20" x 20" x 12") and submitt this w/o # on the request. Mike						

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
44949		Parking Lot			4/23/2009		13		\$0.00
Medium	Work In Progress				4/23/2009 8:30:53 AM				
Aldaz, Bobby	Need help with fence lines and pick up debris left from bond fire.								
<u>Guadalupe Ontiveros</u>									
44995					4/24/2009		12		\$0.00
Medium	Work In Progress	Cafeteria			4/24/2009 7:43:04 AM				
Lozoya, Manny	DOOR GOING INTO CAFETERIA, HARDWARE FELL OFF DOOR I HAVE THE HANDLE TO DOOR								
<u>Paul Quinones</u>									
45109					4/28/2009		8		\$0.00
Medium	Work In Progress				4/28/2009 2:55:53 PM				
Ontiveros, Joe	BOYS REST RM . BROKEN LAVATORY FAUCET IN WING B NEED TO BE REPLACED.								
<u>Paul Quinones</u>									
45152					4/29/2009		7		\$0.00
Medium	Work In Progress				4/29/2009 2:42:22 PM				
Ontiveros, Joe	Provide proper drainage to fire pump leak. (see Mike)								
<u>Michael Munoz</u>									
45163					4/29/2009		7		\$0.00
Medium	Work In Progress				4/29/2009 3:27:55 PM				
Lozoya, Manny	FRONT ENTRANCE DOOR KEY WILL NOT OPEN DOOR, AND PANIC BAR AS WELL. AREA COURT YARD FRONT ENTRANCE.								
<u>Paul Quinones</u>									
45164					4/29/2009		7		\$0.00
Medium	Work In Progress				4/29/2009 3:30:57 PM				
Lozoya, Manny	NORTH END FIELD HOUSE BOYS LOCKER RM DOOR WILL NOT CLOSE PROPERLY WITH DEAD BOLT								
<u>Paul Quinones</u>									
45199					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress				4/30/2009 12:21:37 AM				
Quinones, Paul	Yearly - Chaparral HS C11 (Evaporative)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45233					5/1/2009		5		\$0.00
Medium	Work In Progress				5/1/2009 7:48:06 AM				
Solis, Lorenzo	BAD ACTUATOR VALVE NO WATER PRESSURE UNIT GOING OFF ON HI/LO PRESSURE.								
<u>Paul Quinones</u>									

5/6/2009 11:28:08 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral HS

45319					5/3/2009		3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:48 AM					
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45320					5/3/2009		3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:49 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
45321					5/3/2009		3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:49 AM					
Quinones, Paul	Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45322					5/3/2009	6/3/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:49 AM					
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
45384					5/4/2009		2		\$0.00
Medium	Work In Progress			5/4/2009 3:32:28 PM					
Lozoya, Manny	LOCK NEEDED IN NORTH END FIELD HOUSE ELECTRICAL HIGH VOLTAGE PANEL FOR SAFETY REASONS. LATCH WILL BE NEEDED AS WELL, THANKS.								
Paul Quinones									
Count: 66 Work Orders			Avg. Age of WO's	71		Total for Chaparral HS	0		\$0.00

Location: Chaparral MS

35697					7/6/2008	8/6/2008	304		\$0.00
Medium	Work In Progress			7/6/2008 12:20:06 AM					
Villalobos, David	Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
37050					8/14/2008		265		\$0.00
Medium	Work In Progress			8/14/2008 8:28:32 AM					
Ontiveros, Joe	need to replace shower columns in boys and girls rest rooms. Thxs								
Marti Muela									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
38127		Gym			9/16/2008		232		\$0.00
Medium	Work In Progress			9/16/2008 10:22:53 AM					
Ronquillo, Ruben	Asp PM 37575 FXT-CHM -017 Need plexiglass cover. FXT-CHM-018 Need plexiglass cover.								
Eric Medina									
38437					9/25/2008		223		\$0.00
Medium	Work In Progress			9/25/2008 3:39:35 PM					
Sotelo, Enrique	need light covers plastic								
Eric Medina									
38779					10/5/2008	10/26/2008	213		\$0.00
Medium	Work In Progress			10/5/2008 12:24:03 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
40741					12/10/2008		147		\$0.00
Medium	Work In Progress			12/10/2008 11:12:20					
Medina, Eric	About 8 of the exhaust fans in the restrooms or the custodial closets have not been working for a while.		12/16 - Asp Mike route to Eric.						
Robert Gonzalez									
40744					12/10/2008		147		\$0.00
Medium	Work In Progress			12/10/2008 11:20:18					
Medina, Eric	The floors in the boys and girls locker rooms need painting . They look very bad. Mike painted them about five years ago.								
Robert Gonzalez									
41070					1/4/2009	1/25/2009	122		\$0.00
Medium	Work In Progress			1/4/2009 12:18:49 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
41253	Main Building	Classroom			1/7/2009		119		\$0.00
Medium	Work In Progress	Room 303, 406,		1/7/2009 3:55:06 PM					
Lozoya, Manny	***URGENT THIRD REQUEST*** NEED KEYS FOR THEIR FILING CABINET HAVE VERY PRIVATE SPED INFO THAT NEEDS TO BE LOCKED UP								
Elena Palacios									
41651		Classroom			1/20/2009		106		\$0.00
Medium	Work In Progress	ROOM 203		1/20/2009 2:34:58 PM					
Lozoya, Manny	DRAWERS IN HOME EC ROOM DO NOT OPEN NEED TO HAVE THE KEY LOCKS REMOVED								
Elena Palacios									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
41653					1/20/2009		106		\$0.00
Medium	Work In Progress			1/20/2009 2:56:17 PM					
Lozoya, Manny		manny need to fix loose door handle in portable 14 and straightend the door for room 312							
Eric Medina									
41877					1/27/2009		99		\$0.00
Medium	Work In Progress	OUTSIDE AND		1/27/2009 9:57:18 AM					
Orozco, Danny		NEED FOR DIMAR TO COME AND CK LEAKING SPRINKLER HEAD.							
Eric Medina									
41954					1/28/2009		98		\$0.00
Medium	Work In Progress			1/28/2009 3:14:33 PM					
Estrada, Jesus		NEED CARPET REPLACED IN BAND ROOM.				1/28/09 - FAXED TO MICHAEL @ AZTEC			
Jesus Estrada									
41980					1/29/2009		97		\$0.00
Medium	Work In Progress			1/29/2009 8:17:34 AM					
Medina, Eric		please order and replace alll window screens that are damaged. thxs							
Michael Munoz									
42032					1/30/2009		96		\$0.00
Medium	Work In Progress			1/30/2009 3:03:37 PM					
Ontiveros, Joe		joe i need you to look at the toilet in the womens faculty rr							
Eric Medina									
42142					2/2/2009		93		\$0.00
Medium	Work In Progress			2/2/2009 9:50:09 AM					
Lozoya, Manny		I NEED TWO XX2 KEYS ONE FOR CARMEN THE CUSTODIAN THAT CLEANS THAT ROOM 405A AND ONE FOR MYSELF. I LOAN MINE TO THE COMPUTOR TECH THATS IN THAT ROOM							
Robert Gonzalez									
42320		Cafeteria			2/6/2009		89		\$0.00
Medium	Work In Progress			2/6/2009 11:05:24 AM					
Orozco, Danny		FIX OR INSTALL BELL (DELIVERY DOOR) DEMETRIOS P. GIOVAS - SNP DIRECTOR 882-6771							
Alma Terrell									
42703	Main Building	Portables			2/19/2009		76		\$0.00
Medium	Work In Progress	PORTABLE 14		2/19/2009 11:19:25 AM					
Lozoya, Manny		REKEY THE BATHROOM DOOR WE CAN THEN USE THE ROOM FOR STORAGE.							
Elena Palacios									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

42992					2/26/2009		69		\$0.00
Medium	Work In Progress			2/26/2009 3:17:49 PM					
Jacquez, Ricardo	need to upgrade filtration system, too small, and also need to up size pumps								
Eric Medina									
43372					3/5/2009		6		\$0.00
Medium	Work In Progress			3/5/2009 1:05:54 PM		3/11/2009			
Ronquillo, Ruben	need to order 22 window screens with frames (will send size with sample to Ruben)								
Eric Medina									
43731					3/16/2009		51		\$0.00
Medium	Work In Progress			3/16/2009 9:09:28 AM					
Medina, Eric	all fire lanes, curbs and handicap ramps and logos need to be painted. thankyou								
Michael Munoz									
43732		Portables			3/16/2009		51		\$0.00
Medium	Work In Progress			3/16/2009 9:11:02 AM					
Medina, Eric	Doors to portables need to be painted especially the wooden one where the fire hydrant is in front.								
Michael Munoz									
43781					3/17/2009		50		\$0.00
Medium	Work In Progress			3/17/2009 9:10:57 AM					
Lozoya, Manny	we have a key that is stuck on the door lock the door on the west doors in the main hall exiting to the south								
Robert Gonzalez									
43956	Main Building				3/23/2009		44		\$0.00
Medium	Work In Progress			3/23/2009 1:28:13 PM					
Medina, Eric	GYM LOCKER ROOM DOORS NEED TO BE REPAINTED								
Elena Palacios									
43957	Main Building	Gym			3/23/2009		44		\$0.00
Medium	Work In Progress	BOYS LOCKER			3/23/2009 1:30:16 PM				
Medina, Eric	ENTRANCE TO BOYS LOCKER ROOM NEEDS TWO PLACES TO BE REPAIRED WITH SHEETROCK DUE TO HOLES ON WALLS								
Elena Palacios									
43960	Main Building	Office			3/23/2009		44		\$0.00
Medium	Work In Progress	ENTIRE			3/23/2009 1:35:18 PM				
Medina, Eric	DAMAGED CEILING TILES NEED TO BE REPLACED THROUGHOUT ENTIRE SCHOOL, MANY TILES ARE MISSING								
Elena Palacios									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

43961	Main Building	Classroom			3/23/2009		44		\$0.00
Medium	Work In Progress	30		3/23/2009 1:36:20 PM					
Medina, Eric		30 CLASSROOMS NEED WINDOW SCREENS							
Elena Palacios									
43962	Main Building	Parking Lot			3/23/2009		44		\$0.00
Medium	Work In Progress	FLOWER BED		3/23/2009 1:38:45 PM					
Medina, Eric		TRASH NEEDS TO BE CLEANED OUT OF FLOWER BED NEXT TO FRONT DOORS OUTSIDE SCHOOL							
Elena Palacios									
44184	Main Building	Restroom (Boys)			4/1/2009		35		\$0.00
Medium	Work In Progress			4/1/2009 3:39:48 PM					
Ontiveros, Joe		joe lavatory in boys rr is leaking water from lines that go to solenoid valves feeding dispensers							
Eric Medina									
44314					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:42 AM					
Orozco, Danny		Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
44975	Phase III New	Classroom			4/23/2009		13		\$0.00
Medium	Work In Progress	BAND ROOM		4/23/2009 2:47:36 PM					
Medina, Eric		need to repair walls and paint room							
Eric Medina									
45088					4/28/2009		8		\$0.00
Medium	Work In Progress			4/28/2009 8:44:50 AM					
Solis, Lorenzo		Lorenzo mr bogourdes package unit isn't working again could you please come look at it							
Eric Medina									
45108		Classroom			4/28/2009		8		\$0.00
Medium	Work In Progress	Science and		4/28/2009 2:12:32 PM					
Hernandez, Guillermo		Please set up computer furniture for the Science and Language Arts classrooms. Furniture will be delivered on May 13. Thank you!							
Sandra Almeraz									
45160					4/29/2009		7		\$0.00
Medium	Work In Progress			4/29/2009 3:20:12 PM					
Medina, Eric		will be setting up display for art teacher at gms on 4/30 and tear down on 5/4							
Eric Medina									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

45177					4/29/2009		7		\$0.00
Medium	Work In Progress			4/29/2009 3:54:54 PM					
Medina, Eric	Library cove. Please cut weeds and water (grass is not green)								

Michael Munoz

45178					4/29/2009		7		\$0.00
Medium	Work In Progress			4/29/2009 3:55:56 PM					
Medina, Eric	Gym- remove awning and return to PPD for repair.								

Michael Munoz

45179					4/29/2009		7		\$0.00
Medium	Work In Progress			4/29/2009 3:56:53 PM					
Medina, Eric	Fire extinguishers are not being inspected. PMS are but the tag is not. This is a code violation.								

Michael Munoz

45191					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:34 AM					
Medina, Eric	Yearly - Chaparral MS C11 (Swamp Coolers)(Yearly) - Refer to PM schedule details.								

Margret Villalobos

45279					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:34 AM					
Medina, Eric	Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.								

Margret Villalobos

45280					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:35 AM					
Medina, Eric	Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.								

Margret Villalobos

45281					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:35 AM					
Medina, Eric	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								

Margret Villalobos

45282					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:35 AM					
Medina, Eric	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								

Margret Villalobos

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral MS

45283					5/3/2009	6/3/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:36 AM				
Medina, Eric	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
45328					5/3/2009		3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:51 AM				
Jacquez, Ricardo	Monthly - Chaparral MS - DP-781 - Refer to PM schedule details.								
Margret Villalobos									
45416		Cafeteria			5/5/2009		1		\$0.00
Medium	Work In Progress				5/5/2009 11:27:47 AM				
Orozco, Danny	HAVING PROBLEMS WITH DISHWASHER / IT TURNS ON BUT IT IS NOT RUNNING OR SPRAYING WATER.								
	SANDRA DIAZ - 824-4376								

Alma Terrell

Count: 45 Work Orders	Avg. Age of WO's 72	Total for Chaparral MS	0	\$0.00
------------------------------	----------------------------	-------------------------------	----------	---------------

Location: Desert Pride

36451		Classroom			8/1/2008		278		\$0.00
Medium	Work In Progress	14,15			8/1/2008 7:22:52 AM				
Castillo, Carlos	EMER. LIGHT DO NOT TURN ON IN BOTH ROOMS WHEN TURNING OFF BREAKER SWITCH FOR TESTING.								
David Acosta									
36452		Library			8/1/2008		278		\$0.00
Medium	Work In Progress				8/1/2008 7:26:27 AM				
Castillo, Carlos	EMER LIGHT WON'T STAY ON VERY LONG WHEN DOING ANNUAL TEST.								
David Acosta									
37699		Classroom			9/2/2008		246		\$0.00
Medium	Work In Progress	1,2			9/2/2008 2:08:10 PM				
Castillo, Carlos	NEED MORE EMERG. EXIT SIGNS. (ASK BY STATE FIREMARSHAL TO REQUEST).								
David Acosta									
39333		Portables			10/21/2008		197		\$0.00
Medium	Work In Progress	16			10/21/2008 11:07:07				
Castillo, Carlos	NEED EXIT SIGN AND EMER. LIGHT FOR LAST PORTABLE (ROOM 16).								
David Acosta									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Pride

42847		Parking Lot			2/24/2009		71		\$0.00
Medium	Work In Progress				2/24/2009 2:01:57 PM				
Gonzalez, Salvador		NEED CONCRETE RAMP ACCESSABLE TO OFFICE FOR HANDICAP AND TRUCK DELIVERY				3/3/09 - Route to Sal asp Mike			
David Acosta									
43228		Restroom (Boys)			3/2/2009		65		\$0.00
Medium	Work In Progress	2ND BLDG, 1&2,			3/2/2009 12:13:26 PM				
Lara, Ralph		PRINCIPLE REQUEST TO HAVE LOCK ON RESTROOM DOORS.							
David Acosta									
43230	Storage A				3/2/2009		65		\$0.00
Medium	Work In Progress				3/2/2009 12:27:02 PM				
Ontiveros, Guadalupe		NEED A COUPLE OF LOADS OF DIRT TO FILL IN AROUND LUNCH AREA.							
David Acosta									
44051		Office			3/30/2009		37		\$0.00
Medium	Work In Progress				3/30/2009 1:51:00 PM				
Lara, Ralph		NEED TO INSTALL 4X4 SLIDING WINDOW (WITH LOCK) ON WALL THAT DIVIDES HALL WAY AND DATA CLERK OFFICE							
David Acosta									
44076					3/31/2009		36		\$0.00
Medium	Work In Progress				3/31/2009 12:22:42 AM				
Acosta, David		Monthly - Desert Pride HS A16 (Fan Ex.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
44308					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:40 AM				
Acosta, David		Monthly - Desert Pride HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
44518		Parking Lot			4/7/2009		29		\$0.00
Medium	Work In Progress				4/7/2009 3:54:00 PM				
Ontiveros, Guadalupe		Measure and re-align parking curbs for more parking space.							
Michael Munoz									
45107		Classroom			4/28/2009		8		\$0.00
Medium	Work In Progress	Science and			4/28/2009 2:08:21 PM				
Acosta, David		Please set up furniture for computers that will be delivered on May 12 for the Science and Language Arts classrooms. Thank you.							
Sandra Almeraz									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Pride

45189					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress				4/30/2009 12:21:33 AM				
Aguilar, Patricio	Yearly - Desert Pride HS C11 (Evap.)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
45267					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:30 AM				
Acosta, David	Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45268					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:30 AM				
Acosta, David	Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45269					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:31 AM				
Acosta, David	Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 16 Work Orders			Avg. Age of WO's	85		Total for Desert Pride	0		\$0.00

Location: Desert Trail Intermediate

38213					9/18/2008		230		\$0.00
Medium	Work In Progress				9/18/2008 12:09:20 PM				
Gonzalez, Salvador	Please weld extra metal to the top of the metal scraper to add on a little more weight to it. Thank You....								
Johnny Acuna									
38780					10/5/2008	10/26/2008	213		\$0.00
Medium	Work In Progress				10/5/2008 12:24:03 AM				
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
39012					10/7/2008		211		\$0.00
Medium	Work In Progress				10/7/2008 3:30:52 PM				
Lozoya, Manny	Need a replacement Door and Door Frame for Portable #413 inside Restroom Door.								
Johnny Acuna									
39014					10/7/2008		211		\$0.00
Medium	Work In Progress				10/7/2008 3:33:24 PM				
Lozoya, Manny	Portable #410: Need a Replacement Metal Door.								
Johnny Acuna									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
39677					10/31/2008		187		\$0.00
Medium	Work In Progress			10/31/2008 4:09:15 PM					
Gonzalez, Salvador		Need to re-weld stainless sheetmetal sheet together that came apart in the kitchen sink area.							
Johnny Acuna									
39760					11/3/2008		184		\$0.00
Medium	Work In Progress			11/3/2008 7:40:41 AM					
Ronquillo, Ruben		Window frames in the side of the main doors in the NW hall needs to be replaced or repaired. There is too much corrosion.							
Johnny Acuna									
41071					1/4/2009	1/25/2009	122		\$0.00
Medium	Work In Progress			1/4/2009 12:18:50 AM					
Orozco, Danny		Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
41192					1/6/2009		120		\$0.00
Medium	Work In Progress			1/6/2009 12:08:50 PM					
Lozoya, Manny		Room #117: need assistance in adjusting door frame and door.							
Johnny Acuna									
41193					1/6/2009		120		\$0.00
Medium	Work In Progress			1/6/2009 12:10:21 PM					
Lozoya, Manny		Portable #412: Door knob is very loose and teacher has problems opening door.							
Johnny Acuna									
41199	Main Building	Classroom			1/6/2009		120		\$0.00
Medium	Work In Progress			1/6/2009 2:18:47 PM					
Lozoya, Manny		Urgente. Cuarto 410 la chapa se quebro, y no se puede cerrar. gracias							
Marisela Torres									
41414					1/12/2009		114		\$0.00
Medium	Work In Progress			1/12/2009 4:08:44 PM					
Lozoya, Manny		Portable #403: (Mrs. Rios): Need to install a new door knob to Portable #403. Has been repaired several times. Door knob gets stuck and the teacher and student's sometimes cannot come out of the classroom. It's the only door to their classroom. (Safety Issue in case of an Emergency).							
Johnny Acuna									
41494					1/14/2009		112		\$0.00
Medium	Work In Progress			1/14/2009 1:33:10 PM					
Ontiveros, Guadalupe		(Need Assistance): Need tractor to dig up 6'ft. in all directions around 2 sets of swings in the playground area and fill in with playground sand. Thank You.....							
Johnny Acuna									
5/6/2009 11:28:09 AM									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Trail Intermediate

41496					1/14/2009		112		\$0.00
Medium	Work In Progress			1/14/2009 1:45:26 PM					
Lozoya, Manny	Need an oval lock for filing cabinet to the nurse's office. (Student Records).								
Johnny Acuna									
41594		Cafeteria			1/16/2009		110		\$0.00
Medium	Work In Progress			1/16/2009 11:58:05 AM					
Orozco, Danny	Plastic Handle fell off to Sprayer in Dishwashing Area								
	Pat Cisneros - SNP Manager 824-3822								
Alma Terrell									
41790	Main Building	Custodial			1/23/2009		56		\$0.00
Medium	Work In Progress			1/23/2009 11:10:22 AM		3/20/2009			
Carbajal, Jimmy	Podria prestarme el extractor de 2 galones?. Gracias.								
Marisela Torres						1/30/09 - DELIVERED EXTRACTOR (AS LOANER); 4/20/09 - REQUESTED STATUS FROM JIMMY. 4/23/09 - AS PER JIMMY, HAS NOT BEEN PICKED UP YET. MARISELA STILL HAS IT.			
41985					1/29/2009		97		\$0.00
Medium	Work In Progress			1/29/2009 10:16:23 AM					
Gonzalez, Salvador	Please re-weld stainless steel sink that came apart in the left corner of the sink tub. (kitchen) (South sink)								
Johnny Acuna									
42029	Main Building	Hallway/Corridor			1/30/2009		96		\$0.00
Medium	Work In Progress			1/30/2009 1:01:18 PM					
Lozoya, Manny	Puerta principal (pasillo kinder) esta caida,								
Marisela Torres									
42144					2/2/2009		93		\$0.00
Medium	Work In Progress			2/2/2009 12:12:43 PM					
Gonzales, Angel	Please repair Echo Blower. (Desert Trail) Got sent over to Auto shop by Memo on Payday. (1/30/09)								
Johnny Acuna									
42594					2/17/2009		78		\$0.00
Medium	Work In Progress			2/17/2009 8:07:41 AM					
Lozoya, Manny	Need a key made for storage cabinet lock in room #204 (Mrs. Stewart). (Will send out core by Mail to Locksmith)								
Johnny Acuna									
43733	Main Building	Restroom (Boys)			3/16/2009		51		\$0.00
Medium	Work In Progress			3/16/2009 9:33:28 AM					
Lozoya, Manny	Puerta de un bano para maestros esta cerrada, no se puede abrir.								
Marisela Torres									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Desert Trail Intermediate									
43738	Main Building	Custodial			3/16/2009		51		\$0.00
Medium	Work In Progress			3/16/2009 11:26:13 AM					
Lozoya, Manny	Reemplasar llave (J master, para Laura) esta doblada.								
Marisela Torres									
43740					3/16/2009		51		\$0.00
Medium	Work In Progress			3/16/2009 1:12:03 PM					
Acuna, Johnny	NOT GOOD FOR 5 YEAR OLD.- NEED SIGN FOR 6YRS AND OLDER.								
Michael Munoz									
44139					3/31/2009		36		\$0.00
Medium	Work In Progress			3/31/2009 3:50:56 PM					
Solis, Lorenzo	Need installation of duct work for 5 Ton unit in Room #398								
Johnny Acuna									
44315					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:42 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
44370					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:23:00 AM					
Acuna, Johnny	Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
44372					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:23:01 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
44499					4/7/2009		29		\$0.00
Medium	Work In Progress			4/7/2009 12:13:18 PM					
Lozoya, Manny	Need 2 Hasp locks, (2) masterlocks with same key, and a can of Super Lube.								
Johnny Acuna									
44633					4/12/2009	4/28/2009	24		\$0.00
Medium	Work In Progress			4/12/2009 12:21:22 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
44919	Main Building	Restroom (Girls)			4/22/2009		14		\$0.00
Medium	Work In Progress			4/22/2009 12:29:51 PM					
Ontiveros, Joe	Sanitarios ninas hall 2 grado, tira demasiada agua por la valvula.								
Marisela Torres									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert Trail Intermediate

44920	Main Building	Restroom (Boys)			4/22/2009		14		\$0.00
Medium	Work In Progress			4/22/2009 12:34:11 PM					
Ontiveros, Joe	sanitarios ninos frente teacher lounge esta tapado,se necesita el cable.								
Marisela Torres									
45078					4/28/2009		8		\$0.00
Medium	Work In Progress			4/28/2009 7:50:29 AM					
Orozco, Danny	There was a Fire Sprinkler Inspection on 4/24/09 for the main building. The system was Red Tagged: Need to replace the Retard Chamber on the fire sprinkler system. It does not deliver the signal to the main panel to trigger the Fire Alarm.								
Johnny Acuna									
45194					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:35 AM					
Acuna, Johnny	Yearly - Desert Trail ES C11 (Evap.Cool)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
45202					4/30/2009		6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:38 AM					
Jacquez, Ricardo	Monthly - Desert Trail - Refer to PM schedule details.								
Margret Villalobos									
45208	Main Building				4/30/2009		6		\$0.00
Medium	Work In Progress			4/30/2009 11:34:03 AM					
Carbajal, Jimmy	Aspiradora #LO6000000048 No ajusta la altura y el motor hace un ruido muy fuerte.								
Marisela Torres									
45293					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:39 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45294					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:40 AM					
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
45295					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:40 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Comp Date	Aged	Hours	Costs
Assigned To	Description		Action Taken						
Requester Name									

Location: Desert Trail Intermediate

45344	Main Building	Restroom (Boys)			5/4/2009		2		\$0.00
Medium	Work In Progress			5/4/2009 11:22:01 AM					

Ontiveros, Joe PASILLO 2 GRADO . ORINAL ,BANO NINOS ,
VALVULA TIRANDO MUCHA AGUA,

Marisela Torres

45390					5/4/2009		2		\$0.00
Medium	Work In Progress			5/4/2009 3:48:59 PM					

Ontiveros, Joe need assistance in repair of outdoor waterfountain.
(playground)

Johnny Acuna

Count: 39 Work Orders			Avg. Age of WO's 77		Total for Desert Trail Intermediate		0		\$0.00
------------------------------	--	--	----------------------------	--	--	--	----------	--	---------------

Location: Desert View ES

36939	Main Building				8/12/2008		267		\$0.00
Medium	Work In Progress			8/12/2008 8:37:50 AM					

Ortiz, Ruben Tested exit signs (4) are not working 2 in Gym and Cafeteria asp PM 36526. Need to order thru material request and complete wo once they are replaced.

Ruben Ortiz

37044					8/13/2008		-2	8	\$200.00
Medium	Work In Progress			8/13/2008 8:42:58 PM		8/11/2008			

Ortiz, Ruben To: Carlos Castillo, Electrical
There are four Exit signs and light combo that are not working. In the cafeteria and gym, two and two. There are two emergency light that are not working, in the middle hallway and the west hallway.
Thank you.

Ruben Ortiz

38108					9/15/2008		233		\$0.00
Medium	Work In Progress			9/15/2008 7:13:21 PM					

Villalobos, David Requesting for plumber to check if two water faucets can be installed for cleaning purposes

Ruben Ortiz

39053					10/8/2008		210		\$0.00
Medium	Work In Progress			10/8/2008 5:07:00 PM					

Villalobos, David To Mike Munoz
I was asked by Mr. Carrasco that he needs hot water and more water pressure for the shower in the Special Ed room. There is a child that needs to be bathed often and the water is too cold. He asked for an urgent work order.
Mr. Carrasco asked for this work order to be sent directly to you because he wants it ASAP 10/08/08.
Child is being bathed in cold water. Thank you.

Ruben Ortiz

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
39404					10/22/2008		196		\$0.00
Medium	Work In Progress				10/22/2008 9:10:57 PM				
Lara, Ralph		Carlos Castillo				The button for the handicap door is not working on the southside of the building exit.			
Ruben Ortiz									
40871		Cafeteria			12/15/2008		142		\$0.00
Medium	Work In Progress				12/15/2008 2:35:04 PM				
Moncayo, Fernando		AS PER DIMAR SYSTEM, RANGE HOOD SYSTEMS REPORT DATED 12/15/08, EXHAUST FAN IS NOT OPERATING.							
		DIANA LAZARIN SNP MGR 589-2425							
Jacqueline Aguilar									
41887					1/27/2009		99		\$0.00
Medium	Work In Progress				1/27/2009 12:56:50 PM				
Lara, Ralph		please replace exterior door to rm 25. thxs							
Michael Munoz									
41888					1/27/2009		99		\$0.00
Medium	Work In Progress				1/27/2009 12:58:48 PM				
Ortiz, Ruben		please schedule the aerator order seed and fertilizer for the areas on campus that do no have grass in the circle. thxs							
Michael Munoz									
41921					1/28/2009		98		\$0.00
Medium	Work In Progress				1/28/2009 6:49:22 AM				
Moncayo, Fernando		Ladies in cafeteria need a lock for their file cabinet. Hinges on the walk in refrigerator are broken having trouble locking it. Thank you.							
Ruben Ortiz									
42165					2/2/2009		93		\$0.00
Medium	Work In Progress				2/2/2009 9:33:14 PM				
Lara, Ralph		Need a door replaced in room 25; 2 inches from the bottom of the door is rusted through; the replacement has been request by Principal Carrasco. Thank you, Ruben							
Ruben Ortiz									
42230		Portables			2/4/2009		91		\$0.00
Medium	Work In Progress				2/4/2009 2:49:07 PM				
Gonzalez, Salvador		Need to install ramps to portable (see Mike).							
Michael Munoz									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

42588					2/13/2009		82		\$0.00
Medium	Work In Progress				2/13/2009 8:18:55 PM				
Villalobos, David		Need wall faucets outside replaced due to leaking. Thank you.							
Ruben Ortiz									
42616		Cafeteria			2/17/2009		78		\$0.00
Medium	Work In Progress				2/17/2009 11:21:14 AM				
Moncayo, Fernando		WHEELS TO STAINLESS STEEL WORK TABLE NEEDS TO BE REPLACED (WHEELS ARE ROTTED OUT)							
		DIANA LAZARIN - SNP MANAGER 589-2425							
Alma Terrell									
43936					3/20/2009		47		\$0.00
Medium	Work In Progress				3/20/2009 3:17:43 PM				
Lara, Ralph		Alfredo Holguin came by request for the door to be fixed on the new portable. Rafa came by to check about the key for the door. Worked on the doors, middle door is complete, outside doors are pending materials							
Ruben Ortiz									
43981					3/24/2009		43		\$0.00
Medium	Work In Progress				3/24/2009 2:51:11 PM				
Munoz, Michael		need to lay concrete to stair and ramp area to tie into asphalt on portable that was moved.							
Michael Munoz									
44009		Restroom (Boys)			3/25/2009		42		\$0.00
Medium	Work In Progress				3/25/2009 9:48:15 AM				
Ortiz, Ruben		This work order is for two urinals in the boys restroom water dont go so fast like it use to do. Please stop by and take care of the problem. THANKYOU IN ADVANCED.				4/6 - Asp Mike, route to Ruben			
Hector Rivera									
44098		Restroom (Boys)			3/31/2009		36		\$0.00
Medium	Work In Progress				3/31/2009 8:04:09 AM				
Ortiz, Ruben		This work order is for new water faucets in the boys and girls restrooms that are broken . THANK YOU IN ADVANCED.				4/6 - Asp Mike, route to Ruben			
Hector Rivera									
44206					4/1/2009		35		\$0.00
Medium	Work In Progress				4/1/2009 9:16:38 PM				
Villalobos, David		To David, I need the outside water fountain faucets in the lower level replaced. Thank you. Ruben							
Ruben Ortiz									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert View ES

44323					4/5/2009	4/26/2009	31		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			4/5/2009 12:22:45 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Orozco, Danny Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

44430					4/5/2009	4/11/2009	31		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			4/5/2009 12:23:21 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ortiz, Ruben Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.

Margret Villalobos

44491					4/7/2009		29		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			4/7/2009 8:56:27 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ortiz, Ruben Trash by fence and apartments needs to be picked up and any trash or glass around. Also as per the picture the weeds growing on the sand pond need to be removed. Shrubs growing along the fence line are fine.

Michael Munoz

44492					4/7/2009		29		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			4/7/2009 8:59:44 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ortiz, Ruben Wood piles and pole on south east side need to be removed. You could throw a little at a time in the dumpsters or when its your turn to come to the plant you can request a trailer and dispose off here a the large role away dumpster.

Michael Munoz

44493					4/7/2009		29		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			4/7/2009 9:08:20 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ortiz, Ruben Crusher fine needs to be added along the bottom of the portable.

Michael Munoz

44494					4/7/2009		29		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			4/7/2009 9:09:10 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ortiz, Ruben Russian olive trees need to be trimmed and pruned to form a shade and wind barrier.

Michael Munoz

44523					4/7/2009		29		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			4/7/2009 10:17:11 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David The water fountain cooler on the westside wing needs the drain replaced that goes to the trap. I think it's called a pigtail drain, (not quit sure) it's made out of brace. I also need a pressure valve ½ inch. Need parts asap children are testing and they need the water fountain working. Thank you, Ruben

Ruben Ortiz

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Desert View ES

44566					4/8/2009		28		\$0.00
Medium	Work In Progress			4/8/2009 10:01:19 PM					
Lara, Ralph	Door in the new portable is falling off the hinges, screws can't be tightened. Will need 2 inch wooden screws 1/4 thickness, will need 12 screws. Will need the screws asap due to spring holiday. Thank you, Ruben								
Ruben Ortiz									
44567					4/8/2009		28		\$0.00
Medium	Work In Progress			4/8/2009 10:03:54 PM					
Ortiz, Ruben	Will need 16 brackets or bearings for the swings. Thank you, Ruben								
Ruben Ortiz									
44614					4/12/2009	4/28/2009	24		\$0.00
Medium	Work In Progress			4/12/2009 12:21:14 AM					
Rivera, Hector	Monthly - QRTLY BLDG INSP REPORT (DV) - Refer to PM schedule details.								
Jesus Estrada									
44900					4/21/2009		15		\$0.00
Medium	Work In Progress			4/21/2009 9:56:36 PM					
Holguin, Alfredo	The new sponge foam that was added to the playground is peeling in different areas, please advice as to what needs to be done to have it fixed. Thank you, Ruben								
Ruben Ortiz									
44901					4/21/2009		15		\$0.00
Medium	Work In Progress			4/21/2009 10:01:38 PM					
Ronquillo, Ruben	Requesting 10 yards of screening to put around the new portable. Thank you, Ruben					Route to Warehouse 4/27			
Ruben Ortiz									
45203					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:39 AM					
Ortiz, Ruben	Yearly - Desert View ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									
45329					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:52 AM					
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45330					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:52 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

45331					5/3/2009	5/11/2009	3		\$0.00
-------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				5/3/2009 12:22:52 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ortiz, Ruben		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
--------------	--	--	--	--	--	--	--	--	--

Margret Villalobos

45419					5/5/2009		1		\$0.00
-------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				5/5/2009 2:11:24 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph		Need key mullium for back dinning room door - hall way door							
-------------	--	---	--	--	--	--	--	--	--

Patricio Aguilar

Count: 35 Work Orders			Avg. Age of WO's 63			Total for Desert View ES	8		\$200.00
------------------------------	--	--	----------------------------	--	--	---------------------------------	----------	--	-----------------

Location: GAC

36280					7/28/2008		282		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Back bottom road			7/28/2008 12:11:48 PM				
--------	------------------	------------------	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe		need to apply dirt and crusherfine in back road due to running water after haevy rain.							
----------------------	--	--	--	--	--	--	--	--	--

Juan Ambriz

36334		Parking Lot			7/29/2008		281		\$0.00
-------	--	-------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	bottom dirt			7/29/2008 3:47:57 PM				
--------	------------------	-------------	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe		Need to apply more crusherfine in bottom dirt parking lot accumulating water after rain							
----------------------	--	---	--	--	--	--	--	--	--

Juan Ambriz

36949		Office			8/12/2008		267		\$0.00
-------	--	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	A-WING			8/12/2008 10:35:44 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Ambriz, Juan		IF IT WOULD BE POSSIBLE TO HAVE THE AIR VENTS IN JESUS REYE'S OFFICE ADJUSTED. NOT ENOUGH AIR COMES THROUGH.							
--------------	--	--	--	--	--	--	--	--	--

Mary Garcia

37912		Parking Lot			9/8/2008		240		\$0.00
-------	--	-------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	bottom dirt			9/8/2008 3:39:17 PM				
--------	------------------	-------------	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe		Need to level bottom parking lot with crusher fine to avoid accumulated water after rains							
----------------------	--	---	--	--	--	--	--	--	--

Juan Ambriz

37939					9/9/2008		239		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress	Back dirt road			9/9/2008 8:25:56 AM				
--------	------------------	----------------	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe		need to add dirt to back dirt road due to running water after rains. If possible add crusher fine.							
----------------------	--	--	--	--	--	--	--	--	--

Juan Ambriz

39366		Office			10/22/2008		196		\$0.00
-------	--	--------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	C-WING			10/22/2008 9:54:03 AM				
--------	------------------	--------	--	--	-----------------------	--	--	--	--

Ambriz, Juan		AS PER ALFREDO-GO AHEAD AND SEAL OFF THE WALL WHERE THE AIR UNIT WAS IN OFELIA'S OFFICE.				APPROVED BY ALFREDO			
--------------	--	--	--	--	--	---------------------	--	--	--

Mary Garcia

5/6/2009 11:28:09 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: GAC

40674	RTC	Parking Lot			12/8/2008		32	1	\$25.00
Medium	Work In Progress	RTC ACROSS			12/8/2008 2:30:07 PM	1/9/2009			
Soria, Mike	AS PER GLORIA SAENZ-NEED TO HAVE THE DIRT REMOVED FROM THE PARKING LOT.		Completed asp report 1/9/09						
Mary Garcia									
41072					1/4/2009	1/25/2009	122		\$0.00
Medium	Work In Progress				1/4/2009 12:18:50 AM				
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
41865					1/26/2009		100		\$0.00
Medium	Work In Progress	OUTSIDE AND			1/26/2009 4:09:18 PM				
Orozco, Danny	AS PER JUAN AMBRIZ-NEED FOR DIMAR TO COME IN AN RECAP A PIPE THAT IS LEAKING WATER. (TO ASK FOR JUAN WHEN DIMAR COMES IN)		DAVID VILLALOBOS ALREADY LOOKING INTO THIS SITUATION AND SUGGESTED FOR JUAN TO PUT IN A WORK ORDER FOR DIMAR TO TAKE CARE OF THIS.						
Mary Garcia									
41937	RTC	Portables			1/28/2009		98		\$0.00
Medium	Work In Progress	RTC ACROSS			1/28/2009 10:42:26 AM				
Ambriz, Juan	AS PER GLORIA SAENZ-KEYS UNABLE TO OPEN CLASSROOM-MS. MORALES, MAYBE DUE TO DUST.								
Mary Garcia									
42414	Pre-K	Cafeteria			2/10/2009		85		\$0.00
Medium	Work In Progress	PRE-K			2/10/2009 11:21:26 AM				
Ambriz, Juan	AS PER MS. BERRY- NEED HELP W/ 2 WALL HANINGS IN THE CAFETERIA.								
Mary Garcia									
42453	RTC	Portables			2/10/2009		85		\$0.00
Medium	Work In Progress	RTC ACROSS			2/10/2009 3:53:38 PM				
Ambriz, Juan	AS PER GLORIA SAENZ-NEED TO HAVE THE RAMP BOARDS REPLACED. (THERE IN REAL BAD SHAPE DUE TO RAIN)		2/29/09 - Have you ck'd w/Warehouse on the status of supplies? - mkv						
Mary Garcia									
42625		Parking Lot			2/17/2009		78		\$0.00
Medium	Work In Progress	bottom dirt			2/17/2009 2:13:55 PM				
Ontiveros, Guadalupe	Need to level and add crusher fine both west and east ends to add more parking spaces.								
Juan Ambriz									
43031		Office			2/27/2009		68		\$0.00
Medium	Work In Progress	A-WING			2/27/2009 10:29:17 AM				
Ambriz, Juan	AS PER CALIXTO-NEED MAINTENANCE (JUAN) TO INSTALL BASE BOARDS AROUND THE AREA WHERE FURNITURE WAS REMOVED, DUE TO THE REMODELING OF THERE OFFICE.		2/29/09 - Juan have you ck'd w/warehouse for staus? - mkv						
Mary Garcia									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
43126					3/1/2009		66		\$0.00
Medium	Work In Progress			3/1/2009 12:23:03 AM					
Orozco, Danny		Yearly - GAC Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
43376		Office			3/5/2009		62		\$0.00
Medium	Work In Progress	C-WING		3/5/2009 1:37:51 PM					
Ambriz, Juan		AS PER KARLA QUEZADA-NEED HELP IN TRANSFERING THE FURNITURE FROM CONFERENCE ROOM #2 INTO MPT'S OFFICES (SHIRLEY & VICKI)							
<u>Mary Garcia</u>									
43583		Electrical Room			3/11/2009		56		\$0.00
Medium	Work In Progress			3/11/2009 9:07:28 AM					
Orozco, Danny		In the server room at GAC . . .cap off the fire sprinkler inside the server room on March 25 during the water shut down starting @ 9:00							
<u>Cora Ramirez</u>									
43646					3/12/2009		55		\$0.00
Medium	Work In Progress			3/12/2009 10:14:04 AM					
Munoz, Michael		Install fencing on south side where none exists.							
<u>Alfredo Holguin</u>									
43822					3/18/2009		49		\$0.00
Medium	Work In Progress			3/18/2009 7:37:31 AM					
Ambriz, Juan		as per our conversation, please dispose of exhaust fans the are not working by the morgan bldgs, and pick-up and deliver the railroad ties by the tennis courts.continue on the cleaning around your morgan bldg. thxs							
<u>Michael Munoz</u>									
43930					3/20/2009		47		\$0.00
Medium	Work In Progress			3/20/2009 2:21:10 PM					
Villalobos, David		Having problems with hot water							
<u>Juan Ambriz</u>									
44144	B-Wing	Hallway/Corridor			3/31/2009		36		\$2.99
Medium	Work In Progress	Human		3/31/2009 3:53:32 PM					
Ambriz, Juan		Handicap door not working							
<u>Juan Ambriz</u>									
44251	Pre-K	Cafeteria			4/3/2009		33		\$0.00
Medium	Work In Progress	PRE-K		4/3/2009 10:37:37 AM					
Ambriz, Juan		AS PER MS. BERRY-NEED TO HAVE 2 NEW SAND & WATER TABLES ASSEMBLED.							
<u>Mary Garcia</u>									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
44316					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:42 AM				
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
44336					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:49 AM				
Orozco, Danny		Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
44389					4/5/2009	4/21/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:07 AM				
Ambriz, Juan		Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
44479					4/6/2009		30		\$0.00
Medium	Work In Progress				4/6/2009 3:50:07 PM				
Ambriz, Juan		please paint yellow lines and arrows in bus turn around and any where else that need painting. thxs							
<u>Michael Munoz</u>									
44599		Parking Lot			4/9/2009		27		\$0.00
Medium	Work In Progress	Flag pole			4/9/2009 3:53:55 PM				
Ambriz, Juan		Need to replace flag pole rope and hooks.							
<u>Juan Ambriz</u>									
44798		Restroom (Girls)			4/17/2009		19		\$0.00
Medium	Work In Progress	B-Wing HR Dept			4/17/2009 3:14:03 PM				
Castillo, Carlos		Need to run power to exhaust fan.							
<u>Juan Ambriz</u>									
44800		Restroom (Girls)			4/17/2009		19		\$0.00
Medium	Work In Progress	C-Wing behind			4/17/2009 3:16:22 PM				
Castillo, Carlos		Need to run power to exhaust fan							
<u>Juan Ambriz</u>									
44834		Parking Lot			4/20/2009		16		\$0.00
Medium	Work In Progress	Exterior lighting			4/20/2009 3:33:33 PM				
Castillo, Carlos		Breaker keeps tripping for the exterior lighting							
<u>Juan Ambriz</u>									
44852					4/21/2009		15		\$0.00
Medium	Work In Progress				4/21/2009 8:37:06 AM				
Orozco, Danny		Gauges are outdated, need to be replaced asp inspection by Century Fire.							
<u>Michael Munoz</u>									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

44853					4/21/2009		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/21/2009 8:39:04 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny Water motor gong not working, asp inspection by Century Fire Systems. Please repair or acquire quote.

Michael Munoz

44854					4/21/2009		15		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	B-Wing			4/21/2009 8:41:28 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Orozco, Danny East cooridor (B-Wing) need to relocate and plug one fire sprinkler head, asp inspection by Century Fire Systems.

Michael Munoz

44927	RTC	Office			4/22/2009		14		\$0.00
-------	-----	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	RTC ACROSS			4/22/2009 1:23:23 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Ambriz, Juan AS PER GLORIA SAENZ-NEED TO HAVE 2 LARGE BOXED PICKED UP AND BROUGHT OVER TO THE SPED OFFICE.

Mary Garcia

44928		Office			4/22/2009		14		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	B-WING			4/22/2009 1:24:50 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan AS PER ANNE-NEED TO HAVE AN EXTRA LIGHT TURNED ON BY RICHARD ACOSTA OFFICE FOR PSFA AUDITORS, IT'S TO DARK

Mary Garcia

44929		Office			4/22/2009		14		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	A WING			4/22/2009 1:26:31 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan AS PER CORA-NEED TO HAVE HER AIR UNIT CHECK, BECAUSE IT'S THROWING HOT AIR.

Mary Garcia

44930		Office			4/22/2009		14		\$0.00
-------	--	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	A WING			4/22/2009 1:27:45 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Ambriz, Juan AS PER MARY GARCIA-NEED TO HAVE AN EXTRA LIGHT TURNED ON THE THE FILE ROOM, IT'S TO DARK.

Mary Garcia

44969	Pre-K				4/23/2009		13		\$0.00
-------	-------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	PRE-K			4/23/2009 1:56:40 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Ambriz, Juan AS PER MS. BERRY-NEED TO ASSEMBLE A DID SIZE COTTAGE

Mary Garcia

44970	Pre-K				4/23/2009		13		\$0.00
-------	-------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	PRE-K			4/23/2009 2:00:16 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Ambriz, Juan AS PER MS. BERRY-WOULD LIKE THE LITTLE PLOT OF IDT TURNED OVER SO THEY CAN ADD SOME SOIL TO IT, BECAUSE IT'S AS HARD AS A ROCK.

Mary Garcia

5/6/2009 11:28:09 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

45028					4/24/2009		12		\$0.00
Medium	Work In Progress	GROUNDS			4/24/2009 4:52:13 PM				
Ambriz, Juan		AS PER MIKE SORIA-WATER SYSTEM IS NOT WORKING PROPERLY.				AS PER MIKE, HE ALREADY TALKED W/JUAN AMBRIZ			
Mary Garcia									
45029	Pre-K	Parking Lot			4/24/2009		12		\$0.00
Medium	Work In Progress	PRE-L PARKING			4/24/2009 4:54:31 PM				
Ambriz, Juan		AS PER MS. BERRY-NEED CHALK LINES DRAWN AND CONES IN THE BUS AREA FOR A TRIKE-A-TON ON 4/30/09. ALREADY TALKED W/JUAN AMBRIZ				JUAN IS AWARE OF THIS.			
Mary Garcia									
45176		Office			4/29/2009		7		\$0.00
Medium	Work In Progress	Georgina's office			4/29/2009 3:52:15 PM				
Ambriz, Juan		As per Ms. Georgina Install keyboard holder.							
Juan Ambriz									
45225		Office			4/30/2009		6		\$0.00
Medium	Work In Progress	B-Wing Norma			4/30/2009 3:55:32 PM				
Ambriz, Juan		As per Norma Reyes need to Install flipper cabinet in the office							
Juan Ambriz									
45242		Office			5/1/2009		5		\$0.00
Medium	Work In Progress	C-Wing			5/1/2009 12:39:53 PM				
Ambriz, Juan		As per Ms. Sheila Raihl need to Install new door stop.							
Juan Ambriz									
45303					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:43 AM				
Ambriz, Juan		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
45304					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:43 AM				
Ambriz, Juan		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
45305					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:43 AM				
Ambriz, Juan		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC

45343		Cafeteria			5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 10:45:27 AM				
Moncayo, Fernando		HOT UNIT SERVING AREA - PIPE CORRODED FROM UNIT TO THE DRAIN AREA							
Alma Terrell		GESSICA BLAZQUEZ - SNP MANAGER 882-6784							
45402		Office			5/5/2009		1		\$0.00
Medium	Work In Progress	Technology			5/5/2009 8:04:30 AM				
Ambriz, Jose		A/C unit not working properly							
Juan Ambriz									
45403		Hallway/Corridor			5/5/2009		1		\$0.00
Medium	Work In Progress	A-Wing			5/5/2009 8:06:39 AM				
Ambriz, Jose		Need to check thermostat not working properly with settings							
Juan Ambriz									
45429		Hallway/Corridor			5/5/2009		1		\$0.00
Medium	Work In Progress	B-Wing Main Unit			5/5/2009 3:15:12 PM				
Villalobos, Margret		A/C unit not working properly							
Juan Ambriz									
Count: 51 Work Orders			Avg. Age of WO's 58				Total for GAC	1	\$27.99

Location: Gadsden HS

35876	Main Building	Office			7/11/2008		299		\$0.00
Medium	Work In Progress				7/11/2008 2:28:45 PM				
Carrasco, Danny		NEED NEW BLINDS FOR PRINCIPAL CHAMBERS OFFICE							
Mario Apodaca		1. 40" X 5'							
		2. 7' X 5'							
36000	Library	Library			7/16/2008		294		\$0.00
Medium	Work In Progress				7/16/2008 3:18:40 PM				
Ontiveros, Guadalupe		An irrigation control box has a water leak underneath the asphalt outside the southwest exit.							
Albert Vallejo									
36066	North Building	Classroom			7/18/2008		292		\$0.00
Medium	Work In Progress				7/18/2008 3:19:18 PM				
Ronquillo, Ruben		NEED NEW WINDOW BLINDS (35"WX56"L) FOR ROOM 207 NEED 11 EA							
Mario Apodaca									
36067	Old English Bldg	Classroom			7/18/2008		292		\$0.00
Medium	Work In Progress				7/18/2008 3:21:06 PM				
Ambriz, Jose		NEED A NEW HEATING CONDESER AT ROOM 141 DO TO VANDALISM							
Mario Apodaca									
5/6/2009 11:28:09 AM									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

36310	Cafeteria (1998)	Cafeteria			7/29/2008		281		\$0.00
-------	------------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/29/2008 8:10:33 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando		NEED A SAFETY POWER DISCONNECT TO THE GHS WALK-IN'S (BOTH) ON THE CONDENSER UNITS ON THE ROOF				11/18 - Asp Mike route to Fernie			
-------------------	--	---	--	--	--	----------------------------------	--	--	--

MR. DEMETRIIOUS GIOVAS

Jacqueline Aguilar

36622					8/4/2008		275		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress	WWT			8/4/2008 4:10:54 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Sanchez, Raul		Replace motor for Wastewater Treatment Plant Blowers.							
---------------	--	---	--	--	--	--	--	--	--

Raul Sanchez

36878	Boys Gym				8/11/2008		268		\$0.00
-------	----------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/11/2008 8:35:04 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo		new shower column was installed in girls dressing room. need to install tile to complete project. see mike. thxs							
------------------	--	--	--	--	--	--	--	--	--

Michael Munoz

37049	Football Stadium	Football Field			8/14/2008		265		\$0.00
-------	------------------	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/14/2008 8:14:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael		Some of the concrete piers that support the bleachers are cracked and need to be repaired.							
----------------	--	--	--	--	--	--	--	--	--

Albert Vallejo

37094	Cafeteria (1998)	Cafeteria			8/14/2008		265		\$0.00
-------	------------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/14/2008 3:40:19 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose		ALL OUTSIDE DUCTS OF THE CAFE BLDG NEED TO BE RESEAL DOTO SUN AND WATER DAMAGE. ASAP							
--------------	--	--	--	--	--	--	--	--	--

Mario Apodaca

37232	Old English Bldg	Classroom			8/20/2008		259		\$0.00
-------	------------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2008 2:03:04 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Carrasco, Danny		NEED NEW WINDOW MINI BLINDS DOTO VANDALISM (W43 1/2" X L90") NEED #4							
-----------------	--	--	--	--	--	--	--	--	--

Mario Apodaca

37400					8/26/2008		253		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/26/2008 3:35:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos		Requested by Mr. Roberson for Rm. 127 Main Building- Install on/off switch for lights in room #127. When room was divided switch was left in room #128.							
------------------	--	---	--	--	--	--	--	--	--

Velia Alarcon

37431					8/27/2008		252		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/27/2008 8:10:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador		NEED TO CONSTRUCT SHADE AT GROUNDS DEPT. TO PROTECT IMPLEMENT.							
--------------------	--	--	--	--	--	--	--	--	--

Guadalupe Ontiveros

5/6/2009 11:28:09 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

37442					8/27/2008		252		\$0.00
Medium	Work In Progress			8/27/2008 10:51:46 AM					
Ontiveros, Guadalupe	Requested by Coach Hite for Football Field-Sod bare areas on Football Field before first home game on September 12th.								
Velia Alarcon									
37996	Agricultural	Classroom			9/10/2008		238		\$0.00
Medium	Work In Progress			9/10/2008 3:10:19 PM					
Ronquillo, Ruben	need new window blinds for room 568.ea 2 (60 1/2"x45")								
Mario Apodaca									
38286					9/22/2008		226		\$0.00
Medium	Work In Progress			9/22/2008 10:13:18 AM					
Apodaca, Mario	Requested by Ms. Lam Rm. 104 Main Building-Holder of the glass door of the south book shelf is broken.								
Velia Alarcon									
38287					9/22/2008		226		\$0.00
Medium	Work In Progress			9/22/2008 10:30:07 AM					
Villalobos, David	Requested by Ms. Lam Rm. 104 Main Building-Both cold and hot water of the faucet on the south side have sulfur smell.								
Velia Alarcon									
38296					9/22/2008		226		\$0.00
Medium	Work In Progress			9/22/2008 11:16:00 AM					
Vallejo, Albert	Requested by Ms. Roth Rm. 213 North Building-Legs are loose on various HEAVY lab tables and need to be tightened and possibly secured. Table tops are not attached to certain tables and also pose a safety hazard and noise maker.								
Velia Alarcon									
38429	Academic Bldg	Classroom			9/25/2008		223		\$0.00
Medium	Work In Progress			9/25/2008 2:39:13 PM					
Carrasco, Danny	need windos blinds (46 3/4" x 62") for the academic bldg need 10								
Mario Apodaca									
38465					9/26/2008		222		\$0.00
Medium	Work In Progress			9/26/2008 12:29:32 PM					
Lozoya, Manny	Mr. Chacon, Band Director needs a gate key.								
Michael Munoz									
38497					9/29/2008		219		\$0.00
Medium	Work In Progress			9/29/2008 10:57:19 AM					
Ontiveros, Guadalupe	Requested by Julio Alcantar for Student Parking Lot- Need more electrical poles to help mark the parking spaces in the student parking lot.					2/17/09 - Asp Mike, route to Lupe. Danny C.			
Velia Alarcon									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

38604					10/1/2008		217		\$0.00
Medium	Work In Progress			10/1/2008 2:02:50 PM					
Ambriz, Jose	Requested by Ms. Hartmann Rm. 568 Classroom between Ag. Shop and Wood Shop-Install an extracting fan to remove fumes coming into room 568, created by Auto and Ag engines. There's currently no way for fumes to exit from classroom. Fumes giving teacher and students headaches.								
<u>Velia Alarcon</u>									
38744					10/5/2008		213		\$0.00
Medium	Work In Progress			10/5/2008 12:23:50 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.		10/6/08 - Emailed to Ricky Borrego						
<u>Margret Villalobos</u>									
38790					10/5/2008	10/26/2008	99		\$0.00
Medium	Work In Progress			10/5/2008 12:24:06 AM		1/12/2009			
Orozco, Danny	Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
38893					10/5/2008	10/13/2008	213		\$0.00
Medium	Work In Progress			10/5/2008 12:24:44 AM					
Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39073	Agricultural	Classroom			10/9/2008		209		\$0.00
Medium	Work In Progress			10/9/2008 3:15:51 PM					
Ronquillo, Ruben	need a window blind for room 569 (60"x48")								
<u>Mario Apodaca</u>									
39823	Auto Shop	Classroom			11/4/2008		183		\$0.00
Medium	Work In Progress			11/4/2008 3:05:39 PM					
Lara, Ralph	need 2 new doors at the auto shop the doors are broken do to vandalism		Pending - No Funding - Received quote for 1,205.00 from Architectural Products. asp Mike						
<u>Mario Apodaca</u>									
40054	Old English Bldg	Gym			11/13/2008		174		\$0.00
Medium	Work In Progress			11/13/2008 3:05:05 PM					
Munoz, Michael	the girls gym need work on the gym floor do to roof leaks . A.S.A.P								
<u>Mario Apodaca</u>									
40182	Auto Shop	Classroom			11/18/2008		169		\$0.00
Medium	Work In Progress			11/18/2008 1:01:06 PM					
Moncayo, Fernando	NEED TO REMOVE THE OLD WASHER AT STORED IN THE AUTO SHOP. AT WAS IN THE KITCHEN ASAP.								
<u>Mario Apodaca</u>									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

40542	Old English Bldg	Restroom (Girls)			12/3/2008		154		\$0.00
Medium	Work In Progress				12/3/2008 2:51:58 PM				
Lara, Ralph	need a new door for the girls restroom at the old eng bldg at the top floor. asap.								
Mario Apodaca									
40695	Old English Bldg				12/9/2008		148		\$0.00
Medium	Work In Progress				12/9/2008 12:33:28 PM				
Ambriz, Jose	Girls Gym - Need to check heating and control dampers in gym.								
Michael Munoz									
40707	Library	Library			12/9/2008		148		\$0.00
Medium	Work In Progress				12/9/2008 2:59:42 PM				
Ambriz, Jose	NEED A NEW GAS VALVE FOR A HEATING UNIT AT THE LIBRARY								
Mario Apodaca									
40893		Athletic Field			12/16/2008		141		\$0.00
Medium	Work In Progress				12/16/2008 9:23:01 AM				
Ontiveros, Guadalupe	Requested by Mr. Lawrence for Soccer Field-Over seed soccer field, top soil for soccer field.								
Velia Alarcon									
40898					12/16/2008		141		\$0.00
Medium	Work In Progress				12/16/2008 10:00:05				
Ronquillo, Ruben	Requested by Coach Hite Football J.V. Locker Room in Boy's Gym-Install a mirror in J.V. locker room. Please make mirror as large as possible, alot of students need to use it at the same time.								
Velia Alarcon									
41052					1/4/2009	1/12/2009	122		\$0.00
Medium	Work In Progress				1/4/2009 12:18:42 AM				
Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
41149					1/4/2009		122		\$0.00
Medium	Work In Progress				1/4/2009 12:19:23 AM				
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.					1/6/09 - E-mailed to ricky.borrego@cummins.com'			
Margret Villalobos									
41205	Academic Bldg				1/6/2009		120		\$0.00
Medium	Work In Progress				1/6/2009 3:21:19 PM				
Ambriz, Jose	the heating unit at the greenhous need a new fan moter								
Mario Apodaca									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
41271	North Building	Gym			1/8/2009		118		\$0.00
Medium	Work In Progress				1/8/2009 2:36:51 PM				
Ronquillo, Ruben	NEED A NEW GLASS SHELV PUT IN AT THE DLSPLAY CASES(76"X12"1/4")								
Mario Apodaca									
41732	Cafeteria (1998)	Cafeteria			1/22/2009		104	11	\$275.00
Medium	Work In Progress				1/22/2009 12:38:06 PM				
Moncayo, Fernando	THE WHEELS ON THE CAFE TABLES NEED TO BE ADJUST ON ALL TABLES. A.S.A.P!!!!!!								
Mario Apodaca									
41733	Cafeteria (1998)	Cafeteria			1/22/2009		104		\$0.00
Medium	Work In Progress				1/22/2009 12:44:35 PM				
Moncayo, Fernando	A FLUORESCENT FIXTURES IS OUT AT THE KITCHEN NEED TO BE FIX								
Mario Apodaca									
41799	Main Building	Office			1/23/2009		103		\$0.00
Medium	Work In Progress				1/23/2009 2:38:36 PM				
Lara, Ralph	NEED A NEW DOOR FOR MR. CHEMBERS OFFICE. A.S.A.P								
Mario Apodaca									
42049	Academic Bldg	Classroom			1/30/2009		96		\$0.00
Medium	Work In Progress	Academic 306			1/30/2009 4:00:26 PM				
Castillo, Carlos	I'm also running 10 computers off of 3 power outlets. I have talked to Victor and he agrees that the wiring in my room is a problem. I did ask for this last year and I was told that it would be taken care of but I have not been told when that will happen.								
Erica Acosta									
42301	New Vocational				2/6/2009		89		\$0.00
Medium	Work In Progress				2/6/2009 8:27:10 AM				
Lara, Ralph	need new restroom toilet partitons at the boys restroom. do to vandalism								
Mario Apodaca									
42319	Cafeteria (1998)	Cafeteria			2/6/2009		89		\$0.00
Medium	Work In Progress				2/6/2009 11:04:33 AM				
Moncayo, Fernando	FIX OR INSTALL BELL (DELIVERY DOOR)								
	DEMETRIOUS P. GIOVAS - SNP DIRECTOR 882-6771								
Alma Terrell									
42389					2/9/2009		86		\$0.00
Medium	Work In Progress				2/9/2009 3:26:54 PM				
Moncayo, Fernando	THE DELI CART AT ROOM 233 IS AT 49 NEED TO BE AT 38 OR LOWER. ASAP.								
Mario Apodaca									
5/6/2009 11:28:10 AM									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

42429	Cafeteria (1998)	Cafeteria			2/10/2009		85		\$0.00
Medium	Work In Progress				2/10/2009 2:07:12 PM				
Moncayo, Fernando		PUSH CART NEEDS NEW WHEELS							
		LYDIA MONTOYA - SNP MANAGER -882-5522							

Alma Terrell

42546	Academic Bldg	Classroom			2/13/2009		82		\$0.00
Medium	Work In Progress				2/13/2009 8:10:20 AM				
Lara, Ralph		NEED A NEW DOOR CLOSER FOR CLASSROOM AT THE ACADEMIC BLDG TO ROOM 333							

Mario Apodaca

42551	Cafeteria (1998)				2/13/2009		82		\$0.00
Medium	Work In Progress				2/13/2009 9:24:33 AM				
Garcia, Jose		please clean area around cafeteria. please use the power washer. coordinate w/ joey custodial so when you do the windows they can dry and clean them. Thanks							

Michael Munoz

42598					2/17/2009		78		\$0.00
Medium	Work In Progress				2/17/2009 8:58:46 AM				
Appelzoller, Fred		Please check all metering faucets throughout campus. They are not turning off by themselves. (See Mike Munoz)							

Michael Munoz

42606	Main Building				2/17/2009		78		\$0.00
Medium	Work In Progress				2/17/2009 9:53:50 AM				
Apodaca, Mario		Requested by Ms. R. Holguin Rm. 125 Main Building- Need to replace bulb in storage room 125a, no light.							

Velia Alarcon

42627	Cafeteria (1998)				2/17/2009		78		\$0.00
Medium	Work In Progress				2/17/2009 2:36:05 PM				
Moncayo, Fernando		NEED TO SERVICE ALL EVAPOATIVE COOLER UNIT AT COOL DOWN THE KITCHEN FOR START-UP IN THE SPRING							

Mario Apodaca

42799	Football Stadium				2/23/2009		72		\$0.00
Medium	Work In Progress				2/23/2009 2:54:56 PM				
Lara, Ralph		need a new lock set for the football shack							
Mario Apodaca									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

42819	North Building				2/23/2009		72		\$0.00
-------	----------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/23/2009 4:19:30 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos Requested by Mr. J. Gonzales Rm. 206 North Building- No power on all wall outlets, breaker form Teacher's Lounge possibly needs to be reset. POSSIBLE FIRE HAZARD with refrigerator, Coke Machine, microwave and all my outlets drawing power from the same wire.

Velia Alarcon

42821					2/23/2009		72		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/23/2009 4:24:00 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Vallejo, Albert Requested by Mr. R. Grace for Facility Goal Team-Move lockers from hallway in Business Building to P.E. Locker rooms and Weight rooms. SEE MR. GRACE FOR FURTHER INSTRUCTIONS.

Velia Alarcon

42918					2/25/2009		70		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/25/2009 11:27:29 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Carrasco, Danny Danny need to conduct inventory of all Building Mechanic tools and equipment. Ask Ruben for present inventory list to match up.

Michael Munoz

42927					2/25/2009		70		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/25/2009 12:30:55 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Carrasco, Danny Danny need to conduct inventory of all Bldg Mechanic tools and equipment. Ask Ruben for present inventory list to match up.

Michael Munoz

42942	Auto Shop	Classroom			2/25/2009		70		\$0.00
-------	-----------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/25/2009 3:36:20 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Moncayo, Fernando REQUEST # 2
W/O 40182
NEED TO REMOVE THE OLD WASHER AT STORED IN THE AUTO SHOP AT WAS IN THE KITCHEN
A.S.A.P

Mario Apodaca

42968		Lift Station			2/26/2009		69		\$0.00
-------	--	--------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/26/2009 9:20:48 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Jacquez, Ricardo please replace starter on lift station for pump #1

Ricardo Jacquez

43036	Academic Bldg	Restroom (Boys)			2/27/2009		68		\$0.00
-------	---------------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/27/2009 12:45:08 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Apodaca, Mario THE PARTITONS AT ACADEMIC BLDG AT THE BOY'S RESTROOM ARE VANDALISED ON THE E/SIDE WING
(4/28/08 Asp Mario has not been done) 3/11 - Asp Mike need to now how many are needed and the sizes. Thanks mkv

Mario Apodaca

5/6/2009 11:28:10 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

43189					3/1/2009		66		\$0.00
Medium	Work In Progress				3/1/2009 12:23:25 AM				
Apodaca, Mario		Yearly - Gadsden HS A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
43357	Main Building				3/5/2009		62		\$0.00
Medium	Work In Progress				3/5/2009 8:42:04 AM				
Castillo, Carlos		Check on Lyncos Refrigeration installations.							
Michael Munoz									
43367					3/5/2009		62		\$0.00
Medium	Work In Progress				3/5/2009 11:02:22 AM				
Jacquez, Ricardo		60,000 Gal. Water Storage Tank - Relocate 4" inlet from bottom of tank to top to reduce short cycling.							
Alfredo Holguin									
43422	Vocational	Classroom			3/6/2009		61		\$0.00
Medium	Work In Progress				3/6/2009 11:10:08 AM				
Castillo, Carlos		SPED Classroom Rm 551 - Need to check for appropriate amperage for new unit to be installed. Please submit your material request form by 3/11/09. (asp our discussion)							
Michael Munoz									
43423	Vocational	Classroom			3/6/2009		61		\$0.00
Medium	Work In Progress				3/6/2009 11:11:24 AM				
Ambriz, Jose		SPED Classroom Rm 551 - Need to check for appropriate unit to be installed. Please submit your material request form by 3/11/09. (asp our discussion)							
Michael Munoz									
43453	New Vocational				3/6/2009		61		\$0.00
High	Work In Progress				3/6/2009 4:23:25 PM				
Appelzoller, Fred		shower in sped room in vocational bldg by wood shop water leaks out, please see mike for repairs.thxs							
Michael Munoz									
43485		Athletic Field			3/9/2009		58		\$0.00
Medium	Work In Progress				3/9/2009 10:21:07 AM				
Ontiveros, Guadalupe		request by coach lowrens soccer to install two 4'x6' gates at soccer fields. This is a saftey, players keep jumping over fence to recover balls.							
Guadalupe Ontiveros									
43488					3/9/2009		58		\$0.00
Medium	Work In Progress				3/9/2009 11:29:30 AM				
Lara, Ralph		Requested by Mr. Grubaugh for Library-There is a leak coming from the door frame in the Library's main entry way, please fix as soon as possible.							
Velia Alarcon									

5/6/2009 11:28:10 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

43679	Business	Classroom			3/13/2009		54		\$0.00
-------	----------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/13/2009 8:41:57 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose
THE HEATING UNIT AT ROOM 660 AT BUS BLDG
NEED WORK DO TO A ROLL BACK FIRE

Mario Apodaca

43721					3/15/2009		52		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/15/2009 12:19:49 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
Monthly - Gadsden HS Soil Sampling - Refer to PM
schedule details.

Margret Villalobos

43907	Cafeteria (1998)	Cafeteria			3/20/2009		47		\$0.00
-------	------------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/20/2009 7:56:17 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador
OUTSIDE THE CAFE BLDG THE CANOPY NEED TO
BE REMOVE AND REPLACES W/ CORRUGATED
STEEL PANEL OR PVC PANEL DO TO WEAT AND
TEAR

Mario Apodaca

44015		Athletic Field			3/25/2009		42		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/25/2009 2:22:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
Repair Damaged Perimeter Fence on the northwest
corner (west side) next to entrance by Ag Farm.

Alfredo Holguin

44089					3/31/2009		36		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/31/2009 12:22:49 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario
Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) -
Refer to PM schedule details.

Margret Villalobos

44090					3/31/2009	5/1/2009	36		\$0.00
-------	--	--	--	--	-----------	----------	----	--	--------

Medium	Work In Progress				3/31/2009 12:22:49 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario
Yearly - Gadsden HS A8 (Window Unit)(Yearly) - Refer
to PM schedule details.

Margret Villalobos

44114					3/31/2009		36		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/31/2009 12:01:39 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario
Requested by Cathy Cano-Requesting the welding
generator and extra long extension cords and extra
gasoline for Senior Field Day to be held on Friday, May
8, 2009 from 9:00 a.m. thru 3:30 p.m.

Velia Alarcon

44116	Academic Bldg				3/31/2009		36		\$0.00
-------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/31/2009 12:05:36 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Apodaca, Mario
Requested by Ms. Leahy Rm. 328 Academic Building-
Replace window screen, screen was damaged beyond
repair. 4/8/09 - Asp Ruben, Mario has extra
screen and he will replace.

Velia Alarcon

5/6/2009 11:28:10 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

44117					3/31/2009		36		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/31/2009 12:07:23 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Gonzalez, Salvador Requested by Mr. Roberson for Cafeteria Picnic Area-
Repair the canvas cover over the cafeteria picnic area.

Velia Alarcon

44125	Cafeteria (1998)	Restroom (Boys)			3/31/2009		36		\$0.00
-------	------------------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/31/2009 2:42:26 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose we have two roof top exhaust fans one at the boys
restroom and the other next door in the custodial closet
that do not function

Joe Munoz

44154	Pool Pump	Pool			4/1/2009		0		\$0.00
-------	-----------	------	--	--	----------	--	---	--	--------

Medium	Work In Progress			4/1/2009 9:40:12 AM	4/1/2009				
--------	------------------	--	--	---------------------	----------	--	--	--	--

Sanchez, Raul Annual Pool Start-up to include procurement of
supplies,contracting of services,cleaning of pool & pump
room,pool inspection & opening to the public

Raul Sanchez

44278					4/3/2009		33		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			4/3/2009 3:57:15 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Vallejo, Albert Requested by Ms. Garcia Rm. 231 North Building-Would
like to install a door stopper on the bottom of the door to
keep door open.

Velia Alarcon

44279					4/3/2009		33		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			4/3/2009 4:01:01 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ontiveros, Guadalupe Requested by Coach Lawrence for Soccer Field-Fix
sprinklers in Main Soccer Field (4). Set up Soccer Goals
in practice field and paint soccer field. FOR FURTHER
INSTRUCTION PLEASE SPEAK TO COACH
LAWRENCE.

Velia Alarcon

44280					4/3/2009		33		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			4/3/2009 4:02:37 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Apodaca, Mario Requested by Isela Martinez for Counseling Center-
Assemble chairs and desk for Ms. Ortiz/Ms. Hernandez.

Velia Alarcon

44281					4/3/2009		33		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			4/3/2009 4:05:24 PM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Vallejo, Albert Requested by Teachers in Business Building-Check
seals and latches on all windows in the building. If
possible have all windows replaced.

Velia Alarcon

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
44287					4/5/2009		31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:30 AM				
Holguin, Alfredo		Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.				4/7/09 E-mailed PM to Ricky and Garrett at Rocky Mtn.			
Margret Villalobos									
44294					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:32 AM				
Vallejo, Albert		Monthly - Gadsden HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
44324					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:45 AM				
Orozco, Danny		Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
44401					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:11 AM				
Apodaca, Mario		Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
44402					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:11 AM				
Apodaca, Mario		Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
44403					4/5/2009	4/21/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:12 AM				
Apodaca, Mario		Monthly - Gadsden HS A1 (Air Dryer)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
44404					4/5/2009		31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:12 AM				
Apodaca, Mario		Yearly - Gadsden HS A13 (Ceil/Wall Unit)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
44571					4/9/2009		27		\$0.00
Medium	Work In Progress				4/9/2009 8:52:10 AM				
Gonzalez, Salvador		Need to Repair the pole vault upright.							
Albert Vallejo									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

44577	Boys Gym	Dressing Room			4/9/2009		27		\$0.00
Medium	Work In Progress			4/9/2009 12:27:09 PM					
Estrada, Jesus	AS PER MR CHAMBER THE FLOORS AT LOCKER ROOMS NEED TO BE REPLACES . BOYS GYM ROOM 404,400								
Mario Apodaca									
44578	Varsity Gym	Dressing Room			4/9/2009		27		\$0.00
Medium	Work In Progress			4/9/2009 12:37:53 PM					
Mario Apodaca	AS PER MR CHAMBER THE FLOOR AT THE VOLLEYBALL LOCK ROOM NEED TO BE REPLACS. AT THE V-GYM ROOM 241								
44615					4/12/2009	4/28/2009	24		\$0.00
Medium	Work In Progress			4/12/2009 12:21:14 AM					
Munoz, Joe	Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.								
Jesus Estrada									
44651					4/14/2009		22		\$0.00
Medium	Work In Progress			4/14/2009 12:19:37 AM					
Jacquez, Ricardo	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
44741	Cafeteria (1998)				4/16/2009		20		\$0.00
Medium	Work In Progress			4/16/2009 8:29:03 AM					
Ambriz, Jose	GHS cafeteria electrical room exhaust fan not working.								
Carlos Castillo									
44868	North Building				4/21/2009		15		\$0.00
Medium	Work In Progress			4/21/2009 2:33:30 PM					
Vallejo, Albert	Requested by Ms. Holzhausen Rm. 226 North Building- Please hang the small white board by the clock.								
Velia Alarcon									
44869	Main Building				4/21/2009		15		\$0.00
Medium	Work In Progress			4/21/2009 2:36:17 PM					
Apodaca, Mario	Requested by Velia for Rm. 124 Main Building-Hang up a flag from the cieling.								
Velia Alarcon									
44872	Boys Gym				4/21/2009		15		\$0.00
Medium	Work In Progress			4/21/2009 2:43:47 PM					
Apodaca, Mario	Requested by Mr. Mora for Rm. 403 Training Room in Boy's Gym-Replace light bulbs in Athletic Training room.								
Velia Alarcon									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

44914					4/22/2009		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			4/22/2009 10:17:27 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Vallejo, Albert
Requested by Ms. Arredondo Rm. 550 Wood Shop-Deliver panels and help set them up at Gadsden Middle School on Thursday, April 30, 2009. Please see Ms. Arredondo if you have any questions.

Velia Alarcon

44918					4/22/2009		14		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Girls Gym		4/22/2009 12:05:03 PM					
--------	------------------	-----------	--	-----------------------	--	--	--	--	--

Lara, Ralph
Requested by Ms. Letz for Girl's Gym-Replace the doors and door frames between Girl's Gym and locker room, between hall and gym, and the door for the equipment room inside the locker room. This problem has never been repaired properly. All the equipment for the P.E. Department is stored in the equipment room of the girl's locker room and when Ms. Letz is out for the day P.E. equipment has been stolen. Please repair as soon as possible.

Velia Alarcon

44962					4/23/2009		13		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			4/23/2009 11:35:47 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Vallejo, Albert
Requested by Mr. Roberson for Room 569 (DACC Nursing Classroom) Ag. Shop-Repair outer wall by entrance where plywood is warped and rotting, prefer masonry fill in.

Velia Alarcon

44966	Pool Dressing	Pool			4/23/2009		13		\$0.00
-------	---------------	------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			4/23/2009 12:47:06 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Sanchez, Raul
4/23/09
Need to procure materails to install a water line from irrigation well #1 to the pool pump room & the dressing room bathrooms & showers. This is to provide temporary water during the shutoff of the system in July.

Raul Sanchez

45092	Academic Bldg				4/28/2009		8		\$0.00
-------	---------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			4/28/2009 11:11:04 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Ontiveros, Guadalupe
Please install irr. watering system to all trees and shurbs around bldg.

Michael Munoz

45105		Classroom			4/28/2009		8		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Science and		4/28/2009 2:00:46 PM					
--------	------------------	-------------	--	----------------------	--	--	--	--	--

Vallejo, Albert
Please set up furniture for computers on the Science and Language Arts classrooms, furniture was delivered on April 16.
Thank you!

Sandra Almeraz

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

45110					4/28/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/28/2009 2:57:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Velia for Football and Soccer Practice Fields-Please do not water or flood fields the week of the 4th thru the 8th of May. Senior Field Day is scheduled for Friday, May 8, 2009.

Velia Alarcon

45112					4/28/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/28/2009 3:03:09 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by Cathy for Football and Soccer Practice Fields-Mow the grass before the 8th of May, when the Senior Fields Day is scheduled.

Velia Alarcon

45113	Agricultural	Classroom			4/28/2009		8		\$0.00
-------	--------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/28/2009 3:13:24 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred need a new utility twin sink at the ag shop bldg to room 568

Mario Apodaca

45114	North Building				4/28/2009		8		\$0.00
-------	----------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/28/2009 3:14:09 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Estrada, Jesus Requested by Mr. Martinez for Hallway and Locker Areas in the North Building-The tile and carpet on the columns need to be repaired or replaced.

Velia Alarcon

45115					4/28/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/28/2009 3:15:47 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Apodaca, Mario Requested by Mr. Martinez for North Building Boy's Restroom-Boy's restroom needs to be painted due to the writing on the walls.

Velia Alarcon

45124	North Building				4/28/2009		8		\$0.00
-------	----------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/28/2009 3:52:46 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert Requested by Mr. Martinez for Hallway and Locker Areas in the North Building-Variou areas in the hall need painting and some wall areas need to be repaired.

Velia Alarcon

45147					4/29/2009		7		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	SPED Bldg			4/29/2009 12:08:19 PM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Castillo, Carlos Need to insulate connections. They are very close to shorting out and causing an outage.

Carlos Castillo

45148		Athletic Field			4/29/2009		7		\$0.00
-------	--	----------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				4/29/2009 12:11:18 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos Chek power capacity for senior day picnic electrical.

Carlos Castillo

5/6/2009 11:28:10 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

45186					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:32 AM					
Vallejo, Albert	Yearly - Gadsden HS C11 (Evap.Condnser)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
45260					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:27 AM					
Vallejo, Albert	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
45261					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:28 AM					
Vallejo, Albert	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45262					5/3/2009	6/3/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:28 AM					
Vallejo, Albert	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
45312					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:46 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45389	Old English Bldg				5/4/2009		2		\$0.00
Medium	Work In Progress			5/4/2009 3:48:48 PM					
Ambriz, Jose	Unit 1 - is not coming on need to ck end switch.								
Margret Villalobos									
45425	Main Building	Classroom			5/5/2009		1		\$0.00
Medium	Work In Progress			5/5/2009 2:57:50 PM					
Lara, Ralph	NEED TO REKEY DOORS AT CLASS ROOM 105 AT MAIN BLDG , BY MAY- 7- 09								
Mario Apodaca									
45426	North Building	Classroom			5/5/2009		1		\$0.00
Medium	Work In Progress			5/5/2009 3:00:55 PM					
Ronquillo, Ruben	NEED TO PUT A NEW GLASS WINDOW AT ROOM 226 N-BLDG (38"X20")								
Mario Apodaca									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

45427	Cafeteria (1998)				5/5/2009		1		\$0.00
Medium	Work In Progress				5/5/2009 3:03:36 PM				
Moncayo, Fernando	NEED TO WORK ON THE LIGHING IN THE KITCHEN AT CAFE BLDG ASAP !!!!..								

Mario Apodaca

Count: 120 Work Orders	Avg. Age of WO's 93	Total for Gadsden HS	11	\$275.00
-------------------------------	----------------------------	-----------------------------	-----------	-----------------

Location: Gadsden MS

35955					7/14/2008		296		\$0.00
Medium	Work In Progress				7/14/2008 3:35:17 PM				
Lozoya, Manny	Need fix main entrance doors the punish bar not work properly thank you								

Sebastian Diaz

36222	Office				7/25/2008		285		\$0.00
Medium	Work In Progress	Awing/GMS Front			7/25/2008 11:40:57 AM				
Lozoya, Manny	Need to set up A57 key lock on new door in Ms. Quinonez's office as soon as possible.								

Maricruz Carrasco

36627	Office				8/5/2008		274		\$0.00
Medium	Work In Progress	GMS Front			8/5/2008 5:44:35 AM				
Lozoya, Manny	Need A53 door lock on Nancy's door as soon as possible.								

Maricruz Carrasco

36628	Office				8/5/2008		274		\$0.00
Medium	Work In Progress	Awing/155/Dr.			8/5/2008 5:47:23 AM				
Lozoya, Manny	Door lock in Dr. Garcia's office supposed to be opened by M36 key only. W key can be used to open the door. Please check door lock.								

Maricruz Carrasco

36632	Parking Lot				8/5/2008		274		\$0.00
Medium	Work In Progress	Parking			8/5/2008 5:59:53 AM				
Lozoya, Manny	Need metal door installed in Security shed.								

Maricruz Carrasco

37267	Office				8/21/2008		258		\$0.00
Medium	Work In Progress	Awing/162/Securit			8/20/2008 10:01:58 PM				
Lozoya, Manny	"W" key is getting jammed.								

Maricruz Carrasco

37270	Classroom				8/21/2008		258		\$0.00
Medium	Work In Progress	Awing/159/E.			8/20/2008 10:06:16 PM				
Lozoya, Manny	Door does not close and lock.								
Maricruz Carrasco									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
37763	C-Wing	Classroom			9/3/2008		245		\$0.00
Medium	Work In Progress	Cwing/C-		9/3/2008 9:29:19 PM					
Lozoya, Manny		Door does not lock. Safety issue.							
Maricruz Carrasco									
37764	C-Wing	Office			9/3/2008		245		\$0.00
Medium	Work In Progress	Cwing/Dr. Montes		9/3/2008 9:30:21 PM					
Lozoya, Manny		Door does not lock.							
Maricruz Carrasco									
37770		Portables			9/4/2008		244		\$0.00
Medium	Work In Progress			9/4/2008 8:13:40 AM					
Sotelo, Enrique		Please provide electrical connection to 2 Bard units.							
Lorenzo Solis									
38385					9/24/2008		224		\$0.00
Medium	Work In Progress	All GMS Staff		9/23/2008 10:06:29 PM					
Lozoya, Manny		All staff restrooms to have latch placed on door for privacy reasons.							
Maricruz Carrasco									
38417	C-Wing				9/24/2008		224		\$0.00
Medium	Work In Progress			9/24/2008 3:44:29 PM					
Lozoya, Manny		New Portable - 1st thing tomorrow need to recore like GMS (see Mike if u have any questions).							
Michael Munoz									
38464	C-Wing				9/26/2008		222		\$0.00
Medium	Work In Progress			9/26/2008 12:26:38 PM					
Lozoya, Manny		Mr. Chacon, Band Director needs a gate key for gate by C-Wing.							
Michael Munoz									
38485					9/26/2008		222		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:32:43 PM					
Lozoya, Manny		Need three WA-83 keys. Need two V-3 keys.							
Maricruz Carrasco									
38486					9/26/2008		222		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:34:17 PM					
Lozoya, Manny		Need two keys made for golf cart.							
Maricruz Carrasco									
38487	C-Wing	Portables			9/26/2008		222		\$0.00
Medium	Work In Progress	C-wing/New		9/26/2008 4:35:35 PM					
Lozoya, Manny		Fix lock to main entrance on new portable-Health Center							
Maricruz Carrasco									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden MS

38651	Annex				10/2/2008		216		\$0.00
Medium	Work In Progress				10/2/2008 3:20:00 PM				
Lozoya, Manny	Need fix handi cup door in annex bldg thank you								
Sebastian Diaz									
39213		Office			10/14/2008		204		\$0.00
Medium	Work In Progress	Dr. Garcia's			10/14/2008 9:56:39 AM				
Lozoya, Manny	Install lock on black storage cabinet for Maricruz.								
Maricruz Carrasco									
39856					11/5/2008		182		\$0.00
Medium	Work In Progress				11/5/2008 2:20:53 PM				
Lozoya, Manny	Controls contractor (Trane) Needs keys to acces building on Monday Nov. 10								
Alfredo Holguin									
40147	C-Wing				11/17/2008		170		\$0.00
Medium	Work In Progress				11/17/2008 2:29:35 PM				
Lozoya, Manny	Nursing Coordinator Offices - Rekey - check with Ms. Cregan on keying								
Alfredo Holguin									
40601		Cafeteria			12/4/2008		153		\$0.00
Medium	Work In Progress				12/4/2008 4:02:49 PM				
Moncayo, Fernando	SNP Warehouse - Some windows are broken and seals are poor in existing windows allowing a large amount of dust to come in where food is being stored. Good lighting is available therefore, we are requesting that the windows be covered with plywood and sealed to prevent contamination of food items.								
	Johnny Lechuga - SNP Warehouse								
Alma Terrell									
40785					12/11/2008		146		\$0.00
Medium	Work In Progress	A wing / Sped			12/11/2008 10:29:02				
Lozoya, Manny	Re-Key File Cabinet								
Maricruz Carrasco									
40786		Classroom			12/11/2008		146		\$0.00
Medium	Work In Progress	A wing / 178			12/11/2008 10:30:20				
Lozoya, Manny	Repair Lock to File Cabinet								
Maricruz Carrasco									
40787					12/11/2008		146		\$0.00
Medium	Work In Progress	B Wing / New			12/11/2008 10:31:39				
Lozoya, Manny	Re-Key to A53								
Maricruz Carrasco									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

41220	Annex				1/6/2009		120		\$0.00
Medium	Work In Progress	GMS			1/6/2009 4:52:10 PM				
Ontiveros, Guadalupe		Two large holes between Annex and portable need to be filled with dirt. Please see Dr. Garcia for more information.							
<u>Maricruz Carrasco</u>									
41221					1/6/2009		120		\$0.00
Medium	Work In Progress	GMS Campus			1/6/2009 4:53:38 PM				
Ontiveros, Guadalupe		Uprooted tree needs to be covered with dirt. Please see Dr. Garcia for more information.							
<u>Maricruz Carrasco</u>									
41266					1/8/2009		118		\$0.00
Medium	Work In Progress				1/8/2009 10:14:34 AM				
Lozoya, Manny		NEED TO INSTALL CORES IN NEW ANNEX BUILDING.							
<u>Maritza Gonzalez</u>									
41382	Gym	Gym			1/11/2009		115		\$0.00
Medium	Work In Progress	Gym/Boys and			1/11/2009 12:34:27 AM				
Appelzoller, Fred		Toilets in both coaches offices restrooms leak when flushed.							
<u>Maricruz Carrasco</u>									
41573					1/16/2009		110		\$0.00
Medium	Work In Progress	War room in			1/16/2009 10:54:08 AM				
Lozoya, Manny		Secure storage cabinet with clasp in WAR Room							
<u>Maricruz Carrasco</u>									
41575	C-Wing				1/16/2009		110		\$0.00
Medium	Work In Progress	C wing/ Elev. 8			1/16/2009 10:57:09 AM				
Lozoya, Manny		Lock change for storage room in the Elev. 8 room. (See Shirley Baca)							
<u>Maricruz Carrasco</u>									
41578		Cafeteria			1/16/2009		110		\$0.00
Medium	Work In Progress	War room			1/16/2009 11:04:53 AM				
Lozoya, Manny		Re-key off Master to M36, same as Dr. Garcia's office							
<u>Maricruz Carrasco</u>									
41588		Computer Lab			1/16/2009		110		\$0.00
Medium	Work In Progress	rooms next to			1/16/2009 11:25:41 AM				
Lozoya, Manny		Need construction Core removed from computer labs next to library and Keyed to GISD Key Core. ASAP							
<u>Maricruz Carrasco</u>									
41590					1/16/2009		110		\$0.00
Medium	Work In Progress				1/16/2009 11:30:43 AM				
Lozoya, Manny		Need extra copy of key 56 for boiler room for Dr. Garcia							
<u>Maricruz Carrasco</u>									

5/6/2009 11:28:10 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
41788		Classroom			1/23/2009		103		\$0.00
Medium	Work In Progress	B wing/ room 109			1/23/2009 10:56:22 AM				
Lozoya, Manny		Need two new locks for cabinets							
Maricruz Carrasco									
41792	Annex				1/23/2009		103		\$0.00
Medium	Work In Progress	Home Ec/ room			1/23/2009 11:54:39 AM				
Lozoya, Manny		Lock to storage cabinet (see mr. kohl)							
Maricruz Carrasco									
41924					1/28/2009		98		\$0.00
Medium	Work In Progress				1/28/2009 8:15:30 AM				
Lozoya, Manny		Need to fix door handal in room 303 vocatinal bldg thank you							
Sebastian Diaz									
41932					1/28/2009		98		\$0.00
Medium	Work In Progress	room 146 and			1/28/2009 10:15:28 AM				
Lozoya, Manny		Key new computer labs, rooms 146 and 148.							
		Need 5 keys of the V8 (Connie)							
Maricruz Carrasco									
41938					1/28/2009		98		\$0.00
Medium	Work In Progress	Library			1/28/2009 11:19:35 AM				
Lozoya, Manny		Rekey inside new library							
Maricruz Carrasco									
41988					1/29/2009		97		\$0.00
Medium	Work In Progress				1/29/2009 11:28:47 AM				
Ontiveros, Guadalupe		could you please support w/ the irrigation system in the front of the campus to include the backflow preventer. no water thxs							
Michael Munoz									
41989					1/29/2009		97		\$0.00
Medium	Work In Progress				1/29/2009 11:32:40 AM				
Appelzoller, Fred		please provide and check all hose bibbs around campus for water hose hook ups. thxs							
Michael Munoz									
42020					1/30/2009		96		\$0.00
Medium	Work In Progress				1/30/2009 11:37:16 AM				
Lozoya, Manny		Need to check key and lock in computer lab thank you							
Sebastian Diaz									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

42398	Gym	Gym			2/9/2009		86		\$0.00
Medium	Work In Progress	Gym/Boys			2/9/2009 4:15:46 PM				
Lozoya, Manny		New lock needed for Boys Basketball Storage. See Connie for more information.							
<u>Maricruz Carrasco</u>									
42619	Main Building				2/17/2009		78		\$0.00
Medium	Work In Progress	B- Wing			2/17/2009 12:06:39 PM				
Sotelo, Enrique		Asp PM 42129, Need power in Main Entrance for emerg.lights. (see Sebastian for further info).							
<u>Sebastian Diaz</u>									
42691		Classroom			2/19/2009		76		\$0.00
Medium	Work In Progress	Bwing/140/G.Riva			2/19/2009 12:20:14 AM				
Lozoya, Manny		Filing cabinet lock needs to be replaced.							
<u>Maricruz Carrasco</u>									
42965					2/26/2009		69		\$0.00
Medium	Work In Progress				2/26/2009 8:25:09 AM				
Appelzoller, Fred		Isolate water valves for all new bldg, water valves.				Summer Project			
Michael Munoz		Need Ditch Witch for digging french drain for drinking fountain. asp report 2/24/09							
43119					3/1/2009		66		\$0.00
Medium	Work In Progress				3/1/2009 12:23:01 AM				
Orozco, Danny		Yearly - Gadsden MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
43780		Library			3/17/2009		50		\$0.00
Medium	Work In Progress	Library Rm. 147			3/17/2009 9:01:22 AM				
Lozoya, Manny		Lock to Equipment storage room not working.							
<u>Maricruz Carrasco</u>									
43810					3/17/2009		50		\$0.00
Medium	Work In Progress				3/17/2009 3:41:27 PM				
Appelzoller, Fred		Need to replace parts on water fountain in the playground is broken thank you							
<u>Sebastian Diaz</u>									
43992					3/24/2009		43		\$0.00
Medium	Work In Progress				3/24/2009 3:59:48 PM				
Ambriz, Jose		west wing chiller, as per Johnson controls the flow swith is not operatable.please replace.thanks							
<u>Michael Munoz</u>									
44072	Annex				3/30/2009		37		\$0.00
Medium	Work In Progress				3/30/2009 4:18:40 PM				
Appelzoller, Fred		Water Heater in (old annex) leaking where transformer is located need to ck out 1st thing in the morning. (Any ?'s ask Ruben R.)							
Jesus Estrada									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

44127		Athletic Field			3/31/2009		36		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Baseball			3/31/2009 2:50:44 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Lozoya, Manny
Lock to walk through gate at baseball field worn out.
Needs to be replaced.

Maricruz Carrasco

44216	Cafeteria	Office			4/2/2009		34		\$0.00
-------	-----------	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/2/2009 9:04:13 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny
WORK ORDER FOR SNP WAREHOUSE - NEED
PADLOCK WITH C CORE

FERNANDO MONCAYO - SNP TECH - 575-305-0190

Alma Terrell

44217	Cafeteria	Office			4/2/2009		34		\$0.00
-------	-----------	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/2/2009 9:08:26 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lozoya, Manny
WORK ORDER FOR DANNY OROZCO'S OFFICE -
NEED 2 PADLOCKS WITH M 256 CORE (FOR
DANNY'S OFFICE AND STORAGE ROOM)

FERNANDO MONCAYO - SNP TECH - 575-305-0190

Alma Terrell

44227	Cafeteria	Cafeteria			4/2/2009		34		\$0.00
-------	-----------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/2/2009 3:24:49 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
SNP WAREHOUSE: FRONT DOOR KNOB JAMS/
UNABLE TO OPEN

JOHNNY LECHUGA SNP WHSE MANAGER 882-
6927

Jacqueline Aguilar

44438					4/5/2009	4/21/2009	31		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/5/2009 12:23:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Diaz, Sebastian
Monthly - Gadsden MS A-1 Wall Ref Elec Semiannual -
Refer to PM schedule details.

Margret Villalobos

44580	Cafeteria	Cafeteria			4/9/2009		27		\$0.00
-------	-----------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/9/2009 2:23:28 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Moncayo, Fernando
SNP WAREHOUSE: AC DEFUSER NEED TO BE
REPLACED.

JOHNNY LECHUGA SNP MGR WHSE 882-6771

Jacqueline Aguilar

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden MS							
44581	Cafeteria	Cafeteria			4/9/2009		27		\$0.00
Medium	Work In Progress				4/9/2009 2:27:43 PM				
Moncayo, Fernando	SNP WAREHOUSE: THE CEILING INSIDE THE WAREHOUSE IS STARTING TO HANG. (PLYWOOD - SAGGING)								
Jacqueline Aguilar	JOHNNY LECHUGA SNP WHSE MGR 882-6927								
44652					4/14/2009		22		\$0.00
Medium	Work In Progress				4/14/2009 12:19:38 AM				
Jacquez, Ricardo	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
44838					4/20/2009		16		\$0.00
Medium	Work In Progress				4/20/2009 3:40:37 PM				
Lozoya, Manny	Need to fix door in vocational bldg room 302 thank you								
Sebastian Diaz									
44866					4/21/2009		15		\$0.00
Medium	Work In Progress				4/21/2009 2:07:41 PM				
Diaz, Sebastian	Need to replace register in food services for A/C 24X 24 thank you								
Sebastian Diaz									
45097	Band Room	Classroom			4/28/2009		8		\$0.00
Medium	Work In Progress	Gym/Band room			4/28/2009 12:14:21 PM				
Diaz, Sebastian	Repair band cabinets as soon as possible.								
Maricruz Carrasco									
45165					4/29/2009		7		\$0.00
Medium	Work In Progress				4/29/2009 3:38:22 PM				
Sotelo, Enrique	Need to replace cover in out side light at the gym thank you								
Sebastian Diaz									
45166					4/29/2009		7		\$0.00
Medium	Work In Progress				4/29/2009 3:39:58 PM				
Sotelo, Enrique	In the gym four lights are out need replace thank you								
Sebastian Diaz									
45204					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress				4/30/2009 12:21:39 AM				
Diaz, Sebastian	Yearly - Gadsden MS C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden MS

45215	Annex	Classroom			4/30/2009		6		\$0.00
Medium	Work In Progress	Rm. 300, 307 and			4/30/2009 2:40:02 PM				
Lozoya, Manny	Room 300, Mr. Kohl, new lock. Room 307, Mr. Escarciga, new lock. Room 407, Mrs. Robles, adjust door.								

Maricruz Carrasco

45333					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:53 AM				
Diaz, Sebastian	Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.								

Margret Villalobos

45334					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:53 AM				
Diaz, Sebastian	Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.								

Margret Villalobos

45335					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:54 AM				
Diaz, Sebastian	Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.								

Margret Villalobos

Count: 68 Work Orders	Avg. Age of WO's	118	Total for Gadsden MS	0	\$0.00				
------------------------------	-------------------------	------------	-----------------------------	----------	---------------	--	--	--	--

Location: La Union - JTP Alvarez Farms

43542					3/10/2009		57		\$0.00
Medium	Work In Progress				3/10/2009 12:26:00 PM				
Ronquillo, Ruben	See Sam Avalos: Glass window on Fire extinguisher holder is broken. Please replace.								

Margaret Villalobos

Count: 1 Work Orders	Avg. Age of WO's	57	Total for La Union - JTP Alvarez Farms	0	\$0.00				
-----------------------------	-------------------------	-----------	---	----------	---------------	--	--	--	--

Location: La Union ES

38034					9/11/2008		237		\$0.00
Medium	Work In Progress				9/11/2008 3:14:33 PM				
Villalobos, David	pat aguilar need rubber bushing for water faucet - thank you								

Patricio Aguilar

40988					12/18/2008		139		\$0.00
Medium	Work In Progress				12/18/2008 3:20:23 PM				
Ambriz, Jose	pat aguilar the thermostat not working right - dayton electric heater model 2e441 ser 143933 volts 240/208 wats 4800/2500 60 hz 13tu 16382/11946								

Patricio Aguilar

5/6/2009 11:28:10 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
41167					1/5/2009		121		\$0.00
Medium	Work In Progress			1/5/2009 3:33:50 PM					
Ambriz, Jose	pat aguilar heater boiler pump taco model fm1207 has a bad bearing								
Patricio Aguilar									
41244					1/7/2009		119		\$0.00
Medium	Work In Progress			1/7/2009 3:11:39 PM					
Lara, Ralph	pat aguilar need a new frame & door for rest room r210								
Patricio Aguilar									
42202					2/3/2009		92		\$0.00
Medium	Work In Progress			2/3/2009 3:44:11 PM					
Gonzales, Angel	Need to use sweeper for drive ways								
Patricio Aguilar									
43366		Pump House			3/5/2009		62		\$0.00
Medium	Work In Progress			3/5/2009 10:48:31 AM					
Sanchez, Raul	Repair in line check valve.								
Raul Sanchez									
43655					3/12/2009		55		\$0.00
Medium	Work In Progress			3/12/2009 3:12:30 PM					
Ambriz, Jose	the thermostat is not working - heater will not go on r313								
Patricio Aguilar									
43895					3/19/2009		48		\$0.00
Medium	Work In Progress			3/19/2009 3:27:57 PM					
Castillo, Carlos	the light bulbs keep blowing out - teachers rest room - may need trasformer								
Patricio Aguilar									
44191		Athletic Field			4/1/2009		35		\$0.00
Medium	Work In Progress			4/1/2009 3:47:19 PM					
Ontiveros, Guadalupe	need to build a burm/vordo on the canel valve on the south end of campus to irragate the new playfield.please see mike.								
Michael Munoz									
44326					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:46 AM					
Orozco, Danny	Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: La Union ES

44537	Main Building	Mechanical Room			4/8/2009		28		\$0.00	
Medium	Work In Progress				4/8/2009 9:28:41 AM					
Villalobos, David		installation of new main water line from meter to the main mechanical room								
David Villalobos										
44668					4/14/2009		22		\$0.00	
Medium	Work In Progress				4/14/2009 3:00:28 PM					
Villalobos, Margret		spray for bugs room 210				4/22 approved by A. Holguin pending PO				
Patricio Aguilar		25.00								
44875					4/21/2009		15		\$0.00	
Medium	Work In Progress				4/21/2009 3:11:57 PM					
Gonzales, Angel		would like the use of bobcat with the sweeper - thank you								
Patricio Aguilar										
45035					4/27/2009		9		\$0.00	
Medium	Work In Progress				4/27/2009 9:08:11 AM					
Aguilar, Patricio		Please cut grass and weedeat and irrigate campus asp e-mail sent w/pictures.								
Michael Munoz										
45102	Classroom				4/28/2009		8		\$0.00	
Medium	Work In Progress	1st to 5th grade			4/28/2009 1:28:06 PM					
Aguilar, Patricio		Furniture for computers will be delivered to the school on May 5 please set up in classrooms first to fifth grade. Thank you.								
Sandra Almeraz										
45198					4/30/2009	5/31/2009	6		\$0.00	
Medium	Work In Progress				4/30/2009 12:21:37 AM					
Aguilar, Patricio		Yearly - La Union ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos										
45316					5/3/2009	5/11/2009	3		\$0.00	
Medium	Work In Progress				5/3/2009 12:22:47 AM					
Aguilar, Patricio		Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos										
45317					5/3/2009	5/11/2009	3		\$0.00	
Medium	Work In Progress				5/3/2009 12:22:48 AM					
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos										

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

45318					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:48 AM				
Aguilar, Patricio		Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
45354		Cafeteria			5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 1:23:12 PM				
Moncayo, Fernando		FREEZER- COMPLETELY DOWN							
		LINDA YANAGA SNP MGR 589-2040							

Jacqueline Aguilar

Count: 20 Work Orders

Avg. Age of WO's 52

Total for La Union ES

0

\$0.00

Location: Loma Linda ES

38964					10/6/2008		212		\$0.00
Medium	Work In Progress				10/6/2008 1:40:46 PM				
Carrasco, Danny		Need pressure washer and hose to wash off wall of the east side of main bldg.							
Rudy Arreola									
41073					1/4/2009	1/25/2009	122		\$0.00
Medium	Work In Progress				1/4/2009 12:18:50 AM				
Orozco, Danny		Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
42146					2/2/2009		93		\$0.00
Medium	Work In Progress				2/2/2009 2:22:39 PM				
Gonzales, Angel		Riding mower needs service and new blades also back tires are low.							
Rudy Arreola									
42259	Main Building	Classroom			2/5/2009		90		\$0.00
Medium	Work In Progress				2/5/2009 8:53:21 AM				
Lozoya, Manny		RM 317 Music Room - Having trouble opening door.							
Luis Solis									
42276					2/5/2009		90		\$0.00
Medium	Work In Progress				2/5/2009 2:03:22 PM				
Lozoya, Manny		We need to have 2 sets of RR have the door handle changed so we can lock the RR One is front lobby and the other is cafeteria lobby. BOYS AND GIRLS							
Rudy Arreola									
42524					2/12/2009		83		\$0.00
Medium	Work In Progress				2/12/2009 12:54:24 PM				
Sotelo, Enrique		We need an outlet relocated for tv.							
Rudy Arreola									

5/6/2009 11:28:10 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Loma Linda ES

42525					2/12/2009		83		\$0.00
Medium	Work In Progress			2/12/2009 12:55:10 PM					
Sotelo, Enrique	We need to have 2 more outlets in installed in server RM.								
Rudy Arreola									
43301					3/4/2009		63		\$0.00
Medium	Work In Progress			3/4/2009 9:32:34 AM					
Lozoya, Manny	Manny Lozoya, please check key for room 307. Mr. Solis has sprayed stuff into lock, but teacher continues to have problem unlocking door.								
Grace Alvarado									
43421					3/6/2009		61		\$0.00
Medium	Work In Progress			3/6/2009 10:40:21 AM					
Arreola, Rudy	Rudy Arzola, for the district ART show, needing you to help set up at GMS April 30, 8:00, Take down on May 4, starting at 8:00. For further instructions, see Ms. Powel								
Grace Alvarado									
43504					3/9/2009		58		\$0.00
Medium	Work In Progress			3/9/2009 2:51:26 PM					
Appelzoller, Fred	Need to have 2 urinals replaced they keep cloging them .with smaller holes so they cant stuff them with any thing.								
Rudy Arreola									
43530					3/10/2009		57		\$0.00
Medium	Work In Progress			3/10/2009 9:10:16 AM					
Lozoya, Manny	MANNY LOZOYA, ROOM 203, DOOR HANDLE STICKING, NOT LOCKING								
Grace Alvarado									
43548					3/10/2009		57		\$0.00
Medium	Work In Progress			3/10/2009 2:53:13 PM					
Arreola, Rudy	Plastic barriers are buckling and sand is going over them.		3/11 Rudy, call me if he has a questions. This would be a PM on playground equipment. - Thanks Mike						
Rudy Arreola									
44258		Athletic Field			4/3/2009		33		\$0.00
Medium	Work In Progress			4/3/2009 2:21:57 PM					
Ontiveros, Guadalupe	Need top soil to level off are around back stop.								
Rudy Arreola									
44317					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:43 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Loma Linda ES

44423					4/5/2009	4/11/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:23:18 AM					
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
44989					4/23/2009		13		\$0.00
Medium	Work In Progress			4/23/2009 3:54:48 PM					
Solis, Lorenzo	THE CLOSET ON THE STAGE IS BEING USED AS AN OFFICE WHERE TECHNOLOGY HAS DROPPED LINES AND IS THEREFORE BEING USED AS AN OFFICE , IS THERE ANY WAY THAT WE CAN PROVIDE SOME KIND OF COOLING SYSTEM TO THESE TWO TEACHERS?								
Grace Alvarado									
45091					4/28/2009		8		\$0.00
Medium	Work In Progress			4/28/2009 11:03:52 AM					
Ontiveros, Guadalupe	LANDSCAPE/PLANT GRASS AND INSTALL A SPRINKLER SYSTEM BETWEEN WINGS.								
Alfredo Holguin									
45139					4/29/2009		7		\$0.00
Medium	Work In Progress			4/29/2009 8:47:06 AM					
Arreola, Rudy	Rudy, airconditioner in Mrs. Gutierrez room not working.								
Grace Alvarado									
45200					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:38 AM					
Arreola, Rudy	Yearly - Loma Linda ES C11(Evap.Condnsr)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
45323					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:50 AM					
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
45324					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:50 AM					
Arreola, Rudy	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45325					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:50 AM					
Arreola, Rudy	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Loma Linda ES

45410					5/5/2009		1		\$0.00
Medium	Work In Progress				5/5/2009 10:24:01 AM				
Lozoya, Manny		Pad lock is not locking and need it for emergencys							
Rudy Arreola									
45411					5/5/2009		1		\$0.00
Medium	Work In Progress				5/5/2009 10:24:57 AM				
Lozoya, Manny		Panic bar is loose on westside doors to main bldg.							
Rudy Arreola									
Count: 24 Work Orders			Avg. Age of WO's 50				Total for Loma Linda ES	0	\$0.00

Location: Mesquite ES

35706					7/6/2008	8/6/2008	304		\$0.00
Medium	Work In Progress				7/6/2008 12:20:09 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
36109					7/22/2008		288		\$0.00
Medium	Work In Progress				7/22/2008 10:11:48 AM				
Lozoya, Manny		on (work room) needs a cylinder with a key they have school files need to be lock all the time as per montano principal asap. thank you. luis							
Luis Saucedo									
36147	Main Building	Office			7/23/2008		287		\$0.00
Medium	Work In Progress	Main office area			7/23/2008 12:29:38 PM				
Lozoya, Manny		Main office need's (4) engraved plaque's for front office door. Name and Title (Jacob Montano, Principal), (Sandra Mora, Secretary), (Dora Lerma, Data-Entry Clerk), (Maribel Villela, Receptionist-Clerk) for Manny Lozoya.							
Sandra Mora									
36227		Portables			7/25/2008		285		\$0.00
Medium	Work In Progress				7/25/2008 2:11:53 PM				
Lozoya, Manny		Ms. Flores room # 801 has filing cabinet that doesn't have a key, need's to be re-key.							
Sandra Mora									
36256	2003 Classroom	Classroom			7/28/2008		282		\$0.00
Medium	Work In Progress	Portable room #			7/28/2008 8:30:02 AM				
Lozoya, Manny		Ms. Jimenez, portable room # 506 she has a storage cabinet needs to be re-key.							
Sandra Mora									
36259	2003 Classroom	Classroom			7/28/2008		282		\$0.00
Medium	Work In Progress	Kinder hallway,			7/28/2008 8:58:17 AM				
Lozoya, Manny		Need a master for that room # 405 for our inventory, and key # 305.							
Sandra Mora									

5/6/2009 11:28:10 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Mesquite ES

36885	Main Building	Office			8/11/2008		268		\$0.00
Medium	Work In Progress	Office area		8/11/2008 11:09:39 AM					
Lozoya, Manny		(1) engraved plaque for front office door. Name and Title (Norma Sierra, Assistant Principal) for Manny Lozoya							
<u>Sandra Mora</u>									
38210					9/18/2008		230		\$0.00
Medium	Work In Progress			9/18/2008 9:18:18 AM					
Sotelo, Enrique		marquee lights not working.							
<u>Joe Ramirez</u>									
39519					10/27/2008		191		\$0.00
Medium	Work In Progress			10/27/2008 3:11:39 PM					
Ramirez, Joe		GRASS IS GROWING IN DRAIN GRID BY BUS TURN AROUND.							
<u>Michael Munoz</u>									
40256					11/20/2008		167		\$0.00
Medium	Work In Progress			11/20/2008 9:34:58 AM					
Lozoya, Manny		file cabinet in rm 405 needs a new lock installed the other was damaged.							
<u>Joe Ramirez</u>									
41227	Main Building	Classroom			1/7/2009		119		\$0.00
Medium	Work In Progress	Room # 203		1/7/2009 8:59:31 AM					
Lozoya, Manny		Key is needed for Pamela Uribe IA to that classroom.							
<u>Sandra Mora</u>									
41305		Classroom			1/9/2009		117		\$0.00
Medium	Work In Progress			1/9/2009 8:12:50 AM					
Lozoya, Manny		Rm 608 (Wendy Tow) - Door continues to stick, even after it has been fixed.							
<u>Joe Ramirez</u>									
41567					1/16/2009		110		\$0.00
Medium	Work In Progress			1/16/2009 9:32:05 AM					
Ontiveros, Joe		outside drinking fountain one bubbler missing the other one doesn't work need to be replaced.							
<u>Joe Ramirez</u>									
41690	Main Building	Classroom			1/21/2009		105		\$0.00
Medium	Work In Progress	Room # 203		1/21/2009 10:37:15 AM					
Lozoya, Manny		Pamela Uribe IA needs key we don't have another in key box for that room.							
<u>Sandra Mora</u>									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

41977					1/29/2009		97		\$0.00
High	Work In Progress				1/29/2009 8:14:01 AM				
Gonzalez, Salvador		covers to lift station are rusty and old and need replacement ASAP. safty thxs							
Michael Munoz									
43297					3/4/2009		63		\$0.00
Medium	Work In Progress				3/4/2009 8:56:21 AM				
Lozoya, Manny		i need 3 latchkeepers for bathroom stalls.							
Joe Ramirez									
44087					3/31/2009		36		\$0.00
Medium	Work In Progress				3/31/2009 12:22:48 AM				
Ramirez, Joe		Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.							
Margret Villalobos									
44088					3/31/2009	5/1/2009	36		\$0.00
Medium	Work In Progress				3/31/2009 12:22:48 AM				
Ramirez, Joe		Yearly - Mesquite ES A-8 A/C Window Unit Yearly - Refer to PM schedule details.							
Margret Villalobos									
44395					4/5/2009	4/21/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:09 AM				
Ramirez, Joe		Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.							
Margret Villalobos									
44396					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:09 AM				
Ramirez, Joe		Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
44397					4/5/2009		31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:10 AM				
Ramirez, Joe		Yearly - Mesquite ES A-13 A/C Wall Mount Yearly - Refer to PM schedule details.							
Margret Villalobos									
44398					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:10 AM				
Ramirez, Joe		Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

44399					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:10 AM				
Ramirez, Joe		Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
44400					4/5/2009	4/11/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:11 AM				
Ramirez, Joe		Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
44448					4/6/2009		30		\$0.00
Medium	Work In Progress				4/6/2009 10:36:12 AM				
Ronquillo, Ruben		need to replace 1,000 feet of covebase in the hallways.							
Joe Ramirez									
45197					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress				4/30/2009 12:21:36 AM				
Ramirez, Joe		Yearly - Mesquite ES C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
45211					4/30/2009		6		\$0.00
Medium	Work In Progress				4/30/2009 1:35:15 PM				
Sotelo, Enrique		need electrical board put for spring fling may 8th							
Joe Ramirez									
45309					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:45 AM				
Ramirez, Joe		Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
45310					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:45 AM				
Ramirez, Joe		Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
45311					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:46 AM				
Ramirez, Joe		Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
45340		Cafeteria			5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 7:33:37 AM				
Orozco, Danny		SILVER MILK COOLER NOT COOLING AT ALL.							
Jacqueline Aguilar		ALICE F. SNP MGR 233-2341							
45413					5/5/2009		1		\$0.00
Medium	Work In Progress				5/5/2009 11:22:46 AM				
Ramirez, Joe		joe as per pictures e-mailed to you could you please trim trees that need to be, remove chinese elm, rake leaves trim parking lot / mulberry area and sweep.also water bty main entrance.(office area) thankyou							
Michael Munoz					5/5/2009		1		\$0.00
45414					5/5/2009 11:24:54 AM				
High	Work In Progress								
Ramirez, Joe		please re-paint yellow parking lines and paint also fire lanes and handi-cap parking if need be.thanks							
Michael Munoz					5/5/2009		1		\$0.00
45415					5/5/2009 11:26:51 AM				
High	Work In Progress								
Ramirez, Joe		Joe as per pictures e-mailed, please repair soffit and paint. also apply 10% bleach solution as per discussion with you. thanks							
Michael Munoz					5/5/2009		1		\$0.00
45422					5/5/2009 2:35:37 PM				
Medium	Work In Progress								
Ramirez, Joe		NEEDS TO REPLACED 10 TILES ON ROOM #111 THANK YOU LUIS							
Luis Saucedo					5/5/2009		1		\$0.00
45423					5/5/2009 2:36:59 PM				
Medium	Work In Progress								
Ramirez, Joe		ON PORTABLE #229 GIRLS RESTROOMS NEEDS TO REPLACEDE 9 TILES THANK YOU LUIS							
Luis Saucedo					5/5/2009		1		\$0.00
45424					5/5/2009 2:38:19 PM				
Medium	Work In Progress								
Ramirez, Joe		NEED TO REPLEACE (10) TILES ON ROOM #110 THANK YOU LUIS, ANY QUESTIONS ASK LUIS.							
Luis Saucedo									
Count: 37 Work Orders		Avg. Age of WO's 95				Total for Mesquite ES	0		\$0.00

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
36463		Office			8/1/2008		278		\$0.00
Medium	Work In Progress	room 400			8/1/2008 11:44:39 AM				
Lozoya, Manny		Hello Manny,							
		The alarm box key was broken off, please replace.							
<u>Priscilla Martinez</u>									
37136		Office			8/18/2008		261		\$0.00
Medium	Work In Progress	video			8/18/2008 10:18:19 AM				
Lozoya, Manny		could not locate a key				Need a black box located in our office to be opened, could not locate the correct key in our vault			
Priscilla Martinez									
37221		Classroom			8/20/2008		259		\$0.00
Medium	Work In Progress	various			8/20/2008 9:15:00 AM				
Lozoya, Manny		Send Lozoya to make various keys for various classrooms, desks, cabinets, filing cabinets, storage closets,				please visit the front office for this list of keys that are needed, thanks Priscilla			
<u>Priscilla Martinez</u>									
38084		Classroom			9/15/2008		233		\$0.00
Medium	Work In Progress				9/15/2008 1:35:12 PM				
Lozoya, Manny		need a key made for Larry Roybal (Deputy Dona Ana County Sheriff) for the gates at North Valley Elementary							
<u>Priscilla Martinez</u>									
38743					10/5/2008		213		\$0.00
Medium	Work In Progress				10/5/2008 12:23:50 AM				
Holguin, Alfredo		Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.				10/6/08 - Emailed to Ricky Borrego			
<u>Margret Villalobos</u>									
39280					10/20/2008		198		\$0.00
Medium	Work In Progress				10/20/2008 9:11:35 AM				
Lozoya, Manny		need new pad lock for bus exit gate/had to cut old lock this morning-key didnt turn core							
<u>Danny Vega</u>									
39383					10/22/2008		196		\$0.00
Medium	Work In Progress				10/22/2008 1:41:03 PM				
Lozoya, Manny		p.e coaches office door will not open -core will not turn with key-please ck out asap							
<u>Danny Vega</u>									
39456		Classroom			10/24/2008		194		\$0.00
Medium	Work In Progress	room 210			10/24/2008 12:13:11				
Lozoya, Manny		black file cabinet w/blue sticker does not lock.							
Priscilla Martinez									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: North Valley ES									
39804					11/4/2008		183		\$0.00
Medium	Work In Progress			11/4/2008 9:20:53 AM					
Lozoya, Manny	need key made for rm 304 art rm/cabinet key broke in core-need to lock-up supplies asap								
Danny Vega									
40891					12/16/2008		141		\$0.00
Medium	Work In Progress			12/16/2008 8:10:47 AM					
Lozoya, Manny	need duplicate from rm 306/cabinet keys- parent center (402) has 01 and 06 key locks-need to give rm 402 a 06 key								
Danny Vega									
41151					1/4/2009		122		\$0.00
Medium	Work In Progress			1/4/2009 12:19:23 AM					
Holguin, Alfredo	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.		1/6/09 - E-mailed to ricky.borrego@cummins.com'						
Margret Villalobos									
42695					2/19/2009		76		\$0.00
Medium	Work In Progress			2/19/2009 8:14:21 AM					
Holguin, Alfredo	Rm 201 - Unit was changed out and is still going out on Hi/low pressure cutout.		This work order is for Trane.						
Lorenzo Solis									
42737					2/20/2009		75		\$0.00
Medium	Work In Progress			2/20/2009 8:28:56 AM					
Holguin, Alfredo	Rm 101 - Unit going out on Hi/low pressure cutout.								
Lorenzo Solis									
44289					4/5/2009		31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:31 AM					
Holguin, Alfredo	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.		4/7/09 E-mailed PM to Ricky and Garrett at Rocky Mtn.						
Margret Villalobos									
44343					4/5/2009	4/13/2009	31	1	\$25.00
Medium	Work In Progress			4/5/2009 12:22:51 AM					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.		done						
Margret Villalobos									
44444		Mechanical Room			4/6/2009		30		\$446.50
Medium	Work In Progress			4/6/2009 8:58:26 AM					
Solis, Lorenzo	We have no communication w/BCU. Tech has reset BCU and it will not reset. Please send someone out a/s/a/p								
Lorenzo Solis									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: North Valley ES

44497		Classroom			4/7/2009		29		\$0.00
Medium	Work In Progress				4/7/2009 9:21:44 AM				
Ontiveros, Joe		Foul odor in room 108.							
Danny Vega									
44622					4/12/2009	4/28/2009	24		\$0.00
Medium	Work In Progress				4/12/2009 12:21:17 AM				
Parra, Javier		Monthly - QRTL BLDG INSP REPORT (SM) - Refer to PM schedule details.							
Jesus Estrada									
44867					4/21/2009		15		\$0.00
Medium	Work In Progress				4/21/2009 2:12:09 PM				
Lozoya, Manny		mullion lock on door needs repaired (pump house storage)stop by when in area							
Danny Vega									
45212					4/30/2009		6		\$0.00
Medium	Work In Progress				4/30/2009 2:05:12 PM				
Gonzales, Angel		pump house diesel fuel tank needs to be topped -off showing 3/4 full as of 4-30-09							
Danny Vega									
45273					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:32 AM				
Vega, Danny		Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
45275					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:33 AM				
Vega, Danny		Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
45277					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:34 AM				
Vega, Danny		Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
Count: 23 Work Orders			Avg. Age of WO's	113		Total for North Valley ES	1		\$471.50

Location: Northern On-Track Pre-K (LM)

37774		Athletic Field			9/4/2008		244		\$0.00
Medium	Work In Progress				9/4/2008 8:52:16 AM				
Lozoya, Manny		send us the lock and chain to secure the west gate							
Gilbert Trujillo									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

37775	Main Building	Restroom (Girls)			9/4/2008		244		\$0.00
Medium	Work In Progress	classroom 114			9/4/2008 9:33:49 AM				
Lozoya, Manny		Bathroom door in the baby room won't close.							
Concepcion Montalvo									
39602	Pump House	Pump House			10/30/2008		188		\$0.00
Medium	Work In Progress				10/30/2008 9:07:18 AM				
Lozoya, Manny		please change lock back to original lock on irrigation well thanks							
Ricardo Jacquez									
39905		Restroom (Boys)			11/6/2008		181		\$0.00
Medium	Work In Progress				11/6/2008 10:29:38 AM				
Lozoya, Manny		alma de valle restroom door need to be worked on.							
Gilbert Trujillo									
40019	Main Building	Classroom			11/12/2008		175		\$0.00
Medium	Work In Progress				11/12/2008 8:35:22 AM				
Sotelo, Enrique		classroom plug switch is shorted out. room 112							
Gilbert Trujillo									
41981	Cafeteria				1/29/2009		97		\$0.00
Medium	Work In Progress				1/29/2009 8:40:25 AM				
Carrasco, Danny		please pick-up shelving that belongs to gms and deliver to sunland carpentry, so they can make adjustments for installation at loma linda. as per ida garcia and phillip medina							
Michael Munoz									
42974	Main Building	Elevator			2/26/2009		69		\$0.00
Medium	Work In Progress				2/26/2009 11:30:06 AM				
Lozoya, Manny		we need 1 master key for alma del valle day care							
Gilbert Trujillo									
43540					3/10/2009		57		\$0.00
Medium	Work In Progress				3/10/2009 11:17:33 AM				
Lozoya, Manny		rm110 keys binding in cylinder /need to clean or replace key cylinder /alma del valle talk with maria she will show you /please ck her key as well							
Danny Vega									
44078					3/31/2009	5/1/2009	36		\$0.00
Medium	Work In Progress				3/31/2009 12:22:43 AM				
Vega, Danny		Yearly - Northern Pre-k A8 (Window Unit)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location:	Northern On-Track Pre-K (LM)								
44639					4/12/2009	4/28/2009	24		\$0.00
Medium	Work In Progress			4/12/2009 12:21:24 AM					
Vega, Danny	Monthly - Northern On-Track Pre-K Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
45190					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:33 AM					
Vega, Danny	Yearly - Northern Prek C11 (Evap.Cooler)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
45274					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:33 AM					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45276					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:33 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45278					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:34 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
45432					5/5/2009		1		\$0.00
Medium	Work In Progress			5/5/2009 3:30:24 PM					
Ontiveros, Joe	water fountain in east hallway keeps backing -up need small snake on this								
Danny Vega									
Count: 15 Work Orders			Avg. Age of WO's	89		Total for Northern On-Track Pre-K (LM)	0		\$0.00

Location:	Physical Plant Complex								
36213	Maintenance				7/25/2008		285		\$0.00
Medium	Work In Progress			7/25/2008 10:15:21 AM					
Sotelo, Enrique	please install electrical outlet to cooling duct fan and pilot switch. Thxs								
Michael Munoz									
36291					7/28/2008		282		\$0.00
Medium	Work In Progress			7/28/2008 3:26:53 PM					
Ronquillo, Ruben	Purchase a new water tank								
Alfredo Holguin									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
36355	Food Services	Parking Lot			7/30/2008		280		\$0.00
Medium	Work In Progress	SNP			7/30/2008 12:01:33 PM				
Ontiveros, Guadalupe	AS PER MR. GIOVAS-IF NEAR THE WAREHOUSE GOING FROM THE SHADED AREA TO THE STAIR WAY INTO THE WAREHOUSE IF THEY CAN LEVEL OUT THE PATH WAY. (PLEASE SEE JOHNNY L. IF NEED DIRECTION.)								
Mary Garcia									
37767					9/4/2008		244		\$0.00
Medium	Work In Progress				9/4/2008 8:02:44 AM				
Lozoya, Manny	need to replace door lock on water department office does not lock thanks								
Ricardo Jacquez									
37791	Purchasing				9/4/2008		244		\$0.00
Medium	Work In Progress				9/4/2008 2:35:30 PM				
Sotelo, Enrique	I would like to have a light switch in my office to control the lights. Currently the switch is in the hall and the one switch controls my office and hallway.								
Vicky Lopez									
37882	Food Services				9/8/2008		240		\$0.00
Medium	Work In Progress				9/8/2008 8:10:34 AM				
Ontiveros, Guadalupe	Need to add Crusher fines to dock area.								
Alfredo Holguin									
39941					11/7/2008		180		\$0.00
Medium	Work In Progress				11/7/2008 1:06:01 PM				
Ontiveros, Guadalupe	Gooseneck Trailers 2 ea. - Replace damaged floor boards								
Alfredo Holguin									
41518	Food Services	Cafeteria			1/15/2009		111		\$0.00
Medium	Work In Progress				1/15/2009 9:29:05 AM				
Moncayo, Fernando	WORK ORDER FOR GADSDEN STUDENT NUTRITION PROGRAM WAREHOUSE - -- MOTOR WENT OUT TO THE FURNACE								
	JOHNNY LECHUGA - SNP WAREHOUSE MGR 882-6927								
Alma Terrell									
41915					1/27/2009		99		\$0.00
Medium	Work In Progress				1/27/2009 4:07:07 PM				
Gonzales, Angel	Mail Van - driver side seat needs additional padding call Alfredo Holguin if you have questions								
Alfredo Holguin									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

42215	Maintenance				2/4/2009		91		\$0.00
Medium	Work In Progress				2/4/2009 8:52:47 AM				
Sotelo, Enrique		Need to remove electrical from old HVAC Shop.							
Manny Lozoya									
42228	Maintenance				2/4/2009		91		\$0.00
Medium	Work In Progress				2/4/2009 1:23:11 PM				
Miranda, Danny		FRAME AND FURR MAINT.WHS. OPENING TO PLUMBING DANNY MIRANDA							
Danny Carrasco									
42234	Maintenance				2/4/2009		91		\$0.00
Medium	Work In Progress				2/4/2009 3:22:07 PM				
Lozoya, Manny		NEED TO INSTALL BARREL BOLT ON PLUMB. EXIT DOUBLE DOOR							
Ruben Ronquillo									
42264	Maintenance				2/5/2009		90		\$0.00
Medium	Work In Progress				2/5/2009 10:40:01 AM				
Sotelo, Enrique		Need to change bulbs in my office.							
Margret Villalobos									
42359	Food Services	Electrical Room			2/9/2009		86		\$0.00
Medium	Work In Progress				2/9/2009 8:24:32 AM				
Sotelo, Enrique		need to Relocated swich box where they installed the new door frame. thank you							
Ralph Lara									
42670	Custodial				2/18/2009		77		\$0.00
Medium	Work In Progress				2/18/2009 1:13:19 PM				
Carbajal, Jimmy		I need a custodial equipment inventory of all sites.							
Jesus Estrada									
42915					2/25/2009		70		\$0.00
Medium	Work In Progress				2/25/2009 11:25:40 AM				
Carrasco, Danny		Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.							
Michael Munoz									
42917					2/25/2009		70		\$0.00
Medium	Work In Progress				2/25/2009 11:26:42 AM				
Carrasco, Danny		Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.							
Michael Munoz									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Physical Plant Complex

42929					2/25/2009		70		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/25/2009 12:32:49 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Carrasco, Danny
 Danny need to conduct inventory of all Technicians c tools and equipment. Ask Ruben for present inventory list to match up.

Michael Munoz

42930					2/25/2009		70		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/25/2009 12:35:59 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Carrasco, Danny
 Danny need to conduct inventory of all Technicians c tools and equipment. Ask Ruben for present inventory list to match up.

Michael Munoz

42931					2/25/2009		70		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/25/2009 12:36:53 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Carrasco, Danny
 Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.

Michael Munoz

42932					2/25/2009		70		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/25/2009 12:37:43 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Carrasco, Danny
 Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.

Michael Munoz

42933					2/25/2009		70		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/25/2009 12:39:11 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Carrasco, Danny
 Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.

Michael Munoz

43127					3/1/2009		66		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			3/1/2009 12:23:04 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Orozco, Danny
 Yearly - Physical Plant Fire Ext. Insp. (Yearly) - Refer to PM schedule details.

Margret Villalobos

43420	Food Services	Cafeteria			3/6/2009		61		\$0.00
-------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			3/6/2009 9:35:24 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Moncayo, Fernando
 SNP WHSE: Need to replace some lights that went out in the SNP Warehouse.

Johnny Lechuga SNP WHSE MGR 882-6927

Jacqueline Aguilar

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

43492	Food Services	Cafeteria			3/9/2009		58		\$0.00
Medium	Work In Progress				3/9/2009 1:53:23 PM				

Moncayo, Fernando SNP WHSE: RAIN GUTTER AT LOADING DOCK NEEDS TO BE REPAIRED.

JOHNNY LECHUGA SNP WHSE MGR 882-6775

Jacqueline Aguilar

43574					3/11/2009		56		\$0.00
High	Work In Progress				3/11/2009 8:35:17 AM				

Gonzales, Angel please install trailer brakes on vehicle #152. Thankyou

Michael Munoz

43818	Motor Vehicle	Electrical Room			3/17/2009		50		\$0.00
Medium	Work In Progress				3/17/2009 4:00:47 PM				

Gonzales, Angel Vehicle #152 needs a new set of tires.

Carlos Castillo

43875					3/19/2009		48		\$0.00
Medium	Work In Progress				3/19/2009 1:13:24 PM				

Gonzales, Angel Need to install flashing light and backup alarm signal on all Maintenance Vehicles - asp Mike Munoz.

Michael Munoz

43876	Motor Vehicle				3/19/2009		48		\$0.00
Medium	Work In Progress				3/19/2009 1:14:17 PM				

Gonzales, Angel PLEASE CHECK WATER PUMP ENGINE, NOT STARTING. THANKS RUBEN

Ruben Ronquillo

43877	Motor Vehicle				3/19/2009		48		\$0.00
Medium	Work In Progress				3/19/2009 1:15:08 PM				

Gonzales, Angel PLEASE CHECK YELLOW DOUBLE AIR TANK COMPRESSOR, IDLE IS NOT WORKING, IT WILL NOT IDLE DOWN WHEN TANKS ARE FULL. THANKS RUBEN

Ruben Ronquillo

44121	Maintenance				3/31/2009		36		\$0.00
Medium	Work In Progress				3/31/2009 1:58:40 PM				

Carrasco, Danny Asp Mike need to shrink wrap all Video Equipment stored in storage room in Tech Office.

Michael Munoz

44158	Maintenance				4/1/2009		35		\$0.00
Medium	Work In Progress				4/1/2009 10:09:41 AM				

Gonzales, Angel Also generate a w/o for Angel to check the generator for proper operation. The small one we have here at the maint office. (Will be needed on May 8th @ GHS)

Michael Munoz

5/6/2009 11:28:11 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Physical Plant Complex

44545					4/8/2009		28		\$0.00
Medium	Work In Progress				4/8/2009 1:25:02 PM				
Gonzales, Angel	Truck #16 needs brakes checked, front wheels drag when it stops. Need new wiper blades.								
Jesus Estrada									
45219	Purchasing				4/30/2009		6		\$0.00
Medium	Work In Progress				4/30/2009 3:30:57 PM				
Solis, Luis	run power supply to industrial a/c unit.								
Lorenzo Solis									
45221					4/30/2009		6		\$0.00
Medium	Work In Progress				4/30/2009 3:35:20 PM				
Solis, Lorenzo	Need to replace custodial warehouse A/C for safty thank you								
Sebastian Diaz									
45332					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:53 AM				
Diaz, Sebastian	Monthly - Physical Plant FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
45337					5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 12:20:07 AM				
Villalobos, Margret	Monthly - PPD - Quarterly Meeting - Refer to PM schedule details.								
Margret Villalobos									
45339					5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 7:32:11 AM				
Gonzales, Angel	Van # 23 (locksmith) has a flat. please repair. thankyou								
Michael Munoz									
45420					5/5/2009		1		\$0.00
Medium	Work In Progress				5/5/2009 2:24:27 PM				
Lara, Ralph	RELOCATE DOUBLE DOORS ON BARRACK #1.								
Ruben Ronquillo									
Count: 39 Work Orders			Avg. Age of WO's 91			Total for Physical Plant Complex	0		\$0.00

Location: Riverside ES

37820					9/5/2008		243		\$0.00
Medium	Work In Progress				9/5/2008 8:39:36 AM				
Gonzalez, Salvador	Need to make a canopy for behind of cafeteria.								
Michael Munoz									
39543					10/28/2008		190		\$0.00
Medium	Work In Progress				10/28/2008 1:28:41 PM				
Lozoya, Manny	remove lock from the flashing lights -								
Cora Ramirez									
5/6/2009 11:28:11 AM									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

40264					11/20/2008		167		\$0.00
Medium	Work In Progress				11/20/2008 3:11:28 PM				
Gonzales, Angel		truck seat needs repair truck #21							
Carlos Hernandez									
40877		Cafeteria			12/15/2008		2	1	\$25.00
Medium	Work In Progress				12/15/2008 3:27:13 PM	12/17/2008			
Moncayo, Fernando		alarm showing dirty duct in cafeteria and dirty 2, 16				12/17/08 ck Dimar Report was showing exhaust fan in kitchen alarm. Ck inside and it reflects to kitchen equip, route to Fernie. - J. Ambriz			
Carlos Hernandez									
40950					12/17/2008		140		\$0.00
Medium	Work In Progress				12/17/2008 3:08:54 PM				
Moncayo, Fernando		range hood systems exhaust fan not operating							
Carlos Hernandez									
42669					2/18/2009		77		\$0.00
Medium	Work In Progress				2/18/2009 1:11:51 PM				
Villalobos, David		need 7 new water fountain heads for water fountains outside need to be replaced							
Carlos Hernandez									
42801	New Wing 1/02				2/23/2009		72		\$0.00
Medium	Work In Progress				2/23/2009 2:58:23 PM				
Castillo, Carlos		need new switch for heater room 104							
Carlos Hernandez									
43114					3/1/2009		66		\$0.00
Medium	Work In Progress				3/1/2009 12:22:59 AM				
Orozco, Danny		Yearly - Riverside ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
43598		Cafeteria			3/11/2009		56		\$0.00
Medium	Work In Progress				3/11/2009 1:00:50 PM				
Moncayo, Fernando		EXHAUST WON'T TURN ON							
		AIDA SALCEDO - SNP COMPLIANCE COORDINATOR 915/472-4748							
Alma Terrell									
43599		Cafeteria			3/11/2009		56		\$0.00
Medium	Work In Progress				3/11/2009 1:02:05 PM				
Moncayo, Fernando		TWO LIGHTS IN THE EXHAUST AREA ARE DOWN							
		AIDA SALCEDO -SNP COMPLIANCE COORDINATOR 915-472-4748							
Alma Terrell									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
44329					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:47 AM					
Orozco, Danny	Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
44559					4/8/2009		28		\$0.00
Medium	Work In Progress			4/8/2009 3:22:26 PM					
Ambriz, Jose	2 water fountians not cooling main building								
<u>Carlos Hernandez</u>									
44621					4/12/2009	4/28/2009	24		\$0.00
Medium	Work In Progress			4/12/2009 12:21:17 AM					
Mata, Daniel	Monthly - QRTLY BLDG INSP REPORT (RS) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
44745					4/16/2009		20		\$0.00
Medium	Work In Progress			4/16/2009 1:05:36 PM					
Ambriz, Jose	water fountain in middle wing water stays running broken valve								
<u>Carlos Hernandez</u>									
44783					4/17/2009		19		\$0.00
Medium	Work In Progress			4/17/2009 11:09:05 AM					
Hernandez, Carlos	Need to pick up debris (ie: trash, weeds dirt etc) on Teacher parking lot an student drop off.								
<u>Michael Munoz</u>									
45096		Classroom			4/28/2009		8		\$0.00
Medium	Work In Progress	1st to 5th grade		4/28/2009 11:45:38 AM					
Hernandez, Carlos	Furniture for computers delivered to the school please set up in classrooms first to fifth grade. Furniture will be delivered to the school on April 30th. Thank you.								
<u>Sandra Almeraz</u>									
45188					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:33 AM					
Hernandez, Carlos	Yearly - Riverside ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45264					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:29 AM					
Hernandez, Carlos	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

45265					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:29 AM				
Hernandez, Carlos		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
45266					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:30 AM				
Hernandez, Carlos		Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
45374					5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 3:01:28 PM				
Ronquillo, Ruben		broken window 19x20 double pane window room 126							
<u>Carlos Hernandez</u>									
45431					5/5/2009		1		\$0.00
Medium	Work In Progress				5/5/2009 3:29:41 PM				
Lara, Ralph		need replacement key for custodial and clean core storage room custodial							
<u>Carlos Hernandez</u>									
Count: 22 Work Orders			Avg. Age of WO's 55			Total for Riverside ES	1		\$25.00

Location: San Miguel ES

37343					8/22/2008		257		\$0.00
Medium	Work In Progress				8/22/2008 3:24:23 PM				
Lozoya, Manny		Asp Mike, please core back to GM 6 or 7 pin.							
<u>Michael Munoz</u>									
39565	Main Building				10/29/2008		189		\$0.00
Medium	Work In Progress				10/29/2008 7:32:46 AM				
Lozoya, Manny		please change cores to where the techs can have access to the back door of the boiler room so they can service equipment.							
<u>Michael Munoz</u>									
43315	Main Building				3/4/2009		63		\$0.00
Medium	Work In Progress				3/4/2009 1:58:33 PM				
Ramirez, Joe		Need to clean around pine trees.							
<u>Michael Munoz</u>									
43382					3/5/2009		62		\$0.00
Medium	Work In Progress	Going to CMS			3/5/2009 2:25:02 PM				
Briones, Enrique		AS PER SHEILA RAIHL-NEED TO HAVE THE FOLLOWING FURNITURE TAKEN FROM SAN MIGUEL ELEM. AND MOVED TO CHAPARRAL MIDDLE SCHOOL: 52-LARGE CHAIRS							
									APPROVED BY MR. RICHARD G. CHAVEZ ON RELEASE OF FURNITURE FROM SAN MIGUEL ELEM.
<u>Mary Garcia</u>									

5/6/2009 11:28:11 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: San Miguel ES

43384					3/5/2009		62		\$0.00
Medium	Work In Progress	Going to Desert		3/5/2009 2:39:19 PM					
Briones, Enrique		AS PER SHEILA RAIHL-NEED TO HAVE THE FOLLOWING FURNITURE TAKEN FROM SAN MIGUEL ELEM. AND MOVED TO DESERT PRIDE ACADEMY: 28-LARGE CHAIRS 14-5 FT TABLES				APPROVED BY MR. RICHARD G. CHAVEZ ON RELEASE OF FURNITURE FROM SAN MIGUEL.			
<u>Mary Garcia</u>									
43425	Main Building	Mechanical Room			3/6/2009		61		\$0.00
Medium	Work In Progress			3/6/2009 12:42:01 PM					
Solis, Lorenzo		Check boiler room.							
<u>Lorenzo Solis</u>									
45366					5/4/2009		2		\$0.00
Medium	Work In Progress			5/4/2009 2:28:55 PM					
Vega, Danny		Open bldg tomorrow 5/5/09 @ 10:00am for Ms. Vigil to look at furniture.							
<u>Mary Garcia</u>									
Count: 7 Work Orders			Avg. Age of WO's 99			Total for San Miguel ES	0		\$0.00

Location: Santa Teresa ES

39918	Main Building	Restroom (Girls)			11/6/2008		181		\$0.00
Medium	Work In Progress	ladies restroom		11/6/2008 3:11:24 PM					
Marquez, Gerardo		Large spacing in between the wall and other toilet partition needs to be covered. The gap is large enough to see other people inside the stall. Thank you.							
<u>Rita Mendez</u>									
41235		Cafeteria			1/7/2009		119		\$0.00
Medium	Work In Progress			1/7/2009 10:45:02 AM					
Moncayo, Fernando		NEED DOOR BELL FOR BACK DOO (DELIVERY) PAT SANCHEZ STE SNP MGR 589-3439							
<u>Jacqueline Aguilar</u>									
41278		Classroom			1/8/2009		118		\$0.00
Medium	Work In Progress	RM 102		1/8/2009 3:18:53 PM					
Marquez, Gerardo		NEED RACK FOR JACKETS TO SET UP IN CLASSROOM 102							
<u>Rita Mendez</u>									
41990					1/29/2009		97		\$0.00
Medium	Work In Progress			1/29/2009 1:38:38 PM					
Moncayo, Fernando		FERNIE; THE HANDWASHING STATIONS IN THE CAFET. PREP AREA ARE BOTH RUNNING CONTINUOUSLY. WOULD YOU PLEASE CORRECT THE PROBLEM.							
<u>Gerardo Marquez</u>									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa ES

42521					2/12/2009		83		\$0.00
Medium	Work In Progress			2/12/2009 11:03:36 AM					
Ontiveros, Guadalupe	LUPE, AS PER OUR CONVERSATION ON 2/12/09. WE NEED TO HAVE THE S. W. CORNER OF THE FENCE THAT THE CONTRACTOR STATED TO REMOVE PUT BACK UP.								
Gerardo Marquez									
42672	Main Building	Parking Lot			2/18/2009		77		\$0.00
Medium	Work In Progress	FENCE		2/18/2009 1:21:13 PM					
Ronquillo, Ruben	NEED 2 SIGNS TO SAY: NOT A STUDENT DROP OFF. THESE SIGNS NEED TO BE POSTED AT FACULTY PARKING LOT ENTRANCE. NEED SIGNS TO BE BIG ENOUGH TO BE VISIBLE. THANKS.								
Rita Mendez									
43467					3/8/2009	3/24/2009	59		\$0.00
Medium	Work In Progress			3/8/2009 12:20:42 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
43573					3/11/2009		56		\$0.00
Medium	Work In Progress			3/11/2009 8:32:09 AM					
Castillo, Carlos	CALI; THERE ARE 3 BURNT OUT LIGHTS IN THE FACULTY PARKING LOT THAT NEED REPLACING. WOULD YOU PLEASE SCHEDULE THE LIFT TO CHANGE THEM OUT.								
Gerardo Marquez									
43785					3/17/2009		50		\$0.00
Medium	Work In Progress			3/17/2009 10:31:16 AM					
Villalobos, David	DAVID, COULD YOU PLEASE CHECK OUT FAUCETS IN GIRLS RRM. BY CAFETERIA & ALSO @ TEACHERS LOUNGE.								
Gerardo Marquez									
44080					3/31/2009		36		\$0.00
Medium	Work In Progress			3/31/2009 12:22:44 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES-A-16 Fan Exhaust (SemiA) - Refer to PM schedule details.								
Margret Villalobos									
44330					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:47 AM					
Orozco, Danny	Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

44358					4/5/2009	4/11/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:56 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
44359					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:57 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
44360					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:57 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
44361					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:57 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
44496					4/7/2009		29		\$0.00
Medium	Work In Progress				4/7/2009 9:11:13 AM				
Ontiveros, Guadalupe		LUPE, NEED TO SCHEDULE TO HAVE PLAYGROUND AREA AERATED, & FERTILIZED. THANKS.							
Gerardo Marquez									
44498					4/7/2009		29		\$0.00
Medium	Work In Progress				4/7/2009 9:25:06 AM				
Ontiveros, Guadalupe		LUPE, SOUTHWEST CORNER OF FENCE THAT WAS PARTIALLY REMOVED BY ACADEMY FENCE WAS NEVER REPAIRED . AT ONE TIME YOU SENT RAFA TO TAKE CARE OF THIS. COULD YOU TAKE CARE OF THIS?							
Gerardo Marquez									
44623					4/12/2009	4/28/2009	24		\$0.00
Medium	Work In Progress				4/12/2009 12:21:17 AM				
Diaz, Pablo		Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.							
Jesus Estrada									
44641					4/12/2009	4/28/2009	24		\$0.00
Medium	Work In Progress				4/12/2009 12:21:25 AM				
Marquez, Gerardo		Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa ES

45010	Main Building	Office			4/24/2009		12		\$0.00
Medium	Work In Progress	WORKORDER			4/24/2009 9:51:57 AM				
Marquez, Gerardo	ART PANELS NEED TO BE TRANSPORTED TO GADSDEN MIDDLE SCHOOL ON 4/29/09 AND NEED TO BE SET UP FOR ART SHOW. PANELS NEED TO BE PICKED UP ON 5/4/09.								
Rita Mendez									
45094		Classroom			4/28/2009		8		\$0.00
Medium	Work In Progress	1st - 5th grade			4/28/2009 11:41:37 AM				
Marquez, Gerardo	Furniture for computers delivered to the school please set up in classrooms first to fifth grade. Furniture will be delivered on Apri. 28. Thank you.								
Sandra Almeraz									
45287					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:37 AM				
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45288					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:37 AM				
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45289					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:38 AM				
Marquez, Gerardo	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
Count: 24 Work Orders			Avg. Age of WO's	49		Total for Santa Teresa ES	0		\$0.00

Location: Santa Teresa HS

42903	Main Building	Classroom			2/25/2009		70		\$0.00
Medium	Work In Progress				2/25/2009 9:39:24 AM				
Nunez, Arturo	Room 308 screens for windows								
Rosa Hood									
35552					7/6/2008	7/12/2008	304		\$0.00
Medium	Work In Progress				7/6/2008 12:19:21 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
35569					7/6/2008	7/14/2008	304		\$0.00
Medium	Work In Progress				7/6/2008 12:19:26 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
35666					7/6/2008	8/6/2008	304		\$0.00
Medium	Work In Progress				7/6/2008 12:19:56 AM				
Nunez, Arturo		Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35689					7/6/2008	8/6/2008	304		\$0.00
Medium	Work In Progress				7/6/2008 12:20:04 AM				
Nunez, Arturo		Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
36510					8/3/2008	8/9/2008	276		\$0.00
Medium	Work In Progress				8/3/2008 12:20:16 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
37386					8/26/2008		253		\$0.00
Medium	Work In Progress				8/26/2008 7:30:49 AM				
Ontiveros, Guadalupe		Pedestrian Gate on South side that goes to the Bluffs. - Install taller gate to prevent access through bottom of gate.							
Alfredo Holguin									
37545					8/31/2008	9/6/2008	248		\$0.00
Medium	Work In Progress				8/31/2008 12:25:12 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
38544	Cafeteria (2005)	Cafeteria			9/30/2008		218		\$0.00
Medium	Work In Progress				9/30/2008 8:10:55 AM				
Moncayo, Fernando		Comments from Ecolab Report: Dishwasher is not filling up. Pre-spray hose id damaged & should be replaced. Olga Bustamante SNP MANAGER 58905332							
Jacqueline Aguilar									
38595	Gymnasium				10/1/2008		217		\$0.00
Medium	Work In Progress				10/1/2008 12:31:34 PM				
Nunez, Arturo		REPLACE STAINED AND BROKEN CIELING TILES							
Michael Munoz									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

38753					10/5/2008	10/11/2008	213		\$0.00
Medium	Work In Progress				10/5/2008 12:23:53 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
38754					10/5/2008	10/13/2008	213		\$0.00
Medium	Work In Progress				10/5/2008 12:23:53 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
38755					10/5/2008	10/26/2008	213		\$0.00
Medium	Work In Progress				10/5/2008 12:23:54 AM				
Nunez, Arturo		Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.							
Margret Villalobos									
38756					10/5/2008	11/5/2008	213		\$0.00
Medium	Work In Progress				10/5/2008 12:23:54 AM				
Nunez, Arturo		Yearly - Santa Teresa HS H-6 Rftop Furn Yearly - Refer to PM schedule details.							
Margret Villalobos									
38757					10/5/2008	11/5/2008	213		\$0.00
Medium	Work In Progress				10/5/2008 12:23:54 AM				
Nunez, Arturo		Yearly - Santa Teresa HS R-9 Radiator Ht Wtr 2yr - Refer to PM schedule details.							
Margret Villalobos									
38758					10/5/2008	10/21/2008	213		\$0.00
Medium	Work In Progress				10/5/2008 12:23:55 AM				
Nunez, Arturo		Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.							
Margret Villalobos									
39164					10/12/2008	10/28/2008	206		\$0.00
Medium	Work In Progress				10/12/2008 12:21:05				
Nunez, Arturo		Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.							
Margret Villalobos									
39344					10/21/2008		197		\$0.00
Medium	Work In Progress				10/21/2008 3:13:05 PM				
Villalobos, David		NEED SOME ASSISTANCE ON LEAK TEST GAS LINES ON WELDING BOTHS, THERE SEEMS TO BE A GAS LEAK, BUT CAN'T LOCATE.							
Arturo Nunez									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

39396	Main Building	Choral			10/22/2008		196		\$0.00
Medium	Work In Progress				10/22/2008 3:57:04 PM				

Lara, Ralph
Door from Band Room Top Corner broken, needs to be replaced
Thank you,
Rosa

Rosa Hood

39398	Main Building	Hallway/Corridor			10/22/2008		160		\$0.00
Medium	Work In Progress				10/22/2008 3:59:35 PM	3/31/2009			

Prospero, Manuel
Remove lockers in hallway near counseling area and across from Main office
Thank you,
Rosa

Rosa Hood

39542	Main Building	Office			10/28/2008		190		\$0.00
Medium	Work In Progress				10/28/2008 1:18:25 PM				

Nunez, Arturo
We need signs to indicate what building is what since we do not have a front entrance. Please feel free to call me or Art Nunez so that we can be more specific
Thank you,
Rosa
1/23/09 - Art asp our conversation you would take care of it and asp Mike please submit request for signs. - Thank You Ruben

Rosa Hood

39695	Main Building				11/2/2008	11/8/2008	185		\$0.00
Medium	Work In Progress				11/2/2008 12:24:36 AM				

Nunez, Arturo
Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

40365	Main Building				11/30/2008	12/6/2008	157		\$0.00
Medium	Work In Progress				11/30/2008 12:23:29				

Nunez, Arturo
Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

PSFA View Only

40873	Main Building				12/15/2008		142		\$0.00
Medium	Work In Progress				12/15/2008 2:57:45 PM				

Castillo, Carlos
NEED A 115V ELEC. OUTLET INSTALLED ON CONFERENCE ROOM IN LIBRARY, FOR POWER POINT PROJECTOR.

Arturo Nunez

41042	Main Building				1/4/2009	1/10/2009	122		\$0.00
Medium	Work In Progress				1/4/2009 12:18:38 AM				

Nunez, Arturo
Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

41059					1/4/2009	1/12/2009	122		\$0.00
-------	--	--	--	--	----------	-----------	-----	--	--------

Medium	Work In Progress			1/4/2009 12:18:45 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.

Margret Villalobos

41154					1/5/2009		121		\$0.00
-------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress			1/5/2009 8:52:07 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Villalobos, David NEED SOME ASSISTANCE ON CHECKING MANHOLE BY GAS METER, ON EAST SIDE. METHANE GAS LEVEL READING IS A 8 , AS PER P.N.M. TECH. WOULD LIKE TO HAVE IT CHECKED OUT.

Arturo Nunez

41307	Dressing Rooms	Dressing Room			1/9/2009		117		\$0.00
-------	----------------	---------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress			1/9/2009 8:54:39 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Nunez, Arturo Boys athletic lockers need to be bolted down for safety reasons
This is the second request
Someone is going to get hurt with a falling bank of lockers

Art Nunez had previously submitted a work order and has spokent to someone at the GAC/Warehouse regarding this situation
1/15 - Route to Art asp Mike

Rosa Hood

41629					1/20/2009		106		\$0.00
-------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			1/20/2009 8:21:41 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe Remove equipment asp attached pictures and e-mail.

Michael Munoz

41699	Gymnasium	Hallway/Corridor			1/21/2009		105		\$0.00
-------	-----------	------------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			1/21/2009 2:21:21 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Prospero, Manuel Mr. Kelch has asked that we retile the hallway between the old and new gym. He spoke with Manuel Prospero about the tiles (they need to be the same color and pattern)
Thank you,
Rosa

5/4/09 - Asp Mike go ahead and replace tiles that are in need and use this wo.
Mr. Kelch has spoken wth Manny Prospero regarding tiles that need to be ordered and changed throughout the building
Thank you,
Rosa

Rosa Hood

41751	Annex Building	Classroom			1/22/2009		104		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress			1/22/2009 3:19:52 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo Anchor the serving set s to the ground and need to make a safety zone unger the servings
Thank you

License inspection 1-15-09
2/9 - Mailed to Art asp Mike

Rosa Hood

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

41752	Annex Building	Classroom			1/22/2009		104		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	DAYCARE			1/22/2009 3:21:49 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Nunez, Arturo
Replace all stained ceiling tiles
Thank you,
Rosa

License inspection 1-15-09

Rosa Hood

41753	Annex Building	Classroom			1/22/2009		104		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/22/2009 3:23:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Estrada, Jesus
Linolium in both bathrms need to be replaced and floor tiles at each exit need to be replace and any around the day care center
Thank you,
Rosa

License inspection 1-15-09

Rosa Hood

41929		Classroom			1/28/2009		98		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	MR.			1/28/2009 9:21:25 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Nunez, Arturo
NEED TO INSTALL PROJECTION TV-DIGITAL RECORDING SYSTEM-PROJECTION SCREEN-AND TIE IN HD DVD-MULTI CHANNEL AV RECEIVER-STEREO CASSETTE DECK-BBE PROCESSOR. PLEASE VISIT WITH MR. RIVERA ON THESE INSTALLATIONS.

Jimenez, Marylou

42057					2/1/2009	2/7/2009	94		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				2/1/2009 12:24:28 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo
Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

42485	Cafeteria (2005)				2/11/2009		84		\$0.00
-------	------------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/11/2009 2:17:51 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
need to send Horizon Mechanical to repair backlow preventer for irrigation, located next to cafetorium,

David Villalobos

42595	Main Building	Classroom			2/17/2009		78		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/17/2009 8:08:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Nunez, Arturo
Room 200 has a leak
The ceiling tile has already caved in
Thanks,
Rosa

Art and Prospero have been made aware according to teacher Ms. Rios on Friday
Thanks,
Rosa

Rosa Hood

42793	Main Building	Classroom			2/23/2009		72		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/23/2009 11:33:13 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Nunez, Arturo
Mr. Portillo's room needs door stops for bathroom and air freshner dispensers need to be mounted
Thank you,
Rosa

Rosa Hood

5/6/2009 11:28:11 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

42794	Main Building	Restroom (Girls)			2/23/2009		72		\$0.00
Medium	Work In Progress				2/23/2009 11:35:20 AM				

Nunez, Arturo
Air freshners need to be mounted in the women restroom in the main office
Next to Receptionist Ana Perez
Thank you,
Rosa

Rosa Hood

42795	Main Building	Restroom (Girls)			2/23/2009		72		\$0.00
Medium	Work In Progress				2/23/2009 11:36:51 AM				

Prospero, Manuel
All boys and girls restrooms need to be painted. They are now black and we need the natural color (white, beige, whatever you have in stock)
Thank you,
Rosa

This is a summer project.

Rosa Hood

42796	Main Building	Hallway/Corridor			2/23/2009		72		\$0.00
Medium	Work In Progress				2/23/2009 11:38:36 AM				

Nunez, Arturo
All entry ways, door frames, window frames need to be painted black per Mr. Kelch our principal
Mr. Munoz, Art Nunez, and Manuel Prospero are aware

Thank you,
Rosa

Rosa Hood

42807					2/23/2009		72		\$0.00
Medium	Work In Progress				2/23/2009 3:41:55 PM				

Castillo, Carlos
Arturo Nunez
NEED SIX (6) FNR-50 FUSES FOR KILN.

42811					2/23/2009		72		\$0.00
Medium	Work In Progress				2/23/2009 3:48:44 PM				

Lara, Ralph
NEED A DOOR CLOSER FOR NURSES STATION PORTABLE.

Arturo Nunez

42839	Main Building	Classroom			2/24/2009		71		\$0.00
Medium	Work In Progress				2/24/2009 1:42:45 PM				

Nunez, Arturo
ceiling tiles need to be replace in room 200 Ms. Rios

Thanks,
Rosa

Rosa Hood

42841	Main Building	Classroom			2/24/2009		71		\$0.00
Medium	Work In Progress				2/24/2009 1:47:07 PM				

Nunez, Arturo
Ms McConnell a few tiles need to be replaced
Thanks,
Rosa

Rosa Hood

5/6/2009 11:28:11 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

42843	Main Building	Office			2/24/2009		71		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/24/2009 1:52:40 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo
Leak in counseling office and rusted vents need to be replaced
Thank you,
Rosa

Rosa Hood

42844	Main Building	Office			2/24/2009		71		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/24/2009 1:53:40 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo
Counseling offices and lobby area need to be painted
Thank you,
Rosa

Rosa Hood

42845	Main Building	Office			2/24/2009		71		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/24/2009 1:54:50 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos
Counseling offices need more outlets
Thank you,
Rosa

Rosa Hood

42846	Main Building	Office			2/24/2009		71	1	\$25.00
-------	---------------	--------	--	--	-----------	--	----	---	---------

Medium	Work In Progress			2/24/2009 1:56:20 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Estrada, Jesus
Counseling Center needs carpet replaced in lobby and in offices. (dirty and safety issue)
Thanks,
Rosa

2/26/08 NO TEAR OR STAIN, ON HOLD AS PER CHUY

Rosa Hood

42874	Applied Science	Classroom			2/24/2009		71		\$0.00
-------	-----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/24/2009 6:02:00 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo
L 1 needs some ceiling tiles replaced
Thank you,
Rosa

Rosa Hood

42875	Applied Science	Classroom			2/24/2009		71		\$0.00
-------	-----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/24/2009 6:03:23 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo
L1 needs screens on windows replaced
Ms McKnight
Thanks,
Rosa

Rosa Hood

42900		Classroom			2/25/2009		70		\$0.00
-------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	MR. RAY/ROOM		2/25/2009 9:12:29 AM					
--------	------------------	--------------	--	----------------------	--	--	--	--	--

Nunez, Arturo
PLEASE REPLACE TV IN MY ROOM. MARYLOU HAS TV'S AVAILABLE.

Marylou Jimenez

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

42902	Applied Science	Classroom			2/25/2009		70		\$0.00
Medium	Work In Progress				2/25/2009 9:27:31 AM				
Nunez, Arturo		Room 14	molding around desk needs to be glued						
Rosa Hood									
42905	Main Building	Classroom			2/25/2009		70		\$0.00
Medium	Work In Progress				2/25/2009 9:42:00 AM				
Nunez, Arturo		Room 308	needs to be painted during Spring Break or Summer schedule						
Rosa Hood									
42906	Main Building	Restroom (Girls)			2/25/2009		70		\$0.00
Medium	Work In Progress				2/25/2009 9:57:52 AM				
Nunez, Arturo		Handcap bathroom in 300 hall	needs to be tightend						
Rosa Hood									
42916					2/25/2009		70		\$0.00
Medium	Work In Progress				2/25/2009 11:26:08 AM				
Murillo, Luis		Shampoo and extract carpet in lobby and offices in counseling center. To be done in week of March 23-27. (Assign to L. Murillo)				4/20/09- REQUESTED STATUS FROM LUIS.			
Jesus Estrada									
42922					2/25/2009		70		\$0.00
Medium	Work In Progress				2/25/2009 11:30:45 AM				
Carrasco, Danny		Danny need to conduct inventory of all Building Mechanic tools and equipment. Ask Ruben for present inventory list to match up.							
Michael Munoz									
42984	Main Building	Classroom			2/26/2009		69		\$0.00
Medium	Work In Progress				2/26/2009 2:25:07 PM				
Lara, Ralph		213	needs locks replaced on cabinets to secure materials						
Rosa Hood									
43023	Main Building	Classroom			2/27/2009		68		\$0.00
Medium	Work In Progress				2/27/2009 9:11:22 AM				
Nunez, Arturo		I really do not know who this goes to... we are donating four Art racks to different schools we need them moved to those shcools Desert View E (2) and STMS (2) Thank you, Rosa							
Rosa Hood									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

43037	Main Building	Restroom (Girls)			2/27/2009		68		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/27/2009 12:59:16 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lara, Ralph
Office bathrooms men and women
Hallway mens need to be keyed so that only faculty can
use
Hallway womens is already keyed
Thank you,
Rosa

Rosa Hood

43038	Main Building	Hallway/Corridor			2/27/2009		68		\$0.00
-------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/27/2009 1:01:01 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ronquillo, Ruben
Fire ex glass is broken
New hallway near bookroom

Rosa Hood

43040	Main Building	Classroom			2/27/2009		32		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/27/2009 2:14:19 PM	3/31/2009				
--------	------------------	--	--	----------------------	-----------	--	--	--	--

Prospero, Manuel
Tiles need to be repalced room 200
Thank you,
Rosa

Rosa Hood

43090					3/1/2009	3/7/2009	66		\$0.00
-------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress			3/1/2009 12:22:51 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo
Monthly - Santa Teresa HS Monthly FE Inspection -
Refer to PM schedule details.

Margret Villalobos

43128					3/1/2009	3/22/2009	66		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress			3/1/2009 12:23:04 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Orozco, Danny
Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer
to PM schedule details.

Margret Villalobos

43252	Main Building	Hallway/Corridor			3/3/2009		64		\$0.00
-------	---------------	------------------	--	--	----------	--	----	--	--------

Medium	Work In Progress			3/3/2009 8:07:26 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Lara, Ralph
Mr. Kelch would like the rooms re-numbered for next
school year (summer project)
Thank you,
Rosa

Rosa Hood

43287	Main Building	Classroom			3/4/2009		63		\$0.00
-------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress			3/4/2009 8:11:16 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Castillo, Carlos
The kiln in the Art room is not working again...may be a
problem with electrical outlet or breaker
Thank you,
Rosa

Rosa Hood

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

43289	Main Building	Classroom			3/4/2009		63		\$0.00
-------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/4/2009 8:14:25 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Nunez, Arturo
Two roof leaks need to be fixed
6 ceiling tiles need to be replaced

Rosa Hood

43303		Athletic Field			3/4/2009		63		\$0.00
-------	--	----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/4/2009 10:45:39 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
Mr. Dodson needs the batting cage returnedHe spoke with Mr. Valdez ...it was picked up for repairs and it has not been returned

Thank you,
Rosa

Rosa Hood

43455	Main Building	Office			3/7/2009		60		\$0.00
-------	---------------	--------	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/7/2009 2:05:14 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Nunez, Arturo
Replace two stained ceiling tiles and paint air conditioner covers/grates...they are rusty

Thank you,
Administration

Rosa Hood

43513	Annex Building	Restroom (Girls)			3/9/2009		58		\$0.00
-------	----------------	------------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/9/2009 3:38:59 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
DEAD BOLT FROM GIRLS BATHROOM DOOR IS BROKEN / WILL NOT LOCK NEEDS TO BE REPLACE
THANK YOU.

Luis Murillo

43604	Vocational	Classroom			3/11/2009		56		\$0.00
-------	------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2009 2:15:40 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
The old band room ... needs electrical checked out for new kilns and art studio

Mr. Joseph Angelo
Ms Turner or Mr. Lowrance
Thank you,
Rosa

Rosa Hood

43605	Vocational	Classroom			3/11/2009		56		\$0.00
-------	------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2009 2:17:04 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Need sink from Art room removed and placed in new art studio (old band room)

Mr. Angelo, Ms Turner , Mr Lowrance

Rosa Hood

43720					3/15/2009		52		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/15/2009 12:19:49 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
Monthly - Santa Teresa HS Soil Sampling - Refer to PM schedule details.

Margret Villalobos

5/6/2009 11:28:12 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

43728	Applied Science	Hallway/Corridor			3/16/2009		51		\$0.00
-------	-----------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/16/2009 8:41:48 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo
Summer Project - removal of remaining locker banks
Thanks,
Rosa

Rosa Hood

43748					3/16/2009		51		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/16/2009 3:22:36 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos
SHUT OFF POWER FOR DEMO IN OLD VOCATIONAL BUILDING (HOME ECONOMICS ROOM). PLEASE CONTACT MIKE MUNOZ OR ROSA HOOD IF ANY QUESTIONS.

Michael Munoz

43749					3/16/2009		51		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/16/2009 3:25:14 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David
SHUT OFF GAS AND WATER FOR DEMO IN OLD VOCATIONAL BUILDING (HOME ECONOMICS ROOM). PLEASE CONTACT MIKE MUNOZ OR ROSA HOOD IF ANY QUESTIONS.

Michael Munoz

43779	Main Building	Custodial			3/17/2009		50		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/17/2009 8:28:56 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo
Move washer and dryer from old home economics room to custodial room (remove broken washer and dryer and replace with the ones in the home ec room)
Thank you,
Rosa

Rosa Hood

43799	Main Building	Office			3/17/2009		50		\$0.00
-------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/17/2009 3:27:43 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph
We need a new lock and key for storage room near the counseling center that will now be an office for Jason Barela TRIO from New Mexico
Thank you,
Rosa

Rosa Hood

43835	Vocational	Classroom			3/18/2009		49		\$0.00
-------	------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/18/2009 11:28:57 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Lara, Ralph
Work order 43730 to go along with this we need 7 doorsets replaced per Rafa and Mr. Buckley for the Voc Ed building
Thank you,
Rosa

Rosa Hood

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

44091					3/31/2009		36		\$0.00
Medium	Work In Progress			3/31/2009 12:22:49 AM					
Prospero, Manuel	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								
Margret Villalobos									
44295					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:33 AM					
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
Margret Villalobos									
44296					4/5/2009	4/11/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:35 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
44297					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:36 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
44298					4/5/2009	4/21/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:36 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
Margret Villalobos									
44331					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:47 AM					
Orozco, Danny	Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
44405					4/5/2009	5/6/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:23:12 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
44408					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:23:13 AM					
Prospero, Manuel	Monthly - Santa Teresa HS C-12 Chm Feeder Semimly - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

44446	Gymnasium	Gym			4/6/2009		30		\$0.00
-------	-----------	-----	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/6/2009 10:24:59 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
MR. CARLOS CASTILLO LIGHT SWITCH NEEDS TO BE REPLACE / LIGHTS WILL NOT TURN OFF BY DRESSING ROOM THANK YOU.

Luis Murillo

44457	Main Building	Hallway/Corridor			4/6/2009		30		\$0.00
-------	---------------	------------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/6/2009 1:16:21 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ronquillo, Ruben
Art Nunez ordered 15 cases of cove base so that the old one can be replaced after we paint the halls and classrooms
Thank you,
Rosa

Rosa Hood

44482	Main Building	Hallway/Corridor			4/6/2009		30		\$0.00
-------	---------------	------------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/6/2009 3:54:50 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
The door in the counseling hallway is coming unhinged...dangerous. It is the left door as you go out

Thank you

Rosa Hood

44483	Main Building	Hallway/Corridor			4/6/2009		30		\$0.00
-------	---------------	------------------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/6/2009 3:56:18 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Nunez, Arturo
Mr. Kelch would like the main lobby repainted. Art Nunez knows what Mr. Kelch needs done. This is a project that we need done this summer
Thank you

Rosa Hood

44541	Main Building	Classroom			4/8/2009		28		\$0.00
-------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/8/2009 10:27:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Prospero, Manuel
New classrom 200 has a roof leak
Thank you

Rosa Hood

44542	Main Building	Classroom			4/8/2009		28		\$0.00
-------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/8/2009 10:30:22 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
The door needs a new lock the entire tumbler is missing
Room 613 Kitchen for nutrition class
Security issue
Thank you

Rosa Hood

44647					4/12/2009	4/28/2009	24		\$0.00
-------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				4/12/2009 12:21:27 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Nunez, Arturo
Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.

Margret Villalobos

5/6/2009 11:28:12 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

44801	Vocational	Classroom			4/17/2009		19		\$0.00
Medium	Work In Progress				4/17/2009 3:24:40 PM				

Villalobos, David
Need to have the natural gas line attached to the heat treatment furnace and test operation per Mr Angelo in the welding area
Thank you

Rosa Hood

44803					4/17/2009		19		\$0.00
Medium	Work In Progress				4/17/2009 3:46:41 PM				

Ambriz, Jose
NEED SOME ASSISTANCE ON LIBRARY A.H.U. WATER VALVE FOR COOLING MODE IS NOT WORKING PROPERLY, UNIT GOES FROM ONE EXTREME TO AN OTHER,. UNIT HAS TO BE CONTROLLED MANUALLY.

Arturo Nunez

44922	Vocational	Classroom			4/22/2009		14		\$0.00
Medium	Work In Progress				4/22/2009 12:39:10 PM				

Nunez, Arturo
We need the fence fabric stretched and attached to the post at the fenced storage area at the voc building
Nunez/Angelo
Thanks,
Rosa

Rosa Hood

44924	Gymnasium	Gym			4/22/2009		14		\$0.00
Medium	Work In Progress				4/22/2009 1:08:34 PM				

Lara, Ralph
Per Mr. Gallegos the new gym male and female lobby bathrooms (4 in total) need dead bolt locks installed asap
Thank you,
Rosa

Rosa Hood

44925	Annex Building	Classroom			4/22/2009		14		\$0.00
Medium	Work In Progress				4/22/2009 1:10:12 PM				

Nunez, Arturo
Rosie Gonzalez ask that the air conditioners be turned on in the daycare center
Thank you

Rosa Hood

44939					4/22/2009		14		\$0.00
Medium	Work In Progress				4/22/2009 3:47:58 PM				

Ambriz, Jose
4/22/09. WE NEED TO CHENGE CONDANCER FAN MOTOR ON ROOM 10. THA INFORMATION IS:
MOD.5KCP39HG K896AS. HP. 1/5 RPM 840 V. 208-230 HZ 60 AMPS1.20 ROT 1 PH. CAP500/370 EQUIP.MFRS.#37VL233B. THIS QORK ORDER IS FOR JOSE AMBIZ.

Manuel Prospero

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

45039	Dressing Rooms	Dressing Room			4/27/2009		9		\$0.00
-------	----------------	---------------	--	--	-----------	--	---	--	--------

Medium	Work In Progress			4/27/2009 12:53:09 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Castillo, Carlos
The light switch in the boys PE dressing room will not turn off/it has been like this for a month. Mr. Meraz and Mr. Munoz have tried to shut it off however it will not go off
Thanks

Rosa Hood

45101		Classroom			4/28/2009		8		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Science and Lang		4/28/2009 1:26:21 PM					
--------	------------------	------------------	--	----------------------	--	--	--	--	--

Nunez, Arturo
Please set up furniture that was delivered on 4/16 for computers in the Science and Language Arts classrooms. Thank you.

Sandra Almeraz

45134		Classroom			4/29/2009		7		\$0.00
-------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress			4/29/2009 7:56:28 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ambriz, Jose
THE A/C ON ROOM 7 IS ON BAD CONDITION, WE NEED TO CHANGED FOR 6800AEROCOOL 8" PMT D/D

Manuel Prospero

45145					4/29/2009		7		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			4/29/2009 11:35:36 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Murillo, Luis
LUIS, PLEASE CHANGE THE STANDARD TOILET PAPAER DISPENSERS IN THE NEW GYM ADDITION TO JUMBO. ORDER THRU INVENTORY DIRECT IF NEEDED. THANKS

Jesus Estrada

45183	Gymnasium	Gym			4/29/2009		7		\$0.00
-------	-----------	-----	--	--	-----------	--	---	--	--------

Medium	Work In Progress			4/29/2009 7:59:48 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Nunez, Arturo
Mr. Munoz our trainer needs the ice machine and the whirlpool from the old training room moved to the new training room

Thank you

Rosa Hood

45187					4/30/2009	5/31/2009	6		\$0.00
-------	--	--	--	--	-----------	-----------	---	--	--------

Medium	Work In Progress			4/30/2009 12:21:32 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Nunez, Arturo
Yearly - Santa Teresa HS C-11 Evap Coolers Yearly - Refer to PM schedule details.

Margret Villalobos

45213					4/30/2009		6		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			4/30/2009 2:19:16 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph
PLEASE FIXED CAFETERIAS PANICBARS AND ADJUSTED DOORS THANK YOU.

Manuel Prospero

5/6/2009 11:28:12 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

45214					4/30/2009		6		\$0.00
Medium	Work In Progress				4/30/2009 2:25:24 PM				
Lara, Ralph	rAFA PLEASE FIXED R.O.T.C. BUILDING DOORS .ALSO IN RESTROOMS YOU NEED TO INSTALL A CORE CYINDER.								
<u>Manuel Prospero</u>									
45217		Parking Lot			4/30/2009		6		\$0.00
Medium	Work In Progress				4/30/2009 3:13:30 PM				
Castillo, Carlos	Guard House - Provide a generator to provide temporary power to the AC on the Guard house. Please complete by 5 -04-09								
<u>Alfredo Holguin</u>									
45263					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:28 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45313					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:46 AM				
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45314					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:47 AM				
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45315					5/3/2009	6/3/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:47 AM				
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45345	Main Building	Computer Lab			5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 12:06:57 PM				
Castillo, Carlos	Reading 180 lab needs to be moved to room 205 Computers, etc I spoke with Ms. Trujillo and Ann Steinhoff about moving the lab form Math hall to 205 for 9th grade academy Thank you,								
<u>Rosa Hood</u>									
45346	Main Building	Hallway/Corridor			5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 12:08:02 PM				
Prospero, Manuel	Removal of locker bank in Science Wing this summer Thank you, Rosa								
<u>Rosa Hood</u>									

5/6/2009 11:28:12 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

45347	Main Building	Hallway/Corridor			5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 12:09:08 PM				

Nunez, Arturo
Painting of all hallways, doors, frames, etc during the summer

Rosa Hood

45348	Main Building	Hallway/Corridor			5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 12:10:26 PM				

Prospero, Manuel
Paint over mural on wall per Mr. Kelch
Mr. Munoz asked that I submit a work order for each job

Rosa Hood

45349	Main Building	Hallway/Corridor			5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 12:11:54 PM				

Nunez, Arturo
Repaint lobby area per Mr. Kelch (Art is aware of how it needs to be painted...stripes)

Rosa Hood

45350	Main Building	Office			5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 12:13:48 PM				

Villalobos, Margret
Mr. Kelch wants part of a non load bearing wall to be taken down in the attendance office...see Mr. Kelch or Mrs. Hood for particulars
Thanks

Rosa Hood

45351	Main Building	Classroom			5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 12:16:55 PM				

Nunez, Arturo
Paint all classrooms

Rosa Hood

45352	Main Building	Classroom			5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 12:18:31 PM				

Nunez, Arturo
Replacement of ceiling tiles that still have not been replaced (broken, steined)
Mr. Munoz asked I submit all projects that still need attention
Thanks

Rosa Hood

45353	Vocational	Classroom			5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 1:05:57 PM				

Nunez, Arturo
Mr. Jewett the surface planner is not working in woodshop class

Rosa Hood

45418					5/5/2009		1		\$0.00
Medium	Work In Progress				5/5/2009 2:01:50 PM				

Villalobos, David
WE NEED ASSISTANCE ON BROKEN COPPER WATER LINE ON ROOF TOP (DAY CARE AREA).

Manuel Prospero

Count: 123 Work Orders			Avg. Age of WO's	81		Total for Santa Teresa HS	1		\$25.00
-------------------------------	--	--	-------------------------	-----------	--	----------------------------------	----------	--	----------------

5/6/2009 11:28:12 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

36170	North Building	Custodial			7/24/2008		286		\$0.00
Medium	Work In Progress				7/24/2008 7:42:22 AM				
Gonzales, Angel		pete,the truck 39 needs a complete tune up i need to have it ready for the school year.thank you.							
Ismael Rodriguez									
36903	North Building	Classroom			8/11/2008		268		\$0.00
Medium	Work In Progress	Room 3A			8/11/2008 3:12:40 PM				
Mijarez, Jaime		1. Portable leaks when it rains.							
Laura Parra									
37603					8/31/2008	9/6/2008	248		\$0.00
Medium	Work In Progress				8/31/2008 12:25:31 AM				
Mijarez, Jaime		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
38535					9/30/2008		218		\$0.00
Medium	Work In Progress				9/30/2008 12:26:01 AM				
Mijarez, Jaime		Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.							
Margret Villalobos									
38596					10/1/2008		217		\$0.00
Medium	Work In Progress				10/1/2008 12:33:20 PM				
Soria, Mike		CUT WEEDS AT NEW LANDSCAPING IN FRONT OF SOUTH BUILDING.							
Michael Munoz									
38597					10/1/2008		217		\$0.00
Medium	Work In Progress				10/1/2008 12:34:21 PM				
Soria, Mike		OPEN DRAIN BY MORGAN BUILDING. CUT WEEDS AND BARRICADE. SAFETY HAZARD.							
Michael Munoz									
38869					10/5/2008	11/5/2008	213		\$0.00
Medium	Work In Progress				10/5/2008 12:24:36 AM				
Mijarez, Jaime		Yearly - Santa Teresa MS U2 (Heat Gas)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
39406					10/23/2008		195		\$0.00
Medium	Work In Progress				10/23/2008 7:58:22 AM				
Castillo, Carlos		See if we can repair the timers and order additional triggers. (see Jaime if you have any questions).							
Michael Munoz									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

40169					11/18/2008		169		\$1,400.00
-------	--	--	--	--	------------	--	-----	--	------------

Medium	Work In Progress				11/18/2008 9:33:58 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ronquillo, Ruben
N.bldg office exterior windows. Replace 2nd glass window with new aluminum molding. Existing molding is to corroded. Replace aluminum molding around glass window that was replaced for W/O #39295. I checked molding around window and it is too damaged.

Jaime Mijarez

40475	South Building	Choral			12/2/2008		155		\$0.00
-------	----------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Outside Choir			12/2/2008 8:05:57 AM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Gonzalez, Salvador
Replace the old worn out gate behind the south building and relocate by the corner of the south building with a new one. (A safety measure)

Laura Parra

40476	North Building	Portables			12/2/2008		155		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Outside by			12/2/2008 8:09:53 AM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Gonzalez, Salvador
North building by the portable-- Place a gate by the portables so we could keep people from driving their cars around the north building to get to the gym. (A SAFETY MEASURE)

Laura Parra

41024					12/31/2008		126		\$0.00
-------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				12/31/2008 12:18:22				
--------	------------------	--	--	--	---------------------	--	--	--	--

Mijarez, Jaime
Yearly - Santa Teresa MS H6(Roof Furnace)(Yearly) - Refer to PM schedule details.

Margret Villalobos

41216	South Building				1/6/2009		120		\$0.00
-------	----------------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				1/6/2009 4:25:30 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Soria, Mike
please cut weeds in culvert by ground morgan bldg.

Michael Munoz

41632	North Building	Custodial			1/20/2009		106		\$0.00
-------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/20/2009 8:39:52 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzales, Angel
pete, the truck 39 needs the the oil change i will be taking it in during this week thank you.

Ismael Rodriguez

42477					2/11/2009		84		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Grounds Truck			2/11/2009 9:23:05 AM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Gonzales, Angel
Need to repair door to truck #17 Mike Soria.

Mike Soria

42478	South Building	Mechanical Room			2/11/2009		84		\$0.00
-------	----------------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/11/2009 9:25:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
Mike Soria
Need to repair irrigation valve in Mechanical Room. 2/17/09 - Grounds works w/irrigation they need to repair their valves. D. Villalobos

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

42923					2/25/2009		70		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/25/2009 11:32:07 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Carrasco, Danny
 Danny need to conduct inventory of all Building
 Mechanic tools and equipment. Ask Ruben for present
 inventory list to match up.

Michael Munoz

43020	Gym (1997)	Athletic Field			2/27/2009		0		\$0.00
-------	------------	----------------	--	--	-----------	--	---	--	--------

High	Work In Progress			2/27/2009 8:40:07 AM	2/27/2009				
------	------------------	--	--	----------------------	-----------	--	--	--	--

Soria, Mike
 Replace sprinklers that are not working at playing fields.

Guadalupe Ontiveros

43035					2/27/2009		68		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			2/27/2009 12:41:47 PM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Estrada, Jesus
 North bldg Requested by Philip Dorantes. Special Ed
 room needs new carpeting due to the constant wear and
 tear of daily activity, and also due to the foul odor of the
 constant urination of the students with severe
 disabilities. The odor has been very noticeable to visiting
 teachers and administration visits for observation.
 (5/2/08 Asp Jaime still pending)

Jaime Mijarez

43167					3/1/2009		66		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			3/1/2009 12:23:18 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Mijarez, Jaime
 Yearly - Santa Teresa MS A10 (Heat Pump)(Yearly) -
 Refer to PM schedule details.

Margret Villalobos

43254		Gym			3/3/2009		64		\$0.00
-------	--	-----	--	--	----------	--	----	--	--------

Medium	Work In Progress			3/3/2009 8:26:41 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Soria, Mike
 Replace broken hot box to protect reduce pressure
 assembly.

Guadalupe Ontiveros

43259	North Building	Mechanical Room			3/3/2009		64		\$0.00
-------	----------------	-----------------	--	--	----------	--	----	--	--------

Medium	Work In Progress			3/3/2009 11:19:45 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Villalobos, David
 NEED TO REPLACE PRESSURE REDUCING VALVE
 AT NORTH BUILDING MECHANICAL ROOM Summer Project

David Villalobos

43647	South Building	Classroom			3/12/2009		55		\$0.00
-------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	ROOM 34		3/12/2009 10:32:20 AM					
--------	------------------	---------	--	-----------------------	--	--	--	--	--

Lara, Ralph
 KEY IS STUCK IN KEY HOLE. CYLINDER NEEDS TO
 BE REPLACED.

Laura Parra

43842	Gym (1997)	Athletic Field			3/18/2009		49		\$0.00
-------	------------	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/18/2009 1:02:19 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Aldaz, Bobby
 Remove stock piles of dirt and transport to sths.

Guadalupe Ontiveros

5/6/2009 11:28:12 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

44084					3/31/2009		36		\$0.00
Medium	Work In Progress				3/31/2009 12:22:46 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.								
Margret Villalobos									
44152	South Building	Custodial			4/1/2009		35		\$0.00
Medium	Work In Progress				4/1/2009 8:43:23 AM				
Ontiveros, Guadalupe	can we borrow the small tractor that is in riverside to remove sand along the sidewalk in the south building will help mr. soria.mr. rodriguez								
Ismael Rodriguez									
44207	North Building	Portables			4/2/2009		34		\$0.00
Medium	Work In Progress				4/2/2009 7:28:55 AM				
Soria, Mike	fix the fence door to the exit parking lot and remove sand from portables.mr. soria and mr.rodriguez completed this work order.								
Ismael Rodriguez									
44332					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:22:48 AM				
Orozco, Danny	Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
44380					4/5/2009	4/11/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:04 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
44382					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:04 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
44383					4/5/2009	4/21/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:05 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS A1(Wall Refr.E/H)(Semi) - Refer to PM schedule details.								
Margret Villalobos									
44384					4/5/2009	4/13/2009	31		\$0.00
Medium	Work In Progress				4/5/2009 12:23:05 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

44693					4/15/2009		21		\$0.00
Medium	Work In Progress				4/15/2009 7:48:38 AM				
Castillo, Carlos	S.bldg lobby. Need to install a GFI recepticle with a safety cover. Power from the exiting recepticle is being used for social workers office in lobby. I will be setting up a spiral water fountain and will be connected to the GFI.								
Jaime Mijarez									
44746		Cafeteria			4/16/2009		20		\$0.00
Medium	Work In Progress				4/16/2009 1:30:37 PM				
Moncayo, Fernando	Mop room moulding is very bad and water is leaking through the wall from the bathroom.		Regenerated from Work Order 21548						
	Paula Sanchez - SNP Manager - 589-9836								
Alma Terrell									
44747		Cafeteria			4/16/2009		20		\$0.00
Medium	Work In Progress				4/16/2009 1:33:14 PM				
Moncayo, Fernando	Dry storage door hinges are loose, wood is broken to door frame, the existing screws will not stay screwed into the door frame.		Regerated from work order 22340						
	PAULA SANCHEZ - SNP MANAGER 589-9836								
Alma Terrell									
44748		Cafeteria			4/16/2009		20		\$0.00
Medium	Work In Progress				4/16/2009 1:34:33 PM				
Moncayo, Fernando	WEATHER STRIPS TO THE BACK DOOR TO THE CAFETERIA NEEDS TO BE REPLACED, ALOT OF DIRT COMES IN THROUGH THESE DOORS.		Regenerated from work order 22343						
	PAULA SANCHEZ - SNP MANAGER 589-9836								
Alma Terrell									
44891		Athletic Field			4/21/2009		15		\$0.00
Medium	Work In Progress				4/21/2009 3:56:56 PM				
Aldaz, Bobby	Battery for Gator has to be replaced not holding charge.								
Guadalupe Ontiveros									
44948					4/23/2009		13		\$0.00
Medium	Work In Progress				4/23/2009 8:19:59 AM				
Carbajal, Jimmy	NEED TO PICK UP ALL TARPS FROM GADSDEN HIGH AND DELLIVER TO SANTA TERESA MIDDLE BEFORE APRIL 29. ON MAY 6 OR AFTER, AGAIN NEED TO PICK UP FROM STM AND RETURN TO GH.								
Jesus Estrada									
44956	Gym (1997)				4/23/2009		13		\$0.00
Medium	Work In Progress				4/23/2009 9:45:24 AM				
Castillo, Carlos	Please assist Jaime w/installation of lighting for the Cino De Mayo Festival. Needs to be done before April 30th.								
Michael Munoz									

5/6/2009 11:28:12 AM

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

44958	Gym (1997)				4/23/2009		13		\$0.00
-------	------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			4/23/2009 9:50:39 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Mijarez, Jaime Pickup stage on 4/29 from STHS (Ismael R., Art, Manuel) will assist to load and set-up at STMS gym for Cinco De Mayo Festival.

Michael Munoz

45080					4/28/2009		8		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			4/28/2009 8:13:43 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Carrasco, Danny I am going to need a trailer to pick up the 12 pieces of stage from STHS.

Jaime Mijarez

45106	Classroom				4/28/2009		8		\$0.00
-------	-----------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Science and		4/28/2009 2:03:29 PM					
--------	------------------	-------------	--	----------------------	--	--	--	--	--

Mijarez, Jaime Please set up furniture for computers, furniture will be delivered on May 8. Set up in the Science and Language Arts classrooms. Thank you!

Sandra Almeraz

45129	Gym (1997)	Custodial			4/29/2009		7		\$0.00
-------	------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress			4/29/2009 7:27:06 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe lupe, i will be needing a trailer from 4-29-09 to 5-6-09 reason cinco de mayo concert to move certain things and also for the art show.

Ismael Rodriguez

45142	South Building	Classroom			4/29/2009		7		\$0.00
-------	----------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Room 46		4/29/2009 9:55:29 AM					
--------	------------------	---------	--	----------------------	--	--	--	--	--

Lara, Ralph Ms Medrano needs lock for cabinet

Laura Parra

45206	North Building	Custodial			4/30/2009		6		\$0.00
-------	----------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress			4/30/2009 8:06:37 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph rafa, i need a peace of chain to secure the latter thats in the school vechile and a lock.

Ismael Rodriguez

45240	North Building				5/1/2009		5		\$0.00
-------	----------------	--	--	--	----------	--	---	--	--------

Medium	Work In Progress			5/1/2009 9:33:53 AM					
--------	------------------	--	--	---------------------	--	--	--	--	--

Ambriz, Jose N.bldg upper level mechanical room. We need a vent duct with register like the one you installed in the lower level mechanical room on the heat pump.

Jaime Mijarez

45299					5/3/2009	6/3/2009	3		\$0.00
-------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress			5/3/2009 12:22:41 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Mijarez, Jaime Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

45300					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:42 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
45301					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:42 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45302					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:42 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45342	North Building	Parking Lot			5/4/2009		2		\$0.00
Medium	Work In Progress			5/4/2009 7:41:55 AM					
Soria, Mike	mr.soria we need for you to have ready the parking lot behind the cafeteria swept and clean for the teacher luncheon on may 8 09 custodians will assit on this work order.								
Ismael Rodriguez									
45421	Gym (1997)				5/5/2009		1		\$0.00
Medium	Work In Progress			5/5/2009 2:27:03 PM					
Lara, Ralph	Need new door in gym.								
Danny Miranda									
Count: 52 Work Orders			Avg. Age of WO's 72			Total for Santa Teresa MS	0	\$1,400.00	

Location: Sunland Park ES

38310					9/22/2008		226		\$0.00
Medium	Work In Progress	outside		9/22/2008 2:14:13 PM					
Herrera, Joel	Please replace broken tiles located by the main entrance.								
Jessica Lopez									
37362					8/25/2008		254		\$0.00
Medium	Work In Progress			8/25/2008 2:14:46 PM					
Lara, Ralph	WE NEED REPLACE CLASS ROOMS DOORS THEY ARE TO RUSTING								
Joel Herrera									
38801					10/5/2008	10/26/2008	213		\$0.00
Medium	Work In Progress			10/5/2008 12:24:11 AM					
Orozco, Danny	Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

38958					10/6/2008		212	1	\$25.00
Medium	Work In Progress	library			10/6/2008 12:29:14 PM				
Herrera, Joel		Attach electrical strip to new computer cart.				10/24 -NON ELECTRICAL, NEED BM TO OBTAIN A POWER SURGE STRIP AND INSTALL HIMSELF. C. CASTILLO.			
Jessica Lopez						Route to Joel 11/3/08			

39888					11/6/2008		181		\$0.00
Medium	Work In Progress				11/6/2008 8:12:18 AM				
Gonzalez, Salvador		WE NEED REPLACE CONCRET WALL AND STEEL GATE AT OUTSIDE AREA							

41299		Cafeteria			1/8/2009		118		\$0.00
Medium	Work In Progress				1/8/2009 4:08:12 PM				
Moncayo, Fernando		Dishwasher is down - System corroded - Not working at all							
		Marina Ramirez - SNP Manager 589-2545							

41300		Cafeteria			1/8/2009		118		\$0.00
Medium	Work In Progress				1/8/2009 4:09:11 PM				
Moncayo, Fernando		Hobart Mixer - Dropping oil and making a grinding sound							
		Marina Ramirez - SNP Manager 589-2545							

42161		Cafeteria			2/2/2009		93		\$0.00
Medium	Work In Progress				2/2/2009 4:00:22 PM				
Moncayo, Fernando		2-compartment Veg. Sink is leaking.							
		Marina Ramirez SNP Mgr 589-2545							

42235					2/4/2009		91		\$0.00
Medium	Work In Progress				2/4/2009 3:26:24 PM				
Lara, Ralph		WE NEED TO SECURED MALLEN ON SOUTH SIDE EXIT DOOR'S A.S.P THANK YOU RAFA							

42540		Cafeteria			2/12/2009		83		\$0.00
Medium	Work In Progress				2/12/2009 3:51:46 PM				
Moncayo, Fernando		RECEIVED CALL AT 3:50 PM (HOBART MIXER IS NOT WORKING AT ALL - FERNANDO WENT OVER TODAY TO PUT OIL IN MACHINE AND MARINA SAYS THAT THE MACHINE DOES NOT WORK ANYMORE)							
		MARINA RAMIREZ - SNP MANAGER 589-2545							

Alma Terrell

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Sunland Park ES

43015					2/27/2009		68		\$0.00
Medium	Work In Progress				2/27/2009 7:58:21 AM				
Herrera, Joel	I NEED PAINT TO PAINTING G.Y.M AREA AND I NEED PAINT TO PAINTING OUTSIDE CONCRET WALL								
Joel Herrera									
43028					2/27/2009		68		\$0.00
Medium	Work In Progress				2/27/2009 10:18:35 AM				
Herrera, Joel	TILES ON THE FRONT ENTRANCE - MANY ARE BROKEN AND NEED REPLACEMENT.								
Irene Trujillo									
43029					2/27/2009		68		\$0.00
Medium	Work In Progress				2/27/2009 10:19:54 AM				
Herrera, Joel	THE PLANTERS ON THE FRONT ENTRANCE NEED TO BE PAINTED.								
Irene Trujillo									
43030	Main Building				2/27/2009		68		\$0.00
Medium	Work In Progress				2/27/2009 10:22:10 AM				
Herrera, Joel	2nd request - Tile in nurse's office is not level. Safety hazard concern, as student/staff may possibly trip and be injured.								
Irene Trujillo									
43240					3/2/2009		65		\$0.00
Medium	Work In Progress				3/2/2009 3:42:53 PM				
Gonzalez, Salvador	WE NEED WELD FLAG POST'S HANGER AT MAIN ENTRANCE POSTS								
Joel Herrera									
43317					3/4/2009		63		\$0.00
Medium	Work In Progress				3/4/2009 2:00:31 PM				
Villalobos, David	WE HAVE SINK'S WATER LEACK AT CLASS ROOM #32								
Joel Herrera									
43677	Main Building	Auditorium			3/13/2009		54		\$0.00
Medium	Work In Progress				3/13/2009 8:25:37 AM				
Herrera, Joel	Seal gap between clear story windows and cinderblock wall on south side above stage.								
Alfredo Holguin									
43826					3/18/2009		49		\$0.00
Medium	Work In Progress				3/18/2009 10:56:15 AM				
Herrera, Joel	Mr. Herrera please paint outside portables. 4th year request								
Jessica Lopez									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

43827					3/18/2009		49		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/18/2009 10:57:41 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Herrera, Joel		MR. HERRERA PLEASE PAINT ALL CLASSROOM DOORS. 2ND YEAR REQUEST							
---------------	--	---	--	--	--	--	--	--	--

Jessica Lopez

43828					3/18/2009		49		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/18/2009 11:04:03 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Herrera, Joel		MR. HERRERA PLEASE REPLACE ALL OUTSIDE BROKEN TILES. 2ND YEAR REQUEST							
---------------	--	--	--	--	--	--	--	--	--

Jessica Lopez

43830					3/18/2009		49		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/18/2009 11:05:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Herrera, Joel		MR. HERRERA PLEASE PAINT OR TOUCH UP ALL CLASSROOMS.							
---------------	--	--	--	--	--	--	--	--	--

Jessica Lopez

43832					3/18/2009		49		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/18/2009 11:08:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Herrera, Joel		MR. HERRERA PLEASE PAINT STUDENT RESTROOMS.							
---------------	--	---	--	--	--	--	--	--	--

Jessica Lopez

43833					3/18/2009		49		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/18/2009 11:11:56 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Herrera, Joel		MR. HERRERA PLEASE SECURE DISPLAY FIXTURE IN FRON OF THE OFFICE.							
---------------	--	--	--	--	--	--	--	--	--

Jessica Lopez

43923					3/20/2009		47		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/20/2009 10:22:46 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Herrera, Joel		MR. HERRERA PLEASE PAINT CAFETERIA MAIN ENTRANCE.							
---------------	--	---	--	--	--	--	--	--	--

Jessica Lopez

44333					4/5/2009	4/26/2009	31		\$0.00
-------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/5/2009 12:22:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Danny		Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.							
---------------	--	---	--	--	--	--	--	--	--

Margret Villalobos

44963					4/23/2009		13		\$0.00
-------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	PORTABLE A &			4/23/2009 11:49:57 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Herrera, Joel		MR. HERRERA- DOORS TO PORTABLE A & B NEED TO BE PAINTED AND ALSO RESTROOM DOORS NEED TO BE PAINTED							
---------------	--	--	--	--	--	--	--	--	--

Jessica Lopez

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

44964					4/23/2009		13		\$0.00
Medium	Work In Progress	CUSTODIAL			4/23/2009 11:52:20 AM				
Herrera, Joel		MR. HERRERA CUSTODIAN STORAGE ROOMS NEED TO BE PAINTED							
Jessica Lopez									
45031	Main Building	Gym			4/27/2009		9		\$0.00
Medium	Work In Progress				4/27/2009 7:42:29 AM				
Herrera, Joel		MR. HERRERA PLEASE PAINT STAGE. LOCATION: GYM							
Jessica Lopez									
45032	Main Building				4/27/2009		9		\$0.00
Medium	Work In Progress	FRONT OF			4/27/2009 7:52:25 AM				
Herrera, Joel		MR. HERRERA PLEASE PAINT SUNLAND PARK SIGN LOCATED IN FRONT OF THE BUILDING.							
Jessica Lopez									
45104		Classroom			4/28/2009		8		\$0.00
Medium	Work In Progress	1st to 5th grade			4/28/2009 1:31:46 PM				
Herrera, Joel		Furniture for computers delivered on April 16 to the school please set up in classrooms first to fifth grade. Thank you.							
Sandra Almeraz									
45146		Cafeteria			4/29/2009		7		\$0.00
Medium	Work In Progress				4/29/2009 11:39:35 AM				
Moncayo, Fernando		Reach-In Refrigerator is at 25 degrees Marina Ramirez - SNP Manager 589-2545							
Alma Terrell									
45195					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress				4/30/2009 12:21:36 AM				
Herrera, Joel		Yearly - Sunland Park ES C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
45296					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:40 AM				
Herrera, Joel		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
45297					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:41 AM				
Herrera, Joel		Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

45298					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:41 AM				
Herrera, Joel		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
45358					5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 2:01:01 PM				
Lara, Ralph		RAFA I NEED YOU TO MAKE A HOLE WITH YOUR DRILL OFFICES DESCK							
Joel Herrera									
45359					5/4/2009		2		\$0.00
Medium	Work In Progress				5/4/2009 2:05:17 PM				
Lara, Ralph		RAFA PLEASE CHECK EXIT DOORS, NOT WORKING RIGHT THANK YOU RAFA....							
Joel Herrera									
45404					5/5/2009		1		\$0.00
Medium	Work In Progress	10			5/5/2009 8:08:30 AM				
Herrera, Joel		MR. HERRERA SHARPERNER NOT WORKING, BROKEN DESK. LOCATION: ROOM # 10							
Jessica Lopez									
45406					5/5/2009		1		\$0.00
Medium	Work In Progress	LIBRARY			5/5/2009 8:12:36 AM				
Herrera, Joel		MR. HERRERA PLEASE SET UP TABLE/STAND FOR PRINTER LOCATION: LIBRARY							
Jessica Lopez									
45443					5/5/2009		1		\$0.00
Medium	Work In Progress				5/5/2009 3:48:24 PM				
Ambriz, Jose		REFRI. UNIT IT DOESNT WORKING WELL AT MAIN OFFICE THANK YOU JOSE...							
Joel Herrera									
Count: 40 Work Orders									
		Avg. Age of WO's 62							
						Total for Sunland Park ES	1		\$25.00

Location: Sunrise ES

37422					8/26/2008		253		\$0.00
Medium	Work In Progress				8/26/2008 4:19:28 PM				
Ontiveros, Joe		HOSE BIBB ON WALL NEXT TO UPPER PLAY GROUND WATER LEAKING,BROKEN HANDLE.							
Paul Quinones									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
39872					11/5/2008		182		\$0.00
Medium	Work In Progress			11/5/2008 3:35:43 PM					
Jacquez, Ricardo	REQUESTING WIND SCREEN FOR BACK CHAIN LINK FENCING AREA,LIFT STATION AREAS. BALL PARK FIGURE 200' WILL BE NEEDED @ 4' HIGH THANK YOU VERY MUCH								
Paul Quinones									
40018		Classroom			11/12/2008		175		\$0.00
Medium	Work In Progress	Parent Room		11/12/2008 8:11:32 AM					
Sotelo, Enrique	Check outlet with built in breaker, in Parent Room, by office, it keeps tripping.								
Joanne Munoz									
41164		Classroom			1/5/2009		121		\$0.00
Medium	Work In Progress	102		1/5/2009 2:51:54 PM					
Lara, Ralph	I will need a extra key for our RPT key # 1c38								
Joanne Munoz									
41559					1/16/2009		110		\$0.00
Medium	Work In Progress			1/16/2009 8:17:12 AM					
Sotelo, Enrique	DRYER HANDS BOYS AND GRLS. NEED REPLCE SENSOR NOT WORK								
Juan Vargas									
41786		Lift Station			1/23/2009		103		\$0.00
Medium	Work In Progress			1/23/2009 9:31:44 AM					
Jacquez, Ricardo	please installe air valve on lift station								
Ricardo Jacquez									
42708					2/19/2009		76		\$0.00
Medium	Work In Progress			2/19/2009 12:58:11 PM					
Lozoya, Manny	room 303 back door need fix lock								
Juan Vargas									
42709					2/19/2009		76		\$0.00
Medium	Work In Progress			2/19/2009 1:02:20 PM					
Lozoya, Manny	entry main need fix handy cop door								
Juan Vargas									
44225					4/2/2009		34		\$0.00
Medium	Work In Progress			4/2/2009 3:03:37 PM					
Jacquez, Ricardo	need move up buster electical disconet								
Juan Vargas									
44426					4/5/2009		31		\$0.00
Medium	Work In Progress			4/5/2009 12:23:19 AM					
Jacquez, Ricardo	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
44427					4/5/2009		31		\$0.00
Medium	Work In Progress			4/5/2009 12:23:20 AM					
Jacquez, Ricardo	Monthly - Sunrise ES - DP-1421 - Refer to PM schedule details.								
Margret Villalobos									
44513					4/7/2009		29		\$0.00
Medium	Work In Progress			4/7/2009 3:46:37 PM					
Gonzales, Angel	need replace small glass i broke								
Juan Vargas									
44742					4/16/2009		20		\$0.00
Medium	Work In Progress			4/16/2009 8:48:10 AM					
Ontiveros, Joe	need fix 2in. pvc pipe on play field have big leak								
Juan Vargas									
44992		Cafeteria			4/23/2009		13		\$0.00
Medium	Work In Progress			4/23/2009 4:13:31 PM					
Orozco, Danny	AIR CONDITIONER NOT WORKING AT ALL.								
	VIRGINIA PRUIT SNP MGR 824-3194								
Jacqueline Aguilar									
45033					4/27/2009		9		\$0.00
Medium	Work In Progress			4/27/2009 7:57:20 AM					
Lozoya, Manny	need two locks on garbage can								
Juan Vargas									
45098					4/28/2009		8		\$0.00
Medium	Work In Progress			4/28/2009 12:37:01 PM					
Sotelo, Enrique	need replace 3 lights on gym								
Juan Vargas									
45196					4/30/2009	5/31/2009	6		\$0.00
Medium	Work In Progress			4/30/2009 12:21:36 AM					
Vargas, Juan	Yearly - Sunrise ES C11 (Evap.Cooler)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
45306					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:44 AM					
Vargas, Juan	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
45307					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:44 AM					
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Sunrise ES

45308					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:45 AM					
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45327					5/3/2009		3		\$0.00
Medium	Work In Progress			5/3/2009 12:22:51 AM					
Jacquez, Ricardo	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									
Count: 21 Work Orders			Avg. Age of WO's 61			Total for Sunrise ES	0		\$0.00

Location: Vado ES

36103					7/22/2008		288		\$0.00
Medium	Work In Progress			7/22/2008 8:39:31 AM					
Sotelo, Enrique	NEED TO REPLACE 4 EXIT SIGNS								
Danny Miranda									
36104					7/22/2008		288		\$0.00
Medium	Work In Progress			7/22/2008 8:40:50 AM					
Sotelo, Enrique	NEED TO REPLACE 6 EMER. LIGHTS								
Danny Miranda									
41189					1/6/2009		120		\$0.00
Medium	Work In Progress			1/6/2009 10:43:25 AM					
Sotelo, Enrique	NEED TO REPAIR THREE POWER POLES IN KITCHEN								
Danny Miranda									
41569					1/16/2009		110		\$0.00
Medium	Work In Progress			1/16/2009 9:52:29 AM					
Lozoya, Manny	NEED TOCK. DOOR KNOB IN CUSTODIAL ROOM AT 300-WING HANDLE CAME OUT								
Danny Miranda									
41880					1/27/2009		99		\$0.00
Medium	Work In Progress			1/27/2009 10:03:30 AM					
Lozoya, Manny	NEED TO PUT CHANGE DOOR KNOB AND TWO KEYS TO BEST IN NEW CLASSROOM AT LIBUERY								
Danny Miranda									
41947					1/28/2009		98		\$0.00
Medium	Work In Progress			1/28/2009 2:23:55 PM					
Lozoya, Manny	NEED TO CK. CORE ON DOOR KNOB TO BACK ELECTRICAL ROOM KEY WILL NOT LOCK								
Danny Miranda									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Vado ES

43843	Main Building	Athletic Field			3/18/2009		49		\$0.00
Medium	Work In Progress			3/18/2009 1:18:53 PM					
Miranda, Danny	Pine trees need to be treated for Aphids.								
Guadalupe Ontiveros									
44118					3/31/2009		36		\$0.00
Medium	Work In Progress			3/31/2009 1:31:54 PM					
Villalobos, David	Backflow Testing and Inspection								
David Villalobos									
44119					3/31/2009		36		\$0.00
Medium	Work In Progress			3/31/2009 1:32:46 PM					
Villalobos, David	Backflow Testing and Inspection								
David Villalobos									
44337					4/5/2009	4/26/2009	31		\$0.00
Medium	Work In Progress			4/5/2009 12:22:49 AM					
Orozco, Danny	Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.								
Margret Villalobos									
44628					4/12/2009	4/28/2009	24		\$0.00
Medium	Work In Progress			4/12/2009 12:21:19 AM					
Diaz, Armando	Monthly - QRTLY BLDG INSP REPORT (VE) - Refer to PM schedule details.								
Jesus Estrada									
44728					4/15/2009		21		\$0.00
Medium	Work In Progress			4/15/2009 3:44:53 PM					
Lozoya, Manny	need new locks on marquee sign (total of four keyed alike)								
Danny Miranda									
44779					4/17/2009		19		\$0.00
Medium	Work In Progress			4/17/2009 11:00:25 AM					
Ontiveros, Joe	Line Locate Monday 4/20/09. Please see Danny Miranda for exact location.								
Danny Miranda									
44855					4/21/2009		15		\$0.00
Medium	Work In Progress			4/21/2009 9:24:52 AM					
Gonzales, Angel	NEED BOBCAT FOR WORKING GRAVEL & SOIL TO BE PUT IN RAISED GARDENS								
Danny Miranda									
45100	Classroom				4/28/2009		8		\$0.00
Medium	Work In Progress	1st to 5th grade		4/28/2009 1:21:33 PM					
Miranda, Danny	Furniture for computers delivered on April 17 to the school please set up in classrooms first to fifth grade. Thank you.								
Sandra Almeraz									

993 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
45270					5/3/2009	5/9/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:31 AM				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
45271					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:31 AM				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
45272					5/3/2009	5/11/2009	3		\$0.00
Medium	Work In Progress				5/3/2009 12:22:32 AM				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
45412	Main Building	Classroom			5/5/2009		1		\$0.00
Medium	Work In Progress				5/5/2009 10:34:30 AM				
Solis, Lorenzo		CHECK ROOMS ON THE 300 WING ON TRACER SUMMIT.							
Lorenzo Solis									
Count: 19 Work Orders		Avg. Age of WO's 66		Total for Vado ES		0		\$0.00	
Count: 993 Work Orders		Avg. Age of WO's 78		Grand Total		24		\$2,449.49	