

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Anthony - On Track Pre-K</b>							
45830		Classroom			5/19/2009		14		\$0.00
Medium	Work In Progress				5/19/2009 10:00:49 AM				
Villalobos, Margret	spray for spyders,poisonus spyder found in classroom,sray rooms 306,307, 309,310								
David Vega									
<b>Count: 1</b>	<b>Work Orders</b>	<b>Avg. Age of WO's</b>	<b>14</b>	<b>Total for Anthony - On Track Pre-K</b>				<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
36176	Cafeteria	Cafeteria			7/24/2008		313		\$0.00
Medium	Work In Progress				7/24/2008 11:26:39 AM				
Ontiveros, Guadalupe		remove old tree next to cafeteria, health issue as per ms.marquez							
<u>David Vega</u>									
36641	Drug Free Bldg.				8/5/2008		301		\$0.00
Medium	Work In Progress				8/5/2008 10:48:59 AM				
Sotelo, Enrique		please install a power strip for radios. please see irene for location.thxs							
<u>Michael Munoz</u>									
37287	Cafeteria	Cafeteria			8/21/2008		285		\$0.00
Medium	Work In Progress				8/21/2008 11:49:08 AM				
Orozco, Danny		SEAL TO WALK-IN REFRIGERATOR IS ALL TORN AND MOLDY, SEAL NEEDS TO BE REPLACED							
		BECKY SAENZ - 882-3507 (K-3 CAFETERIA)							
<u>Alma Terrell</u>									
39028		Athletic Field			10/8/2008		237		\$0.00
Medium	Work In Progress				10/8/2008 10:07:55 AM				
Appelzoller, Fred		Outside water fountains mounted on concrete block columns located east of the Old Main Cafeteria are not working. REPAIR							
<u>Alfredo Holguin</u>									
40016	Cafeteria	Cafeteria			11/12/2008		202		\$0.00
Medium	Work In Progress				11/12/2008 7:52:56 AM				
Sotelo, Enrique		please install light fixture in bathroom, old main cafeteria where remodeling is being done. thxs							
<u>Michael Munoz</u>									
41163	Original Main	Athletic Field			1/5/2009		148		\$0.00
Medium	Work In Progress				1/5/2009 2:35:27 PM				
Holguin, Alfredo		Canopy tore in pieces by wind need to replace old main blg side palyground equipment							
<u>Hector Villalobos</u>									
41625	Main Building	Classroom			1/20/2009		133		\$0.00
Medium	Work In Progress				1/20/2009 7:23:55 AM				
Lozoya, Manny		room 16 needs keys made for cabinet							
<u>Hector Villalobos</u>									
41626	Original Main	Office			1/20/2009		133		\$0.00
Medium	Work In Progress				1/20/2009 7:28:24 AM				
Lozoya, Manny		Room 112 needs adoor guard for door lock handle							
Hector Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
41944	Original Main				1/28/2009		125		\$0.00
Medium	Work In Progress			1/28/2009 1:26:53 PM					
Lozoya, Manny		old main blg stoage supplie room needs door handle lock guard							
Hector Villalobos									
42372					2/9/2009		113		\$0.00
Medium	Work In Progress			2/9/2009 12:43:22 PM					
Lozoya, Manny		Need to ck padlock or issue a new key for the gate on church street, where the NM Environment Dept goes in. She said her key does not open that lock.							
Margret Villalobos									
42600	Original Main	Mechanical Room			2/17/2009		105		\$0.00
Medium	Work In Progress			2/17/2009 9:14:54 AM					
Solis, Lorenzo		old main blg boilers room pump is leaking							
Hector Villalobos									
42895		Parking Lot			2/25/2009		97		\$0.00
Medium	Work In Progress			2/25/2009 8:28:10 AM					
Villalobos, David		Have contractor(s) see about installation of Backflow preventer for the school site to be located at far northwest end of campus next to main water meter							
David Villalobos									
42912		Classroom			2/25/2009		97		\$0.00
Medium	Work In Progress	ON TRACK PRE		2/25/2009 11:11:40 AM					
Ronquillo, Ruben		SCREENS & BLINDS FOR 4 CLASSROOMS * SCREENS FOR 20 WINDOWS 31 1/2 " H X 4 FT 11" W * BLINDS FOR 20 WINDOWS 54" H X 63" W  BLINDS FOR OFFICE * 2 WINDOWS 38" H X 95" W * 2 WINDOWS 62" H X 34" W							
Lucy Meza									
42913					2/25/2009		97		\$0.00
Medium	Work In Progress	Anthony On Track		2/25/2009 11:12:28 AM					
Ronquillo, Ruben		Blinds for windows (6) in office portable and in two classrooms. 4- 47 x 37 2- 33 x 62							
Lucy Meza									
42914		Classroom			2/25/2009		97		\$0.00
Medium	Work In Progress	Pre - K		2/25/2009 11:13:20 AM					
Ronquillo, Ruben		P.R.E.K headstart rooms 306 307 blinds 12 63x54							
Hector Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
42964					2/26/2009		96		\$0.00
Medium	Work In Progress				2/26/2009 8:23:36 AM				
Appelzoller, Fred	Upper Primary - Need to relocate spikett.		Summer Project						
Michael Munoz									
43231	Annex Building	Office			3/2/2009		92		\$0.00
Medium	Work In Progress				3/2/2009 12:56:02 PM				
Lozoya, Manny	room 212 door lock handle broken off need to replace it annex blg								
Hector Villalobos									
43774	Main Building				3/17/2009		77		\$0.00
Medium	Work In Progress				3/17/2009 8:05:30 AM				
Appelzoller, Fred	Some kind of water problem in main bldg.								
Michael Munoz									
44020					3/25/2009		69		\$0.00
Medium	Work In Progress				3/25/2009 2:56:57 PM				
Villalobos, Hector	3/25/09					3/25-8			
	7.5 chapter o. therapy room relocate bulletin boards		Material 251.55						
	paint walls Q-7-36-P 4 gals \$80 1 painters caulk \$3. 85								
	suspended ceiling 2 boxes \$27.95 \$139.75								
	5 log on work order log								
Hector Villalobos									
44256					4/3/2009		60		\$0.00
Medium	Work In Progress				4/3/2009 2:10:33 PM				
Villalobos, David	Need to ck pressure on water entering site, and see if water pressure could be reduced. Make sure piping is strapped properly.								
Michael Munoz									
44318					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress				4/5/2009 12:22:43 AM				
Orozco, Danny	Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
44474	Main Building	Custodial			4/6/2009		57		\$0.00
Medium	Work In Progress				4/6/2009 3:37:22 PM				
Lozoya, Manny	Room 16 needs to make new lock for cabinet								
Hector Villalobos									
44646					4/12/2009	4/28/2009	51		\$0.00
Medium	Work In Progress				4/12/2009 12:21:27 AM				
Villalobos, Hector	Monthly - Anthony ES A4 (Rooftop Unit)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Anthony ES</b>								
44817	Boiler Room	Pump House			4/20/2009		43		\$0.00	
Medium	Work In Progress				4/20/2009 8:05:45 AM					
Gonzalez, Salvador		PLEASE CUT 3 INCH PIPE FOR CIRCULATING PUMP AND RE-WELD. THANKS!								
Lorenzo Solis										
45355	Pump House	Pump House			5/4/2009		29		\$0.00	
Medium	Work In Progress				5/4/2009 1:32:11 PM					
Sanchez, Raul		upper primary pump houes . pump is not working								
Hector Villalobos										
45357	Main Building	Hallway/Corridor			5/4/2009		29		\$0.00	
Medium	Work In Progress				5/4/2009 1:38:14 PM					
Lozoya, Manny		mild blg north doors need to replace mild bar for doors								
Hector Villalobos										
45576					5/11/2009	5/17/2009	22		\$0.00	
Medium	Work In Progress				5/11/2009 12:17:22 AM					
Villalobos, Hector		Monthly - Anthony ES A7 (Rooftop Unit)(Monthly) - Refer to PM schedule details.								
Margret Villalobos										
45613	Main Building	Hallway/Corridor			5/11/2009		22		\$0.00	
Medium	Work In Progress				5/11/2009 3:51:40 PM					
Lozoya, Manny		mild blg hallway south exit door broken panic bar								
Hector Villalobos										
45748	Main Building	Classroom			5/15/2009		18		\$0.00	
Medium	Work In Progress				5/15/2009 8:12:20 AM					
Solis, Lorenzo		Room 3 refrigerating is not working								
Hector Villalobos										
45961	Original Main	Computer Lab			5/22/2009		11		\$0.00	
Medium	Work In Progress				5/22/2009 1:09:03 PM					
Solis, Lorenzo		old main blg need to replace big a/c unit								
Hector Villalobos										
46097	Pump House	Pump House			5/29/2009		4		\$0.00	
Medium	Work In Progress				5/29/2009 10:24:32 AM					
Sotelo, Enrique		We need an electrician to diconnect and reconnect the wiring for the installation of a new pump & motor for the sprinkler system at the upper primary. Will take place in June around the 15-18.								
Raul Sanchez										
46175					5/31/2009	6/6/2009	2		\$0.00	
Medium	Work In Progress				5/31/2009 12:23:31 AM					
Villalobos, Hector		Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos										

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
46176					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:31 AM					
Villalobos, Hector	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46177					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:32 AM					
Villalobos, Hector	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46178					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:32 AM					
Villalobos, Hector	Yearly - Anthony ES A2 (Split System)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
46179					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:33 AM					
Villalobos, Hector	Yearly - Anthony ES - B2 Boiler (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
46180					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:33 AM					
Villalobos, Hector	Yearly - Anthony ES B2(Boiler H.Water)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
46319	Annex Building				6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 4:01:48 PM					
Sotelo, Enrique	please install electrical power for new kiln in room 213 south east corner as per our conversation.thxs								
Michael Munoz									
<b>Count: 38 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>85</b>		<b>Total for Anthony ES</b>	<b>0</b>		<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
36845					8/8/2008		298		\$0.00
Medium	Work In Progress	Mobile Home		8/8/2008 3:52:51 PM					
Sotelo, Enrique		Need to install utility hook-up for mobile home.							
Michael Munoz									
36879					8/11/2008		295		\$0.00
Medium	Work In Progress			8/11/2008 9:01:25 AM					
Ontiveros, Guadalupe		MR LUPE ONTIVEROS SIR PER MR VALTIERRA HE WOULD LIKE THE SCHOOL CLEAN TO MANNY WEEDS PONDING AREA NEEDS CLEAN IN FRONT AND BACK AROUND PORTABLES ALONE FENCE IN FRONT OUTSIDE AND IN SIDE THANK YOU SIR							
Adan Duran									
38128					9/16/2008		259		\$0.00
Medium	Work In Progress			9/16/2008 10:30:21 AM					
Sotelo, Enrique		Emer. Light need replacing at west entrance and Custodial room.							
Adan Duran									
38442	Main Building				9/25/2008		250		\$0.00
Medium	Work In Progress			9/25/2008 3:59:37 PM					
Duran, Adan		Restrooms nest to multipurpose room- sand entrance doors and reseal							
Alfredo Holguin									
39479					10/24/2008		221		\$0.00
Medium	Work In Progress			10/24/2008 3:26:04 PM					
Sotelo, Enrique		MR ENRIQUE SOTELO SIR EMERGENCY LIGHT FALL OFF WALL IN CAFETERIA NEED TO REPLACE BROKEN BURN ELEMENTS THE ONE IN CUSTODIAL ROOM ALSO THANK YOU SIR							
Adan Duran									
40997					12/18/2008		166		\$0.00
High	Work In Progress			12/18/2008 4:24:02 PM					
Miranda, Danny		as epr our conversation, the wall to the entrance of the boys restroom on the east wing has been kicked in. please replace w/ durock as discussed. if other areas at site need the same please take of them. Thxs							
Michael Munoz									
41069					1/4/2009	1/25/2009	149		\$0.00
Medium	Work In Progress			1/4/2009 12:18:49 AM					
Orozco, Danny		Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
41153					1/5/2009		148		\$0.00
Medium	Work In Progress				1/5/2009 8:18:40 AM				
Lozoya, Manny	MR MANNY LOZOYA HAPPY NEW YEAR AND GOD BLESS MR LOZOYS SIR WE HAVE A BROKEN KEY IN GATE LOCK WEST GATE NEED TO REPLACE WILL NEED TO LOCK TO NIGHT THANK YOU SIR								
Adan Duran									
42002					1/29/2009		124		\$0.00
Medium	Work In Progress				1/29/2009 3:19:45 PM				
Sotelo, Enrique	MR ENRIQUE SOTELO SIR NEED TO CHECK MOTOR ON EXHUAST FAN ROOMS 105 AND 106 ALSO CHECK SWITCHS FANS NOT WORKING THANK YOU AND GOD BLESS								
Adan Duran									
43055					2/27/2009		95		\$0.00
Medium	Work In Progress				2/27/2009 3:22:22 PM				
Sotelo, Enrique	MR ENRIQUE SOTELO PER MR VALTIERRA NEED TO REPLACE LIGHT BULBS GYM STAGE SOME ARE COLORED THANK YOU SIR AND GOD BLESS								
Adan Duran									
43707					3/13/2009		81		\$0.00
Medium	Work In Progress	Playground			3/13/2009 3:38:18 PM				
Ontiveros, Guadalupe	MRS MARGRET VILLALOBOS PER MIKE MUNOZ THE PLAYGROUND HERE AT BERINO NEEDS SOME WORK UNEVEN HOLES NEED SOME TOP SOIL ECT NEED YOUR ASSISTANCE IN THIS THANK YOU SIR AND GOD BLESS								
Adan Duran									
43869		Cafeteria			3/19/2009		75		\$0.00
Medium	Work In Progress				3/19/2009 10:53:01 AM				
Orozco, Danny	DISHWASHER: CHECK OUT PRE RINSE DRAIN UNIT								
	MR. G. SNP DIRECTOR 882-6771								
Jacqueline Aguilar									
44021					3/25/2009		69		\$0.00
Medium	Work In Progress				3/25/2009 3:00:16 PM				
Duran, Adan	3/25/09					3/25-8			
	1/2 SIGN IN CHECK SCHOOL BUILDING GROUNDS 1 WATER NEW PLANTED PINE TREES 41/2 WORKED ON AC UNITS CLEAN HOOK UP 1/2 OPEN DOORS FOR PALAN-B CAMERA HOOK UP 1/2 SHUT DOWN MARQUEE PULL OUT FUESES FROM BREAKER BOX 1 FILE DAILY LOG AND SIGN OUT								
Adan Duran									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
44313					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:41 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
44849					4/21/2009		42		\$0.00
Medium	Work In Progress			4/21/2009 7:56:02 AM					
Lozoya, Manny	MR MANNY LOZOYA SIR THE LOBBOY DOORS IN FRONT ARE NOT LOCKING NEED YOUR ASSISTANCE IT HAS THE LITTLE LEVER THAT PUSH UP AND DOWN TO LOCK AND OPEN THANK YOU SIR AND GOD BLESS								
Adan Duran									
44934					4/22/2009		41		\$0.00
Medium	Work In Progress			4/22/2009 3:00:04 PM					
Villalobos, Margret	AS PER MR VALTIERRA THERE WHERE FOUND IN ROOM 106 GRADE EC ABOUT 20 ROACHS UNDER BOOKSHELF COULD WE PLEASE HAVE IT SPRAY WITH PESTICIDE THANK YOU		4/22 - Waiting on Price Quote 37.50						
Adan Duran									
45093		Classroom			4/28/2009		35		\$0.00
Medium	Work In Progress	1st - 5th grade		4/28/2009 11:34:32 AM					
Duran, Adan	Furniture for computers was delivered on April 27th to school please set up in classrooms first to fifth grade. Thank you.								
Sandra Almeraz									
45121					4/28/2009		35		\$0.00
Medium	Work In Progress			4/28/2009 3:32:33 PM					
Lozoya, Manny	MR MANNY LOZOYA SIR WILL NEED A NAME PLATE FOR DOOR RM 129 NEW TEACHER HER NAME IS R. S. SEPULVEDA THANK YOU SIR AND GOD BLESS								
Adan Duran									
45797					5/18/2009		15		\$0.00
Medium	Work In Progress			5/18/2009 3:04:16 PM					
Sotelo, Enrique	MR ENRIQUE SOTELO SIR WE HAVE SEVERAL EMERGENCY LIGHT THAT NEED REPLACEMENT ALSO ABOUT 6 NEED BATTERY THANK YOU SIR AND GOD BLESS								
Adan Duran									
45926					5/21/2009		12		\$0.00
Medium	Work In Progress			5/21/2009 3:08:04 PM					
Ontiveros, Guadalupe	MR LUPE ONTIVEROS SIR NEED TO INSTALL NEW VALUES IRRIGATION SYSTEM TO WORK WITH TIMER KIDS WILL BE OUT NEXT FRIDAY 29 THANK YOU SIR AND GOD BLESS								
Adan Duran									
6/2/2009 9:39:29 AM									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
45972					5/22/2009		11		\$0.00
Medium	Work In Progress				5/22/2009 3:28:06 PM				
Lozoya, Manny	MR MANNY LOZOYA SIR NEED TO REPLACE CENTER POLES FRONT ENTRANCE ONE SIDE AND EAST ENTRANCE ONE SIDE VERY OLD AND HAVING TROUBLE REMOVEING WHEN BIG CRATES HAVE TO BE UNLOADED AND BROUGHT INTO BUILDING PLEASE ORDER TWO FOR OUR SITE LAST DAY THANK YOU AND GOD BLESS								
<u>Adan Duran</u>									
46121					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:10 AM				
Duran, Adan	Yearly - Berino ES A2 (Split System)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46122					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:11 AM				
Duran, Adan	Yearly - Berino ES B2(Boiler H.Water)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46123					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:11 AM				
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46124					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:12 AM				
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46125					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:12 AM				
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
<b>Count: 26 Work Orders</b>		<b>Avg. Age of WO's 96</b>			<b>Total for Berino ES</b>			<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral ES</b>									
37135	West Central				8/18/2008		288		\$0.00
Medium	Work In Progress			8/18/2008 9:11:53 AM					
Hernandez, Guillermo	new doors are being installed in the esat and west barrack. please order paint so you can paint doors. thxs		Left by J. Vargas 4/6/09						
<u>Michael Munoz</u>									
37990		Cafeteria			9/10/2008		265		\$0.00
Medium	Work In Progress			9/10/2008 1:49:03 PM					
Orozco, Danny	Side of grease trap caving in.								
<u>Michael Munoz</u>									
38027		Athletic Field			9/11/2008		264		\$0.00
Medium	Work In Progress			9/11/2008 2:05:24 PM					
Ontiveros, Guadalupe	Lower Grades playground equipment located between classroom wings - Re layout plastic borders so they are aroun the remaining playground (slide) structure.								
<u>Alfredo Holguin</u>									
40604					12/4/2008		180		\$0.00
Medium	Work In Progress			12/4/2008 4:46:38 PM					
Sotelo, Enrique	Need assistence to replace two outside light fixtures of portable 34DW (#402 and #404)								
<u>Guillermo Hernandez</u>									
41137					1/4/2009		149		\$0.00
Medium	Work In Progress			1/4/2009 12:19:17 AM					
Jacquez, Ricardo	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41968					1/28/2009		125		\$0.00
Medium	Work In Progress			1/28/2009 3:46:13 PM					
Ontiveros, Joe	Need to replace two bubblers on the water fountain by the field and one by E wing. Thank you.								
<u>Guillermo Hernandez</u>									
43069					2/27/2009		95		\$0.00
Medium	Work In Progress			2/27/2009 3:58:35 PM					
Ontiveros, Joe	Would you please replace the flushing valves to the comodes in the boy's and girl's restrooms. Thank you								
<u>Guillermo Hernandez</u>									
44198					4/1/2009		62		\$0.00
Medium	Work In Progress			4/1/2009 3:53:55 PM					
Ontiveros, Joe	No hot water on the New addition 200's, Reversing valve on the Water heater not working. thank you								
<u>Guillermo Hernandez</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
45000					4/24/2009		39		\$0.00
Medium	Work In Progress				4/24/2009 8:01:45 AM				
Hernandez, Guillermo	Need to repair air bubbles on Main building roof. Thank you								
<u>Guillermo Hernandez</u>									
45069					4/27/2009		36		\$0.00
Medium	Work In Progress				4/27/2009 4:00:38 PM				
Ontiveros, Joe	Need to replace wax ring on the urinals in the boy's restroom on the hallway for kinder. Thank you.								
<u>Guillermo Hernandez</u>									
45201					4/30/2009		33		\$0.00
Medium	Work In Progress				4/30/2009 12:21:38 AM				
Jacquez, Ricardo	Monthly - Chaparral ES DP-91 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45522					5/8/2009		25		\$0.00
Medium	Work In Progress				5/8/2009 9:18:24 AM				
Ontiveros, Joe	Need to install cut off water valves on main building, Lobby area restroom: 2", 1 1/2, and 1" valves. Thank you								
<u>Guillermo Hernandez</u>									
45629					5/12/2009		21		\$0.00
Medium	Work In Progress				5/12/2009 8:23:20 AM				
Estrada, Jesus	TILE IN BOYS REST ROOM (IN FRONT OF THE LOBBY) NEEDS TO BE REPLACED. PLEASE MAKE RECOMMENDATION ON SAME OR VCT		FAXED TO MICHAEL GARCIA 5/12/09. 6/1/09 - PENDING QUOTE						
<u>Jesus Estrada</u>									
45665	P.E. Building	Classroom			5/12/2009		21		\$0.00
Medium	Work In Progress	403, 405			5/12/2009 3:56:23 PM				
Hernandez, Guillermo	Need to have bars taken out of windows and doors. See Mr. Moncrief and Ms. DeGeeter. Both have bars in windows.								
<u>Jennifer Corral</u>									
45860					5/20/2009		13		\$0.00
Medium	Work In Progress				5/20/2009 8:06:22 AM				
Villalobos, Margret	Will you please fumigate Main Building, new addition and E wing, concern about roaches, Thank you.								
<u>Guillermo Hernandez</u>									
45955		Custodial			5/22/2009		11		\$0.00
Medium	Work In Progress				5/22/2009 9:09:03 AM				
Carbajal, Jimmy	need,to,fix,vaccum,cleaner,not,working								
<u>Daniel Ramirez</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
45956		Custodial			5/22/2009		11		\$0.00
Medium	Work In Progress			5/22/2009 9:11:32 AM					
Carbajal, Jimmy		need, to, fix, vaccum, not, working, good.							
Daniel Ramirez									
45998					5/26/2009		7		\$0.00
Medium	Work In Progress			5/26/2009 1:02:16 PM					
Ontiveros, Guadalupe		need to fill with cobblestones the east side of new addition where roof gutters are causing erosion. Thank you							
Guillermo Hernandez									
45999					5/26/2009		7		\$0.00
Medium	Work In Progress			5/26/2009 2:00:06 PM					
Lozoya, Manny		Would you please check the door closer on the front door to the Library (ASAP) Thank you							
Guillermo Hernandez									
46000					5/26/2009		7		\$0.00
Medium	Work In Progress			5/26/2009 2:03:02 PM					
Lozoya, Manny		Classroom #211 is requesting keys for the cabinets, could you please make a set of key for the cabinets. Thank you							
Guillermo Hernandez									
46167					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:28 AM					
Hernandez, Guillermo		Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
46168					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:28 AM					
Hernandez, Guillermo		Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
46169					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:29 AM					
Hernandez, Guillermo		Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
46170					5/31/2009		2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:29 AM					
Hernandez, Guillermo		Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.							
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
46232					5/31/2009		2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:52 AM					
Jacquez, Ricardo	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									
46264		Athletic Field			6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 8:05:34 AM					
Aldaz, Bobby	need support from grounds dept to aertate and fertilze playing fields.								
Guadalupe Ontiveros									
<b>Count: 26 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>64</b>		<b>Total for Chaparral ES</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral HS</b>									
37783					9/4/2008		271		\$0.00
Medium	Work In Progress			9/4/2008 10:52:49 AM					
Lozoya, Manny	(65) LATCH PROTECTORS ARE REQUESTED FOR CLASS RMS AND OFFICE DOORS								
Eddie Baeza									
38742					10/5/2008		240		\$0.00
Medium	Work In Progress			10/5/2008 12:23:49 AM					
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.		10/6/08 - Emailed to Ricky Borrego						
Margret Villalobos									
39393					10/22/2008		223		\$0.00
Medium	Work In Progress			10/22/2008 3:50:18 PM					
Ontiveros, Guadalupe	(4) BATTING CAGES ARE REQUESTED FOR THE BASEBALL FIELDS.								
Eddie Baeza									
40782	A-Wing				12/11/2008		173		\$0.00
Medium	Work In Progress			12/11/2008 9:11:02 AM					
Quinones, Paul	Need to install pencil sharpeners in the A Wing. (Ms. Ballard)								
Guadalupe Gonzalez									
40973					12/18/2008		166		\$0.00
Medium	Work In Progress			12/18/2008 11:05:11					
Lozoya, Manny	PROTECTOR LATCHES,AND DOOR STOPS ARE NEEDED TO ALL CLASS RM. DOORS,AND OTHER DOORS REQUESTED BY CHS PRINCAPLE.ADDITIONAL HELP WILL HELP AS PROJECT STARTS.THANKS MANNY								
Paul Quinones									
41139					1/4/2009		149		\$0.00
Medium	Work In Progress			1/4/2009 12:19:18 AM					
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
41140					1/4/2009		149		\$0.00
Medium	Work In Progress			1/4/2009 12:19:19 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
41141					1/4/2009		149		\$0.00
Medium	Work In Progress			1/4/2009 12:19:19 AM					
Quinones, Paul	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
41142					1/4/2009	1/12/2009	149		\$0.00
Medium	Work In Progress			1/4/2009 12:19:20 AM					
Quinones, Paul	Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
41144					1/4/2009	2/4/2009	149		\$0.00
Medium	Work In Progress			1/4/2009 12:19:21 AM					
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
41150					1/4/2009		149		\$0.00
Medium	Work In Progress			1/4/2009 12:19:23 AM					
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.		1/6/09 e-mailed to ricky.borrego@cummins.com - mkv						
Margret Villalobos									
41178					1/5/2009		148		\$0.00
Medium	Work In Progress	R-Bldg		1/5/2009 3:59:51 PM					
Lozoya, Manny	DOOR IN R-2 BUILDING DOOR DOESNT LOCK DOOR ENTRANCE.								
Paul Quinones									
41180					1/5/2009		148		\$0.00
Medium	Work In Progress			1/5/2009 4:02:23 PM					
Lozoya, Manny	DOOR NEXT TO FRONT ENTRANCE WILL NOT LOCK WITH KEY.ON THE LEFT SIDE OF DOOR.								
Paul Quinones									
41479					1/14/2009		139		\$0.00
Medium	Work In Progress	SECURITY		1/14/2009 9:12:39 AM					
Lozoya, Manny	RE-KEY SECURITY SHACK WHEN COMPLETED WITH A CH-1 KEY. (DE SANTIAGO)								
Rosa Quezada									
41529					1/15/2009		138		\$0.00
Medium	Work In Progress	B Wing -		1/15/2009 2:15:39 PM					
Lozoya, Manny	Right entrance door to the classroom can not be unlocked with the key. Please check. (Ms. Duran-Campbell)								
Guadalupe Gonzalez									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
41607					1/16/2009		137		\$0.00
Medium	Work In Progress			1/16/2009 3:12:37 PM					
Lozoya, Manny	FIELD HOUSE BUILDING,BOYS WEIGHT RM.DOOR ENTRANCE KEY CYLINDERS DEED TO BE REPLACED FROM MULLEN TO BEST 2 DOORS.GIRLS LOCKER RM.3 CYLINDERS WILL BE NEEDED,AND BOYS LOCKER RM.4 CYLINDERS WILL BE NEEDED TO PANIC BARS THANKS								
Paul Quinones									
41608					1/16/2009		137		\$0.00
Medium	Work In Progress			1/16/2009 3:18:26 PM					
Sotelo, Enrique	Q,AND R BUILDING BUILDING ELECTRICAL KEY SWITCHES NEED TO BE REPLACED IN RES RMS.,AND HALL WAYS. CUSTODIANS HAVIING PROBLEMS TURNING OFF LIGHTS. MUCHOS GRACIAS HENRY.								
Paul Quinones									
41610					1/16/2009		137		\$0.00
Medium	Work In Progress			1/16/2009 3:23:48 PM					
Lozoya, Manny	REAR GATE TO KITCHEN REAR ENTRANCE.HOLES ARE NEEDED TO BE PLACED ON FLOOR TO SECURE GATE LATCHES								
Paul Quinones									
41612					1/16/2009		137		\$0.00
Medium	Work In Progress			1/16/2009 3:28:00 PM					
Lozoya, Manny	GYM ENTRANCE DOORS HOLES NEED TO BE PLACED TO SECURE DOOR LATCHES								
Paul Quinones									
41973					1/28/2009		0		\$0.00
High	Work In Progress			1/28/2009 4:21:00 PM	1/28/2009				
Lozoya, Manny	Head Custodian Armando Rivera needs his desk to lock so he can keep documents locked up.								
Jesus Estrada									
42027					1/30/2009		123		\$0.00
Medium	Work In Progress			1/30/2009 12:56:48 PM					
Lozoya, Manny	NEED TO REPLACE LOCKS IN HOT BOX FENCE AREA NORTH END FENCE LINE.								
Paul Quinones									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
42113					2/1/2009		121		\$0.00
Medium	Work In Progress			2/1/2009 12:24:48 AM					
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42115					2/1/2009		121		\$0.00
Medium	Work In Progress			2/1/2009 12:24:49 AM					
Quinones, Paul	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
42182					2/3/2009		119		\$0.00
Medium	Work In Progress			2/3/2009 12:59:06 PM					
Lozoya, Manny	PANIC BAR IN REAR ENTRANCE KITCHEN NEEDS TO BE SECURED TO DOOR FOR SAFETY PURPOSES, AND TO LOCCK DOOR								
<u>Paul Quinones</u>									
42183					2/3/2009		119		\$0.00
Medium	Work In Progress			2/3/2009 1:04:18 PM					
Lozoya, Manny	ADMIN.OFFICE NEEDS CAM LOCK TO SECURE PARTITION IN OFFICE AREA NEXT TO MR.DIGGS OFFICE								
<u>Paul Quinones</u>									
42197					2/3/2009		119		\$0.00
Medium	Work In Progress			2/3/2009 3:32:47 PM					
Lozoya, Manny	OUTSIDE DOOR HEALTHCENTER AREA DOOR WILL NOT CLOSE DOOR FROM CYLINDER, AND THE PANIC BAR KEY CYLINDER AS WELL.								
<u>Paul Quinones</u>									
42403					2/10/2009		112		\$0.00
Medium	Work In Progress			2/10/2009 8:31:08 AM					
Sotelo, Enrique	NEED TO INSTALL OUTLETS IN NEW GROUNDS STORAGE.								
<u>Guadalupe Ontiveros</u>									
42479	A-Wing	Library			2/11/2009		111		\$0.00
Medium	Work In Progress	trophy case		2/11/2009 11:14:25 AM					
Lozoya, Manny	replace lock on display case (middle one) for the library								
<u>Rosa Quezada</u>									
42480					2/11/2009		111		\$0.00
Medium	Work In Progress	whole school		2/11/2009 11:18:00 AM					
Lozoya, Manny	NEED A CH-1 FOR JOHNNY VALLES (GROUNDSMAN) QUEZADA								
<u>Rosa Quezada</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
43104					3/1/2009	3/22/2009	93		\$0.00
Medium	Work In Progress			3/1/2009 12:22:56 AM					
Orozco, Danny	Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
43122					3/1/2009		93		\$0.00
Medium	Work In Progress			3/1/2009 12:23:02 AM					
Orozco, Danny	Yearly - Chaparral HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43227		Cafeteria			3/2/2009		18		\$0.00
Medium	Work In Progress			3/2/2009 9:26:05 AM		3/20/2009			
Carbajal, Jimmy	scrubber-auto bearings from motor making to much noise droning battery					3/20/09 - AS PER JIMMY, NO PARTS AND HAVE NOT HAD A CHANCE TO CHECK OUT MACHINE. 4/20/09 - STILL PENDING?			
Armando Rivera									
43264		Classroom			3/3/2009		91		\$0.00
Medium	Work In Progress	Q-2		3/3/2009 2:02:58 PM					
Lozoya, Manny	KEY BROKE IN LOCK ON TOOL CAGE IN CONSTRUCTION ROOM Q-2 - PLEASE SEND MANNY OUT A.S.A.P. (QUEZADA)								
Rosa Quezada									
43719					3/15/2009		79		\$0.00
Medium	Work In Progress			3/15/2009 12:19:48 AM					
Ontiveros, Guadalupe	Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.								
Margret Villalobos									
43743		Parking Lot			3/16/2009		78		\$0.00
Medium	Work In Progress	install signs		3/16/2009 2:40:01 PM					
Quinones, Paul	NEED TO SETUP SIGNS IN THE FRONT OF THE BUILDING BY PARKING LOT FOR VISITORS THAT COME ON CAMPUS (DE SANTIAGO)								
Rosa Quezada									
43871		Athletic Field			3/19/2009		75		\$0.00
Medium	Work In Progress	FIELD HOUSE		3/19/2009 12:24:45 PM					
Lozoya, Manny	THE FIELD HAS HAS BEEN RELEASED TO US. NEED MANNY TO COME OUT AND ISSUE KEYS. (DIGGS)								
Rosa Quezada									
44220	E-Wing	Custodial			4/2/2009		61		\$0.00
Medium	Work In Progress			4/2/2009 10:54:33 AM					
Lozoya, Manny	custodial office desk, replace key								
Armando Rivera									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
44288					4/5/2009		58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:30 AM					
Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.			4/7/09	E-mailed PM to Ricky and Garrett at Rocky Mtn.			
Margret Villalobos									
44787					4/17/2009		46		\$0.00
Medium	Work In Progress			4/17/2009 1:16:20 PM					
Ontiveros, Joe		BOYS LOCKER RM.WATER WASH FOUNTAIN WATER WILL NOT SHUT OFF FROM BOTTOM SOLENOID VALVE							
Paul Quinones									
44788					4/17/2009		46		\$0.00
Medium	Work In Progress			4/17/2009 1:19:24 PM					
Ontiveros, Joe		BOOSTER PUMP FOR CIRCULATING WATER NEEDS TO BE REPLACED IN BOILER RM. IN WING B. HEALTH CENTER NEEDS WARM WATER.							
Paul Quinones									
44822					4/20/2009		43		\$0.00
Medium	Work In Progress			4/20/2009 9:59:00 AM					
Quinones, Paul		AS PER MR.DIGGS TROPHY CASES IN FRONT OF CAFETERIA SERVING LINES NEED TO BE REMOVED DUE TO STUDENT BUILD UP DURING A,AND B LUNCH SHIFTS.							
Paul Quinones									
44826					4/20/2009		43		\$0.00
Medium	Work In Progress			4/20/2009 10:25:43 AM					
Carrasco, Danny		LIGHTING IN GYM LIGHT BULBS NEED TO BE REPLACED SISSER LIFT WILL BE NEEDED TO REMOVE LIGHTS BULBS.							
Paul Quinones									
44827					4/20/2009		43		\$0.00
Medium	Work In Progress			4/20/2009 11:15:43 AM					
Quinones, Paul		MAIL BOX NEEDED FOR C.H.S. NEED A MUCH LARGER MAILBOX.			4/20	Paul, this is a request for material. Go ahead and use this work order so you can complete the task and let Ruben know how big you want the mailbox(example 20" x 20" x 12") and submitt this w/o # on the request.			
Paul Quinones						Mike			

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
44995					4/24/2009		39		\$0.00
Medium	Work In Progress	Cafeteria		4/24/2009 7:43:04 AM					
Lozoya, Manny		DOOR GOING INTO CAFETERIA, HARDWARE FELL OFF DOOR I HAVE THE HANDLE TO DOOR							
Paul Quinones									
45109					4/28/2009		35		\$0.00
Medium	Work In Progress			4/28/2009 2:55:53 PM					
Ontiveros, Joe		BOYS REST RM . BROKEN LAVATORY FAUCET IN WING B NEED TO BE REPLACED.							
Paul Quinones									
45152					4/29/2009		34		\$0.00
Medium	Work In Progress			4/29/2009 2:42:22 PM					
Ontiveros, Joe		Provide proper drainage to fire pump leak. (see Mike)							
Michael Munoz									
45163					4/29/2009		34		\$0.00
Medium	Work In Progress			4/29/2009 3:27:55 PM					
Lozoya, Manny		FRONT ENTRANCE DOOR KEY WILL NOT OPEN DOOR, AND PANIC BAR AS WELL. AREA COURT YARD FRONT ENTRANCE.							
Paul Quinones									
45164					4/29/2009		34		\$0.00
Medium	Work In Progress			4/29/2009 3:30:57 PM					
Lozoya, Manny		NORTH END FIELD HOUSE BOYS LOCKER RM DOOR WILL NOT CLOSE PROPERLY WITH DEAD BOLT							
Paul Quinones									
45319					5/3/2009		30		\$0.00
Medium	Work In Progress			5/3/2009 12:22:48 AM					
Quinones, Paul		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
45320					5/3/2009		30		\$0.00
Medium	Work In Progress			5/3/2009 12:22:49 AM					
Quinones, Paul		Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
45321					5/3/2009		30		\$0.00
Medium	Work In Progress			5/3/2009 12:22:49 AM					
Quinones, Paul		Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
45322					5/3/2009	6/3/2009	30		\$0.00
Medium	Work In Progress			5/3/2009 12:22:49 AM					
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
45384					5/4/2009		29		\$0.00
Medium	Work In Progress			5/4/2009 3:32:28 PM					
Lozoya, Manny	LOCK NEEDED IN NORTH END FIELD HOUSE ELECTRICAL HIGH VOLTAGE PANEL FOR SAFETY REASONS.LATCH WILL BE NEEDED AS WELL, THANKS.								
Paul Quinones									
45592					5/11/2009		22		\$0.00
Medium	Work In Progress			5/11/2009 1:03:15 PM					
Lozoya, Manny	NEED TO CHANGE HOUSING TO PANIC BAR FOR #7 PIN TO BOYS LOCKER RM. NORTH END FIELD HOUSE.								
Paul Quinones									
45616		Athletic Field			5/11/2009		0		\$0.00
High	Work In Progress			5/11/2009 3:58:22 PM	5/11/2009				
Lozoya, Manny	Need pad lock for grounds storage fence Gate MD-7 Also need two pad locks for gates CH-86.								
Guadalupe Ontiveros									
45674					5/13/2009		20		\$0.00
Medium	Work In Progress			5/13/2009 8:32:46 AM					
Quinones, Paul	BASKETBALL GYM, COACH HEREDIA REQUESTING REMOVAL OF 4 BASKETBALL BACK BOARDS, AND TO BE REPLACED W/ GLASS TYPE BACK BOARDS. BASKETBALL BACK BOARDS ARE LOCATED HERE AT C.H.S.								
Paul Quinones									
46028					5/27/2009		6		\$0.00
Medium	Work In Progress			5/27/2009 9:03:11 AM					
Lozoya, Manny	REQUESTING ALL DOORS TO BE CHECKED TOO MANY DOORS ARE UNABLE TO OPEN W/ISSUED KEY. HARDWARE ARE BROKEN ON SOME DOORS REQUESTING NEW HARDWARE TO BE INSTALLED								
Paul Quinones									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
46102					5/29/2009		4		\$0.00
Medium	Work In Progress			5/29/2009 2:00:07 PM					
Sotelo, Enrique	EXTERIOR LIGHTING NOT LIGHTING PROPERLY IN WING E BALLAST SHORTED OUT.								
Paul Quinones									
46222					5/31/2009		2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:48 AM					
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46223					5/31/2009		2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:49 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
46224					5/31/2009		2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:49 AM					
Quinones, Paul	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46225					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:50 AM					
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
46226					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:50 AM					
Quinones, Paul	Yearly - Chaparral HS A2 (H/C Unit)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
46260		Athletic Field			6/1/2009		0		\$0.00
Medium	Work In Progress			6/1/2009 7:45:30 AM		6/1/2009			
Aldaz, Bobby	need to fertilize p.e playing fields and softball,baseball fields.								
Guadalupe Ontiveros									
46273					6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 11:01:10 AM					
Carrasco, Danny	Carlos Vigil would like to borrow a blue lift some time this week or asap, please.								
Sandra Almeraz									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
46306					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:44:39 PM				
Solis, Lorenzo		Rm G-6 no gas to class rm, please check solenoid and replace if needed.							
Michael Munoz									
46307					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:46:02 PM				
Solis, Lorenzo		Rm f-6, no gas to solenoids, please check and replace if needed.							
Michael Munoz									
46308					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:47:45 PM				
Solis, Lorenzo		rm-e-7, gas solenoid leaks and needs fuse. please replace if needed.							
Michael Munoz									
46309					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:49:19 PM				
Solis, Lorenzo		rm-B-3, hot water solenoid does not work, please replace or repair if needed.							
Michael Munoz									
46313					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:53:10 PM				
Solis, Lorenzo		rm-f-3, dirty solenoid and no gas, please replace or repair if needed.							
Michael Munoz									
<b>Count: 70 Work Orders</b>			<b>Avg. Age of WO's 77</b>				<b>Total for Chaparral HS</b>	<b>0</b>	<b>\$0.00</b>



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
37050					8/14/2008		292		\$0.00
Medium	Work In Progress			8/14/2008 8:28:32 AM					
Ontiveros, Joe	need to replace shower columns in boys and girls reast rooms. Thxs								
<u>Marti Muela</u>									
38127		Gym			9/16/2008		259		\$0.00
Medium	Work In Progress			9/16/2008 10:22:53 AM					
Ronquillo, Ruben	Asp PM 37575 FXT-CHM -017 Need plexiglass cover. FXT-CHM-018 Need plexiglass cover.								
<u>Eric Medina</u>									
38437					9/25/2008		250		\$0.00
Medium	Work In Progress			9/25/2008 3:39:35 PM					
Sotelo, Enrique	need light covers plastic								
<u>Eric Medina</u>									
38779					10/5/2008	10/26/2008	240		\$0.00
Medium	Work In Progress			10/5/2008 12:24:03 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
40741					12/10/2008		174		\$0.00
Medium	Work In Progress			12/10/2008 11:12:20					
Medina, Eric	About 8 of the exhaust fans in the restrooms or the custodial closets have not been working for a while.		12/16 - Asp Mike route to Eric.						
<u>Robert Gonzalez</u>									
40744					12/10/2008		174		\$0.00
Medium	Work In Progress			12/10/2008 11:20:18					
Medina, Eric	The floors in the boys and girls locker rooms need painting . They look very bad. Mike painted them about five years ago.								
<u>Robert Gonzalez</u>									
41070					1/4/2009	1/25/2009	149		\$0.00
Medium	Work In Progress			1/4/2009 12:18:49 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41253	Main Building	Classroom			1/7/2009		146		\$0.00
Medium	Work In Progress	Room 303, 406,		1/7/2009 3:55:06 PM					
Lozoya, Manny	***URGENT THIRD REQUEST*** NEED KEYS FOR THEIR FILING CABINET HAVE VERY PRIVATE SPED INFO THAT NEEDS TO BE LOCKED UP								
Elena Palacios									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
41651		Classroom			1/20/2009		133		\$0.00
Medium	Work In Progress	ROOM 203		1/20/2009 2:34:58 PM					
Lozoya, Manny		DRAWERS IN HOME EC ROOM DO NOT OPEN NEED TO HAVE THE KEY LOCKS REMOVED							
Elena Palacios									
41653					1/20/2009		133		\$0.00
Medium	Work In Progress			1/20/2009 2:56:17 PM					
Lozoya, Manny		manny need to fix loose door handle in portable 14 and straightend the door for room 312							
Eric Medina									
41877					1/27/2009		126		\$0.00
Medium	Work In Progress	OUTSIDE AND		1/27/2009 9:57:18 AM					
Orozco, Danny		NEED FOR DIMAR TO COME AND CK LEAKING SPRINKLER HEAD.							
Eric Medina									
41980					1/29/2009		124		\$0.00
Medium	Work In Progress			1/29/2009 8:17:34 AM					
Medina, Eric		please order and replace all window screens that are damaged. thxs							
Michael Munoz									
42142					2/2/2009		120		\$0.00
Medium	Work In Progress			2/2/2009 9:50:09 AM					
Lozoya, Manny		I NEED TWO XX2 KEYS ONE FOR CARMEN THE CUSTODIAN THAT CLEANS THAT ROOM 405A AND ONE FOR MYSELF. I LOAN MINE TO THE COMPUTOR TECH THATS IN THAT ROOM							
Robert Gonzalez									
42320		Cafeteria			2/6/2009		116		\$0.00
Medium	Work In Progress			2/6/2009 11:05:24 AM					
Orozco, Danny		FIX OR INSTALL BELL (DELIVERY DOOR) DEMETRIOS P. GIOVAS - SNP DIRECTOR 882-6771							
Alma Terrell									
42703	Main Building	Portables			2/19/2009		103		\$0.00
Medium	Work In Progress	PORTABLE 14		2/19/2009 11:19:25 AM					
Lozoya, Manny		REKEY THE BATHROOM DOOR WE CAN THEN USE THE ROOM FOR STORAGE.							
Elena Palacios									
43731					3/16/2009		78		\$0.00
Medium	Work In Progress			3/16/2009 9:09:28 AM					
Medina, Eric		all fire lanes, curbs and handicap ramps and logos need to be painted. thankyou							
Michael Munoz									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
43732		Portables			3/16/2009		78		\$0.00
Medium	Work In Progress			3/16/2009 9:11:02 AM					
Medina, Eric	Doors to portables need to be painted especially the wooden one where the fire hydrant is in front.								
<u>Michael Munoz</u>									
43781					3/17/2009		77		\$0.00
Medium	Work In Progress			3/17/2009 9:10:57 AM					
Lozoya, Manny	we have a key that is stuck on the door lock the door on the west doors in the main hall exiting to the south								
<u>Robert Gonzalez</u>									
43956	Main Building				3/23/2009		71		\$0.00
Medium	Work In Progress			3/23/2009 1:28:13 PM					
Medina, Eric	GYM LOCKER ROOM DOORS NEED TO BE REPAINTED								
<u>Elena Palacios</u>									
43957	Main Building	Gym			3/23/2009		71		\$0.00
Medium	Work In Progress	BOYS LOCKER		3/23/2009 1:30:16 PM					
Medina, Eric	ENTRANCE TO BOYS LOCKER ROOM NEEDS TWO PLACES TO BE REPAIRED WITH SHEETROCK DUE TO HOLES ON WALLS								
<u>Elena Palacios</u>									
43960	Main Building	Office			3/23/2009		71		\$0.00
Medium	Work In Progress	ENTIRE		3/23/2009 1:35:18 PM					
Medina, Eric	DAMAGED CEILING TILES NEED TO BE REPLACED THROUGHOUT ENTIRE SCHOOL, MANY TILES ARE MISSING								
<u>Elena Palacios</u>									
43961	Main Building	Classroom			3/23/2009		71		\$0.00
Medium	Work In Progress	30		3/23/2009 1:36:20 PM					
Medina, Eric	30 CLASSROOMS NEED WINDOW SCREENS								
<u>Elena Palacios</u>									
44184	Main Building	Restroom (Boys)			4/1/2009		62		\$0.00
Medium	Work In Progress			4/1/2009 3:39:48 PM					
Ontiveros, Joe	joe lavoratory in boys rr is leaking water from lines that go to solenoid valves feeding dispensers								
<u>Eric Medina</u>									
44314					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:42 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
44975	Phase III New	Classroom			4/23/2009		40		\$0.00
Medium	Work In Progress	BAND ROOM			4/23/2009 2:47:36 PM				
Medina, Eric		need to repair walls and paint room							
Eric Medina									
45108		Classroom			4/28/2009		35		\$0.00
Medium	Work In Progress	Science and			4/28/2009 2:12:32 PM				
Medina, Eric		Please set up computer furniture for the Science and Language Arts classrooms. Furniture will be delivered on May 13. Thank you!							
Sandra Almeraz									
45634					5/12/2009		21		\$0.00
Medium	Work In Progress				5/12/2009 9:22:14 AM				
Lozoya, Manny		SECURITY OFFICE DOOR IS VERY HARD TO UNLOCK.							
Robert Gonzalez									
45750					5/15/2009		18		\$0.00
Medium	Work In Progress				5/15/2009 10:14:36 AM				
Estrada, Jesus		I WOULD LIKE TO REQUEST A FIRST AID KIT DURING THE BREAK SOMEONE ALWAYS GETS A CUT OR SCRAPE. A FIRST AID KIT WOULD COME IN HANDY.				6/1/09 - PENDING QUOTE/PURCHASE			
Robert Gonzalez									
45807					5/18/2009		15		\$0.00
Medium	Work In Progress				5/18/2009 3:38:12 PM				
Solis, Lorenzo		Lorenzo need to see if you can order three more 6500 size a/c units							
Eric Medina									
45969	Phase II New	Computer Lab			5/22/2009		11		\$0.00
Medium	Work In Progress	ROOM 208			5/22/2009 2:33:47 PM				
Lozoya, Manny		DOOR CLOSER IN COMPUTER LAB IS LETTING THE DOOR SLAM SHUT							
Elena Palacios									
46096		Gym			5/29/2009		0		\$0.00
Medium	Work In Progress				5/29/2009 10:24:15 AM	5/29/2009			
Lozoya, Manny		WE NEED THE LOCKS IN THE GYM CHANGED BY JUNE 12. WE WILL BE DOING THE GYM ON JUNE 15 THRU JUNE 19. THANKS							
Robert Gonzalez									
46161					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:26 AM				
Medina, Eric		Yearly - Chaparral MS A2 (H/C Unit)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
46162					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:26 AM					
Medina, Eric	Yearly - Chaparral MS B2 (Boiler)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46163					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:27 AM					
Medina, Eric	Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46164					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:27 AM					
Medina, Eric	Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46165					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:27 AM					
Medina, Eric	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46166					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:28 AM					
Medina, Eric	Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46263		Athletic Field			6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 8:00:10 AM					
Aldaz, Bobby	need help to fertilize and aertate football and soccer fields.								
<u>Guadalupe Ontiveros</u>									
46269		Classroom			6/1/2009		1		\$0.00
Medium	Work In Progress	ROOM 405 B		6/1/2009 9:41:01 AM					
Lozoya, Manny	MRS. MENDOZA (DIAG) NEEDS HER FILING CABINET KEYED SHE HAS VERY IMPORTANT DOCUMENTS THAT MUST BE KEPT CONFIDENTIAL								
<u>Elena Palacios</u>									
46271					6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 11:00:04 AM					
Carrasco, Danny	Carlos Vigil would like to request to borrow a blue lift some time this week if possible or asap, please.								
<u>Sandra Almeraz</u>									
<b>Count: 40 Work Orders</b>			<b>Avg. Age of WO's 83</b>				<b>Total for Chaparral MS</b>	<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Pride</b>							
36451		Classroom			8/1/2008		305		\$0.00
Medium	Work In Progress	14,15			8/1/2008 7:22:52 AM				
Castillo, Carlos		EMER. LIGHT DO NOT TURN ON IN BOTH ROOMS WHEN TURNING OFF BREAKER SWITCH FOR TESTING.							
David Acosta									
36452		Library			8/1/2008		305		\$0.00
Medium	Work In Progress				8/1/2008 7:26:27 AM				
Castillo, Carlos		EMER LIGHT WON'T STAY ON VERY LONG WHEN DOING ANNUAL TEST.							
David Acosta									
37699		Classroom			9/2/2008		273		\$0.00
Medium	Work In Progress	1,2			9/2/2008 2:08:10 PM				
Castillo, Carlos		NEED MORE EMERG. EXIT SIGNS. (ASK BY STATE FIREMARSHAL TO REQUEST).							
David Acosta									
39333		Portables			10/21/2008		224		\$0.00
Medium	Work In Progress	16			10/21/2008 11:07:07				
Castillo, Carlos		NEED EXIT SIGN AND EMER. LIGHT FOR LAST PORTABLE (ROOM 16).							
David Acosta									
42847		Parking Lot			2/24/2009		98		\$0.00
Medium	Work In Progress				2/24/2009 2:01:57 PM				
Gonzalez, Salvador		NEED CONCRETE RAMP ACCESSABLE TO OFFICE FOR HANDICAP AND TRUCK DELIVERY				3/3/09 - Route to Sal asp Mike			
David Acosta									
43228		Restroom (Boys)			3/2/2009		92		\$0.00
Medium	Work In Progress	2ND BLDG, 1&2,			3/2/2009 12:13:26 PM				
Lara, Ralph		PRINCIPLE REQUEST TO HAVE LOCK ON RESTROOM DOORS.							
David Acosta									
44051		Office			3/30/2009		64		\$0.00
Medium	Work In Progress				3/30/2009 1:51:00 PM				
Lara, Ralph		NEED TO INSTALL 4X4 SLIDING WINDOW (WITH LOCK ) ON WALL THAT DIVIDES HALL WAY AND DATA CLERK OFFICE							
David Acosta									
44518		Parking Lot			4/7/2009		56		\$0.00
Medium	Work In Progress				4/7/2009 3:54:00 PM				
Ontiveros, Guadalupe		Measure and re-align parking curbs for more parking space.							
Michael Munoz									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Desert Pride</b>								
45107		Classroom			4/28/2009		35		\$0.00	
Medium	Work In Progress	Science and			4/28/2009 2:08:21 PM					
Acosta, David		Please set up furniture for computers that will be delivered on May 12 for the Science and Language Arts classrooms. Thank you.								
<u>Sandra Almeraz</u>										
46035		Library			5/27/2009		6		\$0.00	
Medium	Work In Progress				5/27/2009 2:02:24 PM					
Ontiveros, Guadalupe		NEED HELP WITH SPREADING OUT TWO LOADS OF DIRT HERE AT DP. (FOR THE LUNCH AREA AND LIBRARY BLDG).								
<u>David Acosta</u>										
46065		Pump House			5/28/2009		5		\$0.00	
Medium	Work In Progress	ROOM #5			5/28/2009 9:39:04 AM					
Castillo, Carlos		A COUPLE OF NIGHT LIGHTS STAY ON DURING THE DAY								
<u>David Acosta</u>										
46138					5/31/2009	7/1/2009	2		\$0.00	
Medium	Work In Progress				5/31/2009 12:23:17 AM					
Aguilar, Patricio		Yearly - Desert Pride HS A2 (H/C Unit)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
46139					5/31/2009	6/8/2009	2		\$0.00	
Medium	Work In Progress				5/31/2009 12:23:17 AM					
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
46140					5/31/2009	6/8/2009	2		\$0.00	
Medium	Work In Progress				5/31/2009 12:23:18 AM					
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
46141					5/31/2009	6/6/2009	2		\$0.00	
Medium	Work In Progress				5/31/2009 12:23:18 AM					
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
<b>Count: 15 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>98</b>	<b>Total for Desert Pride</b>			<b>0</b>	<b>\$0.00</b>	

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
38213					9/18/2008		257		\$0.00
Medium	Work In Progress			9/18/2008 12:09:20 PM					
Gonzalez, Salvador	Please weld extra metal to the top of the metal scraper to add on a little more weight to it. Thank You....								
Johnny Acuna									
38780					10/5/2008	10/26/2008	240		\$0.00
Medium	Work In Progress			10/5/2008 12:24:03 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
39012					10/7/2008		238		\$0.00
Medium	Work In Progress			10/7/2008 3:30:52 PM					
Lozoya, Manny	Need a replacement Door and Door Frame for Portable #413 inside Restroom Door.								
Johnny Acuna									
39014					10/7/2008		238		\$0.00
Medium	Work In Progress			10/7/2008 3:33:24 PM					
Lozoya, Manny	Portable #410: Need a Replacement Metal Door.								
Johnny Acuna									
39677					10/31/2008		214		\$0.00
Medium	Work In Progress			10/31/2008 4:09:15 PM					
Gonzalez, Salvador	Need to re-weld stainless sheetmetal sheet together that came apart in the kitchen sink area.								
Johnny Acuna									
39760					11/3/2008		211		\$0.00
Medium	Work In Progress			11/3/2008 7:40:41 AM					
Ronquillo, Ruben	Window frames in the side of the main doors in the NW hall needs to be replaced or repaired. There is too much corrosion.								
Johnny Acuna									
41071					1/4/2009	1/25/2009	149		\$0.00
Medium	Work In Progress			1/4/2009 12:18:50 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
41192					1/6/2009		147		\$0.00
Medium	Work In Progress			1/6/2009 12:08:50 PM					
Lozoya, Manny	Room #117: need assistance in adjusting door frame and door.								
Johnny Acuna									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
41193					1/6/2009		147		\$0.00
Medium	Work In Progress			1/6/2009 12:10:21 PM					
Lozoya, Manny	Portable #412: Door knob is very loose and teacher has problems opening door.								
Johnny Acuna									
41199	Main Building	Classroom			1/6/2009		147		\$0.00
Medium	Work In Progress			1/6/2009 2:18:47 PM					
Lozoya, Manny	Urgente. Cuarto 410 la chapa se quebro, y no se puede cerrar. gracias								
Marisela Torres									
41414					1/12/2009		141		\$0.00
Medium	Work In Progress			1/12/2009 4:08:44 PM					
Lozoya, Manny	Portable #403: (Mrs. Rios): Need to install a new door knob to Portable #403. Has been repaired several times. Door knob gets stuck and the teacher and student's sometimes cannot come out of the classroom. It's the only door to their classroom. (Safety Issue in case of an Emergency).								
Johnny Acuna									
41494					1/14/2009		139		\$0.00
Medium	Work In Progress			1/14/2009 1:33:10 PM					
Ontiveros, Guadalupe	(Need Assistance): Need tractor to dig up 6'ft. in all directions around 2 sets of swings in the playground area and fill in with playground sand. Thank You.....								
Johnny Acuna									
41496					1/14/2009		139		\$0.00
Medium	Work In Progress			1/14/2009 1:45:26 PM					
Lozoya, Manny	Need an oval lock for filing cabinet to the nurse's office. (Student Records).								
Johnny Acuna									
41594		Cafeteria			1/16/2009		137		\$0.00
Medium	Work In Progress			1/16/2009 11:58:05 AM					
Orozco, Danny	Plastic Handle fell off to Sprayer in Dishwashing Area								
Pat Cisneros - SNP Manager 824-3822									
Alma Terrell									
41790	Main Building	Custodial			1/23/2009		56		\$0.00
Medium	Work In Progress			1/23/2009 11:10:22 AM	3/20/2009				
Carbajal, Jimmy	Podria prestarme el extractor de 2 galones?. Gracias.				1/30/09 - DELIVERED EXTRACTOR ( AS LOANER); 4/20/09 - REQUESTED STATUS FROM JIMMY.				
Marisela Torres					4/23/09 - AS PER JIMMY, HAS NOT BEEN PICKED UP YET. MARISELA STILL HAS IT.				

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
41985					1/29/2009		124		\$0.00
Medium	Work In Progress			1/29/2009 10:16:23 AM					
Gonzalez, Salvador		Please re-weld stainless steel sink that came apart in the left corner of the sink tub. (kitchen) (South sink)							
Johnny Acuna									
42029	Main Building	Hallway/Corridor			1/30/2009		123		\$0.00
Medium	Work In Progress			1/30/2009 1:01:18 PM					
Lozoya, Manny		Puerta principal (pasillo kinder) esta caida,							
Marisela Torres									
42144					2/2/2009		120		\$0.00
Medium	Work In Progress			2/2/2009 12:12:43 PM					
Gonzales, Angel		Please repair Echo Blower. (Desert Trail) Got sent over to Auto shop by Memo on Payday. (1/30/09)							
Johnny Acuna									
42594					2/17/2009		105		\$0.00
Medium	Work In Progress			2/17/2009 8:07:41 AM					
Lozoya, Manny		Need a key made for storage cabinet lock in room #204 (Mrs. Stewart). (Will send out core by Mail to Locksmith)							
Johnny Acuna									
43733	Main Building	Restroom (Boys)			3/16/2009		78		\$0.00
Medium	Work In Progress			3/16/2009 9:33:28 AM					
Lozoya, Manny		Puerta de un bano para maestros esta cerrada, no se puede abrir.							
Marisela Torres									
43738	Main Building	Custodial			3/16/2009		78		\$0.00
Medium	Work In Progress			3/16/2009 11:26:13 AM					
Lozoya, Manny		Reemplasar llave ( J master, para Laura ) esta doblada.							
Marisela Torres									
43740					3/16/2009		78		\$0.00
Medium	Work In Progress			3/16/2009 1:12:03 PM					
Acuna, Johnny		NOT GOOD FOR 5 YEAR OLD.- NEED SIGN FOR 6YRS AND OLDER.							
Michael Munoz									
44315					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:42 AM					
Orozco, Danny		Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
44633					4/12/2009	4/28/2009	51		\$0.00
Medium	Work In Progress			4/12/2009 12:21:22 AM					
Acuna, Johnny		Monthly - Desert Trail Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
6/2/2009 9:39:30 AM									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
44919	Main Building	Restroom (Girls)			4/22/2009		41		\$0.00
Medium	Work In Progress				4/22/2009 12:29:51 PM				
Ontiveros, Joe	Sanitarios ninas hall 2 grado, tira demasiada agua por la valvula.								
Marisela Torres									
45078					4/28/2009		35		\$0.00
Medium	Work In Progress				4/28/2009 7:50:29 AM				
Orozco, Danny	There was a Fire Sprinkler Inspection on 4/24/09 for the main building. The system was Red Tagged: Need to replace the Retard Chamber on the fire sprinkler system. It does not deliver the signal to the main panel to trigger the Fire Alarm.								
Johnny Acuna									
45202					4/30/2009		33		\$0.00
Medium	Work In Progress				4/30/2009 12:21:38 AM				
Jacquez, Ricardo	Monthly - Desert Trail - Refer to PM schedule details.								
Margret Villalobos									
45344	Main Building	Restroom (Boys)			5/4/2009		29		\$0.00
Medium	Work In Progress				5/4/2009 11:22:01 AM				
Ontiveros, Joe	PASILLO 2 GRADO . ORINAL ,BANO NINOS , VALVULA TIRANDO MUCHA AGUA,								
Marisela Torres									
45390					5/4/2009		29		\$0.00
Medium	Work In Progress				5/4/2009 3:48:59 PM				
Ontiveros, Joe	need assistance in repair of outdoor waterfountain. (playground)								
Johnny Acuna									
45489		Cafeteria			5/7/2009		26		\$0.00
Medium	Work In Progress				5/7/2009 9:19:56 AM				
Orozco, Danny	ICE MACHINE IS NOT WORKING								
	PAT CISNEROS - SNP MANAGER 824-3822								
Alma Terrell									
45562					5/10/2009	5/26/2009	23		\$0.00
Medium	Work In Progress				5/10/2009 12:19:09 AM				
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
45725		Restroom (Boys)			5/14/2009		19		\$0.00
Medium	Work In Progress				5/14/2009 12:44:13 PM				
Ontiveros, Joe	pasillo 2 grado orinal esta tapado.								
Marisela Torres									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
45779					5/18/2009		15		\$0.00
Medium	Work In Progress			5/18/2009 8:18:46 AM					
Lozoya, Manny		Need to change lock cylinder to Conference room in the Front Office. (Bldg. Mechanic has the cylinder)							
Johnny Acuna									
46094					5/29/2009		4		\$0.00
Medium	Work In Progress			5/29/2009 10:11:30 AM					
Acuna, Johnny		To: Johnny Acuna Need wood studs to replace old broken up wood to portable #402 Deck and ramp.							
Johnny Acuna									
46181					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:33 AM					
Acuna, Johnny		Yearly - Desert Trail ES B2 (Boiler)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
46182					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:34 AM					
Acuna, Johnny		Yearly - Desert Trail ES A2 (H&C Unit)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
46183					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:34 AM					
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
46184					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:34 AM					
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
46185					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:35 AM					
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
46262		Athletic Field			6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 7:53:10 AM					
Holguin, Ramiro		Need help to aerate and fertilize playing fields.							
Guadalupe Ontiveros									
46267	Main Building	Custodial			6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 8:55:42 AM					
Lozoya, Manny		cambiar candado. que no habra j24-j25-j52- j10-							
Marisela Torres									

6/2/2009 9:39:30 AM

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
46333					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 4:55:40 PM				
Sotelo, Enrique	Need assistance in removing 3 Electrical poles from old computer room. Room #110.								
Johnny Acuna									
46334					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 4:56:49 PM				
Lozoya, Manny	Need keys made for cabinets in room #110.								
Johnny Acuna									
<b>Count: 43 Work Orders</b>		<b>Avg. Age of WO's 86</b>		<b>Total for Desert Trail Intermediate</b>				<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
44323					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:45 AM					
Orozco, Danny	Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
36939	Main Building				8/12/2008		294		\$0.00
Medium	Work In Progress			8/12/2008 8:37:50 AM					
Ortiz, Ruben	Tested exit signs (4) are not working 2 in Gym and Cafeteria asp PM 36526.		Need to order thru material request and complete wo once they are replaced.						
Ruben Ortiz									
37044					8/13/2008		-2	8	\$200.00
Medium	Work In Progress			8/13/2008 8:42:58 PM	8/11/2008				
Ortiz, Ruben	To: Carlos Castillo, Electrical There are four Exit signs and light combo that are not working. In the cafeteria and gym, two and two. There are two emergency light that are not working, in the middle hallway and the west hallway. Thank you.								
Ruben Ortiz									
38108					9/15/2008		260		\$0.00
Medium	Work In Progress			9/15/2008 7:13:21 PM					
Villalobos, David	Requesting for plumber to check if two water faucets can be installed for cleaning purposes								
Ruben Ortiz									
39053					10/8/2008		237		\$0.00
Medium	Work In Progress			10/8/2008 5:07:00 PM					
Villalobos, David	To Mike Munoz I was asked by Mr. Carrasco that he needs hot water and more water pressure for the shower in the Special Ed room. There is a child that needs to be bathed often and the water is too cold. He asked for an urgent work order. Mr. Carrasco asked for this work order to be sent directly to you because he wants it ASAP 10/08/08. Child is being bathed in cold water. Thank you.								
Ruben Ortiz									
39404					10/22/2008		223		\$0.00
Medium	Work In Progress			10/22/2008 9:10:57 PM					
Lara, Ralph	Carlos Castillo The button for the handicap door is not working on the southside of the building exit.								
Ruben Ortiz									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
40871		Cafeteria			12/15/2008		169		\$0.00
Medium	Work In Progress				12/15/2008 2:35:04 PM				
Moncayo, Fernando	AS PER DIMAR SYSTEM, RANGE HOOD SYSTEMS REPORT DATED 12/15/08, EXHAUST FAN IS NOT OPERATING.								
Jacqueline Aguilar	DIANA LAZARIN SNP MGR 589-2425								
41887					1/27/2009		126		\$0.00
Medium	Work In Progress				1/27/2009 12:56:50 PM				
Lara, Ralph	please replace exterior door to rm 25. thxs								
Michael Munoz									
41888					1/27/2009		126		\$0.00
Medium	Work In Progress				1/27/2009 12:58:48 PM				
Ortiz, Ruben	please schedule the aerator order seed and fertilizer for the areas on campus that do no have grass in the circle. thxs								
Michael Munoz									
41921					1/28/2009		125		\$0.00
Medium	Work In Progress				1/28/2009 6:49:22 AM				
Moncayo, Fernando	Ladies in cafeteria need a lock for their file cabinet. Hinges on the walk in refrigerator are broken having trouble locking it. Thank you.								
Ruben Ortiz									
42165					2/2/2009		120		\$0.00
Medium	Work In Progress				2/2/2009 9:33:14 PM				
Lara, Ralph	Need a door replaced in room 25; 2 inches from the bottom of the door is rusted through; the replacement has been request by Principal Carrasco. Thank you, Ruben								
Ruben Ortiz									
42230		Portables			2/4/2009		118		\$0.00
Medium	Work In Progress				2/4/2009 2:49:07 PM				
Gonzalez, Salvador	Need to install ramps to portable (see Mike).								
Michael Munoz									
42588					2/13/2009		109		\$0.00
Medium	Work In Progress				2/13/2009 8:18:55 PM				
Villalobos, David	Need wall faucets outside replaced due to leaking. Thank you.								
Ruben Ortiz									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
42616		Cafeteria			2/17/2009		105		\$0.00
Medium	Work In Progress			2/17/2009 11:21:14 AM					
Moncayo, Fernando	WHEELS TO STAINLESS STEEL WORK TABLE NEEDS TO BE REPLACED (WHEELS ARE ROTTED OUT)								
	DIANA LAZARIN - SNP MANAGER 589-2425								
Alma Terrell									
43981					3/24/2009		70		\$0.00
Medium	Work In Progress			3/24/2009 2:51:11 PM					
Munoz, Michael	need to lay concrete to stair and ramp area to tie into asphalt on portable that was moved.								
Michael Munoz									
44009		Restroom (Boys)			3/25/2009		69		\$0.00
Medium	Work In Progress			3/25/2009 9:48:15 AM					
Ortiz, Ruben	This work order is for two urinals in the boys restroom water dont go so fast like it use to do. Please stop by and take care of the problem. THANKYOU IN ADVANCED.		4/6 - Asp Mike, route to Ruben						
Hector Rivera									
44098		Restroom (Boys)			3/31/2009		63		\$0.00
Medium	Work In Progress			3/31/2009 8:04:09 AM					
Ortiz, Ruben	This work order is for new water faucets in the boys and girls restrooms that are broken . THANK YOU IN ADVANCED.		4/6 - Asp Mike, route to Ruben						
Hector Rivera									
44206					4/1/2009		62		\$0.00
Medium	Work In Progress			4/1/2009 9:16:38 PM					
Villalobos, David	To David, I need the outside water fountain faucets in the lower level replaced. Thank you. Ruben								
Ruben Ortiz									
44493					4/7/2009		56		\$0.00
Medium	Work In Progress			4/7/2009 9:08:20 AM					
Ortiz, Ruben	Crusher fine needs to be added along the bottom of the portable.								
Michael Munoz									
44523					4/7/2009		56		\$0.00
Medium	Work In Progress			4/7/2009 10:17:11 PM					
Villalobos, David	The water fountain cooler on the westside wing needs the drain replaced that goes to the trap. I think it's called a pigtail drain, (not quit sure) it's made out of brace. I also need a pressure valve 1/2 inch. Need parts asap children are testing and they need the water fountain working. Thank you, Ruben								
Ruben Ortiz									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
44567					4/8/2009		55		\$0.00
Medium	Work In Progress			4/8/2009 10:03:54 PM					
Ortiz, Ruben	Will need 16 brackets or bearings for the swings. Thank you, Ruben								
Ruben Ortiz									
44900					4/21/2009		42		\$0.00
Medium	Work In Progress			4/21/2009 9:56:36 PM					
Holguin, Alfredo	The new sponge foam that was added to the playground is peeling in different areas, please advice as to what needs to be done to have it fixed. Thank you, Ruben								
Ruben Ortiz									
44901					4/21/2009		42		\$0.00
Medium	Work In Progress			4/21/2009 10:01:38 PM					
Ronquillo, Ruben	Requesting 10 yards of screening to put around the new portable. Thank you, Ruben		Route to Warehouse 4/27						
Ruben Ortiz									
45203					4/30/2009	5/31/2009	33		\$0.00
Medium	Work In Progress			4/30/2009 12:21:39 AM					
Ortiz, Ruben	Yearly - Desert View ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									
45419					5/5/2009		28		\$0.00
Medium	Work In Progress			5/5/2009 2:11:24 PM					
Lara, Ralph	Need key mullium for back dinning room door - hall way door								
Patricio Aguilar									
45621					5/11/2009		22		\$0.00
Medium	Work In Progress			5/11/2009 10:27:48 PM					
Ontiveros, Guadalupe	There is a leaking valve on the westside. Need repairs. Thank you, Ruben								
Ruben Ortiz									
45862					5/20/2009		13		\$0.00
Medium	Work In Progress			5/20/2009 8:18:01 AM					
Ortiz, Ruben	EP Paso Disposal was not able to pick up trash, due to School Function, dumpsters are full. Need to take trash to STHS compactor.								
Michael Munoz									
45949					5/21/2009		12		\$0.00
Medium	Work In Progress			5/21/2009 9:46:21 PM					
Ontiveros, Guadalupe	Need main valves for the sprinkler system to be replaced. Thank you, Ruben								
Ruben Ortiz									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
46234					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:53 AM					
Ortiz, Ruben	Yearly - Desert View ES A-2 A/C SS Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46235					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:53 AM					
Ortiz, Ruben	Yearly - Desert View ES B-2 Boiler Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46236					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:54 AM					
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46237					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:54 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46238					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:54 AM					
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46321					6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 4:03:36 PM					
Ortiz, Ruben	please repair pot holes on main entrace drive. order material from maintence warehose.thxs								
<u>Michael Munoz</u>									
46322		Classroom			6/1/2009		1		\$0.00
High	Work In Progress			6/1/2009 4:05:37 PM					
Ortiz, Ruben	a new exterior door was installed on the corner southeast class room. please finish painting w/ an oil base.								
<u>Michael Munoz</u>									
46323					6/1/2009		1		\$0.00
High	Work In Progress			6/1/2009 4:07:14 PM					
Ortiz, Ruben	the side and back yard need water. please check system to all stations for proper operation and irrigate. thxs								
<u>Michael Munoz</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
46325					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 4:08:57 PM				
Ortiz, Ruben	on the west side yard there are tree brancehes that need to be picked up and disposed of and remove the dead pine tree.								
	thxs								
Michael Munoz									
<b>Count: 37 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>73</b>		<b>Total for Desert View ES</b>		<b>8</b>	<b>\$200.00</b>	

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
36280					7/28/2008		309		\$0.00
Medium	Work In Progress	Back bottom road		7/28/2008 12:11:48 PM					
Ontiveros, Guadalupe		need to apply dirt and crusherfine in back road due to running water after haevy rain.							
Juan Ambriz									
36334		Parking Lot			7/29/2008		308		\$0.00
Medium	Work In Progress	bottom dirt		7/29/2008 3:47:57 PM					
Ontiveros, Guadalupe		Need to apply more crusherfine in bottom dirt parking lot accumulating water after rain							
Juan Ambriz									
36949		Office			8/12/2008		294		\$0.00
Medium	Work In Progress	A-WING		8/12/2008 10:35:44 AM					
Ambriz, Juan		IF IT WOULD BE POSSIBLE TO HAVE THE AIR VENTS IN JESUS REYE'S OFFICE ADJUSTED. NOT ENOUGH AIR COMES THROUGH.							
Mary Garcia									
37912		Parking Lot			9/8/2008		267		\$0.00
Medium	Work In Progress	bottom dirt		9/8/2008 3:39:17 PM					
Ontiveros, Guadalupe		Need to level bottom parking lot with crusher fine to avoid accumulated water after rains							
Juan Ambriz									
37939					9/9/2008		266		\$0.00
Medium	Work In Progress	Back dirt road		9/9/2008 8:25:56 AM					
Ontiveros, Guadalupe		need to add dirt to back dirt road due to running water after rains. If possible add crusher fine.							
Juan Ambriz									
39366		Office			10/22/2008		223		\$0.00
Medium	Work In Progress	C-WING		10/22/2008 9:54:03 AM					
Ambriz, Juan		AS PER ALFREDO-GO AHEAD AND SEAL OFF THE WALL WHERE THE AIR UNIT WAS IN OFELIA'S OFFICE.				APPROVED BY ALFREDO			
Mary Garcia									
40674	RTC	Parking Lot			12/8/2008		32	1	\$25.00
Medium	Work In Progress	RTC ACROSS		12/8/2008 2:30:07 PM		1/9/2009			
Soria, Mike		AS PER GLORIA SAENZ-NEED TO HAVE THE DIRT REMOVED FROM THE PARKING LOT.				Completed asp report 1/9/09			
Mary Garcia									
41072					1/4/2009	1/25/2009	149		\$0.00
Medium	Work In Progress			1/4/2009 12:18:50 AM					
Orozco, Danny		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									
<b>Location:</b>		<b>GAC</b>							
41865					1/26/2009		127		\$0.00
Medium	Work In Progress	OUTSIDE AND		1/26/2009 4:09:18 PM					
Orozco, Danny		AS PER JUAN AMBRIZ-NEED FOR DIMAR TO COME IN AN RECAP A PIPE THAT IS LEAKING WATER. (TO ASK FOR JUAN WHEN DIMAR COMES IN)				DAVID VILLALOBOS ALREADY LOOKING INTO THIS SITUATION AND SUGGESTED FOR JUAN TO PUT IN A WORK ORDER FOR DIMAR TO TAKE CARE OF THIS.			
Mary Garcia									
41937	RTC	Portables			1/28/2009		125		\$0.00
Medium	Work In Progress	RTC ACROSS		1/28/2009 10:42:26 AM					
Ambriz, Juan		AS PER GLORIA SAENZ-KEYS UNABLE TO OPEN CLASSROOM-MS. MORALES, MAYBE DUE TO DUST.							
Mary Garcia									
42414	Pre-K	Cafeteria			2/10/2009		112		\$0.00
Medium	Work In Progress	PRE-K		2/10/2009 11:21:26 AM					
Ambriz, Juan		AS PER MS. BERRY- NEED HELP W/ 2 WALL HANINGS IN THE CAFETERIA.							
Mary Garcia									
42453	RTC	Portables			2/10/2009		112		\$0.00
Medium	Work In Progress	RTC ACROSS		2/10/2009 3:53:38 PM					
Ambriz, Juan		AS PER GLORIA SAENZ-NEED TO HAVE THE RAMP BOARDS REPLACED. (THERE IN REAL BAD SHAPE DUE TO RAIN)				2/29/09 - Have you ck'd w/Warehouse on the status of supplies? - mkv			
Mary Garcia									
42625		Parking Lot			2/17/2009		105		\$0.00
Medium	Work In Progress	bottom dirt		2/17/2009 2:13:55 PM					
Ontiveros, Guadalupe		Need to level and add crusher fine both west and east ends to add more parking spaces.							
Juan Ambriz									
43031		Office			2/27/2009		95		\$0.00
Medium	Work In Progress	A-WING		2/27/2009 10:29:17 AM					
Ambriz, Juan		AS PER CALIXTO-NEED MAINTENANCE (JUAN) TO INSTALL BASE BOARDS AROUND THE AREA WHERE FURNITURE WAS REMOVED, DUE TO THE REMODELING OF THERE OFFICE.				2/29/09 - Juan have you ck'd w/warehouse for staus? - mkv			
Mary Garcia									
43126					3/1/2009		93		\$0.00
Medium	Work In Progress			3/1/2009 12:23:03 AM					
Orozco, Danny		Yearly - GAC Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
43376		Office			3/5/2009		89		\$0.00
Medium	Work In Progress	C-WING			3/5/2009 1:37:51 PM				
Ambriz, Juan	AS PER KARLA QUEZADA-NEED HELP IN TRANSFERING THE FURNITURE FROM CONFERENCE ROOM #2 INTO MPT'S OFFICES (SHIRLEY & VICKI)								
Mary Garcia									
43646					3/12/2009		82		\$0.00
Medium	Work In Progress				3/12/2009 10:14:04 AM				
Munoz, Michael	Install fencing on south side where none exists.								
Alfredo Holguin									
43822					3/18/2009		76		\$0.00
Medium	Work In Progress				3/18/2009 7:37:31 AM				
Ambriz, Juan	as per our conversation, please dispose of exhaust fans the are not working by the morgan bldgs, and pick-up and deliver the railroad ties by the tennis courts.continue on the cleaning around your morgan bldg. thxs								
Michael Munoz									
43930					3/20/2009		74		\$0.00
Medium	Work In Progress				3/20/2009 2:21:10 PM				
Villalobos, David	Having problems with hot water								
Juan Ambriz									
44144	B-Wing	Hallway/Corridor			3/31/2009		63		\$2.99
Medium	Work In Progress	Human			3/31/2009 3:53:32 PM				
Ambriz, Juan	Handicap door not working								
Juan Ambriz									
44251	Pre-K	Cafeteria			4/3/2009		60		\$0.00
Medium	Work In Progress	PRE-K			4/3/2009 10:37:37 AM				
Ambriz, Juan	AS PER MS. BERRY-NEED TO HAVE 2 NEW SAND & WATER TABLES ASSEMBLED.								
Mary Garcia									
44316					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress				4/5/2009 12:22:42 AM				
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
44336					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress				4/5/2009 12:22:49 AM				
Orozco, Danny	Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC</b>							
44389					4/5/2009	4/21/2009	58		\$0.00
Medium	Work In Progress				4/5/2009 12:23:07 AM				
Ambriz, Juan		Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.							
Margret Villalobos									
44479					4/6/2009		57		\$0.00
Medium	Work In Progress				4/6/2009 3:50:07 PM				
Ambriz, Juan		please paint yellow lines and arrows in bus turn around and any where else that need painting. thxs							
Michael Munoz									
44599		Parking Lot			4/9/2009		54		\$0.00
Medium	Work In Progress	Flag pole			4/9/2009 3:53:55 PM				
Ambriz, Juan		Need to replace flag pole rope and hooks.							
Juan Ambriz									
44798		Restroom (Girls)			4/17/2009		46		\$0.00
Medium	Work In Progress	B-Wing HR Dept			4/17/2009 3:14:03 PM				
Castillo, Carlos		Need to run power to exhaust fan.							
Juan Ambriz									
44800		Restroom (Girls)			4/17/2009		46		\$0.00
Medium	Work In Progress	C-Wing behind			4/17/2009 3:16:22 PM				
Castillo, Carlos		Need to run power to exhaust fan							
Juan Ambriz									
44834		Parking Lot			4/20/2009		43		\$0.00
Medium	Work In Progress	Exterior lighting			4/20/2009 3:33:33 PM				
Castillo, Carlos		Breaker keeps tripping for the exterior lighting							
Juan Ambriz									
44852					4/21/2009		42		\$0.00
Medium	Work In Progress				4/21/2009 8:37:06 AM				
Orozco, Danny		Gauges are outdated, need to be replaced asp inspection by Century Fire.							
Michael Munoz									
44853					4/21/2009		42		\$0.00
Medium	Work In Progress				4/21/2009 8:39:04 AM				
Orozco, Danny		Water motor gong not working, asp inspection by Century Fire Systems. Please repair or acquire quote.							
Michael Munoz									
44854					4/21/2009		42		\$0.00
Medium	Work In Progress	B-Wing			4/21/2009 8:41:28 AM				
Orozco, Danny		East cooridor (B-Wing) need to relocate and plug one fire sprinkler head, asp inspection by Century Fire Systems.							
Michael Munoz									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>GAC</b>								
44927	RTC	Office			4/22/2009		41		\$0.00	
Medium	Work In Progress	RTC ACROSS		4/22/2009 1:23:23 PM						
Ambriz, Juan		AS PER GLORIA SAENZ-NEED TO HAVE 2 LARGE BOXED PICKED UP AND BROUGHT OVER TO THE SPED OFFICE.								
Mary Garcia										
44928		Office			4/22/2009		41		\$0.00	
Medium	Work In Progress	B-WING		4/22/2009 1:24:50 PM						
Ambriz, Juan		AS PER ANNE-NEED TO HAVE AN EXTRA LIGHT TURNED ON BY RICHARD ACOSTA OFFICE FOR PSFA AUDITORS, IT'S TO DARK								
Mary Garcia										
44929		Office			4/22/2009		41		\$0.00	
Medium	Work In Progress	A WING		4/22/2009 1:26:31 PM						
Ambriz, Juan		AS PER CORA-NEED TO HAVE HER AIR UNIT CHECK, BECAUSE IT'S THROWING HOT AIR.								
Mary Garcia										
44930		Office			4/22/2009		41		\$0.00	
Medium	Work In Progress	A WING		4/22/2009 1:27:45 PM						
Ambriz, Juan		AS PER MARY GARCIA-NEED TO HAVE AN EXTRA LIGHT TURNED ON THE THE FILE ROOM, IT'S TO DARK.								
Mary Garcia										
44969	Pre-K				4/23/2009		40		\$0.00	
Medium	Work In Progress	PRE-K		4/23/2009 1:56:40 PM						
Ambriz, Juan		AS PER MS. BERRY-NEED TO ASSEMBLE A DID SIZE COTTAGE								
Mary Garcia										
44970	Pre-K				4/23/2009		40		\$0.00	
Medium	Work In Progress	PRE-K		4/23/2009 2:00:16 PM						
Ambriz, Juan		AS PER MS. BERRY-WOULD LIKE THE LITTLE PLOT OF IDT TURNED OVER SO THEY CAN ADD SOME SOIL TO IT, BECAUSE IT'S AS HARD AS A ROCK.								
Mary Garcia										
45029	Pre-K	Parking Lot			4/24/2009		39		\$0.00	
Medium	Work In Progress	PRE-L PARKING		4/24/2009 4:54:31 PM						
Ambriz, Juan		AS PER MS. BERRY-NEED CHALK LINES DRAWN AND CONES IN THE BUS AREA FOR A TRIKE-A-TON ON 4/30/09. ALREADY TALKED W/JUAN AMBRIZ								
Mary Garcia										
45176		Office			4/29/2009		34		\$0.00	
Medium	Work In Progress	Georgina's office		4/29/2009 3:52:15 PM						
Ambriz, Juan		As per Ms. Georgina Install keyboard holder.								
Juan Ambriz										



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>GAC</b>								
45225		Office			4/30/2009		33		\$0.00	
Medium	Work In Progress	B-Wing Norma			4/30/2009 3:55:32 PM					
Ambriz, Juan		As per Norma Reyes need to Install flipper cabinet in the office								
Juan Ambriz										
45242		Office			5/1/2009		32		\$0.00	
Medium	Work In Progress	C-Wing			5/1/2009 12:39:53 PM					
Ambriz, Juan		As per Ms. Sheila Raihl need to Install new door stop.								
Juan Ambriz										
45343		Cafeteria			5/4/2009		29		\$0.00	
Medium	Work In Progress				5/4/2009 10:45:27 AM					
Moncayo, Fernando		HOT UNIT SERVING AREA - PIPE CORRODED FROM UNIT TO THE DRAIN AREA								
		GESSICA BLAZQUEZ - SNP MANAGER 882-6784								
Alma Terrell										
45494		Office			5/7/2009		26		\$0.00	
Medium	Work In Progress	A-WING			5/7/2009 1:36:13 PM					
Ambriz, Juan		AS PER CORA-NEED TO HAVE THE AC UNIT CHECKED AND CLEANED OUT, THROWING HOT AIR.								
Mary Garcia										
45540	Pre-K				5/8/2009		25		\$0.00	
Medium	Work In Progress	PLAYGROUND			5/8/2009 2:50:03 PM					
Ambriz, Juan		AS PER MS. BERRY-NEED TO HAVE A SAND & WATER TABLE ASSEMBLED.								
Mary Garcia										
45541	Pre-K				5/8/2009		25		\$0.00	
Medium	Work In Progress	PLAYGROUND			5/8/2009 2:52:12 PM					
Ambriz, Juan		AS PER MS. BERRY-NEED TO HAVE 2 DECK BOXES ASSEMBLED AND SCREWED INTO THE CEMENT OUT IN THE PLAYGROUND								
Mary Garcia										
45605					5/11/2009		22		\$0.00	
Medium	Work In Progress	SM SCHOOL			5/11/2009 3:37:25 PM					
Vega, Danny		AS PER MR. SONJA W/ADVANCE (915) 383-6135- WOULD LIKE TO HAVE SOMEONE OPEN THE SAN MIGUEL SCHOOL @ 9:15AM. MR. TRUJILLO FROM NMSU WANTS TO GO IN TO SEE THE SCHOOL.				OKAY AS PER MR. RICHARD G. CHAVEZ.				
Mary Garcia										
45609	Pre-K	Classroom			5/11/2009		22		\$0.00	
Medium	Work In Progress	PRE-K			5/11/2009 3:43:45 PM					
Villalobos, David		AS PER MS. ALICE-STATES THAT THERE IS NO WATER IN CLASSROOM 102.								
Mary Garcia										

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
45708					5/14/2009		19		\$0.00
Medium	Work In Progress			5/14/2009 8:54:25 AM					
Lara, Ralph	NEED TO MAKE 20 KEYS FOR CART TO POLYCOMS LOCATED AT DIFFERENT SITES.								
	JERRY WITH EQ CONSULTING SPOKE WITH RAFAEL LARA.								
	PLEASE MAKE ONE KEY TO TEST IN CART AT SUNLAND PARK COMPUTER LAB. PICK UP ORGINIAL KEY WITH CORA AT GAC.								
Cora Ramirez									
45723		Restroom (Girls)			5/14/2009		19		\$0.00
Medium	Work In Progress	A-Wing FER-GAC		5/14/2009 12:27:29 PM					
Castillo, Carlos	Need to repair exhaust fan in restroom not working (no power).								
Juan Ambriz									
45724		Restroom (Boys)			5/14/2009		19		\$0.00
Medium	Work In Progress	A-Wing Handicap		5/14/2009 12:28:57 PM					
Castillo, Carlos	Need to repair exhaust fan in handicap restroom not working (no power).								
Juan Ambriz									
45784		Restroom (Girls)			5/18/2009		15		\$0.00
Medium	Work In Progress	A-WING GIRLS		5/18/2009 10:43:05 AM					
Ambriz, Juan	AS PER ELISA-WHEN EVER TIME PERMITS, IF THE BATHROOM CAN GET PAINTED. PAINT HAS BEEN PROVIDED BY ALL SECRETARIES IN A WING.				OK AS PER MR. CHAVEZ				
Mary Garcia									
45785		Office			5/18/2009		15		\$0.00
Medium	Work In Progress	C-WING		5/18/2009 11:50:00 AM					
Ambriz, Jose	AS PER DAVID AVILA-AIR UNIT IS MAKING TO MUCH NOISE AND DOES NOT ALLOW US TO EVEN HEAR THE PHONE OR EACH OTHER WHEN TALKING.								
Mary Garcia									
45842		Grounds			5/19/2009		14		\$0.00
Medium	Work In Progress	GROUND		5/19/2009 2:18:04 PM					
Castillo, Carlos	AS PER MIKE SORIA-NEEDS A HEAVY DUTY ELECTRICAL EXTENSION CORD FOR HIS STORAGE.				AS PER MIKE SORIA, CALI IS ALREADY AWARE OF WHAT HE NEEDS.				
Mary Garcia									
45843		Mechanical Room			5/19/2009		14		\$0.00
Medium	Work In Progress	A WING		5/19/2009 2:19:05 PM					
Ambriz, Juan	AS PER ELISA-MR. YTURREALDE NEEDS A PLAQUE TO BE HUNG IN HIS OFFICE.								
Mary Garcia									

**1049 - Work Orders In Progress (Fiscal Year)**

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
45925		Office			5/21/2009		12		\$0.00
Medium	Work In Progress	A-WING			5/21/2009 3:02:18 PM				
Ambriz, Juan		AS PER MARY GARCIA-NEED TO HAVE ALL OFFICE LIGHTS TURNED ON.				APPROVED BY MR. RICHARD G. CHAVEZ			
Mary Garcia									
45939		Office			5/21/2009		12		\$0.00
Medium	Work In Progress	Carolyn Gressitt			5/21/2009 3:27:56 PM				
Ambriz, Juan		As per Carolyn Gressitt need to check lights not turning on.							
Juan Ambriz									
45942		Office			5/21/2009		12		\$0.00
Medium	Work In Progress	vehicle#140			5/21/2009 3:38:44 PM				
Gonzales, Angel		Need to do oil change and filters replacement							
Juan Ambriz									
45947	Pre-K	Cafeteria			5/21/2009		12		\$0.00
Medium	Work In Progress	PRE-K			5/21/2009 3:58:37 PM				
Ambriz, Juan		AS PER MS. BERRY-NEED TO HAVE 2 SMALL TABLES ASSEMBLED. (1 CHALK & DRAW TABLE AND 1 LISTENING STATION TABLE.)							
Mary Garcia									
45960					5/22/2009		11		\$0.00
Medium	Work In Progress				5/22/2009 11:19:51 AM				
Castillo, Carlos		Requesting approval for a controlled electrical shutdown to test new transfer switches for proper operation and determine where emergency lighting is needed as per w.o.#32027.							
Carlos Castillo									
46011		Restroom (Girls)			5/26/2009		7		\$0.00
Medium	Work In Progress	A WING			5/26/2009 4:03:30 PM				
Ambriz, Juan		AS PER MARTHA-NEED TO HAVE THE LIGHT BULBS REPLACED IN THE GIRLS BATHROOM.							
Mary Garcia									
46012		Restroom (Girls)			5/26/2009		7		\$0.00
Medium	Work In Progress	B-WING GIRLS			5/26/2009 4:05:23 PM				
Ambriz, Juan		AS PER JUAN AMBRIZ-NEED TO HAVE THE LIGHT COVER REPLACED. (COVER IS BROKEN)				JUAN WILL CALL RUBEN TO CHECK AND SEE IF ONE IS IN STOCK.			
Mary Garcia									
46068		Parking Lot			5/28/2009		5		\$0.00
Medium	Work In Progress	Exterior light pole			5/28/2009 10:24:06 AM				
Castillo, Carlos		Need to rehung ballast in light pole. Hanging dangerous for traffic.							
Juan Ambriz									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
46069					5/28/2009		5		\$0.00
Medium	Work In Progress	LINE LOCATE		5/28/2009 10:26:45 AM					
Castillo, Carlos		Need to line locate at SW Area. (See Juan Ambriz, Building Mechanic for specifics)							
Michael Munoz									
46072					5/28/2009		5		\$0.00
Medium	Work In Progress	LINE LOCATE		5/28/2009 10:56:06 AM					
Villalobos, David		Need to line locate at SW Area. (See Juan Ambriz, Building Mechanic for specifics)							
Michael Munoz									
46092		Parking Lot			5/29/2009		4		\$0.00
Medium	Work In Progress			5/29/2009 8:36:35 AM					
Barrientos, Manuel		Need Manny Barrintos to transport lift from the Gac to Sta.Teresa Elementary							
Carlos Castillo									
46195					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:38 AM					
Ambriz, Juan		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
46196					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:39 AM					
Ambriz, Juan		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
46197					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:39 AM					
Ambriz, Juan		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
46198					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:39 AM					
Ambriz, Juan		Yearly - GAC A-2 Package Unit Gas Yearly - Refer to PM schedule details.							
Margret Villalobos									
46337		Office			6/1/2009		1		\$0.00
Medium	Work In Progress	C-WING		6/1/2009 5:27:16 PM					
Ambriz, Jose		AS PER CARMEN M. - NEED TO HAVE HER AIR UNIT CHECK OUT, BECAUSE IT'S TO HOT AND NEED TO HAVE COPIES COOLED OFF.							
Mary Garcia									
<b>Count: 71 Work Orders</b>		<b>Avg. Age of WO's 61</b>		<b>Total for GAC</b>		<b>1</b>	<b>\$27.99</b>		

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Gadsden HS

35876	Main Building	Office			7/11/2008		326		\$0.00
Medium	Work In Progress				7/11/2008 2:28:45 PM				
Carrasco, Danny	NEED NEW BLINDS FOR PRINCIPAL CHAMBERS OFFICE								
		1. 40" X 5'							
		2. 7' X 5'							

Mario Apodaca

36000	Library	Library			7/16/2008		321		\$0.00
Medium	Work In Progress				7/16/2008 3:18:40 PM				
Ontiveros, Guadalupe	An irrigation control box has a water leak underneath the asphalt outside the southwest exit.								

Albert Vallejo

36066	North Building	Classroom			7/18/2008		319		\$0.00
Medium	Work In Progress				7/18/2008 3:19:18 PM				
Ronquillo, Ruben	NEED NEW WINDOW BLINDS (35"WX56"L) FOR ROOM 207 NEED 11 EA								

Mario Apodaca

36067	Old English Bldg	Classroom			7/18/2008		319		\$0.00
Medium	Work In Progress				7/18/2008 3:21:06 PM				
Ambriz, Jose	NEED A NEW HEATING CONDESER AT ROOM 141 DO TO VANDALISM								

Mario Apodaca

36310	Cafeteria (1998)	Cafeteria			7/29/2008		308		\$0.00
Medium	Work In Progress				7/29/2008 8:10:33 AM				
Moncayo, Fernando	NEED A SAFETY POWER DISCONNECT TO THE GHS WALK-IN'S (BOTH) ON THE CONDENSER UNITS ON THE ROOF					11/18 - Asp Mike route to Fernie			
	MR. DEMETRIIOUS GIOVAS								

Jacqueline Aguilar

36622					8/4/2008		302		\$0.00
Medium	Work In Progress	WWT			8/4/2008 4:10:54 PM				
Sanchez, Raul	Replace motor for Wastewater Treatment Plant Blowers.								

Raul Sanchez

36878	Boys Gym				8/11/2008		295		\$0.00
Medium	Work In Progress				8/11/2008 8:35:04 AM				
Marquez, Gerardo	new shower column was installed in girls dressing room. need to install tile to complete project.see mike. thxs								

Michael Munoz

37049	Football Stadium	Football Field			8/14/2008		292		\$0.00
Medium	Work In Progress				8/14/2008 8:14:03 AM				
Munoz, Michael	Some of the concrete piers that support the bleachers are cracked and need to be repaired.								

Albert Vallejo

6/2/2009 9:39:31 AM

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
37094	Cafeteria (1998)	Cafeteria			8/14/2008		292		\$0.00
Medium	Work In Progress			8/14/2008 3:40:19 PM					
Ambriz, Jose	ALL OUTSIDE DUCTS OF THE CAFE BLDG NEED TO BE RESEAL DOTO SUN AND WATER DAMAGE. ASAP								
<u>Mario Apodaca</u>									
37232	Old English Bldg	Classroom			8/20/2008		286		\$0.00
Medium	Work In Progress			8/20/2008 2:03:04 PM					
Carrasco, Danny	NEED NEW WINDOW MINI BLINDS DOTO VANDALISM (W43 1/2" X L90") NEED #4								
<u>Mario Apodaca</u>									
37400					8/26/2008		280		\$0.00
Medium	Work In Progress			8/26/2008 3:35:15 PM					
Castillo, Carlos	Requested by Mr. Roberson for Rm. 127 Main Building- Install on/off switch for lights in room #127. When room was divided switch was left in room #128.								
<u>Velia Alarcon</u>									
37431					8/27/2008		279		\$0.00
Medium	Work In Progress			8/27/2008 8:10:43 AM					
Gonzalez, Salvador	NEED TO CONSTRUCT SHADE AT GROUNDS DEPT. TO PROTECT IMPLEMENT.								
<u>Guadalupe Ontiveros</u>									
37996	Agricultural	Classroom			9/10/2008		265		\$0.00
Medium	Work In Progress			9/10/2008 3:10:19 PM					
Ronquillo, Ruben	need new window blinds for room 568.ea 2 (60 1/2"x45")								
<u>Mario Apodaca</u>									
38286					9/22/2008		253		\$0.00
Medium	Work In Progress			9/22/2008 10:13:18 AM					
Apodaca, Mario	Requested by Ms. Lam Rm. 104 Main Building-Holder of the glass door of the south book shelf is broken.								
<u>Velia Alarcon</u>									
38287					9/22/2008		253		\$0.00
Medium	Work In Progress			9/22/2008 10:30:07 AM					
Villalobos, David	Requested by Ms. Lam Rm. 104 Main Building-Both cold and hot water of the faucet on the south side have sulfur smell.								
<u>Velia Alarcon</u>									
38296					9/22/2008		253		\$0.00
Medium	Work In Progress			9/22/2008 11:16:00 AM					
Vallejo, Albert	Requested by Ms. Roth Rm. 213 North Building-Legs are loose on various HEAVY lab tables and need to be tightened and possibly secured. Table tops are not attached to certain tables and also pose a safety hazard and noise maker.								
<u>Velia Alarcon</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
38429	Academic Bldg	Classroom			9/25/2008		250		\$0.00
Medium	Work In Progress				9/25/2008 2:39:13 PM				
Carrasco, Danny	need windos blinds (46 3/4" x 62") for the academic bldg need 10								
Mario Apodaca									
38497					9/29/2008		246		\$0.00
Medium	Work In Progress				9/29/2008 10:57:19 AM				
Ontiveros, Guadalupe	Requested by Julio Alcantar for Student Parking Lot- Need more electrical poles to help mark the parking spaces in the student parking lot.					2/17/09 - Asp Mike, route to Lupe. Danny C.			
Velia Alarcon									
38744					10/5/2008		240		\$0.00
Medium	Work In Progress				10/5/2008 12:23:50 AM				
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.					10/6/08 - Emailed to Ricky Borrego			
Margret Villalobos									
38790					10/5/2008	10/26/2008	99		\$0.00
Medium	Work In Progress				10/5/2008 12:24:06 AM	1/12/2009			
Orozco, Danny	Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
39073	Agricultural	Classroom			10/9/2008		236		\$0.00
Medium	Work In Progress				10/9/2008 3:15:51 PM				
Ronquillo, Ruben	need a window blind for room 569 (60"x48")								
Mario Apodaca									
39823	Auto Shop	Classroom			11/4/2008		210		\$0.00
Medium	Work In Progress				11/4/2008 3:05:39 PM				
Lara, Ralph	need 2 new doors at the auto shop the doors are broken do to vandalism					Pending - No Funding - Received quote for 1,205.00 from Architectural Products. asp Mike			
Mario Apodaca									
40054	Old English Bldg	Gym			11/13/2008		201		\$0.00
Medium	Work In Progress				11/13/2008 3:05:05 PM				
Munoz, Michael	the girls gym need work on the gym floor do to roof leaks . A.S.A.P								
Mario Apodaca									
40182	Auto Shop	Classroom			11/18/2008		196		\$0.00
Medium	Work In Progress				11/18/2008 1:01:06 PM				
Moncayo, Fernando	NEED TO REMOVE THE OLD WASHER AT STORED IN THE AUTO SHOP. AT WAS IN THE KITCHEN ASAP.								
Mario Apodaca									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
40542	Old English Bldg	Restroom (Girls)			12/3/2008		181		\$0.00
Medium	Work In Progress				12/3/2008 2:51:58 PM				
Lara, Ralph	need a new door for the girls restroom at the old eng bldg at the top floor. asap.								
<u>Mario Apodaca</u>									
40695	Old English Bldg				12/9/2008		175		\$0.00
Medium	Work In Progress				12/9/2008 12:33:28 PM				
Ambriz, Jose	Girls Gym - Need to check heating and control dampers in gym.								
<u>Michael Munoz</u>									
40707	Library	Library			12/9/2008		175		\$0.00
Medium	Work In Progress				12/9/2008 2:59:42 PM				
Ambriz, Jose	NEED A NEW GAS VALVE FOR A HEATING UNIT AT THE LIBRARY								
<u>Mario Apodaca</u>									
40893		Athletic Field			12/16/2008		168		\$0.00
Medium	Work In Progress				12/16/2008 9:23:01 AM				
Ontiveros, Guadalupe	Requested by Mr. Lawrence for Soccer Field-Over seed soccer field, top soil for soccer field.								
<u>Velia Alarcon</u>									
40898					12/16/2008		168		\$0.00
Medium	Work In Progress				12/16/2008 10:00:05				
Ronquillo, Ruben	Requested by Coach Hite Football J.V. Locker Room in Boy's Gym-Install a mirror in J.V. locker room. Please make mirror as large as possible, alot of students need to use it at the same time.								
<u>Velia Alarcon</u>									
41149					1/4/2009		149		\$0.00
Medium	Work In Progress				1/4/2009 12:19:23 AM				
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.					1/6/09 - E-mailed to ricky.borrego@cummins.com'			
<u>Margret Villalobos</u>									
41205	Academic Bldg				1/6/2009		147		\$0.00
Medium	Work In Progress				1/6/2009 3:21:19 PM				
Ambriz, Jose	the heating unit at the greenhous need a new fan moter								
<u>Mario Apodaca</u>									
41271	North Building	Gym			1/8/2009		145		\$0.00
Medium	Work In Progress				1/8/2009 2:36:51 PM				
Ronquillo, Ruben	NEED A NEW GLASS SHELV PUT IN AT THE DLSPLAY CASES(76"X12"1/4")								
<u>Mario Apodaca</u>									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
41732	Cafeteria (1998)	Cafeteria			1/22/2009		131	11	\$275.00
Medium	Work In Progress				1/22/2009 12:38:06 PM				
Moncayo, Fernando	THE WHEELS ON THE CAFE TABLES NEED TO BE ADJUST ON ALL TABLES. A.S.A.P!!!!!!								
<u>Mario Apodaca</u>									
41799	Main Building	Office			1/23/2009		130		\$0.00
Medium	Work In Progress				1/23/2009 2:38:36 PM				
Lara, Ralph	NEED A NEW DOOR FOR MR. CHEMBERS OFFICE. A.S.A.P								
<u>Mario Apodaca</u>									
42049	Academic Bldg	Classroom			1/30/2009		123		\$0.00
Medium	Work In Progress	Academic 306			1/30/2009 4:00:26 PM				
Castillo, Carlos	I'm also running 10 computers off of 3 power outlets. I have talked to Victor and he agrees that the wiring in my room is a problem. I did ask for this last year and I was told that it would be taken care of but I have not been told when that will happen.								
<u>Erica Acosta</u>									
42301	New Vocational				2/6/2009		116		\$0.00
Medium	Work In Progress				2/6/2009 8:27:10 AM				
Lara, Ralph	need new restroom toilet partitons at the boys restroom. do to vandalism								
<u>Mario Apodaca</u>									
42319	Cafeteria (1998)	Cafeteria			2/6/2009		116		\$0.00
Medium	Work In Progress				2/6/2009 11:04:33 AM				
Moncayo, Fernando	FIX OR INSTALL BELL (DELIVERY DOOR)								
	DEMETRIOUS P. GIOVAS - SNP DIRECTOR 882-6771								
<u>Alma Terrell</u>									
42389					2/9/2009		113		\$0.00
Medium	Work In Progress				2/9/2009 3:26:54 PM				
Moncayo, Fernando	THE DELI CART AT ROOM 233 IS AT 49 NEED TO BE AT 38 OR LOWER. ASAP.								
<u>Mario Apodaca</u>									
42546	Academic Bldg	Classroom			2/13/2009		109		\$0.00
Medium	Work In Progress				2/13/2009 8:10:20 AM				
Lara, Ralph	NEED A NEW DOOR CLOSER FOR CLASSROOM AT THE ACADEMIC BLDG TO ROOM 333								
<u>Mario Apodaca</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
42551	Cafeteria (1998)				2/13/2009		109		\$0.00
Medium	Work In Progress				2/13/2009 9:24:33 AM				
Garcia, Jose	please clean area around cafeteria. please use the power washer. coordinate w/ joey custodial so when you do the windows they can dry and clean them.								
	Thanks								
Michael Munoz									
42598					2/17/2009		105		\$0.00
Medium	Work In Progress				2/17/2009 8:58:46 AM				
Appelzoller, Fred	Please check all metering faucets throughout campus. They are not turning off by themselves. (See Mike Munoz)								
Michael Munoz									
42606	Main Building				2/17/2009		105		\$0.00
Medium	Work In Progress				2/17/2009 9:53:50 AM				
Apodaca, Mario	Requested by Ms. R. Holguin Rm. 125 Main Building- Need to replace bulb in storage room 125a, no light.								
Velia Alarcon									
42799	Football Stadium				2/23/2009		99		\$0.00
Medium	Work In Progress				2/23/2009 2:54:56 PM				
Lara, Ralph	need a new lock set for the football shack								
Mario Apodaca									
42819	North Building				2/23/2009		99		\$0.00
Medium	Work In Progress				2/23/2009 4:19:30 PM				
Castillo, Carlos	Requested by Mr. J. Gonzales Rm. 206 North Building- No power on all wall outlets, breaker form Teacher's Lounge possibly needs to be reset. POSSIBLE FIRE HAZARD with refrigerator, Coke Machine, microwave and all my outlets drawing power from the same wire.								
Velia Alarcon									
42821					2/23/2009		99		\$0.00
Medium	Work In Progress				2/23/2009 4:24:00 PM				
Vallejo, Albert	Requested by Mr. R. Grace for Facility Goal Team-Move lockers from hallway in Business Building to P.E. Locker rooms and Weight rooms. SEE MR. GRACE FOR FURTHER INSTRUCTIONS.								
Velia Alarcon									
42918					2/25/2009		97		\$0.00
Medium	Work In Progress				2/25/2009 11:27:29 AM				
Carrasco, Danny	Danny need to conduct inventory of all Building Mechanic tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
42927					2/25/2009		97		\$0.00
Medium	Work In Progress			2/25/2009 12:30:55 PM					
Carrasco, Danny	Danny need to conduct inventory of all Bldg Mechanic tools and equipment. Ask Ruben for present inventory list to match up.								
<u>Michael Munoz</u>									
42942	Auto Shop	Classroom			2/25/2009		97		\$0.00
Medium	Work In Progress			2/25/2009 3:36:20 PM					
Moncayo, Fernando	REQUEST # 2 W/O 40182 NEED TO REMOVE THE OLD WASHER AT STORED IN THE AUTO SHOP AT WAS IN THE KITCHEN A.S.A.P								
<u>Mario Apodaca</u>									
43036	Academic Bldg	Restroom (Boys)			2/27/2009		95		\$0.00
Medium	Work In Progress			2/27/2009 12:45:08 PM					
Apodaca, Mario	THE PARTITONS AT ACADEMIC BLDG AT THE BOY'S RESTROOM ARE VANDALISED ON THE E/SIDE WING (4/28/08 Asp Mario has not been done)					3/11 - Asp Mike need to now how many are needed and the sizes. Thanks mkv			
<u>Mario Apodaca</u>									
43357	Main Building				3/5/2009		89		\$0.00
Medium	Work In Progress			3/5/2009 8:42:04 AM					
Castillo, Carlos	Check on Lyncos Refrigeration installations.								
<u>Michael Munoz</u>									
43367					3/5/2009		89		\$0.00
Medium	Work In Progress			3/5/2009 11:02:22 AM					
Jacquez, Ricardo	60,000 Gal. Water Storage Tank - Relocate 4" inlet from bottom of tank to top to reduce short cycling.								
<u>Alfredo Holguin</u>									
43453	New Vocational				3/6/2009		88		\$0.00
High	Work In Progress			3/6/2009 4:23:25 PM					
Appelzoller, Fred	shower in sped room in vocational bldg by wood shop water leaks out, please see mike for repairs.thxs								
<u>Michael Munoz</u>									
43488					3/9/2009		85		\$0.00
Medium	Work In Progress			3/9/2009 11:29:30 AM					
Lara, Ralph	Requested by Mr. Grubaugh for Library-There is a leak coming from the door frame in the Library's main entry way, please fix as soon as possible.								
<u>Velia Alarcon</u>									
43679	Business	Classroom			3/13/2009		81		\$0.00
Medium	Work In Progress			3/13/2009 8:41:57 AM					
Ambriz, Jose	THE HEATING UNIT AT ROOM 660 AT BUS BLDG NEED WORK DO TO A ROLL BACK FIRE								
<u>Mario Apodaca</u>									
6/2/2009 9:39:31 AM									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
43721					3/15/2009		79		\$0.00
Medium	Work In Progress			3/15/2009 12:19:49 AM					
Ontiveros, Guadalupe	Monthly - Gadsden HS Soil Sampling - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
43907	Cafeteria (1998)	Cafeteria			3/20/2009		74		\$0.00
Medium	Work In Progress			3/20/2009 7:56:17 AM					
Gonzalez, Salvador	OUTSIDE THE CAFE BLDG THE CANOPY NEED TO BE REMOVE AND REPLACES W/ CORRUGATED STEEL PANEL OR PVC PANEL DO TO WEAT AND TEAR								
<u>Mario Apodaca</u>									
44015		Athletic Field			3/25/2009		69		\$0.00
Medium	Work In Progress			3/25/2009 2:22:05 PM					
Ontiveros, Guadalupe	Repair Damaged Perimeter Fence on the northwest corner (west side) next to entrance by Ag Farm.								
<u>Alfredo Holguin</u>									
44089					3/31/2009		63		\$0.00
Medium	Work In Progress			3/31/2009 12:22:49 AM					
Apodaca, Mario	Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
44117					3/31/2009		63		\$0.00
Medium	Work In Progress			3/31/2009 12:07:23 PM					
Gonzalez, Salvador	Requested by Mr. Roberson for Cafeteria Picnic Area- Repair the canvas cover over the cafeteria picnic area.								
<u>Velia Alarcon</u>									
44125	Cafeteria (1998)	Restroom (Boys)			3/31/2009		63		\$0.00
Medium	Work In Progress			3/31/2009 2:42:26 PM					
Ambriz, Jose	we have two roof top exhaust fans one at the boys restroom and the other next door in the custodial closet that do not function								
<u>Joe Munoz</u>									
44154	Pool Pump	Pool			4/1/2009		0		\$0.00
Medium	Work In Progress			4/1/2009 9:40:12 AM		4/1/2009			
Sanchez, Raul	Annual Pool Start-up to include procurement of supplies,contracting of services,cleaning of pool & pump room,pool inspection & opening to the public								
<u>Raul Sanchez</u>									
44280					4/3/2009		60		\$0.00
Medium	Work In Progress			4/3/2009 4:02:37 PM					
Apodaca, Mario	Requested by Isela Martinez for Counseling Center- Assemble chairs and desk for Ms. Ortiz/Ms. Hernandez.								
<u>Velia Alarcon</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
44281					4/3/2009		60		\$0.00
Medium	Work In Progress				4/3/2009 4:05:24 PM				
Vallejo, Albert	Requested by Teachers in Business Building-Check seals and latches on all windows in the building. If possible have all windows replaced.								
<u>Velia Alarcon</u>									
44287					4/5/2009		58		\$0.00
Medium	Work In Progress				4/5/2009 12:22:30 AM				
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.		4/7/09 E-mailed PM to Ricky and Garrett at Rocky Mtn.						
<u>Margret Villalobos</u>									
44324					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress				4/5/2009 12:22:45 AM				
Orozco, Danny	Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
44402					4/5/2009	4/13/2009	58		\$0.00
Medium	Work In Progress				4/5/2009 12:23:11 AM				
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
44571					4/9/2009		54		\$0.00
Medium	Work In Progress				4/9/2009 8:52:10 AM				
Gonzalez, Salvador	Need to Repair the pole vault upright.								
<u>Albert Vallejo</u>									
44577	Boys Gym	Dressing Room			4/9/2009		54		\$0.00
Medium	Work In Progress				4/9/2009 12:27:09 PM				
Estrada, Jesus	AS PER MR CHAMBER THE FLOORS AT LOCKER ROOMS NEED TO BE REPLACES . BOYS GYM ROOM 404,400		6/1/09 ON HOLD AS PER CHUY						
<u>Mario Apodaca</u>									
44578	Varsity Gym	Dressing Room			4/9/2009		54		\$0.00
Medium	Work In Progress				4/9/2009 12:37:53 PM				
Estrada, Jesus	AS PER MR CHAMBER THE FLOOR AT THE VOLLEYBALL LOCK ROOM NEED TO BE REPLACS. AT THE V-GYM ROOM 241		6/1/09 - ON HOLD AS PER CHUY						
<u>Mario Apodaca</u>									
44741	Cafeteria (1998)				4/16/2009		47		\$0.00
Medium	Work In Progress				4/16/2009 8:29:03 AM				
Ambriz, Jose Carlos Castillo	GHS cafeteria electrical room exhaust fan not working.								

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
44868	North Building				4/21/2009		42		\$0.00
Medium	Work In Progress				4/21/2009 2:33:30 PM				
Vallejo, Albert	Requested by Ms. Holzhausen Rm. 226 North Building- Please hang the small white board by the clock.								
Velia Alarcon									
44869	Main Building				4/21/2009		42		\$0.00
Medium	Work In Progress				4/21/2009 2:36:17 PM				
Apodaca, Mario	Requested by Velia for Rm. 124 Main Building-Hang up a flag from the cieling.								
Velia Alarcon									
44872	Boys Gym				4/21/2009		42		\$0.00
Medium	Work In Progress				4/21/2009 2:43:47 PM				
Apodaca, Mario	Requested by Mr. Mora for Rm. 403 Training Room in Boy's Gym-Replace light bulbs in Athletic Training room.								
Velia Alarcon									
44918					4/22/2009		41		\$0.00
Medium	Work In Progress	Girls Gym			4/22/2009 12:05:03 PM				
Lara, Ralph	Requested by Ms. Letz for Girl's Gym-Replace the doors and door frames between Girl's Gym and locker room, between hall and gym, and the door for the equipment room inside the locker room. This problem has never been repaired properly. All the equipment for the P.E. Department is stored in the equipment room of the girl's locker room and when Ms. Letz is out for the day P.E. equipment has been stolen. Please repair as soon as possible.								
Velia Alarcon									
44962					4/23/2009		40		\$0.00
Medium	Work In Progress				4/23/2009 11:35:47 AM				
Vallejo, Albert	Requested by Mr. Roberson for Room 569 (DACC Nursing Classroom) Ag. Shop-Repair outer wall by entrance where plywood is warped and rotting, prefer masonry fill in.								
Velia Alarcon									
44966	Pool Dressing	Pool			4/23/2009		40		\$0.00
Medium	Work In Progress				4/23/2009 12:47:06 PM				
Sanchez, Raul	4/23/09 Need to procure materails to install a water line from irrigation well #1 to the pool pump room & the dressing room bathrooms & showers. This is to provide temporary water during the shutoff of the system in July.								
Raul Sanchez									
45092	Academic Bldg				4/28/2009		35		\$0.00
Medium	Work In Progress				4/28/2009 11:11:04 AM				
Ontiveros, Guadalupe	Please install irr. watering system to all trees and shurbs around bldg.								
Michael Munoz									
6/2/2009 9:39:31 AM									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
45105		Classroom			4/28/2009		35		\$0.00
Medium	Work In Progress	Science and			4/28/2009 2:00:46 PM				
Vallejo, Albert		Please set up furniture for computers on the Science and Language Arts classrooms, furniture was delivered on April 16. Thank you!							
<u>Sandra Almeraz</u>									
45113	Agricultural	Classroom			4/28/2009		35		\$0.00
Medium	Work In Progress				4/28/2009 3:13:24 PM				
Appelzoller, Fred		need a new utility twin sink at the ag shop bldg to room 568							
<u>Mario Apodaca</u>									
45114	North Building				4/28/2009		35		\$0.00
Medium	Work In Progress				4/28/2009 3:14:09 PM				
Estrada, Jesus		Requested by Mr. Martinez for Hallway and Locker Areas in the North Building-The tile and carpet on the columns need to be repaired or replaced.				6/1/09 QUOTE PENDING			
<u>Velia Alarcon</u>									
45124	North Building				4/28/2009		35		\$0.00
Medium	Work In Progress				4/28/2009 3:52:46 PM				
Vallejo, Albert		Requested by Mr. Martinez for Hallway and Locker Areas in the North Building-Variou areas in the hall need painting and some wall areas need to be repaired.							
<u>Velia Alarcon</u>									
45312					5/3/2009	5/11/2009	30		\$0.00
Medium	Work In Progress				5/3/2009 12:22:46 AM				
Apodaca, Mario		Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
45425	Main Building	Classroom			5/5/2009		28		\$0.00
Medium	Work In Progress				5/5/2009 2:57:50 PM				
Lara, Ralph		NEED TO REKEY DOORS AT CLASS ROOM 105 AT MAIN BLDG , BY MAY- 7- 09							
<u>Mario Apodaca</u>									
45628	Academic Bldg	Custodial			5/12/2009		21		\$0.00
Medium	Work In Progress				5/12/2009 8:17:32 AM				
Lara, Ralph		The door handle spins around making the door unable to lock, needs to be replaced							
<u>Albert Vallejo</u>									
45635	Pool Pump				5/12/2009		0		\$0.00
High	Work In Progress				5/12/2009 9:40:04 AM	5/12/2009			
Castillo, Carlos		Need 600'-24 volt wire for well #2 to be connected to irrigation control.							
<u>Guadalupe Ontiveros</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
45637					5/12/2009		21		\$0.00
Medium	Work In Progress			5/12/2009 10:41:37 AM					
Ontiveros, Guadalupe	Requested by Coach Yanez for Baseball Field-Extend home dugout with fencing (4ft.), already spoke with Lupe Ontiveros for summer project.								
<u>Velia Alarcon</u>									
45638	Academic Bldg				5/12/2009		21		\$0.00
Medium	Work In Progress			5/12/2009 10:43:51 AM					
Lara, Ralph	Requested by Ms. L. Melendrez Rm. 333 Academic Building-The lock on the cabinet next to the door doesn't work. It doesn't lock.								
<u>Velia Alarcon</u>									
45639	Academic Bldg				5/12/2009		21		\$0.00
Medium	Work In Progress			5/12/2009 10:47:56 AM					
Lara, Ralph	Requested by Ms. L. Melendrez Rm. 333 Academic Building-The closing hinge on the top of the door broke off.								
<u>Velia Alarcon</u>									
45669					4/30/2009		0		\$0.00
Medium	Work In Progress			5/12/2009 4:06:44 PM	4/30/2009				
Castillo, Carlos	Damage to light fixture in rm 502. (est cost 508.00)		Light Fixture - Grainger catalog #398 pg 531 Item #5ya99						
<u>Julio Alcantar</u>									
45676	North Building	Restroom (Boys)			5/13/2009		20		\$0.00
Medium	Work In Progress			5/13/2009 8:37:00 AM					
Vallejo, Albert	as per mr. martinez assist. principle, he is requesting that due to excessive graffiti he would like to have the boys restroom painted at the north building								
<u>Joe Munoz</u>									
45678					5/13/2009		20		\$0.00
Medium	Work In Progress	GHS-SPED		5/13/2009 9:09:57 AM					
Vallejo, Albert	AS PER MR. RICHARD G. CHAVEZ-AT GHS THE SPED CLASSROOM, BATHROOM EXHAUST NEEDS TO BE CLEANED.								
<u>Mary Garcia</u>									
45679	Auto Shop				5/13/2009		20		\$0.00
Medium	Work In Progress	GHS		5/13/2009 9:11:41 AM					
Apodaca, Mario	AS PER MR. RICHARD G. CHAVEZ-AT GHS THE AUTOSHOP HANDICAP SIDEWALK NEEDS TO BE REPAINTED.								
<u>Mary Garcia</u>									
45692					5/14/2009		19		\$0.00
Medium	Work In Progress			5/14/2009 12:18:44 AM					
Jacquez, Ricardo	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
6/2/2009 9:39:31 AM									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
45702	Old English Bldg				5/14/2009		19		\$0.00
Medium	Work In Progress				5/14/2009 8:32:03 AM				
Ambriz, Jose	NEED TO PUT NEW SHUTTERS FOR THE E/COOLER UNIT AT THE OLD ENG BLDG								
Mario Apodaca									
45834	Business	Restroom (Boys)			5/19/2009		14		\$0.00
Medium	Work In Progress				5/19/2009 12:25:32 PM				
Lara, Ralph	NEED A NEW LOCK SET AT THE BOYS RESTROOM ON THE TOP FLOOR OF THE BUS BLDG								
Mario Apodaca									
45839					5/19/2009		14		\$0.00
Medium	Work In Progress				5/19/2009 2:04:13 PM				
Vallejo, Albert	Requested by Ms. Howard Rm. 307 Academic Building- Fix bookshelves.								
Velia Alarcon									
45870					5/20/2009		13		\$0.00
Medium	Work In Progress				5/20/2009 10:21:46 AM				
Vallejo, Albert	Please move furniture desk from room 126 B to room 109 in the closet. Mr. Robert Navarro is the contact person for this request. phone number 915-355-2061.								
Anna Alvarez									
45874					5/20/2009		13		\$0.00
Medium	Work In Progress				5/20/2009 2:58:12 PM				
Castillo, Carlos	Possible phase imbalance is causing some appliances in the Panther Hut to not function								
Albert Vallejo									
45912	Cafeteria (1998)	Cafeteria			5/21/2009		12		\$0.00
Medium	Work In Progress				5/21/2009 10:15:07 AM				
Moncayo, Fernando	VICTORY FOOD WARMER: DOOR GASKETS NEED TO BE REPLACED.								
	LYDIA M. SNP MGR 882-5522								
Jacqueline Aguilar									
45915					5/21/2009		12		\$0.00
Medium	Work In Progress				5/21/2009 11:27:08 AM				
Apodaca, Mario	Requested by Ms. Abler for room 140 in Old English Building-New chalkboard will be needed. We believe they've been there since 1927. If you could move a chalk board from another classroom that won't be used and would be good as well.								
Velia Alarcon									
45916					5/21/2009		12		\$0.00
Medium	Work In Progress				5/21/2009 11:39:59 AM				
Ontiveros, Guadalupe	Requested by Coach Maxey for Track Field-Take down discus cage and remove pole vault standard plates.								
Velia Alarcon									
6/2/2009 9:39:31 AM									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
45917					5/21/2009		12		\$0.00
Medium	Work In Progress			5/21/2009 11:41:37 AM					
Vallejo, Albert	Requested by Mr. W. Dickson for room 132 in Old English Building-Replace and add new chalk boards in room 132.								
<u>Velia Alarcon</u>									
46033	Cafeteria (1998)	Cafeteria			5/27/2009		6		\$0.00
Medium	Work In Progress			5/27/2009 1:38:47 PM					
Moncayo, Fernando	BACK DOOR: FLY FAN NEEDS TO BE REPAIRED								
AIDA S. SNP 882-6772									
<u>Jacqueline Aguilar</u>									
46053	Agricultural				5/27/2009		6		\$0.00
Medium	Work In Progress			5/27/2009 4:00:51 PM					
Ambriz, Jose	Need to replace a/c unit.								
<u>Mario Apodaca</u>									
46067					5/28/2009		5		\$0.00
Medium	Work In Progress	LINE LOCATE		5/28/2009 10:22:48 AM					
Castillo, Carlos	Need to line locate for elec. water valves.								
<u>Michael Munoz</u>									
46095	Pool Pump	Pump House			5/29/2009		4		\$0.00
Medium	Work In Progress			5/29/2009 10:17:30 AM					
Castillo, Carlos	We need the services of an electrician to procure the necessary material to connect a new panel box for the new pump & motor that will be installed by Anthony Pump & Drilling commencing in July. The panel box is presently at Anthony Pump's place of business.								
<u>Raul Sanchez</u>									
46099					5/29/2009		4		\$0.00
High	Work In Progress			5/29/2009 10:41:29 AM					
Castillo, Carlos	please check site for proper phase balance and voltage.								
<u>Michael Munoz</u>									
46109	Cafeteria (1998)	Electrical Room			5/29/2009		4		\$0.00
Medium	Work In Progress			5/29/2009 3:29:43 PM					
Castillo, Carlos	Need to replace 3 phase sensing 'motor saver' in cafeteria (serves A/C contactor)								
<u>Albert Vallejo</u>									
46126					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:12 AM					
Vallejo, Albert	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
46127					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:13 AM					
Vallejo, Albert	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46128					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:13 AM					
Vallejo, Albert	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46129					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:14 AM					
Vallejo, Albert	Yearly - Gadsden HS B2 (Boiler)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46212					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:45 AM					
Apodaca, Mario	Yearly - Gadsden HS A2 (H/C Unit)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46213					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:45 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46283	Main Building				6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 1:55:36 PM					
Vallejo, Albert	Requested by Ms. Leahy Rm. 127 Main Building-Paint the classroom.								
<u>Velia Alarcon</u>									
46284	Main Building				6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 2:15:31 PM					
Castillo, Carlos	Requested by Ms. Leahy for Rm. 127 Main Building-WORK ORDER # 37400 HAS NOT BEEN COMPLETED. Install light switch in room 127, currently light switch is in room 128. 2ND REQUEST.								
<u>Velia Alarcon</u>									
46286					6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 2:18:24 PM					
Vallejo, Albert	Requested by Ms. Leahy Rm. 127 Main Building-Please repair a hole in the wall near the base board on the south wall.								
<u>Velia Alarcon</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
46287					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 2:20:39 PM				
Castillo, Carlos	Requested by Mr. Myers Rm. 506 Annex Building-Plugs on the floor need to be repaired.								
Velia Alarcon									
46288					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 2:23:09 PM				
Vallejo, Albert	Requested by Mr. Myers Rm. 506 Annex Building-Four ceiling tiles need replacing.								
Velia Alarcon									
46290					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 2:27:45 PM				
Appelzoller, Fred	Requested by Mr. Myers for Restroom in Annex Building -Sink needs replacement.								
Velia Alarcon									
46291					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 2:29:09 PM				
Apodaca, Mario	Requested by Mr. Myers for Restroom in Annex Building -Walls need to be painted.								
Velia Alarcon									
46292					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 2:39:08 PM				
Apodaca, Mario	Requested by Mr. Myers for Restroom in Annex Building -Toilet walls need replacement.								
Velia Alarcon									
46293					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 2:42:06 PM				
Appelzoller, Fred	Requested by Mr. Villa Rm. 510 in Annex Building-Leak at the water fountain, might be a drain pipe leak.								
Velia Alarcon									
46294					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 2:43:22 PM				
Appelzoller, Fred	Requested by Mr. Villa for Annex Building-The push bars on the water fountain do not operate correctly.								
Velia Alarcon									
46295					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 2:46:08 PM				
Vallejo, Albert	Requested by Mr. Villa Rm. 510 in Annex Building-Light bulbs need to be replaced in different parts of the band room.								
Velia Alarcon									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

46296					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 2:51:31 PM				

Apodaca, Mario Requested by Mr. Villa Rm. 510 in Annex Building-Air leaks in the bottom of the doors which allows dust and dirt to enter. This can damage the instruments in the band room which can increase the amount of funds needed to repair the instruments.

Velia Alarcon

46297					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:00:38 PM				

Lara, Ralph Requested by Mr. Villa Rm. 510 in Annex Building-Northeast door of the portable in missing the inside handle. The handle can be found in the band room office in my desk.

Velia Alarcon

46298					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:02:43 PM				

Vallejo, Albert Requested by Mr. Villa Rm. 510 in Annex Building-Ballast in the uniform room needs to be replaced, light constantly pulsing.

Velia Alarcon

46299					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:04:26 PM				

Ambriz, Jose Requested by Mr. Villa Rm. 510 in Annex Building-Heater on the northwest corner of the band room never ignited and ended up with a gas leak recently.

Velia Alarcon

46300					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:05:51 PM				

Estrada, Jesus Requested by Mr. Villa Rm. 510 in Annex Building-Carpet needs to be steamed cleaned.

Velia Alarcon

46302	Varsity Gym				6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:11:50 PM				

Apodaca, Mario Requested by Coach Hite for Varsity and J.V. Lockerrooms in Boy's Gym-Paint J.V. tile floor, brown or gray.

Velia Alarcon

46303	Varsity Gym				6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:13:55 PM				

Apodaca, Mario Requested by Coach Hite for Varsity Lockerroom in Boy's Gym-Repair varsity lockers, replace all screws missing.

Velia Alarcon

6/2/2009 9:39:32 AM

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
46305		Football Field			6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:18:46 PM				
Ontiveros, Guadalupe	Requested by Coach Hite for Varsity Football Field-Top soil was not treated properly before placing it on the football field and now is over grown with weeds. Please kill all weeds growing on the game field and try to safe as much of the grass as possible preferably before the start of the '09 Football Season. FIRST HOME GAME SCHEDULED FOR FRIDAY, AUGUST 28, 2009.								
<u>Velia Alarcon</u>									
46317	North Building	Library			6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:57:25 PM				
Ontiveros, Guadalupe	please cut and trim grass between library and n.bldg and where else is needed.thxs								
<u>Michael Munoz</u>									
46318	Academic Bldg				6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 3:59:38 PM				
Munoz, Joe	please pick up trash in fenced area, west of buissness bldg as you are going to the academic bldg. this is a drained area. thxs								
<u>Michael Munoz</u>									
<b>Count: 135 Work Orders</b>		<b>Avg. Age of WO's 86</b>			<b>Total for Gadsden HS</b>			<b>11</b>	<b>\$275.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
35955					7/14/2008		323		\$0.00
Medium	Work In Progress			7/14/2008 3:35:17 PM					
Lozoya, Manny		Need fix main entrance doors the punish bar not work properly thank you							
<u>Sebastian Diaz</u>									
36222		Office			7/25/2008		312		\$0.00
Medium	Work In Progress	Awing/GMS Front		7/25/2008 11:40:57 AM					
Lozoya, Manny		Need to set up A57 key lock on new door in Ms. Quinonez's office as soon as possible.							
<u>Maricruz Carrasco</u>									
36627		Office			8/5/2008		301		\$0.00
Medium	Work In Progress	GMS Front		8/5/2008 5:44:35 AM					
Lozoya, Manny		Need A53 door lock on Nancy's door as soon as possible.							
<u>Maricruz Carrasco</u>									
36628		Office			8/5/2008		301		\$0.00
Medium	Work In Progress	Awing/155/Dr.		8/5/2008 5:47:23 AM					
Lozoya, Manny		Door lock in Dr. Garcia's office supposed to be opened by M36 key only. W key can be used to open the door. Please check door lock.							
<u>Maricruz Carrasco</u>									
36632		Parking Lot			8/5/2008		301		\$0.00
Medium	Work In Progress	Parking		8/5/2008 5:59:53 AM					
Lozoya, Manny		Need metal door installed in Security shed.							
<u>Maricruz Carrasco</u>									
37267		Office			8/21/2008		285		\$0.00
Medium	Work In Progress	Awing/162/Securit		8/20/2008 10:01:58 PM					
Lozoya, Manny		"W" key is getting jammed.							
<u>Maricruz Carrasco</u>									
37270		Classroom			8/21/2008		285		\$0.00
Medium	Work In Progress	Awing/159/E.		8/20/2008 10:06:16 PM					
Lozoya, Manny		Door does not close and lock.							
<u>Maricruz Carrasco</u>									
37763	C-Wing	Classroom			9/3/2008		272		\$0.00
Medium	Work In Progress	Cwing/C-		9/3/2008 9:29:19 PM					
Lozoya, Manny		Door does not lock. Safety issue.							
<u>Maricruz Carrasco</u>									
37764	C-Wing	Office			9/3/2008		272		\$0.00
Medium	Work In Progress	Cwing/Dr. Montes		9/3/2008 9:30:21 PM					
Lozoya, Manny		Door does not lock.							
<u>Maricruz Carrasco</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
37770		Portables			9/4/2008		271		\$0.00
Medium	Work In Progress			9/4/2008 8:13:40 AM					
Sotelo, Enrique		Please provide electrical connection to 2 Bard units.							
Lorenzo Solis									
38385					9/24/2008		251		\$0.00
Medium	Work In Progress	All GMS Staff		9/23/2008 10:06:29 PM					
Lozoya, Manny		All staff restrooms to have latch placed on door for privacy reasons.							
Maricruz Carrasco									
38417	C-Wing				9/24/2008		251		\$0.00
Medium	Work In Progress			9/24/2008 3:44:29 PM					
Lozoya, Manny		New Portable - 1st thing tomorrow need to recore like GMS (see Mike if u have any questions).							
Michael Munoz									
38464	C-Wing				9/26/2008		249		\$0.00
Medium	Work In Progress			9/26/2008 12:26:38 PM					
Lozoya, Manny		Mr. Chacon, Band Director needs a gate key for gate by C-Wing.							
Michael Munoz									
38465					9/26/2008		249		\$0.00
Medium	Work In Progress			9/26/2008 12:29:32 PM					
Lozoya, Manny		Mr. Chacon, Band Director needs a gate key.							
Michael Munoz									
38485					9/26/2008		249		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:32:43 PM					
Lozoya, Manny		Need three WA-83 keys. Need two V-3 keys.							
Maricruz Carrasco									
38486					9/26/2008		249		\$0.00
Medium	Work In Progress	Front office		9/26/2008 4:34:17 PM					
Lozoya, Manny		Need two keys made for golf cart.							
Maricruz Carrasco									
38487	C-Wing	Portables			9/26/2008		249		\$0.00
Medium	Work In Progress	C-wing/New		9/26/2008 4:35:35 PM					
Lozoya, Manny		Fix lock to main entrance on new portable-Health Center							
Maricruz Carrasco									
38651	Annex				10/2/2008		243		\$0.00
Medium	Work In Progress			10/2/2008 3:20:00 PM					
Lozoya, Manny		Need fix handi cup door in annex bldg thank you							
Sebastian Diaz									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
39213		Office			10/14/2008		231		\$0.00
Medium	Work In Progress	Dr. Garcia's		10/14/2008 9:56:39 AM					
Lozoya, Manny		Install lock on black storage cabinet for Maricruz.							
Maricruz Carrasco									
39856					11/5/2008		209		\$0.00
Medium	Work In Progress			11/5/2008 2:20:53 PM					
Lozoya, Manny		Controls contractor (Trane) Needs keys to acces building on Monday Nov. 10							
Alfredo Holguin									
40147	C-Wing				11/17/2008		197		\$0.00
Medium	Work In Progress			11/17/2008 2:29:35 PM					
Lozoya, Manny		Nursing Coordinator Offices - Rekey - check with Ms. Cregan on keying							
Alfredo Holguin									
40785					12/11/2008		173		\$0.00
Medium	Work In Progress	A wing / Sped		12/11/2008 10:29:02					
Lozoya, Manny		Re-Key File Cabinet							
Maricruz Carrasco									
40786		Classroom			12/11/2008		173		\$0.00
Medium	Work In Progress	A wing / 178		12/11/2008 10:30:20					
Lozoya, Manny		Repair Lock to File Cabinet							
Maricruz Carrasco									
40787					12/11/2008		173		\$0.00
Medium	Work In Progress	B Wing / New		12/11/2008 10:31:39					
Lozoya, Manny		Re-Key to A53							
Maricruz Carrasco									
41220	Annex				1/6/2009		147		\$0.00
Medium	Work In Progress	GMS		1/6/2009 4:52:10 PM					
Ontiveros, Guadalupe		Two large holes between Annex and portable need to be filled with dirt. Please see Dr. Garcia for more information.							
Maricruz Carrasco									
41221					1/6/2009		147		\$0.00
Medium	Work In Progress	GMS Campus		1/6/2009 4:53:38 PM					
Ontiveros, Guadalupe		Uprooted tree needs to be covered with dirt. Please see Dr. Garcia for more information.							
Maricruz Carrasco									
41266					1/8/2009		145		\$0.00
Medium	Work In Progress			1/8/2009 10:14:34 AM					
Lozoya, Manny		NEED TO INSTALL CORES IN NEW ANNEX BUILDING.							
Maritza Gonzalez									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden MS</b>							
41573					1/16/2009		137		\$0.00
Medium	Work In Progress	War room in		1/16/2009 10:54:08 AM					
Lozoya, Manny		Secure storage cabinet with clasp in WAR Room							
Maricruz Carrasco									
41575	C-Wing				1/16/2009		137		\$0.00
Medium	Work In Progress	C wing/ Elev. 8		1/16/2009 10:57:09 AM					
Lozoya, Manny		Lock change for storage room in the Elev. 8 room. (See Shirley Baca)							
Maricruz Carrasco									
41578		Cafeteria			1/16/2009		137		\$0.00
Medium	Work In Progress	War room		1/16/2009 11:04:53 AM					
Lozoya, Manny		Re-key off Master to M36, same as Dr. Garcia's office							
Maricruz Carrasco									
41588		Computer Lab			1/16/2009		137		\$0.00
Medium	Work In Progress	rooms next to		1/16/2009 11:25:41 AM					
Lozoya, Manny		Need construction Core removed from computer labs next to library and Keyed to GISD Key Core. ASAP							
Maricruz Carrasco									
41590					1/16/2009		137		\$0.00
Medium	Work In Progress			1/16/2009 11:30:43 AM					
Lozoya, Manny		Need extra copy of key 56 for boiler room for Dr. Garcia							
Maricruz Carrasco									
41788		Classroom			1/23/2009		130		\$0.00
Medium	Work In Progress	B wing/ room 109		1/23/2009 10:56:22 AM					
Lozoya, Manny		Need two new locks for cabinets							
Maricruz Carrasco									
41792	Annex				1/23/2009		130		\$0.00
Medium	Work In Progress	Home Ec/ room		1/23/2009 11:54:39 AM					
Lozoya, Manny		Lock to storage cabinet (see mr. kohl)							
Maricruz Carrasco									
41924					1/28/2009		125		\$0.00
Medium	Work In Progress			1/28/2009 8:15:30 AM					
Lozoya, Manny		Need to fix door handal in room 303 vocational bldg thank you							
Sebastian Diaz									
41932					1/28/2009		125		\$0.00
Medium	Work In Progress	room 146 and		1/28/2009 10:15:28 AM					
Lozoya, Manny		Key new computer labs, rooms 146 and 148.							
		Need 5 keys of the V8 (Connie)							
Maricruz Carrasco									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden MS</b>							
41938					1/28/2009		125		\$0.00
Medium	Work In Progress	Library		1/28/2009 11:19:35 AM					
Lozoya, Manny		Rekey inside new library							
Maricruz Carrasco									
41988					1/29/2009		124		\$0.00
Medium	Work In Progress			1/29/2009 11:28:47 AM					
Ontiveros, Guadalupe		could you please support w/ the irrigation system in the front of the campus to include the backflow preventer. no water thxs							
Michael Munoz									
41989					1/29/2009		124		\$0.00
Medium	Work In Progress			1/29/2009 11:32:40 AM					
Appelzoller, Fred		please provide and check all hose bibbs around campus for water hose hook ups. thxs							
Michael Munoz									
42020					1/30/2009		123		\$0.00
Medium	Work In Progress			1/30/2009 11:37:16 AM					
Lozoya, Manny		Need to check key and lock in computer lab thank you							
Sebastian Diaz									
42398	Gym	Gym			2/9/2009		113		\$0.00
Medium	Work In Progress	Gym/Boys		2/9/2009 4:15:46 PM					
Lozoya, Manny		New lock needed for Boys Basketball Storage. See Connie for more information.							
Maricruz Carrasco									
42619	Main Building				2/17/2009		105		\$0.00
Medium	Work In Progress	B- Wing		2/17/2009 12:06:39 PM					
Sotelo, Enrique		Asp PM 42129, Need power in Main Entrance for emerg.lights. (see Sebastian for further info).							
Sebastian Diaz									
42691		Classroom			2/19/2009		103		\$0.00
Medium	Work In Progress	Bwing/140/G.Riva		2/19/2009 12:20:14 AM					
Lozoya, Manny		Filing cabinet lock needs to be replaced.							
Maricruz Carrasco									
42965					2/26/2009		96		\$0.00
Medium	Work In Progress			2/26/2009 8:25:09 AM					
Appelzoller, Fred		Isolate water valves for all new bldg, water valves.				Summer Project			
Michael Munoz						Need Ditch Witch for digging french drain for drinking fountain. asp report 2/24/09			

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Gadsden MS

43119					3/1/2009		93		\$0.00
Medium	Work In Progress			3/1/2009 12:23:01 AM					
Orozco, Danny	Yearly - Gadsden MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43780		Library			3/17/2009		77		\$0.00
Medium	Work In Progress	Library Rm. 147		3/17/2009 9:01:22 AM					
Lozoya, Manny	Lock to Equipment storage room not working.								
Maricruz Carrasco									
43810					3/17/2009		77		\$0.00
Medium	Work In Progress			3/17/2009 3:41:27 PM					
Appelzoller, Fred	Need to replace parts on water fountain in the playground is broken thank you								
Sebastian Diaz									
43992					3/24/2009		70		\$0.00
Medium	Work In Progress			3/24/2009 3:59:48 PM					
Ambriz, Jose	west wing chiller, as per Johnson controls the flow swith is not operatable.please replace.thanks								
Michael Munoz									
44127		Athletic Field			3/31/2009		63		\$0.00
Medium	Work In Progress	Baseball		3/31/2009 2:50:44 PM					
Lozoya, Manny	Lock to walk through gate at baseball field worn out. Needs to be replaced.								
Maricruz Carrasco									
44216	Cafeteria	Office			4/2/2009		61		\$0.00
Medium	Work In Progress			4/2/2009 9:04:13 AM					
Lozoya, Manny	WORK ORDER FOR SNP WAREHOUSE - NEED PADLOCK WITH C CORE								
	FERNANDO MONCAYO - SNP TECH - 575-305-0190								
Alma Terrell									
44217	Cafeteria	Office			4/2/2009		61		\$0.00
Medium	Work In Progress			4/2/2009 9:08:26 AM					
Lozoya, Manny	WORK ORDER FOR DANNY OROZCO'S OFFICE - NEED 2 PADLOCKS WITH M 256 CORE (FOR DANNY'S OFFICE AND STORAGE ROOM)								
	FERNANDO MONCAYO - SNP TECH - 575-305-0190								
Alma Terrell									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden MS</b>							
44580	Cafeteria	Cafeteria			4/9/2009		54		\$0.00
Medium	Work In Progress				4/9/2009 2:23:28 PM				
Moncayo, Fernando		SNP WAREHOUSE: AC DEFUSER NEED TO BE REPLACED.							
Jacqueline Aguilar		JOHNNY LECHUGA SNP MGR WHSE 882-6771							
44838					4/20/2009		43		\$0.00
Medium	Work In Progress				4/20/2009 3:40:37 PM				
Lozoya, Manny		Need to fix door in vocational bldg room 302 thank you							
Sebastian Diaz									
44866					4/21/2009		42		\$0.00
Medium	Work In Progress				4/21/2009 2:07:41 PM				
Diaz, Sebastian		Need to replace register in food services for A/C 24X 24 thank you							
Sebastian Diaz									
45097	Band Room	Classroom			4/28/2009		35		\$0.00
Medium	Work In Progress	Gym/Band room			4/28/2009 12:14:21 PM				
Diaz, Sebastian		Repair band cabinets as soon as possible.							
Maricruz Carrasco									
45215	Annex	Classroom			4/30/2009		33		\$0.00
Medium	Work In Progress	Rm. 300, 307 and			4/30/2009 2:40:02 PM				
Lozoya, Manny		Room 300, Mr. Kohl, new lock. Room 307, Mr. Escarciga, new lock. Room 407, Mrs. Robles, adjust door.							
Maricruz Carrasco									
45451	Gym	Gym			5/5/2009		28		\$0.00
Medium	Work In Progress	Gym/Gym lobby			5/5/2009 4:29:23 PM				
Lozoya, Manny		Need a door chime (alarm) on doors going from gym lobby to the outside (back side of gym-towards the baseball field) Safety issue.							
Maricruz Carrasco									
45693					5/14/2009		19		\$0.00
Medium	Work In Progress				5/14/2009 12:18:44 AM				
Jacquez, Ricardo		Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
45713	C-Wing	Office			5/14/2009		19		\$0.00
Medium	Work In Progress	Cwing/C-212/JPO			5/14/2009 10:31:50 AM				
Lozoya, Manny		Change lock in Room C-212- JPO office.							
Maricruz Carrasco									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Gadsden MS</b>								
45715	Gym	Gym			5/14/2009		19		\$0.00	
Medium	Work In Progress	Gym Storage		5/14/2009 10:34:24 AM						
Lozoya, Manny		The volleyball and girls basketball locks need to be replaced. They don't lock at all.								
<u>Maricruz Carrasco</u>										
45749	Cafeteria	Cafeteria			5/15/2009		18		\$0.00	
Medium	Work In Progress			5/15/2009 9:12:06 AM						
Moncayo, Fernando		WASHING MACHINE IS STILL OUT OF ORDER - IT DOES NOT FILL WITH WATER, THE WATER FALLS OUT BEFORE IT FILLS THE TUB.								
		TERRY PORTILLO - SNP MANAGER - 882-2824 OR 882-3507								
<u>Alma Terrell</u>										
45882					5/20/2009		13		\$0.00	
Medium	Work In Progress			5/20/2009 3:36:22 PM						
Lozoya, Manny		Need a locks in supply medicine storage cabinet in nurse office thank you								
<u>Sebastian Diaz</u>										
45904					5/21/2009		12		\$0.00	
Medium	Work In Progress			5/21/2009 9:15:11 AM						
Lozoya, Manny		need to replace panin bar in front of the school doors thank you need six								
<u>Sebastian Diaz</u>										
46029	C-Wing				5/27/2009		6		\$0.00	
Medium	Work In Progress	Cwing		5/27/2009 11:59:29 AM						
Lozoya, Manny		Lock in C-wing needs to be fixed. See Juan Acosta for more information.								
<u>Maricruz Carrasco</u>										
46071					5/28/2009		5		\$0.00	
Medium	Work In Progress			5/28/2009 10:44:15 AM						
Diaz, Sebastian		Need to paint five books shelves in library thank you								
<u>Sebastian Diaz</u>										
46114					5/29/2009		4		\$0.00	
Medium	Work In Progress			5/29/2009 3:47:37 PM						
Diaz, Sebastian		Need two gallons of paint for partitions in annex restrooms thank you								
<u>Sebastian Diaz</u>										
46120					5/31/2009	6/16/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:10 AM						
Villalobos, Margret		Yearly - Gadsden MS June Chiller Insp. - Refer to PM schedule details.								
Margret Villalobos										

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden MS</b>							
46240					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:55 AM					
Diaz, Sebastian	Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
46241					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:55 AM					
Diaz, Sebastian	Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46242					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:56 AM					
Diaz, Sebastian	Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46243					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:56 AM					
Diaz, Sebastian	Yearly - Gadsden MS A-2 Split Systems Yearly - Refer to PM schedule details.								
Margret Villalobos									
46244					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:57 AM					
Diaz, Sebastian	Yearly - Gadsden MS A-9 Air Cooled Cond Yearly - Refer to PM schedule details.								
Margret Villalobos									
46245					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:57 AM					
Diaz, Sebastian	Yearly - Gadsden MS B-2 Boiler Yearly - Refer to PM schedule details.								
Margret Villalobos									
46278					6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 12:08:12 PM					
Lozoya, Manny	In the library door the key not open need check thank you								
Sebastian Diaz									
<b>Count: 74 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>128</b>	<b>Total for Gadsden MS</b>			<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>La Union - JTP Alvarez Farms</b>							
43542					3/10/2009		84		\$0.00
Medium	Work In Progress				3/10/2009 12:26:00 PM				
Ronquillo, Ruben	See Sam Avalos: Glass window on Fire extinguisher holder is broken. Please replace.								
Margaret Villalobos									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>84</b>		<b>Total for La Union - JTP Alvarez Farms</b>		<b>0</b>		<b>\$0.00</b>



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: La Union ES</b>									
38034					9/11/2008		264		\$0.00
Medium	Work In Progress			9/11/2008 3:14:33 PM					
Villalobos, David	pat aguilar need rubber bushing for water faucet - thank you								
Patricio Aguilar									
40988					12/18/2008		166		\$0.00
Medium	Work In Progress			12/18/2008 3:20:23 PM					
Ambriz, Jose	pat aguilar the thermostat not working right - dayton electric heater model 2e441 ser 143933 volts 240/208 wats 4800/2500 60 hz 13tu 16382/11946								
Patricio Aguilar									
41167					1/5/2009		148		\$0.00
Medium	Work In Progress			1/5/2009 3:33:50 PM					
Ambriz, Jose	pat aguilar heater boiler pump taco model fm1207 has a bad bearing								
Patricio Aguilar									
41244					1/7/2009		146		\$0.00
Medium	Work In Progress			1/7/2009 3:11:39 PM					
Lara, Ralph	pat aguilar need a new frame & door for rest room r210								
Patricio Aguilar									
42202					2/3/2009		119		\$0.00
Medium	Work In Progress			2/3/2009 3:44:11 PM					
Gonzales, Angel	Need to use sweeper for drive ways								
Patricio Aguilar									
43366		Pump House			3/5/2009		89		\$0.00
Medium	Work In Progress			3/5/2009 10:48:31 AM					
Sanchez, Raul	Repair in line check valve.								
Raul Sanchez									
43655					3/12/2009		82		\$0.00
Medium	Work In Progress			3/12/2009 3:12:30 PM					
Ambriz, Jose	the thermostat is not working - heater will not go on r313								
Patricio Aguilar									
43895					3/19/2009		75		\$0.00
Medium	Work In Progress			3/19/2009 3:27:57 PM					
Castillo, Carlos	the light bulbs keep blowing out - teachers rest room - may need trasformer								
Patricio Aguilar									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: La Union ES</b>									
44191		Athletic Field			4/1/2009		62		\$0.00
Medium	Work In Progress			4/1/2009 3:47:19 PM					
Ontiveros, Guadalupe	need to build a burm/vordo on the canel valve on the south end of campus to irrigate the new playfield.please see mike.								
<u>Michael Munoz</u>									
44537	Main Building	Mechanical Room			4/8/2009		55		\$0.00
Medium	Work In Progress			4/8/2009 9:28:41 AM					
Villalobos, David	installation of new main water line from meter to the main mechanical room								
<u>David Villalobos</u>									
44668					4/14/2009		49		\$0.00
Medium	Work In Progress			4/14/2009 3:00:28 PM					
Villalobos, Margret	spray for bugs room 210								
Patricio Aguilar			4/22 approved by A. Holguin pending PO 25.00						
44875					4/21/2009		42		\$0.00
Medium	Work In Progress			4/21/2009 3:11:57 PM					
Gonzales, Angel	would like the use of bobcat with the sweeper - thank you								
<u>Patricio Aguilar</u>									
45198					4/30/2009	5/31/2009	33		\$0.00
Medium	Work In Progress			4/30/2009 12:21:37 AM					
Aguilar, Patricio	Yearly - La Union ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45318					5/3/2009	5/9/2009	30		\$0.00
Medium	Work In Progress			5/3/2009 12:22:48 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45464					5/6/2009		27		\$0.00
Medium	Work In Progress			5/6/2009 3:04:22 PM					
Castillo, Carlos	the fan unit switch on wall is getting hot - thank you								
Patricio Aguilar									
45478					5/6/2009		27		\$0.00
Medium	Work In Progress			5/6/2009 4:08:44 PM					
Gonzales, Angel	REPLACE PANCHOS LAWN MOWER BLADES, SERVICE AND ASSIGN TO PAT AGUILAR								
<u>Michael Munoz</u>									
46217					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:46 AM					
Aguilar, Patricio	Yearly - La Union ES A-2 Package Unit Elec Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

6/2/2009 9:39:32 AM

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location: La Union ES</b>										
46218					5/31/2009	7/1/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:47 AM						
Aguilar, Patricio	Yearly - La Union ES B-2 Boiler Yearly - Refer to PM schedule details.									
Margret Villalobos										
46219					5/31/2009	6/8/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:47 AM						
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.									
Margret Villalobos										
46220					5/31/2009	6/8/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:48 AM						
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
Margret Villalobos										
46221					5/31/2009	6/6/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:48 AM						
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.									
Margret Villalobos										
46340					6/2/2009		0		\$0.00	
Medium	Work In Progress	LINE LOCATE		6/2/2009 6:31:08 AM						
Castillo, Carlos	Need to line locate in front of bus turnaround on Thursday morning. (any questions call David Villalobos call #55)									
David Villalobos										
<b>Count: 22 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>65</b>				<b>Total for La Union ES</b>	<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Loma Linda ES</b>									
38964					10/6/2008		239		\$0.00
Medium	Work In Progress				10/6/2008 1:40:46 PM				
Carrasco, Danny	Need pressure washer and hose to wash off wall of the east side of main bldg.								
Rudy Arreola									
41073					1/4/2009	1/25/2009	149		\$0.00
Medium	Work In Progress				1/4/2009 12:18:50 AM				
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
42146					2/2/2009		120		\$0.00
Medium	Work In Progress				2/2/2009 2:22:39 PM				
Gonzales, Angel	Riding mower needs service and new blades also back tires are low.								
Rudy Arreola									
42259	Main Building	Classroom			2/5/2009		117		\$0.00
Medium	Work In Progress				2/5/2009 8:53:21 AM				
Lozoya, Manny	RM 317 Music Room - Having trouble opening door.								
Luis Solis									
42276					2/5/2009		117		\$0.00
Medium	Work In Progress				2/5/2009 2:03:22 PM				
Lozoya, Manny	We need to have 2 sets of RR have the door handle changed so we can lock the RR One is front lobby and the other is cafeteria lobby. BOYS AND GIRLS								
Rudy Arreola									
42524					2/12/2009		110		\$0.00
Medium	Work In Progress				2/12/2009 12:54:24 PM				
Sotelo, Enrique	We need an outlet relocated for tv.								
Rudy Arreola									
42525					2/12/2009		110		\$0.00
Medium	Work In Progress				2/12/2009 12:55:10 PM				
Sotelo, Enrique	We need to have 2 more outlets in installed in server RM.								
Rudy Arreola									
43301					3/4/2009		90		\$0.00
Medium	Work In Progress				3/4/2009 9:32:34 AM				
Lozoya, Manny	Manny Lozoya, please check key for room 307. Mr. Solis has sprayed stuff into lock, but teacher continues to have problem unlocking door.								
Grace Alvarado									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
43504					3/9/2009		85		\$0.00
Medium	Work In Progress			3/9/2009 2:51:26 PM					
Appelzoller, Fred	Need to have 2 urinals replaced they keep cloging them .with smaller holes so they cant stuff them with any thing.								
Rudy Arreola									
43530					3/10/2009		84		\$0.00
Medium	Work In Progress			3/10/2009 9:10:16 AM					
Lozoya, Manny	MANNY LOZOYA, ROOM 203, DOOR HANDLE STICKING, NOT LOCKING								
Grace Alvarado									
43548					3/10/2009		84		\$0.00
Medium	Work In Progress			3/10/2009 2:53:13 PM					
Arreola, Rudy	Plastic barriers are buckling and sand is going over them.		3/11 Rudy, call me if he has a questions. This would be a PM on playground equipment. - Thanks Mike						
Rudy Arreola									
44317					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:43 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
44989					4/23/2009		40		\$0.00
Medium	Work In Progress			4/23/2009 3:54:48 PM					
Solis, Lorenzo	THE CLOSET ON THE STAGE IS BEING USED AS AN OFFICE WHERE TECHNOLOGY HAS DROPPED LINES AND IS THEREFORE BEING USED AS AN OFFICE , IS THERE ANY WAY THAT WE CAN PROVIDE SOME KIND OF COOLING SYSTEM TO THESE TWO TEACHERS?								
Grace Alvarado									
45091					4/28/2009		35		\$0.00
Medium	Work In Progress			4/28/2009 11:03:52 AM					
Ontiveros, Guadalupe	LANDSCAPE/PLANT GRASS AND INSTALL A SPRINKLER SYSTEM BETWEEN WINGS.								
Alfredo Holguin									
45542					5/8/2009		25		\$0.00
Medium	Work In Progress			5/8/2009 3:01:24 PM					
Lozoya, Manny	Lock to storage not opening and needs to be replaced.								
Rudy Arreola									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Loma Linda ES</b>									
45596					5/11/2009		22		\$0.00
Medium	Work In Progress			5/11/2009 2:52:49 PM					
Lozoya, Manny	Door closure to cafeteria back door broke and the door wont stay open during deliveries.....								
Rudy Arreola									
45597					5/11/2009		22		\$0.00
Medium	Work In Progress			5/11/2009 2:58:42 PM					
Gonzales, Angel	Need tractor to level off walkway for kids and remove sand along fenclines also around grass area. and busturnaround								
Rudy Arreola									
45792		Library			5/18/2009		15		\$0.00
Medium	Work In Progress			5/18/2009 1:51:17 PM					
Sotelo, Enrique	Need 2 electrical outlets in the library to set up two televisions that are on the wall. Have electrician see Rudy for further information.								
Sandra Almeraz									
45850	Main Building	Cafeteria			5/19/2009		14		\$0.00
Medium	Work In Progress			5/19/2009 3:39:56 PM					
Orozco, Danny	CHECK EXHAUST FANS IN KITCHEN								
Danny Orozco									
45864					5/20/2009		13		\$0.00
Medium	Work In Progress			5/20/2009 8:21:46 AM					
Ontiveros, Guadalupe	Irrigation System needs major repair. adj sprinkler heads, replace broken sprinklers, box covers and broken waterline. (Rudy will assist in this project asp discussion w/Mike).								
Michael Munoz									
45865		Cafeteria			5/20/2009		13		\$0.00
Medium	Work In Progress			5/20/2009 8:25:39 AM					
Solis, Lorenzo	BOTH AIR CONDITIONERS ARE OUT. NOT WORKING AT ALL		FRANCES BLACK SNP MGR 882-4707		5/26 - ROUTE TO LORENZO - DO				
Jacqueline Aguilar									
45989		Athletic Field			5/26/2009		7		\$0.00
Medium	Work In Progress			5/26/2009 10:24:52 AM					
Jacquez, Ricardo	Water booster pump needs to be checked it stops running and is very hot.ASAP								
Rudy Arreola									
46001					5/26/2009		7		\$0.00
Medium	Work In Progress			5/26/2009 2:16:41 PM					
Arreola, Rudy	Rudy, Mrs. Ward is moving into one of the portables, she is wanting you to repair the ramp. Please.								
Grace Alvarado									
6/2/2009 9:39:32 AM									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
46227					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:50 AM					
Arreola, Rudy	Yearly - Loma Linda ES B2 (Boiler)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
46228					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:51 AM					
Arreola, Rudy	Yearly - Loma Linda ES A2 (Split System)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
46229					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:51 AM					
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
46230					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:51 AM					
Arreola, Rudy	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46231					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:52 AM					
Arreola, Rudy	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46268		Cafeteria			6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 9:25:41 AM					
Orozco, Danny	THE ELECTRICAL CORD TO CASH REGISTER NEEDS TO BE REPAIRED.								
FRANCES BLACK 882-4707									
Jacqueline Aguilar									
<b>Count: 29 Work Orders</b>		<b>Avg. Age of WO's 55</b>			<b>Total for Loma Linda ES</b>			<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
38210					9/18/2008		257		\$0.00
Medium	Work In Progress			9/18/2008 9:18:18 AM					
Sotelo, Enrique		marquee lights not working.							
Joe Ramirez									
41227	Main Building	Classroom			1/7/2009		146		\$0.00
Medium	Work In Progress	Room # 203		1/7/2009 8:59:31 AM					
Lozoya, Manny		Key is needed for Pamela Uribe IA to that classroom.							
Sandra Mora									
41305		Classroom			1/9/2009		144		\$0.00
Medium	Work In Progress			1/9/2009 8:12:50 AM					
Lozoya, Manny		Rm 608 (Wendy Tow) - Door continues to stick, even after it has been fixed.							
Joe Ramirez									
41567					1/16/2009		137		\$0.00
Medium	Work In Progress			1/16/2009 9:32:05 AM					
Ontiveros, Joe		outside drinking fountain one bubbler missing the other one doesn't work need to be replaced.							
Joe Ramirez									
41690	Main Building	Classroom			1/21/2009		132		\$0.00
Medium	Work In Progress	Room # 203		1/21/2009 10:37:15 AM					
Lozoya, Manny		Pamela Uribe IA needs key we don't have another in key box for that room.							
Sandra Mora									
41977					1/29/2009		124		\$0.00
High	Work In Progress			1/29/2009 8:14:01 AM					
Gonzalez, Salvador		covers to lift station are rusty and old and need replacement ASAP. safty thxs							
Michael Munoz									
43297					3/4/2009		90		\$0.00
Medium	Work In Progress			3/4/2009 8:56:21 AM					
Lozoya, Manny		i need 3 latchkeepers for bathroom stalls.							
Joe Ramirez									
44087					3/31/2009		63		\$0.00
Medium	Work In Progress			3/31/2009 12:22:48 AM					
Ramirez, Joe		Monthly - Mesquite ES A-16 Fan Exhaust Semiannual - Refer to PM schedule details.							
Margret Villalobos									
44088					3/31/2009	5/1/2009	63		\$0.00
Medium	Work In Progress			3/31/2009 12:22:48 AM					
Ramirez, Joe		Yearly - Mesquite ES A-8 A/C Window Unit Yearly - Refer to PM schedule details.							
Margret Villalobos									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
44395					4/5/2009	4/21/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:23:09 AM					
Ramirez, Joe	Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.								
Margret Villalobos									
44396					4/5/2009	4/13/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:23:09 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
44397					4/5/2009		58		\$0.00
Medium	Work In Progress			4/5/2009 12:23:10 AM					
Ramirez, Joe	Yearly - Mesquite ES A-13 A/C Wall Mount Yearly - Refer to PM schedule details.								
Margret Villalobos									
44398					4/5/2009	4/13/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:23:10 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
44399					4/5/2009	4/13/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:23:10 AM					
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
44400					4/5/2009	4/11/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:23:11 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
44448					4/6/2009		57		\$0.00
Medium	Work In Progress			4/6/2009 10:36:12 AM					
Ronquillo, Ruben	need to replace 1,000 feet of covebase in the hallways.								
Joe Ramirez									
45309					5/3/2009	5/11/2009	30		\$0.00
Medium	Work In Progress			5/3/2009 12:22:45 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
45310					5/3/2009	5/11/2009	30		\$0.00
Medium	Work In Progress			5/3/2009 12:22:45 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

6/2/2009 9:39:32 AM

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
45311					5/3/2009	5/9/2009	30		\$0.00
Medium	Work In Progress			5/3/2009 12:22:46 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45413					5/5/2009		28		\$0.00
Medium	Work In Progress			5/5/2009 11:22:46 AM					
Ramirez, Joe	joe as per pictures e-mailed to you could you please trim trees that need to be, remove chinese elm, rake leaves trim parking lot / mulberry area and sweep.also water bty main entrance.(office area) thankyou								
<u>Michael Munoz</u>									
45414					5/5/2009		28		\$0.00
High	Work In Progress			5/5/2009 11:24:54 AM					
Ramirez, Joe	please re-paint yellow parking lines and paint also fire lanes and handi-cap parking if need be.thanks								
<u>Michael Munoz</u>									
45415					5/5/2009		28		\$0.00
High	Work In Progress			5/5/2009 11:26:51 AM					
Ramirez, Joe	Joe as per pictures e-mailed, please repair soffit and paint. also apply 10% bleach solution as per discussion with you. thanks								
<u>Michael Munoz</u>									
45514					5/8/2009		25		\$0.00
Medium	Work In Progress			5/8/2009 7:08:57 AM					
Sotelo, Enrique	bathroom light not working need special ballast.								
<u>Joe Ramirez</u>									
45636					5/12/2009		21		\$0.00
Medium	Work In Progress			5/12/2009 10:24:47 AM					
Ramirez, Joe	as per Mr. Gallegos removing selected light bulbs on hallways,teachers lounge to save energy c.a.s.h. program								
<u>Luis Saucedo</u>									
45992	Main Building	Office			5/26/2009		7		\$0.00
Medium	Work In Progress	front office		5/26/2009 10:50:25 AM					
Lozoya, Manny	Will you please make a door plaques for: Jacob Montano - Principal Norma Sandoval - Asst. Principal Maribel Villela - Receptionist Sandra L. Mora - Secretary								
<u>Sandra Mora</u>									

**1049 - Work Orders In Progress (Fiscal Year)**

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
46073	Main Building				5/28/2009		5		\$0.00
High	Work In Progress				5/28/2009 1:18:02 PM				
Munoz, Michael	metal roof is corroding, please repair.								
Alfredo Holguin									
46207					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:43 AM				
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46208					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:43 AM				
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46209					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:43 AM				
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
46210					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:44 AM				
Ramirez, Joe	Yearly - Mesquite ES A-2 Electric Heat Yearly - Refer to PM schedule details.								
Margret Villalobos									
46211					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:44 AM				
Ramirez, Joe	Yearly - Mesquite ES B-2 Boiler Yearly - Refer to PM schedule details.								
Margret Villalobos									
46270					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 10:42:23 AM				
Solis, Lorenzo	large a/c on top of barracks needs to be removed it's rotting								
Joe Ramirez									
46272					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 11:00:25 AM				
Carbajal, Jimmy	please flat tire ( dolly) thank you. luis								
Luis Saucedo									
46274					6/1/2009		1		\$0.00
Medium	Work In Progress				6/1/2009 11:02:08 AM				
Carbajal, Jimmy	please the handle fro the vaccum is not working & makes a lot a noise thank you, luis								
Luis Saucedo									
<b>Count: 34 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>53</b>	<b>Total for Mesquite ES</b>			<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: North Valley ES</b>									
38743					10/5/2008		240		\$0.00
Medium	Work In Progress			10/5/2008 12:23:50 AM					
Holguin, Alfredo	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.		10/6/08 - Emailed to Ricky Borrego						
<u>Margret Villalobos</u>									
41151					1/4/2009		149		\$0.00
Medium	Work In Progress			1/4/2009 12:19:23 AM					
Holguin, Alfredo	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.		1/6/09 - E-mailed to ricky.borrego@cummins.com'						
<u>Margret Villalobos</u>									
42695					2/19/2009		103		\$0.00
Medium	Work In Progress			2/19/2009 8:14:21 AM					
Holguin, Alfredo	Rm 201 - Unit was changed out and is still going out on Hi/low pressure cutout.		This work order is for Trane.						
<u>Lorenzo Solis</u>									
42737					2/20/2009		102		\$0.00
Medium	Work In Progress			2/20/2009 8:28:56 AM					
Holguin, Alfredo	Rm 101 - Unit going out on Hi/low pressure cutout.								
<u>Lorenzo Solis</u>									
44289					4/5/2009		58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:31 AM					
Holguin, Alfredo	Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.		4/7/09 E-mailed PM to Ricky and Garrett at Rocky Mtn.						
<u>Margret Villalobos</u>									
44343					4/5/2009	4/13/2009	58	1	\$25.00
Medium	Work In Progress			4/5/2009 12:22:51 AM					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.		done						
<u>Margret Villalobos</u>									
44444					4/6/2009		57		\$446.50
Medium	Work In Progress			4/6/2009 8:58:26 AM					
Solis, Lorenzo	We have no communication w/BCU. Tech has reset BCU and it will not reset. Please send someone out a/s/a/p								
<u>Lorenzo Solis</u>									
45212					4/30/2009		33		\$0.00
Medium	Work In Progress			4/30/2009 2:05:12 PM					
Gonzales, Angel	pump house diesel fuel tank needs to be topped -off showing 3/4 full as of 4-30-09								
<u>Danny Vega</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>North Valley ES</b>								
45492					5/7/2009		26		\$0.00	
Medium	Work In Progress			5/7/2009 12:30:32 PM						
Ontiveros, Joe	PECAN VALLEY BYS SINK FAUCET WONT TURN - OFF PLUS LADIES RR BY LOUNGE SAME PROBLEM -ANGLE STOPS WONT TURN -OFF .PLEASE CK OUT ASAP -ORDER NEW FAUCETS									
<u>Danny Vega</u>										
46147					5/31/2009	6/6/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:21 AM						
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
46149					5/31/2009	6/8/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:21 AM						
Vega, Danny	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
46151					5/31/2009	6/8/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:22 AM						
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
46158					5/31/2009		2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:25 AM						
Vega, Danny	Monthly - North Valley ES A16 (Fan Exhst)(S.Ann.) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
46159					5/31/2009	7/1/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:25 AM						
Vega, Danny	Yearly - North Valley ES A2 (H/C Unit)(Yearly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
46160					5/31/2009	6/21/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:25 AM						
Vega, Danny	Monthly - North Valley ES H11(E.Heat)(S.Annual) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
<b>Count: 15 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>56</b>	<b>Total for North Valley ES</b>			<b>1</b>	<b>\$471.50</b>	

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
40019	Main Building	Classroom			11/12/2008		202		\$0.00
Medium	Work In Progress				11/12/2008 8:35:22 AM				
Sotelo, Enrique classroom plug switch is shorted out.room 112 Gilbert Trujillo									
41981	Cafeteria				1/29/2009		124		\$0.00
Medium	Work In Progress				1/29/2009 8:40:25 AM				
Carrasco, Danny please pick-up shelving that belongs to gms and deliver to sunland carpentry, so they can make adjustments for installation at loma linda. as per ida garcia and phillip medina									
Michael Munoz									
42974	Main Building	Elevator			2/26/2009		96		\$0.00
Medium	Work In Progress				2/26/2009 11:30:06 AM				
Lozoya, Manny we need 1 master key for alma del valle day care Gilbert Trujillo									
43540					3/10/2009		84		\$0.00
Medium	Work In Progress				3/10/2009 11:17:33 AM				
Lozoya, Manny rm110 keys binding in cylinder /need to clean or replace key cylinder /alma del valle talk with maria she will show you /please ck her key as well									
Danny Vega									
45595					5/11/2009		22		\$0.00
Medium	Work In Progress				5/11/2009 2:23:46 PM				
Lozoya, Manny mens restroom by lounge/door handle cylinder keeps falling -off-please ck out asap									
Danny Vega									
45607					5/11/2009		22		\$0.00
Medium	Work In Progress				5/11/2009 3:41:20 PM				
Sotelo, Enrique need additional lighting in custodial closet by girls restrooms-4ft flourescent lamp .please									
Danny Vega									
46148					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:21 AM				
Vega, Danny Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.									
Margret Villalobos									
46150					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:22 AM				
Vega, Danny Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.									
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Northern On-Track Pre-K (LM)</b>							
46152					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:22 AM					
Vega, Danny		Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
46153					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:23 AM					
Vega, Danny		Yearly - Northern Prek B2 (Boiler)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
46154					5/31/2009	6/21/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:23 AM					
Vega, Danny		Monthly - Northern Prek C12(Chem.Feeder)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
46155					5/31/2009		2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:24 AM					
Vega, Danny		Monthly - Northern Prek A16(Fan Exhst)(S. Annual) - Refer to PM schedule details.							
Margret Villalobos									
46156					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:24 AM					
Vega, Danny		Yearly - Northern Prek A2 (H/C Unit)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
46157					5/31/2009	6/21/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:24 AM					
Vega, Danny		Monthly - Northern Prek H11(E.Heat)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 14 Work Orders</b>		<b>Avg. Age of WO's 40</b>		<b>Total for Northern On-Track Pre-K (LM)</b>				<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
36213	Maintenance				7/25/2008		312		\$0.00
Medium	Work In Progress				7/25/2008 10:15:21 AM				
Sotelo, Enrique	please install electrical outlet to cooling duct fan and pilot switch. Thxs								
<u>Michael Munoz</u>									
36291					7/28/2008		309		\$0.00
Medium	Work In Progress				7/28/2008 3:26:53 PM				
Ronquillo, Ruben	Purchase a new water tank								
<u>Alfredo Holguin</u>									
36355	Food Services	Parking Lot			7/30/2008		307		\$0.00
Medium	Work In Progress	SNP			7/30/2008 12:01:33 PM				
Ontiveros, Guadalupe	AS PER MR. GIOVAS-IF NEAR THE WAREHOUSE GOING FROM THE SHADED AREA TO THE STAIR WAY INTO THE WAREHOUSE IF THEY CAN LEVEL OUT THE PATH WAY. (PLEASE SEE JOHNNY L. IF NEED DIRECTION.)								
<u>Mary Garcia</u>									
37767					9/4/2008		271		\$0.00
Medium	Work In Progress				9/4/2008 8:02:44 AM				
Lozoya, Manny	need to replace door lock on water department office does not lock thanks								
<u>Ricardo Jacquez</u>									
37791	Purchasing				9/4/2008		271		\$0.00
Medium	Work In Progress				9/4/2008 2:35:30 PM				
Sotelo, Enrique	I would like to have a light switch in my office to control the lights. Currently the switch is in the hall and the one switch controls my office and hallway.								
<u>Vicky Lopez</u>									
37882	Food Services				9/8/2008		267		\$0.00
Medium	Work In Progress				9/8/2008 8:10:34 AM				
Ontiveros, Guadalupe	Need to add Crusher fines to dock area.								
<u>Alfredo Holguin</u>									
39941					11/7/2008		207		\$0.00
Medium	Work In Progress				11/7/2008 1:06:01 PM				
Ontiveros, Guadalupe	Gooseneck Trailers 2 ea. - Replace damaged floor boards								
<u>Alfredo Holguin</u>									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
41518	Food Services	Cafeteria			1/15/2009		138		\$0.00
Medium	Work In Progress				1/15/2009 9:29:05 AM				
Moncayo, Fernando	WORK ORDER FOR GADSDEN STUDENT NUTRITION PROGRAM WAREHOUSE - -- MOTOR WENT OUT TO THE FURNACE								
	JOHNNY LECHUGA - SNP WAREHOUSE MGR 882-6927								
<hr/>									
Alma Terrell					1/27/2009		126		\$0.00
41915									
Medium	Work In Progress				1/27/2009 4:07:07 PM				
Gonzales, Angel	Mail Van - driver side seat needs additional padding call Alfredo Holguin if you have questions								
<hr/>									
Alfredo Holguin					2/4/2009		118		\$0.00
42215	Maintenance								
Medium	Work In Progress				2/4/2009 8:52:47 AM				
Sotelo, Enrique	Need to remove electrical from old HVAC Shop.								
<hr/>									
Manny Lozoya					2/4/2009		118		\$0.00
42228	Maintenance								
Medium	Work In Progress				2/4/2009 1:23:11 PM				
Miranda, Danny	FRAME AND FURR MAINT.WHS. OPENING TO PLUMBING DANNY MIRANDA								
<hr/>									
Danny Carrasco					2/4/2009		118		\$0.00
42234	Maintenance								
Medium	Work In Progress				2/4/2009 3:22:07 PM				
Lozoya, Manny	NEED TO INSTALL BARREL BOLT ON PLUMB. EXIT DOUBLE DOOR								
<hr/>									
Ruben Ronquillo					2/5/2009		117		\$0.00
42264	Maintenance								
Medium	Work In Progress				2/5/2009 10:40:01 AM				
Sotelo, Enrique	Need to change bulbs in my office.								
<hr/>									
Margret Villalobos					2/9/2009		113		\$0.00
42359	Food Services	Electrical Room							
Medium	Work In Progress				2/9/2009 8:24:32 AM				
Sotelo, Enrique	need to Relocated swich box where they installed the new door frame. thank you								
<hr/>									
Ralph Lara					2/25/2009		97		\$0.00
42915									
Medium	Work In Progress				2/25/2009 11:25:40 AM				
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Physical Plant Complex</b>							
42917					2/25/2009		97		\$0.00
Medium	Work In Progress			2/25/2009 11:26:42 AM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.								
<u>Michael Munoz</u>									
42929					2/25/2009		97		\$0.00
Medium	Work In Progress			2/25/2009 12:32:49 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians c tools and equipment. Ask Ruben for present inventory list to match up.								
<u>Michael Munoz</u>									
42930					2/25/2009		97		\$0.00
Medium	Work In Progress			2/25/2009 12:35:59 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians c tools and equipment. Ask Ruben for present inventory list to match up.								
<u>Michael Munoz</u>									
42931					2/25/2009		97		\$0.00
Medium	Work In Progress			2/25/2009 12:36:53 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.								
<u>Michael Munoz</u>									
42932					2/25/2009		97		\$0.00
Medium	Work In Progress			2/25/2009 12:37:43 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.								
<u>Michael Munoz</u>									
42933					2/25/2009		97		\$0.00
Medium	Work In Progress			2/25/2009 12:39:11 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.								
<u>Michael Munoz</u>									
43127					3/1/2009		93		\$0.00
Medium	Work In Progress			3/1/2009 12:23:04 AM					
Orozco, Danny	Yearly - Physical Plant Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
43420	Food Services	Cafeteria			3/6/2009		88		\$0.00
Medium	Work In Progress				3/6/2009 9:35:24 AM				
Moncayo, Fernando	SNP WHSE: Need to replace some lights that went out in the SNP Warehouse.								
Jacqueline Aguilar	Johnny Lechuga SNP WHSE MGR 882-6927								
43574					3/11/2009		83		\$0.00
High	Work In Progress				3/11/2009 8:35:17 AM				
Gonzales, Angel	please install trailer brakes on vehicle #152. Thankyou								
Michael Munoz									
43818	Motor Vehicle	Electrical Room			3/17/2009		77		\$0.00
Medium	Work In Progress				3/17/2009 4:00:47 PM				
Gonzales, Angel	Vehicle #152 needs a new set of tires.								
Carlos Castillo									
43875					3/19/2009		75		\$0.00
Medium	Work In Progress				3/19/2009 1:13:24 PM				
Gonzales, Angel	Need to install flashing light and backup alarm signal on all Maintenance Vehicles - asp Mike Munoz.								
Michael Munoz									
43876	Motor Vehicle				3/19/2009		75		\$0.00
Medium	Work In Progress				3/19/2009 1:14:17 PM				
Gonzales, Angel	PLEASE CHECK WATER PUMP ENGINE, NOT STARTING. THANKS RUBEN								
Ruben Ronquillo									
43877	Motor Vehicle				3/19/2009		75		\$0.00
Medium	Work In Progress				3/19/2009 1:15:08 PM				
Gonzales, Angel	PLEASE CHECK YELLOW DOUBLE AIR TANK COMPRESSOR, IDLE IS NOT WORKING, IT WILL NOT IDLE DOWN WHEN TANKS ARE FULL. THANKS RUBEN								
Ruben Ronquillo									
44121	Maintenance				3/31/2009		63		\$0.00
Medium	Work In Progress				3/31/2009 1:58:40 PM				
Carrasco, Danny	Asp Mike need to shrink wrap all Video Equipment stored in storage room in Tech Office.								
Michael Munoz									
44158	Maintenance				4/1/2009		62		\$0.00
Medium	Work In Progress				4/1/2009 10:09:41 AM				
Gonzales, Angel	Also generate a w/o for Angel to check the generator for proper operation. The small one we have here at the maint office. (Will be needed on May 8th @ GHS)								
Michael Munoz									
6/2/2009 9:39:33 AM									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Physical Plant Complex</b>							
44545					4/8/2009		55		\$0.00
Medium	Work In Progress			4/8/2009 1:25:02 PM					
Gonzales, Angel	Truck #16 needs brakes checked, front wheels drag when it stops. Need new wiper blades.								
<u>Jesus Estrada</u>									
45420					5/5/2009		28		\$0.00
Medium	Work In Progress			5/5/2009 2:24:27 PM					
Lara, Ralph	RELOCATE DOUBLE DOORS ON BARRACK #1.								
<u>Ruben Ronquillo</u>									
45578					5/11/2009		22		\$0.00
Medium	Work In Progress			5/11/2009 7:44:59 AM					
Gonzalez, Salvador	5-11-09 I need to make a metal cage to work.								
<u>Salvador Gonzalez</u>									
45581	Purchasing				5/11/2009		22		\$0.00
Medium	Work In Progress			5/11/2009 8:12:57 AM					
Diaz, Sebastian	Need to check our AC first thing on Monday? It is blowing warm air. Thank you.								
<u>Vicky Lopez</u>									
45728					5/14/2009		19		\$0.00
Medium	Work In Progress			5/14/2009 1:30:55 PM					
Ronquillo, Ruben	need to order 100 parking curbs for new parking set up to be.								
<u>Michael Munoz</u>									
45871					5/20/2009		13		\$0.00
Medium	Work In Progress			5/20/2009 11:11:41 AM					
Gonzales, Angel	please check electricians vehicle(kali) for proper operation of trailer brakes. As per kali the brakes in-gage when the flashers are on.thxs								
<u>Michael Munoz</u>									
45990					5/26/2009		7		\$0.00
Medium	Work In Progress			5/26/2009 10:40:47 AM					
Gonzales, Angel	Ditch Witch 4210 trencher-backhoe- Repair								
<u>Alfredo Holguin</u>									
45991					5/26/2009		7		\$0.00
Medium	Work In Progress			5/26/2009 10:42:47 AM					
Gonzales, Angel	John Deere 5510 - Repair								
<u>Alfredo Holguin</u>									
46058					5/28/2009		5		\$0.00
Medium	Work In Progress			5/28/2009 12:18:36 AM					
Holguin, Alfredo	Yearly - PPD - Maintenance Plan - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Physical Plant Complex</b>							
46074	Maintenance				5/28/2009		5		\$0.00
Medium	Work In Progress				5/28/2009 2:00:32 PM				
Gonzales, Angel		Vehicle #99 - Needs to be serviced, belt is squeaking, hard to start. Will be on vacation July 6 - July 21, 2009							
Michael Munoz									
46239					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:55 AM				
Diaz, Sebastian		Monthly - Physical Plant FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 41 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>106</b>	<b>Total for Physical Plant Complex</b>			<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Riverside ES</b>									
37820					9/5/2008		270		\$0.00
Medium	Work In Progress			9/5/2008 8:39:36 AM					
Gonzalez, Salvador	Need to make a canopy for behind of cafeteria.								
Michael Munoz									
40264					11/20/2008		194		\$0.00
Medium	Work In Progress			11/20/2008 3:11:28 PM					
Gonzales, Angel	truck seat needs repair truck #21								
Carlos Hernandez									
40877		Cafeteria			12/15/2008		2	1	\$25.00
Medium	Work In Progress			12/15/2008 3:27:13 PM	12/17/2008				
Moncayo, Fernando	alarm showing dirty duct in cafeteria and dirty 2, 16		12/17/08 ck Dimar Report was showing exhaust fan in kitchen alarm. Ck inside and it reflects to kitchen equip, route to Fernie.						
Carlos Hernandez	- J. Ambriz								
40950					12/17/2008		167		\$0.00
Medium	Work In Progress			12/17/2008 3:08:54 PM					
Moncayo, Fernando	range hood systems exhaust fan not operating								
Carlos Hernandez									
42801	New Wing 1/02				2/23/2009		99		\$0.00
Medium	Work In Progress			2/23/2009 2:58:23 PM					
Castillo, Carlos	need new switch for heater room 104								
Carlos Hernandez									
43114					3/1/2009		93		\$0.00
Medium	Work In Progress			3/1/2009 12:22:59 AM					
Orozco, Danny	Yearly - Riverside ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
43598		Cafeteria			3/11/2009		83		\$0.00
Medium	Work In Progress			3/11/2009 1:00:50 PM					
Moncayo, Fernando	EXHAUST WON'T TURN ON								
	AIDA SALCEDO - SNP COMPLIANCE COORDINATOR								
	915/472-4748								
Alma Terrell									
43599		Cafeteria			3/11/2009		83		\$0.00
Medium	Work In Progress			3/11/2009 1:02:05 PM					
Moncayo, Fernando	TWO LIGHTS IN THE EXHAUST AREA ARE DOWN								
	AIDA SALCEDO -SNP COMPLIANCE COORDINATOR								
	915-472-4748								
Alma Terrell									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
44329					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:47 AM					
Orozco, Danny	Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
45096		Classroom			4/28/2009		35		\$0.00
Medium	Work In Progress	1st to 5th grade		4/28/2009 11:45:38 AM					
Hernandez, Carlos	Furniture for computers delivered to the school please set up in classrooms first to fifth grade. Furniture will be delivered to the school on April 30th. Thank you.								
Sandra Almeraz									
45684	Main Building	Classroom			5/13/2009		20		\$0.00
Medium	Work In Progress			5/13/2009 3:00:37 PM					
Ambriz, Jose	need new a/c unit room 34and39								
Carlos Hernandez									
45734	Main Building	Classroom			5/14/2009		19		\$0.00
Medium	Work In Progress			5/14/2009 3:15:22 PM					
Castillo, Carlos	have a electrical short on going to a/c unit. unit turns on and off								
Carlos Hernandez									
45919		Cafeteria			5/21/2009		12		\$0.00
Medium	Work In Progress			5/21/2009 1:17:51 PM					
Moncayo, Fernando	STOVE OVEN DOES NOT TURN ON. EMILIA CARRILLO SNP MGR 589-2550								
Jacqueline Aguilar									
45928					5/21/2009		12		\$0.00
Medium	Work In Progress			5/21/2009 3:13:53 PM					
Villalobos, David	got cloged uniral boys b-room upper grade								
Carlos Hernandez									
46017					5/27/2009		6		\$0.00
Medium	Work In Progress			5/27/2009 8:12:23 AM					
Gonzales, Angel	truck has flat tire								
Carlos Hernandez									
46036	Main Building	Hallway/Corridor			5/27/2009		6		\$0.00
Medium	Work In Progress			5/27/2009 2:15:07 PM					
Carbajal, Jimmy	ROYAL BURNISHER HAS A BURNED MOTOR								
Jimmy Carbajal									
46078					5/28/2009		5		\$0.00
Medium	Work In Progress			5/28/2009 3:01:19 PM					
Gonzales, Angel	got flat tire on truck rear right								
Carlos Hernandez									

6/2/2009 9:39:33 AM

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Riverside ES</b>								
46133					5/31/2009	6/6/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:15 AM						
Hernandez, Carlos	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
46134					5/31/2009	6/8/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:16 AM						
Hernandez, Carlos	Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
46135					5/31/2009	6/8/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:16 AM						
Hernandez, Carlos	Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
46136					5/31/2009	7/1/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:16 AM						
Hernandez, Carlos	Yearly - Riverside ES A-2 Gas/Elec Unit Yearly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
46137					5/31/2009	7/1/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:17 AM						
Hernandez, Carlos	Yearly - Riverside ES B-2 Boiler Hot Water Yearly - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
46259					6/1/2009		1		\$0.00	
Medium	Work In Progress			6/1/2009 7:25:28 AM						
Ronquillo, Ruben	need swing swivel assemley 20 or 10 sets									
<u>Carlos Hernandez</u>										
46311					6/1/2009		1		\$0.00	
Medium	Work In Progress			6/1/2009 3:50:55 PM						
Lara, Ralph	need to replace key and lock cylinder due to lost key for room 123									
<u>Carlos Hernandez</u>										
46312					6/1/2009		1		\$0.00	
Medium	Work In Progress			6/1/2009 3:53:04 PM						
Lara, Ralph	need to replace door cylinder and keys to portable 503 due to lost key and to main door to new wing									
<u>Carlos Hernandez</u>										
<b>Count: 25 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>47</b>				<b>Total for Riverside ES</b>	<b>1</b>	<b>\$25.00</b>



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: San Miguel ES</b>									
43315	Main Building				3/4/2009		90		\$0.00
Medium	Work In Progress				3/4/2009 1:58:33 PM				
Ramirez, Joe		Need to clean around pine trees.							
Michael Munoz									
43425	Main Building	Mechanical Room			3/6/2009		88		\$0.00
Medium	Work In Progress				3/6/2009 12:42:01 PM				
Solis, Lorenzo		Check boiler room.							
Lorenzo Solis									
45751		Cafeteria			5/15/2009		18		\$0.00
Medium	Work In Progress				5/15/2009 10:45:31 AM				
Solis, Lorenzo		Please pick up ice machine and install at ppd. see mike if you have questions.thxs							
Michael Munoz									
<b>Count: 3 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>65</b>			<b>Total for San Miguel ES</b>	<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
45570					5/10/2009	5/26/2009	23		\$0.00
Medium	Work In Progress			5/10/2009 12:19:12 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
39918	Main Building	Restroom (Girls)			11/6/2008		208		\$0.00
Medium	Work In Progress	ladies restroom		11/6/2008 3:11:24 PM					
Marquez, Gerardo	Large spacing in between the wall and other toilet partition needs to be covered. The gap is large enough to see other people inside the stall. Thank you.								
<u>Rita Mendez</u>									
41278		Classroom			1/8/2009		145		\$0.00
Medium	Work In Progress	RM 102		1/8/2009 3:18:53 PM					
Marquez, Gerardo	NEED RACK FOR JACKETS TO SET UP IN CLASSROOM 102								
<u>Rita Mendez</u>									
41990					1/29/2009		124		\$0.00
Medium	Work In Progress			1/29/2009 1:38:38 PM					
Moncayo, Fernando	FERNIE; THE HANDWASHING STATIONS IN THE CAFET. PREP AREA ARE BOTH RUNNING CONTINUOUSLY. WOULD YOU PLEASE CORRECT THE PROBLEM.								
<u>Gerardo Marquez</u>									
42521					2/12/2009		110		\$0.00
Medium	Work In Progress			2/12/2009 11:03:36 AM					
Ontiveros, Guadalupe	LUPE, AS PER OUR CONVERSATION ON 2/12/09. WE NEED TO HAVE THE S. W. CORNER OF THE FENCE THAT THE CONTRACTOR STATED TO REMOVE PUT BACK UP.								
<u>Gerardo Marquez</u>									
42672	Main Building	Parking Lot			2/18/2009		104		\$0.00
Medium	Work In Progress	FENCE		2/18/2009 1:21:13 PM					
Ronquillo, Ruben	NEED 2 SIGNS TO SAY: NOT A STUDENT DROP OFF. THESE SIGNS NEED TO BE POSTED AT FACULTY PARKING LOT ENTRANCE. NEED SIGNS TO BE BIG ENOUGH TO BE VISIBLE. THANKS.								
<u>Rita Mendez</u>									
43573					3/11/2009		83		\$0.00
Medium	Work In Progress			3/11/2009 8:32:09 AM					
Castillo, Carlos	CALI; THERE ARE 3 BURNT OUT LIGHTS IN THE FACULTY PARKING LOT THAT NEED REPLACING. WOULD YOU PLEASE SCHEDULE THE LIFT TO CHANGE THEM OUT.								
<u>Gerardo Marquez</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
43785					3/17/2009		77		\$0.00
Medium	Work In Progress			3/17/2009 10:31:16 AM					
Villalobos, David	DAVID, COULD YOU PLEASE CHECK OUT FAUCETS IN GIRLS RRM. BY CAFETERIA & ALSO @ TEACHERS LOUNGE.								
<u>Gerardo Marquez</u>									
44496					4/7/2009		56		\$0.00
Medium	Work In Progress			4/7/2009 9:11:13 AM					
Ontiveros, Guadalupe	LUPE, NEED TO SCHEDULE TO HAVE PLAYGROUND AREA AERATED, & FERTILIZED. THANKS.								
<u>Gerardo Marquez</u>									
44498					4/7/2009		56		\$0.00
Medium	Work In Progress			4/7/2009 9:25:06 AM					
Ontiveros, Guadalupe	LUPE, SOUTHWEST CORNER OF FENCE THAT WAS PARTIALLY REMOVED BY ACADEMY FENCE WAS NEVER REPAIRED . AT ONE TIME YOU SENT RAFA TO TAKE CARE OF THIS. COULD YOU TAKE CARE OF THIS?								
<u>Gerardo Marquez</u>									
44641					4/12/2009	4/28/2009	51		\$0.00
Medium	Work In Progress			4/12/2009 12:21:25 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45094		Classroom			4/28/2009		35		\$0.00
Medium	Work In Progress	1st - 5th grade		4/28/2009 11:41:37 AM					
Marquez, Gerardo	Furniture for computers delivered to the school please set up in classrooms first to fifth grade. Furniture will be delivered on Apri. 28. Thank you.								
<u>Sandra Almeraz</u>									
45288					5/3/2009	5/11/2009	30		\$0.00
Medium	Work In Progress			5/3/2009 12:22:37 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
45525	Main Building	Classroom			5/8/2009		25		\$0.00
Medium	Work In Progress	RM 102		5/8/2009 9:36:30 AM					
Marquez, Gerardo	OVERHEAD SCREEN NEEDS TO BE REMOVED AND SET UP IN ANOTHER AREA IN THE CLASSROOM. THANKS.								
Rita Mendez									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Santa Teresa ES</b>								
45528	Main Building	Classroom			5/8/2009		25		\$0.00	
Medium	Work In Progress	RM 102			5/8/2009 9:47:28 AM					
Lara, Ralph		THE LOCKS IN THE TALL CABINET DOOR NEED TO BE REPLACED. THANKS.								
Rita Mendez										
45794	Main Building	Classroom			5/18/2009		15		\$0.00	
Medium	Work In Progress	room 201			5/18/2009 2:18:36 PM					
Marquez, Gerardo		CHILDREN'S PLAY FURNITURE NEEDS TO BE ASSEMBLED. THANK YOU.								
Rita Mendez										
45876	Main Building	Office			5/20/2009		13		\$0.00	
Medium	Work In Progress	office			5/20/2009 3:13:58 PM					
Lara, Ralph		A BATWING DOOR NEEDS TO BE INSTALLED AT THE END OF THE COUNTER IN THE OFFICE. THANK YOU.								
Rita Mendez										
45906					5/21/2009		12		\$0.00	
Medium	Work In Progress				5/21/2009 9:23:25 AM					
Gonzales, Angel		ANGEL, I WILL NEED TO START CUTTING THE GRASS ON 6/2/09. WOULD YOU PLEASE DELIVER THE MOWER TO STE. THANKS.								
Gerardo Marquez										
45951		Classroom			5/22/2009		11		\$0.00	
Medium	Work In Progress	MS. URREA'S			5/22/2009 8:06:06 AM					
Marquez, Gerardo		MS. URREA'S PORTABLE NEEDS INTERIOR PAINTING. THANK YOU.								
Rita Mendez										
46037	Main Building	Portables			5/27/2009		6		\$0.00	
Medium	Work In Progress	ART PORTABLE			5/27/2009 2:54:24 PM					
Marquez, Gerardo		MS. JOHNSON NEEDS A CABINET TO BE PUT TOGETHER IN HER CLASSROOM. THANK YOU.								
Rita Mendez										
46062	Main Building	Classroom			5/28/2009		5		\$0.00	
Medium	Work In Progress	RM 304 READ			5/28/2009 9:13:07 AM					
Marquez, Gerardo		OVERHEAD SCREEN NEEDS TO BE MOVED TO ANOTHER LOCATION. THANK YOU.								
Rita Mendez										
46171					5/31/2009		2		\$0.00	
Medium	Work In Progress				5/31/2009 12:23:29 AM					
Marquez, Gerardo		Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos										

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
46172					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:30 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46173					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:30 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46174					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:31 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
46285		Parking Lot			6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 2:17:31 PM					
Aldaz, Bobby	Need for Mr.Barrientos or Mr.Aldaz to tranfer Lift to La Union Elementary from Sta.Teresa Elementary.								
Carlos Castillo									
<b>Count: 26 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>47</b>		<b>Total for Santa Teresa ES</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
35552					7/6/2008	7/12/2008	331		\$0.00
Medium	Work In Progress			7/6/2008 12:19:21 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
35569					7/6/2008	7/14/2008	331		\$0.00
Medium	Work In Progress			7/6/2008 12:19:26 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
35666					7/6/2008	8/6/2008	331		\$0.00
Medium	Work In Progress			7/6/2008 12:19:56 AM					
Nunez, Arturo		Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
35689					7/6/2008	8/6/2008	331		\$0.00
Medium	Work In Progress			7/6/2008 12:20:04 AM					
Nunez, Arturo		Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
36510					8/3/2008	8/9/2008	303		\$0.00
Medium	Work In Progress			8/3/2008 12:20:16 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
37386					8/26/2008		280		\$0.00
Medium	Work In Progress			8/26/2008 7:30:49 AM					
Ontiveros, Guadalupe		Pedestrian Gate on South side that goes to the Bluffs. - Install taller gate to prevent access through bottom of gate.							
Alfredo Holguin									
37545					8/31/2008	9/6/2008	275		\$0.00
Medium	Work In Progress			8/31/2008 12:25:12 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
42811					2/23/2009		99		\$0.00
Medium	Work In Progress			2/23/2009 3:48:44 PM					
Lara, Ralph		NEED A DOOR CLOSER FOR NURSES STATION PORTABLE.							
Arturo Nunez									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
38544	Cafeteria (2005)	Cafeteria			9/30/2008		245		\$0.00
Medium	Work In Progress			9/30/2008 8:10:55 AM					
Moncayo, Fernando	Comments from Ecolab Report: Dishwasher is not filling up. Pre-spray hose id damaged & should be replaced. Olga Bustamante SNP MANAGER 58905332								
Jacqueline Aguilar									
38595	Gymnasium				10/1/2008		244		\$0.00
Medium	Work In Progress			10/1/2008 12:31:34 PM					
Nunez, Arturo	REPLACE STAINED AND BROKEN CIELING TILES								
Michael Munoz									
38753					10/5/2008	10/11/2008	240		\$0.00
Medium	Work In Progress			10/5/2008 12:23:53 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
38754					10/5/2008	10/13/2008	240		\$0.00
Medium	Work In Progress			10/5/2008 12:23:53 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
38755					10/5/2008	10/26/2008	240		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
Margret Villalobos									
38756					10/5/2008	11/5/2008	240		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Yearly - Santa Teresa HS H-6 Rftop Furn Yearly - Refer to PM schedule details.								
Margret Villalobos									
38757					10/5/2008	11/5/2008	240		\$0.00
Medium	Work In Progress			10/5/2008 12:23:54 AM					
Nunez, Arturo	Yearly - Santa Teresa HS R-9 Radiator Ht Wtr 2yr - Refer to PM schedule details.								
Margret Villalobos									
38758					10/5/2008	10/21/2008	240		\$0.00
Medium	Work In Progress			10/5/2008 12:23:55 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
39164					10/12/2008	10/28/2008	233		\$0.00
Medium	Work In Progress				10/12/2008 12:21:05				
Nunez, Arturo		Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.							
Margret Villalobos									
39344					10/21/2008		224		\$0.00
Medium	Work In Progress				10/21/2008 3:13:05 PM				
Villalobos, David		NEED SOME ASSISTANCE ON LEAK TEST GAS LINES ON WELDING BOTHS, THERE SEEMS TO BE A GAS LEAK, BUT CAN'T LOCATE.							
Arturo Nunez									
39396	Main Building	Choral			10/22/2008		223		\$0.00
Medium	Work In Progress				10/22/2008 3:57:04 PM				
Lara, Ralph		Door from Band Room Top Corner broken, needs to be replaced Thank you, Rosa							
Rosa Hood									
39398	Main Building	Hallway/Corridor			10/22/2008		160		\$0.00
Medium	Work In Progress				10/22/2008 3:59:35 PM	3/31/2009			
Prospero, Manuel		Remove lockers in hallway near counseling area and across from Main office Thank you, Rosa							
Rosa Hood									
39542	Main Building	Office			10/28/2008		217		\$0.00
Medium	Work In Progress				10/28/2008 1:18:25 PM				
Nunez, Arturo		We need signs to indicate what building is what since we do not have a front entrance. Please feel free to call me or Art Nunez so that we can be more specific Thank you, Rosa				1/23/09 - Art asp our conversation you would take care of it and asp Mike please submit request for signs. - Thank You Ruben			
Rosa Hood									
39695					11/2/2008	11/8/2008	212		\$0.00
Medium	Work In Progress				11/2/2008 12:24:36 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
40365					11/30/2008	12/6/2008	184		\$0.00
Medium	Work In Progress				11/30/2008 12:23:29				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
PSFA View Only									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
40873					12/15/2008		169		\$0.00
Medium	Work In Progress			12/15/2008 2:57:45 PM					
Castillo, Carlos	NEED A 115V ELEC. OUTLET INSTALLED ON CONFERENCE ROOM IN LIBRARY, FOR POWER POINT PROJECTOR.								
<u>Arturo Nunez</u>									
41042					1/4/2009	1/10/2009	149		\$0.00
Medium	Work In Progress			1/4/2009 12:18:38 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41059					1/4/2009	1/12/2009	149		\$0.00
Medium	Work In Progress			1/4/2009 12:18:45 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41154					1/5/2009		148		\$0.00
Medium	Work In Progress			1/5/2009 8:52:07 AM					
Villalobos, David	NEED SOME ASSISTANCE ON CHECKING MANHOLE BY GAS METER, ON EAST SIDE. METHANE GAS LEVEL READING IS A 8 , AS PER P.N.M. TECH. WOULD LIKE TO HAVE IT CHECKED OUT.								
<u>Arturo Nunez</u>									
41307	Dressing Rooms	Dressing Room			1/9/2009		144		\$0.00
Medium	Work In Progress			1/9/2009 8:54:39 AM					
Nunez, Arturo	Boys athletic lockers need to be bolted down for safety reasons This is the second request Someone is going to get hurt with a falling bank of lockers		Art Nunez had previously submitted a work order and has spokent to someone at the GAC/Warehouse regarding this situation 1/15 - Route to Art asp Mike						
<u>Rosa Hood</u>									
41629					1/20/2009		133		\$0.00
Medium	Work In Progress			1/20/2009 8:21:41 AM					
Ontiveros, Guadalupe	Remove equipment asp attached pictures and e-mail.								
<u>Michael Munoz</u>									
41699	Gymnasium	Hallway/Corridor			1/21/2009		132		\$0.00
Medium	Work In Progress			1/21/2009 2:21:21 PM					
Prospero, Manuel	Mr. Kelch has asked that we retile the hallway between the old and new gym. He spoke with Manuel Prospero about the tiles (they need to be the same color and pattern) Thank you, Rosa		5/4/09 - Asp Mike go ahead and replace tiles that are in need and use this wo.  Mr. Kelch has spoken wih Manny Prospero regarding tiles that need to be ordered and changed throughout the building Thank you, Rosa						
<u>Rosa Hood</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Santa Teresa HS

41751	Annex Building	Classroom			1/22/2009		131		\$0.00
Medium	Work In Progress				1/22/2009 3:19:52 PM				
Nunez, Arturo		Anchor the serving set s to the ground and need to make a safety zone unger the servings Thank you				License inspection 1-15-09 2/9 - Mailed to Art asp Mike			

Rosa Hood

41752	Annex Building	Classroom			1/22/2009		131		\$0.00
Medium	Work In Progress	DAYCARE			1/22/2009 3:21:49 PM				
Nunez, Arturo		Replace all stained ceiling tiles Thank you, Rosa				License inspection 1-15-09			

Rosa Hood

41753	Annex Building	Classroom			1/22/2009		131		\$0.00
Medium	Work In Progress				1/22/2009 3:23:59 PM				
Estrada, Jesus		Linolium in both bathrms need to be replaced and floor tiles at each exit need to be replace and any around the day care center Thank you, Rosa				License inspection 1-15-09. 6/1/09 - ON HOLD AS PER CHUY			

Rosa Hood

41929	Annex Building	Classroom			1/28/2009		125		\$0.00
Medium	Work In Progress	MR.			1/28/2009 9:21:25 AM				
Nunez, Arturo		NEED TO INSTALL PROJECTION TV-DIGITAL RECORDING SYSTEM-PROJECTION SCREEN-AND TIE IN HD DVD-MULTI CHANNEL AV RECEIVER-STEREO CASSETTE DECK-BBE PROCESSOR. PLEASE VISIT WITH MR. RIVERA ON THESE INSTALLATIONS.							

Jimenez, Marylou

42057					2/1/2009	2/7/2009	121		\$0.00
Medium	Work In Progress				2/1/2009 12:24:28 AM				
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							

Margret Villalobos

42485	Cafeteria (2005)				2/11/2009		111		\$0.00
Medium	Work In Progress				2/11/2009 2:17:51 PM				
Villalobos, David		need to send Horizon Mechanical to repair backlow preventer for irrigation, located next to cafetorium,							

David Villalobos

42595	Main Building	Classroom			2/17/2009		105		\$0.00
Medium	Work In Progress				2/17/2009 8:08:27 AM				
Nunez, Arturo		Room 200 has a leak The ceiling tile has already caved in Thanks, Rosa				Art and Prospero have been made aware according to teacher Ms. Rios on Friday Thanks, Rosa			

Rosa Hood

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

42793	Main Building	Classroom			2/23/2009		99		\$0.00
Medium	Work In Progress				2/23/2009 11:33:13 AM				

Nunez, Arturo  
Mr. Portillo's room needs door stops for bathroom and air freshner dispensers need to be mounted  
Thank you,  
Rosa

Rosa Hood

42794	Main Building	Restroom (Girls)			2/23/2009		99		\$0.00
Medium	Work In Progress				2/23/2009 11:35:20 AM				

Nunez, Arturo  
Air freshners need to be mounted in the women restroom in the main office  
Next to Receptionist Ana Perez  
Thank you,  
Rosa

Rosa Hood

42795	Main Building	Restroom (Girls)			2/23/2009		99		\$0.00
Medium	Work In Progress				2/23/2009 11:36:51 AM				

Prospero, Manuel  
All boys and girls restrooms need to be painted. They are now black and we need the natural color (white, beige, whatever you have in stock)  
Thank you,  
Rosa  
This is a summer project.

Rosa Hood

42796	Main Building	Hallway/Corridor			2/23/2009		99		\$0.00
Medium	Work In Progress				2/23/2009 11:38:36 AM				

Nunez, Arturo  
All entry ways, door frames, window frames need to be painted black per Mr. Kelch our principal  
Mr. Munoz, Art Nunez, and Manuel Prospero are aware  
Thank you,  
Rosa

Rosa Hood

42839	Main Building	Classroom			2/24/2009		98		\$0.00
Medium	Work In Progress				2/24/2009 1:42:45 PM				

Nunez, Arturo  
ceiling tiles need to be replace in room 200 Ms. Rios  
Thanks,  
Rosa

Rosa Hood

42841	Main Building	Classroom			2/24/2009		98		\$0.00
Medium	Work In Progress				2/24/2009 1:47:07 PM				

Nunez, Arturo  
Ms McConnell a few tiles need to be replaced  
Thanks,  
Rosa

Rosa Hood

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
42843	Main Building	Office			2/24/2009		98		\$0.00
Medium	Work In Progress				2/24/2009 1:52:40 PM				
Nunez, Arturo	Leak in counseling office and rusted vents need to be replaced								
	Thank you, Rosa								
Rosa Hood									
42844	Main Building	Office			2/24/2009		98		\$0.00
Medium	Work In Progress				2/24/2009 1:53:40 PM				
Nunez, Arturo	Counseling offices and lobby area need to be painted								
	Thank you, Rosa								
Rosa Hood									
42845	Main Building	Office			2/24/2009		98		\$0.00
Medium	Work In Progress				2/24/2009 1:54:50 PM				
Castillo, Carlos	Counseling offices need more outlets								
	Thank you, Rosa								
Rosa Hood									
42846	Main Building	Office			2/24/2009		98	1	\$25.00
Medium	Work In Progress				2/24/2009 1:56:20 PM				
Estrada, Jesus	Counseling Center needs carpet replaced in lobby and in offices. (dirty and safety issue)					2/26/08 NO TEAR OR STAIN, ON HOLD AS PER CHUY			
	Thanks, Rosa								
Rosa Hood									
42874	Applied Science	Classroom			2/24/2009		98		\$0.00
Medium	Work In Progress				2/24/2009 6:02:00 PM				
Nunez, Arturo	L 1 needs some ceiling tiles replaced								
	Thank you, Rosa								
Rosa Hood									
42875	Applied Science	Classroom			2/24/2009		98		\$0.00
Medium	Work In Progress				2/24/2009 6:03:23 PM				
Nunez, Arturo	L1 needs screens on windows replaced								
	Ms McKnight Thanks, Rosa								
Rosa Hood									
42900		Classroom			2/25/2009		97		\$0.00
Medium	Work In Progress	MR. RAY/ROOM			2/25/2009 9:12:29 AM				
Nunez, Arturo	PLEASE REPLACE TV IN MY ROOM. MARYLOU HAS TV'S AVAILABLE.								
Marylou Jimenez									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location: Santa Teresa HS**

42902	Applied Science	Classroom			2/25/2009		97	\$0.00	
Medium	Work In Progress			2/25/2009 9:27:31 AM					
Nunez, Arturo	Room 14 molding around desk needs to be glued								
Rosa Hood									
42903	Main Building	Classroom			2/25/2009		97	\$0.00	
Medium	Work In Progress			2/25/2009 9:39:24 AM					
Nunez, Arturo	Room 308 screens for windows								
Rosa Hood									
42905	Main Building	Classroom			2/25/2009		97	\$0.00	
Medium	Work In Progress			2/25/2009 9:42:00 AM					
Nunez, Arturo	Room 308 needs to be painted during Spring Break or Summer schedule								
Rosa Hood									
42906	Main Building	Restroom (Girls)			2/25/2009		97	\$0.00	
Medium	Work In Progress			2/25/2009 9:57:52 AM					
Nunez, Arturo	Handcap bathroom in 300 hall needs to be tightend								
Rosa Hood									
42916					2/25/2009		97	\$0.00	
Medium	Work In Progress			2/25/2009 11:26:08 AM					
Murillo, Luis	Shampoo and extract carpet in lobby and offices in counseling center. To be done in week of March 23-27. (Assign to L. Murillo)				4/20/09- REQUESTED STATUS FROM LUIS.				
					5/28/09 - REFAXED TO LUIS				
Jesus Estrada									
42922					2/25/2009		97	\$0.00	
Medium	Work In Progress			2/25/2009 11:30:45 AM					
Carrasco, Danny	Danny need to conduct inventory of all Building Mechanic tools and equipment. Ask Ruben for present inventory list to match up.								
Michael Munoz									
42984	Main Building	Classroom			2/26/2009		96	\$0.00	
Medium	Work In Progress			2/26/2009 2:25:07 PM					
Lara, Ralph	213 needs locks replaced on cabinets to secure materials								
Rosa Hood									
43023	Main Building	Classroom			2/27/2009		95	\$0.00	
Medium	Work In Progress			2/27/2009 9:11:22 AM					
Nunez, Arturo	I really do not know who this goes to... we are donating four Art racks to different schools we need them moved to those shcools Desert View E (2) and STMS (2) Thank you, Rosa								
Rosa Hood									

6/2/2009 9:39:33 AM

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
43037	Main Building	Restroom (Girls)			2/27/2009		95		\$0.00
Medium	Work In Progress			2/27/2009 12:59:16 PM					
Lara, Ralph	Office bathrooms men and women Hallway mens need to be keyed so that only faculty can use Hallway womens is already keyed Thank you, Rosa								
Rosa Hood									
43038	Main Building	Hallway/Corridor			2/27/2009		95		\$0.00
Medium	Work In Progress			2/27/2009 1:01:01 PM					
Ronquillo, Ruben	Fire ex glass is broken New hallway near bookroom								
Rosa Hood									
43040	Main Building	Classroom			2/27/2009		32		\$0.00
Medium	Work In Progress			2/27/2009 2:14:19 PM	3/31/2009				
Prospero, Manuel	Tiles need to be repalced room 200 Thank you, Rosa								
Rosa Hood									
43090					3/1/2009	3/7/2009	93		\$0.00
Medium	Work In Progress			3/1/2009 12:22:51 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
43128					3/1/2009	3/22/2009	93		\$0.00
Medium	Work In Progress			3/1/2009 12:23:04 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
43252	Main Building	Hallway/Corridor			3/3/2009		91		\$0.00
Medium	Work In Progress			3/3/2009 8:07:26 AM					
Lara, Ralph	Mr. Kelch would like the rooms re-numbered for next school year (summer project) Thank you, Rosa								
Rosa Hood									
43287	Main Building	Classroom			3/4/2009		90		\$0.00
Medium	Work In Progress			3/4/2009 8:11:16 AM					
Castillo, Carlos	The kiln in the Art room is not working again...may be a problem with electrical outlet or breaker Thank you, Rosa								
Rosa Hood									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
43289	Main Building	Classroom			3/4/2009		90		\$0.00
Medium	Work In Progress				3/4/2009 8:14:25 AM				
Nunez, Arturo		Two roof leaks need to be fixed 6 ceiling tiles need to be replaced							
Rosa Hood									
43303		Athletic Field			3/4/2009		90		\$0.00
Medium	Work In Progress				3/4/2009 10:45:39 AM				
Ontiveros, Guadalupe		Mr. Dodson needs the batting cage returned ....He spoke with Mr. Valdez ...it was picked up for repairs and it has not been returned Thank you, Rosa							
Rosa Hood									
43455	Main Building	Office			3/7/2009		87		\$0.00
Medium	Work In Progress				3/7/2009 2:05:14 PM				
Nunez, Arturo		Replace two stained ceiling tiles and paint air conditioner covers/grates...they are rusty Thank you, Administration							
Rosa Hood									
43513	Annex Building	Restroom (Girls)			3/9/2009		85		\$0.00
Medium	Work In Progress				3/9/2009 3:38:59 PM				
Lara, Ralph		DEAD BOLT FROM GIRLS BATHROOM DOOR IS BROKEN / WILL NOT LOCK NEEDS TO BE REPLACE THANK YOU.							
Luis Murillo									
43604	Vocational	Classroom			3/11/2009		83		\$0.00
Medium	Work In Progress				3/11/2009 2:15:40 PM				
Castillo, Carlos		The old band room ... needs electrical checked out for new kilns and art studio Mr. Joseph Angelo Ms Turner or Mr. Lowrance Thank you, Rosa							
Rosa Hood									
43605	Vocational	Classroom			3/11/2009		83		\$0.00
Medium	Work In Progress				3/11/2009 2:17:04 PM				
Villalobos, David		Need sink from Art room removed and placed in new art studio (old band room) Mr. Angelo, Ms Turner , Mr Lowrance							
Rosa Hood									
43720					3/15/2009		79		\$0.00
Medium	Work In Progress				3/15/2009 12:19:49 AM				
Ontiveros, Guadalupe		Monthly - Santa Teresa HS Soil Sampling - Refer to PM schedule details.							
Margret Villalobos									

6/2/2009 9:39:33 AM

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
43728	Applied Science	Hallway/Corridor			3/16/2009		78		\$0.00
Medium	Work In Progress				3/16/2009 8:41:48 AM				
Nunez, Arturo	Summer Project - removal of remaining locker banks Thanks, Rosa								
<u>Rosa Hood</u>									
43748					3/16/2009		78		\$0.00
Medium	Work In Progress				3/16/2009 3:22:36 PM				
Castillo, Carlos	SHUT OFF POWER FOR DEMO IN OLD VOCATIONAL BUILDING ( HOME ECONOMICS ROOM). PLEASE CONTACT MIKE MUNOZ OR ROSA HOOD IF ANY QUESTIONS.								
<u>Michael Munoz</u>									
43749					3/16/2009		78		\$0.00
Medium	Work In Progress				3/16/2009 3:25:14 PM				
Villalobos, David	SHUT OFF GAS AND WATER FOR DEMO IN OLD VOCATIONAL BUILDING ( HOME ECONOMICS ROOM). PLEASE CONTACT MIKE MUNOZ OR ROSA HOOD IF ANY QUESTIONS.								
<u>Michael Munoz</u>									
43779	Main Building	Custodial			3/17/2009		77		\$0.00
Medium	Work In Progress				3/17/2009 8:28:56 AM				
Nunez, Arturo	Move washer and dryer from old home economics room to custodial room (remove broken washer and dryer and replace with the ones in the home ec room) Thank you, Rosa								
<u>Rosa Hood</u>									
46081					5/28/2009		5		\$0.00
Medium	Work In Progress	CHILLER			5/28/2009 3:34:43 PM				
Ambriz, Jose	Need to check chiller it's showing Diagnostic Severe Safe Unbalance.								
<u>Jose Ambriz</u>									
43835	Vocational	Classroom			3/18/2009		76		\$0.00
Medium	Work In Progress				3/18/2009 11:28:57 AM				
Lara, Ralph	Work order 43730 to go along with this we need 7 doorsets replaced per Rafa and Mr. Buckley for the Voc Ed building Thank you, Rosa								
<u>Rosa Hood</u>									
44091					3/31/2009		63		\$0.00
Medium	Work In Progress				3/31/2009 12:22:49 AM				
Prospero, Manuel	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
44295					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:33 AM					
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
44296					4/5/2009	4/11/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:35 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
44297					4/5/2009	4/13/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:36 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
44298					4/5/2009	4/21/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:36 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
44408					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:23:13 AM					
Prospero, Manuel	Monthly - Santa Teresa HS C-12 Chm Feeder Semimly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
44446	Gymnasium	Gym			4/6/2009		57		\$0.00
Medium	Work In Progress			4/6/2009 10:24:59 AM					
Castillo, Carlos	MR. CARLOS CASTILLO LIGHT SWITCH NEEDS TO BE REPLACE / LIGHTS WILL NOT TURN OFF BY DRESSING ROOM THANK YOU.								
<u>Luis Murillo</u>									
44482	Main Building	Hallway/Corridor			4/6/2009		57		\$0.00
Medium	Work In Progress			4/6/2009 3:54:50 PM					
Lara, Ralph	The door in the couseling hallway is coming unhinged...dangerous. It is the left door as you go out								
	Thank you								
<u>Rosa Hood</u>									
44483	Main Building	Hallway/Corridor			4/6/2009		57		\$0.00
Medium	Work In Progress			4/6/2009 3:56:18 PM					
Nunez, Arturo	Mr. Kelch would like the main lobby repainted. Art Nunez knows what Mr. Kelch needs done. This is a project that we need done this summer								
	Thank you								
<u>Rosa Hood</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
44541	Main Building	Classroom			4/8/2009		55		\$0.00
Medium	Work In Progress			4/8/2009 10:27:44 AM					
Prospero, Manuel		New classrom 200 has a roof leak Thank you							
<u>Rosa Hood</u>									
44542	Main Building	Classroom			4/8/2009		55		\$0.00
Medium	Work In Progress			4/8/2009 10:30:22 AM					
Lara, Ralph		The door needs a new lock the entire tumbler is missing Room 613 Kitchen for nutrition class Security issue Thank you							
<u>Rosa Hood</u>									
44647					4/12/2009	4/28/2009	51		\$0.00
Medium	Work In Progress			4/12/2009 12:21:27 AM					
Nunez, Arturo		Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
44801	Vocational	Classroom			4/17/2009		46		\$0.00
Medium	Work In Progress			4/17/2009 3:24:40 PM					
Villalobos, David		Need to have the natural gas line attached to the heat treatment furnance and test operation per Mr Angleo in the welding area Thank you							
<u>Rosa Hood</u>									
44803					4/17/2009		46		\$0.00
Medium	Work In Progress			4/17/2009 3:46:41 PM					
Ambriz, Jose		NEED SOME ASSISTANCE ON LIBRARY A.H.U. WATER VALVE FOR COOLING MODE IS NOT WORKING PROPERLY, UNIT GOES FROM ONE EXTREME TO AN OTHER,. UNIT HAS TO BE CONTROLLED MANUALLY.							
<u>Arturo Nunez</u>									
44922	Vocational	Classroom			4/22/2009		41		\$0.00
Medium	Work In Progress			4/22/2009 12:39:10 PM					
Nunez, Arturo		We need the fence fabric stretched and attached to the post at the fenced storage area at the voc building Nunez/Angelo Thanks, Rosa							
<u>Rosa Hood</u>									
44925	Annex Building	Classroom			4/22/2009		41		\$0.00
Medium	Work In Progress			4/22/2009 1:10:12 PM					
Nunez, Arturo		Rosie Gonzalez ask that the air conditioners be turned on in the daycare center Thank you							
<u>Rosa Hood</u>									

6/2/2009 9:39:33 AM

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
46098					5/29/2009		4		\$0.00
High	Work In Progress			5/29/2009 10:40:34 AM					
Castillo, Carlos	please ckeck for proper balance and voltage to chiller.								
Michael Munoz									
44939					4/22/2009		41		\$0.00
Medium	Work In Progress			4/22/2009 3:47:58 PM					
Ambriz, Jose	4/22/09. WE NEED TO CHENGE CONDANCER FAN MOTOR ON ROOM 10. THA INFORMATION IS: MOD.5KCP39HG K896AS. HP. 1/5 RPM 840 V. 208-230 HZ 60 AMPS1.20 ROT 1 PH. CAP500/370 EQUIP.MFRS.#37VL233B. THIS QORK ORDER IS FOR JOSE AMBIZ.								
Manuel Prospero									
45039	Dressing Rooms	Dressing Room			4/27/2009		36		\$0.00
Medium	Work In Progress			4/27/2009 12:53:09 PM					
Castillo, Carlos	The light switch in the boys PE dressing room will not turn off/it has been like this for a month. Mr. Meraz and Mr. Munoz have tried to shut it off however it will not go off Thanks								
Rosa Hood									
45101		Classroom			4/28/2009		35		\$0.00
Medium	Work In Progress	Science and Lang		4/28/2009 1:26:21 PM					
Nunez, Arturo	Please set up furniture that was delivered on 4/16 for computers in the Science and Language Arts classrooms. Thank you.								
Sandra Almeraz									
45134		Classroom			4/29/2009		34		\$0.00
Medium	Work In Progress			4/29/2009 7:56:28 AM					
Ambriz, Jose	THE A/C ON ROOM 7 IS ON BAD CONDITION,WE NEED TO CHANGED FOR 6800AEROCOOL 8"PMT D/D								
Manuel Prospero									
45145					4/29/2009		34		\$0.00
Medium	Work In Progress			4/29/2009 11:35:36 AM					
Murillo, Luis	LUIS, PLEASE CHANGE THE STANDARD TOILET PAPAER DISPENSERS IN THE NEW GYM ADDITION TO JUMBO. ORDER THRU INVENTORY DIRECT IF NEEDED. THANKS								
Jesus Estrada	5-28-09 - REFAXED TO LUIS								

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
45183	Gymnasium	Gym			4/29/2009		34		\$0.00
Medium	Work In Progress			4/29/2009 7:59:48 PM					
Nunez, Arturo	Mr. Munoz our trainer needs the ice machine and the whirlpool from the old training room moved to the new training room								
	Thank you								
Rosa Hood									
45187					4/30/2009	5/31/2009	33		\$0.00
Medium	Work In Progress			4/30/2009 12:21:32 AM					
Nunez, Arturo	Yearly - Santa Teresa HS C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									
45263					5/3/2009	5/9/2009	30		\$0.00
Medium	Work In Progress			5/3/2009 12:22:28 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
45346	Main Building	Hallway/Corridor			5/4/2009		29		\$0.00
Medium	Work In Progress			5/4/2009 12:08:02 PM					
Prospero, Manuel	Removal of locker bank in Science Wing this summer								
	Thank you, Rosa								
Rosa Hood									
45347	Main Building	Hallway/Corridor			5/4/2009		29		\$0.00
Medium	Work In Progress			5/4/2009 12:09:08 PM					
Nunez, Arturo	Painting of all hallways, doors, frames, etc during the summer								
Rosa Hood									
45348	Main Building	Hallway/Corridor			5/4/2009		29		\$0.00
Medium	Work In Progress			5/4/2009 12:10:26 PM					
Prospero, Manuel	Paint over mural on wall per Mr. Kelch								
	Mr. Munoz asked that I submit a work order for each job								
Rosa Hood									
45349	Main Building	Hallway/Corridor			5/4/2009		29		\$0.00
Medium	Work In Progress			5/4/2009 12:11:54 PM					
Nunez, Arturo	Repaint lobby area per Mr. Kelch (Art is aware of how it needs to be painted...stripes)								
Rosa Hood									
45350	Main Building	Office			5/4/2009		29		\$0.00
Medium	Work In Progress			5/4/2009 12:13:48 PM					
Munoz, Michael	Mr. Kelch wants part of a non load bearing wall to be taken down in the attendance office...see Mr. Kelch or Mrs. Hood for particulars								
	Thanks								
Rosa Hood									
6/2/2009 9:39:34 AM									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
45351	Main Building	Classroom			5/4/2009		29		\$0.00
Medium	Work In Progress			5/4/2009 12:16:55 PM					
Nunez, Arturo		Paint all classrooms							
Rosa Hood									
45352	Main Building	Classroom			5/4/2009		29		\$0.00
Medium	Work In Progress			5/4/2009 12:18:31 PM					
Nunez, Arturo		Replacement of ceiling tiles that still have not been replaced (broken, steined) Mr. Munoz asked I submit all projects that still need attention Thanks							
Rosa Hood									
45486	Main Building	Restroom (Boys)			5/7/2009		26		\$0.00
Medium	Work In Progress			5/7/2009 8:26:50 AM					
Prospero, Manuel		replace the standard toilet paper dispensers with the jumbo dispenser per Mr. Murillo Thanks							
Rosa Hood									
45533	Cafeteria (2005)	Cafeteria			5/8/2009		25		\$0.00
Medium	Work In Progress			5/8/2009 11:15:52 AM					
Lara, Ralph		The handicap access control is not operating properly per Ms. Rios special ed dept chair Thank you							
Rosa Hood									
45534	Library	Library			5/8/2009		25		\$0.00
Medium	Work In Progress			5/8/2009 11:17:20 AM					
Ronquillo, Ruben		The conference room in the library needs blinds to comply with privacy act for Special Education IEP meetings Thank you							
Rosa Hood									
45537					5/8/2009		25		\$0.00
Medium	Work In Progress			5/8/2009 1:36:35 PM					
Carrasco, Danny		please deliver genererator to guard shack 1st thing monday morning.generator to be picked up when school ends. thankyou							
Michael Munoz									
45719	Library	Library			5/14/2009		19		\$0.00
Medium	Work In Progress			5/14/2009 11:35:19 AM					
Nunez, Arturo		Work order #45534 per Mr. Ronquillo needs to be routed thru building mechanics for size, color and quantity and locaiton for Mr. Holguin to review Blinds in the library conference room for Specail Ed IEP (privacy act)							
Rosa Hood									

6/2/2009 9:39:34 AM

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
45720	Main Building	Office			5/14/2009		19		\$0.00
Medium	Work In Progress			5/14/2009 11:39:48 AM					
Lara, Ralph	TRIO office needs lock replaced it is not working per Ms Valdez								
Rosa Hood									
45722					5/14/2009		19		\$0.00
Medium	Work In Progress			5/14/2009 12:00:23 PM					
Gonzales, Angel	NEED TO HAVE DRIVER WINDOW ON VECHILE #69 REPLACED, VANDALIZED .								
Arturo Nunez									
45735	Library	Library			5/14/2009		19		\$0.00
Medium	Work In Progress			5/14/2009 3:27:58 PM					
Lara, Ralph	Library one of the front doors will not lock (security books) Please check Emma's key not able to open the door Thanks, Rosa								
Rosa Hood									
45786		Classroom			5/18/2009		15		\$0.00
Medium	Work In Progress			5/18/2009 12:22:27 PM					
Ronquillo, Ruben	WE NEED TO REPLACE BROKEN WINDOW ON ROOM 5.								
Manuel Prospero									
45790	Gymnasium	Gym			5/18/2009		15		\$0.00
Medium	Work In Progress			5/18/2009 1:24:23 PM					
Villalobos, David	Mr. Munoz has two whirlpools that need to be hooked up to the drain and relocated to new athletic training room Thanks								
Rosa Hood									
45799					5/18/2009		15		\$0.00
Medium	Work In Progress			5/18/2009 3:24:41 PM					
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 5 IS ON VERY BAD CONDITION.								
Manuel Prospero									
45801					5/18/2009		15		\$0.00
Medium	Work In Progress			5/18/2009 3:30:57 PM					
Ronquillo, Ruben	NEED GLASS ON DOOR ON DRESSING ROOM HALLWAY REPLACED , BROKEN. THE MEASUREMENTS ARE 25 1/4 BY 36 1/4 BY 1/4 WIRE MESH GLASS.								
Arturo Nunez									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa HS</b>									
45803					5/18/2009		15		\$0.00
Medium	Work In Progress			5/18/2009 3:33:50 PM					
Ontiveros, Guadalupe	NEED TO BORROW TWO TRAILERS TO TRANSPORT LOCKER THAT WILL BE REMOVED ON HALLWAYS, CAN WE PLEASE HAVE THEM ON SITE ON THURSDAY, SO THAT WE CAN START REMOVING LOCKERS, AND TRANSPORT TO P.P.D. THANK YOU.								
Arturo Nunez									
45833					5/19/2009		14		\$0.00
Medium	Work In Progress			5/19/2009 12:14:41 PM					
Ambriz, Jose	NEED TWO (2) 3 PHASE MONITORS MODEL # A258B , TIME MARK CO. 380,480 VAC. CONTACTS 10A - 240 VAC. FOR VOCATIONAL BUILDING A.C. ONE TO INSTALL, AND ONE FOR SPARE. THANK YOU.								
Arturo Nunez									
45884					5/20/2009		13		\$0.00
Medium	Work In Progress			5/20/2009 3:39:51 PM					
Ambriz, Jose	5/20/09. WE NEED TO CHANGED A/C MOTOR ON GYM ARE. INFORMATION. EVD182TTDB4026BR H FRAME 182T TDR DES B PH 3 HP 3 VOLTS 208-230-460. SF 1.15 RPM 1760 CODE J NOM P.F. 77.5								
Manuel Prospero									
45965	Applied Science	Classroom			5/22/2009		11		\$0.00
Medium	Work In Progress			5/22/2009 2:16:15 PM					
Ronquillo, Ruben	replace glass window with reinforced glass for safety and prevention of theft in room 22 Science wing Luis Villobos room was broken into and computer stolen Thanks								
Rosa Hood									
45967	Annex Building	Classroom			5/22/2009		11		\$0.00
Medium	Work In Progress			5/22/2009 2:17:52 PM					
Prospero, Manuel	Replace ceiling tiles Replace floor tiles Roof is still leaking ...Have submitted previous work order								
Rosa Hood									
45988	Main Building	Classroom			5/26/2009		7		\$0.00
Medium	Work In Progress			5/26/2009 10:03:08 AM					
Nunez, Arturo	window will not close gap lets rain and dust in Mr. Tony Ray room 311								
Rosa Hood									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
46066					5/11/2009		22		\$0.00
Medium	Work In Progress			5/28/2009 10:00:59 AM					
Lara, Ralph	Southside storage rm broke rollup door and hinge lock. Also strip of fence line at yards work site and broke 2 sacks of lime used to line up field.								
<u>Pedro Valdez</u>									
46119					5/31/2009	6/16/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:09 AM					
Villalobos, Margret	Yearly - Santa Teresa HS June Chiller Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46130					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:14 AM					
Nunez, Arturo	Yearly - Santa Teresa HS A-2 H/C Units Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46131					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:14 AM					
Nunez, Arturo	Yearly - Santa Teresa HS B-2 Boiler Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46132					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:15 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46146					5/31/2009	6/21/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:20 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46214					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:45 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
46215					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:46 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
46216					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:46 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
46265		Athletic Field			6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 8:12:07 AM					
Valdez, Pedro		need help to aerate and fertilize football-soccer and softball,baseball fields.							
Guadalupe Ontiveros									
46341					6/2/2009		0		\$0.00
Medium	Work In Progress	CHILLER		6/2/2009 6:35:54 AM					
Ambriz, Jose		Need to check chiller there is a short on condensor wiring.							
Jose Ambriz									
<b>Count: 139 Work Orders</b>		<b>Avg. Age of WO's 93</b>		<b>Total for Santa Teresa HS</b>			<b>1</b>	<b>\$25.00</b>	

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa MS</b>									
36170	North Building	Custodial			7/24/2008		313		\$0.00
Medium	Work In Progress				7/24/2008 7:42:22 AM				
Gonzales, Angel	pete,the truck 39 needs a complete tune up i need to have it ready for the school year.thank you.								
Ismael Rodriguez									
36903	North Building	Classroom			8/11/2008		295		\$0.00
Medium	Work In Progress	Room 3A			8/11/2008 3:12:40 PM				
Mijarez, Jaime	1. Portable leaks when it rains.								
Laura Parra									
37603					8/31/2008	9/6/2008	275		\$0.00
Medium	Work In Progress				8/31/2008 12:25:31 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
38535					9/30/2008		245		\$0.00
Medium	Work In Progress				9/30/2008 12:26:01 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS A16 (Fan Exh.)(Monthly) - Refer to PM schedule details.								
Margret Villalobos									
38596					10/1/2008		244		\$0.00
Medium	Work In Progress				10/1/2008 12:33:20 PM				
Soria, Mike	CUT WEEDS AT NEW LANDSCAPING IN FRONT OF SOUTH BUILDING.								
Michael Munoz									
38597					10/1/2008		244		\$0.00
Medium	Work In Progress				10/1/2008 12:34:21 PM				
Soria, Mike	OPEN DRAIN BY MORGAN BUILDING. CUT WEEDS AND BARRICADE. SAFETY HAZARD.								
Michael Munoz									
38869					10/5/2008	11/5/2008	240		\$0.00
Medium	Work In Progress				10/5/2008 12:24:36 AM				
Mijarez, Jaime	Yearly - Santa Teresa MS U2 (Heat Gas)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
39406					10/23/2008		222		\$0.00
Medium	Work In Progress				10/23/2008 7:58:22 AM				
Castillo, Carlos	See if we can repair the timers and order additional triggers. (see Jaime if you have any questions).								
Michael Munoz									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa MS</b>									
40169					11/18/2008		196		\$1,400.00
Medium	Work In Progress			11/18/2008 9:33:58 AM					
Ronquillo, Ruben	N.bldg office exterior windows. Replace 2nd glass window with new aluminum molding. Existing molding is to corroded. Replace aluminum molding around glass window that was replaced for W/O #39295. I checked molding around window and it is too damaged.								
<u>Jaime Mijarez</u>									
40475	South Building	Choral			12/2/2008		182		\$0.00
Medium	Work In Progress	Outside Choir		12/2/2008 8:05:57 AM					
Gonzalez, Salvador	Replace the old worn out gate behind the south building and relocate by the corner of the south building with a new one. (A safety measure)								
<u>Laura Parra</u>									
40476	North Building	Portables			12/2/2008		182		\$0.00
Medium	Work In Progress	Outside by		12/2/2008 8:09:53 AM					
Gonzalez, Salvador	North building by the portable-- Place a gate by the portables so we could keep people from driving their cars around the north building to get to the gym. ( A SAFETY MEASURE)								
<u>Laura Parra</u>									
41024					12/31/2008		153		\$0.00
Medium	Work In Progress			12/31/2008 12:18:22					
Mijarez, Jaime	Yearly - Santa Teresa MS H6(Roof Furnace)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
41216	South Building				1/6/2009		147		\$0.00
Medium	Work In Progress			1/6/2009 4:25:30 PM					
Soria, Mike	please cut weeds in culvert by ground morgan bldg.								
<u>Michael Munoz</u>									
41632	North Building	Custodial			1/20/2009		133		\$0.00
Medium	Work In Progress			1/20/2009 8:39:52 AM					
Gonzales, Angel	pete, the truck 39 needs the the oil change i will be taking it in during this week thank you.								
<u>Ismael Rodriguez</u>									
42477					2/11/2009		111		\$0.00
Medium	Work In Progress	Grounds Truck		2/11/2009 9:23:05 AM					
Gonzales, Angel	Need to repair door to truck #17 Mike Soria.								
<u>Mike Soria</u>									
42478	South Building	Mechanical Room			2/11/2009		111		\$0.00
Medium	Work In Progress			2/11/2009 9:25:27 AM					
Ontiveros, Guadalupe	Need to repair irrigation valve in Mechanical Room.				2/17/09 -	Grounds works w/irrigation they need to repair their valves. D. Villalobos			
Mike Soria									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa MS</b>									
42923					2/25/2009		97		\$0.00
Medium	Work In Progress			2/25/2009 11:32:07 AM					
Carrasco, Danny	Danny need to conduct inventory of all Building Mechanic tools and equipment. Ask Ruben for present inventory list to match up.								
<u>Michael Munoz</u>									
43020	Gym (1997)	Athletic Field			2/27/2009		0		\$0.00
High	Work In Progress			2/27/2009 8:40:07 AM	2/27/2009				
Soria, Mike	Replace sprinklers that are not working at playing fields.								
<u>Guadalupe Ontiveros</u>									
43035					2/27/2009		95		\$0.00
Medium	Work In Progress			2/27/2009 12:41:47 PM					
Estrada, Jesus	North bldg Requested by Philip Dorantes. Special Ed room needs new carpeting due to the constant wear and tear of daily activity, and also due to the foul odor of the constant urination of the students with severe disabilities. The odor has been very noticeable to visiting teachers and administration visits for observation. (5/2/08 Asp Jaime still pending)				2/29/09 - ROUTE TO CHUY ASP MIKE				
<u>Jaime Mijarez</u>									
43167					3/1/2009		93		\$0.00
Medium	Work In Progress			3/1/2009 12:23:18 AM					
Mijarez, Jaime	Yearly - Santa Teresa MS A10 (Heat Pump)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
43254		Gym			3/3/2009		91		\$0.00
Medium	Work In Progress			3/3/2009 8:26:41 AM					
Soria, Mike	Replace broken hot box to protect reduce pressure assembly.								
<u>Guadalupe Ontiveros</u>									
43259	North Building	Mechanical Room			3/3/2009		91		\$0.00
Medium	Work In Progress			3/3/2009 11:19:45 AM					
Villalobos, David	NEED TO REPLACE PRESSURE REDUCING VALVE AT NORTH BUILDING MECHANICAL ROOM				Summer Project				
<u>David Villalobos</u>									
43647	South Building	Classroom			3/12/2009		82		\$0.00
Medium	Work In Progress	ROOM 34		3/12/2009 10:32:20 AM					
Lara, Ralph	KEY IS STUCK IN KEY HOLE. CYLINDER NEEDS TO BE REPLACED.								
<u>Laura Parra</u>									
44207	North Building	Portables			4/2/2009		61		\$0.00
Medium	Work In Progress			4/2/2009 7:28:55 AM					
Soria, Mike	fix the fence door to the exit parking lot and remove sand from portables.mr. soria and mr.rodriguez completed this work order.								
<u>Ismael Rodriguez</u>									
6/2/2009 9:39:34 AM									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
44693					4/15/2009		48		\$0.00
Medium	Work In Progress			4/15/2009 7:48:38 AM					
Castillo, Carlos	S.bldg lobby. Need to install a GFI recepticle with a safety cover. Power from the exiting recepticle is being used for social workers office in lobby. I will be setting up a spiral water fountain and will be connected to the GFI.								
Jaime Mijarez									
44746		Cafeteria			4/16/2009		47		\$0.00
Medium	Work In Progress			4/16/2009 1:30:37 PM					
Moncayo, Fernando	Mop room moulding is very bad and water is leaking through the wall from the bathroom.		Regenerated from Work Order 21548						
	Paula Sanchez - SNP Manager - 589-9836								
Alma Terrell									
44747		Cafeteria			4/16/2009		47		\$0.00
Medium	Work In Progress			4/16/2009 1:33:14 PM					
Moncayo, Fernando	Dry storage door hinges are loose, wood is broken to door frame, the existing screws will not stay screwed into the door frame.		Regerated from work order 22340						
	PAULA SANCHEZ - SNP MANAGER 589-9836								
Alma Terrell									
44748		Cafeteria			4/16/2009		47		\$0.00
Medium	Work In Progress			4/16/2009 1:34:33 PM					
Moncayo, Fernando	WEATHER STRIPS TO THE BACK DOOR TO THE CAFETERIA NEEDS TO BE REPLACED, ALOT OF DIRT COMES IN THROUGH THESE DOORS.		Regenerated from work order 22343						
	PAULA SANCHEZ - SNP MANAGER 589-9836								
Alma Terrell									
44891		Athletic Field			4/21/2009		42		\$0.00
Medium	Work In Progress			4/21/2009 3:56:56 PM					
Aldaz, Bobby	Battery for Gator has to be replaced not holding charge.								
Guadalupe Ontiveros									
45106		Classroom			4/28/2009		35		\$0.00
Medium	Work In Progress	Science and		4/28/2009 2:03:29 PM					
Mijarez, Jaime	Please set up furniture for computers, furniture will be delivered on May 8. Set up in the Science and Language Arts classrooms.								
	Thank you!								
Sandra Almeraz									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
45240	North Building				5/1/2009		32		\$0.00
Medium	Work In Progress				5/1/2009 9:33:53 AM				
Ambriz, Jose	N.bldg upper level mechanical room. We need a vent duct with register like the one you installed in the lower level mechanical room on the heat pump.								
<u>Jaime Mijarez</u>									
45342	North Building	Parking Lot			5/4/2009		29		\$0.00
Medium	Work In Progress				5/4/2009 7:41:55 AM				
Soria, Mike	mr.soria we need for you to have ready the parking lot behind the cafeteria swept and clean for the teacher luncheon on may 8 09 custodians will assit on this work order.								
<u>Ismael Rodriguez</u>									
45421	Gym (1997)				5/5/2009		28		\$0.00
Medium	Work In Progress				5/5/2009 2:27:03 PM				
Lara, Ralph	Need new door in gym.								
<u>Danny Miranda</u>									
45457					5/6/2009		27		\$0.00
Medium	Work In Progress				5/6/2009 8:13:56 AM				
Ronquillo, Ruben	All buildings. Need 20 ea. boxes of flourescent light bulbs to replace bulbs in the summer. Attn: Ruben Ronguillo								
<u>Jaime Mijarez</u>									
45624	South Building	Restroom (Boys)			5/12/2009		21		\$0.00
Medium	Work In Progress				5/12/2009 7:23:50 AM				
Villalobos, David	we need some 5 gal. of cherry oder for the restrooms drains.								
<u>Ismael Rodriguez</u>									
45675	North Building	Gym			5/13/2009		20	1	\$25.00
Medium	Work In Progress				5/13/2009 8:36:31 AM				
Ontiveros, Guadalupe	Can you please provide us with a trailer on 5-15-09 we got the sports banquet on the gym ,so i have to move the cafeteria tables to the gym and chairs.And also have to deliver lunches on 5/21/09 and on 5/22/09 to the south building.								
<u>Ismael Rodriguez</u>									
45805					5/18/2009		15		\$0.00
Medium	Work In Progress	Front landscaping			5/18/2009 3:36:39 PM				
Ronquillo, Ruben	As per Mr. Mike Soria. Need to Install 4 KEEP OFF GRASS signs.								
<u>Juan Ambriz</u>									
45812					5/18/2009		15		\$0.00
Medium	Work In Progress				5/18/2009 3:53:25 PM				
Estrada, Jesus	NEED TO REPLACE CARPET WITH VCT IN NURSES OFFICE.								

6/2/2009 9:39:34 AM

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
45836					5/19/2009		14		\$0.00
Medium	Work In Progress			5/19/2009 1:17:39 PM					
Gonzales, Angel		Truck 121 needs a tune-up I am starting to have problems starting the truck.							
Jaime Mijarez									
45869					5/20/2009		13		\$0.00
Medium	Work In Progress			5/20/2009 9:45:16 AM					
Lara, Ralph		Gym boys restroom stall door was damaged by students. Door needs to be replaced. Stalls are new and door is not repairable.							
Jaime Mijarez									
45901	North Building	Custodial			5/21/2009		12		\$0.00
Medium	Work In Progress			5/21/2009 8:58:19 AM					
Lara, Ralph		rafa ms allen wants to see you regarding her cabnit, she wants a key to secure her things for summer thank you.							
Ismael Rodriguez									
45918	South Building	Office			5/21/2009		12		\$0.00
Medium	Work In Progress	Ms. Casillas		5/21/2009 12:16:34 PM					
Lara, Ralph		Need to get the cylinder of the door knob replaced. When key is inserted the cylinder just turns and does not open the door.							
Laura Parra									
46080	South Building				5/28/2009		5		\$0.00
Medium	Work In Progress			5/28/2009 3:17:47 PM					
Castillo, Carlos		S.bldg service lighting in administration offices and office restrooms.							
Jaime Mijarez									
46191					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:37 AM					
Mijarez, Jaime		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
46192					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:37 AM					
Mijarez, Jaime		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
46193					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:38 AM					
Mijarez, Jaime		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Santa Teresa MS</b>								
46194					5/31/2009	6/8/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:38 AM						
Mijarez, Jaime	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.									
Margret Villalobos										
46266		Athletic Field			6/1/2009		1		\$0.00	
Medium	Work In Progress			6/1/2009 8:14:55 AM						
Soria, Mike	need help to fertilize and aertate playing fields.									
Guadalupe Ontiveros										
46304		Cafeteria			6/1/2009		1		\$0.00	
Medium	Work In Progress			6/1/2009 3:16:38 PM						
Moncayo, Fernando	DISHWASHER DOESN'T RELEASE THE WATER.									
PAULA SANCHEZ SNP MGR 589-9863										
Jacqueline Aguilar										
<b>Count: 49 Work Orders</b>		<b>Avg. Age of WO's 90</b>		<b>Total for Santa Teresa MS</b>				<b>1</b>	<b>\$1,425.00</b>	



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
37362					8/25/2008		281		\$0.00
Medium	Work In Progress			8/25/2008 2:14:46 PM					
Lara, Ralph	WE NEED REPLACE CLASS ROOMS DOORS THEY ARE TO RUSTING								
Joel Herrera									
38310					9/22/2008		253		\$0.00
Medium	Work In Progress	outside		9/22/2008 2:14:13 PM					
Herrera, Joel	Please replace broken tiles located by the main entrance.								
Jessica Lopez									
38801					10/5/2008	10/26/2008	240		\$0.00
Medium	Work In Progress			10/5/2008 12:24:11 AM					
Orozco, Danny	Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
38958					10/6/2008		239	1	\$25.00
Medium	Work In Progress	library		10/6/2008 12:29:14 PM					
Herrera, Joel	Attach electrical strip to new computer cart.								
Jessica Lopez			10/24 -NON ELECTRICAL, NEED BM TO OBTAIN A POWER SURGE STRIP AND INSTALL HIMSELF. C. CASTILLO. Route to Joel 11/3/08						
39888					11/6/2008		208		\$0.00
Medium	Work In Progress			11/6/2008 8:12:18 AM					
Gonzalez, Salvador	WE NEED TO REPLACE CONCRETE WALL AND STEEL GATE AT OUTSIDE AREA								
Joel Herrera									
41299		Cafeteria			1/8/2009		145		\$0.00
Medium	Work In Progress			1/8/2009 4:08:12 PM					
Moncayo, Fernando	Dishwasher is down - System corroded - Not working at all								
	Marina Ramirez - SNP Manager 589-2545								
Alma Terrell									
41300		Cafeteria			1/8/2009		145		\$0.00
Medium	Work In Progress			1/8/2009 4:09:11 PM					
Moncayo, Fernando	Hobart Mixer - Dropping oil and making a grinding sound								
	Marina Ramirez - SNP Manager 589-2545								
Alma Terrell									
42161		Cafeteria			2/2/2009		120		\$0.00
Medium	Work In Progress			2/2/2009 4:00:22 PM					
Moncayo, Fernando	2-compartment Veg. Sink is leaking.								
	Marina Ramirez SNP Mgr 589-2545								
Jacqueline Aguilar									
6/2/2009 9:39:34 AM									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
42235					2/4/2009		118		\$0.00
Medium	Work In Progress				2/4/2009 3:26:24 PM				
Lara, Ralph	WE NEED TO SECURED MALLEN ON SOUTH SIDE EXIT DOOR'S A.S.P THANK YOU RAFA								
Joel Herrera									
42540		Cafeteria			2/12/2009		110		\$0.00
Medium	Work In Progress				2/12/2009 3:51:46 PM				
Moncayo, Fernando	RECEIVED CALL AT 3:50 PM (HOBART MIXER IS NOT WORKING AT ALL - FERNANDO WENT OVER TODAY TO PUT OIL IN MACHINE AND MARINA SAYS THAT THE MACHINE DOES NOT WORK ANYMORE)								
	MARINA RAMIREZ - SNP MANAGER 589-2545								
Alma Terrell									
43028					2/27/2009		95		\$0.00
Medium	Work In Progress				2/27/2009 10:18:35 AM				
Herrera, Joel	TILES ON THE FRONT ENTRANCE - MANY ARE BROKEN AND NEED REPLACEMENT.								
Irene Trujillo									
43029					2/27/2009		95		\$0.00
Medium	Work In Progress				2/27/2009 10:19:54 AM				
Herrera, Joel	THE PLANTERS ON THE FRONT ENTRANCE NEED TO BE PAINTED.								
Irene Trujillo									
43240					3/2/2009		92		\$0.00
Medium	Work In Progress				3/2/2009 3:42:53 PM				
Gonzalez, Salvador	WE NEED WELD FLAG POST'S HANGER AT MAIN ENTRANCE POSTS								
Joel Herrera									
43317					3/4/2009		90		\$0.00
Medium	Work In Progress				3/4/2009 2:00:31 PM				
Villalobos, David	WE HAVE SINK'S WATER LEACK AT CLASS ROOM #32								
Joel Herrera									
43677	Main Building	Auditorium			3/13/2009		81		\$0.00
Medium	Work In Progress				3/13/2009 8:25:37 AM				
Herrera, Joel	Seal gap between clear story windows and cinderblock wall on south side above stage.								
Alfredo Holguin									
43826					3/18/2009		76		\$0.00
Medium	Work In Progress				3/18/2009 10:56:15 AM				
Herrera, Joel	Mr. Herrera please paint outside portables. 4th year request								
Jessica Lopez									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
43828					3/18/2009		76		\$0.00
Medium	Work In Progress			3/18/2009 11:04:03 AM					
Herrera, Joel	MR. HERRERA PLEASE REPLACE ALL OUTSIDE BROKEN TILES. 2ND YEAR REQUEST								
Jessica Lopez									
43832					3/18/2009		76		\$0.00
Medium	Work In Progress			3/18/2009 11:08:02 AM					
Herrera, Joel	MR. HERRERA PLEASE PAINT STUDENT RESTROOMS.								
Jessica Lopez									
44333					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:48 AM					
Orozco, Danny	Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
44963					4/23/2009		40		\$0.00
Medium	Work In Progress	PORTABLE A &		4/23/2009 11:49:57 AM					
Herrera, Joel	MR. HERRERA- DOORS TO PORTABLE A & B NEED TO BE PAINTED AND ALSO RESTROOM DOORS NEED TO BE PAINTED								
Jessica Lopez									
44964					4/23/2009		40		\$0.00
Medium	Work In Progress	CUSTODIAL		4/23/2009 11:52:20 AM					
Herrera, Joel	MR. HERRERA CUSTODIAN STORAGE ROOMS NEED TO BE PAINTED								
Jessica Lopez									
45104		Classroom			4/28/2009		35		\$0.00
Medium	Work In Progress	1st to 5th grade		4/28/2009 1:31:46 PM					
Herrera, Joel	Furniture for computers delivered on April 16 to the school please set up in classrooms first to fifth grade. Thank you.								
Sandra Almeraz									
46016					5/27/2009		6		\$0.00
Medium	Work In Progress			5/27/2009 7:52:55 AM					
Herrera, Joel	MR. HERRERA PLEASE UNPLUG DRAINAGE. THANK YOU								
Jessica Lopez									
46186					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:35 AM					
Herrera, Joel	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

**1049 - Work Orders In Progress (Fiscal Year)**

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
46187					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:35 AM					
Herrera, Joel	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46188					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:36 AM					
Herrera, Joel	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
46189					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:36 AM					
Herrera, Joel	Yearly - Sunland Park ES B-2 Boiler Yearly - Refer to PM schedule details.								
Margret Villalobos									
46190					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:37 AM					
Herrera, Joel	Yearly - Sunland Park ES A-2 Split System Yearly - Refer to PM schedule details.								
Margret Villalobos									
46326					6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 4:10:28 PM					
Herrera, Joel	please cut weeds and clean around mesquite trees in the front parking lot circle. thxs								
Michael Munoz									
46327		Athletic Field			6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 4:12:20 PM					
Herrera, Joel	please borrow edger from grounds and trim and edge side walk on soccer field and pick up derbre.thxs								
Michael Munoz									
<b>Count: 30 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>91</b>		<b>Total for Sunland Park ES</b>	<b>1</b>		<b>\$25.00</b>

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
37422					8/26/2008		280		\$0.00
Medium	Work In Progress			8/26/2008 4:19:28 PM					
Ontiveros, Joe	HOSE BIBB ON WALL NEXT TO UPPER PLAY GROUND WATER LEAKING,BROKEN HANDLE.								
<u>Paul Quinones</u>									
39872					11/5/2008		209		\$0.00
Medium	Work In Progress			11/5/2008 3:35:43 PM					
Jacquez, Ricardo	REQUESTING WIND SCREEN FOR BACK CHAIN LINK FENCING AREA,LIFT STATION AREAS. BALL PARK FIGURE 200' WILL BE NEEDED @ 4' HIGH THANK YOU VERY MUCH								
<u>Paul Quinones</u>									
40018		Classroom			11/12/2008		202		\$0.00
Medium	Work In Progress	Parent Room		11/12/2008 8:11:32 AM					
Sotelo, Enrique	Check outlet with built in breaker, in Parent Room, by office, it keeps tripping.								
<u>Joanne Munoz</u>									
41164		Classroom			1/5/2009		148		\$0.00
Medium	Work In Progress	102		1/5/2009 2:51:54 PM					
Lara, Ralph	I will need a extra key for our RPT key # 1c38								
<u>Joanne Munoz</u>									
41559					1/16/2009		137		\$0.00
Medium	Work In Progress			1/16/2009 8:17:12 AM					
Sotelo, Enrique	DRYER HANDS BOYS AND GRLS. NEED REPLCE SENSOR NOT WORK								
<u>Juan Vargas</u>									
41786		Lift Station			1/23/2009		130		\$0.00
Medium	Work In Progress			1/23/2009 9:31:44 AM					
Jacquez, Ricardo	please installe air valve on lift station								
<u>Ricardo Jacquez</u>									
42708					2/19/2009		103		\$0.00
Medium	Work In Progress			2/19/2009 12:58:11 PM					
Lozoya, Manny	room 303 back door need fix lock								
<u>Juan Vargas</u>									
42709					2/19/2009		103		\$0.00
Medium	Work In Progress			2/19/2009 1:02:20 PM					
Lozoya, Manny	entry main need fix handy cop door								
<u>Juan Vargas</u>									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
44225					4/2/2009		61		\$0.00
Medium	Work In Progress			4/2/2009 3:03:37 PM					
Jacquez, Ricardo	need move up buster electical disconet								
Juan Vargas									
44513					4/7/2009		56		\$0.00
Medium	Work In Progress			4/7/2009 3:46:37 PM					
Gonzales, Angel	need replace small glass i broke								
Juan Vargas									
44742					4/16/2009		47		\$0.00
Medium	Work In Progress			4/16/2009 8:48:10 AM					
Ontiveros, Joe	need fix 2in. pvc pipe on play field have big leak								
Juan Vargas									
44992		Cafeteria			4/23/2009		40		\$0.00
Medium	Work In Progress			4/23/2009 4:13:31 PM					
Orozco, Danny	AIR CONDITIONER NOT WORKING AT ALL.								
Jacqueline Aguilar	VIRGINIA PRUIT SNP MGR 824-3194								
45098					4/28/2009		35		\$0.00
Medium	Work In Progress			4/28/2009 12:37:01 PM					
Sotelo, Enrique	need replace 3 lights on gym								
Juan Vargas									
46103	Main Building	Office			5/29/2009		4		\$0.00
Medium	Work In Progress	office		5/29/2009 2:07:05 PM					
Lozoya, Manny	Master Cabinet Key, 1006, broke can you please replace								
Joanne Munoz									
46199					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:40 AM					
Vargas, Juan	Yearly - Sunrise ES A2 (H/C Unit)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
46200					5/31/2009		2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:40 AM					
Vargas, Juan	Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM schedule details.								
Margret Villalobos									
46201					5/31/2009		2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:41 AM					
Vargas, Juan	Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM schedule details.								
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Sunrise ES</b>								
46202					5/31/2009		2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:41 AM						
Vargas, Juan	Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details.									
Margret Villalobos										
46203					5/31/2009		2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:41 AM						
Vargas, Juan	Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.									
Margret Villalobos										
46204					5/31/2009	6/6/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:42 AM						
Vargas, Juan	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.									
Margret Villalobos										
46205					5/31/2009	6/8/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:42 AM						
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.									
Margret Villalobos										
46206					5/31/2009	6/8/2009	2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:42 AM						
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.									
Margret Villalobos										
46233					5/31/2009		2		\$0.00	
Medium	Work In Progress			5/31/2009 12:23:53 AM						
Jacquez, Ricardo	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.									
Margret Villalobos										
46261		Athletic Field			6/1/2009		1		\$0.00	
Medium	Work In Progress			6/1/2009 7:50:10 AM						
Aldaz, Bobby	need to aerate and fertilize playing area.									
Guadalupe Ontiveros										
46279		Classroom			6/1/2009		1		\$0.00	
Medium	Work In Progress	101		6/1/2009 12:24:13 PM						
Lozoya, Manny	LOST KEY, 1C42, EDNA CLARY PLEASE REPLACE									
Joanne Munoz										
<b>Count: 25 Work Orders</b>		<b>Avg. Age of WO's 63</b>		<b>Total for Sunrise ES</b>			<b>0</b>	<b>\$0.00</b>		

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
36103					7/22/2008		315		\$0.00
Medium	Work In Progress			7/22/2008 8:39:31 AM					
Sotelo, Enrique		NEED TO REPLACE 4 EXIT SIGNS							
Danny Miranda									
36104					7/22/2008		315		\$0.00
Medium	Work In Progress			7/22/2008 8:40:50 AM					
Sotelo, Enrique		NEED TO REPLACE 6 EMER. LIGHTS							
Danny Miranda									
41189					1/6/2009		147		\$0.00
Medium	Work In Progress			1/6/2009 10:43:25 AM					
Sotelo, Enrique		NEED TO REPAIR THREE POWER POLES IN KITCHEN							
Danny Miranda									
41569					1/16/2009		137		\$0.00
Medium	Work In Progress			1/16/2009 9:52:29 AM					
Lozoya, Manny		NEED TOCK. DOOR KNOB IN CUSTODIAL ROOM AT 300-WING HANDLE CAME OUT							
Danny Miranda									
41880					1/27/2009		126		\$0.00
Medium	Work In Progress			1/27/2009 10:03:30 AM					
Lozoya, Manny		NEED TO PUT CHANGE DOOR KNOB AND TWO KEYS TO BEST IN NEW CLASSROOM AT LIBUERY							
Danny Miranda									
41947					1/28/2009		125		\$0.00
Medium	Work In Progress			1/28/2009 2:23:55 PM					
Lozoya, Manny		NEED TO CK. CORE ON DOOR KNOB TO BACK ELECTRICAL ROOM KEY WILL NOT LOCK							
Danny Miranda									
44118					3/31/2009		63		\$0.00
Medium	Work In Progress			3/31/2009 1:31:54 PM					
Villalobos, David		Backflow Testing and Inspection							
David Villalobos									
44337					4/5/2009	4/26/2009	58		\$0.00
Medium	Work In Progress			4/5/2009 12:22:49 AM					
Orozco, Danny		Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.							
Margret Villalobos									
44779					4/17/2009		46		\$0.00
Medium	Work In Progress			4/17/2009 11:00:25 AM					
Ontiveros, Joe		Line Locate Monday 4/20/09. Please see Danny Miranda for exact location.							
Danny Miranda									



# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
44855					4/21/2009		42		\$0.00
Medium	Work In Progress				4/21/2009 9:24:52 AM				
Gonzales, Angel	NEED BOBCAT FOR WORKING GRAVEL & SOIL TO BE PUT IN RAISED GARDENS								
Danny Miranda									
45531					5/8/2009		25		\$0.00
Medium	Work In Progress				5/8/2009 10:46:58 AM				
Sotelo, Enrique	NEED TO REPLACE SIX EXIT SIGNS								
Danny Miranda									
45591	Main Building				5/11/2009		22		\$0.00
Medium	Work In Progress				5/11/2009 11:37:09 AM				
Ontiveros, Guadalupe	NEED TO HAVE A DRIP SYSTEM PUT IN. -MS. SERVIN								
Debra Facio									
45717					5/14/2009		19		\$0.00
Medium	Work In Progress				5/14/2009 11:22:41 AM				
Miranda, Danny		5/12/09				5/12-5.5			
		(1)CK. BOILERS							
		(1.5) FINISH ASSEMBLING BAR-B Q GRILLS							
		(1.5)45272							
		(1)45270							
		(1)SET UP MARQUEE SIGNE							
		(.5)CK. HALLWAY FOR GAS SMELL							
		(1)CLEAN SIDEWALKS							
		(.5)PAPER WORK							
Danny Miranda									
46064					5/28/2009		5		\$0.00
Medium	Work In Progress				5/28/2009 9:26:12 AM				
Miranda, Danny		5/27/09				5/27 - 8			
		(1)CK. BOILERS							
		(1)CK. R.R. DOOR IN RM. 201 DEAD BOLT WILL NOT OPEN							
		(1)SET UP MARQUEE SIGN							
		(1)CK. DRYER IN SP. ED. RM. NOT DRYING							
		(3.5)GROUNDS CUT WEEDS & BLOW SIDEWALKS WITH BLOWER							
		(.5)PAPER WORK							
Danny Miranda									
46142					5/31/2009	6/6/2009	2		\$0.00
Medium	Work In Progress				5/31/2009 12:23:19 AM				
Miranda, Danny	Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									

# 1049 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2008 - 6/30/2009 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
46143					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:19 AM					
Miranda, Danny	Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46144					5/31/2009	6/8/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:19 AM					
Miranda, Danny	Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
46145					5/31/2009	7/1/2009	2		\$0.00
Medium	Work In Progress			5/31/2009 12:23:20 AM					
Miranda, Danny	Yearly - Vado ES A-2 Package Unit Elec Yearly - Refer to PM schedule details.								
Margret Villalobos									
46276		Library			6/1/2009		1		\$0.00
Medium	Work In Progress			6/1/2009 11:34:25 AM					
Sotelo, Enrique	Need two outlets in the library.								
Sandra Almeraz									
46277					6/1/2009		1		\$0.00
Medium	Work In Progress	Clerk's office		6/1/2009 11:40:52 AM					
Sotelo, Enrique	Need one dedicated circuit 120v 20A in the clerk office where PA system is installed, due to the fact that too much equipment is plugged into one existing outlet and I am getting a voltage drop that is affecting my clocks. This would be done by maintenance. Thanks, Carlos								
Sandra Almeraz									
<b>Count: 20 Work Orders</b>		<b>Avg. Age of WO's 73</b>			<b>Total for Vado ES</b>			<b>0</b>	<b>\$0.00</b>
<b>Count: 1049 Work Orders</b>		<b>Avg. Age of WO's 82</b>			<b>Grand Total</b>			<b>25</b>	<b>\$2,474.49</b>