

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Anthony ES

| | | | | | | | | | |
|-------|---------------|--|--|--|-----------|--|-----|--|--------|
| 47859 | AnnexBuilding | | | | 7/27/2009 | | 162 | | \$0.00 |
|-------|---------------|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/27/2009 12:56:13 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|
| Ontiveros, Joe | | Annexgrils bathroom 2 toilet need closet flange replace | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|

Hector Villalobos

| | | | | | | | | | |
|-------|----------|------------------|--|--|-----------|--|-----|--|--------|
| 47860 | Dona Ana | Restroom (Girls) | | | 7/27/2009 | | 162 | | \$0.00 |
|-------|----------|------------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/27/2009 1:09:34 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|
| Ontiveros, Joe | | chapter blg grils bathroom toilet needs pipe valve and closet flanges | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|

Hector Villalobos

| | | | | | | | | | |
|-------|-----------|-----------|--|--|-----------|--|-----|--|--------|
| 48634 | Cafeteria | Cafeteria | | | 8/11/2009 | | 147 | | \$0.00 |
|-------|-----------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/11/2009 10:28:30 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Orozco, Danny | | LOCK NEEDS TO BE FIXED TO REACH IN REFRIG. WILL NOT LOCK | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|--|--|-------------------|--|--|--|--|--|--|--|
| | | BECKY S. 882-3507 | | | | | | | |
|--|--|-------------------|--|--|--|--|--|--|--|

Jacqueline Aguilar

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50870 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:01 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Orozco, Danny | | Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

Margret Villalobos

| | | | | | | | | | |
|-------|------------|--|--|--|-----------|--|----|--|--------|
| 51117 | Pump House | | | | 10/6/2009 | | 91 | | \$0.00 |
|-------|------------|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/6/2009 11:08:19 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|
| Gonzalez, Salvador | | Upper primary pump house water tank has a big hole | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|

Hector Villalobos

| | | | | | | | | | |
|-------|---------------|------------------|--|--|------------|--|----|--|--------|
| 51632 | AnnexBuilding | Restroom (Girls) | | | 10/22/2009 | | 75 | | \$0.00 |
|-------|---------------|------------------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/22/2009 1:04:52 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|
| Ontiveros, Joe | | two restrooms need to be repaired(have been like that for sometime) | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|

David Vega

| | | | | | | | | | |
|-------|--|-----------|--|--|------------|--|----|--|--------|
| 51727 | | Cafeteria | | | 10/23/2009 | | 74 | | \$0.00 |
|-------|--|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/23/2009 3:13:58 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Orozco, Danny | | AE K-2 CAMPUS: MILK COOLER MAKING A VERY VERY LOUD NOISE | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|--|--|--------------------------|--|--|--|--|--|--|--|
| | | BECKY S SNP MGR 882-3507 | | | | | | | |
|--|--|--------------------------|--|--|--|--|--|--|--|

Jacqueline Aguilar

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|----------------------|------------------|---|--|--|-----------------------|------------|----|--|--------|
| Location: | | Anthony ES | | | | | | | |
| 51748 | | Portables | | | 10/26/2009 | | 71 | | \$0.00 |
| Medium | Work In Progress | | | | 10/26/2009 7:46:15 AM | | | | |
| Ontiveros, Joe | | pt 219 need a fauct for sink | | | | | | | |
| Hector Villalobos | | | | | | | | | |
| 51772 | | | | | 10/26/2009 | | 71 | | \$0.00 |
| Medium | Work In Progress | | | | 10/26/2009 3:07:44 PM | | | | |
| Ontiveros, Guadalupe | | Pre-k upper primary if we can move morgan storage next to office | | | | | | | |
| Hector Villalobos | | | | | | | | | |
| 51887 | AnnexBuilding | | | | 10/28/2009 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | | 10/28/2009 2:53:19 PM | | | | |
| Holguin, Alfredo | | Annex Bldg - 8ft wood overhang without sprinkler system coverage. | | | | | | | |
| Ralph Gallegos | | | | | | | | | |
| 52037 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
| Medium | Work In Progress | | | | 11/1/2009 12:22:52 AM | | | | |
| Orozco, Danny | | Monthly - Anthony ES Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 52138 | | | | | 11/2/2009 | | 64 | | \$0.00 |
| Medium | Work In Progress | | | | 11/2/2009 11:20:17 AM | | | | |
| Briones, Enrique | | On November 4, 2009, please pick-up obsolete computers (Monitors and Towers) from Anthony Elementary. | | | | | | | |
| Yolie Jacquez | | | | | | | | | |
| 52505 | | Cafeteria | | | 11/10/2009 | | 56 | | \$0.00 |
| Medium | Work In Progress | | | | 11/10/2009 9:15:04 AM | | | | |
| Orozco, Danny | | BRAISING SKILLET: WATER HJOSE HANDLE BROKE IN 1/2 (CLEAN CUT STRAIGHT THRU) | | | | | | | |
| | | BECKY S. SNP MGR 882-3507 | | | | | | | |
| Jacqueline Aguilar | | | | | | | | | |
| 52633 | Main Building | Restroom | | | 11/16/2009 | | 50 | | \$0.00 |
| Medium | Work In Progress | | | | 11/16/2009 7:37:54 AM | | | | |
| Lozoya, Manny | | mild blg boys and girls bathroom needs locks on door | | | | | | | |
| Hector Villalobos | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Anthony ES

| | | | | | | | | | |
|-------|---------------|--|--|--|------------|--|----|--|--------|
| 52663 | Main Building | | | | 11/16/2009 | | 50 | | \$0.00 |
|-------|---------------|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/16/2009 2:18:19 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Solis, Lorenzø mild blg hallway need to order a new water fountain

Hector Villalobos

| | | | | | | | | | |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|
| 52664 | Original Main | Classroom | | | 11/16/2009 | | 50 | | \$0.00 |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/16/2009 2:20:55 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Solis, Lorenzø old main blg order sheet metal dampers 4 a/c

Hector Villalobos

| | | | | | | | | | |
|-------|----------------|--------|--|--|------------|--|----|--|--------|
| 52752 | Annex Building | Office | | | 11/18/2009 | | 48 | | \$0.00 |
|-------|----------------|--------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/18/2009 7:20:50 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Solis, Lorenzø annex room 211 order heater code hoses water connectors

Hector Villalobos

| | | | | | | | | | |
|-------|---------------|--|--|--|-----------|--|----|--|--------|
| 53163 | Main Building | | | | 12/4/2009 | | 32 | | \$0.00 |
|-------|---------------|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/4/2009 1:27:22 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, Hector Need two door closers hallway exit door mild blg

Hector Villalobos

| | | | | | | | | | |
|-------|---------------|------------------|--|--|-----------|--|----|--|--------|
| 53164 | Main Building | Hallway/Corridor | | | 12/4/2009 | | 32 | | \$0.00 |
|-------|---------------|------------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/4/2009 1:30:25 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, Hector Mild blg boy and grils , hallway ceiling tiles 12x12 two box

Hector Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 53246 | | | | | 12/6/2009 | 12/12/2009 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:43 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Villalobos, Hector Monthly - Anthony ES Monthly FE Inspection - Refer to PMs schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 53247 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:43 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Villalobos, Hector Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PMs schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 53248 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:43 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Villalobos, Hector Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PMs schedule details.

Margret Villalobos

1/5/2010 12:27:02 PM

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Anthony ES

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53249 | | | | | 12/6/2009 | | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:44 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Villalobos, Hector Monthly - Anthony ES - Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|---------------|----------------|--|--|-----------|--|----|--|--------|
| 53403 | Main Building | Athletic Field | | | 12/9/2009 | | 27 | | \$0.00 |
|-------|---------------|----------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/9/2009 7:21:36 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ontiveros, Guadalupe Remove 3 dead trees by scooper field

Hector Villalobos

| | | | | | | | | | |
|-------|---------------|--|--|--|-----------|--|----|--|--------|
| 53404 | Main Building | | | | 12/9/2009 | | 27 | | \$0.00 |
|-------|---------------|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/9/2009 7:40:21 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, Hector Need 5 gals of roofing adhesives wet and dry for mild blg

Hector Villalobos

| | | | | | | | | | |
|-------|----------------|--|--|--|------------|--|----|--|--------|
| 53439 | Nurse Building | | | | 12/10/2009 | | 26 | | \$0.00 |
|-------|----------------|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/10/2009 7:34:32 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Joe nurse office need two toilet set

Hector Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|------------|------------|----|--|--------|
| 53550 | | | | | 12/13/2009 | 12/19/2009 | 23 | | \$0.00 |
|-------|--|--|--|--|------------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/13/2009 12:18:54 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Villalobos, Hector Monthly - Anthony ES A7 (Rooftop Unit) - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|------------|------------|----|--|--------|
| 53551 | | | | | 12/13/2009 | 12/29/2009 | 23 | | \$0.00 |
|-------|--|--|--|--|------------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/13/2009 12:18:54 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Villalobos, Hector Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|-----------|--|--|------------|--|----|--|--------|
| 53672 | | Cafeteria | | | 12/16/2009 | | 20 | | \$0.00 |
|-------|--|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/16/2009 2:25:41 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny AE K-2 CAMPUS: OVEN IS MAKING A LOUD NOISE

BECKY S. SNP MGR 882-3507

Jacqueline Aguilar

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|--------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|------------------------------|------------------|---|--|-----------------------------|-----------------------|--|----------|---------------|--------|
| Location: | | Anthony ES | | | | | | | |
| 53740 | | | | | 12/18/2009 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 12/18/2009 9:07:29 AM | | | | |
| Solis, Lorenzø | | old main boilers back follow valve is leaking | | | | | | | |
| Hector Villalobos | | | | | | | | | |
| 53743 | | | | | 12/18/2009 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 12/18/2009 10:16:16 | | | | |
| Sotelo, Enrique | | Please check power in the MDF room. causing equipment failure. thank you! | | | | | | | |
| Cora Ramirez | | | | | | | | | |
| Count: 31 Work Orders | | Avg. Age of WO's 57 | | Total for Anthony ES | | | 0 | \$0.00 | |

| | | | | | | | | | |
|--------------------|------------------|--|--|--|-----------------------|-----------|-----|--|--------|
| Location: | | Berino ES | | | | | | | |
| 47149 | | | | | 7/5/2009 | 7/26/2009 | 184 | | \$0.00 |
| Medium | Work In Progress | | | | 7/5/2009 12:21:20 AM | | | | |
| Orozco, Danny | | Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 49319 | | | | | 8/26/2009 | | 132 | | \$0.00 |
| Medium | Work In Progress | | | | 8/26/2009 3:17:26 PM | | | | |
| Lozoya, Manny | | MR ADAN DURAN NEED DOOR LATCH TO PLACE ON DOOR BETWEEN PORTABLES AND DOOR KNOB ON THE OTHER SIDE | | | | | | | |
| Adan Duran | | | | | | | | | |
| 49366 | | | | | 8/27/2009 | | 131 | | \$0.00 |
| Medium | Work In Progress | | | | 8/27/2009 12:40:12 PM | | | | |
| Duran, Adan | | MR ADAN DURAN PER MR ALFEDO HOLGIN NEED TO PAINT WEST ENTRANCE GATES | | | | | | | |
| Adan Duran | | | | | | | | | |
| 49418 | | | | | 8/28/2009 | | 130 | | \$0.00 |
| Medium | Work In Progress | | | | 8/28/2009 9:57:53 AM | | | | |
| Ontiveros, Joe | | WATER VALVE COMING OUT OF SCHOOL BUILDING ON EAST SIDE IS STUCK WILL NOT CLOSE NEED TO REPAIR OR REPLACE THANK YOU AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Berino ES

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 49443 | | | | | 8/28/2009 | | 130 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/28/2009 3:35:23 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, David Need to coordinate w/Bldg Mechanic and Joe Ontiveros on proper training for newer water heaters.

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50186 | | | | | 9/16/2009 | | 111 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/16/2009 3:06:14 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Duran, Adan MR ADAN DURAN THE EXHUAST FAN IN ROOM 100 AND 101 ARE NOT WORKING WILL NEED TO REPLACE MOTORS

Adan Duran

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50865 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:21:59 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50871 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:01 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 51123 | | | | | 10/6/2009 | | 91 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/6/2009 1:06:25 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Estrada, Jesus MR ADAN DURAN THE CARPET ON STAGE THE EDGE IS BEEN TORN AND IS DANGERS TRIPPING HAZARD STAGE IS FOUR FT HIGH SOME ONE CAN FALL

Adan Duran

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51813 | | | | | 10/27/2009 | | 70 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/27/2009 11:15:04 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Orozco, Danny NEED TO GET FIRE EXTINGUISHERS SERVICED

Danny Orozco

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52038 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:53 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|-----------------------|--|----|--|--------|
| Location: | | Berino ES | | | | | | | |
| 52308 | | Classroom | | | 11/5/2009 | | 61 | | \$0.00 |
| Medium | Work In Progress | 111 | | | 11/5/2009 1:33:30 PM | | | | |
| Lozoya, Manny | | RM# 111 - NEED 2 KEYS TO BE MADE (B52 AND B53) | | | | | | | |
| Maribel Chavez | | | | | | | | | |
| 52602 | | | | | 11/13/2009 | | 53 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2009 12:58:44 | | | | |
| Gonzales, Angel | | MR ANGEL GONZALES SIR THE BATTERY ON JOHNDEERE MOWER IS DEAD CLEAN CABLES AND JUMPED STILL WILL NOT START NEED TO REPLACE THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 52711 | | Cafeteria | | | 11/17/2009 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | | 11/17/2009 1:20:46 PM | | | | |
| Orozco, Danny | | DISHWASHER IS MAKING A VERY LOUD NOISE. UNABLE TO USE. | | | | | | | |
| | | ELSA O. SNP MGR 882-2417 | | | | | | | |
| Jacqueline Aguilar | | | | | | | | | |
| 53112 | | | | | 12/3/2009 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | | 12/3/2009 10:10:41 AM | | | | |
| Sotelo, Enrique | | MR ENRIQUE SOTELO SIR NEED TO REPLACE SOME LIGHT BULBS ON STAGE IN CAFETERIA SOME ARE BURN OUT THANK YOU SIR AND GOD BLESS PS MAY NEED LIFT | | | | | | | |
| Adan Duran | | | | | | | | | |
| 53376 | | | | | 12/8/2009 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | | 12/8/2009 12:22:09 PM | | | | |
| Sotelo, Enrique | | MR ENRIQUE SOTELO MR KIKI NEED TO REPLACE TWO EMERGENCY LIGHTS IN KITCHEN NEED TO REPLACE 3 BATTERY THANK YOU SIR AND GOD BLESS | | | | | | | |
| Adan Duran | | | | | | | | | |
| 53466 | | | | | 12/10/2009 | | 26 | | \$0.00 |
| Medium | Work In Progress | | | | 12/10/2009 12:38:50 | | | | |
| Duran, Adan | | MR ADAN DURAN NEED TO REPLACE STRIP ON MARQUI THAT HOLD LETTERS 1 1/2" WIDE BY 48" LONG NEED 6 EA ALSO NEED TO PAINT FRAME AND POLE | | | | | | | |
| Adan Duran | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Berino ES

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53625 | | | | | 12/15/2009 | | 21 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/15/2009 3:02:54 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Duran, Adan MR DURAN NEED TO PICK UP RASIER FROM STMS FOR SCHOOL PLAY PICK UP TRAILER PPD

Adan Duran

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53739 | | | | | 12/18/2009 | | 18 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/18/2009 9:00:04 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Sotelo, Enrique MR ENRIQUE SOTELO SIR NEED BALLAST FOR ROOM 108 CHANGE LIGHT BULBS BALLAST NOT WORKING THANK YOU SIR AND GOD BLESS

Adan Duran

| | | | | | | | | | |
|------------------------------|--|--|----------------------------|--|--|--|----------------------------|----------|---------------|
| Count: 19 Work Orders | | | Avg. Age of WO's 80 | | | | Total for Berino ES | 0 | \$0.00 |
|------------------------------|--|--|----------------------------|--|--|--|----------------------------|----------|---------------|

Location: Chaparral ES

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 48077 | | | | | 7/30/2009 | | 159 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/30/2009 4:07:23 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Solis, Lorenzo Need to replace rusted distribution duct in the cafeteria. Thank you

Guillermo Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 49338 | | | | | 8/26/2009 | | 132 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/26/2009 3:57:27 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ontiveros, Guadalupe Need to use Bobcat to fill water run out erroision spots. Thank you.

Guillermo Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50056 | | | | | 9/14/2009 | | 113 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/14/2009 1:15:32 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ontiveros, Guadalupe water leak on irrigtion system by irrigation tank (shut off water). Thank you.

Guillermo Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50138 | | | | | 9/15/2009 | | 112 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/15/2009 3:03:22 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Jacquez, Ricardo Please check stuck motor for Irrigation pressure tank Booster pump.

U.S. Electrical Motors (MOTOR)
Model #E684A, HP 15, 3-PHASE, 60 HZ, RPM-1745,
FL. AMPS 43.6-40.0 / 20.0, 440 VOLTS

(BOOSTER PUMP) PEERLESS PUMP CO.
MODEL #C1220AMBF

Johnny Acuna

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral ES

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50513 | | | | | 9/25/2009 | | 102 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/25/2009 8:46:06 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Carrasco, Danny Need to use scissor lift on the week of October 12 to replace ducting. thank you

Guillermo Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50872 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:02 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly- Chapparal ES Range Hood Cleaning - Refer to PMschedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|------------|--|--|--|-----------|--|----|--|--------|
| 51216 | E.Building | | | | 10/8/2009 | | 89 | | \$0.00 |
|-------|------------|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/8/2009 1:49:33 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Orozco, Danny Fire extinguisher 5MB-6H #F-817400 in Room #501 was replaced by Dymar system LLC last month and on my inspection today 10/8/09 show low charge. (warranty?)

Guillermo Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 51250 | | | | | 10/9/2009 | | 88 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/9/2009 10:57:44 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Guadalupe Need to repair "RPA" not closing right on irrigation system. Thank you

Guillermo Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52015 | | | | | 10/30/2009 | | 67 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/30/2009 4:23:08 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Gonzalez, Salvador INSTALL MARQUEE, ONCE IT ARRIVES CONTACT MIKE M.

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52039 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:53 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly- Chaparral ES Fire Suppression Insp. - Refer to PMschedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52803 | | | | | 11/19/2009 | | 47 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/19/2009 3:16:51 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lozoya, Manny Please check lock on a file cabinet in classroom #512. Thank you.

Guillermo Hernandez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral ES

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53050 | | | | | 12/2/2009 | | 34 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/2/2009 8:27:59 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Gonzales, Angel Would you please check truck #155, making a clunk noise when applying the brake. Thank you

Guillermo Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53121 | | | | | 12/3/2009 | | 33 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/3/2009 11:48:18 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Holguin, Alfredo Prepare construction cost estimate and connection plans drawings to determine the most effecient way to connect the sewer system to the Dona Ana Couty's wastewater system.

Alfredo Holguin

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53166 | | | | | 12/4/2009 | | 32 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/4/2009 2:10:58 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Sotelo, Enrique Need to replace electric switch in the kitchen. Thank you

Guillermo Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53168 | | | | | 12/4/2009 | | 32 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/4/2009 2:12:55 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Hernandez, Guillermo Guillermo need to isntall pole for the weather station on main building.

Guillermo Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53185 | | | | | 12/4/2009 | | 32 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/4/2009 3:40:26 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Sotelo, Enrique Need assistance to istall exterior light at portables #402 and #404. Thank you

Guillermo Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53239 | | | | | 12/6/2009 | | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:40 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Hernandez, Guillermo Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53538 | | | | | 12/11/2009 | | 25 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/11/2009 3:48:50 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Sotelo, Enrique Need to replace emergency light in hall between classrooms #212 and #210. Thank you

Guillermo Hernandez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral ES

53548 12/13/2009 12/29/2009 23 \$0.00

Medium Work In Progress 12/13/2009 12:18:53

Hernandez, Guillermo Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.

Margret Villalobos

53661 12/16/2009 20 \$0.00

Medium Work In Progress 12/16/2009 12:31:43

Lozoya, Manny Having problems with the GM-6 key to unlock doors. Thank you.

Guillermo Hernandez

53729 Main Building Classroom 12/17/2009 19 \$0.00

Medium Work In Progress 201 12/17/2009 3:45:43 PM

Lozoya, Manny Need two extra keys for cabinet. cabinet key 0015 See Ms. martinez/Jennifer/Rose Alford

Jennifer Corral

53730 Main Building Classroom 12/17/2009 19 \$0.00

Medium Work In Progress all rooms kinder 12/17/2009 3:47:32 PM

Lozoya, Manny Locks in cabinet need to be replaced in the kinder wing. All have different numbers. Per Manny and Memo request. Working progress for all rooms.

Jennifer Corral

Count: 22 Work Orders Avg. Age of WO's 62 Total for Chaparral ES 0 \$0.00

Location: Chaparral HS

47098 7/5/2009 184 \$0.00

Medium Work In Progress 7/5/2009 12:21:00 AM

Holguin, Alfredo Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details. 8/27/09 - Emailed to Rick

Margret Villalobos

47509 7/14/2009 72 \$0.00

Medium Work In Progress 7/14/2009 10:22:37 AM 9/24/2009

Rivera, Armando NEED TO ASSIST IN CUTTING OF THE WEEDS ALL AROUND BUILDING. 7/14/09 - FAXE-MAILED TO ARMADO; 9/15/09 -MAILED COPY TO ARMANDO, NEED STATUS; 11/30-09 - MAILED COPY OUT, REQUESTING STATUS

Jesus Estrada

48121 F-Wing Classroom 7/31/2009 158 \$0.00

Medium Work In Progress Rm. 4 7/31/2009 3:13:30 PM

Quinones, Paul Need a bracket to hold the pull down maps. (Mr. Hubble) ROUTED TO PAUL, AS PER MIKE NEED MORE INFORMATION

Guadalupe Gonzalez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral HS

| | | | | | | | | | |
|-------|--|--|--|--|----------|--|-----|--|--------|
| 48200 | | | | | 8/2/2009 | | 156 | | \$0.00 |
|-------|--|--|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/2/2009 12:21:21 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|
| Quinones, Paul | | Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|----------|--|-----|--|--------|
| 48201 | | | | | 8/2/2009 | | 156 | | \$0.00 |
|-------|--|--|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/2/2009 12:21:22 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|
| Quinones, Paul | | Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|

Margret Villalobos

| | | | | | | | | | |
|-------|--|----------------|--|--|----------|--|-----|--|--------|
| 48229 | | Athletic Field | | | 8/3/2009 | | 155 | | \$0.00 |
|-------|--|----------------|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/3/2009 9:51:50 AM | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

| | | | | | | | | | |
|----------------------|--|--|--|--|--|--|--|--|--|
| Ontiveros, Guadalupe | | Lupe I need the total amount of landscaped areas at this site. | | | | | | | |
|----------------------|--|--|--|--|--|--|--|--|--|

Alfredo Holguin

| | | | | | | | | | |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|
| 48581 | | Classroom | | | 8/10/2009 | | 148 | | \$0.00 |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | E Wing - Rm. 6 | | | 8/10/2009 12:45:39 PM | | | | |
|--------|------------------|----------------|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|
| Quinones, Paul | | Television needs to be turned. (Ms. Pranses) | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|

Guadalupe Gonzalez

| | | | | | | | | | |
|-------|--------|--------------|--|--|-----------|--|-----|--|--------|
| 48712 | C-Wing | Computer Lab | | | 8/12/2009 | | 146 | | \$0.00 |
|-------|--------|--------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/12/2009 10:36:27 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|---|--|--|--|---------------------------|--|--|--|
| Solis, Lorenzo | | ONE OF THE UNITS IS NOT FOUND AT ALL THRU TRACER SUMMIT, NEED TO LOCATE UNIT. | | | | 8/12 - Emailed Trane -mkv | | | |
|----------------|--|---|--|--|--|---------------------------|--|--|--|

Lorenzo Solis

| | | | | | | | | | |
|-------|--------|-----------|--|--|-----------|--|-----|--|--------|
| 48779 | D-Wing | Classroom | | | 8/13/2009 | | 145 | | \$0.00 |
|-------|--------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Rm. 6 | | | 8/13/2009 1:14:56 PM | | | | |
|--------|------------------|-------|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|
| Quinones, Paul | | Remove and replace broken desk (leg fell off) (Ms. Lopez) | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|

Guadalupe Gonzalez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 48781 | | | | | 8/13/2009 | | 145 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Gates | | | 8/13/2009 1:18:57 PM | | | | |
|--------|------------------|-------|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------------|--|---|--|--|--|--|--|--|--|
| Gonzalez, Salvador | | Weld the locks to chains and chains to gates. Locks keep getting moved preventing security to secure the gates. Safety Issue. (Frank De Santiago) | | | | | | | |
|--------------------|--|---|--|--|--|--|--|--|--|

Guadalupe Gonzalez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral HS

50090 E-Wing Restroom 9/14/2009 113 \$0.00

Medium Work In Progress E WING 9/14/2009 3:45:06 PM

Ontiveros, Joe BOYS SINK - NO WATER (DIGGS)

Rosa Quezada

50113 C-Wing 9/15/2009 112 \$0.00

Medium Work In Progress MISCELLANEO 9/15/2009 9:18:33 AM

Ontiveros, Joe
 WING "C" PROBLEMS;
 1. BOYS RESTROOM - 4 SINKS ARE LOOSE
 2. GIRLS RESTROOM - SOAP DISPENSER BROKEN
 3. WATER FOUNTAIN BUTTON IS LOOSE
 4. ROOF BETWEEN C & D HALLWAY HAS A WATER STAIN

Rosa Quezada

50179 F-Wing 9/16/2009 111 \$0.00

Medium Work In Progress 9/16/2009 2:09:20 PM

Ontiveros, Joe
 WING "F" PROBLEMS;
 1. GIRLS RESTROOM - TWO SINKS DON'T RELEASE WATER
 2. BOYS RESTROOM - 3 SINKS ARE LOOSE
 3. ONE SINK DOESN'T RELEASE WATER
 4. URINAL IN BOYS RESTROOM DOESN'T FLUSH

Rosa Quezada

50279 9/20/2009 107 \$0.00

Medium Work In Progress 9/20/2009 12:18:48 AM

Ontiveros, Guadalupe
 Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.

Margret Villalobos

50463 Field House Restroom (Girls) 9/24/2009 103 \$0.00

Medium Work In Progress 9/24/2009 7:17:11 AM

Rivera, Armando
 field house restrooms boys rest room set up 10 toilet roll paper dispensers girls frst room set up 21 toilet roll paper dispensers
 11/30/09 - MAILED OUT COPY REQUESTING STATUS
 9/24(Asp Mike/Alfredo, Custodial needs to install)mkv

Armando Rivera

50523 Library 9/25/2009 102 \$0.00

Medium Work In Progress 9/25/2009 11:08:45 AM

Quinones, Paul
 Repair wheel roller on periodical shelving. Please ask librarian Marty Mayes for specific location.

Phillip Medina

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral HS

| | | | | | | | | | |
|-------|-------------|----------|--|--|-----------|--|----|--|--------|
| 50580 | Field House | Restroom | | | 9/28/2009 | | 99 | | \$0.00 |
|-------|-------------|----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/28/2009 1:42:19 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Rivera, Armando set up 12 soap dispensers boy and girls rest rooms and concession stand

Armando Rivera

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 50833 | | | | | 10/4/2009 | | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:21:48 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Holguin, Alfredo Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50864 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:21:59 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 51090 | | | | | 10/5/2009 | | 92 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/5/2009 4:19:33 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Lozoya, Manny KICK PLATES ARE NEEDED IN KITCHEN REAR ENTRANCE 2, KICK PLATES THANK YOU.

Paul Quinones

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|---|---------|
| 51451 | | | | | 10/14/2009 | | 83 | 2 | \$50.00 |
|-------|--|--|--|--|------------|--|----|---|---------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/14/2009 3:28:58 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Solis, Lorenzo GIRLS LOCKER EAST MP-580 NOT COMMUNICATING W/TRACER OFF LINE. GYM AREA. 10/27 (Asp Lorenzo, reset BCU and ck for loose wires and still not communicating). 10/27 e-mailed J. Valenzuela w/Trane - mkv reset bcu, ck for loose wires, will call Trane controls.

Paul Quinones

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51569 | | | | | 10/21/2009 | | 76 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/21/2009 8:19:36 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Joe B TROUGH G REST ROOMS REPLACE ALL WATER FAUCETS THANK U VERY MUCH. 6-PACK JOE.

Paul Quinones

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral HS

51571 10/21/2009 76 \$0.00

Medium Work In Progress 10/21/2009 8:22:18 AM

Sotelo, Enrique LIGHT BALLAST ARE NEEDED IN SCHOOL GYM
LIGHTING
MUCHOS GRACIAS.

Paul Quinones

52005 10/30/2009 67 \$0.00

Medium Work In Progress 10/30/2009 3:47:45 PM

Lozoya, Manny we need to change all copier room locks to self close
when using key...too many doors remain open because
they dont lock them when they leave...(quezada)

Rosa Quezada

52036 11/1/2009 11/22/2009 65 \$0.00

Medium Work In Progress 11/1/2009 12:22:52 AM

Orozco, Danny Monthly- Chaparral HS Fire Suppression Insp. - Refer
to PM schedule details.

Margret Villalobos

52172 11/3/2009 63 \$0.00

Medium Work In Progress 11/3/2009 7:57:55 AM

Sotelo, Enrique wing. E E-7 entrance is missing the light cover

Juan Vargas

52430 11/9/2009 57 \$0.00

Medium Work In Progress 11/9/2009 8:12:28 AM

Quinones, Paul FDC on North Side is missing cap.

Ralph Gallegos

52489 11/9/2009 57 \$0.00

Medium Work In Progress 11/9/2009 4:14:09 PM

Ontiveros, Joe SPRINKLER HEAD IN RM. B-6 IS LEAKING WATER
NEEDS TO
BE REPLACED.

Paul Quinones

52645 11/16/2009 50 \$0.00

Medium Work In Progress 11/16/2009 8:59:35 AM

Quinones, Paul 10-29-09 10/29-8
5.0,PM SCHEADULE ROOF INSPECTION
3.0,PM SCHEADULE EMER.LIGHT INSPECTION

Paul Quinones

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral HS

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52659 | | | | | 11/16/2009 | | 50 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/16/2009 11:44:46 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Sotelo, Enrique
 PARKING LOT LIGHTING NEED TO REPLACE LIGHT BULBS
 FRONT AND BACK PARKING LOT AREAS.BUCKET TRUCK
 WILL BE NEEDED MUCHOS GRACIAS.

Paul Quinones

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52660 | | | | | 11/16/2009 | | 50 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/16/2009 11:44:52 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Sotelo, Enrique
 PARKING LOT LIGHTING NEED TO REPLACE LIGHT BULBS
 FRONT AND BACK PARKING LOT AREAS.BUCKET TRUCK
 WILL BE NEEDED MUCHOS GRACIAS.

Paul Quinones

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52661 | | | | | 11/16/2009 | | 50 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/16/2009 11:45:13 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Sotelo, Enrique
 PARKING LOT LIGHTING NEED TO REPLACE LIGHT BULBS
 FRONT AND BACK PARKING LOT AREAS.BUCKET TRUCK
 WILL BE NEEDED MUCHOS GRACIAS.

Paul Quinones

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52672 | | | | | 11/16/2009 | | 50 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/16/2009 3:18:01 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Joe
 MECHANICAL RM. IN R BUILDING LEAKING WATER FROM ONE OF THE CIRCULATING PUMPS.WATER LEAKING FROM GASKET

Paul Quinones

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52673 | | | | | 11/16/2009 | | 50 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/16/2009 3:21:27 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lozoya, Manny
 DOOR IN BOYS LOCKER RM. EAST DOOR HINGE BROKEN
 NEEDS TO BE REPLACED THANKS

Paul Quinones

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral HS

52773 11/18/2009 48 \$0.00

Medium Work In Progress 11/18/2009 3:38:21 PM

Gallegos, Ralph
WARRANTY W/0# ATTN.R.GALLEGOS
EXHAUST FAN NOT WORKING IN GIRLS LOCKER
RM.
COACHES OFFICE.

Paul Quinones

52921 11/24/2009 42 \$0.00

Medium Work In Progress 11/24/2009 9:57:56 AM

Lara, Ralph
Need to secure some doors, before the break asp Mr.
Diggs.

Michael Munoz

53110 12/3/2009 33 \$0.00

Medium Work In Progress 12/3/2009 9:26:56 AM

Ontiveros, Joe
REQUESTING TO REPLACE WATER LAV. IN BAND
RM.
REPLACE BATTERIES NO WATER FLOW.6 TOTAL
WATER
LAV. WILL BE NEEDED.

Paul Quinones

53132 12/3/2009 33 \$0.00

Medium Work In Progress 12/3/2009 2:42:16 PM

Quinones, Paul
PARKING LOT LANES,AND SPEED BUMPS NEED TO
BE
PAINTED W/ PARKING LOT YELLOW PAINT.

Paul Quinones

53368 12/8/2009 28 \$0.00

Medium Work In Progress 12/8/2009 8:12:32 AM

Lozoya, Manny
NEED TO REPLACE DOOR SRICKERS TO GYM
DOORS DOORS
ARE BEING YANKED OPEN BY STUDENTS.

Paul Quinones

53411 12/9/2009 27 \$0.00

Medium Work In Progress 12/9/2009 8:48:16 AM

Sotelo, Enrique
GIRLS SOFTBALL FIELD ELECTRICAL OUTLET FOR
PITCHING
M
ACHINE,BROKEN.WIRES EXPOSED CAUSING
SHORT.

Paul Quinones

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days | Labor | Total |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|------|-------|-------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | Aged | Hours | Costs |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral HS

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53419 | | | | | 12/9/2009 | | 27 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/9/2009 12:40:44 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Carrasco, Danny
FRONT ENTRANCE IN COURT YARD AREA WINDOW
BROKEN
GLASS MEASUREMENTS 17"x96".TINT DOUBLE
PANE.THANKS

Paul Quinones

| | | | | | | | | | |
|-------|--|------------|--|--|-----------|--|----|--|--------|
| 53435 | | Mechanical | | | 12/9/2009 | | 27 | | \$0.00 |
|-------|--|------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/9/2009 3:44:05 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Solis, Lorenzo
BROKEN PUMP NEEDS TO BE REPLACE AND
REPAIR.

Lorenzo Solis

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53481 | | | | | 12/10/2009 | | 26 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/10/2009 3:45:24 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lozoya, Manny
COSTUDIAL STAFF NEED A KEY FOR THE TRASH
COMPACTER
2 KEYS WILL BE NEEDED.THANKS

Paul Quinones

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53487 | | | | | 12/10/2009 | | 26 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/10/2009 3:52:56 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lozoya, Manny
GATES ON LOBO LANE NEED LOCKS,AND CHAIN
TO BE
WELDED TO GATE DOOR TO KEEP DOORS
SECURED TO
KEEP DOORS OPEN

Paul Quinones

| | | | | | | | | | |
|-------|--|----------------|--|--|------------|--|----|--|--------|
| 53490 | | Athletic Field | | | 12/10/2009 | | 26 | | \$0.00 |
|-------|--|----------------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/10/2009 3:56:16 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Guadalupe
BATTING CAGES ARE NEEDED FOR GIRLS,AND
BOYS
PLAYING FIELDS.ATTN; LUPE O.

Paul Quinones

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53506 | | | | | 12/11/2009 | | 25 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/11/2009 8:31:34 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Gonzalez, Salvador
NEED TO WELD GATE HINGES TO FENCE
POLES,GATES ARE
UNABLE TO CLOSE PROPERLY W/LOCK.LOBO
LANE GATES
LOCATED ON COUNTY LINE RD.

Paul Quinones

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|------------------------------|------------------|---|--|--|-------------------------------|--|----|----------|----------------|
| Location: | | Chaparral HS | | | | | | | |
| 53636 | | | | | 12/15/2009 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 12/15/2009 3:51:03 PM | | | | |
| Sotelo, Enrique | | ELECTRICAL HAND DRYER IN BOYS REST RM.WING G NEEDS TO BE REPLACED.BROKEN. | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 53638 | | | | | 12/15/2009 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 12/15/2009 3:54:27 PM | | | | |
| Ontiveros, Joe | | TOILET IN HEALTH CENTER STUDENT REST RM.BROKEN FROM BOTTOM OF TOILET BOWEL. | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 53639 | | | | | 12/15/2009 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 12/15/2009 3:59:12 PM | | | | |
| Solis, Lorenzø | | HOT,AND COLD AREAS IN ADMIN. OFFICES CHECKED VAV BOXES NOT CONTROLLING PROPERLY. | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 53647 | | | | | 12/16/2009 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 12/16/2009 8:46:20 AM | | | | |
| Lozoya, Manny | | NEED A KEY CYLINDER IN BACK STOARGE AREA DOOR BROKEN CYLINDER | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 53648 | | | | | 12/16/2009 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 12/16/2009 8:51:30 AM | | | | |
| Sotelo, Enrique | | 3 WAY SWITCH KEY TYPE,COSTUDIAL STAFF HAVING HARD TIME TURNING ON,AND OFF SWITCH IN CAFETERIA.HALL WAY. | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 53747 | | | | | 12/20/2009 | | 16 | | \$0.00 |
| Medium | Work In Progress | | | | 12/20/2009 12:18:38 | | | | |
| Ontiveros, Guadalupe | | Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 52 Work Orders | | Avg. Age of WO's 73 | | | Total for Chaparral HS | | | 2 | \$50.00 |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral MS

| | | | | | | | | | |
|-------|--|--|--|--|----------|-----------|-----|--|--------|
| 47150 | | | | | 7/5/2009 | 7/26/2009 | 184 | | \$0.00 |
|-------|--|--|--|--|----------|-----------|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/5/2009 12:21:20 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Orozco, Danny Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|---------------|-----------|--|--|----------|--|-----|--|--------|
| 48224 | Main Building | Classroom | | | 8/3/2009 | | 155 | | \$0.00 |
|-------|---------------|-----------|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | ROOM 307 | | | 8/3/2009 9:13:24 AM | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|

Lozoya, Manny NEED KEYS MADE TO SCIENCE LAB CABINETS HAVE NEVER BEEN ABLE TO LOCK. NEED THEM TO LOCK SCIENCE EQUIPMENT

Elena Palacios

| | | | | | | | | | |
|-------|--|----------------|--|--|-----------|--|-----|--|--------|
| 48693 | | Athletic Field | | | 8/12/2009 | | 146 | | \$0.00 |
|-------|--|----------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Safety | Work In Progress | | | | 8/12/2009 8:14:17 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Garcia, Jose need to replace sprinklers on football field that are not working.

Guadalupe Ontiveros

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 49439 | | | | | 8/28/2009 | | 130 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/28/2009 3:33:52 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, David Need to coordinate w/Bldg Mechanic and Joe Ontiveros on proper training for newer water heaters.

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50240 | | | | | 9/18/2009 | | 109 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/18/2009 9:55:11 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ontiveros, Joe we need a new faucet in the custodial closet in the gym it leaks real bad. Thank You

Robert Gonzalez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50363 | | | | | 9/22/2009 | | 105 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/22/2009 8:45:53 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ontiveros, Joe Joe I have a mop closet in the gym that needs a new faucet

Eric Medina

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50866 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:00 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral MS

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50873 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:02 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Chapparal MS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|-----|--|--|------------|--|----|--|--------|
| 51618 | | Gym | | | 10/22/2009 | | 75 | | \$0.00 |
|-------|--|-----|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/22/2009 8:19:03 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Sotelo, Enrique as per our conversation please install power for new kiln in storage room by gym.thanks

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51619 | | | | | 10/22/2009 | | 75 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/22/2009 8:42:12 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Gonzales, Angel Angel the tires on my truck (# 80) are really worn could you please replace

Eric Medina

| | | | | | | | | | |
|-------|--|-----|--|--|------------|--|----|--|--------|
| 51620 | | Gym | | | 10/22/2009 | | 75 | | \$0.00 |
|-------|--|-----|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/22/2009 8:42:15 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Solis, Lorenz when kiln is installed please install vent.thankyou. storage room by gym. contact person eric.

Michael Munoz

| | | | | | | | | | |
|-------|--|--------|--|--|------------|--|----|--|--------|
| 51899 | | Office | | | 10/28/2009 | | 69 | | \$0.00 |
|-------|--|--------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|-----------------------|--|--|--|--|
| High | Work In Progress | | | | 10/28/2009 3:42:29 PM | | | | |
|------|------------------|--|--|--|-----------------------|--|--|--|--|

Medina, Eric front blue ramp on concrete needs the handi-cap logo.thank

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52040 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:53 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Chaparral MS Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 52198 | | | | | 11/3/2009 | | 63 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/3/2009 11:21:39 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Sotelo, Enrique We have two light pole lights out. One in the southwest close to portables 9 and 10 and the other one at the main exit gate. The one at the main exit gate is needed as soon as possible it lights up the front of the school and the parking lot it gets dark very early this time of the year. Thank you

Robert Gonzalez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral MS

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 52360 | | | | | 11/6/2009 | | 60 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/6/2009 10:06:13 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Gonzalez, Salvador Sal need you to fabricate a floor covering for the gym

Eric Medina

| | | | | | | | | | |
|-------|---------------|--|--|--|------------|--|----|--|--------|
| 52623 | Phase III New | | | | 11/13/2009 | | 53 | | \$0.00 |
|-------|---------------|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/13/2009 4:00:11 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Medina, Eric 400 wing corridor - completely paint FRP panels which were partially painted because of graffiti

Alfredo Holguin

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52757 | | | | | 11/18/2009 | | 48 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/18/2009 9:14:32 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lozoya, Manny many need you to check out door knob in room 306 and the door closer to the double door leading to the 200 hallway is falling off

Eric Medina

| | | | | | | | | | |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|
| 52789 | Main Building | Classroom | | | 11/19/2009 | | 47 | | \$0.00 |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | ROOM 304 | | | 11/19/2009 11:21:43 | | | | |
|--------|------------------|----------|--|--|---------------------|--|--|--|--|

Lozoya, Manny EL VIA OCHOA LOST HER KEY TO ROOM 304, ADMINISTRATION WOULD LIKE FOR DOOR TO BE REKEYED

Elena Palacios

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52792 | | | | | 11/19/2009 | | 47 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/19/2009 12:01:44 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Solis, Lorenzo Lorenzo I need to order another water fountain for the girls locker room. I don't know the price of the single one but I turned in a vandalism report

Eric Medina

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53122 | | | | | 12/3/2009 | | 33 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/3/2009 11:58:53 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Holguin, Alfredo Prepare construction cost estimate and connection plans drawings to determine the most efficient way to connect the sewer system to the Dona Ana Couty's wastewater system.

Alfredo Holguin

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53199 | | | | | 12/4/2009 | | 32 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/4/2009 4:25:50 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Martinez, Larry Pick up TELEX Record-Player/GISD Tag # 010793/Serial #: 92312013788 and deliver to Berino Elementary School Library/Dolores Sanchez

Phillip Medina

1/5/2010 12:27:03 PM

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral MS

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 53235 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:38 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Medina, Eric
Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|-----|--|--|-----------|--|----|--|--------|
| 53423 | | Gym | | | 11/9/2009 | | 57 | | \$0.00 |
|-------|--|-----|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Girls Locker | | | 12/9/2009 2:07:56 PM | | | | |
|--------|------------------|--------------|--|--|----------------------|--|--|--|--|

Solis, Lorenzo
Broken spigot on water fountain in Girls Locker Rm (single water fountain).

Carl Sullivan

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53534 | | | | | 12/11/2009 | | 25 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/11/2009 3:46:03 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Medina, Eric
Order material thru warehouse asp PM53232 CDE-CHM-001 Dryer needs a new exhaust hose.

Eric Medina

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53594 | | | | | 12/14/2009 | | 22 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/14/2009 3:49:58 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Acuna, Johnny
Johnny Acuña/Guillermo Hernandez: Chaparral Middle School- Re-secure urinal stalls and torn down plywood sheet on restroom walls.

Johnny Acuna

| | | | | | | | | | |
|-------|--|-----------|--|--|------------|--|----|--|--------|
| 53610 | | Cafeteria | | | 12/15/2009 | | 21 | | \$0.00 |
|-------|--|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/15/2009 12:07:53 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Orozco, Danny
TOP OVEN IS STILL NOT HEATING UP.

SANDRA D. SNP MGR 824-4376

Jacqueline Aguilar

| | | | | | | | | | |
|-------|--|-----------|--|--|------------|--|----|--|--------|
| 53611 | | Cafeteria | | | 12/15/2009 | | 21 | | \$0.00 |
|-------|--|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/15/2009 12:09:07 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Orozco, Danny
REACH IN WARMERS ARE NOT HEATING UP, BUT TEMP IS AT 330.

SANDRA D. SNP MGR 824-4376

Jacqueline Aguilar

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Chaparral MS

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53660 | | | | | 12/16/2009 | | 20 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/16/2009 12:27:06 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Solis, Lorenzø
Is there anyways someone could come and fix our heating problems. Our 300 hallway west side is freezing. No heat is coming out at all. The 400 hall is hit and miss. Let me know who can help us. Students parents are calling and getting upset with us because kids are getting sick. HELP.

Marti Muela

| | | | | | | | | | |
|-------|--|----------|--|--|------------|--|----|--|--------|
| 53663 | | Restroom | | | 12/16/2009 | | 20 | | \$0.00 |
|-------|--|----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | LOBBY | | | 12/16/2009 1:14:47 PM | | | | |
|--------|------------------|-------|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|--|--|--|--|-----------------------------------|--|--|--|
| Medina, Eric | | NO EXHAUST FAN IN BOYS RESTROOM IN LOBBY | | | | 1/4/10 - Assign to Eric asp Mike. | | | |
|--------------|--|--|--|--|--|-----------------------------------|--|--|--|

Elena Palacios

| | | | | | | | | | |
|-------|--|----------|--|--|------------|--|----|--|--------|
| 53664 | | Restroom | | | 12/16/2009 | | 20 | | \$0.00 |
|-------|--|----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | 300 HALLWAY | | | 12/16/2009 1:16:48 PM | | | | |
|--------|------------------|-------------|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|---|--|--|--|-----------------------------------|--|--|--|
| Medina, Eric | | NO EXHAUST FAN IN BOYS RESTROOM IN 300 HALL WAY | | | | 1/4/10 - Assign to Eric asp Mike. | | | |
|--------------|--|---|--|--|--|-----------------------------------|--|--|--|

Elena Palacios

| | | | | | | | | | |
|-------|---------------|----------|--|--|------------|--|----|--|--------|
| 53665 | Main Building | Restroom | | | 12/16/2009 | | 20 | | \$0.00 |
|-------|---------------|----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | 100 HALLWAY | | | 12/16/2009 1:20:35 PM | | | | |
|--------|------------------|-------------|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|--|--|--|--|-----------------------------------|--|--|--|
| Medina, Eric | | NO EXHAUST FANS IN MENS BATHROOM IN 100 HALLWAY FOR OVER A YEAR. | | | | 1/4/10 - Assign to Eric asp Mike. | | | |
|--------------|--|--|--|--|--|-----------------------------------|--|--|--|

Elena Palacios

| | | | | | | | | | |
|-------|--|------------------|--|--|------------|--|----|--|--------|
| 53666 | | Hallway/Corridor | | | 12/16/2009 | | 20 | | \$0.00 |
|-------|--|------------------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | 300 & 400 | | | 12/16/2009 1:22:40 PM | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|--|--|--|--|-----------------------------------|--|--|--|
| Medina, Eric | | NEED WATER FOUNTAINS REPLACED IN 300 AND 400 HALLWAY | | | | 1/4/10 - Assign to Eric asp Mike. | | | |
|--------------|--|--|--|--|--|-----------------------------------|--|--|--|

Elena Palacios

| | | | | | | | | | |
|-------|--|----------|--|--|------------|--|----|--|--------|
| 53668 | | Restroom | | | 12/16/2009 | | 20 | | \$0.00 |
|-------|--|----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | RESTROOMS | | | 12/16/2009 1:39:01 PM | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|--|--|--|--|--|--|--|--|
| Medina, Eric | | BOYS AND GIRLS RESTROOMS IS 300 HALLWAY NEED TO BE PAINTED | | | | | | | |
|--------------|--|--|--|--|--|--|--|--|--|

Elena Palacios

| | | | | | | | | | |
|-------|--|-------------|--|--|------------|--|----|--|--------|
| 53669 | | Parking Lot | | | 12/16/2009 | | 20 | | \$0.00 |
|-------|--|-------------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | VISITOR'S | | | 12/16/2009 1:58:37 PM | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Ronquillo, Ruben | | NEED 3 VISITOR'S PARKING SPACES ADDED TO PARKING LOT | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

Elena Palacios

1/5/2010 12:27:03 PM

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| Location: | | Chaparral MS | | | | | | | |
|------------------------------|------------------|--|----------------------------|--|-----------------------|--|-------------------------------|----------|---------------|
| 53695 | | | | | 12/17/2009 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 12/17/2009 9:40:29 AM | | | | |
| Lozoya, Manny | | ROOM 301 DOOR LOCK WILL NOT LOCK | | | | | | | |
| Robert Gonzalez | | | | | | | | | |
| 53697 | | | | | 12/17/2009 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 12/17/2009 9:52:51 AM | | | | |
| Lozoya, Manny | | ENTRANCE DOOR TO CAFETERIA FROM FRONT CORRIDOR CAN NOT BE UNLOCKED | | | | | | | |
| Robert Gonzalez | | | | | | | | | |
| 53701 | | | | | 12/17/2009 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 12/17/2009 10:13:14 | | | | |
| Lozoya, Manny | | ROOM 312 DOOR SEEMS TO HAVE FALLEN HAVE TO LEFT DOOR IN ORDER TO CLOSE DOOR. | | | | | | | |
| Robert Gonzalez | | | | | | | | | |
| 53912 | | | | | 12/18/2009 | | 18 | | \$0.00 |
| Medium | Work In Progress | | | | 1/4/2010 9:33:45 AM | | | | |
| Hernandez, Guillermo | | Leak in room 309-310 | | | | | | | |
| Michael Munoz | | | | | | | | | |
| Count: 38 Work Orders | | | Avg. Age of WO's 57 | | | | Total for Chaparral MS | 0 | \$0.00 |

| Location: | | Charter School | | | | | | | |
|-----------------------------|------------------|---|---------------------------|--|----------------------|--|---------------------------------|----------|---------------|
| 47478 | | | | | 7/13/2009 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 7/13/2009 2:54:32 PM | 7/20/2009 | | | |
| Munoz, Michael | | Portables # 2 DW, 80 DW and 32 SW located in San Miguel Elem. recarpet, paint and get ready for Charter School at GHS old DACC location | | | | 7/15/09 - FAX TO MICHAEL/AZTEC FOR QUOTE ON CARPET | | | |
| Alfredo Holguin | | | | | | | | | |
| Count: 1 Work Orders | | | Avg. Age of WO's 7 | | | | Total for Charter School | 0 | \$0.00 |

| Location: | | Desert Pride | | | | | | | |
|-------------------|------------------|------------------------|--|--|----------------------|--|-----|--|--------|
| 47637 | | | | | 7/20/2009 | | 169 | | \$0.00 |
| Medium | Work In Progress | | | | 7/20/2009 3:59:28 PM | | | | |
| Aguilar, Patricio | | Need to assemble desk. | | | | | | | |
| Irene Herrera | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | |
|------------------|---------------------|
| Location: | Desert Pride |
|------------------|---------------------|

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 48969 | | | | | 8/18/2009 | | 140 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|
| High | Work In Progress | | | | 8/18/2009 3:22:08 PM | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-------------------|--|---|--|--|--|--|--|--|--|
| Villalobos, David | | 2nd bldg, please check to see if gas regulator if functioning properly. thanks | | | | | | | |
|-------------------|--|---|--|--|--|--|--|--|--|

Michael Munoz

| | | | | | | | | | |
|-------|--|--------|--|--|-----------|--|-----|--|--------|
| 50124 | | Office | | | 9/15/2009 | | 112 | | \$0.00 |
|-------|--|--------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | BACK DOOR | | | 9/15/2009 11:20:48 AM | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|-------------|--|---|--|--|--|--|--|--|--|
| Lara, Ralph | | REQUESTING FOR A SMALL WINDOW TO BE INSTALL ON BACK DOOR ENTRANCE. | | | | | | | |
|-------------|--|---|--|--|--|--|--|--|--|

David Acosta

| | | | | | | | | | |
|-------|--|---------|--|--|-----------|--|-----|--|--------|
| 50244 | | Library | | | 9/18/2009 | | 109 | | \$0.00 |
|-------|--|---------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | SECURITY | | | 9/18/2009 11:14:11 AM | | | | |
|--------|------------------|----------|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|---|--|--|--|--|--|--|--|
| Castillo, Carlos | | SECURITY OFFICE NEEDS OWN LIGHT SWITCH. | | | | | | | |
|------------------|--|---|--|--|--|--|--|--|--|

David Acosta

| | | | | | | | | | |
|-------|--|-----------|--|--|------------|--|----|--|--------|
| 51584 | | Portables | | | 10/21/2009 | | 76 | | \$0.00 |
|-------|--|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | ROOM 7 | | | 10/21/2009 1:39:45 PM | | | | |
|--------|------------------|--------|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Castillo, Carlos | | NEED TO REPLACE BALLAST TO LIGHT FIXTURE | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

David Acosta

| | | | | | | | | | |
|-------|--|------------------|--|--|------------|--|----|--|--------|
| 51585 | | Hallway/Corridor | | | 10/21/2009 | | 76 | | \$0.00 |
|-------|--|------------------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | 2ND BLDG, | | | 10/21/2009 2:01:58 PM | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Castillo, Carlos | | ELECTRICAL PANEL BOX AS A OPENING THAT NEEDS TO BE COVER (SAFTY HAZZARD). | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

David Acosta

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51890 | | | | | 10/28/2009 | | 69 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/28/2009 2:58:56 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|---|--|--|--|--|--|--|--|
| Castillo, Carlos | | 2nd Bldg - open blank in electrical panel located at entrance. | | | | | | | |
|------------------|--|---|--|--|--|--|--|--|--|

Ralph Gallegos

| | | | | | | | | | |
|-------|--|-----------|--|--|------------|--|----|--|--------|
| 52825 | | Portables | | | 11/20/2009 | | 46 | | \$0.00 |
|-------|--|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|---|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | 8 | | | 11/20/2009 6:55:46 AM | | | | |
|--------|------------------|---|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|-------------------------|--|--|--|--|--|--|--|
| Castillo, Carlos | | NEED TO REPLACE BALLAST | | | | | | | |
|------------------|--|-------------------------|--|--|--|--|--|--|--|

David Acosta

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Desert Pride

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52856 | | | | | 11/20/2009 | | 46 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/20/2009 10:55:07 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Munoz, Michael Room 14 & 15 - (By Julies MH) - There is a crack in the ceiling, needs to be checked.

Juan Acosta

| | | | | | | | | | |
|-------|--|-----------|--|--|------------|--|----|--|--------|
| 52890 | | Classroom | | | 11/23/2009 | | 43 | | \$0.00 |
|-------|--|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|---|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | 9 | | | 11/23/2009 11:09:10 | | | | |
|--------|------------------|---|--|--|---------------------|--|--|--|--|

Lara, Ralph DOOR HINGE SCREWS KEEP COMING LOOSE.

David Acosta

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53171 | | | | | 12/4/2009 | | 32 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|
| High | Work In Progress | | | | 12/4/2009 2:51:15 PM | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|

Munoz, Michael transfere morgan bldg from gms to desrtpride. for southern new mexico (vince ortega)

Alfredo Holguin

| | | | | | | | | | |
|------------------------------|--|--|----------------------------|--|--|-------------------------------|----------|--|---------------|
| Count: 11 Work Orders | | | Avg. Age of WO's 83 | | | Total for Desert Pride | 0 | | \$0.00 |
|------------------------------|--|--|----------------------------|--|--|-------------------------------|----------|--|---------------|

Location: Desert Trail Intermediate

| | | | | | | | | | |
|-------|--|--|--|--|----------|-----------|-----|--|--------|
| 47151 | | | | | 7/5/2009 | 7/26/2009 | 184 | | \$0.00 |
|-------|--|--|--|--|----------|-----------|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/5/2009 12:21:20 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Orozco, Danny Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47596 | | | | | 7/16/2009 | | 173 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/16/2009 4:17:50 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Estrada, Jesus NEED TO REPLACE CARPETS IN ROOMS 202, 212 & 100. 7/16/09 - FAXED - MIKE, PLEASE QUOTE EACH ROOM SEPERATELY.

Jesus Estrada

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47932 | | | | | 7/28/2009 | | 161 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/28/2009 2:32:25 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Gonzales, Angel Need to borrow 'Bobcat for Desert Trail Elementary.

Johnny Acuna

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50520 | | | | | 9/25/2009 | | 102 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/25/2009 10:31:09 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Joe Need replace all water faucet (custodial clossets) for all the building.

Marisela Torres

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Desert Trail Intermediate

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50867 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:00 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|---------------|--|---|--|--|--|--|--|--|--|
| Orozco, Danny | | Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | |
|---------------|--|---|--|--|--|--|--|--|--|

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50874 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:03 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Orozco, Danny | | Monthly - Desert Trail Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50933 | | | | | 10/4/2009 | 10/12/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:26 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Acuna, Johnny | | Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details. | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 51154 | | | | | 10/7/2009 | | 90 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/7/2009 7:49:11 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|
| Gonzales, Angel | | Work Truck #192 is not working. Truck will not start... (Desert Trail Elementary) | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|

Johnny Acuna

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 51178 | | | | | 10/7/2009 | | 90 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/7/2009 3:46:31 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|
| Gonzales, Angel | | (work truck not shifting gears) Something snapped inside the steering column and will not shift gears. (Truck is in back of the school grounds next to mobile home) | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|

Johnny Acuna

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51738 | | | | | 10/23/2009 | | 74 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/23/2009 3:46:22 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|
| Carrasco, Danny | | Need to borrow scissor lift to service heating units in the cafeteria. | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|

Johnny Acuna

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52041 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:53 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|---------------|--|---|--|--|--|--|--|--|--|
| Orozco, Danny | | Monthly - Desert Trail Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | |
|---------------|--|---|--|--|--|--|--|--|--|

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Desert Trail Intermediate

| | | | | | | | | | |
|-------|--|--|--|--|-----------|-----------|----|--|--------|
| 52078 | | | | | 11/1/2009 | 11/9/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|-----------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:23:06 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Acuna, Johnny Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 52237 | | | | | 11/3/2009 | | 63 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/3/2009 3:56:18 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ontiveros, Joe Please check boiler at Desert Trail for possible water leak. Thank you.

Guillermo Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53124 | | | | | 12/3/2009 | | 33 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/3/2009 12:10:10 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Holguin, Alfredo Prepare construction cost estimate and connection plans drawings to determine the most efficient way to connect the sewer system to the Dona Ana Couty's wastewater system.

Alfredo Holguin

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53125 | | | | | 12/3/2009 | | 33 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/3/2009 12:12:00 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Holguin, Alfredo Prepare construction cost estimate and connection plans drawings to determine the most efficient way to connect the sewer system to the Dona Ana Couty's wastewater system.

Alfredo Holguin

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 53253 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:45 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Acuna, Johnny Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53409 | | | | | 12/9/2009 | | 27 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/9/2009 8:43:12 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Sotelo, Enrique Need Electrical Bucket truck to replace security lamp light bulb, and also to replace rope on flag poles.

Johnny Acuna

| | | | | | | | | | |
|-------|--|--|--|--|------------|------------|----|--|--------|
| 53552 | | | | | 12/13/2009 | 12/29/2009 | 23 | | \$0.00 |
|-------|--|--|--|--|------------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/13/2009 12:18:54 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Acuna, Johnny Monthly - Desert Trail Playground Insp - Refer to PM schedule details.

Margret Villalobos

1/5/2010 12:27:03 PM

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| Location: | | Desert Trail Intermediate | | | | | | | |
|------------------------------|------------------|---|--|--|-----------------------|--|----|----------|---------------|
| 53572 | | | | | 12/14/2009 | | 22 | | \$0.00 |
| Medium | Work In Progress | | | | 12/14/2009 12:58:31 | | | | |
| Ontiveros, Joe | | Need to borrow floor snake to unclogg drain line to waterfountain located in the NW hall. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 53573 | | | | | 12/14/2009 | | 22 | | \$0.00 |
| Medium | Work In Progress | | | | 12/14/2009 1:02:01 PM | | | | |
| Gonzalez, Salvador | | Please re-weld wheel to cafeteria table. | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 53651 | | | | | 12/16/2009 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 12/16/2009 9:31:08 AM | | | | |
| Lozoya, Manny | | Room #205 (Mrs. Amato): Please re-key 1- storage cabinet, 1-Filing Cabinet, and Need an installation of a lock for another filing cabinet. Thank You..... | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| Count: 21 Work Orders | | Avg. Age of WO's 74 | | Total for Desert Trail Intermediate | | | | 0 | \$0.00 |

| Location: | | Desert View ES | | | | | | | |
|----------------------------|------------------|--|--|--|----------------------|----------|-----|--|--------|
| 47234 | | | | | 7/5/2009 | 8/5/2009 | 184 | | \$0.00 |
| Medium | Work In Progress | | | | 7/5/2009 12:21:50 AM | | | | |
| Ortiz, Ruben | | Yearly - Desert View ES Exit Sign Test: Annual - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 48953 | | Cafeteria | | | 8/18/2009 | | 140 | | \$0.00 |
| Medium | Work In Progress | | | | 8/18/2009 2:07:02 PM | | | | |
| Moncayo, Fernando | | DISHWASHER: 1) COLD WATER ONLY, 2) RINSE SPRAYER NOT WORKING | | | | | | | |
| DIANNA L. SNP MGR 589-2425 | | | | | | | | | |
| Jacqueline Aguilar | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Desert View ES

| | | | | | | | | | |
|-------|---------------|-----------|--|--|-----------|--|-----|--|--------|
| 49274 | Main Building | Classroom | | | 8/25/2009 | | 133 | | \$0.00 |
|-------|---------------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|------|------------------|--------|--|--|----------------------|--|--|--|--|
| High | Work In Progress | RM# 24 | | | 8/25/2009 4:26:51 PM | | | | |
|------|------------------|--------|--|--|----------------------|--|--|--|--|

Villalobos, David
Please fix shower in SPED room. The work order had been placed since last year and has not been fixed yet.

It is imperative to have this shower fixed as soon as possible. This room pertains to the Basic Life Skills Classroom.

Thank you,
Fernando Carrasco

Judy Garibay

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 49371 | | | | | 8/27/2009 | | 131 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/27/2009 2:14:07 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ortiz, Ruben
INSTALL BASKETBALL NETS. 2EA.

Ruben Ronquillo

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 49965 | | | | | 9/11/2009 | | 116 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|
| High | Work In Progress | | | | 9/11/2009 8:31:22 AM | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|

Marquez, Gerardo
need to build a fur-out for shower to accompany work order # 49274.

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 50608 | | | | | 9/28/2009 | | 99 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/28/2009 7:48:51 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Lara, Ralph
Westside wing room 34; hinges broken; the door is hard to open. Thank you, Ruben

Ruben Ortiz

| | | | | | | | | | |
|-------|--|-----------|--|--|-----------|--|----|--|--------|
| 50797 | | Cafeteria | | | 10/2/2009 | | 95 | | \$0.00 |
|-------|--|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/2/2009 2:14:46 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Orozco, Danny
ALL 4 LIGHTS TO THE SERVING LINE ON TOP ARE OFF.

DIANNE L. SNP MGR 589-2425

Jacqueline Aguilar

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50875 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:03 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny
Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | |
|------------------|-----------------------|
| Location: | Desert View ES |
|------------------|-----------------------|

| | | | | | | | | | |
|-------|--|-----------|--|--|------------|--|----|--|--------|
| 51975 | | Cafeteria | | | 10/30/2009 | | 67 | | \$0.00 |
|-------|--|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/30/2009 9:34:48 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny
OVEN IS DOWN AGAIN. ONLY WORKS WHEN IT WANTS TO.

DIANA L. SNP MGR 589-2425

Jacqueline Aguilar

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52042 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:54 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny
Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 52377 | | | | | 11/6/2009 | | 60 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Janitors Closet | | | 11/6/2009 1:50:54 PM | | | | |
|--------|------------------|-----------------|--|--|----------------------|--|--|--|--|

Ortiz, Ruben
Janitors Closet covered by sprinkler head. (might be missing the cover).

Ralph Gallegos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 52378 | | | | | 11/6/2009 | | 60 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Kitchen | | | 11/6/2009 1:51:52 PM | | | | |
|--------|------------------|---------|--|--|----------------------|--|--|--|--|

Ortiz, Ruben
Electrical panel in kitchen is blocked.

Ralph Gallegos

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52558 | | | | | 11/12/2009 | | 54 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/12/2009 10:10:41 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Ronquillo, Ruben
Vandalism; broken window on portable 4 room 6; double window; 30x30. Rock climbing board was partially burnt, Police report filed; case number 2009001765

Ruben Ortiz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53103 | | | | | 12/3/2009 | | 33 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/3/2009 8:19:30 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ortiz, Ruben
IN MECHANICAL ROOM IN CAFETERIA - NEED TO FIX ROOF LEAKING ON SMOKE DETECTOR CAUSING IT TO SHORT - CALL SILVER IN TECHNOLOGY IF YOU HAVE ANY QUESTIONS

Cora Ramirez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 53298 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:21:02 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ortiz, Ruben
Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|----------------------|------------------|--|--|--|-----------------------|------------|----|---------------|--------|
| Location: | | Desert View ES | | | | | | | |
| 53299 | | | | | 12/6/2009 | 12/12/2009 | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:21:03 AM | | | | |
| Ortiz, Ruben | | Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 53300 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:21:03 AM | | | | |
| Ortiz, Ruben | | Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 53301 | | | | | 12/6/2009 | | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:21:04 AM | | | | |
| Ortiz, Ruben | | Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 53364 | | | | | 12/7/2009 | | 29 | | \$0.00 |
| Medium | Work In Progress | | | | 12/7/2009 9:44:49 PM | | | | |
| Ortiz, Ruben | | 12/04/09 | | | | 12/4-8 | | Material 1.00 | |
| | | 2 hour delay due to inclement weather | | | | | | | |
| | | 1 1/2 hours directly traffic and informing parents that school was on a 3 hour delay not 2 hours | | | | | | | |
| | | 1 hour checking school grounds | | | | | | | |
| | | 1 1/2 hours clearing front entrance of school of ice | | | | | | | |
| | | 1 hour anchoring a white board; \$1.00 anchors | | | | | | | |
| | | 1 hour work log | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 53402 | | | | | 12/8/2009 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | | 12/8/2009 5:49:13 PM | | | | |
| Lara, Ralph | | The door on the new portable on the Westside was slammed with the hard winds both top and bottom hinges were damages and screws popped out. Need the door fixed or replaced ASAP. Thank you, Ruben | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 53424 | | | | | 12/9/2009 | | 27 | | \$0.00 |
| High | Work In Progress | | | | 12/9/2009 2:12:15 PM | | | | |
| Ontiveros, Guadalupe | | lupe as per our discussion, please repair fence and clean area on school property by the apartments. thank you | | | | | | | |
| Michael Munoz | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Desert View ES

| | | | | | | | | | |
|-------|--|-----------|--|--|------------|--|----|--|--------|
| 53517 | | Classroom | | | 12/11/2009 | | 25 | | \$0.00 |
|-------|--|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | PORT 2 | | | 12/11/2009 12:09:19 | | | | |
|--------|------------------|--------|--|--|---------------------|--|--|--|--|

Lara, Ralph
Mrs. Gallegos is having a very hard time closing and locking her door. Please help.

Thank you,
Judy

Judy Garibay

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53523 | | | | | 12/11/2009 | | 25 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/11/2009 2:25:18 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lara, Ralph
Door in portable 1 room 2; doesn't open or close right

Ruben Ortiz

| | | | | | | | | | |
|-------|--|--|--|--|------------|------------|----|--|--------|
| 53559 | | | | | 12/13/2009 | 12/29/2009 | 23 | | \$0.00 |
|-------|--|--|--|--|------------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/13/2009 12:18:57 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Ortiz, Ruben
Monthly - Desert View ES Playground Insp - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53598 | | | | | 12/14/2009 | | 22 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/14/2009 4:21:33 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Guadalupe
Remove bushes/weeds along fence by apartments, and trim Mesquite Tree.

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53683 | | | | | 12/16/2009 | | 20 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/16/2009 9:07:21 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Castillo, Carlos
The switch in the room of the gym for the coaches is broken, needs to be replaced. Thank you, Ruben

Ruben Ortiz

| | | | | | | | | | |
|------------------------------|--|--|----------------------------|--|--|---------------------------------|----------|--|---------------|
| Count: 26 Work Orders | | | Avg. Age of WO's 63 | | | Total for Desert View ES | 0 | | \$0.00 |
|------------------------------|--|--|----------------------------|--|--|---------------------------------|----------|--|---------------|

Location: GAC

| | | | | | | | | | |
|-------|--|--|--|--|----------|-----------|-----|--|--------|
| 47152 | | | | | 7/5/2009 | 7/26/2009 | 184 | | \$0.00 |
|-------|--|--|--|--|----------|-----------|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/5/2009 12:21:21 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Orozco, Danny
Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|------------------|--|-------------|-------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 48926 | | Parking Lot | | | 8/17/2009 | | 141 | | \$0.00 |
| Medium | Work In Progress | GAC PARKING | | | 8/17/2009 3:57:48 PM | | | | |
| Ambriz, Juan | | AS PER JUAN - NEED PAINT FOR THE PAINTING OF THE PARKING LOT LINES AT GAC. | | | | | | | |
| Mary Garcia | | | | | | | | | |
| 50169 | | | | | 9/16/2009 | | 111 | | \$0.00 |
| Medium | Work In Progress | | | | 9/16/2009 10:29:54 AM | | | | |
| Ambriz, Jose | | please replace heating/cooling unit in the board room .thanks (existing unit is old and needs replacement) | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 50254 | | | | | 9/18/2009 | | 109 | | \$0.00 |
| Medium | Work In Progress | vehicle #140 | | | 9/18/2009 2:31:10 PM | | | | |
| Gonzales, Angel | | Vehicle needs tune-up also transmission 4th gear not kicking in | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 50412 | | | | | 9/22/2009 | | 105 | | \$0.00 |
| Medium | Work In Progress | A/C units | | | 9/22/2009 3:54:41 PM | | | | |
| Ambriz, Juan | | As per juan Need to Install p-traps for condensation in all units | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 50802 | | | | | 10/2/2009 | | 95 | | \$0.00 |
| Medium | Work In Progress | Patio door | | | 10/2/2009 2:39:32 PM | | | | |
| Lara, Ralph | | Need to repair deadbolt in patio door | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 50868 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
| Medium | Work In Progress | | | | 10/4/2009 12:22:00 AM | | | | |
| Orozco, Danny | | Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 50888 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
| Medium | Work In Progress | | | | 10/4/2009 12:22:07 AM | | | | |
| Orozco, Danny | | Monthly - GAC Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: GAC

| | | | | | | | | | |
|-------|--|--------|--|--|-----------|--|----|--|--------|
| 51240 | | Office | | | 10/8/2009 | | 89 | | \$0.00 |
|-------|--|--------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | GAC | | | 10/8/2009 4:43:51 PM | | | | |
|--------|------------------|-----|--|--|----------------------|--|--|--|--|

Ambriz, Juan
AS PER NANCY- NEED TO HAVE THE EDGING OF HER DESK REPAIRED, BECAUSE IT IS SNAGGING HER CLOTHES.

Mary Garcia

| | | | | | | | | | |
|-------|--|-------------|--|--|-----------|--|----|--|--------|
| 51264 | | Parking Lot | | | 10/9/2009 | | 88 | | \$0.00 |
|-------|--|-------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/9/2009 2:39:16 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, David
Fire protection backflow preventer has an constant leak and needs to be repaired. Will need to make arrangements with Horizon Mechanical to fix the BFP

David Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51876 | | | | | 10/28/2009 | | 69 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | Back road | | | 10/28/2009 11:09:18 | | | | |
|--------|------------------|-----------|--|--|---------------------|--|--|--|--|

Ontiveros, Guadalupe
Need to repair back road near pool area

Juan Ambriz

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51892 | | | | | 10/28/2009 | | 69 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | kitchen | | | 10/28/2009 3:02:17 PM | | | | |
|--------|------------------|---------|--|--|-----------------------|--|--|--|--|

Ambriz, Jose
Need to reseal a/c unit in kitchen. Done by contractors didn't set correct causing leaks into the kitchen area. Needs to be picked up reseal and moved 1" forward

Juan Ambriz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52043 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:54 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny
Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52715 | | | | | 11/17/2009 | | 49 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/17/2009 1:58:11 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lozoya, Manny
Asp Mr. Chavez, please re-cut J3-Gate key for Selma Nevarez, she will drop off her old one w/Maria Ruiz.

Maria Ruiz

| | | | | | | | | | |
|-------|--|-------------|--|--|------------|--|----|--|--------|
| 52986 | | Parking Lot | | | 11/30/2009 | | 36 | | \$0.00 |
|-------|--|-------------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | Back road and | | | 11/30/2009 3:46:20 PM | | | | |
|--------|------------------|---------------|--|--|-----------------------|--|--|--|--|

Ontiveros, Guadalupe
Need to repair back road near pool area caused by running water from rains

Juan Ambriz

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-----------|-----------------------|------------------|-----------|---------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 52987 | | Parking Lot | | | 11/30/2009 | | 36 | | \$0.00 |
| Medium | Work In Progress | Bottom dirt | | | 11/30/2009 3:47:39 PM | | | | |
| Ontiveros, Guadalupe | | Need to level out bottom parking lot water accumulation after rains | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 53115 | | Office | | | 12/3/2009 | | 33 | | \$0.00 |
| Medium | Work In Progress | B-WING | | | 12/3/2009 11:08:08 AM | | | | |
| Rodriguez, Arturo | | AS PER JULIE-AFTER PARTITIONS ARE TAKEN DOWN WOULD LIKE TO HAVE FLOORS MOPPED. | | | | | | | |
| Mary Garcia | | | | | | | | | |
| 53554 | | | | | 12/13/2009 | 12/29/2009 | 23 | | \$0.00 |
| Medium | Work In Progress | | | | 12/13/2009 12:18:55 | | | | |
| Ambriz, Juan | | Monthly - GAC Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 53670 | Pre-K | Classroom | | | 12/16/2009 | | 20 | | \$0.00 |
| Medium | Work In Progress | PRE-K | | | 12/16/2009 2:18:01 PM | | | | |
| Rodriguez, Arturo | | AS PER MS. BERRY-NEED TO HAVE THE CARPETS CLEANED IN ALL PRE-K CLASSROOMS. | | | | | | | |
| Mary Garcia | | | | | | | | | |
| 53671 | Pre-K | | | | 12/16/2009 | | 20 | | \$0.00 |
| Medium | Work In Progress | PRE-K | | | 12/16/2009 2:25:31 PM | | | | |
| Rodriguez, Arturo | | AS PER MS. BERRY-NEED TO HAVE THE PLAYGROUNDS CLEANS. DIRT AND SAND IS ACCUMULATING IN THE CLASSROOM FRONT DOORS. | | | | | | | |
| Mary Garcia | | | | | | | | | |
| 53750 | | Library | | | 12/22/2009 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | | 12/22/2009 3:03:59 PM | | | | |
| Briones, Enrique | | Pick up box at Library Media Services with Rosa Hidalgo at GAC and deliver to Anthony Elementary Library with Patricia Marquez. | | | | | | | |
| Phillip Medina | | | | | | | | | |
| Count: 21 Work Orders | | Avg. Age of WO's | | 73 | Total for GAC | | 0 | \$0.00 | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|-----------------------------|------------------|---|--|------------|-----------------------------|--|-----|----------|---------------|
| Location: | | Gadsden ES | | | | | | | |
| 49424 | | | | | 8/28/2009 | | 130 | | \$0.00 |
| Medium | Work In Progress | | | | 8/28/2009 1:06:04 PM | | | | |
| Castillo, Carlos | | when possible, please go ahead and do a walk thru off the new gadsden elementary and write down any deficiencies found or that need to be addressed on the work order so that construction can take care off before completion. | | | | | | | |
| Michael Munoz | | | | | | | | | |
| Count: 1 Work Orders | | Avg. Age of WO's | | 130 | Total for Gadsden ES | | | 0 | \$0.00 |

| | | | | | | | | | |
|--------------------|------------------|--|--|--|-----------------------|--|-----|--|--------|
| Location: | | Gadsden HS | | | | | | | |
| 47097 | | | | | 7/5/2009 | | 184 | | \$0.00 |
| Medium | Work In Progress | | | | 7/5/2009 12:20:59 AM | | | | |
| Holguin, Alfredo | | Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 47387 | Boys Gym | Gym | | | 7/9/2009 | | 180 | | \$0.00 |
| Medium | Work In Progress | | | | 7/9/2009 3:14:42 PM | | | | |
| Ambriz, Jose | | NEED TOW NEW HEATING UNIT AT THE BOYS GYM | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 47398 | | | | | 7/9/2009 | | 180 | | \$0.00 |
| Medium | Work In Progress | | | | 7/9/2009 3:46:30 PM | | | | |
| Castillo, Carlos | | NEED TO SERVICE ALL OUTSIDE AND PARKING LOT LAMPS | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 47466 | Pool Dressing | | | | 7/13/2009 | | 176 | | \$0.00 |
| Medium | Work In Progress | | | | 7/13/2009 10:50:25 AM | | | | |
| Villalobos, David | | Requested by Velia for Girl's Restroom at the Swimming Pool-Water faucet for the sink is leaking water and causing it to pool at the bottom of the sink. Potential hazard. | | | | | | | |
| Velia Alarcon | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47556 | | | | | 7/15/2009 | | 174 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/15/2009 3:09:05 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ontiveros, Guadalupe Requested by Velia for G.H.S. Campus-All grass needs to be mowed and weeds pulled from entire campus. Weeds are growing along side the edges of sidewalks and between cracks in sidewalks. Please complete before Wed., July 29, 2009. Freshman Orientation will take place this day and many parents and students will be on our campus.

Velia Alarcon

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47816 | | | | | 7/24/2009 | | 165 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/24/2009 2:49:12 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ontiveros, Guadalupe Requested by Mr. Chambers for All G.H.S. Grounds- 2ND REQUEST-All grass needs to be mowed and weeds pulled from entire campus. Some weeds are almost 5 feet tall in areas. Please complete before Wed., July 29, 2009. Freshman Orientation will take place this day and many parents and students will be on our campus.

Velia Alarcon

| | | | | | | | | | |
|-------|---------------|--------|--|--|-----------|--|-----|--|--------|
| 47903 | Main Building | Office | | | 7/28/2009 | | 161 | | \$0.00 |
|-------|---------------|--------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/28/2009 7:58:49 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Castillo, Carlos Various fixtures in Main Building office area are in bad repair and need to be replaced. (2'x 4' lay-in style)

Albert Vallejo

| | | | | | | | | | |
|-------|----------------|------------------|--|--|-----------|--|-----|--|--------|
| 47937 | New Vocational | Hallway/Corridor | | | 7/28/2009 | | 161 | | \$0.00 |
|-------|----------------|------------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/28/2009 3:15:27 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ronquillo, Ruben need a new glass door at the annex bldg do to vandalism (28x38) wire glass

Mario Apodaca

| | | | | | | | | | |
|-------|--|--|--|--|----------|--|-----|--|--------|
| 48421 | | | | | 8/6/2009 | | 152 | | \$0.00 |
|-------|--|--|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/6/2009 9:09:40 AM | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Munoz, Michael Requested by Ms. Arredondo Rm. 550 Wood Shop- Redo table tops, 9 sheets of masanate are needed for this.

Velia Alarcon

| | | | | | | | | | |
|-------|---------------|--|--|--|----------|--|-----|--|--------|
| 48436 | Main Building | | | | 8/6/2009 | | 152 | | \$0.00 |
|-------|---------------|--|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/6/2009 11:52:46 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Castillo, Carlos Requested by Mr. Marquez Rm. 240 Main Building- An electrical outlet is not working by teacher desk (counter).

Velia Alarcon

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

48438 8/6/2009 152 \$0.00

Medium Work In Progress 8/6/2009 12:01:38 PM

Ontiveros, Guadalupe Requested by Coach Yanez for Baseball Field-Extend home dugout with a 4' fence. Already spoke with Lupe Ontiveros who said materials are in the Grounds Storage Facilities.

Velia Alarcon

48439 8/6/2009 152 \$0.00

Medium Work In Progress 8/6/2009 12:05:41 PM

Aldaz, Bobby Requested by Coach Yanez for Baseball Field-Cut out a new warning track along 3rd base side and 1st base side of the baseball field. Already spoke with Bob Aldaz about the cut and he requested I put in a work order.

Velia Alarcon

48639 Old English Bldg 8/11/2009 147 \$0.00

Medium Work In Progress 8/11/2009 10:36:58 AM

Lara, Ralph Requested by Ms. Letz Rm. 155 Old English Building-The equipment room door needs to be fixed in the locker room.

Velia Alarcon

48640 Old English Bldg 8/11/2009 147 \$0.00

Medium Work In Progress 8/11/2009 10:38:12 AM

Lara, Ralph Requested by Ms. Letz Rm. 155 Old English Building-The door between locker room and gym will not lock properly, needs to be secured.

Velia Alarcon

48645 Athletic Field 8/11/2009 147 \$0.00

Medium Work In Progress 8/11/2009 11:21:53 AM

Aldaz, Bobby Need to replace front tires on Kubota Tractor

Guadalupe Ontiveros

48672 Boys Gym Office 8/11/2009 147 \$0.00

Medium Work In Progress 8/11/2009 3:30:19 PM

Ambriz, Jose need a new a/c window unit for the boys gym office 400

Mario Apodaca

48677 Vocational Hallway/Corridor 8/11/2009 147 \$0.00

Medium Work In Progress 8/11/2009 3:43:45 PM

Lara, Ralph need a exterior door hinge

Mario Apodaca

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|-------|----------------|-----------|--|--|-----------|--|-----|--|--------|
| 48739 | North Building | Classroom | | | 8/12/2009 | | 146 | | \$0.00 |
|-------|----------------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/12/2009 3:14:47 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, David need a new faucets for room 222 n-bldg 4"spreader unit

Mario Apodaca

| | | | | | | | | | |
|-------|--|------------------|--|--|-----------|--|-----|--|--------|
| 48741 | | Restroom (Girls) | | | 8/12/2009 | | 146 | | \$0.00 |
|-------|--|------------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/12/2009 3:23:50 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, David need new sink faucets put new in all of the restroom boys,girls and locker rooms

Mario Apodaca

| | | | | | | | | | |
|-------|------------------|---------------|--|--|-----------|--|-----|--|--------|
| 48945 | Old English Bldg | Dressing Room | | | 8/18/2009 | | 140 | | \$0.00 |
|-------|------------------|---------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/18/2009 12:18:04 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lara, Ralph NEED TWO NEW DOOR FOR THE DRESSING ROOM AND LOCK SET.

Mario Apodaca

| | | | | | | | | | |
|-------|---------------|--|--|--|-----------|--|-----|--|--------|
| 48982 | Main Building | | | | 8/18/2009 | | 140 | | \$0.00 |
|-------|---------------|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Computer Lab | | | 8/18/2009 4:39:59 PM | | | | |
|--------|------------------|--------------|--|--|----------------------|--|--|--|--|

Castillo, Carlos Requested by Mr. Chambers for Rm. 121 Main Building- More power amperage is needed in room # 121. Breakers are tripping due to overload. A computer lab is being operated in this class room.

Velia Alarcon

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 48983 | | | | | 8/18/2009 | | 140 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/18/2009 4:43:08 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Castillo, Carlos Requested by Velia for All Light Fixture Around the Boy's Gym-All light fixtures or light bulbs need to be checked, repaired, or replaced. Verydark especially on the west side of the gym where the Football players exist to go home after games.

Velia Alarcon

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 48985 | | | | | 8/18/2009 | | 140 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/18/2009 4:47:56 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ronquillo, Ruben Requested by Ms. Leahy Rm. 127 Main Building-Please install mini-blinds in my classroom. Need (2) 106' W X 35' L

Velia Alarcon

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|-----------------------------|------------------|--|--|--|-----------------------|--|-----|--|--------|
| Location: Gadsden HS | | | | | | | | | |
| 49154 | | | | | 8/21/2009 | | 137 | | \$0.00 |
| Medium | Work In Progress | | | | 8/21/2009 3:57:52 PM | | | | |
| Castillo, Carlos | | Requested by Velia for Bus Turn Around-Replace all the light bulbs on the bus turn around. It is very dark in the evening when parents or students are walking the student parking lot where their vehicles are parked. Very dark and could be a safety issue. If possible install light posts on the west side of the bus turn around. This will help parents drive in through the bus turn around to pick up their child(ren) after an athletic event or field trip late at night. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 49928 | | | | | 9/10/2009 | | 117 | | \$0.00 |
| Medium | Work In Progress | | | | 9/10/2009 12:29:10 PM | | | | |
| Villalobos, David | | NEED TO PUT A NEW HOSEBIB OUTSIDE THE ANNEX BLDG | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 50011 | | | | | 9/11/2009 | | 116 | | \$0.00 |
| Medium | Work In Progress | | | | 9/11/2009 3:41:53 PM | | | | |
| Lara, Ralph | | Requested by Ms. Moreno Rm. 126 Main Building- WORK ORDER # 38294 HAS NOT BEEN COMPLETED-SECOND WORK ORDER-The door has fallen and hard to close. The door also gets stuck and students can not get exit classroom. This is a problem during fire drills. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 50273 | Business | Classroom | | | 9/18/2009 | | 109 | | \$0.00 |
| Medium | Work In Progress | | | | 9/18/2009 3:54:13 PM | | | | |
| Castillo, Carlos | | in rm 603, mr grace, the light switch controls the outlet to the computer and shuts off computer when switch is turned off, also the outlets on the north and west wall do not work. could you please check and correct. thanks | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 50281 | | | | | 9/20/2009 | | 107 | | \$0.00 |
| Medium | Work In Progress | | | | 9/20/2009 12:18:49 AM | | | | |
| Ontiveros, Guadalupe | | Monthly - Gadsden HS Soil Sampling - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

50320 Business Hallway/Corridor 9/21/2009 106 \$0.00

Medium Work In Progress 9/21/2009 12:43:20 PM

Gonzalez, Salvador NEED TO WELD THE DOOR HINGE TO A DOOR FRAME AT THE BUS BLDG BOT FLOOR S/SIDE

Mario Apodaca

50324 9/21/2009 106 \$0.00

Medium Work In Progress 9/21/2009 1:50:22 PM

Vallejo, Albert NEED TO REPAIR SOFFITT ??? (OVERHANG) BY MAIN BUILDING ON SOUTH SIDE OF BLDG.

Michael Munoz

50365 9/22/2009 105 \$0.00

Medium Work In Progress 9/22/2009 9:19:30 AM

Apodaca, Mario Requested by Mr. Grace on behalf of the Facilities Goal Team for the Entire Campus-Metal doors, rails, and poles need to be painted maroon.

Velia Alarcon

50392 9/22/2009 105 \$0.00

Medium Work In Progress 9/22/2009 2:47:00 PM

Ontiveros, Guadalupe Requested by Coach A. Lopez for Varsity Softball Field- Replace/fit/adjust back stalk fence. Top and bottom sections bent - open.

Velia Alarcon

50494 9/24/2009 103 \$0.00

Medium Work In Progress 9/24/2009 3:11:36 PM

Munoz, Michael Fence in north field has been knocked down and stretched to the point that it will no longer be tall enough to be refastened. Needs to be replaced. Approximately 6' x 120' chain link.

Albert Vallejo

50639 Vocational Classroom 9/29/2009 98 \$0.00

Medium Work In Progress 9/29/2009 2:15:40 PM

Castillo, Carlos As per M.Munoz ,several receptacles in room 603 are not working.Need to corrct situation.

Carlos Castillo

50669 9/30/2009 97 \$0.00

Medium Work In Progress 9/30/2009 12:23:03 AM

Apodaca, Mario Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PMSchedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|-------|---------------|----------|--|--|-----------|--|----|--|--------|
| 50725 | Main Building | Restroom | | | 10/1/2009 | | 96 | | \$0.00 |
|-------|---------------|----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/1/2009 10:23:23 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Villalobos, David
two problems, at the main bldg. one sink leaks at the trap, next problem is at the cafeteria girls restroom the toilet leaks when flushed at the base we have sealed shut the entrance to this toilet

Joe Munoz

| | | | | | | | | | |
|-------|----------|---------------|--|--|-----------|--|----|--|--------|
| 50777 | Boys Gym | Dressing Room | | | 10/2/2009 | | 95 | | \$0.00 |
|-------|----------|---------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/2/2009 10:55:35 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lara, Ralph
THE BOYS GYM NEED #2 ENTRANCE DOOR ON THE W/SIDE OF THE BLDG TO ROOM 412,404 DO TO VANDALISM

Mario Apodaca

| | | | | | | | | | |
|-------|------------------|---------------|--|--|-----------|--|----|--|--------|
| 50778 | Old English Bldg | Dressing Room | | | 10/2/2009 | | 95 | | \$0.00 |
|-------|------------------|---------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/2/2009 10:59:32 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lara, Ralph
NEED A NEW ENTRANCE DOOR TO THE GIRLS LOCKER ROOM IN GYM DO TO VANDALISM

Mario Apodaca

| | | | | | | | | | |
|-------|---------------|------------|--|--|-----------|--|----|--|--------|
| 50779 | Main Building | Pump House | | | 10/2/2009 | | 95 | | \$0.00 |
|-------|---------------|------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/2/2009 11:10:29 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Guadalupe
AS PER MR. CHAMBERS NEED ALL PLAYGROUND BY THE PUMP HOUSE MOVE TO ANTHONY ELEM PRE.K

Mario Apodaca

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 50832 | | | | | 10/4/2009 | | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:21:47 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Holguin, Alfredo
Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50876 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:03 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny
Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|----------------|--|--|-----------|--|----|--|--------|
| 51036 | | Athletic Field | | | 10/5/2009 | | 92 | | \$0.00 |
|-------|--|----------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Grounds | | | 10/5/2009 9:36:35 AM | | | | |
|--------|------------------|---------|--|--|----------------------|--|--|--|--|

Gonzales, Angel
Goose neck trailer needs two tires to be replaced. 7.50-16LT

Guadalupe Ontiveros

1/5/2010 12:27:03 PM

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 51038 | | | | | 10/5/2009 | | 92 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/5/2009 9:46:29 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, David Requested by Ms. Letz Rm. 155 Girl's Gym-Sinks have leaks in girl's locker room, the pipe under the right hand sink leaks and both faucets do not always turn off by themselves.

Velia Alarcon

| | | | | | | | | | |
|-------|---------------|--|--|--|-----------|--|----|--|--------|
| 51040 | Academic Bldg | | | | 10/5/2009 | | 92 | | \$0.00 |
|-------|---------------|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/5/2009 10:07:03 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lara, Ralph Requested by Ms. Hamilton Rm. 562 Ag. Shop-The door to office needs hindge repair and the lock to the office is stiff.

Velia Alarcon

| | | | | | | | | | |
|-------|---------|---------|--|--|-----------|--|----|--|--------|
| 51110 | Library | Library | | | 10/6/2009 | | 91 | | \$0.00 |
|-------|---------|---------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/6/2009 8:58:05 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Lara, Ralph NEED NWE EXIT DEVICES FOR ALL THE DOOR AT THE LIBRARY

Mario Apodaca

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 51113 | | | | | 10/6/2009 | | 91 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/6/2009 9:01:49 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, David NEED #20 4-INONE SILLCOCK KEY FOR THE CUSTODIAL

Mario Apodaca

| | | | | | | | | | |
|-------|------------------|-----------|--|--|-----------|--|----|--|--------|
| 51183 | Cafeteria (1998) | Cafeteria | | | 10/7/2009 | | 90 | | \$0.00 |
|-------|------------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|
| High | Work In Progress | | | | 10/7/2009 4:28:40 PM | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|

Vallejo, Albert lighting above serving lines where students receive there food are either missing the covers or need the wrap around light bulps. could you please order and repair.thanks

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 51255 | | | | | 10/9/2009 | | 88 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/9/2009 12:18:56 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lara, Ralph need the top pivot hinge for the doors

Mario Apodaca

| | | | | | | | | | |
|-------|--|--|--|--|------------|------------|----|--|--------|
| 51311 | | | | | 10/11/2009 | 10/27/2009 | 86 | | \$0.00 |
|-------|--|--|--|--|------------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/11/2009 12:19:30 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Munoz, Joe Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PMschedule details.

Jesus Estrada

1/5/2010 12:27:03 PM

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51531 | | | | | 10/20/2009 | | 77 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/20/2009 12:19:28 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Apodaca, Mario
Requested by Mr. Contaldo-Move projection screen and mounting brackets from room 223 to room 103. Then move screen from 103 to 223.

Velia Alarcon

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51536 | | | | | 10/20/2009 | | 77 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/20/2009 2:14:51 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Guadalupe
Requested by Mr. Chambers for Steele Panther in Front of School-Move panther at an angle and place higher than street level and a light needs to be placed at its base. Perhaps a solar light might be used and see Mr. Chambers for additional information.

Velia Alarcon

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51598 | | | | | 10/21/2009 | | 76 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/21/2009 3:36:03 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Sanchez, Raul
Need line location on south road between Irrigation well and treatment plant.

Albert Vallejo

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51625 | | | | | 10/22/2009 | | 75 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|------------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | Band truck | | | 10/22/2009 9:16:53 AM | | | | |
|--------|------------------|------------|--|--|-----------------------|--|--|--|--|

Gonzales, Angel
complete vehicle service on band truck # 128

Angel Gonzales

| | | | | | | | | | |
|-------|----------|--|--|--|------------|--|----|---|------------|
| 51796 | Business | | | | 10/26/2009 | | 71 | 3 | \$1,818.50 |
|-------|----------|--|--|--|------------|--|----|---|------------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/26/2009 4:13:16 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Munoz, Michael
lockers where rmoved and asbestos tile is beneath. need to remove and also remove acm tile under lockers that are still there lower bldg. ASBESTOS WAS REMOVED DURING THANKSGIVING BREAK

Michael Munoz

| | | | | | | | | | |
|-------|--------------|--------------|--|--|------------|--|----|--|--------|
| 51886 | Grounds Shop | Lift Station | | | 10/28/2009 | | 69 | | \$0.00 |
|-------|--------------|--------------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/28/2009 2:20:07 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Sanchez, Raul
Procurement of supplies needed for the daily operation & maintenance of the GHS wastewater treatment plant & lift stations

Raul Sanchez

| | | | | | | | | | |
|-------|------------------|--|--|--|------------|--|----|--|--------|
| 51993 | Old English Bldg | | | | 10/30/2009 | | 67 | | \$0.00 |
|-------|------------------|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/30/2009 3:14:58 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Villalobos, David
Please bring connector crimper to install 1/2" ball valve on rooftop copper water line.

Albert Vallejo

1/5/2010 12:27:03 PM

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|-----------------------|------------|----|--|--------|
| Location: | | Gadsden HS | | | | | | | |
| 52044 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
| Medium | Work In Progress | | | | 11/1/2009 12:22:55 AM | | | | |
| Orozco, Danny | | Monthly- Gadsden HS Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 52133 | | | | | 11/2/2009 | | 64 | | \$0.00 |
| Medium | Work In Progress | | | | 11/2/2009 10:48:26 AM | | | | |
| Villalobos, David | | need to re-location all utilities on the new bldg site | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 52188 | Varsity Gym | | | | 11/3/2009 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | | 11/3/2009 9:29:04 AM | | | | |
| Castillo, Carlos | | Requested by Mr. Marquez Rm. 244 Classroom over Varsity Gym - There is an electrical short by the chalk board and my table. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 52442 | Agricultural | Classroom | | | 11/9/2009 | | 57 | | \$0.00 |
| Medium | Work In Progress | 568 | | | 11/9/2009 11:20:51 AM | | | | |
| Castillo, Carlos | | Need to install a new circuit for exhaust fan. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 52443 | Boys Gym | Office | | | 11/9/2009 | | 57 | | \$0.00 |
| Medium | Work In Progress | 400 | | | 11/9/2009 11:22:55 AM | | | | |
| Castillo, Carlos | | Need to supply power to heat pump/ A/C for office. | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 52451 | Auto Shop | | | | 11/9/2009 | | 57 | | \$0.00 |
| Medium | Work In Progress | | | | 11/9/2009 2:12:36 PM | | | | |
| Apodaca, Mario | | Requested by Mr. Enriquez Rm. 580 Auto Shop - Crane needs to be re-located to center of shop. Crane will also be used for loading bearing components. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 52452 | Auto Shop | | | | 11/9/2009 | | 57 | | \$0.00 |
| Medium | Work In Progress | | | | 11/9/2009 2:14:05 PM | | | | |
| Villalobos, David | | Requested by Mr. Enriquez Rm. 580 Auto Shop - Eye wash station leaks. | | | | | | | |
| Velia Alarcon | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

52453 Auto Shop 11/9/2009 57 \$0.00

Medium Work In Progress 11/9/2009 2:16:23 PM

Lara, Ralph Requested by Mr. Enriquez Rm. 580 Auto Shop-Door lock needs to be changed so only teacher and administration have key, reason for change theft.

Velia Alarcon

52454 11/9/2009 57 \$0.00

Medium Work In Progress 11/9/2009 2:19:19 PM

Ontiveros, Guadalupe Requested by Coach Hite for Football Practice Field-Water two days a week "M" and "W", 20 minutes each station.

Velia Alarcon

52503 Football Stadium Athletic Field 11/10/2009 56 \$0.00

Medium Work In Progress 11/10/2009 8:57:13 AM

Castillo, Carlos NEED REPLACE CIRUIT BREAKER BOX FOR THE BACK PLAYING FIELDS

Mario Apodaca

52574 Business Classroom 11/12/2009 54 \$0.00

Medium Work In Progress 11/12/2009 3:02:28 PM

Ambriz, Jose NEED A NEW POTENTIAL RELAY FOR THE HEATING UNIT AT BUS BLDG ROOM 660

Mario Apodaca

52629 11/14/2009 52 \$0.00

Medium Work In Progress 11/14/2009 12:19:29

Sanchez, Raul Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.

Margret Villalobos

52665 Agricultural 11/16/2009 50 \$0.00

Medium Work In Progress 11/16/2009 2:50:51 PM

Lara, Ralph Requested by Ms. Hartmann Rm. 568 Ag. Shop-Outside door lock is difficult to open, it will sometimes stick. Please check key cylinder.

Velia Alarcon

52716 Agricultural 11/17/2009 49 \$0.00

Medium Work In Progress 11/17/2009 2:06:55 PM

Lara, Ralph NEED TO RE-KEY THE A.G SHOP, WOOD SHOP, AUTO SHOP PER MR CHAMBERS. A.S.A.P.

Mario Apodaca

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|-------|---------------|--|--|--|------------|--|----|--|--------|
| 52922 | Academic Bldg | | | | 11/24/2009 | | 42 | | \$0.00 |
|-------|---------------|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/24/2009 10:59:39 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Lara, Ralph Requested by Ms. L. Chavez Rm. 325 Academic Building-Need cylinder lock in filing cabinet replaced.

Velia Alarcon

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52924 | | | | | 11/24/2009 | | 42 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/24/2009 11:07:13 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Apodaca, Mario Requested by Mr. Chambers - Paint panther in front of school black.

Velia Alarcon

| | | | | | | | | | |
|-------|---------------|--|--|--|------------|--|----|-----|---------|
| 52926 | Main Building | | | | 11/24/2009 | | 42 | 1.5 | \$77.50 |
|-------|---------------|--|--|--|------------|--|----|-----|---------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/24/2009 11:18:21 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Vallejo, Albert Requested by Velia Rm. 112 Main Building - Please replace a light bulb that has burned out in my office. REPLACED LAMPS

Velia Alarcon

| | | | | | | | | | |
|-------|------------------|-----------|--|--|-----------|--|----|--|--------|
| 53063 | Cafeteria (1998) | Cafeteria | | | 12/2/2009 | | 34 | | \$0.00 |
|-------|------------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/2/2009 2:57:28 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Moncayo, Fernando the zia signis out at cafe bldg

Mario Apodaca

| | | | | | | | | | |
|-------|--------------|--|--|--|-----------|--|----|--|--------|
| 53136 | Agricultural | | | | 12/3/2009 | | 33 | | \$0.00 |
|-------|--------------|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/3/2009 3:10:37 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Apodaca, Mario need paint ordered for restroom /hallway/classroom

Mario Apodaca

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 53200 | | | | | 12/6/2009 | 12/12/2009 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:25 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Munoz, Michael Monthly - Gadsden HS - Elevator (Monthly) - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 53206 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:28 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Vallejo, Albert Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|-----------------------|----------|----|--|--------|
| Location: | | Gadsden HS | | | | | | | |
| 53207 | | | | | 12/6/2009 | | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:20:28 AM | | | | |
| Vallejo, Albert | | Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 53208 | | | | | 12/6/2009 | 1/6/2010 | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:20:28 AM | | | | |
| Vallejo, Albert | | Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 53371 | Vocational | Classroom | | | 12/8/2009 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | | 12/8/2009 10:40:12 AM | | | | |
| Lara, Ralph | | i will be needing a key to be issued to the new custodian for the new intervention portable that is located next to the weight room | | | | | | | |
| Joe Munoz | | | | | | | | | |
| 53372 | Business | Custodial | | | 12/8/2009 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | | 12/8/2009 10:43:24 AM | | | | |
| Carbajal, Jimmy | | i have two red push carts that the front wheels have broken off | | | | | | | |
| Joe Munoz | | | | | | | | | |
| 53389 | Agricultural | Classroom | | | 12/8/2009 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | | 12/8/2009 3:38:01 PM | | | | |
| Ambriz, Jose | | need a new mechanical temperature control at the ag bldg walk-in- cooler | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 53460 | | | | | 12/10/2009 | | 26 | | \$0.00 |
| Medium | Work In Progress | | | | 12/10/2009 11:13:54 | | | | |
| Vallejo, Albert | | Requested by Mr. Pokluda for Weight Room-Replace all burned out light bulbs. Also replace all fallen or damaged ceiling tiles. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 53461 | | | | | 12/10/2009 | | 26 | | \$0.00 |
| Medium | Work In Progress | | | | 12/10/2009 11:17:49 | | | | |
| Apodaca, Mario | | Requested by Mr. Pokluda for Weight Room-Paint all graffiti that is on the siding of the Weight Room. Please paint, do not clean off. | | | | | | | |
| Velia Alarcon | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53462 | | | | | 12/10/2009 | | 26 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/10/2009 11:52:15 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Estrada, Jesus Requested by Mr. Pokluda for Weight Room-Wooden floors at weight lifting stations in the Weight Room need to be varnished. If possible before off season Football Weight Training.

Velia Alarcon

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53463 | | | | | 12/10/2009 | | 26 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/10/2009 11:54:14 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Lara, Ralph Requested by Mr. Pokluda for Weight Room-The north door of the Weight Room needs closer and frame repairs as soon as possible.

Velia Alarcon

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53494 | | | | | 12/10/2009 | | 26 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/10/2009 4:04:40 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Apodaca, Mario Requested by Mr. Chambers for Canopy Outside of Cafeteria-WORK ORDER # 44117 HAS NOT BEEN COMPLETED-Due to the high wind gust recently the canopy is currently in worse condition. Remove canopy permanently. Sal will look into putting metal roof.

Velia Alarcon

| | | | | | | | | | |
|-------|------------------|--|--|--|------------|--|----|--|--------|
| 53511 | Cafeteria (1998) | | | | 12/11/2009 | | 25 | | \$0.00 |
|-------|------------------|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/11/2009 10:03:02 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Gonzalez, Salvador Requested by Mr. Chambers for Canopy Outside of Cafeteria-WORK ORDER # 44117 HAS NOT BEEN COMPLETED- Replace with a metal roof. Building Mechanics will remove canvas.

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53560 | | | | | 12/14/2009 | | 22 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/14/2009 12:18:33 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Sanchez, Raul Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|----------------|--|--|--|------------|--|----|--|--------|
| 53595 | Athletic Field | | | | 12/14/2009 | | 22 | | \$0.00 |
|-------|----------------|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/14/2009 3:54:03 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Flores, Pete Truck #122 fan clutch needs to be replaced.

Guadalupe Ontiveros

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|----------------------|------------------|--|--|--|-----------------------|--|----|---|---------|
| Location: | | Gadsden HS | | | | | | | |
| 53609 | | Portables | | | 12/15/2009 | | 21 | 2 | \$50.00 |
| Medium | Work In Progress | | | | 12/15/2009 10:46:55 | | | | |
| Lara, Ralph | | Intervention Portable - Need a key for cabinet (Please call Silver for Key #). | | | | | | | |
| Saenz Silver | | | | | | | | | |
| 53613 | | | | | 12/15/2009 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 12/15/2009 2:20:02 PM | | | | |
| Apodaca, Mario | | Requested by Ms. Holzhausen and Ms. Romero-Order gold and maroon paint for our North Building hall way. Also, set up scaffolding for painting. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 53614 | Auto Shop | | | | 12/15/2009 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 12/15/2009 2:21:43 PM | | | | |
| Lara, Ralph | | Requested by Mr. Enriquez Rm. 580 for Auto Shop-Classroom door will not open. | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 53615 | | | | | 12/15/2009 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 12/15/2009 2:25:08 PM | | | | |
| Ontiveros, Guadalupe | | Requested by Coach Lopez for Softball Fields-Move pitching plates back to 43 ft., new N.M.A.A. change both fields (Varsity and J.V.). | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 53616 | | | | | 12/15/2009 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 12/15/2009 2:27:42 PM | | | | |
| Ontiveros, Guadalupe | | Requested by Coach Lopez for Softball Concession Stand-Ramp of dirt, built up in front of concession stand. (to low) (fill dirt) | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 53617 | | | | | 12/15/2009 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 12/15/2009 2:30:20 PM | | | | |
| Villalobos, David | | Requested by Velia Rm. 580 Auto Shop-WORK ORDER # 52452 HAS NOT BEEN COMPLETED-Eye wash station still continues to leak. | | | | | | | |
| Velia Alarcon | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53634 | | | | | 12/15/2009 | | 21 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/15/2009 3:48:55 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Villalobos, David
Need to replace the commode in the boys restroom of the weight room. The tank fills, but will not drain fast enough to make the toilet flush, even when water is forced past the flapper assembly.

Albert Vallejo

| | | | | | | | | | |
|-------|--|----------------|--|--|------------|--|---|--|--------|
| 53646 | | Athletic Field | | | 12/16/2009 | | 0 | | \$0.00 |
|-------|--|----------------|--|--|------------|--|---|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|------------|--|--|--|
| Medium | Work In Progress | | | | 12/16/2009 8:44:52 AM | 12/16/2009 | | | |
|--------|------------------|--|--|--|-----------------------|------------|--|--|--|

Flores, Pete
Ford F-250 #25 Carbon pump is stock, needs to be replaced.

Guadalupe Ontiveros

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53749 | | | | | 12/20/2009 | | 16 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/20/2009 12:18:39 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Ontiveros, Guadalupe
Monthly - Gadsden HS Soil Sampling - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|------------------------------|--|--|----------------------------|--|--|--|-----------------------------|------------|-------------------|
| Count: 99 Work Orders | | | Avg. Age of WO's 83 | | | | Total for Gadsden HS | 6.5 | \$1,946.00 |
|------------------------------|--|--|----------------------------|--|--|--|-----------------------------|------------|-------------------|

Location: Gadsden MS

| | | | | | | | | | |
|-------|--------|-----------|--|--|-----------|--|-----|--|--------|
| 47542 | C-Wing | Portables | | | 7/15/2009 | | 174 | | \$0.00 |
|-------|--------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/15/2009 7:05:10 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Lozoya, Manny
Athletic Portable - Need to install a mail slot for vehicle packets to be dropped.

Priscilla Guiterrez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47893 | | | | | 7/27/2009 | | 162 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Staff | | | 7/27/2009 4:56:25 PM | | | | |
|--------|------------------|-------|--|--|----------------------|--|--|--|--|

Lozoya, Manny
Set up doors in Staff Restrooms. See Mrs. Williams for more information.

Maricruz Carrasco

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 48042 | | | | | 7/30/2009 | | 159 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/30/2009 12:46:38 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Estrada, Jesus
ROOM 156 (CONTAINS ASBESTOS) NEEDS VCT REPLACED - PRIORITY FAXED TO MICHAEL - 7/30/09

Richard Chavez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden MS

| | | | | | | | | | |
|-------|--------|--|--|--|-----------|--|---|--|--------|
| 49011 | C-Wing | | | | 8/19/2009 | | 0 | | \$0.00 |
|-------|--------|--|--|--|-----------|--|---|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|-----------------------|--|-----------|--|--|--|
| Medium | Work In Progress | | | 8/19/2009 11:35:15 AM | | 8/19/2009 | | | |
|--------|------------------|--|--|-----------------------|--|-----------|--|--|--|

Sotelo, Enrique
Need to check all lighting exit/emergeny lighting throughout bldg a/s/a/p.

Michael Munoz

| | | | | | | | | | |
|-------|--------|--|--|--|-----------|--|-----|--|--------|
| 49060 | C-Wing | | | | 8/20/2009 | | 138 | | \$0.00 |
|-------|--------|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|----------------------|--|--|--|--|--|
| Medium | Work In Progress | | | 8/20/2009 8:43:26 AM | | | | | |
|--------|------------------|--|--|----------------------|--|--|--|--|--|

Ontiveros, Guadalupe
Between C-Wing and GMS West Parking Lot need to level out with gravel. (See Mike)

Michael Munoz

| | | | | | | | | | |
|-------|--------|-----------|--|--|-----------|--|-----|--|--------|
| 49482 | C-Wing | Portables | | | 8/31/2009 | | 127 | | \$0.00 |
|-------|--------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|-----------------------|--|--|--|--|--|
| Medium | Work In Progress | | | 8/31/2009 10:55:19 AM | | | | | |
|--------|------------------|--|--|-----------------------|--|--|--|--|--|

Lozoya, Manny
The outside door handle is broken. Can't unlock it. Thanks Colleen

Colleen Runyan

| | | | | | | | | | |
|-------|-----|--------|--|--|-----------|--|-----|--|--------|
| 50377 | Gym | Office | | | 9/22/2009 | | 105 | | \$0.00 |
|-------|-----|--------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------------|--|-----------------------|--|--|--|--|--|
| Medium | Work In Progress | Boys lockerroom | | 9/22/2009 12:46:51 PM | | | | | |
|--------|------------------|-----------------|--|-----------------------|--|--|--|--|--|

Lozoya, Manny
Change lock in PE equipment room to be able to open with master.

Maricruz Carrasco

| | | | | | | | | | |
|-------|--------|-----------|--|--|-----------|--|-----|--|--------|
| 50397 | C-Wing | Portables | | | 9/22/2009 | | 105 | | \$0.00 |
|-------|--------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------|--|----------------------|--|--|--|--|--|
| Medium | Work In Progress | ATHLETICS | | 9/22/2009 3:10:55 PM | | | | | |
|--------|------------------|-----------|--|----------------------|--|--|--|--|--|

Lara, Ralph
TO FIX INSIDE HINGE FOR SAFE IN ATHLETIC OFFICE. NEED TO SECURE VEHICLE KEYS AND OTHER ITEMS.

Terry Alvarado

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50877 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|-----------------------|--|--|--|--|--|
| Medium | Work In Progress | | | 10/4/2009 12:22:04 AM | | | | | |
|--------|------------------|--|--|-----------------------|--|--|--|--|--|

Orozco, Danny
Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52045 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|-----------------------|--|--|--|--|--|
| Medium | Work In Progress | | | 11/1/2009 12:22:55 AM | | | | | |
|--------|------------------|--|--|-----------------------|--|--|--|--|--|

Orozco, Danny
Monthly - Gadsden MS Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|--|--|--|-----------------------|--|----|--|--------|
| Location: | | Gadsden MS | | | | | | | |
| 52295 | | | | | 11/5/2009 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | | 11/5/2009 8:12:24 AM | | | | |
| Lozoya, Manny | | In the gym restrooms doors need to install door knob with key thank you | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 52326 | | | | | 11/5/2009 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | | 11/5/2009 3:21:51 PM | | | | |
| Ontiveros, Joe | | Need to check custodian closer small bad in B wing thank you | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 52566 | | | | | 11/12/2009 | | 54 | | \$0.00 |
| Medium | Work In Progress | | | | 11/12/2009 1:29:23 PM | | | | |
| Gonzalez, Salvador | | Build fence by bus turnaround (See Sebas). | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 52628 | Vocational | Classroom | | | 11/13/2009 | | 53 | | \$0.00 |
| Medium | Work In Progress | Vocational/307/ | | | 11/13/2009 4:38:21 PM | | | | |
| Maricruz Carrasco | | Need items taken out of room: file cabinets, boards, ceiling in cage. Red security cabinet taken down. Move metal press against wall. Walls and cage painted. Remove bulletin board from wall. | | | | | | | |
| 52646 | | Portables | | | 11/16/2009 | | 50 | | \$0.00 |
| Medium | Work In Progress | | | | 11/16/2009 9:01:33 AM | | | | |
| Sotelo, Enrique | | Check if we have adequate power to hook up modular building. (portable next to band/truck room). | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 52687 | | Library | | | 11/16/2009 | | 50 | | \$0.00 |
| Medium | Work In Progress | Library/B. Paz | | | 11/16/2009 3:52:06 PM | | | | |
| Lozoya, Manny | | Key to front library door does not unlock the door. | | | | | | | |
| Maricruz Carrasco | | | | | | | | | |
| 52710 | Vocational | Mechanical | | | 11/17/2009 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | | 11/17/2009 10:54:48 | | | | |
| Solis, Lorenzø | | boiler on west side, having problems please check. | | | | | | | |
| Sebastian Diaz | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days | Labor | Total |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|------|-------|-------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | Aged | Hours | Costs |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden MS

| | | | | | | | | | |
|-------|-----------|--|--|--|------------|--|----|--|--------|
| 52769 | Gymnasium | | | | 11/18/2009 | | 48 | | \$0.00 |
|-------|-----------|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | Gym | | | 11/18/2009 2:50:34 PM | | | | |
|--------|------------------|-----|--|--|-----------------------|--|--|--|--|

Lozoya, Manny
Key Gym lobby faculty restroom with same key as room 600. Please see Connie for more details.

Maricruz Carrasco

| | | | | | | | | | |
|-------|--------|--|--|--|------------|--|----|--|--------|
| 52882 | C-Wing | | | | 11/20/2009 | | 46 | | \$0.00 |
|-------|--------|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | 207C | | | 11/20/2009 4:22:39 PM | | | | |
|--------|------------------|------|--|--|-----------------------|--|--|--|--|

Lara, Ralph
Outside Door handle is broken. 2nd request.
Thanks, Colleen

Colleen Runyan

| | | | | | | | | | |
|-------|-----------|-----------|--|--|------------|--|----|--|--------|
| 52954 | Cafeteria | Cafeteria | | | 11/30/2009 | | 36 | | \$0.00 |
|-------|-----------|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/30/2009 8:38:59 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Moncayo, Fernando
MILK COOLER IS DOWN.

Jacqueline Aguilar

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52969 | | | | | 11/30/2009 | | 36 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|-----------------------|--|--|--|--|
| High | Work In Progress | | | | 11/30/2009 1:37:30 PM | | | | |
|------|------------------|--|--|--|-----------------------|--|--|--|--|

Solis, Lorenz
heaters are not working on the 400 wing. could you please assist eric to repair problem. thank you

Michael Munoz

| | | | | | | | | | |
|-------|--------|--|--|--|-----------|--|----|--|--------|
| 53040 | C-Wing | | | | 12/1/2009 | | 35 | | \$0.00 |
|-------|--------|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/1/2009 3:57:03 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Sotelo, Enrique
Old Board Room (Portable)- Please install an elec wall heater in ladies restroom.

Alfredo Holguin

| | | | | | | | | | |
|-------|-----|---------------|--|--|-----------|--|----|--|--------|
| 53380 | Gym | Dressing Room | | | 12/8/2009 | | 28 | | \$0.00 |
|-------|-----|---------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Gym/Boys | | | 12/8/2009 1:20:57 PM | | | | |
|--------|------------------|----------|--|--|----------------------|--|--|--|--|

Ontiveros, Joe
Sink runs continuously. Water running non-stop. First sink going into bathroom.

Maricruz Carrasco

| | | | | | | | | | |
|-------|---------------|-----------|--|--|-----------|--|----|--|--------|
| 53412 | Main Building | Custodial | | | 12/9/2009 | | 27 | | \$0.00 |
|-------|---------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/9/2009 9:09:21 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Carbajal, Jimmy
WOULD LIKE TO ORDER TWO RAKES FOR G.M.S

Juan Acosta

| | | | | | | | | | |
|-------|--------|-----------|--|--|------------|--|----|--|--------|
| 53457 | C-Wing | Portables | | | 12/10/2009 | | 26 | | \$0.00 |
|-------|--------|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|-----|------------------|--|--|--|---------------------|--|--|--|--|
| Low | Work In Progress | | | | 12/10/2009 10:11:38 | | | | |
|-----|------------------|--|--|--|---------------------|--|--|--|--|

Solis, Lorenz
Old Computer Lab - Need to repair heater.

Michael Munoz

1/5/2010 12:27:03 PM

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden MS

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53561 | | | | | 12/14/2009 | | 22 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/14/2009 12:18:34 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Jacquez, Ricardo
Monthly - Gadsden MS-WWTP Chemical Order
(Monthly) - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|-----|-----------|--|--|------------|--|----|--|--------|
| 53599 | Gym | Classroom | | | 12/14/2009 | | 22 | | \$0.00 |
|-------|-----|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | Gym lobby and | | | 12/14/2009 4:26:54 PM | | | | |
|--------|------------------|---------------|--|--|-----------------------|--|--|--|--|

Lozoya, Manny
Door locks are through the inside and pose a chance of somebody getting locked in and no chance of getting out. Need replacement as soon as possible.

Maricruz Carrasco

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53631 | | | | | 12/15/2009 | | 21 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/15/2009 3:28:22 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Joe
In teacher lounge B wing sink is leak thank you

Sebastian Diaz

| | | | | | | | | | |
|-------|--|-----------|--|--|------------|--|----|--|--------|
| 53738 | | Portables | | | 12/18/2009 | | 18 | | \$0.00 |
|-------|--|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/18/2009 8:31:22 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lozoya, Manny
Portable- door is not closing (needs to be secured).

Judy Creegan

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53741 | | | | | 12/18/2009 | | 18 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/18/2009 10:07:12 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Diaz, Sebastian
According to Tom R. the leak in room 129 is on the old section and is the responsibility of GISD. Tom stated that he informed Sebastian.

Michael Munoz

| | | | | | | | | | |
|------------------------------|--|--|----------------------------|--|--|-----------------------------|----------|--|---------------|
| Count: 30 Work Orders | | | Avg. Age of WO's 63 | | | Total for Gadsden MS | 0 | | \$0.00 |
|------------------------------|--|--|----------------------------|--|--|-----------------------------|----------|--|---------------|

Location: La Union - JTP Alvarez Farms

| | | | | | | | | | |
|-------|--|------------------|--|--|-----------|--|-----|--|--------|
| 47763 | | Restroom (Girls) | | | 7/23/2009 | | 166 | | \$0.00 |
|-------|--|------------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/23/2009 9:39:55 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Lara, Ralph
Fix door to girls bathroom at LUJTP
Contact Person Sam Avalos or Margaret S. Villalobos

Margaret Villalobos

| | | | | | | | | | |
|-----------------------------|--|--|-----------------------------|--|--|---|----------|--|---------------|
| Count: 1 Work Orders | | | Avg. Age of WO's 166 | | | Total for La Union - JTP Alvarez Farms | 0 | | \$0.00 |
|-----------------------------|--|--|-----------------------------|--|--|---|----------|--|---------------|

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|--|--|--|-----------------------|------------|-----|--|--------|
| Location: | | La Union ES | | | | | | | |
| 50442 | | | | | 9/23/2009 | | 104 | | \$0.00 |
| Medium | Work In Progress | | | | 9/23/2009 1:53:41 PM | | | | |
| Aguilar, Patricio | | w.o. for myself - need covers for a/c winter close down | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 50878 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
| Medium | Work In Progress | | | | 10/4/2009 12:22:04 AM | | | | |
| Orozco, Danny | | Monthly - La Union ES Range Hood Cleaning - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 50984 | | | | | 10/4/2009 | 11/4/2009 | 93 | | \$0.00 |
| Medium | Work In Progress | | | | 10/4/2009 12:22:44 AM | | | | |
| Aguilar, Patricio | | Yearly - La Union ES I-4 Fan Coil Unit Yearly - Refer to PMschedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 51351 | | | | | 10/12/2009 | | 85 | | \$0.00 |
| Medium | Work In Progress | | | | 10/12/2009 3:46:49 PM | | | | |
| Aguilar, Patricio | | 10/12/09 5hr replace heater fliters 1hr work log | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 51378 | | | | | 10/13/2009 | | 84 | | \$0.00 |
| Medium | Work In Progress | | | | 10/13/2009 2:06:01 PM | | | | |
| Martinez, Larry | | On October 20, 2009, please deliver 39 boxes of HP Computers (Towers and Monitors) plus computer accessories to La Union Elementary. | | | | | | | |
| Yolie Jacquez | | | | | | | | | |
| 51760 | | | | | 10/26/2009 | | 71 | | \$0.00 |
| Medium | Work In Progress | | | | 10/26/2009 10:23:25 | | | | |
| Aguilar, Patricio | | assign to me - need to replace batters to emer lights | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 51762 | | | | | 10/26/2009 | | 71 | | \$0.00 |
| Medium | Work In Progress | | | | 10/26/2009 10:28:23 | | | | |
| Castillo, Carlos | | need 11 emer lights replacements - throw out building | | | | | | | |
| Patricio Aguilar | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|--|-------------|------------------------------|-----------------------|------------------|-----------|---------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: La Union ES | | | | | | | | | |
| 51850 | | Parking Lot | | | 10/27/2009 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | | 10/27/2009 4:24:39 PM | | | | |
| Munoz, Michael | | need to repair asphalt and sidewalk where new water line was run to back flow. | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 52046 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
| Medium | Work In Progress | | | | 11/1/2009 12:22:55 AM | | | | |
| Orozco, Danny | | Monthly - La Union ES Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 52179 | | | | | 11/3/2009 | | 63 | | \$0.00 |
| Medium | Work In Progress | | | | 11/3/2009 8:54:13 AM | | | | |
| Castillo, Carlos | | Piggy-backed power strips for computers in library | | | | | | | |
| 52329 | | | | | 11/5/2009 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | | 11/5/2009 3:29:42 PM | | | | |
| Villalobos, David | | need to have leak on back flow ck | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 52331 | | | | | 11/5/2009 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | | 11/5/2009 3:32:56 PM | | | | |
| Villalobos, David | | need to have gass leak on gass line repaired - front of school fences in | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 52576 | | | | | 11/12/2009 | | 54 | | \$0.00 |
| Medium | Work In Progress | | | | 11/12/2009 3:17:31 PM | | | | |
| Ambriz, Jose | | thermastat will not close heater vale - will just keep hot r311 | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 53456 | | | | | 12/10/2009 | | 26 | | \$0.00 |
| Low | Work In Progress | | | | 12/10/2009 10:08:56 | | | | |
| Aguilar, Patricio | | Need to backfil hole where asphalt was cut out at Bus Entrance until it is repaired. | | | | | | | |
| Michael Munoz | | | | | | | | | |
| Count: 14 Work Orders | | Avg. Age of WO's 72 | | Total for La Union ES | | 0 | | \$0.00 | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Loma Linda ES

| | | | | | | | | | |
|-------|--|--|--|--|----------|-----------|-----|--|--------|
| 47153 | | | | | 7/5/2009 | 7/26/2009 | 184 | | \$0.00 |
|-------|--|--|--|--|----------|-----------|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/5/2009 12:21:21 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Orozco, Danny Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|
| 47980 | | Cafeteria | | | 7/29/2009 | | 160 | | \$0.00 |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/29/2009 10:28:15 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny FLOOR TILES NEED TO BE REPLACED.

FRANCES B. SNP MGR 882-4707

Jacqueline Aguilar

| | | | | | | | | | |
|-------|---------------|-----------|--|--|-----------|--|-----|--|--------|
| 48869 | Main Building | Classroom | | | 8/17/2009 | | 141 | | \$0.00 |
|-------|---------------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/17/2009 9:37:50 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Arreola, Rudy Please replace light bulbs in RM327, teacher is Ms. Blancas she states bulbs are out.

Claudia Rodriguez

| | | | | | | | | | |
|-------|---------------|--------|--|--|-----------|--|-----|--|--------|
| 49095 | Main Building | Office | | | 8/21/2009 | | 137 | | \$0.00 |
|-------|---------------|--------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/21/2009 8:16:59 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Arreola, Rudy Counter gate in front office does not close. It is stuck. Please check. Thank you.

Claudia Rodriguez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 49441 | | | | | 8/28/2009 | | 130 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/28/2009 3:34:44 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, David Need to coordinate w/Bldg Mechanic and Joe Ontiveros on proper training for newer water heaters.

Michael Munoz

| | | | | | | | | | |
|-------|---------------|-----------|--|--|-----------|--|----|--|--------|
| 50735 | Main Building | Classroom | | | 10/1/2009 | | 96 | | \$0.00 |
|-------|---------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/1/2009 2:15:52 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ontiveros, Joe Bubbler is rusted and broke off. for sink area. Needs to be replaced in RM 330.

Rudy Arreola

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50869 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:01 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Loma Linda ES

50879 10/4/2009 10/25/2009 93 \$0.00

Medium Work In Progress 10/4/2009 12:22:04 AM

Orozco, Danny Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

51628 Main Building Restroom 10/22/2009 75 \$0.00

Medium Work In Progress 10/22/2009 9:30:46 AM

Ontiveros, Joe Water basin is leaking from water lines.

Rudy Arreola

52047 11/1/2009 11/22/2009 65 \$0.00

Medium Work In Progress 11/1/2009 12:22:55 AM

Orozco, Danny Monthly - Loma Linda ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

52800 Main Building Classroom 11/19/2009 22 \$0.00

Medium Work In Progress 11/19/2009 2:25:02 PM 12/11/2009

Solis, Luis Please distribute science fair boards to all teachers. Total of 53. Thank you. 11/19/09 - FAXED TO LUIS

Claudia Rodriguez

52863 Main Building Portables 11/20/2009 46 \$0.00

Medium Work In Progress 11/20/2009 2:49:55 PM

Arreola, Rudy Please replace ceiling tiles in Portable 333 for Ms. Ward. Thank you.

Claudia Rodriguez

53128 Main Building Classroom 12/3/2009 33 \$0.00

Medium Work In Progress 12/3/2009 1:39:25 PM

Arreola, Rudy Please assemble (2) Art poster stands for Ms. Powell, RM 326. They sit 2 1/2 high and 3ft long. Thank you.

Claudia Rodriguez

53293 12/6/2009 12/12/2009 30 \$0.00

Medium Work In Progress 12/6/2009 12:21:01 AM

Arreola, Rudy Monthly - Loma Linda ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Loma Linda ES

| | | | | | | | | | |
|--------------------|------------------|---|--|--|---------------------|------------|----|--|--------|
| 53558 | | | | | 12/13/2009 | 12/29/2009 | 23 | | \$0.00 |
| Medium | Work In Progress | | | | 12/13/2009 12:18:57 | | | | |
| Arreola, Rudy | | Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

| | | | | | | | | | |
|---------------|------------------|---------------------------|--|--|---------------------|--|----|--|--------|
| 53963 | | | | | 12/11/2009 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 1/5/2010 9:33:50 AM | | | | |
| Arreola, Rudy | | Right side mirror broken. | | | | | | | |
| Rudy Arreola | | | | | | | | | |

Count: 16 Work Orders Avg. Age of WO's 85 Total for Loma Linda ES 0 \$0.00

Location: Mesquite ES

| | | | | | | | | | |
|--------------------|------------------|---|--|--|----------------------|----------|-----|--|--------|
| 47224 | | | | | 7/5/2009 | 8/5/2009 | 184 | | \$0.00 |
| Medium | Work In Progress | | | | 7/5/2009 12:21:46 AM | | | | |
| Ramirez, Joe | | Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|----------------------|-----------|-----|--|--------|
| 47219 | | | | | 7/5/2009 | 7/13/2009 | 184 | | \$0.00 |
| Medium | Work In Progress | | | | 7/5/2009 12:21:45 AM | | | | |
| Ramirez, Joe | | Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|----------------------|-----------|-----|--|--------|
| 47220 | | | | | 7/5/2009 | 7/11/2009 | 184 | | \$0.00 |
| Medium | Work In Progress | | | | 7/5/2009 12:21:45 AM | | | | |
| Ramirez, Joe | | Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|----------------------|-----------|-----|--|--------|
| 47221 | | | | | 7/5/2009 | 7/13/2009 | 184 | | \$0.00 |
| Medium | Work In Progress | | | | 7/5/2009 12:21:45 AM | | | | |
| Ramirez, Joe | | Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|----------------------|-----------|-----|--|--------|
| 47222 | | | | | 7/5/2009 | 7/13/2009 | 184 | | \$0.00 |
| Medium | Work In Progress | | | | 7/5/2009 12:21:46 AM | | | | |
| Ramirez, Joe | | Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|---|--|--|-----------------------|------------|-----|--|--------|
| Location: | | Mesquite ES | | | | | | | |
| 47223 | | | | | 7/5/2009 | 8/5/2009 | 184 | | \$0.00 |
| Medium | Work In Progress | | | | 7/5/2009 12:21:46 AM | | | | |
| Ramirez, Joe | | Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 49374 | 2003 Classroom | | | | 8/27/2009 | | 131 | | \$0.00 |
| Medium | Work In Progress | Room # 305 | | | 8/27/2009 2:56:42 PM | | | | |
| Estrada, Jesus | | Larry Sedillo, needs floor tiles replaced stained by urine. | | | | | | | |
| Sandra Mora | | | | | | | | | |
| 49635 | | Cafeteria | | | 9/3/2009 | | 124 | | \$0.00 |
| Medium | Work In Progress | | | | 9/3/2009 10:14:42 AM | | | | |
| Orozco, Danny | | BATHROOM EXHAUST FAN NOT WORKING | | | | | | | |
| Danny Orozco | | | | | | | | | |
| 49796 | | | | | 9/6/2009 | 9/14/2009 | 121 | | \$0.00 |
| Medium | Work In Progress | | | | 9/6/2009 12:22:49 AM | | | | |
| Ramirez, Joe | | Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 49797 | | | | | 9/6/2009 | 9/14/2009 | 121 | | \$0.00 |
| Medium | Work In Progress | | | | 9/6/2009 12:22:49 AM | | | | |
| Ramirez, Joe | | Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 50880 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
| Medium | Work In Progress | | | | 10/4/2009 12:22:05 AM | | | | |
| Orozco, Danny | | Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 51356 | | | | | 10/13/2009 | | 84 | | \$0.00 |
| Medium | Work In Progress | | | | 10/13/2009 7:36:08 AM | | | | |
| Sotelo, Enrique | | need the bucket truck to replace light bulb at the bus turnaround street lamps | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 51475 | | | | | 10/19/2009 | | 78 | | \$0.00 |
| Medium | Work In Progress | | | | 10/19/2009 9:38:50 AM | | | | |
| Ronquillo, Ruben | | need to replace window blinds in the library. | | | | | | | |
| Joe Ramirez | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|---|-------------|-------|-----------------------|------------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Mesquite ES | | | | | | | | | |
| 51811 | | | | | 10/27/2009 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | | 10/27/2009 11:10:47 | | | | |
| Orozco, Danny | | NEED TO GET FIRE EXTINGUISHERS SERVICED | | | | | | | |
| Danny Orozco | | | | | | | | | |
| 52048 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
| Medium | Work In Progress | | | | 11/1/2009 12:22:56 AM | | | | |
| Orozco, Danny | | Monthly - Mesquite ES Fire Suppression Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 52564 | Restrooms | Hallway/Corridor | | | 11/12/2009 | | 54 | | \$0.00 |
| Medium | Work In Progress | Restroom next | | | 11/12/2009 11:29:28 | | | | |
| Lozoya, Manny | | Door to ladies bathroom hinges not working right. | | | | | | | |
| Sandra Mora | | | | | | | | | |
| 52708 | | | | | 11/17/2009 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | | 11/17/2009 10:10:23 | | | | |
| Ramirez, Joe | | need to replace several handicap signs. | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 53154 | | Custodial | | | 12/4/2009 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 12/4/2009 7:19:29 AM | | | | |
| Carbajal, Jimmy | | please the vaccum the motor burn out no power at all thank you, luis | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 53182 | | | | | 12/4/2009 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 12/4/2009 3:36:14 PM | | | | |
| Ramirez, Joe | | 11/3/09. | | | | 11/3-8 | | | |
| | | .5 building walk thru. | | | | | | | |
| | | 1.5 heaters and boiler. | | | | | | | |
| | | 2.0 warehouse. | | | | | | | |
| | | 1.0 replace tiles. | | | | | | | |
| | | 2.5 covebase removal. | | | | | | | |
| | | .5 clean up. | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 53278 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:20:54 AM | | | | |
| Ramirez, Joe | | Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 20 Work Orders | | Avg. Age of WO's | 109 | | | Total for Mesquite ES | 0 | | \$0.00 |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: North Valley ES

| | | | | | | | | | |
|-------|--|--|--|--|----------|--|-----|--|--------|
| 47099 | | | | | 7/5/2009 | | 184 | | \$0.00 |
|-------|--|--|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/5/2009 12:21:00 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|----------------------------|--|--|--|
| Holguin, Alfredo | | Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details. | | | | 8/27/09 - e-mailed to Rick | | | |
|------------------|--|--|--|--|--|----------------------------|--|--|--|

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 48061 | | | | | 7/30/2009 | | 159 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/30/2009 3:33:30 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|
| Solis, Lorenzo | | ROOF-TOP ERV UNIT MAKING LOUD NOISE- PLEASE RE -CK FOR SOURCE OF NOISE .ALL LOOKS WELL ON UNIT-BEARING AND BELT OK | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|

Danny Vega

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 48986 | | | | | 8/19/2009 | | 139 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/19/2009 7:31:35 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|
| Gonzalez, Salvador | | need to weld chains on parent-drop-off gates /weld chain to gate/need to bring chain with you.have bus drop -off gates also.asap | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|

Danny Vega

| | | | | | | | | | |
|-------|--|------------|--|--|-----------|--|-----|--|--------|
| 49195 | | Mechanical | | | 8/24/2009 | | 134 | | \$0.00 |
|-------|--|------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|
| High | Work In Progress | | | | 8/24/2009 3:31:11 PM | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|
| Sotelo, Enrique | | as per boiler inspector need to install manual shut-offs inside boiler rooms close to the door, cover guards and identification tag for boilers serial #s K07h00203547 and k07h00203548 | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 49197 | | | | | 8/24/2009 | | 134 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|
| High | Work In Progress | | | | 8/24/2009 3:34:19 PM | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|
| Sotelo, Enrique | | (boiler room) as per bolier inspector, boiler needs to be hardwired to a junction box. (boiler serail # k07h00203547. thankyou | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 50834 | | | | | 10/4/2009 | | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:21:48 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Holguin, Alfredo | | Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details. | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: North Valley ES

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51885 | | | | | 10/28/2009 | | 69 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/28/2009 1:49:49 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Guadalupe need one load crusher-fines at east ponding area/to be used at fence line poles-

Danny Vega

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52050 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:57 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - North Valley ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52919 | | | | | 11/24/2009 | | 42 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/24/2009 8:42:16 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Munoz, Michael Need Dimar to check Fire Pump for proper operation.

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|------------|------------|----|--|--------|
| 53546 | | | | | 12/13/2009 | 12/29/2009 | 23 | | \$0.00 |
|-------|--|--|--|--|------------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/13/2009 12:18:52 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Vega, Danny Monthly - North Valley ES Playground Inspection - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53612 | | | | | 12/15/2009 | | 21 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/15/2009 2:11:59 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lozoya, Manny rm 212 exit door will not open from inside class rm /this is a fire drill evacuation route exit .please ck asap

Danny Vega

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53650 | | | | | 12/16/2009 | | 20 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/16/2009 8:56:52 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lozoya, Manny rio grande wing mechanical rm door lock not securing (exterior)please ck asap

Danny Vega

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53706 | | | | | 12/17/2009 | | 19 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/17/2009 12:45:02 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Ontiveros, Joe rio grande wing in girls restroom -water faucet keeps runing need to replace faucet

Danny Vega

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| Location: | | North Valley ES | | | | | | | |
|------------------------------|------------------|---|-------------------------|-----------|---------------------|----------------------------------|----------|--|---------------|
| 53707 | | | | | 12/17/2009 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 12/17/2009 12:47:42 | | | | |
| Ontiveros, Joe | | pecan valley wing /girls restroom sink faucet keeps runing need to replace faucet | | | | | | | |
| Danny Vega | | | | | | | | | |
| 53708 | | | | | 12/17/2009 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 12/17/2009 12:50:19 | | | | |
| Ontiveros, Joe | | pecan valley wing bys restrooms sink faucet leaks /angle stop is off /please replace faucet | | | | | | | |
| Danny Vega | | | | | | | | | |
| Count: 15 Work Orders | | | Avg. Age of WO's | 76 | | Total for North Valley ES | 0 | | \$0.00 |

| Location: | | Northern On-Track Pre-K (LM) | | | | | | | |
|-----------------|------------------|---|--|--|-----------------------|--|----|--|--------|
| 51812 | | | | | 10/27/2009 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | | 10/27/2009 11:13:22 | | | | |
| Orozco, Danny | | NEED TO GET FIRE EXTINGUISHERS SERVICED | | | | | | | |
| Danny Orozco | | | | | | | | | |
| 51884 | | | | | 10/28/2009 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | | 10/28/2009 1:47:16 PM | | | | |
| Gonzales, Angel | | single axle trailer#4 has a bad 6-waytrailer plug /has no lights at all/please ck out | | | | | | | |
| Danny Vega | | | | | | | | | |
| 52436 | | | | | 11/9/2009 | | 57 | | \$0.00 |
| Medium | Work In Progress | | | | 11/9/2009 9:31:31 AM | | | | |
| Lozoya, Manny | | OUTSIDE CLASSROOM DOOR WILL NOT SECURE, INVENTORY FURNITURE STORED INSIDE. 11-6-09 | | | | | | | |
| Adam Montoya | | | | | | | | | |
| 52657 | | | | | 11/16/2009 | | 50 | | \$0.00 |
| Medium | Work In Progress | | | | 11/16/2009 10:50:10 | | | | |
| Lozoya, Manny | | NEED THREE 2 1/2 FT CHAIN, AND 2 LOCKS. | | | | | | | |
| Adam Montoya | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Northern On-Track Pre-K (LM)

53513 12/11/2009 25 \$0.00

Medium Work In Progress LM PRE-K 12/11/2009 11:24:42

Ontiveros, Joe AS PER ANN STEINHOFF-NEED TO HAVE HOT WATER IN BOTH BATHROOM SINKS IN THE PRE-K. (THIS IS MANDATORY AS PER CYFD.) NOTE: INDIVIDUAL SMALL WATER HEATER UNITS CAN BE INSTALLED UNDER THE SINKS, AS PER MR. RICHARD CHAVEZ. ALSO, IF THIS CAN BE DONE NEXT WEEK IF POSSIBLE, IF NOT THE LATEST WOULD BE THE FIRST WEEK OF JANUARY BEFORE CYFD COMES BACK TO EVALUATE. APPROVED BY MR. RICHARD G. CHAVEZ.

Mary Garcia

53514 12/11/2009 25 \$0.00

Medium Work In Progress LM PRE-K 12/11/2009 11:30:09

Ontiveros, Joe AS PER ANN STEINHOFF-NEED TO HAVE HOT WATER IN TODDLERS ROOM SINKS IN THE PRE-K. (THIS IS MANDATORY AS PER CYFD.) NOTE: INDIVIDUAL SMALL WATER HEATER UNITS CAN BE INSTALLED UNDER THE SINKS, AS PER MR. RICHARD CHAVEZ. ALSO, IF THIS CAN BE DONE NEXT WEEK IF POSSIBLE, IF NOT THE LATEST WOULD BE THE FIRST WEEK OF JANUARY BEFORE CYFD COMES BACK TO EVALUATE. APPROVED BY MR. RICHARD G. CHAVEZ

Mary Garcia

53515 12/11/2009 25 \$0.00

Medium Work In Progress LM PRE-K 12/11/2009 11:33:10

Rodriguez, Arturo AS PER MS. ANN STEINHOFF-NEED TO HAVE THE FURNITURE MOVED OUT FROM THE LOUNGE AND MOVED INTO THE FORMER NURSES ROOM. IF POSSIBLE NEXT WEEK.

Mary Garcia

53516 12/11/2009 25 \$0.00

Medium Work In Progress 12/11/2009 11:36:14

Ontiveros, Joe AS PER ANN STEINHOFF-NEED TO HAVE HOT WATER IN THE LOUNGE SINK IN THE PRE-K. (THIS IS MANDATORY AS PER CYFD.) NOTE: INDIVIDUAL SMALL WATER HEATER UNITS CAN BE INSTALLED UNDER THE SINKS, AS PER MR. RICHARD CHAVEZ. ALSO, IF THIS CAN BE DONE NEXT WEEK IF POSSIBLE, IF NOT THE LATEST WOULD BE THE FIRST WEEK OF JANUARY BEFORE CYFD COMES BACK TO EVALUATE. APPROVED BY MR. RICHARD G. CHAVEZ.

Mary Garcia

Count: 8 Work Orders Avg. Age of WO's 43 Total for Northern On-Track Pre-K (LM) 0 \$0.00

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| Location: | Physical Plant Complex |
|-----------|------------------------|
|-----------|------------------------|

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50382 | | | | | 9/22/2009 | | 105 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/22/2009 1:48:21 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|
| Gonzales, Angel | | VEHICLE 135 - COMPLETE ENGINE SERVICE. | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|
| Angel Gonzales | | | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|------------|--|--|--|----------|--|-----|--|--------|
| 47290 | Purchasing | | | | 7/6/2009 | | 183 | | \$0.00 |
|-------|------------|--|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/6/2009 10:27:57 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|
| Munoz, Michael | | PPD Main Entrance - Build designate Handicap Parking area and no parking area | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|
| Alfredo Holguin | | | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|-------------|--|--|--|----------|--|-----|--|--------|
| 47292 | Maintenance | | | | 7/6/2009 | | 183 | | \$0.00 |
|-------|-------------|--|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/6/2009 10:30:38 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|
| Munoz, Michael | | Designate build handicap and visitors parking in front of Maint Bldg. | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|
| Alfredo Holguin | | | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|---------------|--|--|--|-----------|--|-----|--|--------|
| 48795 | Food Services | | | | 8/14/2009 | | 144 | | \$0.00 |
|-------|---------------|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|
| High | Work In Progress | | | | 8/14/2009 8:06:35 AM | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-------------------|--|--|--|--|--|--|--|--|--|
| Moncayo, Fernando | | could you please repair or replace existing gutters. when it rains it is very hard to load trucks.thankyou | | | | | | | |
|-------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Michael Munoz | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|-------------|--|--|--|-----------|--|-----|--|--------|
| 48809 | Maintenance | | | | 8/14/2009 | | 144 | | \$0.00 |
|-------|-------------|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/14/2009 11:34:28 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|---|--|--|--|--|--|--|--|
| Ambriz, Jose | | Need to fixed vibration from ref. unit. | | | | | | | |
|--------------|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|
| Margret Villalobos | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|
| 49172 | | Cafeteria | | | 8/24/2009 | | 134 | | \$0.00 |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/24/2009 9:43:35 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-------------------|--|--|--|--|--|--|--|--|--|
| Moncayo, Fernando | | LOADING DOCK ROOF IS LEAKING. HOLES NEED TO BE SEALED OR PATCHED UP. | | | | | | | |
|-------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|--|--|---|--|--|--|--|--|--|--|
| | | JOHNNY LECHUGA SNP WAREHOUSE MGR 882-6927 | | | | | | | |
|--|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|
| Jacqueline Aguilar | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|---------------|-----------|--|--|-----------|--|-----|--|--------|
| 49174 | Food Services | Cafeteria | | | 8/24/2009 | | 134 | | \$0.00 |
|-------|---------------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/24/2009 9:56:39 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-------------------|--|---|--|--|--|--|--|--|--|
| Moncayo, Fernando | | SNP WAREHOUSE: 2ND REQUEST - RAIN GUTTER WAS NEVER REPAIRED AT LOADING DOCK. WATER LEADING ALL OVER DOCK. 1ST W/O # 43492 | | | | | | | |
| | | JOHNNY LECHUGA SNP MGR 882-6927 | | | | | | | |

| | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|
| Jacqueline Aguilar | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days | Labor | Total |
|----------------|-------------|-------------|--------------|-------|-------------------|------------------|------|-------|-------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | Aged | Hours | Costs |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |

Location: Physical Plant Complex

| | | | | | | | | | |
|-------|-------------|--|--|--|-----------|--|-----|--|--------|
| 49290 | Maintenance | | | | 8/26/2009 | | 132 | | \$0.00 |
|-------|-------------|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|------------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | Technology | | | 8/26/2009 11:29:48 AM | | | | |
|--------|------------------|------------|--|--|-----------------------|--|--|--|--|

Gonzales, Angel Regular oil change for Richard Santillano's van #157.

Thank you!

Sandra Almeraz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 49358 | | | | | 8/27/2009 | | 131 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | DIST WIDE | | | 8/27/2009 9:19:50 AM | | | | |
|--------|------------------|-----------|--|--|----------------------|--|--|--|--|

Gonzales, Angel FOR REPAIR OF TIRE MOUNT AND BALANCE ON ALL DISTRICT VEHICLES

Angel Gonzales

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 49359 | | | | | 8/27/2009 | | 131 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | DIST WIDE | | | 8/27/2009 9:21:57 AM | | | | |
|--------|------------------|-----------|--|--|----------------------|--|--|--|--|

Gonzales, Angel FOR TIRE REPAIR ON ALL DISTRICT VEHICLES

Angel Gonzales

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 49421 | | | | | 8/28/2009 | | 130 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | AG SHOP | | | 8/28/2009 10:48:00 AM | | | | |
|--------|------------------|---------|--|--|-----------------------|--|--|--|--|

Gonzales, Angel Vehicle#120 AG Truck
Angel, go ahead and work on scheduling the work for next week if possible.

Armando Montoya

| | | | | | | | | | |
|-------|--|--|--|--|----------|--|-----|--|--------|
| 49536 | | | | | 9/1/2009 | | 126 | | \$0.00 |
|-------|--|--|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/1/2009 1:05:29 PM | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Jacquez, Ricardo Water pressure is low.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|----------|--|-----|--|--------|
| 49645 | | | | | 9/3/2009 | | 124 | | \$0.00 |
|-------|--|--|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|------------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | Mike Munoz | | | 9/3/2009 2:02:14 PM | | | | |
|--------|------------------|------------|--|--|---------------------|--|--|--|--|

Gonzales, Angel Vehicle 99 - Has and odor of anti-freeze inside.

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|----------|--|-----|--|--------|
| 49698 | | | | | 9/4/2009 | | 123 | | \$0.00 |
|-------|--|--|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/4/2009 8:56:16 AM | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Gonzales, Angel Complete service on bobcat loader.

Angel Gonzales

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days | Labor | Total |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|------|-------|-------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | Aged | Hours | Costs |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| Location: | Physical Plant Complex |
|-----------|------------------------|
|-----------|------------------------|

| | | | | | | | | | |
|-------|------------|--------|--|--|-----------|--|-----|--|--------|
| 50115 | Purchasing | Office | | | 9/15/2009 | | 112 | | \$0.00 |
|-------|------------|--------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Instructional | | | 9/15/2009 9:23:59 AM | | | | |
|--------|------------------|---------------|--|--|----------------------|--|--|--|--|

Lara, Ralph

Due to it being a fire hazard, we need a key/lock to be made for the wrought-iron bars that are on the window in the Instructional Materials Department. Work order placed as per Alfredo Holguin.

Yolie Jacquez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50151 | | | | | 9/15/2009 | | 112 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/15/2009 4:13:43 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Gonzales, Angel

PLEASE REPLACE WIPER MOTOR FOR VEHICLE #32.
THANK YOU RUBEN

Ruben Ronquillo

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50242 | | | | | 9/18/2009 | | 109 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/18/2009 11:02:09 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Flores, Pete

Forklift needs service

Danny Carrasco

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50381 | | | | | 9/22/2009 | | 105 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/22/2009 1:47:18 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Gonzales, Angel

VEHICLE 97 - COMPLETE ENGINE SERVICE.

Angel Gonzales

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50383 | | | | | 9/22/2009 | | 105 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/22/2009 1:49:21 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Gonzales, Angel

VEHICLE 104 - SPARK PLUGS

Angel Gonzales

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50384 | | | | | 9/22/2009 | | 105 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/22/2009 1:50:16 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Gonzales, Angel

VEHICLE 100- SERVICE ON AC

Angel Gonzales

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50386 | | | | | 9/22/2009 | | 105 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/22/2009 1:52:10 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Gonzales, Angel

VEHICLE 02 - WINDOW REGULATOR

Angel Gonzales

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|--------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|---|--|-----------------|--|--|-----------------------|---------|-----|--|--------|
| Location: Physical Plant Complex | | | | | | | | | |
| 50482 | Maintenance | | | | 9/24/2009 | | 103 | | \$0.00 |
| Medium | Work In Progress | | | | 9/24/2009 1:13:48 PM | | | | |
| Miranda, Danny | Need to extend old HVAC office (into new lounge). | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 50693 | | | | | 9/30/2009 | | 97 | | \$0.00 |
| Medium | Work In Progress | | | | 9/30/2009 3:02:11 PM | | | | |
| Solis, Lorenzo | Please install ice machine in warehouse. | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 50759 | Maintenance | | | | 10/2/2009 | | 95 | | \$0.00 |
| Medium | Work In Progress | | | | 10/2/2009 7:42:02 AM | | | | |
| Gonzalez, Salvador | Need to make a bench table for sheetmetal bender. | | | | | | | | |
| Jose Ambriz | | | | | | | | | |
| 51162 | | | | | 10/7/2009 | | 90 | | \$0.00 |
| Medium | Work In Progress | | | | 10/7/2009 8:43:16 AM | | | | |
| Gonzales, Angel | Need to replace fuel pump and service engine on vehicle #53. | | | | | | | | |
| Angel Gonzales | | | | | | | | | |
| 51211 | | | | | 10/8/2009 | | 89 | | \$0.00 |
| Medium | Work In Progress | | | | 10/8/2009 12:42:58 PM | | | | |
| Gonzales, Angel | REPLACE LEFT REAR BROKEN LENS. TRUCK #32 | | | | | | | | |
| Ruben Ronquillo | | | | | | | | | |
| 51508 | | | | | 10/20/2009 | | 77 | | \$0.00 |
| Medium | Work In Progress | | | | 10/20/2009 7:51:23 AM | | | | |
| Gonzalez, Salvador | 10-9-091.0 Shop and check computer.- 1.0 Weld back ramp on portable 402 on Desert trail w.o. 514695. - 5.0 Go to CHS to put original basquetball boards back w.o. 51469. | | | | | 10/19-1 | | | |
| Salvador Gonzalez | | | | | | | | | |
| 51614 | Maintenance | Electrical Room | | | 10/22/2009 | | 75 | | \$0.00 |
| Medium | Work In Progress | | | | 10/22/2009 7:43:20 AM | | | | |
| Gonzales, Angel | Requesting windshield wipers for vehicle #152. | | | | | | | | |
| Carlos Castillo | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Physical Plant Complex

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 52120 | | | | | 11/2/2009 | | 64 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/2/2009 12:22:22 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|---------------------|--|---|--|--|--|---------------------------------|--|--|--|
| Villalobos, Margret | | Monthly - PPD - Quarterly Meeting - Refer to PM schedule details. | | | | Schedule for Dec. 3rd at 9:00am | | | |
|---------------------|--|---|--|--|--|---------------------------------|--|--|--|

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 52171 | | | | | 11/3/2009 | | 63 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/3/2009 7:57:49 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|
| Sotelo, Enrique | | AS PER ALFREDO, MOTION SENSOR LIGHTS NEED TO BE INSTALLED IN FILING/WAITING AREA AND LOBBY/HALLWAY. IF ANY QUESTIONS SEE ALFREDO. | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|

Alfredo Holguin

| | | | | | | | | | |
|-------|--|-----------|--|--|-----------|--|----|--|--------|
| 52427 | | Custodial | | | 11/9/2009 | | 57 | | \$0.00 |
|-------|--|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/9/2009 7:52:31 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|
| Gonzales, Angel | | VAN #73 USED IN CUSTODIAL CLEANING DUTIES HERE AT THE PHYSICAL PLANT NEEDS A BATTERY THANK YOU. | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|

Jimmy Carbajal

| | | | | | | | | | |
|-------|---------------|--|--|--|------------|--|----|--|--------|
| 52596 | Motor Vehicle | | | | 11/13/2009 | | 53 | | \$0.00 |
|-------|---------------|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/13/2009 9:16:13 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|
| Gonzales, Angel | | Move SNP delivery trucks located next to staff parking to the south side of the parking next to the other large vehicels and equipment (bucket truck, Custodial Van). | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|

Alfredo Holguin

| | | | | | | | | | |
|-------|------------|--|--|--|------------|--|----|--|--------|
| 52597 | Purchasing | | | | 11/13/2009 | | 53 | | \$0.00 |
|-------|------------|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/13/2009 9:22:12 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|
| Diaz, Sebastian | | Install Visitor Parking signs in parking area on west side of construction office. Remove reserved parking signs. | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|

Alfredo Holguin

| | | | | | | | | | |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|
| 52760 | Food Services | Cafeteria | | | 11/18/2009 | | 48 | | \$0.00 |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/18/2009 9:39:23 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|---------------|--|---|--|--|--|--|--|--|--|
| Orozco, Danny | | FREEZER #1 DOOR DOES NOT CLOSE ALL THE WAY. | | | | | | | |
|---------------|--|---|--|--|--|--|--|--|--|

JOHNNY LECHUGA SNP MGR 882-6927

Jacqueline Aguilar

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Physical Plant Complex

| | | | | | | | | | |
|-------|--|----------------|--|--|------------|--|----|--|--------|
| 52836 | | Athletic Field | | | 11/20/2009 | | 46 | | \$0.00 |
|-------|--|----------------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|-----------------------|--|--|--|--|
| High | Work In Progress | | | | 11/20/2009 8:14:00 AM | | | | |
|------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|
| Gonzales, Angel | | Truck #28 need to replaced master cyclinder. | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------------|--|--|--|--|--|--|--|--|--|
| Guadalupe Ontiveros | | | | | | | | | |
|---------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|
| 52982 | Food Services | Cafeteria | | | 11/30/2009 | | 36 | | \$0.00 |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/30/2009 3:40:53 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|-------------------|--|---|--|--|--|--|--|--|--|
| Moncayo, Fernando | | W/O # 43492 HAS NOT BEEN COMPLETED. AS PER SNP WHSE MGR. | | | | | | | |
|-------------------|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|--|--|---------------------------------|--|--|--|--|--|--|--|
| | | JOHNNY LECHUGA SNP MGR 882-6927 | | | | | | | |
|--|--|---------------------------------|--|--|--|--|--|--|--|

| | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|
| Jacqueline Aguilar | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53012 | | | | | 12/1/2009 | | 35 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/1/2009 12:04:33 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|
| Gonzales, Angel | | VEHICLE 99 - Only cold air coming out on heater, ck T- Stat. | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Michael Munoz | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53013 | | | | | 12/1/2009 | | 35 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/1/2009 12:05:53 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|
| Gonzales, Angel | | VEHICLE 75 - Heater and Radio are not working. | | | | | | | |
|-----------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Michael Munoz | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53101 | | | | | 12/3/2009 | | 33 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/3/2009 7:36:48 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-------------------|--|---|--|--|--|--|--|--|--|
| Villalobos, David | | as per the meeting held w/you, please go ahead and visit every site and identify all back flow preventers. information needed are as follows. brand, serial #, model # type, and if backflow is a fire, irrigation or domectic. also order from maintenace warehouse metal tags to place on back flow and log on information needed also.thankyou | | | | | | | |
|-------------------|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Michael Munoz | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|---------------|-----------|--|--|-----------|--|----|--|--------|
| 53160 | Food Services | Cafeteria | | | 12/4/2009 | | 32 | | \$0.00 |
|-------|---------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/4/2009 10:33:55 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|-------------------|--|------------------------|--|--|--|--|--|--|--|
| Moncayo, Fernando | | FREEZER #2: DOWN / FAN | | | | | | | |
|-------------------|--|------------------------|--|--|--|--|--|--|--|

| | | | | | | | | | |
|--|--|-------------------|--|--|--|--|--|--|--|
| | | SNP WHSE 882-6927 | | | | | | | |
|--|--|-------------------|--|--|--|--|--|--|--|

| | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|
| Jacqueline Aguilar | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|------------------------------|------------------|--|--|-----------|---|--|----|----------|---------------|
| Location: | | Physical Plant Complex | | | | | | | |
| 53342 | Maintenance | | | | 12/7/2009 | | 29 | | \$0.00 |
| Medium | Work In Progress | | | | 12/7/2009 12:37:51 PM | | | | |
| Gonzalez, Salvador | | adapt platform on trailer #7 and install winch | | | | | | | |
| Danny Carrasco | | | | | | | | | |
| 53370 | Maintenance | | | | 12/8/2009 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | | 12/8/2009 10:03:09 AM | | | | |
| Ronquillo, Ruben | | NEED TO REPLACE TOGGLE SWITCHES AND MALE PLUGS ON PORTABLE YELLOW HEATERS | | | | | | | |
| Ruben Ronquillo | | | | | | | | | |
| 53377 | Motor Vehicle | | | | 12/8/2009 | | 28 | | \$0.00 |
| Medium | Work In Progress | | | | 12/8/2009 12:27:31 PM | | | | |
| Gonzales, Angel | | 5510 tractor needs rear tires replaced. | | | | | | | |
| Angel Gonzales | | | | | | | | | |
| 53408 | Motor Vehicle | | | | 12/9/2009 | | 27 | | \$0.00 |
| Medium | Work In Progress | | | | 12/9/2009 8:16:57 AM | | | | |
| Gonzales, Angel | | Need to Fixed Services Truck Heater and Mufler as Per Mike THANK YOU GUYS. | | | | | | | |
| Joe Ontiveros | | | | | | | | | |
| 53563 | | | | | 12/14/2009 | | 22 | | \$0.00 |
| Medium | Work In Progress | | | | 12/14/2009 7:47:00 AM | | | | |
| Gonzales, Angel | | 12-14-09 Angel the speedometer of my does not work may you repaired so I can fill it up mileage paper work. Thank you. | | | | | | | |
| Salvador Gonzalez | | | | | | | | | |
| 53629 | Purchasing | | | | 12/15/2009 | | 21 | | \$0.00 |
| Medium | Work In Progress | | | | 12/15/2009 3:19:17 PM | | | | |
| Briones, Enrique | | On December 16, 2009, please assist the Inventory Technicians take four (4) pallets of obsolete computers to the computer "graveyard". | | | | | | | |
| Yolie Jacquez | | | | | | | | | |
| 53705 | Motor Vehicle | | | | 12/17/2009 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 12/17/2009 10:32:28 | | | | |
| Gonzales, Angel | | Vehicle #135 needs complete service. | | | | | | | |
| Angel Gonzales | | | | | | | | | |
| Count: 47 Work Orders | | Avg. Age of WO's | | 86 | Total for Physical Plant Complex | | | 0 | \$0.00 |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Riverside ES

| | | | | | | | | | |
|-------|--|-----------|--|--|----------|--|-----|--|--------|
| 48455 | | Cafeteria | | | 8/6/2009 | | 152 | | \$0.00 |
|-------|--|-----------|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/6/2009 3:01:56 PM | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Moncayo, Fernando
CART FOR REGISTER NEED WHEELS TO BE REPLACED.

EMILLA C SNP MGR 589-2550

Jacqueline Aguilar

| | | | | | | | | | |
|-------|---------------|--|--|--|-----------|--|-----|--|--------|
| 49126 | Main Building | | | | 8/21/2009 | | 137 | | \$0.00 |
|-------|---------------|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/21/2009 2:07:00 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Lara, Ralph
Door in the Sixth Grade Wing is not locking correctly.

Olga Arias

| | | | | | | | | | |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|
| 50214 | | Classroom | | | 9/16/2009 | | 111 | | \$0.00 |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/16/2009 4:17:03 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Hernandez, Carlos
2" x8' cork railings will be ordered.please install when you receive them.thankyou

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50335 | | | | | 9/21/2009 | | 106 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/21/2009 3:20:06 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ambriz, Jose
need new a/c unit room 17

Carlos Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50380 | | | | | 9/18/2009 | | 109 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/22/2009 1:45:19 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ontiveros, Guadalupe
RIPPED OUT POLE AND SIGN, ALSO PULLED OUT AND BROKE 8 SPRINKLERS.
(CASE#SP009001453)
EST DAMAGE 800.00

Carlos Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 50698 | | | | | 9/30/2009 | | 97 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/30/2009 3:24:33 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ambriz, Jose
need a/c uint room 16

Carlos Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50881 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:05 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny
Monthly - Riverside ES Range Hood Cleaning - Refer to PMschedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Riverside ES

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 51270 | | | | | 10/9/2009 | | 88 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/9/2009 3:07:54 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|-----------------------|--|--|--|--|--|--|--|
| Ambriz, Jose | | need a/c unit room 32 | | | | | | | |
|--------------|--|-----------------------|--|--|--|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Carlos Hernandez | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51392 | | | | | 10/13/2009 | | 84 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/13/2009 3:18:05 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|-------------------------------------|--|--|--|--|--|--|--|
| Ambriz, Jose | | need 2 new a/c units 43 for room 23 | | | | | | | |
|--------------|--|-------------------------------------|--|--|--|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Carlos Hernandez | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51393 | | | | | 10/13/2009 | | 84 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/13/2009 3:18:47 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|------------------------|--|--|--|--|--|--|--|
| Ambriz, Jose | | need a/c uinit room 10 | | | | | | | |
|--------------|--|------------------------|--|--|--|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Carlos Hernandez | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51394 | | | | | 10/13/2009 | | 84 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/13/2009 3:19:54 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|-----------------------|--|--|--|--|--|--|--|
| Ambriz, Juan | | need a/c unit room 24 | | | | | | | |
|--------------|--|-----------------------|--|--|--|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Carlos Hernandez | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51395 | | | | | 10/13/2009 | | 84 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/13/2009 3:20:53 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|---------------------------|--|--|--|--|--|--|--|
| Ambriz, Jose | | need new a/c unit room 11 | | | | | | | |
|--------------|--|---------------------------|--|--|--|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Carlos Hernandez | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51396 | | | | | 10/13/2009 | | 84 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/13/2009 3:21:36 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|---------------------------|--|--|--|--|--|--|--|
| Ambriz, Jose | | need new a/c unit room 32 | | | | | | | |
|--------------|--|---------------------------|--|--|--|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Carlos Hernandez | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51397 | | | | | 10/13/2009 | | 84 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/13/2009 3:22:18 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|---------------------------|--|--|--|--|--|--|--|
| Ambriz, Jose | | need new a/c unit room 12 | | | | | | | |
|--------------|--|---------------------------|--|--|--|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Carlos Hernandez | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51398 | | | | | 10/13/2009 | | 84 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/13/2009 3:23:05 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|--------------|--|---------------------------|--|--|--|--|--|--|--|
| Ambriz, Jose | | need new a/c unit room 13 | | | | | | | |
|--------------|--|---------------------------|--|--|--|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Carlos Hernandez | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days | Labor | Total |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|------|-------|-------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | Aged | Hours | Costs |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Riverside ES

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51399 | | | | | 10/13/2009 | | 84 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/13/2009 3:24:02 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ambriz, Jose need 2 new a/c units 43 for room 15

Carlos Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51649 | | | | | 10/22/2009 | | 75 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/22/2009 3:20:57 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ambriz, Jose need to replace two siwtches heaters rtf-rs 004 and rtf-rs -002

Carlos Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52049 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:56 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Riverside ES Fire Suppression Insp. - Refer to PMschedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|---------|--|--|-----------|--|----|--|--------|
| 52383 | | Library | | | 11/6/2009 | | 60 | | \$0.00 |
|-------|--|---------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/6/2009 1:55:44 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Castillo, Carlos Exit light out in library.

Ralph Gallegos

| | | | | | | | | | |
|-------|--|-----------|--|--|------------|--|----|--|--------|
| 52535 | | Cafeteria | | | 11/10/2009 | | 56 | | \$0.00 |
|-------|--|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/10/2009 3:57:08 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny NEED SOME LIGHT BLUBS TO BE REPLACED

EMILIA CARRILLO SNP MGR 589-2550

Jacqueline Aguilar

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53026 | | | | | 12/1/2009 | | 35 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/1/2009 3:00:15 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ambriz, Jose need vent covers for new a/c units that were installed (cold air going in to classrooms)need 12

Carlos Hernandez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53052 | | | | | 12/2/2009 | | 34 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/2/2009 10:03:41 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Gonzales, Angel 455 tractor needs new battery.

Angel Gonzales

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| Location: | | Riverside ES | | | | | | | |
|------------------------------|------------------|---|--|-----------|-------------------------------|--|----|----------|---------------|
| 53104 | | | | | 12/3/2009 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | | 12/3/2009 8:20:59 AM | | | | |
| Castillo, Carlos | | NEED AN ELECTRICAL OUTLET NEAR CABINET - CALL SILVER IN TECHNOLOGY IF YOU QUESTIONS | | | | | | | |
| Cora Ramirez | | | | | | | | | |
| 53139 | | | | | 12/3/2009 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | | 12/3/2009 3:22:57 PM | | | | |
| Ambriz, Jose | | heater main office shutting down | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 53176 | | | | | 12/4/2009 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 12/4/2009 3:20:08 PM | | | | |
| Lara, Ralph | | need door closer for doors in westside doors upper wing | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 53349 | | | | | 12/7/2009 | | 29 | | \$0.00 |
| Medium | Work In Progress | | | | 12/7/2009 3:02:42 PM | | | | |
| Ambriz, Jose | | need t-stat for faucly bathroom outside upper wing | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 53351 | | | | | 12/7/2009 | | 29 | | \$0.00 |
| Medium | Work In Progress | | | | 12/7/2009 3:05:06 PM | | | | |
| Ambriz, Jose | | need 9 covers for bottom of new a/c units | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| Count: 27 Work Orders | | Avg. Age of WO's | | 76 | Total for Riverside ES | | | 0 | \$0.00 |

| Location: | | San Miguel ES | | | | | | | |
|-----------------------------|------------------|--|--|------------|--------------------------------|-----------------------------------|-----|----------|---------------|
| 49386 | | Office | | | 8/27/2009 | | 131 | | \$0.00 |
| Medium | Work In Progress | PPD AUTO | | | 8/27/2009 3:57:30 PM | | | | |
| Martinez, Larry | | AS PER MARIA-NEED TO HAVE SOMEONE PICK UP A PLASTIC FLOOR MAT FROM SAN MIGUEL ELEMENTARY AND TO DELIVER IT TO HER OFFICE AT PPD - AUTO SHOP. | | | | APPROVED BY MR. RICHARD G. CHAVEZ | | | |
| Mary Garcia | | | | | | | | | |
| Count: 1 Work Orders | | Avg. Age of WO's | | 131 | Total for San Miguel ES | | | 0 | \$0.00 |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa ES

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47581 | | | | | 7/16/2009 | | 173 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/16/2009 12:54:46 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Estrada, Jesus
NEED TO REPLACE VCT WITH CARPET IN PORTABLE A & B.

Jesus Estrada

| | | | | | | | | | |
|-------|---------------|--------|--|--|-----------|--|-----|--|--------|
| 49045 | Main Building | Office | | | 8/19/2009 | | 139 | | \$0.00 |
|-------|---------------|--------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | NURSE'S | | | 8/19/2009 5:11:14 PM | | | | |
|--------|------------------|---------|--|--|----------------------|--|--|--|--|

Lara, Ralph
MEDICINE CABINET IN NURSE'S OFFICE NEEDS A LOCK. THANK YOU.

Rita Mendez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50487 | | | | | 9/24/2009 | | 103 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/24/2009 2:13:35 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|---------|--|--|--|--------|--|--|--|
| Marquez, Gerardo | | 9/14/09 | | | | 9/14-8 | | | |
|------------------|--|---------|--|--|--|--------|--|--|--|

1-INSP. BLDG. & GRNDS. (CHECKED FOR VANDALISM & GRAFITTI.)
1-PICKED UP TRASH.
2-CLEANED OFF ENTRYWAYS & SIDEWALKS.
1-CLEANED & INSP. P.G. EQUIP.
2-CLEANED UP PAINT SPILL ON SIDEWALK OUTSIDE RM. 306. (KIDS SPILLED PAINT WHILE WORKING ON A PROJECT.)
1-UNCLOGGED URINAL IN BOYS R.RM. B-WING.

Gerardo Marquez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50882 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:05 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny
Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|
| 51496 | Main Building | Classroom | | | 10/19/2009 | | 78 | | \$0.00 |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | ART | | | 10/19/2009 3:42:36 PM | | | | |
|--------|------------------|-----|--|--|-----------------------|--|--|--|--|

Estrada, Jesus
FOR ART PORTABLE: PLEASE INSTALL LINOLEUM FLOORING AROUND THE SINK THAT WILL BE INSTALLED IN PORTABLE AND ALSO IF POSSIBLE, PLEASE INSTALL LINOLEUM AT THE ENTRANCE OF THE PORTABLE. THANKS.

Rita Mendez

| | | | | | | | | | |
|-------|--|-----------|--|--|------------|--|----|--|--------|
| 51655 | | Portables | | | 10/22/2009 | | 75 | | \$0.00 |
|-------|--|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|-----------------------|--|--|--|--|
| High | Work In Progress | | | | 10/22/2009 3:32:11 PM | | | | |
|------|------------------|--|--|--|-----------------------|--|--|--|--|

Marquez, Gerardo
as per our conversation, please pour concrete where old concrete was removed for new sewer line. please contact mike for support. thanks

Michael Munoz

1/5/2010 12:27:04 PM

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa ES

| | | | | | | | | | |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|
| 51753 | Main Building | Portables | | | 10/26/2009 | | 71 | | \$0.00 |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | ART | | | 10/26/2009 9:39:03 AM | | | | |
|--------|------------------|-----|--|--|-----------------------|--|--|--|--|

Diaz, Pablo
I NEED A BOOK HOLDER TO BE BUILT. THANK YOU.

Rita Mendez

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51765 | | | | | 10/26/2009 | | 71 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/26/2009 11:22:40 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Munoz, Michael
ATTN. MIKE MUNOZ; MIKE, AS PER OUR PREVIOUS CONVERSATIONS, I HAVE INFORMED YOU THAT THE RUBBER MATTING IN BOTH PLAYGROUND AREAS HAS BEEN KNURLING AND NEEDS TO BE REPLACED. YOU SAID THAT YOU WOULD NOTIFY DONNIE GONZALEZ WITH RECREATION CREATIONS TO CORRECT THE PROBLEM. AS OF YET THERE HAS BEEN NO ACTION. COULD YOU LET ME KNOW THE STATUS OF THIS MATTER. THANKS.

Gerardo Marquez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52051 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:57 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny
Monthly- Santa Teresa ES Fire Suppression Insp. - Refer to PMSchedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 52444 | | | | | 11/9/2009 | | 57 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/9/2009 11:25:43 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Castillo, Carlos
Need to provide kill switch for boiler (NM-09737) asp Inspector.

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 52445 | | | | | 11/9/2009 | | 57 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/9/2009 11:27:30 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Castillo, Carlos
Need to provide kill switch for boiler (NM-09738) asp Inspector.

Michael Munoz

| | | | | | | | | | |
|-------|---------------|-----------|--|--|-----------|--|----|--|--------|
| 52447 | Main Building | Classroom | | | 11/9/2009 | | 57 | | \$0.00 |
|-------|---------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | MUSIC | | | 11/9/2009 2:02:45 PM | | | | |
|--------|------------------|-------|--|--|----------------------|--|--|--|--|

Marquez, Gerardo
MS. URREA NEEDS A MUSIC STAND TO BE BUILT. THANKS

Rita Mendez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa ES

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52908 | | | | | 11/23/2009 | | 43 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/23/2009 3:53:34 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Castillo, Carlos
 CALI;ONE OF THE EMERGENCYLIGHT FIXTURES IN THE TEACHERS LOUNGE WILL NOT TURN ON. I CHANGED THE BULBS BUT IT STILL DIDNT TURN ON. COULD YOU PLEASE CHECK IT OUT. THERE IS ALSO AN EMERG. LIGHT IN PORTABLE C. THAT WILL NOT GO ON. I CHECKED IT OUT AND IT SEEMS THAT THE BATTERY IS CRACKED . WOULD YOU CHECK IT OUT ALSO. THANKS.

Gerardo Marquez

| | | | | | | | | | |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|
| 52993 | Main Building | Cafeteria | | | 11/30/2009 | | 36 | | \$0.00 |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | CAFETERIA | | | 11/30/2009 5:02:54 PM | | | | |
|--------|------------------|-----------|--|--|-----------------------|--|--|--|--|

Ambriz, Jose
 HEATER IN THE CAFETERIA IS NOT WORKING. PLEASE CHECK. PABLO CALLED IT IN. THANKS.

Rita Mendez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53127 | | | | | 12/3/2009 | | 33 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/3/2009 12:59:22 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ambriz, Jose
 STERLING HEATERS @ CAFETERIA ARE NOT WORKING PROPERLY. NEED TO BE CHECKED OUT.

Gerardo Marquez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53241 | | | | | 12/6/2009 | | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:41 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Marquez, Gerardo
 Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PMschedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53242 | | | | | 12/6/2009 | | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:41 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Marquez, Gerardo
 Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PMschedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 53243 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:41 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Marquez, Gerardo
 Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PMschedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa ES

53244 12/6/2009 12/14/2009 30 \$0.00

Medium Work In Progress 12/6/2009 12:20:42 AM

Marquez, Gerardo Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

53245 12/6/2009 12/12/2009 30 \$0.00

Medium Work In Progress 12/6/2009 12:20:42 AM

Marquez, Gerardo Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

53333 12/7/2009 29 \$0.00

Medium Work In Progress 12/7/2009 10:17:10 AM

Villalobos, David ART TEACHER IS REQUESTING A WATER HEATER FOR THE SINK THAT WAS INSTALLED IN THE ART RM. THANKS.

Gerardo Marquez

53416 Cafeteria 12/9/2009 27 \$0.00

Medium Work In Progress 12/9/2009 11:44:08 AM

Moncayo, Fernando DISHWASHER NOT WORKING
PAT S. SNP MGR 589-3439

Jacqueline Aguilar

53549 12/13/2009 12/29/2009 23 \$0.00

Medium Work In Progress 12/13/2009 12:18:53

Marquez, Gerardo Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.

Margret Villalobos

Count: 23 Work Orders Avg. Age of WO's 60 Total for Santa Teresa ES 0 \$0.00

Location: Santa Teresa HS

47782 7/23/2009 166 \$0.00

Medium Work In Progress 7/23/2009 3:29:47 PM

Lara, Ralph NEED TO HAVE METAL DOORS , AND HARDWARE ON COUNSELORS OFFICE REPLACED HINDGES ARE BROKEN, SECURITY ISSUE. THANK YOU.

Arturo Nunez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa HS

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47783 | | | | | 7/23/2009 | | 166 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/23/2009 3:32:26 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Lara, Ralph
NEED DOUBLE DOORS IN BAND ROOM REPLACED OR REPAIRED , TOP LOCK ON DOOR IS BROKEN BEYOND REPAIR, SECURITY ISSUE.

Arturo Nunez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47784 | | | | | 7/23/2009 | | 166 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/23/2009 3:35:04 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Munoz, Michael
NEED TO REPLACE FORMICA ON FRONT OFFICE COUNTER, EXISTING IS ALL CHIPPED, AND IN BAD SHAPE.

Arturo Nunez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47786 | | | | | 7/23/2009 | | 166 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/23/2009 3:38:07 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ambriz, Jose
NEED FOUR (4) EA. 7"X23" GRILLS, AND FOUR (4) EA. 7"X13" GRILLS FOR BAND ROOM.

Arturo Nunez

| | | | | | | | | | |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|
| 48657 | | Classroom | | | 8/11/2009 | | 147 | | \$0.00 |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | MR. | | | 8/11/2009 2:34:31 PM | | | | |
|--------|------------------|-----|--|--|----------------------|--|--|--|--|

Lara, Ralph
ENTRY DOORS TO BANDROOM TO INSTALL METAL DOORS.

Marylou Jimenez

| | | | | | | | | | |
|-------|---------------|----------------|--|--|-----------|--|-----|--|--------|
| 48689 | Main Building | Athletic Field | | | 8/12/2009 | | 146 | | \$0.00 |
|-------|---------------|----------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/12/2009 7:58:04 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Valdez, Pedro
Soccer Field: Install and adjust retaining nets behind North and South Goals.

Luis Calleros

| | | | | | | | | | |
|-------|---------------|-----------|--|--|-----------|--|-----|--|--------|
| 49079 | Main Building | Classroom | | | 8/20/2009 | | 138 | | \$0.00 |
|-------|---------------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | room 213 | | | 8/20/2009 5:26:03 PM | | | | |
|--------|------------------|----------|--|--|----------------------|--|--|--|--|

Lara, Ralph
change door mechanism to a door handle with manual lock on top to the bathroom door

Luis Calleros

| | | | | | | | | | |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|
| 49192 | | Cafeteria | | | 8/24/2009 | | 134 | | \$0.00 |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|
| High | Work In Progress | | | | 8/24/2009 3:09:28 PM | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|

Ambriz, Jose
as per boiler inspector a low water cut off such as a flow switch and a high limit temp control w/a manual reset button needs to be installed on the following boilers (serial #s 0501230507 and 050123506). thanks

Michael Munoz

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa HS

| | | | | | | | | | |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|
| 49193 | | Cafeteria | | | 8/24/2009 | | 134 | | \$0.00 |
|-------|--|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|
| High | Work In Progress | | | | 8/24/2009 3:13:34 PM | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|

Castillo, Carlos
As per boiler inspector a manually operated remote shut down safety device needs to be installed inside boiler rooms by the door w/ cover guard and identification tag. (boilers serial #s 0501230507 and 0501230506) thank you

Michael Munoz

| | | | | | | | | | |
|-------|------------------|-----------|--|--|-----------|--|-----|--|--------|
| 49289 | Cafeteria (2005) | Cafeteria | | | 8/26/2009 | | 132 | | \$0.00 |
|-------|------------------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/26/2009 10:18:57 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lara, Ralph
HANDI CAP DOOR NOT OPENING WHEN BOX IS PUSHED TO OPEN NEEDS TO BE CHECKED OUT THANK YOU.

Luis Murillo

| | | | | | | | | | |
|-------|---------------|----------------|--|--|-----------|--|-----|--|--------|
| 49395 | Main Building | Athletic Field | | | 8/27/2009 | | 131 | | \$0.00 |
|-------|---------------|----------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Baseball field | | | 8/27/2009 5:07:41 PM | | | | |
|--------|------------------|----------------|--|--|----------------------|--|--|--|--|

Ontiveros, Guadalupe
Nee the following paint and paint supplies as needed:
5 gal. black paint
5 gal. whitpaint
5 gal. turquoise paint as discussed with Mr. Lupe Ontiveros and Mr. Pedro Valdez

Luis Calleros

| | | | | | | | | | |
|-------|--|-----------|--|--|----------|--|-----|--|--------|
| 49564 | | Cafeteria | | | 9/2/2009 | | 125 | | \$0.00 |
|-------|--|-----------|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/2/2009 7:06:02 AM | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Nunez, Arturo
WE HAVE TWO FIRE EXTINGUISHERS COVERS THAT ARE BROKEN ONE IN THE CAFETERIA AND ANOTHER IN THE NEW GYM THEY NEED TO BE REPLACE THANK YOU.
9/2 - Asp Ruben, needs to go thru BM for measurements. - mkv

Luis Murillo

| | | | | | | | | | |
|-------|--|--|--|--|----------|-----------|-----|--|--------|
| 49751 | | | | | 9/6/2009 | 9/27/2009 | 121 | | \$0.00 |
|-------|--|--|--|--|----------|-----------|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/6/2009 12:22:34 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Orozco, Danny
Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|----------------|-----------|--|--|-----------|--|-----|--|--------|
| 50152 | Annex Building | Portables | | | 9/15/2009 | | 112 | | \$0.00 |
|-------|----------------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Day Care | | | 9/15/2009 5:00:15 PM | | | | |
|--------|------------------|----------|--|--|----------------------|--|--|--|--|

Nunez, Arturo
Replace gutters, (two sets), outside of front doors

Luis Calleros

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa HS

| | | | | | | | | | |
|-------|---------------|-----------|--|--|-----------|--|-----|--|--------|
| 50154 | AnnexBuilding | Portables | | | 9/15/2009 | | 112 | | \$0.00 |
|-------|---------------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Day care center | | | 9/15/2009 5:04:57 PM | | | | |
|--------|------------------|-----------------|--|--|----------------------|--|--|--|--|

Nunez, Arturo replace floor tiles by doors

Luis Calleros

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50280 | | | | | 9/20/2009 | | 107 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/20/2009 12:18:49 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Guadalupe Monthly - Santa Teresa HS Soil Sampling - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|------------|-----------|--|--|-----------|--|-----|--|--------|
| 50378 | Vocational | Cafeteria | | | 9/22/2009 | | 105 | | \$0.00 |
|-------|------------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/22/2009 1:17:16 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Castillo, Carlos LIGHTS BEHIND CAFETERIA ARE NOT COMEING ON / THE ONES THAT ARE BY THE TRASH COMPACTER / CUSTODIANS CAN NOT SEE WHEN THROWING TRASH THANK YOU.

Luis Murillo

| | | | | | | | | | |
|-------|---------------|----------------|--|--|-----------|--|-----|--|--------|
| 50462 | Main Building | Athletic Field | | | 9/23/2009 | | 104 | | \$0.00 |
|-------|---------------|----------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Soccer Field | | | 9/23/2009 4:26:27 PM | | | | |
|--------|------------------|--------------|--|--|----------------------|--|--|--|--|

Ontiveros, Guadalupe Replace North / South retaining nylon nets behind the goals with chain link fence or other weather erosion proof material

Luis Calleros

| | | | | | | | | | |
|-------|------------|----------|--|--|-----------|--|----|--|--------|
| 50728 | Concession | Restroom | | | 10/1/2009 | | 96 | | \$0.00 |
|-------|------------|----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/1/2009 10:41:06 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Castillo, Carlos HOT AIR BLOWERS ARE NOT WORKING FROM THE GIRLS BATHROOM IN THE CONCESSION STAND NEEDS TO BE CHECKED OUT THANK YOU.

Luis Murillo

| | | | | | | | | | |
|-------|------------|----------------|--|--|-----------|--|----|--|--------|
| 50738 | Concession | Athletic Field | | | 10/1/2009 | | 96 | | \$0.00 |
|-------|------------|----------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/1/2009 2:51:45 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Castillo, Carlos Hand dryers in ladies restroom need to be checked, not working.

Luis Calleros

| | | | | | | | | | |
|-------|-------------|----------|--|--|-----------|--|----|--|--------|
| 50774 | Locker Room | Restroom | | | 10/2/2009 | | 95 | | \$0.00 |
|-------|-------------|----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/2/2009 9:35:51 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Villalobos, David WATER FAUCET IS COMEING APART IT IS ALL LOSE / FROM BOYS BATHROOM IN THE LIBRARY NEEDS TO BE CHECKED OUT THANK YOU.

Luis Murillo

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|--|--|--|-----------------------|------------|----|--|--------|
| Location: | | Santa Teresa HS | | | | | | | |
| 50883 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
| Medium | Work In Progress | | | | 10/4/2009 12:22:06 AM | | | | |
| Orozco, Danny | | Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 50979 | | | | | 10/4/2009 | 11/4/2009 | 93 | | \$0.00 |
| Medium | Work In Progress | | | | 10/4/2009 12:22:42 AM | | | | |
| Prospero, Manuel | | Yearly - Santa Teresa HS I-4 Fan Coil Unit Yearly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 51037 | | Classroom | | | 10/5/2009 | | 92 | | \$0.00 |
| Medium | Work In Progress | | | | 10/5/2009 9:39:12 AM | | | | |
| Prospero, Manuel | | THERE IS A TABLE THAT NEEDS TO BE REMOVE ITS SCREWED TO THE WALL / FROM RM* 18 THANK YOU. | | | | | | | |
| Luis Murillo | | | | | | | | | |
| 51525 | | Classroom | | | 10/20/2009 | | 77 | | \$0.00 |
| Medium | Work In Progress | MRS. | | | 10/20/2009 11:34:05 | | | | |
| Villalobos, David | | 2ND REQUEST-NEED WATER RESTORED TO THE TEACHER'S DEMONSTATION TABLE. | | | | | | | |
| Marylou Jimenez | | | | | | | | | |
| 51526 | | Classroom | | | 10/20/2009 | | 77 | | \$0.00 |
| Medium | Work In Progress | MRS. | | | 10/20/2009 11:35:58 | | | | |
| Villalobos, David | | 2ND REQUEST-NEED GAS LINES FIXED AND RESTORED, ESPECIALLY TO THE TEACHERS DEMO TABLE. | | | | | | | |
| Marylou Jimenez | | | | | | | | | |
| 51527 | | Classroom | | | 10/20/2009 | | 77 | | \$0.00 |
| Medium | Work In Progress | MRS. | | | 10/20/2009 11:38:05 | | | | |
| Villalobos, David | | SINK IS STOPPED UP PAST THE U-TRAP. I REMOVED THE ELBOW JOINT AND EMPTIED ITS DEBRIS. ART TRIED USING THE SNAKE BUT IT IS STILL STOPPED UP AND SMELLS BAD. | | | | | | | |
| Marylou Jimenez | | | | | | | | | |
| 51602 | | | | | 10/21/2009 | | 76 | | \$0.00 |
| Medium | Work In Progress | Band Truck | | | 10/21/2009 3:45:40 PM | | | | |
| Gonzales, Angel | | Complete Vehicle Service on Bandtruck # 127. | | | | | | | |
| Frank Rivera | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days | Labor | Total |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|------|-------|-------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | Aged | Hours | Costs |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa HS

| | | | | | | | | | |
|-------|--|----------------|--|--|------------|--|----|--|--------|
| 51658 | | Athletic Field | | | 10/22/2009 | | 75 | | \$0.00 |
|-------|--|----------------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|-----------------------|--|--|--|--|
| High | Work In Progress | | | | 10/22/2009 3:34:50 PM | | | | |
|------|------------------|--|--|--|-----------------------|--|--|--|--|

Prospero, Manuel
sidewalk west of the press box has collapsed, need to remove section of concrete and pour new one. this is a ADA issue. student on wheel chair uses this side walk. please call mike to coordinate. thanks

Michael Munoz

| | | | | | | | | | |
|-------|---------|---------|--|--|------------|--|----|--|--------|
| 51682 | Library | Library | | | 10/23/2009 | | 74 | | \$0.00 |
|-------|---------|---------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|---------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | Library | | | 10/23/2009 7:36:59 AM | | | | |
|--------|------------------|---------|--|--|-----------------------|--|--|--|--|

Nunez, Arturo
Hang large wall screen and install ceiling mounted LCD projector with security cage.

Luis Calleros

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51793 | | | | | 10/26/2009 | | 71 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/26/2009 3:57:45 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ambriz, Jose
NEED SOME ASSISTANCE ON WATER HEATER AT CAFETERIA, LEAKING WATER. SEEMS TO BE FROM COILS ABOVE BURNERS DRAINED WATER.

Arturo Nunez

| | | | | | | | | | |
|-------|---------------|---------|--|--|------------|--|----|--|--------|
| 51829 | Main Building | Library | | | 10/27/2009 | | 70 | | \$0.00 |
|-------|---------------|---------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/27/2009 2:45:46 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Nunez, Arturo
Mount media projector in the library. Please see Mary Albert for specific instructions on where in the library media projector will be mounted.

Phillip Medina

| | | | | | | | | | |
|-------|-------------|-----|--|--|------------|--|----|--|--------|
| 51872 | Locker Room | Gym | | | 10/28/2009 | | 69 | | \$0.00 |
|-------|-------------|-----|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|----------------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | Wrestling Room | | | 10/28/2009 9:27:20 AM | | | | |
|--------|------------------|----------------|--|--|-----------------------|--|--|--|--|

Prospero, Manuel
Remove two storage shelves from wrestling storage and place them in Coach Bennetts' volleyball office. See Coach Douglas or Coach Bennett.

Luis Calleros

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51883 | | | | | 10/28/2009 | | 69 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | COACH | | | 10/28/2009 1:41:45 PM | | | | |
|--------|------------------|-------|--|--|-----------------------|--|--|--|--|

Valdez, Pedro
AERATE THE INFIELD AND RESEED WITH WINTER RYE.

Marylou Jimenez

| | | | | | | | | | |
|-------|-----------|-----|--|--|------------|--|----|--|--------|
| 51915 | Gymnasium | Gym | | | 10/29/2009 | | 68 | | \$0.00 |
|-------|-----------|-----|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/29/2009 7:59:30 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ambriz, Jose
10/29/09. WE NEED TO REPLACE HEATERS. THER ARE ON BED CONDITIONS.

Manuel Prospero

1/5/2010 12:27:04 PM

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa HS

| | | | | | | | | | |
|-------|--|--|--|--|-----------|-----------|----|--|--------|
| 52025 | | | | | 11/1/2009 | 11/7/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|-----------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:48 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Nunez, Arturo
Monthly - Santa Teresa HS Monthly FE Inspection -
Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52052 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:57 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny
Monthly - Santa Teresa HS Fire Suppression Insp. -
Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|----------------|-----------|--|--|-----------|--|----|--|--------|
| 52217 | Annex Building | Classroom | | | 11/3/2009 | | 63 | | \$0.00 |
|-------|----------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|------------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Portable 55 - 56 | | | 11/3/2009 3:30:04 PM | | | | |
|--------|------------------|------------------|--|--|----------------------|--|--|--|--|

Estrada, Jesus
Replace broken tiles (floor) at both ends

Luis Calleros

| | | | | | | | | | |
|-------|----------------|-----------|--|--|-----------|--|----|--|--------|
| 52221 | Annex Building | Classroom | | | 11/3/2009 | | 63 | | \$0.00 |
|-------|----------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | 55-56 | | | 11/3/2009 3:32:08 PM | | | | |
|--------|------------------|-------|--|--|----------------------|--|--|--|--|

Prospero, Manuel
Replace all stained ceiling tiles in Child Care Center

Luis Calleros

| | | | | | | | | | |
|-------|---------------|----------------|--|--|-----------|--|----|--|--------|
| 52229 | Main Building | Athletic Field | | | 11/3/2009 | | 63 | | \$0.00 |
|-------|---------------|----------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Soccer field | | | 11/3/2009 3:43:45 PM | | | | |
|--------|------------------|--------------|--|--|----------------------|--|--|--|--|

Ontiveros, Guadalupe
Remove old weathered nylon netting behind the North
and South Goals
Replace with non-weathering chain link fence or other
metal based fencing

Luis Calleros

| | | | | | | | | | |
|-------|-----------------|-----------|--|--|-----------|--|----|--|--------|
| 52234 | Applied Science | Classroom | | | 11/3/2009 | | 63 | | \$0.00 |
|-------|-----------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-----------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | 21 and 22 | | | 11/3/2009 3:47:57 PM | | | | |
|--------|------------------|-----------|--|--|----------------------|--|--|--|--|

Nunez, Arturo
can we please install cork strips between room 21 and
22 to hang student projects; i.e., duct tape and other
adhesives to not last very long on cinder block walls

Luis Calleros

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52419 | | | | | 11/8/2009 | 11/24/2009 | 58 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/8/2009 12:19:06 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Prospero, Manuel
Monthly - Santa Teresa HS Playground Insp - Refer to
PM schedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|--------------------|------------------|--|--|--|-----------------------|---|----|--|--------|
| Location: | | Santa Teresa HS | | | | | | | |
| 52541 | | | | | 11/12/2009 | | 54 | | \$0.00 |
| Medium | Work In Progress | | | | 11/12/2009 8:10:44 AM | | | | |
| Carrasco, Danny | | NEED TO BORROW LIFT TO INSTALL SCREEN IN LIBRARY | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| 52570 | | | | | 11/12/2009 | | 54 | | \$0.00 |
| Medium | Work In Progress | MR. | | | 11/12/2009 2:32:18 PM | | | | |
| Castillo, Carlos | | ELECTRICAL OUTLET NOT FUNCTIONING. WE NEED IT FOR THE COMPUTER. | | | | | | | |
| Marylou Jimenez | | | | | | | | | |
| 52584 | | | | | 11/12/2009 | | 54 | | \$0.00 |
| Medium | Work In Progress | MR. | | | 11/12/2009 4:18:19 PM | | | | |
| Castillo, Carlos | | ELECTRICAL OUTLETS IN OFFICE DO NOT WORK. | | | | | | | |
| Marylou Jimenez | | | | | | | | | |
| 52749 | Main Building | Classroom | | | 11/17/2009 | | 49 | | \$0.00 |
| Medium | Work In Progress | Room # 6 | | | 11/17/2009 6:55:44 PM | | | | |
| Prospero, Manuel | | Replace two broken tiles in front of classroom. There exists a hole where a tile is missing, which causes a person to trip. | | | | | | | |
| Luis Calleros | | | | | | | | | |
| 52857 | Gymnasium | | | | 11/20/2009 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | | 11/20/2009 1:34:01 PM | | | | |
| Ambriz, Jose | | WE NEED TO CHANGED 2 EXAUST FAN MOTOR ON GYM AREA. CAT NO SOO3. MOD. AVM48S17D2089. FR-48 PH 1 TYPE-SS. AMB-40CINS B3 DUTY-CONT 01606940 120203 HZ 60 HP 1/4 RPM1725 VOLT 115. | | | | | | | |
| Manuel Prospero | | | | | | | | | |
| 53048 | Cafeteria (2005) | Cafeteria | | | 12/2/2009 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | | 12/2/2009 7:41:33 AM | | | | |
| Nunez, Arturo | | STRIPPING FROM CERAMIC TILE NEEDS TO BE GLUED DOWN TO FLOOR IN CAFETERIA THANK YOU. | | | | 12/2/09 - AS PER CHUY, ROUTE TO BLDG MECHANIC | | | |
| Luis Murillo | | | | | | | | | |
| 53221 | | | | | 12/6/2009 | 12/27/2009 | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:20:33 AM | | | | |
| Orozco, Danny | | Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|----------------------|------------------|---|--|--|-----------------------|------------|----|--|--------|
| Location: | | Santa Teresa HS | | | | | | | |
| 53280 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:20:55 AM | | | | |
| Prospero, Manuel | | Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 53281 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:20:55 AM | | | | |
| Prospero, Manuel | | Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 53282 | | | | | 12/6/2009 | 1/6/2010 | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:20:56 AM | | | | |
| Prospero, Manuel | | Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 53312 | Main Building | Classroom | | | 12/7/2009 | | 29 | | \$0.00 |
| Medium | Work In Progress | | | | 12/7/2009 7:41:44 AM | | | | |
| Castillo, Carlos | | As per Art Nunez, room 609 lights not working. | | | | | | | |
| Carlos Castillo | | | | | | | | | |
| 53355 | | | | | 12/7/2009 | | 29 | | \$0.00 |
| Medium | Work In Progress | Soccer field | | | 12/7/2009 3:39:43 PM | | | | |
| Ontiveros, Guadalupe | | Please paint four (4) 3 vs 3 soccer fields, each 30 yds. X 40 yards long on the curent field. Fiel for Spring Fund raising tournament | | | | | | | |
| Luis Calleros | | | | | | | | | |
| 53529 | | | | | 12/11/2009 | | 25 | | \$0.00 |
| Medium | Work In Progress | | | | 12/11/2009 3:05:05 PM | | | | |
| Lara, Ralph | | NEED TO SEE IF IT WOULD BE POSSIBLE TO INSTALL A WINDOW GUARD ON ROOM # 22, FOR SECURITY PURPOSES | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| 53556 | | | | | 12/13/2009 | 12/29/2009 | 23 | | \$0.00 |
| Medium | Work In Progress | | | | 12/13/2009 12:18:56 | | | | |
| Prospero, Manuel | | Monthly - Santa Teresa HS Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa HS

| | | | | | | | | | |
|-------------------|------------------|--------------------------------------|--|--|---------------------|--|----|--|--------|
| 53570 | | Cafeteria | | | 12/14/2009 | | 22 | | \$0.00 |
| Medium | Work In Progress | | | | 12/14/2009 11:53:44 | | | | |
| Moncayo, Fernando | | DISHWASHER IS LEAKING ALOT OF WATER. | | | | | | | |
| | | OLGA B. SNP MGR 589-5332 | | | | | | | |

Jacqueline Aguilar

| | | | | | | | | | |
|------------------|------------------|---|--|--|-----------------------|---|----|--|--------|
| 53649 | | | | | 12/16/2009 | | 20 | | \$0.00 |
| Medium | Work In Progress | MS. | | | 12/16/2009 8:52:21 AM | | | | |
| Castillo, Carlos | | INTERNET LINKING LINES NEEDED FOR ALL COMPUTERS IN THE ROOM. CURRENTLY, THERE IS ONLY ONE OUTLET. | | | | NEED ELECTRICAL OUTLET - PLEASE CALL SILVER IS YOU HAVE ANY QUESTIONS | | | |

Marylou Jimenez

| | | | | | | | | | |
|-------------|------------------|--|--|--|----------------------------|--|----|-----|---------|
| 53704 | | | | | 12/17/2009 | | 19 | 1.5 | \$43.50 |
| Medium | Work In Progress | | | | 12/17/2009 10:20:49 | | | | |
| Lara, Ralph | | WE NEED KEYS MADE FOR MR PORTILLO CLASSROOM FOR SOME CABINETS. | | | MADE KEYS FOR MR. PORTILLO | | | | |

Manuel Prospero

| | | | | | | | | | |
|----------------------|------------------|---|--|--|---------------------|--|----|--|--------|
| 53748 | | | | | 12/20/2009 | | 16 | | \$0.00 |
| Medium | Work In Progress | | | | 12/20/2009 12:18:38 | | | | |
| Ontiveros, Guadalupe | | Monthly - Santa Teresa HS Soil Sampling - Refer to PM schedule details. | | | | | | | |

Margret Villalobos

| | | | | | | | | | |
|------------------------------|--|----------------------------|--|--|--|----------------------------------|------------|--|----------------|
| Count: 60 Work Orders | | Avg. Age of WO's 80 | | | | Total for Santa Teresa HS | 1.5 | | \$43.50 |
|------------------------------|--|----------------------------|--|--|--|----------------------------------|------------|--|----------------|

Location: Santa Teresa MS

| | | | | | | | | | |
|-------------------|------------------|--|--|--|----------------------|--|-----|--|--------|
| 49445 | | | | | 8/28/2009 | | 130 | | \$0.00 |
| Medium | Work In Progress | | | | 8/28/2009 3:36:39 PM | | | | |
| Villalobos, David | | Need to coordinate w/Bldg Mechanic on proper training for newer water heaters. | | | | | | | |

Michael Munoz

| | | | | | | | | | |
|----------------|------------------|--|--|--|---------------------|--|-----|--|--------|
| 47070 | | | | | 7/1/2009 | | 188 | | \$0.00 |
| Medium | Work In Progress | | | | 7/1/2009 7:23:52 AM | | | | |
| Mijarez, Jaime | | 6/18/09 .50 Sign in and fill out paper work. 1.0 Troubleshoot thru tracer sum mit. 4.5 S.bldg office heat pump 74. 3.0 w/o 46585 N.bldg electrical room mini split system. .50 Fillout paper work. .50 lockup buildings. | | | 6/18-6 | | | | |

Jaime Mijarez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa MS

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47553 | | | | | 7/15/2009 | | 174 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/15/2009 1:29:49 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ambriz, Jose Storage Room - Asp Mike Soria need some kind of ventilation in this area, it is extremely hot in there.

Mike Soria

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47820 | | | | | 7/24/2009 | | 165 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/24/2009 3:16:14 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Gonzales, Angel Truck 121. The brakes need to be worked on they are sounding real bad. Thank you.

Jaime Mijarez

| | | | | | | | | | |
|-------|----------------|--|--|--|----------|--|-----|--|--------|
| 48425 | North Building | | | | 8/6/2009 | | 152 | | \$0.00 |
|-------|----------------|--|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | AREA | | | 8/6/2009 10:06:23 AM | | | | |
|--------|------------------|------|--|--|----------------------|--|--|--|--|

Soria, Mike AREA BETWEEN TWO BUILDINGS HAS WEEDS THAT NEED TO BE REMOVED.

Laura Parra

| | | | | | | | | | |
|-------|----------------|-----------|--|--|----------|--|-----|--|--------|
| 48426 | North Building | Custodial | | | 8/6/2009 | | 152 | | \$0.00 |
|-------|----------------|-----------|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/6/2009 10:36:16 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Flores, Pete Pete one of the gas blowers is not working the string got of the rail.And i needed for the southbuilding thank you.

Ismael Rodriguez

| | | | | | | | | | |
|-------|------------|-----|--|--|-----------|--|-----|--|--------|
| 48761 | Gym (1997) | Gym | | | 8/13/2009 | | 145 | | \$0.00 |
|-------|------------|-----|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/13/2009 10:09:34 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Lara, Ralph As per Mr. TonyEnciso is requesting handi-cap devices on all doors in the gym.

Jaime Mijarez

| | | | | | | | | | |
|-------|----------------|--------------|--|--|-----------|--|-----|--|--------|
| 49033 | South Building | Computer Lab | | | 8/19/2009 | | 139 | | \$0.00 |
|-------|----------------|--------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 8/19/2009 3:19:50 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Castillo, Carlos S.bldg lower level rooms S-36-Aand S-36-B. Circuit is tripping because there is to many computers in room S-36-Aand causing to lose power in room S-36-B.

Jaime Mijarez

| | | | | | | | | | |
|-------|--|-----------|--|--|----------|--|-----|--|--------|
| 49634 | | Cafeteria | | | 9/3/2009 | | 124 | | \$0.00 |
|-------|--|-----------|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/3/2009 10:13:22 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Orozco, Danny DRY STORAGE EXHAUST FAN NOT WORKING

Danny Orozco

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa MS

| | | | | | | | | | |
|-------|--|--|--|--|----------|--|-----|--|--------|
| 49682 | | | | | 9/3/2009 | | 124 | | \$0.00 |
|-------|--|--|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | SANTA | | | 9/3/2009 4:58:50 PM | | | | |
|--------|------------------|-------|--|--|---------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|
| Martinez, Larry | | DELIVERY OF 1 BOX FOR SANTA TERESA MIDDLE | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------------|--|--|--|--|--|--|--|--|--|
| Mary Garcia | | | | | | | | | |
|-------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|----------------|-----------|--|--|----------|--|-----|--|--------|
| 49835 | North Building | Custodial | | | 9/8/2009 | | 119 | | \$0.00 |
|-------|----------------|-----------|--|--|----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/8/2009 11:48:07 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|
| Gonzales, Angel | | The truck bed needs to be welded or be replace it is loose and unsafe th truck number is #39. | | | | | | | |
|-----------------|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|
| Ismael Rodriguez | | | | | | | | | |
|------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|----------------|-----------|--|--|-----------|--|-----|--|--------|
| 49925 | North Building | Cafeteria | | | 9/10/2009 | | 117 | | \$0.00 |
|-------|----------------|-----------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/10/2009 10:20:01 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|-------------|--|---|--|--|--|--|--|--|--|
| Lara, Ralph | | Cafeteria exterior exit door. As per Mrs. Yvonne Casillas she want's a dead bolt lock installed on door. Joe Laguna from architectural products recommends a Schlage Mortise Indecader Lock instead of the dead bolt. Mike it is an exit door and there are exit signs indicating that there is and exit. | | | | | | | |
|-------------|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Jaime Mijarez | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|-------------|--|--|-----------|--|-----|--|--------|
| 50483 | | Parking Lot | | | 9/24/2009 | | 103 | | \$0.00 |
|-------|--|-------------|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/24/2009 1:40:21 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|
| Mijarez, Jaime | | Parking lot. Install no pets allowed signs. | | | | | | | |
|----------------|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Jaime Mijarez | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|------------|--|--|--|-----------|--|----|--|--------|
| 50581 | Gym (1997) | | | | 9/28/2009 | | 99 | | \$0.00 |
|-------|------------|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/28/2009 2:00:08 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|------------------|--|---|--|--|--|--|--|--|--|
| Castillo, Carlos | | Gym light. One of the plastic light covers is broken. | | | | | | | |
|------------------|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Jaime Mijarez | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50884 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:06 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Orozco, Danny | | Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PMs schedule details. | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|
| Margret Villalobos | | | | | | | | | |
|--------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 51034 | | | | | 10/5/2009 | | 92 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/5/2009 9:19:18 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|---|--|--|--|---------------------------------------|--|--|--|
| Mijarez, Jaime | | David i am going to need 4 ea. fountain bubbler cartridges I used my last one on 10/05/09. I already sent the order to Ruben. | | | | 10/9 - Route to Jaime to complete. RR | | | |
|----------------|--|---|--|--|--|---------------------------------------|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Jaime Mijarez | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa MS

| | | | | | | | | | |
|-------|--|----------------|--|--|-----------|--|----|--|--------|
| 51132 | | Athletic Field | | | 10/6/2009 | | 91 | | \$0.00 |
|-------|--|----------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/6/2009 2:49:57 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Gonzalez, Salvador Soccer and football fields. Can you please build doors and install them where the entrance and exits are to the fields. Security wants those areas closed when there are games and people won't go in with out paying.

Jaime Mijarez

| | | | | | | | | | |
|-------|----------------|--|--|--|-----------|--|----|--|--------|
| 51137 | South Building | | | | 10/6/2009 | | 91 | | \$0.00 |
|-------|----------------|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/6/2009 3:11:27 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Gonzalez, Salvador S.bldg black gate. One of the black gates swinging door, leg broke off, needs to be re-welded.

Jaime Mijarez

| | | | | | | | | | |
|-------|----------------|--|--|--|-----------|--|----|--|--------|
| 51195 | South Building | | | | 10/8/2009 | | 89 | | \$0.00 |
|-------|----------------|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/8/2009 8:51:02 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Soria, Mike Mr.Soria to clear the weeds behind southbuilding as per Ms.Casillas.thank you.

Ismael Rodriguez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52053 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:57 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Santa Teresa MS Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|----------------|-----------|--|--|-----------|--|----|--|--------|
| 52141 | North Building | Custodial | | | 11/2/2009 | | 64 | | \$0.00 |
|-------|----------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/2/2009 11:36:37 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Gonzales, Angel Pete, the truck #39 needs a tire replace it is in bad shape i always have to put air on it.Thank You.

Ismael Rodriguez

| | | | | | | | | | |
|-------|----------------|------------------|--|--|-----------|--|----|--|--------|
| 52367 | North Building | Restroom (Girls) | | | 11/6/2009 | | 60 | | \$0.00 |
|-------|----------------|------------------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/6/2009 11:36:13 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Castillo, Carlos Cali, as per Ms.Lovlace wants for you to put a electrical outlet in her private restroom theres any outlets.Thankyou.

Ismael Rodriguez

| | | | | | | | | | |
|-------|----------------|--|--|--|-----------|--|----|--|--------|
| 52432 | South Building | | | | 11/9/2009 | | 57 | | \$0.00 |
|-------|----------------|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/9/2009 8:56:29 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ambriz, Jose S.bldg Choir room office heat pump has a fualtyhi pressure switch that is causing compressor contactor to open and close contantly.

Jaime Mijarez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days | Labor | Total |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|------|-------|-------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | Aged | Hours | Costs |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa MS

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52755 | | | | | 11/18/2009 | | 48 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/18/2009 9:02:46 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ambriz, Jose Cafeteria. Need to replace existing water fountain with a handi-cap type water fountain.

Jaime Mijarez

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52765 | | | | | 11/18/2009 | | 48 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/18/2009 1:35:15 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ambriz, Jose S.bldg ramp heat pump. Motor is giving out will need to order one so i can install it.

Jaime Mijarez

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52766 | | | | | 11/18/2009 | | 48 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/18/2009 1:39:34 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Gonzales, Angel Gulf cart. Cart has a rear flat tire that might be damaged. Tire needs to be replaced.

Jaime Mijarez

| | | | | | | | | | |
|-------|------------|-----------|--|--|-----------|--|----|--|--------|
| 53056 | Gym (1997) | Custodial | | | 12/2/2009 | | 34 | | \$0.00 |
|-------|------------|-----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/2/2009 1:57:05 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Lara, Ralph Rafa, a door to the main entrance to the gym needs a new panic bar it doesnt close and we need to secure the gym

Ismael Rodriguez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 53258 | | | | | 12/6/2009 | 12/12/2009 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:47 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Mijarez, Jaime Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PMSchedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|----------|----|--|--------|
| 53259 | | | | | 12/6/2009 | 1/6/2010 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|----------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:47 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Mijarez, Jaime Monthly - Santa Teresa MS Bleacher Inspection - Refer to PMSchedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 53260 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:48 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Mijarez, Jaime Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PMSchedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Santa Teresa MS

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 53261 | | | | | 12/6/2009 | 12/14/2009 | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:48 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Mijarez, Jaime Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53262 | | | | | 12/6/2009 | | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:48 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Mijarez, Jaime Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|----------------|-----------|--|--|------------|--|----|--|--------|
| 53608 | North Building | Custodial | | | 12/15/2009 | | 21 | | \$0.00 |
|-------|----------------|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/15/2009 9:03:13 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Guadalupe Lupe, i will be needing the trailer on this dates 12-16-09&12-17-09 for lunch delivery.thank you.

Ismael Rodriguez

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|---|--|--------|
| 53751 | | | | | 12/31/2009 | | 5 | | \$0.00 |
|-------|--|--|--|--|------------|--|---|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/31/2009 12:20:49 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Mijarez, Jaime Yearly - Santa Teresa MS H6(Roof Furnace)(Yearly) - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|------------------------------|--|--|----------------------------|--|--|----------------------------------|----------|--|---------------|
| Count: 34 Work Orders | | | Avg. Age of WO's 88 | | | Total for Santa Teresa MS | 0 | | \$0.00 |
|------------------------------|--|--|----------------------------|--|--|----------------------------------|----------|--|---------------|

Location: Sunland Park ES

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47646 | | | | | 7/21/2009 | | 168 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/21/2009 8:06:31 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Herrera, Joel MR. HERRERA OUTSIDE GRASS INCLUDING SOCCER FIELD IS DRY. PLEASE CHECK SPRINKLER SYSTEM. RUN MANUALLY IS NEEDED.

Jessica Lopez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 47647 | | | | | 7/21/2009 | | 168 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 7/21/2009 8:08:04 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Herrera, Joel MR. HERRERA PLEASE PAINT CUSTODIAN'S STORAGE ROOMS.

Jessica Lopez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Sunland Park ES

47648 7/21/2009 168 \$0.00

Medium Work In Progress 7/21/2009 8:10:09 AM

Herrera, Joel MR. HERRERA PLEASE REPLACE ALL OUTSIDE
BROKEN TILES.
3RD REQUEST.
SAFETY HAZARD

Jessica Lopez

47649 7/21/2009 168 \$0.00

Medium Work In Progress 7/21/2009 8:16:21 AM

Herrera, Joel MR. HERRERA PLEASE PAINT OUTSIDE
PORTABLES.
4TH YEAR REQUEST.
LAST REQUEST WAS ENTERED ON 3/18.09

Jessica Lopez

47650 7/21/2009 168 \$0.00

Medium Work In Progress 7/21/2009 8:17:27 AM

Herrera, Joel MR. HERRERA PLEASE PAINT PLANTERS LOCATED
AT THE MAIN ENTRANCE.
2ND REQUEST

Jessica Lopez

47931 7/28/2009 161 \$0.00

Medium Work In Progress ROOM # 40 7/28/2009 2:26:02 PM

Lara, Ralph MS. ALARCON NEEDS A KEY TO LOCK HER
CABINET.
TAG # N/A
DOUBLE DOOR CABINET
LOCATION: ROOM # 40

Jessica Lopez

49343 8/26/2009 132 \$0.00

Medium Work In Progress 8/26/2009 7:50:47 PM

Gonzales, Angel I HAVE PROBLEMS WITH MY WEEDEATER IT
DOESNT WORK

Joel Herrera

49580 9/2/2009 125 \$0.00

High Work In Progress 9/2/2009 10:08:28 AM

Herrera, Joel as per our discussion, please remve cattails and repair
water leak. if assistance is needed for the repair please
call me (mike) so i maysupport.
thanks

Michael Munoz

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Sunland Park ES

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50195 | | | | | 9/16/2009 | | 111 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/16/2009 3:25:30 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Herrera, Joel MR. HERRERA PLEASE CHECK MS. GAMBOA'S ROOM IT LEAKS WHEN IT RAINS.

Jessica Lopez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50198 | | | | | 9/16/2009 | | 111 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|----|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | 32 | | | 9/16/2009 3:28:58 PM | | | | |
|--------|------------------|----|--|--|----------------------|--|--|--|--|

Herrera, Joel MR. HERRERA ROOM # 32 BATHROOM SINK IS FALLING

Jessica Lopez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 50811 | | | | | 10/2/2009 | | 95 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/2/2009 3:43:13 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Ambriz, Jose WE NEED REPLACE MASTERCOOL 65 AT CLASS ROOM #24

Joel Herrera

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50885 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:06 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|----------|--|--|-----------|--|----|--|--------|
| 51241 | | Restroom | | | 10/8/2009 | | 89 | | \$0.00 |
|-------|--|----------|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|------------------|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | Outside of Port: | | | 10/8/2009 6:17:49 PM | | | | |
|--------|------------------|------------------|--|--|----------------------|--|--|--|--|

Herrera, Joel Arreglar la Pared del Bano y la esquina tiene un Abujero en el shirock.

Baudelio De Santiago

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51635 | | | | | 10/22/2009 | | 75 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/22/2009 1:50:43 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Herrera, Joel 10-22-09 I NEED 3 = 1 1/2 INCHES SPUDS COMODE TO REPLACE REST ROOMS

Joel Herrera

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51697 | | | | | 10/23/2009 | | 74 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | OFFICE | | | 10/23/2009 8:49:44 AM | | | | |
|--------|------------------|--------|--|--|-----------------------|--|--|--|--|

Munoz, Michael PLEASE REDO RECEPTIONIST AREA

Jessica Lopez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Sunland Park ES

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51801 | | | | | 10/27/2009 | | 70 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/27/2009 8:07:54 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Herrera, Joel
 LOCATION: HALL WAYS
 TWO OF OUR CAMERA MOUNTS ARE BROKEN
 CAMERA ARE NOT TAKING GOOD VIDEO

Jessica Lopez

| | | | | | | | | | |
|-------|--|----------------|--|--|------------|--|----|--|--------|
| 51904 | | Athletic Field | | | 10/28/2009 | | 69 | | \$0.00 |
|-------|--|----------------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/28/2009 3:57:50 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Herrera, Joel
 joel the wind screen on the south fence by the soccer field need to be secured from the top to prevent further damage.
 please order hog ties from the maint dept and take care of this .thanks

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51910 | | | | | 10/28/2009 | | 69 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/28/2009 4:10:49 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Herrera, Joel
 joel. the dirt area where bobbyscraped is ready for another scrapping. i was w/you when we did it. please continue and finish this. use the truck and scraper. if this is done done the weeds are going to take over. this should be done a minimum of once a month.thank you

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52054 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:58 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny
 Monthly- Sunland Park ES Fire Suppression Insp. -
 Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52511 | | | | | 11/10/2009 | | 56 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--------|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | OFFICE | | | 11/10/2009 12:47:57 | | | | |
|--------|------------------|--------|--|--|---------------------|--|--|--|--|

Herrera, Joel
 MR. HERRERA PLEASE REPLACE DOOR STOPPER
 LOCATION: OFFICE

Jessica Lopez

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52585 | | | | | 11/12/2009 | | 54 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|-------------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | LIBRARY/COM | | | 11/12/2009 4:22:50 PM | | | | |
|--------|------------------|-------------|--|--|-----------------------|--|--|--|--|

Herrera, Joel
 MR. HERRERA PLEASE MOVE INFOCUS CEILING MOUNT LOCATED IN THE LIBRARY TO THE COMPUTER LAB. INSTAL NEW CEILING MOUNT IN THE LIBRARY.

Jessica Lopez

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Sunland Park ES

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52642 | | | | | 11/16/2009 | | 50 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--------|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | OFFICE | | | 11/16/2009 8:32:20 AM | | | | |
|--------|------------------|--------|--|--|-----------------------|--|--|--|--|

Herrera, Joel
MR. HERRERA OFFICE SINK IS NOT WORKING
PROPERLY PLEASE REPLACE WITH DELTA SINK
FAUCET

Jessica Lopez

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52658 | | | | | 11/16/2009 | | 50 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/16/2009 11:29:33 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Ambriz, Jose
LIBRARY HEATING UNIT IT DOESNT WORKING
WELL

Joel Herrera

| | | | | | | | | | |
|-------|--|-------------|--|--|------------|--|----|--|--------|
| 52945 | | Parking Lot | | | 11/26/2009 | | 40 | | \$0.00 |
|-------|--|-------------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/26/2009 12:16:06 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Gonzales, Angel
Requesting pick-up of blower for repair
12/4/09 - ROUTE TO ANGEL AS PER
JIMMY, HE DOES NOT REPAIR
BLOWERS.

Baudelio De Santiago

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53010 | | | | | 12/1/2009 | | 35 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/1/2009 11:14:19 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ambriz, Jose
WE NEED REPLACE KITCHEN'S HEATING UNIT
THERMOSTAT THANK YOU MR.AMBRIZ

Joel Herrera

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53504 | | | | | 12/11/2009 | | 25 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/11/2009 7:26:30 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ambriz, Jose
MR. AMBRIZ I NEED THE ACS COVERS THANK
YOU

Joel Herrera

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53596 | | | | | 12/14/2009 | | 22 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/14/2009 4:17:02 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Guadalupe
Remove existing dirt around new valve that was
installed, and fill holes w/sand around school site.

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53645 | | | | | 12/16/2009 | | 20 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/16/2009 8:10:40 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Guadalupe
LUPE WE NEED CUT AND PICKUP OLD BIG TREE
DROP THROUGH STRONG WING LAST WEEK
THANK YOU....

Joel Herrera

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Sunland Park ES

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53655 | | | | | 12/16/2009 | | 20 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/16/2009 11:09:41 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Villalobos, David DAVID WE NEED TO REPLACE WATER HEATERS
AT MAIN OFFICE AND CUSTODIANS CLOSET

Joel Herrera

| | | | | |
|------------------------------|----------------------------|----------------------------------|----------|---------------|
| Count: 29 Work Orders | Avg. Age of WO's 88 | Total for Sunland Park ES | 0 | \$0.00 |
|------------------------------|----------------------------|----------------------------------|----------|---------------|

Location: Sunrise ES

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 50736 | | | | | 10/1/2009 | | 96 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/1/2009 2:32:10 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Gonzales, Angel truck # 156 need complete service and tires

Juan Vargas

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50886 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:07 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Sunrise ES Range Hood Cleaning - Refer to
PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51380 | | | | | 10/13/2009 | | 84 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/13/2009 2:13:08 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Martinez, Larry On October 21, 2009, please deliver 40 boxes of HP
Computers (Towers and Monitors) plus computer
accessories to Sunrise Elementary.

Yolie Jacquez

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52055 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:58 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Sunrise ES Fire Suppression Insp. - Refer to
PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53266 | | | | | 12/6/2009 | | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:50 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Vargas, Juan Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM
schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53267 | | | | | 12/6/2009 | | 30 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/6/2009 12:20:50 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Vargas, Juan Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM
schedule details.

Margret Villalobos

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WIOD | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| Location: | | Sunrise ES | | | | | | | |
|------------------------------|------------------|--|--|-----------|-----------------------------|------------|----|----------|---------------|
| 53268 | | | | | 12/6/2009 | | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:20:51 AM | | | | |
| Vargas, Juan | | Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 53269 | | | | | 12/6/2009 | | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:20:51 AM | | | | |
| Vargas, Juan | | Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 53270 | | | | | 12/6/2009 | 12/12/2009 | 30 | | \$0.00 |
| Medium | Work In Progress | | | | 12/6/2009 12:20:51 AM | | | | |
| Vargas, Juan | | Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 53555 | | | | | 12/13/2009 | 12/29/2009 | 23 | | \$0.00 |
| Medium | Work In Progress | | | | 12/13/2009 12:18:56 | | | | |
| Vargas, Juan | | Monthly - Sunrise ES Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 10 Work Orders | | Avg. Age of WO's | | 51 | Total for Sunrise ES | | | 0 | \$0.00 |

| Location: | | Vado ES | | | | | | | |
|----------------------|------------------|--|--|--|-----------------------|--|-----|--|--------|
| 48098 | | | | | 7/31/2009 | | 158 | | \$0.00 |
| Medium | Work In Progress | | | | 7/31/2009 10:23:46 AM | | | | |
| Ontiveros, Guadalupe | | NEED TRACTOR AND DISKS FOR BACK PONDING AREA | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 49012 | | | | | 8/19/2009 | | 139 | | \$0.00 |
| Medium | Work In Progress | | | | 8/19/2009 11:52:30 AM | | | | |
| Miranda, Danny | | need two wood 4"x4"x8' to build ramp for mower | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 49016 | | | | | 8/19/2009 | | 139 | | \$0.00 |
| Medium | Work In Progress | | | | 8/19/2009 11:59:38 AM | | | | |
| Miranda, Danny | | need 5 gal. wt. paint for (classroom's and hallways (DUNN-EDWARDS HAS COLOR ON FILE) | | | | | | | |
| Danny Miranda | | | | | | | | | |

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Vado ES

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|-----|--|--------|
| 50316 | | | | | 9/21/2009 | | 106 | | \$0.00 |
|-------|--|--|--|--|-----------|--|-----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/21/2009 11:28:15 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Ontiveros, Guadalupe please get quote to bore ponds for water to flow in the front campus. please see mike. thanks

Michael Munoz

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 50590 | | | | | 9/28/2009 | | 99 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/28/2009 3:25:58 PM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Gonzales, Angel International Tractor with Mower - Repair and deliver to Danny Miranda for use at Vado Elem.

Alfredo Holguin

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 50609 | | | | | 9/29/2009 | | 98 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 9/29/2009 7:51:07 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

Sotelo, Enrique NEED NEW HAND DRYER IN GIRLS R.R. 300-WING

Danny Miranda

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50887 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:07 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 50889 | | | | | 10/4/2009 | 10/25/2009 | 93 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/4/2009 12:22:08 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.

Margret Villalobos

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 51203 | | | | | 10/8/2009 | | 89 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/8/2009 10:26:51 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Miranda, Danny NEED EXHAUST FAN MOTORS FOR HALLWAYS

Danny Miranda

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 51814 | | | | | 10/27/2009 | | 70 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 10/27/2009 11:17:48 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

Orozco, Danny NEED TO GET FIRE EXTINGUISHERS SERVICED

Danny Orozco

| | | | | | | | | | |
|-------|--|--|--|--|-----------|------------|----|--|--------|
| 52056 | | | | | 11/1/2009 | 11/22/2009 | 65 | | \$0.00 |
|-------|--|--|--|--|-----------|------------|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/1/2009 12:22:58 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

Orozco, Danny Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

1/5/2010 12:27:05 PM

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

Location: Vado ES

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 52345 | | | | | 11/6/2009 | | 60 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/6/2009 7:32:23 AM | | | | |
|--------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|
| Miranda, Danny | | NEED 2 GALLONS OF PAINT FOR CAFETERIA (W6250 VERSASATIN) | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Danny Miranda | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52508 | | | | | 11/10/2009 | | 56 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/10/2009 11:08:07 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|
| Ontiveros, Joe | | NEED TO CK WATER LEAK ON WATER FOUNTAIN IN FRONT ENTERANCE I CAN NOT REPAIR OR STOP IT | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Danny Miranda | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 52853 | | | | | 11/20/2009 | | 46 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|
| Medium | Work In Progress | | | | 11/20/2009 10:03:51 | | | | |
|--------|------------------|--|--|--|---------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|
| Miranda, Danny | | NEED TO REPLACE BLOWER MOTORS IN COM. RM,S 100 AND 200-WINGS | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Danny Miranda | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53100 | | | | | 12/3/2009 | | 33 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|
| High | Work In Progress | | | | 12/3/2009 7:31:13 AM | | | | |
|------|------------------|--|--|--|----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|
| Solis, Lorenzo | | as per converstion and meeting held w/boyd, gallegos, john fiend. please flush all systems that are on geo thermal and fill back up w/ domestic water. the system is filled up now w/ well water causing metal fittings ie nipples, elbows etc to corode.thank you | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Michael Munoz | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|-----------|--|----|--|--------|
| 53123 | | | | | 12/3/2009 | | 33 | | \$0.00 |
|-------|--|--|--|--|-----------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/3/2009 12:08:23 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|----------------------|--|--|--|--|--|--|--|--|--|
| Ontiveros, Guadalupe | | NEED TO PUT IN BETTER DRAINAGE ON POND BY BUSS TURN AROUND | | | | | | | |
|----------------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Danny Miranda | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|--|--|--|--|------------|--|----|--|--------|
| 53581 | | | | | 12/14/2009 | | 22 | | \$0.00 |
|-------|--|--|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/14/2009 3:18:12 PM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|---------------|--|---|--|--|--|--|--|--|--|
| Lozoya, Manny | | need to repair hing and hing plate to double doors in gym | | | | | | | |
|---------------|--|---|--|--|--|--|--|--|--|

| | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|
| Danny Miranda | | | | | | | | | |
|---------------|--|--|--|--|--|--|--|--|--|

| | | | | | | | | | |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|
| 53607 | Main Building | Classroom | | | 12/15/2009 | | 21 | | \$0.00 |
|-------|---------------|-----------|--|--|------------|--|----|--|--------|

| | | | | | | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|
| Medium | Work In Progress | | | | 12/15/2009 8:28:37 AM | | | | |
|--------|------------------|--|--|--|-----------------------|--|--|--|--|

| | | | | | | | | | |
|---------------------|--|---|--|--|--|-----------------------|---------|--|--|
| Villalobos, Margret | | NEED TO SPRAY FOR BUGS IN CLASSROOM 101 AND 105 | | | | Schedule for Jan-2010 | \$50.00 | | |
|---------------------|--|---|--|--|--|-----------------------|---------|--|--|

| | | | | | | | | | |
|-------------|--|--|--|--|--|--|--|--|--|
| Debra Facio | | | | | | | | | |
|-------------|--|--|--|--|--|--|--|--|--|

1/5/2010 12:27:05 PM

697 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2009 - 12/31/2009 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|----------|-------------|-------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |

| | | | | | | | | | |
|-------------------------------|------------------|---|-----------|--|-----------------------|--------------------------|-----------|-------------------|--------|
| Location: | | Vado ES | | | | | | | |
| 53653 | | | | | 12/16/2009 | | 20 | | \$0.00 |
| Medium | Work In Progress | | | | 12/16/2009 10:40:46 | | | | |
| Ontiveros, Joe | | NEED TO CK. SINK AND FAUCET IN GIRLS R.R. AND A 3" CLEAN OUT COVER 300-WING | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 53684 | | Cafeteria | | | 12/17/2009 | | 19 | | \$0.00 |
| Medium | Work In Progress | | | | 12/17/2009 7:32:25 AM | | | | |
| Lozoya, Manny | | CHANGE THE KEY TO THE STORAGE IN THE CAFET. | | | | | | | |
| | | MR. GIOVAS, SNP DIRECTOR 882-6771 | | | | | | | |
| Jacqueline Aguilar | | | | | | | | | |
| Count: 20 Work Orders | | Avg. Age of WO's | 73 | | | Total for Vado ES | 0 | \$0.00 | |
| Count: 697 Work Orders | | Avg. Age of WO's | 76 | | | Grand Total | 10 | \$2,039.50 | |