

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: Anthony - On Track Pre-K</b>									
71992					4/11/2011		36		\$0.00
Medium	Work In Progress				4/11/2011 4:08:07 PM				
Estrada, Jesus	Pre-K offices need tile to be replaced by carpet. bathroom and storage need tile replaced with new tile.								
Jesus Estrada									
<b>Count: 1 Work Orders</b>	<b>Avg. Age of WO's</b>		<b>36</b>	<b>Total for Anthony - On Track Pre-K</b>				<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Anthony ES</b>							
62752					8/20/2010		270		\$0.00
Medium	Work In Progress	SPECIAL		8/20/2010 3:26:11 PM					
Lozoya, Manny		EXCHANGE DOORS BETWEEN ANGIE SANCHEZ AND MARGARET VILLALOBOS/ HALF DOOR TO ANGIE'S OFFICE FULL DOOR TO MARGARET'S OFFICE				Reprinted 4/21/11			
<u>Margaret Villalobos</u>									
65000		Portables			10/6/2010		223		\$0.00
Medium	Work In Progress			10/6/2010 7:51:35 AM					
Villalobos, Hector		I need materials for pt 220 2x4x10 and 4x8 siding skiting pt							
<u>Hector Villalobos</u>									
66080					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:20					
Orozco, Danny		Monthly - Anthony ES Fire Suppression Insp. - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
67131					12/3/2010		165		\$0.00
Medium	Work In Progress			12/3/2010 1:25:25 PM					
Flores, Pete		truck will not start. Will need a starter # 153							
<u>Hector Villalobos</u>									
67266					12/5/2010		163		\$0.00
Medium	Work In Progress			12/5/2010 12:27:27 AM					
Sanchez, Raul		Monthly - Anthony ES - Monthly Meter Readings - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
67602		Mechanical			12/14/2010		154		\$0.00
Medium	Work In Progress			12/14/2010 11:00:40					
Villalobos, David		For David V upper primary boilers back flow valve is leaking							
<u>Hector Villalobos</u>									
67816					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:36 AM					
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
67868					1/2/2011	1/10/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:29:01 AM					
Villalobos, Hector		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
67869					1/2/2011	1/10/2011	135		\$0.00
Medium	Work In Progress				1/2/2011 12:29:01 AM				
Villalobos, Hector	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67870					1/2/2011	1/8/2011	135		\$0.00
Medium	Work In Progress				1/2/2011 12:29:02 AM				
Villalobos, Hector	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67871					1/2/2011	1/10/2011	135		\$0.00
Medium	Work In Progress				1/2/2011 12:29:02 AM				
Villalobos, Hector	Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68524					1/19/2011		118		\$0.00
Medium	Work In Progress	PORTABLE 5 &			1/19/2011 8:08:13 AM				
Appelzoller, Fred	NO WATER IN PORTABLES 5 AND 6 (PRE/K STUDENTS) PLEASE CHECK PLUMBING								
<u>Jessica Lopez</u>									
69051					2/6/2011	2/12/2011	100		\$0.00
Medium	Work In Progress				2/6/2011 12:33:45 AM				
Villalobos, Hector	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69052					2/6/2011	2/14/2011	100		\$0.00
Medium	Work In Progress				2/6/2011 12:33:46 AM				
Villalobos, Hector	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69053					2/6/2011	2/14/2011	100		\$0.00
Medium	Work In Progress				2/6/2011 12:33:46 AM				
Villalobos, Hector	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69175					2/8/2011		98		\$0.00
Medium	Work In Progress				2/8/2011 8:41:41 AM				
Moncayo, Fernando	ADULT BATHROOM CEILING COLLAPSED PLEASE REPAIR								
<u>Jessica Lopez</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
69202					2/8/2011		98		\$0.00
Medium	Work In Progress			2/8/2011 12:16:37 PM					
Estrada, Jesus	NEED TO REPLACE CARPET & VCT IN PORTABLE #117 (NOT A CLASSROOM)								
<u>Jesus Estrada</u>									
69445	Main Building				2/14/2011		92		\$0.00
Medium	Work In Progress			2/14/2011 12:24:54 PM					
Appelzoller, Fred	repair or replace water faucet near entrance to main building								
<u>David Vega</u>									
69494	Main Building	Classroom			2/15/2011		91		\$0.00
High	Work In Progress			2/15/2011 9:08:42 AM					
Solis, Lorenzo	coil in rm 102 burst due to weather, please replace and install when it purchased and start-up.thankyou								
<u>Michael Munoz</u>									
69985					2/28/2011		78		\$0.00
Medium	Work In Progress	SPED		2/28/2011 9:22:20 AM					
Moncayo, Fernando	SECOND REQUEST TO HAVE WINDOWS SEALED AND NOW TO HAVE THE WINDOW SILLS DUSTED (THERE IS A LOT OF DIRT)								
<u>Margaret Villalobos</u>									
70000	Main Building	Classroom			2/28/2011		78		\$0.00
Medium	Work In Progress			2/28/2011 11:22:09 AM					
Moncayo, Fernando	all rooms in upper primary (VILLAGE) need door sweeps some have them and need to be lowered and some dont have them at all teachers are complaining that alot of dirt and dust is coming in and children are snizzing and coughing,especially ones with azthma								
<u>David Vega</u>									
70086	Main Building				3/2/2011		76		\$0.00
Medium	Work In Progress			3/2/2011 9:19:50 AM					
Appelzoller, Fred	repair or replace water faucet near entrane to main building								
<u>David Vega</u>									
70236					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:36 AM					
Orozco, Danny	Yearly - Anthony ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
70494	Main Building	Restroom (Boys)			3/9/2011		69		\$0.00
Medium	Work In Progress				3/9/2011 11:16:14 AM				
Appelzoller, Fred	boys restroom (6th grade) flushes real slow, last stall towards wall								
<u>David Vega</u>									
70567					3/10/2011		68		\$0.00
Medium	Work In Progress				3/10/2011 8:02:56 AM				
Estrada, Jesus	NEED CARPET REPLACED IN PORTABLE #217								
<u>Jesus Estrada</u>									
70593					3/10/2011		68		\$0.00
Medium	Work In Progress	SPED OFFICE			3/10/2011 9:56:47 AM				
Moncayo, Fernando	MOVE FAMILY INTERVENTION SPECIALIST CABINETS FROM HALLWAY INTO ROOM 112								
<u>Margaret Villalobos</u>									
70776	Main Building				3/15/2011		63		\$0.00
Medium	Work In Progress				3/15/2011 10:22:52 AM				
Flores, Pete	weed eater serial #272031758 needs minor repair, weed eater string spool broken								
<u>David Vega</u>									
70777	Main Building				3/15/2011		63		\$0.00
Medium	Work In Progress				3/15/2011 10:25:03 AM				
Flores, Pete	weedeater serial #272031746 needs minor repair, weedeater string spool is broken								
<u>David Vega</u>									
71201					3/29/2011		49		\$0.00
Medium	Work In Progress				3/29/2011 10:27:04 AM				
Orozco, Danny	REACH IN IS AT 80 DEGREES. SNP MANAGER BECKY S. 882.3507.								
<u>Maritza Gonzalez</u>									
71428					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress				4/3/2011 12:19:50 AM				
Orozco, Danny	Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71691		Portables			4/6/2011		41		\$0.00
Medium	Work In Progress				4/6/2011 7:29:31 AM				
Lozoya, Manny	pt 221 need to be secure for music instruments. dead bolt key								
<u>Hector Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
71957	Office				4/11/2011		36		\$0.00
Medium	Work In Progress			4/11/2011 11:30:18 AM					
Ronquillo, Ruben	Upper primary rooms 110, 111.bronken windows 3 19 1/4x 14 1/4 wire glass								
<u>Hector Villalobos</u>									
72007	Classroom				4/12/2011		35		\$0.00
Medium	Work In Progress			4/12/2011 2:02:52 PM					
Villalobos, Hector	upper primary need door sweeps 36 inch . need 20								
<u>Hector Villalobos</u>									
72033	Portables				4/13/2011		34		\$0.00
High	Work In Progress			4/13/2011 8:22:58 AM					
Villalobos, Hector	Please repair the wall in Ms. Butlers portable with drywall and cemplite so the Fred can finish installing comodes and sinks. Let Fred know when complete. Thanks								
<u>Michael Munoz</u>									
72597					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:53 AM					
Villalobos, Hector	Yearly - Anthony ES C11 (Evap.Down)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72638					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:55 AM					
Orozco, Danny	Monthly - Anthony ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72680					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:17 AM					
Villalobos, Hector	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72681					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:17 AM					
Villalobos, Hector	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72682					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:18 AM					
Villalobos, Hector	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Anthony ES</b>									
72864					5/4/2011		13		\$0.00
Medium	Work In Progress			5/4/2011 8:28:37 AM					
Carrasco, Danny	need diesel and oil , oil filter for 936 ID mof935x186432 ridingmow								
<u>Hector Villalobos</u>									
72883					5/4/2011		13		\$0.00
Medium	Work In Progress			5/4/2011 3:21:43 PM					
Lozoya, Manny	upper primary outside new electrical boxs need locks 3								
<u>Hector Villalobos</u>									
72923					5/5/2011		12		\$0.00
Medium	Work In Progress	SPED OFFICE		5/5/2011 10:34:16 AM					
Ontiveros, Joe	SINK IN WOMEN'S BATHROOM NEEDS TO BE UNCLOGGED. HAVE ALREADY SPOKEN TO MARCOS								
<u>Margaret Villalobos</u>									
73014					5/9/2011		8		\$0.00
Medium	Work In Progress	SPED OFFICE		5/9/2011 10:46:09 AM					
Villalobos, Hector	PLEASE REPLACE LIGHT BULB IN SAM GALLEGOS' OFFICE ROOM 120								
<u>Margaret Villalobos</u>									
73041		Classroom			5/9/2011		8		\$0.00
Medium	Work In Progress			5/9/2011 3:40:16 PM					
Lozoya, Manny	need to replace lock on door will not lock upper primary room 109								
<u>Hector Villalobos</u>									
73063		Classroom			5/10/2011		7		\$0.00
Medium	Work In Progress			5/10/2011 9:13:43 AM					
Lozoya, Manny	Upper primary room 110 need 3 keys for cabinet								
<u>Hector Villalobos</u>									
73070					5/10/2011		7		\$0.00
Medium	Work In Progress	111		5/10/2011 1:21:17 PM					
Lozoya, Manny	KEYS NEEDED TO CABINETS LOCATED IN ROOM 111- SUPPLY ROOM								
<u>Jessica Lopez</u>									
73103					5/11/2011		6		\$0.00
Medium	Work In Progress			5/11/2011 9:00:31 AM					
Lozoya, Manny	Mild bld outside pods storage need 2 locks								
<u>Hector Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: Anthony ES</b>									
73104					5/11/2011		6		\$0.00
Medium	Work In Progress				5/11/2011 9:02:01 AM				
Lozoya, Manny	Upper primary outside electrical box need 3 locks								
Hector Villalobos									
73105					5/11/2011		6		\$0.00
Medium	Work In Progress				5/11/2011 9:04:59 AM				
Ontiveros, Guadalupe	Mild blg outside need to remove 7 benches with backhole tractor								
Hector Villalobos									
73231					5/16/2011		1		\$0.00
Medium	Work In Progress	ALAMO			5/16/2011 8:40:30 AM				
Villalobos, Hector	PLEASE PAINT THE ALAMO FROM THE OUTSIDE								
Jessica Lopez									
73253					5/16/2011		1		\$0.00
Medium	Work In Progress				5/16/2011 2:35:50 PM				
Orozco, Danny	MILK COOLER IS DOWN SNP MANAGER BECKY S. 882.3507								
Maritza Gonzalez									
<b>Count: 51 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>72</b>			<b>Total for Anthony ES</b>	<b>0</b>	<b>\$0.00</b>



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
67267					12/5/2010		163		\$0.00
Medium	Work In Progress			12/5/2010 12:27:28 AM					
Sanchez, Raul	Monthly - Berino ES - Monthly Meter Readings - Refer to PM schedule details.								
Margret Villalobos									
60598					7/4/2010	7/25/2010	317		\$0.00
Medium	Work In Progress			7/4/2010 12:23:43 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
64739					10/3/2010	10/24/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:26:58 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
66081					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:20					
Orozco, Danny	Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
66431		Cafeteria			11/8/2010		190		\$0.00
Medium	Work In Progress			11/8/2010 9:40:42 AM					
Orozco, Danny	REACH IN FREEZER TEMP AT 58								
ELSA ORTEGA SNP MGR 882-2417									
Jacqueline Aguilar									
66601					11/15/2010		183		\$0.00
Medium	Work In Progress			11/15/2010 8:09:27 AM					
Solis, Lorenzo	MR LORENZO SOLIS SIR THE CIRCULATING PUMP IN THE BOILER ROOM IS LEAKING BLEW A GASKET NEED GO FIX THANK YOU SIR AND GOD BLESS								
Adan Duran									
66713					11/16/2010		182		\$0.00
Medium	Work In Progress			11/16/2010 11:06:12					
Flores, Pete	MR PETE FLORES SIR MY JOHN DEERE MOWER NEEDS BLADES NEED TO BE SERVICE IT HAS NOT BEEN SERVICE FOR TWO YEARS THANK YOU SIR AND GOD BLESS								
Adan Duran									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Berino ES

67435 12/9/2010 159 \$0.00

Medium Work In Progress 12/9/2010 12:20:33 PM

Appelzoller, Fred MR FRED APPELL SIR THE CIRCULATION PUMP FOR THE HOT WATER NOT WORKING NOT GETTING HOT WATER TO OFFICE MAY NEED TO REPLACE THANK YOU SIR AND GOD BLESS

Adan Duran

67436 12/9/2010 159 \$0.00

Medium Work In Progress 12/9/2010 12:23:08 PM

Villalobos, David MR DAVID VILLALOBOS SIR THE BACK FLOW VALUE IS LEAKING NEED TO CHECK THANK YOU SIR AND GOD BLESS

Adan Duran

67817 1/2/2011 2/2/2011 135 \$0.00

Medium Work In Progress 1/2/2011 12:28:36 AM

Villalobos, David Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

67836 1/2/2011 1/23/2011 135 \$0.00

Medium Work In Progress 1/2/2011 12:28:44 AM

Orozco, Danny Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

68936 1/31/2011 106 \$0.00

Medium Work In Progress 1/31/2011 3:11:05 PM

Ontiveros, Guadalupe MR LUPE ONTIVEOS SIR AS PER MR MUNOZ NEED THE USE OF ONE OF YOUR TRATORS TO SPEAD DIRT ON PLAYGROUND THANK SIR AND GOOD BLESS

Adan Duran

70194 3/4/2011 74 \$0.00

Medium Work In Progress 3/4/2011 2:33:42 PM

Appelzoller, Fred MR FRED APPELOZLLER THE FUACETS IN ROOM 133 NEED TO BE REPLACE WILL NOT SHUT OFF OLD AND RUSTY THANK YOU SIR AND GOD BLESS

Adan Duran

70195 3/4/2011 74 \$0.00

Medium Work In Progress 3/4/2011 2:39:32 PM

Appelzoller, Fred MR FRED APPELOZLLER SIR THE HEATING UNIT ON BOTTOM THAT HEATS WATER FOR KITCHEN HAS A CRACK ON MONIFOLD NEED REPLACING THANK YOU SIR AND GOD BLESS YOU

Adan Duran

5/17/2011 12:10:25 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Berino ES</b>									
70237					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:37 AM					
Orozco, Danny	Yearly - Berino ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70607					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 2:43:43 PM					
Villalobos, David	MR DAVID VILLALOBOS SIR THE BACK FLOW PREVENTOR IS LEAKING PRETTY BAD NEEDS REPAIR THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
71110		Athletic Field			3/28/2011		50		\$0.00
Medium	Work In Progress			3/28/2011 7:36:58 AM					
Ontiveros, Guadalupe	please remove 4 adjustable basketball courts /goals and set in at berino.adan is aware of the locations.sal g will support with this project. see mike for details.thank you								
<u>Joe Munoz</u>									
71237					3/30/2011		48		\$0.00
Medium	Work In Progress			3/30/2011 10:02:41 AM					
Sanchez, Raul	MR RAUL SANCHEZ SIR I'M HAVING TROUBLE WITH COMPRESSER WILL NOT SHUT OFF AT 120 KEEPS GOING TILL RELEF VALUE POPS OPEN THE CUT OF SWITCH MAY BE BAD PLEASE CHECK THANK YOU AND GOD BLESS								
<u>Adan Duran</u>									
71422					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:48 AM					
Orozco, Danny	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71429					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:51 AM					
Orozco, Danny	Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72590					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:49 AM					
Duran, Adan	Yearly - Berino ES C11 (Evap.Down)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
72610					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:39 AM					
Duran, Adan	Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
72611					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:40 AM					
Duran, Adan	Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
72612					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:40 AM					
Duran, Adan	Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
72613					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:41 AM					
Duran, Adan	Monthly - Berino ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
72639					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:56 AM					
Orozco, Danny	Monthly - Berino ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
72972					5/6/2011		11		\$0.00
Medium	Work In Progress			5/6/2011 3:09:22 PM					
Duran, Adan	MR ADAN DURAN SIR NEED TO REPACE 1/2"X6"LONG HUNTER SPRINKLERS WINNIE TYPE NEED 6 FOR FRONT AND 6 FOR EARLY CHILDHOOD PLAYGROUND 12 IN ALL THANK YOU SIR								
Adan Duran									
72992					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:12 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
73047					5/9/2011		8		\$0.00
Medium	Work In Progress	Construction			5/9/2011 4:32:13 PM				
Villalobos, David	Please call Dean Pogue (Sub-Contractor) at (575) 382-8474 to coordinate meeting to find the waterline coming from back flow preventor.								
Peggy Jo Hernandez									
73124					5/11/2011		6		\$0.00
Medium	Work In Progress				5/11/2011 3:33:19 PM				
Sotelo, Enrique	MR ENRIQUE SOTELO MR KIKI NEED TO REPLACE 3 EMERGENCY LIGHTS NOT WORKING THANK YOU SIR AND GOD BLESS								
Adan Duran									
73126					5/11/2011		6		\$0.00
Medium	Work In Progress				5/11/2011 3:37:34 PM				
Ontiveros, Joe	MR JOE ONTIVEROS SIR THE SPUD WASHER ON COMODE UPPER WEST WING NEEDS REPLACEING THANK YOU SIR AND GOD BLESS								
Adan Duran									
<b>Count: 31 Work Orders</b>		<b>Avg. Age of WO's 89</b>			<b>Total for Berino ES</b>			<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
<b>Location:</b>		<b>Chaparral Elem East Pre-K</b>							
73061					5/10/2011		7		\$0.00
Medium	Work In Progress				5/10/2011 8:51:23 AM				
Sotelo, Enrique	Lights out in Portable #7. Please check. Thank you								
Guillermo Hernandez									
<b>Count: 1</b>	<b>Work Orders</b>		<b>Avg. Age of WO's</b>	<b>7</b>		<b>Total for Chaparral Elem East Pre-K</b>	<b>0</b>		<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
61455					7/28/2010		293		\$0.00
Medium	Work In Progress			7/28/2010 3:35:20 PM					
Ontiveros, Joe	Need to replace leaking faucets in new wing classrooms. Thank you								
<u>Guillermo Hernandez</u>									
66082					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:20					
Orozco, Danny	Monthly - Chaparral ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67256					12/5/2010		163		\$0.00
Medium	Work In Progress			12/5/2010 12:27:24 AM					
Sanchez, Raul	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67815					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:36 AM					
Villalobos, David	Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68417					1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 8:33:22 AM					
Gonzalez, Salvador	Need to replace and reinforce bend pole to the canopy on main playground and need to sew tarp or patch a hole made by rubbing on a lower pole. Thank you								
<u>Guillermo Hernandez</u>									
68667					1/21/2011		116		\$0.00
Medium	Work In Progress			1/21/2011 3:58:12 PM					
Ontiveros, Joe	Need to replace broken toilet tank lid in mes restroom front lobby. Thank you.								
<u>Guillermo Hernandez</u>									
68836					1/27/2011		110		\$0.00
Medium	Work In Progress			1/27/2011 11:16:47 AM					
Hernandez, Guillermo	Need to replace exhaust fan motors in classrooms #201 and #212. Thank you								
<u>Guillermo Hernandez</u>									
68841	Main Building				1/27/2011		110		\$0.00
Medium	Work In Progress			1/27/2011 2:03:29 PM					
Solis, Lorenzo	Need to replace A/C unit Principals office, side draft. Thank you.								
<u>Guillermo Hernandez</u>									

5/17/2011 12:10:25 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
68842	Main Building				1/27/2011		110		\$0.00
Medium	Work In Progress				1/27/2011 2:04:55 PM				
Solis, Lorenzo	Need to replace A/C unit Assistant Principals office, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68843	Main Building				1/27/2011		110		\$0.00
Medium	Work In Progress				1/27/2011 2:06:27 PM				
Solis, Lorenzo	Need to replace A/C unit Room #101, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68844	Main Building				1/27/2011		110		\$0.00
Medium	Work In Progress				1/27/2011 2:07:07 PM				
Solis, Lorenzo	Need to replace A/C unit Room #103, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68845	Main Building				1/27/2011		110		\$0.00
Medium	Work In Progress				1/27/2011 2:07:48 PM				
Solis, Lorenzo	Need to replace A/C unit Room #104, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68846	Main Building				1/27/2011		110		\$0.00
Medium	Work In Progress				1/27/2011 2:08:54 PM				
Solis, Lorenzo	Need to replace A/C unit Library office, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68847	Main Building				1/27/2011		110		\$0.00
Medium	Work In Progress				1/27/2011 2:10:15 PM				
Solis, Lorenzo	Need to replace A/C unit in the Library, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68848	Main Building				1/27/2011		110		\$0.00
Medium	Work In Progress				1/27/2011 2:11:24 PM				
Solis, Lorenzo	Need to replace A/C unit Lobby front office, side draft. Thank you.								
<u>Guillermo Hernandez</u>									
68849	Main Building				1/27/2011		110		\$0.00
Medium	Work In Progress				1/27/2011 2:12:12 PM				
Solis, Lorenzo	Need to replace A/C unit Room #302, side draft. Thank you.								
<u>Guillermo Hernandez</u>									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
68932	Main Building	Hallway/Corridor			1/31/2011		106		\$0.00
Medium	Work In Progress	School			1/31/2011 2:44:44 PM				
Hernandez, Guillermo		Memo please install map rails							
Jennifer Corral									
69100					2/6/2011		100		\$0.00
Medium	Work In Progress				2/6/2011 12:34:05 AM				
Sanchez, Raul		Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.							
Margret Villalobos									
70149					3/3/2011		75		\$0.00
Medium	Work In Progress				3/3/2011 12:31:54 PM				
Ontiveros, Guadalupe		Lupe would you please stop by to check the irrigation tank there is a small water leak on the compressor and on the gauge meter. Thank you							
Guillermo Hernandez									
70238					3/6/2011		72		\$0.00
Medium	Work In Progress				3/6/2011 12:17:37 AM				
Orozco, Danny		Yearly - Chaparral ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
70756		Lift Station			3/14/2011		64		\$0.00
Medium	Work In Progress				3/14/2011 3:57:35 PM				
Sanchez, Raul		Need to contract services with lift station contractor; Cubic Water Construction, Inc. and repair broken pipe in north pump column & replace other pump piping with sch 80 PVC. Contractor has all the safety equipment needed to do the job. We do not.							
Raul Sanchez									
70850					3/16/2011		62		\$0.00
Medium	Work In Progress				3/16/2011 3:53:25 PM				
Ontiveros, Guadalupe		Lupe can you stop by to check the covers for the main valves for irrigation on the field (time's = 3). They need to be replaced safety issue. Thank you							
Guillermo Hernandez									
71430					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress				4/3/2011 12:19:51 AM				
Orozco, Danny		Monthly - Chapparal ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
72044					4/13/2011		34		\$0.00
Medium	Work In Progress			4/13/2011 11:00:56 AM					
Gonzalez, Salvador	Need to weld broken pipe on sign by busses turn around and cut metal plate by E wing rain run out. Thank you								
<u>Guillermo Hernandez</u>									
72045					4/13/2011		34		\$0.00
Medium	Work In Progress			4/13/2011 11:03:21 AM					
Flores, Pete	Need to use Bobcat to add sand to playground and add crusher fine to side salks. Thank you.								
<u>Guillermo Hernandez</u>									
72161					4/18/2011		29		\$0.00
Medium	Work In Progress			4/18/2011 8:12:54 AM					
Lozoya, Manny	Please generate a work order for the locksmith to Determine the Replacement Cost for gate key, She will need to pay for any rekeying cost. (Cynthia Linck-Mobile Home Occupant)								
<u>Alfredo Holguin</u>									
72278					4/20/2011		27		\$0.00
Medium	Work In Progress			4/20/2011 7:55:11 AM					
Hernandez, Guillermo	NEED TO REMOVE TOILETS IN BOYS AND GIRLS RESTROOMS ON WEDNESDAY, APRIL 27. RODRIGUEZ UPHOLSTERY WILL BE REPLACE VCT (W.O. #69939) ON THURSDAY, FRIDAY & SATURDAY. TOILETS NEED TO BE REPLACED ON MONDAY, MAY 2 OR AFTER.								
<u>Jesus Estrada</u>									
72606					4/30/2011		17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:58 AM					
Sanchez, Raul	Monthly - Chaparral ES DP-91 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72640					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:56 AM					
Orozco, Danny	Monthly - Chaparral ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72742					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:47 AM					
Sanchez, Raul	Monthly - Chaparral ES-Wastewater Weed Control - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
72886	2001 Classroom				5/4/2011		13		\$0.00
Medium	Work In Progress				5/4/2011 3:30:04 PM				
Ontiveros, Joe	Need to replace broken toilet in restroom between classrooms #207 and #209. Thank you.								
Guillermo Hernandez									
72888					5/4/2011		13		\$0.00
Medium	Work In Progress				5/4/2011 3:32:51 PM				
Ontiveros, Joe	Need to replace water tank or complete toilet in restroom between classrooms #214 and #216. Thank you.								
Guillermo Hernandez									
72916	Main Building	Classroom			5/5/2011		12		\$0.00
Medium	Work In Progress	whole school			5/5/2011 9:23:55 AM				
Villalobos, Hector	Nurse has been getting a lot of students and teachers with insect/spider bites. in all areas of the school. please see front office								
Jennifer Corral									
72977					5/6/2011		11		\$0.00
Medium	Work In Progress				5/6/2011 3:31:08 PM				
Hernandez, Guillermo	Memo need to replace 1" anti-siphon valve on irrigation for the trees by the bus turn around. Thank you								
Guillermo Hernandez									
72999					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress				5/8/2011 12:18:15 AM				
Hernandez, Guillermo	Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
73164					5/12/2011		5		\$0.00
Medium	Work In Progress				5/12/2011 2:26:02 PM				
Lozoya, Manny	Please check padlock on gate by irrigation tank. We can't unlock the padlock. thank you.								
Guillermo Hernandez									
73165					5/12/2011		5		\$0.00
Medium	Work In Progress				5/12/2011 2:27:49 PM				
Ontiveros, Joe	Need to unclog sewer line in the concession stand washer is backing up. Thank you.								
Guillermo Hernandez									
73237					5/16/2011		1		\$0.00
Medium	Work In Progress				5/16/2011 9:37:55 AM				
Flores, Pete	Need to replace two flat tires on truck #155 (CHE). Thank you								
Guillermo Hernandez									
5/17/2011 12:10:25 PM									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
73252					5/16/2011		1		\$0.00
Medium	Work In Progress				5/16/2011 2:34:33 PM				
Orozco, Danny	1).REACH IN NOT WORKING. 2.) SERVING LINE IS LEAKING. 3.) TILT SKILLET HAS AN ELECTRICAL SHORT.								
Maritza Gonzalez									
73264					5/16/2011		1		\$0.00
Medium	Work In Progress				5/16/2011 3:43:11 PM				
Solis, Lorenzo	Please install power cords to new roof top A/C's installed on main building. Thank you.								
Guillermo Hernandez									
<b>Count: 40 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>72</b>		<b>Total for Chaparral ES</b>	<b>0</b>		<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
60938		Custodial			7/13/2010		308		\$0.00
Medium	Work In Progress			7/13/2010 6:39:07 AM					
Carbajal, Jimmy		SWEEPER SN# 072820509 ESTA QUEBRADO DE LOS CEPILLOS Y NO FUNCIONA EL FRENO.				1/31/10 - ASP JIMMY, NO PARTS; STILL PENDING REPAIR			
Marisela Torres									
61938					8/5/2010		285		\$0.00
Medium	Work In Progress			8/5/2010 10:28:48 AM					
Lozoya, Manny		REQUESTING DOOR BETWEEN GIRLS LOCKER EAST,AND WEST.DOOR WAS REMOVED AND NEVER INSTALLED BACK. ACCORDING TO STAFF NOBODY KNOWS ABOUT THIS DOOR.				Reprinted 4/21/11			
Paul Quinones									
61990					8/6/2010		284		\$0.00
Medium	Work In Progress			8/6/2010 8:27:56 AM					
Ontiveros, Joe		NO HOT WATER IN SHOWERS,AND COACH SMITHS SHOWER STALL AS WELL.							
Paul Quinones									
63670					9/9/2010		250		\$0.00
Medium	Work In Progress			9/9/2010 8:49:24 AM					
Ontiveros, Joe		WATER FOUNTAIN NEXT TO THE OUTSIDE BASKETBALL COURTS,WATER IS LEAKING UNDER THE WATER FOUNTAIN							
Paul Quinones									
64475					9/28/2010		231		\$0.00
Medium	Work In Progress			9/28/2010 1:06:08 PM					
Flores, Pete		FLOAT SWITCH NOT WORKING PROPERLY REMOVE WIRING SETS OFF NOTIFIER IN MAIN BUILDING,REMOVE WIRING FROM TERMINAL.FUEL TANKS SIGHT GLASS DOESNT SHOW FUEL LEVELS.							
Paul Quinones									
65240					10/11/2010		218		\$0.00
Medium	Work In Progress			10/11/2010 2:33:23 PM					
Lozoya, Manny		REQUESTING BOYS,AND GIRLS SIGNS W/BRAIL FOR REST ROOMS IN B THROUGH G.AND Q,AND R AS WELL. TOTAL BOYS 8 SIGNS,AND 8 GIRLS. COLOR BLUE W/ WHITE LETTERS				Reprinted 4/21/11			
Paul Quinones									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
65356		Athletic Field			10/13/2010		216		\$0.00
High	Work In Progress			10/13/2010 12:56:47					
Ontiveros, Joe	need to run water line to storage.								
<u>Guadalupe Ontiveros</u>									
65357		Athletic Field			10/13/2010		216		\$0.00
Medium	Work In Progress			10/13/2010 1:00:34 PM					
Gonzalez, Salvador	need shade to protect sweeper and tractors from elements.								
<u>Jose Garcia</u>									
66076					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:18					
Orozco, Danny	Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66734					11/16/2010		182		\$0.00
Medium	Work In Progress			11/16/2010 3:53:57 PM					
Ontiveros, Joe	REQUESTING TO CHECK WASHING MACHINE,AND DRYER IN GIRLS LOCKER NORTH IN GYM.								
<u>Paul Quinones</u>									
67067					12/2/2010		166		\$0.00
Medium	Work In Progress			12/2/2010 9:23:29 AM					
Lozoya, Manny	REQUESTING PROTECTIVE LATCHES TO ALL DOORS IN CYBER CAFE,DUE TO VANDILISM IN SCIENCE CLASS RMS. AND COMPUTER LABS.					Reprinted 4/21/11			
<u>Paul Quinones</u>									
67120					12/3/2010		165		\$0.00
Medium	Work In Progress			12/3/2010 8:20:52 AM					
Estrada, Jesus	(PROJECT)	GYM - Need to re-stripe and refinish floor.				Leadership Request			
						Re-routed to J. Estrada on 4/11/11 - mkv			
<u>Paul Quinones</u>									
67835					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:43 AM					
Villalobos, David	Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
68529					1/19/2011		30		\$0.00
Medium	Work In Progress			1/19/2011 8:22:07 AM		2/18/2011			
Quinones, Paul	REQUESTING PLEADED AIR FILTERS FOR FIELD HOUSE UNITS 16"X24"								
Paul Quinones									
69441					2/14/2011		92		\$0.00
Medium	Work In Progress			2/14/2011 10:55:25 AM					
Solis, Lorenzo	REPLACE CHK VALVES TO UNITS IN C D, AND E WINGS, VALVES RUPTURED DURING FREEZE CYBER CAFES								
Paul Quinones									
69898		Football Field			2/24/2011		82		\$0.00
Medium	Work In Progress	softball practice		2/24/2011 2:42:08 PM					
Garcia, Jose	please relocate softball backstop practice field. please contact Ms. Nougues for exact location. (Nougues)								
Rosa Quezada									
69922					2/24/2011		82		\$0.00
Medium	Work In Progress			2/24/2011 4:30:59 PM					
Quinones, Paul	CIELING TILES NEED TO BE REPLACED DUE TO WINTER STORM DAMAGE THROUGH OUT SCHOOL.								
Paul Quinones									
70001					2/28/2011		78		\$0.00
Medium	Work In Progress			2/28/2011 12:40:36 PM					
Quinones, Paul	NEED TO REPLACE CIELING TILES IN CLASS RMS., AND CYBER CAFES DUE TO WINTER STORM. REQUESTING NEW TILES.								
Paul Quinones									
70108					3/2/2011		76		\$0.00
Medium	Work In Progress			3/2/2011 3:38:47 PM					
Carrasco, Danny	requesting 15 gal. of gasoline for work truck #139								
Paul Quinones									
70144					3/3/2011		75		\$0.00
Medium	Work In Progress			3/3/2011 11:00:08 AM					
Quinones, Paul	NEED TO PAINT DOUBLE DOORS TO BOTH ENTRANCES IN GYM NEXT TO CAFETERIA. REQUESTING 2 GAL. OF PAINT								
Paul Quinones									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
70253					3/6/2011		72		\$0.00
Medium	Work In Progress				3/6/2011 12:17:45 AM				
Orozco, Danny	Yearly - Chaparral HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
70415					3/7/2011		71		\$0.00
Medium	Work In Progress				3/7/2011 2:51:01 PM				
Quinones, Paul	ELECTRIC FIRE PUMP CONTROLLER,ELECTRICAL FROM INSIDE ELECTRICAL PANEL SHORTED OUT. PACKING GLANDS LEAKING TO PUMP.DUE TO SPRINKLER LEAK FROM INSIDE								
Paul Quinones									
70416					3/7/2011		71		\$0.00
Medium	Work In Progress				3/7/2011 2:55:03 PM				
Quinones, Paul	DIESEL FIRE PUMP STATION LEAKING WATER FROM PACKING GLAND NEED TO REPLACE.								
Paul Quinones									
70480					3/9/2011		69		\$0.00
Medium	Work In Progress				3/9/2011 8:07:26 AM				
Solis, Lorenzo	GEO THERMAL PUMP LEAKING FROM SEAL,NEED TO BE REPLACED.MECH.RM. NEXT TO KITCHEN								
Paul Quinones									
70574					3/10/2011		68		\$0.00
Medium	Work In Progress				3/10/2011 8:20:26 AM				
Ontiveros, Joe	D-WING SCIENCE CLASS RM. DUE TO WINTER STORM FREEZE,WE NEED TO FIND WATER LEAKS BEHIND TABLES,AND LAVATORY COUNTER TOPS WILL TAKE LONGER THAN OTHER CLASS RMS..								
Paul Quinones									
70575					3/10/2011		68		\$0.00
Medium	Work In Progress				3/10/2011 8:22:19 AM				
Ontiveros, Joe	E-WING SCIENCE CLASS RM. NEED TO FIND WATER LEEAKS BEHIND WALLS.DUE TO FREEZE								
Paul Quinones									
70761					3/14/2011		64		\$0.00
Medium	Work In Progress				3/14/2011 4:31:56 PM				
Ontiveros, Joe	NO HOT WATER IN F-WING BAD IGNITOR								
Paul Quinones									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
70813					3/16/2011		62		\$0.00
Medium	Work In Progress			3/16/2011 9:32:45 AM					
Quinones, Paul	NEED TO REPLACE ALL BROKEN T-STAT COVERS IN ALL AREAS,REQUESTING 24.								
Paul Quinones									
70833		Computer Lab			3/16/2011		62		\$0.00
Medium	Work In Progress	COMPUTER		3/16/2011 2:38:23 PM					
Lozoya, Manny	INSTALL DOOR GUARDS TO PREVENT STUDENTS FROM OPENING LOCKED DOORS TO ALL COMPUTER LABS IN EACH WING					Reprinted 4/21/11			
Rosa Quezada									
70858					3/17/2011		61		\$0.00
Medium	Work In Progress			3/17/2011 9:00:34 AM					
Gonzalez, Salvador	FENCE CHAIN LINK TYPE NEEDS TO BE REPLACED W/POLE AND POLE ALONG PRESSCOTT ANTHONY								
Paul Quinones									
70876					3/17/2011		61		\$0.00
Medium	Work In Progress			3/17/2011 1:23:05 PM					
Castillo, Carlos	REINSTALL LIGHTING IN GIRLS REST RM.								
Paul Quinones									
70878	Field House	Athletic Field			3/17/2011		61		\$0.00
Medium	Work In Progress			3/17/2011 2:32:11 PM					
Quinones, Paul	the tape and texture has been completed. please paint. thank you								
Michael Munoz									
70909					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 9:17:05 AM					
Solis, Lorenzo	GYM A/C'S I NEED SOME SHEETMETAL,MEASUREMENTS ARE 30"X94'1/2".24 GAUGE.								
Paul Quinones									
70968					3/20/2011		58		\$0.00
Medium	Work In Progress			3/20/2011 12:12:34 AM					
Ontiveros, Guadalupe	Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
71020					3/23/2011		55		\$0.00
Medium	Work In Progress			3/23/2011 10:39:40 AM					
Ontiveros, Joe	GIRLS,AND BOYS REST RM. TOILETS NEED TO BE REPLACED TOILETS ARE CRACKED DUE TO WINTER FREEZE. IN THE NORTH END FIELD HOUSE								
Paul Quinones									
71447					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:59 AM					
Orozco, Danny	Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71604					4/4/2011		43		\$0.00
Medium	Work In Progress			4/4/2011 11:22:39 AM					
Lozoya, Manny	DOOR IN BAND RM. DOESNT CLOSE WITH KEY,DOOR IS ALSO NOT ALIGNED WITH DOOR FRAME.DOOR WAS OPEND FORCED OPEN WITH HIGH WINDS.								
Paul Quinones									
71854					4/8/2011		39		\$0.00
Medium	Work In Progress			4/8/2011 3:32:39 PM					
Lozoya, Manny	DOUBLE DOORS NEXT TO CAFETERIA DOORS ARE HARD TO OPEN W/ KEY								
Paul Quinones									
72050		Restroom (Boys)			4/13/2011		34		\$0.00
Medium	Work In Progress			4/13/2011 12:57:11 PM					
Urquidi, Jesus	All urinals need to have a deodorant screen. Some of the screens need to be refilled with a new block.								
Jesus Estrada									
72289		Athletic Field			4/20/2011		27		\$0.00
Medium	Work In Progress			4/20/2011 8:31:44 AM					
Sotelo, Enrique	need to run electric line to grounds storage from lift station about 300'								
Guadalupe Ontiveros									
72350					4/21/2011		26		\$0.00
Medium	Work In Progress			4/21/2011 3:11:22 PM					
Quinones, Paul	PAINT WALLS IN CYBER CAFE TO REMOVE GRAFFITI ON WALLS								
Paul Quinones									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
72528					4/28/2011		19		\$0.00
Medium	Work In Progress			4/28/2011 3:39:52 PM					
Quinones, Paul	NEED TO REPLACE EXTERIOR LIGHTS NORTH, AND SOUTH FIELD HOUSE								
Paul Quinones									
72533					4/28/2011		19		\$0.00
Medium	Work In Progress			4/28/2011 3:45:53 PM					
Solis, Lorenzo	BROKEN WATER FAUCET IN GYM, REMOVE FROM WALL FOR SAFETY PURPOSES								
Paul Quinones									
72604					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:57 AM					
Quinones, Paul	Yearly - Chaparral HS C11 (Evaporative)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
72634					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:53 AM					
Orozco, Danny	Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
72719					5/1/2011	5/4/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:36 AM					
Quinones, Paul	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
72720					5/1/2011	6/1/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:36 AM					
Quinones, Paul	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
72721					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:37 AM					
Quinones, Paul	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
72722					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:37 AM					
Quinones, Paul	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
5/17/2011 12:10:26 PM									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral HS</b>									
72723					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:38 AM					
Quinones, Paul	Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72724					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:38 AM					
Quinones, Paul	Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72831					5/3/2011		14		\$0.00
Medium	Work In Progress			5/3/2011 3:02:37 PM					
Ontiveros, Joe	B-WING SINK IN GIRLS REST RM. CRACKED LEAKING WATER FROM BOTTOM OF SINK. SHUT OFF WATER FROM WALL								
<u>Paul Quinones</u>									
72834					5/3/2011		14		\$0.00
Medium	Work In Progress			5/3/2011 3:18:39 PM					
Ontiveros, Joe	NEED WTAER FAUCETS IN STOCK FOR BROKEN VANDILISED FAUCETS IN WINGS B THRU G .THANKS								
<u>Paul Quinones</u>									
72929		Office			5/5/2011		12		\$0.00
Medium	Work In Progress	attendance		5/5/2011 2:29:44 PM					
Lozoya, Manny	lock in bottom of counter is busted (meza)								
<u>Rosa Quezada</u>									
73012					5/9/2011		8		\$0.00
Medium	Work In Progress			5/9/2011 10:01:12 AM					
Quinones, Paul	REQUESTING AIR FILTERS FOR CHANGE OUT TO UNITS IN B THROUGH G WINGS.								
<u>Paul Quinones</u>									
73013					5/9/2011		8		\$0.00
Medium	Work In Progress			5/9/2011 10:08:02 AM					
Quinones, Paul	NEED SMALL 1" LETTERS TO PAINT BOYS, AND GIRLS SIGN ON WALL FOR REST RM. IN B THROUGH G WINGS, AND Q, AND R BUILDING.								
<u>Paul Quinones</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
73015					5/9/2011		8		\$0.00
Medium	Work In Progress			5/9/2011 10:47:28 AM					
Gonzalez, Salvador	REQUESTING SOME TYPE OF GAURD TO PREVENT STUDENTS FROM CLIMBING GAS LINE ON WALL TO GET ON ROOF.THE LOCATION IS RIGHT BEHIND GYM DOUBLE DOORS								
Paul Quinones									
73016					5/9/2011		8		\$0.00
Medium	Work In Progress			5/9/2011 10:57:18 AM					
Quinones, Paul	REMOVE GRAFFITI REQUESTING SPRAY WASHER,AND THINNER.SCHOOL WAS TAGGED DURING WEEK END. NEED 5 TO 10 GALLONS OF THINNER.								
Paul Quinones									
73068					5/10/2011		7		\$0.00
Medium	Work In Progress			5/10/2011 10:50:51 AM					
Orozco, Danny	ICE MACHINE IS LEAKING FROM THE BOTTOM. SNP MANAGER JUANITA M. 824.4461.								
Maritza Gonzalez									
73131					5/11/2011		6		\$0.00
Medium	Work In Progress			5/11/2011 3:52:53 PM					
Quinones, Paul	REMOVE GRAFITTI,AND NEEDING PAINT TO REMOVE STAINS ON OUTSIDE WALLS.MAIN BUILDING FIELD HOUSES								
Paul Quinones									
73137					5/11/2011		6		\$0.00
Medium	Work In Progress			5/11/2011 4:21:51 PM					
Flores, Pete	5 GALLONS OF GAS FOR PRESSURE WASHER TO REMOVE GRAFITTI FROM WALLS EQUIP#603								
Paul Quinones									
73166					5/12/2011		5		\$0.00
Medium	Work In Progress			5/12/2011 3:09:43 PM					
Carrasco, Danny	REQUESTING SCISSER LIFT TO CAULK SKYLIGHTS IN WINGS MAIN BUILDING.								
Paul Quinones									
73168					5/12/2011		5		\$0.00
Medium	Work In Progress			5/12/2011 3:26:05 PM					
Solis, Lorenzo	UNIT IN E WING RM.E-1 NO COOLING								
Paul Quinones									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
73179		Football Field			5/12/2011		5		\$0.00
Medium	Work In Progress	practice field			5/12/2011 4:12:35 PM				
Garcia, Jose		football field to be lined may 12-15th. (smith)							
Rosa Quezada									
73186					5/13/2011		4		\$0.00
Medium	Work In Progress				5/13/2011 7:46:33 AM				
Briones, Enrique		On May 18, 2011, please deliver 2 boxes to Chaparral High School. Reference P.O. # 101107376							
Yolie Jacquez									
73225	A-Wing	Football Field			5/13/2011		4		\$0.00
Medium	Work In Progress	practice field			5/13/2011 4:22:39 PM				
Garcia, Jose		need lines painted on the practice fields for 7 on 7 tournament being held june 25, 2011. (smith)							
Rosa Quezada									
73244					5/16/2011		1		\$0.00
Medium	Work In Progress				5/16/2011 12:13:26 PM				
Villalobos, Margret		MICE IN KITCHEN STORAGE ROOM.							
Maritza Gonzalez									
<b>Count: 67 Work Orders</b>		<b>Avg. Age of WO's 72</b>			<b>Total for Chaparral HS</b>			<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
60599					7/4/2010	7/25/2010	317		\$0.00
Medium	Work In Progress			7/4/2010 12:23:43 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
62838					8/24/2010		266		\$0.00
Medium	Work In Progress			8/24/2010 9:45:04 AM					
Vallejo, Albert	Need to reinforce shelves in book room								
<u>Albert Vallejo</u>									
64740					10/3/2010	10/24/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:26:59 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
65077		Dressing Room			10/7/2010		222		\$0.00
Medium	Work In Progress			10/7/2010 9:28:04 AM					
Ontiveros, Joe	Motion activated sink in girls P.E. locker room has two broken solenoids which need to be replaced.								
<u>Albert Vallejo</u>									
65458		Cafeteria			10/15/2010		214		\$0.00
Medium	Work In Progress			10/15/2010 8:50:44 AM					
Vallejo, Albert	ENVIRONMENT DEPT. INSPECTION: 1- LOW RISK VIOLATION: MISSING 1 BROKEN FLOOR TILE UNDER THE DISH SINK. STATE INSPECTOR - SANDRA DIAZ SNP MGR 824-4376		Asp Mike, route to A. Vallejo - D. Orozco 1/26/11						
<u>Jacqueline Aguilar</u>									
66083					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:21					
Orozco, Danny	Monthly - Chaparral MS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67347	Phase II New	Hallway/Corridor			12/7/2010		161		\$0.00
Medium	Work In Progress			12/7/2010 8:02:33 AM					
Ronquillo, Ruben	Need to replace transom glass above door in main hallway. 24" x 60" x 1/4" wired glass.								
<u>Albert Vallejo</u>									
67542					12/13/2010		155		\$0.00
Medium	Work In Progress			12/13/2010 9:02:23 AM					
Vallejo, Albert	Need to install Handrail in restroom between I.S.S. room and room #107.								
<u>Albert Vallejo</u>									
5/17/2011 12:10:26 PM									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
67818					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:37 AM					
Villalobos, David	Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67837					1/2/2011	1/23/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:44 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67969					1/5/2011		132		\$0.00
Medium	Work In Progress			1/5/2011 2:30:29 PM					
Vallejo, Albert	Repair front entrance canopy up-lighting fixtures								
<u>Albert Vallejo</u>									
68086		Athletic Field			1/7/2011		130		\$0.00
Medium	Work In Progress			1/7/2011 1:49:10 PM					
Aldaz, Bobby	Football and soccer field need to be fertilize with 16-8-8.								
<u>Guadalupe Ontiveros</u>									
68442					1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 2:21:27 PM					
Ontiveros, Joe	Install refrigerated water fountains on exterior of building south side facing playfields					Leadership Request			
<u>Alfredo Holguin</u>									
68446					1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 2:30:03 PM					
Vallejo, Albert	(PROJECT) Both courtyards - remove all trash and relevel area. Install raised planters (Vado Elem) and cover other areas with crusher fines.					Leadership Request			
<u>Alfredo Holguin</u>									
69104					2/6/2011		100		\$0.00
Medium	Work In Progress			2/6/2011 12:34:07 AM					
Sanchez, Raul	Monthly - Chaparral MS - DP-781 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69207					2/8/2011		98		\$0.00
Medium	Work In Progress			2/8/2011 12:43:29 PM					
Orozco, Danny	BOTH PASS THROUGH WARMERS ARE NOT WORKING, PLEASE CHECK. SNP MANAGER SANDRA D. 824-4376.								
<u>Maritza Gonzalez</u>									
5/17/2011 12:10:26 PM									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
69252					2/9/2011		97		\$0.00
Medium	Work In Progress			2/9/2011 8:59:08 AM					
Orozco, Danny	I will need the bucket truck to obtain specifics of pole lighting for donated fixture.								
Albert Vallejo									
69813					2/23/2011		83		\$0.00
Medium	Work In Progress			2/23/2011 9:20:27 AM					
Ontiveros, Joe	Automatic lavatory faucets throughout campus need to be replaced or repaired.								
Albert Vallejo									
70252					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:44 AM					
Orozco, Danny	Yearly - Chaparral MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
71275					3/31/2011		47		\$0.00
Medium	Work In Progress			3/31/2011 12:17:27 AM					
Vallejo, Albert	Monthly - Chaparral MS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
71396					4/3/2011	4/11/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:34 AM					
Vallejo, Albert	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
71423					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:48 AM					
Orozco, Danny	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
71431					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:52 AM					
Orozco, Danny	Monthly - Chapparral MS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71461					4/3/2011		44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:06 AM					
Vallejo, Albert	Yearly - Chaparral MS A13(AC Wall)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
71462					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:06 AM					
Vallejo, Albert		Monthly - Chaparral MS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
71641					4/5/2011		42		\$0.00
Medium	Work In Progress			4/5/2011 9:07:59 AM					
Ontiveros, Guadalupe		Please remove non-functioning solenoid valves and install ball valves so that trees can be irrigated properly.							
<u>Albert Vallejo</u>									
71672					4/5/2011		42		\$0.00
Medium	Work In Progress			4/5/2011 3:22:29 PM					
Orozco, Danny		SEVERAL TILES MISSING IN KITCHEN AREA. SNP MANAGER SANDRA D. 824-4376							
<u>Maria Gonzalez</u>									
71949					4/11/2011		36		\$0.00
Medium	Work In Progress	Leadership		4/11/2011 11:06:11 AM					
Ontiveros, Joe		Soutside of Bldg (west) need to repair exterior water fountain - pipe base is leaning. (Needs to be complete within 30 days)				Leadership Request			
<u>Alfredo Holguin</u>									
71968	Phase III New	Electrical Room			4/11/2011		36		\$0.00
Medium	Work In Progress			4/11/2011 3:07:26 PM					
Vallejo, Albert		Repair or replace exterior lighting timer for west side lights.							
<u>Albert Vallejo</u>									
72132	Main Building				4/15/2011		32		\$0.00
Medium	Work In Progress			4/15/2011 9:12:06 AM					
Lozoya, Manny		Please repair or replace door handle in room #402							
<u>Albert Vallejo</u>									
72236		Classroom			4/19/2011		28		\$0.00
Medium	Work In Progress	ROOM 310		4/19/2011 1:01:17 PM					
Lozoya, Manny		RICKY CHAVEZ - KEY IS GETTING STUCK IN DOOR WAS AN EMERGENCY HAZARD DURING A FIRE DRILL							
<u>Elena Palacios</u>									
72329					4/21/2011		26		\$0.00
Medium	Work In Progress			4/21/2011 7:45:16 AM					
Vallejo, Albert		Repair sprinklers in front lawn area.							
<u>Albert Vallejo</u>									

5/17/2011 12:10:26 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
72373					4/26/2011		21		\$0.00
Medium	Work In Progress			4/26/2011 7:59:24 AM					
Vallejo, Albert		Paint cubicles black							
Albert Vallejo									
72595					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:52 AM					
Vallejo, Albert		Yearly - Chaparral MS C11 (Swamp Coolers)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
72617					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:43 AM					
Vallejo, Albert		Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
72618					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:44 AM					
Vallejo, Albert		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
72619					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:44 AM					
Vallejo, Albert		Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
72620					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:45 AM					
Vallejo, Albert		Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
72641					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:57 AM					
Orozco, Danny		Monthly - Chaparral MS Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
72741					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:46 AM					
Sanchez, Raul		Monthly - Chaparral MS - DP-781 - Refer to PM schedule details.							
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
72802					5/3/2011		14		\$0.00
Medium	Work In Progress			5/3/2011 8:13:27 AM					
Estrada, Jesus	(PROJECT) GYM - Need to refinish floor.								
Jesus Estrada									
73057					5/10/2011		7		\$0.00
Medium	Work In Progress			5/10/2011 8:28:37 AM					
Carrasco, Danny	Please deliver Five (5) gallons fuel for equipment #604.								
Albert Vallejo									
<b>Count: 42 Work Orders</b>		<b>Avg. Age of WO's 87</b>		<b>Total for Chaparral MS</b>			<b>0</b>	<b>\$0.00</b>	

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Pride</b>							
65860		Office			10/26/2010		203		\$0.00
Medium	Work In Progress			10/26/2010 10:28:42					
Lara, Ralph	NEED TO REPLACE TO OLD DOORS FOR ADMINIST. ASSIST. AND TO COUNSELOR OFFICE.								
<u>David Acosta</u>									
67264					12/5/2010		163		\$0.00
Medium	Work In Progress			12/5/2010 12:27:27 AM					
Sanchez, Raul	Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68494		Library			1/18/2011		119		\$0.00
Medium	Work In Progress	READING/LAD		1/18/2011 1:09:34 PM					
Castillo, Carlos	EMER. LIGHT NOT WORKING								
<u>David Acosta</u>									
69526		Portables			2/15/2011		91		\$0.00
Medium	Work In Progress	BOXING		2/15/2011 12:10:20 PM					
Munoz, Michael	NEED TO PUT UP FENCE ALONG THE EDGE AND END OF SIDE WALK AND RUN IT TO FENCE LINE TO SECURE BOXING RING REQUESTED BY BOXING COACH.								
<u>David Acosta</u>									
70255					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:46 AM					
Orozco, Danny	Yearly - Desert Pride HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70599		Classroom			3/10/2011		68		\$0.00
Medium	Work In Progress	BOXING		3/10/2011 11:30:00 AM					
Carrasco, Danny	TEACHER MR. FERNANDEZ STATES THAT MAINTENANCE ON THE TREADMILLS FOR THE BOXING CLASS NEEDS TO BE TAKEN CARE OF BY WESTSIDE FITNESS.								
<u>Mary Telles</u>									
71289					3/31/2011		47		\$0.00
Medium	Work In Progress			3/31/2011 12:17:35 AM					
Aguilar, Patricio	Monthly - Desert Pride HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Pride</b>							
71872					4/8/2011		39		\$0.00
Medium	Work In Progress			4/8/2011 4:16:26 PM					
Ronquillo, Ruben		Leadership Request				Leadership Request			
		Boxing (some) treadmills don't work.							
		Needs to be completed within 30 days.							
Richard Chavez									
72092		Portables			4/14/2011		33		\$0.00
Medium	Work In Progress			4/14/2011 11:48:12 AM					
Castillo, Carlos		NEED TO CHECK NIGHT LIGHTS ON ALL PORTABLES AND BLDG.							
David Acosta									
72412		Office			4/26/2011		21		\$0.00
Medium	Work In Progress			4/26/2011 11:49:50 AM					
Ambriz, Jose		AC/UNIT NOT COOLING IN CUSTODIAL ROOM ( REMOVE FILTERS TO CLEAN ).							
David Acosta									
72603					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:57 AM					
Aguilar, Patricio		Yearly - Desert Pride HS C11 (Evap.)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
72627					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:48 AM					
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
72628					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:49 AM					
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
72629					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:50 AM					
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
72734					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:43 AM					
Sanchez, Raul		Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Desert Pride</b>							
73158		Library			5/12/2011		5		\$0.00
Medium	Work In Progress	SECURITY			5/12/2011 10:51:15 AM				
Lara, Ralph		HAVING TROUBLE WITH LOCKING AND UNLOCKING DOOR.							
David Acosta									
73159		Library			5/12/2011		5		\$0.00
Medium	Work In Progress	READING / LAD			5/12/2011 10:56:19 AM				
Lara, Ralph		NEED TO REPLACE DOOR KNOB TO REESTROOM.							
David Acosta									
73251					5/16/2011		1		\$0.00
Medium	Work In Progress				5/16/2011 2:32:08 PM				
Estrada, Jesus		NEED TO REPLACE VCT WITH CARPET IN PORTABLE # 6 & 7.							
Jesus Estrada									
73276		Portables			5/17/2011		0		\$0.00
Medium	Work In Progress	ROOM 16			5/17/2011 9:34:06 AM				
Ambriz, Jose		ON DUSTY & WINDY DAYS, DUST COMING IN THROUGH RETURN VENT.							
David Acosta									
<b>Count: 19 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>50</b>	<b>Total for Desert Pride</b>			<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
60600					7/4/2010	7/25/2010	317		\$0.00
Medium	Work In Progress			7/4/2010 12:23:43 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
63218					8/31/2010		259		\$0.00
Medium	Work In Progress			8/31/2010 12:25:01 AM					
Sanchez, Raul	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.								
Margret Villalobos									
63407					9/3/2010		256		\$0.00
Medium	Work In Progress			9/3/2010 2:30:57 PM					
Flores, Pete	Please check red stiner tractor and deliver to Desert Trail to be used with only the front bucket. Thanks								
Johnny Acuna									
64741					10/3/2010	10/24/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:26:59 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
65716		Cafeteria			10/21/2010		208		\$0.00
Medium	Work In Progress			10/21/2010 9:38:23 AM					
Orozco, Danny	FRONT SLIDING DOOR IS HARD TO OPEN AND CLOSE.								
PAT CISNEROS SNP MGR 824-3822									
Jacqueline Aguilar									
66084					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:21					
Orozco, Danny	Monthly - Desert Trail Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
66173					10/31/2010		198		\$0.00
Medium	Work In Progress			10/31/2010 12:37:03					
Sanchez, Raul	Monthly - Desert Trail - Refer to PM schedule details.								
Margret Villalobos									
66228					11/2/2010		196		\$0.00
Medium	Work In Progress			11/2/2010 12:22:21 AM					
Sanchez, Raul	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.								
Margret Villalobos									
5/17/2011 12:10:26 PM									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Desert Trail Intermediate</b>									
67819					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:37 AM					
Villalobos, David	Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
67838					1/2/2011	1/23/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:44 AM					
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
67957					1/4/2011		133		\$0.00
Medium	Work In Progress			1/4/2011 12:24:41 AM					
Sanchez, Raul	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.								
Margret Villalobos									
69986					2/28/2011		78		\$0.00
Medium	Work In Progress			2/28/2011 9:55:12 AM					
Sanchez, Raul	Need a replacement broken pump for the one next to the working one inside the sewer tank, and need to fix or replace check valve: Sewage water keeps backing up from the other tank through the pump.								
Johnny Acuna									
70024					3/1/2011		77		\$0.00
Medium	Work In Progress			3/1/2011 12:18:22 AM					
Sanchez, Raul	Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.								
Margret Villalobos									
70239					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:38 AM					
Orozco, Danny	Yearly - Desert Trail ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
70563					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 5:35:50 PM					
Gonzalez, Salvador	Need 2 posts and chain installed for parking lot area entry to front of Main Building.								
Johnny Acuna									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
70606					3/10/2011		68		\$0.00
Medium	Work In Progress				3/10/2011 2:21:27 PM				
Ontiveros, Joe	Two backflow preventers inside mechanical room are leaking(Domestic). One backflow preventer from heating system is leaking (Mechanical Room).								
<u>Johnny Acuna</u>									
71424					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress				4/3/2011 12:19:48 AM				
Orozco, Danny	Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71432					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress				4/3/2011 12:19:52 AM				
Orozco, Danny	Monthly - Desert Trail Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71490					4/3/2011	4/11/2011	44		\$0.00
Medium	Work In Progress				4/3/2011 12:20:18 AM				
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72034					4/13/2011		34		\$0.00
Medium	Work In Progress				4/13/2011 8:29:17 AM				
Carrasco, Danny	(Danny Carrasco) Need scissor lift for use in painting cafeteria upper part of walls. (Needed for June 2, 2011)								
<u>Johnny Acuna</u>									
72223					4/19/2011		28		\$0.00
Medium	Work In Progress				4/19/2011 10:05:03 AM				
Lozoya, Manny	Need 2 keys made for a storage unit.								
<u>Johnny Acuna</u>									
72312					4/20/2011		27		\$0.00
Medium	Work In Progress				4/20/2011 3:33:05 PM				
Ontiveros, Guadalupe	Please tear down and haul back oven in back playground area.								
<u>Johnny Acuna</u>									
72328					4/21/2011		26		\$0.00
Medium	Work In Progress				4/21/2011 7:33:11 AM				
Sotelo, Enrique	Please fix outdoor security light (Pole) next to main parking lot gates.								
<u>Johnny Acuna</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
72387					4/26/2011		21		\$0.00
Medium	Work In Progress			4/26/2011 8:31:15 AM					
Ontiveros, Guadalupe	Need 2 Rainbird solenoid valves for Irrigation system.								
<u>Johnny Acuna</u>									
72464					4/27/2011		20		\$0.00
Medium	Work In Progress			4/27/2011 10:45:45 AM					
Solis, Lorenzo	(Lorenzo Solis): Need an (overload and relay) for one waterfountain and an (overload) for the other waterfountain in the SW hall.								
<u>Johnny Acuna</u>									
72588					4/29/2011		18		\$0.00
Medium	Work In Progress			4/29/2011 3:53:04 PM					
Lozoya, Manny	Please check and fix doorknob to Restroom in room #205 (Ms. Hernandez) in the kinder hall. Doorknob sometimes gets stuck and teachers cannot open the restroom door.								
<u>Johnny Acuna</u>									
72607					4/30/2011		17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:59 AM					
Sanchez, Raul	Monthly - Desert Trail - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72642					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:57 AM					
Orozco, Danny	Monthly - Desert Trail Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72684					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:19 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72685					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:19 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72686					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:20 AM					
Acuna, Johnny	Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
5/17/2011 12:10:26 PM									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
72756					5/2/2011		15		\$0.00
Medium	Work In Progress	111		5/2/2011 8:47:18 AM					
Lozoya, Manny		In room #111 Mrs. Voldahl needs key for cabinet.							
Elizabeth Hernandez									
72797					5/3/2011		14		\$0.00
Medium	Work In Progress			5/3/2011 12:15:04 AM					
Sanchez, Raul		Monthly - Desert Trail - Domestic Water Filter - Refer to PM schedule details.							
Margret Villalobos									
72823					5/3/2011		14		\$0.00
Medium	Work In Progress			5/3/2011 11:14:59 AM					
Carrasco, Danny		Danny Carrasco: Need 16' of railing for chalkboards and (6) Brackets w/wheels for chalkboard. (Closet Type)							
Johnny Acuna									
72866					5/4/2011		13		\$0.00
Medium	Work In Progress			5/4/2011 8:32:51 AM					
Briones, Enrique		Please pick-up numerous, obsolete projectors, TVs, Cassette Recorders, DVD Players, etc. from Desert Trail Elementary.							
Yolie Jacquez									
72960					5/6/2011		11		\$0.00
Medium	Work In Progress			5/6/2011 11:21:56 AM					
Ontiveros, Guadalupe		(Lupe Ontiveros) Need (2) Diaphragms for Rainbird Irrigation solenoid valves. (Playground Area)							
Johnny Acuna									
73001					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:16 AM					
Acuna, Johnny		Monthly - Desert Trail Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
73056					5/10/2011		7		\$0.00
Medium	Work In Progress			5/10/2011 8:25:55 AM					
Carrasco, Danny		Danny Carrasco: Need (2) (Reversible) 1/3-1/4 Hp motors for rooftop exhaust fans. 115V							
Johnny Acuna									
73060					5/10/2011		7		\$0.00
Medium	Work In Progress			5/10/2011 8:41:30 AM					
Solis, Lorenzo		(Lorenzo Solis) Need (3) Fan Belts: 4L-210							
Johnny Acuna									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Desert Trail Intermediate</b>							
73111					5/11/2011		6		\$0.00
Medium	Work In Progress				5/11/2011 11:31:47 AM				
Carrasco, Danny	Need 15 Gal. of Unleaded gasoline for worktruck (#192) and 1 Gal. of Unleaded gas for Weedeater/Blower. (Equip. #606)								
Johnny Acuna									
73254					5/16/2011		1		\$0.00
Medium	Work In Progress				5/16/2011 2:36:58 PM				
Orozco, Danny	the faucet where you wash your hands is not working. SNP manager Pat C. 824.3822								
Maritza Gonzalez									
<b>Count: 41 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>76</b>	<b>Total for Desert Trail Intermediate</b>			<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
61164					7/20/2010		301		\$0.00
Medium	Work In Progress			7/20/2010 3:53:44 PM					
Ortiz, Ruben	Asp PSFA - Replace or fill red clay pavers on sidewalk. This is a trip hazard.								
<u>Michael Munoz</u>									
61509		Cafeteria			7/29/2010		292		\$0.00
Medium	Work In Progress			7/29/2010 2:48:16 PM					
Moncayo, Fernando	BATHROOM SINK IS LEAKING ALOT OF WATER. (WATER FORMING UNDER SINK).								
	DIANNE L. SNP MGR 580-2425								
<u>Jacqueline Aguilar</u>									
62214					8/10/2010		280		\$0.00
Medium	Work In Progress			8/10/2010 8:51:23 AM					
Orozco, Danny	NEED TO HAVE FIRE EXTINGUISHERS SERVICED AS PER YEARLY INSPECTION								
<u>Danny Orozco</u>									
62218					8/10/2010		280		\$0.00
Safety	Work In Progress			8/10/2010 8:55:30 AM					
Ortiz, Ruben	Check all wall cabinets throughout your site and make sure they are secure to wall and remind teachers not to overload with books. If you should have any questions, call Alfredo or Mike.								
<u>Alfredo Holguin</u>									
63208					8/30/2010		1		\$0.00
Medium	Work In Progress			8/30/2010 5:19:53 PM		8/31/2010			
Ortiz, Ruben	Bathroom doors needs new hinges replaced								
<u>Ruben Ortiz</u>									
66085					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:22					
Orozco, Danny	Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66790					11/17/2010		181		\$0.00
Medium	Work In Progress			11/17/2010 8:03:48 PM					
Lara, Ralph	Requesting two dead bolt locks for portable 6 room A & B. Thank you, Ruben								
Ruben Ortiz									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Desert View ES</b>									
66792					11/17/2010		181		\$0.00
Medium	Work In Progress			11/17/2010 8:33:41 PM					
Ortiz, Ruben	Requesting 6 window screens 20x21 to be replaced due to the vandalism. Thank you, Ruben								
Ruben Ortiz									
67014	Main Building	Classroom			12/1/2010		167		\$0.00
Medium	Work In Progress			12/1/2010 10:54:03 AM					
Lara, Ralph	Keys are not opening the door to room 22 stodge on the west and need key replase. Thank you Ruben								
Ruben Ortiz									
67381					12/7/2010		161		\$0.00
Medium	Work In Progress			12/7/2010 9:08:28 PM					
Lara, Ralph	Assistant Principal would like all the deadbolts in the portables worked on, in case of a lock down. Thank you, Ruben								
Ruben Ortiz									
67563		Athletic Field			12/13/2010		155		\$0.00
Medium	Work In Progress			12/13/2010 3:13:46 PM					
Ortiz, Ruben	Rermove graffiti from playgrounds								
Ruben Ortiz									
67820					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:38 AM					
Villalobos, David	Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
67962	Main Building	Custodial			1/5/2011		132		\$0.00
Medium	Work In Progress			1/5/2011 8:21:11 AM					
Villalobos, David	East side Custodial room water heater has to be replace. Thank you Ruben								
Ruben Ortiz									
69823					2/23/2011		83		\$0.00
Medium	Work In Progress			2/23/2011 11:03:40 AM					
Ortiz, Ruben	Broken chain on the flag pole, needs to replaced. Thank you, Ruben								
Ruben Ortiz									
70240					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:38 AM					
Orozco, Danny	Yearly - Desert View ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
70495					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 11:46:55 AM					
Ambriz, Jose	Rm 27 MCD 004 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70497					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 11:48:40 AM					
Ambriz, Jose	Rm 29 MCD 003 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70498					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 11:50:24 AM					
Ambriz, Jose	Rm 31 MCD 002 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70499					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 11:52:19 AM					
Ambriz, Jose	Rm 33 MCD 001 Size 43; need 1 cover and 1 base								
Ruben Ortiz									
70500					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 11:54:06 AM					
Ambriz, Jose	Rm 24 MCD 005 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70501					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 11:55:48 AM					
Ambriz, Jose	Rm 26 MCD 006 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70502					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 11:57:18 AM					
Ambriz, Jose	Rm 28 MCD 007 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70503					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:07:34 PM					
Ambriz, Jose	Rm 30 MCD 008 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70508					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:21:02 PM					
Ambriz, Jose	Rm 35 MCD 009 Size 43; need 1 cover and 1 base								
Ruben Ortiz									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
70510					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:22:24 PM					
Ambriz, Jose	Rm 37 MCD 010 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70511					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:25:25 PM					
Ambriz, Jose	Rm 39 MCD 011 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70512					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:28:21 PM					
Ambriz, Jose	Rm 41 MCD 012 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70513					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:29:46 PM					
Ambriz, Jose	Rm 32 MCD 015 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70514					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:31:14 PM					
Ambriz, Jose	Rm 34 MCD 014 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70515					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:32:39 PM					
Ambriz, Jose	Rm 36 MCD 013 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70516					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:34:13 PM					
Ambriz, Jose	Rm 10 MCD 021 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70517					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:35:58 PM					
Ambriz, Jose	Rm 12 MCD 022 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70518					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:37:14 PM					
Ambriz, Jose	Rm 14 MCD 023 Size 68; need 1 cover and 1 base								
Ruben Ortiz									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Desert View ES

70519					3/9/2011		69		\$0.00
Medium	Work In Progress				3/9/2011 12:38:49 PM				
Ambriz, Jose		Rm 16 MCD 024 Size 68; need 1 cover and 1 base							
Ruben Ortiz									
70520					3/9/2011		69		\$0.00
Medium	Work In Progress				3/9/2011 12:40:09 PM				
Ambriz, Jose		Rm 11 MCD 020 Size 68; need 1 cover and 1 base							
Ruben Ortiz									
70521					3/9/2011		69		\$0.00
Medium	Work In Progress				3/9/2011 12:41:37 PM				
Ambriz, Jose		Rm 13 MCD 019 Size 68; need 1 cover and 1 base							
Ruben Ortiz									
70522					3/9/2011		69		\$0.00
Medium	Work In Progress				3/9/2011 12:43:13 PM				
Ambriz, Jose		Rm 15A MCD 018 Size 43; need 1 cover and 1 base							
Ruben Ortiz									
70523					3/9/2011		69		\$0.00
Medium	Work In Progress				3/9/2011 12:45:31 PM				
Ambriz, Jose		Rm 15B MCD 017 Size 43; need 1 cover and 1 base							
Ruben Ortiz									
70524					3/9/2011		69		\$0.00
Medium	Work In Progress				3/9/2011 12:46:57 PM				
Ambriz, Jose		Rm 17 MCD 016 Size 43; need 1 cover and 1 base							
Ruben Ortiz									
70525					3/9/2011		69		\$0.00
Medium	Work In Progress				3/9/2011 12:48:14 PM				
Ambriz, Jose		Rm 18 MCD 032 Size 68; need 1 cover and 1 base							
Ruben Ortiz									
70526					3/9/2011		69		\$0.00
Medium	Work In Progress				3/9/2011 12:49:30 PM				
Ambriz, Jose		Rm 20 MCD 031 Size 68; need 1 cover and 1 base							
Ruben Ortiz									
70527					3/9/2011		69		\$0.00
Medium	Work In Progress				3/9/2011 12:50:48 PM				
Ambriz, Jose		Rm 22 MCD 030 Size 68; need 1 cover and 1 base							
Ruben Ortiz									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
70528					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:52:14 PM					
Ambriz, Jose	Rm 19 MCD 029 Size 43; need 1 cover and 1 base								
Ruben Ortiz									
70529					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:53:34 PM					
Ambriz, Jose	Rm 21A MCD 028 Size 43; need 1 cover and 1 base								
Ruben Ortiz									
70530					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:54:56 PM					
Ambriz, Jose	Rm 21B MCD 027 Size 43; need 1 cover and 1 base								
Ruben Ortiz									
70531					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:56:14 PM					
Ambriz, Jose	Rm 23 MCD 026 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
70532					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 12:57:49 PM					
Ambriz, Jose	Rm 25 MCD 025 Size 68; need 1 cover and 1 base								
Ruben Ortiz									
71261		Custodial			3/30/2011		48		\$0.00
Medium	Work In Progress			3/30/2011 3:25:01 PM					
Carbajal, Jimmy	Wet-n-dry needs a new squeegee.								
Jesus Estrada									
71433					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:53 AM					
Orozco, Danny	Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71984					4/11/2011		36		\$0.00
Medium	Work In Progress			4/11/2011 3:44:44 PM					
Ortiz, Ruben	Need to replace 10 swings on the eastside playground								
Ruben Ortiz									
72272					4/19/2011		28		\$0.00
Medium	Work In Progress			4/19/2011 9:30:45 PM					
Ortiz, Ruben	Need to replace 6 water faucets in the restrooms both boys/girls								
Ruben Ortiz									
5/17/2011 12:10:26 PM									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
72355		Classroom			4/21/2011		26		\$0.00
Medium	Work In Progress	Art Class		4/21/2011 3:24:21 PM					
Ortiz, Ruben	Ruben Ortiz to help haul & set up Art Booth on 4/28/11 and take down on 5/2/11 both days morning only. (Bruce Lee)								
<u>Guadalupe Gonzalez</u>									
72608					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:16:00 AM					
Ortiz, Ruben	Yearly - Desert View ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72643					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:58 AM					
Orozco, Danny	Monthly - Desert View ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72744					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:48 AM					
Ortiz, Ruben	Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72745					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:48 AM					
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72746					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:49 AM					
Ortiz, Ruben	Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72747					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:49 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72928					5/5/2011		12		\$0.00
Medium	Work In Progress			5/5/2011 1:06:52 PM					
Flores, Pete	On riding lawn mower tractor 110 replace the shut and trash collecting sac; and blade								
Ruben Ortiz									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
73006					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:18 AM					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
73022					5/9/2011		8		\$0.00
Medium	Work In Progress			5/9/2011 1:44:45 PM					
Orozco, Danny	OVEN IS DOWN. DISHWASHER IS CLOGGING UP UNDERNEATH. SNP MANAGER DIANA L. 589-2425.								
<u>Maritza Gonzalez</u>									
73134					5/11/2011		6		\$0.00
Medium	Work In Progress	Desert View		5/11/2011 4:11:53 PM					
Martinez, Larry	Please pick up the following broken items from Desert View Elem. for disposal T-I 100286 Califone Recorder F00754- Califone T-I 100269 USI Laminator T-I 10027 3M Overhead projector F03911 Hitachi VHS player								
<u>Lucia Almeraz</u>									
73234					5/16/2011		1		\$0.00
Medium	Work In Progress			5/16/2011 9:15:23 AM					
Ronquillo, Ruben	Vandalism 13 broken square glasses 12; 10 by 10 single glass 1; 13 by 15 single glass 7; 20 by 21 window screen								
<u>Ruben Ortiz</u>									
73240					5/16/2011		1		\$0.00
Medium	Work In Progress			5/16/2011 10:24:15 AM					
Ortiz, Ruben	Vandalism Need to replace 7 window screens; 20 by 21								
<u>Ruben Ortiz</u>									
73245					5/16/2011		1		\$0.00
Medium	Work In Progress			5/16/2011 12:38:20 PM					
Carrasco, Danny	Emergency No WATER due to broken water line Need portable water and drinking water ASAP								
Ruben Ortiz									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
73273					5/17/2011		0		\$0.00
Medium	Work In Progress				5/17/2011 8:27:23 AM				
Orozco, Danny	SINK IS CLOGGED UP.								
	LARRY BAKER - ASSIST DIRECTOR SNP								
Jacqueline Aguilar									
73280					5/17/2011		0		\$0.00
Medium	Work In Progress				5/17/2011 10:03:12 AM				
Briones, Enrique	On May 19, 2011, please pick-up 4 obsolete items and 1 working table from Desert View Elementary. Contact Person: Linda Dulovich.								
Yolie Jacquez									
<b>Count: 67 Work Orders</b>		<b>Avg. Age of WO's 77</b>			<b>Total for Desert View ES</b>			<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
60601					7/4/2010	7/25/2010	317		\$0.00
Medium	Work In Progress			7/4/2010 12:23:44 AM					
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
62207					8/10/2010		280		\$0.00
Medium	Work In Progress			8/10/2010 8:44:53 AM					
Orozco, Danny	NEED TO HAVE FIRE EXTINGUISHERS SERVICED AS PER YEARLY INSPECTION								
<u>Danny Orozco</u>									
63425					9/3/2010		256		\$0.00
Medium	Work In Progress			9/3/2010 4:26:13 PM					
Holguin, Alfredo	AS PER JUAN A., GENERATOR DID NOT GO ON TUESDAY AS SCHEDULED.								
<u>Maritza Gonzalez</u>									
64742					10/3/2010	10/24/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:26:59 AM					
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
65962					10/28/2010		201		\$0.00
Medium	Work In Progress			10/28/2010 10:25:54					
Castillo, Carlos	BREAKER IN RECEPTIONIST AREA AND LOUNGE KEEPS JUMPING.								
<u>Maritza Gonzalez</u>									
66086					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:22					
Orozco, Danny	Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67821					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:38 AM					
Villalobos, David	Yearly - GAC Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67839					1/2/2011	1/23/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:45 AM					
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
68249					1/11/2011		126		\$0.00
Medium	Work In Progress			1/11/2011 3:13:39 PM					
Ambriz, Jose	TECHNOLOGY SERVER ROOM- UNIT IS NOT WORKING PROPERLY.								
<u>Maritza Gonzalez</u>									
68250					1/11/2011		126		\$0.00
Medium	Work In Progress			1/11/2011 3:17:23 PM					
Villalobos, David	FLOOR DRAIN CLOGGED- MENS RESTROOM A-WING								
<u>Maritza Gonzalez</u>									
68461					1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 3:11:10 PM					
Miranda, Danny	as per our meeting, please build 4 offices in the dining area. thank you								
<u>Richard Chavez</u>									
68594					1/20/2011		117		\$0.00
Medium	Work In Progress			1/20/2011 9:46:48 AM					
Orozco, Danny	PILOT TO GRILL IS NOT GOIN ON, GENTLEMEN FROM HYDRO CLEAN CAME TO SERVICE/CLEAN HOODS THEY REMOVED APPLIANCES WHEN PUT BACK PILOT DID NOT WORK. APPLIANCES WERE WORKING FINE BEFORE THEY WERE REMOVED. SNP MANAGER GESSICA M.882-6784.								
<u>Maritza Gonzalez</u>									
70132		Parking Lot			3/3/2011		75		\$0.00
Medium	Work In Progress			3/3/2011 9:04:28 AM					
Ontiveros, Guadalupe	need repair with aspalt where leak was.								
<u>Guadalupe Ontiveros</u>									
70175		Parking Lot			3/4/2011		74		\$0.00
Medium	Work In Progress			3/4/2011 8:18:36 AM					
Ambriz, Juan	Need to Install parking stoppers to avoid sprinkler head damage.								
<u>Juan Ambriz</u>									
70199					3/4/2011		74		\$0.00
Medium	Work In Progress	Northside main		3/4/2011 3:40:56 PM					
Ambriz, Jose	Need to repair sprinklers leaking water								
<u>Juan Ambriz</u>									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
70257					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:47 AM					
Orozco, Danny	Yearly - GAC Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70398					3/7/2011		71		\$0.00
Medium	Work In Progress			3/7/2011 9:29:16 AM					
Ambriz, Jose	COOLING UNIT IS NOT WORKING PROPERLY IN SERVER ROOM.								
<u>Juan Ambriz</u>									
71425					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:49 AM					
Orozco, Danny	Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71446					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:59 AM					
Orozco, Danny	Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71505					4/3/2011	4/19/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:25 AM					
Ambriz, Juan	Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71510					4/3/2011	4/11/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:27 AM					
Ambriz, Juan	Monthly - GAC Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71806					4/7/2011		40		\$0.00
Medium	Work In Progress			4/7/2011 4:28:49 PM					
Lara, Ralph	PANIC BAR GETS STUCK ON SIDE ENTRANCE DOOR IN A-WING.								
<u>Maritza Gonzalez</u>									
72094		Electrical Room			4/14/2011		33		\$0.00
Medium	Work In Progress			4/14/2011 1:08:54 PM					
Castillo, Carlos	need to run electrical to sprinkler system alarm								
Danny Orozco									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
72293					4/20/2011		27		\$0.00
Medium	Work In Progress			4/20/2011 9:17:23 AM					
Ambriz, Juan	LIGHT WENT OUT IN UNISEX RESTROOM IN FRONT OF RECEPTIONIST AREA.								
<u>Maritza Gonzalez</u>									
72416					4/26/2011		21		\$0.00
Medium	Work In Progress			4/26/2011 1:00:41 PM					
Lara, Ralph	NEED A AB169 KEY MADE FOR OLD SUPERINTENDENT CONFERENCE ROOM. PLEASE SEE MARITZA.								
<u>Maritza Gonzalez</u>									
72560					4/29/2011		18		\$0.00
Medium	Work In Progress			4/29/2011 11:05:14 AM					
Villalobos, David	SINK IN MENS AND WOMENS HANDICAP RESTROOMS IN A WING ARE CLOGGED.								
<u>Maritza Gonzalez</u>									
72644					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:58 AM					
Orozco, Danny	Monthly - GAC Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72698					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:25 AM					
Ambriz, Juan	Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72699					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:26 AM					
Ambriz, Juan	Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72700					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:26 AM					
Ambriz, Juan	Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72778					5/2/2011		15		\$0.00
Medium	Work In Progress	Dino Martinez		5/2/2011 2:33:51 PM					
Ambriz, Juan	Please paint skylight in Dino's office Thank you								
Lucia Almeraz									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
72899					5/4/2011		13		\$0.00
Medium	Work In Progress				5/4/2011 4:34:05 PM				
Flores, Pete	SNP VEHICLE 150 (LARRY BAKER)- REAR PASSANGER WINDOW DOES NOT GO UP, SERVICE FRACTION CONTROL LIGHT IS COMING ON.								
Maritza Gonzalez									
73002					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress				5/8/2011 12:18:16 AM				
Ambriz, Juan	Monthly - GAC Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
73281		Office			5/17/2011		0		\$0.00
Medium	Work In Progress	Technology			5/17/2011 10:04:58 AM				
Briones, Enrique	On May 19, 2011, please deliver 1 box to Calixto Arzaga at GAC. Reference P.O. # 101107979.								
Yolie Jacquez									
<b>Count: 34 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>89</b>		<b>Total for GAC</b>		<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
61541					7/30/2010		291		\$0.00
Medium	Work In Progress			7/30/2010 11:21:54 AM					
Moncayo, Fernando	Mini blinds need to be replaced where the windows were broken.								
	1. Washington wing workroom 1 blind broken. 2. Jefferson wing Room 202 blinds are broken.								
<u>Fernando Moncayo</u>									
63295		Classroom			9/1/2010		258		\$0.00
Medium	Work In Progress			9/1/2010 12:52:01 PM					
Moncayo, Fernando	MOVE EIGHT SHELVING UNITS FROM GADSDEN ELEMENTARY TO LA UNION JTP FOR ROBERT SAAVEDRA CHECK WITH GRACE MARQUEZ @ GE REGARDING UNITS								
<u>Margaret Villalobos</u>									
66078					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:19					
Orozco, Danny	Monthly - Gadsden ES Fire Sprinkler Insp -Qrtly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66079					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:19					
Orozco, Danny	Monthly - Gadsden ES - Fire Suppression Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67395		Cafeteria			12/8/2010		160		\$0.00
Medium	Work In Progress			12/8/2010 10:58:12 AM					
Moncayo, Fernando	As per Mr. Gallegos reroute and redo serving lines drain plumbing								
<u>Fernando Moncayo</u>									
68176					1/10/2011		127		\$0.00
Medium	Work In Progress			1/10/2011 1:32:21 PM					
Ontiveros, Guadalupe	Please schedule Spring Season fertilaizer for Gadsden Elementary								
<u>Fernando Moncayo</u>									
68903					1/28/2011		109		\$0.00
Medium	Work In Progress			1/28/2011 3:42:34 PM					
Munoz, Michael	need to purchase morgan for site.								
<u>Michael Munoz</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden ES</b>									
68906					1/28/2011		109		\$0.00
Medium	Work In Progress			1/28/2011 3:54:21 PM					
Gallegos, Rafael	Warranty w/o heat pump filters are petty bad(clogged)								
Fernando Moncayo									
69028					2/6/2011	2/27/2011	100		\$0.00
Medium	Work In Progress			2/6/2011 12:33:36 AM					
Orozco, Danny	Monthly - Gadsden ES Fire Sprinkler Insp -Qrtly - Refer to PM schedule details.								
Margret Villalobos									
69866					2/24/2011		82		\$0.00
Medium	Work In Progress			2/24/2011 9:26:18 AM					
Appelzoller, Fred	room 101; Ecoflush toilet won't flush,cleaned strainer,ckd water lines no luck. Also no hot water on shower all valves are open please assist ASAP thanks!!								
Fernando Moncayo									
70143		Library			3/3/2011		75		\$0.00
Medium	Work In Progress			3/3/2011 10:38:12 AM					
Appelzoller, Fred	A horrible smell coming from( the sewer trap?) in or by the Library-Please speak to Mrs. Ida Garcia. Please send a plumber to come fix.								
Rosa Hidalgo									
70719					3/14/2011		64		\$0.00
Medium	Work In Progress			3/14/2011 12:15:18 AM					
Villalobos, Hector	Monthly - Gadsden ES - Grease Trap (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
70733					3/14/2011		64		\$0.00
Medium	Work In Progress			3/14/2011 10:12:49 AM					
Moncayo, Fernando	Need a carpet roto block jose pinon								
Fernando Moncayo									
70885					3/17/2011		61		\$0.00
Medium	Work In Progress			3/17/2011 3:24:06 PM					
Moncayo, Fernando	filters on units need to be changed ASAP, we will start to loose compressors if not changed soon. let me know when complete.thank you								
Michael Munoz									
71648					4/5/2011		42		\$0.00
Medium	Work In Progress			4/5/2011 9:46:56 AM					
Flores, Pete	Mr. Flores, can I borrow the bobcat,for one day, maybe half day will do.Thanks!								
Fernando Moncayo									
5/17/2011 12:10:26 PM									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
71654		Cafeteria			4/5/2011		42		\$0.00
Medium	Work In Progress			4/5/2011 11:12:35 AM					
Moncayo, Fernando	please assist Cuca in cafeteria... ovens are not working properly... thank you								
Loraine Gandara									
71655					4/5/2011		42		\$0.00
Medium	Work In Progress			4/5/2011 11:20:17 AM					
Moncayo, Fernando	As per Mr. Gallegos need to turn off some of the hallways lights								
Fernando Moncayo									
71899					4/10/2011		37		\$0.00
Medium	Work In Progress			4/10/2011 12:14:32 AM					
Pinon, Jose	Monthly -QRTLY BLDG INSP REPORT (GES) - Refer to PM schedule details.								
Jesus Estrada									
71921					4/11/2011		36		\$0.00
Medium	Work In Progress			4/11/2011 8:07:05 AM					
Moncayo, Fernando	Need to paint fire lane curb and no parking zone								
Fernando Moncayo									
72087					4/14/2011		33		\$0.00
Medium	Work In Progress			4/14/2011 10:01:38 AM					
Moncayo, Fernando	Need to treat and clean the holding ponds area, fencelines and the westside of fence next to Hwy 78.								
Michael Munoz									
72212		Classroom			4/19/2011		28		\$0.00
Medium	Work In Progress			4/19/2011 8:10:07 AM					
Moncayo, Fernando	received carts for ELMOS... need for them to be put together and installed in the classrooms... thank you								
Loraine Gandara									
72242		Classroom			4/19/2011		28		\$0.00
Medium	Work In Progress			4/19/2011 2:34:03 PM					
Moncayo, Fernando	loud sounds were coming out of air vents in rm 101....once looked at noticed that there was no filters went to verify other rooms and also were missing filters...some of them were very filthy... please assist in this matter... greatly appreciate your assistance ....								
Loraine Gandara									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
72296		Restroom (Girls)			4/20/2011		27		\$0.00
Medium	Work In Progress			4/20/2011 9:49:13 AM					
Moncayo, Fernando	the water in the girls bathroom as well as in classroom 202 is coming out very hott.. please assist in this matter thank you								
<u>Loraine Gandara</u>									
72635					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:54 AM					
Orozco, Danny	Monthly - Gadsden ES - Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72636					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:54 AM					
Orozco, Danny	Monthly - Gadsden ES Fire Sprinkler Insp -Qrtly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72637					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:55 AM					
Orozco, Danny	Monthly - Gadsden ES - Fire Suppression Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72667					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:10 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72668					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:11 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72669					5/1/2011	5/12/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:11 AM					
Moncayo, Fernando	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72670					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:12 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
72671					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:12 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72806		Cafeteria			5/3/2011		14		\$0.00
Medium	Work In Progress			5/3/2011 8:30:41 AM					
Moncayo, Fernando	weatherstrip needs to be fixed in back door also dripping in the stands needs maintnance... geatly appreciate your assitance in this matter.....								
<u>Loraine Gandara</u>									
72843					5/3/2011		14		\$0.00
Medium	Work In Progress			5/3/2011 3:44:43 PM					
Ontiveros, Joe	Water leak on a 3" copper pipe on Jefferson wing Boy's restrooms								
<u>Fernando Moncayo</u>									
72893					5/4/2011		13		\$0.00
Medium	Work In Progress			5/4/2011 3:51:09 PM					
Flores, Pete	need lawn mower please								
<u>Fernando Moncayo</u>									
72914					5/5/2011		12		\$0.00
Medium	Work In Progress			5/5/2011 8:32:28 AM					
Gonzalez, Salvador	Need two 6"x6" metal plates with a 5/16 hole on each corner								
	Thanks!								
<u>Fernando Moncayo</u>									
72998					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:15 AM					
Moncayo, Fernando	Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
73021					5/9/2011		8		\$0.00
Medium	Work In Progress			5/9/2011 1:01:46 PM					
Moncayo, Fernando	Need parts for haws drinking fountains								
<u>Fernando Moncayo</u>									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden ES</b>							
73066		Football Field			5/10/2011		7		\$0.00
Medium	Work In Progress			5/10/2011 9:35:24 AM					
Ontiveros, Guadalupe	PER MS. MARQUES NEED ASSISTANCE IN INSTALLING SOCCER GOALS AND MEASURING THE WIDTH AND LENGHT OF THE SOCCER FIELDS...THANK YOU...								
<hr/>									
Loraine Gandara		Athletic Field			5/12/2011		5		\$0.00
73157				5/12/2011 9:47:07 AM					
Medium	Work In Progress								
Moncayo, Fernando	please assemble soccer goals and install. please call mike when ready so that he may send support.thank you								
Michael Munoz									
<b>Count: 39 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>62</b>	<b>Total for Gadsden ES</b>				<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
61798					8/3/2010		287		\$0.00
Medium	Work In Progress			8/3/2010 11:00:19 AM					
Lara, Ralph	Requested by Mr. Chambers for Entire Campus-Name plates w/room numbers for entire campus-all teachers, offices, etc.								
<u>Velia Alarcon</u>									
62248					8/10/2010		280		\$0.00
Medium	Work In Progress			8/10/2010 10:55:42 AM					
Herrera, Joel	Requested by Coach Lawrence for Main Soccer Field- Paint both awnings on Main Soccer Field.								
<u>Velia Alarcon</u>									
62314	Boys Gym				8/11/2010		279		\$0.00
Medium	Work In Progress			8/11/2010 11:13:51 AM					
Ambriz, Jose	Requested by Coach Lawrence for Rm. 408 Boy's Gym- The new Boy's Soccer Locker Room needs air conditioning of some type. It's very hot in there.								
<u>Velia Alarcon</u>									
62985					8/26/2010		264		\$0.00
Medium	Work In Progress			8/26/2010 12:38:44 PM					
Castillo, Carlos	Requested by Ms. Leahy Rm. 127 Main Building-The electricity keeps going out in my room. Please check on this since it is effecting my computer.								
<u>Velia Alarcon</u>									
63373					9/2/2010		257		\$0.00
Medium	Work In Progress			9/2/2010 3:07:40 PM					
Apodaca, Mario	Requested by Coach Hite for Press Box at Football Field -If we provide paint, can you paint press box.				Assign to Mario asp Mike. The paint is not the problem is the labor, If Mario/Joel can squeeze this in, if it's not possible stay on priority wo's and pms.				
<u>Velia Alarcon</u>									
63613					9/8/2010		251		\$0.00
Medium	Work In Progress			9/8/2010 9:42:08 AM					
Lara, Ralph	Need to install locks between wood shop and art class.								
<u>Michael Munoz</u>									
63766					9/10/2010		249		\$0.00
Medium	Work In Progress			9/10/2010 2:58:55 PM					
Apodaca, Mario	Requested by Ms. Simmons Rm. 324 English Book Room in Academic Building-Need shelves for back wall in English book room. This would help immensely.								
<u>Velia Alarcon</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
64440					9/28/2010		231		\$0.00
Medium	Work In Progress			9/28/2010 7:59:08 AM					
Castillo, Carlos	CALI WE NEED TO REPLACE TWO BULBS LIGHTS AT G.Y.M THANK YOU CALI								
Joel Herrera									
64598					9/30/2010		229		\$0.00
Medium	Work In Progress			9/30/2010 11:04:24 AM					
Castillo, Carlos	Requested by Mr. Pokluda for Tennis Courts-Re-wire electrical outlet on south side of Tennis Courts. Outlet is needed for tennis ball machine during practice.								
Velia Alarcon									
65724					10/21/2010		208		\$0.00
Medium	Work In Progress			10/21/2010 2:23:13 PM					
Castillo, Carlos	10/21/10 I need an electrician to disconnect swimming pool pump and reconnect a new pump in place of the old one. The old pump needs to be rebuilt as it is not pumping to full capacity Thanks, Raul								
Raul Sanchez									
65815					10/25/2010		204		\$0.00
Medium	Work In Progress			10/25/2010 1:25:16 PM					
Sanchez, Raul	10/25/10 I need a w.o. for the purchase of a replacement clear effluent pump that I will be installing at the GHS wwtp. We are presently working on only one pump as the other one overheated & burnt out. I will use work order for the initial installation as well. Thanks, Raul								
Raul Sanchez									
65866	North Building	Classroom			10/26/2010		203		\$0.00
Medium	Work In Progress			10/26/2010 2:18:58 PM					
Appelzoller, Fred	As per Ms. Romero, she would like to have the gas jets on the science workbenches repaired in room 222, north building.								
Mario Apodaca									
65974					10/28/2010		201		\$0.00
Medium	Work In Progress			10/28/2010 3:03:22 PM					
Castillo, Carlos	CALI WE HAVE PROBLEM WITH THE LIGHT BEHIND TO ACADEMIC BUILDING IT DOESNT TURON								
Joel Herrera									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
66087					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:23					
Orozco, Danny	Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66483					11/9/2010		189		\$0.00
Medium	Work In Progress			11/9/2010 9:07:47 AM					
Castillo, Carlos	please check lighting around buss turn- around and repair as need be. thanks								
<u>Michael Munoz</u>									
66488					11/9/2010		189		\$0.00
Medium	Work In Progress			11/9/2010 9:50:24 AM					
Appelzoller, Fred	FRED WE NEED TO RE PLACE SINCK ON GIRLS REST ROOMS AT NORTH BUILDING								
<u>Joel Herrera</u>									
66843	Cafeteria (1998)	Cafeteria			11/19/2010		179		\$0.00
Medium	Work In Progress			11/19/2010 10:34:10					
Apodaca, Mario	As per Mr. Pokluda he wants the floor tiles that were broken during basketball practice inside the cafeteria repaired.		Mary,		I went to GHS and there are not enough broken tiles in the cafeteria to make it worth their while. Go ahead and forward that work order to the building mechanic. Thanks.				
<u>Joe Munoz</u>									
66919					11/29/2010		169		\$0.00
Medium	Work In Progress			11/29/2010 2:50:42 PM					
Apodaca, Mario	Requested by Coach Greenwald Rm. 651 Business Building-Need new blind and need window latch fixed.								
<u>Velia Alarcon</u>									
67138					12/3/2010		165		\$0.00
Medium	Work In Progress			12/3/2010 3:08:33 PM					
Castillo, Carlos	Requested by Velia for Lights on the West Side of the Academic Building Facing Bus Turn Around-The two west lights are burned out and is very dark when students arrive from Athletic Events or late field trips.								
<u>Velia Alarcon</u>									
67140					12/3/2010		165		\$0.00
Medium	Work In Progress			12/3/2010 3:09:49 PM					
Castillo, Carlos	Requested by Velia for Marquee in Front of the School- South side light is burned out, please replace.								
<u>Velia Alarcon</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
67312		Athletic Field			12/6/2010		162		\$0.00
Medium	Work In Progress				12/6/2010 2:12:53 PM				
Ontiveros, Guadalupe	Truck#122 needs module lite protector replaced.								
Guadalupe Ontiveros									
67421					12/8/2010		160		\$0.00
Medium	Work In Progress				12/8/2010 3:50:47 PM				
Castillo, Carlos	CALI LIGHTS TO CAFETERIA OUTSIDE NOT WORKING THANK YOU CALI								
Joel Herrera									
67609					12/14/2010		154		\$0.00
Medium	Work In Progress				12/14/2010 12:25:29				
Castillo, Carlos	Requested by Velia for Academic Building-All outside lights around the building need to be checked, many students walk around or between buildings to get to the Bus Turn Around afterschool. Extremely dark at night and a possible safety issue with the construction fence between the North and Academic Buildings.								
Velia Alarcon									
67822					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress				1/2/2011 12:28:38 AM				
Villalobos, David	Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
67905					1/2/2011	1/10/2011	135		\$0.00
Medium	Work In Progress				1/2/2011 12:29:20 AM				
Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
68083		Athletic Field			1/7/2011		130		\$0.00
Medium	Work In Progress				1/7/2011 1:05:58 PM				
Ontiveros, Guadalupe	Gator 4x2 needs steering gear replaced and hood to be replaced. also battery.								
Guadalupe Ontiveros									
68084		Athletic Field			1/7/2011		130		\$0.00
Medium	Work In Progress				1/7/2011 1:13:33 PM				
Ontiveros, Guadalupe	735 mower leaking from crank shaft and intake valve needs to be replaced. Also cylinder block needs replacement.								
Guadalupe Ontiveros									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
68333	Auto Shop	Classroom			1/13/2011		124		\$0.00
Medium	Work In Progress			1/13/2011 8:08:45 AM					
Castillo, Carlos		need assist on put new ballast for the lamps at the auto shop							
<u>Mario Apodaca</u>									
68406					1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 12:23:45 AM					
Sanchez, Raul		Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
68451	Old English Bldg				1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 2:41:54 PM					
Munoz, Michael		(PROJECT)				Leadership Request			
		Sidewalk in front is trip hazard. - repair / replace							
<u>Alfredo Holguin</u>									
68457					1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 2:50:01 PM					
Munoz, Michael		(PROJECT)				Leadership Request			
		Purchase and install new marquee.							
<u>Alfredo Holguin</u>									
68535					1/19/2011		118		\$0.00
Medium	Work In Progress			1/19/2011 8:55:23 AM					
Apodaca, Mario		Requested by Ms. Roth Rm. 328 Academic Building- Shelves in storage cabinets need to be re-enforced so they don't break holding the stored science equipment and materials.							
<u>Velia Alarcon</u>									
69082					2/6/2011	2/12/2011	100		\$0.00
Medium	Work In Progress			2/6/2011 12:33:58 AM					
Apodaca, Mario		Monthly - Gadsden HS - Elevator (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
69168	Pool Dressing	Dressing Room			2/8/2011		98		\$0.00
Medium	Work In Progress			2/8/2011 8:24:29 AM					
Appelzoller, Fred		the pool dressing room need new sink faucet and shower faucet do to freezeing water in pipe							
<u>Mario Apodaca</u>									
69177	North Building	Hallway/Corridor			2/8/2011		98		\$0.00
Medium	Work In Progress			2/8/2011 8:49:40 AM					
Appelzoller, Fred		outside hosebib at the n-bldg by room 221 a copper pipe need to be repair							
<u>Mario Apodaca</u>									
5/17/2011 12:10:27 PM									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
69330					2/10/2011		96		\$0.00
Medium	Work In Progress			2/10/2011 10:33:45 AM					
Ontiveros, Guadalupe	Requested by Coach Lawrence for Soccer Fields-Over seed, top soil, and fertilize main soccer field.								
<u>Velia Alarcon</u>									
69422					2/14/2011		92		\$0.00
Medium	Work In Progress			2/14/2011 12:26:03 AM					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69591	North Building	Parking Lot			2/16/2011		90		\$0.00
Medium	Work In Progress			2/16/2011 11:13:36 AM					
Apodaca, Mario	the n/side parking lot need to be restrip and handicap repaint for the new office								
<u>Mario Apodaca</u>									
70254					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:45 AM					
Orozco, Danny	Yearly - Gadsden HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70331					3/6/2011	3/14/2011	72		\$0.00
Medium	Work In Progress			3/6/2011 12:18:24 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70333					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:18:25 AM					
Apodaca, Mario	Yearly - Gadsden HS A10 (Heat Pumps)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70445					3/8/2011		70		\$0.00
Medium	Work In Progress			3/8/2011 9:24:16 AM					
Castillo, Carlos	Requested by Ms. Moreno Rm. 126 Main Building- Electricity on for wall shorted out, no electricity to the computer and printer.								
<u>Velia Alarcon</u>									
70446					3/8/2011		70		\$0.00
Medium	Work In Progress			3/8/2011 9:27:02 AM					
Gonzalez, Salvador	Requested by Al Marmolejo for Bus Turn Around Gate- North Bus Turn Around Gate is not working properly, does not open or close correctly.								
<u>Velia Alarcon</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
70447					3/8/2011		70		\$0.00
Medium	Work In Progress			3/8/2011 9:28:32 AM					
Herrera, Joel	Requested by Velia for Marque in Front of School-Both lights on the marquee are burned out, they need to be replaced.								
<u>Velia Alarcon</u>									
70490	North Building				3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 10:22:49 AM					
Lara, Ralph	Requested by Commander Dixon for Room #'s 201, 202, 203 in the North Building-Repair or replace wooden doors on all three classrooms.								
<u>Velia Alarcon</u>									
70708					3/13/2011		65		\$0.00
Medium	Work In Progress			3/13/2011 12:13:05 AM					
Apodaca, Mario	Monthly - Gadsden HS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70724					3/14/2011		64		\$0.00
Medium	Work In Progress			3/14/2011 12:15:20 AM					
Sanchez, Raul	Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70883					3/17/2011		61		\$0.00
Medium	Work In Progress			3/17/2011 3:19:35 PM					
Ontiveros, Guadalupe	Requested by Coach Letz for Tennis Courts-WORK ORDER # 69374 HAS NOT BEEN COMPLETED. Please clean and blow off sand from Tennis Courts, 2nd Notice.								
<u>Velia Alarcon</u>									
70979		Classroom			3/21/2011		57		\$0.00
Medium	Work In Progress			3/21/2011 12:36:15 PM					
Castillo, Carlos	need to put new outlet at od to a shot. room 126								
<u>Mario Apodaca</u>									
71028	Main Building	Classroom			3/23/2011		55		\$0.00
Medium	Work In Progress			3/23/2011 3:24:20 PM					
Lara, Ralph	The door lock at classroom 121 will lock but when you pull on it the door will open because it will not secure.								
<u>Joe Munoz</u>									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

71048	Boys Gym	Dressing Room			3/24/2011		54		\$0.00
Medium	Work In Progress				3/24/2011 12:30:35 PM				

Castillo, Carlos  
a lamp at the boys gym w3as pull down off the ceiling  
need to be repair. do to vandalism. A.S.A.P

Mario Apodaca

71049	Boys Gym	Dressing Room			3/24/2011		54		\$0.00
Medium	Work In Progress				3/24/2011 12:34:36 PM				

Apodaca, Mario  
THE CEILING IN THE BOYS DRESSING ROOM WAS  
PULL DOWN NEED TO BE REPAIR DO TO  
VANDALISM. A.S.A.P

Mario Apodaca

71127	Pool Pump	Pool			3/28/2011		50		\$0.00
Medium	Work In Progress				3/28/2011 8:57:01 AM				

Sanchez, Raul  
3/28/11  
need a work order to purchase a cast iron hair & lint  
strainer for the swimming pool. The one in place now is  
leaking & is corroded. I have the quote for a new  
one. Thanks, Raul

Raul Sanchez

71142	Pool Dressing	Changing Room			3/28/2011		50		\$0.00
Medium	Work In Progress				3/28/2011 10:58:45 AM				

Sanchez, Raul  
Need the following completed by April 29th. (Asp Mike,  
Fred will assist)  
-4 shower Heads popped out  
-4 shower valves popped out  
-2 sink faucets broke  
-1 sink feeder line broke  
-2 sink traps leaking  
-Janitor Sink faucet not working

Alfredo Holguin

71143	Pool Dressing	Changing Room			3/28/2011		50		\$0.00
Medium	Work In Progress				3/28/2011 11:03:19 AM				

Apodaca, Mario  
Need the following completed by April 29th. (Mario &  
Joel)  
-A/C line burst  
-Heavy water leak from ceiling ( office area )  
-Broken tiles along edges ( safety hazard )  
-Broken benches ( both dressing areas )

Alfredo Holguin

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

71145	Pool Pump				3/28/2011		50		\$0.00
-------	-----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/28/2011 11:13:13 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Sanchez, Raul Need the following completed by April 29th.

- Pump room main line broke
- Switch out pump
- Backflow valve leaks
- Clean Diodes
- Check System lines for leaks
- Flush Chlorinator
- Repair lifeguard Chairs
- Repair Handicap lift
- Repair steps to water slide
- Repair water lines on slide
- Overall clean up

Alfredo Holguin

71146	Pool Pump				3/28/2011		50		\$0.00
-------	-----------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/28/2011 11:14:58 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Apodaca, Mario Need the following completed by April 29th. (Mario &amp; Joel)

- Install signs
- Install picnic shade

Alfredo Holguin

71287					3/31/2011	5/1/2011	47		\$0.00
-------	--	--	--	--	-----------	----------	----	--	--------

Medium	Work In Progress			3/31/2011 12:17:34 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Apodaca, Mario Yearly - Gadsden HS A8 (Window Unit)(Yearly) - Refer to PM schedule details.

Margret Villalobos

71304					3/31/2011		0		\$0.00
-------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress			3/31/2011 9:11:38 AM	3/31/2011				
--------	------------------	--	--	----------------------	-----------	--	--	--	--

Flores, Pete Truck #137 needs oil change.

Guadalupe Ontiveros

71327	Main Building	Classroom			3/31/2011		47		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			3/31/2011 2:49:07 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos the outlet at room126 are not working (wo#70979)

Mario Apodaca

71362					4/1/2011		46		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress			4/1/2011 10:43:38 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe Requested by Coach Hite for Practice Football Field-We want the practice Football Field (dirt field) marked, lined, as soon as possible.

Velia Alarcon

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
71363					4/1/2011		46		\$0.00
Medium	Work In Progress			4/1/2011 10:46:13 AM					
Appelzoller, Fred	Requested by Oscar Menchaca for Boy's & Girl's Dressing Rooms in the Boy's Gym-Water fountain is broken and a sink keep leaking.								
<u>Velia Alarcon</u>									
71400					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:36 AM					
Vallejo, Albert	Monthly - Gadsden HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71434					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:53 AM					
Orozco, Danny	Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71524					4/3/2011	4/11/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:33 AM					
Apodaca, Mario	Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71525					4/3/2011	4/11/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:33 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71526					4/3/2011	4/19/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:34 AM					
Apodaca, Mario	Monthly - Gadsden HS A1 (Air Dryer)(S.Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71527					4/3/2011		44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:34 AM					
Apodaca, Mario	Yearly - Gadsden HS A13 (Ceil/Wall Unit)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71528					4/3/2011	4/9/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:35 AM					
Apodaca, Mario	Monthly - Gadsden HS - Elevator (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
71649	Library	Library			4/5/2011		42		\$0.00
Medium	Work In Progress				4/5/2011 10:05:51 AM				
Flores, Pete	As per Mr. Grubaugh, the library would like to borrow one or more pickup trucks next week to help with moving into the new library building. They will need them 4/11 - 4/15.								
<u>Mario Apodaca</u>									
71741	Cafeteria (1998)	Cafeteria			4/6/2011		41		\$0.00
Medium	Work In Progress				4/6/2011 3:02:22 PM				
Ambriz, Jose	need a new e/cooler moter for a unit at the cafe bldg 3 hp								
<u>Mario Apodaca</u>									
71751		Football Field			4/6/2011		41		\$0.00
Medium	Work In Progress				4/6/2011 3:35:57 PM				
Ontiveros, Guadalupe	need to move the old electrical post and put on the n-side of the athletic fields								
<u>Mario Apodaca</u>									
71793					4/7/2011		40		\$0.00
Medium	Work In Progress				4/7/2011 3:25:02 PM				
Ontiveros, Guadalupe	need to cover/remove lose dirt in areas between new addition to varsit gym and new admin. add pea gravel								
<u>Alfredo Holguin</u>									
71795	Varsity Gym	Dressing Room			4/7/2011		40		\$0.00
Medium	Work In Progress				4/7/2011 3:28:07 PM				
Herrera, Joel	Girl locker room on northwest corner of gym- repair and paint ceiling and walls remove tile and paint with epoxy paint								
<u>Alfredo Holguin</u>									
71798	Pool Pump	Pump House			4/7/2011		40		\$0.00
Medium	Work In Progress				4/7/2011 3:39:50 PM				
Castillo, Carlos	Need to meet with general contractors regarding undersized electrical system for irrigation and fire suppression system.								
<u>Carlos Castillo</u>									
71824	Academic Bldg	Mechanical			4/8/2011		39		\$0.00
Medium	Work In Progress				4/8/2011 10:45:38 AM				
Appelzoller, Fred	need a new pvc female adapter and plug outside the academic bldg by the mech/room								
<u>Mario Apodaca</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
71826	North Building	Parking Lot			4/8/2011		39		\$0.00
Medium	Work In Progress			4/8/2011 10:55:39 AM					
Apodaca, Mario		need a to put a chain by the flagpoles							
<u>Mario Apodaca</u>									
71846	Football Stadium	Athletic Field			4/8/2011		39		\$0.00
Medium	Work In Progress			4/8/2011 2:53:11 PM					
Ontiveros, Guadalupe		As per Mr. Chambers, please sweep the football field on a weekly basis.							
<u>Cathy Ramos</u>									
71898					4/10/2011	4/26/2011	37		\$0.00
Medium	Work In Progress			4/10/2011 12:14:31 AM					
Munoz, Joe		Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.							
<u>Jesus Estrada</u>									
71916	Academic Bldg				4/11/2011		36		\$0.00
High	Work In Progress			4/11/2011 7:30:37 AM					
Villalobos, David		clean out is missing a plug, need to install one for a 4" dwv pipe. area is just south of the mechanical room in the academic building, thank you							
<u>Michael Munoz</u>									
71926	Academic Bldg				4/11/2011		36		\$0.00
High	Work In Progress			4/11/2011 8:29:00 AM					
Ontiveros, Joe		sewer bcked up this weekend 4-09-11 on the academic building. thank you fo r responding.							
<u>Joe Munoz</u>									
71932	Pool Pump	Pool			4/11/2011		36		\$0.00
Medium	Work In Progress			4/11/2011 8:37:35 AM					
Sanchez, Raul		4/11/11 Pool Start-up Project, to be done by water/wastewater tech, helpers & plumber							
<u>Raul Sanchez</u>									
72001	Vocational	Classroom			4/12/2011		35		\$0.00
Medium	Work In Progress			4/12/2011 12:17:12 PM					
Apodaca, Mario		need to pick-up and delivered tables to santa teresa m.s for the art exhibit . set-up 4/28/11 and pick-up 5/02/11							
<u>Mario Apodaca</u>									
72072					4/14/2011		33		\$0.00
Medium	Work In Progress			4/14/2011 12:14:19 AM					
Sanchez, Raul		Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									

5/17/2011 12:10:27 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
72129	North Building				4/15/2011		32		\$0.00
Medium	Work In Progress			4/15/2011 7:34:03 AM					
Castillo, Carlos	in the entrances to the G,H,S wings there is a recessed light. if they are not needed please remove and cap off , if not please repair.thank you								
<u>Michael Munoz</u>									
72286		Athletic Field			4/20/2011		27		\$0.00
Medium	Work In Progress			4/20/2011 8:27:45 AM					
Gonzalez, Salvador	we need two ranchers gates at baseball and softball fields to control traffic.								
<u>Guadalupe Ontiveros</u>									
72332		Football Field			4/21/2011		26		\$0.00
Medium	Work In Progress			4/21/2011 8:01:10 AM					
Castillo, Carlos	As per Raul Sanchez:Motor starter for irrigation pump has a loose connection.								
<u>Carlos Castillo</u>									
72391	Main Building	Pump House			4/26/2011		21		\$0.00
Medium	Work In Progress			4/26/2011 8:37:40 AM					
Castillo, Carlos	need two new 3-phase line monitors for the controlsm at the pressure tank								
<u>Mario Apodaca</u>									
72405		Pool			4/26/2011		21		\$0.00
Medium	Work In Progress			4/26/2011 9:06:38 AM					
Sanchez, Raul	4/26/11 I need a work order for the inspection and initial installation of a new pump,motor,pipe and wire for irrigation well #2 located behind the pool.Changes were necessary to meet the demands of the new Fire Pump system and irrigation of fields								
<u>Raul Sanchez</u>									
72430	Pool Dressing				4/26/2011		21		\$0.00
High	Work In Progress			4/26/2011 3:34:28 PM					
Miranda, Danny	please repair or replace, tape and texture drywall in dressing rooms due to this years winter storm. please contact mike.thankyou								
<u>Michael Munoz</u>									
72439		Pool			4/26/2011		21		\$0.00
High	Work In Progress			4/26/2011 3:39:50 PM					
Marquez, Gerardo	please repair areas in shower areas where valves where replaced due to this years winter storm. thank you								
<u>Michael Munoz</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
72449					4/27/2011		20		\$0.00
Medium	Work In Progress			4/27/2011 8:08:36 AM					
Castillo, Carlos	As per Raul Sanchez ,new irrigation pump tripped the new 175 amp circuit breaker in new control panel.								
<u>Carlos Castillo</u>									
72475					4/27/2011		20		\$0.00
Medium	Work In Progress			4/27/2011 1:32:57 PM					
Castillo, Carlos	CALI WE HAVE ELECTRICAL PROBLEMS ON A/C ON CLASS ROOM # 321 AT ACADEMIC BUILDING THANK YOU CALI								
<u>Joel Herrera</u>									
72509	Pool Pump	Pool			4/28/2011		19		\$0.00
Medium	Work In Progress			4/28/2011 11:12:14 AM					
Castillo, Carlos	need to remove and put back lights fixers at the pool lockroom								
<u>Mario Apodaca</u>									
72525		Athletic Field			4/28/2011		19		\$0.00
Medium	Work In Progress			4/28/2011 3:24:01 PM					
Ontiveros, Guadalupe	need to secure holding pond by grounds shop. safety								
<u>Guadalupe Ontiveros</u>									
72547		Athletic Field			4/29/2011		18		\$0.00
Medium	Work In Progress			4/29/2011 8:36:35 AM					
Ontiveros, Guadalupe	need to install gate and chain link fence. gate needs wheels replaced and gate needs hangers replaced. this material is to secure around football field.								
<u>Guadalupe Ontiveros</u>									
72562	Academic Bldg				4/29/2011		18		\$0.00
Medium	Work In Progress			4/29/2011 11:09:47 AM					
Apodaca, Mario	need outside paint for the academic bldg								
<u>Mario Apodaca</u>									
72591					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:50 AM					
Apodaca, Mario	Yearly - Gadsden HS C11 (Evap.Condnser)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72645					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:59 AM					
Orozco, Danny	Monthly - Gadsden HS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
72688					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:21 AM					
Herrera, Joel	Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72689					5/1/2011	5/4/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:21 AM					
Herrera, Joel	Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72690					5/1/2011	6/1/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:22 AM					
Herrera, Joel	Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72691					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:22 AM					
Herrera, Joel	Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72692					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:22 AM					
Herrera, Joel	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72710					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:31 AM					
Apodaca, Mario	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72711					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:32 AM					
Apodaca, Mario	Monthly - Gadsden HS - Elevator (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72729					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:41 AM					
Sanchez, Raul	Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.								
<u>Margret Villalobos</u>									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden HS</b>							
72755	Pool Dressing	Dressing Room			5/2/2011		15		\$0.00
Medium	Work In Progress				5/2/2011 8:01:17 AM				
Gonzalez, Salvador		Install stainless steel plates in dressing room showers							
Salvador Gonzalez									
72812					5/3/2011		14		\$0.00
Medium	Work In Progress				5/3/2011 8:59:06 AM				
Herrera, Joel		Requested by Ms. G. Nevarez Rm. 125 Main Building- Need lights replaced in storage closet.							
Velia Alarcon									
72813					5/3/2011		14		\$0.00
Medium	Work In Progress				5/3/2011 9:03:02 AM				
Ontiveros, Guadalupe		Requested by Coach Hite for Main Football Field-Need to sweep the entire field. Field has many small objects that can cause cuts on P.E. students or Football Players using the field.							
Velia Alarcon									
72815					5/3/2011		14		\$0.00
Medium	Work In Progress				5/3/2011 9:07:35 AM				
Ontiveros, Guadalupe		Requested by Coach Hite for Practice Football Field- Need to have the practice field marked as soon as possible.							
Velia Alarcon									
72817					5/3/2011		14		\$0.00
Medium	Work In Progress				5/3/2011 9:17:42 AM				
Ontiveros, Guadalupe		Requested by Coach Yanez for Baseball Field-Move Baseball storage shed behind dugout onto slab of cement and put up fence with gate around the slab of cement to store away equipment at the end of the season.							
Velia Alarcon									
72820					5/3/2011		14		\$0.00
Medium	Work In Progress				5/3/2011 10:17:23 AM				
Apodaca, Mario		Requested by Mr. R. Ramos-The Senior Class will be having a Senior Carnival on Thursday, May 19, 2011; 150 chairs will be needed, 25 tables, and 5 generators for that day.							
Velia Alarcon									
72869					5/4/2011		13		\$0.00
Medium	Work In Progress	South Gate			5/4/2011 9:37:23 AM				
Lara, Ralph		Need key for South Gate. Contractor will pick up key at the Construction Office. Contractor Info: GenCon Corp. / Tilley Arenibas (575) 644-2665							
Peggy Jo Hernandez									

5/17/2011 12:10:27 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

72877					5/4/2011		13		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/4/2011 2:59:29 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Munoz, Joe Requested by Ms. Luna Rm 109A Main Building-Tiles need to be taken off and brushed clean. Rat and mice droppings fall on heads and furniture.

Velia Alarcon

72884					5/4/2011		13		\$0.00
-------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/4/2011 3:21:48 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph Requested by Velia-Several keys need to be made for New Library and they are:  
HE5---three are needed  
HE6---three are needed  
HE8---three are needed  
HE9---three are needed  
HE11--three are needed

HE10-- ONE is needed

I also need to speak to Rafa about keys to the new building, if possible as soon as possible. Thank you.

Velia Alarcon

72917	Cafeteria (1998)	Cafeteria			5/5/2011		12		\$0.00
-------	------------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/5/2011 9:53:13 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Apodaca, Mario Service all lights, air conditioners, paint over all grafitti, we need the cafeteria spot less for the governor's visit on 5-7-11. ASAP!!!!!! PLEASE!!!!!!

Cathy Ramos

73032	North Building	Classroom			5/9/2011		8		\$0.00
-------	----------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress				5/9/2011 3:21:20 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Castillo, Carlos the outlet to room 201 are not working

Mario Apodaca

73035		Restroom (Boys)			5/9/2011		8		\$0.00
-------	--	-----------------	--	--	----------	--	---	--	--------

Medium	Work In Progress				5/9/2011 3:31:19 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Villalobos, David the restroom on the s/side of the parking lot the pipe need to be fix do to water leaks.

Mario Apodaca

73075	New Vocational				5/10/2011		7		\$0.00
-------	----------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Annex			5/10/2011 2:20:37 PM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Lara, Ralph Need the following keys for Annex Bldg. (Vocational Bldg.): 1) Main East Doors 2) Mr. Myers' Classroom 3) Electrical Room and 4) South Gate Key. Contractor will pick up at the Construction Office. Contractor Info: Marco Hamilton, ESA Construction (575) 642-1560.

Peggy Jo Hernandez

5/17/2011 12:10:27 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
73085	Boys Gym	Dressing Room			5/10/2011		7		\$0.00
Medium	Work In Progress				5/10/2011 3:29:56 PM				
Villalobos, David	BLOCKAGES ON A SEWER LINE OUTSIDE THE BOYS GYM ON THE S/SIDE BLDG								
Mario Apodaca									
73135					5/11/2011		6		\$0.00
Medium	Work In Progress				5/11/2011 4:18:31 PM				
Lara, Ralph	Requested by Velia-Key that was made for East Wing of Cafeteria does not work. Also, key cylinder comes out half ways. I also need to see and speak to Rafa regarding keys to the new buildings (Admin., Varsity Gym, and Library) as soon as possible.								
Velia Alarcon									
73141	Vocational				5/12/2011		5		\$0.00
High	Work In Progress				5/12/2011 7:23:15 AM				
Apodaca, Mario	a dumpster will be delivered to the southside of the woodshop classroom. we need to start cleaning out the room this coming monday 5-16-11. please dispose of any unwanted items.a fork lift will be present to move equipment into the ag shop. the teacher is aware. please call me if you should have any questions. thank you								
Michael Munoz									
73172	Varsity Gym				5/12/2011		5		\$0.00
Medium	Work In Progress				5/12/2011 3:43:19 PM				
Lara, Ralph	Requested by Velia-Keys for the Varsity Gym Concession Stand are needed. Four # 227 keys are needed and four gold keys are needed for gate in concession stand of Varsity Gym.								
Velia Alarcon									
73174					5/12/2011		5		\$0.00
Medium	Work In Progress				5/12/2011 3:46:33 PM				
Lara, Ralph	Requested by Velia-No keys to drawers and cabinets for both Varsity Gym and Administrative Building Work Room's were given to me. Two sets for now are needed for both areas.								
Velia Alarcon									
73198					5/13/2011		4		\$0.00
Medium	Work In Progress				5/13/2011 9:38:45 AM				
Apodaca, Mario	Requested by Ms. Smith Rm. 127 Main Building-Room is frigid, kids are all shivering (as am I), could some of the vents be closed.								
Velia Alarcon									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
73200					5/13/2011		4		\$0.00
Medium	Work In Progress			5/13/2011 9:41:33 AM					
Herrera, Joel	Requested by Matt Grubaugh-Mrs. Conley would like some book shelves moved from the old Library into the book room in the Academic Building. SEE MRS. CONLEY ON WHICH SHELVES SHE'D LIKE MOVED AND WHERE SHE'D LIKE THEM PLACED.								
<u>Velia Alarcon</u>									
73203					5/13/2011		4		\$0.00
Medium	Work In Progress			5/13/2011 9:53:09 AM					
Appelzoller, Fred	Requested by Matt Grubaugh for New Library-The urinal does not flush right. It has very low water pressure. This repair should be under warranty.								
<u>Velia Alarcon</u>									
73204					5/13/2011		4		\$0.00
Medium	Work In Progress			5/13/2011 9:55:30 AM					
Apodaca, Mario	Requested by Debbie Costalez-Move Panther painting from Debbie's office to New Admin. Building. SEE DEBBIE FOR PLACE TO HAVE IT RE-HUNG.								
<u>Velia Alarcon</u>									
73206					5/13/2011		4		\$0.00
Medium	Work In Progress			5/13/2011 9:58:35 AM					
Herrera, Joel	Requested by Debbie Costalez-Move mounted storage shelves from storage room in New Admin. Building to New Vault in New Admin. Building. SEE DEBBIE FOR PLACE TO MOVE SHELVES TO.								
<u>Velia Alarcon</u>									
73211					5/13/2011		4		\$0.00
Medium	Work In Progress			5/13/2011 11:17:56 AM					
Herrera, Joel	Requested by Velia for Marquee in Front of School- WORK ORDER # 70447 WAS NOT BEEN COMPLETED-All three light are out now and the U.S. Flag is not being lite at night.								
<u>Velia Alarcon</u>									
73239	Boys Gym				5/16/2011		1		\$0.00
Medium	Work In Progress			5/16/2011 10:02:09 AM					
Ontiveros, Joe	boys gym is backing up sewer problems.								
Mario Apodaca									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
73248	New Vocational				5/16/2011		1		\$0.00
Medium	Work In Progress	Annex		5/16/2011 12:45:48 PM					
Lara, Ralph	Need key #D124 for electrical panel located on the outside east wall of the annex building (vocational bldg.). Contractor will pick up key at the Construction Office. Contractor Info: Marco Hamilton, ESA Construction (575) 642-1560								
<b>Peggy Jo Hernandez</b>									
73262					5/16/2011		1		\$0.00
Medium	Work In Progress			5/16/2011 3:35:47 PM					
Lara, Ralph	RAFA KITCHENS MAIN DOOR IT DOESNT LOCK WELL								
<b>Joel Herrera</b>									
73278					5/17/2011		0		\$0.00
Medium	Work In Progress			5/17/2011 9:59:08 AM					
Apodaca, Mario	Requested by Ms. V. Gonzales for Computer Lab's Girl's Restroom-Light bulb burned out needs to be replaced.								
<b>Velia Alarcon</b>									
73279					5/17/2011		0		\$0.00
Medium	Work In Progress			5/17/2011 10:00:33 AM					
Castillo, Carlos	Requested by Chief Arms for ROTC Supply Shed-No electricity in supply shed.								
<b>Velia Alarcon</b>									
<b>Count: 136 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>70</b>			<b>Total for Gadsden HS</b>	<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
66088					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:23					
Orozco, Danny	Monthly - Gadsden MS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67265					12/5/2010		163		\$0.00
Medium	Work In Progress			12/5/2010 12:27:27 AM					
Sanchez, Raul	Monthly - Gadsden MS - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67823					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:39 AM					
Villalobos, David	Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68407					1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 12:23:45 AM					
Sanchez, Raul	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68429	Main Building	Library			1/14/2011		11	1	\$25.00
Medium	Work In Progress			1/14/2011 10:46:15 AM		1/25/2011			
Diaz, Sebastian	Install weather-stripping on exterior doors.					install weather stripping Leadership Request			
<u>Alfredo Holguin</u>									
68430	Gym	Gym			1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 10:48:50 AM					
Estrada, Jesus	(PROJECT) Paint mascot on Gym floor					Leadership Request			
<u>Alfredo Holguin</u>									
68432					1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 10:58:30 AM					
Ontiveros, Guadalupe	(PROJECT) Entire Campus around and in between all buildings. - level all ruts and bumps - backfill against sidewalks - clean out all storm drains.					Leadership Request Asp Alfredo, changed to Project on 5/10/11			
<u>Alfredo Holguin</u>									
68435					1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 11:07:31 AM					
Munoz, Michael	Tree Memorial for Benegas - Install plaque - check with site leadership council for wording					Leadership Request			
<u>Alfredo Holguin</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
69423					2/14/2011		92		\$0.00
Medium	Work In Progress			2/14/2011 12:26:04 AM					
Sanchez, Raul	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70250					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:43 AM					
Orozco, Danny	Yearly - Gadsden MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70541	Gym	Gym			3/9/2011		69		\$0.00
Medium	Work In Progress	GYM FLOOR		3/9/2011 2:41:12 PM					
Diaz, Sebastian	BOTTOM OF THE DOOR NEEDS FLAP TO KEEP DIRT OUT (DOOR LEAD TO FOOTBALL FIELD FROM GYM).								
<u>Maricruz Carrasco</u>									
70725					3/14/2011		64		\$0.00
Medium	Work In Progress			3/14/2011 12:15:21 AM					
Sanchez, Raul	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71018		Athletic Field			3/23/2011		55		\$0.00
Medium	Work In Progress			3/23/2011 10:00:17 AM					
Gonzalez, Salvador	new scoreboard is in for the football field. need to install.see mike for location, thank you								
<u>Michael Munoz</u>									
71019		Athletic Field			3/23/2011		55		\$0.00
Medium	Work In Progress			3/23/2011 10:21:29 AM					
Sotelo, Enrique	need to provide power to scoreboard when installed in football field.thank you								
<u>Michael Munoz</u>									
71199	Gym				3/29/2011		49		\$0.00
Medium	Work In Progress			3/29/2011 10:11:47 AM					
Solis, Lorenzo	new ice machine will coming in . could you please install when it does.thank you								
<u>Michael Munoz</u>									
71231					3/30/2011		48		\$0.00
Medium	Work In Progress			3/30/2011 8:07:10 AM					
Appelzoller, Fred	Need to check water leak in front annex bldg thank you								
Sebastian Diaz									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden MS</b>									
71435					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:54 AM					
Orozco, Danny	Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71619					4/4/2011		43		\$0.00
Medium	Work In Progress			4/4/2011 3:35:09 PM					
Appelzoller, Fred	Need to check bad olor in closer B wing thank you								
<u>Sebastian Diaz</u>									
71683					4/5/2011		42		\$0.00
Medium	Work In Progress			4/5/2011 3:47:28 PM					
Gonzalez, Salvador	Need cover plate in A/C in some places thank you								
<u>Sebastian Diaz</u>									
71769		Athletic Field			4/7/2011		40		\$0.00
Medium	Work In Progress			4/7/2011 8:04:19 AM					
Ontiveros, Guadalupe	please adjust sprinklers on the football field, the track is getting watered as well. thank you								
<u>Guadalupe Ontiveros</u>									
71828					4/8/2011		39		\$0.00
Medium	Work In Progress			4/8/2011 11:32:51 AM					
Diaz, Sebastian	Need 10 plastic cover in annex lights thank you								
<u>Sebastian Diaz</u>									
71953	Main Building	Hallway/Corridor			4/11/2011		36		\$0.00
Medium	Work In Progress			4/11/2011 11:19:12 AM					
Lozoya, Manny	B.WING WEST OUTSIDE EXIT DOORS RIM CYLINDER NEED CLEANING								
<u>Juan Acosta</u>									
71955	Gymnasium	Hallway/Corridor			4/11/2011		36		\$0.00
Medium	Work In Progress			4/11/2011 11:23:54 AM					
Lozoya, Manny	GYM LOBBY OUTSIDE EXIT DOORS RIM CYLINDER NEED CLEANING								
<u>Juan Acosta</u>									
72073					4/14/2011		33		\$0.00
Medium	Work In Progress			4/14/2011 12:14:20 AM					
Sanchez, Raul	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Gadsden MS</b>							
72200	Annex	Restroom (Girls)			4/18/2011		29		\$0.00
Medium	Work In Progress	Annex/Girls			4/18/2011 4:21:37 PM				
Appelzoller, Fred		Commode is leaking a lot of water at the flushing valve every time it is flushed. Needs to be repaired ASAP. Thank you!							
<hr/>									
72217	C-Wing				4/19/2011		28		\$0.00
Medium	Work In Progress	CHARTER			4/19/2011 8:42:55 AM				
Lozoya, Manny		CHARTER SCHOOL 1. Change the 2 back exit door locks to match the new entry door lock. 2. A replacement lock for the exterior gate with a key that matches the classroom keys.							
<hr/>									
72446					4/27/2011		20		\$0.00
Medium	Work In Progress				4/27/2011 8:02:58 AM				
Ontiveros, Guadalupe		please install 2 bradford pare trees where mulberry trees where removed in the front. thank you							
<hr/>									
72646					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress				5/1/2011 12:21:59 AM				
Orozco, Danny		Monthly - Gadsden MS Fire Suppression Insp. - Refer to PM schedule details.							
<hr/>									
72730					5/1/2011		16		\$0.00
Medium	Work In Progress				5/1/2011 12:22:41 AM				
Sanchez, Raul		Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details.							
<hr/>									
72825	Main Building	Restroom (Girls)			5/3/2011		14		\$0.00
Medium	Work In Progress				5/3/2011 12:36:36 PM				
Diaz, Sebastian		GIRLS RESTROOM NEED TO REPLACE TOILET SEAT AND REPLACE 4 LIGHTS							
<hr/>									
73214					5/13/2011		4		\$0.00
Medium	Work In Progress	Office/Storage/M			5/13/2011 1:25:36 PM				
Lozoya, Manny		Change key lock to storage room to A53. Please see Mrs. Quinonez for instructions.							
<hr/>									
Maricruz Carrasco									
<b>Count: 31 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>63</b>	<b>Total for Gadsden MS</b>			<b>1</b>	<b>\$25.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>La Union ES</b>							
60989					7/14/2010		307		\$0.00
Medium	Work In Progress				7/14/2010 1:44:37 PM				
Ontiveros, Guadalupe	canal levee brock - now walking path is under 4" of dirt - need to have tracker dig it out - thank you								
Patricio Aguilar									
62217					8/10/2010		280		\$0.00
Medium	Work In Progress				8/10/2010 8:54:51 AM				
Sanchez, Raul	the air pump to the well tank is not working - dead								
Patricio Aguilar									
64314					9/23/2010		236		\$0.00
Medium	Work In Progress				9/23/2010 3:13:04 PM				
Flores, Pete	the differential is making a bad noise - need repair or replace allso need wipers - oil change								
Patricio Aguilar									
65723					10/21/2010		208		\$0.00
Medium	Work In Progress				10/21/2010 1:31:55 PM				
Castillo, Carlos	need 2 wall mounted multiple elect outlets bar r100								
Patricio Aguilar									
66089					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress				10/31/2010 12:36:24				
Orozco, Danny	Monthly - La Union ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
66525	Main Building	Classroom			11/10/2010		188		\$0.00
Medium	Work In Progress				11/10/2010 6:48:52 AM				
Villalobos, David	Talked to Mr. Rapanut about a sink in the parenty room 104, they would like to have one there. the hook ups are there, all it needs is the sink and faucet.								
Santos Galindo									
66626					11/15/2010		183		\$0.00
Medium	Work In Progress				11/15/2010 3:12:17 PM				
Villalobos, David	need a p-trap replaced water founten old hall way								
Patricio Aguilar									
67826					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress				1/2/2011 12:28:40 AM				
Villalobos, David	Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>La Union ES</b>							
69977					2/28/2011		78		\$0.00
Medium	Work In Progress			2/28/2011 12:25:17 AM					
Aguilar, Patricio	Monthly - La Union ES A-16 Fan Exhaust Semimonthly - Refer to PM schedule details.								
Margret Villalobos									
70241					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:39 AM					
Orozco, Danny	Yearly - La Union ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
70603					3/10/2011		1	10	\$400.00
Medium	Work In Progress			3/10/2011 12:57:27 PM		3/11/2011			
Villalobos, David	winter storm repair 3 copper lines out to building faucets need repair - copper line to play ground water founter need repair		Work Still Pending will need to reconnect piping to outside hosebibbs, find exact cutoff locations and leaks.						
Patricio Aguilar									
71436					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:54 AM					
Orozco, Danny	Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71735		Athletic Field			4/6/2011		41		\$0.00
High	Work In Progress			4/6/2011 2:34:38 PM					
Villalobos, David	please provide water to the fields in the back with irrigation system. please see mike ion this work order. thank you								
Alfredo Holguin									
72503					4/28/2011		19		\$0.00
Medium	Work In Progress			4/28/2011 9:30:56 AM					
Aguilar, Patricio	wo to myself 4/28/11 take display to STHS 5/2/11 pick up display from STHS								
Patricio Aguilar									
72602					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:56 AM					
Aguilar, Patricio	Yearly - La Union ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>La Union ES</b>							
72647					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:00 AM					
Orozco, Danny	Monthly - La Union ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72715					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:34 AM					
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72716					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:34 AM					
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72717					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:35 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72718					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:35 AM					
Aguilar, Patricio	Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72918					5/5/2011		12		\$0.00
Medium	Work In Progress			5/5/2011 9:53:17 AM					
Flores, Pete	need truck serviced - leaking oil bad -oil chang - fliters - windshield wipers -differential making bad noise - thank you								
<u>Patricio Aguilar</u>									
73004					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:17 AM					
Aguilar, Patricio	Monthly - La Union ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
73257					5/16/2011		1		\$0.00
Medium	Work In Progress			5/16/2011 3:22:28 PM					
Lara, Ralph	can not unluck door to paper stoeage room - thank you								
<u>Patricio Aguilar</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									
<b>Location:</b>		<b>La Union ES</b>							
73258					5/16/2011		1		\$0.00
Medium	Work In Progress				5/16/2011 3:24:14 PM				
Ambriz, Jose	a/c to comp server is no cooling - making noise - thank you								
Patricio Aguilar									
<b>Count: 24 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>88</b>	<b>Total for La Union ES</b>		<b>10</b>	<b>\$400.00</b>	

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Loma Linda ES</b>									
60602					7/4/2010	7/25/2010	317		\$0.00
Medium	Work In Progress			7/4/2010 12:23:44 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60892					7/12/2010		309		\$0.00
Medium	Work In Progress			7/12/2010 6:13:58 AM					
Flores, Pete	Need tractor to clean pathways and washed out rain paths.								
<u>Rudy Arreola</u>									
62846		Athletic Field			8/24/2010		266		\$0.00
High	Work In Progress			8/24/2010 10:53:22 AM					
Munoz, Michael	please install a fence on the north end of campus where desert begins. this is a safty issue as per mr.lawler.								
<u>Alfredo Holguin</u>									
63055	Main Building	Athletic Field			8/27/2010		263		\$0.00
Medium	Work In Progress			8/27/2010 1:02:33 PM					
Ontiveros, Guadalupe	Possible to reseed area that was torn up by by the installation of new sidewalks.								
<u>Rudy Arreola</u>									
63296	Main Building	Classroom			9/1/2010		258		\$0.00
Medium	Work In Progress	101		9/1/2010 1:00:28 PM					
Arreola, Rudy	Blinds behind teachers desk not working. The cords are frayed and the blinds wont go up or down.								
<u>Gidget Mora</u>									
64208	Main Building				9/21/2010		238		\$0.00
Medium	Work In Progress			9/21/2010 3:05:39 PM					
Sanchez, Raul	Grease trap is caving in and has broken parts where filters go.								
<u>Rudy Arreola</u>									
64743					10/3/2010	10/24/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:27:00 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
65095	Main Building	Classroom			10/7/2010		222		\$0.00
Medium	Work In Progress			10/7/2010 2:41:32 PM					
Solis, Lorenzo	A/C needs to be replaced rusted out really bad.RM 101								
<u>Rudy Arreola</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Loma Linda ES</b>									
65096	Main Building	Classroom			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 2:42:17 PM				
Solis, Lorenzo	A/C needs to be replaced rusted out. RM 103								
Rudy Arreola									
65097	Main Building	Classroom			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 2:43:18 PM				
Solis, Lorenzo	A/C is rusted out needs to be replaced. RM 108								
Rudy Arreola									
65098	Main Building	Classroom			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 2:44:03 PM				
Solis, Lorenzo	A/C is rusted out needs to be replaced. RM 110								
Rudy Arreola									
65099	Main Building	Classroom			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 2:45:02 PM				
Solis, Lorenzo	A/C is rusted out needs to be replaced. RM 111								
Rudy Arreola									
65100	Main Building	Classroom			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 2:45:45 PM				
Solis, Lorenzo	A/C is rusted out needs to be replaced. RM 112								
Rudy Arreola									
65101	Main Building	Classroom			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 2:46:40 PM				
Solis, Lorenzo	A/C is rusted out needs to be replaced. RM 118								
Rudy Arreola									
65102	Main Building	Classroom			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 2:47:39 PM				
Solis, Lorenzo	A/C is rusted out needs to be replaced. RM 201								
Rudy Arreola									
65103	Main Building	Classroom			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 2:48:34 PM				
Solis, Lorenzo	A/C is rusted out needs to be replaced. Rm 206								
Rudy Arreola									
65104	Main Building	Classroom			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 2:49:16 PM				
Solis, Lorenzo	A/C is rusted out needs to be replaced. RM 212								
Rudy Arreola									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
65105	Main Building	Office			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 2:56:25 PM				
Solis, Lorenzo		A/C is rusted out needs to be replaced. Teachers lounge 308							
Rudy Arreola									
65106	Main Building	Office			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 3:01:05 PM				
Solis, Lorenzo		A/C is rusted out needs to be replaced RM 312							
Rudy Arreola									
65107	Main Building	Classroom			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 3:02:13 PM				
Solis, Lorenzo		A/C is rusted out needs to be replaced NURSES OFFICE. 313							
Rudy Arreola									
65108	Main Building	Office			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 3:03:40 PM				
Solis, Lorenzo		A/C is rusted out needs to be replaced front office.							
Rudy Arreola									
65110	Main Building	Office			10/7/2010		222		\$0.00
Medium	Work In Progress				10/7/2010 3:07:08 PM				
Solis, Lorenzo		A/C is rusted out needs to be replaced principals offices							
Rudy Arreola									
65346	Main Building	Classroom			10/13/2010		216		\$0.00
Medium	Work In Progress	109			10/13/2010 8:59:54 AM				
Arreola, Rudy		Window blinds not working in room 109							
Gidget Mora									
66090					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress				10/31/2010 12:36:24				
Orozco, Danny		Monthly - Loma Linda ES Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
67824					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress				1/2/2011 12:28:39 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
67840					1/2/2011	1/23/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:45 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68072	Main Building	Classroom			1/7/2011		130		\$0.00
Medium	Work In Progress	212		1/7/2011 10:37:56 AM					
Arreola, Rudy	BLINDS IN CLASSROOM NEED TO BE FIXED								
<u>Gidget Mora</u>									
68463	Main Building	Restroom (Girls)			1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 3:16:53 PM					
Appelzoller, Fred	TOILET IS LEAKING WATER FROM ANGLE STOP AND FLUSHVALVE. WOMENS RESTROOM RIGHT ACROSS TEACHERS LOUNGE. CLOSED WATER SUPPLY								
<u>Rudy Arreola</u>									
68700	Main Building	Classroom			1/24/2011		113		\$0.00
Medium	Work In Progress			1/24/2011 3:17:29 PM					
Appelzoller, Fred	NEED TO REPLACED WATER HEATER IN ROOM 208 SLOW LEAK.								
<u>Rudy Arreola</u>									
69314	Main Building	Mechanical			2/10/2011		96		\$0.00
Medium	Work In Progress			2/10/2011 8:29:55 AM					
Appelzoller, Fred	MAIN WATER SUPPLY IS LEAKING FROM ELBOW.								
<u>Rudy Arreola</u>									
69316	Main Building	Mechanical			2/10/2011		96		\$0.00
Medium	Work In Progress			2/10/2011 8:31:19 AM					
Appelzoller, Fred	WATER LEAK BACKFLOW IS CRACKED.								
<u>Rudy Arreola</u>									
69318	Main Building	Mechanical			2/10/2011		96		\$0.00
Medium	Work In Progress			2/10/2011 8:34:18 AM					
Appelzoller, Fred	WATER HEATER IN MECHANICAL ROOM IS LEAKING.								
<u>Rudy Arreola</u>									
69319	Main Building	Cafeteria			2/10/2011		96		\$0.00
Medium	Work In Progress			2/10/2011 8:35:29 AM					
Solis, Lorenzo	HEATING COIL IS LEAKING WATER,								
Rudy Arreola									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
69322	Main Building	Portables			2/10/2011		96		\$0.00
Medium	Work In Progress			2/10/2011 8:39:00 AM					
Appelzoller, Fred	WATER LEAK IN WALL IN DOUBLE PORTABLE BATHROOM								
Rudy Arreola									
69341	Main Building	Mechanical			2/10/2011		96		\$0.00
Medium	Work In Progress			2/10/2011 3:01:58 PM					
Sanchez, Raul	WATER FILTERING SYSTEM ALSO HAS A WATER LEAK.								
Rudy Arreola									
69582	Main Building	Cafeteria			2/16/2011		90		\$0.00
Medium	Work In Progress			2/16/2011 9:36:51 AM					
Estrada, Jesus	TILES ARE LIFTING AND NEED TO BE REPLACED IN KITCHEN & LAUNDRY AREA. SAFETY ISSUE SNP MANAGER FRANCES B.882-4707. AS OF 3/30/11 - REVISED / NEED TO ADD RESTROOM AND MANGAGERS OFFICE BUT DO NOT INCLUDE DISHWASHING AREA .					P.O. RECIEVED. SUBMITTED REVISED REQUEST AS OF 3/30/11			
Jesus Estrada									
69617					2/16/2011		90		\$0.00
Medium	Work In Progress			2/16/2011 4:03:24 PM					
Appelzoller, Fred	please replace backflow we have in stock in the mechanical room for irrigation.thank you								
Joe Munoz									
69636	Main Building	Restroom (Boys)			2/17/2011		89		\$0.00
Medium	Work In Progress			2/17/2011 9:06:15 AM					
Solis, Lorenzo	NEED TO REPLACE ENTIRE EXHAUST FAN COVER HAS HOLES SIZE IS 22X22 DUCT COVER.								
Rudy Arreola									
69881	Main Building	Classroom			2/24/2011		82		\$0.00
Medium	Work In Progress	201		2/24/2011 10:37:47 AM					
Arreola, Rudy	Repair or replace blinds								
Gidget Mora									
70242					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:39 AM					
Orozco, Danny	Yearly - Loma Linda ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Loma Linda ES</b>									
70626	Main Building	Classroom			3/10/2011		68		\$0.00
Medium	Work In Progress				3/10/2011 3:25:51 PM				
Arreola, Rudy	Need to paint old conference room								
Rudy Arreola									
71426					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress				4/3/2011 12:19:49 AM				
Orozco, Danny	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
71437					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress				4/3/2011 12:19:55 AM				
Orozco, Danny	Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71839	Main Building	Athletic Field			4/8/2011		39		\$0.00
Medium	Work In Progress				4/8/2011 2:28:50 PM				
Ontiveros, Guadalupe	SOLENOID VALVE NEEDS TO BE REPLACED STILL GETTING STUCK.								
Rudy Arreola									
71861	Main Building	Mechanical			4/8/2011		39		\$0.00
Medium	Work In Progress				4/8/2011 3:39:45 PM				
Villalobos, David	replaced backflow preventer (3/4") to boiler broken during freeze								
David Villalobos									
72013		Cafeteria			4/12/2011		35		\$0.00
Medium	Work In Progress				4/12/2011 2:56:35 PM				
Arreola, Rudy	as per our converstaion, please paint the cafeteria kitchen,office, restroom and laundryroom. Thank you								
Michael Munoz									
72032	Main Building	Auditorium			4/13/2011		34		\$0.00
Medium	Work In Progress				4/13/2011 8:10:38 AM				
Estrada, Jesus	WARRANTY. CARPET NEEDS TO BE REPAIRED COMING UNDONE ALONG FRONT OF STAGE BEFORE IT GETS WORST AND RIPS MORE. CARPET WAS JUST INSTALLED ABOUT JAN.WARRANTY.								
Rudy Arreola									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
72135		Hallway/Corridor			4/15/2011		32		\$0.00
Medium	Work In Progress			4/15/2011 12:24:57 PM					
Estrada, Jesus	TILE IN HALLS UNDER THE DOUBLE WATER FOUNTAINS NEEDS TO BE REPLACED. 3 SECTIONS.								
<u>Rudy Arreola</u>									
72136	Main Building	Office			4/15/2011		32		\$0.00
Medium	Work In Progress			4/15/2011 12:26:23 PM					
Estrada, Jesus	CARPET IN THE MAIN ENTRANCE TO OFFICE NEEDS TO BE REPAIRED OR GLUED.								
<u>Rudy Arreola</u>									
72137		Classroom			4/15/2011		32		\$0.00
Medium	Work In Progress			4/15/2011 12:29:00 PM					
Estrada, Jesus	CARPET IN ROOM 220 THE SEAM THAT SEPARTES CARPET AND TILE IS DAMAGED.		request for p.o. has been submitted						
<u>Rudy Arreola</u>									
72141	Main Building	Athletic Field			4/15/2011		32		\$0.00
Medium	Work In Progress			4/15/2011 2:19:57 PM					
Munoz, Michael	NEED FENCE INSTALLED ON THE NORTHSIDE OF CAMPUS THAT SEPARTES CAMPUS FROM DESSERT AREA IT EXTENDS FROM EAST TO WEST.								
<u>Rudy Arreola</u>									
72605					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:58 AM					
Arreola, Rudy	Yearly - Loma Linda ES C11(Evap.Condnsr)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72648					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:00 AM					
Orozco, Danny	Monthly - Loma Linda ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72725					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:39 AM					
Arreola, Rudy	Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Loma Linda ES</b>									
72726					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:39 AM					
Arreola, Rudy	Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
72727					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:40 AM					
Arreola, Rudy	Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
72728					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:40 AM					
Arreola, Rudy	Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
72861	Main Building	Athletic Field			5/4/2011		13		\$0.00
Medium	Work In Progress			5/4/2011 8:13:27 AM					
Arreola, Rudy	NEED SOME HELP REMOVING 6 DEAD TREES THEY RANGE FROM 14 FT TO 30 FT HEIGHT.		5/5 - Asp Mike, route back to R. Arreola						
Rudy Arreola									
72962	Main Building				5/6/2011		11		\$0.00
Medium	Work In Progress			5/6/2011 2:41:20 PM					
Arreola, Rudy	AS PER MIKE. MUNOZ ASSIT AT GHS WITH CLEAN UP OF GROUNDS.								
Rudy Arreola									
73005					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:18 AM					
Arreola, Rudy	Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
73107					5/11/2011		6		\$0.00
Medium	Work In Progress			5/11/2011 9:41:54 AM					
Orozco, Danny	1)LAMPS/BANISTER IS OUT. 2) SLICER IS BROKEN 3) LIGHTS IN HOOD/EXHAUST OUT. SNP MANGER FRANCES B.882.4707								
Maritza Gonzalez									
73140		Cafeteria			5/12/2011		5		\$0.00
Medium	Work In Progress			5/12/2011 7:18:20 AM					
Arreola, Rudy	please paint door that was installed in the cafeteria. thank you								
Michael Munoz									

5/17/2011 12:10:27 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Loma Linda ES</b>									
73193	Main Building	Classroom			5/13/2011		4		\$0.00
Medium	Work In Progress	204		5/13/2011 9:16:56 AM					
Arreola, Rudy Having trouble with low cool on air conditioner									
Gidget Mora									
73194	Main Building	Classroom			5/13/2011		4		\$0.00
Medium	Work In Progress	102		5/13/2011 9:24:52 AM					
Arreola, Rudy Air conditioner does not work.									
Gidget Mora									
73195	Main Building	Classroom			5/13/2011		4		\$0.00
Medium	Work In Progress	109		5/13/2011 9:29:42 AM					
Arreola, Rudy Paper towel roller dispenser fell off the wall.									
Gidget Mora									
73196	Main Building	Classroom			5/13/2011		4		\$0.00
Medium	Work In Progress	201		5/13/2011 9:36:28 AM					
Arreola, Rudy Air conditioner not working									
Gidget Mora									
73197	Main Building	Classroom			5/13/2011		4		\$0.00
Medium	Work In Progress	201		5/13/2011 9:37:37 AM					
Arreola, Rudy Light falling off right next to entrance									
Gidget Mora									
73199	Main Building	Classroom			5/13/2011		4		\$0.00
Medium	Work In Progress	112		5/13/2011 9:41:27 AM					
Arreola, Rudy Table in center #3 is wobbly. New screw on leg to be tightened.									
Gidget Mora									
73201	Main Building	Hallway/Corridor			5/13/2011		4		\$0.00
Medium	Work In Progress			5/13/2011 9:46:10 AM					
Arreola, Rudy Please install two Bullitin boards for Mr Ibarra									
Gidget Mora									
73202	Main Building	Restroom (Girls)			5/13/2011		4		\$0.00
Medium	Work In Progress	112		5/13/2011 9:48:25 AM					
Arreola, Rudy Toilet in room 112 is not flushing. The handle is broken.									
Gidget Mora									
73205	Main Building	Classroom			5/13/2011		4		\$0.00
Medium	Work In Progress	201		5/13/2011 9:57:11 AM					
Arreola, Rudy Air conditioner switch broke. It is not working.									
Gidget Mora									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Loma Linda ES</b>									
73207	Main Building	Classroom			5/13/2011		4		\$0.00
Medium	Work In Progress	220			5/13/2011 9:58:40 AM				
Arreola, Rudy		Having A/C problems. Not working properly							
Gidget Mora									
73208	Main Building	Restroom (Girls)			5/13/2011		4		\$0.00
Medium	Work In Progress	3rd Grade Hall			5/13/2011 10:04:20 AM				
Arreola, Rudy		Exhaust fan does not work							
Gidget Mora									
73209	Main Building	Classroom			5/13/2011		4		\$0.00
Medium	Work In Progress	204			5/13/2011 10:11:29 AM				
Arreola, Rudy		Air conditioner does not work on low cool							
Gidget Mora									
73210					5/13/2011		4		\$0.00
Medium	Work In Progress				5/13/2011 10:30:06 AM				
Arreola, Rudy		NEED 5 SIGNS THAT SAY NO PARKING 18X24 RED AND WHITE.							
Rudy Arreola									
<b>Count: 75 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>105</b>	<b>Total for Loma Linda ES</b>			<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Mesquite ES</b>									
61265					7/23/2010		298		\$0.00
Medium	Work In Progress			7/23/2010 8:42:38 AM					
Lozoya, Manny	principal is requesting that locks be installed on southside staff bathrooms.		Reprinted 4/21/11						
<b>Joe Ramirez</b>									
65094		Athletic Field			10/7/2010		222		\$0.00
Medium	Work In Progress			10/7/2010 1:42:39 PM					
Ramirez, Joe	please clean up along fence line on the back parking lot to include the pile of dirt by handi cap parking as well. also cut weeds and grass along sidewalk around enviromental park.thank you								
<b>Michael Munoz</b>									
65221					10/11/2010		218		\$0.00
Medium	Work In Progress			10/11/2010 11:32:16					
Ramirez, Joe	please trim grass and cut weeds along sidewalk on the exterior of enviromental park.thanks								
<b>Michael Munoz</b>									
65455	Main Building				10/15/2010		214		\$0.00
Medium	Work In Progress	Staff Bathroom		10/15/2010 8:27:22 AM					
Lozoya, Manny	Mr. Van Nosdale/Principal needs dead bolt lock place on Men/Women Bathroom located in main hallway next to lounge, for staff privacy when using bathrooms.		Reprinted 4/21/11						
<b>Sandra Mora</b>									
66091					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:24					
Orozco, Danny	Monthly - Mesquite ES Fire Suppression Insp. - Refer to PM schedule details.								
<b>Margret Villalobos</b>									
66943					11/30/2010		168		\$0.00
Medium	Work In Progress			11/30/2010 12:25:58					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<b>Margret Villalobos</b>									
67269					12/5/2010		163		\$0.00
Medium	Work In Progress			12/5/2010 12:27:29 AM					
Sanchez, Raul	Monthly - Mesquite ES - Monthly Meter Readings - Refer to PM schedule details.								
<b>Margret Villalobos</b>									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
67433					12/9/2010		159		\$0.00
Medium	Work In Progress			12/9/2010 9:55:49 AM					
Ramirez, Joe	as per mr. moreno,asst principal eastside entrance gate needs to be repaired or replaced.		Asp Sal, completed by Joe						
<u>Joe Ramirez</u>									
67827					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:40 AM					
Villalobos, David	Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67903					1/2/2011	1/10/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:29:18 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67956					1/4/2011		133		\$0.00
Medium	Work In Progress			1/4/2011 12:24:41 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68000					1/6/2011		131		\$0.00
Medium	Work In Progress			1/6/2011 9:21:44 AM					
Orozco, Danny	TOP OVEN ON RIGHT SIDE OF CAFETERIA NOT HEATING. SNP MANAGER ALICE F.233.2341								
<u>Maritza Gonzalez</u>									
68956					2/1/2011		105		\$0.00
Medium	Work In Progress			2/1/2011 12:27:38 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70023					3/1/2011		77		\$0.00
Medium	Work In Progress			3/1/2011 12:18:21 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70243					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:40 AM					
Orozco, Danny	Yearly - Mesquite ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Mesquite ES</b>									
70391	Restrooms				3/7/2011		71		\$0.00
Medium	Work In Progress				3/7/2011 7:51:02 AM				
Ontiveros, Joe	please replace wash basin in restrooms in the corridore between office area and caferteis								
<u>Michael Munoz</u>									
70728					3/14/2011		64		\$0.00
Medium	Work In Progress				3/14/2011 7:43:50 AM				
Villalobos, David	back flow preventor by the pump house has a busted union needs to be replaced								
<u>Joe Ramirez</u>									
71438					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress				4/3/2011 12:19:55 AM				
Orozco, Danny	Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71518					4/3/2011	4/19/2011	44		\$0.00
Medium	Work In Progress				4/3/2011 12:20:30 AM				
Ramirez, Joe	Monthly - Mesquite ES A-1 Wall Ref Elec Heat Semi - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71523					4/3/2011	4/11/2011	44		\$0.00
Medium	Work In Progress				4/3/2011 12:20:32 AM				
Ramirez, Joe	Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71632					4/5/2011		42		\$0.00
Medium	Work In Progress				4/5/2011 12:15:00 AM				
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71925					4/11/2011		36		\$0.00
Medium	Work In Progress				4/11/2011 8:28:51 AM				
Gonzalez, Salvador	need to install security bars on windows in rm.506								
<u>Joe Ramirez</u>									
71928					4/11/2011		36		\$0.00
Medium	Work In Progress				4/11/2011 8:29:44 AM				
Gonzalez, Salvador	need to install security bars on windows in rm.602.								
Joe Ramirez									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
71929					4/11/2011		36		\$0.00
Medium	Work In Progress			4/11/2011 8:31:01 AM					
Gonzalez, Salvador	nned to install security bars on windows in rm.606. front and back								
Joe Ramirez									
71930					4/11/2011		36		\$0.00
Medium	Work In Progress			4/11/2011 8:33:18 AM					
Gonzalez, Salvador	need to install security bars on windows in rm.606 front and back.								
Joe Ramirez									
71931					4/11/2011		36		\$0.00
Medium	Work In Progress			4/11/2011 8:34:31 AM					
Gonzalez, Salvador	need to install security bars on windows in rm.607 front and back.								
Joe Ramirez									
72117					4/14/2011		33		\$0.00
Medium	Work In Progress			4/14/2011 3:49:50 PM					
Gonzalez, Salvador	need a ladder from the main roof to the library roof								
Joe Ramirez									
72138					4/15/2011		32		\$0.00
Medium	Work In Progress			4/15/2011 12:52:50 PM					
Estrada, Jesus	rm. 300 whole floor needs to be retiled.								
	5/5/11 - ASP CHUY, NEEDS TO BE REPLACED WITH CARPET INSTEAD OF VCT								
Joe Ramirez									
72178					4/18/2011		29		\$0.00
Medium	Work In Progress			4/18/2011 1:55:52 PM					
Ronquillo, Ruben	skylight in cafe. dining area needs to be replaced								
Joe Ramirez									
72305					4/20/2011		27		\$0.00
Medium	Work In Progress			4/20/2011 1:36:36 PM					
Estrada, Jesus	Room 229 floor needs to be retiled along with small hallway.								
	5/5/11 - ASP CHUY - REPLACE WITH CARPET								
Joe Ramirez									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
72330					4/21/2011		26		\$0.00
Medium	Work In Progress			4/21/2011 7:48:47 AM					
Solis, Luis	need to repair roof top boiler leak from the winter freeze.								
Joe Ramirez									
72465					4/27/2011		20		\$0.00
Medium	Work In Progress			4/27/2011 10:47:42 AM					
Munoz, Michael	fence line on eastside of campus needs to be repaired or replaced.				4/29 - Faxed to Academy				
Joe Ramirez									
72467					4/27/2011		20		\$0.00
Medium	Work In Progress			4/27/2011 10:52:40 AM					
Ramirez, Joe	need to place no trespassing signs along fence line.								
Joe Ramirez									
72601					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:56 AM					
Ramirez, Joe	Yearly - Mesquite ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									
72649					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:01 AM					
Orozco, Danny	Monthly - Mesquite ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
72705					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:29 AM					
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
72706					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:29 AM					
Ramirez, Joe	Monthly - Mesquite ES - Barrack Drainage (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
72707					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:30 AM					
Ramirez, Joe	Monthly - Mesquite ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Mesquite ES</b>									
72708					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:30 AM					
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72709					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:31 AM					
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72796					5/3/2011		14		\$0.00
Medium	Work In Progress			5/3/2011 12:15:04 AM					
Sanchez, Raul	Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72868		Custodial			5/4/2011		13		\$0.00
Medium	Work In Progress			5/4/2011 9:19:47 AM					
Carbajal, Jimmy	please flat tire ( dolly) thank you								
<u>Luis Saucedo</u>									
72932					5/5/2011		12		\$0.00
Medium	Work In Progress			5/5/2011 2:50:46 PM					
Sotelo, Enrique	Kitchen light needs to be replaced asp PM 71521								
<u>Joe Ramirez</u>									
73083					5/10/2011		7		\$0.00
Medium	Work In Progress			5/10/2011 3:27:19 PM					
Ronquillo, Ruben	need to replace broken entrance window 23 1/2 x23 1/2. wire glass								
<u>Joe Ramirez</u>									
73084					5/10/2011		7		\$0.00
Medium	Work In Progress			5/10/2011 3:28:48 PM					
Ontiveros, Guadalupe	need the back hoe to remove 2 dead trees from the front of campus								
<u>Joe Ramirez</u>									
73212		Custodial			5/13/2011		4		\$0.00
Medium	Work In Progress			5/13/2011 11:37:52 AM					
Lozoya, Manny	please, i have trouble to open a classroom w/my key to old thank you. luis								
<u>Luis Saucedo</u>									
<b>Count: 46 Work Orders</b>			<b>Avg. Age of WO's 71</b>			<b>Total for Mesquite ES</b>	<b>0</b>		<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>North Valley ES</b>							
66093					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:25					
Orozco, Danny	Monthly - North Valley ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67075					12/2/2010		166		\$0.00
Medium	Work In Progress			12/2/2010 10:39:18 AM					
Ronquillo, Ruben	NEED A HAMMER DRILL /so i can make holes in pavement for some sign post/ attention ruben ronquillo								
<u>Danny Vega</u>									
67080					12/2/2010		166		\$0.00
Medium	Work In Progress			12/2/2010 10:56:08 AM					
Sotelo, Enrique	need replacement lamp cover for dome type exterior lamps/12 in. diamiter(round cover)								
<u>Danny Vega</u>									
67813					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:35 AM					
Villalobos, David	Yearly - North Valley ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69267					2/9/2011		97		\$0.00
Medium	Work In Progress			2/9/2011 12:34:29 PM					
Orozco, Danny	Washing machine main water line broke. SNP Manager Laura B.								
<u>Maritza Gonzalez</u>									
69857					2/24/2011		82		\$0.00
Medium	Work In Progress			2/24/2011 8:08:53 AM					
Ontiveros, Joe	pecan valley wing bys restrooms /sink faucet needs replaced /plus angle stops and supply lines /no more adjustments on this - water will not stop								
<u>Danny Vega</u>									
70147					3/3/2011		75		\$0.00
Medium	Work In Progress			3/3/2011 11:58:52 AM					
Ontiveros, Joe	exterior water fountains/need to replace screen cartrige as it cracked during winter freeze/3/8 copper line to 1/4 poly.please repair these are the only two outside fountains we have(storm day)								
<u>Danny Vega</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>North Valley ES</b>							
70244					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:40 AM					
Orozco, Danny	Yearly - North Valley ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70632					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:29:48 PM					
Villalobos, David	(back -flow preventer) by -pass wilkins zurn type 180f 175psi 3/4 in. model 975xl needs replaced								
<u>Danny Vega</u>									
70993					3/22/2011		56		\$0.00
Medium	Work In Progress			3/22/2011 7:51:34 AM					
Carrasco, Danny	need 16-8-8 fertilizer 30 sacks for entire campus lawn								
<u>Danny Vega</u>									
71186					3/29/2011		49		\$0.00
Medium	Work In Progress			3/29/2011 7:43:08 AM					
Sotelo, Enrique	need the door buzzerd hooked up in the kithchen door/buzzerd is on door								
<u>Danny Vega</u>									
71421					4/3/2011		44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:47 AM					
Orozco, Danny	Monthly - North Valley ES - Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71732					4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 1:25:09 PM					
Vega, Danny	NEED SPRINKLERS REPLACED.								
<u>Adam Montoya</u>									
71777					4/7/2011		40		\$0.00
Medium	Work In Progress			4/7/2011 10:40:21 AM					
Ontiveros, Joe	2 faucets in organ trail wont stop running and 1 in pecan valley wont turn on...								
<u>Javier Parra</u>									
71787					4/7/2011		40		\$0.00
Medium	Work In Progress			4/7/2011 1:01:07 PM					
Munoz, Michael	NEED TWO (2) 3FT X 6 FT GATES DOORS FOR CAMPUS EVACUATION ROUTES ONE AT SOUTH WEST CORNER OF PONDING AREA/THEY OTHER IS BY MARQUEE SIGN								
<u>Danny Vega</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>North Valley ES</b>							
71825					4/8/2011		39		\$0.00
Medium	Work In Progress			4/8/2011 10:47:52 AM					
Vega, Danny	need barricades for traffic control in parent drop -off and front entrance								
Danny Vega									
72021					4/12/2011		35		\$0.00
Medium	Work In Progress			4/12/2011 3:34:14 PM					
Villalobos, David	need to check water pressure at backflow test ports with gauges								
Danny Vega									
72276					4/20/2011		27		\$0.00
Medium	Work In Progress			4/20/2011 7:51:10 AM					
Ontiveros, Guadalupe	NEED KABOTA TRACTOR TO REMOVE SAND BLOWN OVER BY WINDS ONTO GRASS/MOST OF SAND IS FROM PLYGRD SAND BOXES AND IS ON GRASS								
Danny Vega									
72316		Athletic Field			4/20/2011		27		\$0.00
Medium	Work In Progress			4/20/2011 3:41:55 PM					
Munoz, Michael	please order soccer goals for site.								
Alfredo Holguin									
72370					4/26/2011		21		\$0.00
Medium	Work In Progress			4/26/2011 7:50:11 AM					
Villalobos, David	backflow preventer at nve/county is giving us 70 psi /gauges on test ports (outlet)shows 35-45 psi/inlet test port shows 65 psi(we are losing psi on our side as per county)please ck backflow asap								
Danny Vega									
72651					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:02 AM					
Orozco, Danny	Monthly - North Valley ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
72658					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:06 AM					
Vega, Danny	Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>North Valley ES</b>							
72661					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:07 AM					
Vega, Danny	Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72662					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:08 AM					
Vega, Danny	Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72865					5/4/2011		13		\$0.00
Medium	Work In Progress			5/4/2011 8:32:15 AM					
Carrasco, Danny	need 2 gal gas for blowers weed eaters nv 616/as per custodians . j parra								
<u>Danny Vega</u>									
72952					5/6/2011		11		\$0.00
Medium	Work In Progress			5/6/2011 7:32:44 AM					
Ontiveros, Joe	organ trail bys rr/need faucet replaced/water is turned off this sink								
<u>Danny Vega</u>									
72953					5/6/2011		11		\$0.00
Medium	Work In Progress			5/6/2011 7:35:29 AM					
Ontiveros, Joe	rio grand wng/girls rr sink faucets are down /have two (2)sinks turned off								
<u>Danny Vega</u>									
72954					5/6/2011		11		\$0.00
Medium	Work In Progress			5/6/2011 7:38:01 AM					
Ontiveros, Joe	pecan wng/sink faucet in girls are tuned -off have two (2) sinks down								
<u>Danny Vega</u>									
72956					5/6/2011		11		\$0.00
Medium	Work In Progress			5/6/2011 8:24:49 AM					
Sotelo, Enrique	rio grande wing /staff restroom /emegency lamp ballast is out/we have no lite in restrm								
<u>Danny Vega</u>									
72957					5/6/2011		11		\$0.00
Medium	Work In Progress			5/6/2011 8:26:31 AM					
Sotelo, Enrique	restrooms by lounge /staff rr /emegency lamp ballast is out/have only one lamp wking								
<u>Danny Vega</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>North Valley ES</b>							
72995					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:13 AM					
Vega, Danny		Monthly - North Valley ES Playground Inspection - Refer to PM schedule details.							
Margret Villalobos									
73067					5/10/2011		7		\$0.00
Medium	Work In Progress			5/10/2011 10:08:37 AM					
Carbajal, Jimmy		extension cord on sgower scrubber not working.							
Javier Parra									
73255					5/16/2011		1		\$0.00
Medium	Work In Progress			5/16/2011 2:43:24 PM					
Gonzalez, Salvador		NEED TO WELD BASKETBALL RIM /HAVE REMOVE FROM BACK BOARD							
Danny Vega									
<b>Count: 33 Work Orders</b>		<b>Avg. Age of WO's 49</b>			<b>Total for North Valley ES</b>			<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
63741					9/10/2010		249		\$0.00
Medium	Work In Progress			9/10/2010 10:28:46 AM					
Ontiveros, Guadalupe	as per conversation, please remove front hedges and design a small landscaping sceem.thank you								
<u>Michael Munoz</u>									
67268					12/5/2010		163		\$0.00
Medium	Work In Progress			12/5/2010 12:27:28 AM					
Sanchez, Raul	Monthly - Northern Pre-K - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67825					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:39 AM					
Villalobos, David	Yearly - Northern Pre-K Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68782					1/26/2011		111		\$0.00
Medium	Work In Progress			1/26/2011 9:41:38 AM					
Flores, Pete	john deere 125 mower will need new belt and blades at Im pre-k/service for summer use .please thanks								
<u>Danny Vega</u>									
69113					2/6/2011		100		\$0.00
Medium	Work In Progress			2/6/2011 12:34:10 AM					
Sanchez, Raul	Monthly - Northern Pre-K - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69965					2/28/2011	3/11/2011	78		\$0.00
Medium	Work In Progress			2/28/2011 12:25:14 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69966					2/28/2011	3/11/2011	78		\$0.00
Medium	Work In Progress			2/28/2011 12:25:14 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69967					2/28/2011	3/11/2011	78		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
69968					2/28/2011	3/11/2011	78		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69969					2/28/2011	3/11/2011	78		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69970					2/28/2011	3/11/2011	78		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69971					2/28/2011	3/11/2011	78		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69972					2/28/2011	3/11/2011	78		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
69973					2/28/2011	3/11/2011	78		\$0.00
Medium	Work In Progress			2/28/2011 12:25:15 AM					
Orozco, Danny	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70146	Main Building	Classroom			3/3/2011		75		\$0.00
Medium	Work In Progress	101		3/3/2011 11:32:55 AM					
Ontiveros, Joe	Room 101 repair lavatory faucet								
<u>Alfredo Holguin</u>									
70595	Main Building	Office			3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 10:23:30 AM					
Ontiveros, Guadalupe	Remove old shrubs from front of building. Last person that came in to see shrubs said this was a winter project. Currently not done yet.								
<u>Concepcion Montalvo</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Northern On-Track Pre-K (LM)

71240					3/30/2011		48		\$0.00
Medium	Work In Progress			3/30/2011 10:53:45 AM					
Estrada, Jesus	ROOM #114 - UNEVEN TILES ARE A TRIP HAZARD. PLEASE MAKE RECOMMENDATION.								

Jesus Estrada

71324					3/31/2011		47		\$0.00
Medium	Work In Progress			3/31/2011 2:36:49 PM					
Munoz, Michael	NEED TO INSTALL 3' WALK THRU GATE BY THE BASKETBALL COURTS								

Michael Munoz

71354					4/1/2011		46		\$0.00
Medium	Work In Progress			4/1/2011 7:36:32 AM					
Flores, Pete	need diesel fuel for fire protection pump/need to top it off /showing 3/4 full(pump house)								

Danny Vega

71631					4/5/2011		42		\$0.00
Medium	Work In Progress			4/5/2011 12:14:59 AM					
Sanchez, Raul	Monthly - Northern Pre-K- Domestic Water Filters - Refer to PM schedule details.								

Margret Villalobos

71715					4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 11:34:26 AM					
Gonzalez, Salvador	build ramp for new morgan bldg/diamond plated								

Danny Vega

71739					4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 2:51:02 PM					
Lozoya, Manny	NEED NEW LOCK FOR MORGAN BUILDING, NEED CORED TO MASTER KEY.								

Adam Montoya

71748		Athletic Field			4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 3:31:22 PM					
Munoz, Michael	need a gate on northwest corner of campus so children can play on basketball concrete pads. thank you								

Michael Munoz

72070					4/13/2011		34		\$0.00
Medium	Work In Progress			4/13/2011 4:17:23 PM					
Lozoya, Manny	NEED LOCK FOR NEW GATE NEXT TO MORGAN BUILDING.								

Adam Montoya

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Northern On-Track Pre-K (LM)</b>							
72594					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:52 AM					
Vega, Danny	Yearly - Northern Pre-K C11 (Evap.Cooler)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
72659					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:06 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
72660					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:07 AM					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
72663					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:08 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
72795					5/3/2011		14		\$0.00
Medium	Work In Progress			5/3/2011 12:15:03 AM					
Sanchez, Raul	Monthly - Northern Pre-K- Domestic Water Filters - Refer to PM schedule details.								
Margret Villalobos									
72996					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:14 AM					
Vega, Danny	Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 30 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>68</b>	<b>Total for Northern On-Track Pre-K (LM)</b>			<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Physical Plant Complex

60767 Maintenance 7/7/2010 314 \$0.00

Medium Work In Progress 7/7/2010 6:40:24 AM

Ambriz, Jose

The unit here at the Maintenance Office keeps freezing up and it seems to happen mid day when it's really hot. We had this problem last summer too. Do you think we could have the unit replaced with a Heating/Cooling Unit?

PS....It also vibrates a lot.

Margret Villalobos

62486 8/13/2010 277 \$0.00

Medium Work In Progress 8/13/2010 3:50:09 PM

Flores, Pete

NEED TO FIX FRONT PASSAGER TIRE IS LOCKOUT AND MAKING KNOCKING BADLY SOUND.

Joe Ontiveros

64249 9/22/2010 237 \$0.00

Medium Work In Progress 9/22/2010 8:33:53 AM

Flores, Pete

our ditch with backhoe attachment needs repair the chain drive on it: the chain on it or the gears are wore and the chain is jumping when you select to move it forward or in reverse. we need it fixed asap. need it for some jobs at some school sites. if we continue to use as is we will run into higher repairs on the machine. thank Fred

Fred Appelzoller

64255 Food Services 9/22/2010 237 \$0.00

Medium Work In Progress 9/22/2010 11:30:35 AM

Orozco, Danny

FREEZER #3 AND #5: DOOR SEALS NEED TO BE REPLACED. DOORS DON'T SHUT RIGHT. TORN DOOR SEALS.

JOHNNY LECHUGA SNP MGR 882-6927

Jacqueline Aguilar

65010 Motor Vehicle 10/6/2010 223 \$0.00

Medium Work In Progress 10/6/2010 9:46:33 AM

Appelzoller, Fred

please remove existing compressor and replace with new one. location will change and install will be outside in the metal building.thanks

Michael Munoz

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Physical Plant Complex</b>							
65725					10/21/2010		208		\$0.00
Medium	Work In Progress			10/21/2010 2:31:05 PM					
Gonzalez, Salvador		10/21/10	Need a welder to install an iron bracket at the wastewater plant to secure the pipe that connects to the static screen. This pipe vibrates too much when the pumps turn off. It may break if it is not supported						
<u>Raul Sanchez</u>									
66231	Maintenance				11/2/2010		196		\$0.00
Medium	Work In Progress			11/2/2010 8:00:06 AM					
Sotelo, Enrique			please provide power to the new compressor to be installed. thank you						
<u>Michael Munoz</u>									
66998					11/30/2010		168		\$0.00
Medium	Work In Progress			11/30/2010 4:11:27 PM					
Perez, Raul			Mail Van # 11 - Seats need to be upholstered. Remove and do the passenger side first. then remove driver side and replace with passenger side and do the driver side and install on passenger side if necessary.						
<u>Alfredo Holguin</u>									
66999					11/30/2010		168		\$0.00
Medium	Work In Progress			11/30/2010 4:16:27 PM					
Flores, Pete			Van # 23 - Needs to be serviced.						
<u>Manny Lozoya</u>									
67015					12/1/2010		167		\$0.00
Low	Work In Progress			12/1/2010 11:54:46 AM					
Perez, Raul			wash car #33						
67062	Motor Vehicle				12/2/2010		166		\$0.00
Medium	Work In Progress	vehicles-183		12/2/2010 8:32:28 AM					
Flores, Pete			athletic's ford expeditions require wiper blade refills.						
<u>Pete Flores</u>									
67705	Motor Vehicle				12/16/2010		152		\$0.00
Medium	Work In Progress	vehicle#116		12/16/2010 10:13:43					
Flores, Pete			left rear tire flat.						
<u>Pete Flores</u>									
67706	Motor Vehicle				12/16/2010		152		\$0.00
Medium	Work In Progress	vehicle#161		12/16/2010 10:16:11					
Flores, Pete			flat tire on vehicle's left front.						
<u>Pete Flores</u>									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Physical Plant Complex</b>							
67828					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:41 AM					
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
68082	Motor Vehicle				1/7/2011		130		\$0.00
Medium	Work In Progress	vehicle#92		1/7/2011 1:03:42 PM					
Flores, Pete		vehicle#92 is scheduled for routine service.							
Pete Flores									
68682					1/24/2011		113		\$0.00
Medium	Work In Progress			1/24/2011 10:11:33 AM					
Carrasco, Danny		please texture, paint and install vct in room next to techs.thank you							
Michael Munoz									
68683					1/24/2011		113		\$0.00
Medium	Work In Progress			1/24/2011 10:13:34 AM					
Carrasco, Danny		as per our conversation we had, please dispose of any material outdated and cut and clean in fenced area.thank you							
Michael Munoz									
68685					1/24/2011		113		\$0.00
Medium	Work In Progress			1/24/2011 10:45:44 AM					
Ronquillo, Ruben		as per meeting held, please dispose of any unused material and clean and organize barracks. thank you.							
Michael Munoz									
68801					1/26/2011		111		\$0.00
Medium	Work In Progress			1/26/2011 3:08:04 PM					
Ronquillo, Ruben		Need to refill First Aide Boxes at Maint. Warehouse and Maint Lobby. Asp Alfredo now is the time...							
Margret Villalobos									
69148	Motor Vehicle				2/7/2011		99		\$0.00
Medium	Work In Progress	vehicle #128		2/7/2011 3:16:36 PM					
Flores, Pete		vehicle sluggish at highway speeds and clutch is very difficult to engage.							
Pete Flores									
69276					2/9/2011		97		\$0.00
Medium	Work In Progress			2/9/2011 2:05:42 PM					
Estrada, Jesus		NEED FOR CARPET IN JULIES OFFICE TO BE REPLACED.							
Jesus Estrada									
5/17/2011 12:10:28 PM									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
69797					2/22/2011		84		\$0.00
Medium	Work In Progress			2/22/2011 4:17:36 PM					
Ronquillo, Ruben	PURCHASE DEEP CYCLE BATTERIES FOR SCISSOR LIFT. FOR RUBEN THANK YOU								
<u>Ruben Ronquillo</u>									
70122	Maintenance				3/3/2011		75		\$0.00
Medium	Work In Progress			3/3/2011 8:12:40 AM					
Gonzalez, Salvador	build an iron frame cart with wheels to be used at work shop.								
<u>Lorenzo Solis</u>									
70135		Athletic Field			3/3/2011		75		\$0.00
Medium	Work In Progress			3/3/2011 9:16:15 AM					
Flores, Pete	dump truck #96 needs new tarp to transport material as per D.P.S								
<u>Guadalupe Ontiveros</u>									
70258					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:47 AM					
Orozco, Danny	Yearly - Physical Plant Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70687					3/11/2011		67		\$0.00
Medium	Work In Progress			3/11/2011 3:44:00 PM					
Flores, Pete	Truck #16 dies at the stops. Loud pop when in reverse, when traveling at 15 mph the front wheels pull to the sides. The A/C does not work.								
<u>Jesus Estrada</u>									
70869	Motor Vehicle				3/17/2011		61		\$0.00
Medium	Work In Progress	vehicle#104-		3/17/2011 11:01:37 AM					
Flores, Pete	vehicle stalls intermittently.check and advise								
<u>Pete Flores</u>									
70898	Maintenance	Mechanical			3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 7:49:30 AM					
Gonzalez, Salvador	please weld a 3 tank rack for compay truck to carry freon. safety								
<u>Lorenzo Solis</u>									
71132	Motor Vehicle				3/28/2011		50		\$0.00
Medium	Work In Progress	vehicle#120		3/28/2011 9:06:52 AM					
Flores, Pete	vehicle is in need of tires								
<u>Pete Flores</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
71586					4/4/2011		43		\$0.00
Medium	Work In Progress			4/4/2011 7:27:39 AM					
Flores, Pete	Vehicle # 23, please replace front windshield and repair side one as well.thank you(locksmith manny)								
<u>Michael Munoz</u>									
71602	Motor Vehicle				4/4/2011		43		\$0.00
Medium	Work In Progress	vehicle#44		4/4/2011 9:57:28 AM					
Flores, Pete	vehicle leaking engine coolant.check&advise								
<u>Pete Flores</u>									
71618	Motor Vehicle				4/4/2011		43		\$0.00
Medium	Work In Progress	vehicle#160		4/4/2011 3:34:07 PM					
Flores, Pete	vehicle requires maintenance								
<u>Pete Flores</u>									
71697		Athletic Field			4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 8:49:47 AM					
Flores, Pete	back hoe is leaking from hydraulic fitting.								
<u>Guadalupe Ontiveros</u>									
71699		Athletic Field			4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 8:56:55 AM					
Flores, Pete	dump truck #96 needs windshield replaced.hydraulic tank needs to be weld, leaking oil. left front signal broken. as per d.o.t.								
<u>Guadalupe Ontiveros</u>									
71729	Maintenance	Custodial			4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 12:57:33 PM					
Flores, Pete	VAN #29 STALLED AT MESQUITE ELEM I BELIVE IT MAY BE THE FUEL PUMP THIS IS THE VAN WE USE AT THE PPD FOR THE CUSTODIAL DUTIES I HAVE BEEN USING MY PERSONNAL VEHICLE TO PERFORM THE CUSTODIAL DUTIES WHICH I BELIVE TO BE UNETHICAL WE ALSO USE THIS VAN FOR MISCELLANEOUS RUNS WE ONLY HAVE THIS ONE.								
<u>Jimmy Carbajal</u>									
71813					4/8/2011		39		\$0.00
Medium	Work In Progress			4/8/2011 8:41:02 AM					
Ronquillo, Ruben	OREDER NEW US/NM NYLON FLAGS. FOR RUBEN THANK YOU								
Ruben Ronquillo									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
72348	Food Services				4/21/2011		26		\$0.00
Medium	Work In Progress			4/21/2011 1:43:47 PM					
Perez, Raul	VAN 143 (JOHHNY LECHUGA) NEEDS TO BE WASHED.								
<u>Maritza Gonzalez</u>									
72543					4/29/2011		18		\$0.00
Medium	Work In Progress	Construction		4/29/2011 8:01:13 AM					
Flores, Pete	GISD Vehicle No. 16 (Mr. Gallegos' Truck) needs to be serviced. He will be out May 2-4 so the truck will be available for servicing on any of those days. Thanks								
<u>Peggy Jo Hernandez</u>									
72764	Motor Vehicle				5/2/2011		15		\$0.00
Medium	Work In Progress	vehicle#159		5/2/2011 10:58:58 AM					
Flores, Pete	window to driver's door inoperable.vehicle is also in need of maintenance								
<u>Pete Flores</u>									
72765	Motor Vehicle				5/2/2011		15		\$0.00
Medium	Work In Progress	vehicle#157		5/2/2011 11:02:27 AM					
Flores, Pete	vehicle requires maintenance and a new set of tires								
<u>Pete Flores</u>									
72766	Motor Vehicle				5/2/2011		15		\$0.00
Medium	Work In Progress	vehicle#138		5/2/2011 11:04:58 AM					
Flores, Pete	vehicle requires service								
<u>Pete Flores</u>									
72768	Motor Vehicle				5/2/2011		15		\$0.00
Medium	Work In Progress	vehicle#136		5/2/2011 11:07:38 AM					
Flores, Pete	driver's door window will not roll down.								
<u>Pete Flores</u>									
72769	Motor Vehicle				5/2/2011		15		\$0.00
Medium	Work In Progress	vehicle#121		5/2/2011 11:09:42 AM					
Flores, Pete	vehicle cranks but at times does not start								
<u>Pete Flores</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Physical Plant Complex</b>									
72772		Custodial			5/2/2011		15		\$0.00
Medium	Work In Progress			5/2/2011 12:40:08 PM					
Flores, Pete	CUSTODIAL VAN #29 HAS STALLED AT GHS WONT START NEEDS FUEL PUMP I USE THIS VAN FOR CUSTODIAL DUTIES HERE AT THE PPD WITHOUT IT I HAVE TO USE MY PERSONEL VEHICLE I ALSO USE THIS VEHICLE FOR TIME SHEET PICK UP AND OTHER ERRANDS.								
Jimmy Carbajal									
72777					5/2/2011		15		\$0.00
Medium	Work In Progress			5/2/2011 2:04:54 PM					
Carbajal, Jimmy	NEED TO COMPLETE A CUSTODIAL EQUIPMENT ANNUAL INVENTORY FOR ALL SCHOOL SITES.								
	5/5/11 - REVISED - INVENTORY NEEDS TO INCLUDE WHS INVENTORY AS WELL. THANK YOU!								
Jesus Estrada									
72818	Motor Vehicle				5/3/2011		14		\$0.00
Medium	Work In Progress	vehicle#168		5/3/2011 10:04:43 AM					
Flores, Pete	vehicle's tires are worn beyond limits.replacement required								
Pete Flores									
73072					5/10/2011		7		\$0.00
Medium	Work In Progress			5/10/2011 1:50:00 PM					
Ronquillo, Ruben	ORDER NEW NYLON ROPE FOR BOOM TRUCK. FOR RUBEN								
Ruben Ronquillo									
73109	Motor Vehicle				5/11/2011		6		\$0.00
Medium	Work In Progress	vehicle#129		5/11/2011 10:05:02 AM					
Flores, Pete	vehicle requires 4 new tires								
Pete Flores									
73110	Motor Vehicle				5/11/2011		6		\$0.00
Medium	Work In Progress	vehicle#109		5/11/2011 10:06:40 AM					
Flores, Pete	vehicle requires 4 new tires								
Pete Flores									
73277	Motor Vehicle				5/17/2011		0		\$0.00
Medium	Work In Progress	vehicle#48		5/17/2011 9:35:05 AM					
Flores, Pete	vehicle is in need of oil change								
Pete Flores									
<b>Count: 50 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>92</b>		<b>Total for Physical Plant Complex</b>	<b>0</b>		<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
62586		Cafeteria			8/17/2010		273		\$0.00
Medium	Work In Progress			8/17/2010 11:24:47 AM					
Orozco, Danny	GARBAGE DISPOSAL: NEED TO REPLACE THE START AND STOP SWITCH.								
	DANNY O SNP TECH.								
<u>Jacqueline Aguilar</u>									
64030					9/16/2010		243		\$0.00
Medium	Work In Progress			9/16/2010 3:38:00 PM					
Perez, Raul	need 10gal desil and 5gal gas								
<u>Carlos Hernandez</u>									
65568					10/18/2010		211		\$0.00
Medium	Work In Progress			10/18/2010 3:26:52 PM					
Gonzalez, Salvador	need to make metal frame cover for outside water fountains								
<u>Carlos Hernandez</u>									
66092					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:25					
Orozco, Danny	Monthly - Riverside ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67139					12/3/2010		165		\$0.00
Medium	Work In Progress			12/3/2010 3:08:38 PM					
Flores, Pete	need to replace broken pin on scraper to 970								
<u>Carlos Hernandez</u>									
67829					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:41 AM					
Villalobos, David	Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68190					1/10/2011		127		\$0.00
Medium	Work In Progress			1/10/2011 3:36:33 PM					
Lara, Ralph	need replacement padlock for back gates old one missing and a spare one								
<u>Carlos Hernandez</u>									
68498					1/18/2011		119		\$0.00
Medium	Work In Progress			1/18/2011 2:11:20 PM					
Villalobos, David	need to replace koler seat need special part to install new one								
Carlos Hernandez									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
68725					1/25/2011		112		\$0.00
Medium	Work In Progress			1/25/2011 9:09:10 AM					
Castillo, Carlos	need to replace covers and light bulbs on light poles outside new wing								
Carlos Hernandez									
68958					2/1/2011		105		\$0.00
Medium	Work In Progress			2/1/2011 8:20:29 AM					
Carrasco, Danny	need 15 gallon gas for truck								
Carlos Hernandez									
70245					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:41 AM					
Orozco, Danny	Yearly - Riverside ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
70572		Cafeteria			3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 8:16:48 AM					
Orozco, Danny	WALK IN DOOR STOPPER NOT WORKING.								
EMILIA SNP MGR 589-2550									
Jacqueline Aguilar									
71168					3/28/2011		50		\$0.00
Medium	Work In Progress	Landscaping		3/28/2011 3:42:10 PM					
Villalobos, David	Need line locate for landscaping project. For location, please coordinate with Contractor - Joe Garcia/ESA Construction - (915)549-4582.								
Peggy Jo Hernandez									
71271					3/30/2011		48		\$0.00
Medium	Work In Progress			3/30/2011 4:31:54 PM					
Orozco, Danny	SPRING NEEDS TO BE REPLACED ON DISHWASHER. SNP MANAGER EMILIA C. 589.2550								
Maritza Gonzalez									
71439					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:55 AM					
Orozco, Danny	Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71974					4/11/2011		36		\$0.00
Medium	Work In Progress			4/11/2011 3:33:19 PM					
Villalobos, David	need replace faucet in room 117 leaking								
Carlos Hernandez									
5/17/2011 12:10:28 PM									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Riverside ES</b>									
71975					4/11/2011		36		\$0.00
Medium	Work In Progress			4/11/2011 3:34:15 PM					
Villalobos, David	need to replace faucet in roomn 126 keeps running								
Carlos Hernandez									
72354					4/21/2011		26		\$0.00
Medium	Work In Progress			4/21/2011 3:21:36 PM					
Villalobos, David	need replace faucet to upperwing custodial closet leaking								
Carlos Hernandez									
72650					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:01 AM					
Orozco, Danny	Monthly - Riverside ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
72763		Gym			5/2/2011		15		\$0.00
Medium	Work In Progress			5/2/2011 10:41:06 AM					
Briones, Enrique	PICK-UP STUDENTS DESK AND CHAIRS NO LONGER IN USE OR BREAK								
Olga Arias									
72821					4/26/2011		21		\$0.00
Medium	Work In Progress			5/3/2011 10:44:30 AM					
Hernandez, Carlos	Kinder Playground - Burnt canopy and graffiti slide, pulled out pole to helicopter. (Case# 2011562)								
Vicente Sanchez									
72836					5/3/2011		14		\$0.00
Medium	Work In Progress			5/3/2011 3:29:10 PM					
Flores, Pete	need barrow botcat to clean up sand around campus								
Carlos Hernandez									
72993					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:12 AM					
Hernandez, Carlos	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
73108					5/11/2011		6		\$0.00
Medium	Work In Progress			5/11/2011 9:46:34 AM					
Orozco, Danny	1) REFRIGERATOR STAYS AT 40 DEGREES, TEMP WILL NOT GO UP/DOWN. 2) WALK IN HAS A LINE THAT IS LEAKING.								
Maritza Gonzalez									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Riverside ES</b>								
73242					5/16/2011		1		\$0.00	
Medium	Work In Progress			5/16/2011 11:18:32 AM						
Carrasco, Danny	need driking water and water for comotes due to main water break									
Carlos Hernandez										
73247					5/16/2011		1		\$0.00	
Medium	Work In Progress			5/16/2011 12:45:25 PM						
Briones, Enrique	On May 19, 2011, please deliver 1 box to Riverside Elementary. Reference p.O. # 101107498. Also, deliver 1 empty Gaylord + Pallet to Ms. Frederick.									
Yolie Jacquez										
73271		Custodial			5/17/2011		0		\$0.00	
Medium	Work In Progress			5/17/2011 7:51:04 AM						
Carbajal, Jimmy	mr. j.c. se desconpuso 1 aspiradora favor de arreglarla. gracias r. r.									
Raul Romero										
<b>Count: 27 Work Orders</b>		<b>Avg. Age of WO's 80</b>		<b>Total for Riverside ES</b>			<b>0</b>	<b>\$0.00</b>		

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: RTC - Alliance</b>									
70128		Stairway			3/3/2011		75		\$0.00
Medium	Work In Progress				3/3/2011 8:43:55 AM				
Ambriz, Juan		need to repair ramp that are warped safety precautions							
Gloria Delgado									
70130		Office			3/3/2011		75		\$0.00
Medium	Work In Progress				3/3/2011 8:46:06 AM				
Ambriz, Juan		would like my office painted in the summer							
Gloria Delgado									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>75</b>		<b>Total for RTC - Alliance</b>	<b>0</b>		<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>San Miguel ES</b>							
62911		Pump House			8/25/2010		265		\$0.00
Medium	Work In Progress			8/25/2010 11:04:05 AM					
Sanchez, Raul	Plug well LRG 7618 as per Satate Engineer Requierments and have Contractor provide a Plugging Report								
Alfredo Holguin									
70749					3/14/2011		64		\$0.00
Medium	Work In Progress			3/14/2011 3:43:01 PM					
Solis, Lorenzo	as per mike need to repair hvac water lines at sme boiler circulating pumps and damage to lines in hallways (winter storm)								
Danny Vega									
73270					5/17/2011		0		\$0.00
Medium	Work In Progress			5/17/2011 7:31:26 AM					
Solis, Lorenzo	water lines are busted in boiler rm/isolation valves are shut-off but water is still coming out/need to repair so we can turn pump on .so i can water lawn as per mike m.								
Danny Vega									
<b>Count: 3 Work Orders</b>		<b>Avg. Age of WO's 110</b>			<b>Total for San Miguel ES</b>			<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
61467	Main Building	Cafeteria			7/28/2010		293		\$0.00
Medium	Work In Progress	cafeteria			7/28/2010 4:00:25 PM				
Moncayo, Fernando		CEILING TILES AND HVAC REGISTERS NEED TO BE CLEANED. PLEASE ASSIT CAFETERIA STAFF WITH THIS MATTER. THANKS.							
<u>Rita Mendez</u>									
63124					8/30/2010		260		\$0.00
Medium	Work In Progress				8/30/2010 9:22:32 AM				
Marquez, Gerardo		MR. Y. IS REQUESTING 3-SECRETARY PARKING SIGNS BE INSTALLED @ FACULTY PARKING LOT.							
<u>Gerardo Marquez</u>									
65678					10/20/2010		209		\$0.00
Medium	Work In Progress				10/20/2010 9:47:18 AM				
Ambriz, Jose		JOSE; HVAC IN PORTABLE-E (THE MUSIC RM. NEEDS UPGRADING. ) THANKS.							
<u>Gerardo Marquez</u>									
66094					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress				10/31/2010 12:36:26				
Orozco, Danny		Monthly - Santa Teresa ES Fire Suppression Insp. - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
67834					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress				1/2/2011 12:28:43 AM				
Villalobos, David		Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
68588	Main Building	Classroom			1/19/2011		118		\$0.00
Medium	Work In Progress	ROOM 309			1/19/2011 4:33:34 PM				
Marquez, Gerardo		MRS. TELLES'S WORLD MAP IS NOT ROLLING DOWN. IT NEEDS TO BE CHECKED. THANKS.							
<u>Rita Mendez</u>									
68593					1/20/2011		117		\$0.00
Medium	Work In Progress				1/20/2011 8:32:32 AM				
Marquez, Gerardo		NEED TO ORDER FERTILIZER & WEED & FEED FOR PLAYGROUND. THANKS.							
<u>Gerardo Marquez</u>									
69185					2/8/2011		98		\$0.00
Medium	Work In Progress				2/8/2011 9:42:03 AM				
Villalobos, David		WATER COMING OUT OF WALL IN CAFET. PREP AREA UNDER DISHWASHER PLEASE CHECK IT OUT. THANKS.							
<u>Gerardo Marquez</u>									

5/17/2011 12:10:28 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
70246					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:41 AM					
Orozco, Danny	Yearly - Santa Teresa ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
70286					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:18:01 AM					
Marquez, Gerardo	Yearly - Santa Teresa ES A-10 HEAT PUMPS (ANNUAL) - Refer to PM schedule details.								
Margret Villalobos									
70287					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:18:02 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos									
71017		Cafeteria			3/23/2011		55		\$0.00
Medium	Work In Progress			3/23/2011 9:58:38 AM					
Castillo, Carlos	new package unit will be installed.unit will need power run to it.please meet with Jose(HVAC) for installation date.thankyou								
Michael Munoz									
71278					3/31/2011		47		\$0.00
Medium	Work In Progress			3/31/2011 12:17:29 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES-A-16 Fan Exhaust (SemiA) - Refer to PM schedule details.								
Margret Villalobos									
71440					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:56 AM					
Orozco, Danny	Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
71475					4/3/2011	4/11/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:12 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
71476					4/3/2011	4/11/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:12 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
71477					4/3/2011		44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:13 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71704					4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 9:16:10 AM					
Marquez, Gerardo	MIKE. BASKETBALL GOAL POLE PADS NEED TO BE INSTALLED ON ALL 8 GOALS. THANKS.								
<u>Gerardo Marquez</u>									
71705					4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 9:19:55 AM					
Villalobos, David	A SHUT OFF VALVE NEEDS TO BE INSTALLED OUTSIDE OF CAFET. ON THE WATER SUPPLY LINE THAT GOES TO PORTABLE C & D, & MOBILE HOME. THANKS.								
<u>Gerardo Marquez</u>									
71708					4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 9:43:49 AM					
Marquez, Gerardo	NEED TO REPLACE CONCRETE THAT WAS REMOVED TO FIX WATER LEAK @ BACK OF CAFETERIA. WILL NEED 15 BAGS OF CONCRETE MIX. THANKS.								
<u>Gerardo Marquez</u>									
71891					4/10/2011	4/26/2011	37		\$0.00
Medium	Work In Progress			4/10/2011 12:14:28 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71908					4/10/2011	4/26/2011	37		\$0.00
Medium	Work In Progress			4/10/2011 12:14:37 AM					
Diaz, Pablo	Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.								
<u>Jesus Estrada</u>									
71943	Main Building	Library			4/11/2011		36		\$0.00
Medium	Work In Progress	Mrs.Harmon		4/11/2011 9:11:13 AM					
Marquez, Gerardo	Please paint and install letters above library door								
Rosie Diaz									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
71999					4/12/2011		35		\$0.00
Medium	Work In Progress			4/12/2011 10:19:09 AM					
Marquez, Gerardo	NEED TO REPLACE SUPPLY LINES TO MASTER COOLS & STERLING UNITS. BALL VALVES ALSO NEED TO BE REPLACES. (NOT SHUTTING OFF.)								
Gerardo Marquez									
72232	Main Building	Restroom (Boys)			4/19/2011		28		\$0.00
Medium	Work In Progress	CASA BLANCA		4/19/2011 10:54:34 AM					
Marquez, Gerardo	URINAL IS PLUGGED AND IS OVERFLOWING.								
Rita Mendez									
72299					4/20/2011		27		\$0.00
Medium	Work In Progress			4/20/2011 11:24:04 AM					
Marquez, Gerardo	Door to Pipe Chase at Bathrooms at end of north wing- Trim top so it closes properly								
Alfredo Holguin									
72301	Main Building				4/20/2011		27		\$0.00
Medium	Work In Progress			4/20/2011 11:30:32 AM					
Holguin, Alfredo	replace tile at various locations through out the building where it is cracked or damaged to inclue repair of control joints if necessary or level of concret by grinding		fax to Rodriguez, requested that they call Alfredo to meet with them at STE when they are ready to go out and quote.						
Alfredo Holguin									
72326	Main Building	Classroom			4/20/2011		27		\$0.00
Medium	Work In Progress	casa azul		4/20/2011 4:31:24 PM					
Marquez, Gerardo	NEED TO INSTALL DRY ERASE BOARD AND RELOCATE CORK BULLETIN BOARD.								
Rita Mendez									
72352	Main Building	Classroom			4/21/2011		26		\$0.00
Medium	Work In Progress	Melendez/Porta		4/21/2011 3:18:05 PM					
Marquez, Gerardo	Please spray for ants in classroom. Thank you		Mike is going to have Gerry look into this. - mkv						
Rosie Diaz									
72468		Auditorium			4/27/2011		20		\$0.00
Medium	Work In Progress			4/27/2011 11:04:49 AM					
Marquez, Gerardo	ART DISPLAY CANOPY NEED TO BE SET UP FOR ART SHOW ON APRIL 28, 2011 AND NEED TO BE BROUGHT DOWN ON MAY 2. 2011. THANKS.								
Rita Mendez									
72652					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:02 AM					
Orozco, Danny	Monthly - Santa Teresa ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
5/17/2011 12:10:28 PM									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
72676					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:15 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72677					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:15 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72678					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:16 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72679					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:16 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72872	Main Building	Classroom			5/4/2011		13		\$0.00
Medium	Work In Progress	PORTABLE A		5/4/2011 11:25:49 AM					
Marquez, Gerardo	EASEL NEEDS TO BE ASSEMBLED FOR MS. MELENDEZ'S CLASSROOM. THANKS.								
<u>Rita Mendez</u>									
72900	Main Building	Hallway/Corridor			5/4/2011		13		\$0.00
Medium	Work In Progress	SCHOOL		5/4/2011 5:35:08 PM					
Marquez, Gerardo	CABINET NEEDS TO BE CONSTRUCTED TO DISPLAY OUR BLUE RIBBON CERTIFICATES/AWARDS. (MATERIALS NEEDED). THANK YOU								
<u>Rita Mendez</u>									
72920	Main Building				5/5/2011		12		\$0.00
Medium	Work In Progress	Deeds/ Room		5/5/2011 9:59:06 AM					
Lara, Ralph	File cabinet needs a new lock. thanks								
<u>Rosie Diaz</u>									
73000					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:15 AM					
Marquez, Gerardo	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

5/17/2011 12:10:28 PM



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa ES</b>							
73011	Main Building	Restroom (Boys)			5/9/2011		8		\$0.00
Medium	Work In Progress	Casa Blanca			5/9/2011 9:10:32 AM				
Castillo, Carlos		The boys and girls restroom lights are not turning on in Casa Blanca. please check. thanks							
Rosie Diaz									
73096	Main Building	Library			5/10/2011		7		\$0.00
Medium	Work In Progress	library			5/10/2011 5:10:13 PM				
Castillo, Carlos		PLEASE INSTALL AN ELECTRICAL OUTLET IN THE LIBRARY TO SET UP OUR FLATSCREEN TV. PLEASE CHECK WITH MRS. HARMON, OUR LIBRARIAN, FOR THE LOCATION. THANK YOU.							
Rita Mendez									
73113	Main Building	Hallway/Corridor			5/11/2011		6		\$0.00
Medium	Work In Progress	ENTRANCE TO			5/11/2011 12:00:25 PM				
Marquez, Gerardo		BLUE RIBBON BRONZE SIGN NEEDS TO BE INSTALLED IN FRONT OF OUR SCHOOL. THANKS.							
Rita Mendez									
73154		Cafeteria			5/12/2011		5		\$0.00
Medium	Work In Progress				5/12/2011 9:16:16 AM				
Carbajal, Jimmy		BACK WHEEL FELL OFF							
Pablo Diaz									
73155	Main Building	Custodial			5/12/2011		5		\$0.00
Medium	Work In Progress				5/12/2011 9:17:30 AM				
,		BROKEN HANDLE							
Pablo Diaz									
73274	Main Building	Classroom			5/17/2011		0		\$0.00
Medium	Work In Progress	ROOM 108			5/17/2011 8:32:54 AM				
Lara, Ralph		MS. DEEDS NEEDS A NEW LOCK ON HER FILE CABINET. THIS CABINET NEEDS TO BE LOCKED BECAUSE OF SPECIAL ED PAPERWORK. IT THIS CAN BE DONE ASAS. THANKS.							
Rita Mendez									
<b>Count: 45 Work Orders</b>		<b>Avg. Age of WO's 56</b>			<b>Total for Santa Teresa ES</b>			<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
60574					7/4/2010	7/10/2010	317		\$0.00
Medium	Work In Progress			7/4/2010 12:23:35 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60575					7/4/2010	7/12/2010	317		\$0.00
Medium	Work In Progress			7/4/2010 12:23:35 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60576					7/4/2010	8/4/2010	317		\$0.00
Medium	Work In Progress			7/4/2010 12:23:35 AM					
Nunez, Arturo	Yearly - Santa Teresa HS Emer. Light Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60577					7/4/2010	8/4/2010	317		\$0.00
Medium	Work In Progress			7/4/2010 12:23:36 AM					
Nunez, Arturo	Yearly - Santa Teresa HS Exit Sign Test: Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60578					7/4/2010		317		\$0.00
Medium	Work In Progress			7/4/2010 12:23:36 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60579					7/4/2010	7/7/2010	317		\$0.00
Medium	Work In Progress			7/4/2010 12:23:36 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60603					7/4/2010	7/25/2010	317		\$0.00
Medium	Work In Progress			7/4/2010 12:23:44 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
60853					7/11/2010	8/11/2010	310		\$0.00
Medium	Work In Progress			7/11/2010 12:20:25 AM					
Nunez, Arturo	Yearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
60968					7/14/2010		307		\$0.00
Medium	Work In Progress			7/14/2010 12:20:23 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Grease Trap (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
61359		Classroom			7/27/2010		294		\$0.00
Medium	Work In Progress	MRS.		7/27/2010 10:07:32 AM					
Nunez, Arturo	1. CEILING TILES NEED TO BE REPLACED. 2. NEED OVERHEAD SCREEN ATTACHED TO CEILING OVER CHALK BOARD.								
<u>Marylou Jimenez</u>									
61530					7/30/2010		291		\$0.00
Medium	Work In Progress			7/30/2010 8:26:29 AM					
Perez, Raul	NEED TO HAVE WINDSHIELD ,PASSENGERS WINDOW , AND BAND TRUCK REARVIEW MIRRORS REPLACED. VANDALISM. Case#2010-07139								
<u>Arturo Nunez</u>									
61606					8/1/2010	8/4/2010	289		\$0.00
Medium	Work In Progress			8/1/2010 12:47:39 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
61607					8/1/2010		289		\$0.00
Medium	Work In Progress			8/1/2010 12:47:39 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
61608					8/1/2010	8/7/2010	289		\$0.00
Medium	Work In Progress			8/1/2010 12:47:40 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
62106					8/8/2010	9/8/2010	282		\$0.00
Medium	Work In Progress			8/8/2010 12:38:55 AM					
Prospero, Manuel	Yearly - Santa Teresa HS A-9 Air Cooled Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
62237					8/10/2010		280		\$0.00
Safety	Work In Progress			8/10/2010 9:13:08 AM					
Nunez, Arturo	Check all wall cabinets throughout your site and make sure they are secure to wall and remind teachers not to overload with books. If you should have any questions, call Alfredo or Mike.								
Alfredo Holguin									
62250		Classroom			8/10/2010		280		\$0.00
Medium	Work In Progress	Room # 17		8/10/2010 11:32:44 AM					
Nunez, Arturo	Replace some ceiling tiles. Walls need to be painted Remount bulletin board once painting is completed Door needs to be put in place.								
Luis Calleros									
62305	GYM (2009)	Gym			8/11/2010		279		\$0.00
Medium	Work In Progress	New Gym -		8/11/2010 10:23:33 AM					
Mijarez, Jaime	Need to hang up large posters in the new gym. See Coach Dotson								
Luis Calleros									
62331		Classroom			8/11/2010		279		\$0.00
Medium	Work In Progress	MR.		8/11/2010 1:16:10 PM					
Nunez, Arturo	I NEED OVERHEAD PROJECTOR SCREEN PUT BACK UP ON MY WALL. IT FELL DOWN IN APRIL AND HASN'T BEEN REINSTALLED YET.								
Marylou Jimenez									
62333					8/11/2010		279		\$0.00
Medium	Work In Progress	COACH		8/11/2010 1:21:00 PM					
Nunez, Arturo	AC IS NOT WORKING IN THE FOOTBALL COACHES OFFICE.								
Marylou Jimenez									
62577		Classroom			8/17/2010		273		\$0.00
Medium	Work In Progress	Room L3		8/17/2010 9:40:49 AM					
Nunez, Arturo	Need projector screen installed								
Luis Calleros									
62609	Main Building	Classroom			8/17/2010		273		\$0.00
Medium	Work In Progress	Room 12		8/17/2010 5:11:54 PM					
Prospero, Manuel	Refrigerated air unit not working in the "Career Lab". Ceiling tiles need to be replaced.								
Luis Calleros	8/23 - Route to Manuel asp Mike.								

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
62712		Classroom			8/19/2010		271		\$0.00
Medium	Work In Progress	Room L2			8/19/2010 5:04:49 PM				
Prospero, Manuel	Water leak in room L2. Ceiling tiles collapsed. Need to respond asap.		8/23 - Route to Manuel asp Mike.						
Luis Calleros									
62713		Gym			8/19/2010		271		\$0.00
Medium	Work In Progress	new gym area			8/19/2010 5:19:38 PM				
Prospero, Manuel	The ice machine in the new gym is not producing ice. Request fixing asap please, since our athletic trainer uses it daily to treat athletes.		8/23 - Route to Manuel asp Mike.						
Luis Calleros									
62775		Classroom			8/21/2010		269		\$0.00
Medium	Work In Progress	Room C2			8/21/2010 3:31:12 PM				
Nunez, Arturo	Request wood dividers be built for middle desk area. See Ms. Armida Vasquez		Tury, please ck on this, any ?'s call Mike.						
Luis Calleros									
62789		Classroom			8/23/2010		267		\$0.00
Medium	Work In Progress	Room 5 Ms.			8/23/2010 9:56:24 AM				
Nunez, Arturo	Rm 5 -Need ceiling tiles and replace floor board trimmings that are missing.								
Luis Calleros									
62905		Classroom			8/25/2010		265		\$0.00
Medium	Work In Progress	cafeteria hallway			8/25/2010 10:29:39 AM				
Nunez, Arturo	Need to repair hole in the cafeteria hallway next to band room.								
Luis Calleros									
62909		Classroom			8/25/2010		265		\$0.00
Medium	Work In Progress	Room 15			8/25/2010 10:56:14 AM				
Prospero, Manuel	Install pencil sharpener								
Luis Calleros									
62943		Classroom			8/25/2010		265		\$0.00
Medium	Work In Progress	C 2			8/25/2010 5:23:41 PM				
Nunez, Arturo	Install a middle wooden divider between computers in middle island								
Luis Calleros									
62976		Classroom			8/26/2010		264		\$0.00
Medium	Work In Progress	Room 19			8/26/2010 10:20:43 AM				
Nunez, Arturo	A/C blowing hot air.								
Luis Calleros									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
63054					8/27/2010		263		\$0.00
Medium	Work In Progress	Counseling		8/27/2010 12:57:45 PM					
Nunez, Arturo	Replace water damaged ceiling tiles								
<u>Luis Calleros</u>									
63203					8/30/2010		1		\$0.00
Medium	Work In Progress	Room 20 See		8/30/2010 4:29:24 PM	8/31/2010				
Nunez, Arturo	Need to replace three vent covers that are missing for the air conditioning ducts. The air is blowing directly on the students.								
<u>Luis Calleros</u>									
63204					8/30/2010		260		\$0.00
Medium	Work In Progress	Room 20 See		8/30/2010 4:33:07 PM					
Nunez, Arturo	Replace the handles on the cabinets in the room. 3rd requests (Jan, March) The handles are with the teacher. We need the screws.								
<u>Luis Calleros</u>									
63224					8/31/2010		259		\$0.00
Medium	Work In Progress	Vocational T-		8/31/2010 8:54:30 AM					
Nunez, Arturo	1 .Broken outlet needs to be replaced/repaired								
<u>Luis Calleros</u>									
63226					8/31/2010		259		\$0.00
Medium	Work In Progress	Vocational T-		8/31/2010 10:15:02 AM					
Prospero, Manuel	Table saw needs to be repaired								
<u>Luis Calleros</u>									
63229					8/31/2010		259		\$0.00
Medium	Work In Progress	Restroom (Boys)		8/31/2010 11:49:08 AM					
Prospero, Manuel	Boys restroom near counselors office has white paint spots that need to be painted black. The frames in the administrative areas need to be touched up.								
<u>Luis Calleros</u>									
63366					9/2/2010		257		\$0.00
Medium	Work In Progress	L 3 See Mrs.		9/2/2010 2:50:19 PM					
Nunez, Arturo	A/C is blowing hot air								
<u>Luis Calleros</u>									
63438					9/5/2010		254		\$0.00
Medium	Work In Progress			9/5/2010 12:41:44 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
63439					9/5/2010	9/8/2010	254		\$0.00
Medium	Work In Progress			9/5/2010 12:41:45 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
63440					9/5/2010	9/11/2010	254		\$0.00
Medium	Work In Progress			9/5/2010 12:41:45 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
63745					9/10/2010		249		\$0.00
Medium	Work In Progress	Room 307		9/10/2010 12:08:12 PM					
Nunez, Arturo	Need to have new projector mounted on wall								
<u>Luis Calleros</u>									
64286					9/22/2010		237		\$0.00
Medium	Work In Progress	Room 16		9/22/2010 5:00:22 PM					
Nunez, Arturo	Need to have bulletin boards attached to the wall. Boards are loose. Need and additional board.								
<u>Luis Calleros</u>									
64298					9/23/2010		236		\$0.00
Medium	Work In Progress	Room 22		9/23/2010 11:11:13 AM					
Nunez, Arturo	Ceiling tiles: 8 tiles are out of place and need to be properly set.								
<u>Luis Calleros</u>									
64574					9/30/2010		229		\$0.00
Medium	Work In Progress			9/30/2010 12:24:00 AM					
Prospero, Manuel	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64713					10/3/2010	10/9/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:26:48 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64714					10/3/2010	10/11/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:26:49 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
64715					10/3/2010	10/6/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:26:49 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64716					10/3/2010	10/24/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:26:50 AM					
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64717					10/3/2010	11/3/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:26:50 AM					
Nunez, Arturo	Yearly - Santa Teresa HS H-6 Rftop Furn Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64718					10/3/2010	11/3/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:26:50 AM					
Nunez, Arturo	Yearly - Santa Teresa HS R-9 Radiator Ht Wtr 2yr - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64719					10/3/2010		226		\$0.00
Medium	Work In Progress			10/3/2010 12:26:51 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64720					10/3/2010	10/19/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:26:51 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64744					10/3/2010	10/24/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:27:00 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64865					10/3/2010	11/3/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:27:48 AM					
Prospero, Manuel	Yearly - Santa Teresa HS I-4 Fan Coil Unit Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
64866					10/3/2010	10/24/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:27:48 AM					
Prospero, Manuel	Monthly - Santa Teresa HS C-12 Chm Feeder Semimntly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64868					10/3/2010	10/11/2010	226		\$0.00
Medium	Work In Progress			10/3/2010 12:27:49 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
64967					10/5/2010		224		\$0.00
Medium	Work In Progress			10/5/2010 2:39:03 PM					
Nunez, Arturo	PLAYGROUND AREA NEXT TO DAYCARE, WATER LEAK, SOUTH END ON BUILDING / STORAGE AREA								
<u>Michael Munoz</u>									
65127					10/7/2010		222		\$0.00
Medium	Work In Progress	Football		10/7/2010 4:52:21 PM					
Nunez, Arturo	Water backed up in football coaches office								
<u>Luis Calleros</u>									
65163					10/10/2010	10/26/2010	219		\$0.00
Medium	Work In Progress			10/10/2010 12:23:11					
Nunez, Arturo	Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
65282					10/12/2010		217		\$0.00
Medium	Work In Progress			10/12/2010 8:04:07 AM					
Villalobos, David	Urinal on restroom in vocational building, needs to be replaced it is broken.								
<u>Arturo Nunez</u>									
66063					10/31/2010		198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:11					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66064					10/31/2010	11/3/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:12					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Santa Teresa HS

66065 10/31/2010 11/6/2010 198 \$0.00  
 Medium Work In Progress 10/31/2010 12:36:12

Nunez, Arturo Monthly - Santa Teresa HS Monthly FE Inspection -  
 Refer to PM schedule details.

Margret Villalobos

66095 10/31/2010 11/21/2010 198 \$0.00  
 Medium Work In Progress 10/31/2010 12:36:26

Orozco, Danny Monthly - Santa Teresa HS Fire Suppression Insp. -  
 Refer to PM schedule details.

Margret Villalobos

66485 Main Building Restroom (Girls) 11/9/2010 189 \$0.00  
 Medium Work In Progress 11/9/2010 9:37:52 AM

Nunez, Arturo NEW JUMBO BATHROOM DISPENSERS NEED TO  
 BE INSTALL IN THE MENS AND LADYS BATHROOMS  
 BY ANNAS OFFICE THANK YOU.

Luis Murillo

66535 11/10/2010 188 \$0.00  
 Medium Work In Progress 11/10/2010 8:54:55 AM

Villalobos, David NEED TO HAVE GAS SHUT VALVE, OFF FOR  
 ANNEX HEATERS RELOCATED FROM ROOF, TO  
 WALL. EASY EXCESS IN CASE OF AN EMERGENCY.

Arturo Nunez

66586 11/14/2010 184 \$0.00  
 Medium Work In Progress 11/14/2010 12:24:37

Nunez, Arturo Monthly - Santa Teresa HS - Grease Trap (Monthly) -  
 Refer to PM schedule details.

Margret Villalobos

66747 Vocational 11/17/2010 181 \$0.00  
 Medium Work In Progress T - 300 11/17/2010 9:44:51 AM

Nunez, Arturo Heater not working

Luis Calleros

66846 11/19/2010 179 \$0.00  
 Medium Work In Progress 11/19/2010 11:51:35

Nunez, Arturo NEED TO HAVE SPRINKLERS ON SOFTBALL FIELD  
 CHECKED SOME ARE MISSING HEADS WATER  
 JUST SHOOTING UP INTO THE AIR. GOT A CALL  
 FROM MR. CALLERO ON 11/19/10 AT 9.00P.M TO  
 COME AND CHECK OUT SITUATION. WRONG INFO.  
 WAS GIVEN TO ME. THE INFO. I GOT WAS THAT, AN  
 A.C. LINE WAS BUSTED, AFTER CHECKING  
 SITUATION, IT CAME OU TO BE A B MISSING  
 SPRINKLER HEAD.

Arturo Nunez

5/17/2011 12:10:29 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
66898					11/29/2010		169		\$0.00
Medium	Work In Progress				11/29/2010 11:03:37				
Villalobos, David	NEED SOME ASSITANCE ON WATER HEATER IN CAFETERIA, WATER COIL SEEMS TO BE BUSTED ,LEAKING WATER								
<u>Arturo Nunez</u>									
67007	Main Building	Hallway/Corridor			12/1/2010		167		\$0.00
Medium	Work In Progress	Hallway by			12/1/2010 8:20:16 AM				
Nunez, Arturo	Please check bad odor that is coming out of the main hallway by the science, math and counseling wing. It has been smelling really bad for the last 2 days.					Leadership Request			
<u>Peggy Jo Hernandez</u>									
67126					12/3/2010		165		\$0.00
Medium	Work In Progress				12/3/2010 8:59:20 AM				
Nunez, Arturo	Hole in wall on warroir room in caferteria needs to be repaired, due to Vandalism								
<u>Arturo Nunez</u>									
67165					12/5/2010	12/8/2010	163		\$0.00
Medium	Work In Progress				12/5/2010 12:26:47 AM				
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67166					12/5/2010		163		\$0.00
Medium	Work In Progress				12/5/2010 12:26:48 AM				
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67167					12/5/2010	12/11/2010	163		\$0.00
Medium	Work In Progress				12/5/2010 12:26:48 AM				
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67376					12/7/2010		161		\$0.00
Medium	Work In Progress	Girls locker			12/7/2010 5:40:09 PM				
Villalobos, David	Clogged toilet in girls locker room, athletic side, middle one								
<u>Luis Calleros</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
67479					12/10/2010		158		\$0.00
Medium	Work In Progress	Attendance		12/10/2010 2:10:50 PM					
Prospero, Manuel		Paint old cabinets in attendance office the same color as the newly insatlled cabinets. Please match the same counter top as the new ones installed.							
<u>Luis Calleros</u>									
67524					12/12/2010	12/28/2010	156		\$0.00
Medium	Work In Progress			12/12/2010 12:25:23					
Prospero, Manuel		Monthly - Santa Teresa HS Playground Insp - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
67631	Main Building	Restroom (Girls)			12/15/2010		153		\$0.00
Medium	Work In Progress			12/15/2010 7:54:45 AM					
Villalobos, David		12/15/10. WE NEED TO REPLACE ALL LAVATORY FAUCETS ON MAIN ENTRANCE GIRLS RESTROOMS.							
<u>Manuel Prospero</u>									
67638	Cafeteria (2005)	Cafeteria			12/15/2010		153		\$0.00
Medium	Work In Progress			12/15/2010 8:17:54 AM					
Nunez, Arturo		no gas to cafeteria.Please check .thank you							
<u>Michael Munoz</u>									
67651					12/15/2010		153		\$0.00
Medium	Work In Progress	new restrooms		12/15/2010 11:15:06					
Lara, Ralph		Need to install lock / key to be able to lock the new restrooms by the math wing.							
<u>Luis Calleros</u>									
67797					1/2/2011		135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:26 AM					
Nunez, Arturo		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
67798					1/2/2011	1/5/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:27 AM					
Nunez, Arturo		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
67799					1/2/2011	1/8/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:28 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
67800					1/2/2011	1/10/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:28 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67832					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:42 AM					
Villalobos, David	Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67841					1/2/2011	1/23/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:46 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67906					1/2/2011	1/10/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:29:21 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67907					1/2/2011	1/10/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:29:21 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67908					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:29:22 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67958					1/4/2011		133		\$0.00
Medium	Work In Progress	Old Gym		1/4/2011 1:25:13 PM					
Murillo, Luis	Lights in old gym need to be replaced. There are about 4-5 lights out.								
<u>Luis Calleros</u>									
67960					1/4/2011		133		\$0.00
Medium	Work In Progress	Vocational		1/4/2011 1:33:14 PM					
Nunez, Arturo	Service air compressor								
<u>Luis Calleros</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
67985					1/5/2011		132		\$0.00
Medium	Work In Progress			1/5/2011 3:55:07 PM					
Nunez, Arturo		NEED TO REPAIR WATER LEAK FOR PORTABLE BUILDINGS, NEAR DAY CARE PLAY GROUND.							
<u>Arturo Nunez</u>									
68115		Classroom			1/8/2011		129		\$0.00
Medium	Work In Progress	Room 307		1/8/2011 1:09:58 PM					
Nunez, Arturo		Exhaust fan does not work. See Mrs. Ochoa							
<u>Luis Calleros</u>									
68149					1/9/2011	1/25/2011	128		\$0.00
Medium	Work In Progress			1/9/2011 12:25:29 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Playground Insp - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
68169					1/10/2011		127		\$0.00
Medium	Work In Progress	Hallway by		1/10/2011 10:42:16 AM					
Prospero, Manuel		Hallway by the old gym needs to be painted							
<u>Luis Calleros</u>									
68240					1/11/2011		126		\$0.00
Medium	Work In Progress	Room 208		1/11/2011 1:51:27 PM					
Nunez, Arturo		Venatlation blinds are broken and need to be replaced. See Mr. Gannon							
<u>Luis Calleros</u>									
68340		Library			1/13/2011		124		\$0.00
Medium	Work In Progress	MARY		1/13/2011 11:20:13 AM					
Nunez, Arturo		ART NUNEZ-PLEASE MOUNT SIMULATED SECURITY CAMERAS (3) IN LIBRARY: ONE IN BACK OF LIBRARY; ONE IN REFERENCE ROOM; AND ONE IN COMPUTER LAB.							
<u>Marylou Jimenez</u>									
68342					1/13/2011		124		\$0.00
Medium	Work In Progress			1/13/2011 12:37:41 PM					
Nunez, Arturo		NEED TO HAVE WALL ON SOFTBALL FIELD PAINTED TO COVER UP GRAFFITI,							
<u>Arturo Nunez</u>									
68363		Classroom			1/13/2011		124		\$0.00
Medium	Work In Progress	MRS.		1/13/2011 3:37:40 PM					
Nunez, Arturo		ART NUNEZ OR MANNY PROSPERO-I NEED A CART ASSEMBLED FOR MY "ELMO".							
<u>Marylou Jimenez</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
68472					1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 3:52:28 PM					
Flores, Pete	NEED TO HAVE GAS PEDAL ON VECHILE #70 REPLACED, LINKAGE IS BROKEN FROM GAS PEDAL								
<u>Arturo Nunez</u>									
68485	Cafeteria (2005)	Custodial			1/18/2011		119		\$0.00
Medium	Work In Progress			1/18/2011 10:53:30 AM					
Villalobos, David	need work done on irrigation backflow preventer constantly leaking								
<u>David Villalobos</u>									
68511					1/13/2011		124		\$0.00
Medium	Work In Progress			1/18/2011 3:50:38 PM					
Nunez, Arturo	Graffiti on softball field wall. (Case# 11-00359) R. Tellez								
<u>Luis Calleros</u>									
68541		Classroom			1/19/2011		118		\$0.00
Medium	Work In Progress	MRS.		1/19/2011 11:09:06 AM					
Nunez, Arturo	ART NUNEZ-PLEASE INSTALL TV IN ROOM #300								
<u>Marylou Jimenez</u>									
68542					1/19/2011		118		\$0.00
Medium	Work In Progress	MARYLOU		1/19/2011 11:10:36 AM					
Nunez, Arturo	ART NUNEZ-PLEASE INSTALL 2 BOARDS 1-ON WALL NEXT TO PRINCIPALS OFFICE 1-TEACHERS LOUNGE PLEASE SEE ME TO GIVE INSTRUCTIONS WHICH WALL TO BE MOUNTED.								
<u>Marylou Jimenez</u>									
68573					1/19/2011		118		\$0.00
Medium	Work In Progress			1/19/2011 3:44:25 PM					
Lara, Ralph	NEED GATE KEY FOR EL PASO DISPOSAL AS PER MIKE/ALFREDO. OLD KEY TO BE TURNED IN WHEN THIS ONE IS PICKED UP								
<u>Michael Munoz</u>									
68664					1/21/2011		116		\$0.00
Medium	Work In Progress			1/21/2011 3:44:10 PM					
Nunez, Arturo	Need 20 - 25 light bulbs in welding classroom / office. See Mr. Angelo								
Luis Calleros									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location:</b>		<b>Santa Teresa HS</b>								
68916					1/31/2011		106		\$0.00	
Medium	Work In Progress			1/31/2011 8:04:26 AM						
Nunez, Arturo		NEED A 4L 380 FAN BELT FOR A.H.U. FOR COMPUTER LAB # 4 .,								
<u>Arturo Nunez</u>										
68968					2/1/2011		105		\$0.00	
Medium	Work In Progress	West side of		2/1/2011 8:33:52 AM						
Villalobos, David		Need Utility Line Locate on the west side of Annex Bldg. - width of building to sidewalk. Please mark on Monday 2/7/11. If you have any questions, please contact Mr. Ralph Gallegos at 882-6921 or (575) 650-9095 / cell.								
<u>Peggy Jo Hernandez</u>										
68971					2/1/2011		105		\$0.00	
Medium	Work In Progress	New Boy's		2/1/2011 9:15:00 AM						
Nunez, Arturo		Basketball: New Boy's Locker Room: Replace bench seat on to the support. Has been repaired before at least twice.				3/9 - Asp Mike, route to Art.				
<u>Luis Calleros</u>										
69015					2/6/2011	2/12/2011	100		\$0.00	
Medium	Work In Progress			2/6/2011 12:33:31 AM						
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
69016					2/6/2011		100		\$0.00	
Medium	Work In Progress			2/6/2011 12:33:31 AM						
Nunez, Arturo		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
69017					2/6/2011	2/9/2011	100		\$0.00	
Medium	Work In Progress			2/6/2011 12:33:32 AM						
Nunez, Arturo		Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>										
69153					2/7/2011		99		\$0.00	
Medium	Work In Progress	Annex Bldg.		2/7/2011 3:27:48 PM						
Villalobos, David		Need line locate - North & South Sides of Annex Bldg. all the way to Chiller. If you have any questions, please call Mr. Ralph Gallegos (575) 650-9095								
<u>Peggy Jo Hernandez</u>										



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
69742					2/21/2011		85		\$0.00
Medium	Work In Progress	Baseball Field		2/21/2011 1:20:35 PM					
Valdez, Pedro	Back Stop, 3rd base, and behind home plate: By 3rd base the fence has been cut. A board has been temporarily placed, but a player can get hurt if he runs into the board or hole while trying to catch a ball. The fence will come apart. A player can be seriously hurt if he slides inot the fence that is sticking up.								
Luis Calleros									
69758					2/22/2011		84		\$0.00
Medium	Work In Progress			2/22/2011 10:18:43 AM					
Ronquillo, Ruben	GLAAS ON DOOR AT DRESSING ROOM EAST ENTRANCE NEEDS TO BE REPLACED, MEASUREMENTS ARE , 25 1/4 X 36 1/4 SAFETY WIRE MESH. 1 EA.								
Arturo Nunez									
69761					2/22/2011		84		\$0.00
Medium	Work In Progress			2/22/2011 10:27:07 AM					
Villalobos, David	NEED TO HAVE BACK FLOW RISER FOR IRRIGATION, CHECKED LEAKING WATER THROUGH VENT RELIEF,								
Arturo Nunez									
69786	Concession	Football Field			2/22/2011		21	47	\$1,341.00
Medium	Work In Progress			2/22/2011 3:34:03 PM	3/15/2011				
Villalobos, David	WE HAVE WATER LEAK ON CONSESSION STAND BOYS RESTROOM WALL.					Work Still Pending Worked on broken water lines from freeze in cinder bolkd, sheetrock, fiberglass capped off lines got water going in concession stand.			
Manuel Prospero									
69788	Annex Building	Mechanical			2/22/2011		3	3	\$125.00
Medium	Work In Progress			2/22/2011 3:36:47 PM	2/25/2011				
Villalobos, David	WE HAVE A WATER LEAK ON WATER HEATER ( OLD R.O.T.C.).					Work still pending need to replace cutoff flex connectors			
Manuel Prospero									
69794					2/22/2011		3	11	\$475.00
Medium	Work In Progress			2/22/2011 3:44:55 PM	2/25/2011				
Villalobos, David	WE AHVE A BIG WATER LEAK ON ANNEX BUILDING ( OLD KITCHEN) IN TE WALL.					Work still pending seek where water leaking from will have to reroute most lines.			
Manuel Prospero									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
69851					2/23/2011		83		\$0.00
Safety	Work In Progress	Room 16		2/23/2011 4:37:52 PM					
Nunez, Arturo	2nd request. Secure / hang a white objective board. Safety issue as it might fall on students. and very important before the TAV visit.								
<u>Luis Calleros</u>									
69852					2/23/2011		83		\$0.00
Medium	Work In Progress	Room 16		2/23/2011 4:39:48 PM					
Nunez, Arturo	Need to acquire bulletin board from storage and attach in room 16.								
<u>Luis Calleros</u>									
69960					2/26/2011		80		\$0.00
Medium	Work In Progress	Wall [panel next		2/26/2011 11:02:23 AM					
Nunez, Arturo	There is a hole the size of a big fist, and getting bigger, on the wall next to the band room. Maintenance attempted to fix on a separate occassion. However, the material used to cover the hole, keeps on falling out. Suggest replacing the entire panel. The problem needs to be properly addressed.								
<u>Luis Calleros</u>									
70027					3/1/2011		77		\$0.00
Medium	Work In Progress	Room 301		3/1/2011 7:51:00 AM					
Nunez, Arturo	Teacher needs an overhead projector screen hung up in room 301. Screen is in portable #2, which will have to be moved from the portable to room 301.								
<u>Luis Calleros</u>									
70033					3/1/2011		77		\$0.00
Medium	Work In Progress	Baseball		3/1/2011 8:18:52 AM					
Castillo, Carlos	Need to have electricity to the baseball concession stand. Request work done asap please since the season has already started and the concession stand is needed.								
<u>Luis Calleros</u>									
70148					3/3/2011		75		\$0.00
Medium	Work In Progress	Science Room		3/3/2011 12:15:58 PM					
Nunez, Arturo	Asp Mr. Gallegos this needs to be check by the maintence its not something the contractor did. Please ck on the exhaust fan in Ms. Stevens' Science classroom is not working. Please coordinate with teacher.								
Peggy Jo Hernandez									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
70220					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:28 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70221					3/6/2011	3/9/2011	72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:29 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70222					3/6/2011	3/12/2011	72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:29 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70256					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:46 AM					
Orozco, Danny	Yearly - Santa Teresa HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70334					3/6/2011	4/6/2011	72		\$0.00
Medium	Work In Progress			3/6/2011 12:18:25 AM					
Prospero, Manuel	Yearly - Santa Teresa HS A-10 HP Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70557					3/9/2011		69		\$0.00
Medium	Work In Progress			3/9/2011 3:48:00 PM					
Nunez, Arturo	NEED TO HAVE MAIN GATE VALVE FOR FIRE SPRINKLER SYSTEM ON VOCATIOAL BUILDING CHECKED, AND REPAIRED, LEAKING WATER PRETTY BAD.								
<u>Arturo Nunez</u>									
70679					3/11/2011		67		\$0.00
Medium	Work In Progress			3/11/2011 3:16:35 PM					
Munoz, Michael	Need to install two gates by old gym area. One gate would be installed immediately by one of the dressing rooms and the other needs to be installed next to the old gym.								
<u>Luis Calleros</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
70713					3/13/2011		65		\$0.00
Medium	Work In Progress	New gym area		3/13/2011 3:54:05 PM					
Lara, Ralph	Would like to chagne the locks to the new gym entry and exit area. See Mr.Calleros.								
Luis Calleros									
70927					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 1:28:37 PM					
Ambriz, Jose	HEATERS ON CLASS ROOM # 807, NEED TO BE REPLACED, CLASSROOM CRPB 175, OFFICE CRPB 125.								
Arturo Nunez									
70928					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 1:31:13 PM					
Ambriz, Jose	HEATERS ON CLASSROOM # 805 NEED TO BE REPLACED, CLASSROOM CRPB 175, OFFICE CRPB 125.								
Arturo Nunez									
70929					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 1:34:22 PM					
Ambriz, Jose	HEATERS ON CLASSROOM # 803 NEED TO BE REPLACED CLASSROOM CRPB 300, OFFICE CRPB 125.								
Arturo Nunez									
70930					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 1:36:05 PM					
Ambriz, Jose	HEATERS ON CLASSROOM # 801 NEED TO BE REPLACED, CLASSROOM CRPB 175, OFFICE CRPB 125.								
Arturo Nunez									
70935					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:23:33 PM					
Ambriz, Jose	CLASSROOM # 507 A.C. NEEDS TO BE REPLACED, 6500 C.F.M. S.D.								
Arturo Nunez									
70937					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:24:57 PM					
Ambriz, Jose	CLASSROOM # 509 NEED TO REPLACE A.C. UNIT, 6500 C.F.M. S.D.								
Arturo Nunez									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
70938					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:26:15 PM					
Ambriz, Jose	CLASSROOM # 504 A.C. UNIT NEEDS TO BE REPLACED 6500 C.F.M. S.D.								
Arturo Nunez									
70939					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:31:48 PM					
Ambriz, Jose	A.C. UNIT ON COUNSELORS OFFICE NEED TO BE REPLACED. TWO AIR FLOW ENTRY, D.D.								
Arturo Nunez									
70940					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:33:45 PM					
Ambriz, Jose	NEED TO REPLACE A.C. UNIT ON ROOM # 501, 6500 C.F.M. S.D.								
Arturo Nunez									
70941					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:35:41 PM					
Ambriz, Jose	A.C. ON CLASSROOM # 400 NEEDS TO BE REPLACED, 6500 C.F.M. S.D.								
Arturo Nunez									
70942					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:39:04 PM					
Ambriz, Jose	A.C. ON CLASSROOM # 403 NEEDS TO BE REPLACED, 6500 C.F.M. S.D.								
Arturo Nunez									
70943					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:41:21 PM					
Ambriz, Jose	A.C. ON CLASSROOM # 404 NEEDS TO BE REPLACED 6500 C.F.M. S.D.								
Arturo Nunez									
70944					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:42:48 PM					
Ambriz, Jose	A.C. ON ATTENDENCE OFFICE NEEDS TO BE REPLACED, 6500 C.F.M. D.D.								
Arturo Nunez									
70945					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:44:27 PM					
Ambriz, Jose	A.C. ON CLASSROOM # 612, NEEDS TO BE REPLACED 6500 C.F.M. D.D.								
Arturo Nunez									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
70946					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:46:25 PM					
Ambriz, Jose	A.C. INCLASSROOM # 616, NEEDS TO BE REPLACED 6500 C.F.M. D.D.								
<u>Arturo Nunez</u>									
70948					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:48:16 PM					
Ambriz, Jose	A.C. ON CLASSROOM # 300 , NEEDS TO BE REPLACED 6500C.F.M. D.D.								
<u>Arturo Nunez</u>									
70949					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:51:45 PM					
Ambriz, Jose	A.C. ON ROOM # 302 NEEDS TO BE REPLACED , 6500 C.F.M. D.D.								
<u>Arturo Nunez</u>									
70950					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:53:36 PM					
Ambriz, Jose	A.C. ONCLASSROOM # 303 NEEDS TO BE REPLACED. 6500 C.F.M. D.D.								
<u>Arturo Nunez</u>									
70951					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 2:57:46 PM					
Ambriz, Jose	A.C. UNIT ON CLASSROOM # 614 NEEDS TO BE REPLACED 6500 C.F.M. D.D.								
<u>Arturo Nunez</u>									
71200					3/29/2011		49		\$0.00
Medium	Work In Progress	Locker Room		3/29/2011 10:13:12 AM					
Prospero, Manuel	Broken faucet on athletic side. Once faucet is turned on, the water will not shut off for about an hopur. See Coach Francis.								
<u>Luis Calleros</u>									
71243					3/30/2011		48		\$0.00
Medium	Work In Progress			3/30/2011 11:48:34 AM					
Nunez, Arturo	AS PER MR. RALPH GALLEGOS, CEILING TILES NEED TO BE REPLACED IN OFFICE ARE AND MATH WING BETWEEN ROOM # 8 & 9.								
<u>Marylou Jimenez</u>									
71247	GYM (2009)	Custodial			3/30/2011		48		\$0.00
Medium	Work In Progress			3/30/2011 1:03:44 PM					
Carbajal, Jimmy	The court clean at this site is pulled by two jump ropes. We need to replace the rope on it.								
<u>Jesus Estrada</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
71288					3/31/2011		47		\$0.00
Medium	Work In Progress			3/31/2011 12:17:34 AM					
Prospero, Manuel	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71384					4/1/2011		46		\$0.00
Medium	Work In Progress	Turf Field		4/1/2011 4:54:46 PM					
Valdez, Pedro	Please re-distribute the black rubber pellets on the Turf field								
<u>Luis Calleros</u>									
71402					4/3/2011		44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:37 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71403					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:38 AM					
Nunez, Arturo	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71404					4/3/2011	4/6/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:38 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71405					4/3/2011	4/9/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:39 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71406					4/3/2011	4/11/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:39 AM					
Nunez, Arturo	Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71407					4/3/2011	4/19/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:40 AM					
Nunez, Arturo	Monthly - Santa Teresa HS A-1 Wall Ref Unit (SM) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
71427					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:50 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71441					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:56 AM					
Orozco, Danny	Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71529					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:35 AM					
Prospero, Manuel	Monthly - Santa Teresa HS C-12 Chm Feeder Semimntly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71530					4/3/2011	5/4/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:35 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71531					4/3/2011	4/11/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:36 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71680	Main Building	Restroom (Boys)			4/5/2011		42		\$0.00
Medium	Work In Progress			4/5/2011 3:43:55 PM					
Villalobos, David	WE NEED SOME ASSINSTING. ON CLOGGED UNRINAL BOYS BATRROMS 300;S WENG.								
<u>Manuel Prospero</u>									
71722	Main Building	Classroom			4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 12:45:11 PM					
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 304, IS ON BAD CONDITION.								
<u>Manuel Prospero</u>									
71723	Main Building	Classroom			4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 12:46:47 PM					
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 306 IS ON BAD CONDITION.								
<u>Manuel Prospero</u>									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
71724	Main Building	Classroom			4/6/2011		41		\$0.00
Medium	Work In Progress				4/6/2011 12:48:17 PM				
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 308 IS ON BAD CONDITONE.								
<u>Manuel Prospero</u>									
71725	Main Building	Classroom			4/6/2011		41		\$0.00
Medium	Work In Progress				4/6/2011 12:50:32 PM				
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 301 6500 CFM MC DOUN DRAFT.								
<u>Manuel Prospero</u>									
71726	Main Building	Classroom			4/6/2011		41		\$0.00
Medium	Work In Progress				4/6/2011 12:52:35 PM				
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 305 6500 CFM MC DOUN DRAFT								
<u>Manuel Prospero</u>									
71728	Main Building	Classroom			4/6/2011		41		\$0.00
Medium	Work In Progress				4/6/2011 12:56:40 PM				
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 307 6500 CFM MC DOUN DRAFT.								
<u>Manuel Prospero</u>									
71730		Classroom			4/6/2011		41		\$0.00
Medium	Work In Progress				4/6/2011 12:58:23 PM				
Ambriz, Jose	WE NEED TO REPLACE A/C ON ROOM 309 6500 CFM MC DOUN DRAFT.								
<u>Manuel Prospero</u>									
71773	Concession	Gym			4/7/2011		40		\$0.00
Medium	Work In Progress				4/7/2011 8:47:07 AM				
Villalobos, David	WE NEED ASSISTIN FOR FIX WATER FOUNTAIN ON CONCESSION STAND OUT SIDE ON GYM.								
<u>Manuel Prospero</u>									
71774	Main Building	Restroom (Boys)			4/7/2011		40		\$0.00
Medium	Work In Progress				4/7/2011 8:50:03 AM				
Villalobos, David	WE NEED SOME ASSISTIN TO UNCLOGG URINAL ON 300; BOYS RESTROOMS.								
<u>Manuel Prospero</u>									
71835		Athletic Field			4/8/2011		39		\$0.00
Medium	Work In Progress				4/8/2011 1:02:18 PM				
Flores, Pete	truck #17 needs oil and filter changed, also sparkplugs.								
<u>Guadalupe Ontiveros</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
71877					4/10/2011	4/26/2011	37		\$0.00
Medium	Work In Progress			4/10/2011 12:14:22 AM					
Nunez, Arturo		Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
71903					4/10/2011	4/26/2011	37		\$0.00
Medium	Work In Progress			4/10/2011 12:14:35 AM					
Meraz, Rafael		Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.							
<u>Jesus Estrada</u>									
71922	Main Building				4/11/2011		36		\$0.00
Medium	Work In Progress	Restroom 530		4/11/2011 8:23:59 AM					
Ambriz, Jose		Install new exhaust fan in Restroom 530 (ISS Restroom).							
<u>Peggy Jo Hernandez</u>									
71951					4/11/2011		36		\$0.00
Medium	Work In Progress	Leadership		4/11/2011 11:13:03 AM					
Prospero, Manuel		Science Room 508 - Need to secure all table tops to base. (Needs to be completed before May 20th)				Leadership Request			
<u>Alfredo Holguin</u>									
72030					4/12/2011		35		\$0.00
Medium	Work In Progress	MARY		4/12/2011 4:46:44 PM					
Lara, Ralph		FRONT DOOR STICKS OPEN-HAVE DIFFICULTY KEEPING IT LOCKED WHEN NECESSARY.							
<u>Marylou Jimenez</u>									
72251					4/19/2011		28		\$0.00
Medium	Work In Progress			4/19/2011 3:29:26 PM					
Villalobos, David		NEED SOME ASSITANCE ON KITCHEN RAYPACK WATER HEATER, HOT WATER COILS ARE BUSTED.							
<u>Arturo Nunez</u>									
72343		Library			4/21/2011		26		\$0.00
Medium	Work In Progress	MARY		4/21/2011 11:54:31 AM					
Nunez, Arturo		AV CART CAME APART NEEDS A SCREW							
<u>Marylou Jimenez</u>									
72451					4/27/2011		20		\$0.00
Medium	Work In Progress	Track		4/27/2011 8:35:57 AM					
Valdez, Pedro		District Track Meet on May 7, 2011 at STHS: Track Surface needs to be cleaned / blown clean Mark shot put, discus, and the javelin area. Add sand to the long jump box Long jump surface needs to be re-surfaced							
<u>Luis Calleros</u>									
5/17/2011 12:10:29 PM									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
72462					4/27/2011		20		\$0.00
Medium	Work In Progress	Boys Restroom		4/27/2011 10:41:31 AM					
Nunez, Arturo		Panel in boys restroom in the main hallway needs to be painted or replaced							
Luis Calleros									
72488					4/27/2011		20		\$0.00
Medium	Work In Progress			4/27/2011 3:39:55 PM					
Prospero, Manuel		4/27/11. 1HR WO 72462. 7HRS WO 72461.				4/27 - See wo above			
Manuel Prospero									
72537					4/28/2011		19		\$0.00
Medium	Work In Progress			4/28/2011 3:51:07 PM					
Villalobos, David		Need some assistance on kitchen water heater ,hot water storage tank letting out to much line and scale, and clogging cir. pump.							
Arturo Nunez									
72559					4/29/2011		18		\$0.00
Medium	Work In Progress	Culinary Arts		4/29/2011 10:58:21 AM					
Ambriz, Juan		Attention Mike Munoz: As per our conversation, need to haul away much broken furniture. Need to move the furniture in the old culinary arts room / area as it is about ready to be renovated. Work needs to be completed by 5-6-2011.				Attention Mike Munoz			
Luis Calleros									
72570		Restroom (Boys)			4/29/2011		18		\$0.00
Medium	Work In Progress			4/29/2011 3:02:14 PM					
Lara, Ralph		NEED FOR YOU TO REKEY TO CORE CYLLINDER IN THE ROTC RESTROOMS .							
Manuel Prospero									
72592					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:50 AM					
Nunez, Arturo		Yearly - Santa Teresa HS C-11 Evap Coolers Yearly - Refer to PM schedule details.							
Margret Villalobos									
72621					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:45 AM					
Nunez, Arturo		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
72622					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:46 AM					
Nunez, Arturo	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72623					5/1/2011	5/4/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:46 AM					
Nunez, Arturo	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72653					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:03 AM					
Orozco, Danny	Monthly - Santa Teresa HS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72712					5/1/2011	6/1/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:32 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72713					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:33 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72714					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:33 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72767	Annex Building	Portables			5/2/2011		15		\$0.00
Medium	Work In Progress			5/2/2011 11:05:56 AM					
Villalobos, David	waterheater leak								
<u>Rafael Meraz</u>									
72793					5/2/2011		15		\$0.00
Medium	Work In Progress	Vocational area		5/2/2011 4:43:43 PM					
Lara, Ralph	The locks / doorhandles do not lock on the doors facing the desert in the vocational rooms. Presently each door is secured by using a chain. The chains cannot be used due to a safety issue for evacuation purposes.								
Luis Calleros									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Santa Teresa HS

72794					5/2/2011		15		\$0.00
Medium	Work In Progress	Voacational area		5/2/2011 4:47:37 PM					
Lara, Ralph	Sorry this WO request goes along with WO#72793. The locks / doorhandles need to be replaced so that the chains can be removed from the doors.								

Luis Calleros

72875					5/4/2011		13		\$0.00
Medium	Work In Progress	Guard Shack		5/4/2011 12:52:04 PM					
Nunez, Arturo	Please service the A/C in the Guard Shack. Security officers are very hot								

Luis Calleros

72913					5/5/2011		12		\$0.00
Medium	Work In Progress	Counselor's		5/5/2011 8:30:56 AM					
Prospero, Manuel	2nd request: Need to remove ceiling tiles taht have gotten wet and look as if mold is starting to grow. See Art Corral.								

Luis Calleros

72942					5/5/2011		12		\$0.00
Medium	Work In Progress			5/5/2011 3:43:34 PM					
Castillo, Carlos	Power outlet needs to be replaced/repared. See Ms. Webber								

Luis Calleros

72943					5/5/2011		12		\$0.00
Medium	Work In Progress			5/5/2011 3:45:12 PM					
Nunez, Arturo	Drinkin fountain clogged in hallway next to Home Economics room and room 300, Mrs. Munoz classroom.								

Luis Calleros

73018					5/9/2011		8		\$0.00
Medium	Work In Progress			5/9/2011 11:47:16 AM					
Lara, Ralph	Door hinge falling down in Mrs. Munoz classroom.								

Luis Calleros

73025		Library			5/9/2011		8		\$0.00
Medium	Work In Progress	MARY ALBERT		5/9/2011 2:59:20 PM					
Prospero, Manuel	AV CART NEEDS A SCREW								

Marylou Jimenez

73031					5/9/2011		8		\$0.00
Medium	Work In Progress	L2		5/9/2011 3:17:19 PM					
Nunez, Arturo	Water leaking from ceiling tile in L2, Coach Camacho's room								

Luis Calleros

5/17/2011 12:10:29 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Santa Teresa HS

73052 5/10/2011 7 \$0.00

Medium Work In Progress 5/10/2011 8:00:38 AM

Prospero, Manuel A/C blowing hot air in Mr. Luis Villalobos classroom.  
Pump not working?

Luis Calleros

73053 5/10/2011 7 \$0.00

Medium Work In Progress Turf Field 5/10/2011 8:16:55 AM

Valdez, Pedro Much sand has accumulated on the NW corner of turf surface on turf field. The sand needs to be removed from the turf field.

Luis Calleros

73055 5/10/2011 7 \$0.00

Medium Work In Progress Turf field 5/10/2011 8:22:47 AM

Valdez, Pedro Turf Field: Re-distribute black rubber pellets in / around mid-field

Luis Calleros

73071 5/10/2011 7 \$0.00

Medium Work In Progress 5/10/2011 1:39:56 PM

Munoz, Michael Purchase and install new marquee Leadership Request

Alfredo Holguin

73100 5/11/2011 6 \$0.00

Medium Work In Progress 5/11/2011 7:57:57 AM

Lara, Ralph CYLINDERS NEED TO BE INSTALLED ON DEAD BOLTS THAT WERE INSTALLED ON REST ROOMS ON 400'S HALLWAY.

Arturo Nunez

73114 5/11/2011 6 \$0.00

Medium Work In Progress 5/11/2011 12:06:03 PM

Martinez, Larry Please deliver six (6) boxes to go to Santa Teresa High School

Tracey Swinford

73122 5/11/2011 6 \$0.00

Medium Work In Progress 5/11/2011 3:29:16 PM

Lara, Ralph Ralp Lara, need to change lock at new baseball consession stand.

Carlos Castillo

73132 5/11/2011 6 \$0.00

Medium Work In Progress 5/11/2011 4:00:58 PM

Orozco, Danny 2 OVENS ARE DOWN. SNP MANAGER OLGA B.589.5332

Maritza Gonzalez

5/17/2011 12:10:29 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa HS</b>							
73139					5/11/2011		6		\$0.00
Medium	Work In Progress	Tennis Courts		5/11/2011 4:36:05 PM					
Valdez, Pedro		The tennis courts need to be cleaned or swepted on a daily basis.							
Luis Calleros									
73151					5/12/2011		5		\$0.00
Medium	Work In Progress	Tennis Courts		5/12/2011 9:07:17 AM					
Valdez, Pedro		Replace Tennis nets on the three courts. The current posts are missing the cranks to raise or lower the height of nets.							
Luis Calleros									
73152					5/12/2011		5		\$0.00
Medium	Work In Progress	Tennis courts		5/12/2011 9:08:55 AM					
Valdez, Pedro		Replace /repair wind screens around the tennis courts							
Luis Calleros									
73153					5/12/2011		5		\$0.00
Medium	Work In Progress	Tennis Courts		5/12/2011 9:10:08 AM					
Valdez, Pedro		Repair the big cracks on the Tennis Courts							
Luis Calleros									
73161	Main Building				5/12/2011		5		\$0.00
Medium	Work In Progress			5/12/2011 1:06:44 PM					
Ambriz, Jose		WE NEED TO CHANGED A/C MOTOR ON ROOM 403 3/4 2 SPEED							
Manuel Prospero									
73162	Main Building	Classroom			5/12/2011		5		\$0.00
Medium	Work In Progress			5/12/2011 1:09:01 PM					
Ambriz, Jose		WE NEED TO CHANGED A/C MOTOR ON ROOM 707 3/4 2 SPEED							
Manuel Prospero									
73184					5/13/2011		4		\$0.00
Medium	Work In Progress			5/13/2011 7:43:34 AM					
Briones, Enrique		On May 17, 2011, please deliver 3 boxes to Santa Teresa High School. Reference P.O. # 101106722 and P.O. # 101106655.							
Yolie Jacquez									
73190					5/13/2011		4		\$0.00
Medium	Work In Progress	Outside Walls of		5/13/2011 8:20:12 AM					
Herrera, Joel		Remove graffitti outsidet side cafeteriaon the East side. the walls will need to be painted.							
Luis Calleros									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Santa Teresa HS</b>										
73235					5/16/2011		1		\$0.00	
Medium	Work In Progress				5/16/2011 9:24:06 AM					
Valdez, Pedro		Much trash on school parking needs to be picked up please.								
Luis Calleros										
73236					5/16/2011		1		\$0.00	
Medium	Work In Progress	Auxillary gym-			5/16/2011 9:27:03 AM					
Castillo, Carlos		Two light fixtures and blubs broken in Boys Locker Room of the Old Gym. They need to be repalced .								
Luis Calleros										
73238					5/16/2011		1		\$0.00	
Medium	Work In Progress	Girls Restroom -			5/16/2011 9:44:46 AM					
Villalobos, David		Girls restroom in the auxillary gym is clogged up. Water keeps on backing up from drain. Restroom recently remodeled.								
Luis Calleros										
<b>Count: 230 Work Orders</b>		<b>Avg. Age of WO's 120</b>		<b>Total for Santa Teresa HS</b>				<b>61</b>	<b>\$1,941.00</b>	



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
64597		Athletic Field			9/30/2010		229		\$0.00
Medium	Work In Progress			9/30/2010 11:02:20 AM					
Gonzalez, Salvador	SOCCER GOALS NEED TO BE WELDED AT BOTTOM AND TOP.								
<u>Guadalupe Ontiveros</u>									
65670					10/20/2010		209		\$0.00
Medium	Work In Progress			10/20/2010 8:33:05 AM					
Castillo, Carlos	I have to 2 classrooms that emergency lights are not working. This are the fluorescent type I need help to either replace emergency ballast or install the frog eyed emergency light fixtures.								
<u>Jaime Mijarez</u>									
66096					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:27					
Orozco, Danny	Monthly - Santa Teresa MS Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
66498	Gym (1997)	Gym			11/9/2010		189		\$0.00
Medium	Work In Progress			11/9/2010 11:34:13 AM					
Mijarez, Jaime	MIDDLE DRY ERASE BOARD IS COMING OFF THE WALL FROM BOTH SIDES								
<u>Laura Parra</u>									
67038					12/1/2010		167		\$0.00
Medium	Work In Progress			12/1/2010 3:35:59 PM					
Flores, Pete	The golf cart needs service it is not holding the charge.								
<u>Jaime Mijarez</u>									
67459					12/10/2010		158		\$0.00
Medium	Work In Progress			12/10/2010 7:58:51 AM					
Villalobos, David	Councilors office sink. I need help with the sink it is plugged up and p-trap is cracked we will need the snake.								
<u>Jaime Mijarez</u>									
67552	Gym (1997)	Parking Lot			12/13/2010		155		\$0.00
Medium	Work In Progress			12/13/2010 2:00:19 PM					
Castillo, Carlos	PLACE NEW LIGHTS GOING TOWARDS THE GYM FROM THE PARKING LOT- FROM THE N BUILDIND AND FROM THE S BUILDING. SAFETY ISSUE-- IT GETS TOO DARK WHEN GOING TOWARD THE GYM AT NIGHT								
<u>Laura Parra</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
67553	North Building	Parking Lot			12/13/2010		155		\$0.00
Medium	Work In Progress			12/13/2010 2:01:40 PM					
Castillo, Carlos	REPAIR ALL OUTSIDE LIGHTS- PARKING LOT- S BUILDING-N BUILDING- AND GYM AREA								
Laura Parra									
67833					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:42 AM					
Villalobos, David	Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
68423	South Building	Classroom			1/14/2011		123		\$0.00
Medium	Work In Progress	Room 39		1/14/2011 9:47:04 AM					
Castillo, Carlos	Repair lights								
Laura Parra									
68425					1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 10:27:28 AM					
Mijarez, Jaime	Rockwall planters - repair broken sections				Noted on Leadership Meeting Asp Mike, route to Jaime 4/14/11-mkv				
Alfredo Holguin									
68427					1/14/2011		123		\$0.00
Medium	Work In Progress			1/14/2011 10:35:43 AM					
Munoz, Michael	(PROJECT) Repaint Flashing/cap on parapet wall both north and south buildings.				Leadership Request				
Alfredo Holguin									
68783					1/26/2011		111		\$0.00
Medium	Work In Progress			1/26/2011 9:42:58 AM					
Mijarez, Jaime	As per Ace Sanchez. Pickup 12 pieces of stage from Sths and have them on campus by or before April 28, 2011 or earlier. Will be used for the Cinco de Mayo Concert.								
Jaime Mijarez									
68934	Gym (1997)	Gym			1/31/2011		106		\$0.00
Medium	Work In Progress	Ms. Snyder		1/31/2011 3:01:55 PM					
Mijarez, Jaime	Dry erase board (center) is falling off the wall. Safety Hazard Please repair								
Laura Parra									
69508	South Building	Mechanical			2/15/2011		17	17	\$519.75
Medium	Work In Progress			2/15/2011 9:56:07 AM		3/4/2011			
Villalobos, David	repaired broken copper water lines at south mechanical room to geothermal heating system				Work still pending replace broken 3/4 bfp and water meter re-routed water lines.				
David Villalobos									
5/17/2011 12:10:29 PM									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
69511	Gym (1997)				2/15/2011		91		\$0.00
Medium	Work In Progress			2/15/2011 10:03:41 AM					
Castillo, Carlos	receiver and antennas came in for scoreboards that were at sths, now at stms. please check to see if they work and if so please install in gym. thank you								
<u>Michael Munoz</u>									
69817	South Building	Restroom (Boys)			2/23/2011		83		\$0.00
Medium	Work In Progress			2/23/2011 9:57:12 AM					
Lara, Ralph	Rafa, the bottom southbuilding restrooms needs replacement of doors and hardware.								
<u>Ismael Rodriguez</u>									
70251					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:44 AM					
Orozco, Danny	Yearly - Santa Teresa MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70581					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 8:44:31 AM					
Ambriz, Jose	Joe can you order me 6 PL-36 Bell & Goss circulating pumps. I have used all the ones I had in stock.								
<u>Jaime Mijarez</u>									
70773					3/15/2011		63		\$0.00
Medium	Work In Progress			3/15/2011 10:09:22 AM					
Castillo, Carlos	N.bldg 2 exterior lights on eastside upper level exterior wall are broken.								
<u>Jaime Mijarez</u>									
70861					3/17/2011		61		\$0.00
Medium	Work In Progress			3/17/2011 9:47:56 AM					
Villalobos, David	w/o for winter storm emergency. South bldg administration area mechanical room had ruptured make water line, water meter, backflow preventer and no water in geothermal administration heat pump area.								
<u>Jaime Mijarez</u>									
71315					3/31/2011		47		\$0.00
Medium	Work In Progress			3/31/2011 1:19:33 PM					
Mijarez, Jaime	Repace broken VCT tiles throughout building-trip hazards per Leadership Council - Jaime Minjarez. knows what areas.								
Alfredo Holguin									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
71442					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:57 AM					
Orozco, Danny	Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71498					4/3/2011	4/9/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:22 AM					
Mijarez, Jaime	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71594	North Building				4/4/2011		43		\$0.00
Medium	Work In Progress			4/4/2011 9:25:18 AM					
Estrada, Jesus	NEED TO REPLACE VCT IN HALLWAY, LOWER LEVEL OF NORHT BUILDING.								
<u>Jesus Estrada</u>									
71595		Cafeteria			4/4/2011		43		\$0.00
Medium	Work In Progress			4/4/2011 9:27:00 AM					
Estrada, Jesus	NEED TO REPLACE BASEBOARD IN CAFETERIA				5/5/11 - REFXED TO RODRIGUEZ, ASP ALFREDO, NEED QUOTE ON REPLACEING VCT AS WELL				
<u>Jesus Estrada</u>									
71816					4/8/2011		39		\$0.00
Medium	Work In Progress			4/8/2011 8:50:13 AM					
Mijarez, Jaime	Stage lights set-up for Cinco de Mayo concert requires scissor lift.								
<u>Jaime Mijarez</u>									
71952					4/11/2011		36		\$0.00
Medium	Work In Progress	Leadership		4/11/2011 11:18:08 AM					
Estrada, Jesus	(PROJECT) North/South Bldgs - Need to abate (absestos) various areas then replace tile.				Leadership Request ASP ALFREDO NORTH BLDG O.K. / SOUTH BLDG PENDING EXCEPT FOR 2 RESTROOM AREAS/LOWER LEVEL.				
<u>Alfredo Holguin</u>									
72042	Gym (1997)	Gym			4/13/2011		34		\$0.00
Medium	Work In Progress	GYM		4/13/2011 10:17:41 AM					
Mijarez, Jaime	HANGING OF SUSPENSION LIGHTS IN GYM ON WEDNESDAY APRIL 27TH.								
<u>Laura Parra</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
72057					4/13/2011		34		\$0.00
Medium	Work In Progress			4/13/2011 3:24:36 PM					
Mijarez, Jaime	School campus install No Trespassing signs along fence line and Reserved parking for assistant principal signs.								
Jaime Mijarez									
72215	North Building	Parking Lot			4/19/2011		28		\$0.00
Medium	Work In Progress			4/19/2011 8:31:02 AM					
Ontiveros, Guadalupe	Lupe we need to borrow the small tractor from riverside so we can remove the sand from the parking lot.								
Ismael Rodriguez									
72216	Gym (1997)	Custodial			4/19/2011		28		\$0.00
Medium	Work In Progress			4/19/2011 8:35:45 AM					
Flores, Pete	Pete i need to borrow a truck for the coming event art show iam going to move chairs and tables to the gym unless you have ready truck 121 by 4-27-11 thanks.								
Ismael Rodriguez									
72307					4/20/2011		27		\$0.00
Medium	Work In Progress			4/20/2011 3:17:29 PM					
Valles, Johnny	South Bldg - landscaped area in front - Remove dead branches from oleanders and other bushes								
Alfredo Holguin									
72340	South Building	Office			4/21/2011		26		\$0.00
Medium	Work In Progress	SECURITY			4/21/2011 10:38:32 AM				
Castillo, Carlos	RELOCATE LIGHT TO THE OTHER SIDE OF THE DOOR. (SAFETY ISSUE)								
Laura Parra									
72443					4/26/2011		21		\$0.00
Medium	Work In Progress			4/26/2011 3:58:17 PM					
Castillo, Carlos	Gym I will need Carlos Castillo assistance on 4/27/2011 with the spot light installation for Cinco de Mayo concert. We will be using the scissor lift.								
Jaime Mijarez									
72515	North Building	Classroom			4/28/2011		19		\$0.00
Medium	Work In Progress	ROOM 3			4/28/2011 12:14:24 PM				
Lara, Ralph	REKEY MARTHA'S DESK								
Laura Parra									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

**Location:** Santa Teresa MS

72546 4/29/2011 18 \$0.00

Medium Work In Progress 4/29/2011 8:35:14 AM

Ontiveros, Guadalupe S.bldg back road that leads to gym. There is an area on the road that runs along side of the asphalt parking behind the bldg that is very loose. Frank Medina is requesting more compact fill dirt on loose sand and watered down for emergency vehicles to use.

Jaime Mijarez

72564 North Building Office 4/29/2011 18 \$0.00

Medium Work In Progress ROOM 8 4/29/2011 11:51:59 AM

Lara, Ralph NEED ADDITIONAL KEYS:P KEY , MEDICAL FILE CABINETS KEYS, AND OTHER CABINET KEYS.

Laura Parra

72654 5/1/2011 5/22/2011 16 \$0.00

Medium Work In Progress 5/1/2011 12:22:03 AM

Orozco, Danny Monthly - Santa Teresa MS Fire Suppression Insp. - Refer to PM schedule details.

Margret Villalobos

72693 5/1/2011 5/7/2011 16 \$0.00

Medium Work In Progress 5/1/2011 12:22:23 AM

Mijarez, Jaime Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

72694 5/1/2011 6/1/2011 16 \$0.00

Medium Work In Progress 5/1/2011 12:22:23 AM

Mijarez, Jaime Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

72695 5/1/2011 5/9/2011 16 \$0.00

Medium Work In Progress 5/1/2011 12:22:24 AM

Mijarez, Jaime Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

72696 5/1/2011 5/9/2011 16 \$0.00

Medium Work In Progress 5/1/2011 12:22:24 AM

Mijarez, Jaime Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
72697					5/1/2011		16		\$0.00
Medium	Work In Progress				5/1/2011 12:22:25 AM				
Mijarez, Jaime	Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72867	North Building	Custodial			5/4/2011		13		\$0.00
Medium	Work In Progress				5/4/2011 9:09:52 AM				
Carbajal, Jimmy	Jimmy i have dolley that needs a set of tires								
<u>Ismael Rodriguez</u>									
72876	South Building				5/4/2011		13		\$0.00
Medium	Work In Progress				5/4/2011 2:49:39 PM				
Villalobos, David	need to provide a water source by the fire hydrant. for trees to be planted. please see mike.thanks								
<u>Michael Munoz</u>									
72891					5/4/2011		13		\$0.00
Medium	Work In Progress				5/4/2011 3:48:49 PM				
Ambriz, Jose	Gym concession stand ice machine is not making ice and is shutting down.								
<u>Jaime Mijarez</u>									
73102	North Building	Portables			5/11/2011		6		\$0.00
Medium	Work In Progress				5/11/2011 8:51:08 AM				
Valles, Johnny	Remove sand from the portables with a tracter.								
<u>Ismael Rodriguez</u>									
73119	North Building	Custodial			5/11/2011		6		\$0.00
Medium	Work In Progress				5/11/2011 1:31:17 PM				
Lara, Ralph	Rafa a custodial closet door needs to be adjusted see Mr. rodriguez.								
<u>Ismael Rodriguez</u>									
73215	North Building	Classroom			5/13/2011		4		\$0.00
Medium	Work In Progress				5/13/2011 1:37:29 PM				
Lara, Ralph	Rafa, Ms.cravens door doesnt open the key cylinder is missing.								
<u>Ismael Rodriguez</u>									
73275					5/17/2011		0		\$0.00
Medium	Work In Progress				5/17/2011 8:46:37 AM				
Mijarez, Jaime	Fire Hydrants - the hydrant by the gym and the two hydrants located by the South Building do not work.								
<u>Alfredo Holguin</u>									
<b>Count: 51 Work Orders</b>			<b>Avg. Age of WO's 65</b>				<b>Total for Santa Teresa MS</b>	<b>17</b>	<b>\$519.75</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
64465	Main Building	Classroom			9/28/2010		231		\$0.00
Medium	Work In Progress			9/28/2010 11:55:05 AM					
Ambriz, Jose	Air conditioning has leaked into classroom and caused several areas to rust, including light fixtures.								
Yvette Cortez									
64493	Main Building	Restroom (Girls)			9/28/2010		231		\$0.00
Medium	Work In Progress			9/28/2010 3:53:31 PM					
Medina, Eric	Floors paint is chipping.		(Summer Job)						
Yvette Cortez									
65051		Cafeteria			10/6/2010		223		\$0.00
Medium	Work In Progress			10/6/2010 3:28:36 PM					
Orozco, Danny	SCREEN DOOR TO THE KITCHEN NEEDS TO BE REPAIRED.								
AS PER STATE INSPECTOR									
Jacqueline Aguilar									
65249					10/11/2010		218		\$0.00
Medium	Work In Progress			10/11/2010 3:26:51 PM					
Orozco, Danny	HAND SINK IS LEAKING SNP MANAGER MARINA R. 589-2545.								
Maritza Gonzalez									
65586					10/18/2010		211		\$0.00
Medium	Work In Progress			10/18/2010 3:53:46 PM					
Flores, Pete	Lupe I would like to request that you send someone with backhoe to dig hole to deposit all the weeds that were cut								
Eric Medina									
66097					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:27					
Orozco, Danny	Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
66285					11/3/2010		195		\$0.00
Medium	Work In Progress			11/3/2010 2:16:14 PM					
Orozco, Danny	LEFT SIDE OF SERVING LANE IS NOT COOLING. MARINA R. SNP MANAGER 589-2545.								
Maritza Gonzalez									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
67831					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:42 AM					
Villalobos, David		Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
68601	Main Building	Gym			1/20/2011		117		\$0.00
Medium	Work In Progress			1/20/2011 3:16:09 PM					
Medina, Eric		Eric, Mrs. Villa has requested for a screen to be installed in the gym. Meanwhile, screen has been placed in the shed for storage.							
<u>Yvette Cortez</u>									
68743	Main Building				1/25/2011		112		\$0.00
Medium	Work In Progress			1/25/2011 2:35:30 PM					
Medina, Eric		pto will paint boys & girls rr with maintainence supervision							
<u>Eric Medina</u>									
69288	Main Building	Hallway/Corridor			2/9/2011		97		\$0.00
Medium	Work In Progress			2/9/2011 3:41:20 PM					
Medina, Eric		Sidewalk on southside of the building is raised by 1/2 inch. Please add cement to even level.							
<u>Yvette Cortez</u>									
69604	Main Building	Classroom			2/16/2011		90		\$0.00
Medium	Work In Progress	38 & 40		2/16/2011 3:12:26 PM					
Castillo, Carlos		Eric, Ms. Gardea and Ms. Cordero both need new light bulbs in theri restrooms. Thanks!							
<u>Yvette Cortez</u>									
70019		Auditorium			2/28/2011		78		\$0.00
Medium	Work In Progress			2/28/2011 3:56:15 PM					
Medina, Eric		2 turbines on the auditorium and 1 on dining area are not working. please check and repiar.thanks							
<u>Michael Munoz</u>									
70247					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:42 AM					
Orozco, Danny		Yearly - Sunland Park ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
70302					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:18:09 AM					
Medina, Eric		Yearly - Sunland Park ES A-10 HP Rooftop Yearly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
70610					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:06:00 PM					
Ambriz, Jose	need to replace a/c in room 29 size 68								
Eric Medina									
70612					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:10:25 PM					
Ambriz, Jose	need to replace a/c in rm 31 size 45								
Eric Medina									
70614					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:11:47 PM					
Ambriz, Jose	need to replace a/c in sped office size 45								
Eric Medina									
70616					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:12:59 PM					
Ambriz, Jose	need to replace a/c in speech office size 45								
Eric Medina									
70617					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:14:05 PM					
Ambriz, Jose	need to replace a/c in rm 37 size 45								
Eric Medina									
70618					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:17:44 PM					
Ambriz, Jose	need to replace a/c in room 39 size 68								
Eric Medina									
70619					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:18:25 PM					
Ambriz, Jose	need to replace a/c in room 41 size 68								
Eric Medina									
70620					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:19:48 PM					
Ambriz, Jose	need to replace a/c in room 40 size 68								
Eric Medina									
70621					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:22:05 PM					
Ambriz, Jose	need to replace a/c in room 38 size 68								
Eric Medina									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
70622					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:23:24 PM					
Ambriz, Jose	need to replace a/c in room 36 size 68								
Eric Medina									
70623					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:24:05 PM					
Ambriz, Jose	need to replace a/c in room 32 size 68								
Eric Medina									
70624					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:24:48 PM					
Ambriz, Jose	need to replace a/c in room 30 size 68								
Eric Medina									
70625					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:25:30 PM					
Ambriz, Jose	need to replace a/c in room 26 size 68								
Eric Medina									
70627					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:26:45 PM					
Ambriz, Jose	need to replace a/c in room 24 size 68								
Eric Medina									
70629					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:27:39 PM					
Ambriz, Jose	need to replace a/c in room 22 size 45								
Eric Medina									
70630					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:28:24 PM					
Ambriz, Jose	need to replace a/c in staff development room size 45								
Eric Medina									
70631					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:29:23 PM					
Ambriz, Jose	need to replace a/c in room 16 size 68								
Eric Medina									
70633					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:30:15 PM					
Ambriz, Jose	need to replace a/c in room 14 size 68								
Eric Medina									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
70634					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:31:53 PM					
Ambriz, Jose	need to replace a/c in room 12 size 68								
Eric Medina									
70636					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:32:30 PM					
Ambriz, Jose	need to replace a/c in room 10 size 68								
Eric Medina									
70638					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:33:26 PM					
Ambriz, Jose	need to replace a/c in room 13 size 68								
Eric Medina									
70639					3/10/2011		68		\$0.00
Medium	Work In Progress			3/10/2011 3:34:08 PM					
Ambriz, Jose	need to replace a/c in room 11 size 68								
Eric Medina									
71007					3/22/2011		56		\$0.00
Medium	Work In Progress			3/22/2011 3:33:21 PM					
Medina, Eric	need to weed and feed all lawns								
Eric Medina									
71205					3/29/2011		49		\$0.00
Medium	Work In Progress			3/29/2011 2:40:36 PM					
Medina, Eric	need to replace motor belts on a/c units 5 ton and 7								
Eric Medina									
71443					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:57 AM					
Orozco, Danny	Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
72599					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:54 AM					
Medina, Eric	Yearly - Sunland Park ES C-11 Evap Coolers Yearly - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
72655					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:04 AM					
Orozco, Danny	Monthly - Sunland Park ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72664					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:09 AM					
Medina, Eric	Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72665					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:09 AM					
Medina, Eric	Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72666					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:10 AM					
Medina, Eric	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72808	Main Building	Classroom			5/3/2011		14		\$0.00
Medium	Work In Progress			5/3/2011 8:38:50 AM					
Medina, Eric	Eric, may you please check the heaters in the classrooms. The heater keeps turning on when the AC is on.								
<u>Yvette Cortez</u>									
72871	Main Building	Office			5/4/2011		13		\$0.00
Medium	Work In Progress	Main		5/4/2011 10:35:59 AM					
Lara, Ralph	Need copy of keys for thermostat.								
<u>Yvette Cortez</u>									
72924	Main Building	Classroom			5/5/2011		12		\$0.00
Medium	Work In Progress	21		5/5/2011 11:05:28 AM					
Medina, Eric	Eric, the heater is leaking water in Mrs. Venegas classroom when the AC is turned on for a long period of time. Please check the AC. Thank you.								
<u>Yvette Cortez</u>									
72997					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:14 AM					
Medina, Eric	Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

5/17/2011 12:10:29 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunland Park ES</b>							
73020	Main Building	Library			5/9/2011		8		\$0.00
Medium	Work In Progress			5/9/2011 12:49:29 PM					
Medina, Eric	Eric, the window latch on one of the windows is the library is not secure. May you please check to see what the problem is? Thank you.								
Yvette Cortez									
73028					5/9/2011		8		\$0.00
Medium	Work In Progress			5/9/2011 3:10:21 PM					
Ambriz, Jose	need to order a/c medina for 6500 master cool a/c for room 11, 13, 16								
Eric Medina									
73246					5/16/2011		1		\$0.00
Medium	Work In Progress			5/16/2011 12:42:58 PM					
Lara, Ralph	Rafe need cafeteria door ajusted, a new key made for computer lab please								
Eric Medina									
73249					5/16/2011		1		\$0.00
Medium	Work In Progress			5/16/2011 12:46:58 PM					
Ambriz, Jose	compressor in 7 ton trane unit above library blew all oil need to replace serial#02a19047 model#cshb075r0b part#570005750700								
Eric Medina									
<b>Count: 53 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>77</b>	<b>Total for Sunland Park ES</b>			<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
66098					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:28					
Orozco, Danny	Monthly - Sunrise ES Fire Suppression Insp. - Refer to PM schedule details.								
Margret Villalobos									
66371					11/5/2010		193		\$0.00
Medium	Work In Progress			11/5/2010 8:13:50 AM					
Ontiveros, Guadalupe	NEED 20 TONS RED SCRINIG								
Juan Vargas									
67830					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:41 AM					
Villalobos, David	Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
67929					1/2/2011		135		\$0.00
Medium	Work In Progress			1/2/2011 12:29:32 AM					
Sanchez, Raul	Monthly - Sunrise ES - DP-1421 - Refer to PM schedule details.								
Margret Villalobos									
69463					2/14/2011		92		\$0.00
Medium	Work In Progress			2/14/2011 3:17:14 PM					
Carrasco, Danny	i need 10 gallons gas for 155 truck and 620- 2 blower								
Juan Vargas									
70248					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:42 AM					
Orozco, Danny	Yearly - Sunrise ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
70356					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:18:37 AM					
Sanchez, Raul	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
Margret Villalobos									
71182					3/29/2011		49		\$0.00
Medium	Work In Progress			3/29/2011 12:20:58 AM					
Vargas, Juan	Monthly - Sunrise ES - Grease Trap (Monthly) - Refer to PM schedule details.								
Margret Villalobos									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
71284					3/31/2011		47		\$0.00
Medium	Work In Progress			3/31/2011 12:17:32 AM					
Vargas, Juan	Monthly - Sunrise ES A16 (Fan Exh.)(S. Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71444					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:58 AM					
Orozco, Danny	Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71557					4/3/2011		44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:47 AM					
Sanchez, Raul	Monthly - Sunrise ES - DP-1421 - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72076					4/14/2011		33		\$0.00
Medium	Work In Progress			4/14/2011 7:58:57 AM					
Orozco, Danny	Pass-Thru Refrigerators it is not working. SNP Manager Virginia P. 824-3194								
<u>Maritza Gonzalez</u>									
72600					4/30/2011	5/31/2011	17		\$0.00
Medium	Work In Progress			4/30/2011 12:15:55 AM					
Vargas, Juan	Yearly - Sunrise ES C11 (Evap.Cooler)(Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72656					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:05 AM					
Orozco, Danny	Monthly - Sunrise ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72701					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:27 AM					
Vargas, Juan	Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72702					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:27 AM					
Vargas, Juan	Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									



# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
72703					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:28 AM					
Vargas, Juan	Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72704					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:28 AM					
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72743					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:47 AM					
Sanchez, Raul	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
73003					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:17 AM					
Vargas, Juan	Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
73039					5/9/2011		8		\$0.00
Medium	Work In Progress			5/9/2011 3:36:23 PM					
Sotelo, Enrique	portable #4 need replace emergency lights								
<u>Juan Vargas</u>									
73081					5/10/2011		7		\$0.00
Medium	Work In Progress			5/10/2011 3:22:29 PM					
Sotelo, Enrique	need help to check water sprinkler buster not work								
<u>Juan Vargas</u>									
73112	Main Building	Hallway/Corridor			5/11/2011		6		\$0.00
Medium	Work In Progress			5/11/2011 11:45:12 AM					
Estrada, Jesus	Ceramic tile in entrance lobby needs to be replaced with new ceramic tile and/OR get a second quote to replace this ceramic tile with vct.					EVA - PLEASE QUOTE ON BOTH - VCT & CERAMIC			
<u>Jesus Estrada</u>									
73115					5/11/2011		6		\$0.00
Medium	Work In Progress			5/11/2011 12:18:19 PM					
Martinez, Larry	Please deliver (1) box to go to Sunrise								
<u>Tracey Swinford</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
73185		Classroom			5/13/2011		4		\$0.00
Medium	Work In Progress				5/13/2011 7:46:23 AM				
Lozoya, Manny		SALON DE CLASE #205 PUERTA TRASERA NO SE OUEDA HABRIR ESTA QUEBRADA LA MANIVELA. URGENTE.							
Marisela Torres									
<b>Count: 25 Work Orders</b>		<b>Avg. Age of WO's 51</b>			<b>Total for Sunrise ES</b>			<b>0</b>	<b>\$0.00</b>

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
63081		Cafeteria			8/27/2010		263		\$0.00
Medium	Work In Progress			8/27/2010 3:06:37 PM					
Orozco, Danny	NEED TO REPLACE THE WHEELS TO THE PREP TABLE. WHEELS THAT LOCK, THE TABLE MOVES.								
	EVA MIRANDA SNP MGR 233-2945								
<u>Jacqueline Aguilar</u>									
63621					9/8/2010		251		\$0.00
Medium	Work In Progress			9/8/2010 10:23:00 AM					
Ontiveros, Guadalupe	NEED TO PUT IN SPRINKLER SYSTEM TO RAISED GARDENS NOW THAT CONTRACTOR HAS PUT IN WATER SUPPLY LINE								
<u>Danny Miranda</u>									
66099					10/31/2010	11/21/2010	198		\$0.00
Medium	Work In Progress			10/31/2010 12:36:28					
Orozco, Danny	Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
67814					1/2/2011	2/2/2011	135		\$0.00
Medium	Work In Progress			1/2/2011 12:28:35 AM					
Villalobos, David	Yearly - Vado ES Backflow Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
68920					1/31/2011		106		\$0.00
Medium	Work In Progress			1/31/2011 8:55:45 AM					
Ontiveros, Joe	NEED TO CK. CIRCULATING PUMP NOISE								
<u>Danny Miranda</u>									
70249					3/6/2011		72		\$0.00
Medium	Work In Progress			3/6/2011 12:17:43 AM					
Orozco, Danny	Yearly - Vado ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
70757					3/14/2011		64		\$0.00
Medium	Work In Progress			3/14/2011 4:27:35 PM					
Miranda, Danny	need 12 emitter tips for drip system								
<u>Danny Miranda</u>									
70917					3/18/2011		60		\$0.00
Medium	Work In Progress			3/18/2011 10:23:11 AM					
Miranda, Danny	NEED TO CHANGE AIR FILTERS TO UNITS								
Danny Miranda									

5/17/2011 12:10:30 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
71178					3/29/2011		49		\$0.00
Medium	Work In Progress			3/29/2011 12:20:56 AM					
Miranda, Danny	Monthly - Vado ES - Grease Trap (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71338					3/31/2011		47		\$0.00
Medium	Work In Progress			3/31/2011 3:37:14 PM					
Ontiveros, Guadalupe	NEED TO MARK SOCCER FIELD								
<u>Danny Miranda</u>									
71445					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:19:58 AM					
Orozco, Danny	Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71448					4/3/2011	4/24/2011	44		\$0.00
Medium	Work In Progress			4/3/2011 12:20:00 AM					
Orozco, Danny	Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
71746					4/6/2011		41		\$0.00
Medium	Work In Progress			4/6/2011 3:25:10 PM					
Ontiveros, Joe	CK. TWO FAUCETS IN 300-WING BOYS R.R.								
<u>Danny Miranda</u>									
72054					4/13/2011		34		\$0.00
Medium	Work In Progress			4/13/2011 3:15:54 PM					
Miranda, Danny	NEED TO PUT FERTILIZER ON TREES AND PLANTS								
<u>Danny Miranda</u>									
72319		Athletic Field			4/20/2011		27		\$0.00
Medium	Work In Progress			4/20/2011 3:42:27 PM					
Munoz, Michael	please order soccer goals for site.								
<u>Alfredo Holguin</u>									
72469					4/27/2011		20		\$0.00
Medium	Work In Progress			4/27/2011 11:41:47 AM					
Ontiveros, Guadalupe	NEED TO LOCATE IRRIGATION CUT OUT VALVE								
<u>Danny Miranda</u>									

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
72630					5/1/2011	5/7/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:51 AM					
Miranda, Danny	Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72631					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:51 AM					
Miranda, Danny	Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72632					5/1/2011	5/9/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:52 AM					
Miranda, Danny	Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72633					5/1/2011		16		\$0.00
Medium	Work In Progress			5/1/2011 12:21:52 AM					
Miranda, Danny	Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72657					5/1/2011	5/22/2011	16		\$0.00
Medium	Work In Progress			5/1/2011 12:22:05 AM					
Orozco, Danny	Monthly - Vado ES Fire Suppression Insp. - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
72915					5/5/2011		12		\$0.00
Medium	Work In Progress			5/5/2011 9:13:54 AM					
Lozoya, Manny	NEED TO REPLACE BEAD BOLT IN RM. 303 THAT CAME OFF								
<u>Danny Miranda</u>									
72994					5/8/2011	5/24/2011	9		\$0.00
Medium	Work In Progress			5/8/2011 12:18:13 AM					
Miranda, Danny	Monthly - Vado ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
73087					5/10/2011		7		\$0.00
Medium	Work In Progress			5/10/2011 3:37:40 PM					
Gonzalez, Salvador	NEED A STRIP OF METAL (STAINLESS STEEL) 3" X 4' TO COVER GAP ON R.R. PARTITIONS								
<u>Danny Miranda</u>									

5/17/2011 12:10:30 PM

# 1319 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2010 - 6/30/2011 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
73256					5/16/2011		1		\$0.00
Medium	Work In Progress				5/16/2011 2:55:05 PM				
Solis, Lorenzo	problems with recovery wheel noise needs to be checked out								
Danny Miranda									
<b>Count: 25 Work Orders</b>		<b>Avg. Age of WO's 63</b>		<b>Total for Vado ES</b>			<b>0</b>	<b>\$0.00</b>	
<b>Count: 1319 Work Orders</b>		<b>Avg. Age of WO's 82</b>		<b>Grand Total</b>			<b>89</b>	<b>\$2,885.75</b>	