

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
82399		Pump House			1/5/2012		193		\$0.00
Medium	Work In Progress			1/5/2012 9:31:02 AM					
Appelzoller, Fred		Remove cutoff that are not be used, that the pump house, old main							
Hector Villalobos									
82665					1/11/2012		187		\$0.00
Medium	Work In Progress			1/11/2012 8:25:29 AM					
Sotelo, Enrique		NEEDS BUZZARD INSTALL OUTSIDE IF BACK DOOR. SNP MANAGER BECKY A. 882.3507							
Maritza Gonzalez									
88257					5/30/2012		47		\$0.00
Medium	Work In Progress			5/30/2012 7:39:13 AM					
Villalobos, Hector		Need to order 5 gal of traffic paint white for cross walk on 4th street							
Hector Villalobos									
88858					6/13/2012		33		\$0.00
Medium	Work In Progress	SPED OFFICE		6/13/2012 1:06:50 PM					
Lozoya, Manny		REPLACE CYLINDER ON DOORKNOB ROOM 102 KEY DOES NOT OPEN (SEE MARGARET)							
Margaret Villalobos									
87980					5/22/2012		55		\$0.00
Medium	Work In Progress			5/22/2012 7:52:00 AM					
Lozoya, Manny		MANNY WE NEED A LOCK FOR THE ROOF, WE HAD TO USE THE LOCK THAT WE USE FOR THE OFFICE CURTAIN							
Jessica Lopez									
88373					6/1/2012		45		\$0.00
Medium	Work In Progress	SPED OFFICE		6/1/2012 8:16:47 AM					
Lozoya, Manny		LOST KEYS TO CABINETS IN SOCIAL WORKER, YOLANDA MUNOZ' OFFICE (RM118) NEED TO BE REKEYED							
Margaret Villalobos									
88844					6/13/2012		33		\$0.00
Medium	Work In Progress			6/13/2012 6:26:37 AM					
Flores, Pete		truck radiator tank is leaking i will be out on 6/18 to 6/28							
Hector Villalobos									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
88356					5/31/2012		46		\$0.00
Medium	Work In Progress			5/31/2012 3:43:19 PM					
Villalobos, Hector		5/31/12			5/31				
		6.5 80497 painting room 102 prek on track 1. shop pick up gas, supplies 5. log on work order log mileage start 127848 stop 127858							
<u>Hector Villalobos</u>									
85821					4/2/2012		105		\$0.00
Medium	Work In Progress			4/2/2012 12:41:26 AM					
Holguin, Alfredo		Monthly - Anthony ES - Fire Pump Engine (Quarterly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
85604					3/27/2012		111		\$0.00
Medium	Work In Progress	SPED OFFICE		3/27/2012 9:35:23 AM					
Gonzalez, Salvador		INSTALL WINDOW GUARDS IN ROOM #101 SOCIAL WORKERS OFFICE							
<u>Margaret Villalobos</u>									
89010					6/19/2012		27		\$0.00
Medium	Work In Progress	SPED OFFICE		6/19/2012 5:07:08 PM					
Martinez, Larry		PO 111207370 33 BOXES DEANNA WILKINSON/SPED INST. SPEC							
<u>Margaret Villalobos</u>									
89015					6/19/2012		27		\$0.00
Medium	Work In Progress	SPED OFFICE		6/19/2012 5:12:57 PM					
Martinez, Larry		PO111207511 1 BOX DEANNA WILKINSON/INST. SPEC/SPED OFFICE							
<u>Margaret Villalobos</u>									
89017					6/19/2012		27		\$0.00
Medium	Work In Progress	SPED OFFICE		6/19/2012 5:15:06 PM					
Martinez, Larry		PO 111207878 1 BOX LISA MCCULLER/INST. SPEC/SPED OFFICE							
<u>Margaret Villalobos</u>									
89018					6/19/2012		27		\$0.00
Medium	Work In Progress	SPED OFFICE		6/19/2012 5:15:53 PM					
Martinez, Larry		PO111207881 8 BOXES SAM AVALOS/INST. SPEC/SPED OFFICE							
Margaret Villalobos									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
89019					6/19/2012		27		\$0.00
Medium	Work In Progress	SPED OFFICE			6/19/2012 5:16:40 PM				
Martinez, Larry		PO111207874 2 BOXES SAM AVALOS/NST. SPEC./SPED OFFICE							
Margaret Villalobos									
89020					6/19/2012		27		\$0.00
Medium	Work In Progress	SPED OFFICE			6/19/2012 5:18:13 PM				
Martinez, Larry		PO111207924 5 BOXES KATRINA GARZA/PT/SPED OFFICE							
Margaret Villalobos									
89022					6/19/2012		27		\$0.00
Medium	Work In Progress	SPED OFFICE			6/19/2012 5:20:43 PM				
Martinez, Larry		PO111207384 11 BOXES SAM AVALOS/INST SPEC/SPED OFFICE							
Margaret Villalobos									
89023					6/19/2012		27		\$0.00
Medium	Work In Progress	SPED OFFICE			6/19/2012 5:21:35 PM				
Martinez, Larry		PO111207391 2 BOXES SAM AVALOS/INST. SPEC/SPED OFFICE							
Margaret Villalobos									
89027					6/19/2012		27		\$0.00
Medium	Work In Progress	SPED OFFICE			6/19/2012 5:25:45 PM				
Martinez, Larry		PO111207395 2 BOXES CLAUDIA PEREZ/INST SPEC/SPED OFFICE							
Margaret Villalobos									
89035					6/19/2012		27		\$0.00
Medium	Work In Progress	SPED OFFICE			6/19/2012 5:35:44 PM				
Martinez, Larry		PO111207371 5 BOXES CLAUDIA PEREZ/INST SPEC/SPED OFFICE							
Margaret Villalobos									
89036					6/19/2012		27		\$0.00
Medium	Work In Progress	SPED OFFICE			6/19/2012 5:37:17 PM				
Martinez, Larry		PO111207425 1 BOX SAM AVALOS/INST. SPEC/SPED OFFICE							
Margaret Villalobos									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
89037					6/19/2012		27		\$0.00
Medium	Work In Progress	SPED OFFICE		6/19/2012 5:38:08 PM					
Martinez, Larry		PO111207418 4 BOXES DEANNA WILKINSON/INST SPEC/SPED OFFICE							
Margaret Villalobos									
87953					5/21/2012		56		\$0.00
Medium	Work In Progress	SPED OFFICE		5/21/2012 2:33:10 PM					
Martinez, Larry		PICK UP BOXES FROM SPED OFFICE FOR SLP, MARISA HERRERA AND DELIVER TO OLD NURSES OFFICE AT ANTHONY ELEMENTARY THE VILLAGE #111							
Margaret Villalobos									
89130					6/25/2012		21		\$0.00
Medium	Work In Progress	SPED OFFICE		6/25/2012 10:26:39 AM					
Briones, Enrique		PO/3111207416 1 BOX NATALIA MARTINEZ/SW/SPED OFFICE							
Margaret Villalobos									
89131					6/25/2012		21		\$0.00
Medium	Work In Progress	SPED OFFICE		6/25/2012 10:30:32 AM					
Briones, Enrique		PO #111207420 1 BOX KATHY BLANCAS/SLP/SPED OFFICE							
Margaret Villalobos									
89135					6/25/2012		21		\$0.00
Medium	Work In Progress	SPED OFFICE		6/25/2012 10:41:33 AM					
Briones, Enrique		PO@111207875 4 BOXES LISA MCCULLER/INST SPEC/SPED OFFICE							
Margaret Villalobos									
89136					6/25/2012		21		\$0.00
Medium	Work In Progress	SPED OFFICE		6/25/2012 10:44:44 AM					
Briones, Enrique		PO#111207876 1 BOX CLAUDIA PEREZ/INST SPEC/SPED OFFICE							
Margaret Villalobos									
89137					6/25/2012		21		\$0.00
Medium	Work In Progress	SPED OFFICE		6/25/2012 10:46:00 AM					
Briones, Enrique		PO@111207883 1 BOX SAM AVALOS/INST SPEC/SPED OFFICE							
Margaret Villalobos									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

89141 6/25/2012 21 \$0.00

Medium Work In Progress SPED OFFICE 6/25/2012 12:40:48 PM

Briones, Enrique PO#111207416
1 BOX
NATALIA MARTINEZ/SW/SPED OFFICE

Margaret Villalobos

89142 6/25/2012 21 \$0.00

Medium Work In Progress SPED OFFICE 6/25/2012 12:42:34 PM

Briones, Enrique PO#111207889
1 BOX
CLAUDIA PEREZ/INST SPEC/SPED OFFICE

Margaret Villalobos

89145 6/25/2012 21 \$0.00

Medium Work In Progress SPED OFFICE 6/25/2012 12:56:38 PM

Briones, Enrique PO#111207895
1 BOX
RACHEL RIVERA/INST SPEC/SPED OFFICE

Margaret Villalobos

89147 6/25/2012 21 \$0.00

Medium Work In Progress SPED OFFICE 6/25/2012 12:58:45 PM

Briones, Enrique PO #111205951
1 BOX
CLAUDIA PEREZ/INST. SPEC/SPED OFFICE

Margaret Villalobos

89149 6/25/2012 21 \$0.00

Medium Work In Progress SPED OFFICE 6/25/2012 1:01:06 PM

Briones, Enrique PO #111207209
DEANNA WILKINSON/INST SPEC/SPED OFFICE

Margaret Villalobos

88139 5/25/2012 52 \$0.00

Medium Work In Progress SPED OFFICE 5/25/2012 8:52:42 AM

Martinez, Larry DELIVER PO #111206919
10 BOXES
SAM AVALOS, ALAMO

Margaret Villalobos

84821 3/4/2012 134 \$0.00

Medium Work In Progress 3/4/2012 12:21:08 AM

Munoz, Michael Yearly - Anthony ES Fire Ext. Insp. (Yearly) - Refer to
PM schedule details.

Margret Villalobos

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Anthony ES							
88375		Portables			6/1/2012		45		\$0.00
Medium	Work In Progress			6/1/2012 9:40:02 AM					
		Upper primary Portables 1, 2, 3,4 need to replace floor tile. In 4 entrance doors, and two bathrooms							
Hector Villalobos									
83742	Main Building				2/6/2012		161		\$0.00
Medium	Work In Progress			2/6/2012 3:29:37 PM					
Ontiveros, Guadalupe		please remove canopy frames and re-locate benches. thank you							
Michael Munoz									
88256	Main Building				5/30/2012		47		\$0.00
Medium	Work In Progress			5/30/2012 7:32:35 AM					
Ontiveros, Guadalupe		Need long trailer to remove dead tree from mild blg parking lot				Asp Alfredo, Grounds will be taking care of tree removal.			
Hector Villalobos									
88773	Cafeteria				6/11/2012		35		\$0.00
Medium	Work In Progress			6/11/2012 3:57:13 PM					
Solis, Lorenzo		old cafeteria a/c units all 4 need duct repair							
Hector Villalobos									
87889	Original Main	Cafeteria			5/17/2012		60		\$0.00
Medium	Work In Progress			5/17/2012 5:24:23 PM					
Lozoya, Manny		Manny - Need two sets (2) of gate keys, Alamo (old AE) building and cafeteria keys made for Old Anthony Elementary (SPED). It should open all the gates and doors on that campus. Jaime Vargas (575-644-7438) with ESA will be checking it out to do the ADA work at AE. Please bring the key to construction office so Peggy Jo can have him sign for it. If you have questions please call me at 882-6921...Thanks...Ralph Gallegos							
Rafael Gallegos									
87123	Original Main	Office			5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 7:51:26 AM					
Villalobos, Hector		old main blg sped office blinds for room 112 w 50x L 56. need two							
Hector Villalobos									
80274	Pump House				10/27/2011		263		\$0.00
Medium	Work In Progress			10/27/2011 7:50:19 AM					
Lozoya, Manny		Pump house needs a door with door jamb				Pending asp report 1/19/12			
Hector Villalobos									
Count: 42 Work Orders		Avg. Age of WO's 55			Total for Anthony ES			0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
84822					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:09 AM					
Munoz, Michael	Yearly - Berino ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
85444					3/19/2012		119		\$0.00
Medium	Work In Progress			3/19/2012 12:36:52 PM					
Briones, Enrique	transfer cabnits to nursing dept Judy Cregan AS SOON AS POSSIBLE								
<u>Jimmy Cortez</u>									
88813					6/12/2012		34		\$0.00
Medium	Work In Progress			6/12/2012 2:16:16 PM					
Briones, Enrique	Please pick up obsolete technology items								
<u>Michelle Tellez</u>									
87571					5/10/2012		67		\$0.00
Medium	Work In Progress			5/10/2012 2:55:08 PM					
Sanchez, Raul	MR RAUL SANCHEZ SIR NEED TO CHANGE OUT WATER FILTER IN THE BOILER ROOM THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
88894					6/14/2012		32		\$0.00
Medium	Work In Progress			6/14/2012 8:25:09 AM					
Sanchez, Raul	MR RAUL SANCHEZ SIR THE PVC MALE ADTER WHERE IT TIES IN THE GALVINIZE UNION IS LEAKING NEED TO REPAIR ITS RIGHT NEXT TO NEW BLUE FILTER WE INSTALLED 3" WATER LINE THANK YOU SIR AND GOD BLESS								
<u>Adan Duran</u>									
85822					4/2/2012		105		\$0.00
Medium	Work In Progress			4/2/2012 12:41:26 AM					
Holguin, Alfredo	Monthly - Berino ES - Fire Pump Engine (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
88234		Portables			5/29/2012		48		\$0.00
High	Work In Progress			5/29/2012 2:37:01 PM					
Estrada, Jesus	please move furniture from portables to new classrooms.thank you								
Michael Munoz									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location:		Berino ES								
88807					6/12/2012		34		\$0.00	
Medium	Work In Progress			6/12/2012 12:32:40 PM						
Estrada, Jesus	remove tile from portables an replace with carpet .portables 155 an 156									
Jimmy Cortez										
86729					4/20/2012		87		\$0.00	
Medium	Work In Progress			4/20/2012 3:36:11 PM						
Lozoya, Manny	LIBRARY NEEDS TO BE RE-KEYED.									
Maribel Chavez										
81351					11/22/2011		237		\$0.00	
Medium	Work In Progress			11/22/2011 3:32:35 PM						
Sotelo, Enrique	MR ENRIQUE SOTELO SIR NEED TO INSTALL OUTSIDE LIGHTS EASTSIDE BY BUS TURN AROUND BETWEEN CAMERA AND EAST ENTRANCE TO DARK AT NIGHT THANK YOU SIR AND GOD BLESS									
Adan Duran										
86376		Classroom			4/12/2012		95		\$0.00	
Medium	Work In Progress	104		4/12/2012 8:49:58 AM						
Miranda, Danny	RM#104-LUCY LOPEZ- SET UP SMARTBOARD NEEDS TO BE MOUNTED									
Chavez, Maribel										
Count: 11 Work Orders		Avg. Age of WO's 90		Total for Berino ES			0	\$0.00		

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
88191					5/25/2012		52		\$0.00
Medium	Work In Progress			5/25/2012 11:13:59 AM					
Ontiveros, Joe	requesting elongated front toilet bowl with tank, and flapper. accelerator flush. location nurses station. heavy usage area.								
Paul Quinones									
84573					2/28/2012		139		\$0.00
Medium	Work In Progress			2/28/2012 12:31:43 PM					
Quinones, Paul	REQUESTING CELDECK PADS FOR EVAP. COOLERS FOR THE UP COMING SUMMER SEASON. TOTAL OF 8 ARE REQUESTED.								
Paul Quinones									
84068					2/13/2012		154		\$0.00
Medium	Work In Progress			2/13/2012 3:43:13 PM					
Quinones, Paul	NEED THERMOSTAT COVERS TOTAL OF 18 FOR CLASS RMS.								
Paul Quinones									
84700					2/29/2012		138		\$0.00
Medium	Work In Progress			2/29/2012 4:09:54 PM					
Quinones, Paul	REQUESTING 4 EVAP COOLERS 2 6300 D/D AND 2 6300 S/D MASTER COOL								
Paul Quinones									
87229					5/3/2012		74		\$0.00
Medium	Work In Progress			5/3/2012 3:51:39 PM					
Quinones, Paul	LAYOUT PRIMARY SCREENING IN FRONT OF SCHOOL W/O# 85780								
Paul Quinones									
75779					7/25/2011		357		\$0.00
Medium	Work In Progress			7/25/2011 1:21:24 PM					
Orozco, Daniel	Chemical room wall needs to be replaced with RFP, it is falling apart. . SNP Manager Esther C. 824.0048								
Maritza Gonzalez									
87600					5/10/2012		67		\$0.00
Medium	Work In Progress			5/10/2012 3:52:23 PM					
Gonzalez, Salvador	NEED A RAMP BEHIND KITCHEN LOADING DOCK, REQUESTING A DIAMOND PLATE RAMP 48" X 48".								
Paul Quinones									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral ES							
86620					4/18/2012		89		\$0.00
Medium	Work In Progress				4/18/2012 2:49:36 PM				
Flores, Pete	REQUESTING BOB CAT TO LAY OUT SCREENING IN FRONT OF SCHOOL. ATTN. PETE THANKS								
Paul Quinones									
84823					3/4/2012		134		\$0.00
Medium	Work In Progress				3/4/2012 12:21:09 AM				
Munoz, Michael	Yearly - Chaparral ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
Count: 9 Work Orders		Avg. Age of WO's	134		Total for Chaparral ES		0		\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral HS									
84838					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:16 AM					
Munoz, Michael	Yearly - Chaparral HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
88801		Athletic Field			6/12/2012		34		\$0.00
Medium	Work In Progress			6/12/2012 10:30:24 AM					
Sotelo, Enrique	need to install power to shop for air compressor.								
<u>Guadalupe Ontiveros</u>									
88384		Library			6/1/2012		45		\$0.00
Medium	Work In Progress	Library		6/1/2012 3:04:51 PM					
Ortiz, Alfredo	Facing pulling away from front shelves in non fiction. Metal plates need to be replaced underneath student computers, wires exposed. (Martha Mays)								
<u>Diana Mendoza</u>									
86913					4/26/2012		81		\$0.00
Medium	Work In Progress			4/26/2012 11:21:06 AM					
Ortiz, Alfredo	Need ot order a industrial push broom and pipe cutter.								
<u>Alfredo Ortiz</u>									
85826					4/2/2012		105		\$0.00
Medium	Work In Progress			4/2/2012 12:41:28 AM					
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump Engine (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
89213	A-Wing				6/27/2012		19		\$0.00
Medium	Work In Progress			6/27/2012 6:16:30 AM					
Ortiz, Alfredo	Need to remove sand from roof tops.								
<u>Alfredo Ortiz</u>									
89253	A-Wing	Hallway/Corridor			6/28/2012		18		\$0.00
Medium	Work In Progress			6/28/2012 6:22:42 AM					
Ortiz, Alfredo	Need to fix and adjust water fountains through-out school.								
<u>Alfredo Ortiz</u>									
88267	A-Wing	Hallway/Corridor			5/30/2012		47		\$0.00
Medium	Work In Progress			5/30/2012 11:48:36 AM					
Ortiz, Alfredo	Need to replace light bulb in A-wing hallway.								
<u>Alfredo Ortiz</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral HS									
88265	A-Wing				5/30/2012		47		\$0.00
Medium	Work In Progress			5/30/2012 10:25:01 AM					
Holguin, Alfredo	Correct problems in Main Geothermal lines in main corridor to including preparation of constructions documents to install expansion loops, piping hangers and repairs to sheetrock grout and other related structures								
<u>Alfredo Holguin</u>									
88396	C-Wing	Classroom			6/1/2012		45		\$0.00
Medium	Work In Progress			6/1/2012 3:41:54 PM					
Ortiz, Alfredo	In C-wing room, C-3 Fix hanle on cabbineets. Book carousel needs screws. Front wall needs projector screen.								
<u>Alfredo Ortiz</u>									
87764	D-Wing				5/15/2012		62		\$0.00
Medium	Work In Progress			5/15/2012 3:42:30 PM					
Solis, Lorenzo	Motor not working.								
<u>Alfredo Ortiz</u>									
82413	E-Wing				1/5/2012		193		\$0.00
Safety	Work In Progress	e- computer lab		1/5/2012 2:58:40 PM					
Solis, Lorenzo	need a vent installed a.s.a.p. in computer lab. this vent is needed to prevent the exhaust and machine fumes from "project lead the way equipment" from causing injury to students. this is the third request. the men come out to look at it but nothing else has been done. (steinert)								
<u>Rosa Quezada</u>									
87668	F-Wing				5/14/2012		63		\$0.00
Medium	Work In Progress	F 3		5/14/2012 11:28:07 AM					
Ontiveros, Joe	Eye wash station- no spray-leaks at floor level.(Lnda Suciu)								
<u>Diana Mendoza</u>									
87900	F-Wing	Restroom (Boys)			5/18/2012		59		\$0.00
Medium	Work In Progress			5/18/2012 11:14:08 AM					
Ontiveros, Joe	Need to replace faucet it is broken								
<u>Alfredo Ortiz</u>									
88571	F-Wing	Restroom (Boys)			6/4/2012		42		\$0.00
Medium	Work In Progress			6/4/2012 10:14:05 AM					
Ontiveros, Joe	Need to replace 3 faucets in F-wing and 2 in G-wing brokend. Boys Restrooms.								
<u>Alfredo Ortiz</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
87805	F-Wing	Classroom			5/16/2012		61		\$0.00
Medium	Work In Progress			5/16/2012 3:12:58 PM					
Ortiz, Alfredo	need to replace mini-bliends for windows.								
<u>Alfredo Ortiz</u>									
87919	G-Wing	Restroom (Boys)			5/18/2012		59		\$0.00
Medium	Work In Progress			5/18/2012 3:38:49 PM					
Ontiveros, Joe	Two faucets need to be replaced vandalised								
<u>Alfredo Ortiz</u>									
88951	I-Wing	Classroom			6/18/2012		28		\$0.00
Medium	Work In Progress			6/18/2012 3:52:02 PM					
Ortiz, Alfredo	Need to replace filters in band room								
<u>Alfredo Ortiz</u>									
89074	R-Wing	Classroom			6/20/2012		26		\$0.00
Medium	Work In Progress			6/20/2012 4:19:22 PM					
Ortiz, Alfredo	In R-3 need to clean sink trap filters under each sink, Art room.								
<u>Alfredo Ortiz</u>									
88269	R-Wing	Classroom			5/30/2012		47		\$0.00
Medium	Work In Progress			5/30/2012 12:08:11 PM					
Ortiz, Alfredo	FLOOD 150W Light bulbs need to be replaced in room R-3 to see the art picturese.								
<u>Alfredo Ortiz</u>									
87415	Field House	Gym			5/7/2012		70		\$0.00
Medium	Work In Progress	Trainers room's		5/7/2012 9:28:18 AM					
Lozoya, Manny	Please re-key trainners room.(Karen Nougues) ASAP								
<u>Diana Mendoza</u>									
87602	H-Wing	Dressing Room			5/10/2012		67		\$0.00
Medium	Work In Progress			5/10/2012 3:54:43 PM					
Lozoya, Manny	Need to replace door knob in girls lockerroom not working.								
<u>Alfredo Ortiz</u>									
87152	H-Wing	Gym			5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 3:25:51 PM					
Ortiz, Alfredo	Need to replace bearing 0n Industrial A/C unit.								
<u>Alfredo Ortiz</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral HS									
87528	H-Wing	Dressing Room			5/9/2012		68		\$0.00
Medium	Work In Progress				5/9/2012 2:45:50 PM				
Ontiveros, Joe	Need to run new gas line to Dryer in Girls locker room Gym.								
Alfredo Ortiz									
82084	H-Wing	Gym			12/14/2011		215		\$0.00
Medium	Work In Progress				12/14/2011 9:33:49 AM				
Munoz, Michael	Need to re-locate cable from basket-ball back-board		2/7/12 - Mike will look into this work order - A. Ortiz						
Alfredo Ortiz									
88266		Parking Lot			5/30/2012		47		\$0.00
Medium	Work In Progress				5/30/2012 11:46:13 AM				
Munoz, Michael	Sidewalk is lifting up and breaking in to peaces. The students can trip and fall. Safty hazard.								
Alfredo Ortiz									
87502					5/8/2012		69		\$0.00
Medium	Work In Progress				5/8/2012 3:51:07 PM				
Ortiz, Alfredo	Need to anchor Picnic Tablles out side Cafeteria.								
Alfredo Ortiz									
83850		Pump House			2/8/2012		159		\$0.00
Medium	Work In Progress				2/8/2012 3:14:53 PM				
Orozco, Daniel	Need to fix fire pump								
Alfredo Ortiz									
88765		Pump House			6/11/2012		35		\$0.00
High	Work In Progress				6/11/2012 2:08:53 PM				
Munoz, Michael	Problem with the Electrical Fire Pump Controler alarm keeps going off reads (Low Voltage)								
Alfredo Ortiz									
89287					6/30/2012		16		\$0.00
Medium	Work In Progress				6/30/2012 12:26:05 AM				
Quinones, Paul	Yearly - Chaparral HS Emer. Light Test: Annual - Refer to PM schedule details.								
Margret Villalobos									
82223					1/1/2012		197		\$0.00
Medium	Work In Progress				1/1/2012 12:44:03 AM				
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump PM (Quarterly) - Refer to PM schedule details.								
Margret Villalobos									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
82138		Classroom			12/15/2011		214		\$0.00
Medium	Work In Progress	sports field			12/15/2011 11:01:48				
Garcia, Jose		overseed the softball, baseball, p.e. (practice) and soccer fields with winter rye grass (sanchez)							
Rosa Quezada									
89288					6/30/2012		16		\$0.00
Medium	Work In Progress				6/30/2012 12:26:05 AM				
Quinones, Paul		Yearly - Chaparral HS Exit Sign Test: Annual - Refer to PM schedule details.							
Margret Villalobos									
86438		Athletic Field			4/13/2012		94		\$0.00
Medium	Work In Progress				4/13/2012 12:17:41 PM				
Ontiveros, Joe		Need to re-anchor two water fountins on basket-ball courts out side.							
Alfredo Ortiz									
87628		Parking Lot			5/11/2012		66		\$0.00
Medium	Work In Progress				5/11/2012 3:44:49 PM				
Sotelo, Enrique		Need to replace several lamps on light posts in Parking lot.							
Alfredo Ortiz									
88666		Office			6/6/2012		40		\$0.00
Medium	Work In Progress				6/6/2012 2:08:36 PM				
Ortiz, Alfredo		Please remove/cover the air vent in Mr. Varela's office due to excessive dirt.							
Mireya Meza									
88926					6/17/2012		29		\$0.00
Medium	Work In Progress				6/17/2012 12:18:51 AM				
Valdez, Pedro		Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.							
Margret Villalobos									
Count: 37 Work Orders		Avg. Age of WO's		73	Total for Chaparral HS			0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
86861		Cafeteria			4/25/2012		82		\$0.00
Medium	Work In Progress			4/25/2012 10:04:36 AM					
Lozoya, Manny		Please repair surface locks on two doors under stage.							
Albert Vallejo									
87065					5/1/2012		76		\$0.00
Medium	Work In Progress			5/1/2012 9:11:04 AM					
Vallejo, Albert		Paint doors and jambs as needed throughout building.							
Albert Vallejo									
86526		Portables			4/16/2012		91		\$0.00
Medium	Work In Progress			4/16/2012 3:44:30 PM					
Vallejo, Albert		Re-route circuit to Athletic field that went through portable building.							
Albert Vallejo									
82546					1/9/2012		189		\$0.00
Medium	Work In Progress			1/9/2012 9:35:39 AM					
Ontiveros, Joe		Please check into installing a new washing machine in the home economics room #203. The machine has been purchased, but there is no water supply or drain.							
Albert Vallejo									
88710		Athletic Field			6/7/2012		39		\$0.00
Medium	Work In Progress			6/7/2012 2:06:19 PM					
Ontiveros, Guadalupe		need to wire up electric valves to control for better watering on tree line by lisa Dr.							
Guadalupe Ontiveros									
87692					5/14/2012		63		\$0.00
Medium	Work In Progress			5/14/2012 3:23:10 PM					
Ontiveros, Guadalupe		Please remove dead trees on West side of campus.							
Albert Vallejo									
86024					4/2/2012		105		\$0.00
Medium	Work In Progress			4/2/2012 11:16:28 AM					
Ontiveros, Guadalupe		Please remove dead cherry tree in front of school and replace with another shade tree.							
Albert Vallejo									
87063					5/1/2012		76		\$0.00
Medium	Work In Progress			5/1/2012 8:46:53 AM					
Vallejo, Albert		Replace lamps and ballasts throughout entire building as needed.							
Albert Vallejo									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
88930	Main Building	Football Field			6/18/2012		28		\$0.00
Medium	Work In Progress			6/18/2012 8:49:24 AM					
Ontiveros, Guadalupe		Please recondition the football field and practice fields							
<u>Gidget Mora</u>									
88236	Main Building	Gym			5/29/2012		48		\$0.00
Medium	Work In Progress			5/29/2012 2:59:44 PM					
Gonzalez, Salvador		Need (6) expanded metal screens, approximately 12"x 30" to cover vents in gym.							
<u>Albert Vallejo</u>									
87797	Main Building	Classroom			5/16/2012		61		\$0.00
Medium	Work In Progress	103		5/16/2012 11:09:32 AM					
Vallejo, Albert		Lights burned out							
<u>Gidget Mora</u>									
84143					2/15/2012		152		\$0.00
Medium	Work In Progress			2/15/2012 9:36:35 AM					
Vallejo, Albert		Repair or replace damaged partitions in boys restroom in 200 hallway							
<u>Albert Vallejo</u>									
84144					2/15/2012		152		\$0.00
Medium	Work In Progress			2/15/2012 9:38:23 AM					
Vallejo, Albert		Repair damaged door and partition in main hall restroom.							
<u>Albert Vallejo</u>									
85175		Custodial			3/9/2012		129		\$0.00
Medium	Work In Progress			3/9/2012 8:44:01 AM					
Vallejo, Albert		Build shelves in Custodial rooms.							
<u>Albert Vallejo</u>									
76354					8/3/2011		348		\$0.00
Medium	Work In Progress			8/3/2011 10:27:46 AM					
Gonzalez, Salvador		Please fabricate expanded metal guard around exterior water fountain, located outside the gym door.							
<u>Albert Vallejo</u>									
84837					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:15 AM					
Munoz, Michael		Yearly - Chaparral MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
Count: 16 Work Orders		Avg. Age of WO's		111		Total for Chaparral MS		0 \$0.00	

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Pride							
88430					6/3/2012	6/9/2012	43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:22 AM					
Acosta, David	Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
84840					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:17 AM					
Munoz, Michael	Yearly - Desert Pride HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
88444					6/3/2012	6/11/2012	43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:27 AM					
Acosta, David	Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
88440					6/3/2012	6/11/2012	43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:26 AM					
Acosta, David	Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
84526					2/27/2012		140		\$0.00
Medium	Work In Progress	NURSE OFFICE		2/27/2012 11:57:02 AM					
Miranda, Danny	FLOOR IN NURSE OFFICE IS SAGGING DUE TO WEIGHT OF FILING CABINETS								
<u>David Acosta</u>									
87858		Classroom			5/17/2012		60		\$0.00
Medium	Work In Progress	ROOM 11		5/17/2012 1:26:38 PM					
Lara, Ralph	NEED KEY FOR LARGE CABINET.								
<u>David Acosta</u>									
88015		Classroom			5/22/2012		55		\$0.00
Medium	Work In Progress	Boxing Ring		5/22/2012 4:45:41 PM					
Ronquillo, Ruben	Attn: Ruben Ronquillo Replace motor on treadmill-endurance Model: XT-6800								
<u>Mary Telles</u>									
82145					12/15/2011		214		\$0.00
Medium	Work In Progress			12/15/2011 1:50:19 PM					
Lara, Ralph	AS PER MR CHAVEZ PLEASE ISSUE GATE KEYS TO ORLANDO GARCIA (SECURITY) THE FOLLOWING SCHOOLS VADO(A-1), NORTH VALLEY(CN-1), MESQUITE (C1).								
<u>Maritza Gonzalez</u>									
7/16/2012 11:48:10 AM									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Pride									
87934		Office			5/21/2012		56		\$0.00
Medium	Work In Progress	RESTROOM			5/21/2012 7:59:52 AM				
Lara, Ralph		NEED NEW KEY FOR RESTROOM DOOR.							
David Acosta									
88809					6/12/2012		34		\$0.00
Medium	Work In Progress				6/12/2012 1:54:04 PM				
Lara, Ralph		NEED A GATE KEY TO BE ISSUED TO EL PASO DISPOSAL, O.K. ASP ALFREDO.							
Mary Sitters									
Count: 10 Work Orders		Avg. Age of WO's		82	Total for Desert Pride			0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Desert Trail Intermediate									
86747					4/20/2012		87		\$0.00
Medium	Work In Progress	205		4/20/2012 7:34:40 PM					
Lozoya, Manny	Mrs. Ibarra in room #205 needs key made for her filing cabinet because it's locked and don't have key for it.								
Elizabeth Hernandez									
88927					6/18/2012		28		\$0.00
Medium	Work In Progress			6/18/2012 7:37:11 AM					
Lozoya, Manny	Need name plaque with: Luz E. Ochoa Clerk/Cook								
Johnny Acuna									
88315					5/31/2012	7/1/2012	46		\$0.00
Medium	Work In Progress			5/31/2012 12:24:37 AM					
Acuna, Johnny	Yearly - Desert Trail ES A2 (H&C Unit)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
88499					6/3/2012	7/4/2012	43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:48 AM					
Acuna, Johnny	Yearly - Desert Trail ES B2 (Boiler)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
85793					3/31/2012		107		\$0.00
Medium	Work In Progress			3/31/2012 12:21:30 AM					
Acuna, Johnny	Monthly - Desert Trail ES A16(Exhst Fan)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
87128					5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 9:16:11 AM					
Acuna, Johnny	Paint parking lot lines.								
Johnny Acuna									
87130					5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 9:17:58 AM					
Acuna, Johnny	Paint blue/green vinyl walls inside main building.								
Johnny Acuna									
87461					5/7/2012		70		\$0.00
Medium	Work In Progress			5/7/2012 4:06:17 PM					
Ronquillo, Ruben	Ruben Ronquillo: Need 8 Nuts, Bolts, and washers for new Portable classroom ramps.								
Johnny Acuna									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
88616					6/5/2012		41		\$0.00
Medium	Work In Progress			6/5/2012 12:53:15 PM					
Ontiveros, Guadalupe	Need to borrow tractor with scraper to clean out fencelines and in back of school grounds.								
Johnny Acuna									
85931					4/2/2012	4/9/2012	105		\$0.00
Medium	Work In Progress			4/2/2012 12:42:13 AM					
Acuna, Johnny	Monthly - Desert Trail Roof Inspection - Refer to PM schedule details.								
Margret Villalobos									
86324		Portables			4/11/2012		96		\$0.00
Medium	Work In Progress			4/11/2012 11:41:44 AM					
Holguin, Alfredo	Relocate Portable # 92 DM from; Chap Mid								
Richard Chavez									
88438					6/3/2012	6/11/2012	43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:25 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
88443					6/3/2012	6/11/2012	43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:27 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
88517					6/3/2012		43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:55 AM					
Acuna, Johnny	Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
86036					4/2/2012		105		\$0.00
Medium	Work In Progress			4/2/2012 1:54:19 PM					
Acuna, Johnny	requesting new backpack sprayer. Old one broken.								
Johnny Acuna									
87197					5/3/2012		74		\$0.00
Medium	Work In Progress			5/3/2012 8:37:23 AM					
Acuna, Johnny	Need window blinds for portable.								
		(2) 94"1/4 X 36"							
		(2) 30" X 60"							
Johnny Acuna									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Desert Trail Intermediate									
87350					5/6/2012	5/14/2012	71		\$0.00
Medium	Work In Progress			5/6/2012 12:17:34 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
87351					5/6/2012	5/14/2012	71		\$0.00
Medium	Work In Progress			5/6/2012 12:17:34 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
84747					3/1/2012		137		\$0.00
Medium	Work In Progress			3/1/2012 4:11:44 PM					
Acuna, Johnny	Need 88 replacement coat hooks for Desert Trail classrooms.								
<u>Johnny Acuna</u>									
81612					12/2/2011		227		\$0.00
Medium	Work In Progress			12/2/2011 12:13:03 PM					
Acuna, Johnny	Need cement runner for new exit gate wheels.		12/5 - Asp Mike route to Johnny						
<u>Johnny Acuna</u>									
88700					6/7/2012		39		\$0.00
Medium	Work In Progress			6/7/2012 9:10:25 AM					
Briones, Enrique	Please deliver one Gaylord box and one pallet								
<u>Michelle Tellez</u>									
88417					6/3/2012	6/9/2012	43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:17 AM					
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82671					1/11/2012		187		\$0.00
Medium	Work In Progress			1/11/2012 10:48:57 AM					
Lozoya, Manny	Portable #410: Door to classroom does not close properly. Door is too flimsy and probably needs replacing.								
<u>Johnny Acuna</u>									
82895					1/18/2012		180		\$0.00
Medium	Work In Progress			1/18/2012 9:57:21 AM					
Lozoya, Manny	Portable #409: Need to replace door as soon as possible, Badly damaged: Welds have come undone and door is wobbly.								
<u>Johnny Acuna</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
82725					1/12/2012		186		\$0.00
Medium	Work In Progress			1/12/2012 12:38:26 PM					
Lozoya, Manny	Portable #400 south door is too flimsy and needs replacing.								
Johnny Acuna									
84824					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:09 AM					
Munoz, Michael	Yearly - Desert Trail ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
83279					1/27/2012		40		\$0.00
Medium	Work In Progress			1/27/2012 11:11:35 AM		3/7/2012			
Orozco, Daniel	The outside metal cover from the walk-in refrigerator door is coming apart and doesn't close right. Also, the metal cover from the walk-in Freezer Wall is also coming apart. Thank You... SNP Manager Pat C. 824.3822								
Maritza Gonzalez									
76883					8/12/2011		339		\$0.00
Medium	Work In Progress			8/12/2011 11:50:32 AM					
Orozco, Daniel	1) SNEEZE SHIELD ON ASSEMBLY LINE WERE BROKEN BY STUDENTS. 2) LADIES ARE HAVING A HARD TIME WITH RAILS/COVERS IN OVEN IS, GETTING STUCK. SNP MANAGER PAT C. 824.3822								
Maritza Gonzalez									
84561					2/28/2012		139		\$0.00
Medium	Work In Progress			2/28/2012 8:30:15 AM					
Gonzalez, Salvador	Please add a new ladder rack to hold 8 Ft. ladder to worktruck #192 Frame.								
Johnny Acuna									
84564					2/28/2012		139		\$0.00
Medium	Work In Progress			2/28/2012 8:33:33 AM					
Gonzalez, Salvador	Need 2 metal posts and chain to be installed in the parking lot next to the new exit area.								
Johnny Acuna									
89187					6/26/2012		20		\$0.00
Medium	Work In Progress			6/26/2012 11:22:04 AM					
Villalobos, Margret	RAT SPOTTED IN STORAGE ROOM IN KITCHEN. SNP MANAGER PAT C. 824.3822								
Maritza Gonzalez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
87648					5/13/2012	5/29/2012	64		\$0.00
Medium	Work In Progress			5/13/2012 12:12:46 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
88744					6/10/2012	6/26/2012	36		\$0.00
Medium	Work In Progress			6/10/2012 12:15:14 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
85213					3/11/2012	3/27/2012	127		\$0.00
Medium	Work In Progress			3/11/2012 12:16:59 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
87860					5/17/2012		60		\$0.00
Medium	Work In Progress			5/17/2012 2:03:30 PM					
Estrada, Jesus	Please replace carpet to Portable #405 classroom.								
<u>Johnny Acuna</u>									
Count: 35 Work Orders			Avg. Age of WO's	95	Total for Desert Trail Intermediate			0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Desert View ES									
85743		Classroom			3/30/2012		108		\$0.00
Medium	Work In Progress	Rm. 22		3/30/2012 9:36:32 AM					
Lara, Ralph	Back door doesn't close. (Chavira)								
<u>Guadalupe Gonzalez</u>									
87738		Classroom			5/15/2012		62		\$0.00
Medium	Work In Progress	Port. 5, Rm. 7,		5/15/2012 10:39:13 AM					
,	Redo the tile in these classrooms; especially the restroom. Teachers want tile instead of carpet. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
78124					9/9/2011		311		\$0.00
Medium	Work In Progress			9/9/2011 2:44:06 PM					
Munoz, Michael	need to construct concret pad for trash dumpsters								
<u>Alfredo Holguin</u>									
85221					3/11/2012	3/27/2012	127		\$0.00
Medium	Work In Progress			3/11/2012 12:17:02 AM					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81989					12/11/2011	12/27/2011	218		\$0.00
Medium	Work In Progress			12/11/2011 12:14:25					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
86238					4/8/2012	4/24/2012	99		\$0.00
Medium	Work In Progress			4/8/2012 12:15:34 AM					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
87132					5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 10:14:05 AM					
Gonzalez, Salvador	Requesting a metal frame for banners and announcements in the front circle of the school, size 5 ft by 8 ft.								
<u>Ruben Ortiz</u>									
87182					5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 4:10:54 PM					
Orozco, Daniel	RACK IN WALK IN BROKE. SNP MANAGER DIANA L. 589.2425								
Maritza Gonzalez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
84825					3/4/2012		134		\$0.00
Medium	Work In Progress				3/4/2012 12:21:10 AM				
Munoz, Michael	Yearly - Desert View ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
85354		Cafeteria			3/15/2012		123		\$0.00
Medium	Work In Progress				3/15/2012 10:12:26 AM				
Lara, Ralph	need to have screen doors replaced in kitchen, they are old and warped								
<u>Daniel Orozco</u>									
77531		Office			8/29/2011		322		\$0.00
Medium	Work In Progress	Office			8/29/2011 3:18:32 PM				
Munoz, Michael	Move the existing counter towards the window located in the Office and move the Handicap table towards the door. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
83576					2/3/2012		164		\$0.00
Medium	Work In Progress				2/3/2012 2:04:04 PM				
Ontiveros, Guadalupe	Need two Flag poles replace and a new base for the new flag poles. Thank you Ruben								
<u>Ruben Ortiz</u>									
86870					4/25/2012		82		\$0.00
Medium	Work In Progress				4/25/2012 1:49:15 PM				
Ortiz, Ruben	Need to clean radiators on a/c refrigerated units								
<u>Ruben Ortiz</u>									
86428					4/13/2012		94		\$0.00
Medium	Work In Progress				4/13/2012 9:38:58 AM				
Ortiz, Ruben	Requesting the following items: 2 100 ft. water hose 2 50 ft. water hose Thank you, Ruben								
<u>Ruben Ortiz</u>									
86429					4/13/2012		94		\$0.00
Medium	Work In Progress				4/13/2012 9:45:01 AM				
Ortiz, Ruben	Requesting following items: Hand held blower A compressor Thank you, Ruben								
<u>Ruben Ortiz</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
86430					4/13/2012		94		\$0.00
Medium	Work In Progress			4/13/2012 9:58:55 AM					
Ortiz, Ruben	Requesting following items: Electric chain saw 2 100 ft. extension cord 1 50 ft. extension cord Thank you, Ruben								
<u>Ruben Ortiz</u>									
81766					12/4/2011	12/12/2011	225		\$0.00
Medium	Work In Progress			12/4/2011 12:17:04 AM					
Ortiz, Ruben	Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
86492					4/16/2012		91		\$0.00
Medium	Work In Progress			4/16/2012 9:47:25 AM					
Flores, Pete	Need fix a flat gel								
<u>Ruben Ortiz</u>									
88089		Library			5/24/2012		53		\$0.00
Medium	Work In Progress	Library		5/24/2012 12:11:20 PM					
Ortiz, Ruben	Please put up 4 bulletin boards (8x4) (Ms. Segura)								
<u>Guadalupe Gonzalez</u>									
88087		Classroom			5/24/2012		53		\$0.00
Medium	Work In Progress	Gym		5/24/2012 12:09:01 PM					
Ortiz, Ruben	Drill bulletin board into Gym wall. (Coach Reade)								
<u>Guadalupe Gonzalez</u>									
83160					1/25/2012		173		\$0.00
Medium	Work In Progress			1/25/2012 9:47:46 AM					
Ortiz, Ruben	Vandalism; sprinkler control pulled pipe and wire out that was connected to the portable; Officer E. Salazar case no. SPPD 201200125				2/23 - sent back to Ruben to fill out asp Mike				
<u>Ruben Ortiz</u>									
81788		Office			12/5/2011		224		\$0.00
Medium	Work In Progress	Office		12/5/2011 11:28:16 AM					
Ortiz, Ruben	Please assemble a projector cart for Ms. Autry. (Gonzalez)								
<u>Guadalupe Gonzalez</u>									
86871					4/25/2012		82		\$0.00
Medium	Work In Progress			4/25/2012 1:50:29 PM					
Ortiz, Ruben	Summer projects, repaint bathroom floors								
<u>Ruben Ortiz</u>									

7/16/2012 11:48:10 AM

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert View ES							
86872					4/25/2012		82		\$0.00
Medium	Work In Progress			4/25/2012 1:51:32 PM					
Ortiz, Ruben	Summer project, paint hallway, library, computer room and lounge								
Ruben Ortiz									
88088		Library			5/24/2012		53		\$0.00
Medium	Work In Progress	Library		5/24/2012 12:09:43 PM					
Ortiz, Ruben	Paint Library (Ms. Segura)								
Guadalupe Gonzalez									
88331					5/31/2012	7/1/2012	46		\$0.00
Medium	Work In Progress			5/31/2012 12:24:43 AM					
Ortiz, Ruben	Yearly - Desert View ES A-2 A/C SS Yearly - Refer to PM schedule details.								
Margret Villalobos									
89083					6/21/2012		25		\$0.00
Medium	Work In Progress			6/21/2012 8:03:05 AM					
Lara, Ralph	Custodial needs two Master keys replace. Thank you Ruben								
Ruben Ortiz									
85749		Library			3/30/2012		108		\$0.00
Medium	Work In Progress	Library		3/30/2012 1:59:15 PM					
Lara, Ralph	Broken key; it's stuck in the visual room in the Library and can't open or lock the door. (Gonzalez)								
Guadalupe Gonzalez									
83981					2/10/2012		157		\$0.00
Medium	Work In Progress			2/10/2012 3:20:49 PM					
Villalobos, David	Need outdoor water fountain replace on the east side of the school. Thank you Ruben								
Ruben Ortiz									
Count: 29 Work Orders			Avg. Age of WO's	123		Total for Desert View ES	0		\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
87941					5/21/2012		56		\$0.00
Medium	Work In Progress			5/21/2012 9:34:24 AM					
		, GROUND NEED TO BE CLEANED UP (WEEDS DEBRIS). THANK YOU.							
Maritza Gonzalez									
88933					6/18/2012		28		\$0.00
Medium	Work In Progress			6/18/2012 9:07:49 AM					
Villalobos, David		SINK LEAKING IN GIRLS RESTROOM, BEHIND RECEPTIONIST AREA IN B-WING.							
Maritza Gonzalez									
89053					6/20/2012		26		\$0.00
Medium	Work In Progress			6/20/2012 2:17:12 PM					
Castillo, Carlos		GAC SIDE MAIN ENTRANCE-NEED TO CONNECT ELECTRICAL TO HANDICAP ACCESS.							
Maritza Gonzalez									
81339					11/22/2011		237		\$0.00
High	Work In Progress			11/22/2011 1:59:42 PM					
Castillo, Carlos		boiler does not have an emergency shut off switch. please install one as per boiler inspectors site vist.thank you							
Michael Munoz									
86449					4/13/2012		94		\$0.00
Medium	Work In Progress			4/13/2012 2:51:23 PM					
Castillo, Carlos		AS PER MR. YTURREALDE HE WOULD LIKE TO SEE IF THERE IS ANY WAY A LIGHT SWITCH TO THE FRONT LOBBY CAN BE INSTALLED IN THE LOBBY AREA RATHER THAN THE FRONT RECEPTION AREA BEHIND DESK. GAC EMPLOYEES DO NOT HAVE ACCESS TO RECEPTION AREA.							
Maritza Gonzalez									
88182					5/25/2012		52		\$0.00
Medium	Work In Progress			5/25/2012 9:38:14 AM					
Lara, Ralph		MR. BAKER NEEDS A LOCK/KEY TO LOCK UP IMPORTANT DOCUMENTS ON ONE OF HIS FILE CABINETS.							
Priscilla Guterrez									
88649					6/6/2012		40		\$0.00
Medium	Work In Progress			6/6/2012 7:58:52 AM					
Lara, Ralph		DOOR TO CLOSET NEEDS TO BE INSTALLED IN ROOM 301.							
Maritza Gonzalez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
82996					1/20/2012		178		\$0.00
Medium	Work In Progress			1/20/2012 8:49:34 AM					
Ambriz, Jose	WALL UNITS DO NOT WORK NEED TO BE CHECKED/FIXED OR REPLACED AS NEEDED (AS PER MR. CHAVEZ) C-WING RMS. 205.206.207.208.209.210.211.212 requesting for units to be checked to see if they will be able to get fixed or if they have to be replaced. If replaced we would need a quote please.		Asp e-mail from Maritza hold wo - Mr. Chavez 1/20/12						
Maritza Gonzalez									
88831					6/12/2012		34		\$0.00
Medium	Work In Progress			6/12/2012 4:09:03 PM					
Ambriz, Jose	Server Room - Circuit #1 not working properly.								
Jose Ambriz									
89255					6/28/2012		18		\$0.00
Medium	Work In Progress	Office in C wing		6/28/2012 8:42:18 AM					
Rodriguez, Arturo	Please move several boxes from C wing to Ann's office								
Lucia Almeraz									
89276					6/28/2012		18		\$0.00
Medium	Work In Progress			6/28/2012 5:08:11 PM					
Rodriguez, Arturo	FLOORS OFFICE ETC NEED TO BE CLEANED IN ANN STEINHOFFS OLD OFFICE.								
Maritza Gonzalez									
89228					6/27/2012		19		\$0.00
Medium	Work In Progress			6/27/2012 3:02:20 PM					
Rodriguez, Arturo	WASP NEST ON WINDOW OUTSIDE OF COMPUTER LAB.								
Maritza Gonzalez									
89191					6/26/2012		20		\$0.00
Medium	Work In Progress	Technology		6/26/2012 2:44:59 PM					
Rodriguez, Arturo	Need help moving furniture. A/C and windows need cleaning...lots of dust								
Cora Ramirez									
88798					6/12/2012		34		\$0.00
Medium	Work In Progress			6/12/2012 9:35:00 AM					
Rodriguez, Arturo	AS PER MRS. YTURRALDE, SHE WOULD LIKE A PICTURE RELOCATED TO HER NEW OFFICE.								
Maritza Gonzalez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
89153					6/25/2012		21		\$0.00
Medium	Work In Progress			6/25/2012 1:53:19 PM					
Rodriguez, Arturo	Mr. Yturralde,								
	With your approval, we would like to submit a work order to take one desk out of Ms. Lindau's office and rearrange her office with one desk and the conference table.								
	Thank you,								
	Lupita Chavez Human Resources								
Maritza Gonzalez									
88975					6/19/2012		27		\$0.00
Medium	Work In Progress	Motor pool		6/19/2012 7:56:58 AM					
Flores, Pete	Please check car# 113 as per Dino Martinez and Ms.Steinhoff the car shakes a lot.								
Lucia Almeraz									
88976					6/19/2012		27		\$0.00
Medium	Work In Progress	Motor Pool #9		6/19/2012 7:58:31 AM					
Flores, Pete	Please check car # 9 as per Tina Guillen when she starts the car it make a funny noise.								
	thank you								
Lucia Almeraz									
88978					6/19/2012		27		\$0.00
Medium	Work In Progress	motor pool all		6/19/2012 8:05:23 AM					
Flores, Pete	Please maintance all Federal programs cars before Social workers get back from break #9, #13, #30, #85, #90, #91, #112, #115, #116,#145, #160, #161, #162,#173, #174, #103, #180 and #175 Thank you if you have any questions please contact Lucia Almeraz 882-6234								
Lucia Almeraz									
85659		Restroom (Girls)			3/28/2012		110		\$0.00
Medium	Work In Progress			3/28/2012 1:30:14 PM					
Mijarez, Jaime	Ladies Restroom - Wing A - light bulb flashing								
Cora Ramirez									
81626					12/2/2011		227		\$0.00
Medium	Work In Progress			12/2/2011 2:58:39 PM					
Mijarez, Jaime	WINDOW UNIT IN BARBARA C. AND ROSA A. OFFICE IN B-WING NEEDS TO BE CLEANED OUT, LOTS OF SAND.								
Maritza Gonzalez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		GAC							
81525					11/30/2011		229		\$0.00
Medium	Work In Progress			11/30/2011 3:11:39 PM					
Mijarez, Jaime	FILTERS ON FURNACES NEED TO BE CHANGED OUT THROUGH OUT BLDG.								
<u>Maritza Gonzalez</u>									
83105					1/24/2012		174		\$0.00
Medium	Work In Progress			1/24/2012 8:08:16 AM					
Mijarez, Jaime	Directory Holder needs to be mounted on Priscilla Escobar office wall.								
<u>Maritza Gonzalez</u>									
84139					2/15/2012		152		\$0.00
Medium	Work In Progress			2/15/2012 9:17:34 AM					
Marquez, Gerardo	Exit Signs - Both in cafe and HR wing not working and very loose asp PM 82330				2/21 - Asp Cali reroute back to Gerry.				
<u>Gerardo Marquez</u>									
79062					9/30/2011		290		\$0.00
Medium	Work In Progress			9/30/2011 4:29:51 PM					
Lara, Ralph	Entrance door on south side currently used to access GAC offices - install automatic door opener or door bell/buzzer that can be used by individuals with disabilities of open the door or get assistance to open the door								
<u>Alfredo Holguin</u>									
87983					5/22/2012		55		\$0.00
Medium	Work In Progress			5/22/2012 8:11:00 AM					
Carbajal, Jimmy	need to replace batteries (2) in the scrubber machine serial no 1721044								
<u>Arturo Rodriguez</u>									
84842					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:18 AM					
Munoz, Michael	Yearly - GAC Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
87795					5/16/2012		61		\$0.00
Medium	Work In Progress			5/16/2012 9:58:00 AM					
Gonzalez, Salvador	Silver spoke with Sal about welding a base for speakers in the board room.								
<u>Cora Ramirez</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
83845					2/8/2012		159		\$0.00
Medium	Work In Progress				2/8/2012 2:29:47 PM				
Gonzalez, Salvador		please fabricate gates for the front entrance. please see mike for details. thank you							
Richard Chavez									
89226					6/27/2012		19		\$0.00
Medium	Work In Progress				6/27/2012 2:29:37 PM				
Villalobos, Margret		BUGS IN MARY TELLES FINANCE HALL (B-WING) OFFICE PLEASE SPRAY.							
Maritza Gonzalez									
85824					4/2/2012		105		\$0.00
Medium	Work In Progress				4/2/2012 12:41:27 AM				
Holguin, Alfredo		Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									
Count: 30 Work Orders			Avg. Age of WO's	89			Total for GAC	0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		GAC - Pre-K							
83054					1/23/2012		175		\$0.00
Medium	Work In Progress	playground			1/23/2012 9:36:58 AM				
Mijarez, Jaime	Please blow off blue area on PreK playground around toyboxes & sidewalks								
<u>Lucia Almeraz</u>									
89052					6/20/2012		26		\$0.00
Medium	Work In Progress				6/20/2012 2:14:00 PM				
Lara, Ralph	LATCH TO OUTSIDE DOOR IS NOT WORKING PROPERLY. (ANGELIQUE CLASSROOM)		ASP RAFA, PENDING PARTS CAN NOT ORDER PARTS UNTIL NEW FISCAL YEAR.MG						
<u>Maritza Gonzalez</u>									
Count: 2 Work Orders			Avg. Age of WO's	101			Total for GAC - Pre-K	0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden ES							
82393		Athletic Field			1/5/2012		193		\$0.00
Medium	Work In Progress			1/5/2012 8:38:44 AM					
Sotelo, Enrique		need to line locate electric and gas and sewer for irrigation on plants. for info contact lupe							
<u>Guadalupe Ontiveros</u>									
86308		Mechanical			4/11/2012		96		\$0.00
Medium	Work In Progress			4/11/2012 7:36:39 AM					
Sanchez, Raul		Check to see if a filter can be installed on the domestic water.							
<u>Alfredo Holguin</u>									
86903		Athletic Field			4/26/2012		81		\$0.00
Medium	Work In Progress			4/26/2012 8:47:10 AM					
Sotelo, Enrique		as per our meeting, please provide power to brincas for splashday on may 24th. thank you							
<u>Michael Munoz</u>									
86904		Athletic Field			4/26/2012		81		\$0.00
Medium	Work In Progress			4/26/2012 8:51:18 AM					
Sotelo, Enrique		please provide power to vending booths on may 18th as per our meeting. thank you							
<u>Michael Munoz</u>									
88657		Parking Lot			6/6/2012		40		\$0.00
Medium	Work In Progress			6/6/2012 10:37:47 AM					
Holguin, Alfredo		Requesting 2 A-Frame barricades made of heavy material. Needed for front of school for students safety. Colors- orange, white and black with repective hazard markings... thank you greatly appreciate your assistance....							
<u>Loraine Gandara</u>									
88656		Parking Lot			6/6/2012		40		\$0.00
Medium	Work In Progress			6/6/2012 10:35:38 AM					
Ronquillo, Ruben		we are missing 2 signs " Buses Only" and for them to be placed on their respected poles... thank you greatly				ROUTED TO RUBEN ASP ALFREDO			
<u>Loraine Gandara</u>									
86901		Athletic Field			4/26/2012		81		\$0.00
Medium	Work In Progress			4/26/2012 8:38:24 AM					
Ronquillo, Ruben		please provide support with the setting of vending stands on may 18th @ 6:00 a.m. around west canopy. thank you							
<u>Michael Munoz</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden ES									
86905		Athletic Field			4/26/2012		81		\$0.00
Medium	Work In Progress			4/26/2012 8:54:01 AM					
Ronquillo, Ruben	please provide (loaners) 6- 100' water hoses for splash day on may24th. thank you								
Michael Munoz									
77578					8/30/2011		321		\$0.00
Medium	Work In Progress			8/30/2011 11:21:44 AM					
Marquez, Gerardo	please repair cracks walls, texture and paint thru-out site.thank you		Pending Summer 2012						
Michael Munoz									
84910					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:48 AM					
Munoz, Michael	Yearly - Gadsden ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
Count: 10 Work Orders		Avg. Age of WO's 115		Total for Gadsden ES			0	\$0.00	

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
84839					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:16 AM					
Munoz, Michael	Yearly - Gadsden HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
82222					1/1/2012		197		\$0.00
Medium	Work In Progress			1/1/2012 12:44:02 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
86322					4/11/2012		96		\$0.00
Medium	Work In Progress			4/11/2012 11:28:27 AM					
Holguin, Alfredo	Renew Permit for installation of Utility lines in Public Right of Way with NMDOT and IBWC								
<u>Alfredo Holguin</u>									
85825					4/2/2012		105		\$0.00
Medium	Work In Progress			4/2/2012 12:41:27 AM					
Holguin, Alfredo	Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
85823					4/2/2012		105		\$0.00
Medium	Work In Progress			4/2/2012 12:41:27 AM					
Holguin, Alfredo	Monthly - Gadsden HS - Fire Pump Engine(Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
88037					5/23/2012		54		\$0.00
Medium	Work In Progress			5/23/2012 10:28:12 AM					
Villalobos, Margret	Requested by the Football Coaching Staff-There are mice and roaches all over the Football Locker Room and Offices. Not a healthy work environment.		Waiting on price quote						
<u>Velia Alarcon</u>									
87789					5/16/2012		61		\$0.00
Medium	Work In Progress			5/16/2012 8:07:10 AM					
Ronquillo, Ruben	BROKEN WINDOW ON CLASS ROOM # 306 SINGLE GLASS AT ACADEMIC BUILDING								
<u>Joel Herrera</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
75625					7/21/2011		361		\$0.00
Medium	Work In Progress			7/21/2011 10:20:47 AM					
Sanchez, Raul	Domestic Water Storage Tank- Perform cleaning and inspections of interior of tank including the one at GMSI Inspection needs to be performed according to AWWA D101-53 Standard.		asp report 1/19/12 - Summer Job 2012						
Alfredo Holguin									
75626					7/21/2011		361		\$0.00
Medium	Work In Progress			7/21/2011 10:24:57 AM					
Sanchez, Raul	Domestic Water Storage Tank- install a 24" mesh wire screen or flapper valve on the overflow pipe. Do the same to the tank at GMS		asp report 1/19/12 - Summer Job 2012						
Alfredo Holguin									
88136					5/25/2012		52		\$0.00
Medium	Work In Progress			5/25/2012 8:46:50 AM					
Martinez, Larry	Requested by Mr. Pokluda-URGENT-Transfer equipment from room # 569 to Warehouse, items must be removed before June 1, 2012 as building will be demolished by contractors. -Hospital Beds-NO GISD TAG# Carl Perkins Grant -Hospital Scales-NO GISD TAG# Carl Perkins Grant -Computer-NO GISD TAG# Carl Perkins Grant NO PROGRAM @ G.H.S.								
Velia Alarcon									
79902					10/18/2011		272		\$0.00
Medium	Work In Progress			10/18/2011 12:52:25					
Gonzalez, Salvador	NEED TO CONSTRUCT SHADE AT GROUNDS DEPT. TO PROTECT IMPLEMENT.								
Guadalupe Ontiveros									
83481					2/1/2012		166		\$0.00
Medium	Work In Progress			2/1/2012 9:46:47 AM					
Gonzalez, Salvador	Requested by Coach Banister for Varsity Football Lockerroom-Need cage type door for shower room #2. See equipment room door as example. See Coach Banister for any questions.								
Velia Alarcon									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
76503					8/5/2011		0		\$0.00
Medium	Work In Progress				8/5/2011 11:12:06 AM	8/5/2011			
Gonzalez, Salvador	Requested by Lupe Quinones for Faculty Parking Lot- Install a cement ramp at the left far end by the "G" hall of the North Building. This ramp will serve as a come and go with the Security Golf Cart as well as for Maintenance Cart. By placing this ramp there well be two parking spaced eliminated. For further instruction please see Lupe Quinones.		8/5/11 - This needs to be approved by new administration. M. Munoz						
<u>Velia Alarcon</u>									
83567	Boys Gym	Gym			2/3/2012		164		\$0.00
Medium	Work In Progress				2/3/2012 8:19:11 AM				
Gonzalez, Salvador	need a screen made for dryer outlet so kids will not throw stuff in the pipe								
<u>Fred Appelzoller</u>									
78031	Boys Gym				9/7/2011		313		\$0.00
High	Work In Progress				9/7/2011 3:03:27 PM				
Herrera, Joel	please check all dressing rooms, bathrooms and shower to see if any painting needs done, all stalls are functional etc. this is a priority.thank you								
<u>Michael Munoz</u>									
81329	Cafeteria (1998)				11/22/2011		237		\$0.00
Medium	Work In Progress				11/22/2011 12:53:45				
Orozco, Daniel	as per psfa site visit. need to replace ceiling tiles in kitchen area and replacement of stained ones or dirty ones as well. thank you								
<u>Michael Munoz</u>									
75781	Main Building	Classroom			7/25/2011		357		\$0.00
Medium	Work In Progress				7/25/2011 2:01:50 PM				
Ambriz, Jose	Need to put new vents for ac units In class room to balance out air on the east side of building								
<u>Mario Apodaca</u>									
88806	Vocational	Classroom			6/12/2012		34		\$0.00
Medium	Work In Progress				6/12/2012 12:27:20 PM				
Lara, Ralph	We will need the cores to be installed on all doors on the Trades/Career Building at GHS on the week of July 23, 2012. For questions please contact Allan Journey at 575-644-0810 or Ralph Gallegos at 882-6921.								
<u>Rafael Gallegos</u>									
86868	Pool Pump	Pool			4/25/2012		82		\$0.00
Medium	Work In Progress				4/25/2012 1:40:07 PM				
Castillo, Carlos	Need for an electrician to connect the booster pump to the handicapped lift (3 phase power) Thanks, Raul								
<u>Raul Sanchez</u>									
7/16/2012 11:48:10 AM									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Gadsden HS

87796	Pool Pump	Pool			5/16/2012		61		\$0.00
-------	-----------	------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			5/16/2012 10:31:07 AM					
--------	------------------	--	--	-----------------------	--	--	--	--	--

Castillo, Carlos We need an electrician to check the voltage coming into the Pool pump house. Circulating pump motor is heating up and the amperage is high. We just shock treated the pool water this morning and need to keep the circulation going. This is of high priority. Thanks, Raul

Raul Sanchez

88031	Grounds Shop	Lift Station			5/23/2012		54		\$0.00
-------	--------------	--------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			5/23/2012 9:36:46 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Castillo, Carlos need assistance installing the new flow meters coming in for ghs so Gary from ted d miller associates can calibrate on June 6 2010

Mario Apodaca

88982	Grounds Shop				6/19/2012		27		\$0.00
-------	--------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress			6/19/2012 9:09:07 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Lara, Ralph requesting key HE163 for Richard Santillano to park the technology van in the ground shop gated area

Cora Ramirez

88937	Academic Bldg	Classroom			6/18/2012		28		\$0.00
-------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			6/18/2012 9:24:41 AM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Carbajal, Jimmy Whirlmatic burnisher 9800415 sets off the circuit breakers when operating

Joe Munoz

87682		Athletic Field			5/14/2012		63		\$0.00
-------	--	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress			5/14/2012 2:17:46 PM					
--------	------------------	--	--	----------------------	--	--	--	--	--

Ontiveros, Guadalupe Requested by Coach L. Chavez for Softball Fields-
 Wood Dugouts--2x6 fascia
 4x8 metal roofing--metal flashing
 2x6 trusses--metal drip cap
 metal fasteners--shelving (metal)
 wood fastener--raise fencing around bull pen
 electrical boxes/in storage/dugout on both sides
 Paint gold/maroon/white (not vegas gold)
 hog ties
 fencing 6' perimeter
 3-2x6 door chain link fence
 Perimeter fence needs to be pulled & anchored down w/hog ties.
 Electrical box installed at score board
 Fix water fountains at backstop and behind bleachers.
 FOR FURTHER INSTRUCTIONS SEE COACH L. CHAVEZ

Velia Alarcon

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
88810		Athletic Field			6/12/2012		34		\$0.00
Medium	Work In Progress			6/12/2012 1:58:01 PM					
Ontiveros, Guadalupe		need to replaced broken irrigation valves at FFA field so that we can water with canal the practice fields.							
<u>Guadalupe Ontiveros</u>									
86658					4/19/2012		88		\$0.00
Medium	Work In Progress			4/19/2012 9:50:33 AM					
Ontiveros, Guadalupe		Requested by Coach Lawrence for Soccer Fields- Replace soccer nets on all three sets of goals.							
<u>Velia Alarcon</u>									
88711		Athletic Field			6/7/2012		39		\$0.00
Medium	Work In Progress			6/7/2012 2:30:19 PM					
Ontiveros, Guadalupe		need to wire up control valves to timer for baseball and softball.							
<u>Guadalupe Ontiveros</u>									
86856					4/25/2012		82		\$0.00
Medium	Work In Progress			4/25/2012 7:29:24 AM					
Appelzoller, Fred		please assist chris licking w/ FMS engineering with plumbing questions and line locations today @ 11:00. thank you							
<u>Rafael Gallegos</u>									
87683					5/14/2012		63		\$0.00
Medium	Work In Progress			5/14/2012 2:20:27 PM					
Castillo, Carlos		Requested by Ms. R. Rodriguez for I.E.P. Room in Main Building-Enfocus needs an electrical wired outlet into the ceiling by the district electrician.							
<u>Velia Alarcon</u>									
86829					4/24/2012		83		\$0.00
Medium	Work In Progress			4/24/2012 2:54:55 PM					
Castillo, Carlos		Getting 6 new printers in different areas on campus. Need to make sure that there is a 20 amp electrical outlet. Please see computer tech (Omar Perales) for locations.							
<u>Cora Ramirez</u>									
89155					6/25/2012		21		\$0.00
Medium	Work In Progress			6/25/2012 3:20:07 PM					
Castillo, Carlos		As per R.Sanchez,need to check tratment plant blowers starters,they keep tripping.							
Carlos Castillo									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
87741					5/15/2012		62		\$0.00
Medium	Work In Progress			5/15/2012 11:13:17 AM					
Castillo, Carlos	Need help to locate a electric short in the weight room. Thank you								
Guillermo Hernandez									
86282					4/10/2012		97		\$0.00
Medium	Work In Progress			4/10/2012 3:17:54 PM					
Castillo, Carlos	As per R.Sanchez,new irrigation pump not working.								
Carlos Castillo									
78771					9/26/2011		294		\$0.00
Medium	Work In Progress			9/26/2011 11:08:07 AM					
Hernandez, Guillermo	Requested by Mr. D. Martinez for Cafeteria Entrance- Requesting to have the awnings located outside the entrances of the cafeteria painted the same color as the cafeteria doors.								
Velia Alarcon									
78772					9/26/2011		294		\$0.00
Medium	Work In Progress			9/26/2011 11:13:48 AM					
Hernandez, Guillermo	Requested by Mr. D. Martinez for Cafeteria-Requesting that the window frames inside and outside of the cafeteria be painted the same color as the cafeteria doors. -The color for the cafeteria doors was chosen the week of 09/19/11. We would like to match the color requested to the color on the window frames of the New Administrative/Library Building.								
Velia Alarcon									
84484					2/24/2012		143		\$0.00
Medium	Work In Progress			2/24/2012 2:59:52 PM					
Lara, Ralph	Need to replace double doors and frame to the washer/ Dryer room at the Boy's Gym. Also center blocks are getting loose. Thank you								
Guillermo Hernandez									
89090					6/21/2012		25		\$0.00
Medium	Work In Progress			6/21/2012 2:35:31 PM					
Lara, Ralph	Requested by Velia for Business Building Rooms 605 & 657-Door cylinders need to be re-keyed to be universal. Centralized printers will be placed in these two locations and this w.o. needs to be completed before the end of the last week of July. This will allow all teachers in the building access to these two areas.								
Velia Alarcon									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
89091					6/21/2012		25		\$0.00
Medium	Work In Progress			6/21/2012 2:38:29 PM					
Lara, Ralph	Requested by Velia for Cafeteria-Most of the door knobs going into the Cafeteria are broken and need to be replaced.								
<u>Velia Alarcon</u>									
84342					2/22/2012		145		\$0.00
Medium	Work In Progress			2/22/2012 8:19:13 AM					
Ambriz, Jose	Need to replace broken toggle switch to furnace in boys Gym. Thank you								
<u>Guillermo Hernandez</u>									
87740					5/15/2012		62		\$0.00
Medium	Work In Progress			5/15/2012 11:06:57 AM					
Ambriz, Jose	JOSE WE NEED INSTALL THERMOSTH AT PRESS ROOM AT FOOTBOOL FIELD								
<u>Joel Herrera</u>									
86739					4/20/2012		87		\$0.00
Medium	Work In Progress			4/20/2012 3:46:59 PM					
Ambriz, Jose	Need assistance to trouble shooting A/C's units in Old English. Thank you								
<u>Guillermo Hernandez</u>									
85318					3/14/2012		124		\$0.00
Medium	Work In Progress			3/14/2012 11:32:10 AM					
Herrera, Joel	Requested by Coach Letz for Girl's Gym-Green marker has been used to write on walls in locker room and gym, walls need to be painted.								
<u>Velia Alarcon</u>									
78777					9/26/2011		294		\$0.00
Medium	Work In Progress			9/26/2011 11:48:49 AM					
Herrera, Joel	Requested by Mr. D. Martinez-After WORK ORDER # 78775 is completed. The short blue/gray wall in front of the Cafeteria needs to be painted.								
<u>Velia Alarcon</u>									
89093					6/21/2012		25		\$0.00
Medium	Work In Progress			6/21/2012 2:47:11 PM					
Herrera, Joel	Requested by Velia for Cafeteria-Paint all rails in the Cafeteria maroon before the start of the new school year.								
<u>Velia Alarcon</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden HS							
89094					6/21/2012		25		\$0.00
Medium	Work In Progress			6/21/2012 2:50:36 PM					
Herrera, Joel	Requested by Velia for Cafeteria-Paint all doors of the Cafeteria maroon or yellow (what ever color is available) before the new school year begins. A Custodial Work Order was submitted to first have all doors clean of grime before painting takes place.								
<hr/>									
85234		Lift Station			3/12/2012		126		\$0.00
Medium	Work In Progress			3/12/2012 2:23:49 PM					
Castillo, Carlos	Trouble with control panel of the lift station north side of campus								
<hr/>									
Mario Apodaca									
Count: 46 Work Orders			Avg. Age of WO's	122		Total for Gadsden HS	0		\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
87136					5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 12:46:25 PM					
Diaz, Sebastian	Need paint floor in couches storage thank you								
<u>Sebastian Diaz</u>									
87137					5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 12:47:55 PM					
Diaz, Sebastian	Need paint some rooms in BA wings thank you								
<u>Sebastian Diaz</u>									
81621		Parking Lot			12/2/2011		227		\$0.00
Medium	Work In Progress	GMS Parking lot		12/2/2011 2:39:34 PM					
Diaz, Sebastian	Paint GMS Parking lot.								
<u>Maricruz Carrasco</u>									
89045					6/20/2012		26		\$0.00
High	Work In Progress			6/20/2012 8:27:08 AM					
Diaz, Sebastian	front center gate, the chain was cut last night. please replace and clook into any vandalism. thank you.								
<u>Michael Munoz</u>									
88610	C-Wing	Portables			6/5/2012		41		\$0.00
Medium	Work In Progress	TRANSPORTAT		6/5/2012 9:56:53 AM					
Diaz, Sebastian	AS PER MARY GARCIA-NEED 2 HANGING FILING CABINETS INSTALLED ON WALL.								
<u>Mary Garcia</u>									
87999	C-Wing				5/22/2012		55		\$0.00
Medium	Work In Progress	Charter School		5/22/2012 3:31:18 PM					
Munoz, Michael	Need to install a 5 ' fence w a 3' gate around gas meter in the front campus of the charter school locted next to GMS. thank you								
<u>Michael Munoz</u>									
85734	C-Wing				3/30/2012		108		\$0.00
High	Work In Progress	Charter School		3/30/2012 7:39:30 AM					
Ambriz, Jose	need to replave existing heat-pumps with new units with fresh-air vents. (IAQ)								
<u>Alfredo Holguin</u>									
87811	C-Wing	Parking Lot			5/16/2012		61		\$0.00
Medium	Work In Progress			5/16/2012 3:33:34 PM					
Appelzoller, Fred	broken shut off valve for fire hydrant need to replace								
<u>Fred Appelzoller</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
87798	Gym	Gym			5/16/2012		61		\$0.00
Medium	Work In Progress	Gym/Girls and			5/16/2012 11:32:54 AM				
Diaz, Sebastian	Paint boys and girls restrooms in they gym lockerrooms.								
Maricruz Carrasco									
87935	Gym				5/21/2012		56		\$0.00
Medium	Work In Progress				5/21/2012 8:14:25 AM				
Diaz, Sebastian	as per our meeting please paint the athletic storage room in the gym. floor and room. thank you								
Michael Munoz									
87936	Gym	Gym			5/21/2012		56		\$0.00
Medium	Work In Progress				5/21/2012 8:15:40 AM				
Lozoya, Manny	THE CORES TO BE CHANGED OUT TO GYM DOORS FOR GYM FLOOR TO BE REFINISHING JUNE 11 TO 22								
Juan Acosta									
86394	Gym	Classroom			4/12/2012		95		\$0.00
Medium	Work In Progress				4/12/2012 2:57:58 PM				
Solis, Lorenzo	Room 602 in the gym at GMS is not showing up on Tracer ES. I do not know what the problem is, please check out the unit and get it back on line. For questions call Ralph Gallegos @ 882-6921. Thanks.								
Rafael Gallegos									
87937	Gym				5/21/2012		56		\$0.00
Medium	Work In Progress				5/21/2012 8:16:13 AM				
Gonzalez, Salvador	need to fabricate and install a metal cage with doors in the athletic storage room this summer. please see mike for details. thank you								
Michael Munoz									
84055					2/13/2012		154		\$0.00
Medium	Work In Progress				2/13/2012 2:05:27 PM				
Orozco, Daniel	AS PER HEALTH INSPECTOR - WALK IN FRIDGE DOOR HAS TO BE FIXED TO CLOSE PROPERLY. SNP MANAGER TERRY P. 882.2824								
Maritza Gonzalez									
86718					4/20/2012		87		\$0.00
Medium	Work In Progress				4/20/2012 2:39:14 PM				
Apodaca, Mario	need to order parts for the water pressure tank at gms ckeck valve and galv steel nipples								
Mario Apodaca									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Gadsden MS							
86986					4/30/2012		77		\$0.00
Medium	Work In Progress				4/30/2012 12:30:12 AM				
Apodaca, Mario	Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
89283					6/30/2012		16		\$0.00
Medium	Work In Progress				6/30/2012 12:26:03 AM				
Apodaca, Mario	Monthly - Gadsden MS - Monthly Meter Readings - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
84835					3/4/2012		134		\$0.00
Medium	Work In Progress				3/4/2012 12:21:14 AM				
Munoz, Michael	Yearly - Gadsden MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
Count: 18 Work Orders		Avg. Age of WO's 81		Total for Gadsden MS			0	\$0.00	

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
84826					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:10 AM					
Munoz, Michael	Yearly - La Union ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
88421					6/3/2012	6/9/2012	43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:18 AM					
Aguilar, Patricio	Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
84481					2/24/2012		143		\$0.00
Medium	Work In Progress			2/24/2012 2:50:00 PM					
Aguilar, Patricio	need a 42" door weep for r210 frount door - thanks for your help								
<u>Patricio Aguilar</u>									
86560	Main Building				4/17/2012		90		\$0.00
Medium	Work In Progress			4/17/2012 2:05:53 PM					
Lara, Ralph	Main Entry on North Side- Doors are loose and need weatherstripping all around.								
<u>Alfredo Holguin</u>									
87088					5/1/2012		76		\$0.00
Medium	Work In Progress			5/1/2012 2:54:28 PM					
Aguilar, Patricio	wo to me - remove old wood boards yard								
<u>Patricio Aguilar</u>									
88459					6/3/2012	6/11/2012	43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:33 AM					
Aguilar, Patricio	Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
88451					6/3/2012	6/11/2012	43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:30 AM					
Aguilar, Patricio	Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
87086					5/1/2012		76		\$0.00
Medium	Work In Progress			5/1/2012 2:50:12 PM					
Aguilar, Patricio	wo to me - repair rest room r111								
<u>Patricio Aguilar</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		La Union ES							
89251					6/27/2012		19		\$0.00
Medium	Work In Progress			6/27/2012 5:44:12 PM					
Aguilar, Patricio	Need to trim the hedges on the North side of La Union Elementary so that Samcon the General Contractor can install the new Kal-Wal windows. They will need 16 – 18 inches of space between the building and the hedges to do the work. For more details or information please contact Ralph Gallegos at 882-6921 or 650-9095. They expected date for work to start in that area is July 23, 2012.								
Rafael Gallegos									
87085					5/1/2012		76		\$0.00
Medium	Work In Progress			5/1/2012 2:49:07 PM					
Aguilar, Patricio	wo to me - paint parking lines								
Patricio Aguilar									
87087					5/1/2012		76		\$0.00
Medium	Work In Progress			5/1/2012 2:51:18 PM					
Aguilar, Patricio	wo to me - paint class room old wing								
Patricio Aguilar									
81336		Cafeteria			11/22/2011		237		\$0.00
High	Work In Progress			11/22/2011 1:24:10 PM					
Castillo, Carlos	boiler to kitchen does not have an emergency shut off switch. please install one as per boiler inspectors site visit boiler sn 9209102691								
Michael Munoz									
80091					10/21/2011		269		\$0.00
Medium	Work In Progress			10/21/2011 3:43:54 PM					
Castillo, Carlos	need 2 light fixer for build out side wall new wing cort yard - thank you - go cowboys								
Patricio Aguilar									
79421					10/5/2011		285		\$0.00
Medium	Work In Progress			10/5/2011 1:52:11 PM					
Castillo, Carlos	need to relocate elect outlet from wall to above counter may need to use gfi - thank you								
Patricio Aguilar									
79695					10/12/2011		278		\$0.00
Medium	Work In Progress			10/12/2011 2:46:16 PM					
Castillo, Carlos	need ballast for light fixer with emer light in it - need new emer light fixer set up								
Patricio Aguilar									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
83248					1/26/2012		172		\$0.00
Medium	Work In Progress			1/26/2012 3:08:45 PM					
Castillo, Carlos	need new light fixer for rest room r309 the ballast is bad - thank you for your help								
Patricio Aguilar									
76712					8/9/2011		342		\$0.00
Medium	Work In Progress			8/9/2011 2:54:02 PM					
Villalobos, David	need faucet for hand sink in women rest room new wing - also need the two cut off valves under sink								
Patricio Aguilar									
78717					9/23/2011		297		\$0.00
Medium	Work In Progress			9/23/2011 10:13:59 AM					
Villalobos, David	need a new water line for new refrigerator ice maker in the new wing teachers lounge								
Patricio Aguilar									
80774					11/7/2011		252		\$0.00
Medium	Work In Progress			11/7/2011 2:32:07 PM					
Villalobos, David	HOT HOT WATER IN KITCHEN.SNP MANAGER LINDA Y.589.2040								
Maritza Gonzalez									
Count: 19 Work Orders			Avg. Age of WO's	155		Total for La Union ES	0		\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
88030					5/23/2012		54		\$0.00
Medium	Work In Progress			5/23/2012 9:19:09 AM					
Sotelo, Enrique	KITCHEN-EXHAUST FAN ON HOOD HAS ELECTRICAL SHORT. AS PER DANNY O. ELECTRICIAN NEEDS TO LOOK AT. SNP MANAGER FRANCES B. 882.4707								
<u>Maritza Gonzalez</u>									
87706		Athletic Field			5/14/2012		63		\$0.00
High	Work In Progress			5/14/2012 3:46:33 PM					
Arreola, Rudy	need to add compost and re-seed areas in playing fields where grass is no onger visible. thank you								
<u>Michael Munoz</u>									
86323		Portables			4/11/2012		96		\$0.00
Medium	Work In Progress			4/11/2012 11:36:56 AM					
Holguin, Alfredo	Relocate Portables # 2DW and 80DW from San Miguel Elem to LL.								
<u>Richard Chavez</u>									
86721		Athletic Field			4/20/2012		87		\$0.00
Medium	Work In Progress			4/20/2012 2:45:26 PM					
Flores, Pete	NEED TO HAVE SPARE MOWER DELIVERED TO LOMALINDA.								
<u>Rudy Arreola</u>									
89796					6/28/2012		18		\$0.00
Medium	Work In Progress			7/12/2012 10:25:32 AM					
Ronquillo, Ruben	Stolen Dewalt Battery and Grinder Pack 18v.								
<u>Rudy Arreola</u>									
87697					5/14/2012		63		\$0.00
Medium	Work In Progress			5/14/2012 3:39:44 PM					
Arreola, Rudy	please remove sand along the curbs on the bus turn around. thank you and install a small asphalt or concrete ramp for vehicules on the corner by the hydrant.								
<u>Michael Munoz</u>									
86722	Main Building	Portables			4/20/2012		87		\$0.00
Medium	Work In Progress			4/20/2012 2:46:31 PM					
Gonzalez, Salvador	RAMP WAS BROKEN DURING UNLOADING PROCESS NEEDS TO BE REWELED.								
<u>Rudy Arreola</u>									
81806	Main Building	Office			12/5/2011		224		\$0.00
Medium	Work In Progress			12/5/2011 3:18:57 PM					
Solis, Lorenzo	NEED MOTOR FOR FAN COIL IN FRONT OFFICE ALSO NEED SUPPORT FOR INSTALLATION.								Reprint 6/14/12 -asp Lorenzo
<u>Rudy Arreola</u>									
7/16/2012 11:48:10 AM									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Loma Linda ES									
89222	Main Building	Portables			6/27/2012		19		\$0.00
Medium	Work In Progress			6/27/2012 11:28:55 AM					
Lozoya, Manny	DOOR FOR PORTABLES ARE LOOSE AND THE FRAMES ALSO								
Rudy Arreola									
86720	Main Building	Athletic Field			4/20/2012		87		\$0.00
Medium	Work In Progress			4/20/2012 2:44:34 PM					
Flores, Pete	NEED NEW BATTERY FOR RIDING MOWER.								
Rudy Arreola									
82571	Main Building	Choral			1/9/2012		189		\$0.00
Medium	Work In Progress			1/9/2012 3:09:16 PM					
Arreola, Rudy	NEED BLINDS REPLACED 62x68. ALMOND COLOR TOTAL OF 40								
Rudy Arreola									
88940		Portables			6/18/2012		28		\$0.00
Medium	Work In Progress			6/18/2012 11:15:54 AM					
Munoz, Michael	need sidewalks to portables that were re-located from san miguel.								
Michael Munoz									
88941					6/18/2012		28		\$0.00
Medium	Work In Progress			6/18/2012 11:19:25 AM					
Munoz, Michael	sidewalk by fire hydrant on back playground is cracked and needs replacement(trip hazard) as well as sidewalk on back by portables along chainlink fence, also need a small concrete ramp for maintenance vehicle access by hydrant as well.								
Michael Munoz									
84827					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:11 AM					
Munoz, Michael	Yearly - Loma Linda ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
83566					2/3/2012		164		\$0.00
Medium	Work In Progress			2/3/2012 8:17:00 AM					
Gonzalez, Salvador	need a stand for drinking fountain made 10 inches wide by 60 inches long with 48 inch of 1 by 1 inch square tubing for the legs								
Fred Appenzoller									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Loma Linda ES							
88942					6/18/2012		28		\$0.00
High	Work In Progress			6/18/2012 11:29:42 AM					
Gonzalez, Salvador		need bollards around fire hydrant on the north east side of campus by playground.thank you							
Michael Munoz									
Count: 16 Work Orders		Avg. Age of WO's		86	Total for Loma Linda ES			0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
77100					8/18/2011		333		\$0.00
Medium	Work In Progress			8/18/2011 9:22:00 AM					
Gonzalez, Salvador	8/18/11 I need welder to fabricate an aluminum cover for the sewage pumps at Mesquite Elementary wwtp ASAP,thanks Raul								
Raul Sanchez									
81425					11/29/2011		230		\$0.00
Medium	Work In Progress			11/29/2011 7:39:32 AM					
Gonzalez, Salvador	need security bars installed in rms. 505,506. 2nd request								
Joe Ramirez									
88344					5/31/2012		46		\$0.00
Medium	Work In Progress			5/31/2012 1:26:41 PM					
Carrasco, Danny	FOOT PEDAL ON LAVATORY IN KITCHEN THE SPRINGS CAME OUT.								
Joe Ramirez									
88227		Classroom			5/29/2012		48		\$0.00
Medium	Work In Progress	Room # 108		5/29/2012 10:29:22 AM					
Villalobos, Margret	Room # 108 need to be sprayed for bugs many different kinds.		Waiting on price quote						
Sandra Mora									
84828					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:11 AM					
Munoz, Michael	Yearly - Mesquite ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
88808		Custodial			6/12/2012		34		\$0.00
Medium	Work In Progress			6/12/2012 12:34:17 PM					
Briones, Enrique	please Warehouse ATT: LARRY MARTINES we have broken computer desk, old furniture, student desk broken, etc. thank you								
Luis Saucedo									
88339					5/31/2012		46		\$0.00
Medium	Work In Progress			5/31/2012 10:30:21 AM					
Flores, Pete	need to replace water pump on truck 141.								
Joe Ramirez									
85532					3/26/2012		112		\$0.00
Medium	Work In Progress			3/26/2012 8:31:54 AM					
Ramirez, Joe	need to spread weed n feed thru out campus grass area								
Joe Ramirez									
7/16/2012 11:48:10 AM									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Mesquite ES							
79890					10/18/2011		272		\$0.00
High	Work In Progress			10/18/2011 8:52:04 AM					
Ramirez, Joe	Need to hook up to the existing irrigation system on the playing fields to irrigate when ebid does not provide water.								
<u>Michael Munoz</u>									
88767					6/11/2012		35		\$0.00
Medium	Work In Progress			6/11/2012 2:50:10 PM					
Ontiveros, Joe	please on north side girls restrooms a water line is broken inside of the blg. thank you								
<u>Luis Saucedo</u>									
87992					5/22/2012		55		\$0.00
Medium	Work In Progress			5/22/2012 2:19:37 PM					
Ontiveros, Joe	please look into connecting the irrigation system to new well. thank you								
<u>Michael Munoz</u>									
89182					6/26/2012		20		\$0.00
Medium	Work In Progress			6/26/2012 8:31:36 AM					
Ramirez, Joe	need to re-paint front office and principals' office.								
<u>Joe Ramirez</u>									
88481					6/3/2012	7/4/2012	43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:41 AM					
Ramirez, Joe	Yearly - Mesquite ES B-2 Boiler Yearly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
87195					5/3/2012		74		\$0.00
Medium	Work In Progress			5/3/2012 8:14:51 AM					
Solis, Lorenzo	NEED TO REPLACE A/C SUPPORT STANDS THE MEASUREMENTS ARE 42" LONG X 9" TALL X 4" WIDE, I NEED A TOTAL OF 16								
<u>Joe Ramirez</u>									
88025					5/23/2012		54		\$0.00
Medium	Work In Progress			5/23/2012 8:45:38 AM					
Ramirez, Joe	need to re-paint rm. 401								
<u>Joe Ramirez</u>									
88026					5/23/2012		54		\$0.00
Medium	Work In Progress			5/23/2012 8:46:42 AM					
Ramirez, Joe	need to re-paint all exterior doors								
<u>Joe Ramirez</u>									
Count: 16 Work Orders	Avg. Age of WO's		99		Total for Mesquite ES			0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		North Valley ES							
86648		Classroom			4/19/2012		88		\$0.00
Medium	Work In Progress	102/104			4/19/2012 8:15:07 AM				
Ontiveros, Joe		Foul odor emanating from ? Please come out to check teachers complaining and students getting sick.							
<u>Priscilla Martinez</u>									
87791		Athletic Field			5/16/2012		61		\$0.00
Medium	Work In Progress	Kinder			5/16/2012 8:42:10 AM				
Munoz, Michael		Remove the gravel from the Kinder playground and install grass. Need chain link fence placed around the Kinder playground.							
<u>Priscilla Martinez</u>									
82224					1/1/2012		197		\$0.00
Medium	Work In Progress				1/1/2012 12:44:03 AM				
Holguin, Alfredo		Monthly - North Valley ES-Fire Pump PM (Quarterly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
84829					3/4/2012		134		\$0.00
Medium	Work In Progress				3/4/2012 12:21:12 AM				
Munoz, Michael		Yearly - North Valley ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
85827					4/2/2012		105		\$0.00
Medium	Work In Progress				4/2/2012 12:41:28 AM				
Holguin, Alfredo		Monthly - North Valley ES-Fire Pump Engine (Quarterly) - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
86124					4/4/2012		103		\$0.00
Medium	Work In Progress				4/4/2012 8:53:30 AM				
Vega, Danny		attentio danny c. need to send plygrd canopy appx 48ft x 36ft to get repaired has section 25 ft torn on top beam							
<u>Danny Vega</u>									
86961					4/27/2012		80		\$0.00
Medium	Work In Progress				4/27/2012 2:33:56 PM				
Gonzalez, Salvador		as per our meeting this morning, please order material and install the brackets /braces for the swings in the sped rooms at the following site. NVE,GES,AE,STHS,STE,SRE,CHS							
<u>Michael Munoz</u>									
Count: 7 Work Orders			Avg. Age of WO's	110	Total for North Valley ES			0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: Northern On-Track Pre-K (LM)										
88604					6/5/2012		41		\$0.00	
Medium	Work In Progress			6/5/2012 12:14:57 AM						
Apodaca, Mario	Monthly - Northern Pre-K- Domestic Water Filters - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
84621					2/29/2012	3/11/2012	138		\$0.00	
Medium	Work In Progress			2/29/2012 12:24:57 AM						
Munoz, Michael	Yearly - Northern Pre-K Fire Ext. Insp. (Yearly) - Refer to PM schedule details.									
<u>Margret Villalobos</u>										
85446	Main Building				3/19/2012		119		\$0.00	
Medium	Work In Progress			3/19/2012 12:40:38 PM						
Ontiveros, Guadalupe	need some landscaping where shrubs were removed.please see mike for details. thank you									
<u>Michael Munoz</u>										
87210	Main Building				5/3/2012		74		\$0.00	
Medium	Work In Progress			5/3/2012 3:16:36 PM						
Ontiveros, Joe	install water outside of building on north side in playground area.									
<u>Alfredo Holguin</u>										
88225					5/29/2012		48		\$0.00	
High	Work In Progress			5/29/2012 9:56:37 AM						
Ramirez, Joe	please support with moving of furniture for new construction to be done. thank you									
<u>Michael Munoz</u>										
Count: 5 Work Orders			Avg. Age of WO's	84	Total for Northern On-Track Pre-K (LM)			0	\$0.00	

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Physical Plant Complex							
86936					4/26/2012		81		\$0.00
Medium	Work In Progress			4/26/2012 3:49:45 PM					
Apodaca, Mario		Need two new water hose about 75 feet							
Mario Apodaca									
88078					5/24/2012		53		\$0.00
Medium	Work In Progress			5/24/2012 12:16:01 AM					
Holguin, Alfredo		Yearly - PPD - Maintenance Plan - Refer to PM schedule details.							
Margret Villalobos									
88402					6/1/2012		45		\$0.00
Medium	Work In Progress			6/1/2012 3:53:57 PM					
Gonzalez, Salvador		6-1-12 I need A/C in morgans welding shop ASAP, Thanks.							
Salvador Gonzalez									
88099					5/24/2012		53		\$0.00
Medium	Work In Progress			5/24/2012 2:22:59 PM					
Flores, Pete		Vehicle #138 - AC is not cooling very good.							
Alfredo Holguin									
89214					6/27/2012		19		\$0.00
Medium	Work In Progress			6/27/2012 6:32:08 AM					
Diaz, Sebastian		Entrance roadway from Washington St. - Install speed limit signs. I recomend 10MPH. Verify with Mike M.							
Alfredo Holguin									
88754					6/11/2012		35		\$0.00
High	Work In Progress			6/11/2012 8:26:46 AM					
Flores, Pete		Truck #16 leaked out water.							
Jesus Estrada									
87979					5/22/2012		55		\$0.00
Medium	Work In Progress			5/22/2012 7:16:06 AM					
Flores, Pete		Truck #16 sideview mirror (drivers side) knocked off.							
Jesus Estrada									
86802					4/24/2012		83		\$0.00
Medium	Work In Progress			4/24/2012 8:35:05 AM					
Flores, Pete		vehicle #108 ...needs servicing							
Cora Ramirez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
84576					2/28/2012		139		\$0.00
Medium	Work In Progress			2/28/2012 12:53:18 PM					
Flores, Pete	PLEASE SERVICE PPD WHS. FORKLIFT, ALSO BATTERY IS GETTING WEAK. THANK YOU!								
<u>Ruben Ronquillo</u>									
78847					9/27/2011		293		\$0.00
Medium	Work In Progress			9/27/2011 1:14:25 PM					
Ontiveros, Guadalupe	please order new 8' disc, 3 point hitch for district projects. thanks								
<u>Michael Munoz</u>									
78848					9/27/2011		293		\$0.00
Medium	Work In Progress			9/27/2011 1:15:56 PM					
Ontiveros, Guadalupe	need new z-trac mower to cut new landscaping in the southern schools. thanks								
<u>Michael Munoz</u>									
88554					6/3/2012		43		\$0.00
Medium	Work In Progress			6/3/2012 12:21:11 AM					
Diaz, Sebastian	Monthly - Physical Plant - Lint Trap (Quarterly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
84466					2/24/2012		143		\$0.00
Medium	Work In Progress			2/24/2012 12:52:40 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.		42931						
<u>Michael Munoz</u>									
84467					2/24/2012		143		\$0.00
Medium	Work In Progress			2/24/2012 12:53:24 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.		42932						
<u>Michael Munoz</u>									
84468					2/24/2012		143		\$0.00
Medium	Work In Progress			2/24/2012 12:54:09 PM					
Carrasco, Danny	Danny need to conduct inventory of all Technicians tools and equipment. Ask Ruben for present inventory list to match up.		42933						
<u>Michael Munoz</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
88665	Motor Vehicle				6/6/2012		40		\$0.00
Medium	Work In Progress	vehicle#184		6/6/2012 1:23:53 PM					
Flores, Pete	please service athletic's vehicle #184								
Pete Flores									
84248	Motor Vehicle				2/17/2012		150		\$0.00
Medium	Work In Progress			2/17/2012 9:25:51 AM					
Flores, Pete	service vehicle #158 - Charles Cotton								
Cora Ramirez									
83939	Motor Vehicle				2/10/2012		157		\$0.00
Medium	Work In Progress	vehicle # 138		2/10/2012 8:00:50 AM					
Flores, Pete	needs spark plugs & routine maintenance								
Pete Flores									
87477	Motor Vehicle				5/8/2012		69		\$0.00
Medium	Work In Progress	vehicle#97		5/8/2012 2:22:05 PM					
Flores, Pete	blower motor noisy-requires replacement								
Pete Flores									
87521	Motor Vehicle				5/9/2012		68		\$0.00
Medium	Work In Progress	vehicle#133		5/9/2012 10:28:13 AM					
Flores, Pete	vehicle's batteries not maintaining charge . need to replace								
Pete Flores									
87522	Motor Vehicle				5/9/2012		68		\$0.00
Medium	Work In Progress	vehicle#119		5/9/2012 10:30:38 AM					
Flores, Pete	turn signals inoperative at times.								
Pete Flores									
88102	Motor Vehicle				5/24/2012		53		\$0.00
Medium	Work In Progress	vehicle#100		5/24/2012 3:11:26 PM					
Flores, Pete	a/c not cooling								
Pete Flores									
81562	Motor Vehicle				12/1/2011		228		\$0.00
Medium	Work In Progress	band truck#127		12/1/2011 8:47:19 AM					
Flores, Pete	scheduled for routine maintenance								
Pete Flores									
88090	Motor Vehicle				5/24/2012		53		\$0.00
Medium	Work In Progress	vehicle's 01&02		5/24/2012 12:42:42 PM					
Flores, Pete	tire replacement required on both vehicle's								
Pete Flores									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
88091	Motor Vehicle				5/24/2012		53		\$0.00
Medium	Work In Progress	vehicle#33		5/24/2012 12:44:23 PM					
Flores, Pete	tire's worn and require replacement								
Pete Flores									
88092	Motor Vehicle				5/24/2012		53		\$0.00
Medium	Work In Progress	vehicle's#152&1		5/24/2012 12:47:06 PM					
Flores, Pete	both vehicle's need one tire replaced,tire's damaged beyond repair								
Pete Flores									
88093	Motor Vehicle				5/24/2012		53		\$0.00
Medium	Work In Progress	vehicle#146		5/24/2012 1:06:48 PM					
Flores, Pete	vehicle's battery has exceeded life expectancy, requires a new one, routine maintenance also required.								
Pete Flores									
78650	Motor Vehicle	Parking Lot			9/22/2011		298		\$0.00
Medium	Work In Progress			9/22/2011 7:56:36 AM					
Ontiveros, Guadalupe	re layout complete parking lot to add additional row and install signage.								
Alfredo Holguin									
89143	Motor Vehicle				6/25/2012		21		\$0.00
Medium	Work In Progress			6/25/2012 12:45:25 PM					
Appelzoller, Fred	air compressor leaking air from auxiliary line located outside of building on north side.								
Pete Flores									
88973	Motor Vehicle				6/19/2012		27		\$0.00
Medium	Work In Progress			6/19/2012 7:00:00 AM					
Estrada, Jesus	Tranportation Clerks Office - Replace carpet with VCT in area between counter and two doors.								
Alfredo Holguin									
88791	Purchasing	Office			6/11/2012		35		\$0.00
Medium	Work In Progress			6/11/2012 4:37:01 PM					
Solis, Lorenzo	Need to check A/C in Mail Room								
Larry Martinez									
80916	Maintenance				11/9/2011		250		\$0.00
Medium	Work In Progress			11/9/2011 4:06:25 PM					
Solis, Lorenzo	Training Room - Need to install a new refrigeration unit. (See Mike)								
Michael Munoz									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
80917	Maintenance				11/9/2011		250		\$0.00
Medium	Work In Progress				11/9/2011 4:07:55 PM				
Sotelo, Enrique		Training Room - Need to upgrade electrical. (See Mike)							
Michael Munoz									
84843					3/4/2012		134		\$0.00
Medium	Work In Progress				3/4/2012 12:21:18 AM				
Munoz, Michael		Yearly - Physical Plant Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
86753					4/23/2012		84		\$0.00
Medium	Work In Progress				4/23/2012 8:23:50 AM				
Gonzalez, Salvador		NEED TRUCK RACK FOR NEW SERVICE TRUCK							
Joe Ontiveros									
84574		Cafeteria			2/28/2012		139		\$0.00
Medium	Work In Progress				2/28/2012 12:49:06 PM				
Gonzalez, Salvador		PLEASE FABRICATE A METAL BOX TO COVER AIR/WATER HOSE REELS AT GAS STATION. THANK YOU!							
Ruben Ronquillo									
Count: 36 Work Orders		Avg. Age of WO's 108		Total for Physical Plant Complex				0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
86967					4/27/2012		80		\$0.00
Medium	Work In Progress			4/27/2012 3:26:53 PM					
Gonzalez, Salvador	need metal plate welded to sidewalk frame came loose in back sidewalk to bus turn around (tripping hazzard)								
Carlos Hernandez									
87513					5/9/2012		68		\$0.00
Medium	Work In Progress			5/9/2012 8:29:59 AM					
Ronquillo, Ruben	need to replace window double pane 43 1/2x 15 1/2 portable a503 window cracked due to heat								
Carlos Hernandez									
84830					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:12 AM					
Munoz, Michael	Yearly - Riverside ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
80231					10/26/2011		155		\$0.00
Medium	Work In Progress			10/26/2011 11:28:21		3/29/2012			
Lara, Ralph	SCREEN DOOR NEEDS TO BE FIXED. SNP MANAGER EMILIA C. 589.2550				AS PER RALPH LARA HE IS CONTRACTING HE HAS WORK ORDER. - MG				
Maritza Gonzalez									
85356		Cafeteria			3/15/2012		123		\$0.00
Medium	Work In Progress			3/15/2012 10:15:14 AM					
Lara, Ralph	need to have screen doors replaced in kitchen old and warped								
Daniel Orozco									
82861					1/17/2012		181		\$0.00
Medium	Work In Progress			1/17/2012 3:22:25 PM					
Gonzalez, Salvador	missing gate to north drop off area sidewalk gate case #2012-00087								
Carlos Hernandez									
78125					9/9/2011		311		\$0.00
Medium	Work In Progress			9/9/2011 2:44:31 PM					
Munoz, Michael	need to construct concret pad for trash dumpsters								
Alfredo Holguin									
87101					5/1/2012		76		\$0.00
Medium	Work In Progress			5/1/2012 3:37:06 PM					
Estrada, Jesus	need to replace tile to carpet portable 503 and 506								
Carlos Hernandez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
86799					4/24/2012		83		\$0.00
Medium	Work In Progress			4/24/2012 8:21:24 AM					
Estrada, Jesus	need to replace carpet with tile room 13								
Carlos Hernandez									
86800					4/24/2012		83		\$0.00
Medium	Work In Progress			4/24/2012 8:22:11 AM					
Estrada, Jesus	need to replace carpet with tile room 17								
Carlos Hernandez									
86806					4/24/2012		83		\$0.00
Medium	Work In Progress			4/24/2012 9:30:40 AM					
Estrada, Jesus	need to replace carpet in muisc portable								
Carlos Hernandez									
86730					4/20/2012		87		\$0.00
Medium	Work In Progress			4/20/2012 3:39:54 PM					
Lara, Ralph	need to remove cable lock on east side door in cafe wont unlock and need new one								
Carlos Hernandez									
84702					3/1/2012		137		\$0.00
Medium	Work In Progress			3/1/2012 8:23:25 AM					
Villalobos, David	toilet seats need replacing in room121and137 and 117 there r no replacements for seats								
Carlos Hernandez									
83854					2/8/2012		159		\$0.00
Medium	Work In Progress			2/8/2012 3:28:09 PM					
Villalobos, David	p-trap to sink in girls b-room middle wing broke off at wall needs to be replaced								
Carlos Hernandez									
88042					5/23/2012		54		\$0.00
Medium	Work In Progress			5/23/2012 1:15:15 PM					
Villalobos, David	uniral in boys bathroom middle clogged tried unclogging								
Carlos Hernandez									
87873					5/17/2012		60		\$0.00
Medium	Work In Progress			5/17/2012 3:33:39 PM					
Castillo, Carlos	need to replace switches to hallway lights in new wing								
Carlos Hernandez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Riverside ES							
88277					5/30/2012		47		\$0.00
Medium	Work In Progress			5/30/2012 3:20:45 PM					
Ontiveros, Guadalupe	need to replace to irrigation valves both are leaking and one is stuck open								
Carlos Hernandez									
87985					5/22/2012		55		\$0.00
Medium	Work In Progress			5/22/2012 8:21:31 AM					
Flores, Pete	970 tractor clutch needs to be adjusted								
Carlos Hernandez									
87950					5/21/2012		56		\$0.00
Medium	Work In Progress			5/21/2012 1:02:30 PM					
Flores, Pete	need license plates for trailer to tractor 445 and light								
Carlos Hernandez									
87155					5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 3:27:41 PM					
Hernandez, Carlos	need to repair front entrance sidewalk missing tile								
Carlos Hernandez									
87156					5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 3:28:39 PM					
Hernandez, Carlos	need to repair sidewalk going to parent parking and drop off								
Carlos Hernandez									
87158					5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 3:29:31 PM					
Hernandez, Carlos	need to replace light bulbs that are out in classrooms								
Carlos Hernandez									
Count: 22 Work Orders			Avg. Age of WO's	103	Total for Riverside ES			0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location:		RTC - Alliance							
89122					6/25/2012		21		\$0.00
Medium	Work In Progress				6/25/2012 8:40:55 AM				
Ontiveros, Guadalupe	As per Gloria, is it possible to send someone to clean our yard. We have weeds and our sidewalks are full of sand. It would greatly appreciated. Thank you								
Maritza Gonzalez									
Count: 1	Work Orders	Avg. Age of WO's			21	Total for RTC - Alliance		0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		San Miguel ES							
85443		Portables			3/19/2012		119		\$0.00
Medium	Work In Progress			3/19/2012 12:35:28 PM					
Ontiveros, Guadalupe	need to relocate stairs, steps and ramps on 2 portables that are to be re-located to loma-linda. please see mike for details. thank you								
<u>Michael Munoz</u>									
86714					4/20/2012		87		\$0.00
Medium	Work In Progress	Cafeteria		4/20/2012 12:50:57 PM					
Ontiveros, Joe	Please check water system to Cafeteria and make sure it is operable.								
<u>Joe Munoz</u>									
86484		Portables			4/16/2012		91		\$0.00
High	Work In Progress			4/16/2012 7:28:04 AM					
Solis, Lorenzo	2 portables will be moved to loma-linda portable a & b. portable a will need new refrigeration units along with heaters and portable b units need to be checked for proper operation. please see mike for details. thankyou								
<u>Michael Munoz</u>									
89084					6/21/2012		25		\$0.00
Medium	Work In Progress			6/21/2012 8:36:31 AM					
Lozoya, Manny	Mech Room - need to change core.								
<u>Manny Lozoya</u>									
87890	Main Building	Classroom			5/17/2012		60		\$0.00
Medium	Work In Progress			5/17/2012 5:26:30 PM					
Lozoya, Manny	Manny - Need two sets (2) of gate keys, San Miguel building keys made for San Miguel. It should open all the gates and doors on that campus. Jaime Vargas (575-644-7438) with ESA will be checking it out to do the ADA work at SM. Please bring the key to construction office so Peggy Jo can have him sign for it. If you have questions please call me at 882- 6921...Thanks...Ralph Gallegos								
<u>Rafael Gallegos</u>									
84337	Main Building	Mechanical			2/22/2012		145		\$0.00
Medium	Work In Progress			2/22/2012 7:55:43 AM					
Solis, Lorenzo	Order parts for hydronic system.								
<u>Lorenzo Solis</u>									
Count: 6 Work Orders		Avg. Age of WO's 88		Total for San Miguel ES			0	\$0.00	

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
86060	Main Building	Hallway/Corridor			4/2/2012		105		\$0.00
Medium	Work In Progress				4/2/2012 3:55:33 PM				
Villalobos, David		install a drain to main water to AC's, constantly freezing up during the cold months							
David Villalobos									
84710	Main Building	Classroom			3/1/2012		137		\$0.00
Medium	Work In Progress	CASA ROJA			3/1/2012 10:17:45 AM				
Lara, Ralph		PLEASE INSTALL LOCKS ON ALL CABINETS/DRAWERS IN THE PARENT ROOM. THANKS.							
Rita Mendez									
86865	Main Building	Classroom			4/25/2012		82		\$0.00
Medium	Work In Progress	5			4/25/2012 12:19:17 PM				
Marquez, Gerardo		CLASSROOMS MAPS NEED TO BE INSTALLED IN THE FOLLOWING CLASSROOM: ROOM 310 CLARIDGE, ROOM 306 NUNEZ, ROOM 207 B. SANCHEZ, ROOM 205 CASTILLO, AND ROOM 306 FLORES. THANKS.							
Rita Mendez									
84831					3/4/2012		134		\$0.00
Medium	Work In Progress				3/4/2012 12:21:13 AM				
Munoz, Michael		Yearly - Santa Teresa ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
88660		Office			6/6/2012		40		\$0.00
Medium	Work In Progress	OFFICE			6/6/2012 11:03:46 AM				
Martinez, Larry		WE HAVE 2 CASES OF STUDENT CUMS THAT NEED TO BE SENT TO THE WAREHOUSE TO BE ARCHIVED. PLEASE PICK UP IN END OF JULY. THANKS.							
Rita Mendez									
87143					5/2/2012		75		\$0.00
Medium	Work In Progress				5/2/2012 2:07:50 PM				
Marquez, Gerardo		SUMMER PROJECT. BROKEN PLASTIC SAND BARRIERS NEED TO BE REPLACED WITH NEW ONES.							
Gerardo Marquez									
88862					6/13/2012		33		\$0.00
Medium	Work In Progress				6/13/2012 3:21:56 PM				
Marquez, Gerardo		NEED TO RESEED BARE SPOTS IN BACK GRASS P.G. AREA.							
Gerardo Marquez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
82017					12/12/2011		217		\$0.00
Medium	Work In Progress			12/12/2011 2:45:16 PM					
Orozco, Daniel	MILK COOLER IS NOT COOLING. SNP MANAGER PAT S. 589.3439								
<u>Maritza Gonzalez</u>									
89282					6/30/2012	7/31/2012	16		\$0.00
Medium	Work In Progress			6/30/2012 12:26:03 AM					
Marquez, Gerardo	Yearly - Santa Teresa ES A-2 Unitary H/C - Annual - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
89281					6/30/2012	7/31/2012	16		\$0.00
Medium	Work In Progress			6/30/2012 12:26:02 AM					
Marquez, Gerardo	Yearly - Santa Teresa ES A-9 Air-Cooled (Annual) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
88075					5/23/2012		54		\$0.00
Medium	Work In Progress			5/23/2012 4:23:51 PM					
Ambriz, Jose	ALARM TO HVAC THAT SUPPLIES THE SERVER RM. STILL GOING OFF. NEEDS TO BE CHECKED OUT.								
<u>Gerardo Marquez</u>									
87140					5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 1:40:30 PM					
Marquez, Gerardo	SUMMER PROJECT. PREP WALLS & REPAINT CLASSRMS & HALL WAYS.								
<u>Gerardo Marquez</u>									
76757					8/10/2011		341		\$0.00
Medium	Work In Progress			8/10/2011 8:58:12 AM					
Castillo, Carlos	HAND DRYER @ BOYS RRM. IN CASA BLANCA NEEDS REPLACING. NOT WORKING. THANKS.								
<u>Gerardo Marquez</u>									
88374					6/1/2012		45		\$0.00
Medium	Work In Progress			6/1/2012 9:13:43 AM					
Marquez, Gerardo	5/31/12					5/31			
	1-INSP. BLDG. & GRNDS. PICKED UP TRASH. 2-CLEANED OFF ENTRANCES & SIDEWALKS. 3-WENT TO PPD. TO TURN IN TIME, PICK UP MATRL. & ATTEND LUNCHEON. 1-MET WITH DUNN-EDWARDS PAINT REP. TO MATCH PAINT COLORS . 1-STARTED REMOVING FIXTURES IN CASA AZUL CLASS-RMS. FOR PAINTING.								
<u>Gerardo Marquez</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location:		Santa Teresa ES							
87427					5/7/2012		70		\$0.00
Medium	Work In Progress				5/7/2012 1:01:47 PM				
Marquez, Gerardo	WATER FOUNTAIN IN FOYER BY TEACHERS LOUNGE IS MAKING LOUD NOISE. SOUNDS LIKE THE COMPRESSOR IS GOING OUT. I HAD TO SHUT IT DOWN. PLEASE CHECK IT OUT. THANKS.								
Gerardo Marquez									
Count: 15 Work Orders		Avg. Age of WO's			96	Total for Santa Teresa ES		0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
80199					10/25/2011		265		\$0.00
Medium	Work In Progress			10/25/2011 3:39:09 PM					
Prospero, Manuel		10/25/11. 8HRS WO 78262.				10/25 - SEE WO ABOVE			
<u>Manuel Prospero</u>									
78116					9/9/2011		311		\$0.00
Medium	Work In Progress			9/9/2011 11:25:30 AM					
Prospero, Manuel		Parking Area - Install stop sign were parking exit intersects access into McNutt (Check w/Dixon on location). Please call Alfredo regarding Stop Sign							
<u>Alfredo Holguin</u>									
85971					4/2/2012	4/9/2012	105		\$0.00
Medium	Work In Progress			4/2/2012 12:42:29 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
85972					4/2/2012	4/9/2012	105		\$0.00
Medium	Work In Progress			4/2/2012 12:42:29 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
87380					5/6/2012	6/6/2012	71		\$0.00
Medium	Work In Progress			5/6/2012 12:17:46 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
87381					5/6/2012	5/14/2012	71		\$0.00
Medium	Work In Progress			5/6/2012 12:17:46 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
75044					7/4/2011	7/11/2011	378		\$0.00
Medium	Work In Progress			7/4/2011 12:22:29 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
<u>Margret Villalobos</u>									
75042					7/4/2011	8/3/2011	378		\$0.00
Medium	Work In Progress			7/4/2011 12:22:28 AM					
Prospero, Manuel		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
<u>Margret Villalobos</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
75043					7/4/2011	7/11/2011	378		\$0.00
Medium	Work In Progress			7/4/2011 12:22:28 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
81617					12/2/2011		227		\$0.00
High	Work In Progress			12/2/2011 1:39:02 PM					
Prospero, Manuel	all boiler rooms need to be cleaned as per inspectors site visit and cleaned on a schedule.call mike for inspection so that he may forward to boiler inspector. thank you								
<u>Michael Munoz</u>									
75464					7/14/2011		368		\$0.00
Medium	Work In Progress			7/14/2011 1:12:03 PM					
Mijarez, Jaime	Need to fix leak in classroom.								
<u>Michael Munoz</u>									
88369					5/31/2012		46		\$0.00
Medium	Work In Progress			5/31/2012 5:11:55 PM					
Mijarez, Jaime	5/31/2012					5/31			
	.50 Sign in and fill out paper work. 1.5 Move white boards out of classrooms. 1.0 Locating circuit for electrical room split unit. 2.5 Report to physical plant and luncheon. .50 Recieve paint from Paint supplier. 1.5 Gas company opened gas had to turn on water heaters and culinary stoves. .50 Fill out paper work and sign out.								
<u>Jaime Mijarez</u>									
87744					5/15/2012		62		\$0.00
Medium	Work In Progress			5/15/2012 11:42:11 AM					
Nunez, Arturo	SOAP HOLDER IN RESTROOM IN KITCHEN AREA IS NOT WORKING PROPERLY. SOAP WILL NOT DISPENSE. SNP MANAGER OLGA B. 589.5332								
<u>Maritza Gonzalez</u>									
82913					1/18/2012		180		\$0.00
Medium	Work In Progress			1/18/2012 3:22:21 PM					
Nunez, Arturo	NEED A BELIMO H.W.V. FOR A.H.U. IN LIBRARY, VALVE IS DAMAGED, AND CLIMATE CAN'T BE CONTROLLED AUTO. IN FO ; G332 + NVF 24 - MFT - E US, G3NV0050, 00413-200030- 130-47, 39716DNDV24- MFT 2				Asp report 6/13/12 - Pending				
Arturo Nunez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
79946					10/19/2011		271		\$0.00
Medium	Work In Progress			10/19/2011 7:55:19 AM					
Flores, Pete	NEED TO HAVE VECHILE # 70 CHECKED , FUEL LEAK.								
Arturo Nunez									
86609					4/18/2012		89		\$0.00
Medium	Work In Progress			4/18/2012 10:22:40 AM					
Flores, Pete	Need to replace gas blower starting cord. I can isntall myself just need the cord Thanks. TO Pete A Flores.								
Jorge Perez									
85135		Library			3/8/2012		130		\$0.00
Medium	Work In Progress			3/8/2012 11:01:36 AM					
Prospero, Manuel	Need to replace outside lights between the library and ROTC class rooms.		3/12 - Asp Cali route back to Bldg Mechanic						
Jorge Perez									
78414		Classroom			9/16/2011		304		\$0.00
Medium	Work In Progress			9/16/2011 7:38:49 AM					
Prospero, Manuel	please remove all ceiling tiles and doors that were removed from the cullinary art room remodel project. only store what is good.dispose of the rest.								
Michael Munoz									
82951					1/19/2012		179		\$0.00
Medium	Work In Progress			1/19/2012 11:16:20 AM					
Prospero, Manuel	Heater in custodial offices is not working, need one of the maintanace to service it please.								
Jorge Perez									
83369					1/30/2012		168		\$0.00
Medium	Work In Progress			1/30/2012 10:28:11 AM					
Prospero, Manuel	Need to replace all 4 wheels on the chair/cart located in the new gym area, tires are bent and dont wheel out properly, and its leaving marks on the gym floor.								
Jorge Perez									
85970					4/2/2012	5/2/2012	105		\$0.00
Medium	Work In Progress			4/2/2012 12:42:28 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
87379					5/6/2012	5/14/2012	71		\$0.00
Medium	Work In Progress			5/6/2012 12:17:45 AM					
Prospero, Manuel	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
7/16/2012 11:48:11 AM									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
81376					11/28/2011		231		\$0.00
High	Work In Progress			11/28/2011 8:30:26 AM					
Castillo, Carlos	boiler lockinvar sn # D04H00002833 in custodial closet does not have an emergency shutoff switch. please install as per boilers inspectors inspection. thank you								
Michael Munoz									
84963					3/5/2012		133		\$0.00
Medium	Work In Progress			3/5/2012 9:28:33 AM					
Castillo, Carlos	Need to connect electrical to HVAC units. (Please see Jose for location)								
Jose Ambriz									
86515					4/16/2012		91		\$0.00
Medium	Work In Progress			4/16/2012 3:37:51 PM					
Castillo, Carlos	NEED TWO OUTLETS INSTALL IN ROOM # 610. CULINARY KIT.								
Arturo Nunez									
87769					5/15/2012		62		\$0.00
Medium	Work In Progress			5/15/2012 3:47:16 PM					
Castillo, Carlos	POWER OUTLETS NEED TO BE INSTALL AT ATHELETIC OFFICE , TO CONNECT HER EQUIPMENT.								
Arturo Nunez									
87894					5/18/2012		59		\$0.00
Medium	Work In Progress			5/18/2012 8:36:06 AM					
Castillo, Carlos	Cafeteria and all classrooms in the building all lights are shutting down. This is due to an electrical short in bandroom storage rooms.		5/25-Asp Enrique, route back to Cali.						
Jaime Mijarez									
83370					1/30/2012		168		\$0.00
Medium	Work In Progress			1/30/2012 10:34:06 AM					
Villalobos, David	Need to replace all Faucets(4) located in the old lockers. Water doesn't come out. and are really old and may need to replace the whole thing. on all 4 faucets/sinks								
Jorge Perez									
87546					5/9/2012		68		\$0.00
Medium	Work In Progress			5/9/2012 3:48:41 PM					
Villalobos, David	200-300 area boys and girls restroom chase all vacume breakers are leaking causing moisture on walls and insulation.								
Jaime Mijarez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

87909					5/18/2012		59		\$0.00
Medium	Work In Progress			5/18/2012 2:15:52 PM					
Villalobos, David	Wood shop classroom has a utility sink with a broken drain that leaks will have to replace the sink.								
Jaime Mijarez									
87813					5/16/2012		61		\$0.00
Medium	Work In Progress			5/16/2012 3:36:41 PM					
Villalobos, David	NEED TWO 8" CENTER WATER FAUCETS FOR SINKS IN ROOMS # 703, AND 705								
Arturo Nunez									
78366					9/14/2011		306		\$0.00
Medium	Work In Progress			9/14/2011 6:22:42 PM					
Villalobos, David	sinks in locker rooms need to be replaced water doesnt come out in some								
Jorge Perez									
79086					10/2/2011	11/2/2011	288		\$0.00
Medium	Work In Progress			10/2/2011 12:26:28 AM					
Prospero, Manuel	Yearly - Santa Teresa HS U-2 Unit Ht Gas Yearly - Refer to PM schedule details.								
Margret Villalobos									
79085					10/2/2011	11/2/2011	288		\$0.00
Medium	Work In Progress			10/2/2011 12:26:27 AM					
Prospero, Manuel	Yearly - Santa Teresa HS I-4 Fan Coil Unit Yearly - Refer to PM schedule details.								
Margret Villalobos									
79018					9/30/2011		290		\$0.00
Medium	Work In Progress			9/30/2011 12:22:34 AM					
Prospero, Manuel	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								
Margret Villalobos									
85804					3/31/2012		107		\$0.00
Medium	Work In Progress			3/31/2012 12:21:34 AM					
Prospero, Manuel	Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.								
Margret Villalobos									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

76015					7/29/2011		353	\$0.00	
Medium	Work In Progress	MRS.		7/29/2011 1:53:52 PM					
Prospero, Manuel	MAINTENANCE PLEASE CHECK ON HVAC UNITS LOCATED BETWEEN MAIN BUILDING AND CAFETERIA-EXCESSIVE NOISE WHILE RUNNING AND LOUD BANGING WHEN AT LEAST 1 UNIT SHUTS DOWN.								
<u>Marylou Jimenez</u>									
85969					4/2/2012	4/22/2012	105	\$0.00	
Medium	Work In Progress			4/2/2012 12:42:28 AM					
Prospero, Manuel	Monthly - Santa Teresa HS C-12 Chm Feeder Semimntly - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
76017					7/29/2011		353	\$0.00	
Medium	Work In Progress	MRS.		7/29/2011 2:01:47 PM					
Nunez, Arturo	URGENT! MAINTENANCE DOORS NEED TO BE PAINTED BEFORE 1ST DAY OF SCHOOL. OUTER AND INNER DOORS. Will do as a summer project - 6/12/12								
<u>Marylou Jimenez</u>									
85028					3/6/2012		132	\$0.00	
Medium	Work In Progress			3/6/2012 11:34:44 AM					
Nunez, Arturo	Need to re paint all Main entrances to the school. All doors have been pressuse washed but a lot of the stains wont come off, as well as theirs alot of chips on the doors due to old paint. Asp report 6/13/12 - Pending								
<u>Jorge Perez</u>									
87190					5/3/2012		74	\$0.00	
Medium	Work In Progress			5/3/2012 7:51:10 AM					
Nunez, Arturo	NEED TO PAINT CLASSROOMS THAT NEED IT, PAINT SOME WALLS THAT NEED TO BE PAINTED.								
<u>Arturo Nunez</u>									
87191					5/3/2012		74	\$0.00	
Medium	Work In Progress			5/3/2012 7:54:18 AM					
Nunez, Arturo	PIAINT ENTRANCE ENTRANCE DOORS MAIN BUILDING.								
<u>Arturo Nunez</u>									
87192					5/3/2012		74	\$0.00	
Medium	Work In Progress			5/3/2012 7:56:06 AM					
Nunez, Arturo	PAINT DOORS AND FRAMES ANNEX BUILDING.								
<u>Arturo Nunez</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
87419					5/7/2012		70		\$0.00
Medium	Work In Progress				5/7/2012 9:52:18 AM				
Mijarez, Jaime	Need to paint all partitions in boys reroom located in the main hallway								
Jorge Perez									
83804					2/7/2012		160		\$0.00
Medium	Work In Progress				2/7/2012 3:52:16 PM				
Ambriz, Jose	NEED SOME ASSITANCE ON REPARING WATER LEAK ON CIRCULATING PUMP 1, FOR 300'S WING.								
Arturo Nunez									
88504					6/3/2012	7/4/2012	43		\$0.00
Medium	Work In Progress				6/3/2012 12:20:50 AM				
Nunez, Arturo	Yearly - Santa Teresa HS B-2 Boiler Yearly - Refer to PM schedule details.								
Margret Villalobos									
83743		Athletic Field			2/6/2012		161		\$0.00
Medium	Work In Progress				2/6/2012 3:30:26 PM				
Valdez, Pedro	tires for new soccer goals are broken.								
Guadalupe Ontiveros									
85738					3/30/2012		108		\$0.00
Medium	Work In Progress				3/30/2012 8:26:23 AM				
Orozco, Daniel	TEMPERATURE GAGES ON DISHWASHER NEED TO BE WORKED ON. SNP MANAGER OLGA B. 589.5332								
Maritza Gonzalez									
87193					5/3/2012		74		\$0.00
Medium	Work In Progress				5/3/2012 7:58:44 AM				
Nunez, Arturo	INSTALL WHITE BOARDS ON CLASSROOMS MAIN BUILDING.								
Arturo Nunez									
87000					4/30/2012		77		\$0.00
Medium	Work In Progress				4/30/2012 8:52:01 AM				
Nunez, Arturo	STORAGE ROOM IN KITCHEN NEEDS TO BE PAINTED. SNP MANAGER OLGA B. 589.5332								
Maritza Gonzalez									
86584					4/17/2012		90		\$0.00
Medium	Work In Progress				4/17/2012 3:40:39 PM				
Nunez, Arturo	NEED 3 EA. A26 V BELTS, NEED 6 EA. 4L 220 V BELTS. FOR RESTROOMS EXHAUST FANS, AND FOR DRESSING ROOM EXHAUST FANS.								
Arturo Nunez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa HS

87772					5/15/2012		62		\$0.00
Medium	Work In Progress			5/15/2012 3:50:57 PM					
Gonzalez, Salvador	Main entrance gate has broken track. we need brackets to repair.								

Jaime Mijarez

82724					1/12/2012		186		\$0.00
Medium	Work In Progress			1/12/2012 12:33:30 PM					
Gonzalez, Salvador	BACK FENCE COMING IN FROM THE ARROYO NEEDS TO BE REINFORCED, FOR SECURITY PURPOSES.								

Manuel Prospero

84841					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:17 AM					
Munoz, Michael	Yearly - Santa Teresa HS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								

Margret Villalobos

88911					6/14/2012		32		\$0.00
Medium	Work In Progress			6/14/2012 4:11:32 PM					
Carrasco, Danny	NEED TO BORROW SISSOR LIFT FOR ART PROJECT IN NEW GYM.								

Arturo Nunez

86379					4/12/2012		95		\$0.00
Medium	Work In Progress			4/12/2012 9:22:51 AM					
Carbajal, Jimmy	Extractos needs P.M								

Jorge Perez

83062					1/23/2012		175		\$0.00
Medium	Work In Progress			1/23/2012 10:59:12 AM					
Nunez, Arturo	NEED 8 (EIGHT) EA. 4.10/3.50-4 WHEELS TO REPLACED THE EXISTING , THE ONES ON ARE ALL SHOT, COACHES CAN'T MOVE AROUND. AS PER MR. DIXON. THANK YOU.		Asp report 6/13/12 - Pending - Waiting on Parts						

Arturo Nunez

87747		Athletic Field			5/15/2012		62		\$0.00
High	Work In Progress			5/15/2012 2:13:11 PM					
Flores, Pete	need diesel fuel for 997-#0425,Jd 3005-#0510,gas for gator-#0509,also s.t.m.s gator-#0511								

Guadalupe Ontiveros

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa HS							
84437		Athletic Field			2/24/2012		143		\$0.00
Medium	Work In Progress			2/24/2012 7:42:03 AM					
Gonzalez, Salvador		please replace wooden roofs with metal to boys baseball dug-outs.							
		thank you							
<u>Michael Munoz</u>									
78512	Main Building	Hallway/Corridor			9/19/2011		301		\$0.00
Medium	Work In Progress			9/19/2011 3:37:15 PM					
Prospero, Manuel		ON 9/16/11 JUAN TELLEZ THE HEAD SECURITY CALL ME AT 6:30 PM FOR WATER LEA ON SCIENCE HALLWAY ON ROOF.							
<u>Manuel Prospero</u>									
77008	Main Building	Classroom			8/16/2011		335		\$0.00
Medium	Work In Progress			8/16/2011 2:28:54 PM					
Nunez, Arturo		Room 511 cabinet handles need to be replaced, teacher has handles needs screws				Asp report 6/13/12 - Pending			
		Lab table doors stick and graffitti needs to be removed							
<u>Rosalinda Rodriguez</u>									
78471	Main Building	Classroom			9/16/2011		304		\$0.00
Medium	Work In Progress			9/16/2011 11:15:48 PM					
Prospero, Manuel		Gloria Goodman needs round table and computer desk repaired. Also check A/C that is not working.							
<u>William Dickson</u>									
79039	Gymnasium	Dressing Room			9/30/2011		290		\$0.00
Medium	Work In Progress			9/30/2011 1:14:44 PM					
Prospero, Manuel		Need to replace Delaney flushvalves throughout dressing rooms, asp per David, Zurn or Sloan flushvalves should be installed							
<u>Manuel Prospero</u>									
80126	Vocational				10/24/2011		266		\$0.00
Medium	Work In Progress			10/24/2011 12:52:20					
Prospero, Manuel		Pickup all furniture from Voc Bldg and bring to PPD. (Art and Danny C. will assist)							
<u>Richard Chavez</u>									
76877	Vocational	Classroom			8/12/2011		339		\$0.00
Medium	Work In Progress			8/12/2011 10:07:05 AM					
Nunez, Arturo		Need Drill Press and Band Saw moved to main floor from 2nd floor in shop 805				Asp report 6/13/12 - Pending			
Rosalinda Rodriguez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
Location: Santa Teresa HS										
81478	Vocational				11/29/2011		230		\$0.00	
Medium	Work In Progress			11/29/2011 3:37:51 PM						
Prospero, Manuel	11/29/11. WE NEED 5 24V.HEATER ONLY FOR CHAGED ON BOCATIONAL BUILDING.									
<u>Manuel Prospero</u>										
88984	Vocational				6/19/2012		27		\$0.00	
Medium	Work In Progress			6/19/2012 9:20:10 AM						
Castillo, Carlos	PM W.O.-Walk-thru vocational bld,check for safety hazzard and defienicies that need to be corrected or repaiared.									
<u>Carlos Castillo</u>										
77090	GYM (2009)	Dressing Room			8/17/2011		334		\$0.00	
Medium	Work In Progress			8/17/2011 4:11:16 PM						
Lara, Ralph	broken lockers need latches installed, coach will purchase latches									
<u>Rosalinda Rodriguez</u>										
87839	GYM (2009)				5/17/2012		60		\$0.00	
Medium	Work In Progress			5/17/2012 7:18:21 AM						
Lara, Ralph	Need to change cores over the summer to the gym area before July 16. This because gym floors will be re done.									
<u>Jorge Perez</u>										
Count: 69 Work Orders		Avg. Age of WO's 171		Total for Santa Teresa HS			0	\$0.00		

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa MS							
81967	Library	Library			12/9/2011		220		\$0.00
Medium	Work In Progress	Library			12/9/2011 3:56:15 PM				
Mijarez, Jaime	Can we please have someone from maintenance tighten tables and chairs they are loose. There are some shelves that need brackets replaced with permanant bracket. These need to be done as soon as possible - this is a safety issue -we had 1 incident already.								
<u>Rosa Hidalgo</u>									
78907					9/28/2011		292		\$0.00
Medium	Work In Progress				9/28/2011 10:20:54 AM				
Munoz, Michael	Gym parking. Principal is requesting a handicap cement ramp by the boys dressing room asphalt parking lot.								
<u>Jaime Mijarez</u>									
76756	North Building	Custodial			8/10/2011		341		\$0.00
Medium	Work In Progress				8/10/2011 8:57:39 AM				
Flores, Pete	Pete, the small tractor #455 needs tires and the oil to be change.								
<u>Ismael Rodriguez</u>									
80181	North Building	Parking Lot			10/25/2011		265		\$0.00
Medium	Work In Progress				10/25/2011 10:58:43				
Mijarez, Jaime	Add two more ADA parking spaces in parking area in center of lot between Mobile Home and North Bldg use parking spaces close to blds- intall post signs and mark pavement with stencil								
<u>Alfredo Holguin</u>									
86545	North Building	Classroom			4/17/2012		90		\$0.00
Medium	Work In Progress				4/17/2012 8:18:49 AM				
Estrada, Jesus	North bldg classrooms carpet removal requested by teachers and principal Mrs. Lovelace. The rooms have tile and carpet the tile is also as old as the carpet. Classrooms are: Room 7, Room 9, and Room 2.								
<u>Jaime Mijarez</u>									
87077	North Building	Classroom			5/1/2012		76		\$0.00
Medium	Work In Progress				5/1/2012 12:57:51 PM				
Estrada, Jesus	As per Ms.Lovelace can you check into Rm. 3 and room 12 also on removing the carpet and replace it with tile thanks.See Mr.Rodriguez								
<u>Ismael Rodriguez</u>									
87989	North Building	Gym			5/22/2012		55		\$0.00
Medium	Work In Progress				5/22/2012 12:22:00 PM				
Ontiveros, Guadalupe	Remove weeds around the gym thanks..								
Ismael Rodriguez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
87660	North Building	Custodial			5/14/2012		63		\$0.00
Medium	Work In Progress				5/14/2012 8:18:14 AM				
Ontiveros, Guadalupe	Need some hose bids for some water hoses male and female two sets.								
<u>Ismael Rodriguez</u>									
88230	North Building	Classroom			5/29/2012		48		\$0.00
Medium	Work In Progress	ROOM 3			5/29/2012 10:54:09 AM				
Prospero, Manuel	1-PAINT BATHROOM WALLS AND REPAIR HOLES IN CEILING 2- REPLACE DOOR SWEEP ON EASTSIDE DOOR 3- REPAIR KITCHEN EXHAUST FAN 4- REPAIR HOLE IN CEILING CLOSET								
<u>Laura Parra</u>									
87799	North Building	Classroom			5/16/2012		61		\$0.00
Medium	Work In Progress				5/16/2012 12:44:10 PM				
Prospero, Manuel	5/16/12. Room 14 need to replace bad condensation pump. Room 17 there is a leak in condensation pump.								
<u>Manuel Prospero</u>									
87133	North Building	Mechanical			5/2/2012		75		\$0.00
Medium	Work In Progress				5/2/2012 10:33:25 AM				
Ambriz, Jose	The air conditioning unit is down i reset it but runs for a while and doesnt kick back on it is located in the head custodian office thank you.								
<u>Ismael Rodriguez</u>									
88570	North Building	Classroom			6/4/2012		42		\$0.00
Medium	Work In Progress				6/4/2012 9:52:13 AM				
Ambriz, Jose	WE HAVE PROBLEMS WHIT B.C.U. COMUNICATION.								
<u>Manuel Prospero</u>									
88695	North Building	Restroom (Boys)			6/7/2012		39		\$0.00
Medium	Work In Progress				6/7/2012 7:09:47 AM				
Prospero, Manuel	Paint restrooms in north building lower and upper see Mr.Rodriguez thanks.								
<u>Ismael Rodriguez</u>									
85081	South Building	Classroom			3/7/2012		131		\$0.00
Medium	Work In Progress	ROOM 2B			3/7/2012 10:53:18 AM				
Castillo, Carlos	NEED POWER FOR SMARTBOARD								
<u>Laura Parra</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
79607	South Building	Parking Lot			10/11/2011		279		\$0.00
Medium	Work In Progress	SOUTH FENCE			10/11/2011 8:25:10 AM				
Gonzalez, Salvador	FENCE NEEDS TO BE REPAIRED. FENCE IS CUT AND IS BEING HELD TOGETHER WITH A WIRE.								
<u>Laura Parra</u>									
80182	South Building	Parking Lot			10/25/2011		265		\$0.00
Medium	Work In Progress				10/25/2011 11:05:34				
Mijarez, Jaime	Add three more ADA parking spaces next to existion ADA parking space- intall post signs and mark pavement with stencil								
<u>Alfredo Holguin</u>									
79733	South Building	Parking Lot			10/13/2011		277		\$0.00
Medium	Work In Progress	NORTH AND			10/13/2011 2:46:54 PM				
Mijarez, Jaime	NEED AT LEAST 2 ADDITIONAL HANDI CAP PARKING SPACES FOR THE SOUTH AND NORTH BUILDINGS.								
<u>Laura Parra</u>									
87121	Gym (1997)				5/2/2012		75		\$0.00
Medium	Work In Progress				5/2/2012 7:43:07 AM				
Ontiveros, Guadalupe	South Side Outside Basketball Court - Paint/layout tennis court on concret								
<u>Alfredo Holguin</u>									
83108		Athletic Field			1/24/2012		174		\$0.00
Medium	Work In Progress				1/24/2012 8:24:26 AM				
Ontiveros, Guadalupe	need concrete slap for R.P.A hot box 8'x 10' will take about two yards.								
<u>Guadalupe Ontiveros</u>									
84836					3/4/2012		134		\$0.00
Medium	Work In Progress				3/4/2012 12:21:15 AM				
Munoz, Michael	Yearly - Santa Teresa MS Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
88427					6/3/2012	6/9/2012	43		\$0.00
Medium	Work In Progress				6/3/2012 12:20:21 AM				
Prospero, Manuel	Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.								
<u>Margret Villalobos</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
84410					2/23/2012		144		\$0.00
Medium	Work In Progress			2/23/2012 2:06:46 PM					
Gonzalez, Salvador	Gym boys dressing room. Need to weld existing small locker cage window and fabricate cover around cage door lock so nobody can reach in to open the door and steal anything that is inside of the cage. contact building mechanic..								
<u>Jaime Mijarez</u>									
75769					7/25/2011		357		\$0.00
Medium	Work In Progress			7/25/2011 9:28:54 AM					
Gonzalez, Salvador	Metal portable rooms 3-a, 3-b need window guards installed on all windows. As per Mrs. Lovelace portables rooms will be used for Orchestra music and they will be having expensive music instruments. A.S.A.P								
<u>Jaime Mijarez</u>									
78278		Gym			9/13/2011		307		\$0.00
Medium	Work In Progress			9/13/2011 3:50:39 PM					
Valles, Johnny	please order and replace hot box for irrigation back flow on the northeast side of gym.thank you								
<u>Michael Munoz</u>									
88023		Gym			5/23/2012		54		\$0.00
Medium	Work In Progress			5/23/2012 8:27:42 AM					
Lara, Ralph	Need to change locks on gym the week of July 9th, working floor refinish.								
<u>Jesus Estrada</u>									
79364					10/4/2011		286		\$0.00
Medium	Work In Progress			10/4/2011 9:36:11 AM					
Lara, Ralph	Principal is requesting Door Mullians with key core on cafeteria doors and lobby doors. Existing mullians are screwed on frame with brackets and makes it a hassle when they have to be removed when cafeteria furniture has to be taken out or when deliveries on pallets are moved into the lobby. The south buliding will require some mullians with key too but first check with the Principal.								
<u>Jaime Mijarez</u>									
78670					9/22/2011		298		\$0.00
High	Work In Progress			9/22/2011 12:32:04 PM					
Mijarez, Jaime	fire lines are in need of painting. please remove sand and paint curbs red to include fire lanes wording on curbs.thank you								
<u>Michael Munoz</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

87126 5/2/2012 75 \$0.00

Medium Work In Progress 5/2/2012 8:46:47 AM

Prospero, Manuel NEED ORDER PAINT POR SUMMER PROJECT.
VANILLA VIN Q736P 20 GALL 10 GALLS10-187
BLACK. GOLD PAINT ENAMEL.

Manuel Prospero

87956 5/21/2012 56 \$0.00

Medium Work In Progress 5/21/2012 3:04:53 PM

Prospero, Manuel Roof is leaking damaging electronic equipement.

Laura Parra

88346 5/31/2012 46 \$0.00

Medium Work In Progress 5/31/2012 2:05:37 PM

Ronquillo, Ruben WE NEED TO HAVE 10 CONDENSATE PUMPS ITEM
554200 MODEL VCC 20ULS 115V 60 HZ 1.5A LITTLE
GIANTS VCC-20S RESERV.

Manuel Prospero

87364 5/6/2012 71 \$0.00

Medium Work In Progress 5/6/2012 12:17:39 AM

Mijarez, Jaime Monthly - Santa Teresa MS -Clothes Dryer (Monthly) -
Refer to PM schedule details.

Margret Villalobos

85943 4/2/2012 4/9/2012 105 \$0.00

Medium Work In Progress 4/2/2012 12:42:18 AM

Mijarez, Jaime Monthly - Santa Teresa MS Emer Light Test: Monthly -
Refer to PM schedule details.

Margret Villalobos

88471 6/3/2012 6/11/2012 43 \$0.00

Medium Work In Progress 6/3/2012 12:20:37 AM

Prospero, Manuel Monthly - Santa Teresa MS Exit Sign Insp: Monthly -
Refer to PM schedule details.

Margret Villalobos

88462 6/3/2012 6/11/2012 43 \$0.00

Medium Work In Progress 6/3/2012 12:20:34 AM

Prospero, Manuel Monthly - Santa Teresa MS Emer Light Test: Monthly -
Refer to PM schedule details.

Margret Villalobos

88527 6/3/2012 43 \$0.00

Medium Work In Progress 6/3/2012 12:21:00 AM

Prospero, Manuel Monthly - Santa Teresa MS -Clothes Dryer (Monthly) -
Refer to PM schedule details.

Margret Villalobos

7/16/2012 11:48:11 AM

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Santa Teresa MS

88494					6/3/2012	7/4/2012	43		\$0.00
Medium	Work In Progress				6/3/2012 12:20:46 AM				
Prospero, Manuel	Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.								

Margret Villalobos

Count: 36 Work Orders	Avg. Age of WO's	139	Total for Santa Teresa MS	0	\$0.00
------------------------------	-------------------------	------------	----------------------------------	----------	---------------

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
89216					6/27/2012		19		\$0.00
Medium	Work In Progress			6/27/2012 6:38:52 AM					
Ortiz, Ruben	Front Entrance East Classroom Wing - remove all branches from trees that are in contact with roof area.								
Alfredo Holguin									
84390					2/23/2012		144		\$0.00
Medium	Work In Progress			2/23/2012 8:46:21 AM					
Medina, Eric	need to replace girls bathroom door for handicap stall								
Eric Medina									
84409					2/23/2012		144		\$0.00
Medium	Work In Progress			2/23/2012 1:49:53 PM					
Medina, Eric	ERIC, CAN YOU PLEASE CHECK INTO THE GIRLS AND BOYS RESTROOM. PLEASE CHECK THE SINKS AND CALK IF NEED BE.								
David Avila									
83185					1/25/2012		173		\$0.00
Medium	Work In Progress			1/25/2012 3:16:41 PM					
Medina, Eric	please repair and sraighten rails on portable e, thank you								
Michael Munoz									
88624					6/5/2012		41		\$0.00
Medium	Work In Progress			6/5/2012 3:50:08 PM					
Carrasco, Danny	Danny need to order new set of ratchet wrenches								
Eric Medina									
87017					4/30/2012		77		\$0.00
Medium	Work In Progress	OUTISDE		4/30/2012 2:12:05 PM					
Medina, Eric	ERIC, PLEASE LOOK INTO TRIMMING BUSHES DOWN IN THE ATRIUM BETWEEN OFFICE AND UPPER GRADE LEVEL IN - IN FRONT OF MS. RAMIREZ OFFICE. BUSHES ARE FULL OF THORNS AND ARE DANGEROUS TO THE DURING DURING FIRE DRILLS. THIS IS OUR ASSIGNED ESCAPE ROUTE. THANK YOU MS. TORRES.								
David Avila									
87243					5/4/2012		73		\$0.00
Medium	Work In Progress	COMPUTER		5/4/2012 8:21:53 AM					
Medina, Eric	ERIC- CAN YOU PLEASE REPLACE THE LIGHT BULBS IN THE COMPUTER LAB. THANK YOU								
David Avila									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
82963					1/19/2012		179		\$0.00
Medium	Work In Progress			1/19/2012 3:23:24 PM					
Medina, Eric	need new toilet for bathroom outside on north campus, toilet is cracked								
Eric Medina									
83184		Portables			1/25/2012		173		\$0.00
High	Work In Progress			1/25/2012 3:15:18 PM					
Medina, Eric	please replace skirting on portable d. this is a safety issue and has been addressed before. thank you								
Michael Munoz									
88893					6/14/2012		32		\$0.00
Medium	Work In Progress			6/14/2012 8:09:59 AM					
Miranda, Danny	as per ocnversation please install tile in the restroom and washer/dryer room 21 to include covebase.thank you					7/10/12 Asp Mike, reassign to D. Miranda			
Michael Munoz									
88764					6/11/2012		35		\$0.00
Medium	Work In Progress			6/11/2012 1:40:56 PM					
Ontiveros, Guadalupe	Need grounds to inspect the sprinkler system because there are a lot of run offs and puddles of water. In Sunland Park.								
Ruben Ortiz									
87487					5/8/2012		69		\$0.00
Medium	Work In Progress			5/8/2012 3:30:41 PM					
Ontiveros, Guadalupe	need to request backhoe and dump for sand removal								
Eric Medina									
88847					6/13/2012		33		\$0.00
Medium	Work In Progress			6/13/2012 6:41:53 AM					
Ontiveros, Guadalupe	In Sunland Park, need to remove tree stump and roots that are above the ground.								
Ruben Ortiz									
88848					6/13/2012		33		\$0.00
Medium	Work In Progress			6/13/2012 6:43:05 AM					
Ontiveros, Guadalupe	In Sunland Park, remove tree branches that are close to the roof on the east side of the building, between the front office and east wing.								
Ruben Ortiz									
88849					6/13/2012		33		\$0.00
Medium	Work In Progress			6/13/2012 6:43:57 AM					
Ontiveros, Guadalupe	In Sunland Park, remove all the shrubs between the front office and east building.								
Ruben Ortiz									
7/16/2012 11:48:11 AM									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Sunland Park ES									
89046					6/20/2012		26		\$0.00
Medium	Work In Progress			6/20/2012 8:54:24 AM					
Ontiveros, Guadalupe	In Sunland Park, need to remove dead tree from the east parking lot.								
Ruben Ortiz									
89047					6/20/2012		26		\$0.00
Medium	Work In Progress			6/20/2012 8:55:22 AM					
Ontiveros, Guadalupe	In Sunland Park, need to remove the baseball backstop.								
Ruben Ortiz									
88852					6/13/2012		33		\$0.00
Medium	Work In Progress			6/13/2012 6:53:09 AM					
Ambriz, Jose	In Sunland Park, need to replace water lines, valves and drain lines for master coolers above the kitchen.								
Ruben Ortiz									
83186					1/25/2012		173		\$0.00
High	Work In Progress			1/25/2012 3:18:25 PM					
Medina, Eric	please paint on asphalt loading and unloading only on cafeteria parking lot for vendors.thank you								
Michael Munoz									
83183					1/25/2012		173		\$0.00
Medium	Work In Progress			1/25/2012 3:13:41 PM					
Medina, Eric	concrete on poarch colums around campus need to painted. thank you								
Michael Munoz									
88039		Classroom			5/23/2012		54		\$0.00
Medium	Work In Progress	CLASSROOM #		5/23/2012 11:09:57 AM					
Ortiz, Ruben	AS PER MS. HERRERA - PLEASE PAINT RESTROOM AND CLASSROOM WALLS. THEY ARE RUSTED AND WERE NOT PAINTED LAST YEAR. THANK YOU.								
David Avila									
88483					6/3/2012	7/4/2012	43		\$0.00
Medium	Work In Progress			6/3/2012 12:20:42 AM					
Medina, Eric	Yearly - Sunland Park ES B-2 Boiler Yearly - Refer to PM schedule details.								
Margret Villalobos									
88312					5/31/2012	7/1/2012	46		\$0.00
Medium	Work In Progress			5/31/2012 12:24:36 AM					
Medina, Eric	Yearly - Sunland Park ES A-2 Split System Yearly - Refer to PM schedule details.								
Margret Villalobos									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Sunland Park ES									
88851					6/13/2012		33		\$0.00
Medium	Work In Progress			6/13/2012 6:50:19 AM					
Villalobos, David	In Sunland Park, need to replace some gas lines that are corroded to the heater above the kitchen.								
Ruben Ortiz									
88762					6/11/2012		35		\$0.00
Medium	Work In Progress			6/11/2012 1:38:32 PM					
Villalobos, David	The kitchen roof is leaking and it's directly falling on to the computer. I tried to unclog the drain on the roof but was unable to do so. Need it unclogged, ASAP. In Sunland Park. Resubmit because it was to Sunland Park.								
Ruben Ortiz									
78325		Classroom			9/14/2011		306		\$0.00
Medium	Work In Progress			9/14/2011 10:41:03 AM					
Castillo, Carlos	Cali need for you to come and see what we need to install washer and dryer in room 20								
Eric Medina									
85068		Classroom			3/7/2012		131		\$0.00
Medium	Work In Progress			3/7/2012 7:56:43 AM					
Medina, Eric	please paint entire sped room where washer and dryer are going to be installed this summer.thank you								
Michael Munoz									
83774					2/7/2012		160		\$0.00
Medium	Work In Progress			2/7/2012 9:14:09 AM					
Orozco, Daniel	MANAGER HAVING TROUBLE WITH OVEN ONCE AGAIN, WHEN SHE OPENS OVEN TO CHECK ON FOOD, OVEN TURNS OFF COMPLETLEY. SNP MARINA R. 589.2545								
Maritza Gonzalez									
84832					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:13 AM					
Munoz, Michael	Yearly - Sunland Park ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
Margret Villalobos									
88647		Athletic Field			6/6/2012		40		\$0.00
Medium	Work In Progress			6/6/2012 7:40:09 AM					
Vasquez, Jose	need to check irrigaton system to many run-offs								
Guadalupe Ontiveros									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
85355		Cafeteria			3/15/2012		123		\$0.00
Medium	Work In Progress			3/15/2012 10:13:49 AM					
Lara, Ralph	need to have screen doors replaced in kitchen old and warped								
<u>Daniel Orozco</u>									
78126					9/9/2011		311		\$0.00
Medium	Work In Progress			9/9/2011 2:44:46 PM					
Munoz, Michael	need to construct concret pad for trash dumpsters								
<u>Alfredo Holguin</u>									
88950					6/18/2012		28		\$0.00
Medium	Work In Progress			6/18/2012 3:49:58 PM					
Estrada, Jesus	NEED TO REPLACE CARPET TO VCT IN ROOMS #20 & 31								
<u>Jesus Estrada</u>									
87663	Main Building				5/14/2012		63		\$0.00
Medium	Work In Progress	LIBRARY (C.		5/14/2012 10:24:25 AM					
Medina, Eric	AS PER MS. MORENO - NEED TO HAVE ALL LIBRARY TABLES TIGHTENED. THE LEG BOLTS HAVE BECOME LOOSE. THANK YOU.								
<u>David Avila</u>									
87615	Main Building				5/11/2012		66		\$0.00
Medium	Work In Progress	CLASSROOM		5/11/2012 2:10:51 PM					
Medina, Eric	AS PER MS. RUBIO - PLEASE REPLACE THE BLUE DOOR STRIP AT THE ENTRANCE OF MY ROOM. THANK YOU.								
<u>David Avila</u>									
86268	Main Building	Classroom			4/10/2012		97		\$0.00
Medium	Work In Progress	ROOM #22 (MS.		4/10/2012 1:31:36 PM					
Medina, Eric	AS PER MS. HERRERA - PLEASE GLUE STUDENT WOODEN CHAIR. THANK YOU.								
<u>David Avila</u>									
86312	Main Building	Classroom			4/11/2012		96		\$0.00
Medium	Work In Progress	CLASSROOM		4/11/2012 9:10:29 AM					
Medina, Eric	AS PER MS. ROSALES - ERIC, CAN YOU PLEASE MOUNT THE TV THAT IS BY HER CLASSROOM. THIS WILL BE THE TV THAT WILL BE USED IN HER ROOM. THANK YOU,!								
David Avila									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunland Park ES							
88270	Main Building				5/30/2012		47		\$0.00
Medium	Work In Progress	MS. BRIONES -		5/30/2012 1:32:32 PM					
Ortiz, Ruben	AS PER MS. BRIONES - NEED PROGRESS BOARDS MOVED TO CLASSROOM #18. PLEASE SEE DAVID AVILA FOR INSTRUCTIONS.								
<u>David Avila</u>									
86765	Main Building	Library			4/23/2012		84		\$0.00
High	Work In Progress			4/23/2012 1:55:59 PM					
Estrada, Jesus	CARPET IN LIBRARY NEEDS TO BE REPLACED.								
<u>Jesus Estrada</u>									
78324	Main Building	Classroom			9/14/2011		306		\$0.00
Medium	Work In Progress			9/14/2011 10:39:24 AM					
Villalobos, David	David need for you to come and see what we need to install washer and dryer in room 20		Summer Project						
<u>Eric Medina</u>									
81793	Main Building	Portables			12/5/2011		224		\$0.00
Medium	Work In Progress	Portable B (Mr.		12/5/2011 12:28:24 PM					
Ambriz, Jose	AS PER MR. MENDEZ- HIS HEATER IS NOT WORKING. DISTRICT TECHNICIAN CAME TO SEE, HE WILL BE ABLE TO FIX IT WITHIN THE NEXT COUPLE OF DAYS. WE ARE REQUESTING SOME SPACE HEATERS TO PUT IN THE CLASSROOM UNTIL THE HEATER IS FIXED. IF YOU HAVE ANY QUESTIONS PLEASE FEEL FREE TO LET ME KNOW. DAVID AVIL AT 575-589-1114. THANK YOU!								
<u>David Avila</u>									
78817	Main Building	Portables			9/27/2011		293		\$0.00
Medium	Work In Progress	PORTABLE E		9/27/2011 8:16:17 AM					
Medina, Eric	WOULD LIKE TO HAVE PORTABLE E PAINTED AS IT IS SERVING AS THE OFFICE FOR THE SCHOOL COUNSELOR, PARENT AMBASSADOR AND SPEECH THERAPIST.								
<u>David Avila</u>									
76545	Main Building	Classroom			8/5/2011		346		\$0.00
Medium	Work In Progress	25		8/5/2011 3:22:25 PM					
Medina, Eric	Eric, the bathroom in room 25 needs to be painted. Room was painted but bathroom needs to be painted as well.								
Yvette Cortez									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Sunland Park ES							
77338	Main Building	Library			8/24/2011		327		\$0.00
Medium	Work In Progress	C. MORENO			8/24/2011 12:18:43 PM				
Medina, Eric	NEED MAIN LIBRARY DOORS AND AUDIO VISUAL DOORS RE-PAINTED.								
David Avila									
Count: 44 Work Orders		Avg. Age of WO's 116			Total for Sunland Park ES			0	\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
84833					3/4/2012		134		\$0.00
Medium	Work In Progress			3/4/2012 12:21:13 AM					
Munoz, Michael	Yearly - Sunrise ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
88990					6/19/2012		27		\$0.00
Medium	Work In Progress			6/19/2012 2:41:29 PM					
Martinez, Larry	Please pick up obsolete technology items								
<u>Michelle Tellez</u>									
88698					6/7/2012		39		\$0.00
Medium	Work In Progress			6/7/2012 9:08:41 AM					
Briones, Enrique	Please pick up obsolete technology items								
<u>Michelle Tellez</u>									
87378					5/6/2012		71		\$0.00
Medium	Work In Progress			5/6/2012 12:17:45 AM					
Apodaca, Mario	Monthly - Sunrise ES - Wastewater Weed Control - Refer to PM schedule details.								
<u>Margret Villalobos</u>									
89058					6/20/2012		26		\$0.00
Medium	Work In Progress			6/20/2012 3:35:53 PM					
Sotelo, Enrique	need replce balast outside lights in portables 8 and 2 not on								
<u>Juan Vargas</u>									
88081					5/24/2012		53		\$0.00
Medium	Work In Progress			5/24/2012 9:35:55 AM					
Ontiveros, Joe	outside water fountig need replace 1" 1/4 trampa is broke								
<u>Juan Vargas</u>									
87071					5/1/2012		76		\$0.00
Medium	Work In Progress			5/1/2012 10:54:04 AM					
Vargas, Juan	need 20 gls. paint # w275/w to painting rooms 103-207 -211- 205								
<u>Juan Vargas</u>									
78619					9/21/2011		299		\$0.00
Medium	Work In Progress			9/21/2011 11:04:59 AM					
Ontiveros, Guadalupe	nesesito un pino de 8 ft. para ponerlo donde el aire tunbo un pino								
<u>Juan Vargas</u>									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Sunrise ES							
85361					3/15/2012		123		\$0.00
Medium	Work In Progress			3/15/2012 1:01:28 PM					
Ronquillo, Ruben	GRAINER . gauges hose set. # 1ynu9 back pack blower #1aaj3 cut lineman 8 in. pilers # 4yu69 cut pilers #4yu77								
<u>Juan Vargas</u>									
88939					6/18/2012		28		\$0.00
Medium	Work In Progress			6/18/2012 10:36:25 AM					
Vargas, Juan	need put concrete round the irrigation buster pump 2ft. up to rain water safety								
<u>Juan Vargas</u>									
Count: 10 Work Orders			Avg. Age of WO's	88		Total for Sunrise ES	0		\$0.00

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Vado ES							
84656					2/29/2012		138		\$0.00
Medium	Work In Progress			2/29/2012 9:11:52 AM					
Miranda, Danny	NEED TO REPLACE MEDIA TO ROOF TOP A/S								
Danny Miranda									
77005					8/16/2011		335		\$0.00
Medium	Work In Progress			8/16/2011 2:05:23 PM					
Ontiveros, Guadalupe	NEED TO REPLACE DEAD PINE TREE WITH NEW ONE BY BUSS TURN AROUND								
Danny Miranda									
87612					5/11/2012		66		\$0.00
Medium	Work In Progress			5/11/2012 8:56:42 AM					
Sotelo, Enrique	NEED A RECEPTICAL OUTLET IN P/E STORAGE FOR TEACHER S/A/A/P								
Danny Miranda									
82255					1/1/2012	2/1/2012	197		\$0.00
Medium	Work In Progress			1/1/2012 12:44:18 AM					
Villalobos, David	Yearly - Vado ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
88107					5/24/2012		53		\$0.00
Medium	Work In Progress			5/24/2012 3:34:11 PM					
Sotelo, Enrique	NEED A ELECTRICAL SWITCH (KEYED) IN 100-WING HALLWAY								
Danny Miranda									
88846					6/13/2012		33		\$0.00
Medium	Work In Progress			6/13/2012 6:31:25 AM					
Sotelo, Enrique	NEED TO REPLACE 10 EMERG. BALLAST								
Danny Miranda									
87135					5/2/2012		75		\$0.00
Medium	Work In Progress			5/2/2012 11:22:08 AM					
Miranda, Danny	NEED TO PAINT CLASSROOMS AS NEEDED								
Danny Miranda									
86247					4/8/2012	4/24/2012	99		\$0.00
Medium	Work In Progress			4/8/2012 12:15:38 AM					
Miranda, Danny	Monthly - Vado ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									

606 - Work Orders In Progress (FY Ending 11-12)

Selected Date Range for Request Dates: 7/1/2011 - 6/30/2012 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Vado ES

84834					3/4/2012		134		\$0.00
Medium	Work In Progress				3/4/2012 12:21:14 AM				
Munoz, Michael	Yearly - Vado ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.								

Margret Villalobos

Count: 9 Work Orders	Avg. Age of WO's	126	Total for Vado ES	0	\$0.00
Count: 606 Work Orders	Avg. Age of WO's	110	Grand Total	0	\$0.00