

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|---|-----------------------|-------------------|---|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Alma Del Valle Daycare | | | | | | | |
| 97188 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | 1/13/2013 12:15:53 AM | | | | | | |
| Montoya, Adam | | Monthly - QRTLY BLDG INSP REPORTS (ADV) - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 1 Work Orders | | Avg. Age of WO's 1 | | | Total for Alma Del Valle Daycare | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|---|-------------|-------------------------|-----------|---|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony - On Track Pre-K (Village) | | | | | | | | | |
| 96401 | | Classroom | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 12/7/2012 5:01:38 PM | | | | |
| Vega, David | Please empty and clean rooms 108, 110 and 111 at the Anthony Pre-K building. AVANCE and a SPED Diagnostician will be moving into them around December 12, 2012. For details or questions call Ralph Gallegos at 882-6921. Thanks. | | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 95797 | | | | | 11/26/2012 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | | 11/26/2012 3:48:45 PM | | | | |
| Nunez, Arturo | CANOPY AT PRE K PLAY AREA NEEDS TO BE REPAIRED OR REPLACED, HAS A PRETTY GOOD SIZE TEAR ON TOP. | | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| Count: 2 Work Orders | | | Avg. Age of WO's | 44 | Total for Anthony - On Track Pre-K (Village) | | 0 | | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|--|-------------|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony ES | | | | | | | | | |
| 89305 | | | | | 7/1/2012 | | 197 | | \$0.00 |
| Medium | Work In Progress | | | | 7/1/2012 12:30:03 AM | | | | |
| Holguin, Alfredo | Monthly - Anthony ES - Fire Pump Engine-Quarterly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96059 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 12/2/2012 12:22:50 AM | | | | |
| Nunez, Arturo | Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96328 | | | | | 12/6/2012 | | 39 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 12/6/2012 3:22:16 PM | | | | |
| Nunez, Arturo | FINISH REMOVING CHALK BOARDS IN ROOM 120 (DISPOSE OF CHALKBOARDS) AND PAINT ROOM 120 | | | | | | | | |
| <u>Margaret Villalobos</u> | | | | | | | | | |
| 95022 | | | | | 11/4/2012 | 11/12/2012 | 71 | | \$0.00 |
| Medium | Work In Progress | | | | 11/4/2012 12:19:13 AM | | | | |
| Nunez, Arturo | Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95023 | | | | | 11/4/2012 | 11/12/2012 | 71 | | \$0.00 |
| Medium | Work In Progress | | | | 11/4/2012 12:19:13 AM | | | | |
| Nunez, Arturo | Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96740 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:23:25 AM | | | | |
| Nunez, Arturo | Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96999 | | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | | 1/8/2013 8:58:52 AM | | | | |
| Nunez, Arturo | PLEASE HAVE MAINTENANCE FINISH ROOM 120 REMOVE ALL CHALKBOARDS FROM THE HALL AND DISPOSE OF, PAINTING STILL NEEDS TO COMPLETED IN ORDER TO SET UP OFFICE SPACE FOR DIAGNOSTICIAN | | | | | | | | |
| <u>Margaret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| W/OID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|---|-------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony ES | | | | | | | | | |
| 97025 | | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 11:59:40 AM | | | | | |
| Nunez, Arturo | MR. NUNEZ PLEASE REMOVE GRAFFITI FOUND ON PLAYGROUND AND SIDEWALK | | | | | | | | |
| <u>Jessica Lopez</u> | | | | | | | | | |
| 94354 | | | | | 10/19/2012 | | 87 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | 10/19/2012 9:00:43 AM | | | | | |
| Nunez, Arturo | MOVE OFFICE DESK FROM J. HERNANDEZ OFFICE TO DIAGNOSTICIANS OFFICE/MOVE DESK FROM DIAGNOSTICIAN OFFICE TO JULIE HERNANDEZ OFFICE (SEE JULIE HERNANDEZ OR MARGARET) | | | | | | | | |
| <u>Margaret Villalobos</u> | | | | | | | | | |
| 96741 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:26 AM | | | | | |
| Nunez, Arturo | Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96718 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:14 AM | | | | | |
| Holguin, Alfredo | Monthly - Anthony ES - Fire Pump Engine-Quarterly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95549 | | | | | 11/14/2012 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | 11/14/2012 3:48:20 PM | | | | | |
| Apodaca, Mario | AS PER MS. PEREZ , REQUESTING FOR WTAER FILTER BE INSTALLED FOR DOMESTIC WATER LINE. | | | | | | | | |
| <u>Arturo Nunez</u> | | | | | | | | | |
| 92466 | | | | | 9/6/2012 | | 130 | | \$0.00 |
| Medium | Work In Progress | | | 9/6/2012 1:00:10 PM | | | | | |
| Orozco, Daniel | DISHWASHER WASH IN WASH MODE AND STOPPED WORKING. SNP MANAGER BECKY S. 882.3507 | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 92595 | | | | | 9/10/2012 | | 126 | | \$0.00 |
| Medium | Work In Progress | | | 9/10/2012 8:13:09 AM | | | | | |
| Flores, Pete | 400 A-E need oil, oil filter for 935 | | | | | | | | |
| <u>Hector Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|--|-------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Anthony ES | | | | | | | | | |
| 93782 | | | | | 10/3/2012 | | 103 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | 10/3/2012 9:31:24 AM | | | | | |
| Lozoya, Manny | NEED TWO (2) KEYS FOR ROOM 120 (CANNOT READ NUMBER ON DOORKNOB) | | | | | | | | |
| <u>Margaret Villalobos</u> | | | | | | | | | |
| 96942 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | OFFICE | | 1/7/2013 2:17:52 PM | | | | | |
| Lozoya, Manny | WE NEED TWO KEYS (KA49) FOR ROOM NUMBER 111. ONE FOR MS. TENA AND ANOTHER FOR MS. HERRERA | | | | | | | | |
| <u>Jessica Lopez</u> | | | | | | | | | |
| 97198 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:15:59 AM | | | | | |
| Vega, David | Monthly - QRTLY BLDG INSP REPORT (AE) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96739 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:25 AM | | | | | |
| Nunez, Arturo | Monthly - Anthony ES Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96759 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:35 AM | | | | | |
| Villalobos, David | Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 94458 | | | | | 10/22/2012 | | 84 | | \$0.00 |
| Medium | Work In Progress | | | 10/22/2012 3:51:07 PM | | | | | |
| Appelzoller, Fred | NEED SOME ASSITANCE ON HOT WATER LINE LEAK INTO F.C.U. # 22. | | | | | | | | |
| <u>Arturo Nunez</u> | | | | | | | | | |
| 94680 | | | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/26/2012 3:48:12 PM | | | | | |
| Sotelo, Enrique | NEED SOME ASSITANCE ON TROUBLE SHOOTING LIGHT FIXTURES ON PRE K. WORK ROOM, HALF OF THE IN ROOM ARE TURNED OFF | | | | | | | | |
| <u>Arturo Nunez</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Anthony ES | | | | | | | |
| 94404 | | | | | 10/22/2012 | | 84 | | \$0.00 |
| Medium | Work In Progress | SPED OFFICE | | 10/22/2012 7:33:07 AM | | | | | |
| Nunez, Arturo | | REMOVE ALL CHALKBOARDS FROM DIAGNOSTICIAN ROOM AND PAINT | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 94859 | | | | | 10/31/2012 | | 75 | | \$0.00 |
| Medium | Work In Progress | | | 10/31/2012 3:38:26 PM | | | | | |
| Solis, Lorenzo | | NEED SOME ASSITANCE ON TROUBLE SHOOTING HIGH DELTA WATER FOR KITCHEN, BURNED DOS NOT COME ON. | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| 96467 | | | | | 12/11/2012 | | 34 | | \$0.00 |
| Medium | Work In Progress | ROOM 108 | | 12/11/2012 9:01:30 AM | | | | | |
| Briones, Enrique | | NEED TO PICK FURNITURE IN ROOM 108 ANTHONY ELEMENTARY AND PLEASE STORE AT WAREHOUSE TIL WE RETURN TO DISTRIBUTE TO SCHOOL SITES | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 96978 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | SPED | | 1/7/2013 3:57:12 PM | | | | | |
| Lozoya, Manny | | INSTALL NEW CORES ON DOORS OF CAFETERIA | | | | | | | |
| Margaret Villalobos | | | | | | | | | |
| 96738 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:24 AM | | | | | |
| Nunez, Arturo | | Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 93981 | | | | | 10/10/2012 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2012 8:36:04 AM | | | | | |
| Carrasco, Danny | | REQUESTING 10 GAL. UNLEADED FUEL FOR VECHILE # 70 RAN OUT OF FUEL IN CAMPUS. | | | | | | | |
| Arturo Nunez | | | | | | | | | |
| 96779 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:43 AM | | | | | |
| Orozco, Daniel | | Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 91739 | Pump House | | | | 8/23/2012 | | 144 | | \$0.00 |
| Medium | Work In Progress | | | 8/23/2012 9:52:41 AM | | | | | |
| Gonzalez, Salvador | | upper primary pump house tank is leaking | | | | | | | |
| Hector Villalobos | | | | | | | | | |
| 1/14/2013 11:04:40 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|--|-------------------|-------------------------|-------------------|----------------------|------------------|-----------------------------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Anthony ES | | | | | | | |
| 97004 | Main Building | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 1/8/2013 9:34:08 AM | | | | |
| Appelzoller, Fred | water fountain on eastside of new addition does not turn off, keeps running | | | | | | | | |
| <u>David Vega</u> | | | | | | | | | |
| 96992 | Main Building | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 1/8/2013 8:22:43 AM | | | | |
| Sotelo, Enrique | some outside lights are not turning on in main building, and new addition, also street light coming in school entry not turning on | | | | | | | | |
| <u>David Vega</u> | | | | | | | | | |
| 96989 | Main Building | Classroom | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 1/8/2013 8:19:24 AM | | | | |
| Solis, Lorenzo | no heat in rooms 103, 104, 108, 111, speech therapy, and pre k office, upper primary (village) | | | | | | | | |
| <u>David Vega</u> | | | | | | | | | |
| 96998 | Main Building | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 1/8/2013 8:39:13 AM | | | | |
| Lozoya, Manny | chane lock cylinder to h master in drive through gate by old cafeteria | | | | | | | | |
| <u>David Vega</u> | | | | | | | | | |
| 96354 | Original Main | | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 12/7/2012 8:31:03 AM | | | | |
| Sotelo, Enrique | outside lights in old primary building and old cafeteria not turning on at night need to be checked out | | | | | | | | |
| <u>David Vega</u> | | | | | | | | | |
| Count: 34 Work Orders | | | Avg. Age of WO's | 49 | | | Total for Anthony ES | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Berino ES | | | | | | | |
| 97016 | Main Building | Office | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 10:39:24 AM | | | | | |
| Briones, Enrique | | Please deliver 2 boxes of TE'S Kits | | | | | | | |
| <u>Larry Martinez</u> | | | | | | | | | |
| 96785 | | | | | 1/6/2013 | 1/27/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:46 AM | | | | | |
| Orozco, Daniel | | Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96713 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:11 AM | | | | | |
| Duran, Adan | | Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95266 | | | | | 11/7/2012 | | 68 | | \$0.00 |
| Medium | Work In Progress | | | 11/7/2012 10:51:05 AM | | | | | |
| Briones, Enrique | | PICK UP EMPTY BOXES THAT WERE USED TO STORE THE LIBRARY BOOKS | | | | | | | |
| <u>Jimmy Cortez</u> | | | | | | | | | |
| 94887 | | | | | 11/1/2012 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2012 10:52:35 AM | | | | | |
| Lozoya, Manny | | put 2 key cores on muntin in the 2 lobbys | | | | | | | |
| <u>Jimmy Cortez</u> | | | | | | | | | |
| 96688 | | | | | 1/3/2013 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | 1/3/2013 8:41:30 AM | | | | | |
| Solis, Lorenzo | | MR LORENZO SOLIS SIR THE HEATING UNIT ROOM 112 NOT HEATING BOWING COLD AIR PLEASE CHECK THANK YOU SIR | | | | | | | |
| <u>Adan Duran</u> | | | | | | | | | |
| 96600 | | | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | 12/13/2012 3:03:45 PM | | | | | |
| Ontiveros, Joe | | MR FRED APPELL0ZER SIR THE WATER HEATER PORTABLE 155&156 SMALL WATER HEATER IS TO HOT NEED TO ADJUST HOT WATER HEADSTART KIDS THANK YOU SIR AND GOD BLESS | | | | | | | |
| <u>Adan Duran</u> | | | | | | | | | |
| 96760 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:36 AM | | | | | |
| Villalobos, David | | Yearly - Berino ES Backflow Inspection - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 1/14/2013 11:04:40 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|--|------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Berino ES | | | | | | | | | |
| 96714 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:12 AM | | | | | |
| Duran, Adan | Monthly - Berino ES Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96217 | | | | | 12/4/2012 | | 41 | | \$0.00 |
| Medium | Work In Progress | | | 12/4/2012 8:19:14 AM | | | | | |
| Ontiveros, Guadalupe | MR LUPE ONTIVEROS SIR NEED TO CLEAN AND DRESS UP PONDING AREA EAST SIDE BOTTOM FULL OF DIRT THANK YOU SIR AND GOD BLESS | | | | | | | | |
| <u>Adan Duran</u> | | | | | | | | | |
| 94300 | | Office | | | 10/18/2012 | | 88 | | \$0.00 |
| Medium | Work In Progress | OFFICE | | 10/18/2012 9:41:51 AM | | | | | |
| Lozoya, Manny | OFFICE- FOR MANNY LOZOYA- I NEED A NEW NAME PLATE MARIBEL GAMBOA. THANK YOU | | | | | | | | |
| <u>Maribel Chavez</u> | | | | | | | | | |
| 97115 | | Hallway/Corridor | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | 1ST & 2ND | | 1/10/2013 1:26:19 PM | | | | | |
| Lozoya, Manny | NEED TO HAVE THE EXTIROR DOORS REKEYED IN THE 1ST & 2ND HALLWAY | | | | | | | | |
| <u>Maribel Chavez</u> | | | | | | | | | |
| 97206 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:03 AM | | | | | |
| Cortez, Jimmy | Monthly - QRTLY BLDG INSP REPORTS (BE) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95628 | | | | | 11/16/2012 | | 59 | | \$0.00 |
| Medium | Work In Progress | | | 11/16/2012 2:06:10 PM | | | | | |
| Lozoya, Manny | NEED A LOCK AND KEY FOR THE GATE DRAINAGE POND AREA. | | | | | | | | |
| <u>Maribel Chavez</u> | | | | | | | | | |
| 95215 | | | | | 11/6/2012 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/6/2012 8:20:10 AM | | | | | |
| Lozoya, Manny | MANNY LOZOYA PER MR VALTIERRA MANNY NEED TO INSTALL A DEAD-BOLT MAIN ENTRANCE TO LIBRARY FOR BETTER SECURITY THANK YOU SIR AND GOD BLESS | | | | | | | | |
| <u>Adan Duran</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs | |
|------------------------------|---|----------------------------|-------------|----------------------------|------------------|------------------|-----------|---------------|-------------|--|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | | |
| Assigned To | Description | | | | | | | | | |
| Requester Name | | | | | | | | | | |
| Location: | | Berino ES | | | | | | | | |
| 96627 | | | | | 12/14/2012 | | 31 | | \$0.00 | |
| Medium | Work In Progress | | | 12/14/2012 8:17:15 AM | | | | | | |
| Gonzalez, Salvador | MR MIKE MUNOZ AND TO WHOM IT MAY CONCERN SIR THE ROPE ON FLAG POLE BROKE AND IS STUCK ON PULLY WILL NEED LIFT-TRUCK TO REPLACE THANK YOU SIR AND GOD BLESS | | | | | | | | | |
| <u>Adan Duran</u> | | | | | | | | | | |
| 96677 | | | | | 12/31/2012 | | 14 | | \$0.00 | |
| Medium | Work In Progress | | | 12/31/2012 12:27:07 | | | | | | |
| Sanchez, Raul | Monthly - Berino ES - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | | |
| 96715 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 | |
| Medium | Work In Progress | | | 1/6/2013 12:23:12 AM | | | | | | |
| Duran, Adan | Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | | |
| 96717 | | | | | 1/6/2013 | | 8 | | \$0.00 | |
| Medium | Work In Progress | | | 1/6/2013 12:23:14 AM | | | | | | |
| Duran, Adan | Monthly - Berino ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | | |
| 96719 | | | | | 1/6/2013 | | 8 | | \$0.00 | |
| Medium | Work In Progress | | | 1/6/2013 12:23:15 AM | | | | | | |
| Holguin, Alfredo | Monthly - Berino ES - Fire Pump Engine-Quarterly - Refer to PM schedule details. | | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | | |
| 96716 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 | |
| Medium | Work In Progress | | | 1/6/2013 12:23:13 AM | | | | | | |
| Duran, Adan | Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | | |
| 97190 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 | |
| Medium | Work In Progress | | | 1/13/2013 12:15:54 AM | | | | | | |
| Duran, Adan | Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details. | | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | | |
| Count: 22 Work Orders | | Avg. Age of WO's 26 | | Total for Berino ES | | | 0 | \$0.00 | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|---------------------|--|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral ES | | | | | | | |
| 97218 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:09 AM | | | | | |
| Quinones, Paul | Monthly - Chaparral ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96415 | | | | | 12/9/2012 | 12/25/2012 | 36 | | \$0.00 |
| Medium | Work In Progress | | | 12/9/2012 12:16:27 AM | | | | | |
| Quinones, Paul | Monthly - Chaparral ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97150 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 4:13:44 PM | | | | | |
| Quinones, Paul | REMOVE GAS VALVE AND CONTROL IGNITOR FROM REZNOR HEATING UNIT INSTALL NEW GAS VALVE CONTROL IGNITOR, AND T-STAT. REWIRE CONTROLS REPLACE 1 IGNITOR KIT @ 289.00 AND GAS VALVE | | Please make sure you include Enrique and Albert's time too on work order. Thanks | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 95567 | | | | | 11/15/2012 | | 60 | | \$0.00 |
| Scheduled | Work In Progress | | | 11/15/2012 10:34:17 | | | | | |
| Quinones, Paul | Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You | | | | | | | | |
| 96359 | | | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | 12/7/2012 8:44:00 AM | | | | | |
| Quinones, Paul | reorder control ignitor for roof top heaters for restock. | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 96360 | | | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | 12/7/2012 8:48:11 AM | | | | | |
| Quinones, Paul | requesting a spool of 3/8" rope | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 95472 | | | | | 11/13/2012 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | 11/13/2012 3:37:29 PM | | | | | |
| Quinones, Paul | BAD GAS VALVE IN ONE OF THE HEATERS IN 200 WING RM. 205, REQUESTING A COUPLE OF VALVES 1 FOR SPARE. | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|---|---------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral ES | | | | | | | |
| 94569 | | | | | 10/25/2012 | | 81 | | \$0.00 |
| Medium | Work In Progress | | | 10/25/2012 8:31:08 AM | | | | | |
| Quinones, Paul | NEED TO REPLACE 5 BROKEN HEATING ONLY T-STATS | | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 94038 | | | | | 10/11/2012 | | 95 | | \$0.00 |
| High | Work In Progress | | | 10/11/2012 7:27:40 AM | | | | | |
| Quinones, Paul | new furniture came in and needs to be assembled. thank you | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 91935 | | | | | 8/28/2012 | | 139 | | \$0.00 |
| Medium | Work In Progress | | | 8/28/2012 8:14:56 AM | | | | | |
| Quinones, Paul | INSTALL DRIP SECTION FOR PINE TREES IN BETWEEN E-WING AND THE 400 WING FOR WATERING. WATERING HAS BEEN W/ THE WATER HOSE. | | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 96862 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:23 AM | | | | | |
| Quinones, Paul | Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96860 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:22 AM | | | | | |
| Quinones, Paul | Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96974 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 3:47:13 PM | | | | | |
| Quinones, Paul | CHK HEATER NO HEATING NEED TO REPLACE IGNITOR CONTROL, SEND W/O. FOR REORDER, AND STOCK | | | | | | | | |
| Paul Quinones | | | | | | | | | |
| 95651 | | | | | 11/16/2012 | | 59 | | \$0.00 |
| Medium | Work In Progress | | | 11/16/2012 4:32:03 PM | | | | | |
| Martinez, Larry | relocate furniture from che to san miguel for storage. | | | | | | | | |
| Paul Quinones | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|---|-------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral ES | | | | | | | | | |
| 97197 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:15:59 AM | | | | | |
| Ramirez, Daniel | Monthly - QRTLY BLDG INSP REPORT (CE) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 94552 | | | | | 10/24/2012 | | 82 | | \$0.00 |
| Medium | Work In Progress | | | 10/24/2012 3:47:10 PM | | | | | |
| Ontiveros, Guadalupe | requesting dump truck to remove dirt pile mixed with trash on the north west fence line.i have the skid loader to load into dump truck.as per mrs.pargas request the principle. | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 96863 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:24 AM | | | | | |
| Quinones, Paul | Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96758 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:35 AM | | | | | |
| Villalobos, David | Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95374 | | | | | 11/9/2012 | | 66 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2012 2:19:25 PM | | | | | |
| Ontiveros, Joe | requesting new valves for a/c water shut off for winter shut down in wing 4oo.thanks | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 95830 | | | | | 11/27/2012 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | 11/27/2012 3:15:19 PM | | | | | |
| Ontiveros, Joe | outside water fountain leaking from behind wall in front of e-wing. | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 96948 | | Classroom | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | 402 | | 1/7/2013 3:01:23 PM | | | | | |
| Quinones, Paul | need to remove overhead screen from mata's room to send to conference room. See Administration | | | | | | | | |
| <u>Corral, Jennifer</u> | | | | | | | | | |
| 94546 | | | | | 10/24/2012 | | 82 | | \$0.00 |
| Medium | Work In Progress | | | 10/24/2012 3:38:23 PM | | | | | |
| Solis, Lorenzo | requesting 2 wall furnaces for p/e room 100,000 btu's | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 1/14/2013 11:04:41 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|---|---------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral ES | | | | | | | |
| 92134 | | | | | 8/31/2012 | | 136 | | \$0.00 |
| Medium | Work In Progress | | | 8/31/2012 12:24:24 AM | | | | | |
| Quinones, Paul | Monthly - Chaparral ES A-16 Exh Fan (Semi Annual) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95597 | | | | | 11/15/2012 | | 60 | | \$0.00 |
| Medium | Work In Progress | | | 11/15/2012 3:35:10 PM | | | | | |
| Quinones, Paul | need to paint yellow markings on front of school and fire hydrant no parking lane,requesting oilbase paint. | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 95831 | | | | | 11/27/2012 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | 11/27/2012 3:17:14 PM | | | | | |
| Quinones, Paul | need to paint behind e-wing requesting paint | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 95739 | | | | | 11/20/2012 | | 55 | | \$0.00 |
| Medium | Work In Progress | | | 11/20/2012 3:50:37 PM | | | | | |
| Solis, Lorenzo | REQUESTING LIMIT SWITCHES FOR WALL HEATERS | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 94654 | | | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/26/2012 2:50:41 PM | | | | | |
| Sotelo, Enrique | no power to heating units in main wing,chk breakers all are on checked for loose wires. | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 97155 | | | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2013 8:11:06 AM | | | | | |
| Lozoya, Manny | DOOR FRAME TO BOYS REST RM.BEND IN E-WING HARD CLOSING AND OPENING DOOR. | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 96864 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:24 AM | | | | | |
| Quinones, Paul | Monthly - Chaparral ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 91936 | | | | | 8/28/2012 | | 139 | | \$0.00 |
| Medium | Work In Progress | | | 8/28/2012 8:33:17 AM | | | | | |
| Munoz, Michael | REQUESTING NEW ROLL GATES FOR FRONT ENTRANCES | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 1/14/2013 11:04:41 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|--|----------------------------|-------------|-------------------------------|-----------------------|------------------|-----------|---------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral ES | | | | | | | |
| 93672 | | | | | 9/30/2012 | 10/21/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:46 AM | | | | | |
| Orozco, Daniel | Monthly - Chapparral ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96861 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:23 AM | | | | | |
| Quinones, Paul | Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96356 | | | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | 12/7/2012 8:40:15 AM | | | | | |
| Quinones, Paul | requesting transition strip to repair carpet to tile edges in class rooms. | | | | | | | | |
| <u>Paul Quinones</u> | | | | | | | | | |
| 96926 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 11:46:06 AM | | | | | |
| Estrada, Jesus | CARPET NEEDS TO BE REPLACED IN PORTABLE #572 | | | | | | | | |
| <u>Jesus Estrada</u> | | | | | | | | | |
| 96945 | Main Building | Classroom | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | gym | | | 1/7/2013 2:33:45 PM | | | | |
| Lozoya, Manny | need keys for coaches N69 please see Nava and Flores | | | | | | | | |
| <u>Jennifer Corral</u> | | | | | | | | | |
| 97031 | Main Building | Hallway/Corridor | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | whole school | | | 1/8/2013 2:14:58 PM | | | | |
| Lozoya, Manny | main doors going to protables need to be rekeyed so teachers may open with their keys. See Administration | | | | | | | | |
| <u>Jennifer Corral</u> | | | | | | | | | |
| 95441 | Main Building | Hallway/Corridor | | | 11/13/2012 | | 62 | | \$0.00 |
| Medium | Work In Progress | 205 | | | 11/13/2012 9:38:00 AM | | | | |
| Lozoya, Manny | Administration would like another key for the storage room in the conference room. It is used for testing and would like it changed. Please see Ms. Arnold or Ms. Pargas | | | | | | | | |
| <u>Jennifer Corral</u> | | | | | | | | | |
| Count: 37 Work Orders | | Avg. Age of WO's 46 | | Total for Chaparral ES | | | 0 | \$0.00 | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|--|------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral HS | | | | | | | | | |
| 96443 | Pre-K | | | | 12/10/2012 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | 12/10/2012 3:07:05 PM | | | | | |
| Gonzalez, Salvador | Need to repaid gate door, lach broken. | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 96936 | Pre-K | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 1:10:55 PM | | | | | |
| Solis, Lorenzo | Having problom with heater in Health center | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 95825 | Pre-K | | | | 11/27/2012 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | 11/27/2012 2:56:41 PM | | | | | |
| Ortiz, Alfredo | Need to sweep sand from side-walk and shavel sand, from high side to low area. | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 97109 | A-Wing | Classroom | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 11:44:40 AM | | | | | |
| Lozoya, Manny | Room A110. Closet door doesn't lock. It is broken. (Ms. Harkless) | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 96925 | A-Wing | Office | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 11:35:25 AM | | | | | |
| Lozoya, Manny | 2nd request please fix nurse's main door does not open or close with key. | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 96563 | A-Wing | Hallway/Corridor | | | 12/12/2012 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | 12/12/2012 4:00:58 PM | | | | | |
| Sotelo, Enrique | Need to replace light switches in A-wing hallway and office. | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 96529 | A-Wing | Hallway/Corridor | | | 12/12/2012 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | 12/12/2012 8:57:47 AM | | | | | |
| Lozoya, Manny | Outer door lock will not open with key. Door is 3rd outer door from nurse's office, between CAP class and ISS class. (Ms. Lopez) | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 96425 | A-Wing | Classroom | | | 12/10/2012 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | 12/10/2012 9:17:38 AM | | | | | |
| Lozoya, Manny | Key #4 for the front door in the nurse's office will not unlock or lock. (Rosie Higgs) | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------|--|---------------------|------------------------------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral HS | | | | | | | |
| 96442 | A-Wing | Classroom | | | 12/10/2012 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | 12/10/2012 3:02:17 PM | | | | | |
| Lozoya, Manny | Having problem with door can't open with key in Nures office. | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 96907 | A-Wing | Cafeteria | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 8:42:27 AM | | | | | |
| Lozoya, Manny | Cafeteria doors lach don't work 3 doors. | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 95767 | A-Wing | Hallway/Corridor | | | 11/26/2012 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | 11/26/2012 12:25:38 | | | | | |
| Ortiz, Alfredo | Need to remove sand from roof-top. A-wing. | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 90826 | A-Wing | Classroom | | | 8/6/2012 | | 161 | | \$0.00 |
| Medium | Work In Progress | | | 8/6/2012 9:16:20 AM | | | | | |
| Ortiz, Alfredo | Need blinds in room A-107. Room gets too hot and for safety reasons as well. (Ms Henry) | | asp report 10/30/12 parts on order | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 90828 | A-Wing | Classroom | | | 8/6/2012 | | 161 | | \$0.00 |
| Medium | Work In Progress | | | 8/6/2012 9:18:17 AM | | | | | |
| Ortiz, Alfredo | Need blinds installed in room A-106. The blinds will help keep the heat out and safety issue in case of an emergency. (Ms. Heddleston) | | asp report 10/30/12 parts on order | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 96930 | B-Wing | Hallway/Corridor | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 12:25:09 PM | | | | | |
| Ortiz, Alfredo | Need a trap to catch a raccoon on roof top | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 96542 | C-Wing | Hallway/Corridor | | | 12/12/2012 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | 12/12/2012 12:58:53 | | | | | |
| Ortiz, Alfredo | Need to replace some toilet seats in C-wing steff and boy-restrooms. | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 95563 | D-Wing | Classroom | | | 11/15/2012 | | 60 | | \$0.00 |
| Medium | Work In Progress | | | 11/15/2012 9:09:07 AM | | | | | |
| Ontiveros, Joe | Need to fix Electric gas soilinoid valves in science room D-7 keeps burning fuses and on gas comes out. | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------|--|---------------------|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral HS | | | | | | | |
| 95935 | D-Wing | Restroom (Boys) | | | 11/29/2012 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | | 11/29/2012 11:17:17 | | | | |
| Ontiveros, Joe | Need to replace two faucets in boys restroom, brokend. | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 96585 | D-Wing | Classroom | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 12/13/2012 11:39:45 | | | | |
| Solis, Lorenzo | Having problom with D-Sped heater | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 96616 | D-Wing | Hallway/Corridor | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 12/13/2012 3:52:16 PM | | | | |
| Ronquillo, Ruben | Need to replace broken window on door D-wing double door in hallway | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 95516 | D-Wing | Hallway/Corridor | | | 11/14/2012 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | | 11/14/2012 1:15:49 PM | | | | |
| Carrasco, Danny | Need the Scissor-lift to clean smoke detectors and replace light bulbs in GYM. | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 97083 | E-Wing | Restroom (Boys) | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 1/10/2013 7:27:26 AM | | | | |
| Ontiveros, Joe | 3RD sink faucet broke | | | | | | | | |
| Jesus Urquidi | | | | | | | | | |
| 97084 | E-Wing | Restroom (Boys) | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 1/10/2013 7:28:33 AM | | | | |
| Ontiveros, Joe | middle toilet still clugging up | | | | | | | | |
| Jesus Urquidi | | | | | | | | | |
| 97085 | F-Wing | Restroom (Boys) | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 1/10/2013 7:29:47 AM | | | | |
| Ontiveros, Joe | middle toilet still cluging up | | | | | | | | |
| Jesus Urquidi | | | | | | | | | |
| 97086 | F-Wing | Restroom (Girls) | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 1/10/2013 7:30:58 AM | | | | |
| Ontiveros, Joe | 3rd faucet loose | | | | | | | | |
| Jesus Urquidi | | | | | | | | | |
| 91888 | G-Wing | Restroom (Boys) | | | 8/27/2012 | | 140 | | \$0.00 |
| Medium | Work In Progress | | | | 8/27/2012 11:27:10 AM | | | | |
| Sotelo, Enrique | hand dryer broke | | | | | | | | |
| Jesus Urquidi | | | | | | | | | |
| 1/14/2013 11:04:41 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------|---|---------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral HS | | | | | | | |
| 95869 | Q-Wing | Restroom (Girls) | | | 11/28/2012 | | 47 | | \$0.00 |
| Medium | Work In Progress | | | 11/28/2012 12:08:54 | | | | | |
| Ontiveros, Joe | Need to replace two faucets in girls restroom. | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 96530 | Q-Wing | Classroom | | | 12/12/2012 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | 12/12/2012 9:36:37 AM | | | | | |
| Solis, Lorenzo | In Q-7 having problem with heaters | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 96906 | R-Wing | Classroom | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 8:38:20 AM | | | | | |
| Lozoya, Manny | Need to replace door handle broken too sharp may cut students | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 95870 | R-Wing | Restroom (Girls) | | | 11/28/2012 | | 47 | | \$0.00 |
| Medium | Work In Progress | | | 11/28/2012 12:11:13 | | | | | |
| Ontiveros, Joe | Two faucets brokend need to be replaced. | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 95765 | R-Wing | Restroom (Boys) | | | 11/26/2012 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | 11/26/2012 12:19:37 | | | | | |
| Ontiveros, Joe | nEED TO REPLACE 1 FAUSET IN BOYSRESTROOM. | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 94898 | R-Wing | Classroom | | | 11/1/2012 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2012 11:59:27 AM | | | | | |
| Lozoya, Manny | Door handle to storeroom in R1 has broken. Needs to be replaced. (Mr. Gabaldon) | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 89726 | Field House | Athletic Field | | | 7/10/2012 | | 188 | | \$0.00 |
| Medium | Work In Progress | | | 7/10/2012 4:23:59 PM | | | | | |
| Valdez, Pedro | We need 8 sets of tires attached to the soccer goals to make them mobile. | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 93777 | Field House | Athletic Field | | | 10/3/2012 | | 103 | | \$0.00 |
| Medium | Work In Progress | | | 10/3/2012 7:29:03 AM | | | | | |
| Gonzalez, Salvador | Please put permanent shade in socccer fields. (Arnold Orozco) | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral HS | | | | | | | |
| 93194 | Field House | Athletic Field | | | 9/24/2012 | | 112 | | \$0.00 |
| Medium | Work In Progress | | | 9/24/2012 3:47:39 PM | | | | | |
| Sotelo, Enrique | | The light pole located out by the large concrete area does not work. It seems like it needs a new bulb. It is located by the football practice field on concession area. It needs to be lit up for football games. (Ms. Ulibarri) | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 96352 | | Pump House | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | 12/7/2012 7:58:18 AM | | | | | |
| Munoz, Michael | | Having problem with the fire pump | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 96931 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 12:27:41 PM | | | | | |
| Ontiveros, Guadalupe | | need fuel for fire pump code 706 | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 96784 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:45 AM | | | | | |
| Orozco, Daniel | | Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96780 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:43 AM | | | | | |
| Orozco, Daniel | | Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96733 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:22 AM | | | | | |
| Ortiz, Alfredo | | Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93668 | | | | | 9/30/2012 | 10/21/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:44 AM | | | | | |
| Orozco, Daniel | | Monthly - Chaparral HS Range Hood Cleaning - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96734 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:22 AM | | | | | |
| Ortiz, Alfredo | | Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|------------------|---|--|-----------------------|------------------|---|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral HS | | | | | | | |
| 89952 | | | | | 7/18/2012 | | 180 | | \$0.00 |
| Medium | Work In Progress | | | 7/18/2012 10:01:25 AM | | | | | |
| Carbajal, Jimmy | | auto scrubber nss SR. 232312A 36169435 | does not pick up water. | | | 11/30/12 - JIMMY, NEEDS TO SCHEDULE AND PICK UP MACHINE. | | | |
| <u>Jesus Urquidi</u> | | | | | | | | | |
| 93161 | | | | | 9/24/2012 | | 112 | | \$0.00 |
| Medium | Work In Progress | | | 9/24/2012 9:14:21 AM | | | | | |
| Carbajal, Jimmy | | auto scrubber sn 8000062994 | scrub brush does not turn also loosing power very quickly. | | | 11/30/12 - ASP JIMMY, NEEDS TO SCHEDULE AND PICK UP FOR SERVICE | | | |
| <u>Jesus Urquidi</u> | | | | | | | | | |
| 96183 | | Hallway/Corridor | | | 12/3/2012 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/3/2012 2:40:58 PM | | | | | |
| Sotelo, Enrique | | Need to replace 10 BALLAST | Magnetic 70w Metal Halide. | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 97064 | | Classroom | | | 1/9/2013 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | 1/9/2013 1:47:46 PM | | | | | |
| Sotelo, Enrique | | Need 10 duplex receptacle 20 amp., 10 singal pole switch 20 amp., 10 3-way key switches 20 amp., 10 male plugs 2pole 3-wire 15amp., 10 femail plug 2pole 3-wire 15amp. for stock. | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 96016 | | Athletic Field | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2012 3:23:44 PM | | | | | |
| Castillo, Carlos | | power will be needed for new scoreboards for base ball/softball. Please contact lynco for quote. thank you | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 97035 | | Athletic Field | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 3:23:26 PM | | | | | |
| Castillo, Carlos | | Requesting power to center area of Chaparral baseball fields for outdoor events. | | | | | | | |
| <u>Carlos Castillo</u> | | | | | | | | | |
| 89769 | | | | | 7/11/2012 | | 187 | | \$0.00 |
| Medium | Work In Progress | | | 7/11/2012 4:18:19 PM | | | | | |
| Vallejo, Albert | | Replace pump motor at lift station for amphitheater. | | | | | | | |
| <u>Albert Vallejo</u> | | | | | | | | | |
| 96737 | | | | | 1/6/2013 | 1/9/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:24 AM | | | | | |
| Ortiz, Alfredo | | Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 1/14/2013 11:04:41 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|---|---------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral HS | | | | | | | |
| 92674 | | Cafeteria | | | 9/11/2012 | | 125 | | \$0.00 |
| Medium | Work In Progress | | | 9/11/2012 11:15:45 AM | | | | | |
| Ontiveros, Joe | Need a water fountain for the students in the same area where tables are needed. (Lupe Quinones) | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 96777 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:42 AM | | | | | |
| Villalobos, David | Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96668 | | | | | 12/16/2012 | | 29 | | \$0.00 |
| Medium | Work In Progress | | | 12/16/2012 12:16:10 | | | | | |
| Valdez, Pedro | Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96736 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:23 AM | | | | | |
| Ortiz, Alfredo | Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97219 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:10 AM | | | | | |
| Urquidi, Jesus | Monthly - QRTLY BLDG INSP REPORT (CH) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 92414 | | Classroom | | | 9/5/2012 | | 131 | | \$0.00 |
| Medium | Work In Progress | | | 9/5/2012 10:29:17 AM | | | | | |
| Vargas, Juan | Whirlpool motor is burned out please take a look at. (Mr. Beets, trainer) | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 96573 | | | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | 12/13/2012 8:37:31 AM | | | | | |
| Carbajal, Jimmy | Need 1 vaccum roller and 3 belts for regular vaccum cleaner. | | | | | | | | |
| <u>Jesus Urquidi</u> | | | | | | | | | |
| 96629 | | Classroom | | | 12/14/2012 | | 31 | | \$0.00 |
| Medium | Work In Progress | | | 12/14/2012 10:02:17 | | | | | |
| Lozoya, Manny | We need a new master key for our custodian. He is having trouble opening some doors. The key might be worn out or bent. Please replace. (Mireya Meza) | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|---------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral HS | | | | | | | |
| 90843 | | | | | 8/6/2012 | | 161 | | \$0.00 |
| Medium | Work In Progress | | | 8/6/2012 11:26:25 AM | | | | | |
| Lozoya, Manny | We need the following keys made for CHS. Room A-108, #86 (6), light keys (10), key to staff room in library, key for trophy case in cafeteria and overhead in Q building. | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 93872 | | Gym | | | 10/8/2012 | | 98 | | \$0.00 |
| Medium | Work In Progress | | | 10/8/2012 10:22:32 AM | | | | | |
| Solis, Lorenzo | The ice machine in the trainer's room in the gym is not working at all. (Mr. Beets) | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 97063 | | | | | 1/9/2013 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | 1/9/2013 1:29:21 PM | | | | | |
| Lozoya, Manny | Need to replace lock on tool storage shed for Gardner brokend | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 93934 | | | | | 10/9/2012 | | 97 | | \$0.00 |
| Medium | Work In Progress | | | 10/9/2012 10:33:13 AM | | | | | |
| Flores, Pete | Truck is trembling alot and have a hard time starting it. | | | | | | | | |
| <u>Jesus Urquidi</u> | | | | | | | | | |
| 96723 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:16 AM | | | | | |
| Holguin, Alfredo | Monthly - Chaparral HS - Fire Pump Eng (Quarterly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95848 | | Hallway/Corridor | | | 11/27/2012 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | 11/27/2012 3:45:08 PM | | | | | |
| Ortiz, Alfredo | Need to replace filters in all the hallways | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 95255 | | Hallway/Corridor | | | 11/7/2012 | | 68 | | \$0.00 |
| Medium | Work In Progress | | | 11/7/2012 8:32:24 AM | | | | | |
| Ortiz, Alfredo | Need to replace push lever on Refrigeration water fountains ELKAY Mod # EZS-8 there are 3 in all. | | | | | | | | |
| <u>Alfredo Ortiz</u> | | | | | | | | | |
| 95940 | | Classroom | | | 11/29/2012 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | 11/29/2012 11:39:16 | | | | | |
| Ortiz, Alfredo | Need to replace several ceiling tiles in several classrooms. | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 1/14/2013 11:04:41 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------|--|---------------------|-------------|-----------------------|------------------|----------------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral HS | | | | | | | |
| 95366 | | Hallway/Corridor | | | 11/9/2012 | | 66 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2012 1:43:13 PM | | | | | |
| Ortiz, Alfredo | Need to replace several weatherproof covers out side throw-out school campus. | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 96187 | | | | | 12/3/2012 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/3/2012 3:02:38 PM | | | | | |
| Ortiz, Alfredo | Need to order some tools to work with. | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 95953 | | | | | 11/29/2012 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | 11/29/2012 3:32:43 PM | | | | | |
| Ortiz, Alfredo | Need to pick-up trash and blow sand from side-walk around High school. | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 96489 | | Classroom | | | 12/11/2012 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | 12/11/2012 3:32:29 PM | | | | | |
| Ortiz, Alfredo | NEED TO REPLACE SEVERAL TEMPERATURE SENSORS. | | | | | | | | |
| Alfredo Ortiz | | | | | | | | | |
| 96735 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:23 AM | | | | | |
| Ortiz, Alfredo | Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96586 | | Parking Lot | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | 12/13/2012 11:43:18 | | | | | |
| Ortiz, Alfredo | We need several signs to be placed at different locations of the school. Please see Lupe Quinones for signs. | | | | | | | | |
| Mireya Meza | | | | | | | | | |
| 91038 | | | | | 8/9/2012 | | 158 | | \$0.00 |
| Medium | Work In Progress | | | 8/9/2012 8:45:38 AM | | | | | |
| Ortiz, Alfredo | Class R3 needs "back splashes" behind the sinks to prevent the wall from getting water damage and mold. Tile would work really well. It would also be easy to clean. Sizes 2 feet by 112 inches preferably or 2 feet by 44 inches. (ms. padgett) | | | | | 12/5 - Reroute to A. Ortiz | | | |
| Mireya Meza | | | | | | | | | |
| 96731 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:21 AM | | | | | |
| Ortiz, Alfredo | Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 1/14/2013 11:04:41 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|---|---------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral HS | | | | | | | |
| 96732 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:21 AM | | | | | |
| Ortiz, Alfredo | Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 94627 | | | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/26/2012 8:23:20 AM | | | | | |
| Apodaca, Mario | Need to rebuild slump pump at the empathy theater outside the main building Chaparral High School | | | | | | | | |
| <u>Mario Apodaca</u> | | | | | | | | | |
| 96845 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:15 AM | | | | | |
| Apodaca, Mario | Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 92677 | | | | | 9/11/2012 | | 125 | | \$0.00 |
| Medium | Work In Progress | | | 9/11/2012 11:25:49 AM | | | | | |
| Apodaca, Mario | Need to install base to mount pump hoist in amphitheater lift station. | | | | | | | | |
| <u>Albert Vallejo</u> | | | | | | | | | |
| 90833 | | | | | 8/6/2012 | | 161 | | \$0.00 |
| Medium | Work In Progress | | | 8/6/2012 10:03:59 AM | | | | | |
| Gonzalez, Salvador | Need to weld Soccer Goals | | | | | | | | |
| <u>Guadalupe Ontiveros</u> | | | | | | | | | |
| 96587 | | Parking Lot | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | 12/13/2012 11:46:18 | | | | | |
| Gonzalez, Salvador | I also need a metal stop bar that comes from the end of the fence that also includes a seperate pole so that driving access can be denied because the students and parents are cutting off the busses as they are driving off. Please see Lupe Quinones for location. | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |
| 92673 | | Cafeteria | | | 9/11/2012 | | 125 | | \$0.00 |
| Medium | Work In Progress | | | 9/11/2012 11:14:39 AM | | | | | |
| Gonzalez, Salvador | Need to create some kind of shade for the students at the sitting area. (Lupe Quinones) | | | | | | | | |
| <u>Mireya Meza</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|---|---------------------|-------------------------|-----------|-----------------------|-------------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | | | Action Taken | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral HS | | | | | | | |
| 94353 | | | | | 10/19/2012 | | 87 | | \$0.00 |
| Medium | Work In Progress | | | | 10/19/2012 8:29:49 AM | | | | |
| Orozco, Daniel | Meat processor, the top cover is hard to close and when we close the top cover it scrapes and it releases metal and I know if I use it, it will fall into whatever we are processing. SNP Manager Juanita M. 824.4461 | | | | | | | | |
| <hr/> | | | | | | | | | |
| 96024 | | Athletic Field | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | | 11/30/2012 3:38:16 PM | | | | |
| Gonzalez, Salvador | please order material for install of new scoreboards .baseball / softball.thank you | | | | | | | | |
| <hr/> | | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| Count: 82 Work Orders | | | Avg. Age of WO's | 54 | | Total for Chaparral HS | 0 | | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------|--|---------------------|-------------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral MS | | | | | | | |
| 95176 | | | | | 11/5/2012 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | 11/5/2012 2:14:02 PM | | | | | |
| Gonzalez, Salvador | Please fabricate ice machine stand in Athletics locker room. | | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 92678 | | | | | 9/11/2012 | | 125 | | \$0.00 |
| Medium | Work In Progress | | | 9/11/2012 11:27:08 AM | | | | | |
| Apodaca, Mario | I would like to have Mario come out to help me work on the irrigation booster pump. | | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 96727 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:18 AM | | | | | |
| Vallejo, Albert | Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96728 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:19 AM | | | | | |
| Vallejo, Albert | Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 91741 | | Restroom (Boys) | | | 8/23/2012 | | 144 | | \$0.00 |
| Medium | Work In Progress | | | 8/23/2012 10:12:01 AM | | | | | |
| Vallejo, Albert | pegar tile en restrooms boys en manhallway | | coincides w/84144 | | | | | | |
| M. Carmen Perez | | | | | | | | | |
| 96464 | | | | | 12/11/2012 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | 12/11/2012 8:50:55 AM | | | | | |
| Vallejo, Albert | Teacher would like to be able to control the heat in the classroom instead of turning on the air to cool the room | | | | | | | | |
| Gidget Mora | | | | | | | | | |
| 95569 | | | | | 11/15/2012 | | 60 | | \$0.00 |
| Scheduled | Work In Progress | | | 11/15/2012 10:37:08 | | | | | |
| Vallejo, Albert | Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You | | | | | | | | |
| 95626 | | | | | 11/16/2012 | | 59 | | \$0.00 |
| Medium | Work In Progress | | | 11/16/2012 1:23:40 PM | | | | | |
| Vallejo, Albert | Set up power monitor at GHS Treatment plant. | | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 1/14/2013 11:04:41 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------|--|---------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral MS | | | | | | | |
| 95356 | | | | | 11/9/2012 | | 66 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2012 9:12:19 AM | | | | | |
| Vallejo, Albert | Repair existing lavatories in 200 and 300 restrooms. | | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 96725 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:17 AM | | | | | |
| Vallejo, Albert | Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96729 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:20 AM | | | | | |
| Vallejo, Albert | Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 93936 | | | | | 10/9/2012 | | 97 | | \$0.00 |
| Medium | Work In Progress | | | 10/9/2012 10:43:47 AM | | | | | |
| Flores, Pete | as per our meeting , please assign vehicle # 121 to albert. thank you | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 96486 | | | | | 12/11/2012 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | 12/11/2012 3:21:43 PM | | | | | |
| Lozoya, Manny | Key to room 106 is not working properly | | | | | | | | |
| Albert Vallejo | | | | | | | | | |
| 94910 | | Athletic Field | | | 11/1/2012 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2012 3:17:23 PM | | | | | |
| Ontiveros, Guadalupe | need two backstops to be built and installed for baseball. | | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |
| 97223 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:12 AM | | | | | |
| Gonzalez, Robert | Monthly - QRTLY BLDG INSP REPORTS (CM) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96771 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:40 AM | | | | | |
| Villalobos, David | Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|---------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Chaparral MS | | | | | | | |
| 96726 | | | | | 1/6/2013 | 1/9/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:18 AM | | | | | |
| Vallejo, Albert | Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 89871 | | | | | 7/16/2012 | | 182 | | \$0.00 |
| Medium | Work In Progress | | | 7/16/2012 4:19:52 PM | | | | | |
| Vallejo, Albert | Re-paint Fire lanes with red GLOSS paint. | | | | | | | | |
| <u>Albert Vallejo</u> | | | | | | | | | |
| 96730 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:20 AM | | | | | |
| Vallejo, Albert | Monthly - Chaparral MS Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96162 | | Parking Lot | | | 12/3/2012 | | 42 | | \$0.00 |
| Safety | Work In Progress | | | 12/3/2012 7:30:45 AM | | | | | |
| Vallejo, Albert | there is a lip on the asphalt where it meets with the handi cap concrete ramp in the front sidewalk. this needs to be level. parent tripped this past saturday while at basketball game. thank you | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 96786 | | | | | 1/6/2013 | 1/27/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:46 AM | | | | | |
| Orozco, Daniel | Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96911 | Main Building | Classroom | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | 104 | | 1/7/2013 8:47:55 AM | | | | | |
| Vallejo, Albert | Window shades no longer functional. Please Replace | | | | | | | | |
| <u>Gidget Mora</u> | | | | | | | | | |
| 96465 | Main Building | Classroom | | | 12/11/2012 | | 34 | | \$0.00 |
| Medium | Work In Progress | 311 | | 12/11/2012 8:54:42 AM | | | | | |
| Vallejo, Albert | please replace ceiling tiles becuase they are stained and look like they are ready to fall | | | | | | | | |
| <u>Gidget Mora</u> | | | | | | | | | |
| 96007 | Main Building | Office | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2012 2:39:01 PM | | | | | |
| Vallejo, Albert | Please replace a file that is smashed in pieces at the nurse's office. | | | | | | | | |
| <u>Gidget Mora</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------------------|-----------|-----------------------|-------------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Chaparral MS | | | | | | | | | |
| 93243 | Main Building | Restroom (Boys) | | | 9/25/2012 | | 111 | | \$0.00 |
| Medium | Work In Progress | | | | 9/25/2012 3:21:37 PM | | | | |
| Vallejo, Albert | | Please repair the hole in the boys restroom. | | | | | | | |
| <u>Gidget Mora</u> | | | | | | | | | |
| 95751 | Main Building | Gym | | | 11/26/2012 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | | 11/26/2012 8:09:59 AM | | | | |
| Lozoya, Manny | | Please make gym key for administrator. Coach is out and no one can get into the room. | | | | | | | |
| <u>Gidget Mora</u> | | | | | | | | | |
| 93237 | Main Building | Classroom | | | 9/25/2012 | | 111 | | \$0.00 |
| Medium | Work In Progress | 308 | | | 9/25/2012 3:11:29 PM | | | | |
| Lozoya, Manny | | Teacher would like locks put on cabinets | | | | | | | |
| <u>Gidget Mora</u> | | | | | | | | | |
| Count: 27 Work Orders | | | Avg. Age of WO's | 52 | | Total for Chaparral MS | 0 | | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|------------------|--|-------------|-----------|---------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: | | Charter School | | | | | | | |
| 96216 | | Parking Lot | | | 12/4/2012 | | 41 | | \$0.00 |
| Medium | Work In Progress | | | | 12/4/2012 8:04:07 AM | | | | |
| Villalobos, David | | Constant drip on 8" fire protection bfp need to replace check valves | | | | | | | |
| David Villalobos | | | | | | | | | |
| Count: 1 Work Orders | | Avg. Age of WO's | | 41 | Total for Charter School | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|---------------------|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert Pride | | | | | | | |
| 95455 | | Office | | | 11/13/2012 | | 62 | | \$0.00 |
| Medium | Work In Progress | RESTROOM | | | 11/13/2012 1:10:10 PM | | | | |
| Appelzoller, Fred | WHEN TOILET IS FLUSHED WATER COMES OR BUBBLES BACK UP. SEPTIC TANK WAS CLEAN OUT 10/26/12 | | | | | | | | |
| <u>David Acosta</u> | | | | | | | | | |
| 95561 | | Office | | | 11/15/2012 | | 60 | | \$0.00 |
| Medium | Work In Progress | RESTROOM | | | 11/15/2012 8:50:39 AM | | | | |
| Appelzoller, Fred | MAY NEED TO REPLACE CRACKED SINK AND LEAKY FAUCET IN STAFF RESTROOM | | | | | | | | |
| <u>David Acosta</u> | | | | | | | | | |
| 93272 | | Portables | | | 9/26/2012 | | 110 | | \$0.00 |
| Medium | Work In Progress | | | | 9/26/2012 9:14:50 AM | | | | |
| Ontiveros, Guadalupe | please assist with the trenching for a new electrical line to the portable this friday 9-28-12.thank you | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 96856 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:24:20 AM | | | | |
| Aguilar, Patricio | Monthly - Desert Pride Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97028 | | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 1/8/2013 12:51:42 PM | | | | |
| Ontiveros, Guadalupe | Repair entrance on road to bus entrance. | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 97195 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | | 1/13/2013 12:15:58 AM | | | | |
| Acosta, David | Monthly - QRTLY BLDG INSP REPORT (DP) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 92503 | | Portables | | | 9/6/2012 | | 130 | | \$0.00 |
| Medium | Work In Progress | | | | 9/6/2012 4:08:35 PM | | | | |
| Ambriz, Jose | desert pride will be receive a portable on 9-07-12. please provide a new window evaporative cooler and a new wall heater w/ fan. thank you | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 96747 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:23:29 AM | | | | |
| Acosta, David | Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 1/14/2013 11:04:41 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|---|---------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert Pride | | | | | | | |
| 96748 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:30 AM | | | | | |
| Acosta, David | Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 94720 | | Portables | | | 10/29/2012 | | 77 | | \$0.00 |
| Medium | Work In Progress | | | 10/29/2012 3:24:15 PM | | | | | |
| Miranda, Danny | Need to redeck portable when abatement is complete. | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 96874 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:30 AM | | | | | |
| Sanchez, Raul | Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97229 | | | | | 1/14/2013 | | 0 | | \$0.00 |
| Medium | Work In Progress | | | 1/14/2013 12:18:44 AM | | | | | |
| Sanchez, Raul | Monthly - Desert Pride - Water Filters - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96624 | | | | | 12/14/2012 | | 31 | | \$0.00 |
| Medium | Work In Progress | | | 12/14/2012 12:16:37 | | | | | |
| Sanchez, Raul | Monthly - Desert Pride - Water Filters - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97165 | | | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2013 3:16:16 PM | | | | | |
| Gonzalez, Salvador | please raise rolling gate where busses enter. road was lifted and now gate needs to be raised. please see mike for details. thank you | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 96680 | | | | | 12/31/2012 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | 12/31/2012 12:27:08 | | | | | |
| Sanchez, Raul | Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|--|----------------------------|-------------|-------------------------------|------------------|------------------|-----------|---------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert Pride | | | | | | | |
| 92513 | | | | | 9/7/2012 | | 129 | | \$0.00 |
| Medium | Work In Progress | | | 9/7/2012 9:19:09 AM | | | | | |
| Estrada, Jesus | PORTABLE FROM SAN MIGUEL WILL BE RELOCATED TO DESERT PRIDE. NEED TO HAVE CARPET REPLACED. | | | | | | | | |
| | 9/7/12 REVISED - NEED TO REPLACE CARPET WITH LINOLEUM AND 4" COVE BASE | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 94686 | | Portables | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/26/2012 4:02:37 PM | | | | | |
| Munoz, Michael | need new side walk for portable that was relocated from san miguel and fill in areas with concrete next to 2nd building to prevent water from going under and repair side walk next to 3rd building. | | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 96746 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:29 AM | | | | | |
| Acosta, David | Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96477 | | Classroom | | | 12/11/2012 | | 34 | | \$0.00 |
| Medium | Work In Progress | ROOM 9 | | 12/11/2012 12:15:40 | | | | | |
| Lara, Ralph | MAY NEED TO REPLACE WOOD DOOR FRAME. (AS SPLITS OR CRACKS) AND SCREWS TO HINGES KEEP COMING LOOSE. | | | | | | | | |
| David Acosta | | | | | | | | | |
| Count: 19 Work Orders | | Avg. Age of WO's 41 | | Total for Desert Pride | | | 0 | \$0.00 | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|----------------------------------|-------------|----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert Trail Intermediate | | | | | | | |
| 92723 | | | | | 9/12/2012 | | 124 | | \$0.00 |
| Medium | Work In Progress | | | 9/12/2012 8:26:47 AM | | | | | |
| Orozco, Daniel | Threshold to walk-in cooler came loose again. Also, please replace thermocouple to stove's oven. (Pilot keeps turning off) thank you. SNP Manager Pat C. 824.3822 | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 97023 | | Custodial | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 11:45:06 AM | | | | | |
| Carbajal, Jimmy | Jimmy buenas tardes por favor pude revisar la aspiradora Num 0214 huele a quemado cuando la prenden gracias | | | | | | | | |
| <u>Laura Sandoval</u> | | | | | | | | | |
| 96928 | | Custodial | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 12:18:13 PM | | | | | |
| Carbajal, Jimmy | hola jimmy por favor puede venir por la aspiradora Num 0255 la llantita se le cayo gracias | | | | | | | | |
| <u>Laura Sandoval</u> | | | | | | | | | |
| 96929 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 12:21:27 PM | | | | | |
| Carbajal, Jimmy | Jimmy tambien aesta aspiradora se le callo la llantita Num1162 gracias | | | | | | | | |
| <u>Laura Sandoval</u> | | | | | | | | | |
| 96810 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:57 AM | | | | | |
| Acuna, Johnny | Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95306 | | Custodial | | | 11/8/2012 | | 67 | | \$0.00 |
| Medium | Work In Progress | | | 11/8/2012 7:10:35 AM | | | | | |
| Estrada, Jesus | Chuy buenos dias si puede revisar por favor los portables Num.405 y 406 pues la alfombra que pusieron se esta desilando gracias | | | | | | | | |
| <u>Laura Sandoval</u> | | | | | | | | | |
| 95308 | | Custodial | | | 11/8/2012 | | 67 | | \$0.00 |
| Medium | Work In Progress | | | 11/8/2012 7:28:35 AM | | | | | |
| Estrada, Jesus | Chuy por favor puede revisar el piso de los portables Num. 414 y 415 el tile se esta quebrando enpedasitos , Jhonny ya los a remplasado y se buelben a quebrar muchas gracias que tenga buen dia | | | | | | | | |
| Laura Sandoval | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|---|----------------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert Trail Intermediate | | | | | | | |
| 96787 | | | | | 1/6/2013 | 1/27/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:46 AM | | | | | |
| Orozco, Daniel | Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96267 | | | | | 12/5/2012 | | 40 | | \$0.00 |
| Medium | Work In Progress | | | 12/5/2012 8:31:37 AM | | | | | |
| Carrasco, Danny | Need to borrow scissor lift to grease and service heating units to Cafeteria. | | | | | | | | |
| <u>Johnny Acuna</u> | | | | | | | | | |
| 94101 | | | | | 10/12/2012 | | 94 | | \$0.00 |
| Medium | Work In Progress | | | 10/12/2012 11:06:14 | | | | | |
| Carrasco, Danny | Need to borrow scissor lift to service cafeteria heating units and replace batteries to cafeteria emergency light kits. | | | | | | | | |
| <u>Johnny Acuna</u> | | | | | | | | | |
| 97062 | | | | | 1/9/2013 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | 1/9/2013 12:36:33 PM | | | | | |
| Orozco, Daniel | ONE OVEN IS NOT WORKING. SNP MANAGER PAT C. 824.3822 | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 97205 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:03 AM | | | | | |
| Acuna, Johnny | Monthly - Desert Trail Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96410 | | | | | 12/9/2012 | 12/25/2012 | 36 | | \$0.00 |
| Medium | Work In Progress | | | 12/9/2012 12:16:25 AM | | | | | |
| Acuna, Johnny | Monthly - Desert Trail Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96812 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:58 AM | | | | | |
| Acuna, Johnny | Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96089 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:03 AM | | | | | |
| Acuna, Johnny | Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|---|----------------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert Trail Intermediate | | | | | | | |
| 96813 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:59 AM | | | | | |
| Acuna, Johnny | Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96814 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:59 AM | | | | | |
| Acuna, Johnny | Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95945 | | Portables | | | 11/29/2012 | | 46 | | \$0.00 |
| High | Work In Progress | | | 11/29/2012 1:44:57 PM | | | | | |
| Acuna, Johnny | The installation date for the HVAC Project at Desert Trail Elementary has been set for Wednesday, December 19th starting at 7:30 am. Need Johnny Acuna to unlock the portables that morning as well as show us where the electrical shut-offs are for the portables. NergyMaster will then call about an hour before finishing so all the portables and electrical boxes secured. | | | | | | | | |
| | Please call or email if you have any questions and thanks in advance for everyone's cooperation! | | | | | | | | |
| | Beth Tuke NergyMaster, LLC 575-644-1384 | | | | | | | | |
| 97027 | | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 12:22:40 PM | | | | | |
| Lozoya, Manny | need to fix cabinet lock to classroom. | | | | | | | | |
| <u>Johnny Acuna</u> | | | | | | | | | |
| 97107 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | front office | | 1/10/2013 11:02:23 AM | | | | | |
| Lozoya, Manny | Mrs. Arrey in the front office needs classroom key room #201 made for new employee. (J38) | | | | | | | | |
| <u>Elizabeth Hernandez</u> | | | | | | | | | |
| 95920 | | | | | 11/29/2012 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | 11/29/2012 8:18:57 AM | | | | | |
| Lozoya, Manny | Need to secure electrical boxes to outdoor portables. | | | | | | | | |
| <u>Johnny Acuna</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------|---|----------------------------------|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert Trail Intermediate | | | | | | | |
| 96376 | | | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 12/7/2012 2:49:15 PM | | | | |
| Lozoya, Manny | Need key made for storage cabinet to Room #394. | | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 96456 | | | | | 12/10/2012 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | | 12/10/2012 3:48:01 PM | | | | |
| Lozoya, Manny | Need to check front doors. Having trouble locking and unlocking. | | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 96990 | | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 1/8/2013 8:19:24 AM | | | | |
| Ontiveros, Guadalupe | Need Top Soil to fill in holes in playground grass area. (Safety Issue) | | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 97213 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | | 1/13/2013 12:16:07 AM | | | | |
| Sandoval, Laura | Monthly - QRTLY BLDG INSP REPORTS (DT) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96811 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:23:58 AM | | | | |
| Acuna, Johnny | Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 94274 | | | | | 10/17/2012 | | 89 | | \$0.00 |
| Medium | Work In Progress | | | | 10/17/2012 3:41:51 PM | | | | |
| Ontiveros, Guadalupe | Coaches requesting to move baseball backstop to another location in same playground area. It is in the way. (Currently Located inside of the soccer playing area) | | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 91106 | | | | | 8/10/2012 | | 157 | | \$0.00 |
| Medium | Work In Progress | | | | 8/10/2012 9:09:37 AM | | | | |
| Sotelo, Enrique | Please fix parking lot security lighting to some poles. | | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 94157 | | | | | 10/15/2012 | | 91 | | \$0.00 |
| Medium | Work In Progress | | | | 10/15/2012 1:08:59 PM | | | | |
| Acuna, Johnny | Need paint for restroom stalls: (Frozen wave: DE5829 oil based 5-Gal.) and (Graham Cracker: DE6144 Oil Based 5-Gal.) | | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 1/14/2013 11:04:42 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|---|----------------------------------|-------------------------|-----------|--|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert Trail Intermediate | | | | | | | |
| 94098 | | | | | 10/12/2012 | | 94 | | \$0.00 |
| Medium | Work In Progress | | | | 10/12/2012 10:11:07 | | | | |
| Ontiveros, Joe | Need to replace all student restroom wash basins (Sinks) (Qty. 6) | | | | | | | | |
| Johnny Acuna | | | | | | | | | |
| 96756 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:23:34 AM | | | | |
| Villalobos, David | Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 31 Work Orders | | | Avg. Age of WO's | 38 | Total for Desert Trail Intermediate | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------------|---|------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Desert View ES | | | | | | | | | |
| 96178 | | | | | 12/3/2012 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/3/2012 1:04:30 PM | | | | | |
| Villalobos, David | Students have been constantly clogging the urinals, need to clear flush to prevent clogging. Thank you, Ruben | | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 95909 | | | | | 11/28/2012 | | 47 | | \$0.00 |
| Medium | Work In Progress | | | 11/28/2012 3:58:06 PM | | | | | |
| Villalobos, David | The lower level boy's bathroom the wall urinal is leaking between the urinal and wall. Need it fixed. | | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 96762 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:37 AM | | | | | |
| Villalobos, David | Yearly - Desert View ES Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96939 | | Restroom (Girls) | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | Lower Grade | | 1/7/2013 2:12:25 PM | | | | | |
| Villalobos, David | Broken toilet needs replacement. (Gonzalez) | | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |
| 96572 | | Office | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | Office | | 12/13/2012 8:21:53 AM | | | | | |
| Villalobos, David | There is a strong odor in the office due to the sewer drainage. If we can have it checked out as soon as possible. (Gonzalez) | | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |
| 97162 | | | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2013 2:58:13 PM | | | | | |
| Villalobos, David | Lower level boy's bathroom p trap is broken; need it fixed ASAP | | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 97163 | | | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2013 2:59:54 PM | | | | | |
| Villalobos, David | Lower level girl's bathroom toilet is broken; need it fixed ASAP | | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 96317 | | Classroom | | | 12/6/2012 | | 39 | | \$0.00 |
| Medium | Work In Progress | Portable #8 | | 12/6/2012 11:51:11 AM | | | | | |
| Villalobos, David | Install sink in the classroom. (Gonzalez) | | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------|---|-----------------------|------------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert View ES | | | | | | | |
| 94995 | | | | | 11/2/2012 | | 73 | | \$0.00 |
| Medium | Work In Progress | | | | 11/2/2012 3:52:29 PM | | | | |
| Villalobos, David | Need broken sink replaced in the upper level girl's bathroom | | Thank you, Ruben | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 96235 | | | | | 12/4/2012 | | 41 | | \$0.00 |
| Medium | Work In Progress | | | | 12/4/2012 2:26:39 PM | | | | |
| Lara, Ralph | SCREEN DOOR IN KITCHEN AREA IS BROKEN, NEEDS TO BE LOOKED AT AND FIXED. SNP MANAGER DIANA L. 589.2425 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 95514 | | Classroom | | | 11/14/2012 | | 61 | | \$0.00 |
| Medium | Work In Progress | Rm. 24 | | | 11/14/2012 1:11:25 PM | | | | |
| Lara, Ralph | Install locks in the classroom for the safety of the students.(Ms. Garcia) | | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |
| 96882 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:24:34 AM | | | | |
| Ortiz, Ruben | Monthly - Desert View ES Roof Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 95917 | | Gym | | | 11/29/2012 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | | 11/29/2012 8:04:06 AM | | | | |
| Ortega, Israel | Set up the stage in the gym for the Spelling Bee. (Gonzalez) | | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |
| 97202 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | | 1/13/2013 12:16:01 AM | | | | |
| Ortega, Israel | Monthly - QRTLY BLDG INSP REPORT (DV) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96881 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:24:34 AM | | | | |
| Ortiz, Ruben | Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96879 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:24:33 AM | | | | |
| Ortiz, Ruben | Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 1/14/2013 11:04:42 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|-----------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert View ES | | | | | | | |
| 96880 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:33 AM | | | | | |
| Ortiz, Ruben | Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96982 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 4:57:10 PM | | | | | |
| Ortiz, Ruben | Received a/c cover and base covers; need to install them. | | | | | | | | |
| <u>Ruben Ortiz</u> | | | | | | | | | |
| 96179 | | | | | 12/3/2012 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/3/2012 1:05:26 PM | | | | | |
| Ortiz, Ruben | Need to change light blubs in the hallway. Thank you, Ruben | | | | | | | | |
| <u>Ruben Ortiz</u> | | | | | | | | | |
| 92736 | | | | | 9/12/2012 | | 124 | | \$0.00 |
| Medium | Work In Progress | | | 9/12/2012 10:18:19 AM | | | | | |
| Ortiz, Ruben | Pick up Donation. (R. Ortiz) | | | | | | | | |
| <u>Guadalupe Gonzalez</u> | | | | | | | | | |
| 96536 | | Office | | | 12/12/2012 | | 33 | | \$0.00 |
| Medium | Work In Progress | Principal's Office | | 12/12/2012 11:40:29 | | | | | |
| Ortiz, Ruben | Replace light bulbs in the Principal's office. (Gonzalez) | | | | | | | | |
| <u>Guadalupe Gonzalez</u> | | | | | | | | | |
| 96537 | | Office | | | 12/12/2012 | | 33 | | \$0.00 |
| Medium | Work In Progress | Asst. Principal | | 12/12/2012 11:41:35 | | | | | |
| Ortiz, Ruben | Sink in the Asst. Principal's Office is not working. (Gonzalez) | | | | | | | | |
| <u>Guadalupe Gonzalez</u> | | | | | | | | | |
| 96588 | | Restroom (Boys) | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | Upper Grade | | 12/13/2012 1:05:29 PM | | | | | |
| Ortiz, Ruben | Replace light bulbs in the upper grade boys bathroom. (Gonzalez) | | | | | | | | |
| <u>Guadalupe Gonzalez</u> | | | | | | | | | |
| 96921 | | Restroom (Boys) | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 10:29:22 AM | | | | | |
| Ortiz, Ruben | The paper towel dispenser in the Lower Grade Boy's Bathroom is broken. | | | | | | | | |
| <u>Guadalupe Gonzalez</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------|--|-----------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert View ES | | | | | | | |
| 96940 | | Restroom (Boys) | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | Lower Grade | | 1/7/2013 2:13:53 PM | | | | | |
| Ortiz, Ruben | Sink fixtures need replacement. (Gonzalez) | | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |
| 96941 | | Restroom (Boys) | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | Lower Grade | | 1/7/2013 2:16:15 PM | | | | | |
| Ortiz, Ruben | Toilet seat doesn't fit. (Gonzalez) | | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |
| 92512 | | Classroom | | | 9/7/2012 | | 129 | | \$0.00 |
| Medium | Work In Progress | Classroom | | 9/7/2012 9:05:01 AM | | | | | |
| Ortiz, Ruben | Install Marker Boards in the classrooms. (Gonzalez) | | | | | | | | |
| Guadalupe Gonzalez | | | | | | | | | |
| 97110 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 11:50:02 AM | | | | | |
| Ortiz, Ruben | Asp walk-thru on 1/7/13 East Electrical Room is being used as storage blocking panels - code violation. | | | | | | | | |
| Carlos Castillo | | | | | | | | | |
| 96919 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 9:42:09 AM | | | | | |
| Orozco, Daniel | REACH IN FREEZER AT 30 DEGREES.SNP MANAGER DIANA L 589.2425. | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 90992 | | | | | 8/8/2012 | | 159 | | \$0.00 |
| Medium | Work In Progress | | | 8/8/2012 10:33:59 AM | | | | | |
| Gonzalez, Salvador | Need a 2 by 6 dragger out of iron angle. Thank you, Ruben | | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 97226 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:13 AM | | | | | |
| Ortiz, Ruben | Monthly - Desert View ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96914 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 9:05:43 AM | | | | | |
| Ronquillo, Ruben | 01/07/13 Vandalism Back entrance door windows on the south side of school broken; room 25 door has broken window; (2) 14x60 inches | | | | | | | | |
| Ruben Ortiz | | | | | | | | | |
| 1/14/2013 11:04:42 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|--|----------------------------|----------------------|---------------------------------|-------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Desert View ES | | | | | | | |
| 96883 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | 1/6/2013 12:24:35 AM | | | | | | |
| Ortiz, Ruben | Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 33 Work Orders | | Avg. Age of WO's 32 | | Total for Desert View ES | | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|-------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 93688 | | | | | 9/30/2012 | 10/21/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:53 AM | | | | | |
| Orozco, Daniel | Monthly - GAC Range Hood Cleaning - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96827 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:06 AM | | | | | |
| Moncayo, Fernando | Monthly - GAC Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96515 | | Classroom | | | 12/11/2012 | | 34 | | \$0.00 |
| Medium | Work In Progress | GAC - WENDY | | 12/11/2012 4:16:20 PM | | | | | |
| Briones, Enrique | PLEASE DELIVER 1 BOX OF LLI (RED SYSTEM) TO GAC - WENDY TAYLOR ON THURSDAY, JANUARY 10TH, 2013. THANK YOU!!! | | | | | | | | |
| <u>Karla Quesada</u> | | | | | | | | | |
| 96788 | | | | | 1/6/2013 | 1/27/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:47 AM | | | | | |
| Orozco, Daniel | Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 91474 | | | | | 8/17/2012 | | 150 | | \$0.00 |
| Medium | Work In Progress | | | 8/17/2012 9:09:56 AM | | | | | |
| Estrada, Jesus | Technology Office - need to have carpet removed in Calixto and Cora office. | | | | | | | | |
| <u>Cora Ramirez</u> | | | | | | | | | |
| 96721 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:15 AM | | | | | |
| Holguin, Alfredo | Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 94698 | | | | | 10/29/2012 | | 77 | | \$0.00 |
| Medium | Work In Progress | | | 10/29/2012 9:26:05 AM | | | | | |
| Rodriguez, Arturo | TOILET IN RR IN FRONT OF RECEPTIONIST AREA WILL NOT FLUSH. | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 96412 | | | | | 12/9/2012 | 12/25/2012 | 36 | | \$0.00 |
| Medium | Work In Progress | | | 12/9/2012 12:16:26 AM | | | | | |
| Ambriz, Juan | Monthly - GAC Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|-------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 97211 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:06 AM | | | | | |
| Ambriz, Juan | Monthly - GAC Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97056 | | | | | 1/9/2013 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | 1/9/2013 12:22:26 PM | | | | | |
| Flores, Pete | MR. BAKERS VEHICLE NEEDS FLUIDS CHECKED. HE WILL BE OUT FRIDAY JANUARY 11, 2012. | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 93982 | | | | | 10/10/2012 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2012 8:40:49 AM | | | | | |
| Flores, Pete | Frank's Balderrama suburban stopped on Mercantile Road. | | | | | | | | |
| <u>Cora Ramirez</u> | | | | | | | | | |
| 93983 | | | | | 10/10/2012 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2012 8:44:59 AM | | | | | |
| Flores, Pete | David Hinojosa's van is not starting. Will drop off tomorrow morning to have it checked out. | | | | | | | | |
| <u>Cora Ramirez</u> | | | | | | | | | |
| 96829 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:07 AM | | | | | |
| Moncayo, Fernando | Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96830 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:07 AM | | | | | |
| Moncayo, Fernando | Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97100 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 8:41:28 AM | | | | | |
| Moncayo, Fernando | Need to hang 22 teachers of the year under the sign in the board room. | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 95108 | | | | | 11/4/2012 | 11/12/2012 | 71 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2012 12:19:45 AM | | | | | |
| Ambriz, Juan | Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------|--|---------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 92964 | | | | | 9/18/2012 | | 118 | | \$0.00 |
| Medium | Work In Progress | Lucia Almeraz | | 9/18/2012 3:45:13 PM | | | | | |
| Ambriz, Juan | ATTN: JUAN AMBRIZ PLEASE INSTALL A REGISTER IN OFFICE | | | | | | | | |
| Lucia Almeraz | | | | | | | | | |
| 95572 | | | | | 11/15/2012 | | 60 | | \$0.00 |
| Scheduled | Work In Progress | | | 11/15/2012 10:40:26 | | | | | |
| Ambriz, Juan | Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You | | | | | | | | |
| 97192 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:15:56 AM | | | | | |
| Rodriguez, Arturo | Monthly - QRTLY BLDG INSP REPORT (GAC) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 90287 | | | | | 7/27/2012 | | 171 | | \$0.00 |
| Medium | Work In Progress | | | 7/27/2012 10:41:27 AM | | | | | |
| Ambriz, Jose | check the vent on the right hand side of office. It is loud and the vent needs to be changed because a lot of air comes out of it. | | | | | | | | |
| | IS Department _ Sally Flores | | | | | | | | |
| Cora Ramirez | | | | | | | | | |
| 97228 | | | | | 1/14/2013 | | 0 | | \$0.00 |
| Medium | Work In Progress | | | 1/14/2013 12:18:44 AM | | | | | |
| Ambriz, Jose | Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96623 | | | | | 12/14/2012 | | 31 | | \$0.00 |
| Medium | Work In Progress | | | 12/14/2012 12:16:36 | | | | | |
| Ambriz, Jose | Monthly - GAC - Monthly Inspection by ACSEES - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 95653 | | | | | 11/19/2012 | | 56 | | \$0.00 |
| High | Work In Progress | | | 11/19/2012 7:30:10 AM | | | | | |
| Ambriz, Jose | need to rewire liebert cooling system in tech room to have only 2 compressors functioning, install 4 contactors, new switches, intelligent board, programming etc. this system is oversized for room and is causing problems as designed. | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 1/14/2013 11:04:42 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|---|-------------|-------------------------|-----------------------|------------------|----------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | GAC | | | | | | | |
| 95358 | | | | | 11/9/2012 | | 66 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2012 9:36:29 AM | | | | | |
| Ambriz, Jose | AS PER MR. Y. WALL UNIT IS NOT WORKING PROPERLY MAY NEED TO BE REPLACED. | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 93781 | | | | | 10/3/2012 | | 103 | | \$0.00 |
| Medium | Work In Progress | | | 10/3/2012 8:34:00 AM | | | | | |
| Lara, Ralph | AS PER MR. YTURREALDE, DOUBLED DOORS ENTERING HUMAN RESOURCES NEED LOCK/NUMBER LOCK INSTALLED FOR SECURITY PURPOSES. PLEASE SEE ARTURO. | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 96832 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:08 AM | | | | | |
| Moncayo, Fernando | Monthly - GAC Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 92932 | | | | | 9/18/2012 | | 118 | | \$0.00 |
| Medium | Work In Progress | | | 9/18/2012 12:44:19 PM | | | | | |
| Villalobos, David | MAIN WATER LINE LEAKING IN C-WING. | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 96763 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:37 AM | | | | | |
| Villalobos, David | Yearly - GAC Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96987 | | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 8:12:56 AM | | | | | |
| Ambriz, Jose | Server Room - Unit is down | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 96315 | | | | | 12/6/2012 | | 39 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2012 10:37:09 AM | | | | | |
| Castillo, Carlos | C-WING, NEED POWER TO CLOSET IN KARLA QUESADAS OFFICE. | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| Count: 30 Work Orders | | | Avg. Age of WO's | 50 | | Total for GAC | 0 | | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|---|----------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden ES | | | | | | | | | |
| 94633 | | | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | outside area | | 10/26/2012 10:31:19 | | | | | |
| Appelzoller, Fred | need immidiate assistance... outside where you hook up the water hoses... there seems to be alot of water drainage... water seems to be coming out even if the faucets are closed... please would greatly apprecite your assistance in this matter... | | | | | | | | |
| <u>Loraine Gandara</u> | | | | | | | | | |
| 97209 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:05 AM | | | | | |
| Pinon, Jose | Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95669 | | Athletic Field | | | 11/19/2012 | | 56 | | \$0.00 |
| Medium | Work In Progress | | | 11/19/2012 10:58:27 | | | | | |
| Ontiveros, Guadalupe | please remove wood mulch from playground area and replace with sand.thank you | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 95947 | | | | | 11/29/2012 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | 11/29/2012 2:23:14 PM | | | | | |
| Lozoya, Manny | Need 2 gate keys. Need to check the keys out to either Hector Torres or Hector Gutierrez For more information contact Ralph Gallegos at 882-6921. Thank You. | | | | | | | | |
| 97240 | | Classroom | | | 1/14/2013 | | 0 | | \$0.00 |
| Medium | Work In Progress | C WING WORK | | 1/14/2013 8:45:06 AM | | | | | |
| Solis, Lorenzo | AIR CONDITIONER NOT WORKING IN C WING WORK ROOM.... NEED ASSITANCE GREATLY APPRECIATE YOUR ASSITANCE IN THIS MATTER... THANK YOU.... | | | | | | | | |
| <u>Loraine Gandara</u> | | | | | | | | | |
| 96144 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:26 AM | | | | | |
| Arreola, Rudy | Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96145 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:26 AM | | | | | |
| Arreola, Rudy | Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|-------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden ES | | | | | | | |
| 96625 | | Cafeteria | | | 12/14/2012 | | 31 | | \$0.00 |
| Medium | Work In Progress | | | 12/14/2012 7:28:27 AM | | | | | |
| Arreola, Rudy | need a high ladder and assistance to take off the snowflakes from the cafeteria that are hanging on stage.... greatly appreciate your assistance | | | | | | | | |
| <u>Loraine Gandara</u> | | | | | | | | | |
| 97161 | | Football Field | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2013 2:08:22 PM | | | | | |
| Ronquillo, Ruben | please provide and install NO PETS ALLOWED for school campus..... greatly appreciate your assistance in this matter... thank you.... | | | | | | | | |
| <u>Loraine Gandara</u> | | | | | | | | | |
| 96872 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:29 AM | | | | | |
| Arreola, Rudy | Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96873 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:29 AM | | | | | |
| Arreola, Rudy | Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96870 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:27 AM | | | | | |
| Arreola, Rudy | Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96894 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| High | Work In Progress | | | 1/7/2013 7:48:53 AM | | | | | |
| Gonzalez, Salvador | please repair broken window. vandalism | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 97221 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:11 AM | | | | | |
| Arreola, Rudy | Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 91738 | | Football Field | | | 8/23/2012 | | 144 | | \$0.00 |
| Medium | Work In Progress | | | 8/23/2012 9:43:56 AM | | | | | |
| Arreola, Rudy | need assistance with the volleyball net... need to install them greatly appreciate your assistance.. | | | | | | | | |
| <u>Loraine Gandara</u> | | | | | | | | | |

1/14/2013 11:04:42 AM

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|--|----------------------------|-------------|-----------------------|-----------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden ES | | | | | | | |
| 96417 | | | | | 12/9/2012 | 12/25/2012 | 36 | | \$0.00 |
| Medium | Work In Progress | | | 12/9/2012 12:16:28 AM | | | | | |
| Arreola, Rudy | Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96683 | | Hallway/Corridor | | | 1/3/2013 | | 11 | | \$0.00 |
| Medium | Work In Progress | lincoln wing | | 1/3/2013 7:44:03 AM | | | | | |
| Ronquillo, Ruben | need assistance with glass door.....door was broken during holiday vacation.... Case Number 2013-00049 | | | | | | | | |
| <u>Loraine Gandara</u> | | | | | | | | | |
| 96143 | | | | | 12/2/2012 | 12/13/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:25 AM | | | | | |
| Arreola, Rudy | Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96871 | | | | | 1/6/2013 | 1/17/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:28 AM | | | | | |
| Arreola, Rudy | Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96778 | | | | | 1/6/2013 | 1/27/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:43 AM | | | | | |
| Orozco, Daniel | Monthly - Gadsden ES - Fire Sprinkler Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| Count: 20 Work Orders | | Avg. Age of WO's 29 | | | Total for Gadsden ES | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|--|-----------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 97159 | Old English Bldg | Restroom (Boys) | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2013 10:44:09 AM | | | | | |
| Appelzoller, Fred | the urinal at the boys restroom in the first floor of the Old Eng. is clogged, it over flows when flushed. | | | | | | | | |
| <u>Joe Munoz</u> | | | | | | | | | |
| 95625 | Old English Bldg | | | | 11/16/2012 | | 59 | | \$0.00 |
| High | Work In Progress | | | 11/16/2012 10:46:22 | | | | | |
| Lozoya, Manny | Need to replace door in Old English #141, door is hanging it is being hold by the door closer, secured door from falling down, but room needs to be secured.. | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 92340 | North Building | | | | 9/4/2012 | | 132 | | \$0.00 |
| Medium | Work In Progress | | | 9/4/2012 11:39:43 AM | | | | | |
| Appelzoller, Fred | Requested by Ms. Romero Rm. 223 North Building- Need to remove water and gas outlets, in additon to bench tables. Laser ingraver and mill need to be properly instaleld and the room is needed to properly install the equipment. | | | | | | | | |
| <u>Velia Alarcon</u> | | | | | | | | | |
| 96230 | Auto Shop | | | | 12/4/2012 | | 41 | | \$0.00 |
| Medium | Work In Progress | | | 12/4/2012 1:14:52 PM | | | | | |
| Appelzoller, Fred | Please install correct clean out fixture for the clean out located east of the electrical setup in the ponding area south of the Auto Shop. This is an existing clean out that the pond was designed around. For more details see Allan Journey or call Rafael Gallegos at 882-6921. Thanks. | | | | | | | | |
| <u>Rafael Gallegos</u> | | | | | | | | | |
| 94945 | Grounds Shop | | | | 11/2/2012 | | 73 | | \$0.00 |
| Medium | Work In Progress | | | 11/2/2012 10:15:23 AM | | | | | |
| Sanchez, Raul | We need a work order to have an ABS submersible effluent pump rebuilt by B&M Machinery. This pump is to be installed in the wwtp chlorine contact chamber located by the Grounds Shop | | | | | | | | |
| <u>Raul Sanchez</u> | | | | | | | | | |
| 97156 | New Admin Bldg | Office | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2013 8:24:42 AM | | | | | |
| Briones, Enrique | please deliver 4 boxes of Science Material & 2 boxes of Spanish espn level 1 | | | | | | | | |
| Larry Martinez | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|-------------|-------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|------------------|---|--------|--|---------------------|----------|--|---|--|--------|
| 97003 | New Admin Bldg | Office | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 9:22:56 AM | | | | | |
| Briones, Enrique | Please deliver 1 box of car kits for PO 121303339 | | | | | | | | |

Larry Martinez

| | | | | | | | | | |
|------------------|---|--------|--|----------------------|----------|--|---|--|--------|
| 97010 | New Admin Bldg | Office | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 10:30:32 AM | | | | | |
| Briones, Enrique | Please deliver 3 boxes of Math Adoption Samples | | | | | | | | |

Larry Martinez

| | | | | | | | | | |
|------------------|---|--------|--|----------------------|----------|--|---|--|--------|
| 97012 | New Admin Bldg | Office | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 10:34:19 AM | | | | | |
| Briones, Enrique | Please deliver 4 boxes of TI84 Calculators for PO 121303405 | | | | | | | | |

Larry Martinez

| | | | | | | | | | |
|------------------|--|--------|--|----------------------|----------|--|---|--|--------|
| 97014 | New Admin Bldg | Office | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 10:37:11 AM | | | | | |
| Briones, Enrique | Please deliver 1 Scakbak Sled for PO 121303447 | | | | | | | | |

Larry Martinez

| | | | | | | | | | |
|---------------|--|--|--|----------------------|----------|-----------|---|--|--------|
| 96820 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:02 AM | | | | | |
| Herrera, Joel | Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |

Margret Villalobos

| | | | | | | | | | |
|----------------------|---|-----------------|--|-----------------------|-----------|--|-----|--|--------|
| 91114 | | Athletic Field | | | 8/10/2012 | | 157 | | \$0.00 |
| Medium | Work In Progress | Softball Fields | | 8/10/2012 10:10:53 AM | | | | | |
| Ontiveros, Guadalupe | Requested by Coach L. Chavez for Softball Fields-fencing 6' perimeter and 3-2x6 door chain link fence | | | | | | | | |

Velia Alarcon

| | | | | | | | | | |
|----------------------|--|-----------------|--|-----------------------|-----------|--|-----|--|--------|
| 91115 | | Athletic Field | | | 8/10/2012 | | 157 | | \$0.00 |
| Medium | Work In Progress | Softball Fields | | 8/10/2012 10:12:25 AM | | | | | |
| Ontiveros, Guadalupe | Requested by Coach L. Chavez for Softball Fields-wood fasterner--raise fencing around bull pen | | | | | | | | |

Velia Alarcon

| | | | | | | | | | |
|----------------------|---|-----------------|--|-----------------------|-----------|--|-----|--|--------|
| 91116 | | Athletic Field | | | 8/10/2012 | | 157 | | \$0.00 |
| Medium | Work In Progress | Softball Fields | | 8/10/2012 10:14:38 AM | | | | | |
| Ontiveros, Guadalupe | Requested by Coach L. Chavez for Softball Fields-Perimeter fence needs to be pulled & anchored down w/hog ties. | | | | | | | | |

Velia Alarcon

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|-------------|-------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|----------------------|---|----------------|--|----------------------|-----------|--|----|--|--------|
| 96167 | | Athletic Field | | | 12/3/2012 | | 42 | | \$0.00 |
| High | Work In Progress | | | 12/3/2012 9:10:56 AM | | | | | |
| Ontiveros, Guadalupe | need to install chian linkfence on infield for offical games. As per coach. | | | | | | | | |

Guadalupe Ontiveros

| | | | | | | | | | |
|-----------------|---|--|--|-----------------------|------------|--|----|--|--------|
| 94778 | | | | | 10/30/2012 | | 76 | | \$0.00 |
| Medium | Work In Progress | | | 10/30/2012 1:39:44 PM | | | | | |
| Martinez, Larry | Please pick up Obsolete Technology items located in the Old Library | | | | | | | | |

Michelle Tellez

| | | | | | | | | | |
|----------------|---|--|--|----------------------|----------|--|---|--|--------|
| 96781 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:44 AM | | | | | |
| Orozco, Daniel | Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | | |

Margret Villalobos

| | | | | | | | | | |
|------------------|---|--|--|-----------------------|-----------|--|-----|--|--------|
| 93615 | | | | | 9/30/2012 | | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:21 AM | | | | | |
| Holguin, Alfredo | Monthly - Gadsden HS - Fire Pump PM (Quarterly) - Refer to PM schedule details. | | | | | | | | |

Margret Villalobos

| | | | | | | | | | |
|------------------|---|--|--|-----------------------|-----------|--|-----|--|--------|
| 93612 | | | | | 9/30/2012 | | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:20 AM | | | | | |
| Holguin, Alfredo | Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details. | | | | | | | | |

Margret Villalobos

| | | | | | | | | | |
|------------------|---|--|--|----------------------|----------|--|-----|--|--------|
| 89302 | | | | | 7/1/2012 | | 197 | | \$0.00 |
| Medium | Work In Progress | | | 7/1/2012 12:30:01 AM | | | | | |
| Holguin, Alfredo | Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details. | | | | | | | | |

Margret Villalobos

| | | | | | | | | | |
|-----------------|---|--|--|----------------------|-----------|--|-----|--|--------|
| 93092 | | | | | 9/20/2012 | | 116 | | \$0.00 |
| Medium | Work In Progress | | | 9/20/2012 3:51:26 PM | | | | | |
| Carrasco, Danny | BROKEN WINDOW ON ROOM #341 SINGLE GLASS ZISE 44 1/2 X 29 1/2 AT ACADEMIC BUILDING | | | | | | | | |

Joel Herrera

| | | | | | | | | | |
|------------------|---|--|--|----------------------|----------|--|---|--|--------|
| 96722 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:16 AM | | | | | |
| Holguin, Alfredo | Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details. | | | | | | | | |

Margret Villalobos

1/14/2013 11:04:42 AM

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------------|---|-------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Gadsden HS | | | | | | | | | |
| 96720 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:15 AM | | | | | |
| Holguin, Alfredo | Monthly - Gadsden HS - Fire Pump PM (Quarterly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96679 | | | | | 12/31/2012 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | 12/31/2012 12:27:08 | | | | | |
| Sanchez, Raul | Monthly - Gadsden HS - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96148 | | | | | 12/2/2012 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:27 AM | | | | | |
| Sanchez, Raul | Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 94821 | | | | | 10/31/2012 | | 75 | | \$0.00 |
| Medium | Work In Progress | | | 10/31/2012 12:26:40 | | | | | |
| Sanchez, Raul | Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95150 | | | | | 11/4/2012 | | 71 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2012 12:20:01 AM | | | | | |
| Sanchez, Raul | Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96875 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:30 AM | | | | | |
| Sanchez, Raul | Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96877 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:32 AM | | | | | |
| Sanchez, Raul | Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93175 | | | | | 9/24/2012 | | 112 | | \$0.00 |
| Medium | Work In Progress | | | 9/24/2012 2:18:30 PM | | | | | |
| Gonzalez, Salvador | Requested by Coach Letz for Tennis Court-Please repair two of the benches on the Tennis Courts. | | | | | | | | |
| Velia Alarcon | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|--|-------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden HS | | | | | | | |
| 92842 | | | | | 9/14/2012 | | 122 | | \$0.00 |
| Medium | Work In Progress | | | 9/14/2012 8:10:27 AM | | | | | |
| Gonzalez, Salvador | need to weld brackets on the south gate, gate is shifting... | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 93070 | | | | | 9/20/2012 | | 116 | | \$0.00 |
| Medium | Work In Progress | | | 9/20/2012 12:14:27 PM | | | | | |
| Gonzalez, Salvador | Need to weld brackets on windows of classroom #106. Main building.... | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 96026 | | Athletic Field | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2012 3:39:43 PM | | | | | |
| Gonzalez, Salvador | please order material for new scoreboards. baseball softball.thank you | | | | | | | | |
| <u>Joe Munoz</u> | | | | | | | | | |
| 92784 | | | | | 9/13/2012 | | 123 | | \$0.00 |
| Medium | Work In Progress | | | 9/13/2012 9:07:47 AM | | | | | |
| Sanchez, Raul | Wastewater Treatment Plant - Solicit a minimum of (3) three qoutes for two (2) Submersible Pumps 208V/3PH . make sure freight if applicable and delivery time frame is included. | | | | | | | | |
| <u>Alfredo Holguin</u> | | | | | | | | | |
| 92301 | | | | | 9/2/2012 | | 134 | | \$0.00 |
| Medium | Work In Progress | | | 9/2/2012 12:21:58 AM | | | | | |
| Sanchez, Raul | Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93642 | | | | | 9/30/2012 | | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:33 AM | | | | | |
| Sanchez, Raul | Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 94760 | | | | | 10/30/2012 | | 76 | | \$0.00 |
| Medium | Work In Progress | | | 10/30/2012 11:12:07 | | | | | |
| Orozco, Daniel | WASHING MACHINE WENT DEAD, NOT WORKING. SNP MANAGER LYDIA M. 882.5522 | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 96818 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:01 AM | | | | | |
| Herrera, Joel | Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 1/14/2013 11:04:42 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|-------------|-------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden HS

| | | | | | | | | | |
|----------------------------|--|--|--|-----------------------|------------|-----------|-----|--|--------|
| 96816 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:00 AM | | | | | |
| Herrera, Joel | Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 90166 | | | | | 7/25/2012 | | 173 | | \$0.00 |
| Medium | Work In Progress | | | 7/25/2012 9:33:19 AM | | | | | |
| Estrada, Jesus | Requested by Mr. Pokluda for Rm. 300 in Academic Building-Replace or repair broken floor tiles at entry to classroom. | | | | | | | | |
| <u>Velia Alarcon</u> | | | | | | | | | |
| 94870 | | | | | 10/31/2012 | | 75 | | \$0.00 |
| Medium | Work In Progress | | | 10/31/2012 3:53:14 PM | | | | | |
| Herrera, Joel | 10-31-12 3.0 CHECK HEATER AND REPLCE THERMOCOUPLE AT BAND ROOM 2.0 WORK ORDER # 91952 3.0 CLEANUP GRAFFITIS AT BOYS REST ROOMS AT THE NEW BUILDING | | | | 10/31-6 | | | | |
| <u>Joel Herrera</u> | | | | | | | | | |
| 96819 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:02 AM | | | | | |
| Herrera, Joel | Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95620 | | | | | 11/16/2012 | | 59 | | \$0.00 |
| Medium | Work In Progress | | | 11/16/2012 9:05:57 AM | | | | | |
| Hernandez, Guillermo | Requested by Coach Lawrence Rm. 341 Academic Building-Need two sets of blinds for window. | | | | | | | | |
| <u>Velia Alarcon</u> | | | | | | | | | |
| 90589 | | | | | 8/2/2012 | | 165 | | \$0.00 |
| Medium | Work In Progress | | | 8/2/2012 11:06:39 AM | | | | | |
| Hernandez, Guillermo | Would you please install blinds to windows in classrooms #105 and #106. Thank you | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 96805 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:55 AM | | | | | |
| Hernandez, Guillermo | Monthly - Gadsden HS - Elevator (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|---|-------------------|--|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden HS | | | | | | | |
| 96803 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:54 AM | | | | | |
| Hernandez, Guillermo | Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 94375 | | | | | 10/19/2012 | | 87 | | \$0.00 |
| Medium | Work In Progress | | | 10/19/2012 2:47:40 PM | | | | | |
| Lara, Ralph | Requested by Velia-Three HG7 are needed for the Old Library. | | | | | | | | |
| <u>Velia Alarcon</u> | | | | | | | | | |
| 95618 | | | | | 11/16/2012 | | 59 | | \$0.00 |
| Medium | Work In Progress | | | 11/16/2012 9:02:24 AM | | | | | |
| Lara, Ralph | Requested by Coach Lawrence Rm 341 Academic Building-Lock on door does not lock. Please repair as soon as possible, since Coach Lawrence has his Sp. Ed. lab top out and is afraid it might get stolen. | | 11/26 - Need status on work order asp email. | | | | | | |
| <u>Velia Alarcon</u> | | | | | | | | | |
| 94185 | | | | | 10/15/2012 | | 91 | | \$0.00 |
| Medium | Work In Progress | | | 10/15/2012 3:54:24 PM | | | | | |
| Ambriz, Jose | Need to replace 6 A/C commercial units for the cafeteria.... | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 95309 | | | | | 11/8/2012 | | 67 | | \$0.00 |
| Medium | Work In Progress | | | 11/8/2012 7:37:54 AM | | | | | |
| Ambriz, Jose | Need to replace T-stat and check leaks on gaskets on boiler for heating system on the Old English... | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 96339 | | | | | 12/6/2012 | | 39 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2012 3:48:09 PM | | | | | |
| Ambriz, Jose | Need to replace gasket to pump in the boiler room for the Old English.... | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 97135 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 3:37:55 PM | | | | | |
| Ambriz, Jose | Need to replace fan motor to furnace in the wrestling room. | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 94829 | | | | | 10/31/2012 | | 75 | | \$0.00 |
| Medium | Work In Progress | | | 10/31/2012 9:33:08 AM | | | | | |
| Ambriz, Jose | HEATER UNIT IN BAND ROOM IT DOESNT WORKING AT ANNEX BUILDING | | | | | | | | |
| <u>Joel Herrera</u> | | | | | | | | | |
| 1/14/2013 11:04:42 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|--|-------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden HS | | | | | | | |
| 93992 | | | | | 10/10/2012 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2012 11:27:53 | | | | | |
| Ambriz, Jose | Need assistance to remove old furnace from the Boys Gym... | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 94019 | | | | | 10/10/2012 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2012 3:43:56 PM | | | | | |
| Ambriz, Jose | Need to replace broken contactor to A/C #6. cafeteria roof. | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 96684 | | | | | 1/3/2013 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | 1/3/2013 7:57:11 AM | | | | | |
| Ambriz, Jose | Need assistance troubleshooting H/C unit for rooms #234 & #232, RTU-15-68 unit.. | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 96692 | | | | | 1/3/2013 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | 1/3/2013 11:06:48 AM | | | | | |
| Ambriz, Jose | Need assistance troubleshooting heater in Business building #651... | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 96693 | | | | | 1/3/2013 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | 1/3/2013 11:08:13 AM | | | | | |
| Ambriz, Jose | Need to replace ignition control to furnace in the girls locker room at Boys Gym.. | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 96804 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:54 AM | | | | | |
| Hernandez, Guillermo | Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97207 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:04 AM | | | | | |
| Munoz, Joe | Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96021 | | Athletic Field | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2012 3:36:57 PM | | | | | |
| Ontiveros, Guadalupe | please reomve existing scoreboards to baseball / softball for new scoreboards. thank you | | | | | | | | |
| Michael Munoz | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|--|-------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden HS | | | | | | | |
| 91588 | | | | | 8/20/2012 | | 147 | | \$0.00 |
| Medium | Work In Progress | | | 8/20/2012 3:50:03 PM | | | | | |
| Ontiveros, Guadalupe | Requested by L. Chavez for Softball Field-Relocate tee's to the area where previous batting cage was located. SEE DIAGRAM | | | | | | | | |
| <u>Velia Alarcon</u> | | | | | | | | | |
| 91590 | | | | | 8/20/2012 | | 147 | | \$0.00 |
| Medium | Work In Progress | | | 8/20/2012 3:52:01 PM | | | | | |
| Ontiveros, Guadalupe | Requested by Ms. L. Chavez for Softball Field-Batting cage needs to be moved next to other batting cage behind scoreboard. SEE DIAGRAM | | | | | | | | |
| <u>Velia Alarcon</u> | | | | | | | | | |
| 91453 | | | | | 8/16/2012 | | 151 | | \$0.00 |
| Medium | Work In Progress | | | 8/16/2012 4:19:55 PM | | | | | |
| Ontiveros, Guadalupe | Requested by Coach Yanez for Baseball Field-Set up brackets for a batting cage to be placed behind "visitors" dugout on mini-base infield. Dimensions asking for L 55' x H 12'. | | | | | | | | |
| <u>Velia Alarcon</u> | | | | | | | | | |
| 90847 | | | | | 8/6/2012 | | 161 | | \$0.00 |
| Medium | Work In Progress | | | 8/6/2012 1:22:50 PM | | | | | |
| Ontiveros, Guadalupe | Requested by Coach L. Chavez for Softball Field-Fill dirt in in-field, drag field. Need a 5 to 6 ft. warning track to be outlined in outfield next to fence. SEE COACH L. CHAVEZ FOR FURTHER INSTRUCTIONS. | | | | | | | | |
| <u>Velia Alarcon</u> | | | | | | | | | |
| 93980 | | | | | 10/10/2012 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2012 8:31:32 AM | | | | | |
| Lara, Ralph | Need to replace cores in two storage's room for maintenance to have access for plumbing... (Academic and Annex building) | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 96599 | | | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | 12/13/2012 2:58:12 PM | | | | | |
| Lara, Ralph | Need to replace broken keys. for Maintenance 6 and 7 pin.. | | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 96994 | | Athletic Field | | | 1/8/2013 | | 6 | | \$0.00 |
| High | Work In Progress | | | 1/8/2013 8:28:17 AM | | | | | |
| Holguin, Ramiro | need 4" metal compression two. main water line leak | | | | | | | | |
| Guadalupe Ontiveros | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden HS | | | | | | | |
| 94661 | | Athletic Field | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/26/2012 3:01:38 PM | | | | | |
| Holguin, Ramiro | | sprinklers at softball and baseball need to be replace to be able for over seeding. | | | | | | | |
| <u>Guadalupe Ontiveros</u> | | | | | | | | | |
| 91592 | | | | | 8/20/2012 | | 147 | | \$0.00 |
| Medium | Work In Progress | | | 8/20/2012 3:55:01 PM | | | | | |
| Gonzalez, Salvador | | Requested by Coach L. Chavez for Softball Field- Replace roofs on both dugouts. | | | | | | | |
| <u>Velia Alarcon</u> | | | | | | | | | |
| 92328 | | | | | 9/4/2012 | | 132 | | \$0.00 |
| Medium | Work In Progress | | | 9/4/2012 10:17:12 AM | | | | | |
| Appelzoller, Fred | | Requested by Ms. Lerma Rm. 105 Main Building-One of the ovens needs callobrating. SEE MS. LERMA FOR LOCATION OF OVEN. | | | | | | | |
| <u>Velia Alarcon</u> | | | | | | | | | |
| 92272 | | | | | 9/2/2012 | | 134 | | \$0.00 |
| Medium | Work In Progress | | | 9/2/2012 12:21:46 AM | | | | | |
| Munoz, Michael | | Monthly - Gadsden HS - Grease Trap (Culinary/Auto) - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 92752 | | Pump House | | | 9/12/2012 | | 124 | | \$0.00 |
| Medium | Work In Progress | | | 9/12/2012 3:26:17 PM | | | | | |
| Appelzoller, Fred | | the new domessitic water filter housing has beed order need to order fitting and parts for installation | | | | | | | |
| <u>Mario Apodaca</u> | | | | | | | | | |
| 96764 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:37 AM | | | | | |
| Villalobos, David | | Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 94618 | | | | | 10/25/2012 | | 81 | | \$0.00 |
| Medium | Work In Progress | | | 10/25/2012 3:54:40 PM | | | | | |
| Castillo, Carlos | | Need to replace ballast around the restrooms by the concession stand.. | | | | | | | |
| <u>Guillermo Hernandez</u> | | | | | | | | | |
| 94830 | | | | | 10/31/2012 | | 75 | | \$0.00 |
| Medium | Work In Progress | | | 10/31/2012 10:03:50 | | | | | |
| Castillo, Carlos | | Requested by Mrs. Munoz Rm. 208 (Store Room) North Building-Need an electrical outlet on the west wall of store room. | | | | | | | |
| <u>Velia Alarcon</u> | | | | | | | | | |
| 1/14/2013 11:04:42 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------|---|-------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden HS | | | | | | | |
| 95924 | | | | | 11/29/2012 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | 11/29/2012 8:56:03 AM | | | | | |
| Castillo, Carlos | ELECTRICAL PROBLEM IN CAFETERIA, NEED YOUR ASSISTANCE | | | | | | | | |
| Joel Herrera | | | | | | | | | |
| 96598 | | | | | 12/13/2012 | | 32 | | \$0.00 |
| High | Work In Progress | | | 12/13/2012 2:56:47 PM | | | | | |
| Castillo, Carlos | Please check east side bleachers motor in the V. Gym, bleachers stock open. Need to be closed for practices... | | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 96358 | | | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | 12/7/2012 8:42:48 AM | | | | | |
| Castillo, Carlos | Please remove all electric wiring for the Science tables in classroom #223, North building. Tables to be removed.... | | | | | | | | |
| Guillermo Hernandez | | | | | | | | | |
| 91596 | | | | | 8/20/2012 | | 147 | | \$0.00 |
| Medium | Work In Progress | | | 8/20/2012 3:59:41 PM | | | | | |
| Castillo, Carlos | Requested by Coach L. Chavez for Softball Field-Run electrical outlet to batting cage that will be moved behind scoreboard. SEE DIAGRAM | | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 91113 | | Athletic Field | | | 8/10/2012 | | 157 | | \$0.00 |
| Medium | Work In Progress | Softball Fields | | 8/10/2012 10:08:48 AM | | | | | |
| Castillo, Carlos | Requested by Coach L. Chavez for Softball Fields-electrical boxes/in storage/dugout on both sides and Electrical box installed at score board | | | | | | | | |
| Velia Alarcon | | | | | | | | | |
| 96525 | | Athletic Field | | | 12/12/2012 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | 12/12/2012 8:10:53 AM | | | | | |
| Castillo, Carlos | GHS-Boys' baseball scoreboard electrical service needs to be upgraded to support new scoreboard. | | | | | | | | |
| Carlos Castillo | | | | | | | | | |
| 96526 | | Athletic Field | | | 12/12/2012 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | 12/12/2012 8:15:30 AM | | | | | |
| Castillo, Carlos | GHS-softball field scoreboard electrical service needs to be upgraded to support new scoreboard. | | | | | | | | |
| Carlos Castillo | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs | |
|------------------------------|--|-------------------|-----------------------------|-----------------------|------------------|------------------|-----------|---------------|-------------|--|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | | |
| Assigned To | Description | | | | | | | | | |
| Requester Name | | | | | | | | | | |
| Location: | | Gadsden HS | | | | | | | | |
| 96543 | | Athletic Field | | | 12/12/2012 | | 33 | | \$0.00 | |
| Medium | Work In Progress | | | 12/12/2012 2:12:30 PM | | | | | | |
| Castillo, Carlos | electrical for new scoreboards needs to be up-graded. thank you | | | | | | | | | |
| Michael Munoz | | | | | | | | | | |
| 96524 | | | | | 12/12/2012 | | 33 | | \$0.00 | |
| Medium | Work In Progress | | | 12/12/2012 7:57:38 AM | | | | | | |
| Sotelo, Enrique | Please check score board, having problems with the lights... | | | | | | | | | |
| Guillermo Hernandez | | | | | | | | | | |
| 96545 | | | | | 12/12/2012 | | 33 | | \$0.00 | |
| High | Work In Progress | | | 12/12/2012 3:03:54 PM | | | | | | |
| Sotelo, Enrique | Need locates. Please do electrical on the south west corner of property from new light poles on south side of lift station. South of current fence 5' span of current fence. For information see Allan Journey (575-644-0810) or call Ralph Gallegos 882-6921. Thank You | | | | | | | | | |
| 96817 | | | | | 1/6/2013 | 1/9/2013 | 8 | | \$0.00 | |
| Medium | Work In Progress | | | 1/6/2013 12:24:01 AM | | | | | | |
| Herrera, Joel | Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details. | | | | | | | | | |
| Margret Villalobos | | | | | | | | | | |
| 95667 | | | | | 11/19/2012 | | 56 | | \$0.00 | |
| High | Work In Progress | | | 11/19/2012 10:06:13 | | | | | | |
| Hernandez, Guillermo | please paint all ADA logos, ramps and curbs etc to meet code requirements.thankyou | | | | | | | | | |
| Joe Munoz | | | | | | | | | | |
| Count: 88 Work Orders | Avg. Age of WO's 67 | | Total for Gadsden HS | | | | 0 | \$0.00 | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|--|-------------------|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden MS | | | | | | | |
| 96202 | | | | | 12/3/2012 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | | 12/3/2012 3:49:00 PM | | | | |
| Solis, Lorenzo | Need to fix heater in room 109 thank you | | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 95435 | | | | | 11/13/2012 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | | 11/13/2012 7:23:47 AM | | | | |
| Solis, Lorenzo | Need to check heater in kitchen thank you | | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 96957 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 1/7/2013 3:24:27 PM | | | | |
| Solis, Lorenzo | Need to fix heater in room 162 thank you | | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 93734 | | | | | 10/1/2012 | | 105 | | \$0.00 |
| Medium | Work In Progress | | | | 10/1/2012 3:42:45 PM | | | | |
| Solis, Lorenzo | Need to check boiler pump in westside thank you | | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 93735 | | | | | 10/1/2012 | | 105 | | \$0.00 |
| Medium | Work In Progress | | | | 10/1/2012 3:44:34 PM | | | | |
| Solis, Lorenzo | Need to check boiler in west side thank you | | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 95834 | | | | | 11/27/2012 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | | 11/27/2012 3:25:28 PM | | | | |
| Sotelo, Enrique | nNEED TO CHECK OUTSIDE LIGHTS THANK YOU | | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 96902 | | Football Field | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | | 1/7/2013 8:18:11 AM | | | | |
| Sotelo, Enrique | Enrique can you help disconnecting power on scoreboard please so we can work on it, thank you. | | | | | | | | |
| Salvador Gonzalez | | | | | | | | | |
| 96765 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:23:38 AM | | | | |
| Villalobos, David | Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96607 | | | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | | 12/13/2012 3:37:50 PM | | | | |
| Appelzoller, Fred | Need to unclog toilet in teacher rest on B wing thank you | | | | | | | | |
| Sebastian Diaz | | | | | | | | | |
| 1/14/2013 | 11:04:42 AM | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|--|-------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden MS | | | | | | | |
| 96886 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:36 AM | | | | | |
| Diaz, Sebastian | Monthly - Gadsden MS Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 94655 | | Athletic Field | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/26/2012 2:51:10 PM | | | | | |
| Vasquez, Jose | need to replace solenoids on electric valves. sprinklers are not working. | | | | | | | | |
| <u>Guadalupe Ontiveros</u> | | | | | | | | | |
| 95444 | | | | | 11/13/2012 | | 62 | | \$0.00 |
| High | Work In Progress | | | 11/13/2012 10:04:19 | | | | | |
| Vasquez, Jose | need hot box for R.P.A | | | | | | | | |
| <u>Guadalupe Ontiveros</u> | | | | | | | | | |
| 95451 | | | | | 11/13/2012 | | 62 | | \$0.00 |
| Medium | Work In Progress | | | 11/13/2012 11:21:58 | | | | | |
| Ontiveros, Guadalupe | Please move guard shed to the back of the school. Set it up on the 6X6 concrete slab. Please see Mr. Calleros for details. | | | | | | | | |
| <u>Nancy Tinajero</u> | | | | | | | | | |
| 96322 | | | | | 12/6/2012 | | 39 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2012 2:58:27 PM | | | | | |
| Lozoya, Manny | Need to fix cilinder in main door in B wing northside thank you | | | | | | | | |
| <u>Sebastian Diaz</u> | | | | | | | | | |
| 97112 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 12:04:03 PM | | | | | |
| Lozoya, Manny | Need to fix door knob in room 307 thank you | | | | | | | | |
| <u>Sebastian Diaz</u> | | | | | | | | | |
| 97113 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 12:05:32 PM | | | | | |
| Lozoya, Manny | Need to fix doors cilinder in room 603 thank you | | | | | | | | |
| <u>Sebastian Diaz</u> | | | | | | | | | |
| 97204 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:02 AM | | | | | |
| Acosta, Juan | Monthly - QRTLY BLDG INSP REPORT (GM) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

1/14/2013 11:04:42 AM

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|---|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden MS | | | | | | | |
| 96262 | | | | | 12/4/2012 | | 41 | | \$0.00 |
| Medium | Work In Progress | | | 12/4/2012 3:55:41 PM | | | | | |
| Ronquillo, Ruben | PAINT FOR GYM WALLS GRAFFITY | | | | | | | | |
| Ruben Ronquillo | | | | | | | | | |
| 95993 | | Classroom | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | A wing/ 160 | | 11/30/2012 9:49:59 AM | | | | | |
| Diaz, Sebastian | Please put up white boards. They are to replace the green boards. | | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 97009 | | Office | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | A wing Room | | 1/8/2013 10:11:15 AM | | | | | |
| Diaz, Sebastian | One fluorescent light is out | | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 97007 | | Classroom | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | A wing Room | | 1/8/2013 10:02:06 AM | | | | | |
| Diaz, Sebastian | Heater not working | | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 96171 | | Classroom | | | 12/3/2012 | | 42 | | \$0.00 |
| Medium | Work In Progress | A wing room 158 | | 12/3/2012 10:02:46 AM | | | | | |
| Diaz, Sebastian | Heater only warms for 5 mins. | | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 96172 | | Classroom | | | 12/3/2012 | | 42 | | \$0.00 |
| Medium | Work In Progress | A wing Room | | 12/3/2012 10:18:50 AM | | | | | |
| Diaz, Sebastian | Install bulletin board on the wall next to the door. West side of the room. | | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 96966 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 3:37:13 PM | | | | | |
| Gonzalez, Salvador | 1-7-13 | Need to repair scoreboard by football field. | | | | | | | |
| Salvador Gonzalez | | | | | | | | | |
| 96319 | | | | | 12/6/2012 | | 39 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2012 1:26:19 PM | | | | | |
| Apodaca, Mario | Need to order Control switches For domestic water Pumps and Pressure tanks | | | | | | | | |
| Mario Apodaca | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|-------------|-------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |

Location: Gadsden MS

| | | | | | | | | | | |
|--------------------|------------------|---|--|--|-----------------------|--|---|--|--------|--|
| 96844 | | | | | 1/6/2013 | | 8 | | \$0.00 | |
| Medium | Work In Progress | | | | 1/6/2013 12:24:14 AM | | | | | |
| Apodaca, Mario | | Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | | |
| 94815 | | | | | 10/31/2012 | | 75 | | \$0.00 | |
| Medium | Work In Progress | | | | 10/31/2012 12:26:38 | | | | | |
| Apodaca, Mario | | Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | | |
| 96847 | | | | | 1/6/2013 | | 8 | | \$0.00 | |
| Medium | Work In Progress | | | | 1/6/2013 12:24:16 AM | | | | | |
| Apodaca, Mario | | Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | | |
| 95623 | Cafeteria | Custodial | | | 11/16/2012 | | 59 | | \$0.00 | |
| Medium | Work In Progress | | | | 11/16/2012 10:32:52 | | | | | |
| Carbajal, Jimmy | | THE DRIVABLE BURNISHERS BATTERY CABLE IS MELTED PLEASE CHECK FOR A SHORTAGE | | | | | | | | |
| Juan Acosta | | | | | | | | | | |
| 95828 | C-Wing | | | | 11/27/2012 | | 48 | | \$0.00 | |
| Medium | Work In Progress | CHARTER | | | 11/27/2012 3:07:11 PM | | | | | |
| Appelzoller, Fred | | Boys Restroom - Toilet will not flush. Sebastian went to check on it and it needs a part that needs to be ordered by the Plumber. | | | | | 12/3- Maggie called for status, asp Fred he needs to order new tank will go by to get model number and will inform Maggie of staus. | | | |
| Margret Villalobos | | | | | | | | | | |
| 93405 | C-Wing | | | | 9/28/2012 | | 108 | | \$0.00 | |
| Medium | Work In Progress | | | | 9/28/2012 2:33:04 PM | | | | | |
| Castillo, Carlos | | Check Transformer by Support Services/Athletic Portable. | | | | | | | | |
| Michael Munoz | | | | | | | | | | |
| 95951 | Gym | | | | 11/29/2012 | | 46 | | \$0.00 | |
| Medium | Work In Progress | Gym Storage | | | 11/29/2012 3:23:49 PM | | | | | |
| Gonzalez, Salvador | | Please build new loft in storage room in gymnasium. See Mr. Calleros for more details. | | | | | | | | |
| Nancy Tinajero | | | | | | | | | | |
| 89884 | | | | | 7/17/2012 | | 181 | | \$0.00 | |
| Medium | Work In Progress | | | | 7/17/2012 7:12:12 AM | | | | | |
| Lozoya, Manny | | ALL CORES TO EXIT DOORS OUTSIDE NEEDS CLEANING | | | | | | | | |
| Juan Acosta | | | | | | | | | | |

1/14/2013 11:04:42 AM

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|--|-------------|-----------------------|-----------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Gadsden MS | | | | | | | |
| 94701 | | | | | 10/29/2012 | | 1 | | \$0.00 |
| Medium | Work In Progress | | | 10/29/2012 10:54:39 | | 10/30/2012 | | | |
| Martinez, Larry | | Please pick up obsolete technology items | | | | | | | |
| Michelle Tellez | | | | | | | | | |
| 94874 | Main Building | | | | 11/1/2012 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2012 7:48:39 AM | | | | | |
| Lozoya, Manny | | B.WING EXIT DOOR NEXT TO ROOM 113 CANNOT UNLOCK WHTH KEY | | | | | | | |
| Juan Acosta | | | | | | | | | |
| 97006 | Annex | Classroom | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | Annex Room | | 1/8/2013 10:01:13 AM | | | | | |
| Lozoya, Manny | | Outdoor lock of greenhouse will not open. | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 94764 | Annex | | | | 10/30/2012 | | 76 | | \$0.00 |
| Medium | Work In Progress | Annex/ old hall | | 10/30/2012 11:47:30 | | | | | |
| Solis, Lorenzo | | Water fountain does not work. It has low water pressure at drinking spout. | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 97044 | Annex | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | Annex/ Staff | | 1/8/2013 3:46:29 PM | | | | | |
| Appelzoller, Fred | | Leaking drain under sink, floor is always wet. | | | | | | | |
| Nancy Tinajero | | | | | | | | | |
| 94878 | Annex | Hallway/Corridor | | | 11/1/2012 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2012 8:00:53 AM | | | | | |
| Lozoya, Manny | | ANNEX EXIT DOOR NEXT TO ROOM 407 WE UNLOCK AND CAN NOT OPEN DOOR | | | | | | | |
| Juan Acosta | | | | | | | | | |
| 94880 | Gymnasium | Hallway/Corridor | | | 11/1/2012 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2012 8:14:11 AM | | | | | |
| Lozoya, Manny | | LOBBY EXIT DOOR GOING IN GYM FLOOR NEXT TO BLEACHERS THE MULLION IS LOOSE | | | | | | | |
| Juan Acosta | | | | | | | | | |
| 95619 | Gymnasium | Classroom | | | 11/16/2012 | | 59 | | \$0.00 |
| Medium | Work In Progress | 602,603 | | 11/16/2012 9:03:35 AM | | | | | |
| Lozoya, Manny | | THE ENTRANCE DOOR KNOB KEYHOLE LEADING INTO RM 602, AND 603 IS NOT USEABLE. THE KEY WILL NOT GO IN | | | | | | | |
| Juan Acosta | | | | | | | | | |
| Count: 41 Work Orders | | Avg. Age of WO's 44 | | | Total for Gadsden MS | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|---|-------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: La Union ES | | | | | | | | | |
| 96398 | Main Building | Classroom | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | 12/7/2012 4:19:00 PM | | | | | |
| Villalobos, David | Please fix the leaking toilet and replace the lavatory faucet in room 111 at La Union. For details visit with Pat Aguilar or call Ralph Gallegos at 882-6921. Thanks. | | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 93326 | | | | | 9/27/2012 | | 109 | | \$0.00 |
| Medium | Work In Progress | | | 9/27/2012 9:57:08 AM | | | | | |
| Lara, Ralph | DOOR BY WATER HEATER NEEDS TO BE SHAVED - CARPET WAS REPLACED IN BARRACK CHILD CARE CLASS (WORK ORDER #92350), . | | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 96131 | | | | | 12/2/2012 | 12/8/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:20 AM | | | | | |
| Aguilar, Patricio | Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96854 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:19 AM | | | | | |
| Aguilar, Patricio | Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96678 | | | | | 12/31/2012 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | 12/31/2012 12:27:07 | | | | | |
| Sanchez, Raul | Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96414 | | | | | 12/9/2012 | 12/25/2012 | 36 | | \$0.00 |
| Medium | Work In Progress | | | 12/9/2012 12:16:27 AM | | | | | |
| Aguilar, Patricio | Monthly - La Union ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97215 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:08 AM | | | | | |
| Aguilar, Patricio | Monthly - La Union ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96129 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:19 AM | | | | | |
| Aguilar, Patricio | Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 1/14/2013 11:04:42 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|--------------------|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | La Union ES | | | | | | | |
| 96130 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 12/2/2012 12:23:20 AM | | | | |
| Aguilar, Patricio | Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96859 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:24:22 AM | | | | |
| Aguilar, Patricio | Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96857 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:24:21 AM | | | | |
| Aguilar, Patricio | Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96858 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:24:21 AM | | | | |
| Aguilar, Patricio | Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96132 | | | | | 12/2/2012 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 12/2/2012 12:23:20 AM | | | | |
| Aguilar, Patricio | Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95576 | | | | | 11/15/2012 | | 60 | | \$0.00 |
| Scheduled | Work In Progress | | | | 11/15/2012 10:46:39 | | | | |
| Aguilar, Patricio | Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93399 | | | | | 9/28/2012 | | 108 | | \$0.00 |
| Medium | Work In Progress | | | | 9/28/2012 1:39:29 PM | | | | |
| Aguilar, Patricio | need a elect wall outlet for r100 thank you for you help | | | | | | | | |
| <u>Patricio Aguilar</u> | | | | | | | | | |
| 96855 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:24:20 AM | | | | |
| Aguilar, Patricio | Monthly - La Union ES Roof Inpsection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 1/14/2013 11:04:42 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|---|-------------|-------------------------|-----------------------|------------------|------------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: La Union ES | | | | | | | | | |
| 97224 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:12 AM | | | | | |
| Ramos, Rudy | Monthly - QRTL Y BLDG INSP REPORT (LU) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 94427 | | | | | 10/22/2012 | | 84 | | \$0.00 |
| Medium | Work In Progress | | | 10/22/2012 11:28:37 | | | | | |
| Aguilar, Patricio | need p trap for urinal restroom b build | | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 96768 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:39 AM | | | | | |
| Villalobos, David | Yearly - La Union ES Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 94429 | | | | | 10/22/2012 | | 84 | | \$0.00 |
| Medium | Work In Progress | | | 10/22/2012 11:31:40 | | | | | |
| Villalobos, David | need wax donut - floor bracket for toilet r207 | | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| 96185 | | Classroom | | | 12/3/2012 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/3/2012 2:54:24 PM | | | | | |
| Arreola, Rudy | NEED ASSITANCE PAINTING AT LA UNION ELEM. CLASSROOMS ARE READY FOR PAINT. | | | | | | | | |
| Rudy Arreola | | | | | | | | | |
| 94907 | | | | | 11/1/2012 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2012 2:43:15 PM | | | | | |
| Aguilar, Patricio | wo to my self - paint class rooms - hall way old wing | | | | | | | | |
| Patricio Aguilar | | | | | | | | | |
| Count: 22 Work Orders | | | Avg. Age of WO's | 40 | | Total for La Union ES | 0 | | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------------|---|-------------|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Loma Linda ES | | | | | | | | | |
| 91008 | | | | | 8/8/2012 | | 159 | | \$0.00 |
| Medium | Work In Progress | | | | 8/8/2012 2:00:00 PM | | | | |
| Sotelo, Enrique | Emerg lights (8) in Boys & Girls Restrooms not working asp PM 90795. | | | | | | | | |
| Rudy Arreola | | | | | | | | | |
| 96766 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:23:38 AM | | | | |
| Villalobos, David | Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96866 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:24:25 AM | | | | |
| Arreola, Rudy | Monthly - Loma Linda ES Roof Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97214 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | | 1/13/2013 12:16:07 AM | | | | |
| Solis, Luis | Monthly - QRTLY BLDG INSP REPORT (LL) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97238 | | | | | 1/14/2013 | | 0 | | \$0.00 |
| Medium | Work In Progress | | | | 1/14/2013 8:34:28 AM | | | | |
| , | NEED TO DETAIL ALL RESTROOMS: FLOORS, CORNERS & EDGES. | | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 91421 | | Portables | | | 8/16/2012 | | 151 | | \$0.00 |
| Medium | Work In Progress | | | | 8/16/2012 2:43:25 PM | | | | |
| Arreola, Rudy | NEED BLINDS FOR PORTABLES | | | | | | | | |
| Rudy Arreola | | | | | | | | | |
| 91422 | | Parking Lot | | | 8/16/2012 | | 151 | | \$0.00 |
| Medium | Work In Progress | | | | 8/16/2012 2:44:29 PM | | | | |
| Arreola, Rudy | NEED 8 PLASTIC BARRIERS FOR TRAFFIC CONTROL. | | | | | | | | |
| Rudy Arreola | | | | | | | | | |
| 96867 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:24:26 AM | | | | |
| Arreola, Rudy | Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|-------------|-------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |

Location: Loma Linda ES

| | | | | | | | | | |
|--------------------|---|--|--|-----------------------|-----------|-----------|---|--|--------|
| 96868 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:26 AM | | | | | |
| Arreola, Rudy | Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96869 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:27 AM | | | | | |
| Arreola, Rudy | Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97220 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:10 AM | | | | | |
| Arreola, Rudy | Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97060 | | | | | 1/9/2013 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | 1/9/2013 12:33:46 PM | | | | | |
| Orozco, Daniel | ICE MACHINE IS NOT MAKING ICE. SNP MANAGER FRANCES B. 882.4707 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 97061 | | | | | 1/9/2013 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | 1/9/2013 12:34:57 PM | | | | | |
| Orozco, Daniel | HAND SINK NEXT TO 3 COMPARTMENT SINK IS LEAKING. SNP MANAGER FRANCES B. 882.4707 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 96865 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:25 AM | | | | | |
| Arreola, Rudy | Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96789 | | | | | 1/6/2013 | 1/27/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:47 AM | | | | | |
| Orozco, Daniel | Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|-------------|-------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |

Location: Loma Linda ES

96483 Main Building Classroom 12/11/2012 34 \$0.00

Medium Work In Progress 112 12/11/2012 3:07:37 PM

Appelzoller, Fred Two weeiks ago "snake" was used to declog toilet. It has been 2 years of the toilet not flushing properly. I dont believe it is an issue of two much toilet paper. I dont know if the whole toilet bowl needs to be replaced. On a daily baisis I have to pause Instruction to hold the lever down so that it flushes. There are water stains on floor from water leaking.

Angie Flores

95663 Main Building Hallway/Corridor 11/19/2012 56 \$0.00

Medium Work In Progress 11/19/2012 9:43:03 AM

Sotelo, Enrique THE SECURITY LIGHT OUTSIDE ENTRANCE AND EXIT DOORS NORTH EAST SIDE IS OFF, WE NEED IT ON FOR THE SECURITY CAMARAS., THANKS.

Luis Solis

92940 Main Building Cafeteria 9/18/2012 118 \$0.00

Medium Work In Progress 9/18/2012 2:52:51 PM

Sotelo, Enrique NEED TO HAVE EXIT SIGN REPLACED BACK DOOR IN KITHECN AREA.

Rudy Arreola

96001 Main Building Parking Lot 11/30/2012 45 \$0.00

Medium Work In Progress 11/30/2012 11:37:03

Arreola, Rudy As per Mr. Lawler please repaint the fire lanes.

Angie Flores

96689 Main Building Hallway/Corridor 1/3/2013 11 \$0.00

Medium Work In Progress 1/3/2013 10:43:37 AM

Lozoya, Manny Need to fix front door. Need to replace the lock door mechanishn (Latch). Do not need new key only to replace the latch. We also need to do the same thing on the door that gives you access to the employee parking lot.

Angie Flores

95918 Main Building Mechanical 11/29/2012 46 \$0.00

Medium Work In Progress 11/29/2012 8:05:08 AM

Solis, Lorenzo PUMP IN MECHANICAL ROOM IS MAKING NOISE THAN NORMAL PUMP WAS GREASED WHEN BOILER WAS STARTED UP. NEEDS TO BE CHECKED.

Rudy Arreola

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|--|----------------------------|-------------|-----------------------|-------------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Loma Linda ES | | | | | | | |
| 97008 | Main Building | Classroom | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 10:10:55 AM | | | | | |
| Lozoya, Manny | As per our principal we need 6 keys to open the back door to the main building. Keys are for Morris, Martinez, Quintero, Gonzalez, Luna and Steinert. Keys will be able to only open one of the back main doors. Not a master key! | | | | | | | | |
| <u>Angie Flores</u> | | | | | | | | | |
| 96008 | Main Building | Athletic Field | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2012 2:49:28 PM | | | | | |
| Ontiveros, Guadalupe | ANOTHER VALVE IS STUCK SPRINKLERS KEEP RUNNING. BY PLAYGROUND AREA. | | | | | | | | |
| <u>Rudy Arreola</u> | | | | | | | | | |
| 95770 | Main Building | Hallway/Corridor | | | 11/26/2012 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | 11/26/2012 12:45:44 | | | | | |
| Arreola, Rudy | Water fountain needed to be turned off water kept running solenoid needs to be replaced. | | | | | | | | |
| <u>Rudy Arreola</u> | | | | | | | | | |
| 95660 | Main Building | Office | | | 11/19/2012 | | 56 | | \$0.00 |
| Medium | Work In Progress | | | 11/19/2012 9:27:33 AM | | | | | |
| Arreola, Rudy | PRINCIPAL OFFICE HAS SOME LIGHTS OFF. THANKS | | | | 11/20/12 - Asp Mike, route to Rudy. | | | | |
| <u>Luis Solis</u> | | | | | | | | | |
| 94643 | Main Building | Athletic Field | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/26/2012 12:36:05 | | | | | |
| Ronquillo, Ruben | SLIDE WAS HIT WITH A ROCK AND MADE A HOLE DEAD CENTER OF SLIDE NEEDS TO BE REPLACED. | | | | | | | | |
| <u>Rudy Arreola</u> | | | | | | | | | |
| 97092 | Main Building | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 7:54:21 AM | | | | | |
| Ronquillo, Ruben | We have 2 broken windows in hall ways sizes are 47x47 needs to be replaced. | | | | | | | | |
| <u>Rudy Arreola</u> | | | | | | | | | |
| Count: 27 Work Orders | | Avg. Age of WO's 40 | | | Total for Loma Linda ES | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|------------------|---|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Mesquite ES | | | | | | | |
| 95896 | Main Building | Hallway/Corridor | | | 11/28/2012 | | 47 | | \$0.00 |
| Safety | Work In Progress | | | 11/28/2012 3:34:31 PM | | | | | |
| Sanchez, Raul | | Collect (4) special water samples from Mesquite Elementary & take to AETL lab for analysis | | | | | | | |
| Richard Chavez | | | | | | | | | |
| 97017 | Main Building | Office | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 10:40:52 AM | | | | | |
| Briones, Enrique | | Please deliver 2 boxes of TE'S Kits | | | | | | | |
| Larry Martinez | | | | | | | | | |
| 91491 | | | | | 8/17/2012 | | 150 | | \$0.00 |
| Medium | Work In Progress | | | 8/17/2012 12:42:10 PM | | | | | |
| Estrada, Jesus | | ATTEN. ALFREDO, RMS.201,202,203,204,205. CARPET NEEDS TO BE REPLACED WITH FLOOR TILE. | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 94625 | | Custodial | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/26/2012 6:55:00 AM | | | | | |
| Estrada, Jesus | | Mr. Estrada, On portables #602 the carpet is torn out and need new carpet. If you have a chance, could you please stop by and see it. Thank you | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 90983 | | Portables | | | 8/8/2012 | | 159 | | \$0.00 |
| Medium | Work In Progress | | | 8/8/2012 9:32:51 AM | | | | | |
| Estrada, Jesus | | Mr. Estrada, On portables #801 and #802 the carpet is torn out and both rooms need new carpet. If you have a chance, could you please stop by and see it. Thank you | | | | | | | |
| Luis Saucedo | | | | | | | | | |
| 89435 | | | | | 7/1/2012 | 8/1/2012 | 197 | | \$0.00 |
| Medium | Work In Progress | | | 7/1/2012 12:30:58 AM | | | | | |
| Ramirez, Joe | | Yearly - Mesquite ES Emer. Light Test: Annual - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 89436 | | | | | 7/1/2012 | 8/1/2012 | 197 | | \$0.00 |
| Medium | Work In Progress | | | 7/1/2012 12:30:58 AM | | | | | |
| Ramirez, Joe | | Yearly - Mesquite ES Exit Sign Test: Annual - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|---|--------------------|-------------|----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Mesquite ES | | | | | | | |
| 96842 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:13 AM | | | | | |
| Ramirez, Joe | Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96893 | | Custodial | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 7:43:24 AM | | | | | |
| Carbajal, Jimmy | please vaccum #1168 the motor is not working also the wheels are broken thank you | | | | | | | | |
| <u>Luis Saucedo</u> | | | | | | | | | |
| 95365 | | | | | 11/9/2012 | | 66 | | \$0.00 |
| Medium | Work In Progress | | | 11/9/2012 1:09:02 PM | | | | | |
| Lozoya, Manny | sothside boys and girls bathroom stalls need to be replaced the floor securing brackets are either broken or rusted through and also most of the stalls are very rusted | | | | | | | | |
| <u>Joe Ramirez</u> | | | | | | | | | |
| 96318 | | | | | 12/6/2012 | | 39 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2012 1:02:43 PM | | | | | |
| Briones, Enrique | please Warehouse ATT: LARRY MARTINES we have broken computer desk, old furniture, student desk broken, etc. thank you | | | | | | | | |
| <u>Luis Saucedo</u> | | | | | | | | | |
| 97059 | | | | | 1/9/2013 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | 1/9/2013 12:30:39 PM | | | | | |
| Orozco, Daniel | WALK IN FREEZER IS AT 32 DEGREES.SNP MANAGER VIRGINIA P. 233.2341 | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 95866 | | | | | 11/28/2012 | | 47 | | \$0.00 |
| Medium | Work In Progress | | | 11/28/2012 10:12:08 | | | | | |
| Orozco, Daniel | WASHER IS NOT WORKING. SNP MANAGER VIRGINIA P. 233.2341 | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 96878 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:32 AM | | | | | |
| Sanchez, Raul | Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|---|----------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Mesquite ES | | | | | | | | | |
| 97166 | | | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2013 3:18:00 PM | | | | | |
| Ramirez, Joe | please check all restrooms and replace partitions that are rusted. thank you | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 91551 | | | | | 8/20/2012 | | 147 | | \$0.00 |
| Medium | Work In Progress | | | 8/20/2012 12:50:51 PM | | | | | |
| Ramirez, Joe | need to install frp panel in rms. 801,802. | | | | | | | | |
| <u>Joe Ramirez</u> | | | | | | | | | |
| 96839 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:12 AM | | | | | |
| Ramirez, Joe | Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96840 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:12 AM | | | | | |
| Ramirez, Joe | Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96841 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:13 AM | | | | | |
| Ramirez, Joe | Monthly - Mesquite ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95182 | | Athletic Field | | | 11/5/2012 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | 11/5/2012 3:27:39 PM | | | | | |
| Ramirez, Joe | As per mr. Mike need to in stall irrigation system on playing fields. | | | | | | | | |
| <u>Guadalupe Ontiveros</u> | | | | | | | | | |
| 96843 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:14 AM | | | | | |
| Ramirez, Joe | Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97225 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:13 AM | | | | | |
| Saucedo, Luis | Monthly - QRTLY BLDG INSP REPORT (MQ) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|---|--------------------|-------------------------|-----------------------|------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Mesquite ES | | | | | | | |
| 96769 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:39 AM | | | | | |
| Villalobos, David | Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97114 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 1:14:20 PM | | | | | |
| Sotelo, Enrique | in rm 601 there is no power to outlets west wall | | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 96221 | | | | | 12/4/2012 | | 41 | | \$0.00 |
| Medium | Work In Progress | | | 12/4/2012 9:01:10 AM | | | | | |
| Sotelo, Enrique | i have 4 parking lot security lights that the bulbs need to be replaced. | | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 95919 | | | | | 11/29/2012 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | 11/29/2012 8:12:40 AM | | | | | |
| Solis, Lorenzo | heater coil unit rm. 402 not working | | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 93466 | | | | | 9/30/2012 | 10/31/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:30:15 AM | | | | | |
| Ramirez, Joe | Yearly - Mesquite ES I-4 Fan Coil Unit Yearly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97179 | | | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2013 3:47:35 PM | | | | | |
| Ramirez, Joe | please paint doors to portable 611 & 612. thank you | | | | | | | | |
| Selma Nevarez | | | | | | | | | |
| 94294 | | | | | 10/18/2012 | | 88 | | \$0.00 |
| Medium | Work In Progress | | | 10/18/2012 8:06:20 AM | | | | | |
| Ramirez, Joe | need to re-paint some of the wall in the lib. | | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| 96685 | | | | | 1/3/2013 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | 1/3/2013 8:23:42 AM | | | | | |
| Solis, Lorenzo | heating units in rms. 505,506 are not working | | | | | | | | |
| Joe Ramirez | | | | | | | | | |
| Count: 30 Work Orders | | | Avg. Age of WO's | 53 | Total for Mesquite ES | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|---|-------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: North Valley ES | | | | | | | | | |
| 97094 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 8:18:54 AM | | | | | |
| Solis, Lorenzo | rm 201 has no heat since yesterday 1-9-13 plz ck and bring portable heaters | | | | | | | | |
| Danny Vega | | | | | | | | | |
| 94004 | | | | | 10/10/2012 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2012 3:11:28 PM | | | | | |
| Sotelo, Enrique | mechanical rms by rms 301-304-303-309-300-203208-210-102 and by lounge lites are out bad emergency ballast | | | | | | | | |
| Danny Vega | | | | | | | | | |
| 96754 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:33 AM | | | | | |
| Villalobos, David | Yearly - North Valley ES Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96797 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:51 AM | | | | | |
| Vega, Danny | Monthly - North Valley ES Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97194 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:15:57 AM | | | | | |
| Parra, Javier | Monthly - QRTLY BLDG INSP REPORT (NV) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 91740 | | Classroom | | | 8/23/2012 | | 144 | | \$0.00 |
| Medium | Work In Progress | various | | 8/23/2012 10:11:46 AM | | | | | |
| Lozoya, Manny | Need to obtain additional cabinet keys for certain classrooms. | | | | | | | | |
| Priscilla Martinez | | | | | | | | | |
| 89953 | | | | | 7/18/2012 | | 180 | | \$0.00 |
| Medium | Work In Progress | | | 7/18/2012 10:38:49 AM | | | | | |
| Lozoya, Manny | need exterior security door handle plates installed in rm 107-108-211-212-309-310 doors to keep vandals from prying doors open as per MR. T | | | | | | | | |
| Danny Vega | | | | | | | | | |
| 94886 | | | | | 11/1/2012 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2012 10:47:05 AM | | | | | |
| Lozoya, Manny | door in between techers lounge and hallway wont close. | | | | | | | | |
| Javier Parra | | | | | | | | | |
| 1/14/2013 11:04:43 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | North Valley ES | | | | | | | |
| 93977 | | | | | 10/10/2012 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2012 7:41:20 AM | | | | | |
| Flores, Pete | truck #76 needs brakes checked-also it stulls on the road it just dies and leaks water thru water pump.plz ck anti freeze.my tool box is loose and will not close .plz remove | | | | | | | | |
| <u>Danny Vega</u> | | | | | | | | | |
| 97168 | | | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2013 3:27:24 PM | | | | | |
| Ronquillo, Ruben | FILTERS FOR HEATING SEASON | | | | | | | | |
| <u>Ruben Ronquillo</u> | | | | | | | | | |
| 95580 | | | | | 11/15/2012 | | 60 | | \$0.00 |
| Scheduled | Work In Progress | | | 11/15/2012 10:48:52 | | | | | |
| Vega, Danny | Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You | | | | | | | | |
| 96793 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:49 AM | | | | | |
| Vega, Danny | Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96535 | | Classroom | | | 12/12/2012 | | 33 | | \$0.00 |
| Medium | Work In Progress | 202 | | 12/12/2012 11:22:46 | | | | | |
| Vega, Danny | Please replace Early Childhood toilet seat with an adult toilet seat. | | | | | | | | |
| <u>Priscilla Martinez</u> | | | | | | | | | |
| 96798 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:51 AM | | | | | |
| Vega, Danny | Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95815 | | | | | 11/27/2012 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | 11/27/2012 8:55:09 AM | | | | | |
| Vega, Danny | need to attach chains to trash can lids. att. Danny | | | | | | | | |
| <u>Javier Parra</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | North Valley ES | | | | | | | |
| 96175 | | | | | 12/3/2012 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/3/2012 11:14:46 AM | | | | | |
| Munoz, Michael | attention (MMUNOZ)need 1 set of soccer goals (additional)6 ft x 12ft (same as vado)for our lower grades-thanks | | | | | | | | |
| <u>Danny Vega</u> | | | | | | | | | |
| 97018 | | Office | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 10:43:29 AM | | | | | |
| Briones, Enrique | Please deliver 2 boxes of Science TE'S Kits | | | | | | | | |
| <u>Larry Martinez</u> | | | | | | | | | |
| 96366 | | | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | 12/7/2012 10:22:43 AM | | | | | |
| Gonzalez, Salvador | need to repair entrance and exit signs by bus area | | | | | | | | |
| <u>Danny Vega</u> | | | | | | | | | |
| 89304 | | | | | 7/1/2012 | | 197 | | \$0.00 |
| Medium | Work In Progress | | | 7/1/2012 12:30:02 AM | | | | | |
| Holguin, Alfredo | Monthly - North Valley ES-Fire Pump Engine-Quartly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93611 | | | | | 9/30/2012 | | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:20 AM | | | | | |
| Holguin, Alfredo | Monthly - North Valley ES-Fire Pump Engine-Quartly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97200 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:00 AM | | | | | |
| Vega, Danny | Monthly - North Valley ES Playground Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96724 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:17 AM | | | | | |
| Holguin, Alfredo | Monthly - North Valley ES-Fire Pump Engine-Quartly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96796 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:51 AM | | | | | |
| Vega, Danny | Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|--------------|-------|-------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |

Location: North Valley ES

| | | | | | | | | | |
|----------------|--|--|--|--|----------------------|--|---|--|--------|
| 96782 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:23:44 AM | | | | |
| Orozco, Daniel | Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | | |

| | | | | | | | | | |
|---------------------------|---|--|--|--|-----------------------|--|----|--|--------|
| <u>Margret Villalobos</u> | | | | | | | | | |
| 94142 | | | | | 10/15/2012 | | 91 | | \$0.00 |
| Medium | Work In Progress | | | | 10/15/2012 7:53:45 AM | | | | |
| Munoz, Michael | fire pump house alarm set -off 10-12-12- at 5:30 pm showin system fault and battery #2 fault on panel - system shut off-please check .we are with out fire spklr protection at this time.(attention mmunoz) | | | | | | | | |

| | | | | | | | | | |
|------------------------------|--|--|-------------------------|-----------|--|----------------------------------|----------|--|---------------|
| <u>Danny Vega</u> | | | | | | | | | |
| Count: 25 Work Orders | | | Avg. Age of WO's | 51 | | Total for North Valley ES | 0 | | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|--|----------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Northern On-Track Pre-K (LM) | | | | | | | | | |
| 96795 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:50 AM | | | | | |
| Vega, Danny | Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96687 | Main Building | | | | 1/3/2013 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | 1/3/2013 8:32:19 AM | | | | | |
| Solis, Lorenzo | CIRCULATING PUMP LEAK IN BOILER ROOM. WATER PRESSURE IS LOW. | | | | | | | | |
| <u>Adam Montoya</u> | | | | | | | | | |
| 97106 | Main Building | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | Room 102 & 110 | | 1/10/2013 10:22:21 AM | | | | | |
| Solis, Lorenzo | Heater do not work when turned on. | | | | | | | | |
| <u>Concepcion Montalvo</u> | | | | | | | | | |
| 97199 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:00 AM | | | | | |
| Vega, Danny | Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95575 | | | | | 11/15/2012 | | 60 | | \$0.00 |
| Scheduled | Work In Progress | | | 11/15/2012 10:46:03 | | | | | |
| Vega, Danny | Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You | | | | | | | | |
| 96791 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:48 AM | | | | | |
| Vega, Danny | Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96792 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:49 AM | | | | | |
| Vega, Danny | Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97189 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:15:54 AM | | | | | |
| Montoya, Adam | Monthly - QRTLY BLDG INSP REPORT (LM/PRE-K) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 1/14/2013 11:04:43 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|---|-------------|-------------------------|----------------------|---|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Northern On-Track Pre-K (LM) | | | | | | | | | |
| 96794 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:50 AM | | | | | |
| Vega, Danny | Monthly - La Mesa ES Roof Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96767 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:38 AM | | | | | |
| Villalobos, David | Yearly - Northern Pre-K Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 10 Work Orders | | | Avg. Age of WO's | 12 | Total for Northern On-Track Pre-K (LM) | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|---|-------------------------------|-------------|-----------------------|------------------|-----------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Physical Plant Complex | | | | | | | |
| 96770 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:40 AM | | | | | |
| Villalobos, David | Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 92274 | | | | | 9/2/2012 | | 134 | | \$0.00 |
| Medium | Work In Progress | | | 9/2/2012 12:21:47 AM | | | | | |
| Munoz, Michael | Monthly - Physical Plant - Grease Trap (Custodial) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95523 | | Parking Lot | | | 11/14/2012 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | 11/14/2012 2:39:27 PM | | | | | |
| Ontiveros, Guadalupe | Parking Area on south side of fence between warehouse and GMS Annex - Install parking stops along fence and around fire hydrant to provide enough clearance around hydrant and next to fence. | | | | | | | | |
| <u>Alfredo Holguin</u> | | | | | | | | | |
| 96885 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:36 AM | | | | | |
| Diaz, Sebastian | Monthly - Physical Plant Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97186 | | | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2013 4:10:21 PM | | | | | |
| Lara, Ralph | DOOR HANDLE IS LOOSE. | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 96035 | | | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2012 3:53:59 PM | | | | | |
| Flores, Pete | vehicle 99 is leaking oil and shocks sounds like if it is loose. please check. thank you | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 95161 | | | | | 11/5/2012 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | 11/5/2012 12:20:02 AM | | | | | |
| Villalobos, Margret | Monthly - PPD - Quarterly Meeting - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93067 | | | | | 9/20/2012 | | 116 | | \$0.00 |
| Medium | Work In Progress | | | 9/20/2012 10:51:22 AM | | | | | |
| Ronquillo, Ruben | as per meeting held, please dispose of any unused material and clean and organize barracks. thank you. | | | | | Continuing from 68685 | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 1/14/2013 11:04:43 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|--|-------------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Physical Plant Complex | | | | | | | |
| 93023 | | | | | 9/19/2012 | | 117 | | \$0.00 |
| Medium | Work In Progress | | | 9/19/2012 3:17:08 PM | | | | | |
| Apodaca, Mario | need to place order for domestic water filters for several school sites | | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 95524 | | | | | 11/14/2012 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | 11/14/2012 2:45:56 PM | | | | | |
| Apodaca, Mario | PPD Sewage treatment plant The expansion joints At the aeration basin are expanding and contracting due to cold weather loosing some product need to be repaired. As soon as possible | | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 93179 | | Lift Station | | | 9/24/2012 | | 112 | | \$0.00 |
| Medium | Work In Progress | | | 9/24/2012 2:41:20 PM | | | | | |
| Gonzalez, Salvador | Meet to manufacture A base for the domestic tablet container for the waste water treatment plant | | | | | | | | |
| Mario Apodaca | | | | | | | | | |
| 96009 | | | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2012 2:57:08 PM | | | | | |
| Ontiveros, Joe | NEED TOOLS FOR SERVICE TRUCK(HAND TOOLS) ASSORTMENT | | | | | | | | |
| Joe Ontiveros | | | | | | | | | |
| 95647 | | | | | 11/16/2012 | | 59 | | \$0.00 |
| High | Work In Progress | | | 11/16/2012 3:52:03 PM | | | | | |
| Munoz, Michael | this is to provide service or replace fire extinguisher (out-dated codes) at the following sites gac,ae,br,che,chs,cms,dp,dt,dv,ge,ghs,gms,northern pre -k,lu,ll,mq,nv,ppd,re,ste,sth,sp,sr,vado. | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 94568 | Food Services | Office | | | 10/25/2012 | | 81 | | \$0.00 |
| Medium | Work In Progress | | | 10/25/2012 8:22:13 AM | | | | | |
| Lozoya, Manny | Manny or Rafa...need to install a core in the new door at the Food Warehouse. The door that goes from the office to the warehouse. Please call me if you have any questions. Thanks. Rafael Gallegos | | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 93208 | Food Services | | | | 9/25/2012 | | 111 | | \$0.00 |
| Medium | Work In Progress | | | 9/25/2012 8:32:47 AM | | | | | |
| Orozco, Daniel | The walk-in refrigerator door has a piece of metal | | | | | | | | |
| | And rubber molding coming off that needs to be fixed | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|---|-----------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 94039 | Motor Vehicle | | | | 10/11/2012 | | 95 | | \$0.00 |
| Medium | Work In Progress | gms-golf cart | | 10/11/2012 7:47:47 AM | | | | | |
| Flores, Pete | golf cart will not travel in forward direction. | | | | | | | | |
| Pete Flores | | | | | | | | | |
| 94371 | Motor Vehicle | | | | 10/19/2012 | | 87 | | \$0.00 |
| Medium | Work In Progress | vehicle's 163 & | | 10/19/2012 1:54:24 PM | | | | | |
| Flores, Pete | tires worn requiring replacement on both units.unit # 164 also in need of alignment. | | | | | | | | |
| Pete Flores | | | | | | | | | |
| 94420 | Motor Vehicle | | | | 10/22/2012 | | 84 | | \$0.00 |
| Medium | Work In Progress | vehicle#101 | | 10/22/2012 11:16:35 | | | | | |
| Flores, Pete | truck has difficulty achieving highway speed,possibly a fuel concern. check and advise. | | | | | | | | |
| Pete Flores | | | | | | | | | |
| 94426 | Motor Vehicle | | | | 10/22/2012 | | 84 | | \$0.00 |
| Medium | Work In Progress | vehicle#126 | | 10/22/2012 11:27:16 | | | | | |
| Flores, Pete | water pump losing coolant and runs very rough intermittently.please check | | | | | | | | |
| Pete Flores | | | | | | | | | |
| 95928 | Motor Vehicle | | | | 11/29/2012 | | 46 | | \$0.00 |
| Medium | Work In Progress | vehicle#86 | | 11/29/2012 9:53:45 AM | | | | | |
| Flores, Pete | van is running rough and engine is misfiring during normal operation. | | | | | | | | |
| Pete Flores | | | | | | | | | |
| 96437 | Motor Vehicle | | | | 12/10/2012 | | 35 | | \$0.00 |
| Medium | Work In Progress | vehicles 139 & | | 12/10/2012 1:47:24 PM | | | | | |
| Flores, Pete | truck # 95 needs to be placed out of service,and replaced with unit # 139. | | | | | | | | |
| Pete Flores | | | | | | | | | |
| 96438 | Motor Vehicle | | | | 12/10/2012 | | 35 | | \$0.00 |
| Medium | Work In Progress | vehicles 08,12 | | 12/10/2012 1:53:06 PM | | | | | |
| Flores, Pete | please prepare new vehicles for introduction to fleet,and assign numbers-08,12. | | | | | | | | |
| Pete Flores | | | | | | | | | |
| 96373 | Motor Vehicle | | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | vehicle #50 | | 12/7/2012 1:34:21 PM | | | | | |
| Flores, Pete | vehicle experiences a vibration at hi-way speeds between 70 and 75 m.p.h. | | | | | | | | |
| Pete Flores | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------|-------------|-------------|-------------|-------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |

Location: Physical Plant Complex

| | | | | | | | | | |
|--------------|---|-------------|--|--|-----------------------|--|----|--|--------|
| 96596 | Motor Vehicle | | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | vehicle#143 | | | 12/13/2012 2:36:26 PM | | | | |
| Flores, Pete | check for leaks at fuel injection pump. | | | | | | | | |

Pete Flores

| | | | | | | | | | |
|--------------|---------------------------------------|-------------|--|--|----------------------|--|---|--|--------|
| 97157 | Motor Vehicle | | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | vehicle#153 | | | 1/11/2013 9:00:45 AM | | | | |
| Flores, Pete | bench seat torn and metal is exposed. | | | | | | | | |

Pete Flores

| | | | | | | | | | |
|--------------|---|------------------|--|--|----------------------|--|---|--|--------|
| 97158 | Motor Vehicle | | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | vehicles 147,187 | | | 1/11/2013 9:11:54 AM | | | | |
| Flores, Pete | please repair windshields on vehicles as needed | | | | | | | | |

Pete Flores

| | | | | | | | | | |
|--------------|---|-------------|--|--|----------------------|--|---|--|--------|
| 97013 | Motor Vehicle | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | vehicle#175 | | | 1/8/2013 10:35:10 AM | | | | |
| Flores, Pete | check for any scheduled maintenance and prepare for trip to albuquerque | | | | | | | | |

Pete Flores

| | | | | | | | | | |
|--------------|---|--|--|--|----------------------|--|-----|--|--------|
| 91931 | Motor Vehicle | | | | 8/28/2012 | | 139 | | \$0.00 |
| Medium | Work In Progress | | | | 8/28/2012 7:52:34 AM | | | | |
| Flores, Pete | driver seat is tearing on unit 170, request seat covers for it and a step to get on the truck to avoid any more damage to seats and steering wheel while getting into the truck. even a dash mat for the dashboard to avoid sun damage to it . thank u !! | | | | | | | | |

Fred Appelzoller

| | | | | | | | | | |
|-------------|---|------------------|--|--|-----------------------|--|----|--|--------|
| 94667 | Motor Vehicle | | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | vehicles 188,161 | | | 10/26/2012 3:24:12 PM | | | | |
| Perez, Raul | please wash,clean,& re-fuel as required by daily trip schedule. | | | | | | | | |

Pete Flores

| | | | | | | | | | |
|-------------|--|-----------|--|--|-----------------------|--|----|--|--------|
| 96593 | Motor Vehicle | | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | vehicles- | | | 12/13/2012 2:27:15 PM | | | | |
| Perez, Raul | please refuel,clean & wash as required by daily trip schedule. | | | | | | | | |

Pete Flores

| | | | | | | | | | |
|-------------|--|-----------|--|--|-----------------------|--|----|--|--------|
| 96594 | Motor Vehicle | | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | vehicles- | | | 12/13/2012 2:31:49 PM | | | | |
| Perez, Raul | please check and prepare listed vehicles for daily trip schedules. | | | | | | | | |

Pete Flores

1/14/2013 11:04:43 AM

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---|---|-------------|-------------|-----------------------|---|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Physical Plant Complex | | | | | | | | | |
| 96595 | Motor Vehicle | | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | vehicles- | | 12/13/2012 2:34:33 PM | | | | | |
| Perez, Raul | please clean, wash, and prepare for daily trip schedule. | | | | | | | | |
| <u>Pete Flores</u> | | | | | | | | | |
| 95859 | Purchasing | Office | | | 11/27/2012 | | 48 | | \$0.00 |
| Medium | Work In Progress | | | 11/27/2012 4:14:46 PM | | | | | |
| Lozoya, Manny | Please make a key for IM office 2. For Larry | | | | | | | | |
| <u>Larry Martinez</u> | | | | | | | | | |
| 91399 | Purchasing | Office | | | 8/16/2012 | | 151 | | \$0.00 |
| Medium | Work In Progress | | | 8/16/2012 7:47:33 AM | | | | | |
| Solis, Lorenzo | need a new central heating unit for this coming winter season at the locksmith, water office area | | | | | | | | |
| <u>Mario Apodaca</u> | | | | | | | | | |
| 94890 | Purchasing | | | | 11/1/2012 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2012 11:12:31 AM | | | | | |
| Lozoya, Manny | Main Entry Lock to PPD-Construction Offices - core is sticking and hard to unlock | | | | | | | | |
| <u>Alfredo Holguin</u> | | | | | | | | | |
| 91966 | Purchasing | | | | 8/28/2012 | | 139 | | \$0.00 |
| Medium | Work In Progress | | | 8/28/2012 2:08:55 PM | | | | | |
| Solis, Lorenzo | Womens Restroom in Custodial Warehouse - The exhaust fan is not working. Humms but does not move air | | | | Pending Construction asp report 10/30/12 11/27/12 - 2nd request from A. Holguin, restroom is complete | | | | |
| <u>Alfredo Holguin</u> | | | | | | | | | |
| 91801 | Maintenance | | | | 8/24/2012 | | 143 | | \$0.00 |
| Medium | Work In Progress | | | 8/24/2012 7:25:21 AM | | | | | |
| Munoz, Michael | please clean-out lint tank for custodial washing machine. the offices and warehouse smell like sewer. | | | | | | | | |
| <u>Alfredo Holguin</u> | | | | | | | | | |
| 97103 | Maintenance | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 9:58:53 AM | | | | | |
| Ronquillo, Ruben | PURCHASE NEW TIRES FOR JLG1935 SCISSOR LIFT, AND INSTALL | | | | | | | | |
| <u>Ruben Ronquillo</u> | | | | | | | | | |
| 97160 | Maintenance | | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | 1/11/2013 1:07:27 PM | | | | | |
| Ronquillo, Ruben | ORDER 50EA. GUN FREE/DRUG FREE SIGNS 20EA NO TRESPASSING SIGNS FOR STOCK | | | | | | | | |
| <u>Ruben Ronquillo</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|---|-------------------------------|--------------|---|-----------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | Description | | Action Taken | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Physical Plant Complex | | | | | | | |
| 95804 | Maintenance | | | | 11/26/2012 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | | 11/26/2012 4:17:27 PM | | | | |
| Carrasco, Danny | REPAIR DIESEL TANK ON TRUCK#32,PUMP IS NOT OPERATING. | | | | | | | | |
| Danny Carrasco | | | | | | | | | |
| Count: 40 Work Orders | | Avg. Age of WO's 63 | | Total for Physical Plant Complex | | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|--|---------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Riverside ES | | | | | | | |
| 90107 | | | | | 7/24/2012 | | 174 | | \$0.00 |
| Medium | Work In Progress | | | 7/24/2012 11:06:46 AM | | | | | |
| Estrada, Jesus | NEED TO REPLACE CARPET TO VCT IN BACK STORAGE OFFICE AREA. SEE RAUL ROMOER (HC). | | | | | | | | |
| Jesus Estrada | | | | | | | | | |
| 91368 | | | | | 8/15/2012 | | 152 | | \$0.00 |
| Medium | Work In Progress | | | 8/15/2012 1:04:21 PM | | | | | |
| Gonzalez, Salvador | fence south side of school needs repair someone cut it open and put it down need to be replaced new | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 92811 | | | | | 9/13/2012 | | 123 | | \$0.00 |
| Medium | Work In Progress | | | 9/13/2012 3:22:20 PM | | | | | |
| Gonzalez, Salvador | fence need to be repaired on south side of school, tubing are broken hardware is missing | | | | | | | | |
| Fernando Moncayo | | | | | | | | | |
| 92813 | | | | | 9/13/2012 | | 123 | | \$0.00 |
| Medium | Work In Progress | | | 9/13/2012 3:24:42 PM | | | | | |
| Carrasco, Danny | need fuel for lawn mower t-rs-0523 | | | | | | | | |
| Fernando Moncayo | | | | | | | | | |
| 93203 | | | | | 9/25/2012 | | 111 | | \$0.00 |
| Medium | Work In Progress | | | 9/25/2012 7:35:15 AM | | | | | |
| Munoz, Michael | need to install new fence w/ gates where mobil home occupant used to be. security for tractors and morgan. | | | | | | | | |
| Alfredo Holguin | | | | | | | | | |
| 93681 | | | | | 9/30/2012 | 10/21/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:50 AM | | | | | |
| Orozco, Daniel | Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96800 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:52 AM | | | | | |
| Moncayo, Fernando | Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96078 | | | | | 12/2/2012 | 12/8/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:22:58 AM | | | | | |
| Moncayo, Fernando | Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|---|---------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Riverside ES | | | | | | | |
| 92671 | Main Building | Parking Lot | | | 9/11/2012 | | 125 | | \$0.00 |
| Medium | Work In Progress | | | 9/11/2012 11:07:54 AM | | | | | |
| Moncayo, Fernando | Paint back parking lot with the assigned titles for Administration office/cafeteria, handicapped parkings, ect. | | | | | | | | |
| <u>Olga Arias</u> | | | | | | | | | |
| 91078 | New Wing 1/02 | | | | 8/9/2012 | | 158 | | \$0.00 |
| Medium | Work In Progress | | | 8/9/2012 3:29:12 PM | | | | | |
| Villalobos, David | need to replace toilet room 117 broken | | | | | | | | |
| <u>Carlos Hernandez</u> | | | | | | | | | |
| 96409 | | | | | 12/9/2012 | 12/25/2012 | 36 | | \$0.00 |
| Medium | Work In Progress | | | 12/9/2012 12:16:24 AM | | | | | |
| Moncayo, Fernando | Monthly - Riverside ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97201 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:01 AM | | | | | |
| Moncayo, Fernando | Monthly - Riverside ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93079 | | | | | 9/20/2012 | | 116 | | \$0.00 |
| Medium | Work In Progress | | | 9/20/2012 3:18:07 PM | | | | | |
| Ronquillo, Ruben | need a plastic dome (bubble) for recreation creations (301701) equipment. please | | | | | | | | |
| <u>Fernando Moncayo</u> | | | | | | | | | |
| 93082 | | | | | 9/20/2012 | | 116 | | \$0.00 |
| Medium | Work In Progress | | | 9/20/2012 3:22:08 PM | | | | | |
| Gonzalez, Salvador | need to make a metal box (plumbing protection) for outside drinking fountains, plywood won't stop vandals | | | | | | | | |
| <u>Fernando Moncayo</u> | | | | | | | | | |
| 97057 | | | | | 1/9/2013 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | 1/9/2013 12:26:08 PM | | | | | |
| Orozco, Daniel | LIGHT ON DISHWASHER IS OUT. SNP MANAGER EMILIA C. 589.2550 | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 97058 | | | | | 1/9/2013 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | 1/9/2013 12:27:17 PM | | | | | |
| Orozco, Daniel | OVEN ON STOVE IS NOT HEATING. SNP MANAGER EMILIA C. 589.2550 | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|---------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Riverside ES | | | | | | | |
| 96802 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:53 AM | | | | | |
| Moncayo, Fernando | Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96799 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:52 AM | | | | | |
| Moncayo, Fernando | Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95579 | | | | | 11/15/2012 | | 60 | | \$0.00 |
| Scheduled | Work In Progress | | | 11/15/2012 10:48:21 | | | | | |
| Moncayo, Fernando | Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You | | | | | | | | |
| 93729 | | | | | 10/1/2012 | | 105 | | \$0.00 |
| Medium | Work In Progress | | | 10/1/2012 3:14:30 PM | | | | | |
| Moncayo, Fernando | cleaned and serviced heating equipment | | | | | | | | |
| <u>Fernando Moncayo</u> | | | | | | | | | |
| 96081 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:00 AM | | | | | |
| Moncayo, Fernando | Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96080 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:22:59 AM | | | | | |
| Moncayo, Fernando | Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96479 | | | | | 12/11/2012 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | 12/11/2012 2:05:01 PM | | | | | |
| Moncayo, Fernando | need a ignition module for roof top heater in rm 107, and a heating thermostat for room 114 Thanks!! | | | | | | | | |
| <u>Fernando Moncayo</u> | | | | | | | | | |
| 96430 | | | | | 12/10/2012 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | 12/10/2012 11:28:55 | | | | | |
| Moncayo, Fernando | class room 116 needs a new heating thermostat | | | | | | | | |
| <u>Fernando Moncayo</u> | | | | | | | | | |
| 1/14/2013 11:04:43 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|--|-------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Riverside ES | | | | | | | | | |
| 97111 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 11:50:47 AM | | | | | |
| Ambriz, Juan | Asp walk-thru on 1/7/13 West Electrical Room is being used as storage blocking panels - code violation. | | | | | | | | |
| Carlos Castillo | | | | | | | | | |
| 94081 | | | | | 10/12/2012 | | 94 | | \$0.00 |
| Medium | Work In Progress | | | 10/12/2012 7:33:49 AM | | | | | |
| Ontiveros, Guadalupe | a new fence will be placed where mobile occupant was at. as per our meeting at site please level area and remove trees that were identified. thank you | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 97222 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:11 AM | | | | | |
| Romero, Raul | Monthly - QRTLY BLDG INSP REPORT (RS) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96801 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:53 AM | | | | | |
| Moncayo, Fernando | Monthly - Riverside ES Roof Inpsection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 95930 | | | | | 11/29/2012 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | 11/29/2012 10:09:16 | | | | | |
| Moncayo, Fernando | roof top furnace (reznor) in room 141 blower motor burn out | | | | | | | | |
| Fernando Moncayo | | | | | | | | | |
| 93788 | | | | | 10/3/2012 | | 103 | | \$0.00 |
| Medium | Work In Progress | | | 10/3/2012 12:38:12 PM | | | | | |
| Ambriz, Jose | need covers for new a/c that were installed front and bottom covers 25 | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 94470 | | | | | 10/23/2012 | | 83 | | \$0.00 |
| Medium | Work In Progress | | | 10/23/2012 8:38:46 AM | | | | | |
| Villalobos, David | need round toilet seats for "kohler" one piece small toilet | | | | | | | | |
| Fernando Moncayo | | | | | | | | | |
| 89794 | | | | | 7/3/2012 | | 195 | | \$0.00 |
| Medium | Work In Progress | | | 7/12/2012 10:22:48 AM | | | | | |
| Villalobos, David | Outside water fountain vandalized. | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|--|---------------------|-------------------------|----------------------|-------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Riverside ES | | | | | | | |
| 90202 | | | | | 7/25/2012 | | 173 | | \$0.00 |
| Medium | Work In Progress | | | 7/25/2012 3:44:33 PM | | | | | |
| Villalobos, David | need new toilet in outside teacher bathroom upper wing | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 96757 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:34 AM | | | | | |
| Villalobos, David | Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 89669 | | | | | 7/9/2012 | | 189 | | \$0.00 |
| Medium | Work In Progress | | | 7/9/2012 4:06:07 PM | | | | | |
| Castillo, Carlos | need tp replace two outside light fixtures torn off in patio area case # sppd201201011 | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 90853 | | | | | 8/6/2012 | | 161 | | \$0.00 |
| Medium | Work In Progress | | | 8/6/2012 2:19:16 PM | | | | | |
| Castillo, Carlos | need to replace 4 perimeter lights in patio areas that were broken due to vandalism case # sppd 20120-1174 | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 97235 | | | | | 1/14/2013 | | 0 | | \$0.00 |
| Medium | Work In Progress | | | 1/14/2013 8:30:09 AM | | | | | |
| Ambriz, Jose | Having problems with heating system in room 105 | | | | | | | | |
| Olga Arias | | | | | | | | | |
| 97237 | | | | | 1/14/2013 | | 0 | | \$0.00 |
| Medium | Work In Progress | | | 1/14/2013 8:33:56 AM | | | | | |
| Ambriz, Jose | Check heating system in office area. | | | | | | | | |
| Olga Arias | | | | | | | | | |
| 97239 | | | | | 1/14/2013 | | 0 | | \$0.00 |
| Medium | Work In Progress | | | 1/14/2013 8:44:05 AM | | | | | |
| Ambriz, Jose | Heating problems in room 121 in the new wing | | | | | | | | |
| Olga Arias | | | | | | | | | |
| Count: 39 Work Orders | | | Avg. Age of WO's | 72 | Total for Riverside ES | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------------------|------------------|---|-------------------------|----------|----------------------|--------------------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: San Miguel ES | | | | | | | | | |
| 96761 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:23:36 AM | | | | |
| Villalobos, David | | Yearly - San Miguel ES Backflow Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97091 | | Cafeteria | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 1/10/2013 7:52:58 AM | | | | |
| Ontiveros, Joe | | water line busted in the custodial room behind cafeteria. please repair and insulate all lines to prevent this from happening again. thank you | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 97090 | | Cafeteria | | | 1/10/2013 | | 4 | | \$0.00 |
| High | Work In Progress | | | | 1/10/2013 7:50:00 AM | | | | |
| Vega, Danny | | as per our conversation please remove tiles that are lifting, put on heat and blowers. please monitor and locate blowers as needed. also please clean out custodial closet and place blowers as well. thank you | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 96876 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:24:31 AM | | | | |
| Sanchez, Raul | | Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| Count: 4 Work Orders | | | Avg. Age of WO's | 6 | | Total for San Miguel ES | 0 | | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|---|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa ES | | | | | | | |
| 97210 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:05 AM | | | | | |
| Ambriz, Juan | Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96411 | | | | | 12/9/2012 | 12/25/2012 | 36 | | \$0.00 |
| Medium | Work In Progress | | | 12/9/2012 12:16:26 AM | | | | | |
| Ambriz, Juan | Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96920 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 9:43:24 AM | | | | | |
| Orozco, Daniel | WALK IN FREEZER AT 40 DEGREES.SNP MANAGER MARINA R. 589.3439. | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 95724 | | Restroom (Boys) | | | 11/20/2012 | | 55 | | \$0.00 |
| Medium | Work In Progress | CASA AZUL | | 11/20/2012 3:14:15 PM | | | | | |
| Marquez, Gerardo | OUR NEW HAND DRYER IS NOT WORKING PROPERLY. IT WAS TURNING ON AND STAYING ON BY ITSELF. IT WAS TURNED OFF COMPLETELY. PLEASE CHECK. THANKS. | | | | | | | | |
| <u>Rita Mendez</u> | | | | | | | | | |
| 96824 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:04 AM | | | | | |
| Ambriz, Juan | Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96831 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:08 AM | | | | | |
| Ambriz, Juan | Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95285 | | | | | 11/7/2012 | | 68 | | \$0.00 |
| Medium | Work In Progress | | | 11/7/2012 3:40:10 PM | | | | | |
| Ambriz, Juan | need to replace filters in all heating and cooling units | | | | | | | | |
| <u>Juan Ambriz</u> | | | | | | | | | |
| 96825 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:05 AM | | | | | |
| Ambriz, Juan | Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 1/14/2013 11:04:43 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|------------------------|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa ES | | | | | | | |
| 95581 | | | | | 11/15/2012 | | 60 | | \$0.00 |
| Scheduled | Work In Progress | | | | 11/15/2012 10:49:42 | | | | |
| Ambriz, Juan | Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You | | | | | | | | |
| 96102 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 12/2/2012 12:23:08 AM | | | | |
| Ambriz, Juan | Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96099 | | | | | 12/2/2012 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 12/2/2012 12:23:07 AM | | | | |
| Ambriz, Juan | Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96100 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 12/2/2012 12:23:07 AM | | | | |
| Ambriz, Juan | Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96776 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:23:42 AM | | | | |
| Villalobos, David | Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96101 | | | | | 12/2/2012 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 12/2/2012 12:23:08 AM | | | | |
| Ambriz, Juan | Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96444 | | Restroom (Boys) | | | 12/10/2012 | | 35 | | \$0.00 |
| Medium | Work In Progress | 100 hall boys | | | 12/10/2012 3:07:41 PM | | | | |
| Castillo, Carlos | Need to replace hand dryer not working properly | | | | | | | | |
| <u>Juan Ambriz</u> | | | | | | | | | |
| 93845 | | | | | 10/7/2012 | 10/23/2012 | 99 | | \$0.00 |
| Medium | Work In Progress | | | | 10/7/2012 12:16:24 AM | | | | |
| Diaz, Pablo | Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 1/14/2013 11:04:44 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|---|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa ES | | | | | | | |
| 97216 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:08 AM | | | | | |
| Diaz, Pablo | Monthly - QRTL Y BLDG INSP REPORT (STE) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96828 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:07 AM | | | | | |
| Ambriz, Juan | Monthly - Santa Teresa ES Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 94165 | | Athletic Field | | | 10/15/2012 | | 91 | | \$0.00 |
| Medium | Work In Progress | BACK FIELD | | 10/15/2012 3:28:57 PM | | | | | |
| Ontiveros, Guadalupe | PLEASE FILL OUT ALL HOLES WITH DIRT IN THE BACK FIELDS. THANKS. | | | | | | | | |
| <u>Rita Mendez</u> | | | | | | | | | |
| 96473 | Main Building | Cafeteria | | | 12/11/2012 | | 34 | | \$0.00 |
| Medium | Work In Progress | CAFETERIA | | 12/11/2012 11:24:42 | | | | | |
| Castillo, Carlos | A NEW LIGHT FIXTURE IS NEEDED IN THE CAFETERIA. THE OTHER WAS BROKEN AND HAD TO BE REMOVED. THANKS. | | | | | | | | |
| <u>Rita Mendez</u> | | | | | | | | | |
| 96474 | Main Building | Cafeteria | | | 12/11/2012 | | 34 | | \$0.00 |
| Medium | Work In Progress | CAFETERIA | | 12/11/2012 11:27:48 | | | | | |
| Castillo, Carlos | THE LIGHTS IN THE CAFETERIA NEED TO BE CHECKED. NOT ALL OF THEM ARE WORKING. THANKS. | | | | | | | | |
| <u>Rita Mendez</u> | | | | | | | | | |
| 96581 | Main Building | Portables | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | Portable B | | 12/13/2012 10:57:58 | | | | | |
| Castillo, Carlos | Please replace 2 ceiling lights that are out in Portable B. | | | | | | | | |
| <u>Melynda Menchaca</u> | | | | | | | | | |
| 95324 | Main Building | Classroom | | | 11/8/2012 | | 67 | | \$0.00 |
| Medium | Work In Progress | 104 | | 11/8/2012 12:07:47 PM | | | | | |
| Castillo, Carlos | Light bulb went out in classroom. Please replace when you have a chance. | | | | | | | | |
| <u>Melynda Menchaca</u> | | | | | | | | | |
| 97232 | Main Building | Classroom | | | 1/14/2013 | | 0 | | \$0.00 |
| Medium | Work In Progress | room #101 | | 1/14/2013 8:07:10 AM | | | | | |
| Ambriz, Jose | Refrigerator in room #101 is not working properly | | | | | | | | |
| Juan Ambriz | | | | | | | | | |

1/14/2013 11:04:44 AM

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|--|----------------|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa ES | | | | | | | | | |
| 97097 | Main Building | Classroom | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | room #107 | | | 1/10/2013 8:26:07 AM | | | | |
| Ambriz, Jose | Heating unit not working properly | | | | | | | | |
| Juan Ambriz | | | | | | | | | |
| 96700 | Main Building | Portables | | | 1/3/2013 | | 11 | | \$0.00 |
| Medium | Work In Progress | MS. | | | 1/3/2013 11:22:33 AM | | | | |
| Lara, Ralph | PLEASE INSTALL A LOCK ON MS. CASTANEDA'S DESK (MIDDLE DRAWER). THANKS. | | | | | | | | |
| Rita Mendez | | | | | | | | | |
| 94044 | Main Building | Football Field | | | 10/11/2012 | | 95 | | \$0.00 |
| Medium | Work In Progress | ALL SCHOOL | | | 10/11/2012 10:28:44 | | | | |
| Ambriz, Juan | THIS WORKORDER IS FOR ALL SCHOOL GROUNDS. WE HAVE A COYOTE THAT KEEPS HANGING OUT AT OUR SCHOOL GROUNDS. (ANIMAL CONTROL HAS BEEN CALLED), PLEASE CHECK OUT ALL POSSIBLE ENTRANCES AND OBSTRUCT AS NEEDED. THANKS. | | | | | | | | |
| Rita Mendez | | | | | | | | | |
| 94161 | Main Building | Portables | | | 10/15/2012 | | 91 | | \$0.00 |
| Medium | Work In Progress | PORTABLE A. | | | 10/15/2012 2:43:09 PM | | | | |
| Ambriz, Juan | WE NEED MINI BLINDS IN PORTABLE A (CASTANEDAS PORTABLE). THANKS. | | | | | | | | |
| Rita Mendez | | | | | | | | | |
| 91681 | Main Building | Portables | | | 8/22/2012 | | 145 | | \$0.00 |
| Medium | Work In Progress | BILINGUAL | | | 8/22/2012 10:10:45 AM | | | | |
| Ambriz, Juan | WE NEED MINI BLINDS IN BILINGUAL PORTABLE. ALSO IN MS. BARRAZA'S (VICE PRINCIPAL) OFFICE. PLEASE SEE RITA ON THIS. THANKS. | | | | | | | | |
| Rita Mendez | | | | | | | | | |
| 92408 | Main Building | Portables | | | 9/5/2012 | | 131 | | \$0.00 |
| Medium | Work In Progress | FIRST | | | 9/5/2012 9:52:41 AM | | | | |
| Ambriz, Juan | PLEASE SET UP HOOKS FOR COATS AND BACKPACKS IN BILINGUAL PORTABLE. THANKS. | | | | | | | | |
| Rita Mendez | | | | | | | | | |
| 94637 | Main Building | Classroom | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | Restroom #102 | | | 10/26/2012 11:02:57 | | | | |
| Ambriz, Juan | Need to replace broken faucet | | | | | | | | |
| Juan Ambriz | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|---|------------------------|-------------------------|-------------------|----------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa ES | | | | | | | |
| 92400 | Main Building | Classroom | | | 9/5/2012 | | 131 | | \$0.00 |
| Medium | Work In Progress | ROOM 210 | | | 9/5/2012 7:52:04 AM | | | | |
| Ambriz, Juan | OVERHEAD SCREEN HAS FALLEN IN ROOM 210. PLEASE HANG UP AGAIN. THANKS. | | | | | | | | |
| <u>Rita Mendez</u> | | | | | | | | | |
| 94449 | Main Building | Restroom (Girls) | | | 10/22/2012 | | 84 | | \$0.00 |
| Medium | Work In Progress | Room #201 | | | 10/22/2012 3:29:04 PM | | | | |
| Ambriz, Juan | Need to replace cover to toilet tank in room 201 | | | | | | | | |
| <u>Juan Ambriz</u> | | | | | | | | | |
| 96935 | Main Building | Office | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | Main Office | | | 1/7/2013 12:59:13 PM | | | | |
| Lara, Ralph | Please rekey Key Cabinet in vault. Please speak to Melynda in office prior to beginning. | | | | | | | | |
| <u>Melynda Menchaca</u> | | | | | | | | | |
| 96103 | | | | | 12/2/2012 | 12/8/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 12/2/2012 12:23:09 AM | | | | |
| Ambriz, Juan | Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96826 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:24:05 AM | | | | |
| Ambriz, Juan | Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93682 | | | | | 9/30/2012 | 10/21/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | | 9/30/2012 12:31:51 AM | | | | |
| Orozco, Daniel | Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97108 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| High | Work In Progress | | | | 1/10/2013 11:33:49 AM | | | | |
| Ambriz, Jose | BCU has locked up, need Trane to reset program again. | | | | | | | | |
| <u>Jose Ambriz</u> | | | | | | | | | |
| 93012 | | Portables | | | 9/19/2012 | | 117 | | \$0.00 |
| Medium | Work In Progress | portable B | | | 9/19/2012 2:33:09 PM | | | | |
| Estrada, Jesus | Floor Tile in portable B is coming off needs to be replaced with tile or carpet. Tripping hazard for students and staff | | | | | | | | |
| <u>Juan Ambriz</u> | | | | | | | | | |
| Count: 39 Work Orders | | | Avg. Age of WO's | 48 | Total for Santa Teresa ES | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|--|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 96790 | | | | | 1/6/2013 | 1/27/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:48 AM | | | | | |
| Orozco, Daniel | Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95746 | | | | | 11/21/2012 | | 54 | | \$0.00 |
| Medium | Work In Progress | | | 11/21/2012 9:09:49 PM | | | | | |
| Estrada, Jesus | The carpet in the weight room needs repairing. It is coming and posing a unsafe setting. | | | | | | | | |
| <u>William Dickson</u> | | | | | | | | | |
| 96533 | | Classroom | | | 12/12/2012 | | 33 | | \$0.00 |
| Medium | Work In Progress | SCIENCE | | 12/12/2012 10:22:59 | | | | | |
| Marquez, Gerardo | 55 GAL. WORTH OF DISSECTING PIG PARTS NEED TO BE DISPOSED. NO PLACE TO STORE OVER HOLIDAY. PLEASE PICK UP ASAP. MRS. RODRIGUEZ SPOKE TO MR. CHAVE ABOUT THIS MATTER. | | | | | | | | |
| <u>Marylou Jimenez</u> | | | | | | | | | |
| 94657 | | Athletic Field | | | 10/26/2012 | | 80 | | \$0.00 |
| High | Work In Progress | | | 10/26/2012 2:57:54 PM | | | | | |
| Garcia, Jose | JD Tractor is leaking from front axle. | | | | | | | | |
| <u>Guadalupe Ontiveros</u> | | | | | | | | | |
| 94897 | | | | | 11/1/2012 | | 74 | | \$0.00 |
| Medium | Work In Progress | | | 11/1/2012 11:54:26 AM | | | | | |
| Munoz, Michael | GATES & FENCE @ VOCATIONAL BLDG. ARE VERY RAGGED LOOOKING. POSTS HAVE BEEN BENT. MESH HAS BEEN RUN INTO IN VARIOUS PLACES. PROBABLY NEEDS TO BE REPLACED. | | | | | | | | |
| <u>Gerardo Marquez</u> | | | | | | | | | |
| 93683 | | | | | 9/30/2012 | 10/21/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:51 AM | | | | | |
| Orozco, Daniel | Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96809 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:57 AM | | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------|--|------------------------|-------------|-----------------------|------------------|------------------|---|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 96226 | | | | | 12/4/2012 | | 41 | | \$0.00 |
| Medium | Work In Progress | | | 12/4/2012 10:18:50 AM | | | | | |
| Marquez, Gerardo | NEED TO REPLACE FIRE EXTINGUISHERS THAT HAVE BEEN DISCHARGED. | | | | | | | | |
| <u>Gerardo Marquez</u> | | | | | | | | | |
| 93667 | | | | | 9/30/2012 | 10/6/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:44 AM | | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96083 | | | | | 12/2/2012 | 12/8/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:00 AM | | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95088 | | | | | 11/4/2012 | 11/10/2012 | 71 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2012 12:19:37 AM | | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 94656 | | Athletic Field | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/26/2012 2:55:46 PM | | | | | |
| Ontiveros, Guadalupe | JD 997 Mower will not start. | | | | | | | | |
| <u>Guadalupe Ontiveros</u> | | | | | | | | | |
| 94523 | | | | | 10/24/2012 | | 82 | | \$0.00 |
| Medium | Work In Progress | | | 10/24/2012 9:52:53 AM | | | | | |
| Carbajal, Jimmy | vacuum cleaner #4088 doesn't turn on. | | | | | | ASP JIMMY, SCHEDULED TO PICK AND AND SERVICE ON 9/29/12 | | |
| <u>Jorge Perez</u> | | | | | | | | | |
| 94151 | | | | | 10/15/2012 | | 91 | | \$0.00 |
| Medium | Work In Progress | | | 10/15/2012 11:32:27 | | | | | |
| Lara, Ralph | The electeic stops that hold the doors open in the gym area needs extensive repair before some gets hurt. The holders are falling off the wall. | | | | | | | | |
| <u>William Dickson</u> | | | | | | | | | |
| 95999 | | | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2012 10:57:11 | | | | | |
| Lara, Ralph | Need to replace the band percussion storage with metal doors. It currently has wood doors and can easy be broken in to. He is receiving a lot of new equipment and will need for it to be secured. | | | | | | | | |
| <u>William Dickson</u> | | | | | | | | | |

1/14/2013 11:04:44 AM

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------|---|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 93402 | Main Building | Classroom | | | 9/28/2012 | | 108 | | \$0.00 |
| Medium | Work In Progress | | | 9/28/2012 2:23:27 PM | | | | | |
| Marquez, Gerardo | There was an announcement made by Mr. Gallegos in reference to some tables and chairs. We would like to get a few of them. We would like to get 4 rectangular and 4 round tables. | | | | | | | | |
| William Dickson | | | | | | | | | |
| 97230 | Main Building | Office | | | 1/14/2013 | | 0 | | \$0.00 |
| Medium | Work In Progress | MARYLOU | | 1/14/2013 7:56:03 AM | | | | | |
| Briones, Enrique | PLEASE DELIVER THE FOLLOWING TO: MARYLOU PO # 111206827 - 1 BOX (BALLS) STHS GIRLS BASKETBALL | | | | | | | | |
| Terry Alvarado | | | | | | | | | |
| 97231 | Main Building | Office | | | 1/14/2013 | | 0 | | \$0.00 |
| Medium | Work In Progress | MARYLOU | | 1/14/2013 7:58:21 AM | | | | | |
| Briones, Enrique | PLEASE DELIVER THE FOLLOWING TO: MARYLOU PO # 111206478 - 6 BOXES (TENNIS BALLS) - STHS TENNIS | | | | | | | | |
| Terry Alvarado | | | | | | | | | |
| 94756 | Vocational | Football Field | | | 10/30/2012 | | 76 | | \$0.00 |
| Medium | Work In Progress | | | 10/30/2012 8:52:33 AM | | | | | |
| Ontiveros, Guadalupe | We need a new fence for the softball field to be set up before the season starts. | | | | | | | | |
| William Dickson | | | | | | | | | |
| 95227 | Library | | | | 11/6/2012 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/6/2012 10:17:04 AM | | | | | |
| Lara, Ralph | The front door of the Library can not be locked properly. It may need to be replaced. They have tried to fix it on several occasions but no luck. Can we please replace so the Library will be secure. | | | | | | | | |
| William Dickson | | | | | | | | | |
| 95226 | Library | Hallway/Corridor | | | 11/6/2012 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/6/2012 10:12:45 AM | | | | | |
| Lara, Ralph | There is a open space in the Library that needs a drop down locking metal screen to keep equipment safe. There are two sections in the Library that are about 11 feet long. This was suppose to enclosed years ago but the job was never completed. | | | | | | | | |
| William Dickson | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------|--|------------------------|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 95225 | Library | Classroom | | | 11/6/2012 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | | 11/6/2012 9:54:33 AM | | | | |
| Estrada, Jesus | The library has carpet that has been there for about 12 years. It has stains, gum, and other ugly looking marks on it. Even after shampooing the carpet it doesn't change the look. We need to exchange that carpet for a new one since we have dignitaries come in quite often. | | | | | | | | |
| <u>William Dickson</u> | | | | | | | | | |
| 93362 | Library | Library | | | 9/27/2012 | | 109 | | \$0.00 |
| Medium | Work In Progress | LIBRARY | | | 9/27/2012 2:41:05 PM | | | | |
| Villalobos, David | ADULT RESTROOM - WATER IN TOILET RUNS CONSTANTLY. | | | | | | | | |
| <u>Marylou Jimenez</u> | | | | | | | | | |
| 94785 | Locker Room | | | | 10/30/2012 | | 76 | | \$0.00 |
| Medium | Work In Progress | | | | 10/30/2012 3:14:53 PM | | | | |
| Marquez, Gerardo | Need paint for the dugouts for both the boys and the girls. The players will paint both dugouts. | | | | | | | | |
| <u>William Dickson</u> | | | | | | | | | |
| 95747 | Locker Room | Classroom | | | 11/21/2012 | | 54 | | \$0.00 |
| Medium | Work In Progress | | | | 11/21/2012 9:12:57 PM | | | | |
| Munoz, Michael | The weight machine cables need repairing. They are off the pulley and are creating an unsafe environment. | | | | | | | | |
| <u>William Dickson</u> | | | | | | | | | |
| 94150 | | | | | 10/15/2012 | | 91 | | \$0.00 |
| Medium | Work In Progress | | | | 10/15/2012 10:14:42 | | | | |
| Lara, Ralph | Culinary Arts- Rework door key to proper working configuration. | | | | | | | | |
| <u>Jaime Mijarez</u> | | | | | | | | | |
| 96362 | | | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | | 12/7/2012 9:21:25 AM | | | | |
| Lara, Ralph | Culinary Arts Kitchen- Rework door key cores to proper working configuration. | | | | | | | | |
| <u>Jaime Mijarez</u> | | | | | | | | | |
| 96808 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:23:56 AM | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|---|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 96565 | | | | | 12/12/2012 | | 33 | | \$0.00 |
| Medium | Work In Progress | | | 12/12/2012 4:18:54 PM | | | | | |
| Perez, Jorge | AS PER SNP MANAGER, PLEASE CLEAN KITCHEN FLOORS JANUARY 3, 2012 IF POSSIBLE. THANK YOU. SNP MANAGER OLGA B. 589.5332 | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| 97208 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:04 AM | | | | | |
| Perez, Jorge | Monthly - QRTL BLDG INSP REPORT (STH) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95926 | | | | | 11/29/2012 | | 46 | | \$0.00 |
| Medium | Work In Progress | | | 11/29/2012 9:49:05 AM | | | | | |
| Garcia, Jose | WELDING SHOP TEACHER IS REQUESTING AN AUGER TO DIG HOLE FOR THE 2013 DREAMCATCHER THAT NEEDS TO BE INSTALLED BY PAST CLASS DREAMCATCHERS . THANKS. | | | | | | | | |
| <u>Gerardo Marquez</u> | | | | | | | | | |
| 90222 | | | | | 7/26/2012 | | 172 | | \$0.00 |
| Medium | Work In Progress | | | 7/26/2012 7:54:01 AM | | | | | |
| Ambriz, Jose | Room 513 with Mrs. Hope. Classroom airconditioner is old and has corrosion on one of the corners of the water pan. A/C will need to be changed out. Check with Jaime or Art. | | | | | | | | |
| <u>Jaime Mijarez</u> | | | | | | | | | |
| 93818 | | | | | 10/7/2012 | 10/23/2012 | 99 | | \$0.00 |
| Medium | Work In Progress | | | 10/7/2012 12:16:12 AM | | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96169 | | | | | 12/3/2012 | | 42 | | \$0.00 |
| Medium | Work In Progress | | | 12/3/2012 9:26:07 AM | | | | | |
| Ambriz, Jose | Mr.Ukestad wood shop teacher would like electrical wood machinery connected to saw dust exhaust collector. Joe will have to order and install the exhaust vent piping and other parts needed. | | | | | | | | |
| <u>Jaime Mijarez</u> | | | | | | | | | |
| 95912 | | | | | 11/28/2012 | | 47 | | \$0.00 |
| Medium | Work In Progress | | | 11/28/2012 4:05:58 PM | | | | | |
| Ambriz, Jose | HEATERS TO 700 WING NOT WORKING. NEED TO BE CHECKED OUT BY TECH ASAP. THANKS. | | | | | | | | |
| <u>Gerardo Marquez</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|---|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 96355 | | | | | 12/7/2012 | | 38 | | \$0.00 |
| Medium | Work In Progress | | | 12/7/2012 8:38:18 AM | | | | | |
| Ambriz, Jose | Classroom 207 need to replace the thermostat existing thermostat is giving false reading and fan coil unit is staying in heat mode. | | | | | | | | |
| <u>Jaime Mijarez</u> | | | | | | | | | |
| 96017 | | Athletic Field | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2012 3:25:22 PM | | | | | |
| Castillo, Carlos | power will be needed for new scoreboards, baseball/softball please contact lynco for quote. thank you | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 93008 | | | | | 9/19/2012 | | 117 | | \$0.00 |
| High | Work In Progress | | | 9/19/2012 1:23:35 PM | | | | | |
| Mijarez, Jaime | gnats are back, please check above ceiling tiles, ducting in ms. panthers classroom and surrounding classrooms for any signs of population. thank you | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 93291 | | Football Field | | | 9/26/2012 | | 110 | | \$0.00 |
| Medium | Work In Progress | | | 9/26/2012 3:02:39 PM | | | | | |
| Castillo, Carlos | Need permanent electrical set-up or better and safer temporary for half-time music. | | | | | | | | |
| <u>Carlos Castillo</u> | | | | | | | | | |
| 92161 | | Parking Lot | | | 8/31/2012 | | 136 | | \$0.00 |
| Medium | Work In Progress | MR. | | 8/31/2012 1:15:00 PM | | | | | |
| Marquez, Gerardo | PAINT THE 45, 35, 25 YARD LINE ON THE PARKING LOT. BAND NEEDS IT FOR AFTER SCHOOL REHEARSAL. ANYWAY IF IT COULD BE DONE ASAP. | | | | | | | | |
| <u>Marylou Jimenez</u> | | | | | | | | | |
| 96774 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:41 AM | | | | | |
| Villalobos, David | Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93984 | | | | | 10/10/2012 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2012 9:16:18 AM | | | | | |
| Villalobos, David | URINAL IN BOYS RRM. CONTINUES TO LEAK UNDERNEATH @ WALL. NEEDS TO BE CHECKED OUT BY PLUMBER. THANKS. | | | | | | | | |
| Gerardo Marquez | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 93711 | | | | | 10/1/2012 | | 105 | | \$0.00 |
| Medium | Work In Progress | | | 10/1/2012 12:03:32 PM | | | | | |
| Villalobos, David | Restrooms in the main hallway Boy and girls need to adjust or replace toilet seats as well as the restroom in the 300 hallway those need to be replaced. | | | | | | | | |
| <u>Jorge Perez</u> | | | | | | | | | |
| 92273 | | | | | 9/2/2012 | | 134 | | \$0.00 |
| Medium | Work In Progress | | | 9/2/2012 12:21:46 AM | | | | | |
| Munoz, Michael | Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96084 | | | | | 12/2/2012 | 12/5/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:01 AM | | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95090 | | | | | 11/4/2012 | 11/7/2012 | 71 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2012 12:19:38 AM | | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96806 | | | | | 1/6/2013 | 1/9/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:55 AM | | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 92205 | | | | | 9/2/2012 | 9/5/2012 | 134 | | \$0.00 |
| Medium | Work In Progress | | | 9/2/2012 12:21:20 AM | | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93789 | | | | | 10/3/2012 | | 103 | | \$0.00 |
| Medium | Work In Progress | | | 10/3/2012 12:40:25 PM | | | | | |
| Villalobos, David | boys and girls restroom in the 300 hallway need new toilet seats as well as the girls restrooms in the main hallway. | | | | | | | | |
| <u>Jorge Perez</u> | | | | | | | | | |
| 92523 | | | | | 9/7/2012 | | 129 | | \$0.00 |
| Medium | Work In Progress | | | 9/7/2012 11:28:42 AM | | | | | |
| Villalobos, David | Coach Dotson and Coach Bennet gym area showers have no water. Please check with Gerry. | | | | | | | | |
| <u>Jaime Mijarez</u> | | | | | | | | | |
| 1/14/2013 11:04:44 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 96823 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:04 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96821 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:03 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96822 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:03 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93586 | | | | | 9/30/2012 | 10/8/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:09 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93587 | | | | | 9/30/2012 | 10/8/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:09 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93588 | | | | | 9/30/2012 | 10/31/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:31:09 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96311 | | | | | 12/6/2012 | | 39 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2012 8:46:00 AM | | | | | |
| Mijarez, Jaime | Need to install power vent to Laser Machine. | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 96096 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:06 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 96097 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:06 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96098 | | | | | 12/2/2012 | 1/2/2013 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:06 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 91802 | | | | | 8/24/2012 | | 143 | | \$0.00 |
| Medium | Work In Progress | | | 8/24/2012 7:27:50 AM | | | | | |
| Mijarez, Jaime | Water fountain located at the end of the 300 hallways is not working. And the water fountain in the back hall way that connects to the 300 is just stays running when power cord is connected. | | | | | | | | |
| <u>Jorge Perez</u> | | | | | | | | | |
| 90782 | | | | | 8/5/2012 | 9/5/2012 | 162 | | \$0.00 |
| Medium | Work In Progress | | | 8/5/2012 12:18:06 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 92249 | | | | | 9/2/2012 | 9/10/2012 | 134 | | \$0.00 |
| Medium | Work In Progress | | | 9/2/2012 12:21:37 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 90185 | | | | | 7/25/2012 | | 173 | | \$0.00 |
| Medium | Work In Progress | | | 7/25/2012 1:25:35 PM | | | | | |
| Mijarez, Jaime | need to install vent motor to laser machine when it comes in. thank you | | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| 90765 | | | | | 8/5/2012 | 8/13/2012 | 162 | | \$0.00 |
| Medium | Work In Progress | | | 8/5/2012 12:18:00 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 90764 | | | | | 8/5/2012 | 8/13/2012 | 162 | | \$0.00 |
| Medium | Work In Progress | | | 8/5/2012 12:17:59 AM | | | | | |
| Mijarez, Jaime | Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 1/14/2013 11:04:44 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 96807 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:56 AM | | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 92204 | | | | | 9/2/2012 | | 134 | | \$0.00 |
| Medium | Work In Progress | | | 9/2/2012 12:21:19 AM | | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93178 | | Classroom | | | 9/24/2012 | | 112 | | \$0.00 |
| Medium | Work In Progress | VARIETY OF | | 9/24/2012 2:38:32 PM | | | | | |
| Marquez, Gerardo | SEVERAL ROOM NEED BRACKETS TO BE MOUNTED ON WALL FOR CLASSROOM FLAGS: MR. RINCON ROOM #801 2 BRACKETS MR. FELIX ROOM #505 2 BRACKETS MR. STOUT ROOM #509 2 BRACKETS RECEPTIONIST AREA NEEDS 2 BRACKETS MR. BAILEY ROOM #406 NEEDS 2 BRACKETS MR. CHAMPAGNE WELDING PORTABLE NEEDS 2 BRACKETS ROOM #301 NEEDS 2 BRACKETS | | | | | | | | |
| <u>Marylou Jimenez</u> | | | | | | | | | |
| 91609 | | | | | 8/21/2012 | | 146 | | \$0.00 |
| Medium | Work In Progress | | | 8/21/2012 9:55:17 AM | | | | | |
| Marquez, Gerardo | NEED TO REPLACE WINDOW BLINDS IN 300 WING. | | | | | | | | |
| <u>Gerardo Marquez</u> | | | | | | | | | |
| 91619 | | | | | 8/21/2012 | | 146 | | \$0.00 |
| Medium | Work In Progress | MARY | | 8/21/2012 12:09:36 PM | | | | | |
| Marquez, Gerardo | NEED TO HAVE 2 SECURITY MIRRORS HUNG IN BACK OF LIBRARY. | | | | | | | | |
| <u>Marylou Jimenez</u> | | | | | | | | | |
| 94027 | | | | | 10/10/2012 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2012 3:48:42 PM | | | | | |
| Marquez, Gerardo | AS PER RICHARD CHAVEZ. GREASE NEEDS TO BE APPLIED TO VERTICAL CONDUITS WHERE VANDALS MAY ACCESS THE ROOF. | | | | | | | | |
| <u>Gerardo Marquez</u> | | | | | | | | | |
| 95089 | | | | | 11/4/2012 | | 71 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2012 12:19:38 AM | | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

1/14/2013 11:04:44 AM

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|------------------------|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 92398 | | | | | 9/5/2012 | | 131 | | \$0.00 |
| Medium | Work In Progress | | | | 9/5/2012 7:39:21 AM | | | | |
| Marquez, Gerardo | 3 urinals in the outside concession stand are leaking water when flushed. | | | | | | | | |
| <u>Jorge Perez</u> | | | | | | | | | |
| 92657 | | | | | 9/11/2012 | | 125 | | \$0.00 |
| Medium | Work In Progress | | | | 9/11/2012 8:11:10 AM | | | | |
| Marquez, Gerardo | need to replace 2 ceiling tiles in the main lobby. as well in room 403. No ceiling tiles are in place due to the rain over the weekend. | | | | | | | | |
| <u>Jorge Perez</u> | | | | | | | | | |
| 94761 | | | | | 10/30/2012 | | 76 | | \$0.00 |
| Medium | Work In Progress | WARRIOR | | | 10/30/2012 11:17:32 | | | | |
| Marquez, Gerardo | MOUNT 3 BULLETIN BOARDS IN WARRIOR ROOM. | | | | | | | | |
| <u>Marylou Jimenez</u> | | | | | | | | | |
| 96085 | | | | | 12/2/2012 | | 43 | | \$0.00 |
| Medium | Work In Progress | | | | 12/2/2012 12:23:01 AM | | | | |
| Marquez, Gerardo | Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96225 | | | | | 12/4/2012 | | 41 | | \$0.00 |
| Medium | Work In Progress | | | | 12/4/2012 9:24:33 AM | | | | |
| Marquez, Gerardo | NEED TO REPLACE BURNT OUT LIGHT BULBS IN CUSTODIAL CLOSET 300 WING. | | | | | | | | |
| <u>Gerardo Marquez</u> | | | | | | | | | |
| 93404 | | Choral | | | 9/28/2012 | | 108 | | \$0.00 |
| Medium | Work In Progress | | | | 9/28/2012 2:31:45 PM | | | | |
| Flores, Pete | We are wanting to remodel the band truck but we need help inpreparing it to be remodeled. the paint is popping off the truck and it may need engine work. Will or can you help us. | | | | | | | | |
| <u>William Dickson</u> | | | | | | | | | |
| 93068 | | | | | 9/20/2012 | | 116 | | \$0.00 |
| Medium | Work In Progress | BAND TRUCK | | | 9/20/2012 11:19:31 AM | | | | |
| Flores, Pete | BAND TRUCK NEEDS MAINTENANCE-CHECK FOR ANY MECHANICAL PROBLEMS ETC. | | | | | | | | |
| <u>Marylou Jimenez</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|--|------------------------|----------------------------|-----------------------|------------------|------------------|----------------------------------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa HS | | | | | | | |
| 93073 | | | | | 9/20/2012 | | 116 | | \$0.00 |
| Medium | Work In Progress | | | 9/20/2012 12:56:13 PM | | | | | |
| Orozco, Daniel | SANIZER ON DISHWASHER NOT WORKING, AS PER ECO LAB IT HAS TO DO WITH THE WATER PRESSURE.SNP MANAGER OLGA B. 589.5332 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |
| 96027 | | Athletic Field | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2012 3:41:07 PM | | | | | |
| Gonzalez, Salvador | pleaase order material for new scoreboards. baseball / softball. thank you | | | | | | | | |
| Michael Munoz | | | | | | | | | |
| 92782 | | | | | 9/13/2012 | | 123 | | \$0.00 |
| Medium | Work In Progress | | | 9/13/2012 8:41:58 AM | | | | | |
| Gonzalez, Salvador | We need to have a chain welded or hooks welded to extend a chain that will keep people from driving onto side walk along tree line. Rafa Lara will be providing the chain and locks. Mr. Dickson would like to have this done before the game on Friday. Please check with me. | | | | | | | | |
| Jaime Mijarez | | | | | | | | | |
| 97001 | | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 9:18:30 AM | | | | | |
| Gonzalez, Salvador | Railling to exterior stairway going from athletic dressing rooms to concession stand was damaged. We had to remove it, might need to fabricate a new one or repair if possible. | | | | | | | | |
| Jaime Mijarez | | | | | | | | | |
| Count: 84 Work Orders | | | Avg. Age of WO's 77 | | | | Total for Santa Teresa HS | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|------------------|--|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa MS | | | | | | | |
| 91549 | | Classroom | | | 8/20/2012 | | 147 | | \$0.00 |
| Medium | Work In Progress | ROOM 1 | | 8/20/2012 12:21:59 PM | | | | | |
| Prospero, Manuel | | 1. PAPER TOWEL DISPENSER ABOVE SINKS 2. PLACE TILES ON BARE CONCRETE FLOOR. | | | | | | | |
| <u>Laura Parra</u> | | | | | | | | | |
| 96849 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:17 AM | | | | | |
| Prospero, Manuel | | Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96850 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:17 AM | | | | | |
| Prospero, Manuel | | Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 90780 | | | | | 8/5/2012 | | 162 | | \$0.00 |
| Medium | Work In Progress | | | 8/5/2012 12:18:06 AM | | | | | |
| Prospero, Manuel | | Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 90784 | | | | | 8/5/2012 | 8/13/2012 | 162 | | \$0.00 |
| Medium | Work In Progress | | | 8/5/2012 12:18:07 AM | | | | | |
| Prospero, Manuel | | Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 90785 | | | | | 8/5/2012 | 8/13/2012 | 162 | | \$0.00 |
| Medium | Work In Progress | | | 8/5/2012 12:18:07 AM | | | | | |
| Prospero, Manuel | | Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96006 | | | | | 11/30/2012 | | 45 | | \$0.00 |
| Medium | Work In Progress | | | 11/30/2012 2:34:29 PM | | | | | |
| Prospero, Manuel | | 11/30/12. 3HRS TROBLE SHUTER ON SOUTH BUILDING (NO COMUNICATION ON HEATERS). 3HRS TROBLE SHUTER ON FIRE ALARM (NO COMUNICATION SOUTH BUILDING.). 1HR PAPER WORK. | | | | | | | |
| Manuel Prospero | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa MS | | | | | | | |
| 96128 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:19 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 95127 | | | | | 11/4/2012 | 11/12/2012 | 71 | | \$0.00 |
| Medium | Work In Progress | | | 11/4/2012 12:19:53 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96127 | | | | | 12/2/2012 | 12/10/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:18 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96848 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:16 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96851 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:18 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96775 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:42 AM | | | | | |
| Villalobos, David | Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 90766 | | | | | 8/5/2012 | 9/5/2012 | 162 | | \$0.00 |
| Medium | Work In Progress | | | 8/5/2012 12:18:00 AM | | | | | |
| Prospero, Manuel | Yearly - Santa Teresa MS C-11(Evap.Down)(Yearly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96672 | | | | | 12/31/2012 | | 14 | | \$0.00 |
| Medium | Work In Progress | | | 12/31/2012 12:27:05 | | | | | |
| Mijarez, Jaime | Yearly - Santa Teresa MS H6(Roof Furnace)(Yearly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa MS | | | | | | | |
| 97203 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:02 AM | | | | | |
| Rodriguez, Ismael | Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93542 | | | | | 9/30/2012 | 10/8/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:30:48 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96852 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:18 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96126 | | | | | 12/2/2012 | 12/8/2012 | 43 | | \$0.00 |
| Medium | Work In Progress | | | 12/2/2012 12:23:18 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96853 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:19 AM | | | | | |
| Prospero, Manuel | Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 90174 | | | | | 7/25/2012 | | 173 | | \$0.00 |
| Medium | Work In Progress | | | 7/25/2012 11:23:39 AM | | | | | |
| Prospero, Manuel | WE NEED SOME GASOLINE POR CUSTODIAN TRUAK AN POLARIS. | | | | | | | | |
| <u>Manuel Prospero</u> | | | | | | | | | |
| 91347 | North Building | Parking Lot | | | 8/15/2012 | | 152 | | \$0.00 |
| Medium | Work In Progress | | | 8/15/2012 8:20:23 AM | | | | | |
| Gonzalez, Salvador | Sal, can you put 23/4inch pipe in the exit doors and weld a chain to secure this doors as per security each time theres wind they come loose see Mr.Rodriguez. | | | | | | | | |
| <u>Ismael Rodriguez</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|----------------------------------|--|------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: Santa Teresa MS | | | | | | | | | |
| 92934 | North Building | Gym | | | 9/18/2012 | | 118 | | \$0.00 |
| Medium | Work In Progress | | | 9/18/2012 1:07:55 PM | | | | | |
| Lara, Ralph | As per Mr.Montano Principal the door to the concession stand needs to be replace with a ventilated door it gets super hot inside the concession stand and trips the ice makerand fridge Mr.Lara is aware of this work order thanks.. | | | | | | | | |
| <u>Ismael Rodriguez</u> | | | | | | | | | |
| 95862 | North Building | Cafeteria | | | 11/28/2012 | | 47 | | \$0.00 |
| Medium | Work In Progress | GESSICA | | 11/28/2012 9:03:08 AM | | | | | |
| Lara, Ralph | DOOR GUARD NEEDED FOR MAINTENANCE ROOM- BUG PROBLEM COMING INTO THE KITCHEN. | | | | | | | | |
| <u>Laura Parra</u> | | | | | | | | | |
| 96312 | North Building | Custodial | | | 12/6/2012 | | 39 | | \$0.00 |
| Medium | Work In Progress | | | 12/6/2012 8:50:27 AM | | | | | |
| Carbajal, Jimmy | Royal vaccum #0027 needs service. | | | | | | | | |
| <u>Ismael Rodriguez</u> | | | | | | | | | |
| 90641 | North Building | Office | | | 8/3/2012 | | 164 | | \$0.00 |
| Medium | Work In Progress | REGISTAR | | 8/3/2012 8:33:52 AM | | | | | |
| Castillo, Carlos | NEED ELECTRICAL OUTLET IN RESTROOM-- AS PER MS LOVELACE'S REQUEST | | | | | | | | |
| <u>Laura Parra</u> | | | | | | | | | |
| 93976 | North Building | Hallway/Corridor | | | 10/10/2012 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2012 7:29:44 AM | | | | | |
| Castillo, Carlos | Replace electrical outlet where the water fountains connect in the north upper level wires expose thanks.. | | | | | | | | |
| <u>Ismael Rodriguez</u> | | | | | | | | | |
| 90913 | North Building | Restroom (Girls) | | | 8/7/2012 | | 160 | | \$0.00 |
| Medium | Work In Progress | | | 8/7/2012 8:41:12 AM | | | | | |
| Castillo, Carlos | Need a electrical outlet in private restroom in north office see Mr.Rodriguez. | | | | | | | | |
| <u>Ismael Rodriguez</u> | | | | | | | | | |
| 95495 | North Building | Gym | | | 11/14/2012 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | 11/14/2012 7:54:10 AM | | | | | |
| Villalobos, David | 5 Gallons of cherry mat for drains in the gym and 5 for north and south building thanks.. | | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------|--|------------------------|--------------------------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa MS | | | | | | | |
| 92943 | North Building | Mechanical | | | 9/18/2012 | | 118 | | \$0.00 |
| Medium | Work In Progress | | | | 9/18/2012 2:58:34 PM | | | | |
| Ambriz, Jose | 9/18/12. geo termal circulation pump is makin nose. | | | | | | | | |
| <u>Manuel Prospero</u> | | | | | | | | | |
| 89803 | North Building | Custodial | | | 7/12/2012 | | 186 | | \$0.00 |
| Medium | Work In Progress | | | | 7/12/2012 12:04:29 PM | | | | |
| Ambriz, Jose | Some water fountains are missing parts in southbuilding and one in north lower level needs replacement Mr.Prospero is aware of this problem. | | 10/9/12 - Routed to Jose - mkv | | | | | | |
| <u>Ismael Rodriguez</u> | | | | | | | | | |
| 90600 | North Building | Cafeteria | | | 8/2/2012 | | 165 | | \$0.00 |
| Medium | Work In Progress | | | | 8/2/2012 1:41:31 PM | | | | |
| Prospero, Manuel | KITCHEN A/C UNID NEED TO CHANGED CIRCULATION PUMP. IS NOT WORKING. | | | | | | | | |
| <u>Manuel Prospero</u> | | | | | | | | | |
| 91364 | North Building | Office | | | 8/15/2012 | | 152 | | \$0.00 |
| Medium | Work In Progress | RECEPTIONIST | | | 8/15/2012 11:34:06 AM | | | | |
| Prospero, Manuel | 1. REMOVE BLIND ATTACHEMENTS 2. PAINT WINDOW FRAMES BLACK 3. PAINT OFFICE | | | | | | | | |
| <u>Laura Parra</u> | | | | | | | | | |
| 97088 | North Building | Classroom | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 1/10/2013 7:39:54 AM | | | | |
| Prospero, Manuel | Replace light switch in Special ED Room #3. | | | | | | | | |
| <u>Ismael Rodriguez</u> | | | | | | | | | |
| 97089 | North Building | Office | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 1/10/2013 7:43:09 AM | | | | |
| Lara, Ralph | Replace core in custodial storage door not working thanks. | | | | | | | | |
| <u>Ismael Rodriguez</u> | | | | | | | | | |
| 97153 | North Building | Parking Lot | | | 1/11/2013 | | 3 | | \$0.00 |
| Medium | Work In Progress | | | | 1/11/2013 7:42:26 AM | | | | |
| Ontiveros, Guadalupe | Remove dirt with tracter dirt build up by portable ramps and also in North main entrance patio. | | | | | | | | |
| <u>Ismael Rodriguez</u> | | | | | | | | | |
| 91685 | South Building | Restroom (Boys) | | | 8/22/2012 | | 145 | | \$0.00 |
| Medium | Work In Progress | | | | 8/22/2012 10:58:29 AM | | | | |
| Prospero, Manuel | Broken water valve to flushvalve needs to be replaced | | | | | | | | |
| <u>Manuel Prospero</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|------------------|--|-------------|-------------------|----------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Santa Teresa MS | | | | | | | |
| 95704 | South Building | Stairway | | | 11/20/2012 | | 55 | | \$0.00 |
| Medium | Work In Progress | | | | 11/20/2012 12:34:22 | | | | |
| Castillo, Carlos | | The stairway in the South Building going up to the second floor the light is not working as per Manny theres a electrical problem we need the light for safety reasons. | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |
| 97029 | South Building | Library | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | | 1/8/2013 1:12:45 PM | | | | |
| Carrasco, Danny | | WE NEED LIFT TO FIX HEATERS ON LIBRERIA . | | | | | | | |
| Manuel Prospero | | | | | | | | | |
| 93323 | Gym (1997) | Gym | | | 9/27/2012 | | 109 | | \$0.00 |
| Medium | Work In Progress | | | | 9/27/2012 9:15:33 AM | | | | |
| Lara, Ralph | | Rafa the exit door behind the boys dressing room gym area is not handicapp accessabel for the student thats riding a wheel chair, he had a hard time opening the door is there any way you can install a push button door as per administration. | | | | | | | |
| Ismael Rodriguez | | | | | | | | | |
| Count: 40 Work Orders | | Avg. Age of WO's 79 | | | Total for Santa Teresa MS | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------|---|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Sunland Park ES | | | | | | | |
| 95758 | | | | | 11/26/2012 | | 49 | | \$0.00 |
| Medium | Work In Progress | | | 11/26/2012 9:30:41 AM | | | | | |
| Carrasco, Danny | Silver needs the small scissor lift any time this week. THANK YOU | | | | | | | | |
| Cora Ramirez | | | | | | | | | |
| 97121 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 3:08:18 PM | | | | | |
| Carrasco, Danny | need 15 gal gas for truck 191 | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 97122 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 3:10:25 PM | | | | | |
| Lara, Ralph | need to replace door closure in kitchen door (door slamming not adjustmet to door) | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 96743 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:27 AM | | | | | |
| Hernandez, Carlos | Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96742 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:27 AM | | | | | |
| Hernandez, Carlos | Monthly - Sunland Park ES Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97227 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:14 AM | | | | | |
| Castillo, Valeria | Monthly - QRTL Y BDLG INSP REPORT (SP) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96589 | | Parking Lot | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | | | 12/13/2012 1:31:50 PM | | | | | |
| Lara, Ralph | Need gate key for Sunland Park Elementary. There will be work there over the break. Need to check the key out to Justin Armendariz with C. D. General (575-635-7988). For more information contact Ralph Gallegos at 882-6921. Need key by December 14, 2012. Thanks. | | | | | | | | |
| Rafael Gallegos | | | | | | | | | |
| 97123 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 3:12:12 PM | | | | | |
| Ontiveros, Guadalupe | need new covers for irragation valves to soccer feild 10 were broken due to vandlism | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 1/14/2013 11:04:45 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|---|------------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Sunland Park ES | | | | | | | |
| 95335 | | | | | 11/8/2012 | | 67 | | \$0.00 |
| Medium | Work In Progress | | | 11/8/2012 3:02:53 PM | | | | | |
| Ambriz, Jose | need to replace heater in outside bathroom | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 94641 | | | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/26/2012 12:18:59 | | | | | |
| Ambriz, Jose | reznor heater in mechanical room next to cafe | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 97039 | | | | | 1/8/2013 | | 6 | | \$0.00 |
| Medium | Work In Progress | | | 1/8/2013 3:40:58 PM | | | | | |
| Ambriz, Jose | need new a/c unit 43 areo cool contractors replaced roof and unit was no good | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 95232 | | | | | 11/6/2012 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/6/2012 11:05:44 AM | | | | | |
| Castillo, Carlos | need to replace ballast music portable | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 95233 | | | | | 11/6/2012 | | 69 | | \$0.00 |
| Medium | Work In Progress | | | 11/6/2012 11:06:43 AM | | | | | |
| Castillo, Carlos | need to replace ballist room 38 | | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 96773 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:41 AM | | | | | |
| Villalobos, David | Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 93395 | | | | | 9/28/2012 | | 108 | | \$0.00 |
| Medium | Work In Progress | NURSE'S | | 9/28/2012 12:28:06 PM | | | | | |
| Villalobos, David | AS PER MS. DUQUE- TOILET IN THE NURSES OFFICE LEAKS WATER WHEN FLUSHED. THANK YOU. | | | | | | | | |
| David Avila | | | | | | | | | |
| 96590 | | | | | 12/13/2012 | | 32 | | \$0.00 |
| Medium | Work In Progress | CLASSROOM | | 12/13/2012 1:40:56 PM | | | | | |
| Villalobos, David | AS PER MS. HERRERA - TOILET LEAKING FROM FLUSHING KNOW AND EVERYTIME ONE FLUSHES EVERYTHING COMES BACK AND IT OVERFLOWS. PLEASE CHECK. THANK YOU. | | | | | | | | |
| David Avila | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|--------------------|------------------|--|-------------|-------------------|-----------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Sunland Park ES | | | | | | | |
| 96476 | | | | | 12/11/2012 | | 34 | | \$0.00 |
| Medium | Work In Progress | | | | 12/11/2012 12:11:39 | | | | |
| Villalobos, David | | need to reconnect gas to portable d for heater | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 95520 | | | | | 11/14/2012 | | 61 | | \$0.00 |
| Medium | Work In Progress | | | | 11/14/2012 2:13:33 PM | | | | |
| Villalobos, David | | need to check gas pressure on portable d | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 97120 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | | 1/10/2013 3:06:08 PM | | | | |
| Flores, Pete | | starter on truck 191 having trouble starter daraging | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 94495 | | | | | 10/23/2012 | | 83 | | \$0.00 |
| Medium | Work In Progress | | | | 10/23/2012 3:40:31 PM | | | | |
| Flores, Pete | | need new tires for 970 john deere tractor | | | | | | | |
| Carlos Hernandez | | | | | | | | | |
| 96744 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | | 1/6/2013 12:23:27 AM | | | | |
| Hernandez, Carlos | | Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 95583 | | | | | 11/15/2012 | | 60 | | \$0.00 |
| Scheduled | Work In Progress | | | | 11/15/2012 10:51:41 | | | | |
| Hernandez, Carlos | | Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You | | | | | | | |
| 97193 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | | 1/13/2013 12:15:56 AM | | | | |
| Hernandez, Carlos | | Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details. | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 94219 | | | | | 10/16/2012 | | 90 | | \$0.00 |
| Medium | Work In Progress | | | | 10/16/2012 3:34:26 PM | | | | |
| Carrasco, Danny | | need no parking signs for front circle | | | | | | | |
| Carlos Hernandez | | | | | | | | | |

1/14/2013 11:04:45 AM

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|------------------------------|---|------------------------|-------------------------|----------------------|----------------------------------|------------------|-----------|-------------|---------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Sunland Park ES | | | | | | | |
| 96745 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:28 AM | | | | | |
| Hernandez, Carlos | Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96922 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | CLASSROOM | | 1/7/2013 10:48:43 AM | | | | | |
| Hernandez, Carlos | AS PER MS. KENNON - PLEASE CHECK ONE OF THE TABLES IN MY ROOM, IT IS WOBBLING AND UNSTEADY. THANK YOU. | | | | | | | | |
| <u>David Avila</u> | | | | | | | | | |
| 96924 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | CLASSROOM | | 1/7/2013 10:50:56 AM | | | | | |
| Hernandez, Carlos | AS PER MS. DUQUE - PLEASE PUT UP 2 WHITEBOARDS IN THE CLASSROOM. ONE OVER CHALKBOARD AND ONE ON OPPOSITE WALL. PLEASE SEE MS. KENNON FOR INSTRUCTIONS. THANK YOU. | | | | | | | | |
| <u>David Avila</u> | | | | | | | | | |
| 96426 | | | | | 12/10/2012 | | 35 | | \$0.00 |
| Medium | Work In Progress | | | 12/10/2012 10:09:35 | | | | | |
| Orozco, Daniel | VEGETABLE SINK IS LEAKING. SNP MANAGER IGNACIA C. 589.2545 | | | | | | | | |
| <u>Maritza Gonzalez</u> | | | | | | | | | |
| Count: 28 Work Orders | | | Avg. Age of WO's | 34 | Total for Sunland Park ES | | | 0 | \$0.00 |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-----------------------|---|-------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Sunrise ES | | | | | | | |
| 96413 | | | | | 12/9/2012 | 12/25/2012 | 36 | | \$0.00 |
| Medium | Work In Progress | | | 12/9/2012 12:16:26 AM | | | | | |
| Vargas, Juan | Monthly - Sunrise ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 97212 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:06 AM | | | | | |
| Vargas, Juan | Monthly - Sunrise ES Playground Insp - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96846 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:15 AM | | | | | |
| Apodaca, Mario | Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 93708 | | | | | 10/1/2012 | | 105 | | \$0.00 |
| Medium | Work In Progress | | | 10/1/2012 9:01:28 AM | | | | | |
| Miranda, Danny | NEED TO REPLACE AIR FILTERS | | | | | | | | |
| Danny Miranda | | | | | | | | | |
| 95584 | | | | | 11/15/2012 | | 60 | | \$0.00 |
| Scheduled | Work In Progress | | | 11/15/2012 10:53:04 | | | | | |
| Vargas, Juan | Ms. Sherri with CLEARresult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You | | | | | | | | |
| 96837 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:11 AM | | | | | |
| Vargas, Juan | Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96835 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:10 AM | | | | | |
| Vargas, Juan | Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 96836 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:10 AM | | | | | |
| Vargas, Juan | Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| Margret Villalobos | | | | | | | | | |
| 1/14/2013 11:04:45 AM | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|---|-------------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Sunrise ES | | | | | | | |
| 97065 | | | | | 1/9/2013 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | 1/9/2013 2:48:30 PM | | | | | |
| Ontiveros, Joe | need replace map sink fouset in kitchen | | | | | | | | |
| <u>Juan Vargas</u> | | | | | | | | | |
| 96772 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:41 AM | | | | | |
| Villalobos, David | Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96958 | | | | | 1/7/2013 | | 7 | | \$0.00 |
| Medium | Work In Progress | | | 1/7/2013 3:26:01 PM | | | | | |
| Sotelo, Enrique | need help to fix electrcal trouble shooting in 100 a/c main circulator pump | | | | | | | | |
| <u>Juan Vargas</u> | | | | | | | | | |
| 95165 | | | | | 11/5/2012 | | 70 | | \$0.00 |
| Medium | Work In Progress | | | 11/5/2012 9:15:59 AM | | | | | |
| Sotelo, Enrique | cafeteria need fix lamps or replace | | | | | | | | |
| <u>Juan Vargas</u> | | | | | | | | | |
| 97116 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 1:56:28 PM | | | | | |
| Solis, Lorenzo | need help to replace a/c circulator pom and electrical wire in room 301 | | | | | | | | |
| <u>Juan Vargas</u> | | | | | | | | | |
| 93999 | | | | | 10/10/2012 | | 96 | | \$0.00 |
| Medium | Work In Progress | | | 10/10/2012 2:36:23 PM | | | | | |
| Vargas, Juan | need 10 gls oil paint to painting entry and portables doors | | | | | | | | |
| <u>Juan Vargas</u> | | | | | | | | | |
| 97217 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:16:09 AM | | | | | |
| Gallegos, Felipe | Monthly - QRTLY BLDG INSP REPORT (SR) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96833 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:24:09 AM | | | | | |
| Vargas, Juan | Monthly - Sunrise ES Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs | |
|------------------------------|---|----------------------------|-------------|-----------------------------|------------------|------------------|-----------|---------------|-------------|--|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | | |
| Assigned To | Description | | | | | | | | | |
| Requester Name | | | | | | | | | | |
| Location: | | Sunrise ES | | | | | | | | |
| 97126 | | | | | 1/10/2013 | | 4 | | \$0.00 | |
| Medium | Work In Progress | | | 1/10/2013 3:20:43 PM | | | | | | |
| Lozoya, Manny | room 207 209 and 301 need check back doors not closed | | | | | | | | | |
| <u>Juan Vargas</u> | | | | | | | | | | |
| 93686 | | | | | 9/30/2012 | 10/21/2012 | 106 | | \$0.00 | |
| Medium | Work In Progress | | | 9/30/2012 12:31:52 AM | | | | | | |
| Orozco, Daniel | Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details. | | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | | |
| 96834 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 | |
| Medium | Work In Progress | | | 1/6/2013 12:24:09 AM | | | | | | |
| Vargas, Juan | Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | | |
| 96427 | Main Building | Custodial | | | 12/10/2012 | | 35 | | \$0.00 | |
| Medium | Work In Progress | | | 12/10/2012 10:35:56 | | | | | | |
| Carbajal, Jimmy | Royal upright vacumme # 3436 cleaner does not stay erect at handle. Please repair. Thank you. | | | | | | | | | |
| <u>Felipe Gallegos</u> | | | | | | | | | | |
| Count: 20 Work Orders | | Avg. Age of WO's 29 | | Total for Sunrise ES | | | 0 | \$0.00 | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|---|----------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Vado ES | | | | | | | |
| 96750 | | | | | 1/6/2013 | 1/12/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:31 AM | | | | | |
| Miranda, Danny | Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96783 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:45 AM | | | | | |
| Orozco, Daniel | Monthly - Vado ES - Fire Sprinkler Insp. - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96749 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:30 AM | | | | | |
| Miranda, Danny | Monthly - Vado ES Roof Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97191 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | 1/13/2013 12:15:55 AM | | | | | |
| Diaz, Armando | Monthly - QRTLY BLDG INSP REPORT (VE) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97079 | | Office | | | 1/9/2013 | | 5 | | \$0.00 |
| Medium | Work In Progress | | | 1/9/2013 4:02:57 PM | | | | | |
| Lozoya, Manny | need doors from main lobby to corridors and cafeteria to have locks installed that can be operated from office area. Check with Alfredo Holguin if you have questions | | | | | | | | |
| <u>Alfredo Holguin</u> | | | | | | | | | |
| 93491 | | | | | 9/30/2012 | 10/21/2012 | 106 | | \$0.00 |
| Medium | Work In Progress | | | 9/30/2012 12:30:26 AM | | | | | |
| Orozco, Daniel | Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 97117 | | | | | 1/10/2013 | | 4 | | \$0.00 |
| Medium | Work In Progress | | | 1/10/2013 2:11:45 PM | | | | | |
| Solis, Lorenzo | need to ck room 105, and 106 rooms will not turn no | | | | | | | | |
| <u>Danny Miranda</u> | | | | | | | | | |
| 96755 | | | | | 1/6/2013 | 2/6/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:33 AM | | | | | |
| Villalobos, David | Yearly - Vado ES Backflow Inspection - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|---------------------------|--|----------------|-------------|-----------------------|------------------|------------------|-----------|-------------|-------------|
| Priority | Status | Area Number | Reason | Created Date/Time | Actual Comp Date | Action Taken | | | |
| Assigned To | Description | | | | | | | | |
| Requester Name | | | | | | | | | |
| Location: | | Vado ES | | | | | | | |
| 94631 | | | | | 10/26/2012 | | 80 | | \$0.00 |
| Medium | Work In Progress | | | 10/26/2012 10:09:07 | | | | | |
| Miranda, Danny | need to replace exhaust motor in communication rm and r.r. | | | | | | | | |
| <u>Danny Miranda</u> | | | | | | | | | |
| 95585 | | | | | 11/15/2012 | | 60 | | \$0.00 |
| Scheduled | Work In Progress | | | 11/15/2012 10:53:43 | | | | | |
| Miranda, Danny | Ms. Sherri with CLEAResult Consulting will come by the school for replacement of aerators. Please assist her with locating the information she needs. She will be visiting schools during the next several days. If you have any questions please call Mr. Gallegos at (575) 882-6921. Thank You | | | | | | | | |
| 96751 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:31 AM | | | | | |
| Miranda, Danny | Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96752 | | | | | 1/6/2013 | 1/14/2013 | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:32 AM | | | | | |
| Miranda, Danny | Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 96753 | | | | | 1/6/2013 | | 8 | | \$0.00 |
| Medium | Work In Progress | | | 1/6/2013 12:23:32 AM | | | | | |
| Miranda, Danny | Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details. | | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93866 | | | | | 10/8/2012 | | 98 | | \$0.00 |
| Medium | Work In Progress | | | 10/8/2012 8:46:35 AM | | | | | |
| Flores, Pete | TRUCK # NEED TO CK FRONT RIGHT SIDE NOISE, DRIVERS SIDE DOOR' TRANSMISION LEVER' WINDSHEALD, CATALYTIC CONVERTER | | | | | | | | |
| <u>Danny Miranda</u> | | | | | | | | | |
| 94699 | | | | | 10/29/2012 | | 77 | | \$0.00 |
| Medium | Work In Progress | | | 10/29/2012 9:58:15 AM | | | | | |
| Orozco, Daniel | EXHAUST FAN OVER OVENS IS NOT WORKING.SNP MANAGER EVA M. 233.2945 | | | | | | | | |
| Maritza Gonzalez | | | | | | | | | |

894 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2012 - 6/30/2013 Order By Location, Status

| WOID | Building | Area | Deferred By | Until | Request Date | Target Comp Date | Days Aged | Labor Hours | Total Costs |
|-------------------------------|------------------|---|-------------|--------------------------|-----------------------|------------------|-----------|---------------|-------------|
| Priority | Status | Area Number | Reason | | Created Date/Time | Actual Comp Date | | | |
| Assigned To | | Description | | | | Action Taken | | | |
| Requester Name | | | | | | | | | |
| Location: Vado ES | | | | | | | | | |
| 96694 | | | | | 1/3/2013 | | 11 | | \$0.00 |
| Medium | Work In Progress | | | | 1/3/2013 11:10:12 AM | | | | |
| Orozco, Daniel | | WASHING MACHINE BURNED OUT. | | | | | | | |
| | | EVA M. SNP MGR 233-2945 | | | | | | | |
| <u>Jacqueline Aguilar</u> | | | | | | | | | |
| 97196 | | | | | 1/13/2013 | 1/29/2013 | 1 | | \$0.00 |
| Medium | Work In Progress | | | | 1/13/2013 12:15:58 AM | | | | |
| Miranda, Danny | | Monthly - Vado ES Playground Insp - Refer to PM schedule details. | | | | | | | |
| <u>Margret Villalobos</u> | | | | | | | | | |
| 93941 | | | | | 10/9/2012 | | 97 | | \$0.00 |
| Medium | Work In Progress | | | | 10/9/2012 2:31:56 PM | | | | |
| Miranda, Danny | | please install new soccer goals when purchased. thank you | | | | | | | |
| <u>Michael Munoz</u> | | | | | | | | | |
| Count: 18 Work Orders | | Avg. Age of WO's 33 | | Total for Vado ES | | 0 | | \$0.00 | |
| Count: 894 Work Orders | | Avg. Age of WO's 52 | | Grand Total | | 0 | | \$0.00 | |