

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Location Not Assigned							
111654					1/6/2014		8		\$0.00
Medium	Work In Progress				1/6/2014 12:24:14 AM				
Flores, Pete		Monthly - District Tractors - Full Service PM - Refer to PM schedule details.							
Margret Villalobos									
Count: 1 Work Orders		Avg. Age of WO's	8			Total for <Blank>	0		\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Alma Del Valle Daycare									
111953					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:40 AM				
Montoya, Adam		Monthly - QRTLY BLDG INSP REPORTS (ADV) - Refer to PM schedule details.							
Margret Villalobos									
Count: 1 Work Orders		Avg. Age of WO's	2		Total for Alma Del Valle Daycare			0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
108723		Classroom			10/11/2013		95		\$0.00
Medium	Work In Progress				10/11/2013 10:28:43				
Marquez, Gerardo		need door knob in class room restroom (room 102)							
David Vega									
106330					8/21/2013		146		\$0.00
Medium	Work In Progress				8/21/2013 10:31:09 AM				
Nunez, Arturo		please assemble new furniture!							
Laura Vazquez									
106090					8/15/2013		152		\$0.00
Medium	Work In Progress				8/15/2013 2:51:26 PM				
Nunez, Arturo		trim shrubs in front of office							
Laura Vazquez									
110293					11/15/2013		60		\$0.00
Medium	Work In Progress	TEACHER'S			11/15/2013 9:14:07 AM				
Nunez, Arturo		NEED A DOOR THRESHOLD INSTALLED TO PREVENT DIRT FROM COMING IN UNDER THE DOOR (M. HIDALGO 575-618-7459)							
Margaret Villalobos									
107866		Office			9/24/2013		112		\$0.00
Medium	Work In Progress	575-882-1904			9/24/2013 2:01:38 PM				
Nunez, Arturo		restroom form the office is making a noise (when we flash it).							
Laura Vazquez									
108845		Classroom			10/14/2013		92		\$0.00
Medium	Work In Progress	575-882-1904			10/14/2013 2:21:41 PM				
Marquez, Gerardo		closet door from room 102 is locked we are not able to open it.							
Laura Vazquez									
Count: 6 Work Orders			Avg. Age of WO's	110	Total for Anthony - On Track Pre-K (Village)		0		\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

111633 1/5/2014 1/11/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:24:52 AM

Nunez, Arturo Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

105552 8/7/2013 160 \$0.00

Medium Work In Progress SPED OFFICE 8/7/2013 7:58:25 AM

Nunez, Arturo ASSEMBLE DESK FOR MARGARET (SEE MARGARET OR JULIE)

Margaret Villalobos

111890 1/10/2014 4 \$0.00

Medium Work In Progress SPED OFFICE 1/10/2014 10:38:58 AM

Gonzales, Camilo DELIVER PO#131403849 EL PASO OFFICE PRODUCTS
16 BOXES
CLAUDIA PEREZ, INSTRUCTIONAL SPECIALIST

Margaret Villalobos

111891 1/10/2014 4 \$0.00

Medium Work In Progress SPED OFFICE 1/10/2014 10:43:04 AM

Gonzales, Camilo DELIVER PO#131403765 DON JOHNSTON
1 PKG
LISA MCCULLER, INSTRUCTIONAL SPECIALIST

Margaret Villalobos

111892 1/10/2014 4 \$0.00

Medium Work In Progress SPED OFFICE 1/10/2014 10:44:26 AM

Gonzales, Camilo DELIVER PO#131403840 ELLISON EDUCATIONAL
1 BOX
JULIE SIMENTAL, BUDGET SPECIALIST

Margaret Villalobos

111893 1/10/2014 4 \$0.00

Medium Work In Progress SPED OFFICE 1/10/2014 10:47:23 AM

Gonzales, Camilo DELIVER PO #131403929 ULINE INC.
2 BOXES
CLAUDIA PEREZ, INSTRUCTIONAL SPECIALIST

Margaret Villalobos

111647 1/5/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:25:01 AM

Munoz, Michael Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

1/14/2014 10:18:59 AM

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
111793	Cafeteria	Kitchen			1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 11:21:06 AM				
Nunez, Arturo		Need two (2) glow plug ignitors for caf. kit hot water heaters. Info: Norton P # 601559 , model 271y , # 1102							
Arturo Nunez									
111016					12/8/2013	12/24/2013	37		\$0.00
Medium	Work In Progress				12/8/2013 12:18:46 AM				
Nunez, Arturo		Monthly - Anthony ES Monthly Playground Insp. - Refer to PMschedule details.							
Margret Villalobos									
111956					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:42 AM				
Nunez, Arturo		Monthly - Anthony ES Monthly Playground Insp. - Refer to PMschedule details.							
Margret Villalobos									
111246					12/13/2013		32		\$0.00
Medium	Work In Progress				12/13/2013 11:58:48				
Nunez, Arturo		As per Ms. Perez, we need a sign that reads "Right turn only" for our drop off zone							
Jessica Lopez									
111154					12/11/2013		34		\$0.00
Medium	Work In Progress	SPED OFFICE			12/11/2013 11:17:25				
Nunez, Arturo		MOVE PHYSICAL THERAPY EQUIPMENT FOR SPED OFFICE TO PORTABLE (EMPTY DRUG FREE) ANTHONY ELEMENTARY							
Margaret Villalobos									
111038					12/9/2013		36		\$0.00
Medium	Work In Progress				12/9/2013 11:24:47 AM				
Nunez, Arturo		Mr. Nunezas per Ms. Perez please replace damaged tiles located outside nurse's office							
Jessica Lopez									
103957					7/2/2013		196		\$0.00
Medium	Work In Progress	SPED OFFICE			7/2/2013 9:37:24 AM				
Nunez, Arturo		INSTALL WINDOW BLINDS IN THE FRONT OFFICE WINDOW (PREFERRABLY BIG SLATS BUT LITTLE SLATS WILL DO)							
Margaret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
103966					7/2/2013		196		\$0.00
Medium	Work In Progress	SPED OFFICE			7/2/2013 3:02:37 PM				
Nunez, Arturo		MOVE DESK FROM BUDGET CLERK OFFICE INTO OTHER OFFICE SEE MARGARET							
Margaret Villalobos									
103967					7/2/2013		196		\$0.00
Medium	Work In Progress	SPED OFFICE			7/2/2013 3:03:37 PM				
Nunez, Arturo		MOVE DESK AND SHELVES FROM MARGARET'S OFFICE INTO NEW EARLY CHILDHOOD OFFICE (SEE MARGARET)							
Margaret Villalobos									
107732					9/20/2013		116		\$0.00
Medium	Work In Progress	SPED			9/20/2013 9:21:01 AM				
Nunez, Arturo		NEED TO RE-CAULK THE WINDOW PANES IN THE DIRECTORS OFFICE (CAULKING IS FALLING OFF)							
Margaret Villalobos									
107813					9/23/2013		113		\$0.00
Medium	Work In Progress	office			9/23/2013 1:42:18 PM				
Nunez, Arturo		Mr. Nunez please hang flags Location : office							
Jessica Lopez									
111550					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:59 AM				
Nunez, Arturo		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111551					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:00 AM				
Nunez, Arturo		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
108415					10/6/2013		100		\$0.00
Medium	Work In Progress				10/6/2013 12:24:12 AM				
Holguin, Alfredo		Monthly - Anthony ES - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
111532					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:48 AM				
Holguin, Alfredo		Monthly - Anthony ES - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
111522					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:41 AM				
Nunez, Arturo		Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
111185					12/11/2013		34		\$0.00
Medium	Work In Progress				12/11/2013 3:52:18 PM				
Flores, Pete		Need to have vechile # 70 checked starter is dragging, having trouble getting started.							
Arturo Nunez									
105809					8/11/2013	9/11/2013	156		\$0.00
Medium	Work In Progress				8/11/2013 12:17:39 AM				
Nunez, Arturo		Yearly - Anthony ES A9 (AC Condenser)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
107934					9/25/2013		111		\$0.00
Medium	Work In Progress				9/25/2013 3:15:54 PM				
Marquez, Gerardo		Lock on wall marque in foyer area needs to be replaced.							
Arturo Nunez									
111827					1/9/2014		5		\$0.00
Medium	Work In Progress	SPED OFFICE			1/9/2014 10:06:54 AM				
Marquez, Gerardo		NEED A CABINET REKEYED CABINET IS LOCKED AND CANNOT FIND KEY (SEE JULIE OR MARGARET)							
Margaret Villalobos									
111964					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:47 AM				
Vega, David		Monthly - QRTLY BLDG INSP REPORT (AE) - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Anthony ES							
112051					1/14/2014		0		\$0.00
Medium	Work In Progress				1/14/2014 7:47:21 AM				
Villalobos, David		Need some assistance on trouble shooting raypac high delta water heater for kitchen.							
Arturo Nunez									
111475					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:16 AM				
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
110040					11/7/2013		68		\$0.00
Medium	Work In Progress				11/7/2013 3:52:03 PM				
Villalobos, David		Need a Taco circulating for raypack water heater. High Capacity circulator, Model # 2400-20s, Max. Press 150, 3450 r.p.m's,							
Arturo Nunez									
110041					11/7/2013		68		\$0.00
Medium	Work In Progress				11/7/2013 3:54:00 PM				
Villalobos, David		Need a water temp. guage replaced on boiler.							
Arturo Nunez									
110042					11/7/2013		68		\$0.00
Medium	Work In Progress				11/7/2013 3:55:07 PM				
Villalobos, David		Water pressure relief valve needs to be replaced on boiler.							
Arturo Nunez									
109941					11/5/2013		70		\$0.00
Medium	Work In Progress				11/5/2013 3:58:09 PM				
Sotelo, Enrique		Need a emergency light balast for boys restroom.(lay in light fix.)							
Arturo Nunez									
110220					11/13/2013		62		\$0.00
Medium	Work In Progress				11/13/2013 4:00:47 PM				
Sotelo, Enrique		Need a new A.S.I. electric hand drier for boys restroom lower grades.							
Arturo Nunez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Anthony ES							
106994					9/3/2013		133		\$0.00
Medium	Work In Progress				9/3/2013 9:55:44 AM				
Sotelo, Enrique	Outside lights are not working please check								
Jessica Lopez									
Count: 36 Work Orders		Avg. Age of WO's	58	Total for Anthony ES				0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

109171 10/22/2013 84 \$0.00

Medium Work In Progress 10/22/2013 1:13:52 PM

Sotelo, Enrique MR ENRIQUE SOTELO SIR NEED TO REPLACE LIGHT BULBS ON POST NEAR MR MORGAN BUILDING AND PUMP HOUSE TO LIGHTS TOO DARK THANK YOU SIR AND GOD BLESS PS WILL NEED LIFT

Adan Duran

111785 1/8/2014 6 \$0.00

Medium Work In Progress 1/8/2014 9:44:23 AM

Sotelo, Enrique MR ENRIQUE SOTELO PER MRS RAMIREZ THE FRONT DOOR BELL IS NOT WORKING PLEASE CHECK

Adan Duran

110410 11/19/2013 56 \$0.00

Medium Work In Progress 11/19/2013 3:25:13 PM

Villalobos, David DAVID VILLALOBOS SIR NEED TO REPLACE WATER FOUNTAIN OUTSIDE PLAYGROUND VANDALS THANK YOU SIR AND GOD BLESS

Adan Duran

111476 1/5/2014 2/5/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:23:16 AM

Villalobos, David Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

111786 1/8/2014 6 \$0.00

Medium Work In Progress 1/8/2014 9:46:51 AM

Villalobos, David MR DAVID VILLALOBOS SIR THE COMODE IN ROOM 139 IS ACTTING UP MAY NEED A NEW INSERT PLEASE CHECK THANK YOU AND GOD BLESS

Adan Duran

110234 11/14/2013 61 \$0.00

Medium Work In Progress 11/14/2013 9:22:17 AM

Villalobos, David MR DAVID VILLALOBOS SIR THE BACK FLOW VALUE FOR FIRE LANE IS LEAKING NEED TO CHECK THANK YOU SIR AND GOD BLESS

Adan Duran

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Berino ES									
110549					11/22/2013		53		\$0.00
Medium	Work In Progress				11/22/2013 11:19:52				
Carbajal, Jimmy		rudy tena rubber boots size 11 and 2 pair of safty goggeles for tena an cervantes							
Jimmy Cortez									
111976					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:54 AM				
Cortez, Jimmy		Monthly - QRTLY BLDG INSP REPORTS (BE) - Refer to PM schedule details.							
Margret Villalobos									
109173					10/22/2013		84		\$0.00
Medium	Work In Progress				10/22/2013 1:20:56 PM				
Flores, Pete		MR PETE FLORES SIR NEED TO SERVICE JOHN DEERE MOWER FULL SERVICE PLEASE THANK YOU SIR AND GOD BLESS MOWER BE-0401							
Adan Duran									
111533					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:49 AM				
Holguin, Alfredo		Monthly - Berino ES - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
111806					1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 3:37:28 PM				
Duran, Adan		1/8/2014 1 SIGN IN OPEN AND CLOSE GATES CHECK SCHOOL GROUNDS 1/2 CHECK BOILERS LOG IN TEMP 140/130 1/2 CHECK COMODE ROOM 113 ACTTING UP RESET 11/2 111527 EMERGENCY LIGHTS INSPECTION 1/2 PUT IN WORK ORDER DOOR BELL NOT WORKING 3 109298 WORKED WITH DIEMAR REPLACE JOCKEY PUMP MR SOTELO REWIRED AND REVERSE ROTATION 1 FILE DAILY LOG AND CHECK E-MAIL				1/8			
Adan Duran									
108416					10/6/2013		100		\$0.00
Medium	Work In Progress				10/6/2013 12:24:12 AM				
Holguin, Alfredo		Monthly - Berino ES - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Berino ES									
111955					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress			1/12/2014 12:17:41 AM					
Duran, Adan	Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.								
Margret Villalobos									
111727	Main Building	Cafeteria			1/7/2014		7		\$0.00
Medium	Work In Progress			1/7/2014 12:06:12 PM					
Carbajal, Jimmy	vaccum needs new motor								
Jimmy Cortez									
110303					11/15/2013		60		\$0.00
Medium	Work In Progress			11/15/2013 2:55:26 PM					
Munoz, Michael	jockey pump on fire pump went out to purchase and replace. thank you								
Adan Duran									
111641					1/5/2014	1/26/2014	9		\$0.00
Medium	Work In Progress			1/5/2014 12:24:57 AM					
Munoz, Michael	Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
111198					12/12/2013		33		\$0.00
Medium	Work In Progress			12/12/2013 9:16:28 AM					
Marquez, Gerardo	MR JERRY MARQUEZ SIR ROOM 140 IS SPECAIL ED FOR HANDY-CAP NEED TO SECURE THE DOOR FROM THE INSIDE HAVE KIDS THAT ARE RUNNERS DOOR HAS HANDLE AND THEY ARE ABLE TO OPEN VERY EASY NEED A SAFETY COVER ITS A SAFETY CONCERN THANK YOU SIR AND GOD BLESS MRS RAMIREZ WANTS IT ASAP								
Adan Duran									
Count: 17 Work Orders			Avg. Age of WO's	35	Total for Berino ES			0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

111236 12/12/2013 33 \$0.00

Medium Work In Progress 12/12/2013 4:03:00 PM

Marquez, Gerardo warranty1 of the 8 new doors installed oil leaking from door closer.

Paul Quinones

111724 1/7/2014 7 \$0.00

Medium Work In Progress 1/7/2014 10:08:05 AM

Marquez, Gerardo DOOR CLOSER LEAKING OIL FROM THE NEW DOORS INSTALLED NEXT TO CAFETERIA DOUBLE DOORS

Paul Quinones

107844 9/23/2013 113 \$0.00

Medium Work In Progress 9/23/2013 3:56:27 PM

Marquez, Gerardo door to double doors in rear entrance door closer needs to be supported to door frame.w/self tapping screws 3/8"excisting screws are stripped

Paul Quinones

111780 1/8/2014 6 \$0.00

Medium Work In Progress 1/8/2014 8:55:54 AM

Orozco, Daniel ICE MACHINE NOT WORKING. SNP MANAGER PAT C.824.3822

Maritza Gonzalez

110886 12/5/2013 40 \$0.00

Medium Work In Progress 12/5/2013 9:29:57 AM

Gonzalez, Salvador DOUBLE DOORS IN BACK OF KITCHEN EXIT NEED A DOOR HEADER TO SUPPORT THE DOOR CLOSER.

Paul Quinones

111618 1/5/2014 1/11/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:24:43 AM

Quinones, Paul Monthly - Chaparral ES Monthly FE Inpsection - Refer to PMschedule details.

Margret Villalobos

110688 12/1/2013 12/7/2013 44 \$0.00

Medium Work In Progress 12/1/2013 12:33:13 AM

Quinones, Paul Monthly - Chaparral ES Monthly FE Inpsection - Refer to PMschedule details.

Margret Villalobos

1/14/2014 10:19:00 AM

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
111359	Main Building	Classroom			12/17/2013		28		\$0.00
Medium	Work In Progress	304			12/17/2013 2:17:49 PM				
Marquez, Gerardo need keyfixed was unlocking and locking and no longer locks. see Ms. Chavez									
Jennifer Corral									
110707					12/1/2013	12/9/2013	44		\$0.00
Medium	Work In Progress				12/1/2013 12:33:22 AM				
Quinones, Paul Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.									
Margret Villalobos									
111652					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:25:03 AM				
Quinones, Paul Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.									
Margret Villalobos									
105357					8/4/2013	8/12/2013	163		\$0.00
Medium	Work In Progress				8/4/2013 12:20:14 AM				
Quinones, Paul Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.									
Margret Villalobos									
111988					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:18:00 AM				
Quinones, Paul Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.									
Margret Villalobos									
110213					11/13/2013		62		\$0.00
Medium	Work In Progress				11/13/2013 3:50:22 PM				
Quinones, Paul need a gas valve for a roof top heater rm.205									
Paul Quinones									
109444					10/28/2013		78		\$0.00
Medium	Work In Progress				10/28/2013 3:58:57 PM				
Quinones, Paul module board for heater in rm.214									
Paul Quinones									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
111045					12/9/2013		36		\$0.00
Medium	Work In Progress				12/9/2013 1:11:15 PM				
Quinones, Paul		need a gas valve for wall heater in rm.510 requesting 3 gas valves 2 for stock							
Paul Quinones									
110657					12/1/2013	12/9/2013	44		\$0.00
Medium	Work In Progress				12/1/2013 12:32:58 AM				
Quinones, Paul		Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
110649					12/1/2013		44		\$0.00
Medium	Work In Progress				12/1/2013 12:32:55 AM				
Quinones, Paul		Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111568					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:11 AM				
Quinones, Paul		Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111572					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:14 AM				
Quinones, Paul		Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
108959					10/16/2013		90		\$0.00
Medium	Work In Progress				10/16/2013 3:27:43 PM				
Quinones, Paul		please cut grass and weeds (pine trees) thank you							
Michael Munoz									
108667					10/10/2013		96		\$0.00
Medium	Work In Progress				10/10/2013 7:56:32 AM				
Quinones, Paul		need 18" thermocouples for wall heaters universal type							
Paul Quinones									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
107982					9/26/2013		110		\$0.00
Medium	Work In Progress				9/26/2013 9:31:41 AM				
Quinones, Paul		need leather washers for the blower wheel housing shaft for 6500 and 4800 evap.coolers							
Paul Quinones									
106592					8/27/2013		140		\$0.00
Medium	Work In Progress				8/27/2013 2:53:40 PM				
Quinones, Paul		girls rest rm. in e-wing,metal latches are broken that secure doors.latches need to be replaced							
Paul Quinones									
107334					9/11/2013		125		\$0.00
Medium	Work In Progress				9/11/2013 8:32:43 AM				
Quinones, Paul		requesting heavy duty coat hooks 3" type for class rms.need for student back packs							
Paul Quinones									
110760					12/3/2013		42		\$0.00
Medium	Work In Progress				12/3/2013 8:40:13 AM				
Quinones, Paul		needing hvac parts for heater repair and restock							
Paul Quinones									
111517					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:39 AM				
Quinones, Paul		Monthly - Chapparral ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
111963					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:46 AM				
Ramirez, Daniel		Monthly - QRTLY BLDG INSP REPORT (CE) - Refer to PMs schedule details.							
Margret Villalobos									
107095					9/4/2013		132		\$0.00
Medium	Work In Progress				9/4/2013 4:03:38 PM				
Ontiveros, Guadalupe		irrigation water line next to the water tank water leak water line connecting pump and motor							
Paul Quinones									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
110568					11/22/2013		53		\$0.00
Medium	Work In Progress				11/22/2013 3:51:45 PM				
Ontiveros, Guadalupe		pressure tank will not stop draining water shut off back flow in front of che, and at the middle school and gate valves next to pressure tank							
Paul Quinones									
111344					12/17/2013		28		\$0.00
Medium	Work In Progress				12/17/2013 8:37:45 AM				
Marquez, Gerardo		new door intall chk keylocks ets custodial staff having hard time w/keys to open doors, and to lock.							
Paul Quinones									
111356					12/17/2013		28		\$0.00
Medium	Work In Progress				12/17/2013 11:43:09				
Marquez, Gerardo		double doors n. end of new wing lock set will not close nor open door with key							
Paul Quinones									
111361		Classroom			12/17/2013		28		\$0.00
Medium	Work In Progress	105			12/17/2013 2:21:12 PM				
Marquez, Gerardo		Manny was supposed to come back and fix Ms. Nelsons door to come in and out of school and open classroom door and never did. Please see Ms. Nelson							
Jennifer Corral									
110783					12/3/2013		42		\$0.00
Medium	Work In Progress				12/3/2013 1:38:07 PM				
Quinones, Paul		PAINT FOR THE NEW DOORS, AND DOOR JAMS TOTAL OF 8 DOORS INSTALLED BY CONTRACTER							
Paul Quinones									
110591					12/1/2013		44		\$0.00
Medium	Work In Progress				12/1/2013 12:32:25 AM				
Quinones, Paul		Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.							
Margret Villalobos									
111474					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:15 AM				
Villalobos, David		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Chaparral ES							
110325					11/15/2013		60		\$0.00
Medium	Work In Progress				11/15/2013 4:01:40 PM				
Vallejo, Albert		requesting an electrical outlet for star board in class rm.103							
Paul Quinones									
Count: 36 Work Orders		Avg. Age of WO's	51			Total for Chaparral ES	0		\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral High - Pre-K									
110983		Classroom			12/6/2013		39		\$0.00
Medium	Work In Progress	Rooms			12/6/2013 3:13:22 PM				
Urquidi, Jesus		Shampoo the carpets in rooms 101, 102, 103 & 104 due to student accidents.							
Noemi Duron									
Count: 1 Work Orders		Avg. Age of WO's		39	Total for Chaparral High - Pre-K			0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
111989					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:18:01 AM				
Urquidi, Jesus		Monthly - QRTLY BLDG INSP REPORT (CH) - Refer to PM schedule details.							
Margret Villalobos									
111278					12/15/2013		30		\$0.00
Medium	Work In Progress				12/15/2013 12:18:11				
Valdez, Pedro		Monthly - Chaparral HS Soil Sampling - Refer to PM schedule details.							
Margret Villalobos									
105456					8/6/2013		161		\$0.00
Medium	Work In Progress	LINE LOCATE			8/6/2013 8:28:25 AM				
Vallejo, Albert		NORTH BOUNDARY BETWEEN HIGH SCHOOL AND GRADE SCHOOL AT THE TENNIS COURTS							
		Company: RCI POWER AND LIGHTING Contact Name: BENNIE WILLIAMS Phone: (575)532-1110							
Alfredo Holguin									
111712					1/7/2014		7		\$0.00
Medium	Work In Progress	LINE LOCATE			1/7/2014 8:23:39 AM				
Vallejo, Albert		Lynco will be drilling at Chaparral this Friday, 01/10/2014. They have the piers marked on the ground and will need your district to locate any utilities underground at these locations.							
Rafael Gallegos									
110544		Exterior			11/22/2013		53		\$0.00
Medium	Work In Progress				11/22/2013 10:19:33				
Marquez, Gerardo		Need to install Security doors on baseball and softball storage sheds							
Alfredo Ortiz									
111783		Lift Station			1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 9:34:54 AM				
Marquez, Gerardo		Need key for gate on pump station.							
Alfredo Ortiz									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
110824		Restroom			12/4/2013		41		\$0.00
Medium	Work In Progress				12/4/2013 9:37:36 AM				
Ortiz, Alfredo		Need to paint restrooms to remove graffitty.							
Alfredo Ortiz									
111473					1/5/2014	1/8/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:14 AM				
Ortiz, Alfredo		Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
107786					9/23/2013		113		\$0.00
Medium	Work In Progress				9/23/2013 8:19:30 AM				
Appelzoller, Fred		tools needed cutting wheels and segmented blades for grinder,6 in one screw driver, t handle tap wrench,9" linemens pliers, tubeing cutters, ridgid chain vise, slug buster punch set wire strippers,heat gun, iron pliers, 1/4 hex drives, saw zall blades, green lee var bits, hex nut setters, magnetic ext,							
Fred Appelzoller									
111711					1/7/2014		7		\$0.00
Medium	Work In Progress	LINE LOCATE			1/7/2014 8:22:58 AM				
Appelzoller, Fred		Lynco will be drilling at Chaparral this Friday, 01/10/2014. They have the piers marked on the ground and will need your district to locate any utilities underground at these locations.							
Rafael Gallegos									
111495					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:26 AM				
Villalobos, David		Yearly - Chaparral HS Backflow Inspection - Refer to PMschedule details.							
Margret Villalobos									
110329					11/16/2013		59		\$0.00
Medium	Work In Progress				11/16/2013 12:18:08				
Flores, Pete		Yearly - Chaparral HS M-0405 (Z-Track) Grounds - Refer to PMschedule details.							
Margret Villalobos									
111523					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:42 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

111609 1/5/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:24:37 AM

Apodaca, Mario Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.

Margret Villalobos

108152 Exterior 10/1/2013 105 \$0.00

Medium Work In Progress 10/1/2013 8:21:32 AM

Gonzalez, Salvador Need to install a new gate for tennis courts.

Alfredo Ortiz

106602 Lift Station 8/27/2013 140 \$0.00

Medium Work In Progress 8/27/2013 3:28:14 PM

Gonzalez, Salvador need to retro fit pump bracket at storm water lift pump station outside and theater. (welding job)

Mario Apodaca

111161 Exterior 12/11/2013 34 \$0.00

Medium Work In Progress 12/11/2013 2:52:47 PM

Gonzalez, Salvador Need welder to weld on all chains and locks to gates too many lost.

Alfredo Ortiz

111039 Exterior 12/9/2013 36 \$0.00

Medium Work In Progress 12/9/2013 11:26:54 AM

Gonzalez, Salvador Need to weld the door hinges to gate.

Alfredo Ortiz

110070 Exterior 11/8/2013 67 \$0.00

Medium Work In Progress 11/8/2013 3:20:29 PM

Gonzalez, Salvador Need to install Fence gate spoppers at main entrances.

Alfredo Ortiz

108413 10/6/2013 100 \$0.00

Medium Work In Progress 10/6/2013 12:24:11 AM

Holguin, Alfredo Monthly - Chaparral HS - Fire Pump Engine - Refer to PM schedule details.

Margret Villalobos

111549 1/5/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:23:59 AM

Ortiz, Alfredo Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
111548					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:58 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
111541					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:53 AM				
Ortiz, Alfredo		Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111530					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:47 AM				
Holguin, Alfredo		Monthly - Chaparral HS - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
111653					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:25:04 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
108886		Exterior			10/15/2013		91		\$0.00
Medium	Work In Progress				10/15/2013 8:40:44 AM				
Gallegos, Rafael		Warrent work order Water leak between tennise courts.							
Alfredo Ortiz									
111870		Office			1/9/2014		5		\$0.00
Medium	Work In Progress				1/9/2014 4:15:47 PM				
Briones, Enrique		Deliver 13 bx. (1)MACBOOK Pro 15 in. w/Retina, (12) IMAC. Attn:S. Gabaldon P.O.#131403622							
Theresa Ramirez									
111025		Exterior			12/9/2013		36		\$0.00
Medium	Work In Progress				12/9/2013 8:29:48 AM				
Munoz, Michael		Attention to Mike Need to replace main gate. It was damage by a vehicle.							
Alfredo Ortiz									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
111916					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 2:36:01 PM				
Ortiz, Alfredo		Asp PM serviced by Dimar - System 3 install escutcheon missing and in E-7 Hallway at T to hallway D, D5.							
Michael Munoz									
111918					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 2:37:30 PM				
Ortiz, Alfredo		Asp PM serviced by Dimar - System 2 install escutcheon missing.							
Michael Munoz									
108495		Pump House			10/7/2013		99		\$0.00
High	Work In Progress				10/7/2013 8:59:05 AM				
Munoz, Michael		Need to have Dimar to check diesel fire pump leaking water and also 10/5/13 Sat. the fire alarm went off the panel read : Heat (Fixed) Pump For HYDRANT. I tightend the Packing but still leaking.							
Alfredo Ortiz									
111648					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:25:01 AM				
Munoz, Michael		Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PMs schedule details.							
Margret Villalobos									
110493	A-Wing	Library			11/21/2013		54		\$0.00
Medium	Work In Progress				11/21/2013 12:10:44				
Ortiz, Alfredo		Need to replace light bulbs and ballast.							
Alfredo Ortiz									
110466	A-Wing	Roof			11/20/2013		55		\$0.00
Medium	Work In Progress				11/20/2013 3:39:39 PM				
Ortiz, Alfredo		Need to seal roof walls to prevent water leaks							
Alfredo Ortiz									
110188	A-Wing	Hallway/Corridor			11/13/2013		62		\$0.00
Medium	Work In Progress				11/13/2013 11:12:20				
Marquez, Gerardo		The outside door to A wing by ISS class room is not working. When I put my key in it just turns and keeps turning all the way around. Please fix ASAP for security reasons. The rooms close to this door are ISS and CAP. (Lupe Quinones, security)							
Mireya Meza									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
110545	A-Wing	Roof			11/22/2013		53		\$0.00
Medium	Work In Progress				11/22/2013 10:23:45				
Ortiz, Alfredo		Need to remove sand from roof top							
Alfredo Ortiz									
104752	A-Wing	Exterior			7/25/2013		173		\$0.00
Medium	Work In Progress				7/25/2013 3:46:15 PM				
Appelzoller, Fred		Need to repair pumps for rain water.							
Alfredo Ortiz									
111794	A-Wing	Library			1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 11:27:08 AM				
Marquez, Gerardo		The right main door to the library does not lock. Please fix. (Ms. DeVine, library)							
Mireya Meza									
109836	A-Wing				11/4/2013		71		\$0.00
Medium	Work In Progress				11/4/2013 10:21:30 AM				
Marquez, Gerardo		Need to turn in keys. They have been here for years and I have no use for them. (Mireya Meza)							
Mireya Meza									
105363	A-Wing	Office			8/5/2013		162		\$0.00
Medium	Work In Progress				8/5/2013 8:11:06 AM				
Marquez, Gerardo		Please make 1 copy of keys #238 & #142 for the nurse's filing cabinet. These are the Fire king cabinets. (Ms. deCastro)							
Mireya Meza									
110845	A-Wing	Cafeteria			12/4/2013		41		\$0.00
Medium	Work In Progress				12/4/2013 2:06:04 PM				
Solis, Lorenzo		Need to replace compressor On unit: TRANE MO# CSHC075K0Aoo SER# 063310MG2A PART# 570008750800 # 3D- SCROLL LRA 95.							
Alfredo Ortiz									
109617	E-Wing	Restroom			11/1/2013		74		\$0.00
Medium	Work In Progress				11/1/2013 10:25:53 AM				
Appelzoller, Fred		Need to replace broken Urinal.							
Alfredo Ortiz									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

109908	I-Wing	Classroom			11/5/2013		70		\$0.00
--------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/5/2013 12:41:09 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo Need to replace door in Band room broken.

Alfredo Ortiz

111037	I-Wing	Kitchen			12/9/2013		36		\$0.00
--------	--------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/9/2013 11:16:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Gonzalez, Salvador Rack on oven broke need to weld together.

Alfredo Ortiz

111036	Q-Wing	Hallway/Corridor			12/9/2013		36		\$0.00
--------	--------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/9/2013 11:14:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Gonzalez, Salvador Need to weld the cable on lockers students took off clamps

Alfredo Ortiz

111112	Q-Wing	Classroom			12/10/2013		35		\$0.00
--------	--------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/10/2013 3:29:18 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo Need to replace door handle broke off. In Q-6 Auto shop.

Alfredo Ortiz

105851	Q-Wing	Classroom			8/12/2013		155		\$0.00
--------	--------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/12/2013 10:14:14 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo The wrestling/tennis room share a door with Q2. This door is locked on my side but it can be opened from the neighboring room without a key. There is a large amount of valuable equipment in Q2 and I would feel better knowing that all access points were secure. Perhaps it would be possible to have the door lock both directions. (Mr. Woodard)

Mireya Meza

109849	Q-Wing	Classroom			11/4/2013		71		\$0.00
--------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/4/2013 2:26:13 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert Please lower some of the power supplies so that we could use them for setting up the computers (south side of the room), please see me to clarify request. (Mr. Woodard, Q2)

Mireya Meza

111434	Q-Wing	Classroom			12/19/2013		26		\$0.00
--------	--------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/19/2013 10:44:41				
--------	------------------	--	--	--	---------------------	--	--	--	--

Vallejo, Albert Please install locking switches in Mr. Galvan's class room. (Mr. Galvan)

Mireya Meza

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

110349	Q-Wing	Hallway/Corridor			11/18/2013		57		\$0.00
--------	--------	------------------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/18/2013 2:44:10 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ortiz, Alfredo Need to order fan duct for exhaust fans with squirl cage.

Alfredo Ortiz

109910	R-Wing	Classroom			11/5/2013		70		\$0.00
--------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				11/5/2013 12:48:59 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo Need to install pull handle in Culinary classroom.

Alfredo Ortiz

108497	Field House	Exterior			10/7/2013		99		\$0.00
--------	-------------	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				10/7/2013 9:26:28 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo Need to fix door knob and Locksets can't lock doors . At the ticket booth Field house.

Alfredo Ortiz

112029	Field House	Restroom			1/13/2014		1		\$0.00
--------	-------------	----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/13/2014 3:42:07 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo Old CH86 keys are not matching new cylinder in field house boys restroom area. Please check that all CH86 (athletics keys) match cylinder in field house area. (Mireya Meza)

Mireya Meza

111853	Field House	Restroom			1/9/2014		5		\$0.00
--------	-------------	----------	--	--	----------	--	---	--	--------

Medium	Work In Progress				1/9/2014 3:36:36 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo Pedro the Grounds man needs a key for restroom

Alfredo Ortiz

111813	Field House	Athletic Field			1/8/2014		6		\$0.00
--------	-------------	----------------	--	--	----------	--	---	--	--------

Medium	Work In Progress	Football			1/8/2014 3:48:24 PM				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Valdez, Pedro Could we have the ticket booth that is used for football to be moved between the softball and baseball fields, near the entrance. The winds during baseball season are very strong and we have trouble keeping the money safe. Electricity needs to be worked on in booth as well. (Sofia Payen, athletic admin)

Mireya Meza

105773	Field House	Athletic Field			8/9/2013		158		\$0.00
--------	-------------	----------------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	KAREN			8/9/2013 2:22:11 PM				
--------	------------------	-------	--	--	---------------------	--	--	--	--

Gonzalez, Salvador CHS - SOCCER FIELDS (2) PERMANENT CANOPIES - ONE FOR VISITORS AND ONE FOR HOME TEAM. THANK YOU!

Terry Alvarado

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
105660	H-Wing	Dressing Room			8/8/2013		159		\$0.00
Medium	Work In Progress				8/8/2013 9:52:01 AM				
Marquez, Gerardo Please put the metal door back on. The door that is suppose to be between the girls basketball locker room and showers. (Ms. Lydia Guerrero, girls dressing room)									
Mireya Meza									
108049	H-Wing	Gym			9/27/2013		109		\$0.00
Medium	Work In Progress				9/27/2013 2:57:56 PM				
Marquez, Gerardo Need to install door louvers on two storage doors because mole is growing on everything. Girls locker rooms in Gym.									
Alfredo Ortiz									
110273	H-Wing	Gym			11/14/2013		61		\$0.00
Medium	Work In Progress				11/14/2013 3:47:14 PM				
Vallejo, Albert Need to replace several Ballast and light bulbs in Gym.									
Alfredo Ortiz									
111885	H-Wing	Restroom			1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 9:09:39 AM				
Appelzoller, Fred Need to replace several faucets in boys and girls restroom bent and sinks are loose.									
Alfredo Ortiz									
106655	Pre-K	Exterior			8/28/2013		139		\$0.00
Medium	Work In Progress				8/28/2013 1:34:33 PM				
Gallegos, Rafael Warranty work order, Cinder block wall at play ground is falling apart									
Alfredo Ortiz									
111789	Pre-K	Classroom			1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 10:19:43 AM				
Ortiz, Alfredo Need to replace Light bulbs in Multipurpose room.									
Alfredo Ortiz									
111651					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:25:03 AM				
Munoz, Michael Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PMSchedule details.									
Margret Villalobos									
Count: 63 Work Orders			Avg. Age of WO's 53		Total for Chaparral HS			0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

111642 1/5/2014 1/26/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:24:58 AM

Munoz, Michael Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

111729 1/7/2014 7 \$0.00

Medium Work In Progress 1/7/2014 1:55:20 PM

Carrasco, Danny Truck #81 has been filled with 13 gallons of fuel by Lupe.

Albert Vallejo

109829 Gym 11/4/2013 71 \$0.00

High Work In Progress 11/4/2013 9:37:52 AM

Munoz, Michael gym floor is buckling in 3 entrances. need to repair

Michael Munoz

109889 11/5/2013 70 \$0.00

Medium Work In Progress 11/5/2013 8:53:26 AM

Marquez, Gerardo Doors by Band room will not close.

Albert Vallejo

109891 11/5/2013 70 \$0.00

Medium Work In Progress 11/5/2013 9:10:39 AM

Marquez, Gerardo Please check locker room cylinder.

Albert Vallejo

107708 9/19/2013 117 \$0.00

Medium Work In Progress 9/19/2013 3:28:01 PM

Marquez, Gerardo South exit door for gym needs to be replaced. The panic bar is also not working properly.

Albert Vallejo

111106 12/10/2013 35 \$0.00

Medium Work In Progress 12/10/2013 3:17:58 PM

Marquez, Gerardo Please replace door closer. It has leaked the oil and cannot be adjusted.

Albert Vallejo

111638 1/5/2014 1/11/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:24:55 AM

Vallejo, Albert Monthly - Chaparral MS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

1/14/2014 10:19:01 AM

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

108118	Main Building	Exterior			9/30/2013		106		\$0.00
--------	---------------	----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/30/2013 11:09:45 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vallejo, Albert Please clean up weeds in front of school

Gidget Mora

111055	Main Building	Computer Lab			12/9/2013		36		\$0.00
--------	---------------	--------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	311			12/9/2013 2:38:18 PM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Vallejo, Albert Please turn off heat-too warm

Gidget Mora

111801	Main Building	Restroom (Girls)			1/8/2014		6		\$0.00
--------	---------------	------------------	--	--	----------	--	---	--	--------

Medium	Work In Progress	100 hallway			1/8/2014 3:04:53 PM				
--------	------------------	-------------	--	--	---------------------	--	--	--	--

Vallejo, Albert Sink in girls restroom is not working

Gidget Mora

104768	Main Building	Office			7/26/2013		172		\$0.00
--------	---------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Merry			7/26/2013 8:31:49 AM				
--------	------------------	-------	--	--	----------------------	--	--	--	--

Marquez, Gerardo Needs keys for desk

Gidget Mora

110350	Main Building				11/18/2013		57		\$0.00
--------	---------------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	Security			11/18/2013 2:45:09 PM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Marquez, Gerardo Please make duplicate keys for security office and custodial offices

Gidget Mora

111735	Main Building	Classroom			1/7/2014		7		\$0.00
--------	---------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	408			1/7/2014 2:08:22 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Solis, Lorenzo no heat in the room

Gidget Mora

106128	Main Building	Computer Lab			8/16/2013		151		\$0.00
--------	---------------	--------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/16/2013 8:31:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo Install refrigeration units for computer labs. Rooms 406 and 207.

Albert Vallejo

108717	Main Building	Hallway/Corridor			10/11/2013		95		\$0.00
--------	---------------	------------------	--	--	------------	--	----	--	--------

Medium	Work In Progress	400 hall			10/11/2013 9:16:30 AM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Vallejo, Albert Please paint wall in 400 hallway

Gidget Mora

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
110341	Main Building	Restroom			11/18/2013		57		\$0.00
Medium	Work In Progress				11/18/2013 8:53:07 AM				
Appelzoller, Fred		lavs in faculty restrooms they are the long lavs and take alot of room in the rest rooms							
Fred Appelzoller									
108954	Main Building	Restroom			10/16/2013		90		\$0.00
Medium	Work In Progress				10/16/2013 2:09:57 PM				
Appelzoller, Fred		Please replace 5 multiple sensor sinks. Not working, also install new basins.				asp Mike - Assign to Fred, but please add on to description to install new basins.			
Gidget Mora									
108501	Main Building				10/7/2013		99		\$0.00
Medium	Work In Progress	teachers lounge			10/7/2013 9:57:51 AM				
Perez, M. Carmen		Please look into mold grow on the ceiling tile in teachers lounge							
Gidget Mora									
111052	Main Building	Classroom			12/9/2013		36		\$0.00
Medium	Work In Progress	401			12/9/2013 2:26:45 PM				
Vallejo, Albert		Please replace shades on windows and fix door so it doesn't slam							
Gidget Mora									
111536					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:50 AM				
Vallejo, Albert		Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
111539					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:52 AM				
Vallejo, Albert		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111537					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:51 AM				
Vallejo, Albert		Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Chaparral MS									
111538					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:51 AM				
Vallejo, Albert	Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
111811					1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 3:44:31 PM				
Vallejo, Albert	Nurses toilet needs fill valve.								
Albert Vallejo									
111887					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 9:52:13 AM				
Vallejo, Albert	Please order tools: 1. Transmitter 2. Line Locator 3. Inductive clamp 4. Phillips Drive bits 5. Hex Drive 4" Extension 6. Hex Drive 6" Extension								
Albert Vallejo									
107344					9/11/2013		125		\$0.00
Medium	Work In Progress				9/11/2013 9:29:23 AM				
Vallejo, Albert	Replace damaged doors in 300 hallway restroom.								
Albert Vallejo									
109831					11/4/2013		71		\$0.00
Medium	Work In Progress				11/4/2013 9:53:19 AM				
Gonzalez, Maritza	CHEMICAL CART IS RUSTED. SNP MANAGER SANDRA D. 824.4376.								
Maritza Gonzalez									
108727					10/11/2013		95		\$0.00
Medium	Work In Progress				10/11/2013 11:19:15				
Perez, M. Carmen	NEED TO CLEAN ALL SPRINKLER HEADS IN HALLWAYS.								
Jesus Estrada									
109614					11/1/2013		74		\$0.00
Medium	Work In Progress				11/1/2013 8:36:37 AM				
Estrada, Jesus	DAMAGED TILE IN FRONT OF WALK-IN FRIDGE AND PREP SINK. SNP MANAGER SANDRA DIAZ 824.4376.								
Maritza Gonzalez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
111472					1/5/2014	1/8/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:12 AM				
Vallejo, Albert		Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111477					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:16 AM				
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
108615		Cafeteria			10/9/2013		97		\$0.00
Medium	Work In Progress				10/9/2013 11:06:30 AM				
Vallejo, Albert		senesecita poner 5 lamparas en cafeteria GRACIAS							
M. Carmen Perez									
108618		Restroom			10/9/2013		97		\$0.00
Medium	Work In Progress				10/9/2013 11:17:29 AM				
Vallejo, Albert		senesecita areglar swich del #300 hallway restroom boys GRACIAS							
M. Carmen Perez									
111731					1/7/2014		7		\$0.00
Medium	Work In Progress				1/7/2014 1:57:30 PM				
Solis, Lorenzo		Left-side boiler pump is leaking							
Albert Vallejo									
111389		Hallway/Corridor			12/18/2013		27		\$0.00
Medium	Work In Progress				12/18/2013 7:52:00 AM				
Appelzoller, Fred		senesecita areglar fuente de agua de tomar agua esta likiando agua del paciyo 100 GRACIAS							
M. Carmen Perez									
111810					1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 3:43:19 PM				
Marquez, Gerardo		Staff restroom doors in 100 hall do not lock from outside.							
Albert Vallejo									
111730					1/7/2014		7		\$0.00
Medium	Work In Progress				1/7/2014 1:56:32 PM				
Marquez, Gerardo		Lock to security office from foyer will not release certain keys.							
Albert Vallejo									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
108089					9/30/2013		106		\$0.00
Medium	Work In Progress				9/30/2013 12:35:37 AM				
Vallejo, Albert		Monthly - Chaparral MS A16 (Fan Exh.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
107339					9/11/2013		125		\$0.00
Medium	Work In Progress				9/11/2013 9:25:04 AM				
Solis, Lorenz		Install refrigeration unit for comp lab in 406.							
Albert Vallejo									
111983					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:58 AM				
Perez, M. Carmen		Monthly - QRTLY BLDG INSP REPORTS (CM) - Refer to PM schedule details.							
Margret Villalobos									
110888					12/5/2013		40		\$0.00
Medium	Work In Progress				12/5/2013 10:46:50 AM				
Carbajal, Jimmy		aquien coresponda GORGE PEREZ NESECITA BOTAS PARA ESTRIPIAR #18 GRACIAS							
M. Carmen Perez									
Count: 42 Work Orders		Avg. Age of WO's 53		Total for Chaparral MS		0		\$0.00	

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert Pride

111516 1/5/2014 1/13/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:23:38 AM

Aguilar, Patricio Monthly - Desert Pride Roof Inspection - Refer to PM schedule details.

Margret Villalobos

111961 1/12/2014 1/28/2014 2 \$0.00

Medium Work In Progress 1/12/2014 12:17:45 AM

Acosta, David Monthly - QRTLY BLDG INSP REPORT (DP) - Refer to PMs schedule details.

Margret Villalobos

110447 Portables 11/20/2013 55 \$0.00

Medium Work In Progress 11/20/2013 12:11:12

Ontiveros, Guadalupe need to haul away two dead and dry out trees.

David Acosta

111725 Custodial 1/7/2014 7 \$0.00

Medium Work In Progress 1/7/2014 11:14:05 AM

Lara, Ralph Need to replace master key. Having problems opening doors.

David Acosta

105370 Classroom 8/5/2013 162 \$0.00

Medium Work In Progress # 9 8/5/2013 9:27:09 AM

Lara, Ralph need to replace door jam.

David Acosta

111673 Portables 1/6/2014 8 \$0.00

Medium Work In Progress room 8 1/6/2014 1:31:52 PM

Sotelo, Enrique need to to replace both outside night lights on portable

David Acosta

111604 1/5/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:24:34 AM

Ronquillo, Ruben Monthly - Desert Pride - (Qtrly) Fitness Equipment - Refer to PMs schedule details.

Margret Villalobos

112043 1/14/2014 0 \$0.00

Medium Work In Progress 1/14/2014 12:22:53 AM

Sanchez, Raul Monthly - Desert Pride - Water Filters - Refer to PM schedule details.

Margret Villalobos

1/14/2014 10:19:01 AM

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Pride							
111275					12/14/2013		31		\$0.00
Medium	Work In Progress				12/14/2013 12:19:30				
Sanchez, Raul		Monthly - Desert Pride - Water Filters - Refer to PM schedule details.							
Margret Villalobos									
111615					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:41 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
111545					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:56 AM				
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111544					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:55 AM				
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111755	Storage A	Pump House			1/7/2014		7		\$0.00
Medium	Work In Progress				1/7/2014 3:32:41 PM				
Apodaca, Mario		need to replace the water meter at district price: Academy on the domestic water system							
Mario Apodaca									
107568					9/17/2013		119		\$0.00
Medium	Work In Progress				9/17/2013 12:07:00 PM				
Carrasco, Danny		NEED GORILLA DUCK TAPE FOR BOXING RING.							
Yvette Cortez									
111635					1/5/2014	1/11/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:53 AM				
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Desert Pride							
108955					10/16/2013		90		\$0.00
Medium	Work In Progress				10/16/2013 2:17:32 PM				
Gonzalez, Salvador	Need poles to divide the drop off and pick up parking area for safety of the children. Parents are double parking and kids are running in between the cars and could get hurt. Thank you, Ruben								
Ruben Ortiz									
Count: 16 Work Orders		Avg. Age of WO's 33			Total for Desert Pride			0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail Intermediate									
111096					12/10/2013		35		\$0.00
Medium	Work In Progress				12/10/2013 12:31:25				
Gonzalez, Salvador		Coach requesting baseball batting cage for students use for school baseball practices.							
Johnny Acuna									
111623					1/5/2014	1/11/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:46 AM				
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inpsection - Refer to PMs schedule details.							
Margret Villalobos									
111836		Custodial			1/9/2014		5		\$0.00
Medium	Work In Progress				1/9/2014 11:50:52 AM				
Carbajal, Jimmy		Hola jimmy la aspiradora num. 0001162 la llanta se le cayo y el gendel esta quebrado por favor la puede revisar gracias							
Laura Sandoval									
111207		Custodial			12/12/2013		33		\$0.00
Medium	Work In Progress				12/12/2013 1:14:30 PM				
Carbajal, Jimmy		Chuy buenas tardes .Se necesita remplasar las alfombras de los portables num. 401,402,403,406,408,409 por favor muchas gracias							
Laura Sandoval									
111643					1/5/2014	1/26/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:58 AM				
Munoz, Michael		Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
105593					8/7/2013		160		\$0.00
Medium	Work In Progress				8/7/2013 12:53:35 PM				
Munoz, Michael		Asp inspection on PM Fire Sprinkler by Dimar the following was found: Retard system is leaking.							
Michael Munoz									
112003	Main Building	Office			1/13/2014		1		\$0.00
Medium	Work In Progress				1/13/2014 9:11:15 AM				
Gonzales, Camilo		Deliver 20 bx. additional HP Compacq 6300 Pro. P.O.# 131403498							
Theresa Ramirez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Desert Trail Intermediate							
112004	Main Building	Office			1/13/2014		1		\$0.00
Medium	Work In Progress				1/13/2014 9:22:02 AM				
Gonzales, Camilo		Deliver 1 bx. w/2 Laptops PO# 131403992							
Theresa Ramirez									
111974					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:52 AM				
Acuna, Johnny		Monthly - Desert Trail Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
105036					8/1/2013		166		\$0.00
Medium	Work In Progress				8/1/2013 9:27:19 AM				
Gonzalez, Salvador		Please install diamond metal plate to new portable ramps and decks.							
Johnny Acuna									
111588					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:24 AM				
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111589					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:24 AM				
Acuna, Johnny		Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111587					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:23 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
110171					11/13/2013		62		\$0.00
Medium	Work In Progress				11/13/2013 7:51:21 AM				
Acuna, Johnny		Need new threshold for SW hall main doors.				11/20 - Reroute to J. Acuna			
Johnny Acuna									
112034					1/13/2014		1		\$0.00
Medium	Work In Progress				1/13/2014 3:48:43 PM				
Acuna, Johnny		Need (single water inlet) Goose Neck faucet for Room #204 Classroom sink.							
Johnny Acuna									
1/14/2014 10:19:02 AM									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail Intermediate							
112036					1/13/2014		1		\$0.00
Medium	Work In Progress				1/13/2014 3:50:37 PM				
Acuna, Johnny		Need tank to bowl Gasket kit for classroom restroom comode in Room #204.							
Johnny Acuna									
111728					1/7/2014		7		\$0.00
Medium	Work In Progress				1/7/2014 1:37:52 PM				
Acuna, Johnny		Need Aluminum Window blinds for classrooms #208,418,410, and 418: (4) 62" 1/2 Wide X 63" Long, (1) 91" 1/2 Wide X 30" Long, (1) 98" Wide X 39" Long, (1) 34" Wide X 63" Long.							
Johnny Acuna									
111155					12/11/2013		34		\$0.00
Medium	Work In Progress				12/11/2013 11:20:25				
Flores, Pete		please check radiator to work truck #192. Radiator has a small pin hole leak on the side.							
Johnny Acuna									
111507					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:33 AM				
Acuna, Johnny		Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
110047					11/8/2013		67		\$0.00
Medium	Work In Progress				11/8/2013 8:01:15 AM				
Vallejo, Albert		Need assistance in installing Exit / outdoor lighting to portable.							
Johnny Acuna									
111478					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:17 AM				
Villalobos, David		Yearly - Desert Trail Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
110170					11/13/2013		62		\$0.00
Medium	Work In Progress				11/13/2013 7:49:23 AM				
Marquez, Gerardo		Need keys for teachers and front office to newest portable installed on site. (Portable is now being used as classrooms)							
Johnny Acuna									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Desert Trail Intermediate									
107227					9/9/2013		127		\$0.00
Medium	Work In Progress				9/9/2013 10:17:23 AM				
Marquez, Gerardo	Security Officer for Chaparral (Elementary) Schools: His keys do not open Chaparral Elementary. Please check keys.								
Johnny Acuna									
108601					10/9/2013		97		\$0.00
Medium	Work In Progress				10/9/2013 8:29:51 AM				
Solis, Lorenzo	Rooftop Reznor Heating Unit: South Unit on Westside on main building. Make: Reznor, Model: #HRPB200, Serial: #EAUD66Q2N28275 Needing Pressure Switch for Unit. (Unit does not Ignite and turn on)								
Johnny Acuna									
111306					12/16/2013		29		\$0.00
Medium	Work In Progress	411			12/16/2013 3:12:47 PM				
Solis, Lorenzo	Mr. Guzman in portable #411 needs small refrigerator checked.								
Elizabeth Hernandez									
111240					12/13/2013		32		\$0.00
Medium	Work In Progress				12/13/2013 9:33:05 AM				
Solis, Lorenzo	check valve to pump is leaking in boiler heating system.								
Johnny Acuna									
110532					11/22/2013		53		\$0.00
Medium	Work In Progress				11/22/2013 7:39:48 AM				
Solis, Lorenzo	Need a/c covers: (4) 42" Wide X 34" Long, (3) 49" Wide X 48" Long								
Johnny Acuna									
111044					12/9/2013		36		\$0.00
Medium	Work In Progress				12/9/2013 12:40:09 PM				
Ontiveros, Guadalupe	Need to add top soil and level out playground grass area.								
Johnny Acuna									
111980					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:56 AM				
Sandoval, Laura	Monthly - QRTLY BLDG INSP REPORTS (DT) - Refer to PM schedule details.								
Margret Villalobos									
Count: 29 Work Orders			Avg. Age of WO's 37	Total for Desert Trail Intermediate			0	\$0.00	

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Desert View ES									
109215					10/22/2013		84		\$0.00
High	Work In Progress			10/22/2013 3:53:15 PM					
Ortiz, Ruben	please remove existing drywall around fur-out to hvac ducting and custodial will do a 10% bleach wipe down. thank you								
Michael Munoz									
111518					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress			1/5/2014 12:23:39 AM					
Ortiz, Ruben	Monthly - Desert View ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
103916					7/1/2013		197		\$0.00
Medium	Work In Progress			7/1/2013 1:08:03 PM					
Ontiveros, Guadalupe	Sprinkler on the new soccer field does not shut off; the valve is not working properly.								
Ruben Ortiz									
111971					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress			1/12/2014 12:17:51 AM					
Ortega, Israel	Monthly - QRTLY BLDG INSP REPORT (DV) - Refer to PM schedule details.								
Margret Villalobos									
108266					10/6/2013	11/6/2013	100		\$0.00
Medium	Work In Progress			10/6/2013 12:23:01 AM					
Ortiz, Ruben	Yearly - Desert View ES I-04 Fan Coil Yearly - Refer to PM schedule details.								
Margret Villalobos									
103915					7/1/2013		197		\$0.00
Medium	Work In Progress			7/1/2013 1:06:14 PM					
Ambriz, Jose	Water fountain needs to be replaced in the front office on the east side of the school.								
Ruben Ortiz									
104086					7/8/2013		190		\$0.00
Medium	Work In Progress			7/8/2013 1:30:24 PM					
Ambriz, Jose	A/C UNIT IN KITCHEN WENT OUT. SNP MANAGER DELORES R. 589.2425								
Maritza Gonzalez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
111479					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:17 AM				
Villalobos, David		Yearly - Desert View ES Backflow Inspection - Refer to PMSchedule details.							
Margret Villalobos									
109214					10/22/2013		84		\$0.00
Medium	Work In Progress				10/22/2013 3:49:08 PM				
Castillo, Carlos		Need a light and switch outlet in the morgon.							
Ruben Ortiz									
107805					9/23/2013		113		\$0.00
Medium	Work In Progress				9/23/2013 10:04:11 AM				
Castillo, Carlos		Replace 26 light diffusers							
Ruben Ortiz									
111664					1/6/2014		8		\$0.00
Medium	Work In Progress	LINE LOCATE			1/6/2014 10:41:22 AM				
Ontiveros, Joe		Need Line Locate asp contractor.							
Alfredo Holguin									
108895					10/15/2013		91		\$0.00
Medium	Work In Progress	Lower Grade			10/15/2013 12:54:01				
Ortiz, Ruben		Repair the swings; some are broken and/or tangled.							
Guadalupe Gonzalez									
111602					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:33 AM				
Ortiz, Ruben		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
111603					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:34 AM				
Ortiz, Ruben		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
111567					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:11 AM				
Ortiz, Ruben		Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PMSchedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
108023					9/26/2013		110		\$0.00
Medium	Work In Progress				9/26/2013 4:35:30 PM				
Ortiz, Ruben		09/26/13	As per Principal Arraujo, need to remove white boards to have smartboards installed.						
Ruben Ortiz									
111790		Classroom			1/8/2014		6		\$0.00
Medium	Work In Progress	Rm. #30			1/8/2014 10:24:46 AM				
Ortiz, Ruben		Ceiling in the classroom is leaking. (C. Bryant)							
Guadalupe Gonzalez									
111095		Classroom			12/10/2013		35		\$0.00
Medium	Work In Progress	Rm. #39			12/10/2013 10:58:10				
Ortiz, Ruben		Install metal pencil sharpener in the classroom. (B. Arguelles)							
Guadalupe Gonzalez									
109981		Classroom			11/6/2013		69		\$0.00
Medium	Work In Progress	Rm. #31			11/6/2013 3:18:33 PM				
Ortiz, Ruben		Install two sheetrock boards in the classroom. (A. Spencer)							
Guadalupe Gonzalez									
111759		Classroom			1/7/2014		7		\$0.00
Medium	Work In Progress	Rm. #39			1/7/2014 4:25:51 PM				
Ortiz, Ruben		Fixlegs of two tables in the classroom. (B. Arguelles)							
Guadalupe Gonzalez									
111684		Classroom			1/6/2014		8		\$0.00
Medium	Work In Progress	Port. #A			1/6/2014 3:20:06 PM				
Ortiz, Ruben		Mount the Smartboard projector to the wall. (I. Sanchez)							
Guadalupe Gonzalez									
105293					8/4/2013	8/12/2013	163		\$0.00
Medium	Work In Progress				8/4/2013 12:19:46 AM				
Ortiz, Ruben		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
105291					8/4/2013		163		\$0.00
Medium	Work In Progress				8/4/2013 12:19:45 AM				
Ortiz, Ruben		Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PMSchedule details.							
Margret Villalobos									
1/14/2014 10:19:02 AM									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
105292					8/4/2013	8/12/2013	163		\$0.00
Medium	Work In Progress				8/4/2013 12:19:45 AM				
Ortiz, Ruben		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
105889		Classroom			8/12/2013		155		\$0.00
Medium	Work In Progress	Rm. #31			8/12/2013 3:54:36 PM				
Ortiz, Ruben		Hang the maps in the classrooms. (A. Spencer)							
Guadalupe Gonzalez									
106257		Classroom			8/20/2013		147		\$0.00
Medium	Work In Progress	Rm. #16			8/20/2013 7:44:28 AM				
Ortiz, Ruben		There are ants in the classroom. If can put caulking around the window. (M. Mack)							
Guadalupe Gonzalez									
106767		Office			8/29/2013		138		\$0.00
Medium	Work In Progress	Office			8/29/2013 4:00:39 PM				
Ortiz, Ruben		Assemble desk. (Gonzalez)							
Guadalupe Gonzalez									
106769		Office			8/29/2013		138		\$0.00
Medium	Work In Progress	Office			8/29/2013 4:01:20 PM				
Ortiz, Ruben		Assemble Podium (Gonzalez)							
Guadalupe Gonzalez									
106703					8/29/2013		138		\$0.00
Medium	Work In Progress				8/29/2013 8:26:01 AM				
Ortiz, Ruben		replace sprinklers in the soccer field							
Ruben Ortiz									
110482					11/20/2013		55		\$0.00
Medium	Work In Progress				11/20/2013 4:22:35 PM				
Ortiz, Ruben		Paint the replacement sheetrock in the computer room and lounge							
Ruben Ortiz									
108896					10/15/2013		13		\$0.00
Medium	Work In Progress	Outside the			10/15/2013 1:06:30 PM	10/28/2013			
Ortega, Israel		Put trash cans on the outside of the north upper grade level.				work order was forwarded to building mechanic, need trash barrels			
Guadalupe Gonzalez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
104962					7/31/2013		167		\$0.00
Medium	Work In Progress				7/31/2013 8:07:41 AM				
Gonzalez, Salvador		Vandalism; need a new library stand the was destroyed in vandalism. Thank you, Ruben							
Ruben Ortiz									
111023					12/8/2013	12/24/2013	37		\$0.00
Medium	Work In Progress				12/8/2013 12:18:51 AM				
Ortiz, Ruben		Monthly - Desert View ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
111992					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:18:02 AM				
Ortiz, Ruben		Monthly - Desert View ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
106745	Main Building	Football Field			8/29/2013		138		\$0.00
Medium	Work In Progress	Soccer			8/29/2013 2:13:50 PM				
Ortiz, Ruben		Talked to Ralph Gallegos about 15 minutes ago. Requesting that someone come down and chalk our soccer field with lines. It has become a hazard because kids are playing outside the field. And when kicking the ball, the ball hits another student in the head. With a chalk the kids know the boundaries. Thank you very much							
Albert Ortiz									
107865					9/24/2013		112		\$0.00
Medium	Work In Progress				9/24/2013 1:59:45 PM				
,		NEED TO REPLACED VCT WITH CARPET							
Jesus Estrada									
106701					8/29/2013		138		\$0.00
Medium	Work In Progress				8/29/2013 8:23:55 AM				
Ortiz, Ruben		lower level girls and boys bathroom panels and doors are corroded and need to be replaced.							
Ruben Ortiz									
111791		Classroom			1/8/2014		6		\$0.00
Medium	Work In Progress	Rm. #34			1/8/2014 10:27:03 AM				
Lara, Ralph		The door threshold in the classroom is broken/cracked and needs to be replaced. (B. Aley)							
Guadalupe Gonzalez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To	Description		Action Taken							
Requester Name										
Location: Desert View ES										
105337					8/4/2013	8/10/2013	163		\$0.00	
Medium	Work In Progress				8/4/2013 12:20:05 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.									
Margret Villalobos										
111617					1/5/2014	1/11/2014	9		\$0.00	
Medium	Work In Progress				1/5/2014 12:24:42 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.									
Margret Villalobos										
111894					12/15/2013		30		\$0.00	
Medium	Work In Progress				1/10/2014 11:24:12 AM					
Ronquillo, Ruben	N side entrance, broken window @ door and lock damaged. (Case# 201301433)									
Israel Ortega										
Count: 41 Work Orders			Avg. Age of WO's		83		Total for Desert View ES		0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
111969					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:50 AM				
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
111626					1/5/2014	1/11/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:48 AM				
Moncayo, Fernando		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
111901					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 1:31:38 PM				
Orozco, Daniel		Asp PM serviced by Dimar - Kitchen storage needs to have 18" minimum clearance from sprinkler head.							
Michael Munoz									
111644					1/5/2014	1/26/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:59 AM				
Munoz, Michael		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
107761		Parking Lot			9/20/2013		116		\$0.00
Medium	Work In Progress				9/20/2013 3:45:35 PM				
Ontiveros, Joe		Need to Work on Shed Recived on Constrution shelf ,ect .							
Joe Ontiveros									
111015					12/8/2013	12/24/2013	37		\$0.00
Medium	Work In Progress				12/8/2013 12:18:45 AM				
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
106754		Electrical Room			8/29/2013		138		\$0.00
Medium	Work In Progress				8/29/2013 3:37:47 PM				
Castillo, Carlos		Need to order lumber for storage shelving.							
Carlos Castillo									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
108373					10/6/2013	10/14/2013	100		\$0.00
Medium	Work In Progress				10/6/2013 12:23:53 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111412					12/18/2013		27		\$0.00
Medium	Work In Progress				12/18/2013 3:43:41 PM				
Moncayo, Fernando		INSTALL HANGING FILES ON WALL IN LINDA CASTRO OFFICE.							
Maritza Gonzalez									
111722					1/7/2014		7		\$0.00
Medium	Work In Progress				1/7/2014 10:03:50 AM				
Moncayo, Fernando		Wall unit is not heating properly in Mrs. Reyes (C-wing)..							
Maritza Gonzalez									
111775					1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 8:48:24 AM				
Moncayo, Fernando		BASKETBALL COURTS- SEAL CRACKS, CUT WEEDS, REMOVE SAND FROM COURTS AND SIDEWALKS LEADING TO COURTS. REQUESTING TO USE COURTS WEEK OF 1-13-14. PLEASE NOTIFY MARITZA WHEN COMPLETE. THANK YOU.							
Maritza Gonzalez									
110489					11/21/2013		54		\$0.00
Medium	Work In Progress				11/21/2013 7:41:43 AM				
Moncayo, Fernando		REPLACE FLOOR TILE IN CARMEN MORENOS STORAGE ROOM.							
Maritza Gonzalez									
110499					11/21/2013		54		\$0.00
Medium	Work In Progress				11/21/2013 2:38:43 PM				
Moncayo, Fernando		When possible , we need to move a black cabinet that is in one of the storage rooms back to Mrs. Avila and Mrs. Taylor's office.							
Maritza Gonzalez									
110457					11/20/2013		55		\$0.00
Medium	Work In Progress				11/20/2013 3:18:42 PM				
Moncayo, Fernando		REPLACE EXIT SIGNS IN C-WING.							
Maritza Gonzalez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
109629					11/1/2013		74		\$0.00
Medium	Work In Progress				11/1/2013 2:39:52 PM				
Moncayo, Fernando		LIGHT BLUB IN JESUS OFFICE NOT WORKING.							
Cora Ramirez									
111210					12/12/2013		33		\$0.00
Medium	Work In Progress				12/12/2013 1:32:23 PM				
Moncayo, Fernando		WALL UNIT IN JOSIE PADILLA OFFICE IS NOT HEATING PROPERLY.							
Maritza Gonzalez									
107672					9/18/2013		118		\$0.00
Medium	Work In Progress				9/18/2013 4:32:16 PM				
Moncayo, Fernando		As per Mr. Yturralde, replace all stained ceiling tiles throughout building.							
Maritza Gonzalez									
107673					9/18/2013		118		\$0.00
Medium	Work In Progress				9/18/2013 4:33:48 PM				
Moncayo, Fernando		As per Mr. Yturralde, In Elisa Saenz office, modular furniture rails (6) to be removed and the holes patched. Thank you.							
Maritza Gonzalez									
107163					9/6/2013		130		\$0.00
Medium	Work In Progress				9/6/2013 9:51:03 AM				
Moncayo, Fernando		C-WING-NEED TO REPLACE SEVERAL FLOURESCENT LIGHTS REPLACED IN HALLWAY							
Maritza Gonzalez									
106824					8/30/2013		137		\$0.00
High	Work In Progress				8/30/2013 4:28:45 PM				
Moncayo, Fernando		please remove all sand from parking lots. thank you							
Richard Chavez									
106718					8/29/2013		138		\$0.00
Medium	Work In Progress				8/29/2013 10:35:13 AM				
Moncayo, Fernando		PLEASE PATCH UP HOLES IN WENDY TAYLOR AND LUZ AVILA OFFICE.							
Maritza Gonzalez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
106720					8/29/2013		138		\$0.00
Medium	Work In Progress				8/29/2013 10:35:57 AM				
Moncayo, Fernando		PLEASE PATCH UP HOLES IN GEORGE MANRIQUEZ OFFICE.							
Maritza Gonzalez									
111562					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:08 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111563					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:08 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111676					1/6/2014		8		\$0.00
Medium	Work In Progress				1/6/2014 1:50:53 PM				
Moncayo, Fernando		B-Wing-Human Resources (Mayela office). Tile is lifting in entrance, please replace.							
Maritza Gonzalez									
108879					10/14/2013		92		\$0.00
Medium	Work In Progress				10/14/2013 4:17:10 PM				
Moncayo, Fernando		MRS. YURRALDE OFFICE0 INSTALL 2 SHELVES IN CLOSET.							
Maritza Gonzalez									
109037					10/17/2013		89		\$0.00
Medium	Work In Progress				10/17/2013 3:46:21 PM				
Moncayo, Fernando		10/17/13-1-ckd bldgs, 2.5-107672, 2.5-108945, 1-108447, 1-dailyworklog				10/17- 3 hrs			
Fernando Moncayo									
108418					10/6/2013		100		\$0.00
Medium	Work In Progress				10/6/2013 12:24:13 AM				
Holguin, Alfredo		Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
111535					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:50 AM				
Holguin, Alfredo		Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									
111510					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:34 AM				
Moncayo, Fernando		Monthly - GAC Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
109302					10/24/2013		82		\$0.00
Medium	Work In Progress				10/24/2013 3:18:13 PM				
Castillo, Carlos		emergency power to Jesus Reyes office - technology department							
Cora Ramirez									
111480					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:18 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
109967					11/6/2013		69		\$0.00
Medium	Work In Progress				11/6/2013 11:29:38 AM				
Ambriz, Jose		Mr. Y would like for Jose to come and set the thermostat in his office.							
Maritza Gonzalez									
108942		Parking Lot			10/16/2013		90		\$0.00
Medium	Work In Progress				10/16/2013 7:49:09 AM				
Moncayo, Fernando		need to repaint all parking lot lines - work can be done in phases over weekends by doing schedule adjustment							
Alfredo Holguin									
111437					12/19/2013		26		\$0.00
Medium	Work In Progress				12/19/2013 11:44:45				
Lara, Ralph		our door in the server room - battery not working anymore							
Cora Ramirez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
111958					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:43 AM				
Rodriguez, Arturo		Monthly - QRTLY BLDG INSP REPORT (GAC) - Refer to PM schedule details.							
Margret Villalobos									
111774					1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 8:38:52 AM				
Rodriguez, Arturo		FEDERAL PROGRAMS-NEED HELP MOVING A BOX OF DOCUMENTS FROM WENDY TAYLOR OFFICE TO STORAGE.							
Maritza Gonzalez									
Count: 37 Work Orders		Avg. Age of WO's 57					Total for GAC	0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC - Pre-K									
106574					8/27/2013		140		\$0.00
Medium	Work In Progress				8/27/2013 1:16:12 PM				
Moncayo, Fernando		PRE-K, work order for the installation of a loft in room 102 with Ms. Martha Valtierra. If possible this Friday, Aug. 30th when we do not have students, if not either September 13th or 27th which are also days when we do not have students. Thank you!							
		NancyBellagamba							
Maritza Gonzalez									
111776					1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 8:49:06 AM				
Moncayo, Fernando		LIGHT OUT IN ROOM 201. PLEASE REPLACE.							
Maritza Gonzalez									
111777					1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 8:49:47 AM				
Moncayo, Fernando		REMOVE SAND IN PREK PLAYGROUND.							
Maritza Gonzalez									
111404					12/18/2013		27		\$0.00
Medium	Work In Progress				12/18/2013 3:25:17 PM				
Moncayo, Fernando		HEATER NOT TURNING ON IN ROOM 201.							
Maritza Gonzalez									
Count: 4 Work Orders			Avg. Age of WO's	45		Total for GAC - Pre-K	0		\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden ES									
112013		Hallway/Corridor			1/13/2014		1		\$0.00
Medium	Work In Progress	Washington			1/13/2014 1:03:25 PM				
Appelzoller, Fred		Need for one of the light bulbs to be replaced where the sign is at... thank you							
Loraine Gandara									
109069		Athletic Field			10/18/2013		88		\$0.00
Medium	Work In Progress				10/18/2013 9:58:19 AM				
Appelzoller, Fred		need assistance..... balance beam broke in the jungle gym outside...other two chains are breaking as well.... thank you.....				1/13/14-Routed to Fred			
Loraine Gandara									
104967		Library			7/31/2013		167		\$0.00
Medium	Work In Progress				7/31/2013 9:14:16 AM				
Appelzoller, Fred		need assistance in hanging up some cork strips in the library thank you....				1/13/14-Routed to Fred			
Loraine Gandara									
110344		Classroom			11/18/2013		57		\$0.00
Medium	Work In Progress	209			11/18/2013 10:48:20				
Appelzoller, Fred		need assistance in hanging bulletin boards and maps back to wall thank you				1/13/14-Routed to Fred			
Loraine Gandara									
111561					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:07 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PMschedule details.							
Margret Villalobos									
111559					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:06 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
111560					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:06 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PMschedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden ES							
111997					1/13/2014		1		\$0.00
Medium	Work In Progress				1/13/2014 8:25:19 AM				
Appelzoller, Fred		would greatly appreciate if EXIT sign could be replace or replace batteries... thank you....							
Loraine Gandara									
112012					1/13/2014		1		\$0.00
Medium	Work In Progress				1/13/2014 12:51:59 PM				
Ontiveros, Guadalupe		need assistance with grounds... we will be having YMCA use our soccer fields... and there are a lot of holes... need assistance in preparing grounds for this Saturday... thank you...							
Loraine Gandara									
104416					7/17/2013		181		\$0.00
Medium	Work In Progress				7/17/2013 11:02:33 AM				
Pinion, Jose		asp Ms. Marquez... need all the vents to please be cleaned thru out the school... thank you greatly....							
Loraine Gandara									
108780					10/13/2013	10/29/2013	93		\$0.00
Medium	Work In Progress				10/13/2013 12:20:31				
Pinon, Jose		Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PM schedule details.				HAS NOT BEEN RECEIVED AS COMPLETED AS OF 12/13/13			
Jesus Estrada									
111977					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:54 AM				
Pinon, Jose		Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PM schedule details.							
Margret Villalobos									
111043					12/9/2013		36		\$0.00
Medium	Work In Progress				12/9/2013 12:13:30 PM				
Marquez, Gerardo		Silver working with DOT on setting up new flashing lights at GE. He cannot open box. need help with keys							
Cora Ramirez									
110127		Restroom			11/12/2013		63		\$0.00
Medium	Work In Progress				11/12/2013 12:43:58				
Appelzoller, Fred		in the jefferson hall restroom boys the toilet bowl is plug up the last bowl				1/13/14-Routed to Fred			
Jose Pinion									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Gadsden ES							
111354		Restroom			12/17/2013		28		\$0.00
Medium	Work In Progress				12/17/2013 11:23:34				
Appelzoller, Fred	boys restroom next to the kitchen toilet is not working		1/13/14-Routed to Fred						
Jose Pinion									
111498					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:27 AM				
Villalobos, David	Yearly - Gadsden ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
111351		Classroom			12/17/2013		28		\$0.00
Medium	Work In Progress	308			12/17/2013 10:15:34				
Solis, Lorenzø	need assistance... exhaust fan in room 308 is not working.. would greatly appreciate your assistance in this matter...								
Loraine Gandara									
109459		Classroom			10/29/2013		77		\$0.00
Medium	Work In Progress	104			10/29/2013 9:42:56 AM				
Appelzoller, Fred	Pressure water tank broke and overflow in room 104... thank you greatly for your assistance...		1/13/14-Routed to Fred						
Loraine Gandara									
111145		Classroom			12/11/2013		34		\$0.00
Medium	Work In Progress	205			12/11/2013 9:15:45 AM				
Solis, Lorenzø	" Under Warranty" room 205 air is coming our cold... thank you...								
Loraine Gandara									
111292		Custodial			12/16/2013		29		\$0.00
Medium	Work In Progress				12/16/2013 10:21:44				
Ronquillo, Ruben	i need one gallon of gas 2 cycle oil for blowetr								
Jose Pinion									
111632					1/5/2014	1/16/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:51 AM				
Appelzoller, Fred	Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.								
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden ES									
110692					12/1/2013	12/12/2013	44		\$0.00
Medium	Work In Progress				12/1/2013 12:33:15 AM				
Medina, Eric		Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.							
Margret Villalobos									
111013					12/8/2013	12/24/2013	37		\$0.00
Medium	Work In Progress				12/8/2013 12:18:44 AM				
Medina, Eric		Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
111967					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:49 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
Count: 24 Work Orders			Avg. Age of WO's	42		Total for Gadsden ES	0	0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

111294 12/16/2013 29 \$0.00

Medium Work In Progress 12/16/2013 1:03:16 PM

Orozco, Daniel 3 COMPARTMENT SINK-LEAKING FROM THE PIPES UNDERNEATH SINKS.

Maritza Gonzalez

111295 12/16/2013 29 \$0.00

Medium Work In Progress 12/16/2013 1:06:21 PM

Orozco, Daniel GARGAGE DISPOSAL NOT WORKING PROPERLY, WATER IS COMING OUT OF OTHER AREAS. SNP MANAGER FRANCES B. 882.5522.

Maritza Gonzalez

111296 12/16/2013 29 \$0.00

Medium Work In Progress 12/16/2013 1:10:39 PM

Orozco, Daniel 3 VEGETABLES SINKS HAVING LEAKING FAUCETS. SNP MANAGER FRANCES B. 882.5522.

Maritza Gonzalez

106135 8/16/2013 151 \$0.00

Medium Work In Progress 8/16/2013 8:50:03 AM

Orozco, Daniel kitchen-ladies restroom – toilet, has a crack in the bottom. It is leaking out water and the exhaust does not work.

Maritza Gonzalez

110536 11/22/2013 53 \$0.00

Medium Work In Progress 11/22/2013 9:11:34 AM

Orozco, Daniel FLOOR LIFTED IN WALK IN REFRIGERATOR. SNP MANAGER FRANCES B. 882.5522

Maritza Gonzalez

107324 9/10/2013 126 \$0.00

Medium Work In Progress 9/10/2013 3:49:14 PM

Gonzalez, Salvador Need to install expanded metal plates to the openings of transformers by the treatment plant. size 6inch x 20 inch (6 total).

Guillermo Hernandez

111798 1/8/2014 6 \$0.00

Medium Work In Progress Girls Softball 1/8/2014 12:57:41 PM

Gonzalez, Salvador Secure gate to dugout and install new gate on right field fence.

Michael Munoz

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

107108		Pool			9/5/2013		131		\$0.00
--------	--	------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/5/2013 8:54:25 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Gonzalez, Salvador
9/5/13
We need a welder to repair the stainlees steel recirculating channel where some of the seams are leaking

Raul Sanchez

111627					1/5/2014	1/11/2014	9		\$0.00
--------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				1/5/2014 12:24:49 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillermo
Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

110437		Athletic Field			11/20/2013		55		\$0.00
--------	--	----------------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/20/2013 6:20:10 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
need to remove 4' existing fence and install 6' foot fence with gates. safety issue.

Michael Munoz

107723	Cafeteria (1998)	Restroom			9/20/2013		116		\$0.00
--------	------------------	----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/20/2013 7:07:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo
The first stall is all rusted on the bottom and is no longer blotted to the floor and now moves freely in the air.

Jaime Herrera

111216	Varsity Gym	Gym			12/12/2013		33		\$0.00
--------	-------------	-----	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/12/2013 2:12:32 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique
Requested by Ms. L. Chavez-Need electrical outlet replaced and please check to see if it is working. SEE MS. LILLY CHAVEZ FOR FURTHER INFORMATION AND LOCATION OF OUTLET IN THE VARSITY GYM.

Velia Alarcon

111649					1/5/2014		9		\$0.00
--------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				1/5/2014 12:25:02 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael
Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

108664					10/10/2013		96		\$0.00
--------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/10/2013 7:13:55 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Carbajal, Jimmy
I need the attachments for a backpack vacuum (older version).

Jaime Herrera

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
110552					11/22/2013		53		\$0.00
Medium	Work In Progress				11/22/2013 11:55:24				
Carbajal, Jimmy		I need 7 goggles and a size 11 boots for Basilio S. Also Jimmy if you could please bring me a size 9 boots for an exchange of a size 10 boots.							
Jaime Herrera									
110189					11/13/2013		62		\$0.00
Medium	Work In Progress				11/13/2013 12:58:39				
Carbajal, Jimmy		I need another back pack vacuum the one we got recently is for the weight room and I need the other one for the portables because they are very compacted with desk and hard to move around with a regular vacuum.							
Jaime Herrera									
111280					12/16/2013		29		\$0.00
Medium	Work In Progress				12/16/2013 8:01:28 AM				
Carbajal, Jimmy		I need 2 more flashlights for some of the custodians here that have to travel from building to building at night.							
Jaime Herrera									
111281					12/16/2013		29		\$0.00
Medium	Work In Progress				12/16/2013 8:04:27 AM				
Carbajal, Jimmy		I need 10 rain coats for all custodial staff here so we can be prepared when it rains and not have to be worried about getting wet.							
Jaime Herrera									
111293					12/16/2013		29		\$0.00
Medium	Work In Progress				12/16/2013 11:09:51				
Carbajal, Jimmy		Roto # 99-000009 does not want to turn on.							
Jaime Herrera									
109360		Athletic Field			10/25/2013		81		\$0.00
Medium	Work In Progress				10/25/2013 3:52:51 PM				
Munoz, Michael		please raise or replace 4' fence to 6' with gates as well. thank you							
Michael Munoz									
112009	Main Building	Classroom			1/13/2014		1		\$0.00
Medium	Work In Progress	104			1/13/2014 10:45:41 AM				
Hernandez, Guillermo		Requested by Mr. R. Ramos Rm. 104 Storage Room inside classroom of the Main Building-We have very OLD chemicals that need to be properly disposed of.							
Velia Alarcon									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Gadsden HS									
105583	Nursing Center				8/7/2013		160		\$0.00
Medium	Work In Progress				8/7/2013 11:27:47 AM				
Ontiveros, Guadalupe	Requested by Mr. D. Martinez for Parking Area next to Nurse's Office-Requesting parking stops to be added to parking spaces from Nurse's Office area to Cafeteria area. PLEASE SEE MR. MARTINEZ FOR FURTHER INSTRUCTION.								
Velia Alarcon									
110110	Vocational				11/12/2013		63		\$0.00
Medium	Work In Progress				11/12/2013 8:26:19 AM				
Villalobos, David	need to replace activating paddle for emergency eyewash in auto shop								
Daniel Sotelo									
109381	Vocational	Restroom			10/28/2013		78		\$0.00
Medium	Work In Progress				10/28/2013 9:05:03 AM				
Villalobos, David	The sink on the very far left near the wall is leaking where the trap is (constant drip).								
Jaime Herrera									
109015	Pool Pump	Pool			10/17/2013		89		\$0.00
Medium	Work In Progress				10/17/2013 3:07:03 PM				
Apodaca, Mario	need to replace all pool ladders at pool do to wear and tear								
Mario Apodaca									
109016	Pool Pump	Pool			10/17/2013		89		\$0.00
Medium	Work In Progress				10/17/2013 3:10:55 PM				
Apodaca, Mario	need to order pool chemicals and equipment								
Mario Apodaca									
110893	Grounds Shop				12/5/2013		40		\$0.00
Medium	Work In Progress				12/5/2013 1:09:29 PM				
Sotelo, Enrique	12/05/13 need an electrician to connect the power to electric water heater for the Grounds Shop kitchen/break room. Thanks, Raul								
Raul Sanchez									
111671	Community				1/6/2014		8		\$0.00
Medium	Work In Progress				1/6/2014 1:20:40 PM				
Ronquillo, Ruben	Re-upholster all benches and torn pads on weight training equipment								
Alfredo Holguin									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

112044	Community	Restroom			1/14/2014		0		\$0.00
--------	-----------	----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/14/2014 7:17:39 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Guillemo
 Guillermo the urinal is not working properly, the water goes down very slowly and every time it is flushed the water gathers up and over flows.

Jaime Herrera

111762	Old English Bldg	Classroom			1/8/2014		6		\$0.00
--------	------------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	134			1/8/2014 7:20:52 AM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Herrera, Jaime
 Remove all items from portable 6 and transfer all item in room 134 to portable 6.

Jaime Herrera

112007	Academic Bldg	Classroom			1/13/2014		1		\$0.00
--------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	331			1/13/2014 10:40:43 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lara, Ralph
 Requested by Ms. Hartmann Rm. 331 Academic Building-Locks for outside doors need to be worked on. They currently do not lock or unlock the doors. PLEASE SEE MS. HARTMANN FOR MORE INSTRUCTION.

Velia Alarcon

112008	Academic Bldg	Classroom			1/13/2014		1		\$0.00
--------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	331			1/13/2014 10:43:20 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lara, Ralph
 Requested by Ms. Hartmann Rm. 331 Academic Building-A new lock is needed to secure storage room. Currently does not lock.

Velia Alarcon

110490	Academic Bldg	Classroom			11/21/2013		54		\$0.00
--------	---------------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/21/2013 8:21:44 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
 Requested by Mr. Cordova Rm 331 Academic Building- Prop room door handle is completely broken and needs to be replaced. Currently cannot get into prop/storage room.

Velia Alarcon

111799	Academic Bldg	Classroom			1/8/2014		6		\$0.00
--------	---------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	336			1/8/2014 1:00:24 PM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Hernandez, Guillemo
 Requested by Mr. Nunez Rm. 336 Academic Building- Heater not working.

Velia Alarcon

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

111289 Academic Bldg 12/16/2013 29 \$0.00

Medium Work In Progress 12/16/2013 9:29:14 AM

Sotelo, Daniel secured area do to break in over the weekend in academic building on Saturday

Daniel Sotelo

111499 1/5/2014 1/8/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:23:27 AM

Sotelo, Daniel Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.

Margret Villalobos

111716 1/7/2014 7 \$0.00

Medium Work In Progress LINE LOCATE 1/7/2014 8:28:51 AM

Sotelo, Enrique Lynco will be drilling Gadsden on Thursday, 01/16/2014 and will need utilities located. They have the piers marked on the ground and will need your district to locate any utilities underground at these locations.

Rafael Gallegos

111833 1/9/2014 5 \$0.00

Medium Work In Progress LINE LOCATE 1/9/2014 11:26:10 AM

Sotelo, Enrique Chris Sepdalieri - A-Mountain Construction 575-525-1405

FR ANTHONY W ON WASHINGTON ST TRN L ON NM28 TO ADDRESS ON RIGHT CONT INTO SW CORNER OF SCHOOLYARD AND SWIMMING POOL COMPLEX: SPOT ADJACENT ROADWAY ABOUT 200FT/LENGTH OF SWIMMING POOL BLDG.

Alfredo Holguin

109351 Athletic Field 10/25/2013 81 \$0.00

Medium Work In Progress 10/25/2013 3:37:05 PM

Sotelo, Enrique new batting cages will be built. please provide power to cages for pitching machines. thank you see mike for details

Michael Munoz

108882 10/15/2013 91 \$0.00

Medium Work In Progress 10/15/2013 7:36:05 AM

Sotelo, Enrique Need assistance to trouble shoot electric outlet in the welding shop 230 volts.

Guillermo Hernandez

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

109324					10/25/2013		81		\$0.00
Medium	Work In Progress				10/25/2013 7:49:07 AM				
Sotelo, Enrique		Need to replace automatic (sensor) light switch in the custodial closet at the Administration building.							
Guillermo Hernandez									
107058					9/4/2013		132		\$0.00
Medium	Work In Progress				9/4/2013 12:02:49 PM				
Sotelo, Enrique		Light fixture on the marque is broken on the terminal and is burning the lamps, light fixture needs to be replaced.							
Guillermo Hernandez									
108046					9/27/2013		109		\$0.00
Medium	Work In Progress				9/27/2013 2:28:05 PM				
Sotelo, Enrique		Bus Turnaround - Need to provide power to lift station to prevent future flooding. (See Mike for details).							
Michael Munoz									
109631					11/1/2013		74		\$0.00
Medium	Work In Progress				11/1/2013 2:50:12 PM				
Villalobos, David		Need assistance to repair hanging toilet, water is leaking behind the wall. Boys restroom Annexbuilding.							
Guillermo Hernandez									
110546					11/22/2013		53		\$0.00
Medium	Work In Progress	LINE LOCATE			11/22/2013 10:54:03				
Villalobos, David		Please put in a WO for locates at GHS (open your e-mail for drawing) for December 2, 2013. Call me if you have any questions. Thanks.							
Rafael Gallegos									
111715					1/7/2014		7		\$0.00
Medium	Work In Progress	LINE LOCATE			1/7/2014 8:28:08 AM				
Villalobos, David		Lynco will be drilling Gadsden on Thursday, 01/16/2014 and will need utilities located. They have the piers marked on the ground and will need your district to locate any utilities underground at these locations.							
Rafael Gallegos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

112010 1/13/2014 1 1/13/2014 10:50:12 AM \$0.00

Medium Work In Progress 1/13/2014 10:50:12 AM

Villalobos, David Requested by Mrs. Hamilton for Greenhouse in New CTE Building-There was a freeze in the greenhouse and the brass fitting on the North Side has a leak. At the present time it is a pin hole leak, but water is 24 hours present. SEE MRS. HAMILTON FOR EXACT LOCATION.

Velia Alarcon

111834 1/9/2014 5 1/9/2014 11:26:50 AM \$0.00

Medium Work In Progress LINE LOCATE 1/9/2014 11:26:50 AM

Villalobos, David Chris Sepdalieri - A-Mountain Construction 575-525-1405

FR ANTHONY W ON WASHINGTON ST TRN L ON NM28 TO ADDRESS ON RIGHT CONT INTO SW CORNER OF SCHOOLYARD AND SWIMMING POOL COMPLEX: SPOT ADJACENT ROADWAY ABOUT 200FT/LENGTH OF SWIMMING POOL BLDG.

Alfredo Holguin

108045 9/27/2013 109 9/27/2013 2:27:09 PM \$0.00

Medium Work In Progress 9/27/2013 2:27:09 PM

Villalobos, David Bus Turnaround - Need to install lift station and storm drains to prevent future flooding. (See Mike for details).

Michael Munoz

111481 1/5/2014 2/5/2014 9 1/5/2014 12:23:18 AM \$0.00

Medium Work In Progress 1/5/2014 12:23:18 AM

Villalobos, David Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

104583 7/22/2013 176 7/22/2013 3:49:21 PM \$0.00

Medium Work In Progress 7/22/2013 3:49:21 PM

Villalobos, David Need to replace gasket to shower in the Sped classroom at the Annex building.

Guillermo Hernandez

108987 10/16/2013 90 10/16/2013 4:12:21 PM \$0.00

Medium Work In Progress 10/16/2013 4:12:21 PM

Villalobos, David Annex building in special ed classroom shower head is leaking needs to be replaced

Daniel Sotelo

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
108988					10/16/2013		90		\$0.00
Medium	Work In Progress				10/16/2013 4:13:50 PM				
Villalobos, David		In weight room girls bathroom shower head is leaking needs to be replaced							
Daniel Sotelo									
105909					8/13/2013		154		\$0.00
Medium	Work In Progress				8/13/2013 8:54:59 AM				
Marquez, Gerardo		Please locate and install two (2) metal doors at the shed east of the green house at Gadsden High School. Installation to include hardware and should be completed by August 27, 2013. For questions or more information please contact Mr. Ralph Gallegos at 575-882-6921.							
Dominique Esparza									
108807					10/14/2013		92		\$0.00
Medium	Work In Progress				10/14/2013 8:54:03 AM				
Marquez, Gerardo		Need to check cylinder for Old English #141, teacher can not open doors.							
Guillermo Hernandez									
105469					8/6/2013		161		\$0.00
Medium	Work In Progress				8/6/2013 9:25:16 AM				
Ambriz, Jose		Requested by Staff in Academic Building-Water fountain near boy's restroom closest to cafeteria is not working.							
Velia Alarcon									
110383					11/19/2013		56		\$0.00
Medium	Work In Progress				11/19/2013 7:54:15 AM				
Ambriz, Jose		Need assistance to trouble shoot fan coils (heating unit) for the Old English.							
Guillermo Hernandez									
110294					11/15/2013		60		\$0.00
Medium	Work In Progress				11/15/2013 9:48:05 AM				
Ambriz, Jose		Need assistance trouble shooting fresh air heaters units for the Old English building.							
Guillermo Hernandez									
110323					11/15/2013		60		\$0.00
Medium	Work In Progress				11/15/2013 3:56:44 PM				
Ambriz, Jose		Need to replace motors for the heating units in Old English #148, #146 and mechanical room.							
Guillermo Hernandez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
108983					10/16/2013		90		\$0.00
Medium	Work In Progress				10/16/2013 4:00:41 PM				
Ambriz, Jose		Need to install filter system for the ice machines in three buildings.							
Guillermo Hernandez									
108985					10/16/2013		90		\$0.00
Medium	Work In Progress				10/16/2013 4:02:28 PM				
Ambriz, Jose		Need to replace three ignition modules for the reznors furnaces at the cafeteria. (Joe has the ignition module).							
Guillermo Hernandez									
107034					9/3/2013		133		\$0.00
Medium	Work In Progress				9/3/2013 3:52:55 PM				
Ambriz, Jose		Need to replace exhaust fan motors in the weight room (Jose has sample motor).							
Guillermo Hernandez									
112039					1/13/2014		1		\$0.00
Medium	Work In Progress				1/13/2014 3:59:51 PM				
Lara, Ralph		Rafa need two keys he125 and m98 thanks							
Daniel Sotelo									
105950					8/13/2013		154		\$0.00
Medium	Work In Progress				8/13/2013 3:24:35 PM				
Ontiveros, Guadalupe		Requested by Mr. Villa-Need the practice fields lined for band rehearsal as soon as possible and to continue up until the middle of November.							
Velia Alarcon									
112006					1/13/2014		1		\$0.00
Medium	Work In Progress				1/13/2014 10:37:11 AM				
Lara, Ralph		Requested by Velia-Two 1HE1 keys are needed for outside doors to gain access to room # 233 (Old Panther Hut).							
Velia Alarcon									
111767					1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 7:45:52 AM				
Lara, Ralph		Need to replace door knob to the inside door in Portable #6. Social Worker moved in to the Portable.							
Guillermo Hernandez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
110840					12/4/2013		41		\$0.00
Medium	Work In Progress				12/4/2013 11:05:26 AM				
Ontiveros, Guadalupe		Requested by Coach Walker-The discus/shot put cage needs to be put up for practice.							
Velia Alarcon									
111350					12/17/2013		22		\$0.00
Medium	Work In Progress				12/17/2013 10:05:06	1/8/2014			
Herrera, Jaime		I need a cordless drill, that way I could install dispensers when needed.							
Jaime Herrera									
111975					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:53 AM				
Herrera, Jaime		Monthly - QRTLY BLDG INSP REPORT (GH) - Refer to PM schedule details.							
Margret Villalobos									
111781					1/8/2014		6		\$0.00
High	Work In Progress				1/8/2014 9:00:08 AM				
Lara, Ralph		Ramiro Holgin needs GM-7 and GM-6 KEYS.							
Ramiro Holguin									
109345		Athletic Field			10/25/2013		81		\$0.00
Medium	Work In Progress				10/25/2013 3:31:19 PM				
Ontiveros, Guadalupe		boys baseball. batting cages will be removed and new ones will be built. please level ground area and lay 4" base coarse with 3" primary screening, level and roll. must be level. thank you							
Michael Munoz									
109347		Athletic Field			10/25/2013		81		\$0.00
Medium	Work In Progress				10/25/2013 3:34:03 PM				
Ontiveros, Guadalupe		please remove tree in batting cage area. boys baseball. thank you							
Michael Munoz									
110632					12/1/2013	12/9/2013	44		\$0.00
Medium	Work In Progress				12/1/2013 12:32:46 AM				
Herrera, Joel		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
110631					12/1/2013	1/1/2014	44		\$0.00
Medium	Work In Progress				12/1/2013 12:32:45 AM				
Herrera, Joel		Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
111585					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:22 AM				
Hernandez, Guillermo		Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111584					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:21 AM				
Hernandez, Guillermo		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111102					12/10/2013		35		\$0.00
Medium	Work In Progress				12/10/2013 2:54:47 PM				
Flores, Pete		Requested by Mr. Smythe for Vehicle # 120- ATTENTION PETE- Repair of fuel leak. As well as service the two filters on vehicle. Install or replace side view mirror.							
Velia Alarcon									
110330					11/16/2013		59		\$0.00
Medium	Work In Progress				11/16/2013 12:18:09				
Flores, Pete		Yearly - Gadsden HS- Mow (0408/0419/0428) Grounds - Refer to PM schedule details.							
Margret Villalobos									
107848		Athletic Field			9/24/2013		112		\$0.00
Medium	Work In Progress				9/24/2013 7:56:38 AM				
Flores, Pete		997 mower will not move forward or backward.							
Guadalupe Ontiveros									
111511					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:35 AM				
Hernandez, Guillermo		Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
111534					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:49 AM				
Holguin, Alfredo		Monthly - Gadsden HS - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
108417					10/6/2013		100		\$0.00
Medium	Work In Progress				10/6/2013 12:24:13 AM				
Holguin, Alfredo		Monthly - Gadsden HS - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
111529					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:46 AM				
Holguin, Alfredo		Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									
110497					11/21/2013		54		\$0.00
Medium	Work In Progress				11/21/2013 1:20:16 PM				
Sotelo, Daniel		Requested by Cathy-Teachers need US & NM flags mounted on walls. PLEASE SEE MARIA FOR LIST.							
Velia Alarcon									
108412					10/6/2013		100		\$0.00
Medium	Work In Progress				10/6/2013 12:24:10 AM				
Holguin, Alfredo		Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.							
Margret Villalobos									
110535					11/22/2013		53		\$0.00
Medium	Work In Progress				11/22/2013 9:10:15 AM				
Hernandez, Guillermo		CEILING TILES IN KITCHEN AREA NEED TO BE REPLACED. SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
110355					11/18/2013		57		\$0.00
Medium	Work In Progress				11/18/2013 3:18:31 PM				
Hernandez, Guillermo		Requested by Ms. Servin-Eight parking poles for "reserved" parking in designated areas. PLEASE SEE CATHY FOR MORE INFORMATION.							
Velia Alarcon									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
111828					1/9/2014		5		\$0.00
Medium	Work In Progress				1/9/2014 10:36:34 AM				
Hernandez, Guillermo		Requested by Administration-ATTENTION MEMO HERNADNEZ-Assistance is needed in moving teachers into the New Science Building and the two remodeled classrooms in the North Building. The move will take place beginning Thursday, Jan. 9, 2014 and on the 10th, 13th, 14th, and 15th of January.							
Velia Alarcon									
111832					1/9/2014		5		\$0.00
Medium	Work In Progress				1/9/2014 11:00:09 AM				
Hernandez, Guillermo		Requested by Ms. Anderson Rm. 515 New CTE Building -Drinking fountain not working in Panther Hut kitchen.							
Velia Alarcon									
111546					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:57 AM				
Sotelo, Daniel		Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
111547					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:57 AM				
Sotelo, Daniel		Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
109343		Athletic Field			10/25/2013		81		\$0.00
Medium	Work In Progress				10/25/2013 3:28:48 PM				
Gonzalez, Salvador		please remove existing batting cages and build new ones. boys baseball. thank you (7)							
Michael Munoz									
109350		Athletic Field			10/25/2013		81		\$0.00
Medium	Work In Progress				10/25/2013 3:35:29 PM				
Gonzalez, Salvador		please replace door to morgan building by batting cages. boys baseball. thank you							
Michael Munoz									
111244					12/13/2013		32		\$0.00
High	Work In Progress				12/13/2013 11:16:36				
Villalobos, Margaret		please spray for bugs in rm 106. ms.arredondos.							
Michael Munoz									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
111613					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:40 AM				
Sanchez, Raul		Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
110229					11/14/2013		61		\$0.00
Medium	Work In Progress				11/14/2013 12:22:11				
Sanchez, Raul		Monthly - Gadsden HS- Filters (Pump Rm) Quarterly - Refer to PM schedule details.							
Margret Villalobos									
111614					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:41 AM				
Sanchez, Raul		Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
105981					8/14/2013		153		\$0.00
Medium	Work In Progress				8/14/2013 12:16:36 AM				
Sanchez, Raul		Monthly - Gadsden HS- Filters (Pump Rm) Quarterly - Refer to PM schedule details.							
Margret Villalobos									
106845					9/1/2013		135		\$0.00
Medium	Work In Progress				9/1/2013 12:29:17 AM				
Sanchez, Raul		Monthly - Gadsden HS - Grease Trap (Culinary/Auto) - Refer to PM schedule details.							
Margret Villalobos									
Count: 99 Work Orders			Avg. Age of WO's	55		Total for Gadsden HS	0		\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden MS							
111607					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:36 AM				
Apodaca, Mario		Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
109564					10/31/2013		75		\$0.00
Medium	Work In Progress				10/31/2013 12:28:45				
Apodaca, Mario		Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111612					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:39 AM				
Apodaca, Mario		Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
111884					1/10/2014		4		\$0.00
Medium	Work In Progress	LINE LOCATE			1/10/2014 8:58:38 AM				
Apodaca, Mario		Frank Sloan - EBID 575-639-4385							
Alfredo Holguin		FRM ANTHONY DR (NM-460) AND WASHINGTON ST (NM-225), GO W ON WASHIINGTON ST 1.24MI TO START OF JOB SITE. SPOT:60FT WIDE PATCH ON BOTH SIDES OF DRAIN FRM BEGINNING STAKE GO SE ON DRAIN TO ENDING STAKE AT 1ST CROSSING APPR 0.24MI IN LENGTH.							
110767		Gym			12/3/2013		42		\$0.00
Medium	Work In Progress				12/3/2013 10:06:01 AM				
Miranda, Danny		lobby area, remove a portion of a wall to include wall tile. tile needs to be removed carefully so that it can be re-used. see mike for details. thank you							
Michael Munoz									
111788		Classroom			1/8/2014		6		\$0.00
Medium	Work In Progress	room 152			1/8/2014 10:17:37 AM				
Diaz, Sebastian		Miss Hidalgo needs the whiteboards in her classroom re-arranged.							
Nancy Tinajero									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
110527					11/21/2013		54		\$0.00
Medium	Work In Progress				11/21/2013 4:10:14 PM				
Diaz, Sebastian		By Morgan Bldg, dispose of desk and chairs in dumpster and the ones that are good take to SM							
Michael Munoz									
111504					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:31 AM				
Diaz, Sebastian		Monthly - Gadsden MS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
111973					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:52 AM				
Acosta, Juan		Monthly - QRTLY BLDG INSP REPORT (GM) - Refer to PM schedule details.							
Margret Villalobos									
110066					11/8/2013		67		\$0.00
Medium	Work In Progress				11/8/2013 2:14:46 PM				
Solis, Lorenzo		Need to fix fan motor on heater gym roof top thank you							
Sebastian Diaz									
109897		Classroom			11/5/2013		70		\$0.00
Medium	Work In Progress	Room 169			11/5/2013 10:25:25 AM				
Marquez, Gerardo		Key needed for filing cabinet and desk							
Nancy Tinajero									
105924		Custodial			8/13/2013		154		\$0.00
Medium	Work In Progress				8/13/2013 12:53:11 PM				
Marquez, Gerardo		WE ALSO NEED AN EXTRA KEY MADE FOR OUR NIGHT CUSTODIAN THIS KEY IS FOR THE JOHN DEER GATOR							
Juan Acosta									
108839					10/14/2013		92		\$0.00
Medium	Work In Progress				10/14/2013 1:21:24 PM				
Marquez, Gerardo		MR. BAKER NEEDS TO GET HIS MASTER KEY FOR KITCHENS CHECKED, HE IS STILL NOT ABLE TO OPEN KITCHEN AT MESQUITE ELEM.							
Maritza Gonzalez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

108201 10/2/2013 104 \$0.00

Medium Work In Progress 10/2/2013 9:48:32 AM

Villalobos, David need to get water line to planters between gym and main building.

Alfredo Holguin

110774 12/3/2013 42 \$0.00

Medium Work In Progress LINE LOCATE 12/3/2013 12:28:37 PM

Villalobos, David Company: DECKER PLUMBING INC.
Contact Name: TIM DECKER
Phone: (575)524-7917

FRM: ANTHONY AT NM-478 & NM-225 (WASHINGTON ST), TRN L ON NM-225 & GO W TO LOCATION ON THE S SIDE.
SPOT: ENTIRE LOT USING PAINT & FLAGS
AREA MARKED W/ WHITE PAINT. NO
HAZARDS/ OPEN ACCESS

Alfredo Holguin

111336 12/17/2013 28 \$0.00

Medium Work In Progress LINE LOCATE 12/17/2013 7:46:45 AM

Villalobos, David Company: TRIPLE J EXCAVATION
Contact Name: ANNETTE GRANADO Contact
Phone: (575)527-1763

PROPERTY IS GADSDEN MIDDLE SCHOOL, FRM THE INTERSECTION OF S MAIN ST & WASHINGTON, GO W ON WASHINGTON FOR APPROX. 1.44MI TO SCHOOL. GO INTO SCHOOL PROPERTY & GO TO GAS PUMP LOCATED BEHIND FOOTBALL FIELD,

Alfredo Holguin

110842 12/4/2013 41 \$0.00

Medium Work In Progress 12/4/2013 11:47:22 AM

Villalobos, David Need to check drain pipe on B wing thank you

Sebastian Diaz

109551 10/30/2013 76 \$0.00

Medium Work In Progress 10/30/2013 3:37:56 PM

Villalobos, David Need to check bad odor on custodian closer on B wing thank you

Sebastian Diaz

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
111482					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:19 AM				
Villalobos, David		Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
111845					1/9/2014		5		\$0.00
Medium	Work In Progress				1/9/2014 3:15:14 PM				
Solis, Lorenz		Need to check boiler room on gym thank you							
Sebastian Diaz									
111752					1/7/2014		7		\$0.00
Medium	Work In Progress				1/7/2014 3:28:48 PM				
Sotelo, Enrique		need assistance in changing out a switch float at the domestic water tank gadsden middle school							
Mario Apodaca									
111883					1/10/2014		4		\$0.00
Medium	Work In Progress	LINE LOCATE			1/10/2014 8:57:42 AM				
Sotelo, Enrique		Frank Sloan - EBID 575-639-4385							
		FRM ANTHONY DR (NM-460) AND WASHINGTON ST (NM-225), GO W ON WASHIINGTON ST 1.24MI TO START OF JOB SITE. SPOT:60FT WIDE PATCH ON BOTH SIDES OF DRAIN FRM BEGINNING STAKE GO SE ON DRAIN TO ENDING STAKE AT 1ST CROSSING APPR 0.24MI IN LENGTH.							
Alfredo Holguin									
111897	Main Building				1/10/2014		4		\$0.00
Medium	Work In Progress	Door next to			1/10/2014 11:33:51 AM				
Marquez, Gerardo		Handicap door in B wing will not open. Its the door close to room 118.							
Nancy Tinajero									
106140	Annex	Restroom			8/16/2013		151		\$0.00
Medium	Work In Progress	STAFF			8/16/2013 10:16:55 AM				
Marquez, Gerardo		CAN NOT OPEN DOOR WITH KEY A.S.A.P							
Juan Acosta									
110796		Gym			12/3/2013		42		\$0.00
Medium	Work In Progress				12/3/2013 3:40:29 PM				
Estrada, Jesus		please replace vct flooring in lobby area of gym. thank you.							
Michael Munoz									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Gadsden MS										
111866	C-Wing	Office			1/9/2014		5		\$0.00	
Medium	Work In Progress	207-C			1/9/2014 3:55:28 PM					
Diaz, Sebastian										
Please replace the thermostat in nursing office. It is set at 68 degrees yet it is 77 degrees in our office. Thank you, Colleen										
Colleen Runyan										
111358	C-Wing				12/17/2013		28		\$0.00	
Safety	Work In Progress				12/17/2013 12:21:17					
Diaz, Sebastian										
All Portable Ramps at C-Wing - Asp Mr. Chavez he wants all ramps replaced w/new boards. Please see him.										
Richard Chavez										
111401					12/18/2013		27		\$0.00	
Medium	Work In Progress	Gym area and			12/18/2013 12:22:29					
Gonzalez, Salvador										
Set up new benches in area between canopies and gym area. See Mrs. Quinonez for instructions										
Nancy Tinajero										
Count: 28 Work Orders		Avg. Age of WO's 42		Total for Gadsden MS				0	\$0.00	

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union - JTP Alvarez Farms									
109321					10/24/2013		82		\$0.00
Medium	Work In Progress				10/24/2013 4:13:59 PM				
Briones, Enrique		Relocate 3 cubicals from the 2nd floor to Anthony Elem - Sped Bldg - Coordinate with Mike M. He will provide assistance							
Margaret Villalobos									
108899					10/15/2013		91		\$0.00
Medium	Work In Progress				10/15/2013 1:15:45 PM				
Carrasco, Danny		need to use chain saw to remove trees far back yard - thanks for the help							
Patricio Aguilar									
111197					12/12/2013		33		\$0.00
Medium	Work In Progress				12/12/2013 9:15:30 AM				
Carrasco, Danny		PLEASE MOVE ALL BOXES LABELED FOR HILARIO MELENDEZ TO GADSDEN HIGH SCHOOL OLD ENGLISH BUILDING ROOM @#110.							
Margaret Villalobos									
Count: 3 Work Orders			Avg. Age of WO's	69	Total for La Union - JTP Alvarez Farms			0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
111021					12/8/2013	12/24/2013	37		\$0.00
Medium	Work In Progress				12/8/2013 12:18:49 AM				
Aguilar, Patricio		Monthly - La Union ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
111985					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:59 AM				
Aguilar, Patricio		Monthly - La Union ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
111577					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:17 AM				
Aguilar, Patricio		Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111578					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:17 AM				
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111569					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:12 AM				
Aguilar, Patricio		Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
106092					8/15/2013		152		\$0.00
Medium	Work In Progress				8/15/2013 3:17:38 PM				
Aguilar, Patricio		wo to myself - need to replace door hinge girls rest room stall							
Patricio Aguilar									
107360					9/11/2013		125		\$0.00
Medium	Work In Progress				9/11/2013 2:53:28 PM				
Aguilar, Patricio		wo to myself - need to replace filter on new ac old hall way							
Patricio Aguilar									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

107469 9/16/2013 120 \$0.00

High Work In Progress 9/16/2013 7:20:19 AM

Ontiveros, Joe
need to install sweat copper fittings to copper and cap off to connect domestic to irrigation water for the future. please leave the rest of the material to connect the water in the boiler room to use in case of no water or emergency supply.

Michael Munoz

111485 1/5/2014 2/5/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:23:20 AM

Villalobos, David
Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

107470 9/16/2013 120 \$0.00

High Work In Progress 9/16/2013 7:26:03 AM

Aguilar, Patricio
please make sure all water to fountains are shut off to include outside hose bibs till further notice. thank you

Michael Munoz

111515 1/5/2014 1/13/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:23:37 AM

Aguilar, Patricio
Monthly - La Union ES Roof Inspection - Refer to PM schedule details.

Margret Villalobos

108793 10/13/2013 10/29/2013 93 \$0.00

Medium Work In Progress 10/13/2013 12:20:37

Ramos, Rudy
Monthly - QRTLY BLDG INSP REPORT (LU) - Refer to PM schedule details. HAS NOT BEEN RECEIVED OR COMPLETED AS OF 12/13/13

Jesus Estrada

111990 1/12/2014 1/28/2014 2 \$0.00

Medium Work In Progress 1/12/2014 12:18:01 AM

Ramos, Rudy
Monthly - QRTLY BLDG INSP REPORT (LU) - Refer to PM schedule details.

Margret Villalobos

106448 Custodial 8/23/2013 90 \$0.00

Medium Work In Progress 8/23/2013 9:00:49 AM 11/21/2013

Carbajal, Jimmy
The bottom plate of the Adfinity shower scubber is not making full contact with the machine itself. Does not spin properly. REPLACED ON BOARD BATTERY CHARGER

Rudy Ramos

1/14/2014 10:19:04 AM

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: La Union ES

111619 1/5/2014 1/11/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:24:44 AM

Aguilar, Patricio Monthly - La Union ES Monthly FE Inpsection - Refer to PM schedule details.

Margret Villalobos

107436 Main Building Mechanical 9/13/2013 123 \$0.00

Medium Work In Progress 9/13/2013 2:44:55 PM

Ontiveros, Joe

No Domestic water to school property Cause to County water Service Issues. Tie water well to Domestic water with County Approval. As per Supervisor.

Joe Ontiveros

105729 Main Building Classroom 8/9/2013 158 \$0.00

Medium Work In Progress 8/9/2013 9:10:44 AM

Lara, Ralph One of the doors in room 102 needs a cylinder.

Rudy Ramos

Count: 17 Work Orders Avg. Age of WO's 63 Total for La Union ES 0 \$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
110064	Main Building	Custodial			11/8/2013		67		\$0.00
Medium	Work In Progress				11/8/2013 12:24:34 PM				
Carbajal, Jimmy		NEED SERVICE FOR MY VACUUM CLEANER (CO7C00000024)MAKES A VERY STRONG AND BAD NOISE .,SMELL BURN.,THANKS.							
Luis Solis									
106997	Main Building	Office			9/3/2013		133		\$0.00
Medium	Work In Progress	Principals Office			9/3/2013 10:48:31 AM				
Estrada, Jesus		Carpet in the office has a hole, needs to be repaired							
Angie Flores									
105109	Main Building	Restroom			8/2/2013		165		\$0.00
Medium	Work In Progress				8/2/2013 8:04:50 AM				
Villalobos, David		Need to replace remaining wash basins at bys and girls restroom							
David Villalobos									
107851	Main Building	Office			9/24/2013		112		\$0.00
Medium	Work In Progress	Nurses Office			9/24/2013 8:43:40 AM				
Marquez, Gerardo		Lock on Medicine cabinet is broken, need an extra key for storage room in nurses office. Lock on hallway door to be changed to be locked from the inside.							
Angie Flores									
108825	Main Building				10/14/2013		92		\$0.00
Medium	Work In Progress	Nurses Office			10/14/2013 11:36:02				
Marquez, Gerardo		New Lock for Large Medicine Cabinet							
Angie Flores									
108563	Main Building	Office			10/8/2013		98		\$0.00
Medium	Work In Progress	Nurses Office			10/8/2013 10:13:13 AM				
Marquez, Gerardo		Need a copy of the nurses key for the office, G18							
Angie Flores									
106797	Main Building	Restroom			8/30/2013		137		\$0.00
Medium	Work In Progress	In Front of Mrs.			8/30/2013 10:48:44 AM				
Marquez, Gerardo		Stall doors in the boys restroom in front of Mrs. Whites room dont lock							
Angie Flores									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
110393	Main Building	Custodial			11/19/2013		56		\$0.00
Medium	Work In Progress				11/19/2013 9:51:01 AM				
Carbajal, Jimmy		NEED THREE (3) ROYAL BELTS,, ONE (1) ROYAL BRUSH,, AND ONE (1) ROYAL BAG,, THANKS.							
Luis Solis									
111837	Main Building	Classroom			1/9/2014		5		\$0.00
Medium	Work In Progress	205			1/9/2014 1:26:31 PM				
Medina, Eric		Lights flick on and off, some missing							
Angie Flores									
111440	Main Building	Classroom			12/19/2013		26		\$0.00
Medium	Work In Progress	Computer Lab			12/19/2013 1:17:27 PM				
Medina, Eric		The computer lab needs more lighting, The classroom is too dark. there are many light bulbs that are not working, that need to be replaced or the fixture replaced.							
Angie Flores									
111742					1/7/2014		7		\$0.00
Medium	Work In Progress				1/7/2014 3:04:27 PM				
Flores, Pete		Pete need to request bobcat							
Eric Medina									
111631					1/5/2014	1/11/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:51 AM				
Medina, Eric		Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
106474					8/23/2013		144		\$0.00
Medium	Work In Progress				8/23/2013 3:28:34 PM				
Gonzalez, Salvador		Chava need a square drag for loma linda thank you							
Eric Medina									
111968					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:49 AM				
Medina, Eric		Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
111014					12/8/2013	12/24/2013	37		\$0.00
Medium	Work In Progress				12/8/2013 12:18:45 AM				
Medina, Eric		Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
1/14/2014 10:19:04 AM									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Loma Linda ES									
111645					1/5/2014	1/26/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:59 AM				
Munoz, Michael	Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
111919					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 2:39:30 PM				
Medina, Eric	Asp PM serviced by Dimar - replace gauge to system.								
Michael Munoz									
111981					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:56 AM				
Solis, Luis	Monthly - QRTLY BLDG INSP REPORT (LL) - Refer to PM schedule details.								
Margret Villalobos									
108264					10/6/2013	11/6/2013	100		\$0.00
Medium	Work In Progress				10/6/2013 12:23:00 AM				
Arreola, Rudy	Yearly - Loma Linda ES I4(Fan Coil)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
107937					9/25/2013		111		\$0.00
Medium	Work In Progress				9/25/2013 3:21:24 PM				
Villalobos, David	David need diaphragm assembly for wash basin in 5th grade wing								
Eric Medina									
111483					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:20 AM				
Villalobos, David	Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
110891					12/5/2013		40		\$0.00
Medium	Work In Progress				12/5/2013 12:23:30 PM				
Villalobos, David	David need to replace j-3 coupler for ray pak water heater circulating pump for hot water supply								
Eric Medina									
107938					9/25/2013		111		\$0.00
Medium	Work In Progress				9/25/2013 3:23:14 PM				
Flores, Pete	Pete need to order new battery for mower thank you								
Eric Medina									
1/14/2014 10:19:05 AM									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
110300					11/15/2013		60		\$0.00
Safety	Work In Progress				11/15/2013 12:28:27				
Flores, Pete		Pete the seat belt in truck 31 fixed or replaced please thank you							
Eric Medina									
111520					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:40 AM				
Medina, Eric		Monthly - Loma Linda ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
111471					12/31/2013		14		\$0.00
Medium	Work In Progress				12/31/2013 12:32:43				
Apodaca, Mario		Monthly - Loma Linda ES - Domestic Water Filters - Refer to PM schedule details.							
Margret Villalobos									
111929					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 3:15:19 PM				
Medina, Eric		need to replace flush valve assembly in women's room near office							
Eric Medina									
111558					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:05 AM				
Medina, Eric		Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111556					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:04 AM				
Medina, Eric		Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111557					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:04 AM				
Medina, Eric		Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Loma Linda ES							
112018		Office			1/13/2014		1		\$0.00
Medium	Work In Progress	Office			1/13/2014 2:44:34 PM				
Medina, Eric		Please pick up order from SAMS at 9 am on 1/14/2014							
Angie Flores									
Count: 31 Work Orders		Avg. Age of WO's 51			Total for Loma Linda ES			0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Mesquite ES							
111219					12/12/2013		33		\$0.00
Medium	Work In Progress				12/12/2013 3:32:59 PM				
Holguin, Alfredo		Demo -Remove septic tank and electrical							
Alfredo Holguin									
111611					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:39 AM				
Apodaca, Mario		Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
111512					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:35 AM				
Ramirez, Joe		Monthly - Mesquite ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
109647					11/1/2013		74		\$0.00
Medium	Work In Progress				11/1/2013 3:42:54 PM				
Flores, Pete		truck #141 needs to be serviced it keeps over heating							
Joe Ramirez									
106246					8/19/2013		148		\$0.00
Medium	Work In Progress				8/19/2013 3:52:32 PM				
Flores, Pete		p.to. on lawnmower 735 (m.e.0421) does not engage needs to be repaired.							
Joe Ramirez									
111579					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:18 AM				
Ramirez, Joe		Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
107191					9/6/2013		130		\$0.00
Medium	Work In Progress				9/6/2013 3:46:53 PM				
Ramirez, Joe		9/6/13. .5 building walk thru. 1.5 marquee. .5 barrack drainage insp. 1.5 exit sign insp. 1.0 sprinkler repair. .5 adj desks. 1.0 work on water fountain. .5 hang banner. .5 clean up				9/6			
Joe Ramirez									
106372					8/21/2013		146		\$0.00
Medium	Work In Progress				8/21/2013 4:14:44 PM				
Ramirez, Joe		Remove piece of broken concrete and replace with new in sidewalk on west side of barrack							
Alfredo Holguin									
111881					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 8:31:13 AM				
Villalobos, David		needs davids assist.with a water leak.							
Joe Ramirez									
111343					12/17/2013		28		\$0.00
Medium	Work In Progress				12/17/2013 8:30:22 AM				
Villalobos, David		need to re-pipe hydronic system.							
Joe Ramirez									
111486					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:21 AM				
Villalobos, David		Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
109888		Cafeteria			11/5/2013		70		\$0.00
High	Work In Progress				11/5/2013 8:48:35 AM				
Villalobos, David		please put camera in drain as per conversation on Wednesday and let alfredo know of findings.							
Michael Munoz									
111346					12/17/2013		28		\$0.00
Medium	Work In Progress				12/17/2013 9:05:59 AM				
Sotelo, Enrique		light switch in the café. shorted out needs to be replaced							
Joe Ramirez									
1/14/2014 10:19:05 AM									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Mesquite ES

110769					12/3/2013		42		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/3/2013 10:17:42 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique need to replace broken exit sign with a new one

Joe Ramirez

111996					1/13/2014		1		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/13/2014 8:11:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo automatic door closer needs to be installed

Joe Ramirez

111991					1/12/2014	1/28/2014	2		\$0.00
--------	--	--	--	--	-----------	-----------	---	--	--------

Medium	Work In Progress				1/12/2014 12:18:02 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Saucedo, Luis Monthly - QRTLY BLDG INSP REPORT (MQ) - Refer to PM schedule details.

Margret Villalobos

110708		Custodial			12/1/2013		44		\$0.00
--------	--	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/1/2013 2:23:47 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Carbajal, Jimmy Please I need stripping boots or goggles for.
Mario= size 10 and 1 pair of goggles.
Marin= size 10 and 1 pair of goggles.
Ambriz= size 10 and 1 pair of goggles.

thank you

Luis Saucedo

109325		Custodial			10/25/2013		81		\$0.00
--------	--	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/25/2013 8:20:54 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Carbajal, Jimmy vaccum # 1166 the handle is broke also can you please replace the core.

thank you

Luis Saucedo

105671					8/8/2013		159		\$0.00
--------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				8/8/2013 1:03:55 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Marquez, Gerardo door and door jamb for rm.608 needs to be replaced it is in really bad shape.

Joe Ramirez

111621					1/5/2014	1/11/2014	9		\$0.00
--------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				1/5/2014 12:24:45 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ramirez, Joe Monthly - Mesquite ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

1/14/2014 10:19:05 AM

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Mesquite ES									
107019	Pump House	Pump House			9/3/2013		133		\$0.00
Medium	Work In Progress				9/3/2013 3:26:54 PM				
Marquez, Gerardo	the door to the Pump Room at mesquite elementary needs to be replaced door hinges are broken up and very hard to open								
Mario Apodaca									
110227		Custodial			11/13/2013		62		\$0.00
Medium	Work In Progress				11/13/2013 4:42:56 PM				
Estrada, Jesus	please on north side of the cafeteria the tile needs to be replace is located on the middle of the cafeteria 10ft from the stage thank you								
Luis Saucedo									
108884		Custodial			10/15/2013		91		\$0.00
Medium	Work In Progress				10/15/2013 7:58:13 AM				
Estrada, Jesus	Mr. Estrada, On the library the carpet is torn out need new carpet. If you have a chance, could you please stop by and see it. Thank you								
Luis Saucedo									
111209		Cafeteria			12/12/2013		33		\$0.00
Medium	Work In Progress				12/12/2013 1:31:15 PM				
Estrada, Jesus	Mr. Estrada, On the kitcken in her office the floor tile needs to be replace (regular tiles)if it possible they would like school colors(lighth blue). If you have a chance, could you please stop by and see it. Thank you								
Luis Saucedo									
111153		Cafeteria			12/11/2013		34		\$0.00
Medium	Work In Progress				12/11/2013 10:28:57				
Estrada, Jesus	Mr. Estrada, On the kitcken in the storage room where they keep the food the floor tile needs to be replace (non slip tiles)if it possible theywould like school colors(lighth blue). If you have a chance, could you please stop by and see it. Thank you								
Luis Saucedo									
111098		LaundryRoom			12/10/2013		35		\$0.00
Medium	Work In Progress				12/10/2013 12:58:35				
Estrada, Jesus	Mr. Estrada, On the kitcken in the laundry room the floor tile needs to be replace . If you have a chance, could you please stop by and see it. Thank you								
Luis Saucedo									
Count: 26 Work Orders	Avg. Age of WO's 55			Total for Mesquite ES			0	\$0.00	

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: North Valley ES									
111772					1/8/2014		6		\$0.00
Medium	Work In Progress			1/8/2014 8:21:54 AM					
Gonzalez, Salvador	need basketball rim welded at courts/will assist								
Danny Vega									
108932					10/15/2013		91		\$0.00
High	Work In Progress			10/15/2013 4:21:30 PM					
Vega, David	need to replace batteries to fire pump. please remove and bring to warehouse for new purchase. once in, please install. thank you								
Michael Munoz									
111650					1/5/2014		9		\$0.00
Medium	Work In Progress			1/5/2014 12:25:02 AM					
Munoz, Michael	Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PM schedule details.								
Margret Villalobos									
111960					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress			1/12/2014 12:17:44 AM					
Parra, Javier	Monthly - QRTLY BLDG INSP REPORT (NV) - Refer to PM schedule details.								
Margret Villalobos									
111035		Office			12/9/2013		36		\$0.00
Medium	Work In Progress	nurses office m		12/9/2013 11:08:57 AM					
Marquez, Gerardo	Please send locksmith, we have purchased 2 new locks for our medicine cabinet that need to be installed.								
Priscilla Martinez									
105550					8/7/2013		160		\$0.00
Medium	Work In Progress			8/7/2013 7:46:50 AM					
Marquez, Gerardo	NEED GATE KEY FOR EL PASO DISPOSAL. PLEASE GIVE TO MARY SITTERS. THANKS								
Jesus Estrada									
111787					1/8/2014		6		\$0.00
Medium	Work In Progress			1/8/2014 9:52:21 AM					
Solis, Lorenz	RM 210 UNIT HAVING PROBLEMS WITH HEAT/PLEASE CK ASAP								
Danny Vega									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
111838		Classroom			1/9/2014		5		\$0.00
Medium	Work In Progress	212/404			1/9/2014 1:38:54 PM				
Sotelo, Enrique Priscilla Martinez Need electrical power for projector on ceiling mount.									
109899		Office			11/5/2013		70		\$0.00
Medium	Work In Progress	nurses office m			11/5/2013 10:44:17 AM				
Villalobos, David Priscilla Martinez Nurse would like her faucet changed out, the one currently in the bathroom sprays water everywhere.									
111496					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:26 AM				
Villalobos, David Margret Villalobos Yearly - North Valley ES Backflow Inspection - Refer to PM schedule details.									
111966					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:48 AM				
Vega, Danny Margret Villalobos Monthly - North Valley ES Playground Inspection - Refer to PM schedule details.									
109053					10/17/2013		89		\$0.00
Medium	Work In Progress				10/17/2013 4:14:55 PM				
Miranda, Danny Michael Munoz please build a furnace closet for new unit in the old hvac / electrical shop .thank you									
109423					10/28/2013		78		\$0.00
Medium	Work In Progress				10/28/2013 2:48:19 PM				
Vallejo, Albert Michael Munoz please assist with career day on Nov 1st, Friday noon - 2:30. thank you (bil jax extended boom)									
108414					10/6/2013		100		\$0.00
Medium	Work In Progress				10/6/2013 12:24:11 AM				
Holguin, Alfredo Margret Villalobos Monthly - North Valley ES - Fire Pump Engine - Refer to PM schedule details.									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		North Valley ES							
111531					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:47 AM				
Holguin, Alfredo	Monthly - North Valley ES - Fire Pump Engine - Refer to PM schedule details.								
Margret Villalobos									
Count: 15 Work Orders		Avg. Age of WO's	45	Total for North Valley ES				0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

111554 1/5/2014 1/13/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:24:03 AM

Vega, Danny Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

111555 1/5/2014 1/13/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:24:03 AM

Vega, Danny Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

111965 1/12/2014 1/28/2014 2 \$0.00

Medium Work In Progress 1/12/2014 12:17:47 AM

Vega, Danny Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.

Margret Villalobos

111484 1/5/2014 2/5/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:23:20 AM

Villalobos, David Yearly - Northern Pre-K Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

111886 1/10/2014 4 \$0.00

High Work In Progress 1/10/2014 9:28:18 AM

Solis, Lorenzo Please check the heating at La Mesa Pre-K. As per summary below it appears that room 102, 104, 108, 110 and the parent room may have an issue. Also, please look at the lobby issue. Thanks.

Dominique Esparza

112005 1/13/2014 1 \$0.00

Medium Work In Progress 1/13/2014 9:26:22 AM

Marquez, Gerardo need pad lock cut-off at Im pre-k gate/custodian cant open gate (pad lock are not is not gisd) please cut out asap.to small parking lot at north side

Danny Vega

111519 1/5/2014 1/13/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:23:40 AM

Vega, Danny Monthly - La Mesa ES Roof Inspection - Refer to PM schedule details.

Margret Villalobos

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Northern On-Track Pre-K (LM)

111954 1/12/2014 1/28/2014 2 \$0.00

Medium Work In Progress 1/12/2014 12:17:40 AM

Montoya, Adam Monthly - QRTLTY BLDG INSP REPORT (LM/PRE-K) - Refer to PM schedule details.

Margret Villalobos

110173 Parking Lot 11/13/2013 62 \$0.00

Medium Work In Progress 11/13/2013 8:05:09 AM

Ontiveros, Guadalupe As per Mr. Munoz need to install above flower beds.

Guadalupe Ontiveros

111683 1/6/2014 8 \$0.00

Medium Work In Progress 1/6/2014 3:05:45 PM

Ontiveros, Guadalupe need 1 load fill dirt for sidewalks at lm pre-k and small bucket tractor to level off

Danny Vega

108567 10/8/2013 98 \$0.00

Medium Work In Progress 10/8/2013 10:58:11 AM

Munoz, Michael Remove sidewalk going from ADA Parking to Main Bldg. E. entrance and replace with 5 Ft. wide walk and ramp.

Alfredo Holguin

108568 10/8/2013 98 \$0.00

Medium Work In Progress 10/8/2013 10:58:45 AM

Munoz, Michael Remove sidewalk going from ADA Parking to Main Bldg. South entrance and replace with 5 Ft. wide walk and ramp.

Alfredo Holguin

107790 9/23/2013 113 \$0.00

Medium Work In Progress 9/23/2013 8:31:46 AM

Marquez, Gerardo rm 108 door will not close/hinges are off alingment/wood is split on top hinge and not holding/this door was last worked on by locksmith-door has to be replaced.

Danny Vega

111373 12/17/2013 28 \$0.00

High Work In Progress 12/17/2013 3:42:45 PM

Gonzalez, Salvador please remove part of front fence and side for concrete trucks to enter. will need to remove 1 pole on each and sleeve. this needs to be done by this Thursday 12-19-13. please see mike for details. thank you

Michael Munoz

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Northern On-Track Pre-K (LM)									
111629					1/5/2014	1/11/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:50 AM				
Vega, Danny		Monthly - La Mesa ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
109121	Main Building				10/21/2013		85		\$0.00
Medium	Work In Progress				10/21/2013 2:21:43 PM				
Gonzales, Camilo		NEED OUTSIDE CLASSROOM (ROOM 17) CLEARED OUT. OLD/BROKEN DESKS AND FURNITURE. AS PER ROSIE REYES.							
Adam Montoya									
111778	Main Building	Hallway/Corridor			1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 8:49:47 AM				
Solis, Lorenzø		WATER FOUNTAINS IN HALLWAY NEED TO BE REPLACED. (REPLACEMENT FOUNTAINS ARE HERE IN BUILDING) WATER WAS SHUT OFF TO THESE FOUNTAINS BEFORE WINTER BREAK.							
Adam Montoya									
107911	Main Building	Hallway/Corridor			9/25/2013		111		\$0.00
Medium	Work In Progress				9/25/2013 10:42:22 AM				
Villalobos, David		Water fountain on pre-k hallway has a leak.							
Concepcion Montalvo									
Count: 18 Work Orders			Avg. Age of WO's	37		Total for Northern On-Track Pre-K (LM)	0		\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

111199	Motor Vehicle				12/12/2013		33		\$0.00
--------	---------------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	vehicle-148			12/12/2013 9:20:39 AM				
--------	------------------	-------------	--	--	-----------------------	--	--	--	--

Flores, Pete please check condition of tires . mileage -- 97,000

Pete Flores

107964	Motor Vehicle				9/26/2013		110		\$0.00
--------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	equip. # 0421			9/26/2013 7:44:09 AM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Flores, Pete please replace battery in mower # 0421-mesquite elem.

Pete Flores

104631	Motor Vehicle				7/23/2013		175		\$0.00
--------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	vehicle#81			7/23/2013 3:13:18 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Flores, Pete left front outrigger leaking excessive hydraulic oil. please check and advise.

Pete Flores

104728	Motor Vehicle				7/25/2013		173		\$0.00
--------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	5510 tractor			7/25/2013 10:19:26 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Flores, Pete tractor's warning lights are inoperative, and fuel gage is inaccurate.please check.

Pete Flores

112014	Motor Vehicle				1/13/2014		1		\$0.00
--------	---------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	ditchwitch rt45			1/13/2014 1:05:57 PM				
--------	------------------	-----------------	--	--	----------------------	--	--	--	--

Flores, Pete please check cause of burning smell.

Pete Flores

111355	Motor Vehicle				12/17/2013		28		\$0.00
--------	---------------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	vehicle 53			12/17/2013 11:25:23				
--------	------------------	------------	--	--	---------------------	--	--	--	--

Flores, Pete check cause of engine coolant loss,and check for any other scheduled maintenance.

Pete Flores

110550	Motor Vehicle				11/22/2013		53		\$0.00
--------	---------------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	Car #161			11/22/2013 11:32:00				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Flores, Pete Car #161 does not have a spare tire.

Noemi Duron

111176	Motor Vehicle				12/11/2013		34		\$0.00
--------	---------------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress	vehicle 48			12/11/2013 3:36:30 PM				
--------	------------------	------------	--	--	-----------------------	--	--	--	--

Flores, Pete please check and advise on malfunctioning anti-lock braking system and inoperative a/c.

Pete Flores

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
110392	Motor Vehicle				11/19/2013		56		\$0.00
Medium	Work In Progress				11/19/2013 9:49:47 AM				
Gonzalez, Salvador		need door installed to addition to auto shop metal back building. thank you.							
Michael Munoz									
110715	Purchasing				12/2/2013		43		\$0.00
Medium	Work In Progress				12/2/2013 11:15:53 AM				
Solis, Lorenz		Men's and Women's restroom. Provide heating							
Alfredo Holguin									
110929	Maintenance				12/6/2013		39		\$0.00
Medium	Work In Progress				12/6/2013 7:34:06 AM				
Sotelo, Enrique		please replace light to north entrance of snp warehouse and install light to door the enters the maintenance warehouse. thank you							
Michael Munoz									
110206	Maintenance				11/13/2013		62		\$0.00
Medium	Work In Progress				11/13/2013 3:42:56 PM				
Flores, Pete		passenger brake light weak							
Gerardo Marquez									
111639					1/5/2014	1/11/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:56 AM				
Diaz, Sebastian		Monthly - Physical Plant FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
111444					12/19/2013		26		\$0.00
Medium	Work In Progress				12/19/2013 2:56:01 PM				
Gonzalez, Salvador		fence behind ppd barracks is down. please install poles to fence for temporary repair. thank you							
Michael Munoz									
109287					10/24/2013		82		\$0.00
Medium	Work In Progress				10/24/2013 10:47:27				
Gonzalez, Salvador		old blue trailer. please raise the sides for scrap metal. see mike for details. thank you							
Michael Munoz									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
109081		Lift Station			10/18/2013		88		\$0.00
Medium	Work In Progress				10/18/2013 3:12:40 PM				
Munoz, Michael		Need to replace the chain link fence around the sewer treatment plant at the physical plant department				11/20 - Routed to M. Munoz			
Mario Apodaca									
109083		Lift Station			10/18/2013		88		\$0.00
Medium	Work In Progress				10/18/2013 3:20:41 PM				
Ontiveros, Guadalupe		need a couple loads of primary screen around the sewer plant at the physical plant department							
Mario Apodaca									
111830					1/9/2014		5		\$0.00
Medium	Work In Progress				1/9/2014 10:40:29 AM				
Marquez, Gerardo		Please issue a key for Gate by ditch (behind GMS) to Frank Sloan, EBID							
Alfredo Holguin									
106552		Athletic Field			8/27/2013		140		\$0.00
Medium	Work In Progress				8/27/2013 8:41:44 AM				
Marquez, Gerardo		need copies of keys for new fuel cap that was install on John Deere Backhoe L110							
Guadalupe Ontiveros									
107331					9/11/2013		125		\$0.00
Medium	Work In Progress				9/11/2013 7:33:13 AM				
Lara, Ralph		Rafa, as per Alfredo need a key log for all sites that have been issued key for El Paso Disposal. This information is needed by Mary Sitters. thank you.							
Alfredo Holguin									
109051					10/17/2013		89		\$0.00
Medium	Work In Progress				10/17/2013 4:11:07 PM				
Solis, Lorenzo		please install heating and cooling unit in old electrical/hvac shop and remove existing furnace and a/c. thank you							
Michael Munoz									
110384					11/19/2013		56		\$0.00
Medium	Work In Progress				11/19/2013 7:56:50 AM				
Sotelo, Enrique		please provide lighting to new conference room . where old electrical/hvac shop used to be.							
Michael Munoz									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Physical Plant Complex							
111139					12/11/2013		34		\$0.00
Medium	Work In Progress				12/11/2013 8:25:15 AM				
Sotelo, Enrique		Need to install light on pole where mobile home use to be.							
Michael Munoz									
111935					1/10/2014		4		\$0.00
Medium	Work In Progress	LINE LOCATE			1/10/2014 3:29:19 PM				
Sotelo, Enrique		Need to line locate from the mobile home occupant space to the WWTP 1st thing Monday morning.							
Michael Munoz									
111952					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 4:32:55 PM				
Sotelo, Enrique		Fuel Station - Need to check lighting not turning on.							
Michael Munoz									
111487					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:21 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
111933					1/10/2014		4		\$0.00
Medium	Work In Progress	LINE LOCATE			1/10/2014 3:28:41 PM				
Villalobos, David		Need to line locate from the mobile home occupant space to the WWTP 1st thing Monday morning.							
Michael Munoz									
110716					12/2/2013		43		\$0.00
Medium	Work In Progress	LINE LOCATE			12/2/2013 11:25:08 AM				
Villalobos, David		New Food Service Warehouse - Need to line locate in this area.							
Alfredo Holguin									
109289					10/24/2013		82		\$0.00
Medium	Work In Progress				10/24/2013 10:51:56				
Villalobos, David		ice machine will be placed in lobby area of rest rooms in the old hvac/electrical shop. will need sewer and water. thank you							
Michael Munoz									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
111365					12/17/2013		28		\$0.00
Medium	Work In Progress				12/17/2013 3:25:24 PM				
Carrasco, Danny		Need to purchase a refrigerator and gas range for lounge room at PPD.							
Danny Carrasco									
109052					10/17/2013		89		\$0.00
Medium	Work In Progress				10/17/2013 4:13:23 PM				
Miranda, Danny		please install a drop ceiling to old electrical / hvac shop and new restroom area. thank you							
Michael Munoz									
110614					12/1/2013		44		\$0.00
Medium	Work In Progress				12/1/2013 12:32:37 AM				
Ruiz, Maria		Monthly - PPD - Fueling Station Monthly Inspection - Refer to PMSchedule details.							
Margret Villalobos									
111540					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:53 AM				
Ruiz, Maria		Monthly - PPD - Fueling Station Monthly Inspection - Refer to PMSchedule details.							
Margret Villalobos									
110835					12/4/2013		41		\$0.00
Medium	Work In Progress				12/4/2013 10:47:58 AM				
Holguin, Alfredo		Acquire "Right of Use Permit" for 40ft of left bank of Anthony drain for parking access, fence and landscaping.							
Alfredo Holguin									
111503					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:30 AM				
Diaz, Sebastian		Monthly - Physical Plant Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
109372					10/28/2013		78		\$0.00
Medium	Work In Progress				10/28/2013 7:25:31 AM				
Diaz, Sebastian		Maint Office - Need to paint inside of main door and replace covebase.							
Michael Munoz									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Physical Plant Complex

109068 10/18/2013 88 \$0.00

Medium Work In Progress 10/18/2013 9:13:52 AM

Ronquillo, Ruben ORDER TWO ENCLOSED TRAILERS FOR SEWER MACHINES. ONE FOR CHAPARRAL AND ONE FOR GAC. THANK YOU!

Ruben Ronquillo

109948 11/6/2013 69 \$0.00

Medium Work In Progress 11/6/2013 8:01:27 AM

Gonzalez, Salvador Need some welding supplies

Salvador Gonzalez

106267 8/20/2013 147 \$0.00

Medium Work In Progress 8/20/2013 8:57:23 AM

Flores, Pete SHIFTER IS LOOSE ON VEHICLE #32. NEED TO SET HAND BRAKE, SOMETIMES SHIFTER WILL NOT LOCK. ENGINE IS KNOCKING. THANK YOU

Ruben Ronquillo

108706 10/10/2013 96 \$0.00

Medium Work In Progress 10/10/2013 3:53:08 PM

Flores, Pete No back lights when I turn on the switch and front windshield is cracked

David Villalobos

111570 1/5/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:24:12 AM

Flores, Pete Monthly - PPD-MP-0143 DT PM Service - by SWP - Refer to PM schedule details.

Margret Villalobos

111571 1/5/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:24:13 AM

Flores, Pete Monthly - PPD-T-0525 PM (Excavator) - by SWP - Refer to PM schedule details.

Margret Villalobos

111655 1/6/2014 8 \$0.00

Medium Work In Progress 1/6/2014 12:24:15 AM

Flores, Pete Monthly - District Backhoe - Full Service PM - Refer to PM schedule details.

Margret Villalobos

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Physical Plant Complex										
111656					1/6/2014		8		\$0.00	
Medium	Work In Progress				1/6/2014 12:24:15 AM					
Flores, Pete		Monthly - PPD - UV-0516 PM Service - Refer to PM schedule details.								
Margret Villalobos										
Count: 44 Work Orders			Avg. Age of WO's	55	Total for Physical Plant Complex			0	\$0.00	

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
111034					12/9/2013		36		\$0.00
Medium	Work In Progress				12/9/2013 10:59:52 AM				
Martinez, Mario		Need repairs on three swings also need nets for four basketball goal post							
Mario Martinez									
109743					11/3/2013	11/11/2013	72		\$0.00
Medium	Work In Progress				11/3/2013 12:25:58 AM				
Martinez, Mario		Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
109742					11/3/2013	11/11/2013	72		\$0.00
Medium	Work In Progress				11/3/2013 12:25:57 AM				
Martinez, Mario		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111583					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:21 AM				
Martinez, Mario		Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111582					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:20 AM				
Martinez, Mario		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111847					1/9/2014		5		\$0.00
Medium	Work In Progress				1/9/2014 3:27:05 PM				
Martinez, Mario		Need to repair small copper water leak at mechanical behind kitchen.							
Mario Martinez									
111872					1/9/2014		5		\$0.00
Medium	Work In Progress				1/9/2014 5:18:40 PM				
Martinez, Mario		Work order for equipment and hand tools.							
Mario Martinez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
111873					1/9/2014		5		\$0.00
Medium	Work In Progress				1/9/2014 5:50:07 PM				
Martinez, Mario		Equipment needed for Riverside Elem. 1 hoe, 1 24 ft extension ladder, 1 12 inch channel lock pliers, 1 hand grinder, 1 3/8 inch ratchet and socket set, 1 100 ft extension cord, 1 50 ft extensions cord, 1 25ft extension cord, 1 soldering torch, 1 6ft step ladder, 1 10 ft step ladder, 1 100 ft water hose, 1 50 ft water hose, 1 wheel barrel, 1 tool pouch carrier							
Mario Martinez									
111773					1/8/2014		6		\$0.00
Medium	Work In Progress				1/8/2014 8:30:43 AM				
Martinez, Mario		Need to replace 14 48 inch florescent light bulbs in room 26.							
Mario Martinez									
111720					1/7/2014		7		\$0.00
Medium	Work In Progress				1/7/2014 9:49:31 AM				
Martinez, Mario		Need to replace 30 10/58/1 filters in middle and north wings							
Mario Martinez									
111719		Restroom			1/7/2014		7		\$0.00
Medium	Work In Progress				1/7/2014 9:04:31 AM				
Martinez, Mario		Need to repair or replace 4 inch lavatory faucets in Boys/Girls bathrooms.							
Mario Martinez									
112046					1/14/2014		0		\$0.00
Medium	Work In Progress				1/14/2014 7:22:53 AM				
Martinez, Mario		Need lights at Southwest portables fixed.							
Mario Martinez									
107303					9/10/2013		126		\$0.00
Medium	Work In Progress				9/10/2013 2:56:25 PM				
Sonora, Miguel		NEED TO SWEEP UNDER BOTH CANOPIES ON A WEEKLY BASIS							
Jesus Estrada									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
106659					8/28/2013		139		\$0.00
Medium	Work In Progress			8/28/2013 2:25:15 PM					
Sonora, Miguel	NEED TO SHOWER SCRUB & WAX FLOORS IN REST ROOM BETWEEN ROOMS 503 & 506								
Jesus Estrada									
111984					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress			1/12/2014 12:17:58 AM					
Sonora, Miguel	Monthly - QRTLY BLDG INSP REPORT (RS) - Refer to PMs schedule details.								
Margret Villalobos									
111254					12/13/2013		32		\$0.00
Medium	Work In Progress			12/13/2013 3:18:32 PM					
Ambriz, Jose	HAVING PROBLEMS WITH VCU, NEED TRANE TO COME CHECK								
Jose Angelo									
109226					10/23/2013		83		\$0.00
Medium	Work In Progress			10/23/2013 9:42:21 AM					
Moncayo, Fernando	please clean out all electrical and mechanical rooms. thank you								
Michael Munoz									
109227					10/23/2013		83		\$0.00
Medium	Work In Progress			10/23/2013 9:43:53 AM					
Moncayo, Fernando	please cut weeds and clean area where mobile home used to be. In the fenced area and surrounding areas as well. thank you								
Michael Munoz									
111982					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress			1/12/2014 12:17:57 AM					
Martinez, Mario	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
110097					11/10/2013	11/26/2013	65		\$0.00
Medium	Work In Progress			11/10/2013 12:18:47					
Martinez, Mario	Monthly - Riverside ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
111020					12/8/2013	12/24/2013	37		\$0.00
Medium	Work In Progress				12/8/2013 12:18:49 AM				
Martinez, Mario		Monthly - Riverside ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
110487		Cafeteria			11/21/2013		54		\$0.00
High	Work In Progress				11/21/2013 6:32:36 AM				
Martinez, Mario		water is puddled in the back parking lot(cafeteria). could be coming out of a man hole. please check and address. thank you							
Miguel Sonora									
111831					1/9/2014		5		\$0.00
Medium	Work In Progress				1/9/2014 10:42:01 AM				
Villalobos, David		Need to repair leaking irrigation Backflow preventor.							
Michael Munoz									
111488					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:22 AM				
Villalobos, David		Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
111430		Electrical Room			12/19/2013		26		\$0.00
Medium	Work In Progress				12/19/2013 9:20:46 AM				
Castillo, Carlos		Annual electrical equipment inspection.							
Carlos Castillo									
110395					11/19/2013		56		\$0.00
Medium	Work In Progress				11/19/2013 10:28:42				
Ontiveros, Joe		main floor drain in boys bathroom clogged							
Mario Martinez									
110787					12/3/2013		42		\$0.00
Medium	Work In Progress				12/3/2013 2:41:42 PM				
Ontiveros, Joe		please check backflow preventers. as per Mario one is leaking every3 minutes. thankyou							
Michael Munoz									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

109469 10/29/2013 77 \$0.00

Medium Work In Progress LINE LOCATE 10/29/2013 2:01:56 PM

Ontiveros, Joe

Company:BOHANNAN HUSTON INC.
Contact Name:KEITH NICOVICH Contact
Phone: (575)532-8670

SPOT ALL UTILITIES 300FT EACH WAY
(N&S) OF THE INTERSECTION OF RIO GRANDE AND
MCNUTT, ON THE WEST SIDE OF MCNUTT.
MAJORITY OF SPOTTING ON/ADJACENT TO
RIVERSIDE ELEMENTARY.

Alfredo Holguin

109049 10/17/2013 89 \$0.00

High Work In Progress 10/17/2013 4:09:06 PM

Castillo, Carlos

as per conversation, please install a motion detector
light in the new wing hall where the skylights are at to
include light switch. thank you

Michael Munoz

106826 8/31/2013 136 \$0.00

Medium Work In Progress 8/31/2013 12:25:33 AM

Martinez, Mario

Monthly - Riverside ES A-16 Fan Exhaust Semiannual - 1/13/14 - Routed to Mario
Refer to PM schedule details.

Margret Villalobos

111896 Cafeteria 1/10/2014 4 \$0.00

Medium Work In Progress 1/10/2014 11:31:36 AM

Solis, Lorenzo

Need Jose Ambriz to fix thermostat or trouble shoot
faulty heater at Cafeteria.

Mario Martinez

105803 8/11/2013 9/11/2013 156 \$0.00

Medium Work In Progress 8/11/2013 12:17:36 AM

Moncayo, Fernando

Yearly - Riverside ES A-9 Air Cooled Cond Yearly - 10/30/13 - route to fernando
Refer to PM schedule details.

Margret Villalobos

108296 10/6/2013 11/6/2013 100 \$0.00

Medium Work In Progress 10/6/2013 12:23:16 AM

Moncayo, Fernando

Yearly - Riverside ES I-4 Fan Coil Unit Yearly - Refer to
PM schedule details.

Margret Villalobos

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Riverside ES									
108295					10/6/2013	11/6/2013	100		\$0.00
Medium	Work In Progress				10/6/2013 12:23:15 AM				
Moncayo, Fernando	Yearly - Riverside ES H-6 Rooftop Furnance Yearly - Refer to PM schedule details.								
Margret Villalobos									
110138					11/12/2013		63		\$0.00
Medium	Work In Progress				11/12/2013 2:53:05 PM				
Ontiveros, Guadalupe	Pine tress on south side next to playground. Need to check irrigation system, trees are dead or dying.								
Alfredo Holguin									
110158					11/12/2013		63		\$0.00
Medium	Work In Progress				11/12/2013 4:02:42 PM				
Ontiveros, Guadalupe	replace damaged soccer goal was hit by a car.								
Alfredo Holguin									
111505					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:31 AM				
Martinez, Mario	Monthly - Riverside ES Roof Inpsection - Refer to PM schedule details.								
Margret Villalobos									
108792					10/13/2013	10/29/2013	93		\$0.00
Medium	Work In Progress				10/13/2013 12:20:37				
Romero, Raul	Monthly - QRTLY BLDG INSP REPORT (RS) - Refer to PM schedule details.						HAS NOT BEEN RECEIVED OR COMPLETED AS OF 12/13/13		
Jesus Estrada									
107290					9/10/2013		126		\$0.00
Medium	Work In Progress				9/10/2013 10:50:21 AM				
Moncayo, Fernando	Lawn is not being cut consistently.								
Teresa Navarro									
110684					12/1/2013	12/7/2013	44		\$0.00
Medium	Work In Progress				12/1/2013 12:33:11 AM				
Martinez, Mario	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
109778					11/3/2013	11/9/2013	72		\$0.00
Medium	Work In Progress				11/3/2013 12:26:13 AM				
Martinez, Mario	Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
1/14/2014 10:19:06 AM									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
111622					1/5/2014	1/11/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:45 AM				
Martinez, Mario		Monthly - Riverside ES Monthly FE Inpsection - Refer to PMs schedule details.							
Margret Villalobos									
108635					10/9/2013		97		\$0.00
Medium	Work In Progress				10/9/2013 3:41:30 PM				
Carrasco, Danny		need to borrow the chain saw, please!!							
Fernando Moncayo									
108454					10/6/2013	10/12/2013	100		\$0.00
Medium	Work In Progress				10/6/2013 12:24:30 AM				
Ambriz, Juan		Monthly - Riverside ES Monthly FE Inpsection - Refer to PMs schedule details.							
Margret Villalobos									
111889	Main Building	Custodial			1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 10:31:16 AM				
Carrasco, Danny		si por favor me pueden mandar un galon de gasolina y un mixoil para el blower. Muchas gracias.							
Miguel Sonora									
108946	Main Building	Exterior			10/16/2013		90		\$0.00
Medium	Work In Progress				10/16/2013 9:31:10 AM				
Moncayo, Fernando		parents are complaining about weeds and stickers near entrances to the school. they need to be removed because stickers are clinging to students clothes.							
Rosa Quezada									
108673	Main Building	Classroom			10/10/2013		96		\$0.00
Medium	Work In Progress	126			10/10/2013 9:29:06 AM				
Castillo, Carlos		LIGHT BULBS FLASHING - PLEASE ADJUST OR REPLACE (VALDEZ)				10/25 Asp Cali, reroute to Fernando			
Rosa Quezada									
109166	Main Building	Classroom			10/22/2013		84		\$0.00
Medium	Work In Progress	FRONT			10/22/2013 11:20:22				
Moncayo, Fernando		WATER FROM SPRINKLERS IN FRONT ENTRANCE MAKE WATER RUN DOWN TO THE DRIVEWAY TOWARDS PARKING LOT AND STAFF HAVE TO JUMP OVER WATER TO ENTER BUILDING. (M. RODRIGUEZ)							
Rosa Quezada									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

106640	Main Building	Office			8/28/2013		139		\$0.00
Medium	Work In Progress	nurses outside			8/28/2013 9:20:28 AM				
Moncayo, Fernando		lights outside nurses station are not working (quezada)				9/24 - Asp Cali route to BM			
Rosa Quezada									

106639	Main Building	Restroom			8/28/2013		139		\$0.00
Medium	Work In Progress	6th grade area			8/28/2013 9:00:11 AM				
Moncayo, Fernando		the lights went out yesterday at riverside and the emergency lights in the boys restroom and nurses station failed to come on. (quezada)				9/24 - Asp Cali, route to BM			
Rosa Quezada									

105775	Main Building	Classroom			8/9/2013		158		\$0.00
Medium	Work In Progress	room 106			8/9/2013 2:31:40 PM				
Martinez, Mario		1. NEED TO MOVE SMART BOARD FROM ROOM 106 TO NEW SPED ROOM #18. 2. NEED CEILING BRACKET MOUNTED FOR SMART BOARD IN ROOM #21 (R. PARRA)				1/13/14 - Routed to Mario			
Rosa Quezada									

111239	Main Building	Hallway/Corridor			12/13/2013		32		\$0.00
Medium	Work In Progress				12/13/2013 9:07:13 AM				
Ontiveros, Joe		we need a plumber to install ice maker in the teacher's lounge. (navarro)							
Rosa Quezada									

107736	Main Building	All building			9/20/2013		116		\$0.00
Medium	Work In Progress				9/20/2013 10:53:27 AM				
Martinez, Mario		Need to repair roof leaks				1/13/14 - Routed to Mario			
Juan Ambriz									

107444	Main Building	Classroom			9/13/2013		123		\$0.00
Medium	Work In Progress	room 39			9/13/2013 3:45:17 PM				
Sonora, Miguel		clean north wall - FULL OF MOLD. SUTDENTS AND PARENTS COMPLAINED ABOUT WATER BUBBLES. (M. RAMIREZ)				9/23/13 - asp Mike -			
Rosa Quezada						Mary, Could you please assign this work order to the custodial crew. If maintenance assistance is needed, have them call me so that I can let Fernando know. Thank you			
						-Mike			

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
105705	Main Building	Restroom (Girls)			8/8/2013		159		\$0.00
Medium	Work In Progress				8/8/2013 3:27:56 PM				
Sonora, Miguel need to install soap dispensers in girls bathrooms by 2nd and 3rd grade wing and main hallway...(r.alvarez)									
Rosa Quezada									
109188	Main Building	Electrical Room			10/22/2013		84		\$0.00
High	Work In Progress				10/22/2013 3:12:48 PM				
Sonora, Miguel Clean out all electrical rooms, we can not use electrical rooms as storage rooms.									
Jesus Estrada									
107050	Main Building	Classroom			9/4/2013		132		\$0.00
Medium	Work In Progress	ROOM 104			9/4/2013 9:57:51 AM				
Martinez, Mario LARGE CLASSROOM EASEL HAS MISING SCREWS. IT FALLS EASITLY IF NOT HELD DOWN AS I WRITE ON IT. SAFETY HAZARD!!! (PALOMARES)									
Rosa Quezada									
106273	Main Building	Classroom			8/20/2013		147		\$0.00
Medium	Work In Progress	ROOM 123			8/20/2013 10:10:58 AM				
Martinez, Mario NEED TO MOVE THE SCREENT TO OTHER WALL (TUCKER)									
Rosa Quezada									
110348	Main Building	Office			11/18/2013		57		\$0.00
Medium	Work In Progress	gyn			11/18/2013 2:20:19 PM				
Martinez, Mario hang banners in gym, as per ms. navarro (quezada)									
Rosa Quezada									
105401	Main Building	Office			8/5/2013		162		\$0.00
Medium	Work In Progress	Assistant			8/5/2013 2:01:45 PM				
Martinez, Mario need to move smart board from room 106 to New SPED room #18. (hernandez)									
Rosa Quezada									
105405	Main Building	Office			8/5/2013		162		\$0.00
Medium	Work In Progress	front office			8/5/2013 2:08:02 PM				
Martinez, Mario need to move Prinicipal sign to conference room and place a new Assistant Principal sign in front office. (navarro)									
Rosa Quezada									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Riverside ES

106276 Main Building Office 8/20/2013 147 \$0.00

Medium Work In Progress DATA ENTRY 8/20/2013 10:15:08 AM

Martinez, Mario NEED TO MOVE CUM FILE CABINETS (FIREPROOF) 1/13/14 - Routed to Mario
TO OTHER SIDE OF OFFICE. (SOTO)

Rosa Quezada

105475 Main Building Restroom 8/6/2013 161 \$0.00

Medium Work In Progress restrooms in 8/6/2013 10:10:29 AM

Martinez, Mario bathrooms need tiles placed on floor (navarro) 1/13/14 - Routed to Mario

Rosa Quezada

109535 Main Building Classroom 10/30/2013 76 \$0.00

Medium Work In Progress ROOM #21 10/30/2013 2:06:19 PM

Ambriz, Jose CONTROL VALVE IS LEAKING ON HEATING COIL IN
ROOM #21 (MONCAYO)

Rosa Quezada

108675 Main Building Restroom 10/10/2013 96 \$0.00

Medium Work In Progress RESTROOM 10/10/2013 10:21:47

Ambriz, Jose VENT IN MAIN OFFICE RESTROOM IS NOT
WORKING

Rosa Quezada

105474 Main Building 8/6/2013 161 \$0.00

Medium Work In Progress 8/6/2013 10:08:22 AM

Moncayo, Fernando bathrooms and main hallways need painting (navarro)

Rosa Quezada

110939 Main Building Restroom 12/6/2013 39 \$0.00

Medium Work In Progress middel wing 12/6/2013 8:25:43 AM

Ontiveros, Joe urinal leaking / replacing or fixing

Rosa Quezada

110937 Main Building Mechanical 12/6/2013 39 \$0.00

Medium Work In Progress 12/6/2013 8:04:19 AM

Ontiveros, Joe Need to InsuLate 2 inch main water line in
Mechanical RM.

Joe Ontiveros

110402 Main Building Restroom 11/19/2013 56 \$0.00

Medium Work In Progress 11/19/2013 12:27:15

Ontiveros, Joe unstop main sewer line in boys restroom in main
building

Mario Martinez

1/14/2014 10:19:06 AM

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
109972	Main Building	Parking Lot			11/6/2013		69		\$0.00
Medium	Work In Progress				11/6/2013 12:30:33 PM				
Ontiveros, Joe		Joe, por favor si nos podia revisar la toma de el agua que esta afuera de la area de kinder para enfrente de la Macnutt, porque necesitamos lavar la entrada y no tiene agua muchas gracias.+							
Miguel Sonora									
110938	Main Building	Gym			12/6/2013		39		\$0.00
Medium	Work In Progress	gym			12/6/2013 8:24:47 AM				
Castillo, Carlos		replacement of two exit emergency signs							
Rosa Quezada									
110400	New Wing 1/02	Classroom			11/19/2013		56		\$0.00
Medium	Work In Progress				11/19/2013 11:47:55				
Ontiveros, Joe		Joe in the new building in the restroom of the room 145 the seat toilet is broken thankyou.							
Miguel Sonora									
111050	New Wing 1/02	Restroom			12/9/2013		36		\$0.00
Medium	Work In Progress				12/9/2013 1:58:21 PM				
Martinez, Mario		Need tiolet in room 145 replaced							
Mario Martinez									
Count: 73 Work Orders		Avg. Age of WO's 71		Total for Riverside ES		0		\$0.00	

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: San Miguel ES									
111391	Main Building	Classroom			12/18/2013		27		\$0.00
Medium	Work In Progress	Room #104			12/18/2013 8:00:02 AM				
Ambriz, Juan		Need to replace sink faucets in room #104							
Juan Ambriz									
111490					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:23 AM				
Villalobos, David		Yearly - San Miguel ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
111608					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:37 AM				
Apodaca, Mario		Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
Count: 3 Work Orders		Avg. Age of WO's 15			Total for San Miguel ES			0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
111978					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:55 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
111399					12/18/2013		27		\$0.00
Medium	Work In Progress				12/18/2013 11:08:49				
Orozco, Daniel		DISHWASHER IS LEAKING. SNP MANAGER MARINA R. 589.3439							
Maritza Gonzalez									
109338		Restroom			10/25/2013		81		\$0.00
Medium	Work In Progress	sink faucet			10/25/2013 3:20:41 PM				
Ambriz, Juan		Need to replace sink faucet in boys restroom							
Juan Ambriz									
111597					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:30 AM				
Ambriz, Juan		Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111595					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:29 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111596					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:29 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111740					1/7/2014		7		\$0.00
Medium	Work In Progress	gas blower			1/7/2014 2:59:22 PM				
Flores, Pete		Need gas blower repaired not working properly							
Juan Ambriz									
111986					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:59 AM				
Diaz, Pablo		Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

111508 1/5/2014 1/13/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:23:33 AM

Ambriz, Juan Monthly - Santa Teresa ES Roof Inspection - Refer to PM schedule details.

Margret Villalobos

111494 1/5/2014 2/5/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:23:25 AM

Villalobos, David Yearly - Santa Teresa ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

109340 Main Building Office 10/25/2013 81 \$0.00

Medium Work In Progress Conference 10/25/2013 3:22:35 PM

Ambriz, Juan Need to replace sink faucets to conference room

Juan Ambriz

109420 Main Building Restroom 10/28/2013 78 \$0.00

Medium Work In Progress Casa Roja Boys 10/28/2013 2:27:55 PM

Ambriz, Juan Need to replace flushing valve in boys restroom not working properly

Juan Ambriz

110347 Main Building Classroom 11/18/2013 57 \$0.00

Medium Work In Progress Room #108 11/18/2013 1:02:31 PM

Ambriz, Juan Need to hang shelves for SPED classroom

Juan Ambriz

110359 Main Building Classroom 11/18/2013 57 \$0.00

Medium Work In Progress Room #106 11/18/2013 3:23:50 PM

Ambriz, Juan Need to check lights in room #106

Juan Ambriz

110909 Main Building Library 12/5/2013 40 \$0.00

Medium Work In Progress 12/5/2013 3:31:57 PM

Ambriz, Juan Need to replace lights in library

Juan Ambriz

110052 Main Building Classroom 11/8/2013 67 \$0.00

Medium Work In Progress 301 Mr. 11/8/2013 9:40:08 AM

Ambriz, Juan Please remove map from wall and install it in another wall. Thank you.

Rita Mendez

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

110054	Main Building	Classroom			11/8/2013		67		\$0.00
Medium	Work In Progress	212 Moraga			11/8/2013 9:42:38 AM				
Ambriz, Juan		Please remove map from wall and install it in another wall. Thank you.							

Rita Mendez

111390	Main Building	Classroom			12/18/2013		27		\$0.00
Medium	Work In Progress	Room #305			12/18/2013 7:58:14 AM				
Ambriz, Juan		Need to repolace lights in room #305							

Juan Ambriz

110346	Main Building	Portables			11/18/2013		57		\$0.00
Medium	Work In Progress	Portable B			11/18/2013 1:01:17 PM				
Ambriz, Juan		Need to replace lights							

Juan Ambriz

110058	Main Building	Portables			11/8/2013		67		\$0.00
Medium	Work In Progress	Art portable			11/8/2013 9:52:13 AM				
Ambriz, Juan		Shelves from art portable need to be moved to storage bldg. next to portable. Shelves might need to be installed to wall. Thank you.							

Rita Mendez

106365	Main Building	Classroom			8/21/2013		146		\$0.00
Medium	Work In Progress	Room #101			8/21/2013 3:49:58 PM				
Lara, Ralph		Need locksmith to replace deadbolt in classroom getting stuck (ASAP) SPECIAL ED CLASSROOM							

Juan Ambriz

111880	Main Building				1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 8:12:26 AM				
Lara, Ralph		Need keys for alarm for staff							

Juan Ambriz

111888	Main Building				1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 10:26:51 AM				
Lara, Ralph		I need a copy of the fire alarm key (front office has original) this keyis for Principal Tarin.							

111841	Main Building	Hallway/Corridor			1/9/2014		5		\$0.00
Medium	Work In Progress	200 hallway			1/9/2014 3:04:10 PM				
Ontiveros, Joe		Need to repair leak in 2 1/2" main domestic water							

Juan Ambriz

1/14/2014 10:19:06 AM

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa ES

107183	Main Building				9/6/2013		130		\$0.00
--------	---------------	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/6/2013 3:09:23 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Joe

Need to Replaces sink facset in Confrances room will not stop dripping.

Joe Ontiveros

107573	Main Building	Office			9/17/2013		119		\$0.00
--------	---------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	coaches office			9/17/2013 2:45:45 PM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Ambriz, Jose

Need to check a/c unit not cooling

Juan Ambriz

110721	Main Building	Portables			12/2/2013		43		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Portable D			12/2/2013 12:42:13 PM				
--------	------------------	------------	--	--	-----------------------	--	--	--	--

Ambriz, Jose

Need to check heating unit in Portable D not working

Juan Ambriz

110723	Main Building	Office			12/2/2013		43		\$0.00
--------	---------------	--------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	o/t room 100			12/2/2013 1:31:22 PM				
--------	------------------	--------------	--	--	----------------------	--	--	--	--

Ambriz, Jose

Heating unit leaking water from main line

Juan Ambriz

109418	Main Building	Classroom			10/28/2013		78		\$0.00
--------	---------------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	Room #206			10/28/2013 2:05:48 PM				
--------	------------------	-----------	--	--	-----------------------	--	--	--	--

Ambriz, Jose

Need to check a/c unit in room #206 not working properly

Juan Ambriz

106980	Main Building	Classroom			9/3/2013		133		\$0.00
--------	---------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	Room 303			9/3/2013 8:48:32 AM				
--------	------------------	----------	--	--	---------------------	--	--	--	--

Ambriz, Jose

Need HVAC TECH to check a/c unit in room #303 not cooling

Juan Ambriz

110908	Main Building	Classroom			12/5/2013		40		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room #206			12/5/2013 3:31:04 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Ambriz, Jose

Need HVAC TECH to check on heating nit in room #206 not working properly

Juan Ambriz

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
106737	Main Building	Office			8/29/2013		138		\$0.00
Medium	Work In Progress	Casa Azul			8/29/2013 1:20:34 PM				
Lara, Ralph		Need to have a key made for Bilingual Speech Therapist. Do not want to issue the original on file. (2 keys needed)							
Melynda Menchaca									
109076	Main Building	Classroom			10/18/2013		88		\$0.00
Medium	Work In Progress	108			10/18/2013 1:21:13 PM				
Lara, Ralph		Please install locks to classroom cabinets. Will need 4 keys for each lock. (2 IA's, 1 teacher, Ms. Grissom, copy for office). Thank you.							
Rita Mendez									
110483	Main Building	Classroom			11/20/2013		55		\$0.00
Medium	Work In Progress	all school			11/20/2013 4:23:17 PM				
Villalobos, Margret		School needs to be fumigated for cockroaches and crickets. Thank you.							
Rita Mendez									
110057	Main Building	Portables			11/8/2013		67		\$0.00
Medium	Work In Progress	Art portable			11/8/2013 9:49:09 AM				
Gonzalez, Salvador		New storage bldg. (by art portable) needs a ramp. Thank you,							
Rita Mendez									
111624					1/5/2014	1/11/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:47 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PMSchedule details.							
Margret Villalobos									
Count: 36 Work Orders			Avg. Age of WO's	52		Total for Santa Teresa ES	0		\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

108661 Exterior 10/9/2013 97 \$0.00

Medium Work In Progress 10/9/2013 10:15:53 PM

Gonzalez, Salvador The Arroyo fence has been cut again. Will need repair please.

William Dickson

105345 8/4/2013 8/10/2013 163 \$0.00

Medium Work In Progress 8/4/2013 12:20:08 AM

Mijarez, Jaime Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

110693 12/1/2013 12/7/2013 44 \$0.00

Medium Work In Progress 12/1/2013 12:33:15 AM

Mijarez, Jaime Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

109776 11/3/2013 11/9/2013 72 \$0.00

Medium Work In Progress 11/3/2013 12:26:12 AM

Mijarez, Jaime Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

111625 1/5/2014 1/11/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:24:47 AM

Mijarez, Jaime Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

106284 Custodial 8/20/2013 147 \$0.00

Medium Work In Progress 8/20/2013 1:54:32 PM

Flores, Pete gas blower draw string broke ROUTE TO AUTO SHOP AS PER JIMMY

284793207

110177 11/13/2013 62 \$0.00

Medium Work In Progress 11/13/2013 8:16:25 AM

Gonzalez, Salvador Welding teacher will be install a dream catcher post by football field. He needs bracing to plumb the post. I spoke to Sal and I will give him the date when we need him to do the bracing.

Jaime Mijarez

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
111905					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 2:03:19 PM				
Carrasco, Danny		Three windows on top of the roof by 500 wing were broken, one window broken at rotc uniform storage room.							
Jaime Mijarez									
108087		Exterior			9/29/2013		107		\$0.00
Medium	Work In Progress				9/29/2013 12:19:45 PM				
Gonzalez, Salvador		The fence by the arroyo has been cut again. Could we get the welder to come in and redo the area. Thanks!							
William Dickson									
111909					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 2:26:29 PM				
Mijarez, Jaime		Asp PM serviced by Dimar - need to add oil and rotate FDC.							
Michael Munoz									
111913					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 2:30:03 PM				
Mijarez, Jaime		Asp PM serviced by Dimar - FAC cap missing in 200 Wing							
Michael Munoz									
111914					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 2:30:43 PM				
Mijarez, Jaime		Asp PM serviced by Dimar - FAC cap missing in 300 Wing							
Michael Munoz									
105592					8/7/2013		160		\$0.00
Medium	Work In Progress				8/7/2013 12:52:27 PM				
Mijarez, Jaime		Asp inspection on PM Fire Sprinkler by Dimar the following was found: FDC missing cap							
Michael Munoz									
111646					1/5/2014	1/26/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:25:00 AM				
Munoz, Michael		Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

109562	Main Building	Classroom			10/30/2013		76		\$0.00
Medium	Work In Progress				10/30/2013 7:16:36 PM				

Lara, Ralph Room 509 is having trouble with door locks and has a cabinet that needs keys to lock doors.

William Dickson

109947	Main Building	Classroom			11/5/2013		70		\$0.00
Medium	Work In Progress				11/5/2013 4:33:24 PM				

Lara, Ralph Room 511 is having trouble with some cabinet locks. These locks are important because it locks up the area where acid is stored. Dangerous.

William Dickson

109618	Main Building	Classroom			11/1/2013		74		\$0.00
Medium	Work In Progress	406, 410, 402,			11/1/2013 10:48:10 AM				

Mijarez, Jaime These classrooms received smart boards. The walls need to be painted where old chalkboards were removed.

Kathryn Harper

106456	Main Building	Classroom			8/23/2013		144		\$0.00
Medium	Work In Progress	203			8/23/2013 10:56:44 AM				

Ambriz, Jose The A/C in room 203 is VERY loud!. Teacher has to speak loudly and it's hard to students to hear. Please make this a priority. Thanks.

Kathryn Harper

107101	Main Building	Foyer			9/5/2013		131		\$0.00
Medium	Work In Progress				9/5/2013 5:52:04 AM				

Ambriz, Jose water fountain in 400 hallway is leaking

Isaac Holguin

110077	Main Building	Mechanical			11/8/2013		67		\$0.00
Medium	Work In Progress				11/8/2013 3:38:05 PM				

Ontiveros, Joe Need to Replaces 1 inch Gas Riser rusted out outside boiler RM.

Joe Ontiveros

109291	Main Building	Classroom			10/24/2013		82		\$0.00
Medium	Work In Progress				10/24/2013 11:34:03				

Castillo, Carlos The classroom will need 4 light bulbs replace. The room is dark.

William Dickson

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
109235	Main Building				10/23/2013		83		\$0.00
Medium	Work In Progress				10/23/2013 11:32:57				
Castillo, Carlos	There are 10 light bulbs out in room 202.								
William Dickson									
107918	Main Building	Hallway/Corridor			9/25/2013		111		\$0.00
Medium	Work In Progress				9/25/2013 12:23:23 PM				
Ontiveros, Joe	The water fountain new the front office is leaking non stop. will a plumber come by and fix it. Thanks!								
William Dickson									
110386	Main Building	Restroom			11/19/2013		56		\$0.00
Medium	Work In Progress				11/19/2013 8:04:28 AM				
Ontiveros, Joe	boys restroom urinal needs to be replaced								
Isaac Holguin									
107274	Main Building				9/9/2013		127		\$0.00
Medium	Work In Progress				9/9/2013 4:49:11 PM				
Mijarez, Jaime	Mr. Gutierrez is wanting a white board mounted in his room. He is also wanting the light bulbs that are out replaced.								
William Dickson									
105148	Main Building	Classroom			8/2/2013		165		\$0.00
Medium	Work In Progress				8/2/2013 2:12:07 PM				
Mijarez, Jaime	Need to get a white board and project monted in room 607 for our SPED teacher.								
William Dickson									
107461	Main Building	Classroom			9/15/2013		121		\$0.00
Medium	Work In Progress				9/15/2013 11:08:32 AM				
Mijarez, Jaime	Room 206 has two lights that are out and needs replacement								
William Dickson									
107930	Main Building	Classroom			9/25/2013		111		\$0.00
Medium	Work In Progress	404			9/25/2013 2:52:28 PM				
Mijarez, Jaime	Please mount two dryerase boards to replace two chalkboards in Ms. Renteria's room.								
Kathryn Harper									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

107105	Main Building	Classroom			9/5/2013		131		\$0.00
--------	---------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress	water pumps			9/5/2013 7:30:16 AM				
--------	------------------	-------------	--	--	---------------------	--	--	--	--

Mijarez, Jaime Please replace water pumps

Kathryn Harper

106268	Main Building	Classroom			8/20/2013		147		\$0.00
--------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/20/2013 9:04:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime Jaime asp Mike need to change out all ceiling tiles that are stained w/mold in this area. Also, to include in other areas as needed.
We are witnessing more mold in the 500 hallway. Room 509 has reported mold in the ceiling tile. Room 501 also has reported additional mold growing in the walls and ceiling tile. This has become a big problem and it will continue to grow unless something is changed. Thanks!

William Dickson

106459	Main Building	Classroom			8/23/2013		144		\$0.00
--------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/23/2013 11:20:00 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Mijarez, Jaime Need light bulbs for classroom C-2. Classroom very dark. It is a computer lab.

William Dickson

106642	Main Building				8/28/2013		139		\$0.00
--------	---------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/28/2013 9:31:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime Teacher wants 21 chairs taken out of classroom.

William Dickson

106121	Main Building	Classroom			8/16/2013		151		\$0.00
--------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Nurses station			8/16/2013 8:18:56 AM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Estrada, Jesus Carpet in nurses office needs to be repaired.

Kathryn Harper

106578	Main Building	Classroom			8/27/2013		140		\$0.00
--------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	band room			8/27/2013 1:36:28 PM				
--------	------------------	-----------	--	--	----------------------	--	--	--	--

Miranda, Danny Right outside band room, there's a hole in the wall

Kathryn Harper

109242	Main Building				10/23/2013		83		\$0.00
--------	---------------	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/23/2013 1:51:44 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Mijarez, Jaime Room 500 has a ceiling tile that has fallen from the ceiling. Needs repair.
Thanks!

William Dickson

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

107779	Main Building	Computer Lab			9/20/2013		116		\$0.00
--------	---------------	--------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/20/2013 4:59:04 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime Relocate a white board so students can review their work.

William Dickson

107780	Main Building	Computer Lab			9/20/2013		116		\$0.00
--------	---------------	--------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/20/2013 5:03:05 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime The classroom that needed the white board moved is C2

William Dickson

111174	Dressing Rooms	Dressing Room			12/11/2013		34		\$0.00
--------	----------------	---------------	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/11/2013 3:35:47 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos Dressing room time clocks need off-on switch to avoid coaching staff to be turning off circuit breakers.

Carlos Castillo

111874	Vocational	Classroom			1/9/2014		5		\$0.00
--------	------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress				1/9/2014 10:47:57 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime The kids in studio to cook ceramic is not working. One braked in the box is taped. Please check it out. Thanks.

William Dickson

111875	Vocational	Classroom			1/9/2014		5		\$0.00
--------	------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress				1/9/2014 10:51:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime Heat will not come on in the clayshop. Need paper dispenser added to sink area. Room is covered with spider webs may have a black widow in the area. Please check out.

William Dickson

111903	Vocational				1/10/2014		4		\$0.00
--------	------------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/10/2014 1:40:49 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador Cover small windows on doors that vandals have used to gain access into rooms with expanded metal. Check with site administration or security Tellez for specifics.

Alfredo Holguin

111904	Library				1/10/2014		4		\$0.00
--------	---------	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				1/10/2014 1:41:56 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph Alarm buzzer on Emergency Egress doors are not working

Alfredo Holguin

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
107313	Library	Library			9/10/2013		126		\$0.00
Medium	Work In Progress	Library			9/10/2013 3:37:35 PM				
Mijarez, Jaime		Put pictures of Classes in library on wall.							
Kathryn Harper									
111007	Library	Library			12/6/2013		39		\$0.00
Medium	Work In Progress				12/6/2013 5:05:57 PM				
Lara, Ralph		Reverse lock in periodic room and workroom.							
William Dickson									
106455	Annex Building	Classroom			8/23/2013		144		\$0.00
Medium	Work In Progress	705			8/23/2013 10:54:59 AM				
Gallegos, Rafael		Roof in ROTC leaks							
Kathryn Harper									
108991	Annex Building	Kitchen			10/16/2013		90		\$0.00
Medium	Work In Progress				10/16/2013 9:48:40 PM				
Mijarez, Jaime		Room 703 has a water leak from the pipes under the sink. It is causing damages to the wooden cabinet.							
William Dickson									
112047	Main Building	Office			1/14/2014		0		\$0.00
Medium	Work In Progress				1/14/2014 7:39:08 AM				
Gonzales, Camilo		Deliver 30 bx. PO# 131403620HP COMPACQ 6300 PRO(MICRO TOWER) ATTN:M.A. VASQUEZ							
Theresa Ramirez									
109502	Main Building	Classroom			10/29/2013		77		\$0.00
Medium	Work In Progress				10/29/2013 4:13:17 PM				
Mijarez, Jaime		Room 215 needs two broom holders monted on the left wall after entering the front door, a pattern is taped to the wall where the holder is to be placed. The hardeare is taped to the pattern. Thge other broom holder patrn is taped on the wall in the storage closet.							
William Dickson									
107460	Main Building	Classroom			9/15/2013		121		\$0.00
Medium	Work In Progress				9/15/2013 11:06:56 AM				
Mijarez, Jaime		The culinary kitchen needs a can opener installed needs to see the Teacher for position of installment.							
William Dickson									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

107815	Main Building	Kitchen			9/23/2013		113		\$0.00
--------	---------------	---------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/23/2013 2:04:36 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe
The culinary kitchen does not have hot water to wash dishes. Can we have the plumber here to fix whatever is wrong.
Thanks!

William Dickson

109615	Main Building	Classroom			11/1/2013		74		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	707			11/1/2013 8:47:50 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Castillo, Carlos
Lights in room 707 (Ms. Luck) and also the main hallway keep going out.

Kathryn Harper

106340	Locker Room	Football Field			8/21/2013		146		\$0.00
--------	-------------	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Turf			8/21/2013 11:21:44 AM				
--------	------------------	------	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
Graffiti remains on turf, needs to be removed. (See Coach Vierra or Ms. Harper)

Kathryn Harper

106125	Locker Room	Gym			8/16/2013		151		\$0.00
--------	-------------	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Pe locker room			8/16/2013 8:25:08 AM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Gonzalez, Salvador
Removal of bent or broken locker doors in PE boys dressing room.

Kathryn Harper

106153	Locker Room	Gym			8/16/2013		151		\$0.00
--------	-------------	-----	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Pe locker room			8/16/2013 3:24:08 PM				
--------	------------------	----------------	--	--	----------------------	--	--	--	--

Estrada, Jesus
Carpet square in back of weight room need to be replaced.

Kathryn Harper

111876	Cafeteria (2005)	Classroom			1/9/2014		5		\$0.00
--------	------------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress				1/9/2014 10:53:38 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Escobar, David
The curtains for the stage are in and need to be hung. Will you hang these up please.
Thanks.

William Dickson

110385	Cafeteria (2005)	Restroom (Girls)			11/19/2013		56		\$0.00
--------	------------------	------------------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/19/2013 8:03:09 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Joe
girls restroom automatic flush valve stuck

Isaac Holguin

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
108549	Cafeteria (2005)	Restroom			10/7/2013		99		\$0.00
Medium	Work In Progress				10/7/2013 7:45:26 PM				
Mijarez, Jaime		The restroom in the cafeteria needs a paper dispenser. The one that was there is broken.							
William Dickson									
107202	Cafeteria (2005)	Cafeteria			9/6/2013		130		\$0.00
Medium	Work In Progress				9/6/2013 5:00:50 PM				
Mijarez, Jaime		Culinary kitchen needs the shelves reinstalled in dining room counter area see teacher.							
William Dickson									
107203	Cafeteria (2005)				9/6/2013		130		\$0.00
Medium	Work In Progress				9/6/2013 5:03:35 PM				
Mijarez, Jaime		Culinary Kitchen has a table that needs two legs that attaches to the wall (or existing counter) in dish area. 2nd notice				12/18/13 - One year warranty ran out in December 2012. This is a Building Mechanic work order. R. Gallegos			
William Dickson									
106338	GYM (2009)	Gym			8/21/2013		146		\$0.00
Medium	Work In Progress	New boys			8/21/2013 11:17:00 AM				
Ontiveros, Joe		In new boys athletic locker room repair leaky student shower (will not full shut off) see coach douglas							
Kathryn Harper									
106341	GYM (2009)	Gym			8/21/2013		146		\$0.00
Medium	Work In Progress	Basketball gym			8/21/2013 11:22:54 AM				
Mijarez, Jaime		Foam rubber edging around basketball backboards in both gyms coming off, needs to be replaced/repared (see Coach Haack or Coach Dotson)							
Kathryn Harper									
106333	GYM (2009)	Gym			8/21/2013		146		\$0.00
Medium	Work In Progress	Weight room			8/21/2013 11:06:11 AM				
Estrada, Jesus		Replace carpet tiles in weightroom							
Kathryn Harper									
111492					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:24 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

110588 12/1/2013 12/4/2013 44 \$0.00

Medium Work In Progress 12/1/2013 12:32:23 AM

Mijarez, Jaime Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.

Margret Villalobos

109681 11/3/2013 11/6/2013 72 \$0.00

Medium Work In Progress 11/3/2013 12:25:32 AM

Mijarez, Jaime Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.

Margret Villalobos

108247 10/6/2013 10/9/2013 100 \$0.00

Medium Work In Progress 10/6/2013 12:22:51 AM

Mijarez, Jaime Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.

Margret Villalobos

111500 1/5/2014 1/8/2014 9 \$0.00

Medium Work In Progress 1/5/2014 12:23:28 AM

Mijarez, Jaime Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.

Margret Villalobos

108093 9/30/2013 106 \$0.00

Medium Work In Progress 9/30/2013 12:35:38 AM

Mijarez, Jaime Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.

Margret Villalobos

104038 7/7/2013 8/7/2013 191 \$0.00

Medium Work In Progress 7/7/2013 12:22:38 AM

Mijarez, Jaime Yearly - Santa Teresa HS A-11 Air Han Unit Yearly - Refer to PM schedule details.

Margret Villalobos

109373 10/28/2013 78 \$0.00

Medium Work In Progress 10/28/2013 7:58:20 AM

Castillo, Carlos Cafeteria area indoor lights went off except kitchen area. Breaker panel H-5 breaker 14 was tripped by sub panel H-5 breaker 18, and breaker 8 both breakers are for chorus room storages. I left the 2 breakers off to reset breaker 14 and turned on all of the cafeteria lights.

Jaime Mijarez

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
109579					10/31/2013		75		\$0.00
Medium	Work In Progress				10/31/2013 9:04:06 AM				
Castillo, Carlos		Marylou is requesting recepticle with power installed on ceiling for smartboard projector in Room 202, and Room 212.							
Jaime Mijarez									
109208					10/22/2013		84		\$0.00
Medium	Work In Progress				10/22/2013 3:45:56 PM				
Castillo, Carlos		Main entrance hallway. All the ivory light switches need to be replaced they are broken and are not working properly. Please check with me (Jaime).							
Jaime Mijarez									
107729					9/20/2013		116		\$0.00
Medium	Work In Progress				9/20/2013 9:02:51 AM				
Ontiveros, Joe		Football locker room. Sewage was backing up again.							
Jaime Mijarez									
111714					1/7/2014		7		\$0.00
Medium	Work In Progress	LINE LOCATE			1/7/2014 8:26:52 AM				
Ontiveros, Joe		Lynco will be drilling at Santa Teresa on Tuesday, 01/14/2014 and will need utilities located. They have the piers marked on the ground and will need your district to locate any utilities underground at these locations.							
Rafael Gallegos									
111738					1/7/2014		7		\$0.00
Medium	Work In Progress				1/7/2014 2:48:17 PM				
Ontiveros, Joe		caffeteria kitchen could not locate a shut off water valve for 3/8 water line to make up air system for kitchen hood. Will need to install a shut off valve. water line burst during holiday break and couldn't shut off water due to no shut off valve present.							
David Escobar									
110010					11/7/2013		68		\$0.00
Medium	Work In Progress				11/7/2013 8:07:10 AM				
Ontiveros, Joe		Gas line outside by 300 wing boiler room is cracked. Needs to be repaired before we get colder weather. Gas line supplies to the 300 wing hydraunic heating system boiler.							
Jaime Mijarez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
111713					1/7/2014		7		\$0.00
Medium	Work In Progress	LINE LOCATE		1/7/2014 8:25:58 AM					
Sotelo, Enrique	Lynco will be drilling at Santa Teresa on Tuesday, 01/14/2014 and will need utilities located. They have the piers marked on the ground and will need your district to locate any utilities underground at these locations.								
Rafael Gallegos									
112048		Athletic Field			1/14/2014		0		\$0.00
Medium	Work In Progress			1/14/2014 7:39:26 AM					
Castillo, Carlos	Need to line locate for Lynco Electric at baseball and softball fields prior to digging holes for light pole installation.								
Carlos Castillo									
111353		Parking Lot			12/17/2013		28		\$0.00
Medium	Work In Progress			12/17/2013 10:38:20					
Castillo, Carlos	Some of the parking light lites are not working. Needs attention because it is very dark at night in some spots.								
William Dickson									
109335		Classroom			10/25/2013		81		\$0.00
Medium	Work In Progress	MR.		10/25/2013 2:14:07 PM					
Castillo, Carlos	NEED AN ELECTRICAL OUTLET FOR PROJECTOR MOUNTED INTO CEILING FOR SMARTBOARD.								
Marylou Jimenez									
109895		Classroom			11/5/2013		70		\$0.00
Medium	Work In Progress	MR.		11/5/2013 10:21:34 AM					
Castillo, Carlos	NEED ELECTRICAL OUTLET INSTALLED IN CEILING FOR PROJECTOR.								
Marylou Jimenez									
105218					8/4/2013	8/7/2013	163		\$0.00
Medium	Work In Progress			8/4/2013 12:19:11 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.								
Margret Villalobos									
111970					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress			1/12/2014 12:17:50 AM					
Holguin, Isaac	Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.								
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
108838					10/14/2013		92		\$0.00
Medium	Work In Progress				10/14/2013 1:20:08 PM				
Holguin, Isaac		KITCHEN AREA- SOAP DISPENSER NEEDS TOP BE FIXED IN RESTROOM. SNP MANAGER OLGA B. 589.5332							
Maritza Gonzalez									
111205					12/12/2013		33		\$0.00
Medium	Work In Progress				12/12/2013 10:35:37				
Ambriz, Jose		Do you know what is going on with the heating at STHS in the area listed on the subject line? We need to check these systems to see if they are functioning correctly. It seems that at the time I looked at the system, when it was 25 degrees outside. The main gym is the only one at the correct temperature. Please check on them. Thanks				Called Trane			
Rafael Gallegos									
104672					7/24/2013		174		\$0.00
Medium	Work In Progress				7/24/2013 8:52:31 AM				
Ambriz, Jose		HU2 airhandler at cafeteria is single phasing. Disconnected the line legs to motor and turned off power to unit.							
Jaime Mijarez									
108286					10/6/2013	11/6/2013	100		\$0.00
Medium	Work In Progress				10/6/2013 12:23:11 AM				
Marquez, Gerardo		Yearly - Santa Teresa HS U-2 Unit Ht Gas Yearly - Refer to PM schedule details.							
Margret Villalobos									
108284					10/6/2013	11/6/2013	100		\$0.00
Medium	Work In Progress				10/6/2013 12:23:10 AM				
Marquez, Gerardo		Yearly - Santa Teresa HS H-6 Rtop Furn Yearly - Refer to PM schedule details.							
Margret Villalobos									
108285					10/6/2013	11/6/2013	100		\$0.00
Medium	Work In Progress				10/6/2013 12:23:10 AM				
Marquez, Gerardo		Yearly - Santa Teresa HS I-4 Fan Coil Unit Yearly - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
108282					10/6/2013	10/27/2013	100		\$0.00
Medium	Work In Progress				10/6/2013 12:23:09 AM				
Marquez, Gerardo		Monthly - Santa Teresa HS C-12 Chm Feeder Semimtlly - Refer to PMschedule details.							
Margret Villalobos									
108283					10/6/2013	10/27/2013	100		\$0.00
Medium	Work In Progress				10/6/2013 12:23:09 AM				
Marquez, Gerardo		Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PMschedule details.							
Margret Villalobos									
110823					12/4/2013		41		\$0.00
Medium	Work In Progress				12/4/2013 8:22:50 AM				
Lara, Ralph		Room 614 door handle is old needs to be replaced. I lubricated the handle mean while to make it work, plus two pieces of the handle were broken and fell out.							
Jaime Mijarez									
111171					12/11/2013		34		\$0.00
Medium	Work In Progress				12/11/2013 3:32:34 PM				
Lara, Ralph		Need to issue keys for new employee David Escobar will be starting 1/6/14.							
Michael Munoz									
106495					8/26/2013		141		\$0.00
Medium	Work In Progress				8/26/2013 9:08:31 AM				
Ambriz, Jose		Room 203. Slave fan coil unit has a noisysquerrel cage. I had to shutdown unit through tracer summit so it won't disrupt the classroom.							
Jaime Mijarez									
107735					9/20/2013		116		\$0.00
Medium	Work In Progress				9/20/2013 10:08:04 AM				
Marquez, Gerardo		Girls soccer locker room. Security Angie broke her key in the core. I tried taking the piece out but no luck. Angie will need a new key.							
Jaime Mijarez									
111506					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:32 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Roof Inspection - Refer to PMschedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

106327 8/21/2013 146 \$0.00

Medium Work In Progress 8/21/2013 9:56:59 AM

Holguin, Alfredo
 Attn: Alfredo Holguin. Roof goose neck vents in old main bldg areas total of 18 count from 12", 24" and 36". These vents are causing roof leaks and ceiling tile damage which produces mold on tiles. Several of the dampers are not functional, screens are detached or torn. One of the problems we've had is cats going into the building and also accessible to intruders breaking in. I viewed the additions to the building and they have a newer and better vent design with a cap on top for better rain water protection and intruder protection. Let me know if you need more information.

Jaime Mijarez

110332 11/16/2013 59 \$0.00

Medium Work In Progress 11/16/2013 12:18:10

Flores, Pete
 Yearly - Santa Teresa HS - Mower 0425 - Grounds - Refer to PM schedule details.

Margret Villalobos

107284 Library 9/10/2013 126 \$0.00

Medium Work In Progress 9/10/2013 8:38:41 AM

Mijarez, Jaime
 Library - The security mirror in the back of the library needs to be hung.

William Dickson

110896 Classroom 12/5/2013 40 \$0.00

Medium Work In Progress ROOM #404 12/5/2013 2:26:42 PM

Mijarez, Jaime
 JAIME CAN YOU PLEASE MOUNT 2 PROJECTION SCREENS IN MRS. RENTERIA'S ROOM #404 AND MR. HELM ROOM #700

Marylou Jimenez

108657 Kitchen 10/9/2013 97 \$0.00

Medium Work In Progress 10/9/2013 10:07:49 PM

Mijarez, Jaime
 Culinary Arts Kitchen needs 2 leg table attached to the wall in dish room.

William Dickson

108658 Kitchen 10/9/2013 97 \$0.00

Medium Work In Progress 10/9/2013 10:09:06 PM

Mijarez, Jaime
 Culinary Arts Kitchen needs the can opener attached to the table.

William Dickson

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
108659		Kitchen			10/9/2013		97		\$0.00
Medium	Work In Progress				10/9/2013 10:10:33 PM				
Mijarez, Jaime		Culinary Arts Kitchen attach self to the wall see teacher for directions							
William Dickson									
104626					7/23/2013		175		\$0.00
Medium	Work In Progress				7/23/2013 2:12:58 PM				
Mijarez, Jaime		Will need to replace ceiling tiles in several gym dressing rooms. Ceiling tile is a different texture can you please order 4 ea. Bundles of the sample that I gave you or at least match it.							
Jaime Mijarez									
105281					8/4/2013	9/4/2013	163		\$0.00
Medium	Work In Progress				8/4/2013 12:19:40 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
105252					8/4/2013	8/12/2013	163		\$0.00
Medium	Work In Progress				8/4/2013 12:19:27 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
105253					8/4/2013	8/12/2013	163		\$0.00
Medium	Work In Progress				8/4/2013 12:19:27 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
105232					8/4/2013		163		\$0.00
Medium	Work In Progress				8/4/2013 12:19:18 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
110628					12/1/2013	1/1/2014	44		\$0.00
Medium	Work In Progress				12/1/2013 12:32:44 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
110629					12/1/2013		44		\$0.00
Medium	Work In Progress				12/1/2013 12:32:44 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PMSchedule details.							
Margret Villalobos									
110633					12/1/2013	12/9/2013	44		\$0.00
Medium	Work In Progress				12/1/2013 12:32:46 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
110634					12/1/2013	12/9/2013	44		\$0.00
Medium	Work In Progress				12/1/2013 12:32:47 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
109702					11/3/2013		72		\$0.00
Medium	Work In Progress				11/3/2013 12:25:42 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PMSchedule details.							
Margret Villalobos									
107682					9/19/2013		117		\$0.00
Medium	Work In Progress				9/19/2013 9:16:10 AM				
Mijarez, Jaime		Double insulated actuators for fan coil units are wearing out. Please order 6 so that I can start replacing them. I have one of them at my office so that you can get the part number.							
Jaime Mijarez									
111594					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:28 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PMSchedule details.							
Margret Villalobos									
111593					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:27 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PMSchedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
111591					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:26 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
111592					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:26 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
106369					8/21/2013		146		\$0.00
Medium	Work In Progress				8/21/2013 4:00:02 PM				
Mijarez, Jaime		Classrooms and hallways. Replace all ceiling tiles with visible mold or damage from water.							
Jaime Mijarez									
109720					11/3/2013	12/4/2013	72		\$0.00
Medium	Work In Progress				11/3/2013 12:25:49 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
109721					11/3/2013	11/11/2013	72		\$0.00
Medium	Work In Progress				11/3/2013 12:25:49 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
109722					11/3/2013	11/11/2013	72		\$0.00
Medium	Work In Progress				11/3/2013 12:25:49 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
106846					9/1/2013		135		\$0.00
Medium	Work In Progress				9/1/2013 12:29:17 AM				
Sanchez, Raul		Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PMschedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
105868					8/12/2013		155		\$0.00
Medium	Work In Progress				8/12/2013 2:12:56 PM				
Miranda, Danny		Showers in football dressing rooms - found 2 walls in showers with holes as large as 3 feet where students have been kicking in the walls.							
Alfredo Holguin									
111325					12/16/2013		29		\$0.00
Medium	Work In Progress				12/16/2013 4:00:06 PM				
Holguin, Alfredo		Old gym bleachers. Please give work order to (Alfredo H.) I spoke to him. Wood swinging boards that run along the bottom of the bleachers are missing several pins on the hindges, The boards are uneven and won't stay flush with each other. I don't know when was the last time they were serviced.							
Jaime Mijarez									
Count: 125 Work Orders		Avg. Age of WO's 85			Total for Santa Teresa HS			0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
111575					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:16 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
111576					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:16 AM				
Prospero, Manuel		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111574					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:15 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111573					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:14 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
110331					11/16/2013		59		\$0.00
Medium	Work In Progress				11/16/2013 12:18:09				
Flores, Pete		Yearly - Santa Teresa MS - Mower 0416 - Grounds - Refer to PM schedule details.							
Margret Villalobos									
109715					11/3/2013	12/4/2013	72		\$0.00
Medium	Work In Progress				11/3/2013 12:25:47 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
109716					11/3/2013	11/11/2013	72		\$0.00
Medium	Work In Progress				11/3/2013 12:25:47 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
111461					12/31/2013		14		\$0.00
Medium	Work In Progress				12/31/2013 12:32:37				
Prospero, Manuel		Yearly - Santa Teresa MS H6(Roof Furnace)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
111513					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:36 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Roof Inspection - Refer to PMschedule details.							
Margret Villalobos									
111717					1/7/2014		7		\$0.00
Medium	Work In Progress				1/7/2014 8:40:41 AM				
Ontiveros, Guadalupe		Relocate bleachers to Elena Park in Sunland Park for this Friday, January 10, 2014 & pickup on Monday. Contact Omar Barraza-575-520-5735							
Michael Munoz									
111972					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:51 AM				
Rodriguez, Ismael		Monthly - QRTLY BLDG INSP REPORT (STM) - Refer to PMschedule details.							
Margret Villalobos									
111431		Electrical Room			12/19/2013		26		\$0.00
Medium	Work In Progress				12/19/2013 9:23:50 AM				
Castillo, Carlos		Annual electrical equipment inspection.							
Carlos Castillo									
106609					8/27/2013		140		\$0.00
Medium	Work In Progress				8/27/2013 3:39:29 PM				
Ontiveros, Joe		Need to Replace broken 4inch pvc pipe next to football field.							
Joe Ontiveros									
108648					10/9/2013		97		\$0.00
High	Work In Progress				10/9/2013 3:55:30 PM				
Ontiveros, Joe		please check fire hydrants for proper operation. as per fire department, the 2/1/2 outlets are broken. please repair. contact at site is frank medina. thank you							
Michael Munoz									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
105812					8/11/2013	9/11/2013	156		\$0.00
Medium	Work In Progress				8/11/2013 12:17:40 AM				
Mijarez, Jaime		Yearly - Santa Teresa MS- A-9 Air Cooled (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
111493					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:25 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
111739					1/7/2014		7		\$0.00
High	Work In Progress				1/7/2014 2:54:01 PM				
Munoz, Michael		please replace all fire hydrants at site they are old and do not work as per fire inspector from sunland							
Alfredo Holguin									
109973	North Building	Custodial			11/6/2013		69		\$0.00
Medium	Work In Progress				11/6/2013 12:41:46 PM				
Gallegos, Rafael		Ajust electrical timer to exterior lights it is getting dark to early as per administration.							
Ismael Rodriguez									
111709	North Building	Athletic Field			1/7/2014		7		\$0.00
Medium	Work In Progress				1/7/2014 8:00:47 AM				
Gonzalez, Salvador		Soccer goal cross bar is broken needs replacement or to be welded as per Jonny before soccer season a.s.a.p thanks..							
Ismael Rodriguez									
105561	North Building	Custodial			8/7/2013		160		\$0.00
Medium	Work In Progress				8/7/2013 9:04:08 AM				
Flores, Pete		Truck #88 needs replacement of water pump.							
Ismael Rodriguez									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

112016	North Building	Office			1/13/2014		1		\$0.00
--------	----------------	--------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	SEE MS			1/13/2014 2:37:03 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Munoz, Michael

BUILD AN ENCLOSURE ON AN EXISTING WALL
AREA:
1- SPACE IS 15 1/2X 16
2- ADD 2 ROWS OF CINDER BLOCK TO AN EXISTING 3 SIDE AREA
3- PURCHASE 4 POSTS
4- PURCHASE GALVANIZED STEEL FOR ROOF
5- ADD A CHAIN LINK FENCE FOR GATE
PURPOSE:
HOUSE FOR 1 OR 2 POLARIS/ CUSTODIANS TRACTOR. MS LOVELACE WILL PROVIDE THE HEAVY DUTY LOCK

Laura Parra

111910	North Building	Classroom			1/10/2014		4		\$0.00
--------	----------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress	20			1/10/2014 2:27:34 PM				
--------	------------------	----	--	--	----------------------	--	--	--	--

Ontiveros, Joe

LEAKY FAUCET

Laura Parra

109457	North Building	Restroom			10/29/2013		77		\$0.00
--------	----------------	----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/29/2013 9:03:08 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Joe

Replace water faucet in boys restroom broken leaking water.

Ismael Rodriguez

106605	North Building	Football Field			8/27/2013		140		\$0.00
--------	----------------	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/27/2013 3:34:39 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe

Need to Replace broken 4inch pvc Clean out pipe next to football field.

Joe Ontiveros

107746	North Building	Office			9/20/2013		116		\$0.00
--------	----------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	ROOM 8			9/20/2013 1:50:16 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Marquez, Gerardo

NEED KEY FOR CABINET LOCATED OUTSIDE NURSES OFFICE

Laura Parra

111083	North Building	Office			12/10/2013		35		\$0.00
--------	----------------	--------	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/10/2013 8:37:03 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose

The heater in my office is not working can you please look into it thank you..

Ismael Rodriguez

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
108607	North Building	Classroom			10/9/2013		97		\$0.00
Medium	Work In Progress	8			10/9/2013 9:43:38 AM				
Castillo, Carlos		NEED EXTRA OUTLETS							
Laura Parra									
110947	South Building	Office			12/6/2013		39		\$0.00
Medium	Work In Progress	MR. ROBERTS			12/6/2013 10:09:11 AM				
Lara, Ralph		LOCK IN CABINET DOOR DOES NOT WORK. USED TO STORE SCHOOL SUPPLIES AND HYGIENE PRODUCTS FOR STUDENTS.							
Laura Parra									
110114	South Building	Restroom (Girls)			11/12/2013		63		\$0.00
Medium	Work In Progress				11/12/2013 9:08:26 AM				
Ontiveros, Joe		5 Gallons of cherry mat for drains.							
Ismael Rodriguez									
112017	South Building	Office			1/13/2014		1		\$0.00
Medium	Work In Progress	SEE MS			1/13/2014 2:40:11 PM				
Munoz, Michael		ADD A SECURE CHAIN LINK GATE TO AN EXISTING COVERED AREA TO PARK A POLARIS. 1- ADD A 9FT WIDE GATE MS. LOVELACE WILL PROVIDE THE HEAVY DUTY LOCK							
Laura Parra									
106730	South Building	Classroom			8/29/2013		138		\$0.00
Medium	Work In Progress	ROOM 46			8/29/2013 11:11:17 AM				
Prospero, Manuel		WHITE BOARD IS COMING OFF WALL							
Laura Parra									
111895	South Building	Office			1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 11:27:14 AM				
Carrasco, Danny		Fuel for administration polaris 4x4.							
Ismael Rodriguez									
112015	Gym (1997)	Restroom (Girls)			1/13/2014		1		\$0.00
Medium	Work In Progress	SNYDER			1/13/2014 2:34:02 PM				
Ontiveros, Joe		NONE OF THE BATHROOMS FLUSH CONSISTENTLY.							
Laura Parra									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
111670	Gym (1997)	Restroom (Girls)			1/6/2014		8		\$0.00
Medium	Work In Progress			1/6/2014 12:02:40 PM					
Solis, Lorenzo		Heater in girls dressing room not working properly needs service.							
Ismael Rodriguez									
109966	Gym (1997)	Gym			11/6/2013		69		\$0.00
Medium	Work In Progress			11/6/2013 11:11:20 AM					
Prospero, Manuel		As per administration basketball courts lanes outside the gym need to be painted there are faded and are use for basketball practice.							
Ismael Rodriguez									
111616					1/5/2014	1/11/2014	9		\$0.00
Medium	Work In Progress			1/5/2014 12:24:42 AM					
Prospero, Manuel		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
109768					11/3/2013	11/9/2013	72		\$0.00
Medium	Work In Progress			11/3/2013 12:26:09 AM					
Prospero, Manuel		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
Count: 37 Work Orders		Avg. Age of WO's 49			Total for Santa Teresa MS			0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

111636					1/5/2014	1/11/2014	9		\$0.00
--------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				1/5/2014 12:24:54 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Carlos Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

112021					1/13/2014		1		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	OFFICE MS.			1/13/2014 3:18:19 PM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Gonzales, Camilo AS APPROVED BY MS. DUQUE- CARLOS, PLEASE PICK UP DESK AT THE CHILD FIND OFFICE AT LA UNION ELEMENTARY FOR MS. VALDEZ. IF YOU HAVE ANY QUESTIONS, PLEASE SEE MS. VALDEZ IN ROOM #35. THANK YOU.

David Avila

111491					1/5/2014	2/5/2014	9		\$0.00
--------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				1/5/2014 12:23:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Sunland Park ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

109022					10/17/2013		89		\$0.00
--------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				10/17/2013 3:23:57 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos need new light fixture in nurses bathroom

Carlos Hernandez

108054					9/27/2013		109		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/27/2013 3:29:09 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Joe need to reconnect gas in portable f going to use for p.e.

Carlos Hernandez

107040					9/4/2013		132		\$0.00
--------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress	TEACHER'S			9/4/2013 7:57:55 AM				
--------	------------------	-----------	--	--	---------------------	--	--	--	--

Ontiveros, Joe AS PER MS. DUQUE----- NEED TO HAVE SINK INSTALLED IN THE TEACHER'S LOUNGE. PLEASE SEE MS. DUQUE ABOUT THIS IF THERE ARE ANY QUESTIONS. THANK YOU.

David Avila

111993					1/12/2014	1/28/2014	2		\$0.00
--------	--	--	--	--	-----------	-----------	---	--	--------

Medium	Work In Progress				1/12/2014 12:18:03 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Valeria Monthly - QRTLTY BDLG INSP REPORT (SP) - Refer to PM schedule details.

Margret Villalobos

1/14/2014 10:19:08 AM

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

106658 8/28/2013 139 \$0.00

Medium Work In Progress 8/28/2013 2:23:40 PM

Castillo, Valeria NEED TO WSH WALLS, SHOWER SCRUB & WAX FLOORS IN ROOM #19

Jesus Estrada

111089 12/10/2013 35 \$0.00

Medium Work In Progress FRONT 12/10/2013 9:32:32 AM

Castillo, Valeria VALERIA - AS PER MR. VAN NOSDALE NEED FRONT COURTYARD TO BE CLEANED AND WASHED DAILY. PLEASE USE THE WATER PRESSURE MACHINE THAT WAS PURCHASED FOR THAT INTENTION. ENSURE THAT THIS IS DONE BY TUESDAY, DECEMBER 17, 2013 FOR THE HOLIDAY EVENING PROGRAM. IF YOU HAVE ANY QUESTIONS, PELASE FEEL FREE TO ASK. THANK YOU.

David Avila

111090 12/10/2013 35 \$0.00

Medium Work In Progress CAFETERIA 12/10/2013 9:35:07 AM

Castillo, Valeria VALERIA - AS PER MR. VAN NOSDALE WOULD LIKE THE CAFETERIA TO BE SWEEPED OUT, MOPPED AND CLEANED FOR THE HOLIDAY PROGRAM. ALSO, MAIN HALLWAY NEEDS TO BE CLEANED AND MOPPED BY DECEMBER 17, 2013 FOR THE HOLIDAY PROGRAM. THANK YOU.,

David Avila

109504 10/30/2013 76 \$0.00

Medium Work In Progress FRONT 10/30/2013 7:30:31 AM

Castillo, Valeria AS PER MR. VAN NOSDALE- VALERIA, WHEN CLEANING THE FRONT COURTYARD, PLEASE ENSURE TO USE THE WATER PRESSURE MACHINE THAT WAS PURCHASED BY THE SCHOOL. THE WATER PRESSURE MACHINE WAS PURCHASED SPECIFICALLY FOR THE CLEANING AND REMOVING OF BIRD DROPPINGS IN THE COURTYARD. IF YOU HAVE ANY QUESTIONS, PLEASE FEEL FREE TO LET ME KNOW.

THANK YOU.

David Avila

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
110843					12/4/2013		41		\$0.00
Medium	Work In Progress				12/4/2013 1:24:14 PM				
Ambriz, Jose		need new heating and cooling system for portable f							
Carlos Hernandez									
106228					8/19/2013		148		\$0.00
Medium	Work In Progress				8/19/2013 3:21:34 PM				
Ambriz, Jose		room 33 needs new a/c unit (43)							
Carlos Hernandez									
112000					1/13/2014		1		\$0.00
Medium	Work In Progress	OFFICE - MS.			1/13/2014 8:52:11 AM				
Lara, Ralph		RALPH- AS PER MS. DUQUE- NEEDS CURRENT CYLINDER MOVED TO A DIFFERENT AREA IN WHICH TEST WILL BE KEPT. PLEASE SEE DAVID AVILA FOR INSTRUCTIONS. THANK YOU.							
David Avila									
106226					8/19/2013		148		\$0.00
Medium	Work In Progress				8/19/2013 3:19:59 PM				
Flores, Pete		truck 191 needs new tires							
Carlos Hernandez									
106155					8/16/2013		151		\$0.00
Medium	Work In Progress				8/16/2013 3:26:33 PM				
Flores, Pete		need new front right tire on truck 191 (has a ball)							
Carlos Hernandez									
111524					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:42 AM				
Hernandez, Carlos		Monthly - Sunland Park ES Roof Inspection - Refer to PMschedule details.							
Margret Villalobos									
111543					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:55 AM				
Hernandez, Carlos		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunland Park ES									
111542					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:54 AM				
Hernandez, Carlos		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111959					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:43 AM				
Hernandez, Carlos		Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
111999					1/13/2014		1		\$0.00
Medium	Work In Progress	MS. KENNON -			1/13/2014 8:32:20 AM				
Ronquillo, Ruben		CARLOS - AS PER MS. KENNON , PLEASE FIX BROKEN WINDOW. GLASS IS SHATTERED (LOOKS LIKE A SMALL ROCK WAS THROWN AT IT). THANK YOU.							
David Avila									
Count: 21 Work Orders			Avg. Age of WO's	55		Total for Sunland Park ES	0		\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
111610					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:38 AM				
Apodaca, Mario		Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
111979					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:55 AM				
Vargas, Juan		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
111019					12/8/2013	12/24/2013	37		\$0.00
Medium	Work In Progress				12/8/2013 12:18:48 AM				
Vargas, Juan		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
111514					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:37 AM				
Vargas, Juan		Monthly - Sunrise ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
107279					9/10/2013		126		\$0.00
Medium	Work In Progress				9/10/2013 8:17:26 AM				
Flores, Pete		430 mower need replace blade							
Juan Vargas									
112023					1/13/2014		1		\$0.00
Medium	Work In Progress				1/13/2014 3:26:50 PM				
Vargas, Juan		need trimmer all trees roun the school							
Juan Vargas									
109633					11/1/2013		74		\$0.00
Medium	Work In Progress				11/1/2013 3:04:55 PM				
Vargas, Juan		need replace delayfuses 5 amp							
Juan Vargas									
109638					11/1/2013		74		\$0.00
Medium	Work In Progress				11/1/2013 3:21:09 PM				
Vargas, Juan		11-1 13 1- check school 3- fix heater in p.2 1- fix toilet in 300 r,room 1- fix ramp p. 1 2- fix exauthfan in kitchen							
Juan Vargas									
1/14/2014 10:19:08 AM									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
111600					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:32 AM				
Vargas, Juan		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
111598					1/5/2014		9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:31 AM				
Vargas, Juan		Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
111599					1/5/2014	1/13/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:31 AM				
Vargas, Juan		Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
107628					9/18/2013		118		\$0.00
Medium	Work In Progress				9/18/2013 12:34:06 PM				
Vargas, Juan		need change 20 ft, extension leter							
Juan Vargas									
111144					12/11/2013		34		\$0.00
Medium	Work In Progress				12/11/2013 8:59:01 AM				
Vargas, Juan		need relace exauhst fan in 300 hall electrical closed							
Juan Vargas									
105697					8/8/2013		159		\$0.00
Medium	Work In Progress				8/8/2013 3:06:53 PM				
Marquez, Gerardo		doors betwen in rooms 307 and 309 need fix							
Juan Vargas									
106424					8/22/2013		145		\$0.00
Medium	Work In Progress				8/22/2013 3:36:46 PM				
Marquez, Gerardo		marqui need replace locks							
Juan Vargas									
111987					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:18:00 AM				
Gallegos, Felipe		Monthly - QRTLY BLDG INSP REPORT (SR) - Refer to PM schedule details.							
Margret Villalobos									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
111927					1/10/2014		4		\$0.00
Medium	Work In Progress				1/10/2014 3:12:34 PM				
Ontiveros, Guadalupe		need replace 6 tress							
Juan Vargas									
112022					1/13/2014		1		\$0.00
Medium	Work In Progress				1/13/2014 3:25:37 PM				
Ontiveros, Guadalupe		need fix 2 in. sprinkler valve							
Juan Vargas									
109922					11/5/2013		70		\$0.00
Medium	Work In Progress				11/5/2013 3:18:06 PM				
Ontiveros, Guadalupe		need 12 tons lavo stone in front parking pond							
Juan Vargas									
110897					12/5/2013		40		\$0.00
Medium	Work In Progress				12/5/2013 2:41:27 PM				
Vallejo, Albert		need replace 2 emergency outside lights							
Juan Vargas									
110017					11/7/2013		68		\$0.00
Medium	Work In Progress				11/7/2013 12:18:53 PM				
Vallejo, Albert		boys r.rooms need replace hand drayer sensor							
Juan Vargas									
108925					10/15/2013		91		\$0.00
Medium	Work In Progress				10/15/2013 3:47:27 PM				
Vallejo, Albert		need move sprinkler disconnect							
Juan Vargas									
111489					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:22 AM				
Villalobos, David		Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
111436					12/19/2013		26		\$0.00
Medium	Work In Progress				12/19/2013 11:34:27				
Appelzoller, Fred		need replace sink fouset in room 301							
Juan Vargas									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Sunrise ES							
111620					1/5/2014	1/11/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:24:44 AM				
Vargas, Juan		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
106427					8/22/2013		145		\$0.00
Medium	Work In Progress				8/22/2013 3:40:03 PM				
Marquez, Gerardo		doors between rooms 309 307 and 212 210 need fixis broken							
Juan Vargas									
Count: 26 Work Orders		Avg. Age of WO's	49			Total for Sunrise ES	0	0	\$0.00

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
105493					8/6/2013		161		\$0.00
Medium	Work In Progress				8/6/2013 12:07:19 PM				
Marquez, Gerardo		need to replace back door to kitchen							
Danny Miranda									
105494					8/6/2013		161		\$0.00
Medium	Work In Progress				8/6/2013 12:10:54 PM				
Marquez, Gerardo		need to replace back door going to bus exit							
Danny Miranda									
111243	Main Building	Custodial			12/13/2013		32		\$0.00
Medium	Work In Progress				12/13/2013 10:58:46				
Carbajal, Jimmy		need vacuum fix has ELEC SHORT							
Armando Diaz									
111497					1/5/2014	2/5/2014	9		\$0.00
Medium	Work In Progress				1/5/2014 12:23:26 AM				
Villalobos, David		Yearly - Vado ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
111842					1/9/2014		5		\$0.00
Medium	Work In Progress				1/9/2014 3:07:06 PM				
Sotelo, Enrique		electrical boxis making a noise in nurses office							
Danny Miranda									
111957					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:42 AM				
Diaz, Armando		Monthly - QRTLY BLDG INSP REPORT (VE) - Refer to PMs schedule details.							
Margret Villalobos									
110570		Cafeteria			11/22/2013		53		\$0.00
Medium	Work In Progress				11/22/2013 4:01:04 PM				
Solis, Lorenzø		ac/heater unit does not turn on therefore exhaust does not come on. will check exhaust again when ac/heater unit is repaired.							
Daniel Orozco									
106787					8/30/2013		137		\$0.00
Medium	Work In Progress				8/30/2013 9:19:14 AM				
Solis, Lorenzø		Check unit in testing room.							
Danny Miranda									

966 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Vado ES							
111962					1/12/2014	1/28/2014	2		\$0.00
Medium	Work In Progress				1/12/2014 12:17:45 AM				
Miranda, Danny		Monthly - Vado ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
106399					8/22/2013		145		\$0.00
Medium	Work In Progress				8/22/2013 10:40:01 AM				
Miranda, Danny		need 3 1" brass sprinklers to water manually and one w/hose bibb							
Danny Miranda									
Count: 10 Work Orders			Avg. Age of WO's 71		Total for Vado ES			0	\$0.00
Count: 966 Work Orders			Avg. Age of WO's 59		Grand Total			0	\$0.00