

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Location Not Assigned							
117083					5/13/2014		22		\$0.00
Medium	Work In Progress				5/13/2014 1:38:16 PM				
Orozco, Daniel		refrig it is not cooling at all the on site maintenance checked it out and tried to reset did not work still holding temp at 70 degrees does have power. SNP Manager Eva M. 882.3410							
Maritza Gonzalez									
Count: 1 Work Orders		Avg. Age of WO's	22			Total for <Blank>	0		\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
117371		Office			5/21/2014		14		\$0.00
Medium	Work In Progress	882-1904			5/21/2014 1:38:13 PM				
Vega, David please waxoffice and launch room floors clean the office and clean office windows thank you...									
Laura Vazquez									
117372		Office			5/21/2014		14		\$0.00
Medium	Work In Progress	882-1904			5/21/2014 1:43:34 PM				
Vega, David please help move furniture form the office									
Laura Vazquez									
117975		Electrical Room			6/4/2014		0		\$0.00
Medium	Work In Progress	882-1904			6/4/2014 9:22:34 AM				
Vega, David please waxfloor from classrooms 111,110,109 and 108 thank you									
Laura Vazquez									
117373		Classroom			5/21/2014		14		\$0.00
Medium	Work In Progress	882-1904			5/21/2014 1:44:58 PM				
Vega, David please help to move, organize and clean room 105									
Laura Vazquez									
117471		Classroom			5/23/2014		12		\$0.00
Medium	Work In Progress	882-1904			5/23/2014 12:41:49 PM				
Nunez, Arturo please paint classrooms 111,110,109,108 thank you									
Laura Vazquez									
117472		Classroom			5/23/2014		12		\$0.00
Medium	Work In Progress	882-1904			5/23/2014 12:42:26 PM				
Nunez, Arturo restroom from room 111 is not working									
Laura Vazquez									
112584		Classroom			1/29/2014		126		\$0.00
Medium	Work In Progress	575-882-1904			1/29/2014 9:25:50 AM				
Nunez, Arturo please paint all classrooms walls for rooms 101,102,103 and 104 thank you									
Laura Vazquez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony - On Track Pre-K (Village)									
107866		Office			9/24/2013		253		\$0.00
Medium	Work In Progress	575-882-1904			9/24/2013 2:01:38 PM				
Nunez, Arturo		restroom form the office is making a noise (when we flash it).							
Laura Vazquez									
113214		Cafeteria			2/10/2014		114		\$0.00
Medium	Work In Progress	575-882-1904			2/10/2014 1:50:52 PM				
Nunez, Arturo		please move white bulletin board and assemble it at the outside wall by the cafeteria... thank you							
Laura Vazquez									
117470		Cafeteria			5/23/2014		12		\$0.00
Medium	Work In Progress	882-1904			5/23/2014 12:40:25 PM				
Nunez, Arturo		please take out all bulleting boards from room 101 & 102 (cafeteria) Thank you							
Laura Vazquez									
110293					11/15/2013		201		\$0.00
Medium	Work In Progress	TEACHER'S			11/15/2013 9:14:07 AM				
Nunez, Arturo		NEED A DOOR THRESHOLD INSTALLED TO PREVENT DIRT FROM COMING IN UNDER THE DOOR (M. HIDALGO 575-618-7459)							
Margaret Villalobos									
117977		Office			6/4/2014		0		\$0.00
Medium	Work In Progress				6/4/2014 9:25:32 AM				
Appelzoller, Fred		the sink from the office launch room is licking water...							
Laura Vazquez									
117973					6/4/2014		0		\$0.00
Medium	Work In Progress				6/4/2014 9:19:58 AM				
Marquez, Gerardo		change all locks on soccer field to 'H' master							
David Vega									
117629					5/29/2014		6		\$0.00
Medium	Work In Progress				5/29/2014 9:31:11 AM				
Marquez, Gerardo		having trouble opening lock on drive through gate of village parking lot.check asap							
David Vega									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Anthony - On Track Pre-K (Village)										
117324					5/20/2014		15		\$0.00	
Medium	Work In Progress				5/20/2014 12:55:00 PM					
Ronquillo, Ruben		PROVIDE NEW ENCLOSED HOSE REEL AS PER RAY LARA. THANK YOU!								
Ruben Ronquillo										
Count: 15 Work Orders			Avg. Age of WO's	53	Total for Anthony - On Track Pre-K (Village)			0	\$0.00	

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
114617					3/13/2014		83		\$0.00
Medium	Work In Progress				3/13/2014 3:28:23 PM				
Gonzalez, Salvador		please add metal build on top concrete slab next to morgan building. for lawn mower coverage. thank you							
Michael Munoz									
113939					2/28/2014		96		\$0.00
Medium	Work In Progress				2/28/2014 12:32:58 AM				
Munoz, Michael		Yearly - Anthony ES - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
115664					4/6/2014		59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:40 AM				
Munoz, Michael		Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
116563					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:37:46 AM				
Villalobos, Margret		Monthly - Anthony ES - Trane PM Quarterly - Refer to PM schedule details.				Emailed 5/5/14			
Margret Villalobos									
117916					6/3/2014		1		\$0.00
Medium	Work In Progress				6/3/2014 8:01:21 AM				
Flores, Pete		fix flats on gator both front tires							
David Vega									
111185					12/11/2013		175		\$0.00
Medium	Work In Progress				12/11/2013 3:52:18 PM				
Flores, Pete		Need to have vechile # 70 checked starter is dragging, having trouble getting started.							
Arturo Nunez									
117976					6/4/2014		0		\$0.00
Medium	Work In Progress				6/4/2014 9:22:41 AM				
Marquez, Gerardo		check mailbox does not want to lock							
David Vega									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Anthony ES

117927 6/3/2014 1 \$0.00

High Work In Progress 6/3/2014 1:40:40 PM

Marquez, Gerardo For Anthony Elementary, two (2) "K" interior gate keys needed for today June 3, 2014. Keys will be checked out to Mario Gonzales of Pure Operations (575) 640-2559. Should you have questions please contact Mr. Gallegos at (575) 882-69221.

Dominique Esparza

117316 5/20/2014 15 \$0.00

Medium Work In Progress 5/20/2014 11:06:17 AM

Marquez, Gerardo hallway door next to custodial closet 232 door lock is jammed

David Vega

107934 9/25/2013 252 \$0.00

Medium Work In Progress 9/25/2013 3:15:54 PM

Marquez, Gerardo Lock on wall marquee in foyer area needs to be replaced.

Arturo Nunez

115639 4/6/2014 4/27/2014 59 \$0.00

Medium Work In Progress 4/6/2014 12:32:23 AM

Orozco, Daniel Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

114846 3/20/2014 76 \$0.00

Medium Work In Progress SPED LOUNGE 3/20/2014 9:39:25 AM

Sotelo, Enrique CHECK ELECTRICAL OUTLETS IN STAFF LOUNGE (THREE ARE NOT WORKING)

Margaret Villalobos

116206 4/24/2014 41 \$0.00

Medium Work In Progress 4/24/2014 11:28:17 AM

Villalobos, David replace water faucet outside of Alamo building (northside) need to water grass

David Vega

112747 1/31/2014 124 \$0.00

Medium Work In Progress 1/31/2014 3:57:45 PM

Sotelo, Enrique Out side lights around building needs to be replaced, will need 20 bulbs, and bucket truck.

Arturo Nunez

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
109941					11/5/2013		211		\$0.00
Medium	Work In Progress				11/5/2013 3:58:09 PM				
Sotelo, Enrique		Need a emergencylight balast for boys restroom.(lay in light fix.)							
Arturo Nunez									
107813					9/23/2013		254		\$0.00
Medium	Work In Progress	office			9/23/2013 1:42:18 PM				
Nunez, Arturo		Mr. Nunez please hang flags Location : office							
Jessica Lopez									
107732					9/20/2013		257		\$0.00
Medium	Work In Progress	SPED			9/20/2013 9:21:01 AM				
Nunez, Arturo		NEED TO RE-CAULK THE WINDOW PANES IN THE DIRECTORS OFFICE (CAULKING IS FALLING OFF)							
Margaret Villalobos									
111246					12/13/2013		173		\$0.00
Medium	Work In Progress				12/13/2013 11:58:48				
Nunez, Arturo		As per Ms. Perez, we need a sign that reads "Right turn only" for our drop off zone							
Jessica Lopez									
113912					2/28/2014	3/31/2014	96		\$0.00
Medium	Work In Progress				2/28/2014 12:32:43 AM				
Nunez, Arturo		Yearly - Anthony ES C-11 (Evap.Down)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
114017					3/2/2014	4/2/2014	94		\$0.00
Medium	Work In Progress				3/2/2014 12:26:08 AM				
Nunez, Arturo		Yearly - Anthony ES R3 (Ref. Unit)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
114016					3/2/2014		94		\$0.00
Medium	Work In Progress				3/2/2014 12:26:07 AM				
Nunez, Arturo		Yearly - Anthony ES A10(Heat Pumps)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
115196					3/31/2014		65		\$0.00
Medium	Work In Progress				3/31/2014 12:54:11 AM				
Nunez, Arturo		Yearly - Anthony ES A6 (Rooftop Unit)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
115191					3/31/2014	5/1/2014	65		\$0.00
Medium	Work In Progress				3/31/2014 12:54:07 AM				
Nunez, Arturo		Yearly - Anthony ES A8(Rooftop Unit)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
115502					4/6/2014	4/14/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:30:42 AM				
Nunez, Arturo		Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
115495					4/6/2014	4/22/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:30:37 AM				
Nunez, Arturo		Monthly - Anthony ES A3(Rooftop Unit)(S.Annual) - Refer to PMschedule details.							
Margret Villalobos									
115488					4/6/2014	5/7/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:30:31 AM				
Nunez, Arturo		Yearly - Anthony ES A13 (AC Wall Mount)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
114841					3/20/2014		76		\$0.00
Medium	Work In Progress	Office			3/20/2014 8:18:14 AM				
Nunez, Arturo		Mr. Nunez as per Ms. Perez please touch up the office during our summer break							
Jessica Lopez									
117753					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:55 AM				
Nunez, Arturo		Yearly - Anthony ES B2(Boiler H.Water)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Anthony ES							
117752					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:54 AM				
Nunez, Arturo		Yearly - Anthony ES - B2 Boiler (Yearly) - Refer to PM schedule details.							
Margret Villalobos									
117008					5/12/2014		23		\$0.00
Medium	Work In Progress	408			5/12/2014 12:17:33 PM				
Nunez, Arturo		Mr. Nunez, please check Mrs. Mendez A/C not working 77 degrees in classroom Room# 408							
Jessica Lopez									
116972					5/11/2014	5/27/2014	24		\$0.00
Medium	Work In Progress				5/11/2014 12:24:41 AM				
Nunez, Arturo		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									
116625					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:29 AM				
Nunez, Arturo		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
116626					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:29 AM				
Nunez, Arturo		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115808					4/13/2014	4/29/2014	52		\$0.00
Medium	Work In Progress				4/13/2014 12:23:59 AM				
Nunez, Arturo		Monthly - Anthony ES A4 (Rooftop Unit)(S. Annual) - Refer to PM schedule details.							
Margret Villalobos									
116066					4/17/2014		48		\$0.00
Medium	Work In Progress				4/17/2014 3:49:51 PM				
Nunez, Arturo		04/17/14 1.0 Sign in paper work. 1.0 Checked and cleaned lock on walk through back gate to village. 2.0 W.O. # 144407. 2.0 Assit David on clogged sewer line. 2.0 Sprayed round up along sidewalks, edges, and basketball courts. G.T. \$ 8.50				4/17			
Arturo Nunez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Anthony ES									
117861					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:55:05 AM					
Nunez, Arturo	Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
117797					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:24 AM					
Nunez, Arturo	Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
117798					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:24 AM					
Nunez, Arturo	Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
117941		Office			6/3/2014		1		\$0.00
Medium	Work In Progress			6/3/2014 3:10:13 PM					
Gonzales, Camilo	Deliver 19 bxs. Math K-6 Eng/Span Workbooks								
Theresa Ramirez									
103957					7/2/2013		337		\$0.00
Medium	Work In Progress	SPED OFFICE		7/2/2013 9:37:24 AM					
Nunez, Arturo	INSTALL WINDOW BLINDS IN THE FRONT OFFICE WINDOW (PREFERRABLY BIG SLATS BUT LITTLE SLATS WILL DO)								
Margaret Villalobos									
103966					7/2/2013		337		\$0.00
Medium	Work In Progress	SPED OFFICE		7/2/2013 3:02:37 PM					
Nunez, Arturo	MOVE DESK FROM BUDGET CLERK OFFICE INTO OTHER OFFICE SEE MARGARET								
Margaret Villalobos									
103967					7/2/2013		337		\$0.00
Medium	Work In Progress	SPED OFFICE		7/2/2013 3:03:37 PM					
Nunez, Arturo	MOVE DESK AND SHELVES FROM MARGARET'S OFFICE INTO NEW EARLY CHILDHOOD OFFICE (SEE MARGARET)								
Margaret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Anthony ES									
105552					8/7/2013		301		\$0.00
Medium	Work In Progress	SPED OFFICE			8/7/2013 7:58:25 AM				
Nunez, Arturo		ASSEMBLE DESK FOR MARGARET (SEE MARGARET OR JULIE)							
Margaret Villalobos									
117878					6/2/2014		2		\$0.00
Medium	Work In Progress				6/2/2014 9:46:29 AM				
Orozco, Daniel		SLICER WILL NOT TURN ON. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									
110042					11/7/2013		209		\$0.00
Medium	Work In Progress				11/7/2013 3:55:07 PM				
Villalobos, David		Water pressure relief valve needs to be replaced on boiler.							
Arturo Nunez									
116519					5/2/2014		33		\$0.00
Medium	Work In Progress				5/2/2014 7:52:09 AM				
Carrasco, Danny		Need a portable air compressor to keep equipment on working order. wil turn in one for exchange. thank you.							
Arturo Nunez									
Count: 46 Work Orders		Avg. Age of WO's 95			Total for Anthony ES			0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Berino ES							
117479					5/23/2014		12		\$0.00
Medium	Work In Progress				5/23/2014 3:29:02 PM				
Carrasco, Danny		MR DANNY CARRASCO SIR WILL NEED ABOUT 10 GAL OF DIESEL FUEL FOR BOBCAT LOADER THANK YOU SIR AND GOD BLESS							
Adan Duran									
117880					6/2/2014		2		\$0.00
Medium	Work In Progress				6/2/2014 9:49:00 AM				
Orozco, Daniel		VEGETABLE SINK LEAKING, SNP MANAGER ELSA C.882.2417							
Maritza Gonzalez									
113310					2/12/2014		112		\$0.00
Medium	Work In Progress				2/12/2014 9:26:34 AM				
Holguin, Alfredo		MR MIKE MUNOZ SIR WILL NEED ENGINEERED WOOD FIBER FOR THREE SET OF SWINGS HAVE SAND ALSO NMSU HEAD START HAS A SMALL CLIMMING EQUIPMENT IN THE EARLY CHILDHOOD PLAYGROUND ALSO HAS SAND THANK YOU SIR AND GOD BLESS							
Adan Duran									
117100					5/13/2014		22		\$0.00
Medium	Work In Progress				5/13/2014 3:42:39 PM				
Duran, Adan		MR ADURAN NEED TO PAINT YELLOW STRIPS BUS TURN AROUND AND ALSO FRONT PARENT PARKING SUMMER PROJECT							
Adan Duran									
117788					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:18 AM				
Duran, Adan		Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
117786					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:17 AM				
Duran, Adan		Monthly - Berino ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

117789 6/1/2014 6/9/2014 3 \$0.00

Medium Work In Progress 6/1/2014 12:54:19 AM

Duran, Adan Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

117757 6/1/2014 7/2/2014 3 \$0.00

Medium Work In Progress 6/1/2014 12:53:58 AM

Duran, Adan Yearly - Berino ES B2(Boiler H.Water)(Yearly) - Refer to PM schedule details.

Margret Villalobos

117863 6/1/2014 6/7/2014 3 \$0.00

Medium Work In Progress 6/1/2014 12:55:07 AM

Duran, Adan Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.

Margret Villalobos

117211 5/15/2014 20 \$0.00

Medium Work In Progress 5/15/2014 4:52:29 PM

Gonzales, Camilo need equipment from Dolores Sanchez (Library) to be picked up and delivered to technology - GAC - Dolores has equipment transfer form

Cora Ramirez

109171 10/22/2013 225 \$0.00

Medium Work In Progress 10/22/2013 1:13:52 PM

Sotelo, Enrique MR ENRIQUE SOTELO SIR NEED TO REPLACE LIGHT BULBS ON POST NEAR MR MORGAN BUILDING AND PUMP HOUSE TO LIGHTS TOO DARK THANK YOU SIR AND GOD BLESS PS WILL NEED LIFT

Adan Duran

117093 5/13/2014 22 \$0.00

Medium Work In Progress 5/13/2014 3:21:01 PM

Villalobos, David MR DAVID VILLALOBOS SIR NEED TO REPLACE 3/4 BRASS BALL VALVE IN BOILER ROOM OLD ONE WILL NOT CLOSE THANK YOU SIR AND GOD BLESS

Adan Duran

115640 4/6/2014 4/27/2014 59 \$0.00

Medium Work In Progress 4/6/2014 12:32:23 AM

Orozco, Daniel Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

6/4/2014 1:35:06 PM

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Berino ES

111198 12/12/2013 174 \$0.00

Medium Work In Progress 12/12/2013 9:16:28 AM

Marquez, Gerardo MR JERRY MARQUEZ SIR ROOM 140 IS SPECAIL ED FOR HANDY-CAP NEED TO SECURE THE DOOR FROM THE INSIDE HAVE KIDS THAT ARE RUNNERS DOOR HAS HANDLE AND THEY ARE ABLE TO OPEN VERY EASY NEED A SAFETY COVER ITS A SAFETY CONCERN THANK YOU SIR AND GOD BLESS MRS RAMIREZ WANTS IT ASAP

Adan Duran

117187 Cafeteria 5/15/2014 20 \$0.00

Medium Work In Progress 5/15/2014 1:03:11 PM

Marquez, Gerardo CAFETERIA- ELSA NEEDS A NEW KEY HER KEY WAS NOT WORKING.

Maribel Chavez

117175 5/15/2014 20 \$0.00

Medium Work In Progress 5/15/2014 8:01:00 AM

Marquez, Gerardo MR G MARQUEZ SIR THE HANDLE ON DOOR PORTABLE 155 KEEPS COMING OFF ITS WORE OUT NEED TO REPLACE THANK YOU AND GOD BLESS

Adan Duran

117258 5/19/2014 16 \$0.00

Medium Work In Progress 5/19/2014 9:43:53 AM

Flores, Pete MR PETE FLORES SIR NEED THE USE OF THE BOBCAT NEED TO CLEAN AND MOVE ALOT OF SAND THANK YOU SIR AND GOD BLESS

Adan Duran

113940 2/28/2014 96 \$0.00

Medium Work In Progress 2/28/2014 12:32:58 AM

Munoz, Michael Yearly - Berino ES - Fire Pump Inspection - Refer to PM schedule details.

Margret Villalobos

116540 5/2/2014 33 \$0.00

Medium Work In Progress 5/2/2014 3:19:11 PM

Ontiveros, Guadalupe MR LUPE ONTIVEROS SIR PER MR MUNOZ NEED TO BORROW LITTLE JOHN DEER LOADER LOTS OF SAND NEED TO CLEAN THANK YOU SIR AND GOD BLESS

Adan Duran

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Berino ES									
116729					5/5/2014		30		\$0.00
Medium	Work In Progress				5/5/2014 3:17:24 PM				
Ontiveros, Guadalupe		MR LUPE ONTIVEROS SIR HAVE IRRGATION VALVE BROKEN NEEDS REPLACING IN FRONT MIDDLE ISLAND							
Adan Duran									
117299	Main Building	Library			5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 7:41:52 AM				
Gonzales, Camilo		Pick up (4) items from the library and deliver to the Tech. Department at the GAC. Attn: Cora Ramirez.							
Theresa Ramirez									
117301	Main Building	Library			5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 7:44:18 AM				
Gonzales, Camilo		Pick Up (6) items from the Library and deliver to the GAC. Attn: Cora Ramirez							
Theresa Ramirez									
115050	Main Building	Mechanical			3/26/2014		70		\$0.00
Medium	Work In Progress				3/26/2014 7:32:54 AM				
Villalobos, David		The storage tank to the water heater boiler is rotting out and will need to be replaced							
David Villalobos									
Count: 23 Work Orders		Avg. Age of WO's 43			Total for Berino ES			0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
Location: Chaparral Elem East Pre-K										
117876					6/2/2014		2		\$0.00	
Medium	Work In Progress	Office & room			6/2/2014 8:41:49 AM					
Quinones, Paul		air conditioner in office not working correctly.								
Noemi Duron										
117883					6/2/2014		2		\$0.00	
Medium	Work In Progress	Office & room			6/2/2014 10:03:40 AM					
Quinones, Paul		room 103 the sink is missing the caulk around it therefore it is lifting.								
Noemi Duron										
Count: 2 Work Orders			Avg. Age of WO's	2	Total for Chaparral Elem East Pre-K			0	\$0.00	

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
117742					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:48 AM				
Quinones, Paul		Monthly - Chaparral ES A-2 Quarterly H/C - Refer to PM schedule details.							
Margret Villalobos									
116985					5/11/2014	5/27/2014	24		\$0.00
Medium	Work In Progress				5/11/2014 12:24:51 AM				
Quinones, Paul		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
116163					4/23/2014		42		\$0.00
Medium	Work In Progress				4/23/2014 12:12:03 PM				
Quinones, Paul		need a round up sprayer with hose and tank for weed control							
Paul Quinones									
113626					2/20/2014		104		\$0.00
Medium	Work In Progress				2/20/2014 3:55:07 PM				
Quinones, Paul		paint bus turnaround traffic yellow							
Paul Quinones									
106592					8/27/2013		281		\$0.00
Medium	Work In Progress				8/27/2013 2:53:40 PM				
Quinones, Paul		girls rest rm. in e-wing,metal latches are broken that secure doors.latches need to be replaced							
Paul Quinones									
109444					10/28/2013		219		\$0.00
Medium	Work In Progress				10/28/2013 3:58:57 PM				
Quinones, Paul		module board for heater in rm.214							
Paul Quinones									
117824					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:42 AM				
Quinones, Paul		Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral ES							
117857					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:03 AM				
Quinones, Paul		Monthly - Chaparral ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
117873					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:13 AM				
Quinones, Paul		Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
117834					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:48 AM				
Quinones, Paul		Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
110886					12/5/2013		181		\$0.00
Medium	Work In Progress				12/5/2013 9:29:57 AM				
Gonzalez, Salvador		DOUBLE DOORS IN BACK OF KITCHEN EXIT NEED A DOOR HEADER TO SUPPORT THE DOOR CLOSER.							
Paul Quinones									
117421					5/22/2014		13		\$0.00
Medium	Work In Progress				5/22/2014 8:46:00 AM				
Marquez, Gerardo		mullion to double doors cafeteria exit will not open with key please check.thanks							
Paul Quinones									
110568					11/22/2013		194		\$0.00
Medium	Work In Progress				11/22/2013 3:51:45 PM				
Ontiveros, Guadalupe		pressure tank will not stop draining water shut off back flow in front of che,and at the middle school and gate valves next to pressure tank							
Paul Quinones									
111236					12/12/2013		174		\$0.00
Medium	Work In Progress				12/12/2013 4:03:00 PM				
Marquez, Gerardo		warranty 1 of the 8 new doors installed oil leaking from door closer.							
Paul Quinones									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral ES

107095					9/4/2013		273		\$0.00
--------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/4/2013 4:03:38 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe
irragation water line next to the water tank water leak
water
line connecting pump and motor

Paul Quinones

117226					5/16/2014		19		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/16/2014 2:00:11 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
pressure tank irragation water line leaking underground
pvc
pipe is 6"back hoe will be needed.thanks

Paul Quinones

117640					5/29/2014		6		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/29/2014 3:08:42 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe
New Chaparral Elementary Site - please make a 50 X
50 pad.

Michael Munoz

115641					4/6/2014	4/27/2014	59		\$0.00
--------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2014 12:32:24 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Daniel
Monthly- Chapparal ES Range Hood Cleaning - Refer
to PM schedule details.

Margret Villalobos

117323					5/20/2014		15		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/20/2014 12:48:05 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Appelzoller, Fred
Need plumber familiar with site utilities available
tomorrow at Chaparral Elem at 10:30 to go over site
utilities

Michael Munoz

117885					6/2/2014		2		\$0.00
--------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				6/2/2014 10:09:39 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred
Domestic Water Service - Verify the direction of the
water line coming off the meter and going to the
building. record information and forward to Chris Licking
with FMS Engineers.

Alfredo Holguin

115682		Custodial			4/7/2014		58		\$0.00
--------	--	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				4/7/2014 1:56:16 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

,
fix,vaccum ,electric,cord,by,switch,not,working,and,handi
e.e000g00004090

Daniel Ramirez

6/4/2014 1:35:07 PM

Page 19 of 209

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral ES									
113279					2/11/2014		113		\$0.00
Medium	Work In Progress				2/11/2014 3:42:24 PM				
Holguin, Alfredo		playground surfacing upgrade total of 4 playgrounds pre -k playground no borders supporting sand measurements 20'x30' total of 3 5 to 12 playgrounds need to replace approx. 30 biege borders for 2 playgrounds							
Paul Quinones									
117585	Main Building	Office			5/28/2014		7		\$0.00
Medium	Work In Progress	office			5/28/2014 2:06:40 PM				
Briones, Enrique		Pick up Cume records and Nurse records for Tracey							
Jennifer Corral									
117888	Main Building	Office			6/2/2014		2		\$0.00
Medium	Work In Progress				6/2/2014 10:18:09 AM				
Briones, Enrique		Deliver 33 bxs. Math K-6th Eng/Span. Workbooks							
Theresa Ramirez									
113761	E.Building	Classroom			2/25/2014		99		\$0.00
Medium	Work In Progress	414			2/25/2014 12:59:26 PM				
Marquez, Gerardo		cabinet keys, file cabinet, storage cabinet need new keys. See Ms. Quinn							
Jennifer Corral									
Count: 25 Work Orders		Avg. Age of WO's 76			Total for Chaparral ES			0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral High - Pre-K									
114976		Exterior			3/24/2014		72		\$0.00
Medium	Work In Progress				3/24/2014 3:59:17 PM				
Ortiz, Alfredo		Need to replace gaskett on outside ZURN hose bibb.							
Alfredo Ortiz									
113131		Exterior			2/7/2014		117		\$0.00
Medium	Work In Progress				2/7/2014 2:44:26 PM				
Appelzoller, Fred		Need to replace broken bubblers on drinking fountain, on playground.							
Alfredo Ortiz									
117023					5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 3:09:36 PM				
Munoz, Michael		needs small block fence for sand barrier from wood chips.							
Michael Munoz									
117424					5/22/2014		13		\$0.00
Medium	Work In Progress				5/22/2014 9:09:18 AM				
Vargas, Juan		Please replace all a/c filters.							
Michael Munoz									
117423					5/22/2014		13		\$0.00
Medium	Work In Progress				5/22/2014 9:07:17 AM				
Solis, Lorenzø		Please ck unit in room 103.							
Elodia Salinas									
Count: 5 Work Orders			Avg. Age of WO's	48	Total for Chaparral High - Pre-K		0		\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
116645					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:42 AM				
Apodaca, Mario		Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
113941					2/28/2014		96		\$0.00
Medium	Work In Progress				2/28/2014 12:32:59 AM				
Munoz, Michael		Yearly - Chaparral HS - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
117844					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:54 AM				
Apodaca, Mario		Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
116146					4/23/2014		42		\$0.00
Medium	Work In Progress				4/23/2014 7:10:17 AM				
Estrada, Jesus		need gym floors re-finished dates 19th to 30th of may 2014.							
Jesus Urquidi									
112824					2/2/2014		122		\$0.00
Medium	Work In Progress				2/2/2014 12:26:31 AM				
Flores, Pete		Monthly - CHS-UV-0513 PM Service - Refer to PM schedule details.							
Margret Villalobos									
114931		Gym			3/21/2014		75		\$0.00
Medium	Work In Progress				3/21/2014 4:16:50 PM				
Munoz, Michael		PM - Annual Bleacher Service performed by A.K. Sales.							
Michael Munoz									
114645					3/14/2014		82		\$0.00
Medium	Work In Progress	Security			3/14/2014 9:30:49 AM				
Flores, Pete		pick up security gulf cart at CHS and deliver to ppd auto shop / cart not work possible needs new (6) batteries and new cable							
Irene Herrera									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

114145 3/3/2014 93 \$0.00

Medium Work In Progress 3/3/2014 8:40:17 AM

Gonzalez, Salvador BLDG. MECH. IS REQUESTING INSTALLATION OF METAL SECURITY DRS. ON ALL ATHLETICS STORAGE SHEDS AND TICKET OFFICE. ONE OF THE STORAGE SHEDS IS AN ODD SIZE AND NEEDS TO BE FABRICATED. WOULD YOU PLEASE CHECK IT OUT ASAP. PLEASE. THANKS.

Gerardo Marquez

110188 A-Wing Hallway/Corridor 11/13/2013 203 \$0.00

Medium Work In Progress 11/13/2013 11:12:20

Marquez, Gerardo The outside door to A wing by ISS class room is not working. When I put my key in it just turns and keeps turning all the way around. Please fix ASAP for security reasons. The rooms close to this door are ISS and CAP. (Lupe Quinones, security)

Mireya Meza

116443 A-Wing Classroom 4/30/2014 35 \$0.00

Medium Work In Progress A-wing 4/30/2014 5:23:20 PM

Marquez, Gerardo Need metal bar installed on the following doors for security reasons. A105, A106 (two doors) and A107. (SO Quinonez, security)

Mireya Meza

105363 A-Wing Office 8/5/2013 303 \$0.00

Medium Work In Progress 8/5/2013 8:11:06 AM

Marquez, Gerardo Please make 1 copy of keys #238 & #142 for the nurse's filing cabinet. These are the Fire king cabinets. (Ms. deCastro)

Mireya Meza

116460 A-Wing Classroom 5/1/2014 34 \$0.00

Medium Work In Progress 5/1/2014 9:43:11 AM

Marquez, Gerardo The following doors need the metal security bars to protect classroom from break in. A-101, A-102, A-103, A-104, A-108, A-110 & A-111. (SO Quinones, security)

Mireya Meza

115675 A-Wing Classroom 4/7/2014 58 \$0.00

Medium Work In Progress 4/7/2014 9:04:19 AM

Marquez, Gerardo Please add safety plates on doors that don't already have it. Plate can prevent future break ins. (Lupe Quinones, security)

Mireya Meza

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
113792	A-Wing	Roof			2/25/2014		99		\$0.00
Medium	Work In Progress				2/25/2014 3:37:04 PM				
Ortiz, Alfredo		Need to remove sand from roof-top.							
Alfredo Ortiz									
117692	A-Wing	Office			5/30/2014		5		\$0.00
Medium	Work In Progress	Mireya's Office			5/30/2014 3:32:19 PM				
Gonzales, Camilo		Please pick up 3 boxes and take to Lucia Almeraz in Finance. (Mireya Meza)							
Mireya Meza									
113966	A-Wing	Office			2/28/2014		96		\$0.00
Medium	Work In Progress				2/28/2014 3:18:18 PM				
Ortiz, Alfredo		Need to fix walls corners broken and repaint.							
Alfredo Ortiz									
116042	A-Wing	Foyer			4/17/2014		48		\$0.00
Medium	Work In Progress	Amphitheater			4/17/2014 9:15:56 AM				
Munoz, Michael		amphitheater repair/replace sidewalk along north western edge of amphitheater - walkway has separated from amphitheater and created a trip hazard. (Vicki Lopez)							
Mireya Meza									
116039	A-Wing	Foyer			4/17/2014		48		\$0.00
Medium	Work In Progress	Amphitheater			4/17/2014 8:44:07 AM				
Valdez, Pedro		Remove dead tree in amphitheater area in front of nurse/ISS. Pull weeds from beds in amphitheater. Cap water hoses that no longer have trees/shrubs to water out by security shack. (Ms. Lopez)							
Mireya Meza									
116774	B-Wing	Classroom			5/6/2014		29		\$0.00
Medium	Work In Progress	B3			5/6/2014 9:14:51 AM				
Ronquillo, Ruben		I need some one from the hazardous dept to pick up dead cats that are used in the anatomy & physiology class. The hazardous dept picked them up 2 years ago. They are starting to smell bad. (Ms. Del Hierro, B3)							
Mireya Meza									
115433	B-Wing	Classroom			4/4/2014		61		\$0.00
Medium	Work In Progress	B3			4/4/2014 9:03:39 AM				
Marquez, Gerardo		Store room cabinets need to be opened. Tried opening with key and the lock comes out. Need them open as soon as possible. (Ms. Del Hierro)							
Mireya Meza									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
116148	C-Wing	Restroom			4/23/2014		42		\$0.00
Medium	Work In Progress				4/23/2014 7:14:56 AM				
Ortiz, Alfredo		last faucet boys restroom real loose.							
Jesus Urquidi									
117425	D-Wing	Classroom			5/22/2014		13		\$0.00
Medium	Work In Progress	D7			5/22/2014 9:30:26 AM				
Appelzoller, Fred		Some faucets are loose in room D7. (Ms. Sanogo)							
Mireya Meza									
117426	D-Wing	Classroom			5/22/2014		13		\$0.00
Medium	Work In Progress	D7			5/22/2014 9:34:59 AM				
Appelzoller, Fred		Main sink at the back of the room gets clogged a lot. (Ms. Sanogo, D7)							
Mireya Meza									
117427	D-Wing	Classroom			5/22/2014		13		\$0.00
Medium	Work In Progress	D7			5/22/2014 9:36:05 AM				
Appelzoller, Fred		Faucets in the main sink (back of room) do not work. (Ms. Sanogo, D7)							
Mireya Meza									
117628	D-Wing	Classroom			5/29/2014		6		\$0.00
Medium	Work In Progress	D-spced room			5/29/2014 9:27:16 AM				
Marquez, Gerardo		Please re-key D-spced room to GR1. This will become an additional testing storage room. Also please add a metal plate cover if one is not on. (Ms. Ballard)							
Mireya Meza									
116442	E-Wing	Classroom			4/30/2014		35		\$0.00
Medium	Work In Progress	All of E-wing			4/30/2014 5:21:32 PM				
Marquez, Gerardo		Need the metal bar installed in the following rooms in E-wing. E6, E7 (two doors), E5, E4, E3, E2 and E1. (SO Quinonez, security)							
Mireya Meza									
117972	E-Wing	Classroom			6/4/2014		0		\$0.00
Medium	Work In Progress	E-5			6/4/2014 9:19:53 AM				
Vargas, Juan		Room # right outside of the door keeps coming off. Please fix. (Ms. Driskill, E5)							
Mireya Meza									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
117971	F-Wing	Classroom			6/4/2014		0		\$0.00
Medium	Work In Progress	F7			6/4/2014 9:18:22 AM				
Vargas, Juan		Drywall by corner of window chipped and drywall by corner by TV monitor chipped. Please repair. (Ms. Loya, F7)							
Mireya Meza									
114301	F-Wing	Classroom			3/5/2014		91		\$0.00
Medium	Work In Progress	F3			3/5/2014 4:08:42 PM				
Ortiz, Alfredo		5 broken chairs from ECHS top half/back of chair came off metal frame, found in storage room. (Ms. Locke, room F3)							
Mireya Meza									
117417	G-Wing	Classroom			5/22/2014		13		\$0.00
Medium	Work In Progress	G3			5/22/2014 8:08:58 AM				
Ortiz, Alfredo		Multiple broken chairs (backs and some of the seats). Ms. Pranses, G3							
Mireya Meza									
117978	G-Wing	Classroom			6/4/2014		0		\$0.00
Medium	Work In Progress	G2			6/4/2014 9:33:09 AM				
Vallejo, Albert		Need new wall cover for media inputs to smart board. (G2)							
Mireya Meza									
114317	G-Wing	Classroom			3/6/2014		90		\$0.00
Medium	Work In Progress	G3			3/6/2014 8:17:41 AM				
Marquez, Gerardo		The lock to my desk is broken. (Ms. Pranses, G3)							
Mireya Meza									
117980	G-Wing	Classroom			6/4/2014		0		\$0.00
Medium	Work In Progress	G2			6/4/2014 9:35:54 AM				
Vargas, Juan		2 desks need new screws for 1 leg of each desk (G2)							
Mireya Meza									
117433	G-Wing	Classroom			5/22/2014		13		\$0.00
Medium	Work In Progress	G6			5/22/2014 11:11:10 AM				
Solis, Lorenzo		I would like the thermostat raised one degree. There are two thermostat in the room. (Ms. Bowermaster, G6)							
Mireya Meza									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
111037	I-Wing	Kitchen			12/9/2013		177		\$0.00
Medium	Work In Progress				12/9/2013 11:16:02 AM				
Gonzalez, Salvador		Rack on oven broke need to weld together.							
Alfredo Ortiz									
117974	I-Wing	Classroom			6/4/2014		0		\$0.00
Medium	Work In Progress	Bandroom			6/4/2014 9:21:15 AM				
Urquidi, Jesus		The carpet is in need of shampoo cleaning. (Mr. Rios, bandroom)							
Mireya Meza									
109908	I-Wing	Classroom			11/5/2013		211		\$0.00
Medium	Work In Progress				11/5/2013 12:41:09 PM				
Marquez, Gerardo		Need to replace door in Band room broken.							
Alfredo Ortiz									
105851	Q-Wing	Classroom			8/12/2013		296		\$0.00
Medium	Work In Progress				8/12/2013 10:14:14 AM				
Marquez, Gerardo		The wrestling/tennis room share a door with Q2. This door is locked on my side but it can be opened from the neighboring room without a key. There is a large amount of valuable equipment in Q2 and I would feel better knowing that all access points were secure. Perhaps it would be possible to have the door lock both directions. (Mr. Woodard)							
Mireya Meza									
116479	Q-Wing	Classroom			5/1/2014		34		\$0.00
Medium	Work In Progress	Q2			5/1/2014 11:27:57 AM				
Vallejo, Albert		Could I please have a hole cut into the wall of my classroom. I would like to set up our laser cutter in Q2, but it must vent to the outdoors. I was thinking it would work best against the north wall towards the east corner. (Mr. Woodard, Q2)							
Mireya Meza									
114227	Q-Wing	Roof			3/4/2014		92		\$0.00
Medium	Work In Progress				3/4/2014 3:40:57 PM				
Ortiz, Alfredo		Need to replace filters on Industrial A/C units in Q-build.							
Alfredo Ortiz									
113215	Q-Wing	Roof			2/10/2014		114		\$0.00
Medium	Work In Progress				2/10/2014 1:51:09 PM				
Ortiz, Alfredo		Need to replace motor on A/C unit burn-out. Replace clean machine too. Industrial unit.							
Alfredo Ortiz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral HS							
113575	Q-Wing	Classroom			2/19/2014		105		\$0.00
Medium	Work In Progress				2/19/2014 3:56:36 PM				
Ortiz, Alfredo	Need to install a Line Duct Exhaust Fan in Q-4 for Laicer.								
Alfredo Ortiz									
117273	Q-Wing	Parking Lot			5/19/2014		16		\$0.00
Safety	Work In Progress	Bus area			5/19/2014 2:48:10 PM				
Gonzalez, Salvador	Please install some kind of gate at the end of the fence that will deny access to parents and student drivers. This fence will ensure the safety of our students in the bus due to the fact that unwanted vehicles are cutting off the buses as they are driving off. Two stop signs on each side, a district lock and reflectors. (Security Quinones)					5/20 -Route to Sal asp Mike			
Mireya Meza									
116040	Q-Wing	Storage			4/17/2014		48		\$0.00
Medium	Work In Progress	Locker Area in			4/17/2014 9:08:31 AM				
Vargas, Juan	JV - Remove all lockers from Q Bldg locker area. Paint walls and cover holes in walls left by lockers.					5/6/14 - Approved by E. Yturalde			
	GM-Install gates or doors to secure area. Area is to be used for wrestling area. (Vicki Lopez)					4/17/14 Good morning, Ms . Lopez, I met with Alfredo and he recommended that your site run this by CMT for approval. I will close the work order for now and if approved could you please re-generate.			
Mireya Meza						Thank you -Mike			
114716	R-Wing	Restroom			3/17/2014		79		\$0.00
Medium	Work In Progress				3/17/2014 3:29:39 PM				
Ortiz, Alfredo	Need to replace broken toilet.								
Alfredo Ortiz									
114717	R-Wing				3/17/2014		79		\$0.00
Medium	Work In Progress				3/17/2014 3:33:14 PM				
Ortiz, Alfredo	Need to replace light bulbs in R-1, C-1 and hall-way.								
Alfredo Ortiz									
108497	Field House	Exterior			10/7/2013		240		\$0.00
Medium	Work In Progress				10/7/2013 9:26:28 AM				
Marquez, Gerardo	Need to fix door knob and Locksets can't lock doors. At the ticket booth Field house.								
Alfredo Ortiz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
113314	Field House	Athletic Field			2/12/2014		112		\$0.00
Medium	Work In Progress				2/12/2014 10:45:25 AM				
Marquez, Gerardo		May need to change corse to trainer rooms to minimum access only to K3 keys. (Mireya Meza)							
Mireya Meza									
112702	Field House	Athletic Field			1/31/2014		124		\$0.00
Medium	Work In Progress	Softball field			1/31/2014 9:07:26 AM				
Sotelo, Enrique		Can I get an electric outlet out by my batting cage and an outlet by 3rd base dug out. (Donna Heddleston, softball field)							
Mireya Meza									
112029	Field House	Restroom			1/13/2014		142		\$0.00
Medium	Work In Progress				1/13/2014 3:42:07 PM				
Marquez, Gerardo		Old CH86 keys are not matching new cylinder in field house boys restroom area. Please check that all CH86 (athletics keys) match cylinder in field house area. (Mireya Meza)							
Mireya Meza									
117969	Field House	Classroom			6/4/2014		0		\$0.00
Medium	Work In Progress	Field House			6/4/2014 9:15:19 AM				
Urquidi, Jesus		I need the filing cabinet in the gym athletic training room moved to the fieldhouse athletic training room. I will empty it before it will be moved. (Trainer, Ms. Walsh)				Please have custodial move it, A. Ortiz is still out.			
Mireya Meza									
112063	Field House	Athletic Field			1/14/2014		141		\$0.00
Medium	Work In Progress	SOCCER FIELD			1/14/2014 10:21:30 AM				
Valdez, Pedro		GROUNDS - CHAPARRAL HS BACKSTOP - SOCCER FIELD ON LOBO LANE SIDE.							
Terry Alvarado									
116932	Field House	Athletic Field			5/9/2014		26		\$0.00
Medium	Work In Progress	Softball field			5/9/2014 10:29:33 AM				
Valdez, Pedro		Please move batting cage from behind right field to the 3rd base side next to the softball shed and please put an electrical outlet next to the batting cage when you move it. (Coach Heddleston)							
Mireya Meza									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
116933	Field House	Athletic Field			5/9/2014		26		\$0.00
Medium	Work In Progress	Softball			5/9/2014 10:30:48 AM				
Valdez, Pedro									
Please replace the pitchers plate on the pitching mound. (Coach Heddleston)									
Mireya Meza									
105660	H-Wing	Dressing Room			8/8/2013		300		\$0.00
Medium	Work In Progress				8/8/2013 9:52:01 AM				
Marquez, Gerardo									
Please put the metal door back on. The door that is suppose to be between the girls basketball locker room and showers. (Ms. Lydia Guerrero, girls dressing room)									
Mireya Meza									
111885	H-Wing	Restroom			1/10/2014		145		\$0.00
Medium	Work In Progress				1/10/2014 9:09:39 AM				
Appelzoller, Fred									
Need to replace several faucets in boys and girls restroom bent and sinks are loose.									
Alfredo Ortiz									
108049	H-Wing	Gym			9/27/2013		250		\$0.00
Medium	Work In Progress				9/27/2013 2:57:56 PM				
Marquez, Gerardo									
Need to install door louvers on two storage doors because mole is growing on everything. Girls locker rooms in Gym.									
Alfredo Ortiz									
117666	H-Wing	Gym			5/30/2014		5		\$0.00
Medium	Work In Progress	Gym doors			5/30/2014 11:29:23 AM				
Marquez, Gerardo									
Please re-key all of the gym doors back to CH86. (Sofia Payen)									
Mireya Meza									
117667	H-Wing	Gym			5/30/2014		5		\$0.00
Medium	Work In Progress				5/30/2014 11:30:46 AM				
Marquez, Gerardo									
Please destroy 1 key (CG16) for coach Yturralde. Key is broken and no longer works. (Coach Y)									
Mireya Meza									
113505	H-Wing	Gym			2/18/2014		106		\$0.00
Medium	Work In Progress				2/18/2014 3:44:27 PM				
Ortiz, Alfredo									
Need to service the Air handlers on the gym roof.									
Alfredo Ortiz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

114192	H-Wing	Roof			3/4/2014		92		\$0.00
Medium	Work In Progress				3/4/2014 7:46:11 AM				
Vallejo, Albert		Need to replace switch and contactors on the Gym air handler.							
Alfredo Ortiz									

113891	H-Wing	Gym			2/27/2014		97		\$0.00
Medium	Work In Progress				2/27/2014 3:43:40 PM				
Vallejo, Albert		Need to fix and replace the main. switche in one of the exauhst fans in the Gym.				3/6 Route to Albert asp Lorenzo			
Alfredo Ortiz									

117215					5/16/2014		19		\$0.00
Medium	Work In Progress				5/16/2014 8:20:47 AM				
Appelzoller, Fred		Company: ACADEMY FENCE Contact Name: JOE COCA Phone: (575)523-0779							
		SPOT: SOCCER FIELD LOCATION, AREA MARKED IN WHITE.							
		(Any ?'s check in w/Pedro Valdez)							
Alfredo Holguin									

114901		Football Field			3/21/2014		75		\$0.00
Medium	Work In Progress				3/21/2014 12:56:55 PM				
Appelzoller, Fred		Need to install water line and bubbler on drinking water fountain outside next to tennise courts							
Alfredo Ortiz									

115638					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:22 AM				
Orozco, Daniel		Monthly- Chaparral HS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									

117167					5/14/2014		21		\$0.00
Medium	Work In Progress				5/14/2014 3:56:02 PM				
Acuna, Johnny		Clean and service a/c's to Gym.							
Johnny Acuna									

116147		Gym			4/23/2014		42		\$0.00
Medium	Work In Progress				4/23/2014 7:13:30 AM				
Marquez, Gerardo		need gym doors re-keyed to re-finish gym floors date 5-19-14							
Jesus Urquidi									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
114326		Athletic Field			3/6/2014		90		\$0.00
Medium	Work In Progress				3/6/2014 12:18:54 PM				
Ontiveros, Guadalupe		Attention to Athletics Grounds request 1 pallet of sod for soccer field goal area.							
Alfredo Ortiz									
110544		Exterior			11/22/2013		194		\$0.00
Medium	Work In Progress				11/22/2013 10:19:33				
Marquez, Gerardo		Need to install Security doors on baseball and softball storage sheds							
Alfredo Ortiz									
113315		Gym			2/12/2014		112		\$0.00
Medium	Work In Progress				2/12/2014 10:50:23 AM				
Vallejo, Albert		please check controller to scoreboard and scoreboard for proper operation. thank you							
Michael Munoz									
115501					4/6/2014	4/14/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:30:42 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
115493					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:30:35 AM				
Ortiz, Alfredo		Monthly - Chaparral HS H11 (E.Heater)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
115190					3/31/2014		65		\$0.00
Medium	Work In Progress				3/31/2014 12:54:06 AM				
Ortiz, Alfredo		Monthly - Chaparral HS A16 (Fan Exhst.)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
114267					3/5/2014		91		\$0.00
Medium	Work In Progress				3/5/2014 9:33:15 AM				
Ortiz, Alfredo		Need to replace broken Bolt Cutter. Old one won't cut lock just bends. Agreas gun old one don't work.							
Alfredo Ortiz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									

Location: Chaparral HS									
113911					2/28/2014	3/31/2014	96		\$0.00
Medium	Work In Progress			2/28/2014 12:32:43 AM					
Ortiz, Alfredo	Yearly - Chaparral HS C11 (Evaporative)(Yearly) - Refer to PM schedule details.								
Margret Villalobos									
112607					1/29/2014		126		\$0.00
High	Work In Progress			1/29/2014 3:27:57 PM					
Ortiz, Alfredo	alfredo, please install reflectors to gates on east and west entrances to lobo lanes. to many accidents. thank you								
Michael Munoz									
116462					5/1/2014		34		\$0.00
Medium	Work In Progress	LINE LOCATE		5/1/2014 9:52:02 AM					
Vallejo, Albert	ACADEMY FENCE Name: DANNY TINGEN Phone: (575)523-0779 SPOT IN THE SOCCOR FIELD RIGHT BEHIND BOTH THE GOAL POSTS PLEASE GO TO THE SECURITY COUNTER AND ASK FOR PEDRO VALDEZ FOR FURTHER SPOTTING								
Alfredo Holguin									
117214					5/16/2014		19		\$0.00
Medium	Work In Progress			5/16/2014 8:19:10 AM					
Vallejo, Albert	Company: ACADEMY FENCE Contact Name: JOE COCA Phone: (575)523-0779 SPOT: SOCCER FIELD LOCATION, AREA MARKED IN WHITE. (Any ?'s check in w/Pedro Valdez)								
Alfredo Holguin									
117795					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:23 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
117796					6/1/2014		3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:23 AM					
Ortiz, Alfredo	Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Chaparral HS									
117794					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:22 AM				
Ortiz, Alfredo	Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
117872					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:12 AM				
Ortiz, Alfredo	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
117849					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:57 AM				
Ortiz, Alfredo	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
117735					6/1/2014	6/4/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:44 AM				
Ortiz, Alfredo	Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
115669					4/6/2014		59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:43 AM				
Ortiz, Alfredo	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
115634					4/6/2014		59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:20 AM				
Ortiz, Alfredo	Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
115585					4/6/2014	5/7/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:31:49 AM				
Ortiz, Alfredo	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral HS							
115586					4/6/2014		59		\$0.00
Medium	Work In Progress				4/6/2014 12:31:49 AM				
Ortiz, Alfredo		Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
115580					4/6/2014		59		\$0.00
Medium	Work In Progress				4/6/2014 12:31:45 AM				
Ortiz, Alfredo		Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
116558					5/4/2014	5/7/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:37:42 AM				
Ortiz, Alfredo		Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
116624					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:28 AM				
Ortiz, Alfredo		Monthly - Chaprral HS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
116606					5/4/2014	6/4/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:17 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
116607					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:17 AM				
Ortiz, Alfredo		Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
116696					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:39:17 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral HS									
116648					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:44 AM				
Ortiz, Alfredo		Monthly - Chaparral HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
117181					5/15/2014		20		\$0.00
Medium	Work In Progress				5/15/2014 11:02:04 AM				
Orozco, Daniel		Can you please put a work order for our dishwashing machine at Chaparral High School one of the volts came off and the maintenance guy (Juan Carlos) put a volt so the screw won't come off so our pans can run through the dishwasher without getting stuck. He told us that the volt was going to be coming off because it's not the correct one and we had to put a work order for that so that the machine could have the correct part placed. SNP Manager Juanita M. 824.4461							
Maritza Gonzalez									
117335					5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 3:34:08 PM				
Orozco, Daniel		ONE OVEN NOT WORKING. SNP MANAGER JUANITA M. 824.4461							
Maritza Gonzalez									
117924		Office			6/3/2014		1		\$0.00
Medium	Work In Progress				6/3/2014 1:04:26 PM				
Gonzales, Camilo		Deliver 2 bx. to Gema Salcedo from ECHS.							
Theresa Ramirez									
106602		Lift Station			8/27/2013		281		\$0.00
Medium	Work In Progress				8/27/2013 3:28:14 PM				
Gonzalez, Salvador		need to retro fit pump bracket at storm water lift pump station outside and theater. (welding job)							
Mario Apodaca									
110070		Exterior			11/8/2013		208		\$0.00
Medium	Work In Progress				11/8/2013 3:20:29 PM				
Gonzalez, Salvador		Need to install Fence gate spoppers at main entrances.							
Alfredo Ortiz									
114266	Pre-K	Restroom			3/5/2014		91		\$0.00
Medium	Work In Progress				3/5/2014 9:22:44 AM				
Ortiz, Alfredo		Need to install floor drain sealers to stop drain odors.							
Alfredo Ortiz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral HS

Count: 101 Work Orders Avg. Age of WO's 72 Total for Chaparral HS 0 \$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

114505 3/11/2014 85 \$0.00

Medium Work In Progress 3/11/2014 3:05:02 PM

Orozco, Daniel I need to put in a work order for the pipe under the salad sink. The pipe leaks a lot. Thank you. SNP Manager Sandra D. 824.4376

Maritza Gonzalez

116996 5/12/2014 23 \$0.00

Medium Work In Progress 5/12/2014 10:17:35 AM

Orozco, Daniel 1) Reach-in refrigerator has shutdown.
2) Freezer Insulation strip is hanging from ceiling.
SNP Manager Sandra D. 882.4376

Maritza Gonzalez

115642 4/6/2014 4/27/2014 59 \$0.00

Medium Work In Progress 4/6/2014 12:32:25 AM

Orozco, Daniel Monthly - Chapparal MS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

109831 11/4/2013 212 \$0.00

Medium Work In Progress 11/4/2013 9:53:19 AM

Orozco, Daniel CHEMICAL CART IS RUSTED. SNP MANAGER SANDRA D. 824.4376.

Maritza Gonzalez

117862 6/1/2014 6/7/2014 3 \$0.00

Medium Work In Progress 6/1/2014 12:55:06 AM

Vallejo, Albert Monthly - Chaparral MS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

117792 6/1/2014 7/2/2014 3 \$0.00

Medium Work In Progress 6/1/2014 12:54:21 AM

Vallejo, Albert Monthly - Chaparral MS Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

117793 6/1/2014 3 \$0.00

Medium Work In Progress 6/1/2014 12:54:21 AM

Vallejo, Albert Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Chaparral MS							
117791					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:20 AM				
Vallejo, Albert		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
117754					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:56 AM				
Vallejo, Albert		Yearly - Chaparral MS B2 (Boiler)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
117790					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:19 AM				
Vallejo, Albert		Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
117734					6/1/2014	6/4/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:43 AM				
Vallejo, Albert		Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
116350					4/29/2014		36		\$0.00
Medium	Work In Progress				4/29/2014 8:33:55 AM				
Vallejo, Albert		Order towing accessories.							
Albert Vallejo									
115692					4/7/2014		58		\$0.00
Medium	Work In Progress				4/7/2014 3:42:18 PM				
Vallejo, Albert		(4-07-14) 1 hr—(113024) Troubleshoot and repair plug for overhead projector (CHS); 6 hrs —Paint library (CMS); 1 hr—Enter work log.				4/7/14 - 7 HRS			
Albert Vallejo									
117931					6/3/2014		1		\$0.00
Medium	Work In Progress				6/3/2014 2:31:46 PM				
Vallejo, Albert		Please put new blade in poster machine							
Gidget Mora									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
117946					6/3/2014		1		\$0.00
Medium	Work In Progress				6/3/2014 3:36:43 PM				
Vallejo, Albert		Repair and/or replace locking switches in Locker rooms for toggles.							
Albert Vallejo									
117351					5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 4:02:14 PM				
Vallejo, Albert		Move stage from UTEP to CMS and back.							
Albert Vallejo									
117352					5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 4:04:29 PM				
Vallejo, Albert		Retrieve scissor lift, repair Gym sound baffle, and return lift.							
Albert Vallejo									
116613					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:21 AM				
Vallejo, Albert		Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
116622					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:27 AM				
Vallejo, Albert		Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
116623					5/4/2014	6/4/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:27 AM				
Vallejo, Albert		Monthly - Chaparral MS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
116566					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:37:48 AM				
Vallejo, Albert		Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
113788					2/25/2014		99		\$0.00
Medium	Work In Progress	courtyard			2/25/2014 3:26:24 PM				
Vallejo, Albert		Please supply water for courtyard garden							
Gidget Mora									

6/4/2014 1:35:08 PM

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Chaparral MS									
113693					2/24/2014		100		\$0.00
Medium	Work In Progress				2/24/2014 10:32:03 AM				
Vallejo, Albert		Need to repair hole in wall in boys athletic hallway.							
Albert Vallejo									
114377					3/7/2014		89		\$0.00
Medium	Work In Progress				3/7/2014 10:57:09 AM				
Vallejo, Albert		Please paint locker rooms before new lockers are installed.							
Albert Vallejo									
117894		Classroom			6/2/2014		2		\$0.00
Medium	Work In Progress	310			6/2/2014 11:40:34 AM				
Vallejo, Albert		Please remove Television from its location and place in the opposite corner by the other window. Teacher feels unsafe with where it is now							
Gidget Mora									
117085					5/13/2014		22		\$0.00
Medium	Work In Progress				5/13/2014 2:07:08 PM				
Holguin, Alfredo		Installation of new lockers.							
Albert Vallejo									
108618		Restroom			10/9/2013		238		\$0.00
Medium	Work In Progress				10/9/2013 11:17:29 AM				
Vallejo, Albert		senesecita areglar swich del #300 hallway restroom boys GRACIAS							
M. Carmen Perez									
116452		Athletic Field			5/1/2014		34		\$0.00
Medium	Work In Progress	soccer			5/1/2014 8:26:17 AM				
Vallejo, Albert		Please put up soccer nets and remove dummypoles							
Gidget Mora									
109889					11/5/2013		211		\$0.00
Medium	Work In Progress				11/5/2013 8:53:26 AM				
Marquez, Gerardo		Doors by Band room will not close.							
Albert Vallejo									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Chaparral MS									
113694					2/24/2014		100		\$0.00
Medium	Work In Progress			2/24/2014 10:33:49 AM					
Marquez, Gerardo	Door jamb is broken and needs to be welded. There is also a hole punched in the outer shell. Closer is also leaking oil.		route to Gerardo asp mike						
Albert Vallejo									
117626		Gym			5/29/2014		6		\$0.00
Medium	Work In Progress			5/29/2014 8:14:40 AM					
Appelzoller, Fred	senesecita areglar horinal banos delos locker delos boys esta tapado es el primero y los resumideros delos locker estan tapados GRACIAS								
M. Carmen Perez									
117981	Main Building	Classroom			6/4/2014		0		\$0.00
Medium	Work In Progress	201		6/4/2014 9:36:51 AM					
Marquez, Gerardo	Replace/Repair locks on closet								
Gidget Mora									
108954	Main Building	Restroom			10/16/2013		231		\$0.00
Medium	Work In Progress			10/16/2013 2:09:57 PM					
Appelzoller, Fred	Please replace 5 multiple sensor sinks. Not working, also install new basins.		asp Mike - Assign to Fred, but please add on to description to install new basins.						
Gidget Mora									
104768	Main Building	Office			7/26/2013		313		\$0.00
Medium	Work In Progress	Merry		7/26/2013 8:31:49 AM					
Marquez, Gerardo	Needs keys for desk								
Gidget Mora									
108717	Main Building	Hallway/Corridor			10/11/2013		236		\$0.00
Medium	Work In Progress	400 hall		10/11/2013 9:16:30 AM					
Vallejo, Albert	Please paint wall in 400 hallway								
Gidget Mora									
111055	Main Building	Computer Lab			12/9/2013		177		\$0.00
Medium	Work In Progress	311		12/9/2013 2:38:18 PM					
Vallejo, Albert	Please turn off heat-too warm								
Gidget Mora									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Chaparral MS

116710	Main Building	Classroom			5/5/2014		30		\$0.00
--------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	406			5/5/2014 10:58:22 AM				
--------	------------------	-----	--	--	----------------------	--	--	--	--

Vallejo, Albert
Knob to turn on air conditioning is broken. Can not be turned on and it is very warm

Gidget Mora

117979	Main Building	Classroom			6/4/2014		0		\$0.00
--------	---------------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	201			6/4/2014 9:34:36 AM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Vallejo, Albert
Ceiling tiles are moldy-need to be replaced. Possible water leak

Gidget Mora

106128	Main Building	Computer Lab			8/16/2013		292		\$0.00
--------	---------------	--------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/16/2013 8:31:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzø
Install refrigeration units for computer labs. Rooms 406 and 207.

Albert Vallejo

113695					2/24/2014		100		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/24/2014 10:36:05 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Gonzalez, Salvador
Need retainers for drive gates at bus turn around.

Albert Vallejo

113696					2/24/2014		100		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/24/2014 10:37:14 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Gonzalez, Salvador
Need retaining clips at entrance to back hall.

Albert Vallejo

114089					3/2/2014		94		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/2/2014 12:26:43 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Flores, Pete
Monthly - CHM-UV-0514 PM Service - Refer to PM schedule details.

Margret Villalobos

114953		Gym			3/24/2014		72		\$0.00
--------	--	-----	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/24/2014 1:56:12 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Munoz, Michael
PM - Annual Bleacher Service performed by A.K. Sales.

Michael Munoz

113944					2/28/2014		96		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				2/28/2014 12:33:00 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Munoz, Michael
Yearly - Chaparral MS - Fire Pump Inspection - Refer to PM schedule details.

Margret Villalobos

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Chaparral MS							
116257		Gym			4/25/2014		40		\$0.00
Medium	Work In Progress			4/25/2014 10:10:59 AM					
Estrada, Jesus	need gym floor replaced, holes for volleyball poles and also senesecita aser re-finishing to the gym thank you								
	week of July 7								
M. Carmen Perez									
114444					3/10/2014		86		\$0.00
Medium	Work In Progress			3/10/2014 1:49:30 PM					
Solis, Lorenzø	The following A/C's are in need of replacement: AERO-CHM-004 (room 204); MCD-CHM-021 (room 309); MCD-CHM-025 (room 306); MCD-CHM-030 (room 205); MCD-CHM-048 (room 107); MCD-CHM-052 (room 104).								
Albert Vallejo									
107339					9/11/2013		266		\$0.00
Medium	Work In Progress			9/11/2013 9:25:04 AM					
Solis, Lorenzø	Install refrigeration unit for comp lab in 406.								
Albert Vallejo									
116312					4/28/2014		37		\$0.00
Medium	Work In Progress			4/28/2014 12:54:45 PM					
Solis, Lorenzø	Need to replace blower assembly on unit for Room 208. Model # TCP060F100AB / Serial # 318345J2H.								
Albert Vallejo									
114378					3/7/2014		89		\$0.00
Medium	Work In Progress			3/7/2014 10:58:49 AM					
Valles, Johnny	Repair soffit lighting.								
Albert Vallejo									
Count: 49 Work Orders		Avg. Age of WO's 78		Total for Chaparral MS			0	\$0.00	

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Charter School							
117895					6/2/2014		2		\$0.00
Medium	Work In Progress				6/2/2014 1:12:15 PM				
Munoz, Michael	purchase new 10x20 tuff shed for new gator.(athletics)								
Alfredo Holguin									
Count: 1 Work Orders		Avg. Age of WO's 2			Total for Charter School			0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Pride									
117076		Office			5/13/2014		22		\$0.00
Medium	Work In Progress	SECURITY			5/13/2014 11:30:41 AM				
Lara, Ralph		REPLACE X MASTER KEY FOR LT. ORLANDO GARCIA AS SOON AS POSSIBLE FOR SECURITY PURPOSES.							
Yvette Cortez									
115104		Portables			3/27/2014		69		\$0.00
Medium	Work In Progress	room 7			3/27/2014 10:51:51 AM				
Lara, Ralph		door handle to restroom door pull off accidentally.							
David Acosta									
108955					10/16/2013		231		\$0.00
Medium	Work In Progress				10/16/2013 2:17:32 PM				
Gonzalez, Salvador		Need poles to divide the drop off and pick up parking area for safety of the children. Parents are double parking and kids are running in between the cars and could get hurt. Thank you, Ruben							
Ruben Ortiz									
117118					5/14/2014		21		\$0.00
Medium	Work In Progress				5/14/2014 12:34:55 AM				
Sanchez, Raul		Monthly - Desert Pride - Water Filters - Refer to PM schedule details.							
Margret Villalobos									
115526					4/6/2014		59		\$0.00
Medium	Work In Progress				4/6/2014 12:31:05 AM				
Ronquillo, Ruben		Monthly - Desert Pride - (Qtrly) Fitness Equipment - Refer to PM schedule details.							
Margret Villalobos									
116950					5/9/2014		26		\$0.00
Medium	Work In Progress				5/9/2014 1:46:25 PM				
Lara, Ralph		2nd Barrack Room 9 - Need to replace panic bar.							
Michael Munoz									
117575					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 11:52:06 AM				
Lara, Ralph		NEED TO HAVE ELECTRICAL POWER BOX UNLOCKED FOR GENCON (DICK SPARKS) AS PER MR. GALLEGOS.							
Rafael Gallegos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Pride									
111725		Custodial			1/7/2014		148		\$0.00
Medium	Work In Progress				1/7/2014 11:14:05 AM				
Lara, Ralph		Need to replace master key. Having problems opening doors.							
David Acosta									
117838					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:51 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
116639					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:38 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
115849					4/14/2014		51		\$0.00
Medium	Work In Progress				4/14/2014 12:31:40 AM				
Sanchez, Raul		Monthly - Desert Pride - Water Filters - Refer to PM schedule details.							
Margret Villalobos									
116397					4/30/2014		35		\$0.00
Medium	Work In Progress				4/30/2014 1:01:44 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details.							
Margret Villalobos									
117606					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 4:01:26 PM				
Sotelo, Enrique		please disconnect power to portables to be moved. thank you							
Michael Munoz									
112495		Pump House			1/27/2014		128		\$0.00
Medium	Work In Progress				1/27/2014 3:16:13 PM				
Villalobos, David		need your assistance on installing a new water meter and upgrading a water filter hous for the domestic water							
Mario Apodaca									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Pride							
117024					5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 3:14:56 PM				
Villalobos, David		install new counter with sink for science lab to be for early college to include hot water. see mike foe details							
Michael Munoz									
117469					5/23/2014		12		\$0.00
Medium	Work In Progress				5/23/2014 12:19:57 PM				
Marquez, Gerardo		at the new desert pride @ Berino, need to install locks on temp. storage building that will be delivered on Wednesday, may 28. see mike for details							
Michael Munoz									
117639					5/29/2014		6		\$0.00
Medium	Work In Progress				5/29/2014 3:06:58 PM				
Marquez, Gerardo		New DP install locks on the storage containers.							
Michael Munoz									
113325		Parking Lot			2/12/2014		112		\$0.00
Medium	Work In Progress	front entrance			2/12/2014 2:00:14 PM				
Ontiveros, Guadalupe		need to add crusher fine and smooth out uneven front entrance ground.							
David Acosta									
117565		Office			5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 9:07:22 AM				
Ambriz, Jose		a/c unit not cooling.							
David Acosta									
117619		Office			5/29/2014		6		\$0.00
Medium	Work In Progress	sever room			5/29/2014 7:33:41 AM				
Ambriz, Jose		a/c unit is turn off and won't turn on.							
David Acosta									
117535					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 1:48:13 PM				
Carrasco, Danny		Move furniture from DP to the new DP storage units. (Tentative starting this Thursday - ck w/Mike) Pat, David A., Jimmy C. and Ruben will assist.							
Michael Munoz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Pride									
117605					5/28/2014		7		\$0.00
Low	Work In Progress				5/28/2014 3:58:36 PM				
Villalobos, David		shut off water to portables to be moved. thank you							
Michael Munoz									
117867					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:09 AM				
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
117804					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:28 AM				
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
117805					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:29 AM				
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
116617					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:24 AM				
Acosta, David		Monthly - Desert Pride Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
116618					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:24 AM				
Acosta, David		Monthly - Desert Pride Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
116665					5/4/2014	5/10/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:55 AM				
Acosta, David		Monthly - Desert Pride Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
Count: 28 Work Orders			Avg. Age of WO's	40		Total for Desert Pride	0		\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail Intermediate									
113259					2/11/2014		113		\$0.00
Medium	Work In Progress				2/11/2014 12:48:08 PM				
Orozco, Daniel		DRYER OUT. SNP MANAGER 824.3822							
Maritza Gonzalez									
113470					2/18/2014		106		\$0.00
Medium	Work In Progress				2/18/2014 10:12:09 AM				
Orozco, Daniel		GOOD MORNING: I'M HAVING PROBLEMS WITH THE ELECTRICAL FOR THE MILK COOLER. PLEASE REPLACE BOX (BROKEN), CHECK ELECTRICAL WIRING AND BREAKER CAUSE BREAKER SOMETIMES DOES NOT RESET. SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
115096					3/26/2014		70		\$0.00
Medium	Work In Progress				3/26/2014 4:28:15 PM				
Orozco, Daniel		ICE MACHINE NOT MAKING ICE. SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
115643					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:26 AM				
Orozco, Daniel		Monthly- Desert Trail Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
116928					5/9/2014		26		\$0.00
Medium	Work In Progress				5/9/2014 9:13:20 AM				
Orozco, Daniel		WASHER MACHINGE, WHEN IT FINISHES THROWING WATER/RINSE, WATER COME OUT FROM DRAIN . SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
117630					5/29/2014		6		\$0.00
Medium	Work In Progress	front office			5/29/2014 10:59:51 AM				
Gonzales, Camilo		Mrs. Chavira needs 2 boxes of cumulative folders piked up.							
Elizabeth Hernandez									
117436					5/22/2014		13		\$0.00
Medium	Work In Progress	front office			5/22/2014 11:39:29 AM				
Gonzales, Camilo		Mrs. Gilpin needs 5 boxes of Sped files picked from her office.							
Elizabeth Hernandez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail Intermediate							
113477					2/18/2014		106		\$0.00
Medium	Work In Progress				2/18/2014 11:30:08 AM				
Vallejo, Albert		Need assistance in new installation of a Securitylight outside of wall to portable #413. Need electrical wiring, elect. box, etc.							
Johnny Acuna									
113826					2/26/2014		98		\$0.00
Medium	Work In Progress				2/26/2014 11:10:19 AM				
Holguin, Alfredo		Need more sand to kinder playground area, Need more sand to swing sets area, W.o. #113599: Need new soccer nets for Playground soccer goals, W.o. #111044: Need top soil to fill in low areas to playground grass area, Need 12 swing hangers with 12 S-Hooks for playground swings, Need approx. 22 borders for playground sand to the bigger playground area sets, Need to fix ground border area around swing sets.							
Johnny Acuna									
115827					4/13/2014	4/29/2014	52		\$0.00
Medium	Work In Progress				4/13/2014 12:24:13 AM				
Acuna, Johnny		Monthly - Desert Trail Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
115715					4/8/2014		57		\$0.00
Medium	Work In Progress				4/8/2014 10:38:46 AM				
Acuna, Johnny		Need to replace faucet to sink in the teacher's lounge.							
Johnny Acuna									
115625					4/6/2014	4/12/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:14 AM				
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
116159					4/23/2014		42		\$0.00
Medium	Work In Progress				4/23/2014 11:12:18 AM				
Acuna, Johnny		Need to set up for district art show at ST. Middle School: 4-24-14, Tear Down: 4-28-14							
Johnny Acuna									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Desert Trail Intermediate							
116980					5/11/2014	5/27/2014	24		\$0.00
Medium	Work In Progress			5/11/2014 12:24:47 AM					
Acuna, Johnny	Monthly - Desert Trail Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
113599					2/20/2014		104		\$0.00
Medium	Work In Progress			2/20/2014 1:10:13 PM					
Ontiveros, Guadalupe	Need 2 sets of soccer goal nets for soccer goals in the playground grass area. Info and measurements have been mailed through Districtmail. Thank You.....								
Johnny Acuna									
111044					12/9/2013		177		\$0.00
Medium	Work In Progress			12/9/2013 12:40:09 PM					
Ontiveros, Guadalupe	Need to add top soil and level out playground grass area.								
Johnny Acuna									
116654					5/4/2014	5/10/2014	31		\$0.00
Medium	Work In Progress			5/4/2014 12:38:48 AM					
Acuna, Johnny	Monthly - Desert Trail Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
116585					5/4/2014		31		\$0.00
Medium	Work In Progress			5/4/2014 12:38:02 AM					
Acuna, Johnny	Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
116584					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress			5/4/2014 12:38:01 AM					
Acuna, Johnny	Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
116583					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress			5/4/2014 12:38:00 AM					
Acuna, Johnny	Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail Intermediate									
117474					5/23/2014		12		\$0.00
Medium	Work In Progress				5/23/2014 3:11:13 PM				
Acuna, Johnny		Need to remove playground step in the bigger playground equipment. (Safety Issue)							
Johnny Acuna									
117516					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 11:15:14 AM				
Acuna, Johnny		Need to remove 17 chalkboards to prep for installation of smartboards.							
Johnny Acuna									
117768					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:05 AM				
Acuna, Johnny		Monthly - Desert Trail Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
117766					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:04 AM				
Acuna, Johnny		Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
117767					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:04 AM				
Acuna, Johnny		Monthly - Desert Trail Emer. Light Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
117765					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:03 AM				
Acuna, Johnny		Yearly - Desert Trail ES B2 (Boiler)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
117871					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:11 AM				
Acuna, Johnny		Monthly - Desert Trail Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert Trail Intermediate							
115197					3/31/2014		65		\$0.00
Medium	Work In Progress				3/31/2014 12:54:12 AM				
Acuna, Johnny		Monthly - Desert Trail ES A16(Exhst Fan)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
115506					4/6/2014	4/14/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:30:46 AM				
Acuna, Johnny		Monthly - Desert Trail Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
115489					4/6/2014	4/22/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:30:33 AM				
Acuna, Johnny		Monthly - Desert Trail ES A1 (Air Dryer)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
114315					3/6/2014		90		\$0.00
Medium	Work In Progress				3/6/2014 8:10:25 AM				
Acuna, Johnny		(Need a 24 gauge sheetmetal transition duct fitting) Base: 22" square all around with a 2" Height overlapping X 20 3/4" square with a 2" Lip all around.							
Johnny Acuna									
114027					3/2/2014		94		\$0.00
Medium	Work In Progress				3/2/2014 12:26:13 AM				
Acuna, Johnny		Yearly - Desert Trail ES A10 (Heat Pump)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
113917					2/28/2014	3/31/2014	96		\$0.00
Medium	Work In Progress				2/28/2014 12:32:46 AM				
Acuna, Johnny		Yearly - Desert Trail ES C-11 (Evap.Cool)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
114265					3/5/2014		91		\$0.00
Medium	Work In Progress				3/5/2014 9:09:45 AM				
Acuna, Johnny		Need 2 large rolls of vinyl window screen to repair torn or worn out screening to main building. Also, need 4 fix a flat cans for steiner tractor tires.							
Johnny Acuna									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To	Description		Action Taken						
Requester Name									
Location:		Desert Trail Intermediate							
113961					2/28/2014		96		\$0.00
Medium	Work In Progress	front office			2/28/2014 2:13:45 PM				
Marquez, Gerardo		Our secretary Elizabeth needs key made for display cabinet							
Elizabeth Hernandez									
116947					5/9/2014		26		\$0.00
Medium	Work In Progress				5/9/2014 1:41:47 PM				
Marquez, Gerardo		Need to check door knob to portable #413. Knob only opens upward.							
Johnny Acuna									
116948					5/9/2014		26		\$0.00
Medium	Work In Progress				5/9/2014 1:43:31 PM				
Marquez, Gerardo		please check lock to Exit parking lot main gate. Having trouble locking.							
Johnny Acuna									
117318		Custodial			5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 11:34:22 AM				
Appelzoller, Fred		buenos dias fred por favor puede revisar el horinal de tercer grado esta ladiado gracias							
Laura Sandoval									
117579					5/28/2014		7		\$0.00
Medium	Work In Progress	107			5/28/2014 12:37:45 PM				
Briones, Enrique		Mr. Salas in room 107 needs 10 boes of DRA's picked up for shredding.							
Elizabeth Hernandez									
117580					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 12:39:46 PM				
Briones, Enrique		Mr. Salas in room #107 needs 7 boxes of Old Math sample books that were supposed to be picked up last year. Needs them picked up to be able arrange new books and these ones are taking up alot of space.							
Elizabeth Hernandez									
117581					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 12:43:03 PM				
Briones, Enrique		Mrs. Gilpin needs 5 boxes of Sped files picked from her office. That we need to let Mr. Rapanut know also.							
Elizabeth Hernandez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert Trail Intermediate									
117213					5/16/2014		19		\$0.00
Medium	Work In Progress				5/16/2014 7:59:19 AM				
Appelzoller, Fred		Need to unclogg custodial mop sinks							
Johnny Acuna									
112970					2/4/2014		120		\$0.00
Medium	Work In Progress				2/4/2014 3:33:48 PM				
Lara, Ralph		main door in the front lobby, both main doors going out to the portables W/Door closures (middle hallway), Portable #409 main door W/Door closure, Portable #410 W/Door closure Need Doors to be Replaced.							
Johnny Acuna									
105036					8/1/2013		307		\$0.00
Medium	Work In Progress				8/1/2013 9:27:19 AM				
Gonzalez, Salvador		Please install diamond metal plate to new portable ramps and decks.							
Johnny Acuna									
115660					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:37 AM				
Munoz, Michael		Monthly - Desert Trail Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
117131					5/14/2014		21		\$0.00
Medium	Work In Progress	supply room			5/14/2014 11:45:09 AM				
Munoz, Michael		The emergendydisplaymonitor in front office is diplaying that there is a waterflow in mechanical room. Needs to be checked.							
Elizabeth Hernandez									
117887	Main Building	Office			6/2/2014		2		\$0.00
Medium	Work In Progress				6/2/2014 10:15:06 AM				
Briones, Enrique		Deliver a total of 38 bxs. (33) Math K-6th Eng/Span Workbooks , (5) Science Materials ,							
Theresa Ramirez									
Count: 47 Work Orders			Avg. Age of WO's	54	Total for Desert Trail Intermediate		0		\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

117891	Main Building	Office			6/2/2014		2		\$0.00
--------	---------------	--------	--	--	----------	--	---	--	--------

Medium	Work In Progress				6/2/2014 10:34:13 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Briones, Enrique
Deliver total of 25 bxs; (24) Math K-6th Eng/Span
Workbooks, (1) Science Material.

Theresa Ramirez

117437	Main Building	Custodial			5/22/2014		13		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/22/2014 12:19:24 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Joe
Hi Joe the mop sink in the custodial closet in the lower
grade level is clogged can you unclog it please. Thank
you

Israel Ortega

117672	Main Building	Portables			5/30/2014		5		\$0.00
--------	---------------	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/30/2014 1:00:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
Hi Rafa in portable 1 the teacher had told me that she
having trouble with her door. If you could help us out
and fix it. Thank you

Israel Ortega

116847	Main Building	Restroom			5/7/2014		28		\$0.00
--------	---------------	----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/7/2014 1:32:35 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Joe
Hi Joe, two sinks in the boys restroom upper grade level
are clogged. Can you unclogg them please. Thank you.

Israel Ortega

114375	Main Building	Restroom			3/7/2014		89		\$0.00
--------	---------------	----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				3/7/2014 9:59:06 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ortiz, Ruben
We have a sink in the lower grade boys restroom that is
clogged if you can unclogg it i have already tried the
plunger but the water won't go down and there all that
black mildew that accumulates on the pipes coming
out. If you can unclog it please.

Israel Ortega

117673		Portables			5/30/2014		5		\$0.00
--------	--	-----------	--	--	-----------	--	---	--	--------

Medium	Work In Progress				5/30/2014 1:03:58 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Lara, Ralph
Hi Rafa also in portable 2 we are having trouble locking
the door if you could help us out and fix it. Thank you

Israel Ortega

116522					5/2/2014		33		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/2/2014 9:32:38 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Lara, Ralph
The cylinder in room 15A is missing; need to have it
replaced.

Ruben Ortiz

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
116523					5/2/2014		33		\$0.00
Medium	Work In Progress				5/2/2014 9:34:06 AM				
Lara, Ralph		The door handle is not closing right to the boiler room; need it fixed.							
Ruben Ortiz									
117385					5/21/2014		14		\$0.00
Medium	Work In Progress	Front of School			5/21/2014 3:26:09 PM				
Ortiz, Ruben		Trim the dry leaves on the Palm Trees in front of the school. (Araujo)							
Guadalupe Gonzalez									
117832					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:47 AM				
Ortiz, Ruben		Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
117854					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:01 AM				
Ortiz, Ruben		Monthly - Desert View ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
117821					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:40 AM				
Ortiz, Ruben		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
117822					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:40 AM				
Ortiz, Ruben		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
117743					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:49 AM				
Ortiz, Ruben		Yearly - Desert View ES B-2 Boiler Yearly - Refer to PM schedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
116092					4/22/2014		43		\$0.00
Medium	Work In Progress				4/22/2014 10:34:40 AM				
Ortiz, Ruben		Need to set up banner in the front circle for carnival on May 16, 2014							
Ruben Ortiz									
116748					5/5/2014		30		\$0.00
Medium	Work In Progress	Outside by the			5/5/2014 3:51:30 PM				
Ortiz, Ruben		The sprinkler by the Basketball Courts isn't working properly. (Gonzalez)							
Guadalupe Gonzalez									
115522					4/6/2014	4/14/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:31:00 AM				
Ortiz, Ruben		Monthly - Desert View ES Roof Inpsection - Refer to PM schedule details.							
Margret Villalobos									
116048					4/17/2014		48		\$0.00
Medium	Work In Progress				4/17/2014 2:12:15 PM				
Ortiz, Ruben		Maintenance summer project; Principal Araujo would like all the hallways and bathrooms painted.							
Ruben Ortiz									
116049					4/17/2014		48		\$0.00
Medium	Work In Progress				4/17/2014 2:13:05 PM				
Ortiz, Ruben		04/17/14 Maintenance summer project; Principal Araujo would like the portable window guards.							
Ruben Ortiz									
116050					4/17/2014		48		\$0.00
Medium	Work In Progress				4/17/2014 2:14:01 PM				
Ortiz, Ruben		Maintenance summer project; Principal Araujo would like the portable ramps and hand rails							
Ruben Ortiz									
116051					4/17/2014		48		\$0.00
Medium	Work In Progress				4/17/2014 2:14:56 PM				
Ortiz, Ruben		Maintenance; Need a waist tool pouch and blue channel locks							
Ruben Ortiz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
116052					4/17/2014		48		\$0.00
Medium	Work In Progress				4/17/2014 2:15:50 PM				
Ortiz, Ruben		Maintenance;							
		Need an 8 foot open ladder and a 12 foot open ladder							
Ruben Ortiz									
115949					4/15/2014		50		\$0.00
Medium	Work In Progress	Basketball			4/15/2014 3:19:08 PM				
Ortiz, Ruben		Repaint lines on the Basketball Courts. (Coach Reade)							
Guadalupe Gonzalez									
116986					5/11/2014	5/27/2014	24		\$0.00
Medium	Work In Progress				5/11/2014 12:24:51 AM				
Ortiz, Ruben		Monthly - Desert View ES Playground Insp - Refer to							
		PMs schedule details.							
Margret Villalobos									
116599					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:12 AM				
Ortiz, Ruben		Monthly - Desert View ES Exit Sign Insp: Monthly -							
		Refer to PMs schedule details.							
Margret Villalobos									
116600					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:12 AM				
Ortiz, Ruben		Monthly - Desert View ES Emer. Light Test: Monthly -							
		Refer to PMs schedule details.							
Margret Villalobos									
116598					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:11 AM				
Ortiz, Ruben		Monthly - Desert View ES - Clothes Dryer (Monthly) -							
		Refer to PMs schedule details.							
Margret Villalobos									
116317		Gym			4/28/2014		37		\$0.00
Medium	Work In Progress	Gym			4/28/2014 2:39:18 PM				
Ortiz, Ruben		Set up all the chairs available in the Gym on May 19th							
		for the Promotional Ceremony. (Gonzalez)							
Guadalupe Gonzalez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
117461		Classroom			5/23/2014		12		\$0.00
Medium	Work In Progress	Rm. #23			5/23/2014 9:43:01 AM				
Ortiz, Ruben		I would like to have the overhead screen removed. (L. Ortiz)							
Guadalupe Gonzalez									
117462		Classroom			5/23/2014		12		\$0.00
Medium	Work In Progress	Rm. #22			5/23/2014 9:44:05 AM				
Ortiz, Ruben		Remove map & screen from board, I no longer need it. (R. Chavira)							
Guadalupe Gonzalez									
114993		Office			3/25/2014		71		\$0.00
Medium	Work In Progress	Asst. Principal			3/25/2014 10:01:32 AM				
Ortiz, Ruben		Install a cork board in the office. (Campos)							
Guadalupe Gonzalez									
117500		Computer Lab			5/27/2014		8		\$0.00
Medium	Work In Progress	Rm. #30			5/27/2014 8:41:51 AM				
Ortiz, Ruben		Remove the old TV and the wall mount from my classroom. Thank you. (C. Bryant)							
Guadalupe Gonzalez									
113907		Computer Lab			2/27/2014		97		\$0.00
Medium	Work In Progress	Rm 76			2/27/2014 9:51:49 PM				
Ortiz, Ruben		Install Infocus projector on ceiling.							
Albert Ortiz									
117149		Classroom			5/14/2014		21		\$0.00
Medium	Work In Progress	Rm. 25			5/14/2014 3:23:41 PM				
Ortiz, Ruben		Install shelves on the wall and remove the wood bulletin board. (Perez)							
Guadalupe Gonzalez									
106257		Classroom			8/20/2013		288		\$0.00
Medium	Work In Progress	Rm. #16			8/20/2013 7:44:28 AM				
Ortiz, Ruben		There are ants in the classroom. If can put caulking around the window. (M. Mack)							
Guadalupe Gonzalez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Desert View ES

114528 3/11/2014 85 \$0.00

Medium Work In Progress 3/11/2014 4:03:46 PM

Ortiz, Ruben
 Items needed for Carnival
 100 feet heavy duty extension cord
 50 feet heavy duty extension cord
 25 feet heavy duty extension cord

Ruben Ortiz

114531 3/11/2014 85 \$0.00

Medium Work In Progress 3/11/2014 4:05:13 PM

Ortiz, Ruben
 Items needed for Carnival
 100 feet heavy duty water holes
 2 of 50 feet heavy duty water holes
 1 heavy duty rake

Ruben Ortiz

114328 3/6/2014 90 \$0.00

Medium Work In Progress 3/6/2014 1:32:46 PM

Ortiz, Ruben
 Need to weed and feed the grass in the front circle and on the side of the school

Ruben Ortiz

114330 3/6/2014 90 \$0.00

Medium Work In Progress 3/6/2014 1:58:56 PM

Ortiz, Ruben
 Need to change light bulbs in classrooms.

Ruben Ortiz

113928 2/28/2014 3/31/2014 96 \$0.00

Medium Work In Progress 2/28/2014 12:32:52 AM

Ortiz, Ruben
 Yearly - Desert View ES C-11 Evap Coolers Yearly - Refer to PM schedule details.

Margret Villalobos

113308 2/12/2014 112 \$0.00

Medium Work In Progress 2/12/2014 9:04:05 AM

Ortiz, Ruben
 Need to patch up or retile the front entrance of the school; due to safety hazard.

Ruben Ortiz

112602 1/29/2014 126 \$0.00

Medium Work In Progress 1/29/2014 2:55:08 PM

Ortiz, Ruben
 AS PER HEALTH ENVIRONMENT INSPECTION DAMAGED WALLS NEED TO BE ADDRESSED IN DISHWASHING ROOM.

Maritza Gonzalez

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Desert View ES									
108895					10/15/2013		232		\$0.00
Medium	Work In Progress	Lower Grade			10/15/2013 12:54:01				
Ortiz, Ruben		Repair the swings; some are broken and/or tangled.							
Guadalupe Gonzalez									
115943		Custodial			4/15/2014		50		\$0.00
Medium	Work In Progress				4/15/2014 2:59:37 PM				
Carbajal, Jimmy		Hi Jimmy we have a whirlomatic advance burnisher serial #1188829 that needs to be repaired. According to the afternoon custodians it started to smell burned and it just stopped working. It is also missing the two wheels in the back. Thank you							
Israel Ortega									
117923					6/3/2014		1		\$0.00
Medium	Work In Progress				6/3/2014 12:40:50 PM				
Ontiveros, Joe		irrigation pump is leaking . please repair.							
Ruben Ortiz									
117926					6/3/2014		1		\$0.00
Medium	Work In Progress				6/3/2014 1:33:16 PM				
Ontiveros, Joe		A water line broke in the buster pump; need it repaired ASAP Thank you, Ruben							
Ruben Ortiz									
116836					5/7/2014		28		\$0.00
Medium	Work In Progress				5/7/2014 10:47:15 AM				
Ontiveros, Joe		Nurses bathroom; the toilet is not flushing correctly; need it fixed ASAP							
Ruben Ortiz									
112082					1/14/2014		141		\$0.00
Medium	Work In Progress				1/14/2014 1:45:30 PM				
Ontiveros, Joe		Boys urinals upper level flush valves are not working; they are not shutting off							
Ruben Ortiz									
104962					7/31/2013		308		\$0.00
Medium	Work In Progress				7/31/2013 8:07:41 AM				
Gonzalez, Salvador		Vandalism; need a new library stand the was destroyed in vandalism. Thank you, Ruben							
Ruben Ortiz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Desert View ES							
113004		Classroom			2/5/2014		119		\$0.00
Medium	Work In Progress	Portable A			2/5/2014 8:56:47 AM				
Lara, Ralph		2nd Request: The lock to the door is broken. (Sanchez)							
Guadalupe Gonzalez									
116991		Portables			5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 8:42:21 AM				
Ronquillo, Ruben		On Monday morning May 12, 2014 I was called by the Principal Mr. Aurajo that there was a broken window in portable 6. Police report was done by Sunland Park PD given us a case #2014-00580. The measurements for the window were taken by Mr.Ortiz the school building mechanic. The measurements are 16 X45 double panel and a 16 x14 single. If these could be replaced. Thank you							
Israel Ortega									
115336					4/1/2014		64		\$0.00
Medium	Work In Progress				4/1/2014 5:34:10 PM				
Ontiveros, Guadalupe		Need to replace 4 pine trees in the front circle of the school entrance.							
Ruben Ortiz									
115337					4/1/2014		64		\$0.00
Medium	Work In Progress				4/1/2014 5:35:18 PM				
Ontiveros, Guadalupe		Need to replace 1 pine trees and 4 oak trees on the level playground.							
Ruben Ortiz									
115338					4/1/2014		64		\$0.00
Medium	Work In Progress				4/1/2014 5:36:24 PM				
Ontiveros, Guadalupe		Need to replace 2 inch water valve for the sprinkler system.							
Ruben Ortiz									
117889					6/2/2014		2		\$0.00
Medium	Work In Progress				6/2/2014 10:20:46 AM				
Ambriz, Jose		The library a/c unit is not working; the alarm went off; need it repaired ASAP							
Ruben Ortiz									
116837					5/7/2014		28		\$0.00
Medium	Work In Progress				5/7/2014 10:48:31 AM				
Ambriz, Jose		Portable 4 room 6 bookroom; the a/c unit is not working; need it fixed							
Ruben Ortiz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Desert View ES									
116524					5/2/2014		33		\$0.00
Medium	Work In Progress				5/2/2014 9:35:38 AM				
Ontiveros, Guadalupe	Need soccer field air rated to have water go into the grass and fertilizer.								
Ruben Ortiz									
109214					10/22/2013		225		\$0.00
Medium	Work In Progress				10/22/2013 3:49:08 PM				
Castillo, Carlos	Need a light and switch outlet in the morgon.								
Ruben Ortiz									
117250					5/19/2014		16		\$0.00
Medium	Work In Progress				5/19/2014 8:32:37 AM				
Orozco, Daniel	COOLER ON SERVING LINE IS NOT COOLING. SNP MANAGER ELIZABETH D. 589.2425								
Maritza Gonzalez									
115644					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:26 AM				
Orozco, Daniel	Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
116521					5/2/2014		33		\$0.00
Medium	Work In Progress				5/2/2014 9:31:10 AM				
Castillo, Carlos	The carnival was moved to May 15th and we need the power set up by 8:00 a.m. that day request by Principal								
Ruben Ortiz									
116090					4/22/2014		43		\$0.00
Medium	Work In Progress				4/22/2014 10:33:10 AM				
Castillo, Carlos	Need electrical hook up for carnival that was moved to May 16th. Thank you, Ruben								
Ruben Ortiz									
Count: 62 Work Orders		Avg. Age of WO's 57			Total for Desert View ES			0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
113853					2/27/2014		97		\$0.00
High	Work In Progress				2/27/2014 7:56:50 AM				
Castillo, Carlos		circuit board to generator is bad. need to have rocky mountain cummins order and replace.							
Michael Munoz									
116826					5/7/2014		28		\$0.00
Medium	Work In Progress				5/7/2014 8:15:59 AM				
Castillo, Carlos		C-WING-ELECTRICAL NEEDS TO BE CONNECTED TO GARGABE DISPOSAL IN KITCHENETTE.							
Maritza Gonzalez									
115151					3/27/2014		69		\$0.00
High	Work In Progress				3/27/2014 4:03:43 PM				
Villalobos, David		back flow to fire protection system is leaking. please repair.							
Michael Munoz									
115657					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:35 AM				
Orozco, Daniel		Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
114642					3/14/2014		82		\$0.00
Medium	Work In Progress				3/14/2014 7:46:14 AM				
Castillo, Carlos		Start contacting bldg.mech. about summer projects and about material that will need to be ordered with sufficient time.							
Carlos Castillo									
115219		Electrical Room			3/31/2014		65		\$0.00
Medium	Work In Progress				3/31/2014 8:34:24 AM				
Castillo, Carlos		Order vehicle cleaning maintenance equipment							
Carlos Castillo									
113073					2/6/2014		118		\$0.00
Medium	Work In Progress				2/6/2014 10:16:16 AM				
Rodriguez, Arturo		ROSA APODACA OFFCE-POWER TO OUTLET WHERE COMPUTER IS CONNECTED WENT OUT.							
Maritza Gonzalez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
117897					6/2/2014		2		\$0.00
Medium	Work In Progress	OFFICE RM.			6/2/2014 2:03:17 PM				
Ambriz, Jose		INSTALL A WALL AIRCONDITIONER IN MRS. JEANNE FIELDS OFFICE.							
Noemi Duron									
117671					5/30/2014		5		\$0.00
Medium	Work In Progress				5/30/2014 12:44:04 PM				
Ambriz, Jose		Please check into a/c being moved asp email attached (See Mike)							
Richard Chavez									
114025					3/2/2014		94		\$0.00
Medium	Work In Progress				3/2/2014 12:26:12 AM				
Moncayo, Fernando		Yearly - GAC A-10 Heat Pump Cooling Only Yearly - Refer to PMschedule details.							
Margret Villalobos									
116501		Cafeteria			5/1/2014		34		\$0.00
Medium	Work In Progress				5/1/2014 3:17:32 PM				
Moncayo, Fernando		called by Maritza,Cafeteria a/c thermostat stuck in cooling,fan cycling							
Fernando Moncayo									
116450		Office			5/1/2014		34		\$0.00
Medium	Work In Progress				5/1/2014 8:02:23 AM				
Moncayo, Fernando		paint technology offices							
Fernando Moncayo									
116496					5/1/2014		34		\$0.00
Medium	Work In Progress				5/1/2014 2:29:34 PM				
Moncayo, Fernando		need to have couple shelves moved to mynew office							
Cora Ramirez									
116726					5/5/2014		30		\$0.00
Medium	Work In Progress				5/5/2014 3:12:57 PM				
Moncayo, Fernando		C-WING RESTROOM-CLOGGED SINK.							
Maritza Gonzalez									
116727					5/5/2014		30		\$0.00
Medium	Work In Progress				5/5/2014 3:13:19 PM				
Moncayo, Fernando		CLOSE VENT TO ADELE OFFICE.							
Maritza Gonzalez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
116305					4/28/2014		37		\$0.00
Medium	Work In Progress				4/28/2014 10:11:34 AM				
Moncayo, Fernando		AS PER MR. CHAVEZ PLEASE CLEAN OR SECURE PIGEON DROPPINGS FROM PRE-K AREA.							
Maritza Gonzalez									
116306					4/28/2014		37		\$0.00
Medium	Work In Progress				4/28/2014 10:31:46 AM				
Moncayo, Fernando		ANNE DE LOS SANTOS- REPLACE KEYBOARD TRAY.							
Maritza Gonzalez									
116307					4/28/2014		37		\$0.00
Medium	Work In Progress				4/28/2014 10:32:58 AM				
Moncayo, Fernando		We received a butcher paper dispenser which needs to be assembled – Mr. Moncayo came by this morning and is working on it, but wanted to make sure that the work order was submitted.							
		The other is for the installation of an astro turf rug which will be delivered . I would like to have it installed under the outdoor blocks shed which is in the playground. I have already spoken to Mr. Moncayo about it too.							
Maritza Gonzalez									
116355					4/29/2014		36		\$0.00
Medium	Work In Progress				4/29/2014 10:06:08 AM				
Moncayo, Fernando		Install a wall file in each of Melissa Murillo and Priscilla's Escobar offices.							
Maritza Gonzalez									
116220					4/24/2014		41		\$0.00
Medium	Work In Progress				4/24/2014 3:32:53 PM				
Moncayo, Fernando		in the technology department, blinds fall from the window. Please fix							
Cora Ramirez									
116230					4/24/2014		41		\$0.00
Medium	Work In Progress				4/24/2014 3:58:34 PM				
Moncayo, Fernando		STEVE SUGGS OFFICE- A/C NOT COOLING ON WALL UNIT.							
Maritza Gonzalez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		GAC							
116240					4/25/2014		40		\$0.00
Medium	Work In Progress				4/25/2014 7:20:24 AM				
Moncayo, Fernando		Board meeting room - Check the thermostat to the cooling unit. not working correctly							
Alfredo Holguin									
115821					4/13/2014	4/29/2014	52		\$0.00
Medium	Work In Progress				4/13/2014 12:24:08 AM				
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
116871					5/7/2014		28		\$0.00
Medium	Work In Progress				5/7/2014 4:17:12 PM				
Moncayo, Fernando		in technology depart. need to have the shelves moved so that the door can be made to open due to the removal of the carpet and the installation of tile							
Cora Ramirez									
116571					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:37:52 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
116572					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:37:53 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
116655					5/4/2014	5/10/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:49 AM				
Moncayo, Fernando		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
116979					5/11/2014	5/27/2014	24		\$0.00
Medium	Work In Progress				5/11/2014 12:24:46 AM				
Moncayo, Fernando		Monthly - GAC Playground Insp - Refer to PM schedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
117870					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:11 AM				
Moncayo, Fernando		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
117776					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:10 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
117773					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:08 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
115065					3/26/2014		70		\$0.00
Medium	Work In Progress				3/26/2014 1:14:51 PM				
Moncayo, Fernando		C-WING KITCHENETTE-SINK CLOGGED.							
Maritza Gonzalez									
115483					4/6/2014	4/22/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:30:27 AM				
Moncayo, Fernando		Monthly - GAC A-1 Wall Ref. Elec Heat Semimonthly - Refer to PM schedule details.							
Margret Villalobos									
115505					4/6/2014	4/14/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:30:45 AM				
Moncayo, Fernando		Monthly - GAC Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
113858					2/27/2014		97		\$0.00
Medium	Work In Progress				2/27/2014 9:25:45 AM				
Moncayo, Fernando		FLOURESCENT LIGHT IN RICHARD ACOSTA OFFICE IS OUT.							
Maritza Gonzalez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		GAC							
113859					2/27/2014		97		\$0.00
Medium	Work In Progress				2/27/2014 9:26:26 AM				
Moncayo, Fernando		AS PER LUCY, PLEASE INSTAL WALL POCKET FILES IN MELISSA ALVARADO OFFICE.							
Maritza Gonzalez									
113770					2/25/2014		99		\$0.00
Medium	Work In Progress				2/25/2014 2:06:15 PM				
Moncayo, Fernando		maintenance rake and pick-up debris. also please start watering and clean other areas around site.yard needs grounds work (pine trees)							
Michael Munoz									
113771					2/25/2014		99		\$0.00
Medium	Work In Progress				2/25/2014 2:07:12 PM				
Moncayo, Fernando		please repair pot holes in dock area. thank you							
Michael Munoz									
113710					2/24/2014		100		\$0.00
Medium	Work In Progress				2/24/2014 1:33:06 PM				
Moncayo, Fernando		AS PER MR. CHAVEZ, GROUNDS NEED TO BE CLEANED UP.							
Maritza Gonzalez									
108942		Parking Lot			10/16/2013		231		\$0.00
Medium	Work In Progress				10/16/2013 7:49:09 AM				
Moncayo, Fernando		need to repaint all parking lot lines - work can be done in phases over weekends bydoing schedule adjustment							
Alfredo Holguin									
117642					5/29/2014		6		\$0.00
Medium	Work In Progress				5/29/2014 3:13:18 PM				
Moncayo, Fernando		WALL UNIT A/C NOT COOLING (ROSA A./LUCIA A.) OFFICE							
Maritza Gonzalez									
117361					5/21/2014		14		\$0.00
Medium	Work In Progress				5/21/2014 9:10:52 AM				
Moncayo, Fernando		GROUNDS NEED TO BE CLEANED UP (CUT WEEDS, PICK UP TRASH ETC.) 2ND REQUEST.							
Richard Chavez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
117362					5/21/2014		14		\$0.00
Medium	Work In Progress				5/21/2014 9:13:59 AM				
Moncayo, Fernando		Install panel on the wall where Linda's office desk is located.							
Maritza Gonzalez									
112142					1/15/2014		140		\$0.00
Medium	Work In Progress				1/15/2014 2:54:39 PM				
Sotelo, Enrique		Asp CIRT (Crisis Intervention Response Team) need to mark Electrical on site plans that were provided by Mike.							
Michael Munoz									
111437					12/19/2013		167		\$0.00
Medium	Work In Progress				12/19/2013 11:44:45				
Lara, Ralph		our door in the server room - battery not working anymore							
Cora Ramirez									
116495					5/1/2014		34		\$0.00
Medium	Work In Progress				5/1/2014 2:25:12 PM				
Lara, Ralph		COME AND CHECK LOCK ON DOOR RM. #111 FEDRERAL PROGRAMS							
Noemi Duron									
114534					3/11/2014		85		\$0.00
Medium	Work In Progress				3/11/2014 4:07:11 PM				
Ontiveros, Joe		REPLACE FAUCETS ON MOP SINK-CUSTODIAL CLOSET A-WING.							
Maritza Gonzalez									
113757					2/25/2014		99		\$0.00
Medium	Work In Progress	Technology			2/25/2014 11:42:35 AM				
Estrada, Jesus		Need to conduct abatement on floor. Carpet has couple of holes, unraveling. Please take it out of Calixto and Cora Office.							
Cora Ramirez									
112358					1/23/2014		132		\$0.00
Medium	Work In Progress				1/23/2014 7:35:42 AM				
Munoz, Michael		new fence 6' and gates for vehicles for techs stationed at site.							
Alfredo Holguin									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: GAC									
116413					4/30/2014		35		\$0.00
Medium	Work In Progress				4/30/2014 2:47:44 PM				
Lara, Ralph		I relocated to new office for just a months time frame. Need a key. It can be the same key as the offices we have C Wing.							
Cora Ramirez									
114685					3/17/2014		79		\$0.00
Medium	Work In Progress				3/17/2014 9:34:48 AM				
Flores, Pete		Good morning Maria, I just wanted to let you know that we had our Suburban over here at GAC since Friday, but just took it back to the lot. Just wanted to advise you on the problems that it's having:							
		<ul style="list-style-type: none"> No Power Steering – it's hard to turn Signal Lights are not working Left side brake lights are not working either 							
		Please have it checked and serviced thoroughly as time to time we use it for our various needs. Also, if you can please let me know when it's completed and ready for use. Thank you and have a good day. ☺							
		Karla M. Quesada							
Karla Quesada									
117645					5/29/2014		6		\$0.00
Medium	Work In Progress				5/29/2014 3:29:16 PM				
Flores, Pete		Vehicle #177 battery low won't start unless it's jump							
Fernando Moncayo									
115661					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:38 AM				
Munoz, Michael		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
112219					1/16/2014		139		\$0.00
Medium	Work In Progress				1/16/2014 4:10:45 PM				
Flores, Pete		Vehicle 172 (Mr. Giovas) needs windshield wipers checked.							
Maritza Gonzalez									
Count: 54 Work Orders			Avg. Age of WO's	59			Total for GAC	0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC - Pre-K

113760 2/25/2014 99 \$0.00

Medium Work In Progress 2/25/2014 12:52:47 PM

Ronquillo, Ruben need to order bolts for dobble slide from (recreation creations)

Fernando Moncayo

114536 3/11/2014 85 \$0.00

Medium Work In Progress 3/11/2014 4:08:34 PM

Moncayo, Fernando ROOM 203-LAMP OUTSIDE NEED TO SECURE SO BIRDS WILL NOT LAND AND MAKE A MESS.

Maritza Gonzalez

117621 5/29/2014 6 \$0.00

Medium Work In Progress 5/29/2014 7:50:56 AM

Moncayo, Fernando I need to put in a couple of work orders please!

1. Move the file cabinet that is the cafeteria to the workroom next to the office. It will go right next to the other file cabinet that's already there.
2. Take down the white board that is the workroom next to the office and install it in room 202. Ms. Sylvia will leave a note on the wall where she would like it
3. Room 203 - Move the white board from one wall to another. Ms. Ceci will leave a note on the wall where she would like it.
4. Room 103-please move bulletin board that is close to outside window to wall near front window. Ms. Viola will leave a note on the wall where she would like it.

Nancy Bellagamba

115716 4/8/2014 57 \$0.00

Medium Work In Progress 4/8/2014 10:50:38 AM

Moncayo, Fernando AS PER NANCY BELLAGAMA-
1.) One of the cabinet doors in room 102 fell off the hinges.
2.) The door stopper to the storage door in the cafeteria fell off. 3.) Two of our trikes - the handle bars fell off.

Nancy Bellagamba

116354 4/29/2014 36 \$0.00

Medium Work In Progress 4/29/2014 10:01:18 AM

Moncayo, Fernando With all the winds this weekend we have sand all over the blue surface of the playground which needs to be blown off and also mounds of sand in the corners as well.

Nancy Bellagamba

6/4/2014 1:35:09 PM

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: GAC - Pre-K

114191 3/4/2014 92 \$0.00

Medium Work In Progress 3/4/2014 7:43:46 AM

Moncayo, Fernando We need to create a work order for the paper towel dispenser in room 103. It's coming off the wall. Also before the custodians come fix it could you have them talk with Ms. Viola or Ms. Pauline, that way they can move it to where the kids can reach it. Thank you.

Maritza Gonzalez

113703 2/24/2014 100 \$0.00

Medium Work In Progress 2/24/2014 11:24:57 AM

Ontiveros, Guadalupe Build an install two raised planters.

Alfredo Holguin

113704 2/24/2014 100 \$0.00

Medium Work In Progress 2/24/2014 11:26:02 AM

Ontiveros, Guadalupe provide water to new raised planters

Alfredo Holguin

113705 2/24/2014 100 \$0.00

Medium Work In Progress 2/24/2014 11:27:40 AM

Ontiveros, Guadalupe provide topsoil and compost for Metal Planters (4)-

Alfredo Holguin

113848 2/26/2014 98 \$0.00

Medium Work In Progress 2/26/2014 4:02:50 PM

Holguin, Alfredo Playground area is 60'x48'+or= and the surface is crushed rubber Glued and painted w/o # 113760 and is for a missing bolt The patio also have two small areas filled with sand

Fernando Moncayo

Count: 10 Work Orders Avg. Age of WO's 77 Total for GAC - Pre-K 0 \$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden ES

114895		Exterior			3/21/2014		75		\$0.00
--------	--	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/21/2014 9:20:56 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Holguin, Alfredo need wood chips for east playground equipment , needs refilling

Fred Appelzoller

115171					3/28/2014		68		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/28/2014 3:06:00 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Daniel LIGHT ON HOOD WENT OUT. SNP MANAGER EVA M. 882.3410

Maritza Gonzalez

117896		Office			6/2/2014		2		\$0.00
--------	--	--------	--	--	----------	--	---	--	--------

Medium	Work In Progress				6/2/2014 2:02:21 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Briones, Enrique Deliver 2 bxs. PO# 131406723

Theresa Ramirez

114995		Foyer			3/25/2014		71		\$0.00
--------	--	-------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/25/2014 10:53:53 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Sotelo, Enrique as per Mr. Munoz and Ms. Marquez conversation... a light fixture must be installed in the foyer... thank you...

Loraine Gandara

114512		Hallway/Corridor			3/11/2014		85		\$0.00
--------	--	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/11/2014 3:35:56 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred need batterypacks for emergency lighting in hallways T-8 lights . also 4 pin lamps for recess lights in lobby area and hall ways (4 pin GE- Biax T/E, F26TBX/830/A/ECO

Fred Appelzoller

113593		Hallway/Corridor			2/20/2014		104		\$0.00
--------	--	------------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/20/2014 10:56:06 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Appelzoller, Fred need assistance with the wall molding in Jefferson wing...there is none next to the water fountain.. thank you...

Loraine Gandara

117988		Athletic Field			6/4/2014		0		\$0.00
--------	--	----------------	--	--	----------	--	---	--	--------

Medium	Work In Progress				6/4/2014 11:24:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Appelzoller, Fred trees are going to be purchased. need to meet with site administrator for locations and stake out. once locations have been identified water will need to be run. need water for 8 trees around campus road that goes around site.

Michael Munoz

6/4/2014 1:35:09 PM

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden ES									
116931		Classroom			5/9/2014		26		\$0.00
Medium	Work In Progress	100			5/9/2014 10:16:34 AM				
Appelzoller, Fred		molding on countertop is falling apart please assist with this... thank you...							
Loraine Gandara									
112124					1/15/2014		140		\$0.00
Medium	Work In Progress				1/15/2014 11:08:10 AM				
Marquez, Gerardo		need to to have keys made for Zern lock boxes outside ...thank you....							
Loraine Gandara									
111043					12/9/2013		177		\$0.00
Medium	Work In Progress				12/9/2013 12:13:30 PM				
Marquez, Gerardo		Silver working with DOT on setting up new flashing lights at GE. He cannot open box. need help with keys							
Cora Ramirez									
114996		Cafeteria			3/25/2014		71		\$0.00
Medium	Work In Progress				3/25/2014 10:55:18 AM				
Appelzoller, Fred		as per Mr.Munoz and Ms. Marquez conversation cafeteria must be painted... thank you...							
Loraine Gandara									
117520		Restroom			5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 1:02:44 PM				
Appelzoller, Fred		water closet keeps clogging							
Fred Appelzoller									
117917					6/3/2014		1		\$0.00
Medium	Work In Progress	front office			6/3/2014 8:33:21 AM				
Appelzoller, Fred		need to replace both toilets in womens restroom... thank you....							
Loraine Gandara									
117772					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:08 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden ES

117771 6/1/2014 6/9/2014 3 \$0.00

Medium Work In Progress 6/1/2014 12:54:07 AM

Appelzoller, Fred Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.

Margret Villalobos

117778 6/1/2014 3 \$0.00

Medium Work In Progress 6/1/2014 12:54:12 AM

Appelzoller, Fred Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

117868 6/1/2014 6/12/2014 3 \$0.00

Medium Work In Progress 6/1/2014 12:55:10 AM

Appelzoller, Fred Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.

Margret Villalobos

116455 5/1/2014 34 \$0.00

Medium Work In Progress 5/1/2014 8:32:15 AM

Appelzoller, Fred lavatory faucets not working in girls restroom... would greatly appreciate your assistance in this matter thank you....

Loraine Gandara

112579 Classroom 1/29/2014 126 \$0.00

Medium Work In Progress 211 1/29/2014 8:42:55 AM

Appelzoller, Fred need assistance with putting some shelves in room 211... I would greatly appreciate your assistance in this matter...

Loraine Gandara

117572 Parking Lot 5/28/2014 7 \$0.00

Medium Work In Progress 5/28/2014 10:56:41 AM

Appelzoller, Fred need for the lines to be painted over again in the parking lot... greatly appreciate your assistance with this matter....

Loraine Gandara

112205 Parking Lot 1/16/2014 139 \$0.00

Medium Work In Progress 1/16/2014 3:36:46 PM

Sotelo, Enrique . He indicated that he and Lorenzo were out checking the problem and determined that there is an electrical issue with the exterior lights. Supposedly Lorenzo was entering a work order, so the electrician could work on it.

Loraine Gandara

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden ES									
116225					4/24/2014		41		\$0.00
Medium	Work In Progress			4/24/2014 3:49:12 PM					
Orozco, Daniel	1 of our bottom ovens does not heat up no more it turns on but no heat. SNP Manager Eva M. 882.3410								
Maritza Gonzalez									
116556					5/4/2014		31		\$0.00
Medium	Work In Progress			5/4/2014 12:37:40 AM					
Villalobos, Margret	Monthly - Gadsden ES - Trane PM Quarterly - Refer to PMs schedule details.		Emailed 5/5/14						
Margret Villalobos									
114772		Classroom			3/18/2014		78		\$0.00
Medium	Work In Progress	Work room in		3/18/2014 2:19:14 PM					
Lara, Ralph	need immediate assistance... cannot open door or get into room...thank you....								
Loraine Gandara									
111145		Classroom			12/11/2013		175		\$0.00
Medium	Work In Progress	205		12/11/2013 9:15:45 AM					
Solis, Lorenzo	" Under Warranty" room 205 air is coming our cold... thank you...								
Loraine Gandara									
115830					4/13/2014	4/29/2014	52		\$0.00
Medium	Work In Progress			4/13/2014 12:24:15 AM					
Pinon, Jose	Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PMs schedule details.								
Margret Villalobos									
Count: 26 Work Orders		Avg. Age of WO's 59			Total for Gadsden ES			0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

113942 2/28/2014 96 \$0.00

Medium Work In Progress 2/28/2014 12:32:59 AM

Munoz, Michael Yearly - Gadsden HS - Fire Pump Inspection - Refer to PM schedule details.

Margret Villalobos

117269 5/19/2014 16 \$0.00

Medium Work In Progress 5/19/2014 1:53:02 PM

Carbajal, Jimmy Jimmy i need at least 2 50' extention cords for the machines during the summer. Someone has taken or stolen some of my extention cords.

Jaime Herrera

116038 Gym 4/17/2014 48 \$0.00

Medium Work In Progress 4/17/2014 8:11:24 AM

Estrada, Jesus All the gym floors (Varsity, Boys, and Girls) need to be refurbished during the summer (June 2-13).

Jaime Herrera

116405 4/30/2014 35 \$0.00

Medium Work In Progress 4/30/2014 9:30:45 AM

Lara, Ralph Requested by Velia-Three HE231 are needed for the Auto Shop. The Administration Team needs to have access to retrieve the golf carts.

Velia Alarcon

116021 4/16/2014 49 \$0.00

Medium Work In Progress 4/16/2014 3:45:50 PM

Lara, Ralph Need to replace door knob to mechanical room in the annex building.

Guillermo Hernandez

116010 Gym 4/16/2014 49 \$0.00

Medium Work In Progress 4/16/2014 3:10:31 PM

Lara, Ralph During June 2-13 they will refurbishing the gym floors and the doors need to be rekeyed during that time so no one can enter. This goes for all the gyms (Varsity, Boys, and Girls).

Jaime Herrera

114817 3/19/2014 77 \$0.00

Medium Work In Progress 3/19/2014 2:10:03 PM

Flores, Pete All the gators tires need to be replaced, the ones in the front are going bald again and the back are going out as well.

Jaime Herrera

6/4/2014 1:35:09 PM

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
115535					4/6/2014		59		\$0.00
Medium	Work In Progress				4/6/2014 12:31:14 AM				
Flores, Pete		Monthly - GHS-UV-0515 PM Service - Refer to PM schedule details.							
Margret Villalobos									
116641					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:40 AM				
Sanchez, Raul		Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
116640					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:39 AM				
Sanchez, Raul		Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
116993		Athletic Field			5/12/2014		23		\$0.00
High	Work In Progress				5/12/2014 9:37:32 AM				
Sanchez, Raul		new sod will be laid in the boys baseball field. need to make sure irrigation pump (behind football field) is working properly so irrigation system will work automatically. project to begin june 1st.							
Guadalupe Ontiveros									
117296					5/19/2014		16		\$0.00
Medium	Work In Progress				5/19/2014 4:09:13 PM				
Lara, Ralph		Please replace cylinder for the testing room on the west wing of the cafeteria as per Mrs. Rodriguez.							
Guillermo Hernandez									
117583					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 1:48:22 PM				
Lara, Ralph		Requested by Ms. Anderson for Panther Hut Pantry Room-Re-key pantry to off master.							
Velia Alarcon									
117584					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 1:51:11 PM				
Lara, Ralph		Requested by Velia-Keys to the New CTE Building are needed.							
Velia Alarcon									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden HS									
117665					5/30/2014		5		\$0.00
Medium	Work In Progress			5/30/2014 11:09:17 AM					
Lara, Ralph	Requested by Coach Gerela for Football Locker Room Boy's Gym-South east side door of football locker room needs new lock. Door can be opened, pryed from outside. Currently has a side lock.								
Velia Alarcon									
112644					1/30/2014		125		\$0.00
Medium	Work In Progress			1/30/2014 10:19:28 AM					
Lara, Ralph	Requested by Velia-An extra key is needed for mailbox # 31 and # 96.								
Velia Alarcon									
112645					1/30/2014		125		\$0.00
Medium	Work In Progress			1/30/2014 10:21:00 AM					
Lara, Ralph	Requested by Velia-Mailbox # 72 is ver hard to open. SEE MARIA FOR EXTRA KEY TO MAILBOX.								
Velia Alarcon									
113213					2/10/2014		114		\$0.00
Medium	Work In Progress			2/10/2014 1:43:43 PM					
Lara, Ralph	Requested by Mrs. Munoz Rm. 207 North Building-Door from kitchen to classroom needs to have a double side lock. Only has lock from kitchen to classroom and not from classroom to kitchen.								
Velia Alarcon									
115355					4/2/2014		63		\$0.00
Medium	Work In Progress			4/2/2014 3:15:21 PM					
Lara, Ralph	Requested by Velia-Mailbox # 110 key was lost and an extra keys needs to be made.								
Velia Alarcon									
117188		Classroom			5/15/2014		20		\$0.00
Medium	Work In Progress	513		5/15/2014 2:58:17 PM					
Lara, Ralph	Requested by Ms. Leal Rm. 513 New CTE Building-One of the wall cabinets won't lock properly.								
Velia Alarcon									
117189		Classroom			5/15/2014		20		\$0.00
Medium	Work In Progress	513		5/15/2014 3:00:00 PM					
Lara, Ralph	Requested by Ms. Leal Rm. 513 New CTE Building-File cabinet lock is falling off.								
Velia Alarcon									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
117113					5/13/2014		22		\$0.00
Medium	Work In Progress				5/13/2014 3:56:23 PM				
Lara, Ralph		Need to repair door knob to the security office at the North building, cylinder came off.							
Guillermo Hernandez									
117566					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 9:32:54 AM				
Lara, Ralph		Requested by Velia-An additional M300 for the Football Concession Stand is needed for Coach Lawrence who has requested and received approval for the key.							
Velia Alarcon									
117839					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:51 AM				
Sanchez, Raul		Monthly - Gadsden HS - Lift Station Inspection - Refer to PMschedule details.							
Margret Villalobos									
117119					5/14/2014		21		\$0.00
Medium	Work In Progress				5/14/2014 12:34:56 AM				
Sanchez, Raul		Monthly - Gadsden HS- Filters (Pump Rm) Quarterly - Refer to PMschedule details.							
Margret Villalobos									
117840					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:52 AM				
Sanchez, Raul		Monthly - Gadsden HS - Monthly Water Samples - Refer to PMschedule details.							
Margret Villalobos									
116396					4/30/2014		35		\$0.00
Medium	Work In Progress				4/30/2014 1:01:42 AM				
Sanchez, Raul		Monthly - Gadsden HS - Monthly Meter Readings - Refer to PMschedule details.							
Margret Villalobos									
115611					4/6/2014		59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:05 AM				
Sanchez, Raul		Monthly - Gadsden HS - Lift Station Inspection - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
116398					4/30/2014		35		\$0.00
Medium	Work In Progress				4/30/2014 1:01:47 AM				
Sanchez, Raul		Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
114669	Boys Gym				3/14/2014		82		\$0.00
High	Work In Progress				3/14/2014 3:50:59 PM				
Estrada, Jesus		Need to repair a bump on the wood floor by the west side basket. This is a safety issue.				3/17/14 - ASP CHUY, (1) NEED TO: FIX (4) CORNERS/AREAS - THEY ARE BUCKLEING; (2) SHAVE COMPLETE FLOOR; (3) REPAINT LINES; (4) REFINISH. FAXED TO STOUT HARDWOODS.			
Guillermo Hernandez									
114858	Cafeteria (1998)	Restroom			3/20/2014		76		\$0.00
Medium	Work In Progress				3/20/2014 2:00:22 PM				
Lara, Ralph		All of the partitions are all rusted out on the bottom and need to be replaced.							
Jaime Herrera									
113062	Varsity Gym	Gym			2/6/2014		118		\$0.00
Medium	Work In Progress				2/6/2014 8:46:53 AM				
Gallegos, Rafael		WARRANTY WORK ON GYM FLOOR need to fix two broken planks on gym floor they are located on the southeast corner right outside of basketball court							
Daniel Sotelo									
117268	Varsity Gym				5/19/2014		16		\$0.00
Medium	Work In Progress				5/19/2014 1:50:47 PM				
Lara, Ralph		New handels are needed in the varsity gym exterior doors, kids have been trying to force them open and are now all loose.							
Jaime Herrera									
114930	Varsity Gym				3/21/2014		75		\$0.00
Medium	Work In Progress				3/21/2014 4:15:43 PM				
Munoz, Michael		PM - Annual Bleacher Service performed by A.K. Sales.							
Michael Munoz									
113815	Varsity Gym				2/25/2014		99		\$0.00
Medium	Work In Progress				2/25/2014 4:09:37 PM				
Sotelo, Daniel		need to replaces a few stair plank's on bleachers							
Daniel Sotelo									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
115418					4/3/2014		62		\$0.00
Medium	Work In Progress				4/3/2014 3:51:10 PM				
Gonzalez, Salvador		Need to cover openings on the outside wall of the Boys gym, size 8ft. x 3ft. and 32 inch x 94 inch.							
Guillermo Hernandez									
113585		Athletic Field			2/20/2014		104		\$0.00
Medium	Work In Progress				2/20/2014 8:29:12 AM				
Gonzalez, Salvador		Requested by Ms. L. Chavez-Move batting tee structure back take poles off fence and attach to metal structure. Add chain link fence to existing poles. ANY QUESTIONS PLEASE SEE COACH LILLY CHAVEZ.							
Velia Alarcon									
109350		Athletic Field			10/25/2013		222		\$0.00
Medium	Work In Progress				10/25/2013 3:35:29 PM				
Gonzalez, Salvador		please replace door to morgan building by batting cages. boys baseball. thank you							
Michael Munoz									
112979	Academic Bldg	Classroom			2/4/2014		120		\$0.00
Medium	Work In Progress	331			2/4/2014 3:45:51 PM				
Villalobos, David		Requested by Ms. Hartmann Rm. 331 Academic Building-Relocate sink cabinet from room 107 in the Main Building to room 331 in the Academic Building.							
Velia Alarcon									
117293	Academic Bldg				5/19/2014		16		\$0.00
Medium	Work In Progress				5/19/2014 4:04:38 PM				
Sotelo, Daniel		brake in over weekend called in to check for damage helped clean and cut locks from gates							
Daniel Sotelo									
116940	Academic Bldg				5/9/2014		26		\$0.00
Medium	Work In Progress				5/9/2014 11:22:09 AM				
Sotelo, Daniel		lights switch not working in the south side of building need to be replaced							
Daniel Sotelo									
117257	Academic Bldg				5/19/2014		16		\$0.00
Medium	Work In Progress				5/19/2014 8:58:45 AM				
Lara, Ralph		Need to check all exit doors as per Mr. Acosta, Security doors can be easily opened not locking properly. Please give Alfredo or Mike status on what you find.							
Alfredo Holguin									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
117267	Academic Bldg				5/19/2014		16		\$0.00
Medium	Work In Progress				5/19/2014 1:48:33 PM				
Lara, Ralph		Pad locks and chains are needed to lock exterior doors so no one can enter when doors are pulled hard.							
Jaime Herrera									
116889	Academic Bldg	Classroom			5/8/2014		27		\$0.00
Medium	Work In Progress	345			5/8/2014 11:40:11 AM				
Lara, Ralph		Requested by Liz Faudoa Rm. 345 Academic Building- The building in cabinet in room # 345 needs to be re-keyed as soon as possible. The Sp.Ed. Office will need to secure and store all Sp.Ed. computers. This w.o. will need to be completed before the last day of school Friday, May 23.							
Velia Alarcon									
112094	Academic Bldg	Classroom			1/14/2014		141		\$0.00
Medium	Work In Progress	331			1/14/2014 3:38:14 PM				
Lara, Ralph		Requested by Ms. Hartmann Rm. 331 Academic Building- Please re-key classroom door, which includes two door into the court yard, to a different key number.							
Velia Alarcon									
117420	Academic Bldg	Classroom			5/22/2014		13		\$0.00
Medium	Work In Progress	334			5/22/2014 8:32:06 AM				
Ambriz, Jose		Requested by Mrs. King Rm. 334 Academic Building- The a/c will not turn on, it just makes a loud rumbling noise.							
Velia Alarcon									
117309					5/20/2014		15		\$0.00
Medium	Work In Progress	Old Panther Hut			5/20/2014 8:57:59 AM				
Briones, Enrique		I am sending you a copy a Request for Authorization to Dispose of Equipment. Please assist me by removing the equipment from the campus. It is to go to surplus. It is no longer functional. Please let me know if you require any additional information. Let me know when you are ready to remove the equipment.							
Alfredo Holguin									
116882					5/8/2014		27		\$0.00
Medium	Work In Progress				5/8/2014 9:16:03 AM				
Sotelo, Enrique		Compactor - is ready to be hookup again asp contractor.							
Guillermo Hernandez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: Gadsden HS

116885 5/8/2014 27 \$0.00

Medium Work In Progress 5/8/2014 10:22:42 AM

Sotelo, Enrique
 Company: SMITH & AGUIRRE CONSTRUCTION
 Contact Name: FREDDIE TORRES
 Contact Phone: (575)527-2500
 Cell Phone: (575)642-6198
 Email: ftorres@runbox.com

Nearest Intersecting Street: WESTSIDE RD
 2nd Intersecting Street: WASHINGTON ST
 Latitude: 32.00034617 Longitude: -106.65685917
 Zip Code: 88027

Township: 26S Range: 03E Section 1/4: 32 SE

Location of Work: SPOT PER WORK PLAN

Dominique Esparza

116481 5/1/2014 34 \$0.00

Medium Work In Progress 5/1/2014 11:40:26 AM

Sotelo, Enrique Need to secure and reinforce lamp in the boys gym.

Guillermo Hernandez

116812 5/6/2014 29 \$0.00

Medium Work In Progress 5/6/2014 3:56:04 PM

Villalobos, David Need assistance to unclog toilet in the girls locker room at the Boys gym. there must be something stock, I try already and no luck.

Guillermo Hernandez

108046 9/27/2013 250 \$0.00

Medium Work In Progress 9/27/2013 2:28:05 PM

Sotelo, Enrique Bus Turnaround - Need to provide power to lift station to prevent future flooding. (See Mike for details).

Michael Munoz

117987 6/4/2014 0 \$0.00

High Work In Progress 6/4/2014 11:23:36 AM

Villalobos, David For Gadsden High School need locates for utilities and data for new tennis court. Locates needed West of existing tennis court by 4 pm Thursday June 5, 2014. Should you have any questions please contact Mr. Tony Saenz of AKS Architecture (575) 532-1310 or Mr. Alfredo Holguin (575) 882-6901. Thank You

Dominique Esparza

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
104583					7/22/2013		317		\$0.00
Medium	Work In Progress				7/22/2013 3:49:21 PM				
Villalobos, David		Need to replace gasket to shower in the Sped classroom at the Annex building.							
Guillermo Hernandez									
115783		Portables			4/10/2014		55		\$0.00
Medium	Work In Progress				4/10/2014 7:40:13 AM				
Villalobos, David		Over in the Portables there is no spot to get water for the mop bucket. If you could please put a water spout by portable 14 please.							
Jaime Herrera									
117489					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 12:33:37 AM				
Hernandez, Guillermo		Weekly - Gadsden HS - Fire Pump (Biweekly) - Refer to PM schedule details.							
Margret Villalobos									
117467					5/23/2014		12		\$0.00
Medium	Work In Progress				5/23/2014 11:20:19 AM				
Hernandez, Guillermo		Please check A/C for grounds shop.							
Guillermo Hernandez									
117764					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:02 AM				
Hernandez, Guillermo		Yearly - Gadsden HS B2 (Boiler)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
117869					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:10 AM				
Hernandez, Guillermo		Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
117812					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:33 AM				
Hernandez, Guillermo		Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Gadsden HS									
116653					5/4/2014	5/10/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:48 AM				
Hernandez, Guillermo	Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
116874					5/8/2014		27		\$0.00
Medium	Work In Progress				5/8/2014 7:41:58 AM				
Hernandez, Guillermo	Please replace boards to ramp by the girls locker room at the Boys gym.								
Guillermo Hernandez									
116900					5/8/2014		27		\$0.00
Medium	Work In Progress				5/8/2014 3:18:32 PM				
Hernandez, Guillermo	Please check H/C units in the computer lab.								
Guillermo Hernandez									
116573					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:37:53 AM				
Hernandez, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
116533					5/2/2014		33		\$0.00
Medium	Work In Progress	233			5/2/2014 2:05:52 PM				
Hernandez, Guillermo	Requested by Mrs. Lerma Rm. 233 North Building- Remove three large pieces of equipment from the old Panter Hut.								
Velia Alarcon									
116534					5/2/2014		33		\$0.00
Medium	Work In Progress				5/2/2014 2:19:24 PM				
Hernandez, Guillermo	Requested by Mrs. Lerma Rm. 233 North Building- Washing machine is leaking.								
Velia Alarcon									
116535					5/2/2014		33		\$0.00
Medium	Work In Progress				5/2/2014 2:39:40 PM				
Hernandez, Guillermo	Requested by Mrs. Lerma Rm. 233 North Building- Wall mounts for U.S. and State flag need to be placed in classroom.								
Velia Alarcon									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
116555					5/2/2014		33		\$0.00
Medium	Work In Progress				5/2/2014 4:25:16 PM				
Hernandez, Guillermo		Requested by Coach Letz for Rm. 100 in Boys Gym- The lights are not working.							
Velia Alarcon									
117419		Classroom			5/22/2014		13		\$0.00
Medium	Work In Progress	516			5/22/2014 8:29:06 AM				
Hernandez, Guillermo		Requested by Mrs. Hamilton Rm. 516 New CTE Building -Relocation of writing white board, bulletin boards (2), and screen. PLEASE SEE MEMO FOR CLARIFICATION.							
Velia Alarcon									
116894		Classroom			5/8/2014		27		\$0.00
Medium	Work In Progress	518			5/8/2014 12:52:45 PM				
Hernandez, Guillermo		Requested by Mr. Martin Rm. 518 Annex Buidling-Two full sets of lights are out in the restroom. This is a Sp.Ed. "D" level classroom and lights need to be changed as soon as possible.							
Velia Alarcon									
116527		Gym			5/2/2014		33		\$0.00
Medium	Work In Progress	Girl's Gym			5/2/2014 10:29:53 AM				
Hernandez, Guillermo		Requested by Coach Letz Girl's Gym-The bulleting board and paper towel dispenser needs to put back in place.							
Velia Alarcon									
115512					4/6/2014	4/14/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:30:50 AM				
Hernandez, Guillermo		Monthly - Gadsden HS Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									
113594					2/20/2014		104		\$0.00
Medium	Work In Progress				2/20/2014 12:17:33 PM				
Sotelo, Enrique		Need to replace 4 lamps to lighting on the south side of campus by the tennis court and swimming pool. We will need the bucket truck.							
Guillermo Hernandez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

117874 6/2/2014 2 \$0.00

High Work In Progress 6/2/2014 6:20:53 AM

Sotelo, Enrique Need assistance to remove and secure light pole between North building and Academic building for replacement

Guillermo Hernandez

117363 5/21/2014 14 \$0.00

Medium Work In Progress 5/21/2014 9:22:38 AM

Sotelo, Enrique For Gadsden High School Locates needed
 Nearest Intersecting Street: WESTSIDE RD
 2nd Intersecting Street: WASHINGTON ST
 Subdivision:
 Latitude: 32.00034617 Longitude: -106.65685917
 Zip Code: 88027
 Township: 26S Range: 03E Section 1/4: 32 SE
 Should you have any questions please contact:
 Company: SMITH & AGUIRRE CONSTRUCTION
 Contact Name: FREDDIE TORRES
 Contact Phone: (575)527-2500
 Cell Phone: (575)642-6198
 Email: ftorres@runbox.com

Dominique Esparza

117503 5/27/2014 8 \$0.00

Medium Work In Progress 5/27/2014 9:09:04 AM

Sotelo, Enrique From fence to pole by old bus gate see e-mail for highlighted map area.....W1405231 127280 FRM ANTHONY GO W ON WASHINGTON ST FOR 2.92MI TO AVENIDA DE MESILLA (NM-28). FROM THE INTERSECTION OF AVENIDA DE MESILLA & WASHINGTON ST. SPOT: 800' NORTH & 200' SOUTH WITH A WIDTH OF 75' WEST FOR FULL LENGTHS.
 Request by: TRIPLE J EXCAVATION
 Contact Name: ANNETTE GRANADO
 Contact Phone: (575)527-1763
 FaxNo: (575)541-8136
 Cell Phone: (575)644-6817
 Email: annettejtriplej@yahoo.com

Dominique Esparza

115677 4/7/2014 58 \$0.00

Medium Work In Progress LINE LOCATE 4/7/2014 9:30:25 AM

Sotelo, Enrique They can check with Allen Journey he should know. This work is being done by one of their subcontractors for the GHS project. Or they may need to attend the conference @ 9am on April 8th.

Alfredo Holguin

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:	Gadsden HS								
117986					6/4/2014		0		\$0.00
High	Work In Progress				6/4/2014 11:19:34 AM				
Sotelo, Enrique		For Gadsden High School need locates for utilities and data for new tennis court. Locates needed West of existing tennis court by 4 pm Thursday June 5, 2014. Should you have any questions please contact Mr. Tony Saenz of AKS Architecture (575) 532-1310 or Mr. Alfredo Holguin (575) 882-6901. Thank You							
Dominique Esparza									
117525		Athletic Field			5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 1:16:21 PM				
Ontiveros, Guadalupe		Requested by Coach D. Vega for Soccer Fields-Paint soccer fields.							
Velia Alarcon									
117530		Athletic Field			5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 1:39:54 PM				
Ontiveros, Guadalupe		Requested by Coach Lawrence-Paint soccer fields							
Velia Alarcon									
117531		Athletic Field			5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 1:41:30 PM				
Ontiveros, Guadalupe		Requested by Coach Lawrence-New sprinkler heads through out soccer field.							
Velia Alarcon									
117532		Athletic Field			5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 1:42:46 PM				
Ontiveros, Guadalupe		Requested by Coach Lawrence-Fertilize and place new grass on goals.							
Velia Alarcon									
117533		Athletic Field			5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 1:44:19 PM				
Ontiveros, Guadalupe		Requested by Coach Lawrence-Place and spread top soil through out soccer field to make it even.							
Velia Alarcon									
117534		Athletic Field			5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 1:45:03 PM				
Ontiveros, Guadalupe		Requested by Coach Lawrence-Put new nets on goals.							
Velia Alarcon									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
116990		Athletic Field			5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 8:35:17 AM				
Ontiveros, Guadalupe		as per mr.chavez order sod for infield of boys baseball and place after old grass has been removed. see mike for details.							
Michael Munoz									
117378					5/21/2014		14		\$0.00
Medium	Work In Progress				5/21/2014 3:05:33 PM				
Herrera, Jaime		At Gadsden High School for the head custodian to move furniture from the North building for Asbestos work as discussed in meeting. Furniture to start being moved Friday May 23, 2014, should you have questions please contact Mr. Gallegos at (575) 882-69221.							
Dominique Esparza									
117608					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 4:05:53 PM				
Ambriz, Jose		Need assistance to trouble shoot A/C's for the shops (problems with the relays).							
Guillermo Hernandez									
116965					5/9/2014		26		\$0.00
Medium	Work In Progress				5/9/2014 3:56:26 PM				
Ambriz, Jose		Requested by Ms. Leal Rm. 513 in New CTE Building- There is a high pitched noise in my classroom every morning...it sounds like it is coming from the vent above the row of cabinets. Very disturbing to the students. It seems to go away by the afternoon. (I checked for the noise is coming from the VAV box)							
Guillermo Hernandez									
117110					5/13/2014		22		\$0.00
Medium	Work In Progress				5/13/2014 3:54:05 PM				
Ambriz, Jose		Need to replace switching relay to H/C unit for portable #1.							
Guillermo Hernandez									
114283					3/5/2014		91		\$0.00
Medium	Work In Progress				3/5/2014 3:27:32 PM				
Ambriz, Jose		Need to replace (7) 6800 Evap. coolers from Academic: EVAP-GHS-23, EVAP-GHS-027, EVAP-GHS-030, EVAP-GHS-31, EVAP-GHS-033, EVAP-GHS-34, EVAP-GHS-38.							
Guillermo Hernandez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
114285					3/5/2014		91		\$0.00
Medium	Work In Progress				3/5/2014 3:35:45 PM				
Ambriz, Jose		Need to replace 1 down draft 6800 Evap cooler MCD-GHS-024 and 2 commercial Evap. cooler, side draft one wet section MCD-GHS-022 and MCD-GHS-023. on the kitchen roof.							
Guillermo Hernandez									
114193					3/4/2014		92		\$0.00
Medium	Work In Progress				3/4/2014 7:55:41 AM				
Ambriz, Jose		Need to replace Damper Actuator to RTU #62 at the North building.							
Guillermo Hernandez									
114962					3/24/2014		72		\$0.00
Medium	Work In Progress				3/24/2014 3:37:22 PM				
Ambriz, Jose		Need to replace gaskets to water supplylines on the boiler room for the heating system on the Old English building.							
Guillermo Hernandez									
107034					9/3/2013		274		\$0.00
Medium	Work In Progress				9/3/2013 3:52:55 PM				
Ambriz, Jose		Need to replace exhaust fan motors in the weight room (Jose has sample motor).							
Guillermo Hernandez									
117683					5/30/2014		5		\$0.00
Medium	Work In Progress				5/30/2014 2:48:34 PM				
Ontiveros, Guadalupe		Haas Road - There are weeds along the fence that need to be cut and trash that needs to be thrown.							
Alfredo Holguin									
115784					4/10/2014		55		\$0.00
Medium	Work In Progress				4/10/2014 7:42:52 AM				
Carbajal, Jimmy		I need at least 4 funnels so we can use them to put the liquid in to smaller bottles.							
Jaime Herrera									
117965					6/4/2014		0		\$0.00
Medium	Work In Progress				6/4/2014 8:41:21 AM				
Ontiveros, Guadalupe		Volleyball sand courts next to mobile home occupant need to be cleaned and refilled with sand.							
Richard Chavez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

113464					2/18/2014		106		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

High	Work In Progress				2/18/2014 7:54:48 AM				
------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose
Need to replace heating assembly to H/C unit for Portable #1. Carrier model CPHEATER051A00, SERIAL #4501G00017. (208/240/1HP/60HZ)

Guillermo Hernandez

106135					8/16/2013		292		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/16/2013 8:50:03 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Daniel
kitchen-ladies restroom – toilet, has a crack in the bottom. It is leaking out water and the exhaust does not work.

Maritza Gonzalez

115645					4/6/2014	4/27/2014	59		\$0.00
--------	--	--	--	--	----------	-----------	----	--	--------

Medium	Work In Progress				4/6/2014 12:32:27 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Orozco, Daniel
Monthly - Gadsden HS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

110536					11/22/2013		194		\$0.00
--------	--	--	--	--	------------	--	-----	--	--------

Medium	Work In Progress				11/22/2013 9:11:34 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Daniel
FLOOR LIFTED IN WALK IN REFRIGERATOR. SNP MANAGER FRANCES B. 882.5522

Maritza Gonzalez

109631					11/1/2013		215		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				11/1/2013 2:50:12 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Need assistance to repair hanging toilet, water is leaking behind the wall. Boys restroom Annex building.

Guillermo Hernandez

117350					5/20/2014		15		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/20/2014 3:59:39 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Please check gas line, by the weight room, rusted pipe on the clamp by the wall it is touching the ground and I'm afraid that could crack due to the rusted spot. (next to the A/C).

Guillermo Hernandez

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

117364 5/21/2014 14 \$0.00

Medium Work In Progress 5/21/2014 9:23:54 AM

Villalobos, David
 For Gadsden High School Locates needed
 Nearest Intersecting Street: WESTSIDE RD
 2nd Intersecting Street: WASHINGTON ST
 Subdivision:
 Latitude: 32.00034617 Longitude: -106.65685917
 Zip Code: 88027
 Township: 26S Range: 03E Section 1/4: 32 SE
 Should you have any questions please contact:
 Company: SMITH & AGUIRRE CONSTRUCTION
 Contact Name: FREDDIE TORRES
 Contact Phone: (575)527-2500
 Cell Phone: (575)642-6198
 Email: ftorres@runbox.com

Dominique Esparza

116451 5/1/2014 34 \$0.00

Medium Work In Progress 5/1/2014 8:11:00 AM

Carrasco, Danny
 Danny, Need to replace the broken socket set with
 Socket Set 5WHZ5 (grainger) a 4 ft. ladder and small
 pipe cutter.

Guillermo Hernandez

108987 10/16/2013 231 \$0.00

Medium Work In Progress 10/16/2013 4:12:21 PM

Villalobos, David
 Annex building in special ed classroom shower head is
 leaking needs to be replaced

Daniel Sotelo

108988 10/16/2013 231 \$0.00

Medium Work In Progress 10/16/2013 4:13:50 PM

Villalobos, David
 In weight room girls bathroom shower head is leaking
 needs to be replaced

Daniel Sotelo

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
117504					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 9:09:42 AM				
Villalobos, David		From fence to pole by old bus gate see e-mail for highlighted map area.....W1405231127280 FRM ANTHONY GO W ON WASHINGTON ST FOR 2.92MI TO AVENIDA DE MESILLA (NM-28). FROM THE INTERSECTION OF AVENIDA DE MESILLA & WASHINGTON ST. SPOT: 800' NORTH & 200' SOUTH WITH A WIDTH OF 75' WEST FOR FULL LENGTHS. Request by: TRIPLE J EXCAVATION Contact Name: ANNETTE GRANADO Contact Phone: (575)527-1763 FaxNo: (575)541-8136 Cell Phone: (575)644-6817 Email: annettetripelj@yahoo.com							
Dominique Esparza									
115464					4/4/2014		61		\$0.00
Medium	Work In Progress				4/4/2014 3:56:55 PM				
Villalobos, David		Need to replace gaskets on hanging toilets in the boys restroom and girls restroom at the Annex building.							
Guillermo Hernandez									
116444		Restroom			5/1/2014		34		\$0.00
Medium	Work In Progress				5/1/2014 7:32:00 AM				
Villalobos, David		In the Annex building in the boys restroom the toilet leaks on the bottom. Also in the girls restroom in the center stall the toilet also leaks when flushed.							
Jaime Herrera									
116620					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:26 AM				
Sotelo, Daniel		Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
116621					5/4/2014	6/4/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:26 AM				
Sotelo, Daniel		Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden HS							
116619					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:25 AM				
Sotelo, Daniel		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
116559					5/4/2014	5/7/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:37:43 AM				
Sotelo, Daniel		Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
117806					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:29 AM				
Sotelo, Daniel		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
117808					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:31 AM				
Sotelo, Daniel		Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
117807					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:30 AM				
Sotelo, Daniel		Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
117736					6/1/2014	6/4/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:44 AM				
Sotelo, Daniel		Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
115394					4/3/2014		62		\$0.00
Medium	Work In Progress				4/3/2014 10:50:56 AM				
Sotelo, Daniel		Requested by Mr. R. Ramos Rm. 617 New Science Building-Would like a shelf from old Science Storage Room to storage room in 617.							
Velia Alarcon									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS									
116174		Classroom			4/23/2014		42		\$0.00
Medium	Work In Progress	511			4/23/2014 3:14:24 PM				
Sotelo, Daniel Requested by Richie Santillano-Computer desks/tables nned to be assembled in Panther Hut room # 511. SEE MS. ANDERSON FOR LOCATION OF DESKS/TABLES.									
Velia Alarcon									
115392		Classroom			4/3/2014		62		\$0.00
Medium	Work In Progress	617			4/3/2014 10:47:38 AM				
Sotelo, Daniel Requested by Mr. R. Ramos Rm. 617 New Science Building-Need to have the U.S. and state flags put in classroom.									
Velia Alarcon									
117909					6/2/2014		2		\$0.00
Medium	Work In Progress				6/2/2014 3:52:34 PM				
Nunez, Arturo Requested by Cathy for Cafeteria-Abig National Guard banner needs to be hung in the cafeteria. PLEASE SEE CATHY FOR BANNER AND LOCATION TO BE HUNG.									
Velia Alarcon									
116518	North Building				5/2/2014		33		\$0.00
High	Work In Progress				5/2/2014 7:28:51 AM				
Sotelo, Daniel rm 210, there is a hole on the wall for a vent on the exterior wall that needs to be covered with a fine mesh screen.(rodents)									
Michael Munoz									
114854	Counselors				3/20/2014		76		\$0.00
Medium	Work In Progress				3/20/2014 11:14:59 AM				
Gonzalez, Salvador football field bleachers - Remove top bench including angle support and cover bottom opening on back rail with welded wire fabric/miners screen.									
Alfredo Holguin									
117587	Pool Dressing	Pool			5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 3:25:23 PM				
Lara, Ralph need to change out the key cylinders at pool dressing room lockers for opening day back to DC 20									
Mario Apodaca									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden HS									
117440	Pool Dressing	Pool			5/22/2014		13		\$0.00
Medium	Work In Progress				5/22/2014 1:21:31 PM				
Ambriz, Jose		need to replace water fountain on pool deck. the water holding tank is cracked and leaking thanks							
Daniel Sotelo									
117382	Pool Dressing	Pool			5/21/2014		14		\$0.00
Medium	Work In Progress				5/21/2014 3:24:37 PM				
Apodaca, Mario		GHS POOL Work need it done on punch list For pool inspector							
Mario Apodaca									
116788	Pool Dressing	Pool			5/6/2014		29		\$0.00
Medium	Work In Progress				5/6/2014 1:25:46 PM				
Villalobos, David		back flow preventer at GHS. pool room needs to be serviced							
Mario Apodaca									
115438	Pool Pump				4/4/2014		61		\$0.00
Medium	Work In Progress				4/4/2014 10:18:09 AM				
Hernandez, Guillermo		patch hole in roof on NW corner							
Alfredo Holguin									
117389	Pool Pump	Pool			5/21/2014		14		\$0.00
Medium	Work In Progress				5/21/2014 3:27:35 PM				
Apodaca, Mario		GHS pool chemical orders to stabilize pool water							
Mario Apodaca									
109016	Pool Pump	Pool			10/17/2013		230		\$0.00
Medium	Work In Progress				10/17/2013 3:10:55 PM				
Apodaca, Mario		need to order pool chemicals and equipment							
Mario Apodaca									
114774	Pool Pump	Pool			3/18/2014		78		\$0.00
Medium	Work In Progress				3/18/2014 3:06:20 PM				
Apodaca, Mario		Annual Pool Start-up; prepare pool for the summer program to include cleaning of pool & pump house & passing of pool inspection by NMED. Please provide copies of work order to both Mario & Raul Thanks							
Raul Sanchez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Gadsden HS									
114777	Pool Pump	Pool			3/18/2014		78		\$0.00
Medium	Work In Progress				3/18/2014 3:17:47 PM				
Apodaca, Mario		need to a new a pool lift seat to meet with the code complains for ada							
Mario Apodaca									
113083	Grounds Shop				2/6/2014		118		\$0.00
Medium	Work In Progress				2/6/2014 2:31:25 PM				
Solis, Lorenz		please order new ice machine and install. thank you							
Michael Munoz									
114853	Football Stadium				3/20/2014		76		\$0.00
Medium	Work In Progress				3/20/2014 11:11:32 AM				
Sotelo, Enrique		Press Box- Complete installation of electrical outlet in football field electrical vault.							
Alfredo Holguin									
Count: 135 Work Orders		Avg. Age of WO's 54			Total for Gadsden HS			0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
116164	Cafeteria	Cafeteria			4/23/2014		42		\$0.00
Medium	Work In Progress	Cafeteria			4/23/2014 12:27:37 PM				
Lara, Ralph		Pad lock at east cafeteria gate needs attention. not locking.							
Nancy Tinajero									
116465	Cafeteria	Cafeteria			5/1/2014		34		\$0.00
Medium	Work In Progress				5/1/2014 10:14:32 AM				
Sotelo, Enrique		Wall outlets are tripping breakers; we had a problem when electric grills and cooking equipment was being used for a food/science fair. Please see Mr. Mora							
Nancy Tinajero									
116777					5/6/2014		29		\$0.00
Medium	Work In Progress				5/6/2014 10:56:48 AM				
Aldaz, Bobby		as per meeting at site location please excavate on north end of bus turn around to locate storm drain pipe that use to drain in the drainage ditch.							
Michael Munoz									
117492		Office			5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 7:35:23 AM				
Gonzales, Camilo		Deliver 27 bxs. PO#131407381. Attn: Sylvia Moreno.							
Theresa Ramirez									
117303		Library			5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 7:46:44 AM				
Gonzales, Camilo		Pick up (19) obsolete items at the Library.							
Theresa Ramirez									
110842					12/4/2013		182		\$0.00
Medium	Work In Progress				12/4/2013 11:47:22 AM				
Villalobos, David		Need to check drain pipe on B wing thank you							
Sebastian Diaz									
117601					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 3:53:46 PM				
Carrasco, Danny		ATT Danny Need filters 20X20 X1 Need filters 20X30X1 thank you DANNY							
Sebastian Diaz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
115646					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress			4/6/2014 12:32:28 AM					
Orozco, Daniel	Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
116995					5/12/2014		23		\$0.00
Medium	Work In Progress			5/12/2014 10:15:13 AM					
Orozco, Daniel	WASHER IS ACTING UP , WONT CHANGE CYCLES AND RINSE AND SPIN. SNP MANAGER TERRY P. 882.2824								
Maritza Gonzalez									
117270					5/19/2014		16		\$0.00
Medium	Work In Progress	Baseball field		5/19/2014 1:54:25 PM					
Ontiveros, Guadalupe	Plant 6-9 trees along baseball field along with irrigation system. See Mr. Calleros for more info.								
Nancy Tinajero									
105924		Custodial			8/13/2013		295		\$0.00
Medium	Work In Progress			8/13/2013 12:53:11 PM					
Marquez, Gerardo	WE ALSO NEED AN EXTRA KEY MADE FOR OUR NIGHT CUSTODIAN THIS KEY IS FOR THE JOHN DEER GATOR								
Juan Acosta									
115826					4/13/2014	4/29/2014	52		\$0.00
Medium	Work In Progress			4/13/2014 12:24:12 AM					
Acosta, Juan	Monthly - QRTLY BLDG INSP REPORT (GM) - Refer to PM schedule details.								
Margret Villalobos									
113295					2/11/2014		113		\$0.00
Safety	Work In Progress			2/11/2014 4:15:31 PM					
Ontiveros, Guadalupe	Basketball Courts - need to put gravel around area.								
Michael Munoz									
117126		Athletic Field			5/14/2014		21		\$0.00
Medium	Work In Progress			5/14/2014 9:56:47 AM					
Ontiveros, Guadalupe	football field needs weed and feed. lots of weeds and no grass.								
Michael Munoz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

117326					5/20/2014		15		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Room 306			5/20/2014 2:51:42 PM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Marquez, Gerardo
Need to change room lock. As of now all employee keys open it.

Nancy Tinajero

117662					5/30/2014		5		\$0.00
--------	--	--	--	--	-----------	--	---	--	--------

Medium	Work In Progress	Room 305			5/30/2014 10:35:12 AM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Marquez, Gerardo
Re-key room 305 back to a WA152.

Nancy Tinajero

112252					1/17/2014		138		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/17/2014 3:49:17 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo
Need to check doors and replace for new on gym thank you

Sebastian Diaz

112198					1/16/2014		139		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/16/2014 3:04:51 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Marquez, Gerardo
Need to fix handicap doors around the entire school.

Nancy Tinajero

113867		Athletic Field			2/27/2014		97		\$0.00
--------	--	----------------	--	--	-----------	--	----	--	--------

High	Work In Progress				2/27/2014 11:26:14 AM				
------	------------------	--	--	--	-----------------------	--	--	--	--

Marquez, Gerardo
NURSES LOCKED KEYS IN THERE OFFICE. NEED A LOCKSMITH TO OPEN DR. ASAP. THANKS.

Juan Acosta

116083					4/22/2014		43		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/22/2014 8:54:35 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Att. David Need to unclog water fountain on B wing thank you

Sebastian Diaz

116891					5/8/2014		27		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/8/2014 12:18:32 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Sotelo, Enrique
Need to check motor on A/C gym thank you

Sebastian Diaz

117740					6/1/2014	7/2/2014	3		\$0.00
--------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				6/1/2014 12:53:47 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Diaz, Sebastian
Yearly - Gadsden MS B-2 Boiler Yearly - Refer to PM schedule details.

Margret Villalobos

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
117739					6/1/2014	6/4/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:46 AM				
Diaz, Sebastian		Monthly - Gadsden MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
117855					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:01 AM				
Diaz, Sebastian		Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
116790	Main Building	Classroom			5/6/2014		29		\$0.00
Medium	Work In Progress	Room 169			5/6/2014 2:16:09 PM				
Marquez, Gerardo		Need a door (full or half door) in room 169, sped room, going from classroom to the classroom restroom. See Mrs. Quinonez for information.							
Nancy Tinajero									
117670	Main Building				5/30/2014		5		\$0.00
Medium	Work In Progress	room 160			5/30/2014 12:14:50 PM				
Marquez, Gerardo		Please fix lock on beige file, it does not lock.							
Nancy Tinajero									
117563	Main Building				5/28/2014		7		\$0.00
Medium	Work In Progress	Front lobby			5/28/2014 8:54:07 AM				
Marquez, Gerardo		Front door lock does not work. Change core.							
Nancy Tinajero									
117062	Main Building	Classroom			5/13/2014		22		\$0.00
Medium	Work In Progress	room 113			5/13/2014 8:34:41 AM				
Diaz, Sebastian		Electrical outlet at entrance needs to be opened- has a cover over the outlet.							
Nancy Tinajero									
116464	Main Building	Classroom			5/1/2014		34		\$0.00
Medium	Work In Progress	All classrooms			5/1/2014 10:09:48 AM				
Diaz, Sebastian		Please paint B wing classrooms							
Nancy Tinajero									
117463	Annex	Classroom			5/23/2014		12		\$0.00
Medium	Work In Progress	Room 403			5/23/2014 10:14:45 AM				
Diaz, Sebastian		Please install a bulletin board to the right of the smart board if there are any available							
Nancy Tinajero									

6/4/2014 1:35:10 PM

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
117674	Annex	Classroom			5/30/2014		5		\$0.00
Medium	Work In Progress	Room 415			5/30/2014 1:14:12 PM				
Diaz, Sebastian		Put display cork board outside the classroom. (cork is in Mr. Callero's office)							
Nancy Tinajero									
117464	Annex	Classroom			5/23/2014		12		\$0.00
Medium	Work In Progress	Room 415			5/23/2014 10:19:13 AM				
Lara, Ralph		Locks on cabinets on wall are broken.							
Nancy Tinajero									
106140	Annex	Restroom			8/16/2013		292		\$0.00
Medium	Work In Progress	STAFF			8/16/2013 10:16:55 AM				
Marquez, Gerardo		CAN NOT OPEN DOOR WITH KEY A.S.A.P							
Juan Acosta									
117465	Annex	Classroom			5/23/2014		12		\$0.00
Medium	Work In Progress	Room 405			5/23/2014 10:21:11 AM				
Estrada, Jesus		Please fixtiles on floor that are broken and coming off.							
Nancy Tinajero									
117368	Annex				5/21/2014		14		\$0.00
Medium	Work In Progress	room 400			5/21/2014 11:07:53 AM				
Marquez, Gerardo		Make the lock/key of room 400 universal							
Nancy Tinajero									
116401	Annex	Classroom			4/30/2014		35		\$0.00
Medium	Work In Progress	Annex new			4/30/2014 8:09:05 AM				
Marquez, Gerardo		Door closer is leaking oil and has lost pressure. Door slams shut with wind. Replace door closer.							
Nancy Tinajero									
117432	Vocational	Classroom			5/22/2014		13		\$0.00
Medium	Work In Progress	room 306			5/22/2014 10:39:08 AM				
Marquez, Gerardo		Door in-between 306 and 307 does not lock.							
Nancy Tinajero									
112197	Vocational				1/16/2014		139		\$0.00
Medium	Work In Progress	Room 306			1/16/2014 3:03:38 PM				
Marquez, Gerardo		Cylinder on lock to cage is not working.							
Nancy Tinajero									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
117669	Vocational	Kitchen			5/30/2014		5		\$0.00
Medium	Work In Progress	Room 301			5/30/2014 11:50:20 AM				
Sotelo, Enrique Electrical short on refrigerator cord in home ec kitchen									
Nancy Tinajero									
117564	Vocational	Classroom			5/28/2014		7		\$0.00
Medium	Work In Progress	room 306/307			5/28/2014 8:58:47 AM				
Marquez, Gerardo The adjoining door between room 306 and 307 needs to lock from both sides.									
Nancy Tinajero									
117002	Vocational				5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 11:05:11 AM				
Villalobos, David Room 305 -remove sink, water and sewer lines and cap below grade for new flooring.									
Michael Munoz									
112592	Gymnasium	Gym			1/29/2014		126		\$0.00
Medium	Work In Progress	Gym Lobby			1/29/2014 11:38:45 AM				
Solis, Lorenzø Please fix heater in gym lobby it is not working.									
Nancy Tinajero									
113306	C-Wing	Parking Lot			2/12/2014		112		\$0.00
Medium	Work In Progress				2/12/2014 8:14:59 AM				
Villalobos, David Constant flow on fire protection bfp, have continuously taken oput debris from unit.									
David Villalobos									
113296	C-Wing				2/11/2014		113		\$0.00
Medium	Work In Progress				2/11/2014 4:16:55 PM				
Villalobos, David Old Central Office - Need to replace all plumbing fixtures to include commode in Main Lobby.									
Michael Munoz									
117084	C-Wing				5/13/2014		22		\$0.00
Medium	Work In Progress	Old Charter			5/13/2014 2:02:58 PM				
Holguin, Alfredo Need clear out offices for floor abatement.									
Alfredo Holguin									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden MS

116707	C-Wing				5/5/2014		30		\$0.00
--------	--------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress				5/5/2014 10:29:13 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Moncayo, Fernando
A chair for Cynthia Maes is located at GAC is stored in Jorge Ortega office's C wing 209. The chair is maroon and needs to be moved here to GMS C wing transportation portable.

Lisa Sanchez

116086	C-Wing				4/22/2014		43		\$0.00
--------	--------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/22/2014 9:03:04 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David
Att. David Villalobos, please raise the water spickets for water hose in front of c wing to water grass area. Thank you!

Sebastian Diaz

114383	C-Wing				3/7/2014		89		\$0.00
--------	--------	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	(Old Central			3/7/2014 2:44:21 PM				
--------	------------------	--------------	--	--	---------------------	--	--	--	--

Solis, Lorenzo
Need to check unit at thank you

Sebastian Diaz

114848	C-Wing	Exterior			3/20/2014		76		\$0.00
--------	--------	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	207-c			3/20/2014 10:19:41 AM				
--------	------------------	-------	--	--	-----------------------	--	--	--	--

Ontiveros, Guadalupe
Our compound would appreciate a shade tree planted where the old palm tree that died was. Thank you , Colleen

Colleen Runyan

111358	C-Wing				12/17/2013		169		\$0.00
--------	--------	--	--	--	------------	--	-----	--	--------

Safety	Work In Progress				12/17/2013 12:21:17				
--------	------------------	--	--	--	---------------------	--	--	--	--

Diaz, Sebastian
All Portable Ramps at C-Wing - Asp Mr. Chavez he wants all ramps replaced w/new boards. Please see him.

Richard Chavez

114618	C-Wing	Portables			3/13/2014		83		\$0.00
--------	--------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/13/2014 3:30:27 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Diaz, Sebastian
gutter is missing in back to athletic and chavez portable. wall is exposed. please install new ones. see mike for details. thank you

Michael Munoz

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
116916	C-Wing	Portables			5/8/2014		27		\$0.00
Medium	Work In Progress	COMPUTER			5/8/2014 3:52:38 PM				
Diaz, Sebastian									
LIGHTS NEED TO BE REPLACE IN THE LADIES BATHROOM IN THE COMPUTER AREA PORTABLE.									
THANK YOU, TERRY									
Terry Alvarado									
117186	Gym				5/15/2014		20		\$0.00
Medium	Work In Progress	Storage room			5/15/2014 12:52:28 PM				
Diaz, Sebastian									
Built a loft in storage room in gym. See Mr. Calleros for more information.									
Nancy Tinajero									
117879	Gym	Gym			6/2/2014		2		\$0.00
Medium	Work In Progress	Terry - Athletics			6/2/2014 9:47:16 AM				
Diaz, Sebastian									
The Athletic Dept. would like to request that the air conditioner be checked at GMS Gym and Gym Lobby. The YMCA will be hosting the Elementary Basketball games this summer and this past weekend it was very hot! Thank you for all your help!									
SEBASTIAN, PLEASE SEE MIKE ON THIS WORK ORDER									
Terry Alvarado									
116703	Gym	Athletic Field			5/5/2014		30		\$0.00
Medium	Work In Progress				5/5/2014 8:47:55 AM				
Gonzalez, Salvador									
as per conversation please fabricate 2 new batting cages. thank you (baseball field)									
Michael Munoz									
112116	Gym	Dressing Room			1/15/2014		140		\$0.00
Medium	Work In Progress				1/15/2014 6:44:11 AM				
Solis, Lorenzo									
please replace existing heating coils with new modern ones.(boys and girls)									
Michael Munoz									
112117	Gym	Dressing Room			1/15/2014		140		\$0.00
High	Work In Progress				1/15/2014 6:46:31 AM				
Solis, Lorenzo									
p.e teacher mentioned that there was no cooling in dressing rooms. please check, also check for a vent relief. thank you									
Michael Munoz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Gadsden MS									
112149	Gym	Mechanical			1/15/2014		140		\$0.00
Medium	Work In Progress			1/15/2014 3:28:01 PM					
Solis, Lorenzo	need to replace old Bryant boiler with new raypac. to include new piping, valves and 2 new motors								
Michael Munoz									
116883	Gym				5/8/2014		27		\$0.00
Medium	Work In Progress			5/8/2014 9:59:37 AM					
Marquez, Gerardo	Please replace doors to mechanical room, to include vents.								
Michael Munoz									
117147	Gym				5/14/2014		21		\$0.00
Medium	Work In Progress			5/14/2014 2:08:12 PM					
Holguin, Alfredo	PE Dressing Rooms - Replacement of lockers in Boy & Girls.								
Alfredo Holguin									
117833					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:47 AM					
Diaz, Sebastian	Monthly - Gadsden MS - Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
117837					6/1/2014		3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:50 AM					
Diaz, Sebastian	Monthly - Gadsden MS - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
117835					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:49 AM					
Diaz, Sebastian	Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
117836					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:49 AM					
Diaz, Sebastian	Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
117163					5/14/2014		21		\$0.00
Medium	Work In Progress				5/14/2014 3:47:16 PM				
Diaz, Sebastian		5/14/14				5/14/14 - 8 hrs			
		8-continous remove chalkboard on B wing and paint paint							
Sebastian Diaz									
117064					5/13/2014		22		\$0.00
Medium	Work In Progress	Gate behind			5/13/2014 8:45:12 AM				
Diaz, Sebastian		The wheels on the gate behind cafeteria (bus turn around entrance) are falling off.							
Nancy Tinajero									
117195					5/15/2014		20		\$0.00
Medium	Work In Progress				5/15/2014 3:30:29 PM				
Diaz, Sebastian		Need to remove and reinstall chalkboard on rooms B wing thank you							
Sebastian Diaz									
116565					5/4/2014	5/20/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:37:47 AM				
Villalobos, Margret		Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details.				Emailed 5/5/14			
Margret Villalobos									
117756					6/1/2014	6/17/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:57 AM				
Villalobos, Margret		Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details.							
Margret Villalobos									
114933		Gym			3/21/2014		75		\$0.00
Medium	Work In Progress				3/21/2014 4:18:31 PM				
Munoz, Michael		PM - Annual Bleacher Service performed by A.K. Sales.							
Michael Munoz									
114537					3/11/2014		85		\$0.00
Medium	Work In Progress				3/11/2014 4:10:58 PM				
Flores, Pete		VEHICLE 150(MR. BAKER) FLASHER/BLINKER NOT WORKING. WILL BE AVAILABLE MARCH 20-28.							
Maritza Gonzalez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Gadsden MS							
116007					4/16/2014		49		\$0.00
Medium	Work In Progress				4/16/2014 3:06:37 PM				
Lara, Ralph		Need to open custodial door for Mario.							
Michael Munoz									
115755					4/9/2014		56		\$0.00
Medium	Work In Progress				4/9/2014 1:33:28 PM				
Estrada, Jesus		GYM FLOOR NEED TO BE REFINISHED							
Juan Acosta									
117842					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:53 AM				
Apodaca, Mario		Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
116760					5/6/2014		29		\$0.00
Medium	Work In Progress				5/6/2014 12:38:17 AM				
Apodaca, Mario		Monthly - Gadsden MS - Domestic Water Filters - Refer to PM schedule details.							
Margret Villalobos									
116387					4/30/2014		35		\$0.00
Medium	Work In Progress				4/30/2014 1:01:10 AM				
Apodaca, Mario		Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
117841					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:52 AM				
Apodaca, Mario		Monthly - Gadsden MS - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
114431					3/10/2014		86		\$0.00
Medium	Work In Progress				3/10/2014 8:54:19 AM				
Solis, Lorenzo		On boiler cafeteria need to check water pump thank you							
Sebastian Diaz									
114432					3/10/2014		86		\$0.00
Medium	Work In Progress				3/10/2014 8:58:01 AM				
Solis, Lorenzo		On boiler east need to replace circulate pump thank you							
Sebastian Diaz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Gadsden MS									
117884					6/2/2014		2		\$0.00
Medium	Work In Progress				6/2/2014 10:07:57 AM				
Solis, Lorenzo		CHILLERS NOT WORKING							
Michael Munoz									
116643					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:41 AM				
Apodaca, Mario		Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
116325					4/28/2014		37		\$0.00
Medium	Work In Progress				4/28/2014 3:18:54 PM				
Apodaca, Mario		Maintenance will need to do the following on Friday May 2 before 4 pm:							
		- close off all water fountains in the affected buildings							
		- Post notice on all sinks that water is not potable							
Alfredo Holguin									
Count: 82 Work Orders			Avg. Age of WO's	50		Total for Gadsden MS	0		\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union - JTP Alvarez Farms									
112573					1/29/2014		126		\$0.00
Medium	Work In Progress				1/29/2014 8:24:23 AM				
Aguilar, Patricio		big toy in playground in bad need of repair. slide cracked bys un age - step broken and rust - taped with caution tape				1/31-Route back to Pat asp Mike			
Patricio Aguilar									
113118					2/7/2014		117		\$0.00
Medium	Work In Progress				2/7/2014 8:52:39 AM				
Aguilar, Patricio		wo to myself - need gopher pellets for playground							
Patricio Aguilar									
Count: 2 Work Orders			Avg. Age of WO's	122		Total for La Union - JTP Alvarez Farms	0		\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location:		La Union ES							
116657					5/4/2014	5/10/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:50 AM				
Aguilar, Patricio		Monthly - La Union ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
116984					5/11/2014	5/27/2014	24		\$0.00
Medium	Work In Progress				5/11/2014 12:24:50 AM				
Aguilar, Patricio		Monthly - La Union ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
116594					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:08 AM				
Aguilar, Patricio		Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
116592					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:07 AM				
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
116593					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:07 AM				
Aguilar, Patricio		Monthly - La Union ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
117858					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:03 AM				
Aguilar, Patricio		Monthly - La Union ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
117830					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:46 AM				
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

Location: La Union ES

117831 6/1/2014 6/9/2014 3 \$0.00

Medium Work In Progress 6/1/2014 12:54:46 AM

Aguilar, Patricio Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

117829 6/1/2014 3 \$0.00

Medium Work In Progress 6/1/2014 12:54:45 AM

Aguilar, Patricio Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

117741 6/1/2014 7/2/2014 3 \$0.00

Medium Work In Progress 6/1/2014 12:53:48 AM

Aguilar, Patricio Yearly - La Union ES B-2 Boiler Yearly - Refer to PM schedule details.

Margret Villalobos

117217 5/16/2014 19 \$0.00

Medium Work In Progress 5/16/2014 10:09:17 AM

Aguilar, Patricio wo to myself - summer project - paint gym - paint hallway new wing - class room annex build

Patricio Aguilar

114649 3/14/2014 82 \$0.00

Medium Work In Progress 3/14/2014 1:04:54 PM

Aguilar, Patricio wo to myself - slide cracked by sum age - step broken and rusted - putting in order to warehouse for parts

Patricio Aguilar

116769 5/6/2014 29 \$0.00

Medium Work In Progress 5/6/2014 8:21:52 AM

Ronquillo, Ruben SERVICE TO REPLACE BROKEN PLAYGROUND EQUIP. WE WILL SUPPLY WITH NEW EQUIP. THANK YOU!

Ruben Ronquillo

116395 4/30/2014 35 \$0.00

Medium Work In Progress 4/30/2014 1:01:40 AM

Sanchez, Raul Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details.

Margret Villalobos

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: La Union ES									
117570	Main Building	Cafeteria			5/28/2014		7		\$0.00
Medium	Work In Progress			5/28/2014 10:32:33 AM					
Aguilar, Patricio	Request from Mr. Sanchez: Clean cafeteria walls and repaint								
Virginia Galindo									
117571	Main Building	Cafeteria			5/28/2014		7		\$0.00
Medium	Work In Progress			5/28/2014 10:37:02 AM					
Aguilar, Patricio	Request from Mr. Sanchez: Clean green sound acoustic panels in the cafeteria. Clean front and back of panels. Thank You.								
Virginia Galindo									
117574	2000 Core	Office			5/28/2014		7		\$0.00
Medium	Work In Progress			5/28/2014 11:12:12 AM					
Ambriz, Jose	Request from Mr. Sanchez: Replace non working thermostats in the front office and classrooms.								
Virginia Galindo									
114151					3/3/2014		93		\$0.00
Medium	Work In Progress			3/3/2014 10:48:17 AM					
Ontiveros, Guadalupe	need the use of a utility tractor with loader - rear blade for the fare back yard thanks for the help.								
Patricio Aguilar									
116929					5/9/2014		26		\$0.00
Medium	Work In Progress			5/9/2014 9:14:58 AM					
Orozco, Daniel	GARBAGE DISPOSAL IS NOT WORKING. SNP MANAGER LINDA Y. 589.2040								
Maritza Gonzalez									
115647					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress			4/6/2014 12:32:28 AM					
Orozco, Daniel	Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
117320					5/20/2014		15		\$0.00
Medium	Work In Progress			5/20/2014 12:23:58 PM					
Carrasco, Danny	need 5gal diesel for mower 935 - thank you for your help								
Patricio Aguilar									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: La Union ES									
117321					5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 12:26:34 PM				
Carrasco, Danny		need 5gal gas for mower 400 - thank you for you help.							
Patricio Aguilar									
116013					4/16/2014		49		\$0.00
Medium	Work In Progress				4/16/2014 3:17:49 PM				
Castillo, Carlos		need to move elect outlet up the wall to plug in a infocus - thank you for your help							
Patricio Aguilar									
113253					2/11/2014		113		\$0.00
Medium	Work In Progress				2/11/2014 8:57:03 AM				
Holguin, Alfredo		changing sand with wood fiber 3 areas 1 - back playground toy 50' x 70' with border need replace 4 2 - back playground swing set 20' x 60' has no borders 3 - courtyard toy 50' x 60' with border need replace 14							
Patricio Aguilar									
Count: 24 Work Orders		Avg. Age of WO's		30	Total for La Union ES			0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
113304					2/12/2014		112		\$0.00
Medium	Work In Progress				2/12/2014 8:06:11 AM				
Holguin, Alfredo		need to replace sand with woodchips on primary playground and replace 12 borders							
Eric Medina									
113305					2/12/2014		112		\$0.00
Medium	Work In Progress				2/12/2014 8:08:01 AM				
Holguin, Alfredo		need to replace sand with woodchips in secondary playground and replace 6 borders							
Eric Medina									
117573					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 10:57:45 AM				
Carrasco, Danny		need to replace tools that were stolen							
Eric Medina									
115648					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:29 AM				
Orozco, Daniel		Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
115172					3/28/2014		68		\$0.00
Medium	Work In Progress				3/28/2014 3:11:32 PM				
Orozco, Daniel		AS PER ECO LAB - VACUUM BREAKER AND FINAL RINSE JETS NEED TO BE REPLACED ON THE DISHWASHER.							
Maritza Gonzalez									
114506					3/11/2014		85		\$0.00
Medium	Work In Progress				3/11/2014 3:05:49 PM				
Orozco, Daniel		The drain from the ice maker is not draining and is full please advice.							
Maritza Gonzalez									
117337					5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 3:35:24 PM				
Orozco, Daniel		The drain where the washing machine is at the water is not going down. SNP Manager Dolores R. 882.4707							
Maritza Gonzalez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
117358					5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 8:00:54 PM				
Ontiveros, Guadalupe		need to replace sprinkler control box							
Eric Medina									
117677		Hallway/Corridor			5/30/2014		5		\$0.00
Medium	Work In Progress				5/30/2014 1:43:37 PM				
Marquez, Gerardo		Unable to open door with key, key is getting stuck. Main door to the big playground needs to be checked.							
Angie Flores									
117678					5/30/2014		5		\$0.00
Medium	Work In Progress				5/30/2014 2:18:00 PM				
Marquez, Gerardo		need to check cylinder for lock on west side entrance							
Eric Medina									
117632		Classroom			5/29/2014		6		\$0.00
Medium	Work In Progress	Ryan & Moralez			5/29/2014 11:00:57 AM				
Marquez, Gerardo		Please check doors in both classrooms, doors do not close right they are fallen							
Angie Flores									
115930					4/15/2014		50		\$0.00
Medium	Work In Progress				4/15/2014 12:33:10 PM				
Marquez, Gerardo		need emoulium replaced on east entrance							
Eric Medina									
112542					1/28/2014		127		\$0.00
Medium	Work In Progress				1/28/2014 3:27:25 PM				
Sotelo, Enrique		need 6 pole light bulbs replaced							
Eric Medina									
117379					5/21/2014		14		\$0.00
Medium	Work In Progress				5/21/2014 3:13:54 PM				
Villalobos, David		need to request snake having trouble with sink in faculty rr							
Eric Medina									
117413					5/22/2014		13		\$0.00
Medium	Work In Progress				5/22/2014 7:23:37 AM				
Medina, Eric		please paint all exterior doors inside and out. thank you							
Michael Munoz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Loma Linda ES							
117414					5/22/2014		13		\$0.00
Medium	Work In Progress				5/22/2014 7:25:31 AM				
Medina, Eric		please remove dirt/sand in turnaround parking lot.							
Michael Munoz									
117415					5/22/2014		13		\$0.00
Medium	Work In Progress				5/22/2014 7:27:45 AM				
Medina, Eric		please clean and repair fence and gates to mobile area. good place to place truck. prevention of vandalism. thank you							
Michael Munoz									
117589					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 3:30:21 PM				
Medina, Eric		1. check school and check in with office 3. cut top half of field 3. worked on wo# 117413				5/28/14 - 5 hrs			
1. enter data									
Eric Medina									
117866					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:08 AM				
Medina, Eric		Monthly - Loma Linda ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
117763					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:02 AM				
Medina, Eric		Yearly - Loma Linda ES B2 (Boiler)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									
117777					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:11 AM				
Medina, Eric		Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
117775					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:10 AM				
Medina, Eric		Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Loma Linda ES							
117774					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:09 AM				
Medina, Eric		Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
116977					5/11/2014	5/27/2014	24		\$0.00
Medium	Work In Progress				5/11/2014 12:24:45 AM				
Medina, Eric		Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
116896		Classroom			5/8/2014		27		\$0.00
Medium	Work In Progress	Computer Lab			5/8/2014 2:49:38 PM				
Medina, Eric		The light fixture over my desk is "out" and the other fixtures are still not working. The computer lab is too dark. Last work order submitted on 3/10/14.							
Angie Flores									
115405					4/3/2014		62		\$0.00
Medium	Work In Progress				4/3/2014 2:54:47 PM				
Medina, Eric		need to weed and feed all fields at alamo also							
Eric Medina									
114380					3/7/2014		89		\$0.00
Medium	Work In Progress				3/7/2014 12:38:08 PM				
Medina, Eric		Need to replace basketball goals							
Eric Medina									
106797	Main Building	Restroom			8/30/2013		278		\$0.00
Medium	Work In Progress	In Front of Mrs.			8/30/2013 10:48:44 AM				
Marquez, Gerardo		Stall doors in the boys restroom in front of Mrs. Whites room dont lock							
Angie Flores									
117013	Main Building	Hallway/Corridor			5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 12:52:32 PM				
Medina, Eric		paint 7th grade hallway							
Eric Medina									
117009	Main Building	Office			5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 12:38:56 PM				
Medina, Eric		need to paint entire office							
Eric Medina									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Loma Linda ES							
117063	Main Building	Classroom			5/13/2014		22		\$0.00
Medium	Work In Progress	215			5/13/2014 8:44:35 AM				
Medina, Eric		Blinds broke and fell (need replacement) Remove Large storage cabinet from myclassroom							
Angie Flores									
113003	Main Building	Classroom			2/5/2014		119		\$0.00
Medium	Work In Progress	108			2/5/2014 8:45:45 AM				
Medina, Eric		Blinds will not open or close "both"							
Angie Flores									
117015	Main Building				5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 12:57:49 PM				
Medina, Eric		replace ballast throughout corridors (all)							
Eric Medina									
115238	Main Building	Classroom			3/31/2014		65		\$0.00
Medium	Work In Progress	204			3/31/2014 12:57:29 PM				
Medina, Eric		Light is turning on/off consequently							
Angie Flores									
114445	Main Building	Classroom			3/10/2014		86		\$0.00
Medium	Work In Progress	Computer Lab			3/10/2014 2:15:19 PM				
Medina, Eric		Three light fixtures in the computer lab are still not working and need to be repaired or replaced.							
Angie Flores									
117010	Main Building	Classroom			5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 12:43:23 PM				
Medina, Eric		paint rm 111							
Eric Medina									
117011	Main Building	Classroom			5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 12:45:03 PM				
Medina, Eric		paint rm 107							
Eric Medina									
117012	Main Building	Classroom			5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 12:50:21 PM				
Medina, Eric		paint rm 110							
Eric Medina									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
117631	Main Building	Gym			5/29/2014		6		\$0.00
Medium	Work In Progress	Stage			5/29/2014 10:59:59 AM				
Marquez, Gerardo		Doors under the stage do not close right, please check.							
Angie Flores									
108825	Main Building				10/14/2013		233		\$0.00
Medium	Work In Progress	Nurses Office			10/14/2013 11:36:02				
Marquez, Gerardo		New Lock for Large Medicine Cabinet							
Angie Flores									
117676	Main Building	Restroom			5/30/2014		5		\$0.00
Medium	Work In Progress				5/30/2014 1:40:54 PM				
Marquez, Gerardo		Womens bathroom in the 200 hall has a hard time being opened with key							
Angie Flores									
117634	Main Building	Portables			5/29/2014		6		\$0.00
Medium	Work In Progress	Anderson			5/29/2014 11:02:26 AM				
Marquez, Gerardo		The key gets stuck when trying to lock or unlock. Please check.							
Angie Flores									
117940	Main Building	Office			6/3/2014		1		\$0.00
Medium	Work In Progress				6/3/2014 3:07:07 PM				
Gonzales, Camilo		Deliver 19 bxs. Math K-6th Eng/Span Workbooks.							
Theresa Ramirez									
114381					3/7/2014		89		\$0.00
Medium	Work In Progress				3/7/2014 12:39:29 PM				
Gonzalez, Salvador		Sal need to lower two basketball goals to six feet							
Eric Medina									
117505					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 9:41:40 AM				
Gonzalez, Salvador		sal need to repair fence on home occupant area							
Eric Medina									
106474					8/23/2013		285		\$0.00
Medium	Work In Progress				8/23/2013 3:28:34 PM				
Gonzalez, Salvador		Chava need a square drag for loma linda thank you							
Eric Medina									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Loma Linda ES									
117357					5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 7:59:12 PM				
Ronquillo, Ruben		need to replace broken glass pains in portable 3 and portable 4. total seven windows case# 201400394							
Eric Medina									
115662					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:39 AM				
Munoz, Michael		Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PMs schedule details.							
Margret Villalobos									
115307					4/1/2014		64		\$0.00
Medium	Work In Progress				4/1/2014 3:07:24 PM				
Flores, Pete		Pete need to request gator							
Eric Medina									
117356					5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 7:56:43 PM				
Flores, Pete		need to replace broken out windows and windshield on truck #31 case# 201400394							
Eric Medina									
117272					5/19/2014		16		\$0.00
Medium	Work In Progress				5/19/2014 2:28:32 PM				
Solis, Lorenzo		need to check a/c in band portable							
Eric Medina									
116761					5/6/2014		29		\$0.00
Medium	Work In Progress				5/6/2014 12:38:18 AM				
Apodaca, Mario		Monthly - Loma Linda ES - Domestic Water Filters - Refer to PMs schedule details.							
Margret Villalobos									
Count: 52 Work Orders			Avg. Age of WO's 48			Total for Loma Linda ES	0		\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
116647					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:43 AM				
Apodaca, Mario		Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
116759					5/6/2014		29		\$0.00
Medium	Work In Progress				5/6/2014 12:38:16 AM				
Apodaca, Mario		Monthly - Mesquite ES - Domestic Water Filter - Refer to PM schedule details.							
Margret Villalobos									
117846					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:55 AM				
Apodaca, Mario		Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
117682					5/30/2014		5		\$0.00
Medium	Work In Progress				5/30/2014 2:47:24 PM				
Apodaca, Mario		irrigation well is not working.							
Joe Ramirez									
116243		Cafeteria			4/25/2014		40		\$0.00
Medium	Work In Progress				4/25/2014 7:59:15 AM				
Ramirez, Joe		please we have few cafeteria tables the are broken the are not good.							
		thank you							
Luis Saucedo									
116453					5/1/2014		34		\$0.00
Medium	Work In Progress				5/1/2014 8:28:42 AM				
Ramirez, Joe		need to repaint 100 wing							
Joe Ramirez									
116454					5/1/2014		34		\$0.00
Medium	Work In Progress				5/1/2014 8:30:01 AM				
Ramirez, Joe		need to replace covebase 100 wing.							
Joe Ramirez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Mesquite ES									
117744					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:50 AM				
Ramirez, Joe	Yearly - Mesquite ES B-2 Boiler Yearly - Refer to PM schedule details.								
Margret Villalobos									
117738					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:46 AM				
Ramirez, Joe	Monthly - Mesquite ES - Barrack Drainage (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
117853					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:00 AM				
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
117819					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:39 AM				
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
117820					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:39 AM				
Ramirez, Joe	Monthly - Mesquite ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
117818					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:38 AM				
Ramirez, Joe	Monthly - Mesquite ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
115102		Computer Lab			3/27/2014		69		\$0.00
Medium	Work In Progress				3/27/2014 8:58:31 AM				
Estrada, Jesus	Mr. Estrada, On the computer lab the carpet is torn out need new carpet. If you have a chance, could you please stop by and see it. Thank you								
Luis Saucedo									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
117080		Custodial			5/13/2014		22		\$0.00
Medium	Work In Progress				5/13/2014 12:42:37 PM				
Flores, Pete		Gas Blower #1032 Is losing power while working.				5/13/14 - ROUTE TO PETE ASP JIMMY			
		thank you							
Luis Saucedo									
117637					5/29/2014		6		\$0.00
Medium	Work In Progress				5/29/2014 2:19:27 PM				
Ronquillo, Ruben		need to replace broken window 45 3/4 x 16 3/4 safety glass slightly tinted eastside entrance door.							
Joe Ramirez									
117558					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 7:55:26 AM				
Saucedo, Luis		NEED TO SCRUB WALLS IN PORTABLE 601							
Jesus Estrada									
116850	Main Building	Office			5/7/2014		28		\$0.00
Medium	Work In Progress				5/7/2014 3:00:17 PM				
Ramirez, Joe		Pick up (18) obsolete items.							
Theresa Ramirez									
116702	Main Building	Office			5/5/2014		30		\$0.00
Medium	Work In Progress				5/5/2014 8:33:06 AM				
Ramirez, Joe		Pick up 18 obsolete items. See Mr Moreno.							
Theresa Ramirez									
117276	2003 Classroom				5/19/2014		16		\$0.00
Medium	Work In Progress	Room # 304			5/19/2014 3:09:38 PM				
Marquez, Gerardo		Graciela Moreno/Kinder teacher lost her key to room # 304, she is unable to find it, so we were asked to submit a workorder. For for lost key. Thank you							
Sandra Mora									
105671					8/8/2013		300		\$0.00
Medium	Work In Progress				8/8/2013 1:03:55 PM				
Marquez, Gerardo		door and door jamb for rm.608 needs to be replaced it is in really bad shape.							
Joe Ramirez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Mesquite ES									
115649					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:30 AM				
Orozco, Daniel		Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
114313					3/6/2014		90		\$0.00
Medium	Work In Progress				3/6/2014 7:58:27 AM				
Villalobos, David		need to replace 4 sensor activated lavatories in 2 bathrooms they are not working properly.							
Joe Ramirez									
113366					2/13/2014		111		\$0.00
Medium	Work In Progress				2/13/2014 9:52:19 AM				
Holguin, Alfredo		need 3 sand play areas replaced with engineered wood fiber. area 2 needs 62 pieces of border replaced							
Joe Ramirez									
111219					12/12/2013		174		\$0.00
Medium	Work In Progress				12/12/2013 3:32:59 PM				
Holguin, Alfredo		Demo - Remove septic tank and electrical							
Alfredo Holguin									
Count: 25 Work Orders		Avg. Age of WO's 44		Total for Mesquite ES		0		\$0.00	

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
113536					2/19/2014		105		\$0.00
Medium	Work In Progress				2/19/2014 11:44:10 AM				
Holguin, Alfredo		have (3ea)sand boxsections need sand removed and fill w/wood chips (borders are all good)							
Danny Vega									
114700					3/17/2014		79		\$0.00
Medium	Work In Progress				3/17/2014 11:13:53 AM				
Villalobos, David		boilers that feeds kitchen is leaking .cant exactlysee from where but it looks like relief valve is bad							
Danny Vega									
116800					5/6/2014		29		\$0.00
Medium	Work In Progress				5/6/2014 3:38:31 PM				
Carrasco, Danny		(attention DannyC) -need scissor lift to replace lamps in gym and bring p.e equipment down from ceiling							
Danny Vega									
111035		Office			12/9/2013		177		\$0.00
Medium	Work In Progress	nurses office m			12/9/2013 11:08:57 AM				
Marquez, Gerardo		Please send locksmith, we have purchased 2 new locks for our medicine cabinet that need to be installed.							
Priscilla Martinez									
114148					3/3/2014		93		\$0.00
Medium	Work In Progress				3/3/2014 10:16:02 AM				
Ontiveros, Guadalupe		Attention Lupe o-/need fertilzer on grass field(weed and feed type)had alot of weed spread out last year /never gave grass a chance to grow its starting come back.APPRX 40 SACKS							
Danny Vega									
115637					4/6/2014		59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:22 AM				
Orozco, Daniel		Monthly - North Valley ES - Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									
116975					5/11/2014	5/27/2014	24		\$0.00
Medium	Work In Progress				5/11/2014 12:24:43 AM				
Vega, Danny		Monthly - North Valley ES Playground Inspection - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		North Valley ES							
117785					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:16 AM				
Vega, Danny		Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
117783					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:15 AM				
Vega, Danny		Monthly - North Valley ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
117761					6/1/2014	6/22/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:00 AM				
Vega, Danny		Monthly - North Valley ES H11(E.Heat)(S.Annual) - Refer to PM schedule details.							
Margret Villalobos									
117865					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:08 AM				
Vega, Danny		Monthly - North Valley ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
115386					4/3/2014		62		\$0.00
Medium	Work In Progress				4/3/2014 8:39:42 AM				
Vega, Danny		need to paint parking lot stripes and handi-cap parkings/west parking lot							
Danny Vega									
114916					3/21/2014		75		\$0.00
Medium	Work In Progress				3/21/2014 3:43:59 PM				
Vega, Danny		3-21-14				3/21			
		1-ck heat pumps at nve							
		7-wk od#112356 total \$230.00							
Danny Vega									
117228					5/16/2014		19		\$0.00
Medium	Work In Progress				5/16/2014 2:22:23 PM				
Vega, Danny		piant classrms and extirior doors at nve							
Danny Vega									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: North Valley ES									
116762					5/6/2014		29		\$0.00
Medium	Work In Progress				5/6/2014 7:35:24 AM				
Villalobos, David		zurn type wall mounted faucet broken/need replacment at pump house-dailyused faucet-thanks							
Danny Vega									
113301					2/12/2014		112		\$0.00
Medium	Work In Progress				2/12/2014 7:41:12 AM				
Sotelo, Enrique		emergency lite ballast are burnt out in mechanical rms by rms 301-303-304-308-309-311-mechanical rm by staff lounge and pipe chase closet by bys rr peacn wing and rio grand wing piope chase also these are for heater unit closets							
Danny Vega									
115983					4/16/2014		49		\$0.00
Medium	Work In Progress				4/16/2014 9:50:45 AM				
Sotelo, Enrique		emergency ballast is out/south entance to gym next to janitor mop sink door							
Danny Vega									
117557					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 7:45:06 AM				
Solis, Lorenzo		server rm unit is down-having internet problems.plz ck asap							
Danny Vega									
113943					2/28/2014		96		\$0.00
Medium	Work In Progress				2/28/2014 12:33:00 AM				
Munoz, Michael		Yearly - North Valley ES - Fire Pump Inspection - Refer to PM schedule details.							
Margret Villalobos									
Count: 19 Work Orders		Avg. Age of WO's 54		Total for North Valley ES		0		\$0.00	

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Northern On-Track Pre-K (LM)									
116128					4/22/2014		43		\$0.00
Medium	Work In Progress				4/22/2014 3:32:19 PM				
Ontiveros, Guadalupe		need two loads playground sand to be spread on soccer field at la mesa/field is uneven from heavy equipment ruts							
Danny Vega									
114650					3/14/2014		82		\$0.00
Medium	Work In Progress				3/14/2014 1:15:29 PM				
Gonzalez, Salvador		Do Repair work on utility trailer #4/-straighten out A-FRAME jack-weld ramp chain lock pins-reinforce expanded metal ramp-weld tie down insert on sides for rope-this is used to transport mowers from lm to sme to nve							
Danny Vega									
113267					2/11/2014		113		\$0.00
Medium	Work In Progress				2/11/2014 2:29:40 PM				
Ronquillo, Ruben		NEED REPLACEMENT FLAGS FOR BOTH AMERICAN AND NEW MEXICO FLAGS.							
Adam Montoya									
117536					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 1:58:37 PM				
Ronquillo, Ruben		BREAK IN OVER THE WEEKEND (5-24 - 5-25) IN OLD BUILDING CAFETERIA. TORE OFF PLYWOOD COVERING WINDOW AND BROKE WINDOW, NEED WINDOW COVERED ASAP. CASE # 2014-05614.							
Adam Montoya									
117864					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:07 AM				
Vega, Danny		Monthly - La Mesa ES Monthly FE Inpsection - Refer to PMschedule details.							
Margret Villalobos									
117758					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:59 AM				
Vega, Danny		Yearly - Northern Pre-K B2 (Boiler)(Yearly) - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Northern On-Track Pre-K (LM)									
117759					6/1/2014	6/22/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:59 AM				
Vega, Danny	Monthly - Northern Pre-K C12-Chem.Feeder(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
117760					6/1/2014	6/22/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:00 AM				
Vega, Danny	Monthly - Northern Prek H11(E.Heat)(S.Annual) - Refer to PM schedule details.								
Margret Villalobos									
117782					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:14 AM				
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
117784					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:16 AM				
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
116976					5/11/2014	5/27/2014	24		\$0.00
Medium	Work In Progress				5/11/2014 12:24:44 AM				
Vega, Danny	Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
111683					1/6/2014		149		\$0.00
Medium	Work In Progress				1/6/2014 3:05:45 PM				
Ontiveros, Guadalupe	need 1 load fill dirt for sidewalks at lm pre-k and small bucket tractor to level off								
Danny Vega									
114155					3/3/2014		93		\$0.00
Medium	Work In Progress				3/3/2014 11:30:24 AM				
Ontiveros, Guadalupe	NEED FERTILIZER ON GRASS FIELD (WWED N FEED)APPRX 20 SACKS								
Danny Vega									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Northern On-Track Pre-K (LM)									
117515					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 10:58:59 AM				
Marquez, Gerardo		need door open to custodial stoarge bymorgan bldg - outside/damage to core byvandals-wont open							
Danny Vega									
113535					2/19/2014		105		\$0.00
Medium	Work In Progress				2/19/2014 11:41:20 AM				
Holguin, Alfredo		need sand removed from 3 (ea)plygrd section sand boxes and filled w/wood chips total of 20 (ea) borders that in need of replacement							
Danny Vega									
117967	Main Building	Exterior			6/4/2014		0		\$0.00
Medium	Work In Progress				6/4/2014 8:52:45 AM				
Gonzalez, Salvador		Please reattach gate to the fence that encloses front yard.							
Concepcion Montalvo									
116172	Main Building				4/23/2014		42		\$0.00
Medium	Work In Progress				4/23/2014 2:51:38 PM				
Solis, Lorenzø		NEED BOILER TURNED OFF FOR THE SUMMER.							
Adam Montoya									
117968	Main Building	Office			6/4/2014		0		\$0.00
Medium	Work In Progress				6/4/2014 9:01:48 AM				
Vega, Danny		Paint back wall of reception office with same blue color Danny painted top wall of reception office. Thank You							
Concepcion Montalvo									
117919	Main Building	Office			6/3/2014		1		\$0.00
Medium	Work In Progress				6/3/2014 9:37:25 AM				
Vega, Danny		Remove two old wooden plant boxes from front entrance to school.							
Concepcion Montalvo									
117966	Main Building	Restroom			6/4/2014		0		\$0.00
Medium	Work In Progress				6/4/2014 8:49:19 AM				
Vega, Danny		Replace burnt bulb in women restroom next to girls bathroom.							
Concepcion Montalvo									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Northern On-Track Pre-K (LM)									
117920	Main Building	Exterior			6/3/2014		1		\$0.00
Medium	Work In Progress	Playground			6/3/2014 9:39:57 AM				
Vega, Danny	Cut grass on playground, daycare children are using playground.								
Concepcion Montalvo									
Count: 21 Work Orders		Avg. Age of WO's	33	Total for Northern On-Track Pre-K (LM)				0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
110835					12/4/2013		182		\$0.00
Medium	Work In Progress				12/4/2013 10:47:58 AM				
Holguin, Alfredo	Acquire "Right of Use Permit" for 40ft of left bank of Anthony drain for parking access, fence and landscaping.								
Alfredo Holguin									
114601					3/13/2014		83		\$0.00
Medium	Work In Progress				3/13/2014 11:31:13 AM				
Vallejo, Albert	Eastern Area - please check all electrical panels, and install blank covers were breakers are not needed. (Any questions, please call Mike)								
Michael Munoz									
117787					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:18 AM				
Ruiz, Maria	Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.								
Margret Villalobos									
116608					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:18 AM				
Ruiz, Maria	Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.								
Margret Villalobos									
117617					5/29/2014		6		\$0.00
Medium	Work In Progress				5/29/2014 12:28:11 AM				
Holguin, Alfredo	Yearly - PPD - Maintenance Plan - Refer to PM schedule details.								
Margret Villalobos									
115747					4/9/2014		56		\$0.00
Medium	Work In Progress				4/9/2014 8:00:45 AM				
Carrasco, Danny	ATT: Danny C. need some tool replaced list of tools was turned in to you guys. thanks								
Enrique Sotelo									
116992					5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 9:29:55 AM				
Carrasco, Danny	Assigned Gator trailer TR-PPD-0778 to TR-STH-0778 (Isaac Holguin).								
Danny Carrasco									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
116926					5/9/2014		26		\$0.00
Medium	Work In Progress				5/9/2014 8:17:31 AM				
Carrasco, Danny		Need to purchase double pane window for PPD Lounge room							
Danny Carrasco									
113453					2/14/2014		110		\$0.00
Medium	Work In Progress				2/14/2014 3:45:58 PM				
Miranda, Danny		Installation of cabinets and appliances in PPD Lounge room assigned to DannyM.							
Danny Carrasco									
117942					6/3/2014		1		\$0.00
Medium	Work In Progress				6/3/2014 3:18:04 PM				
Marquez, Gerardo		Gates on new fence east of GMS - install locks.							
Alfredo Holguin									
117877		Athletic Field			6/2/2014		2		\$0.00
High	Work In Progress				6/2/2014 9:11:51 AM				
Ontiveros, Guadalupe		Backhoe 310 E Hydraulic hose is leaking, needs to be replaced.							
Guadalupe Ontiveros									
116827					5/7/2014		28		\$0.00
Medium	Work In Progress				5/7/2014 8:26:54 AM				
Marquez, Gerardo		Rekey Custodial Warehouses							
Alfredo Holguin									
117072					5/13/2014		22		\$0.00
Medium	Work In Progress				5/13/2014 9:46:48 AM				
Marquez, Gerardo		re-core dc-1 to 7 pin on main restroom entrance to ppd training room and door between restrooms and training room to dc-1. thank you							
Michael Munoz									
106552		Athletic Field			8/27/2013		281		\$0.00
Medium	Work In Progress				8/27/2013 8:41:44 AM				
Marquez, Gerardo		need copies of keys for new fuel cap that was install on John Deere Backhoe L110							
Guadalupe Ontiveros									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
113583					2/20/2014		104		\$0.00
Medium	Work In Progress			2/20/2014 8:01:56 AM					
Marquez, Gerardo	Lock to Margret's office is hard to lock/unlock asp Saul, Custodian.								
Saul Chavez									
113812					2/25/2014		99		\$0.00
Medium	Work In Progress			2/25/2014 3:56:53 PM					
Marquez, Gerardo	need a spare set of keys for trucks 38 For Expedition & toolbox								
Mario Apodaca									
110384					11/19/2013		197		\$0.00
Medium	Work In Progress			11/19/2013 7:56:50 AM					
Sotelo, Enrique	please provide lighting to new conference room . where old electrical/hvac shop used to be.								
Michael Munoz									
114600					3/13/2014		83		\$0.00
Medium	Work In Progress			3/13/2014 11:30:23 AM					
Sotelo, Enrique	Northern Area - please check all electrical panels , and install blank covers were breakers are not needed. (Any questions , please call Mike)								
Michael Munoz									
111139					12/11/2013		175		\$0.00
Medium	Work In Progress			12/11/2013 8:25:15 AM					
Sotelo, Enrique	Need to install light on pole where mobile home use to be.								
Michael Munoz									
117375					5/21/2014		14		\$0.00
Medium	Work In Progress			5/21/2014 2:06:16 PM					
Ronquillo, Ruben	NEED TO ORDER BINDERS FOR TRAILERS. THANK YOU!								
Ruben Ronquillo									
109372					10/28/2013		219		\$0.00
Medium	Work In Progress			10/28/2013 7:25:31 AM					
Diaz, Sebastian	Maint Office - Need to paint inside of main door and replace covebase.								
Michael Munoz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
116360					4/29/2014		36		\$0.00
Medium	Work In Progress				4/29/2014 10:43:59 AM				
Ronquillo, Ruben		please order a new tv converter box and antenna as per our conversation. thank you							
Michael Munoz									
116193					4/24/2014		41		\$0.00
Medium	Work In Progress				4/24/2014 7:44:43 AM				
Ronquillo, Ruben		PURCHASE NEW 36V HILTI DRILL/CHIPING CORDELESS HAMMER DRILL AND LASER RANGE METER. THANK YOU							
Ruben Ronquillo									
115717					4/8/2014		57		\$0.00
Medium	Work In Progress				4/8/2014 12:11:52 PM				
Ronquillo, Ruben		ORDER RATCHET ROUND FLEX TAMPER AND TAMPER BITS FOR PLAYGROUND EQUIPMENT (LOANERS) THANK YOU!							
Ruben Ronquillo									
115300					4/1/2014		64		\$0.00
Medium	Work In Progress				4/1/2014 2:01:52 PM				
Ronquillo, Ruben		INSTALL NEW GAS/DIESEL TANKS NEW TRUCK #37							
Ruben Ronquillo									
117179	Food Services				5/15/2014		20		\$0.00
Medium	Work In Progress				5/15/2014 10:18:15 AM				
Orozco, Daniel		FREEZER #4 HAS NOT TURNED ON TEMPERATURE IS GOING UP.							
Maritza Gonzalez									
117036	Motor Vehicle				5/12/2014		23		\$0.00
Medium	Work In Progress	auto shop bay			5/12/2014 3:46:26 PM				
Sotelo, Enrique		please service, repair, and make operational auto shop bay door #1							
Pete Flores									
117325	Motor Vehicle				5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 2:19:41 PM				
Marquez, Gerardo		Maria Ruiz Office - Door Closer is leaking oil.							
Maria Ruiz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

Location: Physical Plant Complex									
116785	Motor Vehicle				5/6/2014		29		\$0.00
Medium	Work In Progress	equip#0408			5/6/2014 12:51:14 PM				
Flores, Pete	mower will not go in reverse and has sustained some body damage. check and advise.								
Pete Flores									
116158	Motor Vehicle				4/23/2014		42		\$0.00
Medium	Work In Progress				4/23/2014 9:47:37 AM				
Flores, Pete	vehicle #184 passenger side (front) window not working								
Maria Ruiz									
116292	Motor Vehicle				4/25/2014		40		\$0.00
Medium	Work In Progress	vehicle#01			4/25/2014 4:26:54 PM				
Flores, Pete	please check for any scheduled maintenance.-mi.96703								
Pete Flores									
116721	Motor Vehicle				5/5/2014		30		\$0.00
Medium	Work In Progress	vehicle#135			5/5/2014 1:52:01 PM				
Flores, Pete	please check for routine maintenance								
Pete Flores									
116880	Motor Vehicle				5/8/2014		27		\$0.00
Medium	Work In Progress	vehicle 144			5/8/2014 8:11:04 AM				
Flores, Pete	steering wheel shakes when applying brakes between 45-55 mph. please check and advise								
Pete Flores									
116881	Motor Vehicle				5/8/2014		27		\$0.00
Medium	Work In Progress	vehicle 130			5/8/2014 8:14:32 AM				
Flores, Pete	tires weatherbeaten and worn, replacement required.								
Pete Flores									
117144	Motor Vehicle				5/14/2014		21		\$0.00
Medium	Work In Progress				5/14/2014 1:40:06 PM				
Munoz, Michael	need to pour a 20'x36'x6" slab of concrete.								
Michael Munoz									
117090	Motor Vehicle				5/13/2014		22		\$0.00
Medium	Work In Progress	vehicle#163			5/13/2014 3:11:40 PM				
Flores, Pete	transmission requires service, please check and advise								
Pete Flores									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
117092	Motor Vehicle				5/13/2014		22		\$0.00
Medium	Work In Progress	vehicles#183,18			5/13/2014 3:20:16 PM				
Flores, Pete		passenger side windows will not raise or lower							
Pete Flores									
117222	Motor Vehicle				5/16/2014		19		\$0.00
Medium	Work In Progress	vehicle#15			5/16/2014 1:34:57 PM				
Flores, Pete		please check for any required maintenance							
Pete Flores									
117223	Motor Vehicle				5/16/2014		19		\$0.00
Medium	Work In Progress	vehicle#172			5/16/2014 1:36:28 PM				
Flores, Pete		please check for any required maintenance.							
Pete Flores									
117442	Motor Vehicle				5/22/2014		13		\$0.00
Medium	Work In Progress	vehicle#157			5/22/2014 2:36:42 PM				
Flores, Pete		a/c not operating at times, goes out completely and only blows air through defroster vents when it does operate.							
Pete Flores									
117265	Motor Vehicle				5/19/2014		16		\$0.00
Medium	Work In Progress	vehicle#41			5/19/2014 1:37:39 PM				
Flores, Pete		please check for any scheduled maintenance mi.6611							
Pete Flores									
117370	Motor Vehicle				5/21/2014		14		\$0.00
Medium	Work In Progress	equip.#0418			5/21/2014 1:29:40 PM				
Flores, Pete		battery not holding charge properly. please check and advise							
Pete Flores									
115937	Motor Vehicle				4/15/2014		50		\$0.00
Medium	Work In Progress	vehicle #33			4/15/2014 2:00:33 PM				
Flores, Pete		please check for any scheduled maintenance							
Pete Flores									
115982	Motor Vehicle				4/16/2014		49		\$0.00
Medium	Work In Progress	vehicle#49			4/16/2014 9:46:14 AM				
Flores, Pete		windshield is in need of replacement. also check for any other required maintenance.							
Pete Flores									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Physical Plant Complex									
113587	Motor Vehicle				2/20/2014		104		\$0.00
Medium	Work In Progress				2/20/2014 9:01:17 AM				
Flores, Pete	Connie Sifuentes called vehicle #111 is overheating. She is stranded on Westside Dr/South Vinton								
Maria Ruiz									
113740	Motor Vehicle				2/24/2014		100		\$0.00
Medium	Work In Progress				2/24/2014 4:15:21 PM				
Flores, Pete	please service vehicle # 100. once serviced assign to the grounds department								
	thank you								
Michael Munoz									
117970	Motor Vehicle				6/4/2014		0		\$0.00
Medium	Work In Progress	vehicle#16			6/4/2014 9:16:27 AM				
Flores, Pete	check for service and please check a/c for proper cooling.								
Pete Flores									
117886	Motor Vehicle				6/2/2014		2		\$0.00
Medium	Work In Progress	vehicle#192			6/2/2014 10:13:30 AM				
Flores, Pete	vehicle will not start. engine cranks but will not run.								
Pete Flores									
104728	Motor Vehicle				7/25/2013		314		\$0.00
Medium	Work In Progress	5510 tractor			7/25/2013 10:19:26 AM				
Flores, Pete	tractor's warning lights are inoperative, and fuel gage is inaccurate. please check.								
Pete Flores									
114734	Motor Vehicle				3/17/2014		79		\$0.00
Medium	Work In Progress	vehicle#163			3/17/2014 3:51:13 PM				
Flores, Pete	please check for any scheduled maintenance. mileage- 80291								
Pete Flores									
113644	Motor Vehicle				2/21/2014		103		\$0.00
Medium	Work In Progress				2/21/2014 10:55:21 AM				
Perez, Raul	vehicle #48 has a dead battery								
Maria Ruiz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
110392	Motor Vehicle				11/19/2013		197		\$0.00
Medium	Work In Progress				11/19/2013 9:49:47 AM				
Gonzalez, Salvador		need door installed to addition to auto shop metal back building. thank you.							
Michael Munoz									
117263	Motor Vehicle				5/19/2014		16		\$0.00
Medium	Work In Progress				5/19/2014 1:00:37 PM				
Diaz, Sebastian		needs ac line							
Maria Ruiz									
117266	Motor Vehicle				5/19/2014		16		\$0.00
Medium	Work In Progress	shop a/c			5/19/2014 1:41:55 PM				
Diaz, Sebastian		evaporative a/c is not producing sufficient air-flow. please check and advise.							
Pete Flores									
117184	Motor Vehicle				5/15/2014		20	1	\$25.00
Medium	Work In Progress				5/15/2014 11:56:02 AM				
Solis, Lorenzø		water fountain is making noise				5/19/14 - Asp Sebas, Lorenzo needs to order solenoid.			
Maria Ruiz									
114593	Purchasing				3/13/2014		83		\$0.00
Medium	Work In Progress				3/13/2014 10:33:50 AM				
Diaz, Sebastian		PPD Reception Area- Paint							
Alfredo Holguin									
116542	Purchasing				5/2/2014		33		\$0.00
High	Work In Progress				5/2/2014 3:25:22 PM				
Villalobos, David		Please meet Tim Reyes @ 7:30am on Monday 5/5/14 to turn off valve by Morgan Bldg that's behind Purchasing Warehouse.							
Michael Munoz									
117377	Maintenance				5/21/2014		14		\$0.00
Medium	Work In Progress				5/21/2014 2:50:07 PM				
Villalobos, David		Maint. Warehouse - Behind restroom wall, install a utility tub.							
Michael Munoz									
116831	Maintenance				5/7/2014		28		\$0.00
Medium	Work In Progress				5/7/2014 10:01:04 AM				
Diaz, Sebastian		New Lounge - area is ready for painting where restrooms are located.							
Danny Miranda									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
117915	Maintenance				6/3/2014		1		\$0.00
Medium	Work In Progress				6/3/2014 7:23:17 AM				
Solis, Lorenzo		unit to maintenance office does not work properly. unit shatters. please check and repair. thank you							
Michael Munoz									
113953					2/28/2014		96		\$0.00
Medium	Work In Progress				2/28/2014 8:18:47 AM				
Gonzalez, Salvador		2-27-14 Attn Danny Carrasco Requesting 20 ton shop press for welding shop.							
Salvador Gonzalez									
116892					5/8/2014		27		\$0.00
Medium	Work In Progress				5/8/2014 12:26:21 PM				
Gonzalez, Salvador		Repair tailgate on trailer #7							
Danny Carrasco									
109287					10/24/2013		223		\$0.00
Medium	Work In Progress				10/24/2013 10:47:27				
Gonzalez, Salvador		old blue trailer. please raise the sides for scrap metal. see mike for details. thank you							
Michael Munoz									
117856					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:02 AM				
Diaz, Sebastian		Monthly - Physical Plant FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
115974					4/16/2014		49		\$0.00
Medium	Work In Progress				4/16/2014 7:46:53 AM				
Gonzalez, Salvador		need fabricate rack for the new truck.							
Salvador Gonzalez									
111444					12/19/2013		167		\$0.00
Medium	Work In Progress				12/19/2013 2:56:01 PM				
Gonzalez, Salvador		fence behind ppd barracks is down. please install poles to fence for temporary repair. thank you							
Michael Munoz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
117769					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:06 AM				
Carbajal, Jimmy		Monthly - Physical Plant - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
114567					3/12/2014		84		\$0.00
Medium	Work In Progress				3/12/2014 2:46:44 PM				
Apodaca, Mario		need to order accessories truck 38 need a jobox ,ladder carrier and installed							
Mario Apodaca									
116789					5/6/2014		29		\$0.00
Medium	Work In Progress				5/6/2014 1:51:08 PM				
Apodaca, Mario		5 / 06 / 2014 4 hours monthly domestic water sampling and transporting work order 116642 1 hour routine service on wastewater plant 1 hour in put the school dude 95 miles truck 38				5/6			
Mario Apodaca									
116394					4/30/2014		35		\$0.00
Medium	Work In Progress				4/30/2014 1:01:38 AM				
Apodaca, Mario		Monthly - PPD/GHS - WW Monthly Sampling - Refer to PM schedule details.							
Margret Villalobos									
109051					10/17/2013		230		\$0.00
Medium	Work In Progress				10/17/2013 4:11:07 PM				
Solis, Lorenzo		please install heating and cooling unit in old electrical/hvac shop and remove existing furnace and a/c. thank you							
Michael Munoz									
114551					3/12/2014		84		\$0.00
Medium	Work In Progress				3/12/2014 8:47:43 AM				
Flores, Pete		need to order one pair of side steps for vehicle 38							
Mario Apodaca									
117556					5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 7:41:17 AM				
Flores, Pete		Truck #16 check engine light came on and A/C does not work.							

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Physical Plant Complex									
113418					2/14/2014		110		\$0.00
Medium	Work In Progress			2/14/2014 12:22:32 AM					
Flores, Pete	Yearly - PPD-T-0524 Bobcat PM Service - Refer to PM schedule details.								
Margret Villalobos									
117494					5/27/2014		8		\$0.00
Medium	Work In Progress			5/27/2014 7:46:35 AM					
Flores, Pete	Would you please do yet another work order for vehicle # 150 to have the turn signals fixed? Several times a day they do not come on like they should.								
	I will not be using the vehicle until 6.9.14 so there should be plenty of time to fix it. I typically park it along the tree line across from the auto shop.								
	Thanks,								
	Larry D. Baker								
Maritza Gonzalez									
115536					4/6/2014		59		\$0.00
Medium	Work In Progress			4/6/2014 12:31:15 AM					
Flores, Pete	Monthly - PPD-MP-0143 DT PM Service - by SWP - Refer to PM schedule details.								
Margret Villalobos									
114997		Athletic Field			3/25/2014		71		\$0.00
Medium	Work In Progress			3/25/2014 11:07:29 AM					
Flores, Pete	Dump Truck #143 Tail Gate Valve Leaking Alr. Dump Cylinder Leaking Hyd OIL. Check Brakes to low. Front Bearings need to be repack.								
Bobby Aldaz									
112175					1/16/2014		139		\$0.00
Medium	Work In Progress			1/16/2014 7:28:50 AM					
Flores, Pete	please service truck # 119 (jose ambriz) and wash. thank you								
Michael Munoz									
117128					5/14/2014		21		\$0.00
Medium	Work In Progress			5/14/2014 10:20:01 AM					
Flores, Pete	Vehicle #14 - Silver's is in need of maintenance								
Cora Ramirez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Physical Plant Complex									
117392					5/21/2014		14		\$0.00
Medium	Work In Progress				5/21/2014 3:33:23 PM				
Flores, Pete		REPLACE TIRES ON TILT TRAILER #6. WORN OUT. THANK YOU!							
Ruben Ronquillo									
Count: 80 Work Orders			Avg. Age of WO's	63		Total for Physical Plant Complex	1		\$25.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Riverside ES							
117327					5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 3:06:07 PM				
Flores, Pete		5/20/2014.							
Mario Martinez		Need flat tire repaired on truck #76.							
117367					5/21/2014		14		\$0.00
Medium	Work In Progress				5/21/2014 9:35:44 AM				
Martinez, Mario		Need to remove all furniture in south wing to the gym from all class rooms, also need to borrow low profile trailer for moving furniture. This is the beginning of the HVAC PROJECT.							
Mario Martinez									
117847					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:56 AM				
Martinez, Mario		Monthly - Riverside ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
117816					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:37 AM				
Martinez, Mario		Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
117815					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:36 AM				
Martinez, Mario		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
117746					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:51 AM				
Martinez, Mario		Yearly - Riverside ES B-2 Boiler Hot Water Yearly - Refer to PM schedule details.							
Margret Villalobos									
116407					4/30/2014		35		\$0.00
Medium	Work In Progress				4/30/2014 10:13:09 AM				
Martinez, Mario		4/30/2014.							
		Need to install 4 water hose bibbs on roof for washing down rooftops.							
Mario Martinez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
116415					4/30/2014		35		\$0.00
Medium	Work In Progress				4/30/2014 3:14:26 PM				
Martinez, Mario		Need to level Morgan so that doors will open properly.							
Mario Martinez									
116160					4/23/2014		42		\$0.00
Medium	Work In Progress				4/23/2014 11:17:08 AM				
Martinez, Mario		Need to inspect Fire alarm pull stations and replace bad batteries. Dimar Systems showed me one that is not working. Recommended that we test them constantly.							
Mario Martinez									
116161					4/23/2014		42		\$0.00
Medium	Work In Progress				4/23/2014 11:23:17 AM				
Martinez, Mario		Need to replace 12 volt 7 amp batteries on alarm system. The existing batteries are dated 2009/2010. Dimar Systems says batteries are showing weakness.							
Mario Martinez									
115875					4/14/2014		51		\$0.00
Medium	Work In Progress				4/14/2014 3:04:17 PM				
Martinez, Mario		Need to paint complete middle wing and entire north south hall way.							
Mario Martinez									
116659					5/4/2014	5/10/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:51 AM				
Martinez, Mario		Monthly - Riverside ES Monthly FE Inpsection - Refer to PMs schedule details.							
Margret Villalobos									
116602					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:14 AM				
Martinez, Mario		Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PMs schedule details.							
Margret Villalobos									
114384		Athletic Field			3/7/2014		89		\$0.00
Medium	Work In Progress				3/7/2014 2:48:40 PM				
Martinez, Mario		Need to repair broken, and missing sprinkler heads and sprinkler lines.							
Mario Martinez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
115370					4/2/2014		63		\$0.00
Medium	Work In Progress				4/2/2014 3:47:24 PM				
Martinez, Mario		4/02/2014. 1 hr open gates, walk through campus, pick up trash, and monitor school bus drop off. 6 hrs complete A/C start up on north wing. Need to replace 1 A/C motor which has only low speed. Room #41. 1 hr pick up clean up and log in work day.				4/2-8			
Mario Martinez									
113115					2/7/2014		117		\$0.00
Medium	Work In Progress				2/7/2014 8:06:31 AM				
Martinez, Mario		Need to change out florescent lighting through out entire South and Middle wings, Computer lab, and main office. North wing completed on 2/06/14.							
Mario Martinez									
113499					2/18/2014		106		\$0.00
Medium	Work In Progress				2/18/2014 3:30:44 PM				
Martinez, Mario		Need to purchase and install 25 window blinds. Color and size on request. 10 42 inch X 80 inch, 10 24inch X 80 inch, 4 24 inch X 64 inch, and 1 72 inch X 80 inch.							
Mario Martinez									
113382					2/13/2014		111		\$0.00
Medium	Work In Progress				2/13/2014 2:43:44 PM				
Martinez, Mario		Need to fill in broken 6 inch red tiles with concrete.							
Mario Martinez									
117306					5/20/2014		15		\$0.00
High	Work In Progress				5/20/2014 8:33:01 AM				
Ontiveros, Joe		At Riverside Elementary need locates for utilities and data for South West corner of parking lot to building within the circle area. Refer to e-mail for site plan showing highlighted area of parking lot and area where locates are needed. For questions please contact Ron Scott of Sandoval Construction at (575) 649-5425 or Mr. Ralph Gallegos at 575- 882-6921 in the Construction office. Thank You							
Dominique Esparza									
115705					4/8/2014		57		\$0.00
Medium	Work In Progress				4/8/2014 7:39:27 AM				
Ontiveros, Joe		Need plumber Joe O. to come by and fix water leak in mechanical room. A.S.A.P.							
Mario Martinez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
115706					4/8/2014		57		\$0.00
Medium	Work In Progress			4/8/2014 7:51:24 AM					
Ontiveros, Joe	there is a leak in a custodial closet. need help								
Mario Martinez									
117984					6/4/2014		0		\$0.00
Medium	Work In Progress			6/4/2014 11:00:53 AM					
Ontiveros, Joe	SPOT:WITH-IN THE AREA MARKED IN WHITE AT THE ENTRANCE OF SCHOOL. NO KNOWN HAZARDS/ OPEN ACCESS								
Nearest Intersecting Street: RIVERSIDE DR Latitude: 31.81674600 Longitude: -106.59896250 Questions: RENEGADE CONSTRUCTION, LLC Contact Name: ZEKE GREER Contact Phone: (575)523-2600 Alternate Contact: TINA GOEBEL Alternate Phone: (575)523-2600 Fax No: (575)523-5595 Cell Phone: (575)937-0945									
Dominique Esparza									
116313					4/28/2014		37		\$0.00
Medium	Work In Progress			4/28/2014 12:55:14 PM					
Gonzalez, Salvador	Need Salvador to construct a metal box for 700 feet of water hose. For storage only.								
Mario Martinez									
117578	Main Building	Office			5/28/2014		7		\$0.00
Medium	Work In Progress	attendance clerk		5/28/2014 12:18:49 PM					
Briones, Enrique	please pick up EOY cumes that need to be taken to warehouse. (soto)								
Rosa Quezada									
117892	Main Building	Office			6/2/2014		2		\$0.00
Medium	Work In Progress			6/2/2014 10:37:28 AM					
Briones, Enrique	Deliver toatl of 40 bxs; (310 Math k_6th Eng/Span Workbooks (9) Science Materials.								
Theresa Ramirez									
108675	Main Building	Restroom			10/10/2013		237		\$0.00
Medium	Work In Progress	RESTROOM		10/10/2013 10:21:47					
Ambriz, Jose	VENT IN MAIN OFFICE RESTROOM IS NOT WORKING								
Rosa Quezada									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Riverside ES							
116500					5/1/2014		34		\$0.00
Medium	Work In Progress				5/1/2014 3:16:53 PM				
Lara, Ralph		5/1/2014.	Need Rafa L. to work on door locks in north wing.						
Mario Martinez									
110138					11/12/2013		204		\$0.00
Medium	Work In Progress				11/12/2013 2:53:05 PM				
Ontiveros, Guadalupe		Pine tress on south side next to playground. Need to check irrigation system, trees are dead or dying.							
Alfredo Holguin									
110158					11/12/2013		204		\$0.00
Medium	Work In Progress				11/12/2013 4:02:42 PM				
Ontiveros, Guadalupe		replace damaged soccer goal was hit by a car.							
Alfredo Holguin									
117661					5/30/2014		5		\$0.00
Medium	Work In Progress				5/30/2014 10:09:20 AM				
Ontiveros, Guadalupe		Need top soil materials for leveling soccer field. Request assistance with tractor and leveling equipment							
Mario Martinez									
117983					6/4/2014		0		\$0.00
Medium	Work In Progress				6/4/2014 10:36:13 AM				
Castillo, Carlos		SPOT:WITH-IN THE AREA MARKED IN WHITE AT THE ENTRANCE OF SCHOOL. NO KNOWN HAZARDS/ OPEN ACCESS							
		Nearest Intersecting Street: RIVERSIDE DR Latitude: 31.81674600 Longitude: -106.59896250							
		Questions: RENEGADE CONSTRUCTION, LLC Contact Name: ZEKE GREER Contact Phone: (575)523-2600 Alternate Contact: TINA GOEBEL Alternate Phone: (575)523-2600 Fax No: (575)523-5595 Cell Phone: (575)937-0945							
Dominique Esparza									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Riverside ES									
117305					5/20/2014		15		\$0.00
High	Work In Progress			5/20/2014 8:32:07 AM					
Castillo, Carlos	At Riverside Elementary need locates for utilities and data for South West corner of parking lot to building within the circle area. Refer to e-mail for site plan showing highlighted area of parking lot and area where locates are needed. For questions please contact Ron Scott of Sandoval Construction at (575) 649-5425 or Mr. Ralph Gallegos at 575- 882-6921 in the Construction office. Thank You								
Dominique Esparza									
117133					5/14/2014		21		\$0.00
Medium	Work In Progress			5/14/2014 12:18:47 PM					
Castillo, Carlos	Need Carlos C. to fix bad light in art Portable.								
Mario Martinez									
117134					5/14/2014		21		\$0.00
Medium	Work In Progress			5/14/2014 12:20:46 PM					
Castillo, Carlos	Need Carlos C. to rewire electrical at morgan building.								
Mario Martinez									
117684					5/30/2014		5		\$0.00
Medium	Work In Progress			5/30/2014 2:56:57 PM					
Carrasco, Danny	To Ruben R or DannyC. Need gasoline and diesel fuel for tractors, blowers, weed eaters, and pressure washer. 5/30/2014.								
Mario Martinez									
115650					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress			4/6/2014 12:32:30 AM					
Orozco, Daniel	Monthly - Riverside ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
113362					2/13/2014		111		\$0.00
Medium	Work In Progress			2/13/2014 8:16:43 AM					
Holguin, Alfredo	Riverside Elementary has four sand playgrounds. North side has three. 1 is 3149 sq ft. Another is 2760 sq ft. The third is 4545 sq ft. Those are all on North side playground. South side has one sand playground with a sq footage of 11,200 sq feet.								
Mario Martinez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Riverside ES									
115275		Classroom			3/31/2014		65		\$0.00
Medium	Work In Progress	6th grade blg			3/31/2014 4:48:05 PM				
Gonzales, Camilo		we need 200 student high-pressure laminate Fusion maple top front desks (Navarro)							
Rosa Quezada									
112046					1/14/2014		141		\$0.00
Medium	Work In Progress				1/14/2014 7:22:53 AM				
Castillo, Carlos		Need lights at Southwest portables fixed.				2/26 -Reroute to Cali			
Mario Martinez									
111430		Electrical Room			12/19/2013		167		\$0.00
Medium	Work In Progress				12/19/2013 9:20:46 AM				
Castillo, Carlos		Annual electrical equipment inspection.							
Carlos Castillo									
113114					2/7/2014		117		\$0.00
Medium	Work In Progress				2/7/2014 7:56:35 AM				
Castillo, Carlos		Need Carlos C. to replace or repair light fixtures in rooms 116/117/121/123/137/148, also in music portable and art portable.							
Mario Martinez									
Count: 41 Work Orders		Avg. Age of WO's 58			Total for Riverside ES			0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: RTC - Alliance									
112166		Classroom			1/15/2014		140		\$0.00
Medium	Work In Progress				1/15/2014 4:13:38 PM				
Moncayo, Fernando		we need doorstops on all portable and to clean grounds							
Gloria Delgado									
115107		Classroom			3/27/2014		69		\$0.00
Medium	Work In Progress				3/27/2014 11:14:10 AM				
Moncayo, Fernando		repair classroom wall by the entrance (student punched the wall as he was exiting)							
Gloria Delgado									
112426		Classroom			1/24/2014		131		\$0.00
Medium	Work In Progress				1/24/2014 8:30:33 AM				
Moncayo, Fernando		the rooms and office need filters replace							
Gloria Delgado									
113600		Classroom			2/20/2014		104		\$0.00
Medium	Work In Progress				2/20/2014 2:14:57 PM				
Moncayo, Fernando		Please replace air filters and if possible air ducts cleaned.							
Gloria Delgado									
Count: 4 Work Orders		Avg. Age of WO's		111	Total for RTC - Alliance			0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: San Miguel ES									
117517					5/27/2014		-5		\$0.00
Medium	Work In Progress				5/27/2014 12:43:50 PM	5/22/2014			
Sotelo, Enrique		Portable (Klein) - replace exterior light and install w/new photocell.							
Michael Munoz									
117507					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 10:30:30 AM				
Vega, Danny		Portable (Klein) - order and install screens for windows.							
Michael Munoz									
117509					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 10:32:48 AM				
Vega, Danny		Portable (Klein) - remove and dispose shelves							
Michael Munoz									
117511					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 10:36:27 AM				
Vega, Danny		Portable (Klein) - order and replace blinds							
Michael Munoz									
117514					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 10:43:48 AM				
Ontiveros, Guadalupe		Clean area where portable use to be.							
Michael Munoz									
117510					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 10:35:11 AM				
Marquez, Gerardo		Portable (Klein) - replace doorknobs w/new ones that lock and replace exterior doors to furnace.							
Michael Munoz									
117221					5/16/2014		19		\$0.00
Medium	Work In Progress				5/16/2014 1:18:44 PM				
Marquez, Gerardo		Need to install a new padlock (missing) at gate.							
Danny Vega									
117512					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 10:38:30 AM				
Villalobos, David		Portable (Klein) - repair drinking fountain south of portable.							
Michael Munoz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: San Miguel ES									
117252					5/19/2014		16		\$0.00
Medium	Work In Progress				5/19/2014 8:49:21 AM				
Villalobos, David		Portable (Klein) - Need to check restroom, sink and all plumbing fixtures for proper operation a/s/a/p.							
Alfredo Holguin									
117311					5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 9:39:24 AM				
Ronquillo, Ruben		Portable (Klein) - replace windows.							
Michael Munoz									
117508					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 10:31:51 AM				
Gonzalez, Salvador		Portable (Klein) - repair fence on a/c unit and install gate.							
Michael Munoz									
117255					5/19/2014		16		\$0.00
Medium	Work In Progress				5/19/2014 8:53:53 AM				
Estrada, Jesus		Portable (Klein) - Need to re-stretch carpet and clean once Plumber and HVAC are done.							
Alfredo Holguin									
117843					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:53 AM				
Apodaca, Mario		Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
116644					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:41 AM				
Apodaca, Mario		Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
117253					5/19/2014		16		\$0.00
Medium	Work In Progress				5/19/2014 8:50:36 AM				
Solis, Lorenzø		Portable (The Climb) - Need to check HVAC system for proper operation a/s/a/p.							
Alfredo Holguin									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: San Miguel ES									
117312					5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 9:41:05 AM				
Ramirez, Joe		Portable (Klein) - paint inside and outside of portable to include doors, ramps, stairs.							
Michael Munoz									
117513					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 10:42:35 AM				
Ramirez, Joe		Portable (Klein) - clean around portable.							
Michael Munoz									
114897		Cafeteria			3/21/2014		75		\$0.00
High	Work In Progress				3/21/2014 9:47:22 AM				
Munoz, Michael		need to install new flooring in the dining, stage and restrooms.							
Alfredo Holguin									
Count: 18 Work Orders			Avg. Age of WO's	15		Total for San Miguel ES	0		\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

Location:		Santa Teresa ES							
115839					4/13/2014	4/29/2014	52		\$0.00
Medium	Work In Progress				4/13/2014 12:24:22 AM				
Diaz, Pablo	Monthly - QRTLY BLDG INSP REPORT (STE) - Refer to PM schedule details.								
Margret Villalobos									
116210					4/24/2014		41		\$0.00
Medium	Work In Progress	Art show			4/24/2014 1:13:11 PM				
Ambriz, Juan	Need to assist setting up for Art show in STM								
Juan Ambriz									
116981					5/11/2014	5/27/2014	24		\$0.00
Medium	Work In Progress				5/11/2014 12:24:48 AM				
Ambriz, Juan	Monthly - Santa Teresa ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
116650					5/4/2014	5/10/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:45 AM				
Ambriz, Juan	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
116575					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:37:55 AM				
Ambriz, Juan	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
116576					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:37:55 AM				
Ambriz, Juan	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
116574					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:37:54 AM				
Ambriz, Juan	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location:		Santa Teresa ES							
117220		Portables			5/16/2014		19		\$0.00
Medium	Work In Progress			5/16/2014 12:51:43 PM					
Estrada, Jesus	Por parte de la principal Ms. Tarin, en el portable F "arte" tiene problema con la cerpeta se esta muy manchada y se esta destrosando. Pide que si por favor puedan quitar la carpeta y poner floor tile. Gracias								
Ivan Rodriguez									
117745					6/1/2014		3		\$0.00
Medium	Work In Progress			6/1/2014 12:53:50 AM					
Ambriz, Juan	Monthly - Santa Teresa ES C-4 Quarterly MSS - Refer to PM schedule details.								
Margret Villalobos									
117851					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:59 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
117814					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:35 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
117813					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:34 AM					
Ambriz, Juan	Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
117817					6/1/2014		3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:37 AM					
Ambriz, Juan	Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
114006					3/2/2014		94		\$0.00
Medium	Work In Progress			3/2/2014 12:26:02 AM					
Ambriz, Juan	Yearly - Santa Teresa ES A-10 HEAT PUMPS (ANNUAL) - Refer to PM schedule details.								
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
115199					3/31/2014		65		\$0.00
Medium	Work In Progress				3/31/2014 12:54:14 AM				
Ambriz, Juan		Monthly - Santa Teresa ES-A-16 Fan Exhaust (SemiA) - Refer to PM schedule details.							
Margret Villalobos									
117173	Main Building	Classroom			5/14/2014		21		\$0.00
Medium	Work In Progress	rm 302 Mr.			5/14/2014 4:20:15 PM				
Ambriz, Jose		Air conditioner in room 302 is not working. Please check. Thankl you.							
Rita Mendez									
117254	Main Building	Classroom			5/19/2014		16		\$0.00
Medium	Work In Progress	Room #305			5/19/2014 8:51:23 AM				
Ambriz, Jose		Need to check cooling unit in room #305							
Juan Ambriz									
109418	Main Building	Classroom			10/28/2013		219		\$0.00
Medium	Work In Progress	Room #206			10/28/2013 2:05:48 PM				
Ambriz, Jose		Need to check a/c unit in room #206 not working properly							
Juan Ambriz									
111841	Main Building	Hallway/Corridor			1/9/2014		146		\$0.00
Medium	Work In Progress	200 hallway			1/9/2014 3:04:10 PM				
Ontiveros, Joe		Need to repair leak in 2 1/2" main domestic water							
Juan Ambriz									
113386	Main Building	Parking Lot			2/13/2014		111		\$0.00
Medium	Work In Progress	front gates			2/13/2014 2:56:50 PM				
Ambriz, Juan		Need to replace wheels on all gates. Hard to open							
Juan Ambriz									
115406	Main Building	Classroom			4/3/2014		62		\$0.00
Medium	Work In Progress	Room #302			4/3/2014 2:55:34 PM				
Ambriz, Juan		Need to replace broken soap dispenser in room # 301							
Juan Ambriz									
115026	Main Building	Classroom			3/25/2014		71		\$0.00
Medium	Work In Progress				3/25/2014 2:55:13 PM				
Ambriz, Juan		Need to assemble shelves for room #108							
Juan Ambriz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
115767	Main Building	Classroom			4/9/2014		56		\$0.00
Medium	Work In Progress	room #103			4/9/2014 3:37:42 PM				
Ambriz, Juan		Need to replace switch to room #103							
Juan Ambriz									
116482	Main Building	Portables			5/1/2014		34		\$0.00
Medium	Work In Progress	Portable C & D			5/1/2014 12:40:01 PM				
Ambriz, Juan		As per Mrs. Tarin need to repair broken water line in restrooms							
Juan Ambriz									
114215	Main Building	Cafeteria			3/4/2014		92		\$0.00
Medium	Work In Progress	kitchen			3/4/2014 12:39:16 PM				
Ambriz, Juan		Need to install shelves in kitchen office							
Juan Ambriz									
115918	Main Building	Cafeteria			4/15/2014		50		\$0.00
Medium	Work In Progress				4/15/2014 10:46:55 AM				
Ambriz, Juan		As per Mrs. Tarin needs the cafeteria painted between June 6 to june 22							
Juan Ambriz									
115917	Main Building	Office			4/15/2014		50		\$0.00
Medium	Work In Progress	Front office			4/15/2014 10:44:41 AM				
Ambriz, Juan		As per Mrs. Tarin needs the front office painted between June 6 to june 22							
Juan Ambriz									
115116	Main Building	Office			3/27/2014		69		\$0.00
Medium	Work In Progress				3/27/2014 2:17:17 PM				
Ambriz, Juan		As per Mrs. Tarin need to Install blinds in front office							
Juan Ambriz									
115117	Main Building	Restroom			3/27/2014		69		\$0.00
Medium	Work In Progress	adult 100			3/27/2014 2:34:25 PM				
Ambriz, Juan		Need to replace doughnut on toilet							
Juan Ambriz									
117623	Main Building	Office			5/29/2014		6		\$0.00
Medium	Work In Progress	front office			5/29/2014 8:01:37 AM				
Ambriz, Juan		Need to remove and reinstall bulletin boards from teachers lounge to front office							
Juan Ambriz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
117249	Main Building	Classroom			5/19/2014		16		\$0.00
Medium	Work In Progress	Room #301			5/19/2014 8:24:53 AM				
Ambriz, Juan		Need to repair cooling unit in room #301							
Juan Ambriz									
117932	Main Building	Classroom			6/3/2014		1		\$0.00
Medium	Work In Progress	Room #210			6/3/2014 2:36:38 PM				
Ambriz, Juan		As per Mrs. Tarin need to relocate chalkboard and bulletin boards							
Juan Ambriz									
117933	Main Building	Classroom			6/3/2014		1		\$0.00
Medium	Work In Progress	Room #206			6/3/2014 2:38:03 PM				
Ambriz, Juan		As per Mrs. Tarin need to relocate chalkboard							
Juan Ambriz									
117934	Main Building	Classroom			6/3/2014		1		\$0.00
Medium	Work In Progress	Room #106			6/3/2014 2:39:23 PM				
Ambriz, Juan		As per Mrs. Tarin Need to relocate chalkboards							
Juan Ambriz									
117935	Main Building	Classroom			6/3/2014		1		\$0.00
Medium	Work In Progress	Room #104			6/3/2014 2:40:36 PM				
Ambriz, Juan		As per Mrs. Tarin Need to relocate chalkboard							
Juan Ambriz									
117936	Main Building	Classroom			6/3/2014		1		\$0.00
Medium	Work In Progress	Room # 107			6/3/2014 2:41:52 PM				
Ambriz, Juan		As per Mrs. Tarin Need to relocate chalkboard							
Juan Ambriz									
114367	Main Building	Football Field			3/7/2014		89		\$0.00
Medium	Work In Progress	all playground			3/7/2014 8:25:35 AM				
Ambriz, Juan		Need to fertilize back field							
Juan Ambriz									
117659	Main Building	Football Field			5/30/2014		5		\$0.00
Medium	Work In Progress	back field			5/30/2014 8:10:29 AM				
Ambriz, Juan		Need to repair broken sprinklers not working properly							
Juan Ambriz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
112574	Main Building	Exterior			1/29/2014		126		\$0.00
Medium	Work In Progress	Basketball			1/29/2014 8:24:37 AM				
Ambriz, Juan Need to cover cracks on cement on basketball courts									
Juan Ambriz									
115919	Main Building				4/15/2014		50		\$0.00
Medium	Work In Progress	Teachers lounge			4/15/2014 10:49:22 AM				
Ambriz, Juan As per Mrs. Tarin needs teacher's lounge painted									
Juan Ambriz									
117938	Main Building				6/3/2014		1		\$0.00
Medium	Work In Progress				6/3/2014 2:59:16 PM				
Ambriz, Juan 06/03/14 6/3/14 - 2 HRS									
1HR Report to STE front office checked grounds									
6HRS Complete w/o#114367									
1HR Complete paperwork									
Juan Ambriz									
117198	Main Building	Portables			5/15/2014		20		\$0.00
Medium	Work In Progress	Portable B/ Mr.			5/15/2014 3:37:57 PM				
Lara, Ralph The entrance door to Portable B is stuck. It will not open asp chuy, juan is out called rafa									
al all. Please check. Phone call placed to Mr. Estrada									
already. Thank you.									
Rita Mendez									
117310	Main Building	Classroom			5/20/2014		15		\$0.00
Medium	Work In Progress	303 Rivas			5/20/2014 9:37:11 AM				
Lara, Ralph Drawers and closets need locks-they have broken and									
unable to lock. Thank you.									
Rita Mendez									
112234	Main Building	Parking Lot			1/17/2014		138		\$0.00
Medium	Work In Progress	Student Pick			1/17/2014 12:56:02 PM				
Gonzalez, Salvador The school needs a metal shade frame to be located at									
the student drop off/pick up area. Thank you.									
Rita Mendez									
117921	Main Building	Cafeteria			6/3/2014		1		\$0.00
Medium	Work In Progress	cafeteria			6/3/2014 11:01:39 AM				
Gonzales, Camilo Please pick up Early Childhood furniture and distribute									
to appropriate school sites. Furniture labeled. Thank									
you.									
Rita Mendez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa ES									
113441	Main Building	Exterior			2/14/2014		110		\$0.00
Medium	Work In Progress	Playgrounds			2/14/2014 3:25:01 PM				
Holguin, Alfredo		As per Alfredo playground sand needs to be removed and replaced with Engineered wood fibers, 2 playgrounds and a total of 41 borders							
Juan Ambriz									
117390					5/21/2014		14		\$0.00
Medium	Work In Progress	Master key for			5/21/2014 3:27:42 PM				
Lara, Ralph		Need replacement for master key for custodian							
Juan Ambriz									
115651					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:31 AM				
Orozco, Daniel		Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
117274					5/19/2014		16		\$0.00
Medium	Work In Progress	Vehicle # 140			5/19/2014 3:04:08 PM				
Carrasco, Danny		Need fuel for vehicle #140, blowers and weedeater							
Juan Ambriz									
115229					3/31/2014		65		\$0.00
Medium	Work In Progress	LINE LOCATE			3/31/2014 10:51:21 AM				
Castillo, Carlos		Need to line locate at the parent pickup turnaround area will be marked white.							
Salvador Gonzalez									
114592					3/13/2014		83		\$0.00
Medium	Work In Progress				3/13/2014 9:43:14 AM				
Ontiveros, Guadalupe		Asprinkler head is leaking by the basketball courts.							
117124									
Medium	Work In Progress				5/14/2014		21		\$0.00
Villalobos, David		Need Horizon Mechanical to repair failed backflow preventers							
David Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa ES							
116298					4/28/2014		37		\$0.00
Medium	Work In Progress				4/28/2014 8:42:23 AM				
Orozco, Daniel		TEMPERATURE GOIN UP ON REACH IN REFRIGERATOR. SNP MANAGER MARINA R. 589.3439							
Maritza Gonzalez									
Count: 53 Work Orders		Avg. Age of WO's	45	Total for Santa Teresa ES			0	\$0.00	

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
111713					1/7/2014		148		\$0.00
Medium	Work In Progress	LINE LOCATE			1/7/2014 8:25:58 AM				
Sotelo, Enrique		Lynco will be drilling at Santa Teresa on Tuesday, 01/14/2014 and will need utilities located. They have the piers marked on the ground and will need your district to locate any utilities underground at these locations.							
Rafael Gallegos									
117251					5/19/2014		16		\$0.00
Medium	Work In Progress				5/19/2014 8:34:52 AM				
Holguin, Isaac		SNP MANAGER(OLGA B.) WOULD LIKE TO REQUEST TO HAVE KITCHEN FLOORS CLEANED MAY 27,2014. THANK YOU							
Maritza Gonzalez									
106495					8/26/2013		282		\$0.00
Medium	Work In Progress				8/26/2013 9:08:31 AM				
Ambriz, Jose		Room 203. Slave fan coil unit has a noisysquerrel cage. I had to shutdown unit through tracer summit so it won't disrupt the classroom.							
Jaime Mijarez									
116299					4/28/2014		37		\$0.00
Medium	Work In Progress				4/28/2014 9:12:19 AM				
Ambriz, Jose		Culinary kitchen Freezer is tripping breaker and compressor is noisy and condenser fan is rubbing on metal.							
Jaime Mijarez									
117239					5/16/2014		19		\$0.00
Medium	Work In Progress				5/16/2014 3:46:27 PM				
Ambriz, Jose		Mrs. Pope room 515. Teacher wants her a/c registers replaced and air ducts checked for debris. She says there is dirt going in the classroom and registers are very rusted and old.							
Jaime Mijarez									
112962		Athletic Field			2/4/2014		120		\$0.00
Medium	Work In Progress				2/4/2014 3:22:07 PM				
Ontiveros, Guadalupe		as per conversation, please laydown compost on the southeast corner of baseball field by marquee. thank you							
Michael Munoz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
117559		Athletic Field			5/28/2014		7		\$0.00
Medium	Work In Progress			5/28/2014 8:02:29 AM					
Ontiveros, Guadalupe	Coach Bailon would like to get 4 trees by the baseball side cut down. This starts from the first base side and should take away the shadow from the batters which affects the players when they are batting								
William Dickson									
117560		Athletic Field			5/28/2014		7		\$0.00
Medium	Work In Progress			5/28/2014 8:05:41 AM					
Ontiveros, Guadalupe	Coach Bailon would like for the batting cages to be shorten to a size of 14 foot height and 11 feet long creating more individual batting space. Needs this to get more athletes involve in hitting drills.								
William Dickson									
114948					3/24/2014		72		\$0.00
Medium	Work In Progress			3/24/2014 11:12:07 AM					
Castillo, Carlos	Request by Rick Llenez. Please repair lighting at grounds shop.								
Jaime Mijarez									
114982					3/25/2014		71		\$0.00
Medium	Work In Progress			3/25/2014 6:56:29 AM					
Castillo, Carlos	Counciling center/Requested by Mrs. Rodriguez. Will need more recepticles for 10 computers to be installed against the wall including copy machine's that are already connected by the same wall.								
Jaime Mijarez									
109208					10/22/2013		225		\$0.00
Medium	Work In Progress			10/22/2013 3:45:56 PM					
Castillo, Carlos	Main entrance hallway. All the ivory light switches need to be replaced they are broken and are not working properly. Please check with me (Jaime).								
Jaime Mijarez									
117664					5/30/2014		5		\$0.00
Medium	Work In Progress	DSC		5/30/2014 10:48:50 AM					
Gonzales, Camilo	MOVE EQUIPMENT FROM K. ARAMBASIK CLASSROOM @ STHS TO STMS FOR EXTENDED SCHOOL YEAR (1 STANDER, 2 BIKES)								
Margaret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Santa Teresa HS									
106327					8/21/2013		287		\$0.00
Medium	Work In Progress				8/21/2013 9:56:59 AM				
Holguin, Alfredo	Attn: Alfredo Holguin. Roof goose neck vents in old main bldg areas total of 18 count from 12", 24" and 36". These vents are causing roof leaks and ceiling tile damage which produces mold on tiles. Several of the dampers are not functional, screens are detached or torn. One of the problems we've had is cats going into the building and also accessible to intruders breaking in. I viewed the additions to the building and they have a newer and better vent design with a cap on top for better rain water protection and intruder protection. Let me know if you need more information.								
Jaime Mijarez									
117070					5/13/2014		22		\$0.00
Medium	Work In Progress				5/13/2014 9:18:07 AM				
Carrasco, Danny	Attn: Ruben and Danny (Summer projects materials needed). paint, painting supplies, screws and anchors for chalk board removal and white board installation. Painting in 200 wing, 300 wing and exterior doors. Installation of mini blinds.								
Jaime Mijarez									
116272					4/25/2014		40		\$0.00
Medium	Work In Progress				4/25/2014 3:29:15 PM				
Carrasco, Danny	we need the following tools here at STHS. 6", 8" and 12" spatulas and mud pan. Angle grinder and cutting wheels. Gas powered hand blower.								
David Escobar									
116884		Custodial			5/8/2014		27		\$0.00
Medium	Work In Progress				5/8/2014 10:10:33 AM				
Carrasco, Danny	i need a flatbed trailer to pull with my gator to move furniture asap monday i need to move furniture for friday graduation practice in gym 300 chairs from cafeteria to gym					routed to maintenance asp chuy			
Isaac Holguin									
114686					3/17/2014		79		\$0.00
Medium	Work In Progress				3/17/2014 9:36:54 AM				
Orozco, Daniel	NO WATER IN BATHROOM SINK. SNP MANAGER OLGA B.								
Maritza Gonzalez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
113006					2/5/2014		119		\$0.00
Medium	Work In Progress				2/5/2014 9:15:29 AM				
Orozco, Daniel		BOTTOM SWITCH TO TURN OF DISHWASHER IS BROKEN-SNP MANAGER OLGA B.589.5332							
Maritza Gonzalez									
115652					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:32 AM				
Orozco, Daniel		Monthly - Santa Teresa HS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
117071					5/13/2014		22		\$0.00
Medium	Work In Progress				5/13/2014 9:23:15 AM				
Orozco, Daniel		MILK COOLER IN THE RED & GREEN LINE IS NOT WORKING.SNP MANAGER OLGA B.589.5332							
Maritza Gonzalez									
115994					4/16/2014		49		\$0.00
Medium	Work In Progress				4/16/2014 1:05:04 PM				
Orozco, Daniel		One of sink to long for hot water to reach the sink, maybe hot water booster. SNP Manager Olga B. 589.5332							
Maritza Gonzalez									
116347		Exterior			4/28/2014		37		\$0.00
Medium	Work In Progress				4/28/2014 4:57:17 PM				
Castillo, Carlos		Wanted to put a couple of lights 3 to be exact around the sign next to the high announcing Santa Teresa High School. Wants to light it up the area.							
William Dickson									
117177					5/15/2014		20		\$0.00
Medium	Work In Progress				5/15/2014 8:29:58 AM				
Castillo, Carlos		need to install a ceiling receptacle in room C2 .							
David Escobar									
117633					5/29/2014		6		\$0.00
Medium	Work In Progress				5/29/2014 11:02:20 AM				
Castillo, Carlos		several electrical cords in vocational bld. need to be updated and brought to code.							
David Escobar									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
116757		Athletic Field			5/5/2014		30		\$0.00
Medium	Work In Progress			5/5/2014 8:37:15 PM					
Castillo, Carlos	Need to set up the electrical system we had during our Invitation meet. We will be using the same electrical connections as before.								
William Dickson									
115401		Classroom			4/3/2014		62		\$0.00
Medium	Work In Progress	VARIOUS		4/3/2014 11:55:21 AM					
Escobar, David	INSTALL BRACKETS AND NM FLAGS AND US FLAGS IN CLASSROOMS. PLEASE SEE MARYLOU FOR LIST OF CLASSROOMS.								
Marylou Jimenez									
115328		Kitchen			4/1/2014		64		\$0.00
Medium	Work In Progress			4/1/2014 4:01:26 PM					
Escobar, David	Fix 3 back legs on table that holds the 2 grills they are to heavy								
William Dickson									
115330		Kitchen			4/1/2014		64		\$0.00
Medium	Work In Progress			4/1/2014 4:03:11 PM					
Escobar, David	CulinaryArts re-install shelf in pantry								
William Dickson									
116346					4/28/2014		37		\$0.00
Medium	Work In Progress			4/28/2014 4:41:05 PM					
Escobar, David	Replace a ceiling tile a dual board installation was made and left unprotected. the cable in the middle of floor dangerous someone could trip over cable.								
William Dickson									
115578					4/6/2014	5/7/2014	59		\$0.00
Medium	Work In Progress			4/6/2014 12:31:44 AM					
Escobar, David	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PMs schedule details.								
Margret Villalobos									
117166					5/14/2014		21		\$0.00
Medium	Work In Progress			5/14/2014 3:53:49 PM					
Escobar, David	sending a tools list I need to work on Poms inspection report .								
David Escobar									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
116825					5/7/2014		28		\$0.00
Medium	Work In Progress			5/7/2014 8:12:37 AM					
Escobar, David	we need evap motor clamps.								
David Escobar									
116630					5/4/2014	6/4/2014	31		\$0.00
Medium	Work In Progress			5/4/2014 12:38:32 AM					
Escobar, David	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PMschedule details.								
Margret Villalobos									
116628					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress			5/4/2014 12:38:31 AM					
Escobar, David	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PMschedule details.								
Margret Villalobos									
116629					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress			5/4/2014 12:38:31 AM					
Escobar, David	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PMschedule details.								
Margret Villalobos									
117781					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:14 AM					
Escobar, David	Monthly - Santa Teresa HS Bleacher Inspection - Refer to PMschedule details.								
Margret Villalobos									
117780					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:13 AM					
Escobar, David	Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PMschedule details.								
Margret Villalobos									
117779					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:12 AM					
Escobar, David	Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PMschedule details.								
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
117460					5/23/2014		12		\$0.00
Medium	Work In Progress			5/23/2014 9:18:23 AM					
Escobar, David	need 15 boxes ceiling tiles . (G-0002A(586)). to replace several tiles that are either broken or have water damage.								
David Escobar									
117567					5/28/2014		7		\$0.00
Medium	Work In Progress			5/28/2014 10:04:40 AM					
Escobar, David	AC cooler in room 408. has a locked motor and needs replacement								
David Escobar									
117568					5/28/2014		7		\$0.00
Medium	Work In Progress			5/28/2014 10:05:55 AM					
Escobar, David	cooler in ms. harpers office has a locked motor and needs replacement								
David Escobar									
115491					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress			4/6/2014 12:30:34 AM					
Escobar, David	Monthly - Santa Teresa HS H-11 Unit Elec Semimly - Refer to PMschedule details.								
Margret Villalobos									
115490					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress			4/6/2014 12:30:33 AM					
Escobar, David	Monthly - Santa Teresa HS C-12 Chm Feeder Semimly - Refer to PMschedule details.								
Margret Villalobos									
115503					4/6/2014	4/14/2014	59		\$0.00
Medium	Work In Progress			4/6/2014 12:30:43 AM					
Escobar, David	Monthly - Santa Teresa HS Roof Inspection - Refer to PMschedule details.								
Margret Villalobos									
113916					2/28/2014	3/31/2014	96		\$0.00
Medium	Work In Progress			2/28/2014 12:32:46 AM					
Escobar, David	Yearly - Santa Teresa HS C-11 Evap Coolers Yearly - Refer to PMschedule details.								
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

117635 5/29/2014 6 \$0.00

Medium Work In Progress 5/29/2014 11:13:43 AM

Lara, Ralph 15 class rooms have no door close devise. please see bld. mech. 2 for list of rooms.

David Escobar

114100 3/2/2014 94 \$0.00

Medium Work In Progress 3/2/2014 12:26:48 AM

Sanchez, Raul Monthly - Santa Teresa HS-Grease Trap (Cul/Auto) - Refer to PM schedule details.

Margret Villalobos

117569 5/28/2014 7 \$0.00

Medium Work In Progress 5/28/2014 10:10:14 AM

Ronquillo, Ruben Break-in ROTC Room 705. Glass on door is completely broken Size is 48"x5-3/8"x1/4" wire glass.

Jaime Mijarez

117183 5/15/2014 20 \$0.00

Medium Work In Progress 5/15/2014 11:48:03 AM

Lara, Ralph front gate padlock needs to be replaced we have a hardtime opening lock

Isaac Holguin

117159 5/14/2014 21 \$0.00

Medium Work In Progress 5/14/2014 3:41:52 PM

Ronquillo, Ruben Requested by Mrs. Harper and Mrs. Rodriguez. The rooms listed get too much sunlight and principals would like to have them coated with a tint film.
Rooms are:
203,300,303,305,307,309,311,302,304,306,308.

Jaime Mijarez

117937 6/3/2014 1 \$0.00

Medium Work In Progress 6/3/2014 2:44:19 PM

Gonzalez, Salvador Need a kubota hitch modified for pulling artificial turf groomer to keep the groomer level as re-positions the needles on the turf.

William Dickson

116895 Football Field 5/8/2014 27 \$0.00

Medium Work In Progress 5/8/2014 2:04:53 PM

Gonzalez, Salvador The gate where trucks deliver needs access hole cut so it can be opened easily access the lock.

William Dickson

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

115341	Main Building	Classroom			4/2/2014		63		\$0.00
Medium	Work In Progress				4/2/2014 8:18:39 AM				
Mijarez, Jaime		Room 600 has a exposed broken plug creating a safety issue. Please check it out and fix. Thanks!							

William Dickson

110077	Main Building	Mechanical			11/8/2013		208		\$0.00
Medium	Work In Progress				11/8/2013 3:38:05 PM				
Ontiveros, Joe		Need to Replaces 1 inch Gas Riser rusted out outside boiler RM.							

Joe Ontiveros

115294	Main Building	Restroom (Girls)			4/1/2014		64		\$0.00
Medium	Work In Progress				4/1/2014 12:30:38 PM				
Ontiveros, Joe		main hallway near library girls restroom last stall not working							

Isaac Holguin

107779	Main Building	Computer Lab			9/20/2013		257		\$0.00
Medium	Work In Progress				9/20/2013 4:59:04 PM				
Mijarez, Jaime		Relocate a white board so students can review their work.							

William Dickson

107780	Main Building	Computer Lab			9/20/2013		257		\$0.00
Medium	Work In Progress				9/20/2013 5:03:05 PM				
Mijarez, Jaime		The classroom that needed the white board moved is C2							

William Dickson

117612	Main Building	Classroom			5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 7:43:18 PM				
Mijarez, Jaime		The following classrooms need blinds, 202, 203, 207, 208, 300, 304, 306, 307, 308, 401, 404, 405, 408, 504, 505, 515, 602, 606, 700, 704, and 803							

William Dickson

117613	Main Building	Classroom			5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 7:53:31 PM				
Mijarez, Jaime		The following classrooms need screens, 201, 203, 205, 207, 209, 211, 213, 300, 302, 303, 304, 305, 306, 307, 308, 309, 311, 401, 403, 405, 407, 409, 410, 500, 505, 502, 504, 507, 508, 511							

William Dickson

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

106456	Main Building	Classroom			8/23/2013		285		\$0.00
--------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	203			8/23/2013 10:56:44 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Ambriz, Jose
The A/C in room 203 is VERY loud!. Teacher has to speak loudly and it's hard to students to hear. Please make this a priority. Thanks.

Kathryn Harper

117075	Main Building	Classroom			5/13/2014		22		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/13/2014 10:57:41 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
Need to get a key changed in the kitchen area. We have some things that are disappearing the from storage.

William Dickson

117182	Main Building	Restroom			5/15/2014		20		\$0.00
--------	---------------	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/15/2014 11:47:00 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph
boys restroom by old gym cord needs to be replaced cannot open

Isaac Holguin

116202	Main Building				4/24/2014		41		\$0.00
--------	---------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/24/2014 9:28:23 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Holguin, Isaac
Mens bathrooms cafeteria and main building, have custodian clean walls thoroughly and detail corners and edges.

Jesus Estrada

115991	Main Building	Classroom			4/16/2014		49		\$0.00
--------	---------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/16/2014 11:32:47 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Escobar, David
Need to place map hooks to hang maps in the following classrooms: 306, 600, 616, 500, 303

William Dickson

113371	Main Building	Classroom			2/13/2014		111		\$0.00
--------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	200 -700			2/13/2014 10:58:52 AM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Escobar, David
Replace mini blinds in 15 classrooms as needed
Paint the classrooms that had smartboards installed

Kathryn Harper

114609	Gymnasium	Hallway/Corridor			3/13/2014		83		\$0.00
--------	-----------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/13/2014 1:53:09 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime
There is a tile next to the concession stand in the gym that has been broken. Need to get it replaced please.

William Dickson

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

111874	Vocational	Classroom			1/9/2014		146		\$0.00
--------	------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				1/9/2014 10:47:57 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime
The kids in studio to cook ceramic is not working. One braked in the box is taped. Please check it out. Thanks.

William Dickson

111875	Vocational	Classroom			1/9/2014		146		\$0.00
--------	------------	-----------	--	--	----------	--	-----	--	--------

Medium	Work In Progress				1/9/2014 10:51:22 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Mijarez, Jaime
Heat will not come on in the clays shop.
Need paper dispenser added to sink area.
Room is covered with spider webs may have a black widow in the area.
Please check out.

William Dickson

115907	Vocational	Electrical Room			4/15/2014		50		\$0.00
--------	------------	-----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/15/2014 7:50:18 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ambriz, Jose
Exhaust fan in voc.build. main electrical room is not working.

Carlos Castillo

111903	Vocational				1/10/2014		145		\$0.00
--------	------------	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/10/2014 1:40:49 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador
Cover small windows on doors that vandals have used to gain access into rooms with expanded metal. Check with site administration or security Telezfor specifics.

Alfredo Holguin

117212	Vocational				5/16/2014		19		\$0.00
--------	------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/16/2014 7:54:01 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos
Need to remove welding 100amp circuit 240volt circuit

Carlos Castillo

107313	Library	Library			9/10/2013		267		\$0.00
--------	---------	---------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Library			9/10/2013 3:37:35 PM				
--------	------------------	---------	--	--	----------------------	--	--	--	--

Mijarez, Jaime
Put pictures of Classes in library on wall.

Kathryn Harper

115924	Library	Library			4/15/2014		50		\$0.00
--------	---------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/15/2014 11:25:15 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Mijarez, Jaime
Thermostat not working needs to be replaced

William Dickson

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

117477 AnnexBuilding 5/23/2014 12 \$0.00

Medium Work In Progress 5/23/2014 3:21:52 PM

Lara, Ralph In need of additional keys for the culinary art classroom MC67. we also have some locks that need keys or need fixing so storage doors can be locked.

William Dickson

117611 AnnexBuilding Custodial 5/28/2014 7 \$0.00

Medium Work In Progress 5/28/2014 7:34:54 PM

Escobar, David White boards to be placed in culinary classroom 707---1 board, 602---1 board, 801---1 board, 803---2 boards

William Dickson

115062 AnnexBuilding 3/26/2014 70 \$0.00

Medium Work In Progress 3/26/2014 10:47:50 AM

Lara, Ralph Door locks needs to be replace in bathroom, replace lock or make key for cabinet #8 on counter desk, Repair handle for file cabinet, Raise desk top computer, move mirror forward, replace carpet with tile, all of this is in the Nurse's office.

William Dickson

115060 AnnexBuilding 3/26/2014 70 \$0.00

Medium Work In Progress 3/26/2014 10:35:47 AM

Mijarez, Jaime The concrete by the steps needs to reinforced. It poses a danger to staff and students when they use the side walk.

William Dickson

109502 Main Building Classroom 10/29/2013 218 \$0.00

Medium Work In Progress 10/29/2013 4:13:17 PM

Mijarez, Jaime Room 215 needs two broom holders monted on the left wall after entering the front door, a pattern is taped to the wall where the holder is to be placed. The hardeare is taped to the pattern. Thge other broom holder patrn is taped on the wall in the storage closet.

William Dickson

116102 Main Building Classroom 4/22/2014 43 \$0.00

Medium Work In Progress 4/22/2014 11:02:14 AM

Lara, Ralph Room 206 has a 6 door filing cabinet that has no keys. The teacher would like to get into the filing cabinet and would also like to use the cabinet. Please help!

William Dickson

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
117675	Main Building	Exterior			5/30/2014		5		\$0.00
Medium	Work In Progress				5/30/2014 1:14:53 PM				
Llanez, Rick		Check water source for pines on Airport							
Kathryn Harper									
117614	Main Building	Classroom			5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 8:08:06 PM				
Ronquillo, Ruben		The following classrooms will need window tint, 203, 300, 302, 303, 304, 305, 306, 307, 308, 309, 311,							
William Dickson									
114503	Locker Room	Office			3/11/2014		85		\$0.00
Medium	Work In Progress				3/11/2014 2:50:04 PM				
Lara, Ralph		Football locker - install locker clasp to 8 lockers with a blue X on it. Lock mechanism.							
William Dickson									
114502	Locker Room	Office			3/11/2014		85		\$0.00
Medium	Work In Progress				3/11/2014 2:32:57 PM				
Escobar, David		Football locker room missing ceiling tiles. Need to get the projector screen screen put up. Fix broken shower tiles.							
William Dickson									
116869	Locker Room				5/7/2014		28		\$0.00
Medium	Work In Progress				5/7/2014 4:09:31 PM				
Castillo, Carlos		Could we get multiple sets of electrical plugs placed in the girls locker room. There are in need of additional outlets							
William Dickson									
108549	Cafeteria (2005)	Restroom			10/7/2013		240		\$0.00
Medium	Work In Progress				10/7/2013 7:45:26 PM				
Mijarez, Jaime		The restroom in the cafeteria needs a paper dispenser. The one that was there is broken.							
William Dickson									
113247	GYM (2009)	Storage			2/10/2014		114		\$0.00
Medium	Work In Progress				2/10/2014 10:29:36 PM				
Ontiveros, Guadalupe		need to move the metal storage from the storage room to the old concession stands.							
William Dickson									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
106341	GYM (2009)	Gym			8/21/2013		287		\$0.00
Medium	Work In Progress	Basketball gym			8/21/2013 11:22:54 AM				
Mijarez, Jaime		Foam rubber edging around basketball backboards in both gyms coming off, needs to be replaced/repaired (see Coach Haack or Coach Dotsen)							
Kathryn Harper									
116259	GYM (2009)	Gym			4/25/2014		40		\$0.00
Medium	Work In Progress				4/25/2014 12:39:16 PM				
Estrada, Jesus		gym floors need to be re done							
Isaac Holguin									
116260	GYM (2009)	Gym			4/25/2014		40		\$0.00
Medium	Work In Progress				4/25/2014 12:40:32 PM				
Lara, Ralph		gym locks need to be changed so gym floors can be done							
Isaac Holguin									
111738					1/7/2014		148		\$0.00
Medium	Work In Progress				1/7/2014 2:48:17 PM				
Ontiveros, Joe		caffeteria kitchen could not locate a shut off water valve for 3/8 water line to make up air system for kitchen hood. Will need to install a shut off valve. water line burst during holiday break and couldn't shut off water due to no shut off valve present.							
David Escobar									
108657		Kitchen			10/9/2013		238		\$0.00
Medium	Work In Progress				10/9/2013 10:07:49 PM				
Mijarez, Jaime		Culinary Arts Kitchen needs 2 leg table attached to the wall in dish room.							
William Dickson									
108659		Kitchen			10/9/2013		238		\$0.00
Medium	Work In Progress				10/9/2013 10:10:33 PM				
Mijarez, Jaime		Culinary Arts Kitchen attach self to the wall see teacher for directions							
William Dickson									
110010					11/7/2013		209		\$0.00
Medium	Work In Progress				11/7/2013 8:07:10 AM				
Ontiveros, Joe		Gas line outside by 300 wing boiler room is cracked. Needs to be repaired before we get colder weather. Gas line supplies to the 300 wing hydraunic heating system boiler.							
Jaime Mijarez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
117561		Custodial			5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 8:50:59 AM				
Carbajal, Jimmy		gray carpet cleaner 0002261 needs to be fixed							
Isaac Holguin									
117562		Custodial			5/28/2014		7		\$0.00
Medium	Work In Progress				5/28/2014 8:52:13 AM				
Carbajal, Jimmy		gray carpet cleaner need to be fixed 009909							
Isaac Holguin									
117074		Custodial			5/13/2014		22		\$0.00
Medium	Work In Progress				5/13/2014 10:04:01 AM				
Carbajal, Jimmy		auto scrubber needs new batteries doesnt hold charge 11634900							
Isaac Holguin									
117122					5/14/2014		21		\$0.00
Medium	Work In Progress				5/14/2014 8:01:37 AM				
Ontiveros, Joe		Main hallway restroom chase. There is a lot water leaking.							
Jaime Mijarez									
117160					5/14/2014		21		\$0.00
Medium	Work In Progress				5/14/2014 3:43:35 PM				
Ontiveros, Joe		plumbing to a toilet in girls rr needs to be fixed.							
David Escobar									
117079					5/13/2014		22		\$0.00
Medium	Work In Progress				5/13/2014 12:38:46 PM				
Ontiveros, Joe		We have a ground water leak behind the football concession stand and fence line. We need Joe to do the water line locating and his assistance.							
Jaime Mijarez									
117086					5/13/2014		22		\$0.00
Medium	Work In Progress				5/13/2014 2:24:18 PM				
Ontiveros, Joe		We have two stalls in the females bathroom that are broken and when flushed will spill water all over the floor and into the hallway. Need a plumber.							
William Dickson									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa HS							
115198					3/31/2014		65		\$0.00
Medium	Work In Progress				3/31/2014 12:54:13 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS A-16 Roof/Exh Semiannual - Refer to PM schedule details.							
Margret Villalobos									
112662					1/30/2014		125		\$0.00
Medium	Work In Progress				1/30/2014 3:19:19 PM				
Mijarez, Jaime		Marylou Jimenez is requesting paint for the vault door in her office.							
Jaime Mijarez									
113018					2/5/2014		119		\$0.00
Medium	Work In Progress				2/5/2014 11:13:13 AM				
Mijarez, Jaime		Councilors and 700 wing heating units. Please order 10 ea. fan/limit combo controls. We need 4 and the other 6 will stay with Joe and Lorenzo. Renznor HU.							
Jaime Mijarez									
111909					1/10/2014		145		\$0.00
Medium	Work In Progress				1/10/2014 2:26:29 PM				
Mijarez, Jaime		Asp PM serviced by Dimar - need to add oil and rotate FDC.							
Michael Munoz									
111913					1/10/2014		145		\$0.00
Medium	Work In Progress				1/10/2014 2:30:03 PM				
Mijarez, Jaime		Asp PM serviced by Dimar - FAC cap missing in 200 Wing							
Michael Munoz									
111914					1/10/2014		145		\$0.00
Medium	Work In Progress				1/10/2014 2:30:43 PM				
Mijarez, Jaime		Asp PM serviced by Dimar - FAC cap missing in 300 Wing							
Michael Munoz									
105592					8/7/2013		301		\$0.00
Medium	Work In Progress				8/7/2013 12:52:27 PM				
Mijarez, Jaime		Asp inspection on PM Fire Sprinkler by Dimar the following was found: FDC missing cap							
Michael Munoz									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
104626					7/23/2013		316		\$0.00
Medium	Work In Progress				7/23/2013 2:12:58 PM				
Mijarez, Jaime		Will need to replace ceiling tiles in several gym dressing rooms. Ceiling tile is a different texture can you please order 4 ea. Bundles of the sample that I gave you or at least match it.							
Jaime Mijarez									
107284		Library			9/10/2013		267		\$0.00
Medium	Work In Progress				9/10/2013 8:38:41 AM				
Mijarez, Jaime		Library - The security mirror in the back of the library needs to be hung.							
William Dickson									
115400		Classroom			4/3/2014		62		\$0.00
Medium	Work In Progress	MRS.			4/3/2014 11:54:00 AM				
Mijarez, Jaime		I HAVE A COUPLE OF TILES COMING UNGLUED ON FLOOR. THIS IS A SPED CLASS AND HAZARDOUS TO STUDENTS.							
Marylou Jimenez									
116262		Classroom			4/25/2014		40		\$0.00
Medium	Work In Progress	MRS.			4/25/2014 1:11:33 PM				
Mijarez, Jaime		PLEASE INSTALL BLINDS ON WINDOW FOR ROOM #202							
Marylou Jimenez									
115621					4/6/2014	4/12/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:12 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
115822					4/13/2014	4/29/2014	52		\$0.00
Medium	Work In Progress				4/13/2014 12:24:09 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS A-4 Comp Air Semiannual - Refer to PM schedule details.							
Margret Villalobos									
116649					5/4/2014	5/10/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:45 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa HS									
116560					5/4/2014	5/7/2014	31		\$0.00
Medium	Work In Progress			5/4/2014 12:37:44 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PMschedule details.								
Margret Villalobos									
116587					5/4/2014		31		\$0.00
Medium	Work In Progress			5/4/2014 12:38:03 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PMschedule details.								
Margret Villalobos									
117737					6/1/2014	6/4/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:53:45 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PMschedule details.								
Margret Villalobos									
117610					5/28/2014		7		\$0.00
Medium	Work In Progress			5/28/2014 7:20:47 PM					
Mijarez, Jaime	The following rooms need painting, 202, 206, 208, 212, 303, 306, 401, 500 hallway, 505, 515 600, 610, 614, 704, 801, C-1, C-2, C-3, Nurse's office								
William Dickson									
117770					6/1/2014		3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:06 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PMschedule details.								
Margret Villalobos									
117747					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:53:51 AM					
Mijarez, Jaime	Yearly - Santa Teresa HS B-2 Boiler Yearly - Refer to PMschedule details.								
Margret Villalobos									
117850					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress			6/1/2014 12:54:58 AM					
Mijarez, Jaime	Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PMschedule details.								
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa HS

113197 Gym 2/10/2014 114 \$0.00

Medium Work In Progress 2/10/2014 11:15:16 AM

Munoz, Michael
 New Gym Lobby concession stand. (Please give w/o to Mike Munoz and a copy to Alfredo H). Can we have a new candy/snack shelve built and installed in the new concession stand. I spoke to Mrs. Harper and told her that I would get with Mike and Alfredo and see if we could go that route instead of having to sand and repainting the old gym concession stand wooden shelve that we installed. Please call me for more info.

Jaime Mijarez

111325 12/16/2013 170 \$0.00

Medium Work In Progress 12/16/2013 4:00:06 PM

Munoz, Michael
 Old gym bleachers. Please give work order to (Alfredo H.) I spoke to him. Wood swinging boards that run along the bottom of the bleachers are missing several pins on the hindges, The boards are uneven and won't stay flush with each other. I don't know when was the last time they were serviced.
 3/26/14
 Margret I believe Mike will be addressing this with AK Sales Please reassign WO asp A. Holguin.

Jaime Mijarez

117441 5/22/2014 13 \$0.00

Medium Work In Progress 5/22/2014 1:23:04 PM

Flores, Pete
 The band truck does not want to start. We need it to transfer music equipment from place to place.
 Thank You

William Dickson

110332 11/16/2013 200 \$0.00

Medium Work In Progress 11/16/2013 12:18:10

Flores, Pete
 Yearly - Santa Teresa HS - Mower 0425 - Grounds - Refer to PM schedule details.

Margret Villalobos

116241 Athletic Field 4/25/2014 40 \$0.00

Medium Work In Progress 4/25/2014 7:39:38 AM

Flores, Pete
 boys baseball. john deere 155 from the el paso optimist club(cloud view park) was donated to coach bailon. he wouldlike to use it to drag his field, however it needs tires and a service. talked to alfredo and he gave the ok for the tires and service.

Michael Munoz

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa HS									
116564					5/4/2014	5/20/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:37:46 AM				
Villalobos, Margret		Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.				Emailed 5/5/14			
Margret Villalobos									
116595					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:09 AM				
Flores, Pete		Monthly - STH-UV-0517 PM Service - Refer to PM schedule details.							
Margret Villalobos									
117755					6/1/2014	6/17/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:57 AM				
Villalobos, Margret		Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.							
Margret Villalobos									
115663					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:39 AM				
Munoz, Michael		Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
114932		Gym			3/21/2014		75		\$0.00
Medium	Work In Progress				3/21/2014 4:17:38 PM				
Munoz, Michael		PM - Annual Bleacher Service performed by A.K. Sales.							
Michael Munoz									
113248		Exterior			2/10/2014		114		\$0.00
Medium	Work In Progress				2/10/2014 10:32:42 PM				
Gonzalez, Salvador		The fence behind the vocational room needs repair. As a matter of fact the entire fence row needs attention. There are several holes in it.							
William Dickson									
Count: 132 Work Orders		Avg. Age of WO's 77		Total for Santa Teresa HS		0	0	\$0.00	

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
114934		Gym			3/21/2014		75		\$0.00
Medium	Work In Progress			3/21/2014 4:19:40 PM					
Munoz, Michael	PM - Annual Bleacher Service performed by A.K. Sales.								
Michael Munoz									
114703		Classroom			3/17/2014		79		\$0.00
Medium	Work In Progress			3/17/2014 1:41:56 PM					
Prospero, Manuel	TROBLE SHUTRING LAB TAB TRACER SUMER A.P. ADRESSES.								
Manuel Prospero									
113270		Classroom			2/11/2014		113		\$0.00
Medium	Work In Progress			2/11/2014 2:39:38 PM					
Prospero, Manuel	WE NEED CHENGED AIR FILTERS ALL BUILDINGS AND PORTABLES.								
Manuel Prospero									
114005					3/2/2014		94		\$0.00
Medium	Work In Progress			3/2/2014 12:26:02 AM					
Prospero, Manuel	Yearly - Santa Teresa MS A10 (Heat Pump)(Yearly) - Refer to PMschedule details.								
Margret Villalobos									
115476					4/6/2014	4/22/2014	59		\$0.00
Medium	Work In Progress			4/6/2014 12:30:21 AM					
Prospero, Manuel	Monthly - Santa Teresa MS A1(Wall Refr.E/H)(Semi) - Refer to PMschedule details.								
Margret Villalobos									
115519					4/6/2014	4/14/2014	59		\$0.00
Medium	Work In Progress			4/6/2014 12:30:58 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Roof Inspection - Refer to PMschedule details.								
Margret Villalobos									
116591					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress			5/4/2014 12:38:06 AM					
Prospero, Manuel	Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PMschedule details.								
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
116589					5/4/2014	5/12/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:05 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
116590					5/4/2014	6/4/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:05 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
116588					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:04 AM				
Prospero, Manuel		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
116658					5/4/2014	5/10/2014	31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:51 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
117827					6/1/2014	7/2/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:44 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
117828					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:44 AM				
Prospero, Manuel		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
117826					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:43 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa MS							
117825					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:42 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
117848					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:57 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
115680					4/7/2014		58		\$0.00
Medium	Work In Progress				4/7/2014 12:12:19 PM				
Soria, Mike		please clean lila tree as discussed. thank you							
Michael Munoz									
110331					11/16/2013		200		\$0.00
Medium	Work In Progress				11/16/2013 12:18:09				
Flores, Pete		Yearly - Santa Teresa MS - Mower 0416 - Grounds - Refer to PM schedule details.							
Margret Villalobos									
117823					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:41 AM				
Flores, Pete		Monthly - STM-UV-0518 PM Service - Refer to PM schedule details.							
Margret Villalobos									
115246					3/31/2014		65		\$0.00
Medium	Work In Progress				3/31/2014 3:16:37 PM				
Ontiveros, Joe		please meet with dean cd mechanical to discuss water shut offs for fire hydrants.							
Michael Munoz									
117308	North Building	Football Field			5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 8:39:35 AM				
Carrasco, Danny		Fuel for Mr.Soria							
Ismael Rodriguez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

114426	North Building	Custodial			3/10/2014		86		\$0.00
--------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				3/10/2014 8:11:37 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos Set the custdian morgan building with electricity for the Gator thanks.

Ismael Rodriguez

116308	North Building	Custodial			4/28/2014		37		\$0.00
--------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/28/2014 11:15:25 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Castillo, Carlos Install securitylights bythe building morgans.

Ismael Rodriguez

107746	North Building	Office			9/20/2013		257		\$0.00
--------	----------------	--------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	ROOM 8			9/20/2013 1:50:16 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Marquez, Gerardo NEED KEY FOR CABINET LOCATED OUTSIDE NURSES OFFICE

Laura Parra

115909	North Building	Custodial			4/15/2014		50		\$0.00
--------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				4/15/2014 8:02:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Carrasco, Danny We need a 2 inch ball for BM polaris to hall trailers...

Ismael Rodriguez

117307	North Building	Custodial			5/20/2014		15		\$0.00
--------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/20/2014 8:38:15 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Carrasco, Danny Fuel for truck #88

Ismael Rodriguez

111910	North Building	Classroom			1/10/2014		145		\$0.00
--------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	20			1/10/2014 2:27:34 PM				
--------	------------------	----	--	--	----------------------	--	--	--	--

Ontiveros, Joe LEAKY FAUCET

Laura Parra

112443	North Building	Classroom			1/24/2014		131		\$0.00
--------	----------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				1/24/2014 12:40:37 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ontiveros, Joe WE NEED TO CHANGED 6 WATER FOUSET ON ROOM 10 AND TRAMPS.

Manuel Prospero

113250	North Building	Football Field			2/11/2014		113		\$0.00
--------	----------------	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				2/11/2014 8:19:14 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Soria, Mike Clean along the fence coming down the hill south building custodians are going to help.

Ismael Rodriguez

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Santa Teresa MS							
116045	North Building	Exterior			4/17/2014		48		\$0.00
Medium	Work In Progress				4/17/2014 12:51:39 PM				
Soria, Mike		Mike clean around the tree thats behind south building and trim the tree.							
Ismael Rodriguez									
116833	North Building	Classroom			5/7/2014		28		\$0.00
Medium	Work In Progress				5/7/2014 10:12:23 AM				
Ambriz, Jose		North Buildig upper level classroom #22 the a.c is not working properly need to be check.							
Ismael Rodriguez									
117668	North Building	Classroom			5/30/2014		5		\$0.00
Medium	Work In Progress				5/30/2014 11:39:57 AM				
Ambriz, Jose		Check North building upper and lower level air conditioning for summer program starting June 2 2014 thru June 24 2014 as per principal thanks.							
Ismael Rodriguez									
115387	North Building	Football Field			4/3/2014		62		\$0.00
Medium	Work In Progress				4/3/2014 8:51:36 AM				
Ontiveros, Guadalupe		Lupe as per Mr.Soria he needs white paint to paint soccer goals.							
Ismael Rodriguez									
115882	North Building				4/14/2014		51		\$0.00
Medium	Work In Progress				4/14/2014 3:32:07 PM				
Ontiveros, Guadalupe		Will need trenching from Rafa's mobile home service to new storage.							
Carlos Castillo									
114427	North Building				3/10/2014		86		\$0.00
Medium	Work In Progress				3/10/2014 8:25:29 AM				
Ontiveros, Joe		As per Mr.Soria he needs the plumer to run water near his morgan.							
Ismael Rodriguez									
117006	North Building	Restroom			5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 11:27:21 AM				
Lara, Ralph		Need to install urinal side panels in boys restrooms in North and South building as per Principal.							
Ismael Rodriguez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Santa Teresa MS

116994	North Building	Classroom			5/12/2014		23		\$0.00
Medium	Work In Progress	1-MEISTER			5/12/2014 9:45:05 AM				
Lara, Ralph		REKEY STORAGE CLOSET TO LOCK UP ART SUPPLIES							
Laura Parra									

117962	North Building	Office			6/4/2014		0		\$0.00
Medium	Work In Progress				6/4/2014 7:24:11 AM				
Lara, Ralph		Replace doors in north office there in bad shape as per principal thanks..							
Ismael Rodriguez									

117961	North Building	Classroom			6/4/2014		0		\$0.00
Medium	Work In Progress				6/4/2014 6:30:15 AM				
Villalobos, Margret		Need pest control to fumigate north and south building roaches and critters are coming out and rodents.							
Ismael Rodriguez									

112282	North Building	Portables			1/21/2014		134		\$0.00
Medium	Work In Progress				1/21/2014 11:15:26 AM				
Prospero, Manuel		Portable 2a the heater is not working properly need to be check.							
Ismael Rodriguez									

106730	South Building	Classroom			8/29/2013		279		\$0.00
Medium	Work In Progress	ROOM 46			8/29/2013 11:11:17 AM				
Prospero, Manuel		WHITE BOARD IS COMING OFF WALL							
Laura Parra									

114555	South Building	Classroom			3/12/2014		84		\$0.00
Medium	Work In Progress				3/12/2014 10:15:08 AM				
Lara, Ralph		Rafa, also Ms.Gold needs a key for her filing cabnit to secure her testing material.							
Ismael Rodriguez									

117922	South Building	Classroom			6/3/2014		1		\$0.00
Medium	Work In Progress				6/3/2014 11:45:32 AM				
Ronquillo, Ruben		Science Room #52 has a broken glass in a shelf need to be repair for safety.							
Ismael Rodriguez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
Location: Santa Teresa MS									
116196	South Building	Restroom			4/24/2014		41		\$0.00
Medium	Work In Progress			4/24/2014 8:14:50 AM					
Ontiveros, Joe	WATER FAUSET ON CONCELORS OFFICE IS LEAKING.								
Manuel Prospero									
112526	South Building	Classroom			1/28/2014		127		\$0.00
Medium	Work In Progress	35-BREITLING		1/28/2014 2:27:20 PM					
Castillo, Carlos	1-NEE4D ELECTRICAL OUTLET FOR SMARTBOARD AND PROJECTOR								
Laura Parra									
116250	Gym (1997)	Gym			4/25/2014		40		\$0.00
Medium	Work In Progress			4/25/2014 8:41:36 AM					
Estrada, Jesus	Resurface gym floor during summer 2014 on this date 7-14-14 thru 7-25-14 thank you.								
Ismael Rodriguez									
116251	Gym (1997)	Gym			4/25/2014		40		\$0.00
Medium	Work In Progress			4/25/2014 8:44:37 AM					
Lara, Ralph	Change locks in the gym on this date 7-11-14.								
Ismael Rodriguez									
109966	Gym (1997)	Gym			11/6/2013		210		\$0.00
Medium	Work In Progress			11/6/2013 11:11:20 AM					
Prospero, Manuel	As per administration basketball courts lanes outside the gym need to be painted there are faded and are use for basketball practice.								
Ismael Rodriguez									
111493					1/5/2014	2/5/2014	150		\$0.00
Medium	Work In Progress			1/5/2014 12:23:25 AM					
Villalobos, David	Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
115653					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress			4/6/2014 12:32:32 AM					
Orozco, Daniel	Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Santa Teresa MS									
112591					1/29/2014		126		\$0.00
High	Work In Progress				1/29/2014 11:18:07 AM				
Ontiveros, Guadalupe		We need the dirt under ramps in portables 1 and 2 removed before the winds start kicking up, the accumulation of dirt has reached the top of ramps and is going into portables.							
117964		Athletic Field			6/4/2014		0		\$0.00
Medium	Work In Progress				6/4/2014 8:20:52 AM				
Ontiveros, Guadalupe		Mike Soria needs gas for gator and diesel for mower.							
Guadalupe Ontiveros									
Count: 52 Work Orders			Avg. Age of WO's	66		Total for Santa Teresa MS	0		\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunland Park ES							
113493					2/18/2014		106		\$0.00
Medium	Work In Progress				2/18/2014 3:08:43 PM				
Ontiveros, Guadalupe		soccer feild needs to be arreated and fertilized							
Carlos Hernandez									
116490					5/1/2014		34		\$0.00
Medium	Work In Progress				5/1/2014 1:51:03 PM				
Orozco, Daniel		SLICER IS NOT WORKING. SNP MANAGER IGNACIA C. 589.2545							
Maritza Gonzalez									
115654					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:33 AM				
Orozco, Daniel		Monthly- Sunland Park ES Range Hood Cleaning - Refer to PMs schedule details.							
Margret Villalobos									
117688					5/30/2014		5		\$0.00
Medium	Work In Progress				5/30/2014 3:15:52 PM				
Carrasco, Danny		need 10 gal gas lawn mower							
Carlos Hernandez									
115914					4/15/2014		50		\$0.00
Medium	Work In Progress				4/15/2014 10:20:54 AM				
Carrasco, Danny		need 5 one waysigns							
Carlos Hernandez									
113223					2/10/2014		114		\$0.00
Medium	Work In Progress				2/10/2014 3:10:42 PM				
Holguin, Alfredo		as per alfredo need playground sand removed and replaced with engineered wood fiber (its at total of 9 playground equipment and 50 border need replacement							
Carlos Hernandez									
114443					3/10/2014		86		\$0.00
Medium	Work In Progress				3/10/2014 12:53:51 PM				
Castillo, Carlos		there are 9 primeriter lights that need replaced							
Carlos Hernandez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

117317					5/20/2014		15		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				5/20/2014 11:15:20 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Hernandez, Carlos need brown mulch color paint to paint portables
need navy blue paint for turn around
(summer projects)

Carlos Hernandez

117762					6/1/2014	7/2/2014	3		\$0.00
--------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				6/1/2014 12:54:01 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Carlos Yearly - Sunland Park ES B-2 Boiler Yearly - Refer to
PMschedule details.

Margret Villalobos

117799					6/1/2014	6/9/2014	3		\$0.00
--------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				6/1/2014 12:54:25 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Carlos Monthly - Sunland Park ES Exit Sign Insp: Monthly -
Refer to PMschedule details.

Margret Villalobos

117800					6/1/2014	6/9/2014	3		\$0.00
--------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				6/1/2014 12:54:26 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Carlos Monthly - Sunland Park ES Emer Light Test: Monthly -
Refer to PMschedule details.

Margret Villalobos

117860					6/1/2014	6/7/2014	3		\$0.00
--------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				6/1/2014 12:55:05 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Hernandez, Carlos Monthly - Sunland Park ES Monthly FE Inspection -
Refer to PMschedule details.

Margret Villalobos

116973					5/11/2014	5/27/2014	24		\$0.00
--------	--	--	--	--	-----------	-----------	----	--	--------

Medium	Work In Progress				5/11/2014 12:24:42 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Hernandez, Carlos Monthly - Sunland Park ES Playground Insp - Refer to
PMschedule details.

Margret Villalobos

117082					5/13/2014		22		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	OFFICE			5/13/2014 1:30:10 PM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Hernandez, Carlos CARLOS -
AS APPROVED BY MS. DUQUE - PLEASE PICK UP
RISERS FOR MS. CHAVEZ FROM THE MUSIC
TEACHERS AT STHS AND RIVERSIDE ELEM.
THANK YOU.

David Avila

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Sunland Park ES

113364 2/13/2014 111 \$0.00

Medium Work In Progress 2/13/2014 8:59:02 AM

Castillo, Carlos need power run to a/c unit portable f

Carlos Hernandez

117260 5/19/2014 16 \$0.00

Medium Work In Progress PORTABLE C 5/19/2014 12:48:24 PM

Gonzales, Camilo Please move the following equipment: 2 wooden chairs, a blue stander, a wheelchair, a ball and 2 loose nets to the storage portable for the PT at the SPED Office. They are located near the entrance of the portable and will be labeled.

Margaret Villalobos

117875 6/2/2014 2 \$0.00

Medium Work In Progress 6/2/2014 8:26:50 AM

Ronquillo, Ruben need window replaced 23 1/4 x 18 1/4 wire glass single pane portable f

Carlos Hernandez

115241 3/31/2014 65 \$0.00

Medium Work In Progress 3/31/2014 2:50:22 PM

Gallegos, Rafael AS PER ENVIRONMENT INSPECTION REPORT ON MARCH 31, 2014. 1.) SPRING LOADED FAUCETS NOT ALLOWED ANYMORE, PROVIDE LEVER FAUCET, EMPLOYEE RESTROOM HAS SPRING LOADED FAUCET. 2.) INSUFFICIENT BACK DOOR SEALS TO DOOR. 3.) DRY STORAGE CEILING HAS TILES THAT DONT MEET SMOOTH DEFENITION. 4.) DIM BULBS IN FREEZER (DANNY REPLACED).

Maritza Gonzalez

115391 4/3/2014 62 \$0.00

Medium Work In Progress 4/3/2014 10:41:17 AM

Gallegos, Rafael SEAL IS OFF ON THE BOTTOM OF 3 COMPARTMENT SINK, WATER LEAKS WHEN TRYING TO WASH.

Maritza Gonzalez

117506 5/27/2014 8 \$0.00

Medium Work In Progress 5/27/2014 9:53:33 AM

Ronquillo, Ruben need glass repaired due to vandalism portable f 22 3/4 x 18 1/4 single pane window wire glass

Carlos Hernandez

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location:		Sunland Park ES							
117893	Main Building	Office			6/2/2014		2		\$0.00
Medium	Work In Progress				6/2/2014 10:39:35 AM				
Briones, Enrique	Deliver total of 22 bxs. Math K-6th Eng/Span Workbooks.								
Theresa Ramirez									
107040					9/4/2013		273		\$0.00
Medium	Work In Progress	TEACHER'S			9/4/2013 7:57:55 AM				
Ontiveros, Joe	AS PER MS. DUQUE----- NEED TO HAVE SINK INSTALLED IN THE TEACHER'S LOUNGE. PLEASE SEE MS. DUQUE ABOUT THIS IF THERE ARE ANY QUESTIONS. THANK YOU.								
David Avila									
116363					4/29/2014		36		\$0.00
Medium	Work In Progress	SPECIAL ED -			4/29/2014 1:15:57 PM				
Ontiveros, Joe	CARLOS- NEED TO HAVE WASHER AND DRYER CHECKED. THEY ARE NOT WORKING PROPERLY. THANK YOU.								
David Avila									
117016					5/12/2014		23		\$0.00
Medium	Work In Progress				5/12/2014 12:58:48 PM				
Ontiveros, Joe	need repair water line going to portable leaking								
Carlos Hernandez									
117387					5/21/2014		14		\$0.00
Medium	Work In Progress				5/21/2014 3:26:51 PM				
Flores, Pete	small tractor 440 has front flat tire needs repair								
Carlos Hernandez									
116311					4/28/2014		37		\$0.00
Medium	Work In Progress				4/28/2014 11:28:41 AM				
Lara, Ralph	custodial closet won't unlock north side								
Carlos Hernandez									
Count: 26 Work Orders		Avg. Age of WO's 45		Total for Sunland Park ES			0	\$0.00	

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunrise ES							
113087					2/6/2014		118		\$0.00
Medium	Work In Progress				2/6/2014 3:07:02 PM				
Flores, Pete		need fix gas tank have leck							
Juan Vargas									
115023					3/25/2014		71		\$0.00
Medium	Work In Progress				3/25/2014 2:35:14 PM				
Estrada, Jesus		portable # 2 need replace the flor tile the tile has raised the students teachers and student slip							
Juan Vargas									
115024					3/25/2014		71		\$0.00
Medium	Work In Progress				3/25/2014 2:39:22 PM				
Estrada, Jesus		library need replace carpet o repair front part							
Juan Vargas									
114943					3/24/2014		72		\$0.00
Medium	Work In Progress				3/24/2014 10:01:59 AM				
Vargas, Juan		need paint all boys and grls. r.rooms							
Juan Vargas									
114944					3/24/2014		72		\$0.00
Medium	Work In Progress				3/24/2014 10:03:53 AM				
Vargas, Juan		need to paint rooms 310 206 203							
Juan Vargas									
117811					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:33 AM				
Vargas, Juan		Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
117810					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:32 AM				
Vargas, Juan		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
117809					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:31 AM				
Vargas, Juan		Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
117852					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:59 AM				
Vargas, Juan		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
117751					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:54 AM				
Vargas, Juan		Monthly - Sunrise ES A-6 Quarterly PUG - Refer to PM schedule details.							
Margret Villalobos									
117749					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:53 AM				
Vargas, Juan		Monthly - Sunrise ES C-6 Quarterly HP - Refer to PM schedule details.							
Margret Villalobos									
117750					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:53 AM				
Vargas, Juan		Monthly - Sunrise ES C-4 Quarterly SS - Refer to PM schedule details.							
Margret Villalobos									
117748					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:53:52 AM				
Vargas, Juan		Monthly - Sunrise ES A-11 Quarterly ERV - Refer to PM schedule details.							
Margret Villalobos									
116982					5/11/2014	5/27/2014	24		\$0.00
Medium	Work In Progress				5/11/2014 12:24:49 AM				
Vargas, Juan		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
116944					5/9/2014		26		\$0.00
Medium	Work In Progress				5/9/2014 12:57:14 PM				
Vargas, Juan		need remove library furniture for instaled new carpet							
Juan Vargas									
116945					5/9/2014		26		\$0.00
Medium	Work In Progress				5/9/2014 1:03:02 PM				
Vargas, Juan		need 20 glls. paint to library walls painting							
Juan Vargas									

6/4/2014 1:35:14 PM

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
Location: Sunrise ES									
117845					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:55 AM				
Apodaca, Mario	Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
116795					5/6/2014		29		\$0.00
Medium	Work In Progress				5/6/2014 3:24:20 PM				
Solis, Lorenzo	need replace or fix water fonting nex to cafeteria compresor not work								
Juan Vargas									
116646					5/4/2014		31		\$0.00
Medium	Work In Progress				5/4/2014 12:38:43 AM				
Apodaca, Mario	Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									
117890	Main Building	Office			6/2/2014		2		\$0.00
Medium	Work In Progress				6/2/2014 10:21:30 AM				
Briones, Enrique	Deliver a total of 25 bxs; (24) Math k_6th Eng/Span Workbooks, (1) Science Material.								
Theresa Ramirez									
117129	Main Building	Cafeteria			5/14/2014		21		\$0.00
Medium	Work In Progress				5/14/2014 11:05:24 AM				
Carbajal, Jimmy	Royal upright vacuum cleaner foot release pin is worn out and wont let vaumm bag stay in upright position.								
Felipe Gallegos									
117328					5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 3:08:22 PM				
Lara, Ralph	need fix file gabinet lock in room 301								
Juan Vargas									
116952					5/9/2014		26		\$0.00
Medium	Work In Progress				5/9/2014 2:13:43 PM				
Vallejo, Albert	need instaled 120 volts outlet in library for a./c unite								
Juan Vargas									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Sunrise ES							
113791					2/25/2014		99		\$0.00
Medium	Work In Progress				2/25/2014 3:36:08 PM				
Holguin, Alfredo		I have two playground areas Northside 100x90 Southside 120x100 need repair of plastic borders.							
Juan Vargas									
114652					3/14/2014		82		\$0.00
Medium	Work In Progress				3/14/2014 1:59:37 PM				
Vallejo, Albert		recovery ventilator need replace contactor and 4L 620 velts							
Juan Vargas									
115097					3/26/2014		70		\$0.00
Medium	Work In Progress				3/26/2014 4:29:52 PM				
Orozco, Daniel		WASHER DIED, STOPPED WORKING ON THE RINSE CYCLE AND WILL NOT GO BACK ON . SNP MANAGER GLENDA G. 824.3194							
Maritza Gonzalez									
115432					4/4/2014		61		\$0.00
Medium	Work In Progress				4/4/2014 7:49:38 AM				
Orozco, Daniel		. I WOULD LIKE TO PUT ONE IN FOR MY LAUNDRY ROOM. I HAVE SEVERAL WALLS WITHOUT THEM AND ON ONE OF THE WALLS THE SHEETROCK IS WET AND COMING APART. I SHOWED THE SCHOOLS MAINTANCE MAN AND HE THINKS THAT MY DRAIN BASIN HAS A CRACK IN IT AND THAT IS WHY IT IS LIKE THAT WAY. SNP MANAGER GLENDA G. 824.3194							
Maritza Gonzalez									
115655					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:34 AM				
Orozco, Daniel		Monthly- Sunrise ES Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									
116927					5/9/2014		26		\$0.00
Medium	Work In Progress				5/9/2014 9:11:26 AM				
Orozco, Daniel		BOTTOM RIGHT OVEN, BLOWER NOT WORKING. SNP MANAGER GLENDA G. 824.3194							
Maritza Gonzalez									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Sunrise ES									
117180					5/15/2014		20		\$0.00
Medium	Work In Progress				5/15/2014 10:21:03 AM				
Orozco, Daniel		BACK DOOR TRIM CAME OFF. SNP MANAGER							
Maritza Gonzalez		GLENDAG. 824.3194							
115126					3/27/2014		69		\$0.00
Medium	Work In Progress				3/27/2014 3:21:31 PM				
Appelzoller, Fred		outside water founting need fix or replace							
Juan Vargas									
112022					1/13/2014		142		\$0.00
Medium	Work In Progress				1/13/2014 3:25:37 PM				
Ontiveros, Guadalupe		need fix 2 in. sprinkler valve							
Juan Vargas									
111927					1/10/2014		145		\$0.00
Medium	Work In Progress				1/10/2014 3:12:34 PM				
Ontiveros, Guadalupe		need replace 6 tress							
Juan Vargas									
106424					8/22/2013		286		\$0.00
Medium	Work In Progress				8/22/2013 3:36:46 PM				
Marquez, Gerardo		marqui need replace locks							
Juan Vargas									
114338					3/6/2014		90		\$0.00
Medium	Work In Progress				3/6/2014 3:24:38 PM				
Ontiveros, Guadalupe		need grass sed for athletic. field							
Juan Vargas									
114942					3/24/2014		72		\$0.00
Medium	Work In Progress				3/24/2014 9:58:58 AM				
Ontiveros, Guadalupe		needn 10 tons crashionfine for portables rain gaters							
Juan Vargas									
109922					11/5/2013		211		\$0.00
Medium	Work In Progress				11/5/2013 3:18:06 PM				
Ontiveros, Guadalupe		need 12 tons lavo stone in front parking pond							
Juan Vargas									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location:		Sunrise ES							
117135					5/14/2014		21		\$0.00
Medium	Work In Progress				5/14/2014 12:31:45 PM				
Carbajal, Jimmy		Royal upright vacuum cleaner SER# 3409 will not engage at foot handle release pedal. Please replace/repair.							
Felipe Gallegos									
Count: 38 Work Orders		Avg. Age of WO's	55			Total for Sunrise ES	0	0	\$0.00

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Vado ES							
115684					4/7/2014		58		\$0.00
Medium	Work In Progress				4/7/2014 2:27:27 PM				
Ontiveros, Guadalupe		need fertilizer for grounds							
Danny Miranda									
105493					8/6/2013		302		\$0.00
Medium	Work In Progress				8/6/2013 12:07:19 PM				
Marquez, Gerardo		need to replace back door to kitchen							
Danny Miranda									
105494					8/6/2013		302		\$0.00
Medium	Work In Progress				8/6/2013 12:10:54 PM				
Marquez, Gerardo		need to replace back door going to bus exit							
Danny Miranda									
112074					1/14/2014		141		\$0.00
Medium	Work In Progress				1/14/2014 11:41:34 AM				
Marquez, Gerardo		need to change core from 200-w/r to roon 202 storage							
Danny Miranda									
115656					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:32:34 AM				
Orozco, Daniel		Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
115492					4/6/2014	4/27/2014	59		\$0.00
Medium	Work In Progress				4/6/2014 12:30:35 AM				
Orozco, Daniel		Monthly - Vado ES F-39 Kitchen Exh Unit Semiannual - Refer to PM schedule details.							
Margret Villalobos									
116821					5/7/2014		28		\$0.00
Medium	Work In Progress				5/7/2014 7:27:11 AM				
Carrasco, Danny		need something to kill alfalfa comming up over taking grass							
Danny Miranda									
117624					5/29/2014		6		\$0.00
Medium	Work In Progress				5/29/2014 8:03:50 AM				
Miranda, Danny		need to remove mold from walls where white boards were removed							
Danny Miranda									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location:		Vado ES							
117625					5/29/2014		6		\$0.00
Medium	Work In Progress				5/29/2014 8:05:21 AM				
Miranda, Danny		need to sprayroundup							
Danny Miranda									
117495					5/27/2014		8		\$0.00
Medium	Work In Progress				5/27/2014 8:03:26 AM				
Miranda, Danny		need to remove white boards for new smart boards							
Danny Miranda									
117803					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:28 AM				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
117802					6/1/2014	6/9/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:27 AM				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
117801					6/1/2014		3		\$0.00
Medium	Work In Progress				6/1/2014 12:54:26 AM				
Miranda, Danny		Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
117859					6/1/2014	6/7/2014	3		\$0.00
Medium	Work In Progress				6/1/2014 12:55:04 AM				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
116547					5/2/2014		33		\$0.00
Medium	Work In Progress				5/2/2014 3:42:26 PM				
Miranda, Danny		5/2/14 (1)ck boilers (.5)ck rooms on t/s (6)109052 (.5)pper work				5/2-2			
Danny Miranda									

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Vado ES

116924 5/9/2014 26 \$0.00

Medium Work In Progress 5/9/2014 7:39:03 AM

Miranda, Danny need to replace exhaust motor in 100-wing staff r.r.

Danny Miranda

116999 5/12/2014 23 \$0.00

Medium Work In Progress 5/12/2014 10:43:07 AM

Miranda, Danny PAINTCLASSROOMS AS NEEDED

Danny Miranda

117001 5/12/2014 23 \$0.00

Medium Work In Progress 5/12/2014 11:01:42 AM

Miranda, Danny GROUNDS UP KEEP AND REPAIRS OF SPRINKLERS

Danny Miranda

115693 4/7/2014 58 \$0.00

Medium Work In Progress 4/7/2014 3:42:28 PM

Miranda, Danny 4/7/14 4/7/14 - 4 HRS

- (1)ck boilers
- (.5)ck rooms on t/s
- (4)114842
- (1.5)cut grass
- (.5)pick up school mail
- (.5)paper work

Danny Miranda

116738 5/5/2014 30 \$0.00

Medium Work In Progress 5/5/2014 3:40:43 PM

Miranda, Danny need to replace damaged tin snips

Danny Miranda

113302 2/12/2014 112 \$0.00

Medium Work In Progress 2/12/2014 7:46:07 AM

Holguin, Alfredo need to replace sand w/wood fiber in playground

Danny Miranda

117663 5/30/2014 5 \$0.00

Medium Work In Progress M. LUCERO 5/30/2014 10:43:09 AM

Gonzales, Camilo MOVE EQUIPMENT TAGGED FROM MARISA LUCERO'S CLASSROOM TO GMS FOR EXTENDED SCHOOL YEAR

Margaret Villalobos

1325 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2013 - 6/30/2014 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
Location: Vado ES									
117314	Main Building	Custodial			5/20/2014		15		\$0.00
Medium	Work In Progress				5/20/2014 10:21:03 AM				
Carbajal, Jimmy		Vacuum cleaner won't start serial # 1176							
Armando Diaz									
115120	Main Building	Office			3/27/2014		69		\$0.00
Medium	Work In Progress	Nurses Office			3/27/2014 2:45:13 PM				
Marquez, Gerardo		Nurse has only one key to file cabinet and it is bending. Could you please make another key for her. Thank you.							
Colleen Runyan									
116943					5/9/2014		26		\$0.00
Medium	Work In Progress				5/9/2014 11:58:29 AM				
Flores, Pete		need to repair blower for vado elem. custodian							
Danny Miranda									
115685					4/7/2014		58		\$0.00
Medium	Work In Progress				4/7/2014 2:29:33 PM				
Flores, Pete		need bobcat to work grounds and ponds							
Danny Miranda									
Count: 26 Work Orders		Avg. Age of WO's 56		Total for Vado ES		0		\$0.00	
Count: 1325 Work Orders		Avg. Age of WO's 59		Grand Total		1		\$25.00	