

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Location Not Assigned</b>							
127017					1/5/2015		35		\$0.00
Medium	Work In Progress				1/5/2015 12:41:42 AM				
Flores, Pete	Monthly - District Tractors - Full Service PM - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>35</b>	<b>Total for &lt;Blank&gt;</b>				<b>0</b>	<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Alta Vista Early College HS</b>									
126459		Office			12/10/2014		61		\$0.00
Medium	Work In Progress	Main Office			12/10/2014 10:09:54				
Aguilar, Patricio	NEED SIX STEEL LEG TABLES TO ASSEMBLE DESK AND TABLE IN ADMINISTRATIVE ASSISTANT'S OFFICE AT ALTA VISTA EARLY COLLEGE. PLEASE CONTACT YVETTE FOR ANY INFORMATION.								
Yvette Cortez									
128272					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:32 AM				
Ronquillo, Ruben	Monthly - Alta Vista ECHS - (Qtrly) Fitness Equip - Refer to PMschedule details.								
Margret Villalobos									
126466		Office			12/10/2014		61		\$0.00
Medium	Work In Progress	Principal's Office			12/10/2014 2:10:11 PM				
Ronquillo, Ruben	NEED ONE WINDOW BLIND IN PRINCIPAL'S OFFICE AT ALTA VISTA EARLY COLLEGE 41.5W X 41.5L).								
Yvette Cortez									
128239					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:10 AM				
Ambriz, Alfredo	Monthly - Alta Vista ECHS Emer Light Test: Monthly - Refer to PMschedule details.								
Margret Villalobos									
128240					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:11 AM				
Ambriz, Alfredo	Monthly - Alta Vista ECHS Exit Sign Insp: Monthly - Refer to PMschedule details.								
Margret Villalobos									
119862					7/25/2014		199		\$0.00
Medium	Work In Progress				7/25/2014 2:25:32 PM				
Lara, Ralph	At Alta Vista Early College (Old Desert Pride) change cores off master. Door was the nurse's office door. Refer to e-mail for picture and sketch for door location. Make 2 keys and issue one (1) to George Foster and one (1) to Gema Salcedo. Should you have any questions please contact Mr. Ralph Gallegos at 575- 882-6921 in the Construction office. Thank You								
Dominique Esparza									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Alta Vista Early College HS</b>									
119421		Classroom			7/15/2014		209		\$0.00
Medium	Work In Progress	2nd bldg			7/15/2014 10:04:15 AM				
Lara, Ralph		Having hard time opening entrance door							
David Acosta									
128554		Classroom			2/5/2015		4		\$0.00
Medium	Work In Progress	201			2/5/2015 4:05:09 PM				
Lara, Ralph		LOCKING MECHANISM DOES NOT LOCK. DOOR OPENS ON ITS OWN DUE TO DEFECTIVE CYLINDER/DOOR KNOB.							
Yvette Cortez									
128141					1/30/2015		10		\$0.00
Safety	Work In Progress				1/30/2015 10:45:16 AM				
Ontiveros, Guadalupe		As per Meeting - a student fell on uneven sidewalk, please repair.							
Richard Chavez									
126151					12/3/2014		68		\$0.00
Medium	Work In Progress				12/3/2014 8:42:06 AM				
Ontiveros, Guadalupe		Mr. Foster also wants some pieces of concrete sidewalks and portable footings removed (trip hazards).							
Alfredo Holguin									
128585		Exterior			2/6/2015		3		\$0.00
Medium	Work In Progress	Front Section			2/6/2015 10:40:45 AM				
Ontiveros, Guadalupe		NEED TO REMOVE PINE TREES IN FRONT OF MAIN BUILDING.							
Yvette Cortez									
120833					8/8/2014		185		\$0.00
Medium	Work In Progress				8/8/2014 1:58:33 PM				
Villalobos, David		Need to repair water line between the morgan bldg.							
Michael Munoz									
123089		Classroom			9/23/2014		139		\$0.00
Medium	Work In Progress				9/23/2014 3:28:10 PM				
Sotelo, Enrique		Connect all new treadmills in the PE portable #504 to the internet/wi-fi							
Minerva Menchaca									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Alta Vista Early College HS

121826	Curriculum and	Portables			8/27/2014		166		\$0.00
Medium	Work In Progress				8/27/2014 8:16:27 AM				

Sotelo, Enrique  
Ned to fix the power outlet strip on the west side wall of the portable. PE portable #504

Minerva Menchaca

122643	Curriculum and	Office			9/11/2014		151		\$0.00
Medium	Work In Progress				9/11/2014 11:33:24 AM				

Carrasco, Danny  
Walls in main office and main hallway painted. Wall on the outside of main office to be repaired and painted. Ceiling tiles need to be replaced in main hallway, library bathroom and whenever else needed. Per Mr. Yturralde.

Minerva Menchaca

124395	Curriculum and	Classroom			10/21/2014		111		\$0.00
Medium	Work In Progress				10/21/2014 12:07:07				

Aguilar, Patricio  
Need 6 cans of black spraypaint to paint the window guards on the classrooms. Blue paint to paint the handicap parking barrier.

Minerva Menchaca

128667					2/9/2015		0		\$0.00
Medium	Work In Progress				2/9/2015 11:08:39 AM				

Ambriz, Jose  
Can you please come and check the heater from the library it smells like carbon monoxide thank you.

Alfredo Ambriz

126467		Classroom			12/10/2014		61		\$0.00
Medium	Work In Progress	ALL			12/10/2014 2:11:34 PM				

Ambriz, Jose  
NEED 11 THERMASTAT COVERS WITH KEYS FOR ALL CLASSROOMS AND MAIN OFFICE AT ATLA VISTA EARLY COLLEGE.

Yvette Cortez

120783	Curriculum and	Classroom			8/8/2014		185		\$0.00
Medium	Work In Progress				8/8/2014 8:03:48 AM				

Ambriz, Jose  
Install a refrigerated unit in the Rm 504 old PE portable and Rm 501 old Art Room.

Minerva Menchaca

127541		Office			1/14/2015		26		\$0.00
Medium	Work In Progress	ASST.			1/14/2015 2:12:24 PM				

Ronquillo, Ruben  
NEED NEW BLIND FOR ASST. PRINCIPAL'S OFFICE (41.5 L X 41.5 W). DOES NOT HAVE BLIND AT THIS MOMENT.

Yvette Cortez

2/9/2015 1:38:21 PM

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Alta Vista Early College HS</b>									
128287					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:42 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
128197					1/31/2015		9		\$0.00
Medium	Work In Progress				1/31/2015 12:39:14 AM				
Sanchez, Raul		Monthly - Desert Pride - Monthly Meter Readings - Refer to PM schedule details.							
Margret Villalobos									
127109					1/6/2015		34		\$0.00
Medium	Work In Progress				1/6/2015 10:14:38 AM				
Gonzalez, Salvador		Can you please come by and weld a pick nick table its one of the the students where they eat for breakfast and lunch thank you.							
Alfredo Ambriz									
126236					12/4/2014		67		\$0.00
Medium	Work In Progress				12/4/2014 11:24:06 AM				
Gonzalez, Salvador		Gate does not work property hard to open and close please repair.							
Alfredo Ambriz									
128666					2/9/2015		0		\$0.00
Medium	Work In Progress				2/9/2015 11:01:09 AM				
Gonzalez, Salvador		Can you please come and fix the front gate the one of the roles is broken and its hard to open and close.							
Alfredo Ambriz									
128605		Office			2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 3:00:59 PM				
Gonzales, Camilo		Deliver 1 cow and 30 bxs. PO# 141504485.							
Theresa Ramirez									
128369		Office			2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 4:08:54 PM				
Gonzales, Camilo		Deliver 1 cow. PO# 141504771							
Theresa Ramirez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location: Alta Vista Early College HS</b>									
128627					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 3:58:42 PM				
Lara, Ralph		DOOR IS MISALIGNED FROM FRAME CAUSING DOOR NOT TO SECURE. DOOR NEEDS TO BE SLAMMED IN ORDER TO CLOSE PROPERLY.							
Yvette Cortez									
127536		Office			1/14/2015		26		\$0.00
Medium	Work In Progress	Main Office			1/14/2015 2:04:52 PM				
Lara, Ralph		DOOR TO ASST. PRINCIPAL NEED TO BE REPLACED WITH NEW DOOR.							
Yvette Cortez									
127540		Office			1/14/2015		26		\$0.00
Medium	Work In Progress	Principal's Office			1/14/2015 2:10:29 PM				
Lara, Ralph		DOOR TO PRINCIPAL'S OFFICE IS UNEVEN NEEDS TO BE REPLACED WITH NEW DOOR.							
Yvette Cortez									
127690		Office			1/20/2015		20		\$0.00
Medium	Work In Progress	MAIN			1/20/2015 8:57:07 AM				
Lara, Ralph		DOOR TO MAIN ENTRANCE DOES NOT LATCH. NEEDS TO BE ADJUSTED. DOOR SHOULD BE UNDER WARRANTY.							
Yvette Cortez									
128664					2/9/2015		0		\$0.00
Medium	Work In Progress				2/9/2015 10:51:38 AM				
Sitters, Mary		Can you please come and pick up my back cum cleaner the motor give out.							
Alfredo Ambriz									
128603					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 2:35:23 PM				
Ronquillo, Ruben		BELTS ON CARDIO SMART TREADMILLS NEED TO BE REPLACED.							
Yvette Cortez									
128307					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:55 AM				
Ambriz, Alfredo		Monthly - Alta Vista ECHS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Alta Vista Early College HS</b>									
126152					12/3/2014		68		\$0.00
Medium	Work In Progress				12/3/2014 8:43:42 AM				
Munoz, Michael		He is also asking if the remaining concrete can be used as a border for a volley ball court but I need to talk to you on this one.							
Alfredo Holguin									
<b>Count: 35 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>56</b>	<b>Total for Alta Vista Early College HS</b>				<b>0</b>	<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony - On Track Pre-K (Village)</b>									
121563		Classroom			8/21/2014		19		\$0.00
Medium	Work In Progress	575-882-1904			8/21/2014 9:46:57 AM	9/9/2014			
Sotelo, Daniel please paint outside the On Track Pre-K @ Anthony the classroom doors form rooms 111,110,109,108, 101 and 102 we already have the paint from a parent the their company donated if you have any questions please contact Estrella thank you, Laura									
Laura Vazquez									
127808					1/22/2015		18		\$0.00
Medium	Work In Progress				1/22/2015 1:17:43 PM				
Vega, David as per teachers request please fill out all paper towel and soup dispenser from all classes and also from cafeterias thank you, Laura									
Laura Vazquez									
125163		Classroom			11/5/2014		96		\$0.00
Medium	Work In Progress	575-882-1904			11/5/2014 9:36:07 AM				
Sotelo, Daniel classroom 108 it is licking water next to the light please check it out... it starting to do it on Monday with the rain thank you, Laura									
Laura Vazquez									
121769					8/26/2014		167		\$0.00
Medium	Work In Progress				8/26/2014 9:12:18 AM				
Marquez, Gerardo speech therapist is having trouble locking door to speech therapy room									
David Vega									
124372					10/21/2014		111		\$0.00
Medium	Work In Progress				10/21/2014 8:07:56 AM				
Marquez, Gerardo cut out counter top for new sink in the 1st portable. contact person estrella. thank you									
Michael Munoz									
128397					2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 10:11:02 AM				
Carrasco, Danny 02/03/2015. BM needs 5 tubes of 3M acrylic to repair a tear on spiral slide at Pre K village .									
David Escobar									
<b>Count: 6 Work Orders</b>		<b>Avg. Age of WO's 70</b>			<b>Total for Anthony - On Track Pre-K (Village)</b>			<b>0</b>	<b>\$0.00</b>



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Anthony ES</b>							
128222					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:58 AM				
Escobar, David		Monthly - Anthony ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
128223					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:59 AM				
Escobar, David		Monthly - Anthony ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
126613					12/15/2014		56		\$0.00
Medium	Work In Progress	nurse's hallway			12/15/2014 10:45:01				
Sotelo, Daniel		As per Ms. Perez please check ceiling tile by the nurse entrance (possible leak)							
Jessica Lopez									
121107					8/13/2014		180		\$0.00
Medium	Work In Progress	SPED			8/13/2014 11:34:37 AM				
Sotelo, Daniel		INSTALL SMALL SLAT WINDOW BLINDS (5) IN OLD AE CAFETERIA TO DECREASE SUNLIGHT (PRESENTATIONS NOT VISIBLE BECAUSE OF TOO MUCH SUNLIGHT)							
Margaret Villalobos									
126847					1/4/2015		36		\$0.00
Medium	Work In Progress				1/4/2015 12:39:51 AM				
Holguin, Alfredo		Monthly - Anthony ES - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
123059					9/23/2014		139		\$0.00
Medium	Work In Progress				9/23/2014 10:30:35 AM				
Marquez, Gerardo		KEEYS LOCKED IN SNP VEHICLE 132.							
Maritza Gonzalez									
126873					1/4/2015	1/12/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:12 AM				
Escobar, David		Monthly - Anthony ES Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
120520					8/5/2014		188		\$0.00
Medium	Work In Progress				8/5/2014 8:28:32 AM				
Estrada, Jesus		need set of tools hammer, channel locks, allen wrenches screw drivers etc							
David Vega									
128519					2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 11:00:16 AM				
Marquez, Gerardo		need 4 locks (2) k masters (2) h master w/ chains for emergency purpose							
David Vega									
128452					2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 9:16:14 AM				
Sotelo, Enrique		02/04/2015. room 244 bath room has a broken lite wall switch and has a potential shock risk . Please replace asap.							
David Escobar									
128413					2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 2:42:13 PM				
Villalobos, David		Toilet in room 244 continues to leak water at bowl .							
David Escobar									
126886					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:23 AM				
Villalobos, David		Yearly - Anthony ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
125008					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:21 AM				
Orozco, Daniel		Monthly - Anthony ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
128536					2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 3:29:26 PM				
Carrasco, Danny		02/05/2015. need 5gals of gas for site stock.							
David Escobar									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
126975					1/4/2015		36		\$0.00
Medium	Work In Progress				1/4/2015 12:41:35 AM				
Munoz, Michael		Monthly - Anthony ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
128305					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:54 AM				
Escobar, David		Monthly - Anthony ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
120333					8/3/2014		190		\$0.00
Medium	Work In Progress				8/3/2014 12:33:36 AM				
Munoz, Michael		Yearly - Anthony ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.				PM not completed as per schedule			
Margret Villalobos									
128486					2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 3:46:09 PM				
Marquez, Gerardo		BM needs 10 bathroom stall latches . need to replace missing and broken ones.							
David Escobar									
120712					8/7/2014		186		\$0.00
Medium	Work In Progress				8/7/2014 12:12:51 PM				
Gonzalez, Salvador		Sal we need to build a ladder rack for the gater as per Mike thanks							
Daniel Sotelo									
128444					2/4/2015		5		\$0.00
Medium	Work In Progress	SPED OFFICE			2/4/2015 7:26:25 AM				
Gonzales, Camilo		DELIVER PO 141504559 PSYCHOLOGICAL ASSESSMENT 1 PKG DR. RUTH HERRERA, PSYCHOLOGIST							
Margaret Villalobos									
121438					8/19/2014		174		\$0.00
Medium	Work In Progress				8/19/2014 2:55:31 PM				
Orozco, Daniel		EXHAUST FAN SWITCH IS NOT WORKING AGAIN. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
121439					8/19/2014		174		\$0.00
Medium	Work In Progress				8/19/2014 2:56:27 PM				
Orozco, Daniel		NEED METAL COVERS FOR FAN INSIDE WALK IN REFRIGERATOR, SAFETY HAZARD. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									
123057					9/23/2014		139		\$0.00
Medium	Work In Progress				9/23/2014 9:58:08 AM				
Orozco, Daniel		PRONG TO SLICER STAYED STUCK IN OUTLET. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									
121985					8/29/2014		164		\$0.00
Medium	Work In Progress				8/29/2014 3:13:57 PM				
Orozco, Daniel		THERE IS A LEAK ON SPRAYER HOSE. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									
121986					8/29/2014		164		\$0.00
Medium	Work In Progress				8/29/2014 3:14:16 PM				
Orozco, Daniel		SERVING LINE CLOGGED. SNP MANAGER BECKY S. 882.3507							
Maritza Gonzalez									
126074					12/1/2014		70		\$0.00
Medium	Work In Progress				12/1/2014 3:59:52 PM				
Sotelo, Daniel		need to clean up dead leaves from trees							
Daniel Sotelo									
128632					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress				2/8/2015 12:29:18 AM				
Escobar, David		Monthly - Anthony ES Monthly Playground Insp. - Refer to PM schedule details.							
Margret Villalobos									
126091					12/2/2014		69		\$0.00
Medium	Work In Progress				12/2/2014 8:41:34 AM				
Sotelo, Daniel		p-trap in boys bathroom is leaking need to be replaced							
Daniel Sotelo									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
126092					12/2/2014		69		\$0.00
Medium	Work In Progress				12/2/2014 8:44:14 AM				
Sotelo, Daniel		need to check light that's out see if its just light bulbs or ballast in room 408							
Daniel Sotelo									
126184					12/3/2014		68		\$0.00
Medium	Work In Progress				12/3/2014 3:22:21 PM				
Sotelo, Daniel		Mr. Sotelo, as per Ms. Perez please blow leaves from landscaping							
Jessica Lopez									
125664					11/18/2014		83		\$0.00
Medium	Work In Progress				11/18/2014 8:10:34 AM				
Sotelo, Daniel		need to fix water leak in old cafeteria by Alamo. water line that go's to swamp coolers							
Daniel Sotelo									
128568					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 8:34:57 AM				
Carrasco, Danny		02/06/2015. BM has submitted a tools list that are needed at site .							
David Escobar									
<b>Count: 32 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>75</b>			<b>Total for Anthony ES</b>	<b>0</b>	<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Berino ES

128630 2/8/2015 2/24/2015 1 \$0.00

Medium Work In Progress 2/8/2015 12:29:16 AM

Duran, Adan Monthly - Berino ES Monthly Playground Insp. - Refer to PM schedule details.

Margret Villalobos

124129 10/14/2014 118 \$0.00

Medium Work In Progress 10/14/2014 10:08:48

Orozco, Daniel OVEN DOWN. SNP MANAGER ELSA C. 882.2417

Maritza Gonzalez

126424 12/9/2014 62 \$0.00

Medium Work In Progress 12/9/2014 3:42:21 PM

Orozco, Daniel WARMER IS NOT HEATING. SNP MANAGER ELSA C. 882.2417

Maritza Gonzalez

128442 2/4/2015 5 \$0.00

Medium Work In Progress O. ARROYO 2/4/2015 7:23:47 AM

Gonzales, Camilo DELIVER PO 141504558 ORIENTAL TRADING CO. 2 BOXES O. ARROYO, TEACHER @ BERINO ELEMENTARY

Margaret Villalobos

128443 2/4/2015 5 \$0.00

Medium Work In Progress O. ARROYO 2/4/2015 7:25:02 AM

Gonzales, Camilo DELIVER PO 141504557 LAKESHORE LEARNING MATERIALS 1 BOX O. ARROYO, TEACHER @ BERINO ELEMENTARY

Margaret Villalobos

127190 1/7/2015 33 \$0.00

Medium Work In Progress 1/7/2015 2:12:03 PM

Gonzalez, Salvador MR WELDER SALVADOR SIR NEED A 1/8 STEEL PLATE TO COVER BROKEN LID ELECTRICAL BOX 25" LONG X 14 1/2" WIDE THANK YOU SIR AND GOD BLESS

Adan Duran

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Berino ES</b>									
128589					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 11:43:30 AM				
Gonzalez, Salvador		MR SAL GONZLES SIR THE BENCH IN NORTH PLAYGROUND IS BROKEN BY VANDALS NEED TO BE REPAIR AND WELDED THANK YOU SIR AND GOD BLESS							
Adan Duran									
128410		Office			2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 1:48:43 PM				
Gonzales, Camilo		Deliver 5 bxs. PO# 141504413.							
Theresa Ramirez									
128306					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:55 AM				
Duran, Adan		Monthly - Berino ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
125221		Custodial			11/6/2014		95		\$0.00
Medium	Work In Progress				11/6/2014 9:58:22 AM				
Carbajal, Jimmy		Cord is tangled bad on Vacuum (2129) and shorting out							
Marin Herrera									
128408		Custodial			2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 12:57:40 PM				
Carbajal, Jimmy		Vacuum (0198) needs repair does not turn on							
Marin Herrera									
118857					7/1/2014		223		\$0.00
High	Work In Progress				7/1/2014 9:56:44 AM				
Munoz, Michael		need to install new water gong fire bell. district electrician will provide power.							
Michael Munoz									
126969					1/4/2015	1/25/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:41:30 AM				
Munoz, Michael		Monthly - Berino ES Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Berino ES</b>							
125009					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:22 AM				
Orozco, Daniel		Monthly - Berino ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
126887					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:24 AM				
Villalobos, David		Yearly - Berino ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
120112					7/31/2014		193		\$0.00
Medium	Work In Progress				7/31/2014 2:44:15 PM				
Sotelo, Enrique		MR ENRIQUE SOTELO SIR BREAKER ON AC UNIT ROOMS 105 AND 107 NEEDS TO BE REPLACE IT HAS A 20 AMP AND THE UNIT CALLS FOR A 25 AMP THANK YOU SIR AND GOD BLESS							
Adan Duran									
128574					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 9:05:45 AM				
Sotelo, Enrique		MR ENRIQUE SOTELO SIR NEED TO REPLACE 3 EMERGENCY LIGHT BATTERY MAY NEED TO REPLACE ONE LIGHT MIDDLE HALL WAY THANK YOU SIR AND GOD BLESS							
Adan Duran									
128597					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 12:10:59 PM				
Marquez, Gerardo		MR GERRY MARQUEZ SIR NEED TO REPLACE CORE IN RESTROOM ROOM 113 OUR MASTER KEYS WILL NOT OPEN IT THANK YOU SIR AND GOD BLESS							
Adan Duran									
128327					2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 8:34:27 AM				
Solis, Lorenzo		MR LORENZO SOLIS SIR ROOM 125 IS VERY COLD HAVE ONE UNIT FOR 3 ROOMS THE LAST ONE IS NOT GETTING HEAT PLEASE CHECK THANK YOU AND GOD BLESS							
Adan Duran									



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Berino ES</b>									
128332					2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 9:30:43 AM				
Solis, Lorenzo		MR LORENZO SOLIS SIR DESERT PRIDE PORTABLE NOT WORKING PROPERLY NEED TO CHECK THANK YOU SIR AND GOD BLESS							
Adan Duran									
128407					2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 12:28:55 PM				
Solis, Lorenzo		MR LORENZO SOLIS SIR NEED NEW MOTOR FOR HEATING UNIT ON ROOF ROOM 135&137 OLD ONE IS BURNED OUT THANK YOU SIR AND GOD BLESS							
Adan Duran									
126848					1/4/2015		36		\$0.00
Medium	Work In Progress				1/4/2015 12:39:52 AM				
Holguin, Alfredo		Monthly - Berino ES - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
128241					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:11 AM				
Duran, Adan		Monthly - Berino ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
128242					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:12 AM				
Duran, Adan		Monthly - Berino ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
128235					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:08 AM				
Duran, Adan		Monthly - Berino ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
120406		Custodial			8/4/2014		189		\$0.00
Medium	Work In Progress				8/4/2014 9:29:22 AM				
Flores, Pete		Leaf Blower (G.I.S.D 98-2229) needs repair, it does not want to start .							
Marin Herrera									
<b>Count: 26 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>46</b>		<b>Total for Berino ES</b>	<b>0</b>		<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
128282					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:39 AM				
Quinones, Paul		Monthly - Chaparral ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
128283					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:39 AM				
Quinones, Paul		Monthly - Chaparral ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
128534					2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 3:13:25 PM				
Quinones, Paul		indoor coils to a/c's need cleaning, requesting coil solvent							
Paul Quinones									
128457		Classroom			2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 9:54:21 AM				
Estrada, Jesus		room,208,need,to,remove,carpet,ceiling,leaks,carpetgot,wet,dduring,weekend,smells,bad.				kids are testing, please go after 3:00 p.m. to measure for carpet area only. call chuy if you have any questions. thank you.			
Daniel Ramirez									
126042					12/1/2014		70		\$0.00
Medium	Work In Progress				12/1/2014 11:52:14 AM				
Ontiveros, Guadalupe		Please replace 6" sch. 40 90 degree elbow that busted next to Chaparral Elementary Irrigation tank.							
Johnny Acuna									
128523		Custodial			2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 1:01:29 PM				
Carbajal, Jimmy		need,three,vacuum,belts							
Daniel Ramirez									
128524		Custodial			2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 1:04:02 PM				
Carbajal, Jimmy		need,a,vacuum,roller,brush							
Daniel Ramirez									
127588					1/15/2015		25		\$0.00
Medium	Work In Progress				1/15/2015 12:32:10 PM				
Marquez, Gerardo		cafeteria double doors on the west side of cafeteria core fell off and lost.need a new core							
Paul Quinones									
2/9/2015 1:38:21 PM									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
125569					11/14/2014		87		\$0.00
Medium	Work In Progress				11/14/2014 1:07:06 PM				
Marquez, Gerardo		double doors located on the west side of building next to cafeteria doors are hard to open with key.							
Paul Quinones									
127901					1/26/2015		14		\$0.00
Medium	Work In Progress				1/26/2015 8:24:13 AM				
Ontiveros, Guadalupe		requesting a water cut off valve next to the irrigation pressure tank to shut off water during the winter season.							
Paul Quinones									
128334					2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 9:35:39 AM				
Quinones, Paul		repipe pvc water lines for the air conditioners in the e-wing, and the 400 wing.							
Paul Quinones									
122854	West Central	Classroom			9/16/2014		146		\$0.00
Medium	Work In Progress	402			9/16/2014 3:28:45 PM				
Marquez, Gerardo		Lost key and need as soon as possible. Wrote a letter to secretary. See Ms. Jackson							
Jennifer Corral									
126317					12/5/2014		66		\$0.00
Medium	Work In Progress				12/5/2014 3:56:12 PM				
Vallejo, Albert		requesting 4 lamp ballast							
Paul Quinones									
126440					12/10/2014		61		\$0.00
Medium	Work In Progress				12/10/2014 8:03:33 AM				
Vallejo, Albert		Repair exterior lights mounted on building.							
Albert Vallejo									
123014					9/19/2014		143		\$0.00
Medium	Work In Progress				9/19/2014 4:04:07 PM				
Vallejo, Albert		need a electrical hand dryer boys rest rm. 120 volt broken element							
Paul Quinones									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
126885					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:22 AM				
Villalobos, David		Yearly - Chaparral ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
128320					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:51:04 AM				
Quinones, Paul		Monthly - Chaparral ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
128309					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:57 AM				
Quinones, Paul		Monthly - Chaparral ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
121424	Main Building	Office			8/19/2014		174		\$0.00
Medium	Work In Progress	concession			8/19/2014 1:31:30 PM				
Quinones, Paul		need changing table moved from Chaparral Elementary to GSAC room 109 to Ms. Ruiz. See front office or Mrs. Pargas							
Jennifer Corral									
124735					10/29/2014		103		\$0.00
Medium	Work In Progress				10/29/2014 12:28:02				
Orozco, Daniel		BROKEN GASKETS ON FREEZER AND WARMER. SNP MANAGER ESTHER C. 824.0048							
Maritza Gonzalez									
123783					10/7/2014		125		\$0.00
Medium	Work In Progress				10/7/2014 8:55:51 AM				
Orozco, Daniel		DISHWASHER IS LEAKING. SNP MANAGER ESTHER C. 824.0048							
Maritza Gonzalez									
128644					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress				2/8/2015 12:29:26 AM				
Quinones, Paul		Monthly - Chaparral ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
128659	East Central	Classroom			2/9/2015		0		\$0.00
Medium	Work In Progress	503			2/9/2015 9:43:17 AM				
Villalobos, Margret		Bees outside of classroom need fumigation as soon as possible. See Administration/Danny				2/9/15-Asp bennie will send someone out a/s/a/p			
Jennifer Corral									
<b>Count: 23 Work Orders</b>		<b>Avg. Age of WO's 48</b>			<b>Total for Chaparral ES</b>			<b>0</b>	<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Chaparral High - Pre-K</b>										
128503					2/5/2015		4		\$0.00	
Medium	Work In Progress				2/5/2015 7:47:48 AM					
Ortiz, Alfredo		At Pre-K need to replace all metal soap dispensers with new plastic dispensers. Soap turns brown in metal ones.								
Alfredo Ortiz										
120159					8/1/2014		192		\$0.00	
Medium	Work In Progress	building back			8/1/2014 8:03:09 AM					
Marquez, Gerardo		Repair the back entrance door to the Pre-k Center the handle is broken and having trouble locking and unlocking the door.								
Noemi Duron										
128501		Office			2/5/2015		4		\$0.00	
Medium	Work In Progress				2/5/2015 7:40:52 AM					
Solis, Lorenzø		Having problems with heaters in main office and room 103.								
Alfredo Ortiz										
<b>Count: 3 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>67</b>	<b>Total for Chaparral High - Pre-K</b>			<b>0</b>	<b>\$0.00</b>	

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Chaparral HS

128628	R-Wing	Roof			2/6/2015		3		\$0.00
--------	--------	------	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/6/2015 3:59:35 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Solis, Lorenzo The heater in the welding shop will not start.

Alfredo Ortiz

125511	Field House	Athletic Field			11/13/2014		88		\$0.00
--------	-------------	----------------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2014 12:03:10				
--------	------------------	--	--	--	---------------------	--	--	--	--

Solis, Lorenzo Need to fix ice maching at field house snak bar

Alfredo Ortiz

125512	Q-Wing	Classroom			11/13/2014		88		\$0.00
--------	--------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress				11/13/2014 12:05:50				
--------	------------------	--	--	--	---------------------	--	--	--	--

Solis, Lorenzo Heater in Q-2 not working.

Alfredo Ortiz

127914	A-Wing	Library			1/26/2015		14		\$0.00
--------	--------	---------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/26/2015 11:07:29 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Solis, Lorenzo Need to replace circuit board on unit burn out.

Alfredo Ortiz

126517	B-Wing	Hallway/Corridor			12/11/2014		60		\$0.00
--------	--------	------------------	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/11/2014 10:11:40				
--------	------------------	--	--	--	---------------------	--	--	--	--

Solis, Lorenzo In cybor cafe Bad odor coming from heating vents.

Alfredo Ortiz

127618		Restroom			1/15/2015		25		\$0.00
--------	--	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/15/2015 3:57:40 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ortiz, Alfredo Need to paint the restrooms to cover graffitty.

Alfredo Ortiz

126087	A-Wing				12/2/2014		69		\$0.00
--------	--------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				12/2/2014 8:16:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Solis, Lorenzo Need to replace burned out circuit board on heater for the Health center.

Alfredo Ortiz

128575	E-Wing	Classroom			2/6/2015		3		\$0.00
--------	--------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	E-spded room			2/6/2015 9:13:49 AM				
--------	------------------	--------------	--	--	---------------------	--	--	--	--

Marquez, Gerardo Please check lock. Keys gets stuck and it will not turn or come out. Once you jiggle the key, the lock turns and I am able to open the door. It seems like something is stuck inside lock. (Michelle Martinez, E-spded)

Mireya Meza

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
128529	Field House				2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 2:29:34 PM				
Marquez, Gerardo		Please re-key door between football & boys soccer locker room at field house. (Sofia Payen)							
Mireya Meza									
128103	H-Wing	Gym			1/29/2015		11		\$0.00
Medium	Work In Progress				1/29/2015 2:49:47 PM				
Marquez, Gerardo		Need to replace Key for Gym basket ball courts.							
Alfredo Ortiz									
128626		Athletic Field			2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 3:57:24 PM				
Marquez, Gerardo		Need the CH-86 locks repined for coaches keys to work on most of the locks.							
Alfredo Ortiz									
125112	H-Wing	Gym			11/3/2014		98		\$0.00
Medium	Work In Progress				11/3/2014 3:47:28 PM				
Marquez, Gerardo		Need to make keys for Amplifier box in Gym.							
Alfredo Ortiz									
124515	B-Wing	Storage			10/23/2014		109		\$0.00
Medium	Work In Progress				10/23/2014 1:39:32 PM				
Marquez, Gerardo		Need to replace key Cilinder on door, teachers can't open door.							
Alfredo Ortiz									
124831	A-Wing	Office			10/31/2014		101		\$0.00
Medium	Work In Progress	Nurse office			10/31/2014 9:23:18 AM				
Marquez, Gerardo		Key for one of the nurse's filing cabinet broke off. Please replace. (Fireking, Medeco, #238) (Ms. de Castro, Nurse)							
Mireya Meza									
127675	E-Wing	Classroom			1/16/2015		24		\$0.00
Medium	Work In Progress	E4			1/16/2015 3:51:38 PM				
Vallejo, Albert		There is no power in E4. Along the wall where the student computers are set up. (Mireya Meza)							
Mireya Meza									
127030	H-Wing	Gym			1/5/2015		35		\$0.00
Medium	Work In Progress				1/5/2015 9:16:47 AM				
Vallejo, Albert		Several Ballast in the Gym need to be replaced.							
Alfredo Ortiz									
2/9/2015 1:38:21 PM									



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Chaparral HS

128038	Field House	Athletic Field			1/28/2015		12		\$0.00
--------	-------------	----------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Baseball field			1/28/2015 12:53:32 PM				
--------	------------------	----------------	--	--	-----------------------	--	--	--	--

Vallejo, Albert  
Please replace burned receptacle at baseball batting cage. (Coach Martinez, baseball field)

Mireya Meza

122910		Football Field			9/17/2014		145		\$0.00
--------	--	----------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				9/17/2014 12:08:33 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Vallejo, Albert  
Need to run electricity from press-box to front of Bleachers at football field.

Alfredo Ortiz

121794	Field House	Dressing Room			8/26/2014		167		\$0.00
--------	-------------	---------------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/26/2014 3:03:15 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert  
do not have power to exhaust fans will not start.

Alfredo Ortiz

127029		Exterior			1/5/2015		35		\$0.00
--------	--	----------	--	--	----------	--	----	--	--------

Medium	Work In Progress				1/5/2015 9:13:03 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Vallejo, Albert  
Need to replace light bulbs outside parking lot light poles.

Alfredo Ortiz

121594	B-Wing	Classroom			8/21/2014		172		\$0.00
--------	--------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/21/2014 3:32:10 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert  
Need to install new wall outlet in B-2 classroom.

Alfredo Ortiz

119549	Field House	Restroom			7/17/2014		207		\$0.00
--------	-------------	----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/17/2014 3:54:07 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Vallejo, Albert  
Need to replace several light switches in Field house restrooms and waight room.

Alfredo Ortiz

126906					1/4/2015	2/4/2015	36		\$0.00
--------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				1/4/2015 12:40:38 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David  
Yearly - Chaparral HS Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

128200					2/1/2015	2/4/2015	8		\$0.00
--------	--	--	--	--	----------	----------	---	--	--------

Medium	Work In Progress				2/1/2015 12:49:44 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ortiz, Alfredo  
Monthly - Chaparral HS - Emer. Eyewash (Monthly) - Refer to PM schedule details.

Margret Villalobos

2/9/2015 1:38:21 PM

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Chaparral HS</b>							
128357	G-Wing	Restroom			2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 3:49:59 PM				
Appelzoller, Fred		Need to replace broken toilet in G-wing boys restroom.							
Alfredo Ortiz									
126411	H-Wing	Gym			12/9/2014		62		\$0.00
Medium	Work In Progress				12/9/2014 11:49:08 AM				
Appelzoller, Fred		No water presure on cold side floor sink in Gym custodins closet							
Alfredo Ortiz									
125746	R-Wing	Classroom			11/19/2014		82		\$0.00
Medium	Work In Progress				11/19/2014 11:02:22				
Appelzoller, Fred		In art classroom Q-Build. Needs new water line and run drain-pipes for a indoor power washer.							
Alfredo Ortiz									
126794	E-Wing	Classroom			12/19/2014		52		\$0.00
Medium	Work In Progress	E7			12/19/2014 9:43:19 AM				
Appelzoller, Fred		Please install gas jets in room E7. It is a chemistryroom without gas jets. (Ms. Gonzalez, E7)							
Mireya Meza									
125053		Athletic Field			11/3/2014		98		\$0.00
Medium	Work In Progress				11/3/2014 7:35:53 AM				
Valdez, Pedro		Need to fixbaseball bleachers bent and broken.							
Alfredo Ortiz									
119906	Field House	Athletic Field			7/28/2014		196		\$0.00
Medium	Work In Progress	Main Soccer			7/28/2014 11:42:35 AM				
Valdez, Pedro		We are needing the main grass soccer field lined for this Thursday July 31, 2014. We are having and inter squad scrimmage that evening. (Coach Mendoza)							
Mireya Meza									
125513	A-Wing				11/13/2014		88		\$0.00
Medium	Work In Progress				11/13/2014 12:07:33				
Marquez, Gerardo		At nurses office key broken in cabinet.							
Alfredo Ortiz									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Chaparral HS

126505 Field House Athletic Field 12/11/2014 60 \$0.00

Medium Work In Progress Gilbert Rojas 12/11/2014 7:46:51 AM

Ontiveros, Guadalupe Request for Chaparral HS Baseball & Softball fields:

1. Warning Track all around the Baseball field.
2. Water fountains (they will accommodate both the Baseball & Softball programs)
3. Electrical power source at each of the dugouts.
4. Yellow Protection Topper for Fence.

THANK YOU FOR ALL YOUR HELP!

Terry Alvarado

128584 Field House Football Field 2/6/2015 3 \$0.00

Medium Work In Progress Lupe - Grounds 2/6/2015 10:23:28 AM

Ontiveros, Guadalupe LUPE - CAN YOU PLEASE MOVE 40 HURDLES FROM (STHS) TO CHAPARRAL HS, FOR THE MIDDLE SCHOOL TRACK MEET TO BE HELD ON FEB. 21ST. HURDLES NEED TO BE MOVED BY FEB. 19TH OR 20TH. THANK YOU!

Terry Alvarado

123349 Elevator 9/29/2014 133 \$0.00

Medium Work In Progress 9/29/2014 12:06:17 PM

Ontiveros, Guadalupe Need to bring 1/2 in. gravel for bus entrance about 4 truck loads.

Alfredo Ortiz

125225 11/6/2014 95 \$0.00

Medium Work In Progress 11/6/2014 10:53:09 AM

Carbajal, Jimmy need a sweeper for long main hallway.

Jesus Urquidi

123054 A-Wing Kitchen 9/23/2014 84 \$0.00

Medium Work In Progress Kitchen Area 9/23/2014 9:29:22 AM 12/16/2014

Gallegos, Rafael Kitchen has a water leak coming from the ceiling and its under one of our conventional ovens and it's next to where we prepare most of the food for students. This is a hazard to all the ladies working here as they can slip and fall. (Juanita Montelongo, Kitchen)

Mireya Meza

125603 11/15/2014 86 \$0.00

Medium Work In Progress 11/15/2014 12:45:32

Flores, Pete Yearly - Chaparral HS M-0405 (Z-Track) Grounds - Refer to PM schedule details.

Margret Villalobos

2/9/2015 1:38:21 PM

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral HS</b>									
126754					12/18/2014		53		\$0.00
Medium	Work In Progress			12/18/2014 11:28:13					
Flores, Pete	On the Chaparral Band truck Need to replace the sun visor, install small round mirrors to see the blind spot, and fix the light in the back cargo cab. Attention to Mechanic.								
Alfredo Ortiz									
127243					1/8/2015		32		\$0.00
Medium	Work In Progress			1/8/2015 1:55:50 PM					
Flores, Pete	Attention to Vehicle Maintenance. The Battery for the polaris is no good need new one.								
Alfredo Ortiz									
128279					2/1/2015		8		\$0.00
Medium	Work In Progress			2/1/2015 12:50:37 AM					
Flores, Pete	Monthly - CHS-UV-0513 PM Service - Refer to PM schedule details.								
Margret Villalobos									
126845					1/4/2015		36		\$0.00
Medium	Work In Progress			1/4/2015 12:39:49 AM					
Holguin, Alfredo	Monthly - Chaparral HS - Fire Pump Engine - Refer to PMs schedule details.								
Margret Villalobos									
128604		Athletic Field			2/6/2015		3		\$0.00
High	Work In Progress			2/6/2015 2:58:06 PM					
Ontiveros, Guadalupe	JD Tractor 3320 need to replaced both front tires.								
Guadalupe Ontiveros									
128319					2/1/2015		8		\$0.00
Medium	Work In Progress			2/1/2015 12:51:03 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Monthly FE Inspection - Refer to PMs schedule details.								
Margret Villalobos									
128321					2/1/2015		8		\$0.00
Medium	Work In Progress			2/1/2015 12:51:05 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Emer. Light Test: Monthly - Refer to PMs schedule details.								
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Chaparral HS</b>							
126976					1/4/2015		36		\$0.00
Medium	Work In Progress				1/4/2015 12:41:36 AM				
Munoz, Michael		Monthly - Chaparral HS - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
125049					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:47 AM				
Orozco, Daniel		Monthly - Chaparral HS Fire Suppression Insp. - Refer to PM schedule details.							
Margret Villalobos									
126979					1/4/2015		36		\$0.00
Medium	Work In Progress				1/4/2015 12:41:38 AM				
Munoz, Michael		Monthly - Chaparral HS Pre-K- Fire Sprinkler Insp - Refer to PM schedule details.							
Margret Villalobos									
123160	A-Wing	Library			9/24/2014		138		\$0.00
High	Work In Progress	Library			9/24/2014 10:26:33 AM				
Estrada, Jesus		Please replace carpet. Alfredo Ortiz will be removing section that was wet due to foundation leak.							
Mireya Meza									
127580	H-Wing	Restroom			1/15/2015		25		\$0.00
Medium	Work In Progress				1/15/2015 10:50:50 AM				
Ortiz, Alfredo		Need to replace ballast and light bulbs in locker room restrooms.							
Alfredo Ortiz									
128599	A-Wing	Classroom			2/6/2015		3		\$0.00
Medium	Work In Progress	A-105			2/6/2015 1:17:17 PM				
Ortiz, Alfredo		Install sharpener in ISS room, A-105. (Ms. Guerrero, A105)							
Mireya Meza									
128247					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:16 AM				
Ortiz, Alfredo		Monthly - Chaparral HS - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral HS</b>									
128249					2/1/2015		8		\$0.00
Medium	Work In Progress			2/1/2015 12:50:17 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
128250					2/1/2015	3/4/2015	8		\$0.00
Medium	Work In Progress			2/1/2015 12:50:18 AM					
Ortiz, Alfredo	Monthly - Chaparral HS Bleacher Inspection - Refer to PM schedule details.								
Margret Villalobos									
128506		Exterior			2/5/2015		4		\$0.00
Medium	Work In Progress			2/5/2015 7:55:49 AM					
Ortiz, Alfredo	Need to caulk and seal windows to prevent water leaks.								
Alfredo Ortiz									
127483		Exterior			1/13/2015		27		\$0.00
Medium	Work In Progress			1/13/2015 3:09:53 PM					
Ortiz, Alfredo	Need to order reflector tape for gates.								
Alfredo Ortiz									
128504		Hallway/Corridor			2/5/2015		4		\$0.00
Medium	Work In Progress			2/5/2015 7:50:42 AM					
Ortiz, Alfredo	Need to replace ceiling tiles that are broken or stained around campus.								
Alfredo Ortiz									
127579	H-Wing	Gym			1/15/2015		25		\$0.00
Medium	Work In Progress			1/15/2015 10:47:58 AM					
Ortiz, Alfredo	Need to fix leak in trainers room washing machine.								
Alfredo Ortiz									
123083	A-Wing	Library			9/23/2014		139		\$0.00
Medium	Work In Progress	Library			9/23/2014 3:15:03 PM				
Marquez, Gerardo	Please unbolt 2 library shelf units from the wall so they can be moved away from water leaking into library. (Ms. DeVine, library)								
Mireya Meza									
128292					2/1/2015		8		\$0.00
Medium	Work In Progress			2/1/2015 12:50:45 AM					
Apodaca, Mario	Monthly - Chaparral HS - Lift Station Inspection - Refer to PM schedule details.								
Margret Villalobos									

2/9/2015 1:38:21 PM

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
126140	A-Wing	Kitchen			12/3/2014		68		\$0.00
Medium	Work In Progress				12/3/2014 7:41:36 AM				
		A hot water circulating pump for the Kitchen not working. Need to be replaced.							
Alfredo Ortiz									
128087					1/29/2015		11		\$0.00
Medium	Work In Progress				1/29/2015 10:12:50 AM				
Orozco, Daniel		ONE OF THE OVENS IS NOT HEATING AT ALL. SNP MANAGER JUANITA M. 824.4461							
Maritza Gonzalez									
121690	Field House	Athletic Field			8/25/2014		168		\$0.00
Medium	Work In Progress	Baseball shed			8/25/2014 10:20:10 AM				
Marquez, Gerardo		Requesting a metal door with knob & dead bolt locking system to secure inventory of equipment in baseball shed. Please see Gregg Martinez for pictures and report. (Mr. Martinez, baseball shed)							
Mireya Meza									
123340					9/29/2014		133		\$0.00
Medium	Work In Progress				9/29/2014 8:09:29 AM				
Marquez, Gerardo		We will need to add door openers to 4 doors:							
		1. The east exit door by the wall on Wing E.							
		2. The west exit door by the wall on Wing F.							
		3. The east exit doors (2 doors – one into the foyer and one into the building) by the wall on Wing R.							
Alfredo Holguin									
124236	A-Wing	Office			10/16/2014		116		\$0.00
Medium	Work In Progress	Front reception			10/16/2014 10:22:52				
Marquez, Gerardo		The left side door right in front of the reception desk is not locking properly. (Mireya Meza)							
Mireya Meza									
121551	R-Wing	Foyer			8/20/2014		173		\$0.00
Medium	Work In Progress	Front Door to R			8/20/2014 4:24:57 PM				
Marquez, Gerardo		The right side front door going into the R building has a broken latch. (Mireya Meza)							
Mireya Meza									
119780		Athletic Field			7/24/2014		200		\$0.00
Medium	Work In Progress				7/24/2014 7:57:00 AM				
Gonzalez, Salvador		fertilizer spreader handle needs to be weld.							
Guadalupe Ontiveros									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
124825		Exterior			10/31/2014		101		\$0.00
Medium	Work In Progress				10/31/2014 7:50:32 AM				
Gonzalez, Salvador		Main gate for bus entrance broken. Need to replace hing welded.							
Alfredo Ortiz									
<b>Count: 67 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>63</b>			<b>Total for Chaparral HS</b>	<b>0</b>		<b>\$0.00</b>



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Chaparral MS</b>							
120816	Main Building	Gym			8/8/2014		185		\$0.00
Medium	Work In Progress				8/8/2014 11:17:35 AM				
Gonzalez, Salvador		Coach would like 3 tether ball poles installed near the outside basketball courts				Route to Sal 10/22/14			
Gidget Mora									
118903					7/2/2014		222		\$0.00
Medium	Work In Progress				7/2/2014 12:29:48 PM				
Marquez, Gerardo		Replace or repair gym south exit doors							
Albert Vallejo									
120454	Main Building	Classroom			8/4/2014		189		\$0.00
Medium	Work In Progress	203			8/4/2014 1:56:06 PM				
Marquez, Gerardo		Please repair all cabinet doors to close properly				8/13 route to Gerry			
Gidget Mora									
128088					1/29/2015		11		\$0.00
Medium	Work In Progress				1/29/2015 10:23:00 AM				
Orozco, Daniel		AIR CURTAIN AT BACK DOOR IS NOT WORKING, NEEDS A NEW MOTOR FAN. SNP MANAGER SANDRA D. 824.4376							
Maritza Gonzalez									
128514					2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 10:24:42 AM				
Orozco, Daniel		I need to place a work order for the washer. It doesn't start right away and when it finally does, it doesn't want to drain/spin. SNP Manager Sandra D. 824.4376							
Maritza Gonzalez									
128515					2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 10:26:15 AM				
Orozco, Daniel		Back door seal worn out, needs to be replaced. (as per environment dept.). SNP Manager Sandra D. 824.4376							
Maritza Gonzalez									
128516					2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 10:26:50 AM				
Orozco, Daniel		Freezer door doesn't close completely without having to push it shut. (as per environment dept.) SNP Manager Sandra D. 824.4376							
Maritza Gonzalez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral MS</b>									
124842					10/31/2014		101		\$0.00
Medium	Work In Progress			10/31/2014 2:26:36 PM					
Orozco, Daniel	The back doors to warmer seems to be hanging a little from both top hinges. This could be why that warmer takes forever to reach its holding temperature. SNP Manager Sandra D.824.4376								
Maritza Gonzalez									
124340					10/20/2014		112		\$0.00
Medium	Work In Progress			10/20/2014 12:33:32					
Orozco, Daniel	AS PER HEALTH DEPARTMENT DOOR SEAL TO BACK DOOR NEEDS TO FIXED. WALK IN DOOR DOES NOT SHUT COMPLETELY WITH OUT PUSHING IT SHUT.SNP MANAGER SANDRA D. 824.4376								
Maritza Gonzalez									
125222	Main Building	Gym			11/6/2014		95		\$0.00
Medium	Work In Progress			11/6/2014 10:20:59 AM					
Vallejo, Albert	Blue pads in the main gym backboards need to be re-glued or re-bolted. All 6								
Gidget Mora									
122338	Main Building	Restroom (Girls)			9/4/2014		158		\$0.00
Medium	Work In Progress	Office ladies			9/4/2014 3:13:32 PM				
Vallejo, Albert	Fan is broken-Making noise								
Gidget Mora									
119504	Main Building	Gym			7/16/2014		208		\$0.00
High	Work In Progress			7/16/2014 4:11:34 PM					
Estrada, Jesus	Replace warped floor boards in gym (southwest)								
Jesus Estrada									
126970					1/4/2015	1/25/2015	36		\$0.00
Medium	Work In Progress			1/4/2015 12:41:31 AM					
Munoz, Michael	Monthly - Chaparral MS Fire Sprinkler Insp. - Refer to PMschedule details.								
Margret Villalobos									
127111	Main Building	Cafeteria			1/6/2015		34		\$0.00
Medium	Work In Progress			1/6/2015 11:27:29 AM					
Estrada, Jesus	re- tile stage								
Jesus Estrada									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Chaparral MS

118858 7/1/2014 223 \$0.00

High Work In Progress 7/1/2014 9:58:32 AM

Munoz, Michael need to install new water gong bell for fire sprinkler system. district electrician will provide power.

Michael Munoz

128308 2/1/2015 2/7/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:56 AM

Vallejo, Albert Monthly - Chaparral MS Monthly FE Inpsection - Refer to PMschedule details.

Margret Villalobos

119869 7/25/2014 199 \$0.00

Medium Work In Progress 7/25/2014 3:18:22 PM

Marquez, Gerardo Need new closers for south main hall exit doors.

Albert Vallejo

119581 Athletic Field 7/18/2014 206 \$0.00

Medium Work In Progress 7/18/2014 1:31:26 PM

Ontiveros, Guadalupe playing fields need to be reseed as per site admin.

Guadalupe Ontiveros

121096 8/13/2014 180 \$0.00

Medium Work In Progress 8/13/2014 10:19:11 AM

Vallejo, Albert Please insulate supplyducts on new refrigeration units.

Albert Vallejo

128236 2/1/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:08 AM

Vallejo, Albert Monthly - Chaparral MS - Clothes Dryer (Monthly) - Refer to PMschedule details.

Margret Villalobos

128237 2/1/2015 3/4/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:09 AM

Vallejo, Albert Monthly - Chaparral MS Bleacher Inspection - Refer to PMschedule details.

Margret Villalobos

128233 2/1/2015 2/9/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:06 AM

Vallejo, Albert Monthly - Chaparral MS Exit Sign Insp: Monthly - Refer to PMschedule details.

Margret Villalobos

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Chaparral MS

128234 2/1/2015 2/9/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:07 AM

Vallejo, Albert Monthly - Chaparral MS Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

128173 1/30/2015 10 \$0.00

Medium Work In Progress 1/30/2015 3:40:29 PM

Vallejo, Albert Please order new sensing/testing equipment

Albert Vallejo

128084 Main Building Classroom 1/29/2015 11 \$0.00

Medium Work In Progress 311 1/29/2015 9:50:55 AM

Vallejo, Albert Garden tower project needs the shed to be built

Gidget Mora

125846 Main Building Restroom 11/21/2014 80 \$0.00

Medium Work In Progress 11/21/2014 1:47:29 PM

Vallejo, Albert Fans in restrooms are not working  
Women's Restroom in 100 hallway  
Mens Restroom in 300 hallway

Gidget Mora

123096 9/23/2014 139 \$0.00

Medium Work In Progress 9/23/2014 3:39:33 PM

Gallegos, Rafael Roof leaks in 400 hallway.

Albert Vallejo

128209 2/1/2015 2/9/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:49:50 AM

Vallejo, Albert Monthly - Chapparral MS Roof Inspection - Refer to PM schedule details.

Margret Villalobos

120809 Main Building Classroom 8/8/2014 185 \$0.00

Medium Work In Progress 205 8/8/2014 10:47:57 AM

Appelzoller, Fred pipes on sinks need to be fixed

Gidget Mora

125798 Main Building Gym 11/20/2014 81 \$0.00

Medium Work In Progress 11/20/2014 2:02:05 PM

Sotelo, Enrique Light switch does not work on main entry into gym.  
Request all 4 switches be changed to toggle switch

Gidget Mora

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Chaparral MS</b>									
126888					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress			1/4/2015 12:40:25 AM					
Villalobos, David		Yearly - Chaparral MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
128199					2/1/2015	2/4/2015	8		\$0.00
Medium	Work In Progress			2/1/2015 12:49:43 AM					
Vallejo, Albert		Monthly - Chaparral MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
123347		Classroom			9/29/2014		133		\$0.00
Medium	Work In Progress	311		9/29/2014 11:05:45 AM					
Vallejo, Albert		Electrical outlets not covered							
Gidget Mora									
121010	Main Building	Gym			8/12/2014		181		\$0.00
Medium	Work In Progress	400 Hallway		8/12/2014 9:58:13 AM					
Vallejo, Albert		Resume painting of gym /400 hallway							
Gidget Mora									
122690		Hallway/Corridor			9/12/2014		150		\$0.00
Medium	Work In Progress			9/12/2014 9:12:02 AM					
Marquez, Gerardo		senesecita arglar chapa delas puertas de 400/hallway GRACIAS							
M. Carmen Perez									
123710	Main Building	Classroom			10/6/2014		126		\$0.00
Medium	Work In Progress	310		10/6/2014 8:58:44 AM					
Marquez, Gerardo		Cabinet locks are very flimsy and can be easily opened							
Gidget Mora									
<b>Count: 36 Work Orders</b>		<b>Avg. Age of WO's 93</b>		<b>Total for Chaparral MS</b>			<b>0</b>	<b>\$0.00</b>	

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Pride HS</b>									
121689		Classroom			8/25/2014		168		\$0.00
Medium	Work In Progress	101			8/25/2014 10:10:50 AM				
Marquez, Gerardo NEED KEY TO READING LAB 180 IN ROOM 101.									
Yvette Cortez									
121338		Portables			8/18/2014		175		\$0.00
Medium	Work In Progress	1 & 2			8/18/2014 11:30:07 AM				
Marquez, Gerardo DOOR CYLINDER TO STORGE ROOM IN PORTABLE 1 & 2 NEEDS TO BE REPLACED. ALSO, WHEN REPLACING CYLINDER, PLEASE GIVE STORAGE KEY TO MS. SCOTT AND MS. JAMESON-SPED TEACHERS.									
Yvette Cortez									
126753		Portables			12/18/2014		53		\$0.00
Medium	Work In Progress	room #14			12/18/2014 11:19:14				
Gallegos, Rafael Heater is working, blower won't start.									
David Acosta									
127415					1/12/2015		28		\$0.00
Medium	Work In Progress				1/12/2015 3:16:17 PM				
Gallegos, Rafael MR LORENZO SOLIS SIR THE HEATER AT DESERT PRIDE IN NOT TURNING ON CAN YOU PLEASE CHECK THANK YOU AND GOD BLESS									
Adan Duran									
124335					10/20/2014		112		\$0.00
Medium	Work In Progress				10/20/2014 10:31:12				
Duran, Adan PAINT LINES ON BASKETBALL COURT.									
Yvette Cortez									
121923					8/28/2014		165		\$0.00
Medium	Work In Progress	11 & 12			8/28/2014 1:40:28 PM				
Appelzoller, Fred TOILET GETS CLOGGED IN PORTABLE 11 & 12. PLEASE CHECK TO SEE WHAT IS CLOGGING THE TOILET.									
Yvette Cortez									
128527		Portables			2/5/2015		4		\$0.00
Medium	Work In Progress	room 11			2/5/2015 1:44:41 PM				
Villalobos, David Can,tget toilet unclog									
David Acosta									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Desert Pride HS</b>							
124388		Office			10/21/2014		111		\$0.00
Medium	Work In Progress	Conference Rm.			10/21/2014 10:30:05				
Villalobos, David		Drainage line needs to be installed in conference rm . 1							
Yvette Cortez									
124127		Office			10/14/2014		118		\$0.00
Medium	Work In Progress	Conference Rm.			10/14/2014 9:54:48 AM				
Villalobos, David		WATER LINE NEEDS TO BE CONNECTED TO ICE MAKER.							
Yvette Cortez									
124563		Portables			10/24/2014		108		\$0.00
Medium	Work In Progress	15			10/24/2014 8:52:05 AM				
Acosta, David		White board needs to be installed in portable 15.							
Yvette Cortez									
120451					8/4/2014		189		\$0.00
Medium	Work In Progress				8/4/2014 1:51:09 PM				
Marquez, Gerardo		For Desert Pride need three (3) Master keys. Please drop off at Construction office when ready. Should you have any questions please contact Mr. Ralph Gallegos at 575- 882-6921 in the Construction office. Thank You							
Dominique Esparza									
126040					12/1/2014		70		\$0.00
Medium	Work In Progress				12/1/2014 11:31:35 AM				
Ronquillo, Ruben		NEED WINDOW BLINDS IN ADMINISTRIVE ASSITANT'S OFFICE (41.5 L X 41.5 W).							
Yvette Cortez									
123170		Gym			9/24/2014		138		\$0.00
Medium	Work In Progress	GYMNASIUM			9/24/2014 3:12:51 PM				
Ronquillo, Ruben		1. ANCHOR BAG STANDS TO THE FLOOR. 2. INSTALL SPEED BAG TO WALL. 3. ANCHOR BENCHES TO THE FLOOR.							
Yvette Cortez									
128569		Portables			2/6/2015		3		\$0.00
Medium	Work In Progress	16			2/6/2015 8:35:48 AM				
Gonzales, Camilo		In need of a whiteboard to be intstalled in classroom . Do not have extras at DPA							
Maria Carbajal									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Desert Pride HS</b>							
128567		Portables			2/6/2015		3		\$0.00
Medium	Work In Progress	rm 15			2/6/2015 8:34:10 AM				
Gonzales, Camilo		In need of a whiteboard to be installed in classroom. We do not have any extras at DPA							
Maria Carbajal									
124401		Portables			10/21/2014		111		\$0.00
Medium	Work In Progress	room no.10			10/21/2014 12:25:05				
Marquez, Gerardo		Door slams heavy and very hard. Need to replace door closer asap.							
David Acosta									
127984		Portables			1/27/2015		13		\$0.00
Medium	Work In Progress	room 16			1/27/2015 10:08:53 AM				
Gonzalez, Salvador		need to have window guard secure properly due to vandalism.							
David Acosta									
128564		Portables			2/6/2015		3		\$0.00
Medium	Work In Progress	room 9			2/6/2015 8:15:21 AM				
Gonzalez, Salvador		security bar or guard to window needs welding to keep shut							
David Acosta									
<b>Count: 18 Work Orders</b>		<b>Avg. Age of WO's 87</b>			<b>Total for Desert Pride HS</b>			<b>0</b>	<b>\$0.00</b>



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Trail ES</b>									
125439					11/12/2014		89		\$0.00
Medium	Work In Progress				11/12/2014 12:27:58				
Gonzalez, Salvador		Need to secure storage shed in mobile home area to concrete.							
Johnny Acuna									
124678					10/28/2014		104		\$0.00
Medium	Work In Progress				10/28/2014 12:31:36				
Gonzalez, Salvador		Need plate replacement for sidewalk on westside of main building portables area.							
Johnny Acuna									
128475					2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 2:31:00 PM				
Gonzalez, Salvador		Need some stakes w/welded brackets to secure small 8'x10' storage shed next to the kinder playground.							
Johnny Acuna									
125611		Classroom			11/17/2014		84		\$0.00
Medium	Work In Progress				11/17/2014 8:58:15 AM				
Marquez, Gerardo		NEED TO LOCATE AND DELIVER A URINAL SCREEN FOR WORK BEING DONE ON PORTABLE R.RM. REMODEL.							
Gerardo Marquez									
122696					9/12/2014		150		\$0.00
Medium	Work In Progress				9/12/2014 11:12:08 AM				
Orozco, Daniel		As per Health Inspection Report-foot pedal (walk-in)door pedal and freezer foot pedal from sinks are leaking.							
Maritza Gonzalez									
128415					2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 2:48:33 PM				
Orozco, Daniel		FAUCET ON DRAIN IN 3 COMPARTMENT SINK IS BROKEN SNP MANAGER PAT C. 824.3822							
Maritza Gonzalez									
118894					7/2/2014		222		\$0.00
Medium	Work In Progress				7/2/2014 8:23:42 AM				
Acuna, Johnny		Need to patch and re-stitch playground picnic table area Blue Canvas Shade.							
Johnny Acuna									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Desert Trail ES</b>							
128510					2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 8:46:03 AM				
Acuna, Johnny		Need glue for panels to hall.							
Johnny Acuna									
128152					1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 12:41:08 PM				
Acuna, Johnny		Need 4 Drinking classroom bubblers							
Johnny Acuna									
128213					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:53 AM				
Acuna, Johnny		Monthly - Desert Trail ES- Emer Light Insp:Monthly - Refer to PM schedule details.							
Margret Villalobos									
128214					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:53 AM				
Acuna, Johnny		Monthly - Desert Trail ES - Exit Sign Insp:Monthly - Refer to PM schedule details.							
Margret Villalobos									
128215					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:54 AM				
Acuna, Johnny		Monthly - Desert Trail ES -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
128062					1/28/2015		12		\$0.00
Medium	Work In Progress				1/28/2015 3:50:06 PM				
Acuna, Johnny		Need to build floor and construct 8' x 10' storage shed for Pre-k classroom.							
Johnny Acuna									
128465	Main Building	Classroom			2/4/2015		5		\$0.00
Medium	Work In Progress	204,206			2/4/2015 11:01:46 AM				
Villalobos, Margret		We need treatment in rooms #204, 206 for head lice activity.							
Elizabeth Hernandez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail ES</b>							
120033					7/30/2014		194		\$0.00
Medium	Work In Progress			7/30/2014 2:18:04 PM					
Acuna, Johnny	As per Alfredo please order borders needed. Need approx. 22 borders for playground sand to the bigger playground area sets.								
Johnny Acuna									
128593					2/6/2015		3		\$0.00
Medium	Work In Progress			2/6/2015 12:01:10 PM					
Acuna, Johnny	Need 6 swing clamps with swivels for swings top rail.								
Johnny Acuna									
128594					2/6/2015		3		\$0.00
Medium	Work In Progress			2/6/2015 12:03:04 PM					
Acuna, Johnny	Need 6 (replacement) swing seats								
Johnny Acuna									
128639					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress			2/8/2015 12:29:23 AM					
Acuna, Johnny	Monthly - Desert Trail ES - Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
128314					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress			2/1/2015 12:51:00 AM					
Acuna, Johnny	Monthly - Desert Trail ES - Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
127657					1/16/2015		24		\$0.00
Medium	Work In Progress			1/16/2015 2:26:12 PM					
Marquez, Gerardo	Please replace main doors and door closures on the westside of main building. (Portables Area)								
Johnny Acuna									
128590		Custodial			2/6/2015		3		\$0.00
Medium	Work In Progress			2/6/2015 11:56:07 AM					
Carbajal, Jimmy	Buenos dias Jimmy la aspiradora num. 0048 esta fallando de la extencion por favor la pudiera revisar gracias								
Laura Sandoval									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Trail ES</b>									
126971					1/4/2015	1/25/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:41:32 AM				
Munoz, Michael		Monthly - Desert Trail ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
125012					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:24 AM				
Orozco, Daniel		Monthly - Desert Trail ES - Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
128669					2/9/2015		0		\$0.00
Medium	Work In Progress				2/9/2015 11:19:27 AM				
Carrasco, Danny		Need diesel fuel for John Deere Tractor.							
Johnny Acuna									
127993					1/27/2015		13		\$0.00
Medium	Work In Progress				1/27/2015 2:30:51 PM				
Carrasco, Danny		Need unleaded gas for worktruck #192							
Johnny Acuna									
125181					11/5/2014		96		\$0.00
Medium	Work In Progress				11/5/2014 2:44:50 PM				
Flores, Pete		Please fix fuel gauge to work truck #192							
Johnny Acuna									
128658					2/9/2015		0		\$0.00
Medium	Work In Progress				2/9/2015 9:19:58 AM				
Ontiveros, Guadalupe		Need to relocate swing set with 2 swings to other side. Please see Coach Scott. Thanks							
Johnny Acuna									
127155					1/6/2015		34		\$0.00
Medium	Work In Progress				1/6/2015 4:06:08 PM				
Appelzoller, Fred		Portable #408: Need a 1/2" water supply valve with (2) 3/8" outlet water supplies to sink and drinking fountain.							
Johnny Acuna									
119597					7/18/2014		206		\$0.00
Medium	Work In Progress				7/18/2014 3:05:40 PM				
Appelzoller, Fred		Need parts to repair broken clean-out.							
Johnny Acuna									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert Trail ES</b>							
126889					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:25 AM				
Villalobos, David	Yearly - Desert Trail ES - Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
128592					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 11:58:23 AM				
Acuna, Johnny	Need oil based paint for main building doors.								
Johnny Acuna									
128377					2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 7:50:03 AM				
Solis, Lorenz	Need control knob for a radiant heater in room #208								
Johnny Acuna									
128596					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 12:08:38 PM				
Marquez, Gerardo	Portable #406: Classroom Door is not locking properly.								
Johnny Acuna									
121108					8/13/2014		180		\$0.00
Medium	Work In Progress				8/13/2014 11:37:57 AM				
Vallejo, Albert	Need assistance with electrical to cafeteria A/c units.								
Johnny Acuna									
<b>Count: 34 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>49</b>	<b>Total for Desert Trail ES</b>			<b>0</b>	<b>\$0.00</b>	

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert View ES</b>									
120106		Library			7/31/2014		193		\$0.00
Medium	Work In Progress	Library			7/31/2014 2:02:45 PM				
Ortiz, Ruben		Paint white window on left side of entrance door to maroon. (Sanchez-Segura)							
Guadalupe Gonzalez									
120107		Library			7/31/2014		193		\$0.00
Medium	Work In Progress	Library			7/31/2014 2:06:39 PM				
Ortiz, Ruben		Paint upper corner triangle of south wall in Golden Yellow like the NM Flag. (Sanchez-Segura)							
Guadalupe Gonzalez									
128072		Parking Lot			1/29/2015		11		\$0.00
Medium	Work In Progress				1/29/2015 7:23:19 AM				
Castillo, Carlos		As per custodial dept., parking lot light poles are not turning on.							
Carlos Castillo									
124435					10/22/2014		110		\$0.00
Medium	Work In Progress				10/22/2014 9:03:17 AM				
Castillo, Carlos		Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Cell Phone: (575)635-8919 Email: blanca@caliperconst.com							
		Location of Work: SPOT: 100FT RAD FROM CENTER OF INTERSECTION.							
Dominique Esparza									
124806					10/30/2014		102		\$0.00
Medium	Work In Progress				10/30/2014 4:04:18 PM				
Castillo, Carlos		Two lights in the office are not working; need it repaired. Thank you, Ruben							
Ruben Ortiz									
127438					1/12/2015		28		\$0.00
Medium	Work In Progress				1/12/2015 4:09:05 PM				
Castillo, Carlos		Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Email: blanca@caliperconst.com							
Dominique Esparza									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

**Location:** Desert View ES

127964 1/26/2015 14 \$0.00

Medium Work In Progress 1/26/2015 3:58:11 PM

Castillo, Carlos  
 Company: CALIPER CONSTRUCTION  
 Contact Name: FERNIE REYES Contact Phone: (575)635-8919  
 Alternate Contact: BLANCA CRUZ  
 Email: blanca@caliperconst.com

Location of Work: LOCATE PER ZONE 1 WORK PLAN

Dominique Esparza

128342 2/2/2015 7 \$0.00

Medium Work In Progress 2/2/2015 2:30:31 PM

Castillo, Carlos  
 Company: CARVER ELECTRIC  
 Contact Name: JACOB CARVER Contact Phone: (575)527-2127  
 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142  
 Cell Phone: (575)649-9207 Pager No:  
 Email: carver@carverelectric.com

Location of Work: LOCATE PER THE DESERT VIEW ELEMENTERY WORK PLAN

Dominique Esparza

128421 2/3/2015 6 \$0.00

Medium Work In Progress 2/3/2015 3:24:47 PM

Castillo, Carlos  
 Company: METRO MECHANICAL  
 Contact Name: RICHARD MUNOZ Contact Phone: (575)649-5554  
 Email: metromechinc@qwestoffice.net

Location of Work: SPOT ENTIRE PROPERTY. OPEN ACCESS; NO HAZARDS

Dominique Esparza

126890 1/4/2015 2/4/2015 36 \$0.00

Medium Work In Progress 1/4/2015 12:40:26 AM

Villalobos, David  
 Yearly - Desert View ES Backflow Inspection - Refer to PMschedule details.

Margret Villalobos

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

<b>Location:</b>	<b>Desert View ES</b>								
124436					10/22/2014		110		\$0.00
Medium	Work In Progress				10/22/2014 9:03:34 AM				
		Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Cell Phone: (575)635-8919 Email: blanca@caliperconstoom  Location of Work: SPOT: 100FT RAD FROM CENTER OF INTERSECTION.							

Dominique Esparza									
123369					9/29/2014		133		\$0.00
Medium	Work In Progress				9/29/2014 4:01:13 PM				
	Sotelo, Enrique	Company: CALIPER CONSTRUCTION Contact Name: FERNIE REYES Contact Phone: (575)635-8919 Alternate Contact: BLANCA CRUZ Alternate Phone: Best Time to Call: Fax No: Cell Phone: Pager No: Email: blanca@caliperconstoom  Location of Work: LOCATE PER ZONE 1 WORK PLAN							

Dominique Esparza									
124300	Main Building	Restroom			10/17/2014		115		\$0.00
Medium	Work In Progress				10/17/2014 12:37:11				
	Ontiveros, Joe	hi Joe we have a urinal in the boys restroom that is clogged. Can you unclogg it please. Thank you							

Israel Ortega									
128043	Main Building	Restroom (Girls)			1/28/2015		12		\$0.00
Medium	Work In Progress				1/28/2015 1:53:12 PM				
	Ontiveros, Joe	Hi Joe on the lower grade restroom there is a sink that is clogged can you unclog it please. Thank you							

Israel Ortega									
128044	Main Building	Restroom			1/28/2015		12		\$0.00
Medium	Work In Progress				1/28/2015 1:54:55 PM				
	Ontiveros, Joe	Hi Joe on the boys upper grade level restrooms the sink faucet is broke. Can you replace it please. Thank you.							

Israel Ortega



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

**Location:** Desert View ES

128045 Main Building Storage 1/28/2015 12 \$0.00

Medium Work In Progress 1/28/2015 1:57:31 PM

Ontiveros, Joe Hi Joe on the storage that is next to the upper grade level restroom the release valve on the water is leaking. It needs to be replaced. Thank you.

Israel Ortega

128046 Main Building Storage 1/28/2015 12 \$0.00

Medium Work In Progress 1/28/2015 2:02:36 PM

Ontiveros, Joe Hi Joe on the storage next to the restroom the back flow pleventer is leaking can you fix it please. Thank you

Israel Ortega

128422 2/3/2015 6 \$0.00

Medium Work In Progress 2/3/2015 3:25:07 PM

Ontiveros, Joe Company: METRO MECHANICAL  
 Contact Name: RICHARD MUNOZ Contact Phone: (575)649-5554  
 Email: metromechinc@qwestoffice.net

Location of Work: SPOT ENTIRE PROPERTY. OPEN ACCESS; NO HAZARDS

Dominique Esparza

128343 2/2/2015 7 \$0.00

Medium Work In Progress 2/2/2015 2:31:05 PM

Ontiveros, Joe Company: CARVER ELECTRIC  
 Contact Name: JACOB CARVER Contact Phone: (575)527-2127  
 Alternate Contact: DANIEL CARVER Alternate Phone: (575)649-9142  
 Cell Phone: (575)649-9207 Pager No:  
 Email: carver@carverelectric.com

Location of Work: LOCATE PER THE DESERT VIEW ELEMENTERY WORK PLAN

Dominique Esparza

127967 1/26/2015 14 \$0.00

Medium Work In Progress 1/26/2015 4:00:50 PM

Ontiveros, Joe Company: CALIPER CONSTRUCTION  
 Contact Name: FERNIE REYES Contact Phone: (575)635-8919  
 Alternate Contact: BLANCA CRUZ  
 Email: blanca@caliperconst.com

Location of Work: LOCATE PER ZONE 1 WORK PLAN

Dominique Esparza

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

<b>Location:</b>	<b>Desert View ES</b>								
126802					12/19/2014		52		\$0.00
Medium	Work In Progress				12/19/2014 1:54:53 PM				
Ontiveros, Joe	Company: TRIPLE J EXCAVATION								
	Contact Name: FREDDIE PAIZ		Contact Phone: (575)527-1763						
	Alternate Contact: JOE RODRIGUEZ		Alternate Phone: (575)642-7427						
	Best Time to Call:		Fax No: (575) 541-8136						
	Cell Phone: (575)639-4189								
	Location of Work: SPOT:25FT RADIUS OF THE RED STAKED FLAG LOCATED NEAR THE INTERSECTION. AREA IS MARKED IN WHITE NO KNOWN HAZARDS/ OPEN ACCESS								

Dominique Esparza									
127439					1/12/2015		28		\$0.00
Medium	Work In Progress				1/12/2015 4:09:23 PM				
Ontiveros, Joe	Company: CALIPER CONSTRUCTION								
	Contact Name: FERNIE REYES		Contact Phone: (575)635-8919						
	Alternate Contact: BLANCA CRUZ		Email: blanca@caliperconstoom						

Dominique Esparza									
128600					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 1:43:42 PM				
Ontiveros, Guadalupe	Buster pump for irrigation is not working; need it fixed ASAP								

Ruben Ortiz									
128601					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 1:44:28 PM				
Ontiveros, Guadalupe	The upper level playground valve no. 1 is not working; need it fixed.								

Ruben Ortiz									
127357					1/11/2015	1/27/2015	29		\$0.00
Medium	Work In Progress				1/11/2015 12:30:00 AM				
Ortega, Israel	Monthly - QRTLY BLDG INSP REPORT (DV) - Refer to PM schedule details.								
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Desert View ES</b>							
120111		Office			7/31/2014		193		\$0.00
Medium	Work In Progress	Office			7/31/2014 2:16:37 PM				
Ortiz, Ruben		Put banners up on the fence. (Gonzalez)							
Guadalupe Gonzalez									
123052		Classroom			9/23/2014		139		\$0.00
Medium	Work In Progress	School Campus			9/23/2014 9:21:13 AM				
Ortiz, Ruben		2nd Request: Due to the construction need weather strips for the doors to keep insects from coming into the school.							
Guadalupe Gonzalez									
120662		Classroom			8/6/2014		187		\$0.00
Medium	Work In Progress	Rm. #14			8/6/2014 2:40:13 PM				
Ortiz, Ruben		Air Conditioner not working. (Bueno)							
Guadalupe Gonzalez									
120663		Classroom			8/6/2014		187		\$0.00
Medium	Work In Progress	Rm. #16			8/6/2014 2:40:57 PM				
Ortiz, Ruben		Air Conditioner not working. (Mack)							
Guadalupe Gonzalez									
122783		Classroom			9/15/2014		147		\$0.00
Medium	Work In Progress	Rm. #12			9/15/2014 3:49:22 PM				
Ortiz, Ruben		Take TV down and remove from classroom. (Ramos)							
Guadalupe Gonzalez									
120105		Library			7/31/2014		193		\$0.00
Medium	Work In Progress	Library			7/31/2014 2:01:36 PM				
Ortiz, Ruben		Move projection screen back towards circulations desk. (Sanchez-Segura)							
Guadalupe Gonzalez									
121789					8/26/2014		167		\$0.00
Medium	Work In Progress				8/26/2014 2:41:33 PM				
Ortiz, Ruben		The sink in the kitchen is clogged. Need it repaired ASAP							
Ruben Ortiz									
121790					8/26/2014		167		\$0.00
Medium	Work In Progress				8/26/2014 2:42:35 PM				
Ortiz, Ruben		The upper level girl's bathroom, the one faucet is leaking and the other is broken. Need it replaced.							
Ruben Ortiz									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Desert View ES</b>							
120664					8/6/2014		187		\$0.00
Medium	Work In Progress	Rm. #33			8/6/2014 2:42:09 PM				
Ortiz, Ruben		Air Conditioner not working. (Gutierrez)							
Guadalupe Gonzalez									
128275					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:34 AM				
Ortiz, Ruben		Monthly - Desert View ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
128276					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:35 AM				
Ortiz, Ruben		Monthly - Desert View ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
128277					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:35 AM				
Ortiz, Ruben		Monthly - Desert View ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
125013					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:24 AM				
Orozco, Daniel		Monthly - Desert View ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
125536					11/13/2014		88		\$0.00
Medium	Work In Progress	Front of School			11/13/2014 3:46:34 PM				
Munoz, Michael		Repair broken sidewalk in the front of school. It can cause someone to trip. (Araujo)							
Guadalupe Gonzalez									
127458		Custodial			1/13/2015		27		\$0.00
Medium	Work In Progress				1/13/2015 9:17:23 AM				
Carbajal, Jimmy		Hi Jimmy, we got an extractor carpet cleaning machine #008435 that is not working properly. It does not spray the soap to the carpet. Can you fix it for us please. Thank you							
Israel Ortega									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
127461		Custodial			1/13/2015		27		\$0.00
Medium	Work In Progress			1/13/2015 9:24:24 AM					
Carbajal, Jimmy	Hi Jimmy, I have another vacuum cleaner ROYAL #20002038 that doesn't want to turn on. Can you fix it for us please. Thank you								
Israel Ortega									
128451		Custodial			2/4/2015		5		\$0.00
Medium	Work In Progress			2/4/2015 8:41:07 AM					
Carbajal, Jimmy	Hi Jimmy we have a vacuum cleaner that shut off it needs to be repaired. Vacuum cleaner #C08C00000330. Thank you								
Israel Ortega									
128310					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress			2/1/2015 12:50:57 AM					
Ortiz, Ruben	Monthly - Desert View ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									
124694					10/28/2014		104		\$0.00
Safety	Work In Progress			10/28/2014 3:34:57 PM					
Ortiz, Ruben	Need to remove all chains and seats from the swing sets in the upper level playground as per Principal Araujo								
Ruben Ortiz									
124687					10/28/2014		104		\$0.00
Safety	Work In Progress			10/28/2014 3:23:14 PM					
Ortiz, Ruben	Replace all the swing sets in the playground								
Ruben Ortiz									
128645					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress			2/8/2015 12:29:27 AM					
Ortiz, Ruben	Monthly - Desert View ES Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
128066					1/28/2015		12		\$0.00
Medium	Work In Progress			1/28/2015 3:56:37 PM					
Orozco, Daniel	SNOUT ON DRAIN IN 3 COMPARTMENT SINK IS BROKEN SNP MANAGER ELIZABETH D. 589.2425								
Maritza Gonzalez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Desert View ES</b>							
122564					9/10/2014		152		\$0.00
Medium	Work In Progress				9/10/2014 9:42:24 AM				
Orozco, Daniel		THE RISE PART ON 3 COMPARTMENT SINK IS CLOGGED. SNP MANAGER ELIZABETH D. 589.2425							
Maritza Gonzalez									
<b>Count: 48 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>72</b>			<b>Total for Desert View ES</b>	<b>0</b>		<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>GAC</b>							
128638					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress			2/8/2015 12:29:22 AM					
Moncayo, Fernando	Monthly - GAC Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
128080					1/29/2015		11		\$0.00
Medium	Work In Progress			1/29/2015 9:22:38 AM					
Villalobos, Margret	MICE PROBLEMS IN KITCHEN AREA (DRY STORAGE AND LAUNDRY ROOM).		1/29/15 Emailed waiver and wo						
Maritza Gonzalez									
126850					1/4/2015		36		\$0.00
Medium	Work In Progress			1/4/2015 12:39:53 AM					
Holguin, Alfredo	Monthly - GAC (Admin) -Generator PM (Quarterly) - Refer to PM schedule details.								
Margret Villalobos									
125757					11/19/2014		82		\$0.00
Medium	Work In Progress			11/19/2014 2:18:32 PM					
Moncayo, Fernando	HR REQUEUSTING TO HAVE HR CONFERENCE ROOM PAINTED.								
Maritza Gonzalez									
125495					11/13/2014		88		\$0.00
Medium	Work In Progress			11/13/2014 8:36:40 AM					
Moncayo, Fernando	A-WING-WALL NEEDS TO BE FIXED IN MENS HANDICAP RR.								
Maritza Gonzalez									
126166					12/3/2014		68		\$0.00
Medium	Work In Progress			12/3/2014 10:24:20 AM					
Moncayo, Fernando	C-WING -LIGHTS NEED TO BE INSTALLED IN HALLWAY WHERE MRS. YTURRALDE IS LOCATED.								
Maritza Gonzalez									
122154					9/2/2014		160		\$0.00
Medium	Work In Progress			9/2/2014 9:18:11 AM					
Moncayo, Fernando	BALLAST NEEDS TO BE CHANGED OUT IN ROSA HIDALGO.								
Maritza Gonzalez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>GAC</b>							
122634					9/11/2014		151		\$0.00
Medium	Work In Progress				9/11/2014 9:48:04 AM				
Moncayo, Fernando		ROSA APODACA OFFICE-BURNT SMELL COMING OUT OF WALL UNIT.							
Maritza Gonzalez									
122635					9/11/2014		151		\$0.00
Medium	Work In Progress				9/11/2014 9:48:24 AM				
Moncayo, Fernando		MARY TELLEZ OFFICE-BURNT SMELL COMING OUT OF WALL UNIT.							
Maritza Gonzalez									
121419					8/19/2014		174		\$0.00
Medium	Work In Progress				8/19/2014 11:43:45 AM				
Moncayo, Fernando		NO POWER TO WALL UNIT IN ROSA HIDALGO OFFICE.							
Maritza Gonzalez									
128211					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:51 AM				
Moncayo, Fernando		Monthly - GAC Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
128212					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:52 AM				
Moncayo, Fernando		Monthly - GAC Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
127465					1/13/2015		27		\$0.00
Medium	Work In Progress				1/13/2015 9:54:51 AM				
Moncayo, Fernando		AS PER TORI GILPIN FOUL SMELL COMING FROM VENTS IN C-WING.							
Maritza Gonzalez									
128035					1/28/2015		12		\$0.00
Medium	Work In Progress				1/28/2015 12:33:38 PM				
Moncayo, Fernando		As per Mr. Yturalde, the corner that was fixed last month in the men's bathroom right by the board room is falling off again we need Fernando to fix right away. We will be hosting another big meeting next Friday and that is one of the main bathrooms that is used.							
Maritza Gonzalez									



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>GAC</b>							
127997					1/27/2015		13		\$0.00
Medium	Work In Progress				1/27/2015 3:24:10 PM				
Moncayo, Fernando		ck and replace broken or leaking irrigation sprinklers							
Fernando Moncayo									
128583					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 10:23:27 AM				
Moncayo, Fernando		Calixto office needs ceiling bulbs in his office							
Cora Ramirez									
128462					2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 10:55:27 AM				
Moncayo, Fernando		RESTROM IN C WING (BY MR. MANRIQUEZ) NOT FLUSHING.							
Maritza Gonzalez									
128555					2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 4:21:18 PM				
Moncayo, Fernando		need blubs to brighten up office							
Cora Ramirez									
128300					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:51 AM				
Moncayo, Fernando		Monthly - GAC Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
125026					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:33 AM				
Orozco, Daniel		Monthly - GAC Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
123748		Restroom (Girls)			10/6/2014		126		\$0.00
High	Work In Progress				10/6/2014 3:43:57 PM				
Estrada, Jesus		Replace tile in bathroom it was removed over fall break c wing							
Jesus Estrada									
126972					1/4/2015	1/25/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:41:32 AM				
Munoz, Michael		Monthly - GAC Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>GAC</b>							
126413					12/9/2014		62		\$0.00
Medium	Work In Progress				12/9/2014 1:10:45 PM				
Munoz, Michael		AS PER MR. CHAVEZ, WEST WALL AT PRE-K BETWEEN WINDOWS/GENERATOR NEEDS TO BE REPAIRED.							
Maritza Gonzalez									
119593					7/18/2014		206		\$0.00
Medium	Work In Progress				7/18/2014 2:11:02 PM				
Lara, Ralph		PLEASE CHECK SNP STORAGE IN BISTRO, LOCK STUCK CANNOT OPEN.							
Maritza Gonzalez									
124231					10/16/2014		116		\$0.00
Medium	Work In Progress				10/16/2014 9:43:06 AM				
Lara, Ralph		NEED KEY TO ROOM 113 IN C WING (ROSIE VILLALOBOS) TO BE PUT BACK ON MASTER, RIGHT NOW IT IS OFF MASTER.							
Maritza Gonzalez									
128629					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 4:02:43 PM				
Lara, Ralph		have a new computer tech - need key to technology office							
Cora Ramirez									
128148					1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 11:31:18 AM				
Ontiveros, Joe		A-WING, WOMENS RR BACKING UP.							
Maritza Gonzalez									
128651					2/9/2015		0		\$0.00
Medium	Work In Progress				2/9/2015 8:08:46 AM				
Ontiveros, Joe		GAS SMELL BY ENTRANCE.							
Maritza Gonzalez									
123425					9/30/2014		132		\$0.00
Medium	Work In Progress				9/30/2014 3:42:13 PM				
,		PROJECT MANAGEMENT & FINAL CLEARANCE FOR ASBESTOS ABATEMENT AT GAC - RESTROOM IN "A" WING							
Alfredo Holguin									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: GAC</b>									
126891					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:27 AM				
Villalobos, David		Yearly - GAC Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
125102		Hallway/Corridor			11/3/2014		98		\$0.00
Medium	Work In Progress				11/3/2014 3:28:00 PM				
Castillo, Carlos		Check hallway dark areas for emergency lighting installation. And install where needed.							
Carlos Castillo									
126541					12/11/2014		60		\$0.00
Medium	Work In Progress				12/11/2014 2:59:29 PM				
Moncayo, Fernando		Conference Room next to Mary Chavez - Re glue wall paper at all areas where its coming lose, properly patch any unused holes in walls, paint entire room							
Alfredo Holguin									
121916					8/28/2014		165		\$0.00
Medium	Work In Progress				8/28/2014 12:23:26 PM				
Ambriz, Jose		Anne de Los Santos would like to place a work order for the possibility of installing an A/C in her office. Approved by Mr. Suggs							
Maritza Gonzalez									
125240					11/6/2014		95		\$0.00
Medium	Work In Progress				11/6/2014 3:04:25 PM				
Ambriz, Jose		As per Mrs. Gilpin, could you please have the A/C unit in her office replaced due to the very loud noise it makes.							
Maritza Gonzalez									
125499					11/13/2014		88		\$0.00
Medium	Work In Progress				11/13/2014 9:12:15 AM				
Ambriz, Jose		REPLACE UNIT IN KITCHEN AREA. LEAKING FROM COMPRESSOR SECTIONG.							
Maritza Gonzalez									
119230					7/9/2014		215		\$0.00
Medium	Work In Progress				7/9/2014 2:40:00 PM				
Ambriz, Jose		As per Mr. Steve Suggs, he would like a wall a/c unit installed in Richard Acosta and Priscilla Escobar office.							
Maritza Gonzalez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC</b>							
119435					7/15/2014		209		\$0.00
Medium	Work In Progress				7/15/2014 1:29:36 PM				
Ambriz, Jose		chiller libert circuit 1 need to replace compressors, making a loud noise.							
Jose Ambriz									
<b>Count: 37 Work Orders</b>		<b>Avg. Age of WO's 75</b>		<b>Total for GAC</b>				<b>0</b>	<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: GAC - Pre-K</b>									
127302		Cafeteria			1/9/2015		31		\$0.00
Medium	Work In Progress				1/9/2015 2:40:16 PM				
Ontiveros, Joe		We need our small sink in our cafeteria replaced with a large deep utility/kitchen sink with counters and cabinets.							
Leticia Tangonan									
128086					1/29/2015		11		\$0.00
Medium	Work In Progress	playground			1/29/2015 10:01:24 AM				
Rodriguez, Arturo		We would like our artificial grass cleaned out in the playground area. Water has leaked on to it and has caused it to have a bad odor.							
Leticia Tangonan									
127307					1/9/2015		31		\$0.00
Medium	Work In Progress	playground			1/9/2015 2:53:53 PM				
Ontiveros, Guadalupe		Requesting 2 raised wooden planters for our playground							
Leticia Tangonan									
128391		Classroom			2/3/2015		6		\$0.00
Medium	Work In Progress	201			2/3/2015 9:40:41 AM				
Ontiveros, Joe		The sink faucet in room 201 needs to be replaced. It has been leaking.							
Leticia Tangonan									
127305		Athletic Field			1/9/2015		31		\$0.00
Medium	Work In Progress	playground			1/9/2015 2:50:09 PM				
Gonzalez, Salvador		Morgan building, where playground equipment is stored needs a ramp to facilitate/easy access to trikes. Morgan building where playground equipment is stored needs a ramp to make for easy access to trikes, wagons and other playground toys.							
Leticia Tangonan									
128393		Hallway/Corridor			2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 9:42:46 AM				
Moncayo, Fernando		please add light bulbs in our hallway.							
Leticia Tangonan									
124226					10/16/2014		116		\$0.00
Medium	Work In Progress				10/16/2014 8:57:29 AM				
Moncayo, Fernando		RM. 103- SINK IS LEAKING.							
Maritza Gonzalez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC - Pre-K</b>							
127751		Classroom			1/21/2015		19		\$0.00
Medium	Work In Progress	101			1/21/2015 10:19:18 AM				
Moncayo, Fernando		please install pencil sharpener in room 101							
Leticia Tangonan									
128085		Classroom			1/29/2015		11		\$0.00
Medium	Work In Progress	103			1/29/2015 9:58:09 AM				
Moncayo, Fernando		We need a pencil sharpener installed in room 103							
Leticia Tangonan									
<b>Count: 9 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>29</b>	<b>Total for GAC - Pre-K</b>			<b>0</b>	<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden ES</b>									
128221					2/1/2015		8		\$0.00
Medium	Work In Progress			2/1/2015 12:49:58 AM					
Appelzoller, Fred	Monthly - Gadsden ES - Clothes Dryer (Monthly) - Refer to PM schedule details.								
Margret Villalobos									
122297		Athletic Field			9/4/2014		158		\$0.00
High	Work In Progress			9/4/2014 9:12:27 AM					
Appelzoller, Fred	need to cut weeds through out site, inside and outside of fence. also the weeds that have been killed with round up need to be cut as well. school is in dire need of weed control. need to include ponds.								
Michael Munoz									
128224					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress			2/1/2015 12:50:00 AM					
Appelzoller, Fred	Monthly - Gadsden ES - Exit Sign Insp-Monthly - Refer to PM schedule details.								
Margret Villalobos									
128225					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress			2/1/2015 12:50:00 AM					
Appelzoller, Fred	Monthly - Gadsden ES - Emer Light Test - Monthly - Refer to PM schedule details.								
Margret Villalobos									
128637					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress			2/8/2015 12:29:21 AM					
Appelzoller, Fred	Monthly - Gadsden ES - Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
126534					12/11/2014		60		\$0.00
Medium	Work In Progress			12/11/2014 1:56:03 PM					
Appelzoller, Fred	need assistance with repairing jungle gym on the premises... would greatly appreciate your assistance in this matter...								
Loraine Gandara									
127755					1/21/2015		19		\$0.00
Medium	Work In Progress			1/21/2015 11:30:47 AM					
Orozco, Daniel	REACH IN REFRIGERATOR IS FREEZING ITEMS. SNP MANAGER EVA M. 882.3410								
Maritza Gonzalez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Gadsden ES</b>							
128647					2/9/2015		0		\$0.00
Medium	Work In Progress				2/9/2015 7:43:31 AM				
Orozco, Daniel		ICE MACHINE DOWN. SNP MANAGER EVA M. 882.3410							
Maritza Gonzalez									
125027					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:33 AM				
Orozco, Daniel		Monthly - Gadsden ES - Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
125028					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:34 AM				
Orozco, Daniel		Monthly - Gadsden ES - Fire Suppression Insp - Refer to PM schedule details.							
Margret Villalobos									
128298					2/1/2015	2/12/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:49 AM				
Appelzoller, Fred		Monthly - Gadsden ES - FE Inspection - Monthly - Refer to PM schedule details.							
Margret Villalobos									
122373		Parking Lot			9/5/2014		157		\$0.00
Medium	Work In Progress				9/5/2014 9:46:47 AM				
Ontiveros, Guadalupe		need for cement barriers to be mounted to the asphalt...I would really appreciate if this could be done asap... thank you...							
Loraine Gandara									
127362					1/11/2015	1/27/2015	29		\$0.00
Medium	Work In Progress				1/11/2015 12:30:08 AM				
Pinon, Jose		Monthly - QRTLY BLDG INSP REPORT (GES) - Refer to PM schedule details.							
Margret Villalobos									
128210					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:51 AM				
Appelzoller, Fred		Monthly - Gadsden ES - Roof Inspection - Refer to PM schedule details.							
Margret Villalobos									



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden ES</b>									
127036		Classroom			1/5/2015		35		\$0.00
Medium	Work In Progress	302			1/5/2015 10:19:00 AM				
Appelzoller, Fred		good morning....one of the outlets is making a lot of noise...need assistance...teacher is unable to plug anything in...							
Loraine Gandara									
123039		Parking Lot			9/23/2014		139		\$0.00
Medium	Work In Progress				9/23/2014 8:35:17 AM				
Sotelo, Enrique		need for the lights to be replaced outside in the parking lot...greatly appreciate your assistance							
Loraine Gandara									
127977		Mechanical			1/27/2015		13		\$0.00
Medium	Work In Progress				1/27/2015 8:04:13 AM				
Sotelo, Enrique		need electrical outlets in Mech room							
Fred Appelzoller									
126909					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:40 AM				
Villalobos, David		Yearly - Gadsden ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
125788		Office			11/20/2014		81		\$0.00
Medium	Work In Progress				11/20/2014 8:00:37 AM				
Appelzoller, Fred		need spray cans to paint , flower pots out in front about 15 cans of almond or white							
Fred Appelzoller									
<b>Count: 19 Work Orders</b>		<b>Avg. Age of WO's 51</b>		<b>Total for Gadsden ES</b>		<b>0</b>	<b>\$0.00</b>		

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
120592	Academic Bldg	Classroom			8/5/2014		188		\$0.00
Medium	Work In Progress	306			8/5/2014 3:54:18 PM				
Nunez, Arturo		Requested by Mr. Nunez Rm. 306 Academic Building- Paint wall with writing.							
Velia Alarcon									
126051	Boys Gym	Dressing Room			12/1/2014		70		\$0.00
Medium	Work In Progress	Boy's Football			12/1/2014 1:35:09 PM				
Nunez, Arturo		Requested by Coach J. Vasquez for Football Locker Room in Boy's Gym - Painting of both locker rooms.							
Velia Alarcon									
122944					9/18/2014		144		\$0.00
Medium	Work In Progress				9/18/2014 7:38:30 AM				
Sotelo, Enrique		Need to replace burn out lamps on the south side of school, area by the swimming pool. This area has now 4 lights out and one by grounds. Need bucket truck.							
Guillermo Hernandez									
125669					11/18/2014		83		\$0.00
Medium	Work In Progress				11/18/2014 8:46:59 AM				
Castillo, Carlos		Assist with replacement of damaged light poles at GHS							
Carlos Castillo									
127873					1/23/2015		17		\$0.00
Medium	Work In Progress				1/23/2015 3:32:32 PM				
Sotelo, Enrique		Need to install 2 light fixtures in portable #6, Art was placed in classroom and needs more light							
Guillermo Hernandez									
128360					2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 3:53:51 PM				
Ambriz, Jose		Need to replace T-stats for the fan coils at the Old English.							
Guillermo Hernandez									
121445					8/19/2014		174		\$0.00
Medium	Work In Progress				8/19/2014 3:12:05 PM				
Ambriz, Jose		Unit need in Portable #4 to be upgraded from 2T to 3T. Too many students, the existing unit is an Armstrong 2Ton unit.							
Guillermo Hernandez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
125483					11/13/2014		88		\$0.00
Medium	Work In Progress				11/13/2014 7:44:53 AM				
Ambriz, Jose		Need to replace broken water fountain in the north building by the boys restroom.							
Guillermo Hernandez									
128445					2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 7:56:08 AM				
Ambriz, Jose		Need to replace communication board for #620 H/C unit at the science building. X13651545010							
Guillermo Hernandez									
127152					1/6/2015		34		\$0.00
Medium	Work In Progress				1/6/2015 3:58:15 PM				
Villalobos, David		Requested by Mr. G. Jordan for Portable # 10-Toilet is running continuously and not working.							
Velia Alarcon									
126892					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:27 AM				
Villalobos, David		Yearly - Gadsden HS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
127729					1/21/2015		19		\$0.00
Medium	Work In Progress				1/21/2015 5:38:14 AM				
Villalobos, David		weightroom womens sink dogged							
Isaac Holguin									
128201					2/1/2015	2/4/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:45 AM				
Nunez, Arturo		Monthly - Gadsden HS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
128449					2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 8:22:53 AM				
Villalobos, David		Need to replace flush valve to toilet in the boys restroom (cafeteria).							
Guillermo Hernandez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
128071	Cafeteria (1998)	Restroom			1/29/2015		11		\$0.00
Medium	Work In Progress				1/29/2015 6:14:39 AM				
Villalobos, David		2 toilets in boys restroom keep flushing by themselves and one urinal flushing by itself, had to turn all 3 of them off							
Isaac Holguin									
128448	Cafeteria (1998)	Restroom			2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 8:17:13 AM				
Villalobos, David		boys restroom in cafeteria after lunch toilets run and run							
Isaac Holguin									
126400		Restroom (Girls)			12/9/2014		62		\$0.00
Medium	Work In Progress				12/9/2014 7:29:53 AM				
Villalobos, David		girls restroom in old gym (boys Gym) clogged toilet							
Isaac Holguin									
124485					10/22/2014		110		\$0.00
Medium	Work In Progress				10/22/2014 3:49:00 PM				
Villalobos, David		Need to replace vandalized sink faucet in Science #600, Lilly Chavez.							
Guillermo Hernandez									
125480					11/13/2014		88		\$0.00
Medium	Work In Progress				11/13/2014 7:40:30 AM				
Villalobos, David		Need assistance to repair water leak by the water fountain in the Old English first floor.							
Guillermo Hernandez									
125481					11/13/2014		88		\$0.00
Medium	Work In Progress				11/13/2014 7:42:20 AM				
Villalobos, David		Need assistance to unclog sink in the weight room, need drain snake.							
Guillermo Hernandez									
125482					11/13/2014		88		\$0.00
Medium	Work In Progress				11/13/2014 7:43:50 AM				
Villalobos, David		Need assistance to unclog sink in the girls restroom at the east wing (testing room) of the cafeteria, Need drain snake.							
Guillermo Hernandez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
119303	Auto Shop				7/11/2014		213		\$0.00
Medium	Work In Progress				7/11/2014 12:42:51 PM				
Sotelo, Enrique		NEED FOR ELECTRICAL POWER TO BE INSTALLED FOR NEW LIFT.							
Gerardo Marquez									
126662	North Building				12/16/2014		55		\$0.00
High	Work In Progress				12/16/2014 10:14:03				
Sotelo, Enrique		need lighting on the west wall of the rotc building. very dark at night. thank you							
Michael Munoz									
127022					1/5/2015		35		\$0.00
High	Work In Progress				1/5/2015 7:42:35 AM				
Sotelo, Enrique		Need to replace ballasts or lamps to the outside lights of the weight room, this area is to dark at night.							
Guillermo Hernandez									
128362					2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 3:55:01 PM				
Sotelo, Enrique		Need to replace ballast in the cafeteria.							
Guillermo Hernandez									
128330					2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 9:02:27 AM				
Sotelo, Enrique		LEAKING IN KITCHEN IN THE LIGHT FIXTURES. SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
119662					7/21/2014		203		\$0.00
Medium	Work In Progress				7/21/2014 3:37:51 PM				
Ronquillo, Ruben		Ruben, need to order two light poles to be replaced. Questions ask Enrique S. as per Alfredo.				2/4/15 - See wo 125669			
Guillermo Hernandez									
128008					1/27/2015		13		\$0.00
Medium	Work In Progress				1/27/2015 3:41:21 PM				
Hernandez, Guillermo		Need to unclog main sewer line in the hallway of the Annexbuilding.							
Guillermo Hernandez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: Gadsden HS</b>									
126570					12/12/2014		59		\$0.00
Medium	Work In Progress				12/12/2014 9:01:17 AM				
Carbajal, Jimmy	i need maybe about 5 more 55 gal drums for trash cans i have some that are rusted out and i need more for the areas where they put more benches								
Isaac Holguin									
127356					1/11/2015	1/27/2015	29		\$0.00
Medium	Work In Progress				1/11/2015 12:29:59 AM				
Holguin, Isaac	Monthly - QRTL BLDG INSP REPORT (GH) - Refer to PM schedule details.		2/5/15- ISAAC, RECEIVED YOUR BUILDING INSPECTION REPORTS BUT NEED WORK ORDER COMPLETED. THANK YOU!						
Margret Villalobos									
121586	Concession				8/21/2014		113		\$0.00
Medium	Work In Progress				8/21/2014 1:47:38 PM	12/12/2014			
Holguin, Isaac	Requested by Cathy for Football Concession/Kitchen Stand-There are cob webs, live and dead roaches, needs to be sprayed.								
Velia Alarcon									
119630					7/21/2014		203		\$0.00
Medium	Work In Progress				7/21/2014 10:01:42 AM				
Flores, Pete	Requested by Mr. Smythe-Ag. tractor needs to be serviced. Engine oil and filter need to be replaced. Both batteries need to be replaced. Hydraulic/trans fluid and filters need to be changed/replaced. Inner and outer air filters need to be replaced. Cab fresh air filters need to be replaced. Injection pump needs to be repaired; fuel system will not hold a prime. Air filter bowl needs to be replaced as well, broken at base. All grease fittings need to be examined in order to take grease.								
Velia Alarcon									
128582	Varsity Gym	Gym			2/6/2015		3		\$0.00
Medium	Work In Progress	Lupe - Grounds			2/6/2015 10:20:56 AM				
Ontiveros, Guadalupe	LUPE - CAN YOU PLEASE MOVE WRESTLING MATS FROM (STHS AND CHS) 1 EACH AND BRING THOSE OVER TO GADSDEN HS, FOR A DISTRICT WRESTLING MEET ON FEB. 14TH. MATS NEED TO BE MOVED BY FEB. 12TH. THANK YOU!								
Terry Alvarado									
127948		Athletic Field			1/26/2015		14		\$0.00
Medium	Work In Progress				1/26/2015 3:15:40 PM				
Ontiveros, Guadalupe	need to order disc for areas to control weeds.								
Guadalupe Ontiveros									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden HS

127400 1/12/2015 28 \$0.00

Medium Work In Progress 1/12/2015 2:33:43 PM

Ontiveros, Guadalupe Requested by Coach Lawrence for Soccer Field-Top soil to soccer field # 1. SEE COACH LAWRENCE FOR FURTHER INSTRUCTION.

Velia Alarcon

127401 1/12/2015 28 \$0.00

Medium Work In Progress 1/12/2015 2:37:01 PM

Ontiveros, Guadalupe Requested by Coach Lawrence for Grass Soccer Field-Update watering system to automatic system. Talked to Lupe Ontiveros and he agreed to it.

Velia Alarcon

128566 2/6/2015 3 \$0.00

Medium Work In Progress 2/6/2015 8:33:34 AM

Ontiveros, Guadalupe need trash cans on all high schools and middles as per Mr Estrada and school Admis.

Guadalupe Ontiveros

125866 Athletic Field 11/21/2014 80 \$0.00

Medium Work In Progress 11/21/2014 3:30:35 PM

Ontiveros, Guadalupe Requested by Ms. L. Chavez for Softball Field-Warning track needs to be widened and then red dirt needs to replace the sand that was placed there when warning tracks was added. The spoiler in that area floods the warning track area between left field foul line and scoreboard. This is also a safety issue for all softball players.

Velia Alarcon

124837 Classroom 10/31/2014 101 \$0.00

Medium Work In Progress Portable # 4 10/31/2014 12:27:22

Lara, Ralph Requested by Ms. Cardona for Portable # 4-Have all file cabinets in the portable re-keyed with three keys made for each file cabinet.

Velia Alarcon

126046 Academic Bldg Classroom 12/1/2014 70 \$0.00

Medium Work In Progress 325 12/1/2014 1:17:31 PM

Lara, Ralph Requested by Ms. J. Schaid Rm. 325 Academic Building -Please replace lock on classroom cabinet door and three keys will be needed. Technology for the Instructional Coach for our campus needs to be secured.

Velia Alarcon

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Gadsden HS**

128470 New Admin Bldg Custodial 2/4/2015 5 \$0.00

Medium Work In Progress 718 2/4/2015 12:45:46 PM

Lara, Ralph Requested by Ms. De La Garza Rm. 718 New Admin. Building-Keycylinder is loose, outside door.

Velia Alarcon

121888 8/28/2014 165 \$0.00

Medium Work In Progress 8/28/2014 9:19:01 AM

Lara, Ralph Need some assistance on door lock in intervention room, lock is stuck, teacher needs to lock and open room frequently.

Arturo Nunez

122312 New Admin Bldg Computer Lab 9/4/2014 158 \$0.00

Medium Work In Progress 718 9/4/2014 10:14:43 AM

Lara, Ralph Requested by Ms. De La Garza Rm. 718 New Admin. Building-Three keys are needed for room # 718. The lab is currently being used for students to access different web site for scholarship opportunities and the lab has many lap tops that need to be secured.

Velia Alarcon

128447 2/4/2015 5 \$0.00

Medium Work In Progress 2/4/2015 8:15:42 AM

Lara, Ralph annexback door does not lock/unlock puh bar stuck door stays open

Isaac Holguin

127137 1/6/2015 34 \$0.00

Medium Work In Progress 1/6/2015 3:36:00 PM

Marquez, Gerardo Requested by Mr. Enriquez Rm. 500 New CTE Building- Need to level floor in shop to install a twin port lift.

Velia Alarcon

127404 1/12/2015 28 \$0.00

Medium Work In Progress 1/12/2015 2:46:13 PM

Lara, Ralph Requested by Coach Lawrence for Portable # 13/14- Dead bolt on two front doors.

Velia Alarcon

127412 1/12/2015 28 \$0.00

Medium Work In Progress 1/12/2015 3:02:03 PM

Lara, Ralph Requested by Maria Grubaugh-Mailbox# 4 needs to have a second key made.

Velia Alarcon



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

**Location: Gadsden HS**

127133 1/6/2015 34 \$0.00

Medium Work In Progress 1/6/2015 3:27:56 PM

Lara, Ralph Requested by Velia-Two HE241 keys are needed for Mrs. Munoz' store room in the North Building.

Velia Alarcon

127140 1/6/2015 34 \$0.00

Medium Work In Progress 1/6/2015 3:42:28 PM

Lara, Ralph Requested by Velia for Mr. Giron-Mr. Giron's MH key is not working. It is a very old key and the teeth might be worn out. Please check key and see if he need a new key.

Velia Alarcon

125604 11/15/2014 86 \$0.00

Medium Work In Progress 11/15/2014 12:45:33

Flores, Pete Yearly- Gadsden HS- Mow (0408/0419/0428) Grounds - Refer to PM schedule details.

Margret Villalobos

127726 Custodial 1/21/2015 19 \$0.00

Medium Work In Progress 1/21/2015 5:24:46 AM

Flores, Pete red electric blower not blowing #1258

Isaac Holguin

126844 1/4/2015 36 \$0.00

Medium Work In Progress 1/4/2015 12:39:48 AM

Holguin, Alfredo Monthly - Gadsden HS Generator PM (Quarterly) - Refer to PM schedule details.

Margret Villalobos

126849 1/4/2015 36 \$0.00

Medium Work In Progress 1/4/2015 12:39:52 AM

Holguin, Alfredo Monthly - Gadsden HS - Fire Pump Engine - Refer to PM schedule details.

Margret Villalobos

128531 Academic Bldg Classroom 2/5/2015 4 \$0.00

Medium Work In Progress 346 2/5/2015 2:35:47 PM

Nunez, Arturo Requested by Marth Perez Long Term Sub for Rm. 346 Academic Building-Two light covers need to be adjusted, about to fall and might cause injury.

Velia Alarcon

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden HS

128135 Classroom 1/30/2015 10 \$0.00

Medium Work In Progress 518 1/30/2015 9:38:53 AM

Nunez, Arturo Requested by Mr. Martin Rm. 518 Annex Building-Install toilet roll holder in a higher position in the restroom.

Velia Alarcon

128020 Academic Bldg Classroom 1/27/2015 13 \$0.00

Medium Work In Progress 301 1/27/2015 4:01:00 PM

Nunez, Arturo Requested by Ms. Aguilar Rm. 301 Academic Building- Need a US Flag and bracket to hang flag. Then, hang both the US and NM Flags on the north wall in the north west corner.

Velia Alarcon

128335 2/2/2015 7 \$0.00

Medium Work In Progress 2/2/2015 9:38:45 AM

Ronquillo, Ruben Requested by Coach Yanez for Baseball Field-Set up square batting cage with cables, clamps, and net at the baseball field. Spoke with Mike Munoz and Ruben Ronquillo regarding the batting cage.

Velia Alarcon

128299 2/1/2015 2/7/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:50 AM

Hernandez, Guillermo Monthly - Gadsden HS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

120351 8/3/2014 190 \$0.00

Medium Work In Progress 8/3/2014 12:33:49 AM

Munoz, Michael Yearly - Gadsden HS Fire Ext. Insp. (Yearly) - Refer to PM not completed as per schedule PM schedule details.

Margret Villalobos

127810 1/22/2015 18 \$0.00

Medium Work In Progress 1/22/2015 2:52:14 PM

Munoz, Michael Could you please purchase new sewing machines for new sewing lab. Purchase 4

Michael Munoz

126410 Classroom 12/9/2014 62 \$0.00

Medium Work In Progress 12/9/2014 11:45:08 AM

Munoz, Michael could you please services all sewing machines in the sewing lab. thank you

Velia Alarcon

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
119592		Athletic Field			7/18/2014		206		\$0.00
Medium	Work In Progress				7/18/2014 2:08:10 PM				
Ontiveros, Guadalupe		Would like to get the grass fields line for competition. First field should be lined as a soccer field and the other lined up as football fields. Thank you!							
William Dickson									
126403		Athletic Field			12/9/2014		62		\$0.00
Medium	Work In Progress				12/9/2014 8:26:59 AM				
Flores, Pete		JD Mower Isolator needs to be replaced.							
Guadalupe Ontiveros									
121243		Football Field			8/15/2014		178		\$0.00
Medium	Work In Progress				8/15/2014 9:53:18 AM				
Ontiveros, Guadalupe		Need to place lines on the middle grass field so the football team can practice.							
William Dickson									
126977					1/4/2015		36		\$0.00
Medium	Work In Progress				1/4/2015 12:41:36 AM				
Munoz, Michael		Monthly - Gadsden HS - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
128375					2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 12:34:11 AM				
Hernandez, Guillermo		Weekly - Gadsden HS - Fire Pump (Biweekly) - Refer to PM schedule details.							
Margret Villalobos									
121330	Library	Library			8/18/2014		175		\$0.00
Medium	Work In Progress	Library			8/18/2014 9:20:11 AM				
Estrada, Jesus		Requested by Matt Grubaugh for Library-Carpet is coming up all over the library floor.							
Velia Alarcon									
123810	Library	Library			10/7/2014		125		\$0.00
Medium	Work In Progress				10/7/2014 12:59:31 PM				
Estrada, Jesus		Requested by Matt Grubaugh for Library-The carpet in the library continues to come up. He's afraid students are going to trip on it and hurt themselves.							
Velia Alarcon									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

**Location:** Gadsden HS

122352					9/4/2014		158		\$0.00
--------	--	--	--	--	----------	--	-----	--	--------

Medium	Work In Progress				9/4/2014 3:46:33 PM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Ontiveros, Guadalupe  
Need to replace about 200 ft. of 3 ft. high fence on the foot ball field visitors side, fence is facing the football field. Safety issue.

Guillermo Hernandez

119657					7/21/2014		203		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				7/21/2014 3:31:25 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gallegos, Rafael  
Warranty work order. Mullen on the west double back door to the Theater building is not working properly. The key gets stuck and can not remove the mullen.

Guillermo Hernandez

121304					8/18/2014		175		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/18/2014 7:54:25 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gallegos, Rafael  
TRANE WARRANTY W/O. Science classroom #619 CO sensor is not reading.

Guillermo Hernandez

121342					8/18/2014		175		\$0.00
--------	--	--	--	--	-----------	--	-----	--	--------

Medium	Work In Progress				8/18/2014 12:19:58 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Gallegos, Rafael  
Warranty work order for roof leak in the manufacturing shop. water seems to be coming from the A/C roof jack, the welded part looks like is crack as possible cause of roof leak.

Guillermo Hernandez

126441					12/10/2014		61		\$0.00
--------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/10/2014 8:05:32 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Carrasco, Danny  
Need five (5) gallons unleaded fuel for U.V. G.H.S. # 0515.

Arturo Nunez

128329					2/2/2015		7		\$0.00
--------	--	--	--	--	----------	--	---	--	--------

Medium	Work In Progress				2/2/2015 8:58:09 AM				
--------	------------------	--	--	--	---------------------	--	--	--	--

Orozco, Daniel  
COLD HOLDING UNIT (MILK BOX) IN RED AND GREEN LINE NOT WORKING. SNP MANAGER FRANCES B. 882.5522

Maritza Gonzalez

126699					12/17/2014		54		\$0.00
--------	--	--	--	--	------------	--	----	--	--------

Medium	Work In Progress				12/17/2014 8:51:44 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Daniel  
THREE OVENS NOT HEATING. SNP MANAGER FRANCES B. 882.5522.

Maritza Gonzalez

2/9/2015 1:38:22 PM

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
128074					1/29/2015		11		\$0.00
Medium	Work In Progress				1/29/2015 7:46:54 AM				
Gonzalez, Salvador		Need to replace broken main sign pole by the flag poles.							
Guillermo Hernandez									
126391					12/8/2014		63		\$0.00
Medium	Work In Progress				12/8/2014 3:56:51 PM				
Orozco, Daniel		DISHWASHER-PANS NOT GETTING CLEANED AND NOT ENOUGH HOT WATER.SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
128646					2/9/2015		0		\$0.00
Medium	Work In Progress				2/9/2015 7:40:31 AM				
Orozco, Daniel		As per Mr. Bakers inspection report, water on floor by the 3 compartment sink (been a problem for some time).							
Maritza Gonzalez									
123327					9/26/2014		136		\$0.00
Medium	Work In Progress				9/26/2014 3:51:00 PM				
Orozco, Daniel		Walk-in floor has lifted – safety issue. SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
123328					9/26/2014		136		\$0.00
Medium	Work In Progress				9/26/2014 3:51:26 PM				
Orozco, Daniel		Mop sink is leaking from the floor.SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
119747					7/23/2014		201		\$0.00
Medium	Work In Progress				7/23/2014 10:08:37 AM				
Orozco, Daniel		WARMER-OLD FAVORITES-INSIDE HAS FALLEN. SNP MANAGER FRANCES B. 882.5522							
Maritza Gonzalez									
128198					1/31/2015		9		\$0.00
Medium	Work In Progress				1/31/2015 12:39:15 AM				
Sanchez, Raul		Monthly - Gadsden HS-WWTP Chemical Order (Monthly) - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
128286					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:41 AM				
Sanchez, Raul		Monthly - Gadsden HS - Monthly Water Samples - Refer to PM schedule details.							
Margret Villalobos									
124632		Athletic Field			10/27/2014		105		\$0.00
Medium	Work In Progress				10/27/2014 2:47:26 PM				
Gonzalez, Salvador		need to install new cables for new batting net on batting cages. boys baseball. contact person @ site. coach Bones. thank you							
Michael Munoz									
125861		Athletic Field			11/21/2014		80		\$0.00
Medium	Work In Progress				11/21/2014 3:17:50 PM				
Gonzalez, Salvador		Requested by Ms. L. Chavez for Softball Field-Replace old batting cage. Add a third batting cage on Softball Field. Add an area for batting off tees. Remove old tee area from fence (left side) welded into fence.							
Velia Alarcon									
125862		Athletic Field			11/21/2014		80		\$0.00
Medium	Work In Progress				11/21/2014 3:21:11 PM				
Gonzalez, Salvador		Requested by Ms. L. Chavez for Softball Field-Backstop on Softball Field needs to be replaced (safety issue). There are white stakes keeping fence down. Officials stated that those stakes were a safety issue to all players.							
Velia Alarcon									
125292		Football Field			11/7/2014		94		\$0.00
Medium	Work In Progress				11/7/2014 1:12:07 PM				
Gonzalez, Salvador		Coach Vasquez would like a door placed in the shower area to store some of his equipment. Door needs to be welded.							
William Dickson									
128581		Office			2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 10:15:09 AM				
Gonzales, Camilo		Deliver 1 bx. PO# 141504869. Attn: Raul Ramos.							
Theresa Ramirez									
128528		Office			2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 2:15:42 PM				
Gonzales, Camilo		Deliver 3 bxs. PO# 141504870. Attn: Raul Ramos.							
Theresa Ramirez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
128347		Office			2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 3:31:41 PM				
Gonzales, Camilo Deliver 1 bx. PO# 141504772. Attn: Christina Munoz									
Theresa Ramirez									
128355		Office			2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 3:41:51 PM				
Gonzales, Camilo Deliver 1 bx. PO# 141503179. Attn: Christina Munoz.									
Theresa Ramirez									
128196					1/31/2015		9		\$0.00
Medium	Work In Progress				1/31/2015 12:39:14 AM				
Sanchez, Raul Monthly - Gadsden HS - Monthly Meter Readings - Refer to PM schedule details.									
Margret Villalobos									
128288					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:43 AM				
Sanchez, Raul Monthly - Gadsden HS - Lift Station Inspection - Refer to PM schedule details.									
Margret Villalobos									
126465	Cafeteria (1998)	Exterior			12/10/2014		61		\$0.00
Medium	Work In Progress				12/10/2014 1:49:04 PM				
Sanchez, Raul 12/10/14 New grease trap overflowed, effluent line is clogged. Need to document that Contractors left clean-outs under pavement and that Southwest Envirotec did not respond on same day. Thanks, Raul									
Raul Sanchez									
126290	Pool Pump	Pump House			12/5/2014		66		\$0.00
Medium	Work In Progress				12/5/2014 2:22:05 PM				
Apodaca, Mario need to update the lifeguard chairs at the pool									
Mario Apodaca									
128417	Pool Pump	Pump House			2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 3:14:25 PM				
Apodaca, Mario need too ordered a spare circulating water pump for the GHS pool									
Mario Apodaca									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
125272					11/7/2014		94		\$0.00
Medium	Work In Progress				11/7/2014 9:03:59 AM				
Sanchez, Raul		Domestic Water Well #1 - install sanitary seal properly around electrical wires.							
Alfredo Holguin									
128136	Academic Bldg	Classroom			1/30/2015		10		\$0.00
Medium	Work In Progress	346			1/30/2015 9:40:43 AM				
Hernandez, Guillermo		Requested by Martha Perez Rm. 346 Academic Building -I would like to have blinds replaced on windows, present ones are broken.							
Velia Alarcon									
121848	Academic Bldg				8/27/2014		166		\$0.00
Medium	Work In Progress				8/27/2014 2:30:48 PM				
Nunez, Arturo		Please replace all window screens.							
Michael Munoz									
128248					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:16 AM				
Nunez, Arturo		Monthly - Gadsden HS-Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
128243					2/1/2015	3/4/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:13 AM				
Nunez, Arturo		Monthly - Gadsden HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
128244					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:14 AM				
Nunez, Arturo		Monthly - Gadsden HS Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
126569		Classroom			12/12/2014		59		\$0.00
Medium	Work In Progress	519			12/12/2014 8:55:43 AM				
Nunez, Arturo		Requested by Mr. Villa Rm. 519 Annex Building-The drain for the ice machine is clogged again.							
Velia Alarcon									



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location: Gadsden HS</b>										
126221		Dressing Room			12/4/2014		67		\$0.00	
Medium	Work In Progress			12/4/2014 9:06:09 AM						
Nunez, Arturo	Requested by Coach J. Vasquez for Football Locker Rooms in Boy's Gym-Fix Lockers.									
Velia Alarcon										
128333	North Building	Classroom			2/2/2015		7		\$0.00	
Medium	Work In Progress	210		2/2/2015 9:35:33 AM						
Hernandez, Guillermo	Requested by Mrs. Munoz Rm. 210 North Building-Put up a US Flag in classroom.									
Velia Alarcon										
128471	Academic Bldg	Classroom			2/4/2015		5		\$0.00	
Medium	Work In Progress	344		2/4/2015 12:47:53 PM						
Hernandez, Guillermo	Requested by Ms. Miller Rm. 344 Academic Building-Door slams shut, also does not stay propped open.									
Velia Alarcon										
128097					1/29/2015		11		\$0.00	
Medium	Work In Progress			1/29/2015 11:57:59 AM						
Hernandez, Guillermo	Need to replace hand dryers in the boys restroom at the cafeteria restrooms.									
Guillermo Hernandez										
128267					2/1/2015	2/9/2015	8		\$0.00	
Medium	Work In Progress			2/1/2015 12:50:29 AM						
Hernandez, Guillermo	Monthly - Gadsden HS Exit Sign Insp: Monthly - Refer to PM schedule details.									
Margret Villalobos										
127402					1/12/2015		28		\$0.00	
Medium	Work In Progress			1/12/2015 2:41:04 PM						
Hernandez, Guillermo	Requested by Coach Lawrence for Portable # 13/14-Fix boiler in restroom.									
Velia Alarcon										
128473					2/4/2015		5		\$0.00	
Medium	Work In Progress			2/4/2015 1:16:02 PM						
Hernandez, Guillermo	Please check switch for the bleachers, having problems opening and closing bleachers.									
Guillermo Hernandez										
<b>Count: 110 Work Orders</b>		<b>Avg. Age of WO's 62</b>		<b>Total for Gadsden HS</b>			<b>0</b>	<b>\$0.00</b>		

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
128396	C-Wing				2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 10:03:34 AM				
Miranda, Danny		Repair walls in classroom and restrooms.							
Michael Munoz									
127685	Cafeteria	Kitchen			1/20/2015		20		\$0.00
Medium	Work In Progress	Cafeteria			1/20/2015 8:34:14 AM				
Ronquillo, Ruben		Please repair broken window in cafeteria, kitchen area.							
Nancy Tinajero									
121844	C-Wing				8/27/2014		166		\$0.00
Medium	Work In Progress				8/27/2014 1:19:05 PM				
Marquez, Gerardo		please change all windows around building. double pane thank you							
Michael Munoz									
125856		Athletic Field			11/21/2014		80		\$0.00
Medium	Work In Progress				11/21/2014 3:02:54 PM				
Gonzalez, Salvador		please install baseball scoreboard on field. please see mike for details. gracias							
Michael Munoz									
125614	Main Building	Classroom			11/17/2014		84		\$0.00
Medium	Work In Progress	room 169			11/17/2014 9:24:51 AM				
Marquez, Gerardo		Need a half door installed in room 169 for student safety.							
Nancy Tinajero									
124293		Classroom			10/17/2014		115		\$0.00
Medium	Work In Progress	room 148			10/17/2014 11:47:27				
Marquez, Gerardo		Classroom entry door needs to be adjusted.							
Nancy Tinajero									
128518	C-Wing				2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 10:37:36 AM				
Marquez, Gerardo		Need to install a slot on west side door like the one on M. Ruiz door. (Please see Margret)							
Richard Chavez									
128368		Office			2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 4:05:11 PM				
Gonzales, Camilo		deliver 1 bx. PO# 141504492.							
Theresa Ramirez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Gadsden MS**

128187 1/31/2015 9 \$0.00

Medium Work In Progress 1/31/2015 12:39:07 AM

Apodaca, Mario Monthly - Gadsden MS-WWTP Chemical Order (Monthly) - Refer to PM schedule details. PM not performed as per schedule 2/9/15

Margret Villalobos

128290 2/1/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:44 AM

Apodaca, Mario Monthly - Gadsden MS - Lift Station Inspection - Refer to PM schedule details.

Margret Villalobos

127753 1/21/2015 19 \$0.00

Medium Work In Progress 1/21/2015 11:25:29 AM

Orozco, Daniel WALK IN FREEZER RAMP NEEDS TO BE REPAIRED, IT LIFTS AND KEEP DOOR AJAR. SNP MANAGER TERRY P. 882.2824

Maritza Gonzalez

127754 1/21/2015 19 \$0.00

Medium Work In Progress 1/21/2015 11:28:32 AM

Orozco, Daniel RACKS IN WARMING CABINET NEED ANCHORS RACKS ARE LOOSE AND CAN CAUSE SOMEONE TO GET BURNED. SNP MANAGER TERRY P. 882.2824

Maritza Gonzalez

127946 1/26/2015 14 \$0.00

Medium Work In Progress 1/26/2015 2:43:41 PM

Orozco, Daniel MILK MACHINE BROKEN, DOOR HANGING OFF HINGES. SNP MANAGER TERRY P. 882.2824

Maritza Gonzalez

128082 1/29/2015 11 \$0.00

Medium Work In Progress 1/29/2015 9:27:22 AM

Orozco, Daniel The building inspector was here , and found that we need an air gap underneath the 3 compartment sink. Will you please do a work order through the plumbing department, so that they come and see what we need to do. SNP Manager Terry P. 882.2824

Maritza Gonzalez

128328 2/2/2015 7 \$0.00

Medium Work In Progress 2/2/2015 8:56:42 AM

Orozco, Daniel WALK IN FREEZER AT 69 DEGREES. SNP MANAGER TERRY P. 882.2824

Maritza Gonzalez

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Gadsden MS**

125015 11/2/2014 11/23/2014 99 \$0.00

Medium Work In Progress 11/2/2014 12:36:26 AM

Orozco, Daniel Monthly - Gadsden MS Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

127469 Main Building Hallway/Corridor 1/13/2015 27 \$0.00

Medium Work In Progress 1/13/2015 11:17:19 AM

Estrada, Jesus Need to replace VCT tile is coming up and breaking off in different sections

Mario Herrera

128662 C-Wing 2/9/2015 0 \$0.00

Medium Work In Progress Alta Vista 2/9/2015 10:18:26 AM

Marquez, Gerardo Need to change cores.

Gerardo Marquez

128311 2/1/2015 2/7/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:58 AM

Diaz, Sebastian Monthly - Gadsden MS Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

128338 2/2/2015 7 \$0.00

Medium Work In Progress 2/2/2015 11:14:45 AM

Ronquillo, Ruben would like a case of "killez paint" to keep here at GMS for tagging's

Mario Herrera

128089 Cafeteria Kitchen 1/29/2015 11 \$0.00

Medium Work In Progress Kitchen area 1/29/2015 10:24:24 AM

Diaz, Sebastian Replace baseboards in the ice machine area and opposite hallway as well

Nancy Tinajero

128090 Cafeteria 1/29/2015 11 \$0.00

Medium Work In Progress kitchen 1/29/2015 10:25:08 AM

Diaz, Sebastian repair holes in the drywall/sheetrock

Nancy Tinajero

128093 Cafeteria 1/29/2015 11 \$0.00

Medium Work In Progress kitchen 1/29/2015 10:26:58 AM

Diaz, Sebastian replace light bulbs

Nancy Tinajero

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden MS

127120 Gym 1/6/2015 34 \$0.00

Medium Work In Progress Gym athletic 1/6/2015 2:39:38 PM

Diaz, Sebastian Add shelving, fix cabinets and add security locks.

Nancy Tinajero

128509 2/5/2015 4 \$0.00

Medium Work In Progress 2/5/2015 8:44:34 AM

Diaz, Sebastian Need to replace pads on vocational thank you

Sebastian Diaz

125784 Gym 11/19/2014 82 \$0.00

Medium Work In Progress 11/19/2014 4:24:32 PM

Diaz, Sebastian Order window screens for Gym and Gym Lobby.  
(See Mike)

Michael Munoz

128144 1/30/2015 10 \$0.00

Medium Work In Progress 1/30/2015 10:58:20 AM

Diaz, Sebastian Need to fix cover lights on rest B wing thank you

Sebastian Diaz

128273 2/1/2015 3/4/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:33 AM

Diaz, Sebastian Monthly - Gadsden MS - Bleacher Inspection - Refer to PM schedule details.

Margret Villalobos

128274 2/1/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:33 AM

Diaz, Sebastian Monthly - Gadsden MS - Clothes Dryer (Monthly) - Refer to PM schedule details.

Margret Villalobos

128284 2/1/2015 2/9/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:40 AM

Diaz, Sebastian Monthly - Gadsden MS Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

128285 2/1/2015 2/9/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:41 AM

Diaz, Sebastian Monthly - Gadsden MS Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
125237	Gym				11/6/2014		95		\$0.00
Medium	Work In Progress				11/6/2014 2:41:40 PM				
Munoz, Michael		The new bleachers not working on the gym thank you							
Sebastian Diaz									
125852		Pump House			11/21/2014		80		\$0.00
Medium	Work In Progress				11/21/2014 2:42:53 PM				
Apodaca, Mario		need to run new control wires to the gms irrigation tank							
Mario Apodaca									
119972					7/29/2014		195		\$0.00
Medium	Work In Progress	front office			7/29/2014 10:04:45 AM				
Marquez, Gerardo		Need key ( A-57) for custodian							
Nancy Tinajero									
119973					7/29/2014		195		\$0.00
Medium	Work In Progress	front office-			7/29/2014 10:06:01 AM				
Marquez, Gerardo		Need Keys for new PE teacher, WA-62, V-8, WA-64, 01, V-15, one each please.							
Nancy Tinajero									
127917					1/26/2015		14		\$0.00
Medium	Work In Progress				1/26/2015 11:47:03 AM				
Marquez, Gerardo		I need a set of P.P.D keys so that I can check area of custodian							
Mario Herrera									
127160	C-Wing				1/7/2015		33		\$0.00
Medium	Work In Progress				1/7/2015 7:24:57 AM				
Marquez, Gerardo		please replace all windows of old central office. thank you							
Michael Munoz									
121935					8/28/2014		165		\$0.00
Medium	Work In Progress				8/28/2014 3:44:19 PM				
Ontiveros, Guadalupe		Need to bring tractor use for water damegs on vocational and front A wing thank you							
Sebastian Diaz									
127470	Main Building	Hallway/Corridor			1/13/2015		27		\$0.00
Medium	Work In Progress				1/13/2015 11:18:30 AM				
Estrada, Jesus		VCT tile needs to be replaced cracking and coming off							
Mario Herrera									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
127471	Cafeteria	Cafeteria			1/13/2015		27		\$0.00
Medium	Work In Progress				1/13/2015 11:20:12 AM				
Estrada, Jesus		Needs new VCT tile in cafeteria a lot of pieces missing and cracking							
Mario Herrera									
126661					12/16/2014		55		\$0.00
Medium	Work In Progress				12/16/2014 10:07:58				
Ontiveros, Guadalupe		please clean court yard where planters are at and remove Chinese elm. also will need a run off for proper drainage. would like floor covering and grave/rock on top. please see mike for details							
Michael Munoz									
125855		Athletic Field			11/21/2014		80		\$0.00
Medium	Work In Progress				11/21/2014 3:01:34 PM				
Ontiveros, Guadalupe		please plant trees around baseball field along with irrigation as discussed. thank you ( Arizona ash)							
Michael Munoz									
123861					10/8/2014		124		\$0.00
Medium	Work In Progress				10/8/2014 9:48:04 AM				
Flores, Pete		weed eater 12746/84512 is not starting fuel is coming out of exhaust. Requesting a new one							
Mario Herrera									
127468	Main Building	Hallway/Corridor			1/13/2015		27		\$0.00
Medium	Work In Progress				1/13/2015 11:15:04 AM				
Estrada, Jesus		New to replace (VCT tile) in west wing tile is coming up and un done pieces of VCT missing							
Mario Herrera									
128339					2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 11:16:02 AM				
Carbajal, Jimmy		Would like pressure washer to wash down buildings							
Mario Herrera									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

**Location:** Gadsden MS

119661 7/21/2014 203 \$0.00

High Work In Progress 7/21/2014 3:36:41 PM

Apodaca, Mario \*\*\*The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house\*\*\*

Company: CD MECHANICAL  
 Contact Name: DEAN POGUE Contact Phone: (575)382-8474  
 State: NM County: DONA ANA City: RURAL  
 DONA ANA  
 Address: 1301, WASHINGTON ST  
 Nearest Intersecting Street: BERRY RD  
 2nd Intersecting Street: GRACIE PL  
 Subdivision: GASDEN MIDDLE SCHOOL  
 Latitude: 31.99971983 Longitude: -106.63006583  
 Zip Code: 88021  
 Township: 26S Range: 03E Section 1/4: 34 SW

Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS. - SPOT ON THE E. SIDE OF PROPERTY, IN THE PONDING AREA BETWEEN THE WATER STORAGE TANK AND THE GYM.

Dominique Esparza



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>	<b>Gadsden MS</b>								
119660					7/21/2014		203		\$0.00

High Work In Progress 7/21/2014 3:36:20 PM

Sanchez, Raul \*\*\*The area indicated between the storage tank and gym marked by CD Mechanical, need to know where main feed runs from the tank to the pump house\*\*\*

Company: CD MECHANICAL  
 Contact Name: DEAN POGUE Contact Phone: (575)382-8474  
 State: NM County: DONA ANA City: RURAL  
 DONA ANA  
 Address: 1301, WASHINGTON ST  
 Nearest Intersecting Street: BERRY RD  
 2nd Intersecting Street: GRACIE PL  
 Subdivision: GASDEN MIDDLE SCHOOL  
 Latitude: 31.99971983 Longitude: -106.63006583  
 Zip Code: 88021  
 Township: 26S Range: 03E Section 1/4: 34 SW

Location of Work: FROM INTERS. OF WASHINGTON ST AND NM-478 IN ANTHONY, GO W. ON WASHINGTON ST TO ADDRESS. - SPOT ON THE E. SIDE OF PROPERTY, IN THE PONDING AREA BETWEEN THE WATER STORAGE TANK AND THE GYM.

Dominique Esparza									
128204					2/1/2015	2/4/2015	8		\$0.00

Medium Work In Progress 2/1/2015 12:49:46 AM

Diaz, Sebastian Monthly - Gadsden MS - Emerg. Eyewash (Monthly) - Refer to PM schedule details.

Margret Villalobos									
125851		Pump House			11/21/2014		80		\$0.00

Medium Work In Progress 11/21/2014 2:41:06 PM

Sotelo, Enrique need to pull new control wires for the switch float at the gms irrigation tank

Mario Apodaca									
125857		Athletic Field			11/21/2014		80		\$0.00

Medium Work In Progress 11/21/2014 3:04:22 PM

Sotelo, Enrique please provide power to baseball scoreboard once installed. please see mike for location. thank you

Michael Munoz

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
124709	Gym				10/29/2014		103		\$0.00
Medium	Work In Progress				10/29/2014 7:43:56 AM				
Villalobos, David		Urinals in boys gym locker room do not have water needs to be fixed A.S.A.P in order to clean by custodian right							
Mario Herrera									
124711					10/29/2014		103		\$0.00
Medium	Work In Progress				10/29/2014 7:45:12 AM				
Villalobos, David		Sink in girls restroom next to b-wing and main hallway there is no running water							
Mario Herrera									
121677					8/25/2014		168		\$0.00
Medium	Work In Progress				8/25/2014 8:10:22 AM				
Villalobos, David		Need o replace sink faucet on rest room A wing thank you							
Sebastian Diaz									
121391	Vocational				8/19/2014		174		\$0.00
Medium	Work In Progress				8/19/2014 6:59:54 AM				
Villalobos, David		outside water for water hoses do not work on the whole building							
Mario Herrera									
119501	C-Wing				7/16/2014		208		\$0.00
Medium	Work In Progress				7/16/2014 3:49:11 PM				
Villalobos, David		Portable - Where restrooms are located. There is a leak underneath the sink, water has been shut off for now. Please check this first thing in the morning.							
Mario Herrera									
124188		Classroom			10/15/2014		117		\$0.00
Safety	Work In Progress	room 129 and			10/15/2014 1:55:35 PM				
Villalobos, David		Water is leaking out of the wall between room 129 and 140. Computers are against that wall. Could be a severe electrical shock issue.							
Nancy Tinajero									
124404		Library			10/21/2014		111		\$0.00
Medium	Work In Progress	Library			10/21/2014 12:30:45				
Villalobos, David		Clogged sink in library office.							
Nancy Tinajero									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden MS

119801	Main Building	Classroom			7/24/2014		200		\$0.00
--------	---------------	-----------	--	--	-----------	--	-----	--	--------

Medium	Work In Progress	Room 152			7/24/2014 11:57:42 AM				
--------	------------------	----------	--	--	-----------------------	--	--	--	--

Villalobos, David Sink is dripping continuously; doesn't drain and is leaking into the cabinet.

Nancy Tinajero

128576	Main Building	Restroom			2/6/2015		3		\$0.00
--------	---------------	----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	B wing			2/6/2015 9:27:12 AM				
--------	------------------	--------	--	--	---------------------	--	--	--	--

Villalobos, David Stench in the boys restroom B wing, replace pipes.

Nancy Tinajero

124628		Gym			10/27/2014		105		\$0.00
--------	--	-----	--	--	------------	--	-----	--	--------

Medium	Work In Progress	baseball field			10/27/2014 2:00:21 PM				
--------	------------------	----------------	--	--	-----------------------	--	--	--	--

Villalobos, David Water fountain outside gym area near baseball field is not working.

Nancy Tinajero

127837					1/23/2015		17		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/23/2015 10:12:48 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Villalobos, David Need to fix toilet on Girl rest on A wing thank you

Sebastian Diaz

127612					1/15/2015		25		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/15/2015 3:49:23 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Need to fix toilet on girls restroom B wing thank you

Sebastian Diaz

126893					1/4/2015	2/4/2015	36		\$0.00
--------	--	--	--	--	----------	----------	----	--	--------

Medium	Work In Progress				1/4/2015 12:40:28 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, David Yearly - Gadsden MS Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

128399	Annex	Classroom			2/3/2015		6		\$0.00
--------	-------	-----------	--	--	----------	--	---	--	--------

Medium	Work In Progress	room 400			2/3/2015 10:59:52 AM				
--------	------------------	----------	--	--	----------------------	--	--	--	--

Marquez, Gerardo The lock on the door inside room 400 needs repair. Also, door has to be lifted very hard to lock.

Nancy Tinajero

128206					2/1/2015	2/17/2015	8		\$0.00
--------	--	--	--	--	----------	-----------	---	--	--------

Medium	Work In Progress				2/1/2015 12:49:48 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Villalobos, Margret Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details.

Margret Villalobos

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
126980					1/4/2015	1/20/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:41:39 AM				
Villalobos, Margret		Monthly - Gadsden MS Monthly Chiller Insp. - Refer to PM schedule details.							
Margret Villalobos									
127161	C-Wing				1/7/2015		33		\$0.00
Medium	Work In Progress				1/7/2015 7:36:46 AM				
Solis, Lorenz		please remove the 2 units on the wall in the back room by restroom and install a new heating/cooling unit. thank you							
Michael Munoz									
128617					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 3:46:24 PM				
Solis, Lorenz		Need to fix pump on boiler room eastside thank you							
Sebastian Diaz									
127838					1/23/2015		17		\$0.00
Medium	Work In Progress				1/23/2015 10:15:02 AM				
Sotelo, Enrique		Need to enough power for meting on cafeteria FEB 6 thank you							
Sebastian Diaz									
128092		Cafeteria			1/29/2015		11		\$0.00
Medium	Work In Progress	kitchen			1/29/2015 10:26:35 AM				
Diaz, Sebastian		Repaint damaged rooms. Clean and paint light fixtures that have not been cleaned in the storage area.							
Nancy Tinajero									
121842	C-Wing				8/27/2014		166		\$0.00
Medium	Work In Progress				8/27/2014 1:15:58 PM				
Diaz, Sebastian		as per conversation, please paint all rooms inside. thank you							
Michael Munoz									
<b>Count: 71 Work Orders</b>		<b>Avg. Age of WO's 60</b>		<b>Total for Gadsden MS</b>		<b>0</b>	<b>0</b>	<b>\$0.00</b>	

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>La Union ES</b>							
126602	2000 Core	Classroom			12/12/2014		59		\$0.00
Medium	Work In Progress	301			12/12/2014 5:15:02 PM				
Castillo, Carlos		Need electrical work for smart board completed.							
Virginia Galindo									
123946					10/9/2014		123		\$0.00
Medium	Work In Progress				10/9/2014 3:15:21 PM				
Ambriz, Jose		need thermostat for heater in gym - thank you							
Patricio Aguilar									
126896					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:30 AM				
Villalobos, David		Yearly - La Union ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
124738					10/29/2014		103		\$0.00
Medium	Work In Progress				10/29/2014 2:49:48 PM				
Aguilar, Patricio		work order to myself - need to replace fire pull station cover not working - alta vista							
Patricio Aguilar									
128265					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:27 AM				
Aguilar, Patricio		Monthly - La Union ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
128266					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:28 AM				
Aguilar, Patricio		Monthly - La Union ES Emer. Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
128278					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:36 AM				
Aguilar, Patricio		Monthly - La Union ES - Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									
120338					8/3/2014		190		\$0.00
Medium	Work In Progress				8/3/2014 12:33:40 AM				
Munoz, Michael		Yearly - La Union ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.				PM not completed as per schedule			
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: La Union ES</b>									
125016					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:26 AM				
Orozco, Daniel		Monthly - La Union ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
128317					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:51:02 AM				
Aguilar, Patricio		Monthly - La Union ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
128081					1/29/2015		11		\$0.00
Medium	Work In Progress				1/29/2015 9:25:07 AM				
Orozco, Daniel		FREEZER AT 29. SNP MANAGER LINDA Y. 589.2040							
Maritza Gonzalez									
126360					12/8/2014		63		\$0.00
Medium	Work In Progress				12/8/2014 12:38:51 PM				
Orozco, Daniel		DISHWASHER IS DOWN. SNP MANAGER LINDA Y. 589.2040							
Maritza Gonzalez									
128195					1/31/2015		9		\$0.00
Medium	Work In Progress				1/31/2015 12:39:13 AM				
Sanchez, Raul		Monthly - La Union ES - Monthly Meter Readings - Refer to PM schedule details.							
Margret Villalobos									
128643					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress				2/8/2015 12:29:26 AM				
Aguilar, Patricio		Monthly - La Union ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 14 Work Orders</b>			<b>Avg. Age of WO's 52</b>			<b>Total for La Union ES</b>	<b>0</b>		<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Loma Linda ES</b>									
128636					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress				2/8/2015 12:29:21 AM				
Medina, Eric		Monthly - Loma Linda ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
128419					2/3/2015		6		\$0.00
Medium	Work In Progress	204			2/3/2015 3:16:40 PM				
Villalobos, Margret		Please fumigate classroom for head lice outbreak							
Angie Flores									
128077		Classroom			1/29/2015		11		\$0.00
Medium	Work In Progress	212 & 214			1/29/2015 8:19:00 AM				
Villalobos, Margret		Please come and fumigate both classrooms for head lice				1/29/15 Emailed waiver and wo			
Angie Flores									
125786					11/19/2014		82		\$0.00
Medium	Work In Progress				11/19/2014 6:23:01 PM				
Medina, Eric		need to replace belt for fan coil in cafe							
Eric Medina									
128502		Classroom			2/5/2015		4		\$0.00
Medium	Work In Progress	112			2/5/2015 7:45:43 AM				
Medina, Eric		Need to put together and set up new table for Mrs. Armendariz							
Angie Flores									
128323		Classroom			2/2/2015		7		\$0.00
Medium	Work In Progress	101			2/2/2015 7:49:57 AM				
Medina, Eric		Will you please reseal windows, thank you!							
Angie Flores									
128042	Main Building	Classroom			1/28/2015		12		\$0.00
Medium	Work In Progress	Mrs. D Sanchez			1/28/2015 1:50:02 PM				
Medina, Eric		Need a flag put up							
Angie Flores									
127596		Classroom			1/15/2015		25		\$0.00
Medium	Work In Progress	Arenas,			1/15/2015 1:31:35 PM				
Medina, Eric		Replace screen for windows in the following classrooms, Arenas, Talamantez, and Casiano							
Angie Flores									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Loma Linda ES

128154					1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 12:53:44 PM				
Medina, Eric		please fixlights in book room							
Eric Medina									

128155					1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 12:55:36 PM				
Medina, Eric		please fixexhaust fan in faculty womens restroom by lounge							
Eric Medina									

128156					1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 12:56:38 PM				
Medina, Eric		please reseal windows in room 101							
Eric Medina									

128218					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:56 AM				
Medina, Eric		Monthly - Loma Linda ES Emer. Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									

128219					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:56 AM				
Medina, Eric		Monthly - Loma Linda ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									

128220					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:57 AM				
Medina, Eric		Monthly - Loma Linda ES - Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									

122493					9/9/2014		153		\$0.00
Medium	Work In Progress				9/9/2014 8:41:31 AM				
Medina, Eric		Soccer Goals- Remove overgrown weeds and order and install new soccer nets.							
Alfredo Holguin									

122497					9/9/2014		153		\$0.00
Medium	Work In Progress				9/9/2014 8:46:31 AM				
Medina, Eric		Pine Trees along rock wall on west side of campus -Pick up pine needles and pine cones							
Alfredo Holguin									



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Loma Linda ES</b>									
122498					9/9/2014		153		\$0.00
Medium	Work In Progress				9/9/2014 8:56:19 AM				
Medina, Eric		Portable area sidewalks- Order fill dirt (crusher fines or screenings) and backfill eroded areas next to sidewalks							
Alfredo Holguin									
128395					2/3/2015		6		\$0.00
Medium	Work In Progress	SPED Portable			2/3/2015 10:00:40 AM				
Miranda, Danny		Portable 1A 1B - Install wood trim on walls and repair suspended ceiling.							
Danny Miranda									
127651					1/16/2015		24		\$0.00
Medium	Work In Progress				1/16/2015 1:23:52 PM				
Orozco, Daniel		SLICER NOT WORKING AT ALL. SNP MANAGER DOLORES R. 882.4707							
Maritza Gonzalez									
128522					2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 11:52:58 AM				
Orozco, Daniel		DRAINS BACKING UP IN KITCHEN AREA. SNP MANAGER DOLORES R. 882.4707							
Maritza Gonzalez									
119567					7/18/2014		206		\$0.00
Medium	Work In Progress				7/18/2014 10:50:19 AM				
Orozco, Daniel		BROKEN GLASS ON SERVING LINE.							
Maritza Gonzalez									
128660					2/9/2015		0		\$0.00
Medium	Work In Progress				2/9/2015 9:48:25 AM				
Gonzalez, Maritza		WALK IN REFRIGERATOR IS AT 50 DEGREES. SNP MANAGER DOLORES R. 882.4707 ( WILL CALL A&M).							
Maritza Gonzalez									
121440					8/19/2014		174		\$0.00
Medium	Work In Progress				8/19/2014 3:03:42 PM				
Orozco, Daniel		LATCH THAT LOCKS THE WALK IN IS BROKEN. SNP MANAGER DOLORES R. 882.4707							
Maritza Gonzalez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Loma Linda ES

123928 10/9/2014 123 \$0.00

Medium Work In Progress rm 105 10/9/2014 1:50:51 PM

Marquez, Gerardo need to replace classroom door

Eric Medina

120081 7/31/2014 193 \$0.00

Medium Work In Progress 7/31/2014 9:06:08 AM

Marquez, Gerardo Gerrydoor handle in portable 4 was broken by vandals

Eric Medina

125017 11/2/2014 11/23/2014 99 \$0.00

Medium Work In Progress 11/2/2014 12:36:27 AM

Orozco, Daniel Monthly - Loma Linda ES Range Hood Cleaning - Refer to PM schedule details.

Margret Villalobos

122914 Portables 9/17/2014 145 \$0.00

Medium Work In Progress 9/17/2014 1:23:41 PM

Munoz, Michael provide new flooring to portable 1a/1b

Alfredo Holguin

127636 Office 1/16/2015 24 \$0.00

Medium Work In Progress Mr. Smiths 1/16/2015 9:33:57 AM

Estrada, Jesus New carpet that was just installed this summer break is already tearing, please fix work order # 113380??

Angie Flores

126973 1/4/2015 1/25/2015 36 \$0.00

Medium Work In Progress 1/4/2015 12:41:33 AM

Munoz, Michael Monthly - Loma Linda ES Fire Sprinkler Insp. - Refer to PM schedule details.

Margret Villalobos

120339 8/3/2014 190 \$0.00

Medium Work In Progress 8/3/2014 12:33:41 AM

Munoz, Michael Yearly - Loma Linda ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details. PM not completed as per schedule

Margret Villalobos

128303 2/1/2015 2/7/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:53 AM

Medina, Eric Monthly - Loma Linda ES Monthly FE Inspection - Refer to PM schedule details.

Margret Villalobos

2/9/2015 1:38:23 PM

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Loma Linda ES</b>							
127477					1/13/2015		27		\$0.00
Medium	Work In Progress				1/13/2015 1:33:17 PM				
Ontiveros, Guadalupe		Pete need to request bobcat							
Eric Medina									
125217					11/6/2014		95		\$0.00
Medium	Work In Progress				11/6/2014 9:09:39 AM				
Ontiveros, Guadalupe		Pete need to request bobcat please							
Eric Medina									
121485					8/20/2014		173		\$0.00
Medium	Work In Progress				8/20/2014 7:41:13 AM				
Marquez, Gerardo		Entrance Door in between 3rd and 6th grade hall, the core broke, its not working at all, need to have this fix so that school can be closed and locked.							
Angie Flores									
126894					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:29 AM				
Villalobos, David		Yearly - Loma Linda ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
122754		Pool			9/15/2014		147		\$0.00
Medium	Work In Progress				9/15/2014 10:42:21 AM				
Villalobos, David		As discussed , need to remove commode and sink in rest room and plumb out for washer and drier, commode and sink need to be plumbed out in the storage room across existing restroom. will need hot water also.							
Michael Munoz									
128649	Main Building	Restroom			2/9/2015		0		\$0.00
Medium	Work In Progress				2/9/2015 8:03:22 AM				
Villalobos, David		need to jet main sewer lines through out campus to sewer main							
David Villalobos									
122774		Portables			9/15/2014		147		\$0.00
Medium	Work In Progress				9/15/2014 3:36:17 PM				
Sotelo, Enrique		need to provide power to new washer and drier room , and to new restroom. also will need a circuit for a lift table.							
Michael Munoz									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Loma Linda ES</b>							
128394					2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 9:58:58 AM				
Medina, Eric	Need to paint and install covebase in SPED Portable.								
Danny Miranda									
125287	Main Building				11/7/2014		94		\$0.00
Medium	Work In Progress				11/7/2014 11:30:08 AM				
Medina, Eric	east Side exit doors need to be repainted properly								
Alfredo Holguin									
<b>Count: 40 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>65</b>	<b>Total for Loma Linda ES</b>			<b>0</b>	<b>\$0.00</b>	

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location: Mesquite ES</b>									
128416	ArmyBuilding	Classroom			2/3/2015		6		\$0.00
Medium	Work In Progress	classrooms			2/3/2015 3:07:21 PM				
Marquez, Gerardo		Luis Saucedo/Head Custodian, needs C-Master made for classrooms.							
Sandra Mora									
127983					1/27/2015		13		\$0.00
Medium	Work In Progress				1/27/2015 10:02:59 AM				
Solis, Lorenzø		need 1 ea wall heater in staff bathrooms (2)							
Joe Ramirez									
122438					9/8/2014		154		\$0.00
Medium	Work In Progress				9/8/2014 8:47:31 AM				
Ramirez, Joe		need to paint math intervention rm.							
Joe Ramirez									
125497					11/13/2014		88		\$0.00
Medium	Work In Progress				11/13/2014 8:50:03 AM				
Gallegos, Rafael		atten. mr. Gallegos unit in rm.206 is showing no flame message also admin offices are cold.							
Joe Ramirez									
127447		Parking Lot			1/13/2015		27		\$0.00
Medium	Work In Progress				1/13/2015 7:45:37 AM				
Villalobos, David		need to replaced damaged cover to domestic backflow preventer							
David Villalobos									
128468					2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 12:33:45 PM				
Villalobos, David		water valve for the north end trees is not working properly this is in the community park needs to be looked at.							
Joe Ramirez									
128001		Mechanical			1/27/2015		13		\$0.00
Medium	Work In Progress				1/27/2015 3:30:39 PM				
Villalobos, David		Need to replace leaking water heater at mechanical room							
David Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

<b>Location: Mesquite ES</b>									
126897					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:31 AM				
Villalobos, David	Yearly - Mesquite ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
126214					12/4/2014		67		\$0.00
Medium	Work In Progress				12/4/2014 8:08:13 AM				
Ontiveros, Guadalupe	I am requesting a truck load of crusher fine , tractor and box-scaper to be used in north parking lot								
Joe Ramirez									
128398		Custodial			2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 10:15:24 AM				
Carbajal, Jimmy	please i need to replace the water hose. If possible of 100ft thank you								
Luis Saucedo									
128269					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:30 AM				
Ramirez, Joe	Monthly - Mesquite ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									
126580					12/12/2014		59		\$0.00
Medium	Work In Progress				12/12/2014 10:39:11				
Ramirez, Joe	need to replace covebase in north lounge.								
Joe Ramirez									
120340					8/3/2014		190		\$0.00
Medium	Work In Progress				8/3/2014 12:33:41 AM				
Munoz, Michael	Yearly - Mesquite ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.		PM not completed as per schedule						
Margret Villalobos									
128296					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:48 AM				
Ramirez, Joe	Monthly - Mesquite ES Monthly FE Inpsection - Refer to PM schedule details.								
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Mesquite ES</b>									
128469					2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 12:35:41 PM				
Ontiveros, Guadalupe		eastside fenceline needs to be replaced (poor condition) this will be at the community park.							
Joe Ramirez									
128024		Custodial			1/28/2015		12		\$0.00
Medium	Work In Progress				1/28/2015 7:38:16 AM				
Carbajal, Jimmy		the vaccum #1148 the motor is making a lot of noise  thank you							
Luis Saucedo									
121721	Main Building	Office			8/25/2014		168		\$0.00
Medium	Work In Progress				8/25/2014 2:28:47 PM				
Estrada, Jesus		Carpet is coming apart at the seam entrance to the first office.							
Jesus Estrada									
121639					8/22/2014		171		\$0.00
Medium	Work In Progress				8/22/2014 1:25:52 PM				
Estrada, Jesus		carpet in portable #601 needs to be repaired.							
Luis Saucedo									
125018					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:28 AM				
Orozco, Daniel		Monthly - Mesquite ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
126417					12/9/2014		62		\$0.00
Medium	Work In Progress				12/9/2014 3:12:51 PM				
Orozco, Daniel		REPLACE WHEELS IN WALK IN AND REFRIGERATOR SHELVES. SNP MANAGER EMILIA C. 233.2341							
Maritza Gonzalez									
128294					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:47 AM				
Apodaca, Mario		Monthly - Mesquite ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 21 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>57</b>			<b>Total for Mesquite ES</b>	<b>0</b>		<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: North Valley ES</b>									
127944					1/26/2015		14		\$0.00
Medium	Work In Progress				1/26/2015 2:42:14 PM				
Orozco, Daniel		ICE MACHINE IS NOT WORKING, NOT MAKING ICE. SNP MANAGER LAURA B. 233.3658							
Maritza Gonzalez									
127844					1/23/2015		17		\$0.00
Medium	Work In Progress				1/23/2015 10:40:59 AM				
Orozco, Daniel		FLOOR LOOSE INSIDE WALK IN.SNP MANAGER LAURA B. 233.3658							
Maritza Gonzalez									
122505					9/9/2014		153		\$0.00
Medium	Work In Progress				9/9/2014 10:21:14 AM				
Gonzalez, Salvador		Principal would like to request a metal canopy at the bus turnaround, like the one at STE.							
Maria Hernandez									
128257					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:22 AM				
Vega, Danny		Monthly - North Valley ES Emer Light Test: Monthly - Refer to PMschedule details.							
Margret Villalobos									
128260					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:24 AM				
Vega, Danny		Monthly - North Valley ES Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									
128634					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress				2/8/2015 12:29:19 AM				
Vega, Danny		Monthly - North Valley ES Playground Inspection - Refer to PMschedule details.							
Margret Villalobos									
118856					7/1/2014		223		\$0.00
Medium	Work In Progress				7/1/2014 8:39:58 AM				
Ronquillo, Ruben		(attention ruben ronquillo)progressive plygrd equip-have five broken platform parts 46 1/2 L x5 1/2 W x3 1/2 H beams-also missing stairs-removed by green contractor solutoins-safetyhazard-please check into replacment parts-(800-585-3131)@progressive design equip.							
Danny Vega									



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>North Valley ES</b>							
123956		Athletic Field			10/9/2014		123		\$0.00
High	Work In Progress				10/9/2014 3:38:52 PM				
Munoz, Michael		playground has broken platforms and a slide. need to replace.							
Alfredo Holguin									
125007					11/2/2014		99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:21 AM				
Orozco, Daniel		Monthly - North Valley ES - Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
126978					1/4/2015		36		\$0.00
Medium	Work In Progress				1/4/2015 12:41:37 AM				
Munoz, Michael		Monthly - North Valley ES - Fire Sprinkler Insp. - Refer to PM schedule details.							
Margret Villalobos									
120341					8/3/2014		190		\$0.00
Medium	Work In Progress				8/3/2014 12:33:42 AM				
Munoz, Michael		Yearly - North Valley ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.				PM not completed as per schedule			
Margret Villalobos									
128302					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:52 AM				
Vega, Danny		Monthly - North Valley ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
126846					1/4/2015		36		\$0.00
Medium	Work In Progress				1/4/2015 12:39:50 AM				
Holguin, Alfredo		Monthly - North Valley ES - Fire Pump Engine - Refer to PM schedule details.							
Margret Villalobos									
127096					1/6/2015		34		\$0.00
Medium	Work In Progress				1/6/2015 7:58:24 AM				
Flores, Pete		truck #107 leaks water from water pump /water pump needs replacement asap.							
Danny Vega									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: North Valley ES</b>									
127125					1/6/2015		34		\$0.00
Medium	Work In Progress				1/6/2015 3:14:11 PM				
Flores, Pete		SNP VEHICLE 54, NEEDS BATTERY AND FLAT TIRE REPAIRED.							
Maritza Gonzalez									
128128		Custodial			1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 8:02:42 AM				
Carbajal, Jimmy		need a refill on propane tank for burnisher.(#b43410)							
Brian Pacheco									
126161		Exterior			12/3/2014		68		\$0.00
High	Work In Progress				12/3/2014 9:55:25 AM				
Ortiz, Ruben		Make sure all trash stuck to the fence line is picked up.							
Jesus Estrada									
122514					9/9/2014		153		\$0.00
Medium	Work In Progress				9/9/2014 1:47:49 PM				
Ontiveros, Guadalupe		(attention Lupe O.)alarm on spklr timer controller-please stop by check it out -rain bird modlue eso -lx. cant clear alarm.help							
Danny Vega									
124383					10/21/2014		111	2	\$50.00
Medium	Work In Progress				10/21/2014 9:58:58 AM				
Ontiveros, Guadalupe		underground water leak by backflow preventer box/by small plygrd				2/3/15 - Routed to Lupe 10/28/14 - Shut off water to BFP - D. Villalobos			
Danny Vega									
125876					11/21/2014		80		\$0.00
Medium	Work In Progress				11/21/2014 3:51:57 PM				
Villalobos, David		No hot water in classrm sinks at rio grand wing /boiler at mechanical rm is out/wont lite-up please ck							
Danny Vega									
126907					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:39 AM				
Villalobos, David		Yearly - North Valley ES Backflow Inspection - Refer to PMschedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** North Valley ES

128098 Classroom 1/29/2015 11 \$0.00

Medium Work In Progress Nurse's office 1/29/2015 12:00:31 PM

Villalobos, David As per Mrs. Hernandez, nurse's office is requesting a small hot water heater to provide warm water for washing hands, gargles, etc.

Gloria Reyes

120825 Parking Lot 8/8/2014 185 \$0.00

Medium Work In Progress front door area 8/8/2014 12:15:43 PM

Villalobos, David As per Principal, please install a water hose bit in the front of the building. Please visit Principal for specifics.

Priscilla Martinez

126484 12/10/2014 61 \$0.00

Medium Work In Progress 12/10/2014 3:37:49 PM

Sotelo, Enrique emergency lamp by rm 310 is out bad ballast

Danny Vega

127224 1/8/2015 32 \$0.00

Medium Work In Progress 1/8/2015 9:45:21 AM

Sotelo, Enrique emergency ballast out by hallway by rm 104-girls rr by rm 107-hallway by rm 202 by rm 206-by rm 211-by rm 305-by rm 300 conference- also pipe chase rm rio grand valley

Danny Vega

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>	<b>North Valley ES</b>								
121456					8/19/2014		174		\$0.00

Medium Work In Progress 8/19/2014 3:33:06 PM

Sotelo, Enrique

Line Locates needed at North Valley  
 NOTICE OF INTENT TO EXCAVATE  
 Header Code: STANDARD LOCATE  
 Request Type:  
 Ticket No: 2014341177 Seq. No: 4  
 Original Call Date: 08/19/2014 Time: 01:01:52  
 PM OP: 190  
 Transmit Date: 08/19/2014 Time: 01:09:13  
 PM  
 Work to Begin Date: 08/21/2014 Time: 12:55:00  
 PM

Company: GADSDEN INDEPENDENT SCHOOL DIST  
 Contact Name: DAVID LOBOS Contact Phone: (575)882-6913  
 Alternate Contact: MIKE MUNOZ Alternate Phone: (575)882-6907  
 Fax No: (575)882-6945  
 Email: dwillalobos@gisb.k12.nm.us

State: NM County: DONA ANA City: RURAL  
 DONA ANA  
 Address: 300 , CASCADE AVE  
 To Address:  
 Nearest Intersecting Street: OZARK ST  
 2nd Intersecting Street:  
 Subdivision: SAN MIGUEL/ NORTH VALLEY ELEM.  
 Latitude: 32.14765050 Longitude: -106.72130800  
 Zip Code: 88046  
 Grid:  
 Township: 25S Range: 02E Section 1/4: 10 NE

Location of Work: FROM INTERS. OF NM-28 & NM-228, GO S. ON NM-28 FOR APPX 1MI, L.(E) ON CASCADE AVE GO APPX 0.25MI TO THE SCHOOL ON S.SIDE OF ROAD. - SPOT ON THE NE.SIDE OF THE SCHOOL PROPERTY, 20FT RADIUS OF THE AREA MARKED IN WHITE ON THE ASPHALT LOCATED S. OF

Remarks: THE LARGE WATER TANK AND PUMP BLDG.

Type of Work: REROUTING WATER LINE  
 Private Property: Street: Overhead Lines:  
 Blasting:  
 Easement: Mechanical Boring: Premarked:  
 Y  
 Work Being Done For: GADSDEN INDEPENDENT SCHOOL DIST

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: North Valley ES</b>									
Dominique Esparza									
128652					2/9/2015		0		\$0.00
Medium	Work In Progress				2/9/2015 8:09:46 AM				
Marquez, Gerardo		we need a chain for a walk in gate. do to the fact that we have kids coming in after school and work hours forcing the gate open. when theres a lock already on it.							
Brian Pacheco									
<b>Count: 27 Work Orders</b>		<b>Avg. Age of WO's 71</b>			<b>Total for North Valley ES</b>			<b>2</b>	<b>\$50.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
128025	Main Building				1/28/2015		12		\$0.00
Medium	Work In Progress			1/28/2015 8:32:41 AM					
Sotelo, Enrique	LOUNGE RESTROOM LIGHT SWITCH IS NOT WORKING. SENSORED LIGHTS IN RESTROOM BUT OVERRIDE IS DAMAGED.								
Adam Montoya									
126895					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress			1/4/2015 12:40:30 AM					
Villalobos, David	Yearly - Northern Pre-K Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
126790	Main Building				12/19/2014		52		\$0.00
Medium	Work In Progress			12/19/2014 8:00:45 AM					
Ontiveros, Guadalupe	(AS PER THE DAYCARE) NEED SAND DELIVERED FOR FRONT OF BUILDING SANDBOX.								
Adam Montoya									
128301					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress			2/1/2015 12:50:51 AM					
Vega, Danny	Monthly - La Mesa ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
128635					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress			2/8/2015 12:29:20 AM					
Vega, Danny	Monthly - Northern Pre-K Playground Insp - Refer to PM schedule details.								
Margret Villalobos									
128258					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress			2/1/2015 12:50:23 AM					
Vega, Danny	Monthly - La Mesa ES Exit Sign Insp: Monthly - Refer to PM schedule details.								
Margret Villalobos									
128259					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress			2/1/2015 12:50:23 AM					
Vega, Danny	Monthly - La Mesa ES Emer. Light Test: Monthly - Refer to PM schedule details.								
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
128414					2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 2:43:51 PM				
Vega, Danny		NEED GROUNDS SPRAYED FOR WEEDS.							
Adam Montoya									
128289					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:43 AM				
Apodaca, Mario		Monthly - Northern Pre-K -Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 9 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>15</b>		<b>Total for Northern On-Track Pre-K (LM)</b>	<b>0</b>		<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: Physical Plant Complex</b>									
128194					1/31/2015		9		\$0.00
Medium	Work In Progress				1/31/2015 12:39:12 AM				
Apodaca, Mario	Monthly - PPD/GHS - WW Monthly Sampling - Refer to PM schedule details.								
Margret Villalobos									
127806					1/22/2015		18		\$0.00
Medium	Work In Progress				1/22/2015 12:28:46 PM				
Apodaca, Mario	need to reorder soda ash for wastewater treatment plant and pool to maintain pH levels in range								
Mario Apodaca									
128588					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 11:23:15 AM				
Gonzalez, Salvador	Need to install metal trash bin in PPD park on cement slab.								
Danny Carrasco									
128464	Maintenance				2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 10:58:49 AM				
Marquez, Gerardo	Need to install doors on Metal Bldg on westside of Autoshop (see Alfredo H. for ?'s)								
Alfredo Holguin									
127567					1/15/2015		25		\$0.00
Medium	Work In Progress				1/15/2015 7:52:14 AM				
Carrasco, Danny	need to remove Julies desk modular, carpet will be replaced. this needs to be done bytomorrow so that carpet be installed over the weekend.								
Jesus Estrada									
127691					1/20/2015		20		\$0.00
Medium	Work In Progress				1/20/2015 10:04:05 AM				
Miranda, Danny	PPD Offices - remolding new office.								
Alfredo Holguin									
121840					8/27/2014		166		\$0.00
Medium	Work In Progress				8/27/2014 1:12:27 PM				
Miranda, Danny	please replace plywood with smart board on training room where a/c was vented. thank you								
Michael Munoz									



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description				Action Taken				
Requester Name									

<b>Location: Physical Plant Complex</b>									
128238					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:10 AM				
Ruiz, Maria	Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.								
Margret Villalobos									
126835					1/4/2015		36		\$0.00
Medium	Work In Progress				1/4/2015 12:39:41 AM				
Ruiz, Maria	Monthly - PPD - Fueling Station Monthly Inspection - Refer to PM schedule details.								
Margret Villalobos									
127639					1/16/2015		24		\$0.00
Medium	Work In Progress				1/16/2015 10:38:58 AM				
Ronquillo, Ruben	NEED BLINDS REPLACED OR PAINTED IN PPD FRONT OFFICE. PLEASE SEE MARY								
Alfredo Holguin									
128609					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 3:36:55 PM				
Apodaca, Mario	meet to order a powerverter for truck 38 to mount in the toolbox								
Mario Apodaca									
128563					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 8:12:37 AM				
Apodaca, Mario	need to read or bacteria block to maintain lift stations and grease traps for district wide use								
Mario Apodaca									
128137	Food Services				1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 9:41:59 AM				
Villalobos, Margret	SPIDER PROBLEMS AT SNP WAREHOUSE.				1/30/15 Emailed				
Maritza Gonzalez									
122868					9/16/2014		146		\$0.00
Medium	Work In Progress				9/16/2014 3:48:24 PM				
Ronquillo, Ruben	ORDER 4EA. ENGINE DRIVEN WATER PUMPS, WITH HOSES. THANK YOU								
Ruben Ronquillo									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Physical Plant Complex

128312 2/1/2015 2/7/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:59 AM

Diaz, Sebastian Monthly - Physical Plant FE Inspection - Refer to PM schedule details.

Margret Villalobos

126672 12/16/2014 55 \$0.00

Medium Work In Progress 12/16/2014 3:15:08 PM

Carrasco, Danny Requesting scissor lift covers for lifts that will be assigned for Chaparral schools and Southern schools.

Danny Carrasco

127534 1/14/2015 26 \$0.00

Medium Work In Progress 1/14/2015 1:58:36 PM

Estrada, Jesus Install new carpet in Julie's office, once office is painted to match Alfredo's carpet.

Michael Munoz

127600 Office 1/15/2015 25 \$0.00

Medium Work In Progress 1/15/2015 3:30:01 PM

Estrada, Jesus NEED QUOTE FOR VCT TO BE REPLACED IN PPD FRONT ENTRANCE & OFFICE.

Jesus Estrada

128653 Maintenance Office 2/9/2015 0 \$0.00

Medium Work In Progress 2/9/2015 8:16:17 AM

Lara, Ralph WE NEED TWO TRIPP POWER VERTAR 3000W TO USED THEM ON DISTRICT VANS, FOR CUTTING KEYS ON DIFFRENT SCHOOL SITES.

Ralph Lara

126240 12/4/2014 67 \$0.00

Medium Work In Progress 12/4/2014 12:43:22 PM

Marquez, Gerardo One (1) key needed for electrical room at New Food WHS. Please drop off key at the construction office. Key needed as soon as possible. Should you have any questions please contact Mr. Ralph Gallegos at 575-882-6921 in the Construction office. Thank You

Dominique Esparza

122948 9/18/2014 144 \$0.00

Medium Work In Progress 9/18/2014 8:57:40 AM

Marquez, Gerardo New Warehouse- Rekey off grand Master - Check with Mike - Alfredo on keying

Alfredo Holguin

2/9/2015 1:38:24 PM

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Physical Plant Complex

124720 Motor Vehicle 10/29/2014 103 \$0.00

Medium Work In Progress 10/29/2014 8:23:36 AM

Marquez, Gerardo  
 COULD YOU PLEASE REPLACE A LOCK ON  
 CABINET IN AUTO SHOP USED FOR CUSTODIAL  
 SUPPLIES IF YOU HAVE ANY QUESTIONS PLEASE  
 CONTACT FERNANDA THE MORNING CUSTODIAN.  
 (2ND REQUEST)

Jimmy Carbajal

126464 Custodial 12/10/2014 61 \$0.00

High Work In Progress 12/10/2014 12:55:12

Flores, Pete Please check brakes on truck #16

Jesus Estrada

128656 Motor Vehicle 2/9/2015 0 \$0.00

Medium Work In Progress vehicle#92 2/9/2015 8:53:05 AM

Flores, Pete please service vehicle as required, mileage is currently-  
150017

Pete Flores

128341 Motor Vehicle 2/2/2015 7 \$0.00

Medium Work In Progress vehicles 2/2/2015 2:02:52 PM

Flores, Pete please repair flat tires on vehicles, 173 and 163

Pete Flores

128130 Motor Vehicle 1/30/2015 10 \$0.00

Medium Work In Progress tilt trailer 1/30/2015 8:20:03 AM

Flores, Pete battery is more than 5 years old, requires replacement.

Pete Flores

127958 Motor Vehicle 1/26/2015 14 \$0.00

Medium Work In Progress Federal vehicle 1/26/2015 3:44:58 PM

Flores, Pete When driving in a long road and picking up speed the  
vehicle starts to jerk. Also, windows on driver side front  
and passenger back do not work.

Noemi Duron

120665 8/6/2014 187 \$0.00

Medium Work In Progress 8/6/2014 2:43:32 PM

Flores, Pete routine service on truck 38 need to change the motor  
oil (3468 miles )

Mario Apodaca

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Physical Plant Complex

122443 Motor Vehicle 9/8/2014 154 \$0.00

Medium Work In Progress ag trailer 9/8/2014 9:06:23 AM

Flores, Pete please prepare trailer as required for use by agriculture dept.

Pete Flores

127922 Food Services 1/26/2015 14 \$0.00

Medium Work In Progress 1/26/2015 1:30:57 PM

Flores, Pete SNP VEHHCILE 56 NEEDS TO BE SERVICED.

Maritza Gonzalez

127923 Food Services 1/26/2015 14 \$0.00

Medium Work In Progress 1/26/2015 1:31:10 PM

Flores, Pete SNP VEHHCILE 52 NEEDS TO BE SERVICED.

Maritza Gonzalez

127924 Food Services 1/26/2015 14 \$0.00

Medium Work In Progress 1/26/2015 1:31:21 PM

Flores, Pete SNP VEHHCILE 43 NEEDS TO BE SERVICED.

Maritza Gonzalez

127811 Food Services 1/22/2015 18 \$0.00

Medium Work In Progress 1/22/2015 2:53:42 PM

Flores, Pete vehicle 176 has no brake lights (received email from district website webmaster)

Maria Ruiz

119759 7/23/2014 201 \$0.00

Medium Work In Progress 7/23/2014 2:32:20 PM

Flores, Pete MAINTANCE ON ALL SPED VEHICLES  
SUBMIT INVOICE TO JULIE HERNANDEZ

Margaret Villalobos

128458 2/4/2015 5 \$0.00

Medium Work In Progress 2/4/2015 10:11:09 AM

Aldaz, Bobby Please fill in holes by entrance gate to PPD.

Margret Villalobos

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
128507		Lift Station			2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 8:20:45 AM				
Ontiveros, Guadalupe		on the east side of the river bank need to place a big boulder rock to block off the outfall of the sewer plant water pipe concrete curve sold vehicles won't drive over and break							
Mario Apodaca									
128508		Lift Station			2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 8:24:35 AM				
Ontiveros, Guadalupe		need the assistance of a heavy equipment operator and tractor to help us replace a air relief check valve on the west side of the river bank							
Mario Apodaca									
127289	Motor Vehicle				1/9/2015		31		\$0.00
Medium	Work In Progress	vehicle#100			1/9/2015 10:33:33 AM				
Flores, Pete		please check cause of vehicle leaning excessively to one side.							
Pete Flores									
127172	Motor Vehicle				1/7/2015		33		\$0.00
Medium	Work In Progress	vehicle#25			1/7/2015 9:26:14 AM				
Flores, Pete		please replace worn tires as required.							
Pete Flores									
127249	Motor Vehicle				1/8/2015		32		\$0.00
Medium	Work In Progress	vehicle#178			1/8/2015 3:03:59 PM				
Flores, Pete		battery is nearing end of expected service life, replacement is required.							
Pete Flores									
127251					1/8/2015		32		\$0.00
Medium	Work In Progress				1/8/2015 3:20:43 PM				
Flores, Pete		TRUCK #32 NEEDS FUEL PUMP REPLACED							
Ruben Ronquillo									
127462	Motor Vehicle				1/13/2015		27		\$0.00
Medium	Work In Progress	vehicle#147			1/13/2015 9:39:06 AM				
Flores, Pete		rear driver's side window inoperative, please check cause of malfunction.							
Pete Flores									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
127416	Motor Vehicle				1/12/2015		28		\$0.00
Medium	Work In Progress	vehicle#172			1/12/2015 3:17:34 PM				
Flores, Pete		please check for any scheduled maintenance							
Pete Flores									
127546	Motor Vehicle				1/14/2015		26		\$0.00
Medium	Work In Progress	chaparral golf			1/14/2015 3:17:18 PM				
Flores, Pete		please prepare fairplay golf cart for use by chaparral security							
Pete Flores									
127582					1/15/2015		25		\$0.00
Medium	Work In Progress				1/15/2015 11:14:29 AM				
Flores, Pete		Need to service truck 193 - need oil change and trailer lights fixed and wipers replaced.							
Joe Ontiveros									
125165	Motor Vehicle				11/5/2014		96		\$0.00
Medium	Work In Progress	equip#0423			11/5/2014 9:41:37 AM				
Flores, Pete		please check mower #0423 for any required maintenance.							
Pete Flores									
124450					10/22/2014		110		\$0.00
Medium	Work In Progress				10/22/2014 11:21:12				
Flores, Pete		vehicle 01, needs wipers and check engine light turned on and turned off (reported by Teresa Ortega)							
Maria Ruiz									
127018					1/5/2015		35		\$0.00
Medium	Work In Progress				1/5/2015 12:41:42 AM				
Flores, Pete		Monthly - District Backhoe - Full Service PM - Refer to PM schedule details.							
Margret Villalobos									
127019					1/5/2015		35		\$0.00
Medium	Work In Progress				1/5/2015 12:41:43 AM				
Flores, Pete		Monthly - PPD - UV-0516 PM Service - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
128280					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:37 AM				
Flores, Pete		Monthly - PPD-MP-0143 DT PM Service - by SWP - Refer to PM schedule details.							
Margret Villalobos									
128281					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:38 AM				
Flores, Pete		Monthly - PPD-T-0529 PM (Trencher) - by SWP - Refer to PM schedule details.							
Margret Villalobos									
128322					2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 12:38:50 AM				
Villalobos, Margret		Monthly - PPD - Quarterly Meeting - Refer to PM schedule details.							
Margret Villalobos									
128131					1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 8:29:08 AM				
Gonzalez, Salvador		Requesting welding cabinet and table							
Salvador Gonzalez									
128562					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 8:10:24 AM				
Carrasco, Danny		need to reorder alcohol to disinfect water sampling points and distilled water to rinse off pH meter and other testing equipment							
Mario Apodaca									
128463	Maintenance				2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 10:57:20 AM				
Holguin, Alfredo		Need quote to insulate Metal Bldg on westside of Autoshop.							
Alfredo Holguin									
122947					9/18/2014		144		\$0.00
Medium	Work In Progress				9/18/2014 8:49:23 AM				
Ronquillo, Ruben		New Warehouse - need new signs for storage shelving (District Warehouse, General Maintenance, Custodial) check with Mary Sitters and Alfredo on additional signage ie. floor products ect.							
Alfredo Holguin									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
127900					1/26/2015		14		\$0.00
Medium	Work In Progress				1/26/2015 8:06:16 AM				
Ronquillo, Ruben		Please order (2) Magnetic Signs that read: Meeting Same format as the others that were ordered. Thank you							
Margret Villalobos									
128119					1/29/2015		11		\$0.00
Medium	Work In Progress				1/29/2015 3:56:50 PM				
Ronquillo, Ruben		Need to order (2) signs: Please see sticker. Would like in White Background w/Blue Lettering on a legal size sheet of paper. Any ?'s see Maria							
Maria Ruiz									
126993					1/4/2015		36		\$0.00
Medium	Work In Progress				1/4/2015 12:41:50 AM				
Flores, Pete		Monthly - PPD-T-0525 PM (Excavator) - by SWP - Refer to PMSchedule details.							
Margret Villalobos									
128384	Purchasing	Office			2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 8:50:45 AM				
Diaz, Sebastian		Heater/AC unit is making a loud, vibrating noise. Please come and take a look at it. Also, Lights in warehouse are flickering again. Please replace.							
Theresa Ramirez									
126898					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:32 AM				
Villalobos, David		Yearly - Physical Plant Backflow Inspection - Refer to PMSchedule details.							
Margret Villalobos									
126289		Office			12/5/2014		66		\$0.00
Medium	Work In Progress				12/5/2014 2:19:58 PM				
Solis, Lorenzo		the evaporative cooler at service the locks smith and water/wastewater and maintenance waehouse needs to be updated due to the one that's on its all rusted out							
Mario Apodaca									
127533					1/14/2015		26		\$0.00
Medium	Work In Progress				1/14/2015 1:56:21 PM				
Carrasco, Danny		Paint Juliet's Office.							
Michael Munoz									
<b>Count: 63 Work Orders</b>			<b>Avg. Age of WO's 40</b>			<b>Total for Physical Plant Complex</b>	<b>0</b>		<b>\$0.00</b>



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Riverside ES</b>							
127121					1/6/2015		34		\$0.00
Medium	Work In Progress				1/6/2015 3:06:59 PM				
Castillo, Carlos		1/06/2015. Need Carlos C. to work on lighting in South girls bathroom.							
Mario Martinez									
128336					2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 9:50:24 AM				
Castillo, Carlos		2/02/2015. Need Carlos C to fix non working lights in South wing and main wing.							
Mario Martinez									
128340					2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 12:38:12 PM				
Castillo, Carlos		2/02/2015. Need Carlos C. to fix lights in hallway at South wing.							
Mario Martinez									
124465					10/22/2014		110		\$0.00
Medium	Work In Progress				10/22/2014 2:54:48 PM				
Castillo, Carlos		10/22/2014. Need Carlos C. to fix electrical power line at Special Ed room.							
Mario Martinez									
126797					12/19/2014		52		\$0.00
Medium	Work In Progress				12/19/2014 9:48:59 AM				
Castillo, Carlos		Need Carlos C. to fix bad lighting fixtures in room 101.							
Mario Martinez									
121093					8/13/2014		180		\$0.00
Medium	Work In Progress				8/13/2014 10:09:02 AM				
Ambriz, Jose		Need Jose A. to check two inside water fountains that are not cooling water.							
Mario Martinez									
127383					1/12/2015		28		\$0.00
Medium	Work In Progress				1/12/2015 7:56:45 AM				
Ambriz, Jose		1/12/2015. Need Jose A. to enlarge exhaust fan motor size at personal restroom in new wing.							
Mario Martinez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Riverside ES</b>									
122686					9/12/2014		150		\$0.00
Medium	Work In Progress			9/12/2014 8:17:14 AM					
Ambriz, Jose	check cooling in room 136								
Michael Munoz									
127260					1/8/2015		32		\$0.00
High	Work In Progress			1/8/2015 3:41:48 PM					
Ambriz, Jose	please clean all strainers to coils for proper heating. the contract did not include flushing lines. thank you								
Michael Munoz									
126899					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress			1/4/2015 12:40:33 AM					
Villalobos, David	Yearly - Riverside ES Backflow Inspection - Refer to PM schedule details.								
Margret Villalobos									
121838					8/27/2014		166		\$0.00
Medium	Work In Progress			8/27/2014 12:58:57 PM					
Ontiveros, Joe	Need plumber Joe O. to fix leaky urinal in boys restroom at north wing.								
Mario Martinez									
125700					11/18/2014		83		\$0.00
Medium	Work In Progress			11/18/2014 3:36:23 PM					
Ontiveros, Joe	11/18/2014. Need PLUMBER Joe O. to replace 8 inch center faucets in rooms # 117, 141, and 137.								
Mario Martinez									
127122					1/6/2015		34		\$0.00
Medium	Work In Progress			1/6/2015 3:10:43 PM					
Ontiveros, Joe	1/06/2015. Need Joe O. to install electric hot water heater for new Nurses office lavatory sink.								
Mario Martinez									
127174					1/7/2015		33		\$0.00
Medium	Work In Progress			1/7/2015 10:13:02 AM					
Ontiveros, Joe	1/07/2015. Need Joe O. to repair or replace five flush valves at boys and girls bathrooms. Also need to replace open elongated toilet seat								
Mario Martinez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Riverside ES

126032 Athletic Field 12/1/2014 70 \$0.00

Medium Work In Progress soccer field 12/1/2014 9:35:45 AM

Martinez, Mario need 40 feet of 3/8 " rebar for anchoring soccer goal post

Mario Martinez

121247 Main Building Classroom 8/15/2014 178 \$0.00

Medium Work In Progress nurses station 8/15/2014 10:30:55 AM

Martinez, Mario we need two installed two SECURED cabinets in the nurses station with lock and key for medicine storage. (navarro)

Rosa Quezada

124523 10/23/2014 109 \$0.00

Medium Work In Progress 10/23/2014 3:19:44 PM

Martinez, Mario 10/23/2014.  
Need air compressor and electric hammer drill for future use. If you can please purchase for Riverside Elementary.

Mario Martinez

128270 2/1/2015 2/9/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:31 AM

Martinez, Mario Monthly - Riverside ES Emer. Light Test: Monthly - Refer to PM schedule details.

Margret Villalobos

128271 2/1/2015 2/9/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:50:31 AM

Martinez, Mario Monthly - Riverside ES Exit Sign Insp: Monthly - Refer to PM schedule details.

Margret Villalobos

128598 Main Building Custodial 2/6/2015 3 \$0.00

Medium Work In Progress 2/6/2015 12:20:10 PM

Carbajal, Jimmy Jimmy, por favor necesito tres cepillos para aspiradora. Muchas gracias.

Miguel Sonora

124633 10/27/2014 105 \$0.00

Medium Work In Progress 10/27/2014 3:17:04 PM

Gallegos, Rafael 10/27/2014.  
Need TPO roof above teachers lounge and above computer room #2 looked at for possible re roofing.

Mario Martinez

2/9/2015 1:38:24 PM

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Riverside ES</b>									
119185					7/8/2014		216		\$0.00
Medium	Work In Progress				7/8/2014 7:28:48 AM				
Marquez, Gerardo		7/08/2014.							
		Need Rafa L. to fix door lock at library.							
Mario Martinez									
120025					7/30/2014		194		\$0.00
Medium	Work In Progress				7/30/2014 1:46:51 PM				
Lara, Ralph		Rekeylocks from storage bins from DP to RS.							
		(DannyC. has the locks)							
Michael Munoz									
124407					10/21/2014		111		\$0.00
Medium	Work In Progress				10/21/2014 1:30:42 PM				
Lara, Ralph		10/21/2014.							
		Need Rafa L. to rekey cylinders to off master at room #76,							
Mario Martinez									
119633					7/21/2014		203		\$0.00
Medium	Work In Progress				7/21/2014 10:19:47 AM				
Ontiveros, Guadalupe		7/21/2014.							
		Booster pump for main irrigation sprinkler not working.							
		Soccer field drying up. Need assistance with booster pump.							
Mario Martinez									
121876					8/28/2014		165		\$0.00
Medium	Work In Progress				8/28/2014 7:33:04 AM				
Gallegos, Rafael		Warranty Work Order!!! Water leaking at roof and walls							
		at rooms #21,25,37,28,33,39,34, and#41.							
Mario Martinez									
125019					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:28 AM				
Orozco, Daniel		Monthly - Riverside ES Range Hood Cleaning - Refer to							
		PMschedule details.							
Margret Villalobos									
119526	Main Building	Classroom			7/17/2014		207		\$0.00
Medium	Work In Progress	Room 17			7/17/2014 2:21:41 PM				
Estrada, Jesus		need tile to be installed a.s.a.p. in room 17 (flavian)				pending as of 9/29/14, p.o. #141500240			
Rosa Quezada									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Riverside ES</b>									
127843					1/23/2015		17		\$0.00
Medium	Work In Progress				1/23/2015 10:30:21 AM				
Martinez, Mario		1/23/2015. Need 4 exterior covers on Fire pull stations fixed. Replaced old batteries and found buttons are broken.							
Mario Martinez									
126186	Main Building	Cafeteria			12/3/2014		68		\$0.00
Medium	Work In Progress	cafeteria			12/3/2014 3:23:58 PM				
Lara, Ralph		need to install a doorbell in north side door of the cafeteria for incoming deliveries to the cafeteria. vendors waiting outside to deliver because we don't know they are out there and we can hear them knocking on the door. (santa Nava)							
Rosa Quezada									
127176					1/7/2015		33		\$0.00
Medium	Work In Progress				1/7/2015 10:42:19 AM				
Lara, Ralph		1/07/2015. Need Rafa L. to replace old double door Mullions with new single key Mullions, also need panic bar door handle fixed. Would also like new hardware kits for all door mullions.							
Mario Martinez									
128313					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:59 AM				
Martinez, Mario		Monthly - Riverside ES Monthly FE Inpsection - Refer to PM schedule details.							
Margret Villalobos									
128642					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress				2/8/2015 12:29:25 AM				
Martinez, Mario		Monthly - Riverside ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
125498					11/13/2014		88		\$0.00
Medium	Work In Progress				11/13/2014 9:05:14 AM				
Gallegos, Rafael		WATER VALVE NEXT TO STOVE NEEDS TO BE TIGHTENED. WATER COMES OUT WHEN TURNED ON. SNP MANAGER S.NAVA							
Maritza Gonzalez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Riverside ES</b>									
125443					11/12/2014		89		\$0.00
Medium	Work In Progress				11/12/2014 2:42:17 PM				
Gallegos, Rafael		SERVING LINE- ELECTRIC OUTLET DOES NOT HAVE NEUTRAL TO 120V TO CONNECT TO REFRIGERATOR.							
Maritza Gonzalez									
126703					12/17/2014		54		\$0.00
Medium	Work In Progress				12/17/2014 9:35:14 AM				
Orozco, Daniel		AS PER INSPECTION REPORT, DRAINS ON LEFT SIDE OF SERVING LANE ARE NOT WORKING PROPERLY, WATER IS BEING DISPENSED MANUALLY.							
Maritza Gonzalez									
<b>Count: 36 Work Orders</b>		<b>Avg. Age of WO's 83</b>		<b>Total for Riverside ES</b>		<b>0</b>		<b>\$0.00</b>	

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: RTC - Alliance</b>									
127239		Portables			1/8/2015		32		\$0.00
Medium	Work In Progress				1/8/2015 1:15:33 PM				
Moncayo, Fernando		ramps very slippery and Mrs. Hirsch's classroom heater not working Mr. Moncada came in salted ramps and fixed heater							
Gloria Delgado									
124511		Portables			10/23/2014		109		\$0.00
Medium	Work In Progress				10/23/2014 12:17:58				
Moncayo, Fernando		Need light bulbs changed in the office. Fire escape security windows keep opening secure locks while maintaing safety egress							
Gloria Delgado									
126234		Office			12/4/2014		67		\$0.00
Medium	Work In Progress				12/4/2014 11:06:49 AM				
Moncayo, Fernando		the office heater has not turned on/ it has been below 50 for the past 2days/ have tried to turn on and off to reset and even walked in and out rooms for the sensor /have the dial up to 90 it does not turn on							
Gloria Delgado									
<b>Count: 3 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>69</b>		<b>Total for RTC - Alliance</b>	<b>0</b>		<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>San Miguel ES</b>							
126901					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:34 AM				
Villalobos, David		Yearly - San Miguel ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
128291					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:45 AM				
Apodaca, Mario		Monthly - San Miguel ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>22</b>			<b>Total for San Miguel ES</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa ES</b>									
124391					10/21/2014		111		\$0.00
Medium	Work In Progress				10/21/2014 10:54:28				
Orozco, Daniel		WALK IN ENTRANCE-FLOOR IS LIFTING. SNP MANAGER MARINA R. 589.3436							
Maritza Gonzalez									
123325					9/26/2014		136		\$0.00
Medium	Work In Progress				9/26/2014 3:48:47 PM				
Orozco, Daniel		REFRIGERATOR SIDE OF STAND FAN BROKEN OFF. SNP MANAGER MARINA R. 589.3439							
Maritza Gonzalez									
126298					12/5/2014		66		\$0.00
Medium	Work In Progress				12/5/2014 3:32:07 PM				
Orozco, Daniel		ICE MAKER LEAKING. SNP MANAGER MARINA R. 589.3439							
Maritza Gonzalez									
128513		Office			2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 10:18:00 AM				
Gonzales, Camilo		Pick up obsolete items (36) and deliver to IM?WHS. See daily delivery log for list.							
Theresa Ramirez									
128363		Office			2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 3:55:45 PM				
Gonzales, Camilo		Deliver 6 bx. PO# 141504443							
Theresa Ramirez									
127847	Main Building	Exterior			1/23/2015		17		\$0.00
Medium	Work In Progress				1/23/2015 11:20:13 AM				
Gonzalez, Salvador		Need to remove steel posts behind kitchen due to new fence installed							
Juan Ambriz									
127742	Main Building	Storage			1/21/2015		19		\$0.00
Medium	Work In Progress	New storage			1/21/2015 9:12:36 AM				
Gonzalez, Salvador		Need to install ramp in new storage building							
Juan Ambriz									
127846	Main Building	Storage			1/23/2015		17		\$0.00
Medium	Work In Progress	new storage			1/23/2015 11:18:22 AM				
Gonzalez, Salvador		Need a new ramp on new storage							
Juan Ambriz									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location: Santa Teresa ES</b>									
128640					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress				2/8/2015 12:29:24 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Playground Insp - Refer to PMschedule details.							
Margret Villalobos									
127761	Main Building	Classroom			1/21/2015		19		\$0.00
Medium	Work In Progress	Room #301			1/21/2015 12:44:54 PM				
Ambriz, Juan		Need to replace blinds in room #301							
Juan Ambriz									
125848					11/21/2014		80		\$0.00
Medium	Work In Progress				11/21/2014 2:28:51 PM				
Munoz, Michael		need new fencing with gates to prevent students from going into parking lots							
Juan Ambriz									
128316					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:51:01 AM				
Ambriz, Juan		Monthly - Santa Teresa ES Monthly FE Inspection - Refer to PMschedule details.							
Margret Villalobos									
128499	Main Building	Custodial			2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 7:34:58 AM				
Carbajal, Jimmy		Jimmy se me termino el propane de la buffer machine, por favor si me lo puede rellenar. Gracias							
Ivan Rodriguez									
125020					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:29 AM				
Orozco, Daniel		Monthly - Santa Teresa ES Range Hood Cleaning - Refer to PMschedule details.							
Margret Villalobos									
126905					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:37 AM				
Villalobos, David		Yearly - Santa Teresa ES Backflow Inspection - Refer to PMschedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa ES</b>									
127454					1/13/2015		27		\$0.00
Medium	Work In Progress				1/13/2015 8:16:32 AM				
Ontiveros, Joe		ACADEMY FENCE Contact: JOE COCA Phone: (575)523-0779							
		SPOT: L SIDE OF THE MAIN BUILDING FRM THE EXISTING FENCE TO THE E SIDE FENCE AND THE ENTRANCE FOR THE BUS PULL AND BACK TO THE BUILDING.							
		Check w/Juan Ambriz, Building Mechanic if any questions.							
Rafael Gallegos									
126573					12/12/2014		59		\$0.00
Medium	Work In Progress				12/12/2014 9:22:46 AM				
Castillo, Carlos		As per our conversation, please check for power for a Double Portable on the Eastside of campus.							
126757	Main Building	Classroom			12/18/2014		53		\$0.00
Medium	Work In Progress	parent room 300			12/18/2014 1:16:34 PM				
Castillo, Carlos		Need to Install electrical outlet for smart board							
Juan Ambriz									
128520	Main Building	Kitchen			2/5/2015		4		\$0.00
Medium	Work In Progress	walk in freezer			2/5/2015 11:04:11 AM				
Castillo, Carlos		Need to replace pilot switch in kitchen's walk in freezer							
Juan Ambriz									
125153		Parking Lot			11/5/2014		96		\$0.00
Medium	Work In Progress	outside lights			11/5/2014 8:05:29 AM				
Castillo, Carlos		Need to repair outside lights too dark for custodians while throwing out trash							
Juan Ambriz									
126164	Main Building	Office			12/3/2014		68		\$0.00
Medium	Work In Progress	Office			12/3/2014 10:02:39 AM				
Lara, Ralph		We need an additional master key so that when we have custodial substitutes and/or computer technician, office staff does not lend their key out. Thank you.							
Rita Mendez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa ES</b>									
126167	Main Building	Office			12/3/2014		68		\$0.00
Medium	Work In Progress	Office			12/3/2014 10:25:37 AM				
Lara, Ralph We need Fire Pull Station keys. The only key that we have is dented. Sort of an emergency. Thank you.									
Rita Mendez									
126112	Main Building				12/2/2014		69		\$0.00
Medium	Work In Progress				12/2/2014 3:05:57 PM				
Ambriz, Juan Need to order filters for units 20 X 30 X 1									
Juan Ambriz									
128028	Main Building	Roof			1/28/2015		12		\$0.00
Medium	Work In Progress	drains			1/28/2015 9:27:06 AM				
Ambriz, Juan Need to raise drains on roof due to smell									
Juan Ambriz									
127518	Main Building	Classroom			1/14/2015		26		\$0.00
Medium	Work In Progress	Room #108			1/14/2015 8:39:33 AM				
Ambriz, Juan Need to assemble white board cart for room #108									
Juan Ambriz									
127595	Main Building	Classroom			1/15/2015		25		\$0.00
Medium	Work In Progress	coaches office			1/15/2015 1:20:03 PM				
Ambriz, Juan Need to hang up hooks for coaches									
Juan Ambriz									
128411	Main Building	Kitchen			2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 2:26:05 PM				
Ambriz, Juan Need to replace pilot switch in kitchen									
Juan Ambriz									
128453	Main Building	Restroom			2/4/2015		5		\$0.00
Medium	Work In Progress				2/4/2015 9:23:39 AM				
Ambriz, Juan As per Mrs. Tarin need to replace hand dryers in boys restroom in 300 hallway									
Juan Ambriz									
125809	Main Building	Restroom			11/20/2014		81		\$0.00
Medium	Work In Progress	Casa roja 300			11/20/2014 2:58:53 PM				
Ambriz, Juan Need to replace hand dryers in boys restrom									
Juan Ambriz									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Santa Teresa ES</b>										
128454	Main Building	Restroom (Girls)			2/4/2015		5		\$0.00	
Medium	Work In Progress				2/4/2015 9:25:22 AM					
Ambriz, Juan		Need to replace sink faucets in girls 300 hallway restroom								
Juan Ambriz										
128455	Main Building	Restroom (Girls)			2/4/2015		5		\$0.00	
Medium	Work In Progress				2/4/2015 9:29:07 AM					
Ambriz, Juan		As per Mrs. Tarin Need to replace Hand dryers in girls 200 hallway								
Juan Ambriz										
128456	Main Building	Restroom (Girls)			2/4/2015		5		\$0.00	
Medium	Work In Progress				2/4/2015 9:33:07 AM					
Ambriz, Juan		Need to replace faucet in girls 100 hallway								
Juan Ambriz										
128227					2/1/2015	2/9/2015	8		\$0.00	
Medium	Work In Progress				2/1/2015 12:50:02 AM					
Ambriz, Juan		Monthly - Santa Teresa ES Emer Light Test: Monthly - Refer to PMSchedule details.								
Margret Villalobos										
128228					2/1/2015	2/9/2015	8		\$0.00	
Medium	Work In Progress				2/1/2015 12:50:03 AM					
Ambriz, Juan		Monthly - Santa Teresa ES Exit Sign Insp: Monthly - Refer to PMSchedule details.								
Margret Villalobos										
128229					2/1/2015		8		\$0.00	
Medium	Work In Progress				2/1/2015 12:50:04 AM					
Ambriz, Juan		Monthly - Santa Teresa ES -Clothes Dryer (Monthly) - Refer to PMSchedule details.								
Margret Villalobos										
<b>Count: 35 Work Orders</b>		<b>Avg. Age of WO's 36</b>		<b>Total for Santa Teresa ES</b>			<b>0</b>	<b>\$0.00</b>		

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
125606					11/15/2014		86		\$0.00
Medium	Work In Progress				11/15/2014 12:45:35				
Flores, Pete		Yearly - Santa Teresa HS - Mower 0425 - Grounds - Refer to PM schedule details.							
Margret Villalobos									
121481		Storage			8/19/2014		174		\$0.00
Medium	Work In Progress	band truck			8/19/2014 3:59:40 PM				
Flores, Pete		Band truck needs to be fixed for use of equipment							
Loraine Soriano									
124222					10/16/2014		116		\$0.00
Medium	Work In Progress				10/16/2014 7:56:45 AM				
Mijarez, Jaime		Room 400. No cooling in the after noon reported by teacher. The a/c motor gave out. I will need a new 3/4 hp motor with pully and clamps to replace.							
Jaime Mijarez									
124792	Main Building	Athletic Field			10/30/2014		102		\$0.00
Medium	Work In Progress	football field			10/30/2014 3:49:56 PM				
Munoz, Michael		Football/soccer score board due to malfunction to box. Scoreboard is about 21 years old.							
Loraine Soriano									
128385					2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 8:58:48 AM				
Ronquillo, Ruben		Need to purchase nets for BB Batting Cages (4) 24L x 10H x 10W							
Alfredo Holguin									
128386		Athletic Field			2/3/2015		6		\$0.00
Medium	Work In Progress	Softball			2/3/2015 9:30:39 AM				
Ronquillo, Ruben		Season started 02/02/2015. Please order nets for softball cages once they're complete. Please get measurements from Sal Gonzalez							
Loraine Soriano									
128217					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:55 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS -Clothes Dryer (Monthly) - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
126447	Main Building	Parking Lot			12/10/2014		61		\$0.00
Medium	Work In Progress	flag pole			12/10/2014 9:15:39 AM				
Escobar, David		Flag pole is not working the pulley is broken							
Loraine Soriano									
120185	Main Building	Classroom			8/1/2014		192		\$0.00
Medium	Work In Progress	main building			8/1/2014 12:28:03 PM				
Escobar, David		Several classrooms leaking. Please see me for map to determine locations							
Loraine Soriano									
124118	Main Building	Classroom			10/14/2014		118		\$0.00
Medium	Work In Progress	312			10/14/2014 8:19:40 AM				
Escobar, David		Need a pencil sharpner installed							
Loraine Soriano									
119429	Cafeteria (2005)	Cafeteria			7/15/2014		209		\$0.00
Medium	Work In Progress				7/15/2014 11:10:21 AM				
Escobar, David		Several cracked, broken or missing tiles in serving line area and dining area around stage need to be replaced.							
Rosalinda Rodriguez									
123302					9/26/2014		136		\$0.00
Medium	Work In Progress				9/26/2014 1:59:51 PM				
Lara, Ralph		doors to dock entrance at daycare will not open and need repair.							
David Escobar									
120999					8/12/2014		181		\$0.00
Medium	Work In Progress				8/12/2014 9:29:38 AM				
Ontiveros, Guadalupe		Sidewalk attached to black cinder block wall and going to arroyo has a lot of erosion from Sundays rain storm and can collapse into arroyo with another heavy rain. and was reported by Security Juan Tellez. Side walk is heavily used by the students and needs immediate attention.							
Jaime Mijarez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									

<b>Location: Santa Teresa HS</b>									
121003					8/12/2014		181		\$0.00
Medium	Work In Progress				8/12/2014 9:38:36 AM				
Ontiveros, Guadalupe	Sidewalk behind the 500 wing exit to the football field has a lot of erosion from Sundays rain storm and can collapse. Right now it is unsafe, I will have to barricade to keep students off this area. need immediate attention. Attention Lupe for this work order and work order # 120999.								
Jaime Mijarez									
127990	Cafeteria (2005)				1/27/2015		13		\$0.00
Medium	Work In Progress				1/27/2015 1:03:31 PM				
Lara, Ralph	need to replace door closer. cylinder is leaking hydraulic fluid and door is slamming ASAP								
	thank you								
Daniel Sotelo									
127991					1/27/2015		13		\$0.00
Medium	Work In Progress				1/27/2015 1:05:16 PM				
Lara, Ralph	door closer in main building going into mail boxes needs to be replaced								
	thank you								
Daniel Sotelo									
125565	Main Building	Gym			11/14/2014		87		\$0.00
Medium	Work In Progress	Football locker			11/14/2014 11:48:10				
Lara, Ralph	Football lockers have broken handles and can no longer be locked or opened, need clasp installed so they can be usable								
Loraine Soriano									
127117	Main Building	Classroom			1/6/2015		34		\$0.00
Medium	Work In Progress	215			1/6/2015 2:13:42 PM				
Lara, Ralph	keys for patio area in room 215								
Loraine Soriano									
121492	Main Building	Exterior			8/20/2014		173		\$0.00
Medium	Work In Progress	sidewalk			8/20/2014 8:59:58 AM				
Llanez, Rick	Sidewalk toward arroyo has hallow areas where water has taken sand out from under it.								
Loraine Soriano									



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

123989 10/10/2014 122 \$0.00

Medium Work In Progress 10/10/2014 11:00:23

Llanez, Rick Please fix hole in sidewalk at the end of Science Wing. Please see e-mail for pictures of area. Should you have any questions please contact Mr. Ralph Gallegos at 575 - 882-6921 in the Construction office. Thank You

Dominique Esparza

126284 12/5/2014 66 \$0.00

Medium Work In Progress 12/5/2014 11:00:49 AM

Llanez, Rick Clean sand around track.

Michael Munoz

120625 Athletic Field 8/6/2014 187 \$0.00

Medium Work In Progress Football field 8/6/2014 9:23:08 AM

Llanez, Rick Turf field in dire need of brushing and maintenance. Pellets needed and field needs to be maintained twice a month. Schedule dates are needed for proper care and equipment needed to brush field as well as pellets. It is crucial as season begins in two weeks.

Lorraine Soriano

124797 Main Building Athletic Field 10/30/2014 102 \$0.00

Medium Work In Progress softball 10/30/2014 3:55:12 PM

Llanez, Rick Bullpen in need of work on visitors side.

Lorraine Soriano

124799 Main Building Athletic Field 10/30/2014 102 \$0.00

Medium Work In Progress softball 10/30/2014 3:57:02 PM

Llanez, Rick Windscreen missing to complete the field. Not complete in the outfield.

Lorraine Soriano

128387 GYM (2009) Athletic Field 2/3/2015 6 \$0.00

Medium Work In Progress Track area 2/3/2015 9:31:46 AM

Llanez, Rick Shot putt area and discuss area several request since last semester. Season has started and no progress has been made.

Lorraine Soriano

128388 Gymnasium Athletic Field 2/3/2015 6 \$0.00

Medium Work In Progress baseball field 2/3/2015 9:33:05 AM

Llanez, Rick Baseball field several request for wind screen, season has started and no progress has been made

Lorraine Soriano

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
122642	Main Building	Classroom			9/11/2014		151		\$0.00
Medium	Work In Progress				9/11/2014 11:25:53 AM				
Flores, Pete		Need warehouse pick up golf cart from Santa Teresa High School, need to check the bolt joint on cart and tires.							
Irene Herrera									
128389	GYM (2009)	Athletic Field			2/3/2015		6		\$0.00
Medium	Work In Progress	Tennis Courts			2/3/2015 9:34:51 AM				
Ontiveros, Guadalupe		Tennis courts cement is cracked, along playing surface.							
Loraine Soriano									
122288	Main Building	Hallway/Corridor			9/4/2014		91		\$0.00
Medium	Work In Progress				9/4/2014 8:02:23 AM	12/4/2014			
Lucero, Arnold		Make sure all hallways are burnished 2 times a week. (Assign to Arnold Lucero)				10/17/14 - REMAILED TO ARNOLD			
Jesus Estrada									
127342					1/11/2015	1/27/2015	29		\$0.00
Medium	Work In Progress				1/11/2015 12:29:46 AM				
Lucero, Arnold		Monthly - QRTLY BLDG INSP REPORT (STH) - Refer to PM schedule details.							
Margret Villalobos									
122320	Main Building	Exterior			9/4/2014		158		\$0.00
Medium	Work In Progress	Admin/handicap			9/4/2014 11:39:20 AM				
Ontiveros, Guadalupe		If concrete curbs can be placed in parking to keep cars from obstructing access to sidewalks for wheelchairs							
Loraine Soriano									
128117	Main Building	Classroom			1/29/2015		11		\$0.00
Medium	Work In Progress	teachers lounge			1/29/2015 3:52:34 PM				
Castillo, Carlos		breaker is going out all the time							
Loraine Soriano									
128580	Cafeteria (2005)	Cafeteria			2/6/2015		3		\$0.00
Medium	Work In Progress	doors			2/6/2015 9:56:29 AM				
Castillo, Carlos		Handicap button in cafeteria is not working							
Loraine Soriano									
128579	Main Building	Hallway/Corridor			2/6/2015		3		\$0.00
Medium	Work In Progress	main entrance			2/6/2015 9:55:42 AM				
Castillo, Carlos		Handicap button not working							
Loraine Soriano									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
127804		Office			1/22/2015		18		\$0.00
Medium	Work In Progress	OFFICE COPY			1/22/2015 12:17:15 PM				
Castillo, Carlos		NEED TWO 20 AMPS TO BE INSTALLED SEPARATELY. WILL BE MOVING TWO COPIERS IN THE ROOM.							
Marylou Jimenez									
127805		Office			1/22/2015		18		\$0.00
Medium	Work In Progress	OFFICE			1/22/2015 12:18:36 PM				
Castillo, Carlos		NEED AN ELECTRICAL OUTLET IN OFFICE STORAE ROOM. WILL BE MOVING IN A REFRIGERATOR.							
Marylou Jimenez									
127839	Dressing Rooms	Dressing Room			1/23/2015		17		\$0.00
Medium	Work In Progress				1/23/2015 10:19:52 AM				
Castillo, Carlos		As per Coach Dotson,the basketball timers in dressing rooms are not working properly.							
Carlos Castillo									
125577	Main Building	Exterior			11/14/2014		3		\$0.00
Medium	Work In Progress	flag pole			11/14/2014 2:51:00 PM	11/17/2014			
Castillo, Carlos		Flag pole pulleyis broken, will need bucket truck.							
Loraine Soriano									
126748	Main Building	Parking Lot			12/18/2014		53		\$0.00
Medium	Work In Progress	parking lot			12/18/2014 9:41:16 AM				
Mijarez, Jaime		Painting parking barriers to prevent accidents							
Loraine Soriano									
128400	Main Building	Parking Lot			2/3/2015		6		\$0.00
Medium	Work In Progress	Parking Lot			2/3/2015 11:04:36 AM				
Mijarez, Jaime		Work order placed last year for painting of parking lot for arrows etc..., for better flow of traffic.							
Loraine Soriano									
128380	GYM (2009)	Football Field			2/3/2015		6		\$0.00
Medium	Work In Progress	outside football			2/3/2015 8:16:52 AM				
Llanez, Rick		Wall on the outside of football field house needs to be painted the same as the other buildings. Also wall along football field needs painting.							
Loraine Soriano									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Santa Teresa HS**

128622 2/6/2015 3 3 \$0.00

Medium Work In Progress 2/6/2015 3:51:16 PM

Castillo, Carlos power is out on the side where the welding shop, wood shop, drafting area. Our technology equipment is down. Please check as soon

Cora Ramirez

128423 2/3/2015 6 3 \$0.00

Medium Work In Progress 2/3/2015 3:25:54 PM

Castillo, Carlos Crafts room by cafeteria stage. There is no lights working for drama class.

Jaime Mijarez

126510 Gymnasium Gym 12/11/2014 60 3 \$0.00

Medium Work In Progress auxillary gym 12/11/2014 9:09:48 AM

Castillo, Carlos Score board and control box not functioning properly missing buttons. Equipment old and in need of replacing.

Loraine Soriano

126710 GYM (2009) Gym 12/17/2014 54 3 \$0.00

Medium Work In Progress girls lockerroom 12/17/2014 12:21:52

Castillo, Carlos extra electrical outlets in locker needed for use

Loraine Soriano

120024 7/30/2014 194 3 \$0.00

Medium Work In Progress 7/30/2014 12:57:15 PM

Castillo, Carlos Grounds shop. Install electrical for new a/c installation.

Jaime Mijarez

127622 1/15/2015 25 3 \$0.00

Medium Work In Progress 1/15/2015 4:19:56 PM

Castillo, Carlos  
 Company: NM GAS CO- ANTHONY  
 Contact Name: ROB JUAREZ Contact Phone: (915)248-8731  
 Alternate Contact: RICHARD BORREGO  
 Alternate Phone: (505)697-5403  
 Email: robbyn.juarez@nmgco.com

Location of Work: FRM SUNLAND PARK N NM273  
 TRN W AIRPORT RD TO  
 ADDRESS ON N SIDE SPOT: FRONT OF PROPERTY  
 AREA MARKED IN WHITE

For details contact Richard Borrego 505-697-5403

Dominique Esparza

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
126364					12/8/2014		63		\$0.00
Medium	Work In Progress				12/8/2014 1:35:42 PM				
Castillo, Carlos		several exterior elec. outlets need to be repaired due to broken weather covers as per NMPSIA standard report.							
David Escobar									
127042	Main Building	Office			1/5/2015		35		\$0.00
Medium	Work In Progress	Counseling			1/5/2015 10:46:12 AM				
Escobar, David		Lights in need of replacing							
Loraine Soriano									
126670					12/16/2014		55		\$0.00
Medium	Work In Progress				12/16/2014 2:54:45 PM				
Ambriz, Jose		room 200 in main building has no heating . no hot water to coil.							
David Escobar									
119914					7/28/2014		196		\$0.00
Medium	Work In Progress				7/28/2014 1:21:02 PM				
Ambriz, Jose		Grounds shop. Please install a ductless heating and cooling in the grounds office/shop building.							
Jaime Mijarez									
128114	Main Building	Classroom			1/29/2015		11		\$0.00
Medium	Work In Progress	601			1/29/2015 3:51:50 PM				
Ambriz, Jose		Heater not working							
Loraine Soriano									
121992	Concession	Football Field			8/29/2014		164		\$0.00
Medium	Work In Progress	ticket booth			8/29/2014 3:40:04 PM				
Ambriz, Jose		Replace window unit due to coil issues							
Loraine Soriano									
128207					2/1/2015	2/17/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:49:49 AM				
Villalobos, Margret		Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.							
Margret Villalobos									
126834					1/4/2015	1/20/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:39:40 AM				
Villalobos, Margret		Monthly - Santa Teresa HS Monthly Chiller Insp. - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

121254 Cafeteria (2005) 8/15/2014 178 \$0.00

Medium Work In Progress 8/15/2014 10:49:31 AM

Mijarez, Jaime mens restroom in cafeteria urinal not enough water pressure

Isaac Holguin

127623 1/15/2015 25 \$0.00

Medium Work In Progress 1/15/2015 4:20:47 PM

Ontiveros, Joe  
 Company: NM GAS CO- ANTHONY  
 Contact Name: ROB JUAREZ Contact Phone: (915)248-8731  
 Alternate Contact: RICHARD BORREGO  
 Alternate Phone: (505)697-5403  
 Email: robbyn.juarez@nmgco.com

Location of Work: FRM SUNLAND PARK N NM273  
 TRN W AIRPORT RD TO  
 ADDRESS ON N SIDE SPOT:FRONT OF PROPERTY  
 AREAMARKED IN WHITE

For details contact Richard Borrego 505-697-5403

Dominique Esparza

125615 11/17/2014 84 \$0.00

Medium Work In Progress 11/17/2014 9:25:00 AM

Ontiveros, Joe Science Room 515 - Repair water and gas lines to lab tables - install new signs on Gas Shut Off Valve locations

Alfredo Holguin

125620 11/17/2014 84 \$0.00

Medium Work In Progress 11/17/2014 9:37:18 AM

Ontiveros, Joe Science Room 508 - Repair gas and water lines to lab tables and install new signs at locations of Gas Shut Off Valve.

Alfredo Holguin

125544 11/13/2014 88 \$0.00

Medium Work In Progress 11/13/2014 4:25:33 PM

Ontiveros, Joe Room 511 Order and access panel under sink to provide access to gas shut off.

Alfredo Holguin

125808 11/20/2014 81 \$0.00

Medium Work In Progress 11/20/2014 2:39:55 PM

Ontiveros, Joe need to replace 2 expansion tanks.

David Escobar

2/9/2015 1:38:25 PM

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

125681 11/18/2014 83 \$0.00

Medium Work In Progress 11/18/2014 2:29:47 PM

Ontiveros, Joe a 1" copper water pipe busted due to freezing on top of new gym. pipe is roughly 100' long and supplies water to 6 commercial AC units.

David Escobar

128203 2/1/2015 2/4/2015 8 \$0.00

Medium Work In Progress 2/1/2015 12:49:46 AM

Mijarez, Jaime Monthly - Santa Teresa HS - Emerg. Eyewash (Mthly) - Refer to PM schedule details.

Margret Villalobos

120184 Main Building Classroom 8/1/2014 192 \$0.00

Medium Work In Progress 610 8/1/2014 12:26:38 PM

Ontiveros, Joe Install new range in room 610

Loraine Soriano

128577 Main Building Classroom 2/6/2015 3 \$0.00

Medium Work In Progress 215 2/6/2015 9:54:47 AM

Ontiveros, Joe Kitchen sink is leaking

Loraine Soriano

125409 Annex Building Classroom 11/10/2014 91 \$0.00

Medium Work In Progress culinary 11/10/2014 4:25:12 PM

Ontiveros, Joe Dryer has not been hooked

Loraine Soriano

125410 Annex Building Classroom 11/10/2014 91 \$0.00

Medium Work In Progress culinary 11/10/2014 4:27:44 PM

Ontiveros, Joe The exhaust vent to the convection oven

Loraine Soriano

125545 Classroom 11/13/2014 88 \$0.00

Medium Work In Progress 11/13/2014 4:29:17 PM

Ontiveros, Joe Science Room 511 - Install new signs on Gas shut off access panels 2 ) to read "gas Shut Off Valve"

Alfredo Holguin

124173 Annex Building Classroom 10/15/2014 117 \$0.00

Medium Work In Progress culinary 10/15/2014 9:51:56 AM

Ontiveros, Joe Dryer not working

Loraine Soriano

2/9/2015 1:38:25 PM

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

124457	Gymnasium	Auditorium			10/22/2014		110		\$0.00
Medium	Work In Progress	gym girls			10/22/2014 12:33:01				
Ontiveros, Joe		sink leaking in girls restroom.							

Loraine Soriano

123303	Main Building	Classroom			9/26/2014		136		\$0.00
Medium	Work In Progress	215			9/26/2014 2:16:35 PM				
Ontiveros, Joe		Toilet malfunctioning							

Loraine Soriano

127480	Main Building	Classroom			1/13/2015		27		\$0.00
Medium	Work In Progress	215			1/13/2015 2:26:17 PM				
Ontiveros, Joe		Student shower needs a knob.							

Loraine Soriano

127270	Vocational	Classroom			1/8/2015		32		\$0.00
Medium	Work In Progress	801			1/8/2015 3:55:21 PM				
Ontiveros, Joe		Water leak, replace valves in water stations please see Jaime							

Loraine Soriano

126903					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:36 AM				
Villalobos, David		Yearly - Santa Teresa HS Backflow Inspection - Refer to PMs schedule details.							

Margret Villalobos

127812	Main Building	Computer Lab			1/22/2015		18		\$0.00
Medium	Work In Progress	C-4			1/22/2015 2:59:03 PM				
Estrada, Jesus		TILE NEEDS REPLACEMENT							

Loraine Soriano

128133	Main Building	Hallway/Corridor			1/30/2015		10		\$0.00
Medium	Work In Progress	in back of 200			1/30/2015 9:23:22 AM				
Estrada, Jesus		tile damaged in front of 200 and 300 wing in front of exiting. Please see Jaime for assistance							

Loraine Soriano

126974					1/4/2015	1/25/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:41:34 AM				
Munoz, Michael		Monthly - Santa Teresa HS Fire Sprinkler Insp. - Refer to PMs schedule details.							

Margret Villalobos



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Santa Teresa HS</b>							
126771	Main Building	Classroom			12/18/2014		53		\$0.00
Medium	Work In Progress	outside behind			12/18/2014 3:30:35 PM				
Munoz, Michael		tire ramps to have access to classroom for grocery drop off							
Loraine Soriano									
119584		Athletic Field			7/18/2014		206		\$0.00
Medium	Work In Progress				7/18/2014 1:44:53 PM				
Ontiveros, Guadalupe		JD tractor 3005 clutch needs to be replaced.							
Guadalupe Ontiveros									
119578		Athletic Field			7/18/2014		206		\$0.00
High	Work In Progress				7/18/2014 12:51:51 PM				
Ontiveros, Guadalupe		need to line locate along pinetrees.anysewer line and gas lines. any? rick will assit							
Guadalupe Ontiveros									
120628		Athletic Field			8/6/2014		187		\$0.00
Medium	Work In Progress	Shot put			8/6/2014 9:28:16 AM				
Ontiveros, Guadalupe		Fence surrounding shot put as none is there. Crucial for athlete safety. Please see Ms. Soriano or Ms. Noughes.							
Loraine Soriano									
128315					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:51:01 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
126365					12/8/2014		63		\$0.00
Medium	Work In Progress				12/8/2014 1:39:20 PM				
Ronquillo, Ruben		culinary arts kitchen needs a fire blanket with wall mount case and 1 Type "K" fire extinguisher as per NMPSIA report.							
David Escobar									
123304	Main Building	Classroom			9/26/2014		136		\$0.00
Medium	Work In Progress	215			9/26/2014 2:17:29 PM				
Mijarez, Jaime		Have mice in classroom							
Loraine Soriano									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Santa Teresa HS</b>							
127894	GYM (2009)				1/23/2015		17		\$0.00
Medium	Work In Progress				1/23/2015 4:14:15 PM				
Villalobos, Margret		need to have some look at the rat problem in the gym and need more glue traps				1/26/15 Emailed to waiver and wo			
Daniel Sotelo									
123084	Main Building	Classroom			9/23/2014		139		\$0.00
Medium	Work In Progress	Lab C-1			9/23/2014 3:16:04 PM				
Mijarez, Jaime		Cabinet door in computer lab office in broken.							
Loraine Soriano									
128254					2/1/2015	3/4/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:20 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Bleacher Inspection - Refer to PM schedule details.							
Margret Villalobos									
128255					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:21 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
128256					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:21 AM				
Mijarez, Jaime		Monthly - Santa Teresa HS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
124299	Annex Building	Classroom			10/17/2014		115		\$0.00
Medium	Work In Progress	culinary arts			10/17/2014 12:25:41				
Mijarez, Jaime		Lockers need to be moved to classroom as well as mounted if possible. Please see Ms. Perez for clarification.							
Loraine Soriano									
123220	Main Building	Library			9/25/2014		137		\$0.00
Medium	Work In Progress	library			9/25/2014 8:26:27 AM				
Mijarez, Jaime		Air conditioning in office needs to be looked at as it is not working							
Loraine Soriano									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Santa Teresa HS</b>							
122803	Cafeteria (2005)	Auditorium			9/15/2014		147		\$0.00
Medium	Work In Progress	Theater area			9/15/2014 4:14:10 PM				
Mijarez, Jaime		Workshop lights, restroom not working							
Loraine Soriano									
119430	Concession	Athletic Field			7/15/2014		209		\$0.00
Medium	Work In Progress				7/15/2014 11:48:16 AM				
Mijarez, Jaime		Holes in concession building near water fountain have exposed copper tubing							
Rosalinda Rodriguez									
126451	Gymnasium	Auditorium			12/10/2014		61		\$0.00
Medium	Work In Progress	Varsity gym			12/10/2014 9:23:31 AM				
Mijarez, Jaime		Locker room water fountain clogged							
Loraine Soriano									
126449	Vocational	Classroom			12/10/2014		61		\$0.00
Medium	Work In Progress	807			12/10/2014 9:20:47 AM				
Mijarez, Jaime		paper towel dispenser							
Loraine Soriano									
126450	Vocational	Classroom			12/10/2014		61		\$0.00
Medium	Work In Progress	807			12/10/2014 9:21:54 AM				
Mijarez, Jaime		paper towel dispenser near sink area							
Loraine Soriano									
128512	Main Building	Classroom			2/5/2015		4		\$0.00
Medium	Work In Progress	608			2/5/2015 9:43:04 AM				
Mijarez, Jaime		Heater blowing cold air							
Loraine Soriano									
120179	Main Building	Classroom			8/1/2014		192		\$0.00
Medium	Work In Progress	505			8/1/2014 11:56:03 AM				
Mijarez, Jaime		Replace pencil sharpner							
Loraine Soriano									
124455	Main Building	Classroom			10/22/2014		110		\$0.00
Medium	Work In Progress	314			10/22/2014 12:30:35				
Mijarez, Jaime		Map strips need center screws, Please refer to Ms. Thornly for further clarification							
Loraine Soriano									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
124301	Main Building	Classroom			10/17/2014		115		\$0.00
Medium	Work In Progress	209			10/17/2014 2:45:48 PM				
Mijarez, Jaime		Needs a safety goggle sanitation cabinet installed in classroom. There might be a possibility that an outlet maybe required for this cabinet. Please see Mrs. Nunez for further information and placement of cabinet.							
Loraine Soriano									
127813	Main Building	Classroom			1/22/2015		18		\$0.00
Medium	Work In Progress	211			1/22/2015 2:59:55 PM				
Mijarez, Jaime		Air conditioner does not turn off							
Loraine Soriano									
121267	Main Building	Classroom			8/15/2014		178		\$0.00
Medium	Work In Progress	608			8/15/2014 2:08:18 PM				
Mijarez, Jaime		Anchor cabinets							
Loraine Soriano									
121272	Main Building	Classroom			8/15/2014		178		\$0.00
Medium	Work In Progress	206			8/15/2014 2:15:43 PM				
Mijarez, Jaime		Remove old white board and old screen							
Loraine Soriano									
124096	Main Building	Office			10/13/2014		119		\$0.00
Medium	Work In Progress	Training room			10/13/2014 3:46:12 PM				
Mijarez, Jaime		Mr. Munoz needs assistance with some hooks please see mr. Munoz for further clarification							
Loraine Soriano									
120624	Gymnasium	Restroom			8/6/2014		187		\$0.00
Medium	Work In Progress	soccer locker			8/6/2014 9:19:21 AM				
Mijarez, Jaime		Missing toilet seat in one of the stalls							
Loraine Soriano									
128511	Locker Room	Restroom (Girls)			2/5/2015		4		\$0.00
Medium	Work In Progress	girls locker room			2/5/2015 9:41:59 AM				
Mijarez, Jaime		Water spilling over in sink							
Loraine Soriano									
128356		Office			2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 3:46:57 PM				
Gonzales, Camilo		Delive 10 bxs. PO# 141504312.							
Theresa Ramirez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
124074					10/13/2014		119		\$0.00
Medium	Work In Progress				10/13/2014 1:10:14 PM				
Gonzalez, Salvador		need a tamper cage for a window unit to be installed in ticket both . See BM2 for specs.							
David Escobar									
127644	Main Building	Athletic Field			1/16/2015		24		\$0.00
Medium	Work In Progress	Softball			1/16/2015 11:27:24 AM				
Gonzalez, Salvador		Batting cages for softball field please see Ms Contreras and Rick for futher guidance							
Loraine Soriano									
128000	Gymnasium	Roof			1/27/2015		13		\$0.00
Medium	Work In Progress				1/27/2015 3:30:20 PM				
Gonzalez, Salvador		Need 3 supports 16" high to set conduit on top of roof.							
Carlos Castillo									
127645	Main Building	Parking Lot			1/16/2015		24		\$0.00
Medium	Work In Progress	student parking			1/16/2015 11:30:59 AM				
Gonzalez, Salvador		Traffic control for after and before school see Rick for further assistance. There has been parental concerns with this issue and we need address the problem.							
Loraine Soriano									
128367		Office			2/2/2015		7		\$0.00
Medium	Work In Progress				2/2/2015 3:59:18 PM				
Gonzales, Camilo		Deliver 2 bxs. PO# 141504311.							
Theresa Ramirez									
128383		Office			2/3/2015		6		\$0.00
Medium	Work In Progress				2/3/2015 8:47:33 AM				
Gonzales, Camilo		Pick up 1 Gaylord and deliver to IMWHS							
Theresa Ramirez									
126520	Gymnasium	Gym			12/11/2014		60		\$0.00
Medium	Work In Progress	varsity gym			12/11/2014 11:18:02				
Lara, Ralph		Door handle is broken and needs to be replaced on doors facing hallway between varsity and auxiliary gym							
Loraine Soriano									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days	Labor	Total
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date	Aged	Hours	Costs
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

126446	AnnexBuilding	Classroom			12/10/2014		61		\$0.00
--------	---------------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	705			12/10/2014 9:14:03 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lara, Ralph  
Main door from outside, door handle is broken and makes it very difficult to lock and unlock door. Door falling off hinges

Loraine Soriano

126452	Gymnasium	Auditorium			12/10/2014		61		\$0.00
--------	-----------	------------	--	--	------------	--	----	--	--------

Medium	Work In Progress	varsity gym			12/10/2014 9:24:30 AM				
--------	------------------	-------------	--	--	-----------------------	--	--	--	--

Lara, Ralph  
Lobby doors to locker room latch loose

Loraine Soriano

126448	Vocational	Classroom			12/10/2014		61		\$0.00
--------	------------	-----------	--	--	------------	--	----	--	--------

Medium	Work In Progress	807			12/10/2014 9:17:50 AM				
--------	------------------	-----	--	--	-----------------------	--	--	--	--

Lara, Ralph  
large metal door will not shut or open when button is pushed

Loraine Soriano

124291	Main Building	Auditorium			10/17/2014		115		\$0.00
--------	---------------	------------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	Basketball			10/17/2014 11:31:42				
--------	------------------	------------	--	--	---------------------	--	--	--	--

Lara, Ralph  
Door is falling off hinges

Loraine Soriano

124298	Main Building	Classroom			10/17/2014		115		\$0.00
--------	---------------	-----------	--	--	------------	--	-----	--	--------

Medium	Work In Progress	215			10/17/2014 12:24:15				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Lara, Ralph  
Bathroom door and front classroom door do not stay open

Loraine Soriano

127419					1/12/2015		28		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/12/2015 3:25:10 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Gonzalez, Salvador  
the wire mesh to some goose neck has fallen off need to be replace with some expandable metal or new wire mesh need two at 37x38

Daniel Sotelo

128091					1/29/2015		11		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				1/29/2015 10:25:58 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Orozco, Daniel  
The technician from Ecolab came and checked dishwasher, He stated that the wash tank Gauge needs to be replaced is not working at all. SNP Manager Olga B. 589.5332

Maritza Gonzalez

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Santa Teresa HS</b>							
127169					1/7/2015		33		\$0.00
Medium	Work In Progress				1/7/2015 9:00:42 AM				
		DISHWASHER MAKING A LOUD NOISE. SNP MANAGER OLGA B. 589.5332							
Maritza Gonzalez									
<b>Count: 122 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>76</b>	<b>Total for Santa Teresa HS</b>			<b>0</b>	<b>\$0.00</b>

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa MS</b>									
128517					2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 10:28:03 AM				
Orozco, Daniel		OVEN (1) NOT HEATING PROPERLY. SNP MANAGER GESSICA M. 589.9836							
Maritza Gonzalez									
128565	South Building	Office			2/6/2015		3		\$0.00
Medium	Work In Progress	SECURITY			2/6/2015 8:29:57 AM				
Lara, Ralph		AS PER MR LARA- REMOVE AND REPLACE DOOR							
Laura Parra									
128404	North Building	Office			2/3/2015		6		\$0.00
Medium	Work In Progress	MS PARRA			2/3/2015 11:47:27 AM				
Gonzales, Camilo		DELIVER TONER AND MASTER ROLL TO MESQUITE ELEMENTARY- ATTENTION SANDRA MORA							
Laura Parra									
128382	North Building	Office			2/3/2015		6		\$0.00
Medium	Work In Progress	MS PARRA			2/3/2015 8:34:43 AM				
Gonzales, Camilo		PLEASE PICK UP TONER AND MASTER ROLL AND DELIVER TO NORTH VALLEY ELEMENTARY.							
Laura Parra									
128318					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:51:03 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
128031					1/28/2015		12		\$0.00
Medium	Work In Progress				1/28/2015 11:05:30 AM				
Lara, Ralph		OUTSIDE DOOR TO KITCHEN IS DIFFICULT TO OPEN. KEY IS GETTING STUCK, MANAGER IS AFRAID KEY WILL BREAK. SNP MANAGER GESSICA							
Maritza Gonzalez									
127544					1/14/2015		26		\$0.00
Medium	Work In Progress				1/14/2015 2:33:50 PM				
Lara, Ralph		As per Environment Dept. slight gap on bottom vertical edge of delivery door needs to be fixed. SNP Manager Gessica M. 589.9836							
Maritza Gonzalez									



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa MS</b>									
128139					1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 10:38:32 AM				
Lara, Ralph		Both Bldgs Girls Restrooms - Please check latches on stall doors, they do not align and not able to lock when in use.							
Richard Chavez									
126361	North Building	Office			12/8/2014		63		\$0.00
Medium	Work In Progress	MAIN			12/8/2014 12:53:00 PM				
Lara, Ralph		FRONT MAIN DOORS NEED TO BE REPLACED. FALLING OFF TOP HINGE AND AS PER MR. LARA UNABLE TO REPAIR.							
Laura Parra									
120039	South Building	Office			7/30/2014		194		\$0.00
Medium	Work In Progress	MEDINA-			7/30/2014 3:12:13 PM				
Lara, Ralph		REMOVE DOOR WITH FRAME AND RELOCATE TO THE SECURITY OFFICE. OFFICE NEEDS TO BE LOCKED WHEN ILLEGAL ITEMS HAVE BEEN CONFISCATED							
Laura Parra									
128029					1/28/2015		12		\$0.00
Medium	Work In Progress				1/28/2015 10:27:15 AM				
Carrasco, Danny		1/28/15. IM RUANING EMPTI NEED SOME GASOLINE FOR POLARIS.							
Manuel Prospero									
128145	North Building	Custodial			1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 11:10:47 AM				
Carrasco, Danny		Fuel for gas equipment.							
Ismael Rodriguez									
128033	North Building	Office			1/28/2015		12		\$0.00
Medium	Work In Progress	Frank Medina/			1/28/2015 11:29:53 AM				
Carrasco, Danny		FUEL FOR ADMIN/SECURITY GATORS							
Laura Parra									
125022					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:30 AM				
Orozco, Daniel		Monthly - Santa Teresa MS Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates:7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa MS</b>									
125794					11/20/2014		81		\$0.00
Medium	Work In Progress				11/20/2014 10:59:18				
Prospero, Manuel		Issued new Trane Laptop to Manuel Prospero.							
126904					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:36 AM				
Villalobos, David		Yearly - Santa Teresa MS Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
123993	North Building	Classroom			10/10/2014		122		\$0.00
Medium	Work In Progress				10/10/2014 11:16:43				
Ontiveros, Joe		Need to replace p-trap in RM #12							
Ismael Rodriguez									
128134	North Building	Classroom			1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 9:26:12 AM				
Ontiveros, Joe		As per teacher remove sink in classroom #7 north lower level.							
Ismael Rodriguez									
128150	North Building	Restroom			1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 12:03:55 PM				
Ontiveros, Joe		Theres a sewer back up in north office and cafeteria restroom need the plumber a.s.a.p.							
Ismael Rodriguez									
127311	Gym (1997)	Mechanical			1/9/2015		31		\$0.00
Medium	Work In Progress				1/9/2015 3:15:27 PM				
Ontiveros, Joe		1/9/15. WE NEED TO REPLACE WATER HEATER ON GYM , IS BROCK (96GALL).							
Manuel Prospero									
127627	North Building	Restroom			1/16/2015		24		\$0.00
Medium	Work In Progress				1/16/2015 7:50:24 AM				
Ontiveros, Joe		Theres water leaking from the toilet boys rest room North Building upper level and also theres a balast that needs to be replace no light.thanks.							
Ismael Rodriguez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location: Santa Teresa MS</b>									
128525	North Building	Cafeteria			2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 1:17:28 PM				
Ontiveros, Joe		Back up in cafeteria kitchen area water coming out the drain.							
Ismael Rodriguez									
126823					12/31/2014		40		\$0.00
Medium	Work In Progress				12/31/2014 12:47:29				
Prospero, Manuel		Yearly - Santa Teresa MS H6(Roof Furnace)(Yearly) - Refer to PM schedule details.							
Margret Villalobos									
124639	South Building	Mechanical			10/27/2014		105		\$0.00
Medium	Work In Progress				10/27/2014 3:30:16 PM				
Ambriz, Jose		10/27/14. A/C MECANICAL ROOM SOUH BUILDING IS NOT WORKING.							
Manuel Prospero									
119474	North Building	Office			7/16/2014		208		\$0.00
Medium	Work In Progress				7/16/2014 8:51:30 AM				
Ambriz, Jose		7/16/14. CUSTODIAN OFFICE A/C IS LOW PRESSON FREON.							
Manuel Prospero									
125241	Gym (1997)	Parking Lot			11/6/2014		95		\$0.00
Medium	Work In Progress				11/6/2014 3:08:50 PM				
Castillo, Carlos		OUTSIDE LIGHTS PARKING LOT GYM AREA DO NOT WORK.							
Manuel Prospero									
125242	North Building	Parking Lot			11/6/2014		95		\$0.00
Medium	Work In Progress				11/6/2014 3:11:37 PM				
Castillo, Carlos		LIGHTS AROUND BUILDING DO NOT WORK (NORTH BUILDING).							
Manuel Prospero									
125243		Parking Lot			11/6/2014		95		\$0.00
Medium	Work In Progress				11/6/2014 3:13:10 PM				
Castillo, Carlos		11/6/14. SOM LIGHTS PARKING LOT IS NOT WORKING.							
Manuel Prospero									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa MS</b>									
126178	South Building	Classroom			12/3/2014		68		\$0.00
Medium	Work In Progress	LIBRARY			12/3/2014 2:41:11 PM				
Castillo, Carlos		AN ELECTRICAL OUTLET IS NEEDED IN STORAGE ROOM FOR NEW ELECTRICAL BOX. ASK MS RUIZ FOR EXACT LOCATION.							
Laura Parra									
128140					1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 10:43:09 AM				
Prospero, Manuel		Both Bldgs Girls Restrooms - Please clean up or paint over graffiti.							
Richard Chavez									
127696	North Building	Office			1/20/2015		20		\$0.00
Medium	Work In Progress	8- Nurses Office			1/20/2015 10:56:02 AM				
Castillo, Carlos		Install light switch on the back entry door							
Laura Parra									
128078	North Building	Parking Lot			1/29/2015		11		\$0.00
Medium	Work In Progress				1/29/2015 8:23:12 AM				
Castillo, Carlos		Parking lights are not on the timer need to be check.							
Ismael Rodriguez									
128096	North Building	Parking Lot			1/29/2015		11		\$0.00
Medium	Work In Progress	Outdoor Area			1/29/2015 11:27:46 AM				
Castillo, Carlos		1- Reset timers to have lights on from 5am-9pm. 2- Need to replace lightbulbs- see Mr. Prospero for areas.							
Laura Parra									
120397	South Building	Office			8/4/2014		189		\$0.00
Medium	Work In Progress	MEDINA-			8/4/2014 9:05:29 AM				
Flores, Pete		GATOR NEEDS WORK DONE: CARB OVERHAUL, CHECK BRAKES, CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS)							
Laura Parra									
123870	North Building	Office			10/8/2014		124		\$0.00
Medium	Work In Progress	MR. POKLUDA			10/8/2014 11:40:04 AM				
Flores, Pete		GATOR NEEDS: CARB OVERHAUL- CHECK BRAKES - CHECK TRANSMISSION WHILE ENGAGING (DRIVE AND REVERSE GRINDS)							
Laura Parra									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Santa Teresa MS</b>							
128526	North Building	Office			2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 1:28:12 PM				
Lara, Ralph		Make a key for Ms. Cervantes conf. room.							
Ismael Rodriguez									
128505	North Building	Cafeteria			2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 7:52:36 AM				
Lara, Ralph		Replace the core in the boys rest room in cafeteria doesnt open..							
Ismael Rodriguez									
128571	North Building	Foyer			2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 8:53:31 AM				
Lara, Ralph		Main entrance doors North Bldg,north side from portables do not lock-not able to secure it.							
Ismael Rodriguez									
120010	North Building	Custodial			7/30/2014		194		\$0.00
Medium	Work In Progress				7/30/2014 7:35:01 AM				
Lara, Ralph		Rafa Mr.Mendoza needs replacements of keys his are not working well.							
Ismael Rodriguez									
128570	North Building	Office			2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 8:46:49 AM				
Lara, Ralph		Entry office doors do not lock.							
Ismael Rodriguez									
128261					2/1/2015	3/4/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:25 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Bleacher Inspection - Refer to PMschedule details.							
Margret Villalobos									
128262					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:25 AM				
Prospero, Manuel		Monthly - Santa Teresa MS -Clothes Dryer (Monthly) - Refer to PMschedule details.							
Margret Villalobos									
128263					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:26 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Exit Sign Insp: Monthly - Refer to PMschedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa MS</b>									
128264					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:27 AM				
Prospero, Manuel		Monthly - Santa Teresa MS Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									
120786	South Building	Hallway/Corridor			8/8/2014		185		\$0.00
Medium	Work In Progress	UPSTAIRS			8/8/2014 8:31:33 AM				
Prospero, Manuel		PLEASE REMOVE LOCKERS AND INSTALL IN P.E ( SEE MS SNYDER)							
Laura Parra									
122262	South Building	Classroom			9/3/2014		159		\$0.00
Medium	Work In Progress	55-WOLLARD			9/3/2014 3:35:43 PM				
Prospero, Manuel		AIR CONDITIONER IS EXTREMELY LOUD AND TILES ARE GETTING WET							
Laura Parra									
125158	South Building	Classroom			11/5/2014		96		\$0.00
Medium	Work In Progress	47-			11/5/2014 8:33:40 AM				
Prospero, Manuel		AIR CONDITIONER MAKING LOUD NOISES							
Laura Parra									
124448	North Building	Classroom			10/22/2014		110		\$0.00
Medium	Work In Progress	6-BAILEY			10/22/2014 10:51:27				
Prospero, Manuel		CEILING LEAKING.							
Laura Parra									
127693	North Building	Classroom			1/20/2015		20		\$0.00
Medium	Work In Progress	3-4 Portillo			1/20/2015 10:53:36 AM				
Prospero, Manuel		Exhaust fans do not function: 1- Storage room 2- Bathroom 3- Kitchen stove hood							
Laura Parra									
123945	North Building	Classroom			10/9/2014		123		\$0.00
Medium	Work In Progress	12-CRAVENS			10/9/2014 3:13:19 PM				
Prospero, Manuel		1- SINK PIPE IS LEAKING- RIGHT SINK 2- BRACKS NEED TO BE REMOVED WITH SCREWS FROM BACK WALL							
Laura Parra									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Santa Teresa MS</b>									
126528	North Building	Classroom			12/11/2014		60		\$0.00
Medium	Work In Progress	3-PORTILLO			12/11/2014 12:45:36				
Prospero, Manuel	1- EXHAUST FAN IN THE BATHROOM IS NOT WORKING PROPERLY. 2- EXHAUST FAN OVER THE STOVE IS NOT WORKING								
Laura Parra									
128500	North Building	Restroom (Girls)			2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 7:38:50 AM				
Prospero, Manuel	Replace balast in girls rest room north upper level no light								
Ismael Rodriguez									
126039	North Building	Kitchen			12/1/2014		70		\$0.00
High	Work In Progress				12/1/2014 11:12:42 AM				
Prospero, Manuel	Please remove toilet so floor can be tiled. Rodriguez upholstery should be there on December 2, 2014 at around 2:00 pm.								
Jesus Estrada									
124584	South Building	Hallway/Corridor			10/24/2014		108		\$0.00
Medium	Work In Progress	#44-ALLEN			10/24/2014 2:56:08 PM				
Prospero, Manuel	REMOVE LOCKERS. STUDENTS ARE PUTTING TRASH IN THEM								
Laura Parra									
122257	South Building	Hallway/Corridor			9/3/2014		159		\$0.00
Medium	Work In Progress	HALL WAY			9/3/2014 3:33:19 PM				
Prospero, Manuel	REMOVE LOCKERS FROM WALL OUTSIDE ROOM 44-45. SECOND REQUEST								
Laura Parra									
125952					11/30/2014		71		\$0.00
Medium	Work In Progress				11/30/2014 12:47:03				
Flores, Pete	Monthly - STM-UV-0518 PM Service - Refer to PM schedule details.								
Margret Villalobos									
125605					11/15/2014		86		\$0.00
Medium	Work In Progress				11/15/2014 12:45:34				
Flores, Pete	Yearly - Santa Teresa MS - Mower 0416 - Grounds - Refer to PM schedule details.								
Margret Villalobos									
<b>Count: 57 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>59</b>	<b>Total for Santa Teresa MS</b>		<b>0</b>	<b>\$0.00</b>	

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Sunland Park ES

124374 10/21/2014 111 \$0.00

Medium Work In Progress SCHOOL 10/21/2014 8:19:39 AM

Ronquillo, Ruben

CARLOS-

AS PER MR. VAN NOSDALE:  
IS THERE A WAY TO FIX THE SCHOOL'S  
MARQUEE? THERE IS A HOLE IN ONE OF THE  
PANELS WHICH MAKES IT LOOK REALLY BAD AND  
WE ARE NOT ABLE TO PUT FULL MESSAGES ON  
THE MARQUEE. PLEASE LET US KNOW IF THERE  
IS ANYTHING THAT CAN BE DONE. THANK YOU.

David Avila

127845 1/23/2015 17 \$0.00

Medium Work In Progress Front Main Gate 1/23/2015 11:09:20 AM

Lara, Ralph

OFFICE - NEEDS A EXTRA KEY FOR THE FRONT  
MAIN GATE

Maribel Chavez

128572 Classroom 2/6/2015 3 \$0.00

Medium Work In Progress COACHES 2/6/2015 9:01:46 AM

Castillo, Carlos

COACHES OFFICE- ANOTHER OUTLET FOR A NEW  
COMPUTER THERES ONE ALREADY BUT WE NEED  
ANOTHER ONE THERE WILL 2 NEW COMPUTERS IN  
THERE OFFICE

Maribel Chavez

127098 Main Building Classroom 1/6/2015 34 \$0.00

Medium Work In Progress 1/6/2015 8:05:49 AM

Gallegos, Rafael

Since yesterday monday 1-5-15 there have been a few  
rooms that seems like the heaters are not turning on at  
all carlos building mechanic for sunland park elementary  
has been out for the past days. thanks

Jesus Lucero

127268 1/8/2015 32 \$0.00

High Work In Progress 1/8/2015 3:52:21 PM

Ambriz, Jose

need to flush system to all hvac coils, flushing was not  
included on contract. thank you

Michael Munoz

123831 10/7/2014 125 \$0.00

Medium Work In Progress 10/7/2014 3:35:15 PM

Ambriz, Jose

a/c to portable a not cooling compressor not turning on

Carlos Hernandez



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
127906		Restroom (Girls)			1/26/2015		14		\$0.00
Medium	Work In Progress				1/26/2015 9:16:04 AM				
Ontiveros, Joe		GIRL RESTROOM- SINK BROKEN							
Maribel Chavez									
127626	Main Building	Restroom			1/16/2015		24		\$0.00
Medium	Work In Progress				1/16/2015 7:39:01 AM				
Ontiveros, Joe		the toilet in room 26 started to leak from the pipes and i had to close the valve if you could please cheack it out. thanks							
Jesus Lucero									
127234		Classroom			1/8/2015		32		\$0.00
Medium	Work In Progress	29			1/8/2015 12:00:34 PM				
Ontiveros, Joe		RM#29- RESENDIZ- SINK IS NOT DRAINING NORMALLY							
Maribel Chavez									
128540					2/5/2015		4		\$0.00
Medium	Work In Progress				2/5/2015 3:35:53 PM				
Ontiveros, Joe		need to remove sink in portable a							
Carlos Hernandez									
126029					12/1/2014		70		\$0.00
Medium	Work In Progress				12/1/2014 8:49:10 AM				
Ontiveros, Joe		need new drain kit for sink in nurses office							
Carlos Hernandez									
126902					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:35 AM				
Villalobos, David		Yearly - Sunland Park ES Backflow Inspection - Refer to PMs schedule details.							
Margret Villalobos									
127809		Classroom			1/22/2015		18		\$0.00
Medium	Work In Progress	LIBRARY			1/22/2015 1:26:00 PM				
Holguin, Alfredo		LIBRARY- NEED TO HAVE CEMENT COMPLETED ON THE SIDE WALK ON THE NORTH SIDE OF THE BUILDING RIGHT NEXT TO ROAD. (BOOK FAIR WILL ARRIVE FEB. 11,2015)							
Maribel Chavez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Sunland Park ES</b>									
125023					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress			11/2/2014 12:36:31 AM					
Orozco, Daniel	Monthly - Sunland Park ES Range Hood Cleaning - Refer to PM schedule details.								
Margret Villalobos									
128663	Main Building				2/9/2015		0		\$0.00
Medium	Work In Progress			2/9/2015 10:29:59 AM					
Carrasco, Danny	refill 5 gallons of gasoline for blower and pressure washer also 1 2cycle mix for blower mix thanks.								
Jesus Lucero									
123862	Main Building	Classroom			10/8/2014		124		\$0.00
Medium	Work In Progress			10/8/2014 10:05:34 AM					
Estrada, Jesus	the tile is lifting up and could become a safety problem this is in room 39.								
Jesus Lucero									
128376	Main Building	Gym			2/3/2015		6		\$0.00
Medium	Work In Progress			2/3/2015 7:35:25 AM					
Castillo, Carlos	requesting the scissor lift to clean the air conditioning ducting on top full of dust. If i could get it on the 21st of february and would be using it 22 and 23 no students on those days. thanks								
Jesus Lucero									
120344					8/3/2014		190		\$0.00
Medium	Work In Progress			8/3/2014 12:33:44 AM					
Munoz, Michael	Yearly - Sunland Park ES Fire Ext. Insp. (Yearly) - Refer to PM schedule details.		PM not completed as per schedule						
Margret Villalobos									
128304					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress			2/1/2015 12:50:53 AM					
Hernandez, Carlos	Monthly - Sunland Park ES Monthly FE Inspection - Refer to PM schedule details.								
Margret Villalobos									
120657					8/6/2014		187		\$0.00
Medium	Work In Progress			8/6/2014 1:56:14 PM					
Gallegos, Rafael	WALK IN REFRIGERATOR IS NOT COOLING. SNP MANAGER IGNACIA C. 589.2545								
Maritza Gonzalez									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
128631					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress				2/8/2015 12:29:17 AM				
Hernandez, Carlos		Monthly - Sunland Park ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
127545					1/14/2015		26		\$0.00
Medium	Work In Progress				1/14/2015 3:16:36 PM				
Carrasco, Danny		need these tools 6 in one screw driver 5/16 bit 8 ft fiberglass ladder channel locks							
Carlos Hernandez									
128402		Classroom			2/3/2015		6		\$0.00
Medium	Work In Progress	20B			2/3/2015 11:36:57 AM				
Hernandez, Carlos		RM#20B - ARMIJO- INSTALL A PENCIL SHARPENER IN HER CLASSROOM							
Maribel Chavez									
128591		Classroom			2/6/2015		3		\$0.00
Medium	Work In Progress	32			2/6/2015 11:56:37 AM				
Hernandez, Carlos		RM#32 ARAPI- NEED TO HAVE A HANDICAP BAR INSTALLED IN THERE BATHROOM							
Maribel Chavez									
128245					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:14 AM				
Hernandez, Carlos		Monthly - Sunland Park ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
128246					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:15 AM				
Hernandez, Carlos		Monthly - Sunland Park ES Emer Light Test: Monthly - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Sunland Park ES

122203					9/3/2014		159		\$0.00
Medium	Work In Progress	PLAYGROUND			9/3/2014 7:24:39 AM				
Hernandez, Carlos		CARLOS - PLEASE CHECK PLAYGROUND EQUIPMENT. THERE IS A WHITE RAIL THAT IS BROKEN AND IS DANGEROUS. THERE USED TO BE A SLIDE THERE, NOW THERE ARE HANGING PARTS. PLEASE SEE MS. DUQUE FOR FURTHER INSTRUCTIONS. THANK YOU.							

David Avila

123123					9/24/2014		138		\$0.00
Medium	Work In Progress	MS. CANO -			9/24/2014 7:21:37 AM				
Hernandez, Carlos		CARLOS - NEED TO HAVE SOMEONE COME CHECK MS. CANO'S PORTABLE. THERE ARE LEAKS THAT NEED TO BE ADDRESSED QUICKLY. THE PORTABLE IS HOUSING THE BOOKROOM AND LOT'S OF BOOKS WILL BE DAMAGED IF THE LEAKS CONTINUE. THANK YOU.							

David Avila

124503					10/23/2014		109		\$0.00
Medium	Work In Progress	CLASSROOM			10/23/2014 10:06:57				
Hernandez, Carlos		AS PER MS. CORDERO - PLEASE CHECK UNDERNEATH SINK - THERE IS A LEAK AND WATER IS SITTING AND NOW THERE ARE MOSQUITOES.							

David Avila

<b>Count: 29 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>55</b>		<b>Total for Sunland Park ES</b>	<b>0</b>		<b>\$0.00</b>
------------------------------	--	--	-------------------------	-----------	--	----------------------------------	----------	--	---------------

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunrise ES</b>									
128641					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress				2/8/2015 12:29:24 AM				
Vargas, Juan		Monthly - Sunrise ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									
128009					1/27/2015		13		\$0.00
Medium	Work In Progress				1/27/2015 3:43:20 PM				
Ontiveros, Guadalupe		need trimming all tress							
Juan Vargas									
121160	Main Building	Classroom			8/13/2014		180		\$0.00
Medium	Work In Progress	P-8			8/13/2014 4:23:28 PM				
Villalobos, Margaret		NILDA MATA, P-8, HAS LITTLE SPIDERS IN HER ROOM PLEASE SPRAY							
Joanne Munoz									
128293					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:46 AM				
Apodaca, Mario		Monthly - Sunrise ES - Lift Station Inspection - Refer to PM schedule details.							
Margret Villalobos									
128295					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:47 AM				
Vargas, Juan		Monthly - Sunrise ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
127253					1/8/2015		32		\$0.00
Medium	Work In Progress				1/8/2015 3:34:16 PM				
Estrada, Jesus		need replace floor tiles in hall out side rooms 310 and 212							
Juan Vargas									
128595					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 12:05:54 PM				
Estrada, Jesus		portables 6 and 8 need replacing floor tiles							
Juan Vargas									
125762					11/19/2014		82		\$0.00
Medium	Work In Progress				11/19/2014 3:14:55 PM				
Estrada, Jesus		need replace floor tiles in 100 work room							
Juan Vargas									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunrise ES</b>									
122989					9/19/2014		143		\$0.00
Medium	Work In Progress				9/19/2014 11:25:15 AM				
Estrada, Jesus		Library carpet has two runs in it south side and north side entrance. Also a pebble underneath a tile is breaking through by main desk.							
Jesus Estrada									
125024					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:32 AM				
Orozco, Daniel		Monthly - Sunrise ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
126900					1/4/2015	2/4/2015	36		\$0.00
Medium	Work In Progress				1/4/2015 12:40:33 AM				
Villalobos, David		Yearly - Sunrise ES Backflow Inspection - Refer to PM schedule details.							
Margret Villalobos									
124690					10/28/2014		104		\$0.00
Medium	Work In Progress				10/28/2014 3:28:58 PM				
Appelzoller, Fred		200 boy r.room need fix or replace sink foucet							
Juan Vargas									
120097					7/31/2014		193		\$0.00
Medium	Work In Progress				7/31/2014 12:37:15 PM				
Appelzoller, Fred		replasar llave pegada ala pared tiene lick in 200 wing							
Juan Vargas									
120182					8/1/2014		192		\$0.00
Medium	Work In Progress				8/1/2014 12:10:52 PM				
Appelzoller, Fred		need replace map sinck and fouset is broke							
Juan Vargas									
127919					1/26/2015		14		\$0.00
Medium	Work In Progress				1/26/2015 12:15:16 PM				
Solis, Lorenzo		need help to fix temperature in room 212							
Juan Vargas									
128559					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 7:46:50 AM				
Vallejo, Albert		need fix outside portables lights							
Juan Vargas									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WIOD	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: Sunrise ES</b>									
122835					9/16/2014		146		\$0.00
Medium	Work In Progress				9/16/2014 12:45:28 PM				
Vallejo, Albert	NEED REPLACE LIGHTS IN R.ROOMS								
Juan Vargas									
120861					8/8/2014		185		\$0.00
Medium	Work In Progress				8/8/2014 3:25:05 PM				
Ontiveros, Guadalupe	need fix o r replace relase valve in irrigation buster pump								
Juan Vargas									
125113					11/3/2014		98		\$0.00
Medium	Work In Progress				11/3/2014 3:48:14 PM				
Ontiveros, Guadalupe	need arena for 2 playgrounds 40 tons.								
Juan Vargas									
128557					2/6/2015		3		\$0.00
Medium	Work In Progress				2/6/2015 7:44:57 AM				
Vargas, Juan	need replacing units in kitchen and cafeteria								
Juan Vargas									
125570					11/14/2014		87		\$0.00
Medium	Work In Progress				11/14/2014 1:15:20 PM				
Vargas, Juan	need replace playground plastic borders north side								
Juan Vargas									
128138					1/30/2015		10		\$0.00
Medium	Work In Progress				1/30/2015 10:26:19 AM				
Vargas, Juan	need replace fourt hand dryers sensors								
Juan Vargas									
128230					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:04 AM				
Vargas, Juan	Monthly - Sunrise ES - Clothes Dryer (Monthly) - Refer to PMschedule details.								
Margret Villalobos									
128231					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:05 AM				
Vargas, Juan	Monthly - Sunrise ES Emer. Light Test: Monthly - Refer to PMschedule details.								
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
128232					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:06 AM				
Vargas, Juan		Monthly - Sunrise ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
<b>Count: 25 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>67</b>			<b>Total for Sunrise ES</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>



# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Vado ES**

119473 Main Building Office 7/16/2014 208 \$0.00

Medium Work In Progress 7/16/2014 8:36:17 AM

Munoz, Michael NEED TO REPLACE COUNTER TOP IN TEACHERS LOUNGE AND FRONT OFFICE. ASAP

Debra Facio

126156 12/3/2014 68 \$0.00

Medium Work In Progress 12/3/2014 9:09:44 AM

Munoz, Michael Bus Drop Off - there is a portion of the asphalt pavement that have failed.

Alfredo Holguin

128163 1/30/2015 10 \$0.00

Medium Work In Progress 1/30/2015 2:59:13 PM

Flores, Pete truck # 135 transmittion slipping bad, bad, bad!!!!

Danny Miranda

127522 Main Building Custodial 1/14/2015 26 \$0.00

Medium Work In Progress 1/14/2015 10:17:42 AM

Carbajal, Jimmy vacuum cleaner won't start 'elec' !

Armando Diaz

128403 Main Building Restroom 2/3/2015 6 \$0.00

Medium Work In Progress 2/3/2015 11:43:17 AM

Villalobos, David Need to replace toilet tank valve in the nurse's restroom asap THANK U !

Armando Diaz

128401 Main Building Hallway/Corridor 2/3/2015 6 \$0.00

Medium Work In Progress 2/3/2015 11:35:53 AM

Villalobos, David Need to replace toilet in the 200 wing 'teacher's restroom'.

Armando Diaz

126908 1/4/2015 2/4/2015 36 \$0.00

Medium Work In Progress 1/4/2015 12:40:39 AM

Villalobos, David Yearly - Vado ES Backflow Inspection - Refer to PM schedule details.

Margret Villalobos

128100 1/29/2015 11 \$0.00

Medium Work In Progress 1/29/2015 12:50:55 PM

Villalobos, David 200 Wing Boys RR - urinal is clogged

Danny Miranda

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

<b>Location:</b>		<b>Vado ES</b>							
125025					11/2/2014	11/23/2014	99		\$0.00
Medium	Work In Progress				11/2/2014 12:36:32 AM				
Orozco, Daniel		Monthly - Vado ES Range Hood Cleaning - Refer to PM schedule details.							
Margret Villalobos									
128297					2/1/2015	2/7/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:49 AM				
Miranda, Danny		Monthly - Vado ES Monthly FE Inspection - Refer to PM schedule details.							
Margret Villalobos									
128036					1/28/2015		12		\$0.00
Medium	Work In Progress				1/28/2015 12:37:24 PM				
Orozco, Daniel		REACH IN IS NOT COOLING. SNP MANAGER ELIZABETH M. 233.2945							
Maritza Gonzalez									
128037					1/28/2015		12		\$0.00
Medium	Work In Progress				1/28/2015 12:38:28 PM				
Orozco, Daniel		ICE MAKER NOT MAKING ICE. SNP MANAGER ELIZABETH M. 233.2945							
Maritza Gonzalez									
127039					1/5/2015		35		\$0.00
Medium	Work In Progress				1/5/2015 10:26:16 AM				
Orozco, Daniel		REGRIGERATOR DOWN. SNP MANAGER ELIZABETH MARRUFO 233.2945							
Maritza Gonzalez									
126444					12/10/2014		61		\$0.00
Medium	Work In Progress				12/10/2014 9:11:12 AM				
Orozco, Daniel		SINK - WHEN SHUT OFF WATER LEAKS.SNP MANAGER ELIZABETH M. 233.2945							
Maritza Gonzalez									
128633					2/8/2015	2/24/2015	1		\$0.00
Medium	Work In Progress				2/8/2015 12:29:18 AM				
Miranda, Danny		Monthly - Vado ES Playground Insp - Refer to PM schedule details.							
Margret Villalobos									

# 1077 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2014 - 6/30/2015 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Vado ES</b>									
127396					1/12/2015		28		\$0.00
Medium	Work In Progress				1/12/2015 11:20:45 AM				
Miranda, Danny		1/12/15	need to change air filters						
Danny Miranda									
128251					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:18 AM				
Miranda, Danny		Monthly - Vado ES Emer. Light Test: Monthly - Refer to PMs schedule details.							
Margret Villalobos									
128252					2/1/2015	2/9/2015	8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:19 AM				
Miranda, Danny		Monthly - Vado ES Exit Sign Insp: Monthly - Refer to PM schedule details.							
Margret Villalobos									
128253					2/1/2015		8		\$0.00
Medium	Work In Progress				2/1/2015 12:50:19 AM				
Miranda, Danny		Monthly - Vado ES - Clothes Dryer (Monthly) - Refer to PMs schedule details.							
Margret Villalobos									
<b>Count: 19 Work Orders</b>		<b>Avg. Age of WO's 34</b>				<b>Total for Vado ES</b>	<b>0</b>	<b>\$0.00</b>	
<b>Count: 1077 Work Orders</b>		<b>Avg. Age of WO's 62</b>				<b>Grand Total</b>	<b>2</b>	<b>\$50.00</b>	