

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Alta Vista ECHS</b>							
233356					7/15/2020		1	1	\$378.94
Medium	Work In Progress			7/15/2020 11:35:35 AM	7/16/2020				
Tellez, Hector	Replaced bulbs in girls restrooms and 2 fixtures did not work needs ballast		Light fixtures need to be replaced with modern fixtures. T-12 light bulbs are no longer ordered or carried by warehouse. Please forwarded to Electrician						
Maria Davila									
233847					7/28/2020		20		\$0.00
Medium	Work In Progress	12		7/28/2020 11:25:42 AM					
Marquez, Gerardo	Please create another name plate for S. Arevalo and affix to P12. Thank you!								
Melanie Beegle									
233863					7/28/2020		20		\$0.00
Medium	Work In Progress	11 & 13		7/28/2020 2:05:26 PM					
Marquez, Gerardo	Classroom doors for portables 11 & 13 are hard to close.								
Melanie Beegle									
234001					7/30/2020		18		\$0.00
Medium	Work In Progress	13		7/30/2020 9:14:16 AM					
Romero, Joaquin	Replace 3 pink colored blinds with white or cream colored blinds.		Ordered on 8-7-20						
Melanie Beegle									
<b>Count: 4 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>15</b>	<b>Total for Alta Vista ECHS</b>			<b>1</b>	<b>\$378.94</b>	

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Anthony - On Track Pre-K (Village)</b>							
233838		Exterior			7/28/2020		20		\$0.00
Medium	Work In Progress	prek courtyard			7/28/2020 10:44:57 AM				
Ontiveros, Guadalupe		Please have grounds come in & spray weed killer around our courtyard to eliminate the spread of weeds and thorns growing around the area.							
Michelle Soto									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>20</b>	<b>Total for Anthony - On Track Pre-K (Village)</b>				<b>0</b>	<b>\$0.00</b>

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
233082					7/7/2020		41		\$0.00
High	Work In Progress				7/7/2020 3:03:09 PM				
Ontiveros, Guadalupe		irrigation system needs to be rewire and replace control to be able to water soccer field.							
Guadalupe Ontiveros									
233568					7/22/2020		26		\$0.00
Medium	Work In Progress				7/22/2020 9:30:48 AM				
Escobar, David		Hvac unit 8 in room 224 is reading compressor low pressure Can Hvac go check it out Thank you							
Joaquin Romero									
233629					7/22/2020		26		\$49.78
Medium	Work In Progress				7/22/2020 3:45:31 PM				
Escobar, David		check RTUS at A.E.							
David Escobar									
233024					7/6/2020		42		\$653.62
Medium	Work In Progress				7/6/2020 2:45:49 PM				
Appelzoller, Fred		need Lav Faucets for restrooms							
Fred Appelzoller									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>34</b>			<b>Total for Anthony ES</b>	<b>0</b>	<b>\$703.40</b>

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Berino ES</b>									
233080					7/7/2020		41		\$0.00
Medium	Work In Progress				7/7/2020 2:36:10 PM				
Appelzoller, Fred		need Lav Faucets for restrooms							
Fred Appelzoller									
233067	Main Building	Office			7/7/2020		41		\$0.00
Medium	Work In Progress	Main Office			7/7/2020 1:12:09 PM				
Romero, Joaquin		Re-paint office							
Michelle Guerra									
233396					7/16/2020		32		\$587.94
Medium	Work In Progress				7/16/2020 2:56:13 PM				
Ambriz, Jose		The following classrooms are very hot: 131, 133, 110, 109, and 109A. Reported by Asst. Principal Hernandez							
233768	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	144			7/27/2020 1:57:16 PM				
Escobar, David		Classroom is hot							
Michelle Guerra									
233769	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	142			7/27/2020 1:57:58 PM				
Escobar, David		classroom is hot							
Michelle Guerra									
233770	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	140			7/27/2020 1:58:49 PM				
Escobar, David		classroom is hot							
Michelle Guerra									
233771	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	137			7/27/2020 2:00:06 PM				
Escobar, David		classroom is hot							
Michelle Guerra									
233772	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	113			7/27/2020 2:00:37 PM				
Escobar, David		classroom is hot							
Michelle Guerra									

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Berino ES</b>									
233773	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	114			7/27/2020 2:01:42 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233774	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	117			7/27/2020 2:02:30 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233775	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	116			7/27/2020 2:03:14 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233780	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	115			7/27/2020 2:16:40 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233781	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	128			7/27/2020 2:17:57 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233782	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	131			7/27/2020 2:18:51 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233783	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	133			7/27/2020 2:19:22 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233785	Main Building	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	133			7/27/2020 2:19:50 PM				
Escobar, David classroom is hot									
Michelle Guerra									

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Berino ES</b>										
233561					7/22/2020		26		\$50.50	
Medium	Work In Progress				7/22/2020 7:45:16 AM					
Escobar, David		trouble at room 109,109a, 110, 131, and 133.								
David Escobar										
233539					7/21/2020		27		\$0.00	
Medium	Work In Progress				7/21/2020 2:49:16 PM					
Marquez, Gerardo		LOCK SETS AT FACULTY RESTROOMS ARE LOOSE AND HARD TO OPEN. PLEASE FIX.								
Gerardo Marquez										
233171					7/9/2020		39		\$0.00	
Medium	Work In Progress				7/9/2020 3:49:17 PM					
Marquez, Gerardo		Need to rekey all exterior doors to main bldg, portables, pump house.								
Jessica Herrera										
233452	Main Building				7/20/2020		28		\$8.98	
Medium	Work In Progress	outside			7/20/2020 12:12:57 PM					
Ontiveros, Guadalupe		Requesting to cut down a dead tree see Mrs. Arnold for more details								
Michelle Guerra										
<b>Count: 20 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>25</b>	<b>Total for Berino ES</b>			<b>0</b>	<b>\$647.42</b>	

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
233827		Classroom			7/28/2020		20		\$0.00
Medium	Work In Progress	301			7/28/2020 9:20:51 AM				
Acuna, Johnny		hole in wall. Please fix see Barraza							
Jennifer Corral									
233873	Main Building	Office			7/28/2020		20		\$0.00
Medium	Work In Progress	office			7/28/2020 3:09:18 PM				
Acuna, Johnny		need mirror to be placed above my desk. See Ms. Davis							
Jennifer Corral									
233165	Main Building	Office			7/9/2020		39		\$0.00
Medium	Work In Progress	Vault and extra			7/9/2020 3:41:05 PM				
Marquez, Gerardo		Administration would like locks to be redone and keyed with different key for vault and extra utility room located in the front office. Please see Jennifer or Duque/Davis							
Jennifer Corral									
233905		Classroom			7/29/2020		19		\$0.00
Medium	Work In Progress	P-4			7/29/2020 9:49:52 AM				
Marquez, Gerardo		please check keys. Keys were given to I.A.'s and they do not work. Core number is the same as keys. I.A. stated the key does not open portable. See Medina and Pacheco							
Jennifer Corral									
233526	Main Building	Office			7/21/2020		27		\$0.00
Medium	Work In Progress	office			7/21/2020 1:13:12 PM				
Marquez, Gerardo		need room across from vault to have same key as vault (rekey) See front office.							
Jennifer Corral									
233517					7/21/2020		27		\$0.00
Medium	Work In Progress				7/21/2020 12:00:00 PM				
Ambriz, Jose		In Room 107 Tracer is showing an alarm FC-23 Supply Fan Failure. Please have HVAC take a look at this unit. Thank You							
Dominique Esparza									
233479		Classroom			7/20/2020		28		\$0.00
Medium	Work In Progress				7/20/2020 3:31:42 PM				
Ambriz, Jose		need to check units resetting.							
Jose Ambriz									

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
234130	Main Building	Classroom			7/31/2020		17		\$0.00
Medium	Work In Progress	207, 213			7/31/2020 5:56:38 PM				
Ambriz, Jose		Rm. 207 & 213 temp is quite warm. The temperature does not stay consistently cool.							
Angelica Duque									
233187		Mechanical			7/10/2020		38		\$0.00
Medium	Work In Progress				7/10/2020 2:04:45 PM				
Ambriz, Jose		Need to check chiller and booster pumps.							
Jose Ambriz									
233667		Kitchen			7/23/2020		25		\$0.00
High	Work In Progress				7/23/2020 2:11:23 PM				
Tellez, Hector		Door bell to back door still not functioning properly							
Dino Facio									
<b>Count: 10 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>26</b>	<b>Total for Chaparral ES</b>			<b>0</b>	<b>\$0.00</b>



## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To		Description							
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
233076	E-Wing	Classroom			7/7/2020		41		\$0.00
Medium	Work In Progress	E4			7/7/2020 2:00:39 PM				
Tellez, Hector		Please fix outlets. Only the one by the front of class works. All the others don't. This has been an on going problem in my room. This is not the first time I ask for them to be fixed. (Ms. Gonzalez, E4)							
Mireya Meza									
234031		Kitchen			7/30/2020		18		\$0.00
High	Work In Progress				7/30/2020 2:36:10 PM				
Ontiveros, Joe		Faucet to hand sink is leaking wont close completely							
Dino Facio									
233765	B-Wing	Classroom			7/27/2020		21		\$384.08
Medium	Work In Progress	B2			7/27/2020 1:41:19 PM				
Ambriz, Jose		Room B2 is very hot. Please fix. (Mr. Lugo, B2)							
Mireya Meza									
233764	G-Wing	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	G1			7/27/2020 1:39:12 PM				
Marquez, Gerardo		The lock in G1 sometimes does not work. Sometimes it opens just fine but other times it doesn't. Don't know if it's the core on the door or my key. (Ms. Montelongo, G1)							
Mireya Meza									
233943	B-Wing	Foyer			7/29/2020		19		\$0.00
Medium	Work In Progress	End of B wing			7/29/2020 2:28:04 PM				
Marquez, Gerardo		The door is out of balance and will not close unless slammed hard. The door will stick open. (custodian)							
Mireya Meza									
233569	A-Wing	Office			7/22/2020		26		\$0.00
Medium	Work In Progress	Counselor area			7/22/2020 9:33:59 AM				
Marquez, Gerardo		Please make me 2 copies of key CH21 & 1 of CH17. (Mireya Meza)							
Mireya Meza									
233807	C-Wing	Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	C5			7/27/2020 3:42:33 PM				
Marquez, Gerardo		We do not have a key to the wall cabinet in C5. Core is not showing key number. It is blank. Don't know what key to give to teacher. (Mireya Meza)							
Mireya Meza									

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
233275	G-Wing	Classroom			7/13/2020		35		\$0.00
Medium	Work In Progress	G1			7/13/2020 3:18:20 PM				
Marquez, Gerardo		Wall cabinet on the right side does not lock. (Ms. Montelongo, G1)							
Mireya Meza									
233504	A-Wing	Office			7/21/2020		27		\$0.00
Medium	Work In Progress	Mireya's office			7/21/2020 11:04:37 AM				
Marquez, Gerardo		Need copy of key to Mireya's office. (Victoria Lopez, principal)							
Mireya Meza									
233512	B-Wing	Classroom			7/21/2020		27		\$0.00
Medium	Work In Progress	B4			7/21/2020 11:40:34 AM				
Marquez, Gerardo		Please make me 2 copies of key CH37. (Mireya Meza)							
Mireya Meza									
233347	G-Wing	Classroom			7/15/2020		33		\$0.00
Medium	Work In Progress	G4			7/15/2020 10:23:27 AM				
Marquez, Gerardo		Lock on this door is hard to open and close. When you insert key it turns several times and key gets stuck. (Mireya Meza)							
Mireya Meza									
233348	F-Wing	Classroom			7/15/2020		33		\$0.00
Medium	Work In Progress	F5			7/15/2020 10:26:19 AM				
Marquez, Gerardo		We do not have a key number for wall cabinet in F5. The core is blank. We don't know if it works. (Mireya Meza)							
Mireya Meza									
234016	A-Wing	Classroom			7/30/2020		18		\$0.00
Medium	Work In Progress	Pre K			7/30/2020 12:22:44 PM				
Marquez, Gerardo		All outside doors by playground need to have key hole on door handles cleaned or replaced. My key will only open classroom 101 outer door. (custodian)							
Mireya Meza									
233734					7/24/2020		24		\$0.00
Medium	Work In Progress				7/27/2020 8:48:32 AM				
Flores, Pete		JD Gator # 0500 needs to be service.							
Guadalupe Ontiveros									

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location: Chaparral HS</b>									
233657	R-Wing	Classroom			7/23/2020		25		\$0.00
Medium	Work In Progress	R3			7/23/2020 11:57:48 AM				
Acuna, Johnny	Please move a bulletin board that is behind my desk to another wall in R3. I will mark the wall that I want it moved to in case I'm not in the room when you come in to move it. (Mr. Alvarado, R3)								
Mireya Meza									
233659	R-Wing	Classroom			7/23/2020		25		\$0.00
Medium	Work In Progress	R3			7/23/2020 12:01:18 PM				
Acuna, Johnny	Please switch the art panel display from Q2 to R3 with the Smart Board in R3 storage room. The Smart Board in storage room no longer works. (Mr. Alvarado, R3)		8/10/20 as per Jessie (HC) , he needs smart boards moved from wall to wall and walls painted afterwards. asp Jimmy, route to maintenance.						
Mireya Meza									
233093					7/7/2020		41		\$39.80
Medium	Work In Progress	AUX. GYM			7/7/2020 5:19:51 PM				
Acuna, Johnny	Need (8) Emergency light batteries for New Aux. Gym. (Hubbell: Part #93012372)								
Johnny Acuna									
233107					7/8/2020		40		\$0.00
Medium	Work In Progress				7/8/2020 10:15:04 AM				
Ontiveros, Joe	check water faucets in all restroom sinks alot of them are loose.								
Jesus Urquidi									
<b>Count: 18 Work Orders</b>		<b>Avg. Age of WO's 28</b>		<b>Total for Chaparral HS</b>				<b>0</b>	<b>\$423.88</b>

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Chaparral MS</b>										
233840	Main Building	Classroom			7/28/2020		20		\$0.00	
Medium	Work In Progress	450			7/28/2020 11:00:08 AM					
Acuna, Johnny		Wooden locker doors have fallen off and need help fixing them back on. Teacher has all wooden pieces for those that fell off.								
Maria Garcia										
233990	Main Building	Cafeteria			7/30/2020		18		\$0.00	
Medium	Work In Progress	boys 100			7/30/2020 8:19:51 AM					
Acuna, Johnny		wall needs to be repaired in boys restroom 100 hall there is a hole next to soap dispenser.								
Maria Garcia										
233991	Main Building	Parking Lot			7/30/2020		18		\$0.00	
Medium	Work In Progress	gate			7/30/2020 8:21:57 AM					
Acuna, Johnny		wheel on bus turn around (exit gate) gate does not turn.								
Maria Garcia										
233344	Main Building	Classroom			7/15/2020		33		\$0.00	
Medium	Work In Progress	102			7/15/2020 9:04:07 AM					
Marquez, Gerardo		Door will not open								
Maria Garcia										
<b>Count: 4 Work Orders</b>		<b>Avg. Age of WO's 22</b>		<b>Total for Chaparral MS</b>				<b>0</b>	<b>\$0.00</b>	

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Desert Pride HS</b>							
233867		Classroom			7/28/2020		20		\$7.80
Medium	Work In Progress	room 114			7/28/2020 2:19:18 PM				
Escobar, David		Room is very hot, was not able to be adjusted by the system.							
Maria Carbajal									
233793		Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	Room 102			7/27/2020 2:48:43 PM				
Escobar, David		For room 102, the Tempure is 80.2° a 6.3° variance, but there are no alarms and the unit does not need to be released.							
Maria Carbajal									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>21</b>			<b>Total for Desert Pride HS</b>	<b>0</b>		<b>\$7.80</b>

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Trail ES</b>									
233352					7/15/2020		33		\$0.00
Medium	Work In Progress				7/15/2020 10:37:32 AM				
Tellez, Hector		Flashers between Desert Trail and continuing to Chaparral Middle need bulbs some replaced. Please check on all flashers and replace blubs as needed. Thank You							
Dominique Esparza									
234106	Main Building	Office			7/31/2020		17		\$0.00
Medium	Work In Progress	front office			7/31/2020 2:48:55 PM				
Marquez, Gerardo		Secretary office door is hard to unlock and lock.							
Elizabeth Hernandez									
233009		Custodial			7/6/2020		42		\$0.00
Medium	Work In Progress				7/6/2020 11:30:33 AM				
,		WALK IN GATE AT BUS TURN AROUND NEEDS TO BE FIXED.							
Laura Sandoval									
<b>Count: 3 Work Orders</b>		<b>Avg. Age of WO's 31</b>			<b>Total for Desert Trail ES</b>			<b>0</b>	<b>\$0.00</b>

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: GAC</b>									
233674					7/23/2020		25		\$0.00
Medium	Work In Progress	SUPERINTEND			7/23/2020 3:08:48 PM				
Hernandez, Javier	CEILING LEAK.								
Abby Oliva									
233395		Classroom			7/16/2020		32		\$0.00
Medium	Work In Progress				7/16/2020 2:17:20 PM				
Lara, Ralph	door marker frame needs alignment door has gap not closing correctly								
Javier Hernandez									
233698					7/24/2020		24		\$0.00
Medium	Work In Progress				7/24/2020 8:59:08 AM				
Lara, Ralph	Re-key a table with a cabinet. When Rafa or his co-worker come by to check the cabinet, please have them see me so I can show them where it is. Thank you.								
Anne De Los Santos									
233705					7/24/2020		24		\$0.00
Medium	Work In Progress				7/24/2020 10:33:58 AM				
Lara, Ralph	These are the techs who still need a SNP key:  Riverside ES, Desert View ES: Frank Balderama Yucca Heights, Sunrise, Chaparral ES: Robert Vasquez STMS: Adam Montoya CMS: Eric Pigram GHS: Josua Moe  approved by Maria Guerra								
Cora Ramirez									
233366		Office			7/15/2020		33		\$0.00
Medium	Work In Progress				7/15/2020 1:48:43 PM				
Hernandez, Javier	Remove wall shelves/files from hallway and install in the closet located in room 314. Thank you.								
Anne De Los Santos									
234029		Office			7/30/2020		18		\$9.98
Medium	Work In Progress	C-WING			7/30/2020 2:32:40 PM				
Sotelo, Daniel	PLEASE SECURELY COVER PANEL AND AREA UNDER AC. CRITTERS (LIZARDS & MICE) ARE COMING IN THROUGH THAT OPENING. CONTACT KARLA EXT. 6282 OR YOLANDA (CUSTODIAN). THANK YOU!								
Karla Quesada									
<b>Count: 6 Work Orders</b>	<b>Avg. Age of WO's 26</b>			<b>Total for GAC</b>			<b>0</b>	<b>\$9.98</b>	

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC - Pre-K</b>							
233675					7/23/2020		25		\$0.00
Medium	Work In Progress	101, 102, 103,			7/23/2020 3:14:57 PM				
Lara, Ralph		Please change key to all classrooms so that one key opens both doors in each classroom. Room 101 needs 3 doors re-keyed so that it opens with the same key.							
		Thank you!							
		Micaela Paniagua							
Micaela Paniagua									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>25</b>			<b>Total for GAC - Pre-K</b>	<b>0</b>		<b>\$0.00</b>



# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden ES</b>									
233742		Classroom			7/27/2020		21		\$0.00
Medium	Work In Progress	208			7/27/2020 9:50:09 AM				
Escobar, David		Air conditioner in Room 208 is not working at GES classroom is very hot. Your help in this matter is greatly appreciated.							
Patty Madrid									
233910		Classroom			7/29/2020		19		\$0.00
Medium	Work In Progress	101,			7/29/2020 10:41:45 AM				
Escobar, David		Room 101 Maintenance Required Room 208 High & Low pressure control Room 210 Maintenance Required Room 205 Fan not working							
Patty Madrid									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>20</b>		<b>Total for Gadsden ES</b>	<b>0</b>		<b>\$0.00</b>

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
234122					7/31/2020		17		\$0.00
Medium	Work In Progress				7/31/2020 4:04:55 PM				
Tellez, Hector		Requested by Chef Anthony Sapien Rm. 515/517 CTE Building-Replace silver receptacles outlets located in the kitchen with purchases Electrical Rooftop Cord Reels (total of 3). FOR FURTHER INFORMATION OR INSTRUCTION PLEASE CHEF SAPIEN. HE HAS CHOSEN THE OPTION OF ONLY BEING ON THE SCHOOL CAMPUS ON MONDAYS AND TUESDAY, PLEASE SEE HIM THEN.							
Velia Alarcon									
234127					7/31/2020		17		\$0.00
Medium	Work In Progress				7/31/2020 4:13:19 PM				
Tellez, Hector		Requested by Chef Anthony Sapien Rm. 515/517 CTE Building-Installation of electrical cord coverings for the t.v. in the Panther Hut Cafe. FOR FURTHER INFORMATION OR INSTRUCTION PLEASE CHEF SAPIEN. HE HAS CHOSEN THE OPTION OF ONLY BEING ON THE SCHOOL CAMPUS ON MONDAYS AND TUESDAY, PLEASE SEE HIM THEN.							
Velia Alarcon									
233633					7/22/2020		26		\$0.00
Medium	Work In Progress				7/22/2020 3:48:51 PM				
Romero, Joaquin		Requested by the G.H.S. Admin. Team-Painting of all handicap markings in all parking lots need to be redone or touched up.							
Velia Alarcon									
233627					7/22/2020		26		\$0.00
Medium	Work In Progress				7/22/2020 3:43:59 PM				
Romero, Joaquin		Requested by the G.H.S. Admin. Team-Railings in front of the Weight Room need to be re-painted.							
Velia Alarcon									
233589	Library				7/22/2020		26		\$0.00
Medium	Work In Progress				7/22/2020 2:04:52 PM				
Romero, Joaquin		Requested by the G.H.S. Admin. Team for Library-The frames on the south side of the Library Building need to be painted.							
Velia Alarcon									

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

233599					7/22/2020		26		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/22/2020 2:37:11 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Romero, Joaquin Requested by the G.H.S. Admin. Team-The fence that is blocking off access to the court yard needs to be painted.

Velia Alarcon

234025	Varsity Gym				7/30/2020		18		\$532.79
--------	-------------	--	--	--	-----------	--	----	--	----------

Medium	Work In Progress				7/30/2020 1:34:25 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Romero, Joaquin Requesting all four locker rooms in Varsity Gym be painted

Liliana Acosta

233257					7/13/2020		35		\$190.00
--------	--	--	--	--	-----------	--	----	--	----------

High	Work In Progress				7/13/2020 9:43:05 AM				
------	------------------	--	--	--	----------------------	--	--	--	--

Castillo, Carlos Communication with system has been lost again.

Our Control-Link® monitoring process has sent out notification that it currently cannot communicate with a Control-Link® control and monitoring system at one of your facilities:

Facility:  
Gadsden High School

Fields:  
Baseball  
Softball

This issue could be related to a power outage due to a storm, breaker shut off due to construction or maintenance, or the system may just need to be reset. Troubleshooting is a simple process in which we provide detailed instructions over the phone and should take less than 10 minutes. Please designate someone from your facility to call us while they are within physical access to the Control-Link® control and monitoring cabinet to troubleshoot this issue. Please ensure that you also have a switch key available to test the lights manually, if needed.

Our technicians are available from 8am to 5pm Central Time Monday through Friday to assist you, please call us toll free at 877/347-3319 and ask to speak with Mason Hoffman or an available technician.

Ref:  
Communication for Call Report # 388148  
Facility #: 21807 Call Report #: 388148

Dominique Esparza

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden HS

233845 Academic Bldg 7/28/2020 20 \$0.00

Medium Work In Progress 7/28/2020 11:22:50 AM

Castillo, Carlos 2 light fixtures in hallways Balast out in both. first light fixture outside classroom 330 the other by room 322

Liliana Acosta

233803 7/27/2020 21 \$0.00

Medium Work In Progress 7/27/2020 3:24:43 PM

Lara, Ralph Requested by Mr. David Martinez for New Panther Gym/Boys Gym-We are requesting for sets of keys to be made for each Athletic Office in the Panther Gym (formally named Boys Gym). Each Head Coach will need access to the Panther Gym Building, their Office, and the Locker Rooms for their sport and also Storage Closets. The Athletic Programs in the Panther Gym are listed below:  
 1. Athletic Trainer's Office  
 2. Baseball  
 3. Boys Soccer Office  
 4. Boys Track Office  
 5. Football  
 6. Girls Soccer Office  
 7. Girls Track Office  
 8. P.E. Locker rooms  
 9. Softball  
 For further instruction please see Mr. David Martinez

Velia Alarcon

234120 7/31/2020 17 \$0.00

Medium Work In Progress 7/31/2020 4:00:37 PM

Lara, Ralph Requested by Mr. David Martinez for Storage Room in the Varsity Gym-Replace the door knob/cylinder at the storage closet on the right side of the stage area. This storage will be used for G.H.S. Girl's Basketball.

Velia Alarcon

233493 7/21/2020 27 \$0.00

Medium Work In Progress 7/21/2020 9:10:58 AM

Lara, Ralph Requested by Frank Marin for Rm. 504 CTE Building-Bay door is not working and needs to be re-set, bay door does not go up.

Velia Alarcon

233252 7/13/2020 35 \$0.00

Medium Work In Progress 7/13/2020 8:05:02 AM

Lara, Ralph The boys gym is going to get the gym floor re-done and need to change the locks so no one may enter except the the company that is doing the gym floor.

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
233068					7/7/2020		41		\$0.00
Medium	Work In Progress				7/7/2020 1:19:34 PM				
Lara, Ralph		Requested by Mrs. Danielle Rodriguez Rm. 714 Admin. Building-Top hinge in her office needs to be fixed. The door is suppose to stay open when pushed, but does not stay open.							
Velia Alarcon									
233066					7/7/2020		41		\$0.00
Medium	Work In Progress				7/7/2020 1:06:50 PM				
Lara, Ralph		Requested by Mrs. Danielle Rodriguez Rm. 713 Admin. Building-Office door is stuck and will not open, needs to be fixed.							
Velia Alarcon									
233434					7/20/2020		28		\$0.00
Medium	Work In Progress				7/20/2020 7:43:03 AM				
Villalobos, Jose		Headger HS 45 will not start.							
Guadalupe Ontiveros									
233070					7/7/2020		41		\$0.00
Medium	Work In Progress				7/7/2020 1:24:36 PM				
Ontiveros, Guadalupe		Requested by Mrs. Danielle Rodriguez for Landscape Outside of the Science Building on the South Side-Rock needs to be added to the landscape outside of the Science Building on the south side.							
Velia Alarcon									
233071					7/7/2020		41		\$0.00
Medium	Work In Progress				7/7/2020 1:26:06 PM				
Ontiveros, Guadalupe		Requested by Mrs. Danielle Rodriguez Landscape Outside of the Cafeteria-Rock needs to be added to the landscape outside of the Cafeteria.							
Velia Alarcon									
233073					7/7/2020		41		\$0.00
Medium	Work In Progress				7/7/2020 1:27:50 PM				
Ontiveros, Guadalupe		Requested by Mrs. Danielle Rodriguez Trees Outside of Cafeteria-Trees need to be trimmed in front of the cafeteria.							
Velia Alarcon									

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden HS

233600 7/22/2020 26 \$0.00

Medium Work In Progress 7/22/2020 2:40:05 PM

Ontiveros, Guadalupe Requested by the G.H.S. Admin. Team-Rocks needs to be filled on the north side of the Theater Building.

Velia Alarcon

233602 7/22/2020 26 \$0.00

Medium Work In Progress 7/22/2020 2:42:23 PM

Ontiveros, Guadalupe Requested by the G.H.S. Admin. Team-Rock needs to be filled on the south side of the North Building between the North Building and Theater.

Velia Alarcon

233603 7/22/2020 26 \$0.00

Medium Work In Progress 7/22/2020 2:44:14 PM

Ontiveros, Guadalupe Requested by the G.H.S. Admin. Team-Sweep rocks off the sidewalk on the north side of the North Building by ROTC.

Velia Alarcon

233605 7/22/2020 26 \$0.00

Medium Work In Progress 7/22/2020 2:47:03 PM

Ontiveros, Guadalupe Requested by the G.H.S. Admin. Team-Rock needs to be filled outside of the Academic Building on the north side.

Velia Alarcon

233607 7/22/2020 26 \$0.00

Medium Work In Progress 7/22/2020 2:56:28 PM

Ontiveros, Guadalupe Requested by the G.H.S. Admin. Team-Weeds need to be pulled in between the portables.

Velia Alarcon

233616 7/22/2020 26 \$0.00

Medium Work In Progress 7/22/2020 3:28:40 PM

Ontiveros, Guadalupe Requested by the G.H.S. Admin. Team-Trim tree outside of Mr. Mora's (Athletic Training Room) by the Panther Gym.

Velia Alarcon

233622 7/22/2020 26 \$0.00

Medium Work In Progress 7/22/2020 3:39:17 PM

Ontiveros, Guadalupe Requested by the G.H.S. Admin. Team-Rocks need to be filled on the north side of the Weight Room.

Velia Alarcon

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Gadsden HS

233590	Cafeteria (1998)				7/22/2020		26		\$0.00
--------	------------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/22/2020 2:06:53 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by the G.H.S. Admin. Team-Leaves in front of the Cafeteria and on the rocks need to be swept up and picked up.

Velia Alarcon

233598					7/22/2020		26		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/22/2020 2:25:33 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Ontiveros, Guadalupe Requested by the G.H.S. Admin. Team-The weeds inside the courtyard of the Old Main Building need to be pulled/cleaned up.

Velia Alarcon

233708					7/24/2020		24		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/24/2020 11:09:30 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by the Admin. Team-Three keys are need to open the storage room # 208S in the North Building.

Velia Alarcon

233709					7/24/2020		24		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/24/2020 11:12:41 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Lara, Ralph Requested by the Admin. Team-The door to the new Football Office cannot be opened with the Head Coach or Custodian Frank Marin's keys, door needs to be looked at and repaired. Six new keys will be needed.

Velia Alarcon

233628					7/22/2020		26		\$112.00
--------	--	--	--	--	-----------	--	----	--	----------

Medium	Work In Progress				7/22/2020 3:44:59 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Romero, Joaquin Requested by the G.H.S. Admin. Team-Signs outside of the Restrooms and outside of the Concession Stand need to re replaced. Ordered signs on 7-28-20

Velia Alarcon

234123					7/31/2020		17		\$0.00
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/31/2020 4:07:11 PM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Romero, Joaquin Requested by Chef Anthony Sapien Rm. 515/517 CTE Building-Instalation of new stove equipment and bread proofer located at the warehouse storage and will need to be installed in the Panther Hut Cafe at G.H.S. FOR FURTHER INFORMATION OR INSTRUCTION PLEASE CHEF SAPIEN. HE HAS CHOSEN THE OPTION OF ONLY BEING ON THE SCHOOL CAMPUS ON MONDAYS AND TUESDAY, PLEASE SEE HIM THEN.

Velia Alarcon

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
234124					7/31/2020		17		\$0.00
Medium	Work In Progress				7/31/2020 4:09:50 PM				
Romero, Joaquin		Requested by Chef Anthony Sapien Rm. 515/517 CTE Building-Relocate tea brewing machine in the Panther Hut Cafe from the dinning room area to the kitchen area. FOR FURTHER INFORMATION OR INSTRUCTION PLEASE CHEF SAPIEN. HE HAS CHOSEN THE OPTION OF ONLY BEING ON THE SCHOOL CAMPUS ON MONDAYS AND TUESDAY, PLEASE SEE HIM THEN.							
Velia Alarcon									
234126					7/31/2020		17		\$0.00
Medium	Work In Progress				7/31/2020 4:11:42 PM				
Romero, Joaquin		Requested by Chef Anthony Sapien Rm. 515/517 CTE Building-Preventative maintenance work on all refrigerator, freezer, and ice machine units. FOR FURTHER INFORMATION OR INSTRUCTION PLEASE CHEF SAPIEN. HE HAS CHOSEN THE OPTION OF ONLY BEING ON THE SCHOOL CAMPUS ON MONDAYS AND TUESDAY, PLEASE SEE HIM THEN.							
Velia Alarcon									
233630					7/22/2020		26		\$0.00
Medium	Work In Progress				7/22/2020 3:45:44 PM				
Romero, Joaquin		Requested by the G.H.S. Admin. Team-Please repair the damage on the Tennis Booth.							
Velia Alarcon									
<b>Count: 35 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>27</b>	<b>Total for Gadsden HS</b>			<b>0</b>	<b>\$834.79</b>



# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
233184					7/10/2020		38		\$0.00
Medium	Work In Progress	Mrs. Quinonez			7/10/2020 1:29:55 PM				
Villalobos, Jose		Please fix Pallet Jack, we need it. Its not working, leaking hydraulic oil. Thank you Mrs. Quinonez				Please forward to Joe - J. Romero 8/4/20			
Hilda Adler									
233578	Vocational	Classroom			7/22/2020		26		\$0.00
Medium	Work In Progress	RM#306/Drama/			7/22/2020 11:08:41 AM				
Marquez, Gerardo		Please fix lock on door, does not lock.							
Hilda Adler									
233354		Office			7/15/2020		33		\$32.48
Medium	Work In Progress	Admin Offices /			7/15/2020 11:15:35 AM				
Escobar, David		Air conditioners are not working in Mrs. Quinonez, Mr. Mora, Mrs. Mejia and Terrys Office. Please fix asap. Thank you Mr. Mora				7/21/20 - Issued #1 / 1464-227 portable cooler - D. Escobar			
Hilda Adler									
233006					7/6/2020		42		\$0.00
Medium	Work In Progress	Garden by			7/6/2020 10:41:01 AM				
Ontiveros, Guadalupe		Please remove weeds from garden ground as per Mrs. Quinonez. Thank you							
Hilda Adler									
234013		Restroom			7/30/2020		18		\$0.00
Medium	Work In Progress	A-Wing Mens			7/30/2020 11:24:47 AM				
Appelzoller, Fred		The water stays running in 2 sinks in the mens staff restroom in Awing. Have to bang on it til the flow stops. As per Chris Uribe							
Hilda Adler									
233820					7/28/2020		20		\$0.00
Medium	Work In Progress				7/28/2020 7:52:40 AM				
Escobar, David		a/c unit in room 115 has a crack in the condensation pan and is leaking. Need to order a new tray. Temporary fix with mp1 on 7-24-20 Thank you							
Joaquin Romero									
233756	Annex				7/27/2020		21		\$0.00
Medium	Work In Progress	Old Annex / Mrs.			7/27/2020 12:04:57 PM				
Escobar, David		Air Conditioners are not working in the old Annex (Rm 413)Classrooms are very hot.							
Hilda Adler									
<b>Count: 7 Work Orders</b>			<b>Avg. Age of WO's 28</b>			<b>Total for Gadsden MS</b>	<b>0</b>		<b>\$32.48</b>

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: La Union ES</b>									
233852	Main Building				7/28/2020		20		\$0.00
Medium	Work In Progress	STAFF			7/28/2020 12:29:05 PM				
Ambriz, Jose		JOANNE MUNOZ, FRONT OFFICE, THE EXHAUST FAN IN THE WOMEN'S STAFF RESTROOM BY THE OFFICE IS NOT WORKING NEEDS TO BE REPLACED.							
Joanne Munoz									
233744					7/27/2020		21		\$121.10
Medium	Work In Progress				7/27/2020 10:06:13 AM				
Pacheco, Hector		The sink faucets have to be replaced in the lower grade staff lounge.							
Guadalupe Parada									
233661	2000 Core	Office			7/23/2020		25		\$0.00
Medium	Work In Progress	MR.			7/23/2020 12:05:13 PM				
Hernandez, Javier		LEAK ON CEILING							
Virginia Galindo									
233994					7/30/2020		18		\$0.00
Medium	Work In Progress				7/30/2020 8:42:58 AM				
Ambriz, Juan		As per Mr. Sanchez requesting to have his entire office to be re-painted and one wall of the old nurses office.							
Guadalupe Parada									
233747	Main Building	Exterior			7/27/2020		21		\$0.00
Medium	Work In Progress	GARDEN			7/27/2020 10:41:34 AM				
Hernandez, Javier		LINDA HAINS, 206, GARDEN REPAIRS, THE MAINTENENCE MOWED THE GRASS AND BROKE THE SPRINKLER LEADS AND THE WIRES FOR THE TIMER. I NEED THE WATER TURNED OMN. THE MAINTENCE BROUGHT ME . LOSE FOR THE BROKEN HOSE. CAN NOT GET THE BROKEN HOSE OFF THE FAUCET.							
Joanne Munoz									
<b>Count: 5 Work Orders</b>		<b>Avg. Age of WO's 21</b>		<b>Total for La Union ES</b>		<b>0</b>		<b>\$121.10</b>	

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
234030	Main Building	Hallway/Corridor			7/30/2020		18		\$0.00
Medium	Work In Progress	Lobby Area			7/30/2020 2:34:25 PM				
Marquez, Gerardo		Our front door the right ones don't close right please fix and thank you.							
Sandra Mora									
233516	Army Building	Portables			7/21/2020		27		\$0.00
Medium	Work In Progress	Portable # 608			7/21/2020 11:59:58 AM				
Marquez, Gerardo		As per Head custodian Branden Jaquemai, door for portable # 608 lock is very hard to open, needs to be replaced please and thank you.							
Sandra Mora									
234003		Kitchen			7/30/2020		18		\$0.00
High	Work In Progress				7/30/2020 9:23:07 AM				
Marquez, Gerardo		Need door sweeps on the two doors coming into the kitchen							
Dino Facio									
233715		Kitchen			7/24/2020		24		\$0.00
High	Work In Progress				7/24/2020 1:34:13 PM				
Tellez, Hector		Need new electrical plug for new cutter/mixture							
Dino Facio									
233763	Army Building	Portables			7/27/2020		21	0.5	\$43.10
Medium	Work In Progress	Portable # 505			7/27/2020 1:36:14 PM				
Escobar, David		Portable A/C is not working we have staff in it please make it cool thank you.				Troubleshoot unit. Compressor did not start Forward to Hvac 7-28-20			
Sandra Mora									
<b>Count: 5 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>22</b>	<b>Total for Mesquite ES</b>			<b>0.5</b>	<b>\$43.10</b>

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: North Valley ES</b>									
233731					7/27/2020		21		\$1,308.57
Medium	Work In Progress				7/27/2020 8:25:18 AM				
Ambriz, Jose		Need Hvac to check units in rooms 106,105,107,108				7/27/20 - Joaquin will deliver (3) fans -			
		Units are not staying on . thank you				2,7,11			
Joaquin Romero									
233648		Kitchen			7/23/2020		25		\$577.11
High	Work In Progress				7/23/2020 8:59:27 AM				
Appelzoller, Fred		No hot water in kitchen area							
Dino Facio									
233472					7/20/2020		28		\$0.00
Medium	Work In Progress				7/20/2020 3:07:34 PM				
Appelzoller, Fred		need to replace lav faucets in restroom							
Fred Appelzoller									
234077		Restroom			7/31/2020		17		\$0.00
Medium	Work In Progress				7/31/2020 9:03:22 AM				
Marquez, Gerardo		broken door metal holder on staff restroom on RIO GRANDE hall. and the door still won't closed perfectly							
Marco Fattorini									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>23</b>		<b>Total for North Valley ES</b>	<b>0</b>	<b>\$1,885.68</b>	

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Northern On-Track Pre-K (LM)</b>									
233750					7/27/2020		21		\$0.00
Medium	Work In Progress				7/27/2020 11:36:23 AM				
Romero, Joaquin		Please check the AC in the cafeteria. It isn't cooling							
Viola Ramos									
<b>Count: 1 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>21</b>	<b>Total for Northern On-Track Pre-K (LM)</b>			<b>0</b>	<b>\$0.00</b>

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
233103					7/8/2020		40		\$0.00
Medium	Work In Progress				7/8/2020 8:30:47 AM				
Gonzalez, Salvador		7-8-2020							
Salvador Gonzalez		Requesting drill bit set and cutting wheels for grinder							
233047					7/7/2020		41		\$0.00
Medium	Work In Progress				7/7/2020 9:30:54 AM				
Romero, Joaquin		In the Construction office. Need to fix/replace or order part of modular office furniture shelf door. Please see Dominique in the construction office for information and door panel in questions. Thank you							
Dominique Esparza									
233474					7/20/2020		28		\$0.00
Medium	Work In Progress				7/20/2020 3:22:44 PM				
Marquez, Gerardo		Please change cores from DC-1 to something different, (see Memo first thing in the morning) Total of (5) - Offices Memo, Margret, Ruben, Maintenance Storage Area front and back door.							
Guillermo Hernandez									
233310					7/14/2020		34		\$0.00
Medium	Work In Progress				7/14/2020 11:54:17 AM				
Marquez, Gerardo		Needed in the construction office preferably by Friday afternoon or Monday Morning at the latest one (1) GM #6 and one (1) GM #7. Keys will be check out to Aliene O'Bryne. Should you have any questions please seemr. Gallegos in the Construction Office.							
Dominique Esparza									
233451					7/20/2020		28		\$307.74
Medium	Work In Progress				7/20/2020 11:47:05 AM				
Castillo, Carlos		Order PPE(SAFETY EQUIPMENT)-DRILL NUT DRIVER SET REPLACEMENT.							
Carlos Castillo									
233642					7/23/2020		25		\$0.00
Medium	Work In Progress				7/23/2020 8:04:32 AM				
Castillo, Carlos		Order circuit tracer							
Carlos Castillo									
<b>Count: 6 Work Orders</b>			<b>Avg. Age of WO's 33</b>			<b>Total for Physical Plant Complex</b>	<b>0</b>		<b>\$307.74</b>

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
234069					7/31/2020		17		\$0.00
Medium	Work In Progress			7/31/2020 8:14:53 AM					
Lara, Ralph	need to get lock of master from the morgan building to many people have the key to go in the morgan building and i have equipment there and school supplies								
Lilia Mondragon									
234032					7/30/2020		18		\$0.00
Medium	Work In Progress	Office		7/30/2020 2:45:34 PM					
Saucedo, Luis	Office is very hot, please adjust temperature. (Mrs. Martinez)								
Norma Martinez									
234034					7/30/2020		18		\$0.00
Medium	Work In Progress	Room 137		7/30/2020 2:47:15 PM					
Saucedo, Luis	Relocate white magnetic board from room 137 to room 18. (Mrs. Martinez)								
Norma Martinez									
234110					7/31/2020		17		\$0.00
Medium	Work In Progress	Room 21		7/31/2020 3:28:51 PM					
Ortiz, Ruben	Relocate magnetic white board from room 21 to room #11. (Mrs. Martinez)								
Norma Martinez									
234035					7/30/2020		18		\$0.00
Medium	Work In Progress			7/30/2020 2:48:42 PM					
Hernandez, Guillermo	Re-stencil parking lot located behind the school. Principal, Assistant Principal, Secretary, Nurse, and SNP Manager. (Mrs. Martinez)								
Norma Martinez									
233703					7/24/2020		24		\$0.00
Medium	Work In Progress	Main Hallway		7/24/2020 10:24:27 AM					
Hernandez, Javier	Main hallway is still very hot, please adjust temperture. it feels like the heater is on. (Mrs. Martnez)								
Norma Martinez									
233704					7/24/2020		24		\$7.77
Medium	Work In Progress	Exit doors		7/24/2020 10:26:52 AM					
Hernandez, Javier	Bird spikes need to be re-secure. Pigeons moved bird spikes. (Mrs. Martinez)								
Norma Martinez									

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Riverside ES</b>							
233850					7/28/2020		20		\$0.00
Medium	Work In Progress				7/28/2020 12:05:55 PM				
Hernandez, Javier	Need assistance assembling science lab tables. (Mrs. Martinez)								
Norma Martinez									
233470					7/20/2020		28		\$0.00
Medium	Work In Progress	Office			7/20/2020 2:50:14 PM				
Hernandez, Javier	Please adjust AC temperature in office and main hallway both areas are very hot. (Mrs. Martinez)								
Norma Martinez									
<b>Count: 9 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>20</b>	<b>Total for Riverside ES</b>				<b>0</b>	<b>\$7.77</b>



# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>RTC - Alliance</b>							
233138					7/9/2020		39		\$0.00
Medium	Work In Progress				7/9/2020 8:11:40 AM				
Hernandez, Javier		Mr. Hawkins social studies classroom air conditioner is not working it only throw hot air. Please sen someone to check it out. We need to have working by the time teachers and students start. I believe one was already generated previously by Mr. Gallegos request while construction was going on for the restrooms. I'm Mondays- Thursdays call prior so I can let you in 575-8826450				7/16/20 1 hr checked and contacts getting stuck might need to be replaced fowarded to hvac refer to wo 233390			
Gloria Delgado									
233390					7/16/2020		32		\$15.74
Medium	Work In Progress				7/16/2020 11:13:45 AM				
Ambriz, Jose		ac unit in portable for rtc dpt not working was checked by maintenance crew but contacts getting stuck was advised							
Javier Hernandez									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>36</b>	<b>Total for RTC - Alliance</b>			<b>0</b>	<b>\$15.74</b>

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa ES</b>									
233952					7/29/2020		19		\$0.00
High	Work In Progress				7/29/2020 3:49:03 PM				
Castillo, Carlos		Need Electricition to look into why lights are not turning on as programmed in the morning, this is a saftey issue. Should be on from 4:45am to 5:15 amThank You							
Dominique Esparza									
233686	Main Building	Classroom			7/23/2020		25		\$0.00
Medium	Work In Progress	Room 305 Mrs.			7/23/2020 3:59:35 PM				
Lara, Ralph		Please install drawer latches. The originals are broken. Thank you.							
Rita Mendez									
233537					7/21/2020		27		\$0.00
Medium	Work In Progress				7/21/2020 2:45:05 PM				
Gonzalez, Salvador		Install gutters at canopy w/downspots.							
Guillermo Hernandez									
<b>Count: 3 Work Orders</b>		<b>Avg. Age of WO's 24</b>			<b>Total for Santa Teresa ES</b>			<b>0</b>	<b>\$0.00</b>

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
233102		Athletic Field			7/8/2020		40		\$0.00
Medium	Work In Progress				7/8/2020 8:28:44 AM				
Villalobos, Jose		please check air compressor, not working. thank you.							
Lauro Jasso									
233835	Main Building	Classroom			7/28/2020		20		\$0.00
Medium	Work In Progress	205			7/28/2020 10:32:17 AM				
Hernandez, Javier		Hot air is blowing making the classroom extremely hot.							
Gema Suggs									
232742					7/1/2020		47		\$0.00
Safety	Work In Progress				7/1/2020 1:42:18 PM				
Hernandez, Javier		STH CREW Start shutting off water, to all water fountains (inside and outside), must be done before school starts. LU, STE, STH, STM, RS, DV, SPE, GAC-PRE-K							
Jessica Herrera									
233944	Vocational	Classroom			7/29/2020		19		\$0.00
Medium	Work In Progress	Vocational			7/29/2020 2:48:30 PM				
Hernandez, Javier		Air conditioning not functioning							
Lorraine Dominguez									
233529	Main Building	Classroom			7/21/2020		27		\$0.00
Medium	Work In Progress	Training room			7/21/2020 1:22:09 PM				
Hernandez, Javier		Air conditioning is not functioning							
Lorraine Dominguez									
233985	Annex Building	Classroom			7/30/2020		18		\$0.00
Medium	Work In Progress	Dinning Room			7/30/2020 7:56:52 AM				
Lara, Ralph		Install Door Top on Dinning rooms door							
Gema Suggs									
233109	Main Building	Athletic Field			7/8/2020		40		\$130.00
Medium	Work In Progress	Outdoor fields			7/8/2020 11:07:23 AM				
Ontiveros, Guadalupe		Grounds is in need of tractor with scraper as well as round up for weeds							
Lorraine Dominguez									

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location:** Santa Teresa HS

233142	Main Building	Classroom			7/9/2020		39		\$0.00
--------	---------------	-----------	--	--	----------	--	----	--	--------

Medium	Work In Progress	502			7/9/2020 8:32:45 AM				
--------	------------------	-----	--	--	---------------------	--	--	--	--

Hernandez, Javier Two tables within classroom are coming unglued from the tabletop to frame

Lorraine Dominguez

233254	Main Building	Restroom			7/13/2020		35		\$0.00
--------	---------------	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Family			7/13/2020 8:31:17 AM				
--------	------------------	--------	--	--	----------------------	--	--	--	--

Hernandez, Javier Light is not working in family restroom in Varsity gym

Lorraine Dominguez

233305	Main Building	Hallway/Corridor			7/14/2020		34		\$0.00
--------	---------------	------------------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	main hallway			7/14/2020 10:52:37 AM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Hernandez, Javier Issue with restroom in main hallway please see below  
En el baño de los hombres, de el pasillo principal, (enfrente de la oficina de Emma) uno de los uriniales no flachea.

Lorraine Dominguez

232735					7/1/2020		47		\$0.00
--------	--	--	--	--	----------	--	----	--	--------

Medium	Work In Progress	Tech Portable			7/1/2020 10:03:00 AM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

, AC not working. Please check and service ASAP.

Nicholas Wohlgemuth

232741		Portables			7/1/2020		47		\$3,729.56
--------	--	-----------	--	--	----------	--	----	--	------------

Medium	Work In Progress				7/1/2020 11:48:53 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Escobar, David ac units in portable for margie computer tech not cooling ,cleaned filters and coils, may need freon or new units

Javier Hernandez

233350	Vocational				7/15/2020		33		\$0.00
--------	------------	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/15/2020 10:36:26 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Escobar, David In the Culinary Arts Kitchen, roof top unit showing alarm. Tempature is showing 90.4°. No other information is showing on diagnostic. Please have HVAC look into this. Thank You

Dominique Esparza

233829					7/28/2020		20		\$7.18
--------	--	--	--	--	-----------	--	----	--	--------

Medium	Work In Progress	Campuswide			7/28/2020 9:50:25 AM				
--------	------------------	------------	--	--	----------------------	--	--	--	--

Lara, Ralph Remove several lock from current off master status. Please see Mr. W and Mrs. Soriano for discussion about which locks and how they would like them keyed.

Nicholas Wohlgemuth

8/17/2020 11:45:24 AM

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Santa Teresa HS</b>										
233335	Concession	Restroom			7/14/2020		34		\$279.00	
Medium	Work In Progress				7/14/2020 3:49:47 PM					
Pacheco, Hector s per conversation with Head Custodian to replace 4 toilet flush valves and also 3 urinal flush valves.										
Hector Pacheco										
233695	Main Building	Restroom			7/24/2020		24		\$0.00	
Medium	Work In Progress				7/24/2020 8:13:24 AM					
Pacheco, Hector Need to replace automatic flush sensor system on a urinal in boys restroom at 200 wing..										
Hector Pacheco										
234037	Main Building	Classroom			7/30/2020		18		\$0.00	
Medium	Work In Progress	410			7/30/2020 3:07:40 PM					
Ambriz, Jose Room 410 is hot, teacher reported extremely hot room										
Gema Suggs										
233883	GYM (2009)	Gym			7/28/2020		20		\$0.00	
Medium	Work In Progress	concession			7/28/2020 3:40:58 PM					
Ambriz, Jose Ice machine is not working in concession stand as well as in the training room area										
Lorraine Dominguez										
233389					7/16/2020		32		\$0.00	
Medium	Work In Progress				7/16/2020 11:09:15 AM					
Ambriz, Jose bolimo valve not working properly on ac unit for library sths										
Javier Hernandez										
<b>Count: 19 Work Orders</b>		<b>Avg. Age of WO's 31</b>		<b>Total for Santa Teresa HS</b>				<b>0</b>	<b>\$4,145.74</b>	

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Santa Teresa MS**

233752	South Building	Classroom			7/27/2020		21		\$0.00
--------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/27/2020 11:53:54 AM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose  
to make a request to report some rooms that the A/C OF Building shouth does not work upper and lower part also hallways and lobby please

Cristian Martinez

233754	North Building	Classroom			7/27/2020		21		\$0.00
--------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress				7/27/2020 12:01:01 PM				
--------	------------------	--	--	--	-----------------------	--	--	--	--

Ambriz, Jose  
to make a request to report some rooms that the A/C of building north does not work upper lab comp , class roms 49 ,44 and MS GRIEGO office please

Cristian Martinez

233842	North Building	Classroom			7/28/2020		20		\$0.00
--------	----------------	-----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	NORTH			7/28/2020 11:04:36 AM				
--------	------------------	-------	--	--	-----------------------	--	--	--	--

Ambriz, Jose  
AC NOT WORKING: Forward to HVAC asp D. Sotelo 8/11/20  
ROOM 10  
ROOM 4  
PORTABLE 2-3  
ROOM 17  
ROOM 18  
ROOM 14  
ROOM 15  
ROOM 7  
REGISTARS OFFICE- MAIN OFFICE

Laura Parra

234093	North Building	Office			7/31/2020		17		\$42.84
--------	----------------	--------	--	--	-----------	--	----	--	---------

Medium	Work In Progress	RECPTIONIST/			7/31/2020 12:03:48 PM				
--------	------------------	--------------	--	--	-----------------------	--	--	--	--

Ambriz, Jose  
AIR CONDITIONERS NOT WORKING.

Laura Parra

233696	North Building	Exterior			7/24/2020		24		\$0.00
--------	----------------	----------	--	--	-----------	--	----	--	--------

Medium	Work In Progress	sidewalk area			7/24/2020 8:18:26 AM				
--------	------------------	---------------	--	--	----------------------	--	--	--	--

Pacheco, Hector  
As per conversation with grounds personal to remove a old pipe from side walk.

Hector Pacheco

233301	South Building	Restroom			7/14/2020		34	1	\$247.90
--------	----------------	----------	--	--	-----------	--	----	---	----------

Medium	Work In Progress				7/14/2020 8:20:13 AM				
--------	------------------	--	--	--	----------------------	--	--	--	--

Pacheco, Hector  
Please change the valves of the toilets of the bathrooms of the south building are still pending Asp report transfer to H. Pacheco, needs valves

Cristian Martinez

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa MS</b>									
233524	North Building				7/21/2020		27		\$0.00
Medium	Work In Progress				7/21/2020 12:28:32 PM				
Castillo, Carlos		to make a request to change a ballast for a women's bathroom lamp from the north up please							
Cristian Martinez									
233525	North Building				7/21/2020		27		\$0.00
Medium	Work In Progress				7/21/2020 12:32:19 PM				
Castillo, Carlos		to make a request to change a ballast for women's bathroom lamp from cafeteria area please							
Cristian Martinez									
233173	South Building				7/9/2020		39		\$17.30
Medium	Work In Progress				7/9/2020 3:58:18 PM				
Ambriz, Jose		Please check unit in office, not working.							
Cristian Martinez									
<b>Count: 9 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>26</b>		<b>Total for Santa Teresa MS</b>	<b>1</b>	<b>\$308.04</b>	

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>SNP Complex</b>							
234062		Portables			7/31/2020		17		\$0.00
High	Work In Progress				7/31/2020 7:28:42 AM				
Romero, Joaquin		AC Unit on portable 6 not working properly							
Dino Facio									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>17</b>	<b>Total for SNP Complex</b>			<b>0</b>	<b>\$0.00</b>



## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
233457		Office			7/20/2020		28		\$0.00
Medium	Work In Progress				7/20/2020 1:13:59 PM				
Hernandez, Javier		Replace blue moldings around office, bathroom and nurses office.							
Ivette Rios									
233458		Office			7/20/2020		28		\$0.00
Medium	Work In Progress				7/20/2020 1:14:55 PM				
Hernandez, Javier		Paint the square in front office where parent window used to be.							
Ivette Rios									
233836					7/28/2020		20		\$0.00
Medium	Work In Progress	gym			7/28/2020 10:42:10 AM				
Hernandez, Javier		the a/c in the gym is not working 2nd notice							
Ivette Rios									
234105					7/31/2020		17		\$0.00
Medium	Work In Progress	38			7/31/2020 2:39:50 PM				
Saucedo, Luis		white board to front of class room and place large blue plastic board on back of wall.							
Ivette Rios									
233562	Main Building	Gym			7/22/2020		26		\$0.00
Medium	Work In Progress				7/22/2020 8:29:01 AM				
Ambriz, Jose		A/C AT THE GYM IS NOT WORKING. THE GYM IS EXTREMELY HOT!							
Ivette Rios									
233588					7/22/2020		26		\$0.00
Medium	Work In Progress	76			7/22/2020 2:03:23 PM				
Hernandez, Javier		computer lab to painted the doors and wall that has a brown stain on it by the blue cabinet. doors also need to be painted.							
Ivette Rios									
233309		Kitchen			7/14/2020		34		\$0.00
High	Work In Progress				7/14/2020 11:44:02 AM				
Escobar, David		AC Unit not cooling in kitchen (Hot)							
Dino Facio									
233534	Main Building	Classroom			7/21/2020		27		\$0.00
Medium	Work In Progress	35			7/21/2020 2:38:37 PM				
Lara, Ralph		draft under exit door lots of dirt/insects							
Ivette Rios									

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
233535					7/21/2020		27		\$0.00
Medium	Work In Progress	33			7/21/2020 2:39:21 PM				
Lara, Ralph		back door needs to be weather stripped							
Ivette Rios									
233454		Classroom			7/20/2020		28		\$0.00
Medium	Work In Progress	32			7/20/2020 1:10:02 PM				
Lara, Ralph		weather strip							
Ivette Rios									
<b>Count: 10 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>26</b>	<b>Total for Sunland Park ES</b>			<b>0</b>	<b>\$0.00</b>

## 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunrise ES</b>									
233288					7/13/2020		35		\$0.00
Medium	Work In Progress	playground			7/13/2020 5:24:35 PM				
Ontiveros, Guadalupe		please repair stuck irrigation valve solenoid to grass irrigation sprinkler system. water is constantly on. Thank You...							
Johnny Acuna									
233960					7/29/2020		19		\$0.00
Medium	Work In Progress				7/29/2020 11:11:48 PM				
Ambriz, Jose		Need assistance with Rooftop ERV's (2 of them are not turning on)							
Johnny Acuna									
233264					7/13/2020		35		\$0.00
Medium	Work In Progress				7/13/2020 1:40:24 PM				
Acuna, Johnny		El salon 104 necesita reparacion de pared tapar algunos ollos.							
Maritxa Vasquez									
233265					7/13/2020		35		\$0.00
Medium	Work In Progress				7/13/2020 1:42:24 PM				
Acuna, Johnny		El salon 309 necesita detalles de pared tapar algunos abujeros gracias buen dia.							
Maritxa Vasquez									
233826	Main Building	Classroom			7/28/2020		20		\$0.00
Medium	Work In Progress				7/28/2020 8:53:37 AM				
Hernandez, Guillermo		Rocio Nieto, Classroom 103, Needs blinds on her windows and side window.							
Monica Narez									
233266					7/13/2020		35		\$0.00
Medium	Work In Progress				7/13/2020 1:45:19 PM				
Tellez, Hector		Entrada de escuela 2 balastras estan descompuestas y necesitan focos gracias buen dia.							
Maritxa Vasquez									
233961					7/29/2020		19		\$0.00
Medium	Work In Progress				7/29/2020 11:42:24 PM				
Acuna, Johnny		Need two signs for chains that read Do Not Enter in English and Spanish to parking lot.							
Johnny Acuna									

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunrise ES</b>									
234086					7/31/2020		17		\$0.00
Medium	Work In Progress				7/31/2020 11:02:44 AM				
Acuna, Johnny		Norma Palma, Classroom 203, Need a bulletin board to be screwed to the wall behind her desk.							
Monica Narez									
234006	Main Building	Classroom			7/30/2020		18		\$0.00
Medium	Work In Progress				7/30/2020 10:14:22 AM				
Acuna, Johnny		En el 102 necesita reparacion de pared .							
Maritxa Vasquez									
233570	Main Building	Classroom			7/22/2020		26		\$0.00
Medium	Work In Progress				7/22/2020 9:40:16 AM				
Acuna, Johnny		Leticia Medina, Classroom 104, need to remove chalkboard from room.							
Monica Narez									
<b>Count: 10 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>26</b>		<b>Total for Sunrise ES</b>	<b>0</b>		<b>\$0.00</b>

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
233573					7/22/2020		26		\$0.00
Medium	Work In Progress				7/22/2020 10:04:08 AM				
Marquez, Gerardo		Room 303 - having issues with handle.							
Armando Diaz									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>26</b>	<b>Total for Vado ES</b>		<b>0</b>	<b>\$0.00</b>	

# 204 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 7/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Yucca Heights ES</b>									
233475		Classroom			7/20/2020		28		\$0.00
Medium	Work In Progress				7/20/2020 3:25:55 PM				
Ambriz, Jose		Need to check units that are not working properly.							
Jose Ambriz									
233954		Classroom			7/29/2020		19		\$0.00
Medium	Work In Progress	223			7/29/2020 3:57:00 PM				
Acuna, Johnny		Cabinet door need to be repaired.							
Rocio Rodriguez									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>24</b>		<b>Total for Yucca Heights ES</b>	<b>0</b>	<b>\$0.00</b>	
<b>Count: 204 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>26</b>		<b>Grand Total</b>	<b>2.5</b>	<b>\$9,873.60</b>	