

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Alta Vista ECHS</b>									
233356					7/15/2020		36	11	\$649.38
Medium	Work In Progress				7/15/2020 11:35:35 AM	8/20/2020			
Tellez, Hector		Replaced bulbs in girls restrooms and 2 fixtures did not work needs ballast				Light fixtures need to be replaced with modern fixtures. T-12 light bulbs are no longer ordered or carried by warehouse. Please forwarded to Electrician			
Maria Davila									
233863					7/28/2020		49		\$0.00
Medium	Work In Progress	11 & 13			7/28/2020 2:05:26 PM				
Marquez, Gerardo		Classroom doors for portables 11 & 13 are hard to close.							
Melanie Beegle									
234001					7/30/2020		47		\$0.00
Medium	Work In Progress	13			7/30/2020 9:14:16 AM				
Romero, Joaquin		Replace 3 pink colored blinds with white or cream colored blinds.				Ordered on 8-7-20			
Melanie Beegle									
<b>Count: 3 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>44</b>		<b>Total for Alta Vista ECHS</b>	<b>11</b>	<b>11</b>	<b>\$649.38</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Anthony ES</b>									
233082					7/7/2020		70		\$0.00
High	Work In Progress				7/7/2020 3:03:09 PM				
Ontiveros, Guadalupe		irrigation system needs to be rewire and replace control to be able to water soccer field.							
Guadalupe Ontiveros									
234460					8/5/2020		41		\$4,950.00
Medium	Work In Progress				8/5/2020 3:51:19 PM				
Tellez, Hector		replace light fixtures with 2x4 flat panels in classrooms							
Hector Tellez									
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>56</b>		<b>Total for Anthony ES</b>	<b>0</b>	<b>\$4,950.00</b>	

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Berino ES</b>							
235146		Kitchen			8/20/2020		26		\$0.00
High	Work In Progress			8/20/2020 2:21:55 PM					
Tellez, Hector	Back door, door bell needs to be relocated from inside the office to somewhere in the kitchen area								
Dino Facio									
233080					7/7/2020		70		\$0.00
Medium	Work In Progress			7/7/2020 2:36:10 PM					
Appelzoller, Fred	need Lav Faucets for restrooms								
Fred Appelzoller									
234706	Main Building	Office			8/11/2020		35		\$0.00
Medium	Work In Progress	Front		8/11/2020 8:21:28 AM					
Romero, Joaquin	Paint the door frames on all the doors of the school can you please close work order 234658 please					paint is on order			
Michelle Guerra									
234346	Main Building	Office			8/4/2020		42		\$0.00
Medium	Work In Progress	Front		8/4/2020 9:18:56 AM					
Romero, Joaquin	Paint the side door frames in the front entrance								
Michelle Guerra									
233768	Main Building	Classroom			7/27/2020		50		\$0.00
Medium	Work In Progress	144		7/27/2020 1:57:16 PM					
Escobar, David	Classroom is hot								
Michelle Guerra									
233769	Main Building	Classroom			7/27/2020		50		\$0.00
Medium	Work In Progress	142		7/27/2020 1:57:58 PM					
Escobar, David	classroom is hot								
Michelle Guerra									
233770	Main Building	Classroom			7/27/2020		50		\$0.00
Medium	Work In Progress	140		7/27/2020 1:58:49 PM					
Escobar, David	classroom is hot								
Michelle Guerra									
233771	Main Building	Classroom			7/27/2020		50		\$0.00
Medium	Work In Progress	137		7/27/2020 2:00:06 PM					
Escobar, David	classroom is hot								
Michelle Guerra									

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Berino ES</b>									
233773	Main Building	Classroom			7/27/2020		50		\$0.00
Medium	Work In Progress	114			7/27/2020 2:01:42 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233774	Main Building	Classroom			7/27/2020		50		\$0.00
Medium	Work In Progress	117			7/27/2020 2:02:30 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233775	Main Building	Classroom			7/27/2020		50		\$0.00
Medium	Work In Progress	116			7/27/2020 2:03:14 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233780	Main Building	Classroom			7/27/2020		50		\$0.00
Medium	Work In Progress	115			7/27/2020 2:16:40 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233781	Main Building	Classroom			7/27/2020		50		\$0.00
Medium	Work In Progress	128			7/27/2020 2:17:57 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233782	Main Building	Classroom			7/27/2020		50		\$0.00
Medium	Work In Progress	131			7/27/2020 2:18:51 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233783	Main Building	Classroom			7/27/2020		50		\$0.00
Medium	Work In Progress	133			7/27/2020 2:19:22 PM				
Escobar, David classroom is hot									
Michelle Guerra									
233785	Main Building	Classroom			7/27/2020		50		\$0.00
Medium	Work In Progress	133			7/27/2020 2:19:50 PM				
Escobar, David classroom is hot									
Michelle Guerra									

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Berino ES</b>									
234823	Main Building	Classroom			8/13/2020		33		\$0.00
Medium	Work In Progress	114			8/13/2020 10:38:21 AM				
Escobar, David		classroom is too cold							
Michelle Guerra									
233539					7/21/2020		56		\$0.00
Medium	Work In Progress				7/21/2020 2:49:16 PM				
Marquez, Gerardo		LOCK SETS AT FACULTY RESTROOMS ARE LOOSE AND HARD TO OPEN. PLEASE FIX.							
Gerardo Marquez									
233561					7/22/2020		55		\$50.50
Medium	Work In Progress				7/22/2020 7:45:16 AM				
Escobar, David		trouble at room 109,109a, 110, 131, and 133.							
David Escobar									
233171					7/9/2020		68		\$0.00
Medium	Work In Progress				7/9/2020 3:49:17 PM				
Marquez, Gerardo		Need to rekey all exterior doors to main bldg, portables, pump house.							
Jessica Herrera									
<b>Count: 20 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>49</b>		<b>Total for Berino ES</b>	<b>0</b>	<b>\$50.50</b>	

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral ES</b>									
233165	Main Building	Office			7/9/2020		68		\$0.00
Medium	Work In Progress	Vault and extra			7/9/2020 3:41:05 PM				
Marquez, Gerardo Administration would like locks to be redone and keyed with different key for vault and extra utility room located in the front office. Please see Jennifer or Duque/Davis									
Jennifer Corral									
233526	Main Building	Office			7/21/2020		56		\$0.00
Medium	Work In Progress	office			7/21/2020 1:13:12 PM				
Marquez, Gerardo need room across from vault to have same key as vault (rekey) See front office.									
Jennifer Corral									
234671					8/10/2020		36		\$0.00
Medium	Work In Progress	Rm. #124 Music			8/10/2020 12:13:15 PM				
Ambriz, Jose Having trouble with A/c to Rm. 124 (Chaparral Elementary). Unit not resetting.									
Johnny Acuna									
235201	Main Building	Classroom			8/21/2020		25		\$0.00
Medium	Work In Progress	school wide			8/21/2020 11:30:00 AM				
Ambriz, Jose change temp for all classrooms and office in the school. Please put temp up to 73 too cold, See admin									
Jennifer Corral									
235082					8/19/2020		27		\$0.00
Medium	Work In Progress				8/19/2020 10:15:11 AM				
Chavez, Santos Need doorbells upgraded									
Jimmy Carbajal									
235319		Kitchen			8/25/2020		21		\$0.00
High	Work In Progress				8/25/2020 9:40:53 AM				
Chavez, Santos Light out in bathroom									
Dino Facio									
233873	Main Building	Office			7/28/2020		49		\$0.00
Medium	Work In Progress	office			7/28/2020 3:09:18 PM				
Acuna, Johnny need mirror to be placed above my desk. See Ms. Davis									
Jennifer Corral									
234544	Main Building	Classroom			8/7/2020		39		\$0.00
Medium	Work In Progress				8/7/2020 9:25:14 AM				
Acuna, Johnny Room #326 doesn't have window blinds Reassign to Memo - 8/12/20									
Adrian Flores									

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Chaparral ES</b>							
233827		Classroom			7/28/2020		49		\$0.00
Medium	Work In Progress	301			7/28/2020 9:20:51 AM				
Acuna, Johnny		hole in wall. Please fix see Barraza							
Jennifer Corral									
<b>Count: 9 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>41</b>	<b>Total for Chaparral ES</b>			<b>0</b>	<b>\$0.00</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
233093					7/7/2020		70		\$39.80
Medium	Work In Progress	AUX. GYM			7/7/2020 5:19:51 PM				
Acuna, Johnny		Need (8) Emergency light batteries for New Aux. Gym. (Hubbell: Part #93012372)							
Johnny Acuna									
235128		Kitchen			8/20/2020		26		\$0.00
High	Work In Progress				8/20/2020 11:46:46 AM				
Acuna, Johnny		Need to replace the mop holders in the mop room broken dont hold the mops anymore							
Dino Facio									
233107					7/8/2020		69		\$0.00
Medium	Work In Progress				7/8/2020 10:15:04 AM				
Ontiveros, Joe		check water faucets in all restroom sinks alot of them are loose.							
Jesus Urquidi									
235184	D-Wing	Restroom			8/21/2020		25		\$0.00
Medium	Work In Progress	Staff restroom			8/21/2020 9:12:00 AM				
Villalobos, Margret		Need to fumigate D wing staff restroom. Has ants. (Custodial)				8/24/20 - Approved and EM Waiver			
Mireya Meza									
235185	Field House	Athletic Field			8/21/2020		25		\$0.00
Medium	Work In Progress	Concession			8/21/2020 9:14:39 AM				
Villalobos, Margret		Need to fumigate concession stand field house. Has black widows in it. (Custodial)				8/24/20 - Approved and EM Waiver			
Mireya Meza									
235186	Q-Wing	Classroom			8/21/2020		25		\$0.00
Medium	Work In Progress	All of Q & R			8/21/2020 9:17:16 AM				
Villalobos, Margret		Need to fumigate Q & R buildings have lots of spiders. Black widows and other type of spiders. (Custodial)				8/24/20 - Approved and EM Waiver			
Mireya Meza									
233076	E-Wing	Classroom			7/7/2020		70		\$0.00
Medium	Work In Progress	E4			7/7/2020 2:00:39 PM				
Chavez, Santos		Please fix outlets. Only the one by the front of class works. All the others don't. This has been an on going problem in my room. This is not the first time I ask for them to be fixed. (Ms. Gonzalez, E4)							
Mireya Meza									



# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
235196					8/21/2020		25		\$2.25
Medium	Work In Progress				8/21/2020 10:36:18 AM				
Chavez, Santos		Fluorescent light cover missing main hallway in front of old gym.							
Jesus Urquidi									
235131	Q-Wing	Restroom			8/20/2020		26		\$14.97
Medium	Work In Progress				8/20/2020 12:24:05 PM				
Ontiveros, Joe		2nd urinal leaking from bottom.							
Jesus Urquidi									
234569	A-Wing	Office			8/7/2020		39		\$0.00
Medium	Work In Progress	Front office			8/7/2020 12:50:08 PM				
Ambriz, Jose		Control Panel in front office shows TBL DD Shell in C wing. (Ms. Lopez)				8/13/20			
Mireya Meza						this work order, according to Silver needs to be addressed by HVAC. Have them call Silver if they have any questions			
235402	G-Wing	Classroom			8/27/2020		19		\$0.00
Medium	Work In Progress	G7			8/27/2020 8:47:48 AM				
Marquez, Gerardo		Door lower hinge is broken on the door's frame. (Mr. Gomez, G7)							
Mireya Meza									
233275	G-Wing	Classroom			7/13/2020		64		\$0.00
Medium	Work In Progress	G1			7/13/2020 3:18:20 PM				
Marquez, Gerardo		Wall cabinet on the right side does not lock. (Ms. Montelongo, G1)							
Mireya Meza									
233569	A-Wing	Office			7/22/2020		55		\$0.00
Medium	Work In Progress	Counselor area			7/22/2020 9:33:59 AM				
Marquez, Gerardo		Please make me 2 copies of key CH21 & 1 of CH17. (Mireya Meza)							
Mireya Meza									
233504	A-Wing	Office			7/21/2020		56		\$0.00
Medium	Work In Progress	Mireya's office			7/21/2020 11:04:37 AM				
Marquez, Gerardo		Need copy of key to Mireya's office. (Victoria Lopez, principal)							
Mireya Meza									

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral HS</b>							
233512	B-Wing	Classroom			7/21/2020		56		\$0.00
Medium	Work In Progress	B4			7/21/2020 11:40:34 AM				
Marquez, Gerardo		Please make me 2 copies of key CH37. (Mireya Meza)							
Mireya Meza									
233347	G-Wing	Classroom			7/15/2020		62		\$0.00
Medium	Work In Progress	G4			7/15/2020 10:23:27 AM				
Marquez, Gerardo		Lock on this door is hard to open and close. When you insert key it turns several times and key gets stuck. (Mireya Meza0							
Mireya Meza									
233348	F-Wing	Classroom			7/15/2020		62		\$0.00
Medium	Work In Progress	F5			7/15/2020 10:26:19 AM				
Marquez, Gerardo		We do not have a key number for wall cabinet in F5. The core is blank. We don't know if it works. (Mireya Meza)							
Mireya Meza									
234505	B-Wing	Classroom			8/6/2020		40		\$0.00
Medium	Work In Progress	B3			8/6/2020 1:53:35 PM				
Marquez, Gerardo		Door is off balance and will not close all the way. (custodian, B3)							
Mireya Meza									
234506	B-Wing	Restroom (Girls)			8/6/2020		40		\$0.00
Medium	Work In Progress	Girls restroom			8/6/2020 1:55:20 PM				
Marquez, Gerardo		The 5th stall in the girls bathroom in B hall is missing part of the locking latch. (custodian, B wing girls bathroom)							
Mireya Meza									
234391		Kitchen			8/4/2020		42		\$0.00
High	Work In Progress				8/4/2020 3:13:23 PM				
Marquez, Gerardo		North side door that leads from the kitchen to the dining area will open with master key							
Dino Facio									
234672					8/10/2020		36		\$0.00
Medium	Work In Progress				8/10/2020 12:14:59 PM				
Marquez, Gerardo		Please replace missing lock cylinder to lock on back of football bleachers gate.							
Johnny Acuna									

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral HS</b>									
234549	A-Wing	Classroom			8/7/2020		39		\$0.00
Medium	Work In Progress	A110			8/7/2020 10:01:39 AM				
Marquez, Gerardo		May I have 3 copies of key 194E. (Mireya Meza)							
Mireya Meza									
234815	Q-Wing	Classroom			8/13/2020		33		\$0.00
Medium	Work In Progress	Q2			8/13/2020 9:33:27 AM				
Marquez, Gerardo		Need key to Q2 Cage. We were able to ope one of the cages but we have no key for the second cage. Since we have so much trouble with this. Is there any way to change the lock completely and issue district keys. These other keys are specialty keys and we don't know where to get replacements for these types of keys. (Mr. Martinez, Q2)							
Mireya Meza									
233734					7/24/2020		53		\$0.00
Medium	Work In Progress				7/27/2020 8:48:32 AM				
Flores, Pete		JD Gator # 0500 needs to be service.							
Guadalupe Ontiveros									
<b>Count: 24 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>44</b>	<b>Total for Chaparral HS</b>			<b>0</b>	<b>\$57.02</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Chaparral MS</b>									
233344	Main Building	Classroom			7/15/2020		62		\$0.00
Medium	Work In Progress	102			7/15/2020 9:04:07 AM				
Marquez, Gerardo Door will not open									
Maria Garcia									
234954					8/17/2020		29		\$30.98
Medium	Work In Progress				8/17/2020 10:20:31 AM				
Ontiveros, Joe Need to replace leaking water supply valve on wall to ice -machine located inside the back Boy's Locker Room.									
Johnny Acuna									
234878	Main Building				8/14/2020		32		\$142.58
Medium	Work In Progress				8/14/2020 8:22:01 AM				
Ontiveros, Joe Boys Restroom In Main Entry Lobby- lavatory metering faucets need adjusting. Water flows for to short of time not allowing for adequate washing time.									
Alfredo Holguin									
235039					8/18/2020		28		\$0.00
Medium	Work In Progress				8/18/2020 1:24:17 PM				
Chavez, Santos Band Room Lobby: Need to replace missing light cover w/frame to light fixture.									
Johnny Acuna									
235034					8/18/2020		28		\$726.72
Medium	Work In Progress				8/18/2020 1:12:12 PM				
Chavez, Santos Need to repair Emergency lighting and Exit lighting. Please see Johnny Acuña for list. ThankYou.....									
Johnny Acuna									
235405	Main Building	Classroom			8/27/2020		19		\$0.00
Medium	Work In Progress	Entire building			8/27/2020 9:33:14 AM				
Acuna, Johnny Need touch up of paint on all walls and door frames from inside classrooms and outside classrooms									
Maria Garcia									
234364	Main Building	Classroom			8/4/2020		42		\$0.00
Medium	Work In Progress	203			8/4/2020 10:33:00 AM				
Ontiveros, Joe sink clogged									
Maria Garcia									

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
233840	Main Building	Classroom			7/28/2020		49		\$0.00
Medium	Work In Progress	450		7/28/2020 11:00:08 AM					
Acuna, Johnny		Wooden locker doors have fallen off and need help fixing them back on. Teacher has all wooden pieces for those that fell off.							
Maria Garcia									
235004		Custodial			8/18/2020		28		\$0.00
Medium	Work In Progress			8/18/2020 9:16:20 AM					
Acuna, Johnny		I needs windo screens throuqhout the whoule school Gracias							
M. Carmen Perez									
235573					8/31/2020		15		\$129.00
Medium	Work In Progress			8/31/2020 4:43:08 PM					
Acuna, Johnny		Need to repair both walls to (Front lobby) custodial closet and inside concession stand.							
Johnny Acuna									
235406	Main Building	Classroom			8/27/2020		19		\$0.00
Medium	Work In Progress	100		8/27/2020 9:40:58 AM					
Acuna, Johnny		Replace missing molding by door							
Maria Garcia									
235407	Main Building	Classroom			8/27/2020		19		\$0.00
Medium	Work In Progress	104		8/27/2020 10:27:52 AM					
Acuna, Johnny		Replace damaged molding by door							
Maria Garcia									
235408	Main Building	Restroom			8/27/2020		19		\$0.00
Medium	Work In Progress	100 Hall		8/27/2020 10:28:54 AM					
Acuna, Johnny		Paint wall panel by urinals- Replace missing tile by window- repair hole in wall by hand dryer							
Maria Garcia									
235409	Main Building	Classroom			8/27/2020		19		\$0.00
Medium	Work In Progress	106		8/27/2020 10:29:22 AM					
Acuna, Johnny		replace missing molding by door							
Maria Garcia									
235412	Main Building	Classroom			8/27/2020		19		\$0.00
Medium	Work In Progress	208		8/27/2020 10:31:11 AM					
Acuna, Johnny		Replace sagging ceiling panels							
Maria Garcia									

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Chaparral MS</b>							
<b>Count: 15 Work Orders</b>			<b>Avg. Age of WO's 28</b>		<b>Total for Chaparral MS</b>			<b>0</b>	<b>\$1,029.28</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To	Description		Action Taken						
Requester Name									
<b>Location:</b>		<b>Desert Pride HS</b>							
234998					8/18/2020		28		\$0.00
Medium	Work In Progress				8/18/2020 8:10:21 AM				
Appelzoller, Fred	Need to replace circulating pump for new boiler at DP.								
Guillermo Hernandez									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>28</b>	<b>Total for Desert Pride HS</b>				<b>0</b>	<b>\$0.00</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert Trail ES</b>									
234106	Main Building	Office			7/31/2020		46		\$0.00
Medium	Work In Progress	front office			7/31/2020 2:48:55 PM				
Marquez, Gerardo Secretary office door is hard to unlock and lock.									
Elizabeth Hernandez									
234470		Kitchen			8/6/2020		40		\$0.00
High	Work In Progress				8/6/2020 7:57:46 AM				
Gallegos, Rafael AC unit not working in kitchen area (hot)									
Dino Facio									
233009		Custodial			7/6/2020		71		\$0.00
Medium	Work In Progress				7/6/2020 11:30:33 AM				
, WALK IN GATE AT BUS TURN AROUND NEEDS TO BE FIXED.									
Laura Sandoval									
234650					8/10/2020		36		\$0.00
Medium	Work In Progress				8/10/2020 8:19:52 AM				
Acuna, Johnny need to replace broken or missing window screens throughout the main building it is an eye sore									
Laura Sandoval									
235251					8/24/2020		22		\$0.00
Medium	Work In Progress				8/24/2020 11:13:36 AM				
Acuna, Johnny El bano de los hombres de tercer grado el extractor no prende por favor de revisarlo gracias									
Laura Sandoval									
<b>Count: 5 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>43</b>	<b>Total for Desert Trail ES</b>			<b>0</b>	<b>\$0.00</b>



# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Desert View ES</b>									
234756					8/11/2020		35		\$0.00
Medium	Work In Progress				8/11/2020 9:08:19 PM				
Gonzalez, Salvador		please need homemade drags							
Luis Saucedo									
234955	Main Building	Storage			8/17/2020		29		\$205.41
Medium	Work In Progress				8/17/2020 10:34:50 AM				
Ambriz, Jose		In the storage room 302 there is an ice maker that is not working. As per the principal he needs it repaired.							
Israel Ortega									
<b>Count: 2 Work Orders</b>				<b>Avg. Age of WO's</b>	<b>32</b>		<b>Total for Desert View ES</b>	<b>0</b>	<b>\$205.41</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC</b>							
233395		Classroom			7/16/2020		61		\$0.00
Medium	Work In Progress				7/16/2020 2:17:20 PM				
Lara, Ralph		door marker frame needs alignment door has gap not closing correctly							
Javier Hernandez									
235075					8/19/2020		27		\$0.00
Medium	Work In Progress				8/19/2020 7:57:35 AM				
Lara, Ralph		Please remove all doors and material that was on the back of the building after renovation was completed for the old front desk.							
Guillermo Hernandez									
<b>Count: 2 Work Orders</b>		<b>Avg. Age of WO's 44</b>		<b>Total for GAC</b>		<b>0</b>		<b>\$0.00</b>	

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>GAC - Pre-K</b>							
235554					8/31/2020		15		\$0.00
Medium	Work In Progress				8/31/2020 1:37:55 PM				
Lara, Ralph		Need A-61 key for the custodial closet in the pre-K or to put the lock back on master for the custodial closet							
Felipa Cortez									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>	<b>15</b>			<b>Total for GAC - Pre-K</b>	<b>0</b>		<b>\$0.00</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden ES</b>									
234937		Custodial			8/17/2020		29		\$0.00
Medium	Work In Progress				8/17/2020 7:10:05 AM				
Ambriz, Jose		Maine Communications room in front of computer lab 404 air conditioner not working real hot in there							
Jose Pinon									
234665		Custodial			8/10/2020		36		\$0.00
Medium	Work In Progress				8/10/2020 11:06:41 AM				
Tellez, Hector		Castoreo closet baluster not working install Lights and didn't work on Jefferson Highway							
Jose Pinon									
234329		Office			8/4/2020		42		\$0.00
Medium	Work In Progress	402			8/4/2020 7:35:47 AM				
Romero, Joaquin		Good Morning Ms. Herrera per our conversation here is the work order for the following. Requesting blinds for the PTO, side office, counselors window for privacy.				waiting for blinds ordered on 8-4-20			
		Greatly Appreciated,							
Patty Madrid									
235523		Office			8/31/2020		15		\$0.00
Medium	Work In Progress	101			8/31/2020 7:55:10 AM				
,		GES-Classroom 101 Temperature in the classroom is very hot							
Patty Madrid									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>31</b>		<b>Total for Gadsden ES</b>	<b>0</b>		<b>\$0.00</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

Location: Gadsden HS

235558 8/31/2020 15 \$0.00

Medium Work In Progress 8/31/2020 2:11:03 PM

Romero, Joaquin Requested by Mr. David Martinez for Varsity Gym- Please check the roof on the Varsity Gym because we have tar droplets on various part of the wood basketball court.

Velia Alarcon

235465 8/28/2020 18 \$16.50

Medium Work In Progress 8/28/2020 11:33:39 AM

Romero, Joaquin Requested by Mr. John Palmer for Men's Staff Restroom in the Science Building-Fix toilet in upstairs men's staff restroom, it has began to keep water running again.

Velia Alarcon

233434 7/20/2020 57 \$0.00

Medium Work In Progress 7/20/2020 7:43:03 AM

Villalobos, Jose Headger HS 45 will not start.

Guadalupe Ontiveros

233845 Academic Bldg 7/28/2020 49 \$0.00

Medium Work In Progress 7/28/2020 11:22:50 AM

Tellez, Hector 2 light fixtures in hallways Balast out in both. first light fixture outside classroom 330 the other by room 322

Liliana Acosta

234122 7/31/2020 46 \$0.00

Medium Work In Progress 7/31/2020 4:04:55 PM

Tellez, Hector Requested by Chef Anthony Sapien Rm. 515/517 CTE Building-Replace silver receptacles outlets located in the kitchen with purchases Electrical Rooftop Cord Reels (total of 3). FOR FURTHER INFORMATION OR INSTRUCTION PLEASE CHEF SAPIEN. HE HAS CHOSEN THE OPTION OF ONLY BEING ON THE SCHOOL CAMPUS ON MONDAYS AND TUESDAY, PLEASE SEE HIM THEN.

Velia Alarcon

234924 8/14/2020 32 \$0.00

Medium Work In Progress 8/14/2020 3:53:18 PM

Tellez, Hector Requested by Mr. Ramon Quiroga Rm. 516 CTE Building Flower Shop-Wants to see if an electrical outlet can be placed in the flower shop where teacher has no electricity. MR. QUIROGA IS ON CAMPUS ON MONDAY, TUESDAY, THURSDAY AND FRIDAY. IF MAINTENANCE HAVE ANY QUESTIONS.

8/19/20 - asp Joaquin, outlets need to be moved

Velia Alarcon

9/15/2020 2:55:13 PM

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location: Gadsden HS</b>									
235423					8/27/2020		19		\$0.00
High	Work In Progress			8/27/2020 12:16:43 PM					
Appelzoller, Fred	Culinary kitchen (Panther Hut) needs a new gas connection for an additional stove. Also needs the quick-disconnect gas lines that were not purchased with the stove.								
Danielle Rodriguez									
234124					7/31/2020		46	2	\$50.00
Medium	Work In Progress			7/31/2020 4:09:50 PM					
Appelzoller, Fred	Requested by Chef Anthony Sapien Rm. 515/517 CTE Building-Relocate tea brewing machine in the Panther Hut Cafe from the dinning room area to the kitchen area. FOR FURTHER INFORMATION OR INSTRUCTION PLEASE CHEF SAPIEN. HE HAS CHOSEN THE OPTION OF ONLY BEING ON THE SCHOOL CAMPUS ON MONDAYS AND TUESDAY, PLEASE SEE HIM THEN.		9/1/20 Disconnected brewing machine and relocated to kitchen area . Need plumber to connect water line to brewing machine .						
Velia Alarcon									
234487					8/6/2020		40		\$0.00
Medium	Work In Progress			8/6/2020 10:13:39 AM					
Escobar, David	Can someone check out Unit HU-2&EC-2 North MP58 girls locker room panel is burned out not allowing unit to operate. Thank you .								
Joaquin Romero									
234773					8/12/2020		34		\$126.83
Medium	Work In Progress			8/12/2020 12:14:04 PM					
Escobar, David	Portable 150 computer tech room unit is not working. trouble shoot unit and it might be the contractor need to order parts								
Joaquin Romero									
235359					8/25/2020		21		\$0.00
Medium	Work In Progress			8/25/2020 3:47:17 PM					
Lara, Ralph	Requested by Ms. Juana Santamaria Rm. 805 Annex Building-Need door knob to lock the door from inside of the classroom restroom.								
Velia Alarcon									
233252					7/13/2020		64		\$0.00
Medium	Work In Progress			7/13/2020 8:05:02 AM					
Lara, Ralph	The boys gym is going to get the gym floor re-done and need to change the locks so no one may enter except the the company that is doing the gym floor.								

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									

**Location: Gadsden HS**

233590	Cafeteria (1998)				7/22/2020		55		\$0.00
Medium	Work In Progress				7/22/2020 2:06:53 PM				
Ontiveros, Guadalupe		Requested by the G.H.S. Admin. Team-Leaves in front of the Cafeteria and on the rocks need to be swept up and picked up.							

Velia Alarcon

233598					7/22/2020		55		\$0.00
Medium	Work In Progress				7/22/2020 2:25:33 PM				
Ontiveros, Guadalupe		Requested by the G.H.S. Admin. Team-The weeds inside the courtyard of the Old Main Building need to be pulled/cleaned up.							

Velia Alarcon

233600					7/22/2020		55		\$0.00
Medium	Work In Progress				7/22/2020 2:40:05 PM				
Ontiveros, Guadalupe		Requested by the G.H.S. Admin. Team-Rocks needs to be filled on the north side of the Theater Building.							

Velia Alarcon

233602					7/22/2020		55		\$0.00
Medium	Work In Progress				7/22/2020 2:42:23 PM				
Ontiveros, Guadalupe		Requested by the G.H.S. Admin. Team-Rock needs to be filled on the south side of the North Building between the North Building and Theater.							

Velia Alarcon

233603					7/22/2020		55		\$0.00
Medium	Work In Progress				7/22/2020 2:44:14 PM				
Ontiveros, Guadalupe		Requested by the G.H.S. Admin. Team-Sweep rocks off the sidewalk on the north side of the North Building by ROTC.							

Velia Alarcon

233605					7/22/2020		55		\$0.00
Medium	Work In Progress				7/22/2020 2:47:03 PM				
Ontiveros, Guadalupe		Requested by the G.H.S. Admin. Team-Rock needs to be filled outside of the Academic Building on the north side.							

Velia Alarcon

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden HS</b>									
233616					7/22/2020		55		\$0.00
Medium	Work In Progress				7/22/2020 3:28:40 PM				
Ontiveros, Guadalupe		Requested by the G.H.S. Admin. Team-Trim tree outside of Mr. Mora's (Athletic Training Room) by the Panther Gym.							
Velia Alarcon									
233622					7/22/2020		55		\$0.00
Medium	Work In Progress				7/22/2020 3:39:17 PM				
Ontiveros, Guadalupe		Requested by the G.H.S. Admin. Team-Rocks need to be filled on the north side of the Weight Room.							
Velia Alarcon									
233070					7/7/2020		70		\$0.00
Medium	Work In Progress				7/7/2020 1:24:36 PM				
Ontiveros, Guadalupe		Requested by Mrs. Danielle Rodriguez for Landscape Outside of the Science Building on the South Side-Rock needs to be added to the landscape outside of the Science Building on the south side.							
Velia Alarcon									
233071					7/7/2020		70		\$0.00
Medium	Work In Progress				7/7/2020 1:26:06 PM				
Ontiveros, Guadalupe		Requested by Mrs. Danielle Rodriguez Landscape Outside of the Cafeteria-Rock needs to be added to the landscape outside of the Cafeteria.							
Velia Alarcon									
233073					7/7/2020		70		\$0.00
Medium	Work In Progress				7/7/2020 1:27:50 PM				
Ontiveros, Guadalupe		Requested by Mrs. Danielle Rodriguez Trees Outside of Cafeteria-Trees need to be trimmed in front of the cafeteria.							
Velia Alarcon									
235122					8/20/2020		26		\$0.00
Medium	Work In Progress				8/20/2020 11:07:00 AM				
Lara, Ralph		Requested by Mr. David Martinez-Please provide a key that will open the Varsity Gym entrance doors only, 8 keys will be needed.							
Velia Alarcon									



# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Gadsden HS</b>										
233493					7/21/2020		56		\$0.00	
Medium	Work In Progress				7/21/2020 9:10:58 AM					
Lara, Ralph		Requested by Frank Marin for Rm. 504 CTE Building- Bay door is not working and needs to be re-set, bay door does not go up.								
Velia Alarcon										
233708					7/24/2020		53		\$0.00	
Medium	Work In Progress				7/24/2020 11:09:30 AM					
Lara, Ralph		Requested by the Admin. Team- Three keys are need to open the storage room # 208S in the North Building.								
Velia Alarcon										
<b>Count: 26 Work Orders</b>		<b>Avg. Age of WO's 47</b>		<b>Total for Gadsden HS</b>				<b>2</b>	<b>\$193.33</b>	

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Gadsden MS</b>									
233006					7/6/2020		71		\$0.00
Medium	Work In Progress	Garden by			7/6/2020 10:41:01 AM				
Ontiveros, Guadalupe		Please remove weeds from garden ground as per Mrs. Quinonez. Thank you							
Hilda Adler									
234594	Cafeteria	Cafeteria			8/7/2020		39		\$4.68
Medium	Work In Progress	Cafeteria / Mr.			8/7/2020 3:41:35 PM				
Escobar, David		One AC unit in the cafeteria is not working.							
Hilda Adler									
235267	C-Wing	Office			8/24/2020		22		\$0.00
Medium	Work In Progress	Nursing			8/24/2020 1:29:00 PM				
Marquez, Gerardo		Please send Locksmith, I have lost a set of keys to my storage portable. Nursing Department. Thank you, Priscilla							
Priscilla Martinez									
233184					7/10/2020		67		\$0.00
Medium	Work In Progress	Mrs. Quinonez			7/10/2020 1:29:55 PM				
Villalobos, Jose		Please fix Pallet Jack, we need it. Its not working, leaking hydraulic oil. Thank you Mrs. Quinonez				Please forward to Joe - J. Romero 8/4/20			
Hilda Adler									
<b>Count: 4 Work Orders</b>		<b>Avg. Age of WO's 50</b>			<b>Total for Gadsden MS</b>			<b>0</b>	<b>\$4.68</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken				
Assigned To	Description									
Requester Name										
<b>Location: La Union ES</b>										
233994					7/30/2020		47		\$238.44	
Medium	Work In Progress			7/30/2020 8:42:58 AM						
Ambriz, Juan	As per Mr. Sanchez requesting to have his entire office to be re-painted and one wall of the old nurses office.		Asp report 8/3/20 - waiting on supplies from warehouse - J. Ambriz							
Guadalupe Parada										
235398					8/27/2020		19		\$0.00	
Medium	Work In Progress			8/27/2020 6:56:45 AM						
Ambriz, Juan	The exhaust fan in the ladies staff restroom next to the main office is not working.									
Guadalupe Parada										
235190	Main Building	Athletic Field			8/21/2020		25		\$0.00	
Medium	Work In Progress			8/21/2020 9:33:50 AM						
Ontiveros, Guadalupe	Poor drainage near PreK playground. Rain water flows toward building instead of drain. Need to re-slope area so that water will run towards drain. Discussed with Mr. Ontiveros last school year. Also, look into installing gutters on middle wing roof that will empty into drain.									
Arthur Moreno										
234446					8/5/2020		41		\$0.00	
Medium	Work In Progress			8/5/2020 2:39:05 PM						
Pacheco, Hector	Hose bid is leaking outside the cafeteria.									
Guadalupe Parada										
233744					7/27/2020		50		\$121.10	
Medium	Work In Progress			7/27/2020 10:06:13 AM						
Pacheco, Hector	The sink faucets have to be replaced in the lower grade staff lounge.									
Guadalupe Parada										
<b>Count: 5 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>36</b>				<b>Total for La Union ES</b>	<b>0</b>	<b>\$359.54</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Loma Linda ES</b>									
235178	Main Building	Exterior			8/21/2020		25		\$0.00
Medium	Work In Progress	Outside of main			8/21/2020 8:26:52 AM				
Romero, Joaquin		Mr. Cardona is requesting for the tables and benches outside to be retouched.							
Crystalee Heredia									
235182	Main Building	Restroom			8/21/2020		25		\$0.00
Medium	Work In Progress	All boy/girl			8/21/2020 8:43:34 AM				
Romero, Joaquin		Mr. Cardona is requesting for all bathroom partitions to be painted.							
Crystalee Heredia									
235469	Main Building	Office			8/28/2020		18		\$0.00
Medium	Work In Progress	Front Office			8/28/2020 12:40:17 PM				
Hernandez, Guillermo		Mr. Cardona is requesting for east side doors to have universal lock so teachers and staff can unlock doors to come in.							
Crystalee Heredia									
235446					8/28/2020		18		\$0.00
Medium	Work In Progress				8/28/2020 6:13:57 AM				
Carrasco, Danny		need plasti-coat paint that turns into a rubber to repair broken cafeteria tables the rubber on the sides of the seats are being peeled off.				8/28/20 - as per Danny, this needs to be routed to maintenance.			
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's 22</b>		<b>Total for Loma Linda ES</b>			<b>0</b>	<b>\$0.00</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Mesquite ES</b>							
235463	Main Building	Office			8/28/2020		18		\$0.00
Medium	Work In Progress	Book room #		8/28/2020 11:18:07 AM					
Hernandez, Guillermo		Lina Flores/ requesting room to be painted white please and thank you.							
Sandra Mora									
233763	Army Building	Portables			7/27/2020		50	0.5	\$43.10
Medium	Work In Progress	Portable # 505		7/27/2020 1:36:14 PM					
Escobar, David		Portable A/C is not working we have staff in it please make it cool thank you.				Troubleshoot unit. Compressor did not start Forward to Hvac 7-28-20			
Sandra Mora									
235022					8/18/2020		28		\$0.00
Medium	Work In Progress			8/18/2020 12:00:06 PM					
Marquez, Gerardo		Front door hinge							
Branden Jaquemai									
234967	Main Building	Office			8/17/2020		29		\$0.00
Medium	Work In Progress	Room # 203/205		8/17/2020 12:44:01 PM					
Escobar, David		In room 203/205 A/C not working please fix. Thank you.							
Sandra Mora									
235531		Kitchen			8/31/2020		15		\$17.98
High	Work In Progress			8/31/2020 9:15:04 AM					
Marquez, Gerardo		Deadbolt to back door not functioning properly and door sweep needed							
Dino Facio									
233715		Kitchen			7/24/2020		53		\$0.00
High	Work In Progress			7/24/2020 1:34:13 PM					
Tellez, Hector		Need new electrical plug for new cutter/mixture							
Dino Facio									
235330	Main Building				8/25/2020		21		\$0.00
Medium	Work In Progress	Room # 107		8/25/2020 11:33:33 AM					
Tellez, Hector		Lina Flores requesting electrical work done in book room plugs installed please and thank you.							
Sandra Mora									
<b>Count: 7 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>31</b>	<b>Total for Mesquite ES</b>			<b>0.5</b>	<b>\$61.08</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: North Valley ES</b>									
233648		Kitchen			7/23/2020		54		\$577.11
High	Work In Progress				7/23/2020 8:59:27 AM				
Appelzoller, Fred		No hot water in kitchen area							
Dino Facio									
233472					7/20/2020		57		\$1,125.48
Medium	Work In Progress				7/20/2020 3:07:34 PM				
Appelzoller, Fred		need to replace lav faucets in restroom							
Fred Appelzoller									
235023					8/18/2020		28		\$0.00
Medium	Work In Progress	playground			8/18/2020 12:36:48 PM				
Ontiveros, Guadalupe		Please refill the bark in playground areas. Thank you.							
Ruth Gomez									
235553					8/31/2020		15		\$0.00
Medium	Work In Progress	105			8/31/2020 1:36:01 PM				
Romero, Joaquin		Please cover up holes and touch up paint on wall due to a removed white board. Thank you.							
Ruth Gomez									
235025		Hallway/Corridor			8/18/2020		28		\$0.00
Medium	Work In Progress	classroom area			8/18/2020 12:41:27 PM				
Romero, Joaquin		Please replace the missing signs identifying the classroom's room number. Thank you.				ordered sign on 8-21-20			
Ruth Gomez									
<b>Count: 5 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>36</b>		<b>Total for North Valley ES</b>	<b>0</b>	<b>\$1,702.59</b>	

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Northern On-Track Pre-K (LM)</b>										
235450					8/28/2020		18		\$0.00	
Medium	Work In Progress				8/28/2020 8:05:26 AM					
		The door handle in classroom 108 is loose and not locking correctly. Please check it out. Thanks!								
Viola Ramos										
235172					8/21/2020		25		\$103.10	
Medium	Work In Progress				8/21/2020 7:22:34 AM					
Ambriz, Jose		A/c unit in the cafeteria is not working. Maintenance checked filters cleaned condensation pan and checked pump. .Need Hvac to check unit . Thank you								
Joaquin Romero										
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>22</b>	<b>Total for Northern On-Track Pre-K (LM)</b>			<b>0</b>	<b>\$103.10</b>	

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Physical Plant Complex</b>									
235370					8/26/2020		20		\$0.00
Medium	Work In Progress				8/26/2020 8:41:42 AM				
Marquez, Gerardo		NEED TO ORDER FANS FOR LOCKSMITH VANS.							
Gerardo Marquez									
234705					8/11/2020		35		\$0.00
Medium	Work In Progress				8/11/2020 8:14:10 AM				
Appelzoller, Fred		need 1/2 cable for general wire drain cleaner							
Fred Appelzoller									
234799					8/13/2020		33		\$0.00
Medium	Work In Progress				8/13/2020 7:52:10 AM				
Pacheco, Hector		In need of sewer cable for machine 1/2 inch x 50 feet and a 1/2 inch x 75 feet cable.							
Hector Pacheco									
233474					7/20/2020		57		\$0.00
Medium	Work In Progress				7/20/2020 3:22:44 PM				
Marquez, Gerardo		Please change cores from DC-1 to something different, (see Memo first thing in the morning) Total of (5) - Offices Memo, Margret, Ruben, Maintenance Storage Area front and back door.							
Guillermo Hernandez									
233310					7/14/2020		63		\$0.00
Medium	Work In Progress				7/14/2020 11:54:17 AM				
Marquez, Gerardo		Needed in the construction office preferably by Friday afternoon or Monday Morning at the latest one (1) GM #6 and one (1) GM #7. Keys will be check out to Aliene O'Bryne. Should you have any questions please seemr. Gallegos in the Construction Office.							
Dominique Esparza									
234945					8/17/2020		29		\$0.00
Medium	Work In Progress				8/17/2020 8:11:58 AM				
Lara, Ralph		we need to order core cylinders, and keys for dist. wide. Jerry -Rafa							
Ralph Lara									
235140					8/20/2020		26		\$224.00
Medium	Work In Progress				8/20/2020 12:47:31 PM				
Gonzalez, Salvador		Need to repair damaged chain link fence in back of Riverside elementary							
Salvador Gonzalez									
<b>Count: 7 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>38</b>		<b>Total for Physical Plant Complex</b>	<b>0</b>	<b>\$224.00</b>	



# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Riverside ES</b>									
234757					8/11/2020		35		\$0.00
Medium	Work In Progress				8/11/2020 9:11:09 PM				
Gonzalez, Salvador		please need homemade drags							
Luis Saucedo									
234035					7/30/2020		47		\$0.00
Medium	Work In Progress				7/30/2020 2:48:42 PM				
Hernandez, Guillermo		Re-stencil parking lot located behind the school. Principal, Assistant Principal, Secretary, Nurse, and SNP Manager. (Mrs. Martinez)							
Norma Martinez									
233704					7/24/2020		53		\$140.57
Medium	Work In Progress	Exit doors			7/24/2020 10:26:52 AM				
Hernandez, Javier		Bird spikes need to be re-secure. Pigeons moved bird spikes. (Mrs. Martinez)				Asp report 8/3/20 - pending supplies have been ordered - R. Ortiz			
Norma Martinez									
235340					8/25/2020		21		\$988.89
Medium	Work In Progress				8/25/2020 1:49:21 PM				
Saucedo, Luis		need to replace swings at RSE							
Luis Saucedo									
235426					8/27/2020		19		\$0.00
Medium	Work In Progress				8/27/2020 1:33:57 PM				
Ortiz, Ruben		Please clean all AC vents in all classrooms and offices. Custodians clean the vents through the outside but vents are very dusty and dirty and need to be clean through the inside. (Mr. Damian)							
Norma Martinez									
234696					8/10/2020		36		\$0.00
Medium	Work In Progress				8/10/2020 3:45:46 PM				
Castillo, Carlos		Pick up at warehouse and install flashing light by bus turnaround.							
Guillermo Hernandez									
<b>Count: 6 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>35</b>		<b>Total for Riverside ES</b>	<b>0</b>	<b>\$1,129.46</b>	

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa ES</b>									
235240		Kitchen			8/24/2020		22		\$359.90
High	Work In Progress				8/24/2020 8:21:08 AM				
Castillo, Carlos		Several burnt bulbs and some lights that dont turn on at all in kitchen area							
Dino Facio									
234969	Main Building	Exterior			8/17/2020		29		\$0.00
Medium	Work In Progress	East gate inside			8/17/2020 12:46:58 PM				
Lara, Ralph		A new lock is needed for gate on east side of school - inside of campus. The other lock broke. Please see Maria, head custodian regarding this work order. Thank you.							
Rita Mendez									
234712					8/11/2020		35		\$0.00
Medium	Work In Progress				8/11/2020 10:04:44 AM				
Ontiveros, Guadalupe		Playground - Asp PM 233239 wood chips need to be replaced.							
Juan Ambriz									
233686	Main Building	Classroom			7/23/2020		54		\$0.00
Medium	Work In Progress	Room 305 Mrs.			7/23/2020 3:59:35 PM				
Lara, Ralph		Please install drawer latches. The originals are broken. Thank you.							
Rita Mendez									
<b>Count: 4 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>35</b>	<b>Total for Santa Teresa ES</b>			<b>0</b>	<b>\$359.90</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
234422	Main Building	Athletic Field				8/5/2020	41		\$0.00
Medium	Work In Progress	all outdoor			8/5/2020 9:53:02 AM				
Ontiveros, Guadalupe		Need more round up to clear up weeds around all athletic fields Round up sprayer one on campus broke In need a Kubota tractor with scraper							
Lorraine Dominguez									
233109	Main Building	Athletic Field				7/8/2020	69		\$130.00
Medium	Work In Progress	Outdoor fields			7/8/2020 11:07:23 AM				
Ontiveros, Guadalupe		Grounds is in need of tractor with scraper as well as round up for weeds							
Lorraine Dominguez									
235032						8/18/2020	28		\$0.00
Medium	Work In Progress				8/18/2020 1:08:17 PM				
Ontiveros, Guadalupe		enclosed courtyard area - remove trash including pieces of walk mats blown of roof							
Alfredo Holguin									
235033						8/18/2020	28		\$0.00
Medium	Work In Progress				8/18/2020 1:10:37 PM				
Ontiveros, Guadalupe		Area between cafeteria and library - There is a dead tree and orleandars that have dead branches. Are they being watered or herbicide damage?							
Alfredo Holguin									
235036						8/18/2020	28		\$0.00
Medium	Work In Progress				8/18/2020 1:15:48 PM				
Ontiveros, Guadalupe		Softball Field- The storm drain located in the fenced area where a mesquite trees is growing - the tree and all the weeds need to be removed inside this area.							
Alfredo Holguin									
235058	Main Building	Athletic Field				8/18/2020	28		\$10.80
Medium	Work In Progress	soccer field			8/18/2020 2:50:26 PM				
Ontiveros, Guadalupe		Soccer field needs weeds on edges cut and pine tree needles picked up							
Lorraine Dominguez									
233829						7/28/2020	49		\$7.18
Medium	Work In Progress	Campuswide			7/28/2020 9:50:25 AM				
Lara, Ralph		Remove several lock from current off master status. Please see Mr. W and Mrs. Soriano for discussion about which locks and how they would like them keyed.							
Nicholas Wohlgemuth									

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
235148	Main Building	Gym			8/20/2020		26		\$0.00
Medium	Work In Progress	Varsity gym area			8/20/2020 3:06:51 PM				
Lara, Ralph		Door is missing screws							
Lorraine Dominguez									
235149	Main Building	Classroom			8/20/2020		26		\$0.00
Medium	Work In Progress	610			8/20/2020 3:07:46 PM				
Lara, Ralph		Classroom door does not open with master key							
Lorraine Dominguez									
234735	Main Building	Hallway/Corridor			8/11/2020		35		\$0.00
Medium	Work In Progress	corridor in			8/11/2020 2:15:31 PM				
Ontiveros, Guadalupe		Please clear up all weeds, grass and debris from corridors right outside admin offices							
Lorraine Dominguez									
234664	Main Building	Classroom			8/10/2020		36		\$0.00
Medium	Work In Progress	509			8/10/2020 10:55:25 AM				
Lara, Ralph		Teacher classroom is accessible to all teachers, please make her key for classroom only for her key.							
Lorraine Dominguez									
233985	Annex Building	Classroom			7/30/2020		47		\$0.00
Medium	Work In Progress	Dinning Room			7/30/2020 7:56:52 AM				
Lara, Ralph		Install Door Top on Dinning rooms door							
Gema Suggs									
233350	Vocational				7/15/2020		62		\$0.00
Medium	Work In Progress				7/15/2020 10:36:26 AM				
Escobar, David		In the Culinary Arts Kitchen, roof top unit showing alarm. Tempature is showing 90.4°. No other information is showing on diagnostic. Please have HVAC look into this. Thank You							
Dominique Esparza									
235496	Annex Building	Kitchen			8/29/2020		17		\$0.00
Medium	Work In Progress	707			8/29/2020 10:46:04 AM				
Castillo, Carlos		Fix sagging and broken ceiling light cover in womens bathroom							
Gema Suggs									

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
233335	Concession	Restroom			7/14/2020		63		\$586.16
Medium	Work In Progress				7/14/2020 3:49:47 PM				
Pacheco, Hector s per conversation with Head Custodian to replace 4 toilet flush valves and also 3 urinal flush valves.									
Hector Pacheco									
233695	Main Building	Restroom			7/24/2020		53		\$690.00
Medium	Work In Progress				7/24/2020 8:13:24 AM				
Pacheco, Hector Need to replace automatic flush sensor system on a urinal in boys restroom at 200 wing..									
Hector Pacheco									
234642					8/10/2020		36		\$573.26
Medium	Work In Progress				8/10/2020 7:30:21 AM				
Ambriz, Jose Unit in culinary kitchen not cooling.									
Jose Ambriz									
233389					7/16/2020		61		\$0.00
Medium	Work In Progress				7/16/2020 11:09:15 AM				
Ambriz, Jose bolimo valve not working properly on ac unit for library sths									
Javier Hernandez									
232741		Portables			7/1/2020		76		\$3,784.22
Medium	Work In Progress				7/1/2020 11:48:53 AM				
Escobar, David ac units in portable for margie computer tech not cooling ,cleaned filters and coils, may need freon or new units									
Javier Hernandez									
232735					7/1/2020		76		\$0.00
Medium	Work In Progress	Tech Portable			7/1/2020 10:03:00 AM				
, AC not working. Please check and service ASAP.									
Nicholas Wohlgemuth									
234814	Main Building	Portables			8/13/2020		33		\$0.00
Medium	Work In Progress	Nurse Portable			8/13/2020 9:32:13 AM				
Ramos, Rudy Nurse has reported that both AC's in her portable are not working. 8/13/2020 at 9:31am									
Gema Suggs									
235044	Main Building	Classroom			8/18/2020		28		\$0.00
Medium	Work In Progress	801			8/18/2020 1:28:06 PM				
Ramos, Rudy Ceiling tiles need replacement									
Lorraine Dominguez									
9/15/2020 2:55:14 PM									

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Santa Teresa HS</b>									
235046	Vocational	Classroom			8/18/2020		28		\$0.00
Medium	Work In Progress	803			8/18/2020 1:28:50 PM				
Ramos, Rudy		Ceiling tiles need replacing							
Lorraine Dominguez									
235047	Vocational	Classroom			8/18/2020		28		\$0.00
Medium	Work In Progress	805			8/18/2020 1:29:27 PM				
Ramos, Rudy		Ceiling tiles need replacing							
Lorraine Dominguez									
235048	Vocational	Restroom			8/18/2020		28		\$0.00
Medium	Work In Progress	restroom			8/18/2020 1:30:19 PM				
Ramos, Rudy		Lights need to be looked at not sure if its light bulbs or not functioning							
Lorraine Dominguez									
235051	Main Building	Hallway/Corridor			8/18/2020		28		\$0.00
Medium	Work In Progress	500 hallway			8/18/2020 1:32:58 PM				
Ramos, Rudy		Need lights in the hallway replaced as there is about 6 out.							
Lorraine Dominguez									
233305	Main Building	Hallway/Corridor			7/14/2020		63		\$0.00
Medium	Work In Progress	main hallway			7/14/2020 10:52:37 AM				
Hernandez, Javier		Issue with restroom in main hallway please see below En el baño de los hombres, de el pasillo principal, (enfrente de la oficina de Emma) uno de los uriniales no flachea.				waiting on sensors asp report 8/3/20 - R. Ramos			
Lorraine Dominguez									
235383					8/26/2020		20		\$0.00
Medium	Work In Progress				8/26/2020 3:23:54 PM				
Gonzalez, Salvador		Need to fabricate ladders for culinary building in STHS							
Salvador Gonzalez									
233102		Athletic Field			7/8/2020		69		\$0.00
Medium	Work In Progress				7/8/2020 8:28:44 AM				
Villalobos, Jose		please check air compressor, not working. thank you.							
Lauro Jasso									
<b>Count: 29 Work Orders</b>			<b>Avg. Age of WO's 42</b>			<b>Total for Santa Teresa HS</b>	<b>0</b>	<b>\$5,781.62</b>	

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Santa Teresa MS</b>							
234717	North Building	Hallway/Corridor			8/11/2020		35		\$0.00
Medium	Work In Progress	NORTH/SOUTH			8/11/2020 11:30:15 AM				
Hernandez, Javier	SET UP MOTIVATIONAL BANNERS ON THE WALL IN FRONT OF THE RAMP LEADING TO THE LOWER LEVEL-- BOTH BUILDINGS. PLEASE SEE MS BERTHA VALENZUELA BEFORE SETTING UP		Assign to D. Sotelo						
Laura Parra									
234449		Hallway/Corridor			8/5/2020		41		\$900.00
Medium	Work In Progress				8/5/2020 3:22:18 PM				
Sotelo, Daniel	I NEED to change the ceiling tiles (not lights) in rooms 13,14,16,23,22,21,20,18,17, and teacher lounge 19, and hallways of the north building please		8/28/20 - work order will be re-routed to maintenance; this is for ceiling tiles to be replaced not lights. Danny will be picking up bulbs from STM and adjusting them back into inventory.						
Cristian Martinez									
235524	North Building				8/31/2020		15		\$0.00
Medium	Work In Progress				8/31/2020 7:59:05 AM				
Sotelo, Daniel	Need ceiling tiles in rooms #13-14-16-23-22-21-20-18-17 and in hallways on the north building as well.								
Cristian Martinez									
235415	North Building	Office			8/27/2020		19		\$23.33
Medium	Work In Progress	SECURITY			8/27/2020 10:33:51 AM				
Ambriz, Jose	HEATING/COOLING NEEDS TO BE REPAIRED. AS PER BUILDING MECHANIC OFFICE NEEDS NEW DUCT WORK								
Laura Parra									
234523	North Building	Classroom			8/6/2020		40		\$0.00
Medium	Work In Progress	P3A MIHALICK			8/6/2020 3:25:43 PM				
Lara, Ralph	TEACHER NEEDS KEY TO ENTER BUILDING, IF POSSIBLE SAME AS CLASSROOM KEY								
Laura Parra									
<b>Count: 5 Work Orders</b>		<b>Avg. Age of WO's 30</b>			<b>Total for Santa Teresa MS</b>			<b>0</b>	<b>\$923.33</b>

## 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
233454		Classroom			7/20/2020		57		\$0.00
Medium	Work In Progress	32			7/20/2020 1:10:02 PM				
Lara, Ralph		weather strip							
Ivette Rios									
233534	Main Building	Classroom			7/21/2020		56		\$0.00
Medium	Work In Progress	35			7/21/2020 2:38:37 PM				
Lara, Ralph		draft under exit door lots of dirt/insects							
Ivette Rios									
233535					7/21/2020		56		\$0.00
Medium	Work In Progress	33			7/21/2020 2:39:21 PM				
Lara, Ralph		back door needs to be weather stripped							
Ivette Rios									
235328	Main Building				8/25/2020		21		\$0.00
Medium	Work In Progress	18/23			8/25/2020 11:27:26 AM				
Lara, Ralph		ROOM 18 AND 23 HAVE THE SAME KEY TA64							
Ivette Rios									
235329					8/25/2020		21		\$0.00
Medium	Work In Progress				8/25/2020 11:31:31 AM				
Lara, Ralph		room 37 and room 40 have the same key TA40							
Ivette Rios									
234644					8/10/2020		36		\$0.00
Medium	Work In Progress				8/10/2020 7:47:28 AM				
Ambriz, Jose		MP 581 needs to be replaced and program burned out.							
Jose Ambriz									
233309		Kitchen			7/14/2020		63		\$0.00
High	Work In Progress				7/14/2020 11:44:02 AM				
Escobar, David		AC Unit not cooling in kitchen (Hot)							
Dino Facio									
235417					8/27/2020		19		\$324.70
Medium	Work In Progress	book room			8/27/2020 10:37:20 AM				
Pacheco, Hector		book room the portable next to portable a the sink is clogged and stinks really bad all the way to portable A.							
Ivette Rios									



# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunland Park ES</b>									
233588					7/22/2020		55		\$0.00
Medium	Work In Progress	76			7/22/2020 2:03:23 PM				
Hernandez, Javier		computer lab to painted the doors and wall that has a brown stain on it by the blue cabinet. doors also need to be painted.				Pending asp report 8/3/20 - waiting on supplies have been ordered			
Ivette Rios									
234354					8/4/2020		42		\$0.00
Medium	Work In Progress	16			8/4/2020 9:47:19 AM				
Hernandez, Javier		ALL STUDENTS DESK HAVE TO BE THE SAME HEIGHT				Assigned to Luis Saucedo-mkv			
Ivette Rios									
234676					8/10/2020		36		\$0.00
Medium	Work In Progress				8/10/2020 12:40:48 PM				
Gonzalez, Salvador		please need homemade drags please ask luis							
Luis Saucedo									
<b>Count: 11 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>42</b>		<b>Total for Sunland Park ES</b>	<b>0</b>	<b>\$324.70</b>	

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason	Created Date/Time	Actual Comp Date	Action Taken			
Assigned To	Description								
Requester Name									
<b>Location:</b>		<b>Sunrise ES</b>							
235536	Main Building	Office			8/31/2020		15		\$0.00
Medium	Work In Progress			8/31/2020 10:56:10 AM					
Acuna, Johnny	Cathie Williams, Office, Need to remove Newsletter from wall and install new one.								
Monica Narez									
235552	Main Building	Office			8/31/2020		15		\$0.00
Medium	Work In Progress			8/31/2020 12:43:24 PM					
Acuna, Johnny	Elizabeth Leal, Office, The keyboard tray needs to be fixed, and the left bottom drawer won't close.								
Monica Narez									
234372	Main Building	Office			8/4/2020		42		\$285.84
Medium	Work In Progress	Outside front		8/4/2020 12:04:05 PM					
Acuna, Johnny	As per Mrs. Williams, Office, The birds through the front outside office they are making a mess and if they can do something about the birds.								
Monica Narez									
234373	Main Building	Parking Lot			8/4/2020		42		\$107.36
Medium	Work In Progress	by Buses		8/4/2020 12:08:34 PM					
Acuna, Johnny	Cathie Williams, Office, If they can reroute the gouter by the buses.								
Monica Narez									
233961					7/29/2020		48		\$0.00
Medium	Work In Progress			7/29/2020 11:42:24 PM					
Acuna, Johnny	Need two signs for chains that read Do Not Enter in English and Spanish to parking lot.								
Johnny Acuna									
234805	Main Building	Parking Lot			8/13/2020		33		\$0.00
Medium	Work In Progress			8/13/2020 8:16:33 AM					
Acuna, Johnny	As per Mrs. Williams, Office, Need to put signs that say DO NOT ENTER outside where the poles were installed with chains.								
Monica Narez									
233826	Main Building	Classroom			7/28/2020		49		\$0.00
Medium	Work In Progress			7/28/2020 8:53:37 AM					
Acuna, Johnny	Rocio Nieto, Classroom 103, Needs blinds on her windows and side window.								
Monica Narez									

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location: Sunrise ES</b>									
235266					8/24/2020		22		\$0.00
Medium	Work In Progress				8/24/2020 1:28:02 PM				
Acuna, Johnny		Cathie Williams, Office, Trim bushes and shrubs around school.							
Monica Narez									
233266					7/13/2020		64		\$0.00
Medium	Work In Progress				7/13/2020 1:45:19 PM				
Chavez, Santos		Entrada de escuela 2 balastras estan descompuestas y necesitan focos gracias buen dia.							
Maritxa Vasquez									
235270	Main Building				8/24/2020		22		\$0.00
Medium	Work In Progress				8/24/2020 2:06:20 PM				
Marquez, Gerardo		Need new pad loock west bus turn around gate.							
Monica Narez									
235272					8/24/2020		22		\$0.00
Medium	Work In Progress				8/24/2020 2:07:08 PM				
Marquez, Gerardo		Cathie Williams, Office, Key gets stuck to open the Isolation Room.							
Monica Narez									
233288					7/13/2020		64		\$0.00
Medium	Work In Progress	playground			7/13/2020 5:24:35 PM				
Ontiveros, Guadalupe		please repair stuck irrigation valve solenoid to grass irrigation sprinkler system. water is constantly on. Thank You...							
Johnny Acuna									
235265	Main Building				8/24/2020		22		\$0.00
Medium	Work In Progress	Playground			8/24/2020 1:24:40 PM				
Ontiveros, Guadalupe		Cathie Williams, Office, Clean playground wood chips and level wood chips in the playground.							
Monica Narez									
<b>Count: 13 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>35</b>		<b>Total for Sunrise ES</b>	<b>0</b>	<b>\$393.20</b>	

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date			
Assigned To		Description				Action Taken			
Requester Name									
<b>Location:</b>		<b>Vado ES</b>							
234333		Kitchen			8/4/2020		42		\$0.00
High	Work In Progress				8/4/2020 7:58:13 AM				
Escobar, David		AC units not working very hot in kitchen area							
Dino Facio									
<b>Count: 1 Work Orders</b>		<b>Avg. Age of WO's</b>		<b>42</b>	<b>Total for Vado ES</b>			<b>0</b>	<b>\$0.00</b>

# 219 - Work Orders In Progress (Fiscal Year)

Selected Date Range for Request Dates: 7/1/2020 - 8/31/2020 Order By Location, Status

WOID	Building	Area	Deferred By	Until	Request Date	Target Comp Date	Days Aged	Labor Hours	Total Costs	
Priority	Status	Area Number	Reason		Created Date/Time	Actual Comp Date				
Assigned To		Description				Action Taken				
Requester Name										
<b>Location: Yucca Heights ES</b>										
233475		Classroom			7/20/2020		57	\$0.00		
Medium	Work In Progress				7/20/2020 3:25:55 PM					
Ambriz, Jose		Need to check units that are not working properly.								
Jose Ambriz										
234547		Office			8/7/2020		39	\$0.00		
Medium	Work In Progress				8/7/2020 9:37:16 AM					
Acuna, Johnny		Automatic door warning sign needs to be replaced								
Ernesto Diaz										
<b>Count: 2 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>48</b>	<b>Total for Yucca Heights ES</b>			<b>0</b>	<b>\$0.00</b>	
<b>Count: 219 Work Orders</b>			<b>Avg. Age of WO's</b>	<b>40</b>	<b>Grand Total</b>			<b>13.5</b>	<b>\$18,502.12</b>	